



County of Armstrong
 Department of Planning and Development

Richard L. Palilla, Executive Director

402 Market Street, Kittanning, PA 16201
 724.548.3223 Phone | 724.545.7050 Fax
 email: planning@co.armstrong.pa.us

May 26, 2011

David C. Hart, P.E., Manager
 Rail Safety Division
 Pennsylvania Public Utility Commission
 P.O. Box 3265
 Harrisburg, PA 17105-3265

PA PUBLIC UTILITY COMMISSION

JUN 02 2011

**BUREAU OF TRANSPORTATION & SAFETY
 RAIL SAFETY DIVISION**

RE: Armstrong County NBIS Bridge Inspection Report
 South Buffalo Township Bridge #3

Dear Mr. Hart,

Please find enclosed a NBIS Bridge Inspection Report for South Buffalo Township Bridge #3 prepared by the County's engineer, Senate Engineering Company. The structure carries T-881 over the Buffalo & Pittsburgh Railroad in South Buffalo Township, Armstrong County. We are submitting this inspection report in compliance with the PUC order dated April 21, 2009, at C-20030388.

If you have any questions please do not hesitate to contact me at (724) 548-3223.

Sincerely,

Darin Alviano
 Planning Coordinator

PA P.U.C. SECRETARY'S BUREAU

2011 JUN -3 PM 2:59

RECEIVED

SENATE ENGINEERING COMPANY

U-PARC, 420 William Pitt Way
Pittsburgh, PA 15238-1330
Telephone (412) 826-5454
Fax (412) 826-5458
senate@senateengineering.com
www.senateengineering.com

30 South Main Street, Suite 202
Washington, PA 15301
Telephone (724) 228-6446

250 South Jefferson Street
Kittanning, PA 16201
Telephone (724) 548-1770


500 Fifth Avenue, Suite 502
McKeesport, PA 15132
Telephone (412) 664-7125

STRUCTURE B.M.S. NUMBER: 03 7223 0881 0003 (NORTH CLINTON Bridge)
BRIDGE NAME: T-881 Clinton Road over Buffalo and Pittsburgh Railroad
LOCATION: South Buffalo Township
Armstrong County
INSPECTION DATE: April 27, 2011
INSPECTION BY: Senate Engineering Company
Nathan Guntrum, C.B.I.
Mathew Pitsch, E.I.T.
PREPARED FOR: Armstrong County
Via
Pennsylvania Department
of Transportation District 10-0
PREPARED BY: Senate Engineering Company
Written by: N. Guntrum, CBI
Reviewed by: W.F.Braun, P.E.
Phone no. (412) 826-5454
OWNER OF BRIDGE: BUFFALO AND PITTSBURGH RAILROAD/SOUTH BUFFALO
TOWNSHIP
BRIDGE POSTING: 10 TONS

PA PUBLIC UTILITY COMMISSION

JUN 02 2011

BUREAU OF TRANSPORTATION SAFETY
RAIL SAFETY DIVISION



5-18-11

WILLIAM F. BRAUN P.E.

SECRETARY'S BUREAU
PA P.U.C.

2011 JUN -3 PM 2:59

RECEIVED

SOUTH BUFFALO TOWNSHIP BRIDGE #3 OVER BUFFALO AND
PITTSBURGH RAILROAD NORTH CLINTON

TABLE OF CONTENTS

LOCATION MAP	3
GENERAL INFORMATION	4
FIELD INSPECTION RESULTS	5
LOAD RATINGS	6
CONCLUSIONS AND RECOMMENDATIONS	7
PHOTOGRAPHS	8
PLAN, ELEVATION, SECTION	
FORM A	SITE DATA
FORM B	DECK AND SUPERSTRUCTURE DATA
FORM C	ABUTMENT DATA
FORM D	PIER DATA
FORM E	ELEMENT DATA
FORM F	FRACTURE CRITICAL
FORM G	UNDERWATER INSPECTION
FORM H	CULVERT DATA
FORM J	CHANNEL AND WATERWAY DATA
FORM K	PAINT, STRUCTURE APPRAISAL AND LOAD RATINGS
FORM M	MAINTENANCE NEEDS DATA
FORM P	INSPECTION ADMINISTRATION

SOUTH BUFFALO TOWNSHIP BRIDGE #3 OVER BUFFALO AND PITTSBURGH RAILROAD NORTH CLINTON

LOCATION MAP

SOUTH BUFFALO TOWNSHIP, ARMSTRONG COUNTY




Figure 1 SOUTH BUFFALO TOWNSHIP BRIDGE #3 CARRIES T-881 (CLINTON ROAD) OVER
BUFFALO AND PITTSBURGH RAILROAD

SOUTH BUFFALO TOWNSHIP BRIDGE #3 OVER BUFFALO AND PITTSBURGH RAILROAD NORTH CLINTON

GENERAL INFORMATION

PURPOSE OF REPORT

The preparation of this bridge Inspection and analysis report was authorized by the Armstrong county commissioners for the purpose of performing an inspection to establish the present physical condition of the structure and to use these findings to perform a complete bridge rating analysis. The inspection was performed in accordance with the 1990 AASHTO "manual of Maintenance Inspection of Bridges," the 1993 AASHTO "Standard Specifications for Highway Bridges" including the interim specifications, and "National Bridge Inspection Standards" (Title 23), Code of Federal Regulations, Part 650-307, "Qualification of Personnel" along with the Bureau of Design, BMS2, Coding Manual, Publication 100A. An outline of recommended maintenance, repair and reconstruction needs are identified as part of the "Conclusions and Recommendations" section of this report in order to promote the extended service life of this bridge.

BRIDGE DESCRIPTION

Township Bridge No. 3 carries T-881 over Buffalo and Pittsburgh Railroad in South Buffalo Township, Armstrong County. The deck comprised of 2 x 4 lumber on edge, placed a 45 degree angle with a 3" bituminous wearing surface. The laminated deck is supported by wooden timbers (8" x 15.5") placed at 21" on center. The timber beams are supported by 4 timber bents and 2 timber abutments. The railing consists of 6" x 6" timber posts and treated 2 x 6 side rails. The structure length is 113'-8" and the clear distance between the deck railing is 19'-6" and curb to curb is 18'-6". This bridge was built in 1910.

POSTING

10 TONS

INSPECTION DATE AND PERSONNEL

Nathan Guntrum, C.B.I. and Matthew Pitsch, E.I.T. inspected bridge #3 April 27, 2011.

SOUTH BUFFALO TOWNSHIP BRIDGE #3 OVER BUFFALO AND PITTSBURGH RAILROAD NORTH CLINTON

FIELD INSPECTION RESULTS

GENERAL

CONDITION RATINGS ARE USED IN THIS REPORT TO DESCRIBE THE EXISTING, IN-PLACE BRIDGE AS COMPARED TO THE AS-BUILT CONDITION.

Condition codes provide an overall characterization of the general condition of the entire component being rated. Assignment of a condition code must, therefore, consider both the severity of the deterioration or disrepair and the extent to which it is widespread throughout the component being rated. The load-carrying capacity is not used in evaluating condition items.

The determination as to which of the ratings apply to each of the items will be based on an evaluation of all relevant factors and information that are included in the report. The rating chosen for each of these items will be a composite of all of the relevant factors. It should be recognized that this will require judgment, particularly for those items where the ratings seem not to apply.

The bituminous approach roadway has medium tire abrasion and wheel rutting, randomly with random longitudinal and transverse cracking. The near and far approaches are sunken slightly at the abutments. There is a large bituminous cold patch area at the near abutment right and center. The deck consists of a 3" thick bituminous overlay on top of a 2 x 4 laminated timber deck. There are medium sized bumps above the piers, several areas of heavy transverse and map cracking (w/potholes starting.) There are random longitudinal cracks, a 2' diameter cold patch area @ midspan #3 right side. There is moderate to heavy water leakage and staining with random splitting and cracking.

In span 1 there are 10 solid beams with random cracking and splitting with areas of moderate water staining and medium deterioration areas. There are medium hairline to 1/8" longitudinal shear cracks at neutral axis @ left and right sides with the tops displaced towards right side. The tops of all beams are rotating towards the right 5/8".

SOUTH BUFFALO TOWNSHIP BRIDGE #3 OVER BUFFALO AND PITTSBURGH RAILROAD NORTH CLINTON

In spans 2-4 there are 10 timber beams in each span. Random beams have longitudinal shear cracks along the neutral axis with the tops rotating. There is moderate decay at the near side ends of beams 1,2,3,8,9,10. Span 3 has 3/8" longitudinal cracks at near and far underside of beam 10 of span 2. There are 1/4" longitudinal cracks at near underside of beam 1 at span 2. There is a 1/4" longitudinal crack at the far underside of beam 1 at span 3. There is a 1/4" longitudinal crack at nearside of beam 10 at span 3.

In span 5 there are 10 timber beams with the tops rotating towards the left 1/2". The beams at the far abutment are pushing the backwall ahead. The entire structure is migrating and twisting. Many beams are in the early stages of crushing (ends of many beams are crushing up to 3/16" at bearing areas.

The near timber abutment back wall has random splitting and cracking with deterioration and decay with the top 2 timbers on the right side are loose. The far timber abutment back wall has random splitting and cracking with deterioration and decay with the top 2 timbers on the left side are loose.

LOAD RATING SUMMARY

LOAD RATING TABLE

LOAD CASE	INVENTORY RATING (TONS)	OPERATING RATING (TONS)
H20	8	10
HS20	8	10
ML80	8	10

SOUTH BUFFALO TOWNSHIP BRIDGE #3 OVER BUFFALO AND PITTSBURGH RAILROAD NORTH CLINTON

CONCLUSIONS AND RECOMMENDATIONS

The overall condition of the bridge is poor, based on the condition ratings. Therefore, we only have a few recommendations to make at this time.

0) CRITICAL (WITHIN 7 DAYS)

NONE

1) HIGH PRIORITY (WITHIN 6 MONTHS)

RECONNECT GUIDERAIL TO BRIDGE

REPAIR RAILING

2) PRIORITY (RE-PRIORITIZE SCHEDULE)

REPAIR/REPLACE TIMBERS

REPAIR ABUTMENT/BACKWALL

REPAIR TIMBER DECK

REPAIR PIERS (SEE FORM D)

3) SCHEDULE (ADD TO SCHEDULED WORK)

REPAIR BIT. WEARING SURFACE

4) PROGRAM (ADD TO PROGRAMMED WORK WHEN FUNDS ARE AVAILIABLE)

5) ROUTINE (WITHIN NEXT WORK CYCLE)

SOUTH BUFFALO TOWNSHIP BRIDGE #3 OVER BUFFALO AND
PITTSBURGH RAILROAD NORTH CLINTON




PHOTO 1 NEAR APPROACH/TYPICAL WEARING SURFACE




PHOTO 2 FAR APPROACH

SOUTH BUFFALO TOWNSHIP BRIDGE #3 OVER BUFFALO AND
PITTSBURGH RAILROAD NORTH CLINTON




PHOTO 3 TYPICAL WEARING SURFACE LOOKING TOWARDS NEAR



PHOTO 4 LEFT ELEVATION

SOUTH BUFFALO TOWNSHIP BRIDGE #3 OVER BUFFALO AND
PITTSBURGH RAILROAD NORTH CLINTON



PHOTO 5 RIGHT ELEVATION




PHOTO 6 LOOKING NORTHEAST

SOUTH BUFFALO TOWNSHIP BRIDGE #3 OVER BUFFALO AND
PITTSBURGH RAILROAD NORTH CLINTON



PHOTO 7 LOOKING SOUTHWEST




PHOTO 8 NEAR ABUTMENT

SOUTH BUFFALO TOWNSHIP BRIDGE #3 OVER BUFFALO AND
PITTSBURGH RAILROAD NORTH CLINTON




PHOTO 9 FAR ABUTMENT




PHOTO 10 TYPICAL SUPERSTRUCTURE

SOUTH BUFFALO TOWNSHIP BRIDGE #3 OVER BUFFALO AND
PITTSBURGH RAILROAD NORTH CLINTON




PHOTO 11 HOLE AT NEAR RIGHT






PHOTO 12 HOLE IN FAR RIGHT WEARING SURFACE




PLAN VIEW



LEFT ELEVATION

<p>NORTH CLINTON BRIDGE BMS # 03 7223 0881 0003</p>		<p>SENATE ENGINEERING COMPANY ENGINEERS - PLANNERS - SURVEYORS UNIVERSITY OF PITTSBURGH APPLIED RESEARCH CENTER 420 WILLIAM PITT WAY, PITTSBURGH, PA. 15238 PHONE (412) 826-5454 FAX (412) 826-5458</p>		
<p>SITUATE IN: SOUTH BUFFALO TOWNSHIP ARMSTRONG COUNTY, PA</p>		<p>DRAWN BY: N.G. CHECKED BY: DATE: 5/18/11 SCALE:</p>		
<p>PREPARED FOR: PA DEPT. OF TRANSPORTATION ENGINEERING DISTRICT 10-0</p>		<p>JOB NUMBER 9245</p>	<p>DRAWING NUMBER</p>	
		<p>_____ OF _____</p>		



SECTION A-A

<p>NORTH CLINTON BRIDGE BMS # 03 7223 0881 0003</p>	<p>SENATE ENGINEERING COMPANY ENGINEERS — PLANNERS — SURVEYORS UNIVERSITY OF PITTSBURGH APPLIED RESEARCH CENTER 420 WILLIAM PITT WAY, PITTSBURGH, PA. 15238 PHONE (412) 826-5454 FAX (412) 826-5458</p>			
<p>SITUATE IN: SOUTH BUFFALO TOWNSHIP ARMSTRONG COUNTY, PA</p>	<p>DRAWN BY: N.G.</p>	<p>CHECKED BY:</p>	<p>DATE: 5/18/11</p>	<p>SCALE:</p>
<p>PREPARED FOR: PA DEPT. OF TRANSPORTATION ENGINEERING DISTRICT 10-0</p>	<p>JOB NUMBER 9245</p>	<p>DRAWING NUMBER</p>		<p>_____ OF _____</p>



5A01 SR ID: 03722308810003 **5A03** BR Key: 3298 **7A01** Inspection Date: April 27, 2011

7A09 Inspection Status: 2 - Submitted
7A02 Team Leader: 1685 Senate Engineering C Guntrum
7A03 Inspection Type: R - Regular (routine)
7A05 Inspected By: 8 - Consulting Firm

Structure Description

5A08 FHWA Facility Carried: T-881
5A07 Features Intersected: BUFFALO & PITTSBURG RR
5A09 Location: TWP #3 NORTH CLINTON RR
5C01 Roadway Name: T-881
5A06 City / Borough Name: 03/223 - SOUTH BUFFALO

Structure Type

Main

6A26 Material Makeup: 5 - Timber
6A27 Physical Makeup: 9 - Other or none
6A28 Span Interaction: 1 - Simple, non-comp
6A29 Structural Config: 36 - Solid timber beams

Approach

6A26 Material Makeup:
6A27 Physical Makeup:
6A28 Span Interaction:
6A29 Structural Config:



5A01 SR ID: 03722308810003 **5A03** BR Key: 3298 **7A01** Inspection Date: April 27, 2011

Sign Information

Type of Sign	ID01	ID02	ID03	ID06	ID04	ID07	ID05	Comments
	Sign Needed	Sign Message	Near Adv	Bridge Site Near	Far	Far Adv		
0 - Bridge	Yes			G	G	G	G	
1 - Bridge Weight Limit	Yes 10			G	G	G	G	
2 - Except Combinations	No	N/A						-
3 - One Truck at a Time	No							-
4 - Vertical Clearance On	No							-
5 - Vertical Clearance Under	No							-
6 - One Lane Bridge	Yes			G	N	N	G	-
7 - Narrow Bridge	No							-
8 - Hazardous Clearance	Yes			N	G	G	N	-
9 - Other	Yes			G	N	N	G	BRIDGE MAY BE ICY

Features Intersected

6C02	5C03	5B09	5C06	5C29	4A20	4A19	6C18	6C19	6C20	6C21	6C22	6C23	6C24	6B17
SR ID	On/	Skew		NHS	Min Lat Cl	Tot Hor Cl	Min Vrt Cl	Rdwys	Vrt Cl Over 10ft	VT				
SR	Seg	Under	Angle	Dir	Left	Right	Left	Right	Left	Right	Left	Right	Sign	ADT
-	-	1	45		0.0	28.2	-1.0	18.3	-1.0	99.9	-1.0	-1.0	0	0
-	-	A	0	N/A	0.0	28.2	-1.0	-1.0	-1.0	20.6	-1.0	-1.0	0	0



A01 SR ID: 03722308810003 **5A03** BR Key: 3298 **7A01** Inspection Date: April 27, 2011

- 6B15** Design Exceptions:
- 6A50** Sup Latent Problem: _
- 6A51** Sub Latent Problem: _

Deck Geometry

Table Used for Appraisal: 1 - 2A/2B

Controlling Values

- 5C10** ADT:
- 5C27** Bridge Road Width: 18.3
- 4A10** Appraisal: 3 - Intolerable-Correct
- Notes:

- 4A11** Underclr Appr: 4 - Tolerable
- 6B13** Controlling Vertical: 21.1 FT
- Controlling Lateral: LAT = 8'-6" = (4)

Traffic Safety Features

Feature Type	Location	Adequacy Rating	Description	Posted Spd Lmt (mph)
1 - Railing		3 - inadeq for cond		-1
Comment: TIMBER POSTS W/ TIMBER RAILS, SOME TIMBERS HAVE BEEN REPAIRED & REPLACED, MANY POSTS & PLANKS HAVE MED CRACKING & ROTTING AREAS, MANY POSTS @ F LT END ARE LOOSE & LEANING TO LT 2" +/-, MANY POSTS @ N RT END ARE LOOSE & LEANING TO RT 1" +/-				
2 - Transition		2 - Req not provided		-1
Comment: NONE @ ALL ENDS				
3 - Approach Guiderail		2 - Req not provided		-1
Comment: NONE @ ALL ENDS				
4 - Approach railend		2 - Req not provided		-1
Comment: NONE @ ALL ENDS				

Approach Alignment

- 4A02** Code: 5 - Above Tolerable
- Comment: LIMITED SIGHT DIST MINOR SPEED REDUCTION (VERT CURVE)

Approach Roadway

- 6B39** Code: 6 - Satisfactory
- Pavement: BIT = MED TIRE ABRASION & WHEEL RUTTING, RANDOM LONGIT & TRANSV CRACKS, NS/FS APPROACHES ARE SUNKEN SLIGHTLY @ NAB & FAB AREAS, LARGE BIT COLD PATCH AREA @ NAB RT & CTR,
- Drainage: SATIS
- Shoulders: GRAVEL = SATIS COND, MINOR AREAS SUNKEN SLIGHTLY

Approach Slab

- 6B38** Code: N - N/A
- Pavement: NONE



A01 SR ID: 03722308810003 **5A03** BR Key: 3298 **7A01** Inspection Date: April 27, 2011

6B04 Bump at Bridge: Bump MINOR TO MED BUMPS @ NAB,P01,P02,P03,P04,FAB, NS/FS APPROACHES ARE SUNKEN
SLIGHTLY @ NAB & FAB AREAS, LARGE BIT COLD PATCH AREA @ NAB RT & CTR,

6A39 Relief Joints: 0 - Joints not present **6A41** Number of Joints: 0
Comment: NONE

6B02 New Wearing Surface Under Bridge: No

5A01

SR ID: 03722308810003

5A03

BR Key: 3298

7A01

Inspection Date: April 27, 2011

Deck Wearing Surface

Main

5B02 Type of Wearing Surface: 6 - Bituminous
 5B03 Type of Memb. Water-Proof: 0 - None
 5B04 Deck Corrosion Protection: 0 - None
 6A33 Thickness: 3.0
 6A34 Date Recorded: 01/01/1901

Approach

6A30 Type of Wearing Surface: - Unknown (NBI)
 6A31 Type of Memb. Water-Proof: - Unknown (NBI)
 6A32 Deck Corrosion Protection: - Unknown (NBI)
 6A33 Thickness: 0.0
 6A34 Date Recorded: 01/01/1901

6B40 Condition Rating: 4 - Poor-adv. section loss, deterioration, spalling or scour.
 IC02 Dk WS Notes: 3" BIT OVERLAY OF 2"x4" LAMINATED TIMBER DECK = MED TIRE ABRASION & MOD WHEEL RUTTING, HEAVY 1/4"+ DIAG & TRANSV CRACKS, MED BUMPS ABOVE PIERS, SEVERAL AREAS OF HEAVY TRANSV & MAP CRACKS W/ POTHOLES STARTING, RANDOM LONGIT CRACKS, 2' DIA COLD PATCH AREA @ MIDSPAN #3 RT SIDE, ***5'x5' CRACKED / POTHOLES AREAS FORMING @ LT/RT SIDES - MIDSPAN #3, 1' DIA COLD PATCH AREA @ FS SPAN #4 - RT SIDE,

Expansion Joints

6A41 Number of Expansion Joints: 0

Joint Number	VD25 Joint Type	VD26 Movement Class	VD27 Manufacture Code
0			

Deck

1A01 Condition Rating: 4 - Poor-advanced section loss, deterioration, spalling or scour.
 1A07 Est. Spall Delamination: 0.00 %
 1A10 Est. Chloride Content: 0.00 %
 1A07 Unrepaired Spalls: -1.00 SF

6B08 Date: 01/01/1901
 6B11 Date: 01/01/1901

Deck Top: 3" BIT OVERLAY OF 2"x4" LAMINATED TIMBER DECK = MED TIRE ABRASION & MOD WHEEL RUTTING, HEAVY 1/4"+ DIAG & TRANSV CRACKS, MED BUMPS ABOVE PIERS, SEVERAL AREAS OF HEAVY TRANSV & MAP CRACKS W/ POTHOLES STARTING, RANDOM LONGIT CRACKS, 2' DIA COLD PATCH AREA @ MIDSPAN #3 RT SIDE, ***5'x5' CRACKED / POTHOLES AREAS FORMING @ LT/RT SIDES - MIDSPAN #3, 1' DIA COLD PATCH AREA @ FS SPAN #4 - RT SIDE,

Deck Underside: LAMINATED 2"x4" TIMBER DECK = FAIR COND, MOD TO HEAVY WATER LEAKAGE & STAINING, RANDOM SPLITTING & CRACKING, MED DET & DECAY AREAS, MANY DECAY / DET AREAS NOTED @ ENDS OF TIMBERS, ***LT/RT ENDS OF 2"x4" LAMINATED TIMBERS ARE LIFTING 1/4" + UP FROM TOP SIDES OF BMS # 1 & 10 @ ALL SPANS DUE TO WHEEL RUTTING & BENDING OF DECK TIMBERS BETW BMS,

Deck Drainage: NONE
 Expansion Joints: NONE

Deck Notes:

Superstructure

1A04 Condition Rating: 4 - Poor-adv. section loss, deterioration, spalling or scour.
 Narrative: ****UTILITY PIPES RESTING ON LT & RT TOP ENDS OF PIER CAPS



5A01

SR ID: 03722308810003

5A03

BR Key: 3298

7A01

Inspection Date: April 27, 2011

Girders/Beams: (10) SOLID TIMBER BMS . (5) SPANS 119', 59136, (TYP) = MED HL TO 1/8" LONGIT "SHEAR" CRACKS @ NEUTRAL AXIS @ LT & RT SIDES W/ TOPS DISPLACED , RANDOM VERT CRACKS NOTED @ END SIDES OF BMS # P01, P02, P03, P04 BEARING AREAS , ***RANDOM BMS ARE CRUSHING 1/8" TO 1/4" @ VISIBLE @ FACE OF BRIDGE SEATS (BEARING AREAS) OF ALL SPANS, TYP BM DEPTH = 16", RANDOM 1/8" LONGIT CRACKS @ UNDERSIDES OF BMS,

***SPAN #1 (10) SOLID TIMBER BMS = RANDOM CRACKING & SPLITTING AREAS W/ MOD WATER STAINING & MED DET AREAS, MED HL TO 1/8" LONGIT "SHEAR" CRACKS @ NEUTRAL AXIS @ LT & RT SIDES W/ TOPS DISPLACED TOWARD RT SIDE, = **TOPS OF ALL BMS ARE ROTATING TO Rt. 5/8" +/- , MEAS USING 4' LEVEL,

SPANS #2,3,4 (10) TIMBER BMS IN EA SPAN = ***RANDOM BMS HAVE LONGIT SHEAR CRACKS ALONG NEUTRAL AXIS W/ TOPS ROTATING, INSPECTED FROM GROUND, *MOD DECAY @ NS ENDS OF BMS #1,2,3,8,9,10 @ SPAN#3, **3/8" LONGIT CRACKS @ NS/FS UNDERSIDE OF BM #10 @ SPAN#2, **1/4" LONGIT CRACK @ NS UNDERSIDE OF BM #1 @ SPAN#2, **1/4" LONGIT CRACK @ FS UNDERSIDE OF BM #1 @ SPAN#3, **1/4" LONGIT CRACK @ NS UNDERSIDE OF BM #10 @ SPAN#3,

SPAN #5 = (10) TIMBER BMS. , **TYP TO SPAN #1 EXCEPT TOPS ARE ROTATING TOWARD LT 1/2" +/- MEAS. USING A LEVEL, ***BMS. @ FAB ARE PUSHING BACKWALL SEG AHEAD, ***ENTIRE STRUCTURE IS MIGRATING & TWISTING, **TYP ALL SPANS = MANY BMS ARE IN EARLY STAGES OF CRUSHING, (ENDS OF MANY BMS ARE CRUSHING UP TO 3/16") @ BEARING AREAS

Floorbeams: NONE

Stringers: NONE

Diaphragms: NONE

Truss Members: NONE

Portals/Bracings: NONE

Bearings: BEARINGS = TIMBER = MED CRACKING & SPLITTING & MOD DECAY AREAS

Drainage System: NONE



A01

SR ID: 03722308810003

5A03

BR Key: 3298

7A01

Inspection Date: April 27, 2011

1A02

Substructure Condition Rating: 4 - Poor-ad. section loss, deterioration, spalling or scour.

Notes:

Near Abutment

Backwall: TIMBER = RANDOM SPLITTING & CRACKING W/ DETERIORATION & DECAY, TOP (2) TIMBERS IN BACK WALL ARE LOOSE @ TOP RT SIDE

Bridge Seats: TIMBER = RANDOM SPLITTING & CRACKING W/ DETERIORATION & DECAY,

Cheekwalls: NONE

Stem: (4) TIMBER BENTS W/ TIMBER BACKWALLS = RANDOM SPLITTING & CRACKING W/ DETERIORATION & DECAY, ALL BENTS ARE LEANING SEG. AHEAD, FOLLOWING MEASUREMENTS TAKEN WITH 4' LEVEL AT TOP OF BENTS= #1= 6-1/8", #2= 5", #3 = 4", #4 = 3", #5 = 2-3/8"

Wings: TIMBER = RANDOM SPLITTING & CRACKING W/ DETERIORATION & DECAY

Footing: NOT VISIBLE

Piles: NONE

IN20

Scour Undermine: 0 - No

Settlement: ALL BENTS ARE LEANING SEGEMENT AHEAD

Embank Slope-wall: SOIL, MINOR EROSION AREAS @ LT & CTR

Wall Drainage: NOT VISIBLE

Far Abutment

Backwall: TIMBER = BEAMS FROM SUPER STR. ARE PUSHING DIRECTLY BACK ON THE BACK WALL, TOP (2) TIMBERS IN BACK WALL ARE LOOSE @ TOP LT SIDE, RANDOM SPLITTING & CRACKING W/ DETERIORATION & DECAY,

Bridge Seats: TIMBER = RANDOM SPLITTING & CRACKING W/ DETERIORATION & DECAY,

Cheekwalls: NONE

Stem: (5) TIMBER BENTS W/ TIMBER BACKWALLS = RANDOM SPLITTING & CRACKING W/ DETERIORATION & DECAY, BENTS # 2,3,4,5, ARE LEANING SEG. BACK, FOLLOWING MEASUREMENTS WERE TAKEN WITH 4' LEVEL AT TOP OF BENTS-- #2 = 1-1/2", #3 = 3-1/2", #4 = 3-1/4", #5 = 5-1/2", TOP OF BENT #1 IS LEANING 1-3/8" SEG AHEAD

Wings: TIMBER = RANDOM SPLITTING & CRACKING W/ DETERIORATION & DECAY, RANDOM LOOSE TIMBERS

Footing: NOT VISIBLE

Piles: NONE

IN20

Scour Undermine: 0 - No

Settlement: BENTS # 2,3,4,5, ARE LEANING SEG. BACK, #1 IS LEANING SEG AHEAD

Embank Slope-wall: SOIL, MED EROSION AREAS @ RT & CTR

Wall Drainage: NONE VISIBLE



1A01

SR ID: 03722308810003

5A03

BR Key: 3298

7A01

Inspection Date: April 27, 2011

Navigational Control

4A21

Controls Exist: Unknown

4A22

Vert Clearance: 0.00

4A24

Lift Vertical: -1.00

4A23

Horz Clearance: -1.00

4A07

Pier Protection: Not Applicable (N)

5A01

SR ID: 03722308810003

5A03

BR Key: 3298

7A01

Inspection Date: April 27, 2011

Pier Details

5D02

Pier/Bent Number: P01

IN20

Scour Undermine: No

Condition Summary:

Bridge Seats: HORIZ. TIMBER BEAM = MED WEATHERING & CRACKING & SPLITTING, MINOR BENDING UNDER BMS IS NOTED, MED DECAY @ LT/RT ENDS OF TIMBER

Cheekwalls: NONE

Columns/Stems: (5) VERT. TIMBER COLUMNS WITH (2) DIAGONAL TIMBER "X" BRACES = P01 COLUMNS BENTS # 1,2,3 ARE LEANING SEG. AHEAD, FOLLOWING MEASUREMENTS WERE TAKEN WITH 4' LEVEL AT TOP OF BENTS-- #1 = 1-1/4", #2 = 7/8", #3 = 1", #4 = 0", TIMBER X-BRACING FROM P01 TO P02 IS WEATHERED & CRACKING, TIMBER X-BRACING FROM P01 TO P02 IS BENT TO RT @ RT SIDE, RANDOM SPLITTING & CRACKING W/ DETERIORATION & DECAY, MED DECAY TO BASE TIMBER (FOOTER TIMBER)

Settlement: P01 LEANING SEG. AHEAD 1-1/4" @ LT SIDE

5D02

Pier/Bent Number: P02

IN20

Scour Undermine: No

Condition Summary:

Bridge Seats: HORIZ. TIMBER BEAM = MED WEATHERING & CRACKING & SPLITTING, MINOR BENDING UNDER BMS IS NOTED, MED DECAY @ LT/RT ENDS OF TIMBER

Cheekwalls: NONE

Columns/Stems: (5) VERT. TIMBER COLUMNS WITH (2) DIAGONAL TIMBER "X" BRACES = P01 COLUMNS BENTS # 1,2 ARE LEANING SEG. AHEAD, FOLLOWING MEASUREMENTS WERE TAKEN WITH 4' LEVEL AT TOP OF BENTS-- #1 = 3/8", #2 = 0", COL #5 IS LEANING SEG BACK @ TOP = 1/4" W/ 4' LEVEL, RANDOM SPLITTING & CRACKING W/ DETERIORATION & DECAY, MED DECAY TO BASE TIMBER (FOOTER TIMBER), TIMBER X-BRACING FROM P01 TO P02 IS WEATHERED AND CRACKING,

Settlement: NONE

5D02

Pier/Bent Number: P03

IN20

Scour Undermine: No

Condition Summary:

Bridge Seats: HORIZ. TIMBER BEAM = MED WEATHERING & CRACKING & SPLITTING, MINOR BENDING UNDER BMS IS NOTED, 1/4" + TRANSV SHEAR CRACKS @ N RT END & @ UNDERSIDE OF RT END, MED DECAY @ LT/RT ENDS OF TIMBER

Cheekwalls: NONE

Columns/Stems: (5) VERT. TIMBER COLUMNS WITH (2) DIAGONAL TIMBER "X" BRACES = TOPS OF COLUMNS BENTS # 1,2,3,4, ARE LEANING SEG. AHEAD, FOLLOWING MEASUREMENTS WERE TAKEN WITH 4' LEVEL @ TOP OF BENTS -- #1 = 1", #2 = 5/8", #3 = 1", #4 = 1/2", RANDOM SPLITTING & CRACKING W/ DETERIORATION & DECAY, MED DECAY TO BASE TIMBER (FOOTER TIMBER), TIMBER X-BRACING FROM P03 TO P04 IS WEATHERED AND CRACKING

Settlement: TOP OF P03 IS LEANING SEG AHEAD

5D02

Pier/Bent Number: P04

IN20

Scour Undermine: No

Condition Summary:

Bridge Seats: HORIZ. TIMBER BEAM = MED WEATHERING & CRACKING & SPLITTING, MINOR BENDING UNDER BMS IS NOTED, 1/4" + TRANSV SHEAR CRACKS @ UNDERSIDE OF LT/RT ENDS, MED DECAY @ LT/RT ENDS OF TIMBER

Cheekwalls: NONE

Columns/Stems: (5) VERT. TIMBER COLUMNS WITH (2) DIAGONAL TIMBER "X" BRACES = TOPS OF COLUMNS BENTS # 3,4,5, ARE LEANING SEG. BACK, FOLLOWING MEASUREMENTS WERE TAKEN WITH 4' LEVEL AT TOP OF BENTS -- #3 = 1/2", #4 = 3/4", #5 = 1", TOP OF BENT #1 IS LEANING 5/8" SEG AHEAD, BENT #2 IS PLUMB, RANDOM SPLITTING & CRACKING W/ DETERIORATION & DECAY, MED DECAY TO BASE TIMBER (FOOTER TIMBER), TIMBER X-BRACING FROM P03 TO P04 IS WEATHERED AND CRACKING

Settlement: TOP OF P04 IS LEANING SEG. BACK @ RT SIDE & SEG AHEAD @ LT SIDE (TWISTING)



5A01 SR ID: 03722308810003 **5A03** BR Key: 3298 **7A01** Inspection Date: April 27, 2011

6B03 Inventory Item Review Recommended: No

IC01 Notes:

Element Details

5D02 Span: Overall Structure

5D04 Span Type: F - Frame

1B01 Element ID: 999 - Dummy Element

Inspect by Each: Yes

1B03 Environment: Ben.

1B05 Scale Factor Measurement: 1

Description: Dummy placeholder element

1A10 Total QTY: 1.00 each

1A11 Cond State 1 QTY: 1.00

1A11 Cond State 2 QTY: 0.00

1A11 Cond State 3 QTY: 0.00

1A11 Cond State 4 QTY: 0.00

1A11 Cond State 5 QTY: 0.00

Condition:



5A01

SR ID: 03722308810003

5A03

BR Key: 3298

7A01

Inspection Date: April 27, 2011

Main

6A44

Group: 9 - Group 9

6A45 - 6A48

Critical Rating Factor: 9993

6A49

Total Critical Rating Factor: 30

Structure Type (Dept)

6A26

Material Makeup: 5 - Timber

6A27

Physical Makeup: 9 - Other or none

6A28

Span Interaction: 1 - Simple, non-comp

6A29

Structural Config: 36 - Solid timber beams

Approach

6A44

Group:

6A45 - 6A48

Critical Rating Factor: 000

6A49

Total Critical Rating Factor: 0

Structure Type (Dept)

6A26

Material Makeup:

6A27

Physical Makeup:

6A28

Span Interaction:

6A29

Structural Config:

Fracture Critical Details

IF01

Location:

IF02

Type:

IF05

FC Stress Category:

IF03

Member:

IF04

Member Detail:

IF06

Notes:



A01

SR ID: 03722308810003

5A03

BR Key: 3298

7A01

Inspection Date: April 27, 2011

IU00a

UW Reviewer Action:

IU00b

Reviewer Comments:

IU02

Number of Units: 0

IU01

Recalculate SCBI: 1 - recalc needed

IU03

SCBI Source:

4A08

SCBI: N - Not Over Waterway

IU04

Overall SCBI:

IU05

SAR: 0.00

IU06

Streambed Material #1:

IU06

Streambed Material #2:

IU07

Notes:

Current Countermeasures

CM Num	Type	Location	Condition	Subunit	
		IU21	IU22	IU23	IU24

Possible Countermeasures

PCM Num	Location	Work Candidate
	IU25	IU26

SAR Calculation Data

IU08

Debris Potential:

IU09

Trapping Potential:

IU10

Pressure Flow:

IU11

NAB Location:

IU12

FAB Location:

US Left Wingwall

IU13

Presence:

IU14

Condition:

US Right Wingwall

IU15

Presence:

IU16

Condition:

Horizontal Debris Blockage

IU17

Start: 0

IU18

End: 0

Vertical Debris Blockage

IU19

Start: 0

IU20

End: 0



101

SR ID: 03722308810003

5A03

BR Key: 3298

7A01

Inspection Date: April 27, 2011

Sub Unit OSA Data

Observed Scour Rating Components

IN01	IN12	IN13	IN14	IN15	IN19	IN04	IN05	IN06	IN07	IN08	IN09	IN10	IN11	IN03
Sub Unit	Pier/ Abut Type	Inv. Found Type	Found Type	Strmbd Mat	Move Ind	Chg Since Last Insp	Scour Hole	Debris Potential	Scour-ability	Opening Adeq. / Channel	Sediment	Alignment	Velocity/ Stream Slope	Observed Scour Rating
NAB					0									
FAB					0									
P01					0									
P02					0									
P03					0									
P04					0									

Other Subunit Details

IN01	IN16	IN18	IN17	IN20	IN21	IN02	IN22	IN23	IU27	
Sub Unit	UW Insp Type	Water Dept	Observed Scour Depth	Scour Undermine	Counter-measures	Info from Current Insp	100 yr Flood Calc Scour Depth	500 yr Flood Calc Scour Depth	SCBI Code	
NAB		-1.0	-1.0	0	0	0	0.0	0.0		
	4	Notes:								
FAB		-1.0	-1.0	0	0	0	0.0	0.0		
	IN24	Notes:								
P01		-1.0	-1.0	0	0	0	0.0	0.0		
	IN24	Notes:								
P02		-1.0	-1.0	0	0	0	0.0	0.0		
	IN24	Notes:								
P03		-1.0	-1.0	0	0	0	0.0	0.0		
	IN24	Notes:								
P04		-1.0	-1.0	0	0	0	0.0	0.0		
	IN24	Notes:								



A01

SR ID: 03722308810003

5A03

BR Key: 3298

7A01

Inspection Date: April 27, 2011

Underclearance

IL09

Origin Description:

IL10

Horizontal:

IL11

Vertical:

IL12

Notes:



5A01

SR ID: 03722308810003

5A03

BR Key: 3298

7A01

Inspection Date: April 27, 2011

1A03

Culvert Condition Rating: N

Notes:

VD19

Length of Culvert Barrel: -1.00 FT

#	Opening Type	Length	Min Fill Height	Max Fill Height	Eff Width
---	--------------	--------	-----------------	-----------------	-----------

Top Slab:

Barrel:

Floor/Paving:

Headwall:

Wings:

Settlement:

Debris:



5A01

SR ID: 03722308810003

5A03

BR Key: 3298

7A01

Inspection Date: April 27, 2011

Channel

1A05

Channel/ Channel Protection Cond. Rating: N

Channel:

Banks:

Streambed Movements:

Debris, Vegetation:

River Control Devices:

Embank/Streambed Contr:

Drift Other:

Waterway Adequacy

1A06

Appraisal Code: N

Notes:

IL02

Overtop Risk:

IL03

Traffic Delay:

5C22

Functional Class: 09 - Rural Local

High Water Mark

IL05

Elevation: 0.0

IL06

Date: January 01, 1901

IL07

New High Water Mark: No

Notes:



5A01

SR ID: 03722308810003

5A03

BR Key: 3298

7A01

Inspection Date: April 27, 2011

Paint Condition

6B36 Paint Cond Rating: N - Not Applicable

6B37 Ext of Paint Cond: N - Not Applicable

6B35 New Paint: 0 -no new paint

Int Beam / Gird: N/A

Fascias: N/A

Splsh Zone Truss Gird: N/A

Truss: N/A

Bearings: N/A

Other: N/A

4B03 Brdge Cap. Appraisal: 0 - >39.9% below

6B16 Controlling: 5 - Eng. Judg.

4A09 Struct Cond Appraisal: 4

Structure Condition Appraisal Based on

The following Ratings:

1A04 Superstructure Condition R 4 - Poor-adv. section loss, deterioration, s

1A02 Substructure Condition Rating: 4 - Poor-ad. section loss, deterioration, sp

1A03 Culvert Rating: N - Not applicable

Load Ratings

4R15 Load Rating Review Recommended: Recalc not required

Due To:

IR03 Calculation Date: June 07, 2006

IR02 Rating Approval Date: February 25, 2008

Load Rating Details

	IR10	IR11	IR05	IR06	IR07	IR16	IR14	IR15	IR13	IR12
LOAD TYPE	IR LOAD	OR LOAD	NBI IND	RTNG ANAL METH	CONT MEM TYPE	ANALYSIS ENGINEER	AASHTO MANUAL YEAR	AASHTO SPEC YEAR	OPR GOV CRITERIA	INV GOV CRITERIA
1	8	10	0	7	-		1983	1984		
Notes Description:										
2	8	10	1	7	-		1983	1984		
Notes Description:										
8	8	10	0	7	-		1983	1984		
Notes Description:										



01 SR ID: 03722308810003 **5A03** BR Key: 3298 **7A01** Inspection Date: April 27, 2011

IM01	IM03	IM04	IM05	IM06	IM08	IM11	
Type of Work	Action	Est Qty	UOM	Priority	Date Rec	Target Year	Ass. WK
Flexible	62 - A744601-RPR/RPL.TMBR.BEAM	50	EA	2	07/09/2002	0	No
IM07	Status: 0 - Work not planned	IM15	Notes: H03 LOCATION: 12345 Converted from BMS - H01 code: A744601				
IM09	Location						

Flexible	38 - A744801-RPR/RPL.BACKWALL	10	CY	2	07/09/2002	0	No
IM07	Status: 0 - Work not planned	IM15	Notes: H03 LOCATION: LNRLFR Converted from BMS - H01 code: A744801				
IM09	Location						

Flexible	10 - BITWRGS-RPR/RPL.BIT.W.S.	75	SY	3	07/09/2002	0	No
IM07	Status: 0 - Work not planned	IM15	Notes: H03 LOCATION: 12345 Converted from BMS - H01 code: BITWRGS				
IM09	Location						

Flexible	35 - B744301-RPR/RPL.TMBR.DK.	40	SY	2	07/09/2002	0	No
IM07	Status: 0 - Work not planned	IM15	Notes: H03 LOCATION: 1234 Converted from BMS - H01 code: B744301				
IM09	Location						

Flexible	28 - B744802-REPAIR ABUTMENT	20	CY	2	07/09/2002	0	No
IM07	Status: 0 - Work not planned	IM15	Notes: H03 LOCATION: LNRLFR Converted from BMS - H01 code: B744802				
IM09	Location						



101 SR ID: 03722308810003 **5A03** BR Key: 3298 **7A01** Inspection Date: April 27, 2011
 Flexible 32 - D744802-RPR. PIER 50 CY 2 06/07/2006 0 No

IM07 Status: 0 - Work not planned **IM15** Notes: H03 LOCATION: 1234 Converted from BMS - H01 code: D744802

IM09 Location

Flexible 27 - RDGDERL-CONNECT GDERAIL TO BR 4 EA 1 01/24/1995 0 No

IM07 Status: 0 - Work not planned **IM15** Notes: H03 LOCATION: LNRLFR Converted from BMS - H01 code: RDGDERL

IM09 Location ALL 4 QUADRANTS

Flexible 7 - RLGBRPR-RPR/RPL.BR/PARA.RLG 238 LF 1 07/10/2000 0 No

IM07 Status: 0 - Work not planned **IM15** Notes: TIMBER POSTS W/ TIMBER RAILS, SOME TIMBERS HAVE BEEN REPAIRED & REPLACED, MANY POSTS & PLANKS HAVE MED CRACKING & ROTTING AREAS, MANY POSTS @ F LT END ARE LOOSE & LEANING TO LT 2" +/- SEE PHOTO, MANY POSTS @ N RT END ARE LOOSE & LEANING TO RT 1" +/-

IM09 Location 1,2,3,4,5

Flexible 70 - RDLDSGN-RPL.LOAD LIMIT SIGN 1 EA 0 06/04/2007 2008 No

IM07 Status: 5 - Completed/Dept **IM15** Notes: NR

IM09 Location

Flexible 70 - RDLDSGN-RPL.LOAD LIMIT SIGN 1 EA 0 05/05/2009 2008 No

IM07 Status: 5 - Completed/Dept **IM15** Notes: #1 NA #2 FS BRIDGE SITE SIGN IS PRESENT BUT IS ATTACHED TO HAZ CLR SIGN POST; SEE PHOTO; CALLED RAG ON 5-5-09 TO REPORT INCORRECT SIGN #3 See BPOA 101-08-10

IM09 Location F LT BRIDGE SITE



5A01

SR ID: 03722308810003

5A03

BR Key: 3298

7A01

Inspection Date: April 27, 2011

Current Inspection

7A03

Primary Type: R - Regular (routine)

7A06

Types of Inspections Performed:

NBI	Underwater	Element	Fracture Critical	Other Special
Yes	No	Yes	No	Yes

Inspection Man Hours

6B26

NBI Crew: 0.00

6B30

Underwater: 0.00

6B28

Fracture Critical: 0.00

6B29

Other 1: 0.00

6B27

Crane: 0.00

6B31

Other 2: 0.00

Inspection Costs (Entered to nearest dollar)

6B32

Engineering: -1

6B33

Rigging: -1

6B34

Office: -1

Special Equip Used:

6B12

Temperature: 84.0

6B09

Weather: 1 - Clear

6B03

Inventory Review Recommended: No

Change Notes:

Inspection Team

7A05

Inspected By: 8 - Consulting Firm

7A02

Team Leader: Senate Engineering C Guntrum

6B23

Team Member: Matthew Pitsch E.I.T.

6B24

Hired By: 2

6B25

Insp Contract Num:

2A02

Inspection Notes:

5A01

SR ID: 03722308810003

5A03

BR Key: 3298

7A01

Inspection Date: April 27, 2011

Next Inspection

7A14

Next Inspection By: 8 - Consulting Firm

6B20

Next Insp Type: 1 - Interim (special)

Schedule

Insp Types	7A07 Required	7A09 Frequency	7A10 Next Date
NBI	----	24	April 29, 2013
Fractical Critical	No	-1	January 01, 1901
Underwater	No	-1	January 01, 1901
Other Special	No	12	April 27, 2012
Element	----	24	April 29, 2013
Crane	----		6B18 January 01, 1901

6B01

Special InspType: 4 - Problem areas only

Estimated Inspection Man Hours

7A12

NBI Crew: 0.00

7A17

Underwater: 0.00

7A15

Fracture Critical: 0.00

7A16

Other 1: 0.00

7A13

Crane: 0.00

7A18

Other 2: 0.00