

Lindsay A. Baxter
Manager, State Regulatory Strategy
lbaxter@duqlight.com
(412) 393-6224



April 29, 2019

VIA E-FILE

Ms. Rosemary Chiavetta, Secretary
Pennsylvania Public Utility Commission
Commonwealth Keystone Building
2nd Floor, Room-N201
400 North Street
Harrisburg, PA 17120

**Re: Duquesne Light Company 2018 Annual Electric Reliability Report
Docket No. M-2016-2522508**

Dear Secretary Chiavetta:

Please find enclosed for filing Duquesne Light Company's 2018 Annual Electric Reliability Report.

Upon receipt, if you have any questions regarding the information contained in this filing, please contact me or Audrey Waldock at 412-393-6334 or awaldock@duqlight.com.

Sincerely,

A handwritten signature in blue ink, appearing to read "L.A. Baxter", with a long horizontal flourish extending to the right.

Lindsay A. Baxter

Enclosure

Cc (w/ enc.):

Bureau of Technical Utility Services (dsearfoorc@pa.gov, dawashko@pa.gov,
jvanzant@pa.gov)

Office of Consumer Advocate (TMcCloskey@paoca.org)

Office of Small Business Advocate (jorevan@pa.gov, swebb@pa.gov)



2018 Annual Electric Reliability Report

to the

Pennsylvania Public Utility Commission

Duquesne Light Company
411 Seventh Avenue
Pittsburgh, PA 15219

April 29, 2019

**DUQUESNE LIGHT COMPANY
ANNUAL ELECTRIC RELIABILITY REPORT**

Filed April 29, 2019

52 Pa Code §57.195 Reporting Requirements

- (a)(2) The name, title, telephone number and e-mail address of the persons who have knowledge of the matters, and can respond to inquiries.**

Matthew G. Bucek – General Manager, Asset Management
(412) 393-8878, mbucek@duqlight.com

Jason Keller – General Manager, Operations Center
(412) 393-2897, jkeller@duqlight.com

- (b)(1) An overall current assessment of the state of the system reliability in the electric distribution company's service territory including a discussion of the electric distribution company's current programs and procedures for providing reliable electric service.**

Duquesne Light Company's ("Duquesne Light" or "the Company") service territory covers approximately 817 square miles, with a well-developed distribution system throughout. Electric service reliability remains very consistent across the service territory. The combination of an effective outage restoration process and significant distribution automation allows the Company to quickly restore power to large numbers of customers in outage situations.

Achieving outstanding performance in system reliability continues to be one of Duquesne Light's most important long-term objectives. The Asset Management and System Planning Groups performs ongoing analysis of reliability indices, root cause analysis of outages, and tracking and monitoring of other performance measures. This is a long-term process designed to optimize reliability and to identify improvement opportunities. This includes making recommendations for capital projects such as circuit rehabilitation, new substations, and distribution circuits. It also includes implementation of new advanced protection and coordination schemes on the distribution system that better localize customer outages and reduce momentary operations.

Duquesne Light continues its Emergent Work Process, which is used to identify problems, set priorities, and resolve reliability issues as quickly as possible. Each day, field personnel perform field inspections and any abnormalities are logged into a database. This database is reviewed regularly by the Emergent Work Team and any high priority problems are identified and a course of action is determined. Analysis at the device level is used to identify small areas where customers have experienced multiple outages. System level and even circuit level indices may mask these isolated problems. This is the short-term process for real-time analysis and reliability improvement.

Scheduled preventative and predictive maintenance activities continue to reduce the potential for future service interruptions. Corrective maintenance is prioritized with the objective to reduce backlog in the most cost-efficient manner.

Several capital budget projects target distribution reliability improvements, including pole replacement, substation rehabilitation, circuit load relief and voltage improvement, URD

rehabilitation, circuit rearrangement, and installation of additional automated remotely controlled pole top devices.

Specific programs, procedures, and ongoing maintenance activities that support Duquesne Light's commitment to service reliability include:

- A Distribution Overhead Line Inspection Program, which includes infrared inspections, that systemically identifies circuit problems for remedial action in advance of failure.
- A Rights-of-Way Vegetation Management Maintenance Program with the goal of reducing tree and branch failures through proactive pruning and removal to manage proper clearances. Duquesne Light believes that this program will help reduce the frequency of outages by addressing targeted tree failure conditions that typically result in physical damage to our facilities.
- An all pulse-reclosing protection technology has been implemented on some 23kV circuits. This technology eliminates traditional "hard reclosing," thereby making it easier and faster to conduct repairs and restore circuits to normal operation, enabling customers to be restored more quickly. This technology also reduces stress and damage on the entire circuit since the breaker is no longer required to trip, also contributing to the reduction in momentary outages to customers.
- Line maintenance work of various types is regularly performed in order to maintain distribution plant. This work includes replacement of cross arms, arrestors, insulators, and other equipment on the overhead system as well as inspections and remedial work on the underground system.
- Storm Preparedness Training is conducted each year and Storm Review Meetings are held following major events. These meetings focus on the successes and failures of the most recent emergency service restoration effort. Service restoration process improvements are made as needed to improve response time and effectiveness during the next restoration effort.

On April 20, 2017, the Commission adopted the Recommended Decision¹ approving the Company's amended LTIP/DSIC and the Company has begun its accelerated infrastructure program.

¹ Petition of Duquesne Light Company for Approval of Its Long-Term Infrastructure Improvement Plan for period January 1, 2017 through December 31, 2022, Docket No. P-2016-2540046

- (b)(2) A description of each major event that occurred during the year being reported on, including the time and duration of the event, the number of customers affected, the cause of the event and any modified procedures adopted in order to avoid or minimize the impact of similar events in the future.**

Duquesne Light had one major event that occurred on Thursday, November 15, 2018.

Duquesne Light's major outage event was caused by a snow and ice storm in Allegheny and Beaver counties that began on Thursday, November 15, 2018 at 0809 hours and ended on Monday, November 19, 2018 at 1238 hours. The storm affected 63,344 of the 598,295 total customers in our service territory.

A combination of freezing rain, snow, sleet, and ice buildup downed trees on our power lines and caused extensive damage to our poles and equipment throughout Duquesne Light's service territory in Allegheny and Beaver counties.

This snow and ice storm caused more damage to Duquesne Light's equipment than any storm since 2010. The damage was significant because the snowstorm occurred early in the season, when many leaves were still on trees. The leaves accumulated additional heavy snow and ice, making tree limbs and branches more likely to fall than if there were no leaves on the trees.

Please see Duquesne Light's Electric Utility Report of Outage dated Monday, December 3, 2018 and Duquesne Light's Request for Exclusion of Major Outage for Reliability Reporting Purposes dated Friday, December 14, 2018 for more information regarding this outage event.

- (b)(3) A table showing the actual values of each of the reliability indices (SAIFI, CAIDI, SAIDI, and if available, MAIFI) for the electric distribution company’s service territory for each of the preceding 3 calendar years. The report shall include the data used in calculating the indices, namely the average number of customers served, the number of sustained customer minutes interruptions, the number of customers affected, and the minutes of interruption. If MAIFI values are provided, the number of customer momentary interruptions shall also be reported.

RELIABILITY BENCHMARKS AND STANDARDS
Duquesne Light Company
System Performance Measures with Major Events Excluded

	SAIDI	SAIFI	CAIDI	MAIFI
2016	69	0.69	100	*
2017	112	0.98	115	*
2018	89	0.84	106	*
3 Year Average	90	0.84	107	*
Benchmark	126	1.17	108	*

* Sufficient information to calculate MAIFI is unavailable.

Formulas Used in Calculating the Indices

$$\text{SAIFI} = \frac{(\text{Total KVA interrupted}) - (\text{KVA impact of major events})}{\text{System Connected KVA}}$$

$$\text{SAIDI} = \frac{(\text{Total KVA-minutes interrupted}) - (\text{KVA-minute impact of major events})}{\text{System Connected KVA}}$$

$$\text{CAIDI} = \text{SAIDI/SAIFI}$$

Data used in calculating the indices

2018

Total KVA Interrupted for the Period (excluding 11/15/18 Major Event)	6,086,512	KVA
Total KVA-Minutes Interrupted (excluding 11/15/18 Major Event)	646,765,080	KVA Minutes
System Connected Load as of 12/31/18:	7,259,129	KVA
November 15, 2018 Major Event:	760,135 (10.5% of System Load)	KVA
	316,283,090	KVA-Minutes

2017

Total KVA Interrupted for the Period	7,092,245	KVA
Total KVA-Minutes Interrupted	812,501,426	KVA Minutes
System Connected Load as of 12/31/17:	7,259,129	KVA

2016

Total KVA Interrupted for the Period	4,979,083	KVA
Total KVA-Minutes Interrupted	497,296,442	KVA Minutes
System Connected Load as of 12/31/16:	7,210,354	KVA

(b)(4) A breakdown and analysis of outage causes during the year being reported on, including the number and percentage of service outages and customer interruption minutes categorized by outage cause such as equipment failure, animal contact, tree related, and so forth. Proposed solutions to identified service problems shall be reported.

January 1, 2018 through December 31, 2018 – One PUC Major Event Exclusion

CAUSE	NO. OF OUTAGES	OUTAGE PERCENTAGE	KVA TOTAL	KVA PERCENTAGE	KVA-MINUTE TOTAL	KVA-MINUTE PERCENTAGE
Storms	453	13%	861,164	14%	127,193,918	20%
Trees (Contact)	21	1%	23,951	1%	947,120	1%
Trees (Falling)	1,025	30%	1,652,155	27%	212,802,618	33%
Equipment Failures	858	25%	1,780,558	29%	175,924,355	27%
Overloads	155	5%	197,307	3%	11,105,701	2%
Vehicles	144	4%	432,098	7%	42,872,852	7%
Other	734	22%	1,139,279	19%	75,918,516	10%
TOTALS	3,390	100%	6,086,512	100%	646,765,080	100%

(b)(5) A list of remedial efforts taken to date and planned for circuits that have been on the worst performing 5% of circuits list for a year or more.

Duquesne Light has five circuits that have been on the worst performing 5% of circuits list for four consecutive quarters. The majority of these circuits have received remedial actions or are scheduled for maintenance activities in 2019 that are expected to improve their reliability. The Company will continue to monitor these circuits closely during 2019 to verify that the remedial actions taken have been successful and that reliability has improved. Many of the circuits have already shown improvement as indicated in the following detailed descriptions.

Duquesne uses a sophisticated automated protection system on its 23kV circuits, which utilizes numerous 3-phase sectionalizers and reclosers on the main feeders and as ties to adjacent circuits. This automation technology with remote control generally allows circuit problems to be isolated and rerouted in less than five minutes. Generally, only a small portion of the customers on a worst performing circuit experience reliability issues.

Rank, Circuit Name, Device	Outages	Remedial Actions Planned or Taken
<p>1 Midland-Cooks Ferry 22869 Breaker</p>	<p>8 Total Outages:</p> <p>Fourth Quarter Outages:</p> <ul style="list-style-type: none"> • Two outages were caused by tree fall-in during a storm. <p>Previous Outages:</p> <ul style="list-style-type: none"> • One outage was caused by burned conductor. • One outage was caused by wires wrapped together, causing short circuit. • One outage was caused by lightning during a storm. • The cause of two outages were unknown. • One outage was caused by tree fall-in. 	<ul style="list-style-type: none"> • Permanent repairs were made following each outage as necessary. • The Company will continue to monitor this circuit for reliability issues. • Vegetation management completed Q4 2017. • This circuit was reviewed by Protection Engineering to identify any potential device coordination issues. Further work to resolve device coordination issues scheduled for Q1 2019.
<p>2 Pine Creek 23710 Breaker</p>	<p>6 Total Outages:</p> <p>Fourth Quarter Outages:</p> <ul style="list-style-type: none"> • Two outages were caused by high winds causing wires to wrap together. <p>Previous Outages:</p> <ul style="list-style-type: none"> • The cause of three outages were unknown, two during a storm. • One outage was caused by tree fall-in. 	<ul style="list-style-type: none"> • Permanent repairs were made following each outage as necessary. • The Company will continue to monitor this circuit for reliability issues. • Vegetation management completed Q3 2018

Rank, Circuit Name, Device	Outages	Remedial Actions Planned or Taken
<p>3</p> <p>Traverse Run 23770</p> <p>Fuse Link 80E</p>	<p>6 Total Outages:</p> <p>Fourth Quarter Outages:</p> <ul style="list-style-type: none"> • One outage was caused by tree fall-in, during a storm. • The cause of one outage was unknown. • One outage was caused by equipment failures. <p>Previous Outages:</p> <ul style="list-style-type: none"> • The cause of one outage was unknown. • One outage was caused by equipment failure. • One outage was caused by contact with company equipment by vehicle. 	<ul style="list-style-type: none"> • Permanent repairs were made following each outage as necessary. • The Company will continue to monitor this circuit for reliability issues. • Routine vegetation management last performed 2016; proposed for 2020.
<p>4</p> <p>North 23706</p> <p>Sectionalizer WR416</p>	<p>6 Total Outages:</p> <p>Fourth Quarter Outages:</p> <ul style="list-style-type: none"> • One outage was caused by tree fall-in. <p>Previous Outages:</p> <ul style="list-style-type: none"> • One outage was caused by tree fall-in, during a storm. • Four outages were caused by equipment failure. 	<ul style="list-style-type: none"> • Permanent repairs were made following each outage as necessary. • The Company will continue to monitor this circuit for reliability issues. • Vegetation management completed Q3 2018.
<p>5</p> <p>Pine Creek 23714</p> <p>Sectionalizer 609WA</p>	<p>5 Total Outages:</p> <p>Fourth Quarter Outages:</p> <ul style="list-style-type: none"> • One outage was caused by wires wrapping together during a storm. <p>Previous Outages:</p> <ul style="list-style-type: none"> • One outage was caused by equipment failure. • Three outages were caused by tree fall-in during a storm. 	<ul style="list-style-type: none"> • Permanent repairs were made following each outage as necessary. • The Company will continue to monitor this circuit for reliability issues. • Vegetation management completed Q4 2018. • This circuit was reviewed by Protection Engineering to identify any potential device coordination issues. The devices were coordinating properly and no further action is necessary.

Rank, Circuit Name, Device	Outages	Remedial Actions Planned or Taken
<p>6</p> <p>Midland 23640</p> <p>Recloser 100</p>	<p>5 Total Outages:</p> <p>Fourth Quarter Outages:</p> <ul style="list-style-type: none"> • One outage was caused by tree fall-in. • The cause of one outage was unknown. <p>Previous Outages:</p> <ul style="list-style-type: none"> • Three outages were caused by tree fall-in, one during a storm. 	<ul style="list-style-type: none"> • Permanent repairs were made following each outage as necessary. • The Company will continue to monitor this circuit for reliability issues. • Vegetation management completed Q4 2018.
<p>7</p> <p>North 23705</p> <p>Fuse Link 100K</p>	<p>5 Total Outages:</p> <p>Fourth Quarter Outages:</p> <ul style="list-style-type: none"> • One outage was caused by tree fall-in during a storm. <p>Previous Outages:</p> <ul style="list-style-type: none"> • Two outages were caused by tree fall-in one during a storm. • The cause of two outages were unknown. 	<ul style="list-style-type: none"> • Permanent repairs were made following each outage as necessary. • The Company will continue to monitor this circuit for reliability issues. • Vegetation management performed Q1 2017 and proposed for 2021.
<p>8</p> <p>North 23701</p> <p>Fuse Link 65K</p>	<p>5 Total Outages:</p> <p>Fourth Quarter Outages:</p> <ul style="list-style-type: none"> • One outage was caused by tree fall-in, during a storm. • Two outages were caused by high winds causing wires wrapped together. <p>Previous Outages:</p> <ul style="list-style-type: none"> • One outage was caused by tree fall-in during a storm. • One outage was caused by lightning. 	<ul style="list-style-type: none"> • Permanent repairs were made following each outage as necessary. • The Company will continue to monitor this circuit for reliability issues. • Vegetation management performed 2016 and proposed for 2021.

Rank, Circuit Name, Device	Outages	Remedial Actions Planned or Taken
<p>9</p> <p>Pine Creek 23712</p> <p>Recloser WR610</p>	<p>5 Total Outages:</p> <p>Fourth Quarter Outages:</p> <ul style="list-style-type: none"> • One outage was caused by wires wrapping together causing a short circuit. <p>Previous Outages:</p> <ul style="list-style-type: none"> • Four outages were caused by tree fall-in, one during a storm. 	<ul style="list-style-type: none"> • Permanent repairs were made following each outage as necessary. • The Company will continue to monitor this circuit for reliability issues. • Vegetation management completed Q4 2018. • This circuit was reviewed by Protection Engineering to identify any potential device coordination issues. The devices were coordinating properly and no further action is necessary.
<p>10</p> <p>Wildwood 23869</p> <p>Fuse Link 40K</p>	<p>4 Total Outages:</p> <p>Fourth Quarter Outages:</p> <ul style="list-style-type: none"> • Two outages were caused by tree fall-in during a storm. <p>Previous Outages:</p> <ul style="list-style-type: none"> • Two outages were caused by tree fall-in. 	<ul style="list-style-type: none"> • Permanent repairs were made following each outage as necessary. • The Company will continue to monitor this circuit for reliability issues. • Vegetation management performed 2016 and proposed for 2020.
<p>11</p> <p>Fairview 4845</p> <p>Fuse Link 65K</p>	<p>4 Total Outages:</p> <p>Fourth Quarter Outages:</p> <ul style="list-style-type: none"> • One outage was caused by phases coming untied during a storm. • One outage was caused by tree fall-in during a storm. <p>Previous Outages:</p> <ul style="list-style-type: none"> • The cause of one outage was unknown. • One outage was caused by tree fall-in. 	<ul style="list-style-type: none"> • Permanent repairs were made following each outage as necessary. • The Company will continue to monitor this circuit for reliability issues. • Vegetation management completed Q4 2018.

Rank, Circuit Name, Device	Outages	Remedial Actions Planned or Taken
<p>12</p> <p>Mt. Nebo 23870</p> <p>Fuse Link 65K</p>	<p>4 Total Outages:</p> <p>Fourth Quarter Outages:</p> <ul style="list-style-type: none"> • One outage was caused by tree fall-in during a storm. • One outage was caused by icing during a storm. <p>Previous Outages:</p> <ul style="list-style-type: none"> • Two outages were caused by tree fall-in. 	<ul style="list-style-type: none"> • Permanent repairs were made following each outage as necessary. • The Company will continue to monitor this circuit for reliability issues. • Vegetation management performed Q4 2017 and proposed for 2021.
<p>13</p> <p>Woodville 23680</p> <p>Fuse Link 80E</p>	<p>4 Total Outages:</p> <p>Fourth Quarter Outages:</p> <ul style="list-style-type: none"> • Two outages were caused by tree fall-in, one during a storm. • The cause of one outage was unknown. <p>Previous Outages:</p> <ul style="list-style-type: none"> • One outage was caused by contact with company equipment by animal. 	<ul style="list-style-type: none"> • Permanent repairs were made following each outage as necessary. • The Company will continue to monitor this circuit for reliability issues. • Routine vegetation management last performed 2016, proposed for 2020.
<p>14</p> <p>Raccoon 23620</p> <p>Breaker</p>	<p>4 Total Outages:</p> <p>Fourth Quarter Outages:</p> <ul style="list-style-type: none"> • No outages. <p>Previous Outages:</p> <ul style="list-style-type: none"> • One outage was caused by tower collapse during a storm. • Three outages were caused by tree fall-in, two during a storm. 	<ul style="list-style-type: none"> • Permanent repairs were made following each outage as necessary. • The Company will continue to monitor this circuit for reliability issues. • Vegetation management scheduled for 2019.
<p>15</p> <p>Chess 23688</p> <p>Recloser ER863</p>	<p>4 Total Outages:</p> <p>Fourth Quarter Outages:</p> <ul style="list-style-type: none"> • No outages. <p>Previous Outages:</p> <ul style="list-style-type: none"> • Four outages were caused by tree fall-in, one during a storm. 	<ul style="list-style-type: none"> • Permanent repairs were made following each outage as necessary. • The Company will continue to monitor this circuit for reliability issues. • Vegetation management was completed Q4 2018.

Rank, Circuit Name, Device	Outages	Remedial Actions Planned or Taken
<p>16</p> <p>Universal 23733</p> <p>Recloser 100</p>	<p>3 Total Outages:</p> <p>Fourth Quarter Outages:</p> <ul style="list-style-type: none"> • One outage was caused by tree fall-in. <p>Previous Outages:</p> <ul style="list-style-type: none"> • The cause of one outage was unknown, during a storm. • One outage was caused by tree fall-in. 	<ul style="list-style-type: none"> • Permanent repairs were made following each outage as necessary. • The Company will continue to monitor this circuit for reliability issues. • Vegetation management was completed Q2 2018.
<p>17</p> <p>Pine Creek 23711</p> <p>Fuse Link 40K</p>	<p>3 Total Outages:</p> <p>Fourth Quarter Outages:</p> <ul style="list-style-type: none"> • One outage was caused tree fall-in during a storm. <p>Previous Outages:</p> <ul style="list-style-type: none"> • Two outages were caused by tree fall-in. 	<ul style="list-style-type: none"> • Permanent repairs were made following each outage as necessary. • The Company will continue to monitor this circuit for reliability issues. • Vegetation management was performed 2015 and proposed for 2020.
<p>18</p> <p>Wolfe Run 23646</p> <p>Recloser R100</p>	<p>3 Total Outages:</p> <p>Fourth Quarter Outages:</p> <ul style="list-style-type: none"> • One outage was caused by icing during a storm. <p>Previous Outages:</p> <ul style="list-style-type: none"> • One outage was caused by wires wrapping together to create a short. • One outage was caused by contact with company equipment by vehicle. 	<ul style="list-style-type: none"> • Permanent repairs were made following each outage as necessary. • The Company will continue to monitor this circuit for reliability issues.
<p>19</p> <p>Montour 23670</p> <p>Fuse Link 40K</p>	<p>3 Total Outages:</p> <p>Fourth Quarter Outages:</p> <ul style="list-style-type: none"> • One outage was caused by tree fall-in during a storm. <p>Previous Outages:</p> <ul style="list-style-type: none"> • The cause of one outage was unknown. • One outage was caused by tree fall-in during a storm. 	<ul style="list-style-type: none"> • Permanent repairs were made following each outage as necessary. • The Company will continue to monitor this circuit for reliability issues. • Vegetation management was completed Q1 2018.

Rank, Circuit Name, Device	Outages	Remedial Actions Planned or Taken
<p>20</p> <p>Wildwood 23868</p> <p>Breaker</p>	<p>3 Total Outages:</p> <p>Fourth Quarter Outages:</p> <ul style="list-style-type: none"> • One outage was caused by tree fall-in, during a storm. <p>Previous Outages:</p> <ul style="list-style-type: none"> • Two outages were caused by tree fall-in. 	<ul style="list-style-type: none"> • Permanent repairs were made following each outage as necessary. • The Company will continue to monitor this circuit for reliability issues. • Vegetation management was completed 2016 and proposed for 2020.
<p>21</p> <p>Wolfe Run 23645</p> <p>Fuse Link 80E</p>	<p>3 Total Outages:</p> <p>Fourth Quarter Outages:</p> <ul style="list-style-type: none"> • The cause of one outage was unknown. <p>Previous Outages:</p> <ul style="list-style-type: none"> • One outage was caused by equipment failure. • One outage was caused by contact with company equipment by animal. 	<ul style="list-style-type: none"> • Permanent repairs were made following each outage as necessary. • The Company will continue to monitor this circuit for reliability issues.
<p>22</p> <p>Arsenal 23841</p> <p>Fuse Link 100K</p>	<p>3 Total Outages:</p> <p>Fourth Quarter Outages:</p> <ul style="list-style-type: none"> • No outages. <p>Previous Outages:</p> <ul style="list-style-type: none"> • One outage was caused by equipment failure. • The cause of one outage was unknown, during a storm. • One outage was caused by wires wrapping together to create a short. 	<ul style="list-style-type: none"> • Permanent repairs were made following each outage as necessary. • The Company will continue to monitor this circuit for reliability issues.
<p>23</p> <p>Pine Creek 23716</p> <p>Recloser 100</p>	<p>3 Total Outages:</p> <p>Fourth Quarter Outages:</p> <ul style="list-style-type: none"> • No outages. <p>Previous Outages:</p> <ul style="list-style-type: none"> • The cause of three outages were unknown. 	<ul style="list-style-type: none"> • Permanent repairs were made following each outage as necessary. • The Company will continue to monitor this circuit for reliability issues.

Rank, Circuit Name, Device	Outages	Remedial Actions Planned or Taken
<p>24</p> <p>Pine Creek 23713</p> <p>Fuse Link 40K</p>	<p>2 Total Outages:</p> <p>Fourth Quarter Outages:</p> <ul style="list-style-type: none"> • One outage was caused by contact with company equipment by animal. <p>Previous Outages:</p> <ul style="list-style-type: none"> • One outage was caused by equipment failure. 	<ul style="list-style-type: none"> • Permanent repairs were made following each outage as necessary. • The Company will continue to monitor this circuit for reliability issues.
<p>25</p> <p>Montour 23675</p> <p>Recloser ER253</p>	<p>2 Total Outages:</p> <p>Fourth Quarter Outages:</p> <ul style="list-style-type: none"> • One outage was caused by tree fall-in during a storm. <p>Previous Outages:</p> <ul style="list-style-type: none"> • One outage was caused by tree fall-in. 	<ul style="list-style-type: none"> • Permanent repairs were made following each outage as necessary. • The Company will continue to monitor this circuit for reliability issues. • Vegetation management was completed 2015 and proposed for 2020.
<p>26</p> <p>Woodville 23683</p> <p>Breaker</p>	<p>2 Total Outages:</p> <p>Fourth Quarter Outages:</p> <ul style="list-style-type: none"> • One outage was caused by equipment failure. <p>Previous Outages:</p> <ul style="list-style-type: none"> • The cause of one outage was unknown. 	<ul style="list-style-type: none"> • Permanent repairs were made following each outage as necessary. • The Company will continue to monitor this circuit for reliability issues. • Routine vegetation management last performed 2016, proposed for 2021.
<p>27</p> <p>Arsenal 23842</p> <p>Breaker</p>	<p>2 Total Outages:</p> <p>Fourth Quarter Outages:</p> <ul style="list-style-type: none"> • No outages. <p>Previous Outages:</p> <ul style="list-style-type: none"> • The cause of one outage was unknown. • One outage was caused by equipment failure during a storm. 	<ul style="list-style-type: none"> • Permanent repairs were made following each outage as necessary. • The Company will continue to monitor this circuit for reliability issues.

- (b)(6) A comparison of established transmission and distribution inspection and maintenance goals/objectives versus actual results achieved during the year being reported on. Explanations of any variances shall be included.**

2018 Transmission and Distribution Goals and Objectives

Program Project	Unit of Measurement	Target for 2018	YTD Actuals for 2018	Percent Complete
Communications Goals				
Communication Battery Maintenance ²	Batteries	124	143	115%
Overhead Distribution Goals				
Recloser Inspections	Circuits	130	130	100%
Pole Inspections	Poles	17945	18762	105%
OH Line Inspections	Circuits	130	130	100%
OH Transformer Inspections	Circuits	130	130	100%
Padmount & Below Grade Insp	Circuits	80	81	101%
Overhead Transmission Goals				
Helicopter Inspections ³	Number of Structures	533	755	142%
Ground Inspections	Number of Structures	383	383	100%
Substations Goals				
Circuit Breaker Maintenance ⁴	Breakers	610	561	92%
Station Transformer Maintenance ⁵	Transformers	52	86	165%
Station Battery Maintenance ⁶	Batteries	988	942	95%
Station Relay Maintenance	Relays	1391	1535	110%
Station Inspections	Sites	2012	2012	100%
Underground Distribution Goals				
Manhole Inspections	Manholes	700	729	104%
Major Network Insp (Prot Relay)	Ntwk Protectors	92	104	113%
Minor Network Visual Inspection (Transformer/Protector/Vault)	Ntwk Transformers	576	583	101%
Underground Transmission Goals				
Pressurization and Cathodic Protection Plant Inspection	Work Orders	372	384	103%
Vegetation Management Goals				
Overhead Line Clearance	Circuit Overhead Miles	1300	1321	102%

² Additional inspections were performed to ensure reliability.

³ Inspections are selected on a circuit basis; the selected circuits accounted for a higher overall structure count in 2018 than projected.

⁴ Certain maintenance activities were intentionally deferred due to upcoming breaker replacements on Long Term Infrastructure Improvement Plant (LTIIP).

⁵ Opportunistic work to replace desiccant and condition based work on load tap changers increased the total maintenance in 2018.

⁶ Goal based on four inspections annually per battery; regulation requires three inspections annually. Compliance obligation achieved for all batteries.

(b)(7) A comparison of budgeted versus actual transmission and distribution operation and maintenance expenses for the year being reported on. Explanations of any variances shall be included.

Budget Variance Recap – O&M Expenses
For the Twelve Months Ending December 31, 2018
Favorable/(Unfavorable)

	Total Actual	Total Budget	Variance
Customer Service	67,662,866	62,040,152	(5,622,714)
Human Resources	14,505,988	16,680,823	2,174,835
Operations/Operation Services	63,577,951	63,683,038	105,087
Technology	51,471,591	51,498,196	26,605
General Corporate*	47,459,657	48,863,899	1,404,242
Total	244,678,051	242,766,108	(1,911,943)

* Includes Finance, Office of General Counsel, and Senior Management Costs

The O&M expense overspend for the twelve months ended December 31, 2018 is attributable to higher than budgeted enrollment in the CAP Program (Customer Service) partially offset by favorable medical claims activity below industry trends (Human Resources), and the receipt of transmission enhancement charges from PJM resulting from the FERC settlement approved in May 2018 (General Corporate).

(b)(8) A comparison of budgeted versus actual transmission and distribution capital expenditures for the year being reported on. Explanations of any variances shall be included.

Budget Variance Recap – Capital
For the Twelve Months Ending December 31, 2018
Favorable/(Unfavorable)

	Total Actual	Total Budget	Variance
Customer Service	10,973,026	10,750,602	(222,424)
Human Resources	10,775,046	12,856,790	2,081,744
Operations/Operation Services	227,073,661	230,131,752	3,058,091
Technology	74,939,596	58,977,693	(15,961,903)
General Corporate*	34,410,585	31,144,378	(3,266,207)
Total	358,171,913	343,861,215	(14,310,698)

* Includes Finance, Office of General Counsel, and Senior Management Costs

The capital spend overspend for the twelve months ended December 31, 2018 is attributable to and higher than budgeted expenses associated with large system implementations (Information Technology) and materials spend (General Corporate) partially offset by the delay of projects as a result of shifted work scope and engineering design (Operations) and favorable medical claims activity below industry trends (Human Resources).

(b)(9) Quantified transmission and distribution inspection and maintenance goals/objectives for the current calendar year detailed by system area (i.e., transmission, substation, and distribution).

2019 Transmission and Distribution Goals and Objectives

Program Project	Unit of Measurement	Target for Year 2019
Communications Goals		
Communication Battery Maintenance	Batteries	117
Overhead Distribution Goals		
Recloser Inspections	Circuits	130
Pole Inspections	Poles	17945
OH Line Inspections	Circuits	130
OH Transformer Inspections	Circuits	130
Padmount & Below Grade Insp	Circuits	81
Overhead Transmission Goals		
Helicopter Inspections	Number of Structures	576
Ground Inspections	Number of Structures	370
Substations Goals		
Circuit Breaker Maintenance	Breakers	408
Station Transformer Maintenance	Transformers	44
Station Battery Maintenance	Batteries	906
Station Relay Maintenance	Relays	865
Station Inspections	Sites	1942
Underground Distribution Goals		
Manhole Inspections	Manholes	700
Major Network Insp (Prot Relay)	Network Protectors	94
Minor Network Visual Inspection (Transformer/Protector/Vault)	Network Transformers	572
Underground Transmission Goals		
Pressurization and Cathodic Protection Plant Inspection	Work Orders	372
Vegetation Management Goals		
Overhead Line Clearance	Circuit Overhead Miles	1300

(b)(10) Budgeted transmission and distribution operation and maintenance expenses for the current year in total and detailed by FERC account.

	Total Budget
Customer Service	61,399,832
Human Resources	15,540,131
Operations/ Operation Services	68,405,459
Technology	61,672,441
General Corporate*	36,073,901
Total	243,091,764

*Includes Finance, Supply Chain, Office of General Counsel, and Senior Management Costs

(b)(11) Budgeted transmission and distribution capital expenditures for the current year in total and detailed by FERC account.

	Total Budget
Customer Service	9,375,101
Human Resources	12,198,506
Operations/ Operation Services	264,679,039
Technology	66,480,721
General Corporate*	31,233,951
Total	383,967,318

*Includes Finance, Supply Chain, Office of General Counsel, and Senior Management Costs

(b)(12) Significant changes, if any, to the transmission and distribution inspection and maintenance programs previously submitted to the Commission.

Duquesne Light has not made any significant changes to its transmission and distribution inspection and maintenance programs.