

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF TRANSPORTATION



December 21, 1995

ORIGINAL

IN REPLY REFER TO

Beaver County
T-649
Marion Township
AAR No. 145 802 C
PUC No. M-00870123

RECEIVED
95 DEC 28 AM 10:56
PA. P. U. C.
INFO. CONTROL DIV.

Mr. John G. Alford, Secretary
Public Utility Commission
P. O. Box 3265
Harrisburg, PA 17105-3265

Attention: Mr. David C. Hart, P.E.

Dear Secretary Alford:

The Department requests that the five span bridge carrying T-649 over the tracks of CSX Transportation, Inc. in Marion Township, Beaver County, be posted for a maximum load limit of 3 tons. The structure is currently posted for 15 tons.

Attached are two copies of a report prepared by SAI Consulting Engineers for CSX Transportation, Inc. via Engineering District 11-0 entitled "NBIS Bridge Inspection Report".

Sincerely,

Thomas M. Shauder

For: M. G. Patel, P.E.,
Director
Bureau of Design

Attachment

DOCKETED
JAN 16 1996

DOCUMENT
FOLDER

B7L



NBIS BRIDGE INSPECTION REPORT

M-870123

STRUCTURE BMS NUMBER: 04 7210 0649 8302

BRIDGE NAME: T-649 OVER CSX RAILROAD

LOCATION: T-649 OVER CSX RAILROAD
MARION TOWNSHIP
BEAVER COUNTY

INSPECTION DATE: SEPTEMBER 29, 1995

INSPECTED BY: WILLIAM B. SOSKO, C.B.S.I.

PREPARED FOR: CSX RAILROAD (OWNER)
VIA
COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF TRANSPORTATION
DISTRICT 11-0

RECEIVED
95 DEC 28 AM 10:56
PA. P. U. S. DIV.
INFO. CONTROL

AGREEMENT NUMBER: 115851

BRIDGE POSTING: POSTING SHOULD BE REDUCED TO 3 TONS

TABULATION OF COSTS:

INSPECTION AND REPORT PREPARATION:	\$2,590.71
RIGGING:	N/A
RAILROAD PERMITS AND/OR FLAGMEN:	1,295.26
TESTING:	N/A
TRAFFIC CONTROL:	N/A
MEETING WITH OWNER:	N/A
TOTAL COST:	\$3,885.97


DOCKETED
JAN 16 1996

INSPECTION DATA:

BRIDGE INSPECTION NUMBER: 1062

CATEGORY/TYPE: J-B2

TOTAL MANHOURS: 43




DOCUMENT FOLDER

David A. Miller 12-6-95

SAI CONSULTING ENGINEERS, INC.
300 SIXTH AVENUE
PITTSBURGH, PA 15222

(412) 392-8750

LOCATION MAP



T-649 OVER CSX RAILROAD
MARION TOWNSHIP, BEAVER COUNTY



SOUTH APPROACH



NORTH APPROACH



WEST ELEVATION



EAST ELEVATION

LOAD RATING SUMMARY

The structural analysis of the CSX Bridge resulted in the following ratings with the timber deck being the governing element.

Timber Deck Ratings:

Type of Load	Inventory (Tons)	Operating (Tons)	Analysis Sheet No.
H	2**	3**	6 of 37
HS	4**	6**	6 of 37
ML80	7**	10**	7 of 37

* Rating governed by horizontal shear

Timber Stringer Ratings:

Type of Load	Inventory (Tons)	Operating (Tons)	Analysis Sheet No.
H	13*	18*	21 of 37
HS	25*	33*	21 of 37
ML80	21*	29*	21 of 37

* Rating governed by flexural strength

** Rating governed by shear strength

Timber Stringer S5 of Span 4 is the governing stringer.

LOAD RATING SUMMARY (Continued)

Steel Stringer Ratings (Load Factor):

Type of Load	Inventory (Tons)	Operating (Tons)	Analysis Sheet No.
H	69*	116*	33 of 37
HS	102*	171*	33 of 37
ML80	80*	133*	34 of 37

* Rating governed by flexural strength

** Rating governed by shear strength

For additional information, refer to the structural analysis section of this report.

INTRODUCTION

The CSX Railroad Bridge carries T-649 over the CSX Railroad approximately 500' from the intersection with S.R. 588. The bridge is located in Marion Township, Beaver County and is owned and maintained by the CSX Railroad.

The structure was built in 1939 and consists of four timber stringer spans and one rolled steel stringer span supported by four timber bents and two timber bent and retaining wall abutments. The bridge roadway consists of a timber plank deck bordered by timber tie curbs and steel angle bridge railings. The overall structure length is 94'-0" with a bridge roadway width of 12.7' curb-to-curb and an out-to-out deck width of 13.9'. The bridge is currently posted for a 15-ton single-axle weight restriction.



BRIDGE MANAGEMENT SYSTEM
BRIDGE INSPECTION REPORT

Inspection Report for: Entire Bridge <input checked="" type="checkbox"/> Main Span(s) only <input type="checkbox"/> Approach Span(s) Only <input type="checkbox"/>	STRUCTURE IDENTIFICATION NUMBER				STRUCTURE TYPE	
	AD1 <u>04</u> <u>7210</u> <u>0649</u> <u>0302</u>				Main <u>STEEL STRINGER</u> <u>1161104</u>	
	<u>T-649</u> over <u>CSX RAILROAD</u>				Approach <u>TIMBER STRINGER</u> <u>591136</u>	

INSPECTION BY <u>WBS</u>	CITY <input type="checkbox"/> BOROUGH <input type="checkbox"/> TOWNSHIP <input checked="" type="checkbox"/> <u>MARION</u>	INSPECTION DATE <u>9-29-95</u>	TIME STARTED	WEATHER CONDITIONS <u>SUNNY 70°</u>
			TIME COMPLETED	

E15 APPROACH ROADWAY - COND. RATING 4, Details on Page 7
 Pavement GRAVEL AND DIRT - BROKEN CONCRETE SLABS WERE PLACED (SEE SHT. 4 D488F)
 Shoulders GRAVEL AND GRASS MINOR EROSION AT SOUTHWEST CORNER OF BRIDGE.

E14 APPR. SLAB Yes No Cond.: N

C19 RELIEF JOINT Yes No

Guiderail NO GUIDE RAIL PRESENT - BRIDGE RAILS EXTEND A SHORT DISTANCE ONTO
 Drainage NATURAL // APPROACH SHOULDERS.

Embank Slope UNPROTECTED SLOPES WITH HEAVY VEGETATION.

BRIDGE SIGNING <u>LOAD LIMIT SIGNS AT BRIDGE, NO CLEARANCE MARKERS OR ADVANCE WARNING.</u>										
Leg. & Visibility <u>SOUTHEAST APPROACH SIGN KNOCKED OVER AND DAMAGED.</u>										
D15	POSTED LOAD LMTS.:	<u>15</u>	T;	Comb.:	<u>NONE</u>	NR <input type="checkbox"/>	FR <input type="checkbox"/>	ANR <input type="checkbox"/>	AFR <input type="checkbox"/>	
D14	BR LIM 1 TR:	NR <input type="checkbox"/>	FR <input type="checkbox"/>	ANR <input type="checkbox"/>	AFR <input type="checkbox"/>	New wrg surf undr bridge <input type="checkbox"/> yes <input type="checkbox"/> no				
B22	VERT CL SIGNS:	Overhead	<u>N/A</u>	ft.	<u>N/A</u>	in.	NR <input type="checkbox"/>	FR <input type="checkbox"/>	ANR <input type="checkbox"/>	AFR <input type="checkbox"/>
		Under	<u>N/A</u>	ft.	<u>N/A</u>	in.	NR <input type="checkbox"/>	FR <input type="checkbox"/>	ANR <input type="checkbox"/>	AFR <input type="checkbox"/>
Clearance Warning (Striped Diagonal) NR RT <input type="checkbox"/> FR RT <input type="checkbox"/> NR LT <input type="checkbox"/> FR LT <input type="checkbox"/>										

E16 WRG. SURFACE N N/A (TOPS OF TIMBER PLANKS)

E17 DECK - Cond. Rating 6, Details on Pages TIMBER PLANK DECK - THE TIMBER PLANKS ARE NAILED DIRECTLY TO THE TOPS OF THE TIMBER STRINGERS (SEE SHT. 4 D488F)

E16A/C19A EXPANSION JOINTS - Number 0, Cond. N, Details on Pages _____

Median Barrier N/A
 Curb-Parapets CURBS CONSIST OF 84"x44" TIMBER TIES WITH AREAS OF SPLITS, CHECKS & ROTTING.
 Railings STEEL ANGLE RAILS BOLTED TO THE TOPS OF THE CURBS IN SPAN 3 AND THE
 Sidewalks N/A // SIDES OF THE FASCIA STRINGERS IN SPANS 1, 2, 4 AND 5. THE
 Drains/Scuppers N/A // RAILINGS EXHIBIT HEAVY SURFACE RUSTING THROUGHOUT.

E18 SUPERSTRUCTURE - Cond. Rating 7, Details on Pages 6 & 7

Drainage System (Below Deck) N/A
 Bearings THE BEARINGS CONSIST OF TIMBER PLATES AND BLOCKS. THE BEARING BLOCK AT S7 SPAN 1 BENT 1 IS NOT SEATED ON THE BENT CAP BEAM. (SEE SHT. 4 D-488F).
 Stringers THE TIMBER STRINGERS IN SPANS 1, 2, 4 AND 5 EXHIBIT AREAS OF MINOR SPLITTING AND WATER DISCOLORATION BUT NO SIGNIFICANT DETERIORATION WAS NOTED. THE STEEL STRINGERS IN SPAN 3 EXHIBIT AREAS OF PAINT PEELING
 Girders N/A // AND FLAKING WITH HEAVY SURFACE CORROSION. THE TOP EXTERIOR PORTIONS OF THE FASCIA BEAM BOTTOM FLANGES EXHIBIT SOME MINOR PITTING BUT GENERALLY NO SIGNIFICANT SECTION LOSS WAS NOTED.
 Floorbeams N/A

Diaphragms TIMBER END DIAPHRAGMS GENERALLY EXHIBIT NO SIGNIFICANT DETERIORATION.

Trusses _____
N/A
- Portals _____
- Bracing _____

E19 PAINT CONDITION 65 G09 YEAR PAINTED UNKNOWN

(If Instructed) Dry Film Thickness _____ Mils, Adhesion Class _____; G14 Color _____

Fire Damage NONE

Collision Damage NONE

Inspection Walk N/A

Utility Attachments NONE

E20 SUBSTRUCTURE - Cond. Rating 4, Details on Pages _____

Abutments - Wings THE WINGS CONSIST OF THE STEPPED-OFF PORTIONS OF THE ABUTMENT RETAINING WALLS.

- Bridge Seats NO SIGNIFICANT DETERIORATION NOTED

- Backwalls STACKED TIMBER TIE RETAINING WALLS AGAINST TIMBER BENTS. THE ENDS OF THE TIMBER TIES AT THE EAST AND WEST ELEVATIONS (SEE SH. 4 D-488F)

- Stems TIMBER BENTS - THE NORTH STEM COLUMN AND CAP BEAM EXHIBIT SOME MINOR SPLITTING BUT NO SIGNIFICANT DETERIORATION (SEE SH. 4 D-488F)

- Embank-Slope-Wall EARTH EMBANKMENTS COVERED WITH SCATTERED VEGETATION AND APPEAR STABLE.

- Footing APPEAR TO BE TIMBER SILLS AND CRIBBING FOUNDATIONS THAT GENERALLY ARE NOT VISIBLE

- Piles N/A

- Scour N/A

- Undermine NONE DETECTED

- Settlement NONE DETECTED

- ~~Piers~~ Bents THE CAP BEAMS TYPICALLY EXHIBIT AREAS OF SPLITTING AND CHECKING. HOWEVER, THE CAP BEAM AT BENT 2 HAS A 5" DIAMETER HOLE ROTTED INTO THE

- Caps CENTER OF THE BEAM AT THE EAST ELEVATION. THE HOLE PENETRATES 3'-9" INTO THE CAP BEAM. THE CAP BEAM EXHIBITS SCATTERED SPLITS RANGING 1/4" TO 1/2" WIDE.

- Columns/~~Stems~~ THE COLUMN AT BENT 2 EXHIBIT VERTICAL SPLITS RANGING 1/4" TO 3/4" WIDE. THE COLUMN AT BENT 3 EXHIBIT VERTICAL SPLITS TO 3/8" WIDE.

- Footings THE FOOTINGS APPEAR TO BE TIMBER SILLS ON TIMBER CRIBBING. THE WEST END OF THE TIMBER SILL UNDER COLUMN 1 AT BENT 2 IS HEAVILY

- Piles N/A DETERIORATED. THE TIMBER IS ROTTED AND HOLLOW TO A DEPTH

- Scour N/A OF 5'-0" HORIZONTALLY. COLUMN 1 IS SITUATED 2'-0" FROM THE WEST END OF THE TIE.

- Undermine NONE DETECTED TIMBER BENT BRACING CONSISTS OF LATERAL AND LONGITUDINAL TIMBER PLANKS RANGING

- Settlement NONE DETECTED FROM 2'3/4" X 10" TO 3'3/4" X 7'1/2". THE BOTTOM END OF THE LATERAL BRACING PLANK

Bridge Seats SEE CAPS AT COLUMN 4 BENT 2 IS ROTTED AND BROKEN OFF.

E21 CHANNEL/CHANNEL PROTECTION - COND. RATING N, Details on Pages _____

Channel Alignment _____

Scour _____

Embank Erosion _____

Chan./Emb. Protection N/A

Debris _____

Vegetation _____

Highwater Mark _____

Streambed Material _____

E22 CULVERTS - Cond. Rating N, Details on Pages _____ Length _____ L.F. _____

Barrel _____

Sattlement _____

Headwall N/A

Wings _____

Debris _____

E23 EST. REMAINING LIFE Comments _____

E24 STRUCTURAL CONDITION - Appraisal Rating 2, Details on Pages _____
MS20 INVENTORY RATING IS 4 TONS - 0-500 ADT CL REQUIRES REPLACEMENT.

E25 DECK GEOMETRY - Appraisal Rating 4, ADT: 10 ADTT: _____ C-C: 12.7'

E26 UNDERCLEAR - VERT. & LATERAL - Appraisal Rating 4, MIN. VERT. 20'-4 LAT. 9'-0

E27 WATERWAY ADEQUACY - Appraisal Rating N

E28 APPR. RDWY. ALIGNMENT - Appraisal Rating 3, SUBSTANTIAL SPEED REDUCTION DUE TO VERTICAL CURVE.

E28A TRAFFIC SAFETY FEATURES

Bridge Railing 3 Transitions 2 Appr. Guiderail 2 Appr. Guiderail Transition 2

Comments _____

E29 BRIDGE POST 0 MS20 OPERATING RATING - 10 TONS

Recalculate IR/OR: Yes No Calculation Attached: Yes No

E30 IR 102 204 807 **E31** OR 103 206 810

E29A **W06** SCOUR CRITICAL RATING N Based on: Observed Scour Scour Calculation

E01 NEXT INSP. FREQ. 1/2 **E03** EQUIP. NEXT INSP. -

E04 SPEC. INSP. TYPE - **E05** BY DATE - - - -

Remarks _____

APPROACH ROADWAY (CONTINUED) - IN THE WHEEL PATHS AT BOTH ENDS OF THE BRIDGE TO COMPENSATE FOR DEPRESSIONS AT THE TRANSITIONS, THE APPROACH ROADWAYS ARE DEPRESSED FULL WIDTH ALONG BOTH ENDS OF THE BRIDGE. THE SOUTH ROADWAY IS DEPRESSED UP TO 2" WHILE THE NORTH ROADWAY IS DEPRESSED UP TO 2 1/2".

DECK (CONTINUED) - IN SPANS 1, 2, 4 AND 5, THE DECK PLANKS IN SPAN 3 ARE NAILED TO A 2 3/4" x 10" LONGITUDINAL NAILING PLANK THAT IS IN TURN BOLTED TO THE TOPS OF THE STEEL STRINGER FLANGES. THE DECK PLANKS AT BENTS 2 & 3, AT THE APEX OF THE VERTICAL CURVES, EXHIBIT NUMEROUS SCRAPE MARKS AS A RESULT OF VEHICLES BOTTOMING OUT. THE PLANKS APPEAR TO BE TIGHT THROUGHOUT THE BRIDGE AND EXHIBIT AREAS OF SPLITTING AND WEAR BUT GENERALLY ARE IN SATISFACTORY CONDITION. THE PLANKS VARY 9" TO 9 1/2" WIDE x 2 3/4" THICK.

BEARINGS (CONTINUED) - THE SHIM PLATE BENEATH THE BLOCK HAS COMPLETELY ROTTED AWAY RESULTING IN A 1/8" GAP BETWEEN THE BEARING BLOCK AND THE CAP BEAM. THE BEARING BLOCK AT S5 SPAN 2 BENT 2 HAS ROTTED AND SPLIT RESULTING IN A 2" x FULL HEIGHT SLAB SEPARATING FROM THE BLOCK ALONG THE SOUTH FACE OF THE BEARING. THE BEARING BLOCK AT S1 SPAN 4 BENT 3 HAS SPLIT THROUGH ALONG THE SAME LINE WITH THE ANCHOR BOLT SPLITTING THE BLOCK INTO TWO PIECES.

BACKWALLS (CONTINUED) - EXHIBIT HEAVY ROTTED DETEIORATION AND EXPOSED AND DETEIORATED CONNECTION BOLTS AND SPIKES. AT THE NORTH BACKWALL, THE ENDS OF THE TIES HAVE ROTTED AND BECOME HOLLOW TO A DEPTH OF 1'-8". SIMILAR CONDITIONS ARE PRESENT AT THE SOUTH BACKWALL HOWEVER, THE BEAMS HAVE HOLLOW'S TO A DEPTH OF 3'-0". THE ROTTING CONDITION IS WORST AT THE TOP TIE AND DECREASES IN SEVERITY DOWNWARD. THE TIMBER TIE BACKS IN BOTH BACKWALLS ARE SEVERELY DETEIORATED. THE TIE BACKS ARE ROTTED AND HOLLOW TO A DEPTH OF 4'-0".

STEMS (CONTINUED) - WAS NOTED, THE SOUTH STEM COLUMNS AND CAP BEAM EXHIBIT SIMILAR SPLITTING. HOWEVER, THE TOP OF COLUMN 2 HAS A 7" WIDE x FULL DEPTH (11") HOLE ROTTED THROUGH THE TIMBER.



PROJECT BRIDGE No. 1062


COMP. BY WBS DATE 9-29-95

BMS No. 04 7210 0649 8302

PROPOSAL OR JOB NO. 9501

CHK'D BY _____ DATE _____

PLAN VIEW



REV. DATE	REV. DATE	REV. DATE	REV. DATE
BY	BY	BY	BY



PROJECT BRIDGE No. 1062

COMP. BY WBS DATE 9-29-95


BMS No. 047210 0649 8302

PROPOSAL OR JOB NO. 9501

CHK'D BY _____ DATE _____


CROSS SECTIONS

SPAN #1




REV. DATE	BY
REV. DATE	BY
REV. DATE	BY
REV. DATE	BY

SPAN #2




BOLTED NAILER
RAIL TYPICAL

SPAN #3




SPAN #2: #2 =



(ALL CORNERS) 11/16"

SPAN #3 =





PROJECT BRIDGE No. 1062




COMP. BY WBS DATE 9-29-95

BMS No. 04 7210 0649 8302


PROPOSAL OR JOB NO. 9501

CHK'D BY _____ DATE _____

CROSS SECTIONS



BRACING MEMBERS FOR BENTS = $2\frac{3}{4}'' \times 10''$ & $3\frac{3}{4}'' \times 7\frac{1}{2}''$ BENT COLUMNS = $11\frac{3}{4}'' \times 12\frac{3}{4}''$ & $12'' \times 12''$



SEC. AA APPROX. NAILER PLATE BOLT SPACINGS SPAN 3

REV. DATE	REV. DATE	REV. DATE	REV. DATE
By	By	By	By

INSPECTION RESULTS

The field inspection revealed the following deficiencies (see Inspection Forms D-488F for a complete report):

Critical

- None.

Immediate Attention

- None.

General

- The approach roadways are depressed 2" to 2½" at the bridge transitions.
- No guide rail is present at the bridge site.
- Hazard clearance markers, load posting, advance warning signs, and one-lane bridge signs are damaged or missing at the bridge site.
- The timber deck planks exhibit areas of minor splitting. The deck planks at Bent No. 2 and Bent No. 3 exhibit vehicular scrapes.
- The timber curbs exhibit areas of splits, checks, and rotting.
- The steel angle bridge railings are heavily rusted throughout.
- The bearings consist of timber planks and timber blocks. A few of the bearings exhibit rotting and wide splitting. The timber shim plate under the block bearing at S1 in Span 1 at Bent No. 1 has completely rotted away.
- The timber stringers in Spans 1, 2, 4, and 5 exhibit areas of minor splitting and water discoloration.
- The steel stringers in Span 3 exhibit areas of paint peeling and flaking with heavy surface rusting.
- The stacked timber tie backwalls at both abutments exhibit areas of heavy rotted deterioration at the east and west end elevations (wingwalls) and in the tieback members.
- Timber Column No. 2 at the south abutment has a large rotted hole adjacent to the cap beam.

INSPECTION RESULTS (Continued)

- The timber bent caps exhibit areas of splitting and checking. A large hole is rotted into the east end of the cap beam at Bent No. 2.
- The timber bent columns exhibit areas of vertical splitting ranging from 1/4" to 3/4" in width.
- The west end 5'-0" \pm of the sill timber at Bent No. 2 is heavily rotted and deteriorated.

Fracture Critical Members

- None.

Traffic Control/Inspection Vehicle

- None.



SETTLEMENT OF SOUTH APPROACH ROADWAY



EROSION OF SOUTHWEST ROADWAY EMBANKMENT



DAMAGED BRIDGE POSTING SIGN AT SOUTH APPROACH



SETTLEMENT OF NORTH APPROACH ROADWAY



VEHICULAR SCRAPE HACKS IN TIMBER DECKING ABOVE BENT NO. 2



GENERAL VIEW OF TIMBER STRINGER SPAN



5. GENERAL VIEW OF STEEL STRINGER SPAN 3 AND TIMBER BENT NOS. 2 AND 3



SPLITS AND CHECKS IN COLUMNS OF BENT NO. 2



DECAYED AND SPLIT SILL OF BENT NO. 2



DECAY AND ROT IN BENT NO. 2 CAP BEAM

NOTE: 5"-DIAMETER X 3'-9"-LONG HOLE IN END OF CAP BEAM



SPLITS AND CHECKS IN COLUMNS OF BENT NO. 3



GENERAL VIEW OF SOUTH ABUTMENT



SPLITS, CHECKS, AND HOLE ROTTED IN COLUMN OF SOUTH ABUTMENT



GENERAL VIEW OF NORTH ABUTMENT



TYPICAL ROTTED TIE-BACK TIMBER AT NORTH ABUTMENT



ROTTED RETAINING WALL TIMBERS AT NORTH ABUTMENT - EAST SIDE

RECOMMENDATIONS

Immediate Repairs

- A letter transmitted November 7, 1995 to the attention of Mr. Carl Medors of CSX Transportation from SAI Consulting Engineers, Inc. recommended that the bridge be immediately posted for three (3) tons.

Improvement Needs

Maintenance Items

- Regrade and raise the approach roadway transitions.
- Install an approach guide rail system continuous across the bridge in accordance with current PaDOT standards.
- Install proper bridge signing at the site.
- Clean and paint the steel stringers.

Rehabilitation Items

- Replace the rotted and deteriorated bearing blocks and shim plates.
- Replace the heavily deteriorated section of footing timber under Column No. 1 at Bent No. 2.

Replacement Items

- None.

Load Posting

- In place at 15 tons.
- Recommend structure be posted for three (3) tons.

Signs Needed

- Hazard clearance markers.
- Weight limit.
- Advance weight limit.

RECOMMENDATIONS (Continued)

- One-lane bridge.

Special Investigation Needs

- During future inspections, monitor the north and south backwall timbers for additional deterioration and possible problems.

Estimated Maintenance / Repair Activity Costs

Priority Code:

- 0 - Prompt action required.
- 1 - High Priority, as soon as work can be scheduled.
- 2 - Priority, review work plan, adjust schedule if needed.
- 3 - Add to scheduled work.
- 4 - Routine Structural, can be delayed until funds are available
- 5 - Routine Non- structural, can be delayed until programmed.

Bridge Inspection No. 1062

Inspection Date : September 29, 1995

Description of Activity	Item No.	Location	Unit	Quan.	Unit Cost	Total Cost	Priority
Approach Roadway:							
Raise Pavement	RDPAVMT	LNRLFR	S.Y.	10	\$40	\$400	3
Repair / Replace Pavement Relief Joint	RDRLFJT	LNRLFR	S.Y.		\$250	\$0	
Repair / Reconstruct Shoulders	RDSHLDR	LNRLFR	S.Y.		\$60	\$0	
Improve Drainage - Off Bridge	RDDRAIN	LNRLFR	Ea.		\$2,000	\$0	
Connect Guide Rail to Bridge	RDGDERL	LNRLFR	Ea.	4	\$1,000	\$4,000	1
Replace Load Limit & One Lane Br. Sign	RDLDSGN	NR LF	Ea.	6	\$200	\$1,200	0
Replace Clearance Signs	RDCLSGN	LNRLFR	Ea.	4	\$200	\$800	1
Cut Brush to Clear Signs	RDBRUSH	LNRLFR	Ea.		\$150	\$0	
Replace Approach Slab	A744201	LNRLFR	S.Y.		\$150	\$0	
Clean & Flush:							
Deck	A743101	---	E.B.		\$400	\$0	
Scupper / Downspouting	B743101	123450	E.B.		\$275	\$0	
Bearing / Bearing Seat	C743102	123450	E.B.		\$300	\$0	
Horizontal Steel Surfaces	D743102	123450	E.B.		\$200	\$0	
Deck:							
Repair / Replace Bitum. Deck W. Surfac	BITWRGS	123450	S.Y.		\$25	\$0	
Repair / Replace Timber Deck	B744301	123450	S.Y.		\$100	\$0	
Repair / Replace Open Steel Grid	C744302	123450	S.Y.		\$400	\$0	
Repair Concrete Deck	D744303	123450	S.Y.		\$200	\$0	
Repair / Replace Concrete Sidewalk	E744303	123450	S.Y.		\$120	\$0	
Repair / Replace Concrete Curb / Parape	F744303	123450	S.Y.		\$300	\$0	
Deck Joints:							
Reseal	A743301	N 1230 F	L.F.		\$10	\$0	
Repair / Reseal	A744101	N 1230 F	L.F.		\$20	\$0	
Repair / Rehab. Compression Seal	B744102	N 1230 F	L.F.		\$28	\$0	
Repair / Rehab. Modular Dam	C744102	N 1230 F	L.F.		\$150	\$0	
Repair / Rehab. Steel Dam	D744102	N 1230 F	L.F.		\$55	\$0	
Repair / Rehab. Other Types of Dams	E744102	N 1230 F	L.F.		\$50	\$0	
Railing:							
Repair / Replace Bridge Parapet	RLGBRPR	N 1230 F	L.F.		\$97	\$0	
Repair / Replace Structure - Mounted	RLGSTRM	N 1230 F	L.F.	188	\$93	\$17,484	1
Repair / Replace Pedestrian	RLGPEDN	N 1230 F	L.F.		\$63	\$0	
Repair / Replace Median Barrier	RLGMEDB	123450	L.F.		\$51	\$0	

Estimated Maintenance / Repair Activity Costs

Bridge Inspection No. 1062

Description of Activity	Item No.	Location	Unit	Quan.	Unit Cost	Total Cost	Priority
Deck Drain:							
Replace Scupper Grate	DRNGRAT	1 2 3 4 5 0	Ea.		\$200	\$0	
Install / Drain Scupper	B744401	1 2 3 4 5 0	Ea.		\$600	\$0	
Repair / Replace Downspouting	C744402	N 1 2 3 F 0	Ea.		\$800	\$0	
Bearings:							
Lubricate	A74305	N 1 2 3 F 0			\$250	\$0	
Replace Steel	B744501	N 1 2 3 F 0	Ea.		\$1,650	\$0	
Reset Expansion	C744502	N 1 2 3 F 0	Ea.		\$900	\$0	
Reconstruct Pedestal / Seat	D744503	N 1 2 3 F 0	Ea.		\$2,000	\$0	
Timber:							
Repair / Replace Stringer	A744601	1 2 3 4 5 0	Ea.		\$660	\$0	
Replace Timber Bearing Blocks	B744601	1 2 4 5	Ea.	15	\$200	\$3,000	3
Steel:							
Repair / Replace Stringer	A744602	1 2 3 4 5 0	Ea.		\$8,000	\$0	
Repair / Replace Floorbeam	B744602	1 2 3 4 5 0	Ea.		\$9,750	\$0	
Repair Girder	C744602	1 2 3 4 5 0	Ea.		\$9,750	\$0	
Repair / Replace Diaph. / Lateral Bracing	D744602	1 2 3 4 5 0	Ea.		\$1,000	\$0	
Reinforced Concrete / Concrete:							
Repair / Replace Stringer	A744603	1 2 3 4 5 0	Ea.		\$7,000	\$0	
Repair / Replace Diaphragm	B744603	1 2 3 4 5 0	Ea.		\$2,100	\$0	
Repair / Replace Other Members	C744603	1 2 3 4 5 0	Ea.		\$7,000	\$0	
Truss:							
Strengthen / Repair / Replace Members	A744701	1 2 3 4 5 0	Ea.		\$5,000	\$0	
Modify Portal	B744701	1 2 3 4 5 0	Ea.		\$2,000	\$0	
Tighten / Flame shorten Members	C744702	1 2 3 4 5 0	Ea.		\$350	\$0	
Painting:							
Superstructure - Spot	A743201	1 2 3 4 5 0	E.B.		\$3,500	\$0	
Substructure - Spot	B743201	N 1 2 3 0 F	E.B.		\$750	\$0	
Superstructure - Full	C743201	3	S.F.	2000	\$10	\$20,000	5
Substructure - Full	D743201	N 1 2 3 0 F	E.B.		\$1,500	\$0	

Estimated Maintenance / Repair Activity Costs

Bridge Inspection No. 1062

Description of Activity	Item No.	Location	Unit	Quan.	Unit Cost	Total Cost	Priority
Abutment - Wing - Pier, etc. :							
Repair / Replace Backwall	A744801	LNRLFR	C.Y.		\$0	\$0	
Repair Abutments	B744802	LNRLFR	C.Y.		\$1,200	\$0	
Repair / Replace Wingwall	C744802	LNRLFR	C.Y.		\$1,200	\$0	
Repair Bents	D744802	2	Ea.	1	\$3,000	\$3,000	1
Underpin Footing	E744803	N 1230 F	C.Y.		\$600	\$0	
Point Masonry	F744804	N 1230 F	L.F.		\$10	\$0	
Repair / Replace Abutment Slopewall	A745101	LNRLFR	S.Y.		\$50	\$0	
Construct New Abutment Slopewall	B745102	LNRLFR	C.Y.		\$50	\$0	
Pile Repair	A745901	N 1230 F	Ea.		\$1,200	\$0	
Erosion Control:							
Repair / Construct Stream Bed Paving	A745301	UP UN DN	C.Y.		\$300	\$0	
Rock Protection	B745301	UP UN DN	C.Y.		\$30	\$0	
Backfill Scour Hole	C745301	UP UN DN	C.Y.		\$40	\$0	
Repair / Construct Stream Deflector	D745302	UP UN DN	C.Y.		\$52	\$0	
Remove Vegetation / Debris	ECREMGV	UP UN DN	C.Y.		\$13	\$0	
Remove Deposits	ECREMDP	UP UN DN	C.Y.		\$11	\$0	
Culvert:							
Repair / Replace Headwall	A745201	IN OUT	S.Y.		\$360	\$0	
Repair / Replace Wingwall	A745201	IN OUT	S.Y.		\$360	\$0	
Repair / Replace Apron / Cut-off Wall	B745202	IN OUT	S.Y.		\$360	\$0	
Repair Barrel	C745203	-----	S.Y.		\$500	\$0	

Total \$49,884

LOCATION AND UNIT LEGEND	
N	--- Near
F	--- Far
1,2,3,ETC	--- Span or Pier Number
O	--- Other
LNR	--- Near Left or Right
LFR	--- Far Left or Right
UP	--- Upstream
UN	--- Under
DN	--- Downstream
IN	--- Inlet
OUT	--- Outlet
E.B.	--- Each Bridge (Site)

BMS GENERAL DATA

* = MIN. INFORMATION REQUIRED BY FHWA

*BRIDGE INSPECTION
 No. 1062*

CO	SR	SEG	OFF	SD	CD	LD	BORDER ST	%DK	BORDER	BRDG	SR
04	7210	0649	8302								

OLD SR ID
 NEW SR ID

AGCY	SUBM	LOCATION	LATITUDE	LONGITUDE	CTY/BOR	FIPS	BNDY	PSU-PUC
			DEG MIN	DEG MIN	CODE	CODE	CODE	NUMBER
P02	PRK302	W OLD FURNACE ST	40 476	80 101	210		N	M-870123

DESIGN NUMBER	DRAWING NUMBER	ADD DRAW	SHOP NUMBER	DRAWINGS NUMBER	YEAR BUILT	LAST TYPE	RECON YEAR	FED FND	DESX EXCN
		0			1939	000	0000	0	

OWNER/CUSTODIAN	PRINCIPAL AND	LEG ACT CODE	NUMBER	MAINTENANCE RESPONSIBILITY	MAINTENANCE CODE	TOLL
					1 2 3 4 5	
CSX RAILROAD		27		CSX RAILROAD	271	3

TYPE	TEMP	CRIT	PAY	ROWY	ROWY	BRDG	BRDG	SIDEWALK	DECK	TYPE & WIDTH	DETOUR	CURVE	SCH	PUB
SERV	STRC	FAC	WDTH	WDTH	WDTH	FLRD	WDTH	LEFT	RIGHT	LENGTH	HORZ	VERT	BUS	TRAN
12			010	011	012.0	0	013.2	1	00.0	1	00.0	99	0	0
			000	010	012.7		013.9		00.7		00.7			

BMS FEATURES INTERSECTED DATA

SR ID: 04721006498302

* = MIN. INFORMATION REQUIRED BY FHWA

REF	SR	SEG	SEG	FEATURE	ON OR UNDER	TRAF ROUTE	DIR	RTE SGN	DESN SERV	SKEW ANGLE	MEDIAN
A				W OLD FURNAC	1	000	0	5	1	90	0 00
B				CSX RR 355-A	2	NNN	N	N	N	90	N 00

NO	NO	ELECT	NAME	AAR	RAILROAD	ADM	HWY	FUNC	STATE	NAT	MIN	LAT	CL
LANE	TRACKS	STAT	NUMBER	MILEPOST	JUR	SYS	NHS	CLAS	NET	NET	LEFT	RIGHT	
01	00					9	11	0	09	0	00.0	00.0	
02	00	1	02	145802C	0035.4	N	NN	0	NN	0		08.0	09.0

TTL	HORZ	CL	LEFT	RIGHT	LEFT	RIGHT	DEF	ADT	ADTT	ADTT	VT		
LEFT	RIGHT		FT	IN	FT	IN	HWY	ADT	YEAR	ADTT	YEAR	%	SGN
			99	99	99	99	0	000010	1994		05	0	
	12.7		20	04	20	04	0		1995		600		

*	*	*
FHWA FEATURES INTERSECTED	FHWA FACILITY CARRIED	NO LANES
CSX RAILROAD	W-OLD FURNACE RD	01 00

BMS STRUCTURE DATA

* = MIN. INFORMATION REQUIRED BY FHWA

SR ID: 04721006498302

HIST SIGN: 5 * COV BRDG: N EST CUM TK FAT LIFE: 000000 NO DK JNT: 00

STRUCTURE TYPE

D S	MAIN	APPROACH	CULVT	STRUCT	NI	M	SP	G	STEEL	TYPES	CUM	TK	DATE	DK		
L L	FHWA	DEPT	FHWA	DEPT	LNTH	LNTH	LT	LENG	M	1	2	3	4	TRAF	EST	TP
0	302	16104	720	59136	00000	0000	97	Y	00	37						02
				59136			94			35						

SPAN	TTL	SPANS, NUMBER AND LENGTH (MAIN & APPROACH)								FR	CR	CR	RAT	WS	WS	
TYPE		NO	LENG	NO	LENG	NO	LENG	NO	LENG	NO	LENG	GR	NO	FACTOR	TYP	THCK
MAIN	01	01	0037	00	0000	00	0000	00	0000	00	0000	6		4883	NNN	NN
		00	0000	00	0000	00	0000	00	0000	00	0000				700	
APPR	02	02	0030	00	0000	00	0000	00	0000	00	0000	9		9993	700	NN
	04	00	0000	00	0000	00	0000	00	0000	00	0000					
		01	0013	01	0015	02	0014									

REL	EXP	JT	TYPES	BEARING	TYPE	FLD	LT	PROB	STRANDS	TENSION			
JT	FRM	RBR	1	2	3	4	1	2	3	4	1	2	3

VAC	V	LOC	V	TYPE	CNT	FLD	ABT	FND	PIER	TYPE	PIER	FD	SP	L	PR											
DRAP	PROC	1	2	1	2	3	4	UTIL	L	L	SPL	N	F	N	F	1	2	3	4	1	2	3	4	CAP	TIE	SUB

99 PP 13

P

BMS UTIL, HYDRO & POSTING DATA

SR ID: 04721006498302 * = MIN. INFORMATION REQUIRED BY FHWA

REF	UTILITY OCCUPANCIES NAME OF COMPANY AND ADDRESS	LICENSE NUMBER	DATE ISSUED	WGHT KIPS
-----	--	-------------------	----------------	--------------

HYDROLOGY AND NAVIGATION

* * *

STREAM NAME	DRAIN AREA	VERT CLEAR	DESIGN FLOOD MAGNIT FRQ ELEV	MAX W.S. VEL ELEV YEAR	FISH Y/N	VERT LIFT CL VERT
						0 000

*

*

POSTING DATA

HORZ NAV SCR	C/P	SPC	WT	COMB	1ST DT	LAST DT	DT	CLOSE	FLD	SPEC	IMP	
CLR PRT DPTH	A	LMT	LT	LT	POSTED	POSTED	ALL	TRAF	REASON	COND	COND	ACT
0000	P	0	15		043086	043086					B	

02/13/95 P02
 PROGRAM ID: P4575130
 SCREEN: "AF"

COMMONWEALTH OF PENNSYLVANIA
 DEPARTMENT OF TRANSPORTATION
 BRIDGE MANAGEMENT SYSTEM

PAGE NO: 6
 REPORT ID: BMSIS200

BMS PROPOSED IMPROVEMENTS

SR ID: 04721006498302

* = MIN. INFORMATION REQUIRED BY FHWA

* YR	* IMPR	* TYPE	* TYPE	* IMPROV LGTH	* STRUCT	* BRDG	* RDWY	* DESIGN	* NO
COST EST	WORK	SERV	STRUC +	RDWY	IMPR LGTH	WDTH	WDTH	LOAD	LANES
1990	001	1	000150		000097	013.2	012.0	5	02

* FUTURE	* YEAR	* ADJ RDWY	* IMPR
ADT	ADT	YEAR	TYPE
000010	2012	1994 1995	1

ESTIMATED COSTS FOR PROPOSED IMPROVEMENTS IN THOUSANDS

SPAN TYPE	TYPE WORK	* DECK OVRD	* SUPSTR OVRD	* SUBSTR OVRD	* SPAN TOTAL
MAIN	001	00000	00000	00013	000013
APPROACH					

* PREL ENG OVRD	* CONST ENG OVRD	* APPR RDWY OVRD	* DEMO OVRD	* OTHER OVRD
00006	00004	00027	00000	00004

TOTAL TYPE WORK COST: 000054 REV IND: TOTAL REPLACE COST: 000288 OVRD:

02/13/98 P02
PROGRAM ID: P4575130
SCREEN: "AG"

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF TRANSPORTATION
BRIDGE MANAGEMENT SYSTEM

PAGE NO: 7
REPORT ID: BMSI5210

BMS REPAIR & PAINTING

SR ID: 04721006498302

REPAIR DATA

REF YEAR	DRAWING NUMBER	TYPE WORK	REPAIR COST	PGM	REPAIR DESCRIPTION
----------	----------------	-----------	-------------	-----	--------------------

PAINTING DATA

REF YEAR	TONS STEEL	EST AREA SURFACE	NUMBER COATS	GALLONS PAINT	FIN COL NUMBER	TYPE CLEAN	PAINT TYP EXT	PAINT THICK	PAINT COST
----------	------------	------------------	--------------	---------------	----------------	------------	---------------	-------------	------------

BMS PROPOSED MAINTENANCE ACTIVITIES

SR ID: 04721006498302

FHWA FEATURE INTERSECTED: CSX RAILROAD

INSPECTION DATE: 092995
 MAINT DEF PTS: 031.0
 CO RANK: 0314
 MAJ IMPROV PROJ STATUS:

ACTIVITY ID	ACTIVITY DESC	LOC	UNIT	EST QTY	EST COST	OV RD PR	PRG D/C	INSP DATE	OV RD	MTE CD	PR YR
RDPVMT	RAISE ROADWAY	LNRLFR	SY	00010		3		092995			
RDGDEBL	APPROACH RAIL	LNRLFR	EA	00001		2		092995			
RLG BR PR	REPLACE RAILING	N1230F	L.F.	00188		4		092995			
RDLOSGN	LOAD LIMIT SIGNS	LNRLFR	EA	00002		0		092995			
RDCLSGN	INSTALL SIGNS	LNRLFR	EA	00004		1		092995			
A743201	PAINT	123450	EB	00001		4		092995			

For revisions to Screen "AH,"
 see estimated maintenance/repair
 activity costs chart included in this report.

02/13/80 P02
PROGRAM ID: P4575130
SCREEN: "AJ"

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF TRANSPORTATION
BRIDGE MANAGEMENT SYSTEM

PAGE NO: 9
REPORT ID: BMSI5240

BMS FRACTURE CRITICAL DATA

SR ID: 04721006498302

INSP DATE:	MAIN	GROUP: 6	CRF: 4883	TOTAL CRF: 23
INSP FREQ:	APPR	GROUP: 9	CRF: 9993	TOTAL CRF: 30

SPAN NO	FRACT CRITICAL MEMBER	FRACT CRITICAL DETAIL	FRAC CATG	CONDITION
------------	--------------------------	--------------------------	--------------	-----------

Structure BMS Number: 04 7210 0649 8302
Bridge Name: T-649 Over CSX Railroad
Inspection Date: September 29, 1995
Bridge Inspection No.: 1062

STRUCTURAL ANALYSIS

**BRIDGE INSPECTION
DISTRICT 11-0
LOAD FACTOR ANALYSIS AND STRUCTURAL RATING SUMMARY**

BMS I.D. # 04 7210 0649 8302

STANDARD SPEC. FOR HWY BRIDGES: AASHTO "1991" INTERIMS.

T-649 OVER CSX RAILROAD (SAI BR. JDSR. No. 1062)

	Inventory Rating Factor (Tons)	Operating Rating Factor (Tons)
H-20	$\frac{0.14(2.75T)}{0.7(13.9T)}$ *	$\frac{0.18(3.66T)}{0.94(18.8T)}$ *
HS-20	$\frac{0.14(4.94T)}{0.7(25.0T)}$	$\frac{0.18(6.59T)}{0.94(33.9T)}$
ML-80	$\frac{0.21(7.98T)}{0.58(21.7T)}$	$\frac{0.28(10.03T)}{0.78(29.5T)}$

Structural components that govern ratings: TIMBER PLANK DECK - SHEAR

* NEXT GOVERNING RATING: SPAN 4 - STRINGER S5 - MOMENT

Prepared by: DLT 10 / 25 / 95

Checked by: AA 10 / 25 / 95



PROJECT T-649 OVER CSX Railroad

COMP. BY DCT DATE 10/17/95

SAE Br. No. 1062 BUS No. 04 7210 0649 8302

PROPOSAL OR JOB NO. 9501


CHK'D BY AA DATE 10-25-95

WOODEN SPANS

SPAN	SPAN LENGTH	BEAM SIZE	I	Beam Spacing
1	12'-9"	15 1/2 Dp x 7 3/4	2405 in ⁴	Ranges from 2'-1 1/4" to 2'-7 1/2"
2	15'-5"	" "	"	" " 1'-4 1/2" to 3'-4 1/2"
4	14'-2"	11 1/2" x 11 1/2"	1457.5 in ⁴	" " 2'-1 3/4" to 3'-5 1/4"
5	13'-10"	13 3/4" x 11 3/4"	2545.5 in ⁴	" " 1'-1 5/8" to 4'-4 5/8"

STEEL SPAN

3 35'-1" 26 WF 144 4983.4 in⁴ Ranges from 2'-0 3/4" to 2'-3 1/2"



(REFERENCE: INSPECTION REPORT BY S.A.I. "95")



PROJECT T-649 over CSX Railroad

COMP. BY DCT DATE 10/18/95

SAI Be. No. 1062 BMS. No. 04 7210 0649 8302

PROPOSAL OR JOB NO 9501

CHK'D BY AA DATE 10-25-95

DEAD LOADS:

Assume 0.05 K/c.F. for all wood.

Planking: 2×4 WT/ft' = $\left(\frac{2.75}{12}\right) (0.05 \text{ K/c.F.}) = 0.011 \text{ K/s.F.}$

Curb WT/FT = $\frac{(8.25 \times 4.25)}{144} (0.05 \text{ K/c.F.}) = 0.012 \text{ K/ft}$

Railing $(0.0045 \text{ K/ft} \times 2) = 0.009 \text{ K/ft}$

Post $2 \times 2 \times 4 @ 7' \text{ spacing @ } 4' \therefore \text{WT/FT} = 0.003 \text{ K/ft}$

Beam Wt.:

Span 1 & 2 $\left(\frac{15.5 \times 7.75}{144}\right) (0.05 \text{ K/c.F.}) = 0.042 \text{ K/ft}$

Span 4 $\left(\frac{11.5 \times 11.5}{144}\right) (0.05 \text{ K/c.F.}) = 0.046 \text{ K/ft}$

Span 5 $\left(\frac{13.75 \times 11.75}{144}\right) (0.05 \text{ K/c.F.}) = 0.056 \text{ K/ft}$

Span 3 $26 \text{ W } 144 = 0.144 \text{ K/ft}$

Deck Plank Analysis:

$W_{DL} = \left(\frac{9}{12}\right) (0.011 \text{ K/s.F.}) = 0.008 \text{ K/ft}$

Stringer Analysis:

Curb, Rail & Post = $\frac{2(0.012 \text{ K/ft} + 0.009 \text{ K/ft} + 0.003 \text{ K/ft})}{7 \text{ beams}}$
= 0.007 K/ft

Planking 0.011 K/s.F.

WOOD PROPERTIES (AASHTO Table 13.2.1A White Oak)

Planking: Assume $F_b = 1350 \text{ psi}$ $f_{lv} = 110 \text{ psi}$ (No. 1 - Northeast Lumber)

Timber Beams: $F_b = 1400 \text{ psi}$ $f_{lv} = 105 \text{ psi}$ (Select. Structural - Beams & Stringers).

Operating $F_b = 1.33 F_{b(iuv)}$ (M.M.I.B. 5.4.7).



PROJECT T-649 OVER CSX Railroad COMP. BY DCT DATE 10/18/95
SAI Re. No. 1062 BUS No. 04 7210 0649 8302 PROPOSAL OR JOB NO. 9501 CHK'D BY AA DATE 10-25-95


Planking Analysis:

Analyze Planking as Continuous: Reduce center to center span length

as mentioned in AASHTO 3.25.1.2

In addition the load can be distributed based on Tire Contact Area (AASHTO 3.30)


$$(3'-4\frac{1}{2}'' + \frac{7\frac{3}{4}''}{2} - 8\frac{3}{8}'' - 2\frac{1}{4}'') \cdot 12.125''$$



Span 2

The beam dimension width = $7\frac{3}{4}'' = 0.646'$

Reduced Span Length = Clean span + $\frac{1}{2}$ beam width



(Wheel location from actual location to effective location).

Tire Contact Area = $0.01 P$ $0.01 (10,000^{\#}) = 160 \text{ in}^2$ (103 in^2)
↑ H20 ↑ ML80

Rectangle Area $1/2.5$ $\therefore 8 \times 20''$ $6.4'' \times 16''$

Length of distribution = $\frac{20''}{12} = 1.667'$ $\frac{16''}{12} = 1.333'$

Load $w_{H20} = \frac{16^k}{1.667'} = 9.598^k/ft$ $w_{ML80} = \frac{10.3^k}{1.333'} = 7.727^k/ft$

INDEX NO. _____

SHEET NO. 5 OF 37

PROJECT T-649 OVER CSX Rail Road. COMP. BY DC DATE: 10/17/95
 SAI Bk. No. 1062 BMS. No. 04 1210 0649 8302 CHK'D BY AA DATE 10-25-95

Analysis of Wood Deck Planking :

kip := 1000·lbf ksi := 1000· $\frac{\text{lbf}}{\text{in}^2}$ fbwood := 1350·psi vallow := 110·psi

thick := 2.75·in thick = thickness of the floor planking
 width := 9.0·in Width = Width of individual planking
 spanlength := 3.375·ft spanlength = span length being investigated

Planking Moment and Shears: (Ref. to Staad III Output)

Dead Loads:

Mdl := 0.007·kip·ft Vdl := 0.014·kip

Live Loads:

Vh20 := 13.12·kip Mh20 := 4.82·kip·ft
 Vhs20 := 13.12·kip Mhs20 := 4.82·kip·ft
 Vml80 := 8.52·kip Mml80 := 3.31·kip·ft

$S := \frac{\text{width} \cdot \text{thick}^2}{6}$ S = 11.34·in³ Av := width·thick
 Av = 24.75·in²

Allowables:

Mallow := fbwood·S Mallow = 1.28·kip·ft

Vallow := $\frac{2}{3}$ ·vallow·Av Vallow = 1.81·kip (Horizontal Shear Allowable)

INDEX NO. _____

SHEET NO. 6 OF 37

PROJECT T-649 over CSX Railroad COMP. BY DCT DATE: 01/17/95
 SAI Br. No. 1062 BMS. No. 04 7210 0649 8302 CHK'D BY AA DATE 10-25-95

Moment Rating Factors:

$$\text{H20: IRF} := \frac{\text{Mallow} - \text{Mdl}}{\text{Mh20}} \quad \text{IRF} = 0.26 \quad \text{IRF} \cdot 20 = 5.27 \quad \text{tons}$$

$$\text{ORF} := \frac{\text{Mallow} \cdot 1.33 - \text{Mdl}}{\text{Mh20}} \quad \text{ORF} = 0.35 \quad \text{ORF} \cdot 20 = 7.01 \quad \text{tons}$$

$$\text{HS20: Same as H20} \quad \text{IRF} \cdot 36 = 9.48 \quad \text{tons}$$

$$\text{ORF} \cdot 36 = 12.62 \quad \text{tons}$$

$$\text{ML80: IRF} := \frac{\text{Mallow} - \text{Mdl}}{\text{Mml80}} \quad \text{IRF} = 0.38 \quad \text{IRF} \cdot 37.74 = 14.47 \quad \text{tons}$$

$$\text{ORF} := \frac{\text{Mallow} \cdot 1.33 - \text{Mdl}}{\text{Mml80}} \quad \text{ORF} = 0.51 \quad \text{ORF} \cdot 37.74 = 19.27 \quad \text{tons}$$

Horizontal Shear Rating Factors:

$$\text{H20: IRF} := \frac{\text{Vallow} - \text{Vdl}}{\text{Vh20}} \quad \text{IRF} = 0.14 \quad \text{IRF} \cdot 20 = 2.75 \quad \text{tons}$$

$$\text{ORF} := \frac{\text{Vallow} \cdot 1.33 - \text{Vdl}}{\text{Vh20}} \quad \text{ORF} = 0.18 \quad \text{ORF} \cdot 20 = 3.66 \quad \text{tons}$$

$$\text{HS20: Same as H20} \quad \text{IRF} \cdot 36 = 4.94 \quad \text{tons}$$

$$\text{ORF} \cdot 36 = 6.59 \quad \text{tons}$$

INDEX NO. _____

SHEET NO. 7 OF 37

PROJECT T-649 OVER CSX Railroad COMP. BY DCI DATE: 10/17/95
SAE. Be. No. 1062 BMS. No. 04 7210 0649 8302 CHK'D BY AA DATE 10-25-95

ML80: $IRF := \frac{V_{allow} - V_{dl}}{V_{ml80}}$ IRF = 0.21 IRF · 37.74 = 7.98 tons

ORF := $\frac{V_{allow} \cdot 1.33 - V_{dl}}{V_{ml80}}$ ORF = 0.28 ORF · 37.74 = 10.63 tons

```
*****  
*  
*          S T A A D - III          *  
*          Revision 19.0a          *  
*          Proprietary Program of  *  
*          RESEARCH ENGINEERS, Inc.*  
*          Date=    OCT 23, 1995   *  
*          Time=    9:16:45        *  
*  
*          USER ID: SAI CONSULTING ENGINEERS, INC. *  
*****
```

8/37

AA 10-25-95

1. STAAD PLANE TIMBER PLANKING
2. INPUT WIDTH 72
3. UNIT FEET KIP
4. JOINT COORDINATES
5. 1 0. 0. 0.; 2 2.203 0. 0.; 3 3.052 0. 0.; 4 4.812 0. 0.; 5 6.698 0. 0.
6. 6 7.234 0. 0.; 7 8.541 0. 0.; 8 10.364 0. 0.; 9 11.416 0. 0.
7. MEMBER INCIDENCES
8. 1 1 2; 2 2 3; 3 3 4; 4 4 5; 5 5 6; 6 6 7; 7 7 8; 8 8 9
9. UNIT INCHES KIP
10. MEMBER PROPERTY AMERICAN
11. 1 TO 8 PRI YD 2.75 ZD 9.
12. CONSTANTS
13. E 1100. ALL
14. SUPPORTS
15. 1 PINNED
16. 3 TO 5 7 TO 9 FIXED BUT FX MZ
17. LOAD 1 DEAD LOAD
18. MEMBER LOAD
19. 1 TO 8 UNI Y -0.008 *← 4/ft should be kip/in (divide results by 12 for DL).*
20. LOAD 2 16K WHEEL LOAD
21. JOINT LOAD
22. 2 6 FY -16.
23. UNITS FEET KIPS
24. LOAD 3 DISTRIBUTED WHEEL LOAD H20 & HS20
25. MEMBER LOAD
26. 1 UNI Y -9.598 1.370 2.203 0.
27. 2 UNI Y -9.598 0. 0.833 0.
28. JOINT LOAD
29. 6 FY -16.0
30. LOAD 4 DISTRIBUTED WHEEL LOAD ML80
31. MEMBER LOAD
32. 1 UNI Y -7.727 1.536 2.203 0.
33. 2 UNI Y -7.727 0.0 0.667 0.
34. JOINT LOAD
35. 6 FY -10.3
36. UNITS INCHES KIPS
37. PERFORM ANALYSIS

SUPPORT REACTIONS -UNIT KIPS INCH STRUCTURE TYPE = PLANE

11/37

JOINT	LOAD	FORCE-X	FORCE-Y	FORCE-Z	MOM-X	MOM-Y	MOM Z
1	1	0.00	0.12	0.00	0.00	0.00	0.00
	2	0.00	2.59	0.00	0.00	0.00	0.00
	3	0.00	2.87	0.00	0.00	0.00	0.00
	4	0.00	1.78	0.00	0.00	0.00	0.00
3	1	0.00	0.30	0.00	0.00	0.00	0.00
	2	0.00	17.80	0.00	0.00	0.00	0.00
	3	0.00	16.89	0.00	0.00	0.00	0.00
	4	0.00	11.09	0.00	0.00	0.00	0.00
4	1	0.00	0.13	0.00	0.00	0.00	0.00
	2	0.00	-6.90	0.00	0.00	0.00	0.00
	3	0.00	-6.13	0.00	0.00	0.00	0.00
	4	0.00	-4.13	0.00	0.00	0.00	0.00
5	1	0.00	0.19	0.00	0.00	0.00	0.00
	2	0.00	14.57	0.00	0.00	0.00	0.00
	3	0.00	14.39	0.00	0.00	0.00	0.00
	4	0.00	9.31	0.00	0.00	0.00	0.00
7	1	0.00	0.18	0.00	0.00	0.00	0.00
	2	0.00	4.94	0.00	0.00	0.00	0.00
	3	0.00	4.99	0.00	0.00	0.00	0.00
	4	0.00	3.20	0.00	0.00	0.00	0.00
8	1	0.00	0.16	0.00	0.00	0.00	0.00
	2	0.00	-1.41	0.00	0.00	0.00	0.00
	3	0.00	-1.43	0.00	0.00	0.00	0.00
	4	0.00	-0.91	0.00	0.00	0.00	0.00
9	1	0.00	0.03	0.00	0.00	0.00	0.00
	2	0.00	0.41	0.00	0.00	0.00	0.00
	3	0.00	0.41	0.00	0.00	0.00	0.00
	4	0.00	0.26	0.00	0.00	0.00	0.00

12/37

MEMBER END FORCES STRUCTURE TYPE = PLANE

ALL UNITS ARE -- KIPS INCH

MEMB	LOAD	JT	AXIAL	SHEAR-Y	SHEAR-Z	TORSION	MOM-Y	MOM-Z
1	1	1	0.00	0.12	0.00	0.00	0.00	0.00
		2	0.00	0.09	0.00	0.00	0.00	0.37
	2	1	0.00	2.59	0.00	0.00	0.00	0.00
		2	0.00	-2.59	0.00	0.00	0.00	68.37
	3	1	0.00	2.87	0.00	0.00	0.00	0.00
		2	0.00	5.13	0.00	0.00	0.00	35.86
	4	1	0.00	1.78	0.00	0.00	0.00	0.00
		2	0.00	3.37	0.00	0.00	0.00	26.52
2	1	2	0.00	-0.09	0.00	0.00	0.00	-0.37
		3	0.00	<u>0.17</u> DL	0.00	0.00	0.00	<u>-0.98</u> DL
	2	2	0.00	-13.41	0.00	0.00	0.00	-68.37
		3	0.00	13.41	0.00	0.00	0.00	-68.28
	3	2	0.00	-5.13	0.00	0.00	0.00	-35.86
		3	0.00	<u>13.12</u> H20	0.00	0.00	0.00	<u>-57.86</u> H20
	4	2	0.00	-3.37	0.00	0.00	0.00	-26.52
		3	0.00	<u>8.52</u> M80	0.00	0.00	0.00	<u>-39.71</u> M80
3	1	3	0.00	0.12	0.00	0.00	0.00	0.98
		4	0.00	0.05	0.00	0.00	0.00	-0.15
	2	3	0.00	4.38	0.00	0.00	0.00	68.28
		4	0.00	-4.38	0.00	0.00	0.00	24.31
	3	3	0.00	3.77	0.00	0.00	0.00	57.86
		4	0.00	-3.77	0.00	0.00	0.00	21.68
	4	3	0.00	2.57	0.00	0.00	0.00	39.71
		4	0.00	-2.57	0.00	0.00	0.00	14.57
4	1	4	0.00	0.08	0.00	0.00	0.00	0.15
		5	0.00	0.10	0.00	0.00	0.00	-0.38
	2	4	0.00	-2.51	0.00	0.00	0.00	-24.31
		5	0.00	2.51	0.00	0.00	0.00	-32.56
	3	4	0.00	-2.37	0.00	0.00	0.00	-21.68
		5	0.00	2.37	0.00	0.00	0.00	-31.86
	4	4	0.00	-1.56	0.00	0.00	0.00	-14.57
		5	0.00	1.56	0.00	0.00	0.00	-20.68
5	1	5	0.00	0.09	0.00	0.00	0.00	0.38
		6	0.00	-0.04	0.00	0.00	0.00	0.04
	2	5	0.00	12.06	0.00	0.00	0.00	32.56
		6	0.00	-12.06	0.00	0.00	0.00	45.02
	3	5	0.00	12.02	0.00	0.00	0.00	31.86
		6	0.00	-12.02	0.00	0.00	0.00	45.46
	4	5	0.00	7.75	0.00	0.00	0.00	20.68
		6	0.00	-7.75	0.00	0.00	0.00	29.16
6	1	6	0.00	0.04	0.00	0.00	0.00	-0.04
		7	0.00	0.09	0.00	0.00	0.00	-0.32

MEMBER END FORCES STRUCTURE TYPE = PLANE

13/37

 ALL UNITS ARE -- KIPS INCH

MEMB	LOAD	JT	AXIAL	SHEAR-Y	SHEAR-Z	TORSION	MOM-Y	MOM-Z
2	6	6	0.00	-3.94	0.00	0.00	0.00	-45.02
		7	0.00	3.94	0.00	0.00	0.00	-16.75
3	6	6	0.00	-3.98	0.00	0.00	0.00	-45.46
		7	0.00	3.98	0.00	0.00	0.00	-16.94
4	6	6	0.00	-2.55	0.00	0.00	0.00	-29.16
		7	0.00	2.55	0.00	0.00	0.00	-10.86
7	1	7	0.00	0.09	0.00	0.00	0.00	0.32
		8	0.00	0.08	0.00	0.00	0.00	-0.26
	2	7	0.00	1.00	0.00	0.00	0.00	16.75
		8	0.00	-1.00	0.00	0.00	0.00	5.16
	3	7	0.00	1.01	0.00	0.00	0.00	16.94
		8	0.00	-1.01	0.00	0.00	0.00	5.21
	4	7	0.00	0.65	0.00	0.00	0.00	10.86
		8	0.00	-0.65	0.00	0.00	0.00	3.34
8	1	8	0.00	0.07	0.00	0.00	0.00	0.26
		9	0.00	0.03	0.00	0.00	0.00	0.00
	2	8	0.00	-0.41	0.00	0.00	0.00	-5.16
		9	0.00	0.41	0.00	0.00	0.00	0.00
	3	8	0.00	-0.41	0.00	0.00	0.00	-5.21
		9	0.00	0.41	0.00	0.00	0.00	0.00
	4	8	0.00	-0.26	0.00	0.00	0.00	-3.34
		9	0.00	0.26	0.00	0.00	0.00	0.00

***** END OF LATEST ANALYSIS RESULT *****

39. FINISH

***** END OF STAAD-III *****

**** DATE= OCT 23,1995 TIME= 9:16:49 ****

 * For questions on STAAD-III/ISDS, contact: *
 * RESEARCH ENGINEERS, Inc at *
 * Ph: (714) 974-2500 Fax: (714) 974-4771 *



PROJECT T-649 OVER CSX Railroad. COMP. BY DCF DATE 10/17/95
SAI Be. No. 1062 BMS. No. 04 7210 0649 8302 PROPOSAL OR JOB NO. 9501 CHK'D BY AA DATE 10-25-95

SPAN 2 - STRINGER (S2) ANALYSIS

TIMBERS =

$$\text{Avg Spacing} = \left(\frac{3.375 + 2.083}{2} \right) = 2.729'$$

$$\text{Moment Distribution Factor (One Lane)} = \frac{S}{4.0} = \frac{2.729'}{4.0(2)} = 0.341 \text{ lanes}$$

$$\text{Shear Dist. Factor} = 0.5 (0.6 \text{ whls} + 2(0.341 \text{ lanes})) = 0.641 \text{ whls} / 2 = 0.321 \text{ lanes. (AASHTO 13.3.1)}$$

Live Load Moments (Based on AASHTO Table of Moments - 1.0 lanes dist. Factor).

$$M_{H20} = 120.0 \text{ k}' (l=15')$$

$$128.0 \text{ k}' (l=16')$$

$$\therefore M_{H20} = 0.341 (123.3 \text{ k}') = \underline{42.0 \text{ k}'}$$

$$M_{HS20} = \text{same as H20} = \underline{42.0 \text{ k}'}$$

$$M_{ML50} = 149.35 \text{ k}' (l=15')$$

$$164.8 \text{ k}' (l=16')$$

$$M_{ML50} = 0.341 (155.79 \text{ k}') = \underline{53.12 \text{ k}'}$$



PROJECT T-649 OVER CSX Railroad

COMP. BY DCT DATE 10/18/95


SAI BR. No. 1062 BNS. No. 04 7210 0649 8302

PROPOSAL OR JOB NO 9501

CHK'D BY AA DATE 10-25-95

SPAN 2 - STRINGER (S2)

COMPUTE LIVE LOAD SHEAR: (AASHTO 13.3.1)



$$P_{MLBO} = 20.6^k$$

$$P_{H20} = 32^k$$

Place wheels 3D or $\frac{1}{4}l$ away from support, whichever is smaller.

$$3(15.5'') = 46.5'' = 3.875'$$

$$\frac{1}{4}(15.4167') = 3.854' \leftarrow \text{governs.}$$

$$H20 \& HS20 \quad R_A = \left(\frac{11.563'}{15.417'} \right) (P) = 0.75P$$

$$MLBO \quad R_A = \left(\frac{11.563' + 7.563' + 3.563'}{15.417'} \right) P = 1.472P$$

$$V_{H20} = V_{HS20} = 0.321 \text{ lanes } (0.75)(32^k) = 7.70^k$$

$$V_{MLBO} = 0.321 \text{ lanes } (1.472)(20.6^k) = 9.73^k$$

DEAD LOAD:

$$W_{DL} = 0.011^k/\text{s.f.} (2.729') + 0.042^k/\text{ft} + 0.007^k/\text{ft}$$

$$= 0.079^k/\text{ft}$$

INDEX NO. _____

SHEET NO. 16 OF 37

PROJECT T-649 OVER CSX Railroad COMP. BY DCT DATE: 10/17/95
 SAI BR. No. 1062 BMS. No. 04 7210 0649 8302 CHK'D BY AA DATE 10-25-95

Analysis of Timber Stringer (Span 2 Stringer S2) :

$$\text{kip} := 1000 \cdot \text{lbf} \quad \text{ksi} := 1000 \cdot \frac{\text{lbf}}{\text{in}^2} \quad \text{fbwood} := 1400 \cdot \text{psi} \quad \text{vallow} := 105 \cdot \text{psi}$$

$$\text{Depth} := 15.5 \cdot \text{in}$$

Depth = Depth of Beam

$$\text{width} := 7.75 \cdot \text{in}$$

Width = Width of Beam

$$\text{spanlength} := 15.4167 \cdot \text{ft}$$

spanlength = span length being investigated

Moment and Shears:

$$\text{Dead Loads:} \quad \text{wdl} := 0.079 \cdot \frac{\text{kip}}{\text{ft}}$$

$$\text{Mdl} := \frac{\text{wdl} \cdot \text{spanlength}^2}{8}$$

$$\text{Vdl} := \frac{\text{wdl} \cdot \text{spanlength}}{2} - (3 \cdot \text{Depth}) \cdot \text{wdl}$$

$$\text{Mdl} = 2.35 \cdot \text{kip} \cdot \text{ft}$$

$$\text{Vdl} = 0.3 \cdot \text{kip}$$

Live Loads:

$$\text{Vh20} := 7.7 \cdot \text{kip}$$

$$\text{Mh20} := 42.0 \cdot \text{kip} \cdot \text{ft}$$

$$\text{Vhs20} := 7.7 \cdot \text{kip}$$

$$\text{Mhs20} := 42.0 \cdot \text{kip} \cdot \text{ft}$$

$$\text{Vml80} := 9.73 \cdot \text{kip}$$

$$\text{Mml80} := 53.12 \cdot \text{kip} \cdot \text{ft}$$

$$S := \frac{\text{width} \cdot \text{Depth}^2}{6} \quad S = 310.32 \cdot \text{in}^3$$

$$\text{Av} := \text{width} \cdot \text{Depth}$$

$$\text{Av} = 120.13 \cdot \text{in}^2$$

Allowables:

$$\text{Mallow} := \text{fbwood} \cdot S$$

$$\text{Mallow} = 36.2 \cdot \text{kip} \cdot \text{ft}$$

$$\text{Vallow} := \frac{2}{3} \cdot \text{vallow} \cdot \text{Av}$$

$$\text{Vallow} = 8.41 \cdot \text{kip}$$

(Horizontal Shear Allowable)

INDEX NO. _____

SHEET NO. 17 OF 37

PROJECT T-649 over CSX Railroad COMP. BY DCT DATE: 10/17/95
 SAI Br. No. 1062 BUS. No. 04 7210 0649 8302 CHK'D BY AA DATE 10-25-95

Moment Rating Factors:

$$\text{H20: IRF} := \frac{\text{Mallow} - \text{Mdl}}{\text{Mh20}} \quad \text{IRF} = 0.81 \quad \text{IRF} \cdot 20 = 16.12 \quad \text{tons}$$

$$\text{ORF} := \frac{\text{Mallow} \cdot 1.33 - \text{Mdl}}{\text{Mh20}} \quad \text{ORF} = 1.09 \quad \text{ORF} \cdot 20 = 21.81 \quad \text{tons}$$

$$\text{HS20: Same as H20} \quad \text{IRF} \cdot 36 = 29.02 \quad \text{tons}$$

$$\text{ORF} \cdot 36 = 39.26 \quad \text{tons}$$

$$\text{ML80: IRF} := \frac{\text{Mallow} - \text{Mdl}}{\text{Mml80}} \quad \text{IRF} = 0.64 \quad \text{IRF} \cdot 37.74 = 24.05 \quad \text{tons}$$

$$\text{ORF} := \frac{\text{Mallow} \cdot 1.33 - \text{Mdl}}{\text{Mml80}} \quad \text{ORF} = 0.86 \quad \text{ORF} \cdot 37.74 = 32.54 \quad \text{tons}$$

Horizontal Shear Rating Factors:

$$\text{H20: IRF} := \frac{\text{Vallow} - \text{Vdl}}{\text{Vh20}} \quad \text{IRF} = 1.05 \quad \text{IRF} \cdot 20 = 21.05 \quad \text{tons}$$

$$\text{ORF} := \frac{\text{Vallow} \cdot 1.33 - \text{Vdl}}{\text{Vh20}} \quad \text{ORF} = 1.41 \quad \text{ORF} \cdot 20 = 28.26 \quad \text{tons}$$

$$\text{HS20: IRF} := \frac{\text{Vallow} - \text{Vdl}}{\text{Vhs20}} \quad \text{IRF} = 1.05 \quad \text{IRF} \cdot 36 = 37.9 \quad \text{tons}$$

$$\text{ORF} := \frac{\text{Vallow} \cdot 1.33 - \text{Vdl}}{\text{Vhs20}} \quad \text{ORF} = 1.41 \quad \text{ORF} \cdot 36 = 50.87 \quad \text{tons}$$

INDEX NO. _____

SHEET NO. 18 OF 37

PROJECT T-649 over CSX Railroad COMP. BY DCT DATE: 10/17/95

SAI Br. No. 1062 BUS. No. 04 720 0649 8302 CHK'D BY AA DATE 10-25-95

ML80:
$$\text{IRF} := \frac{V_{\text{allow}} - V_{\text{dl}}}{V_{\text{ml80}}} \quad \text{IRF} = 0.83 \quad \text{IRF} \cdot 37.74 = 31.44 \quad \text{tons}$$

$$\text{ORF} := \frac{V_{\text{allow}} \cdot 1.33 - V_{\text{dl}}}{V_{\text{ml80}}} \quad \text{ORF} = 1.12 \quad \text{ORF} \cdot 37.74 = 42.2 \quad \text{tons}$$

PROJECT T-649 OVER CSX RailroadCOMP. BY DJT DATE 10/18/95SAI BR. No. 1062 BMS No. 04 7210 0649 8302PROPOSAL OR JOB NO. 9501CHK'D BY AA DATE 10-25-95SPAN 4 - STRINGER (S5)

(TIMBER)

$$\text{Avg Spacing} = \left(\frac{2.146' + 3.438'}{2} \right) = 2.79'$$

$$\text{Span Length} = \underline{14'-2''}$$

DISTRIBUTION FACTORS:

$$\text{Moment: } \frac{S}{4.0} = \frac{2.79'}{4(2)} = 0.349 \text{ lanes}$$

$$\text{Shear: } 0.5(0.6 \text{ wheels} + 2(0.349 \text{ lanes})) = 0.649 \text{ whl} / 2 = 0.325 \text{ lanes.}$$

(AASHTO 13.3.1)

Live Loads:

Moment: (Based on AASHTO Table of Moments 1.0 lanes Dist. Factor).

$$M_{H20} = M_{HS20} = 113.3 \text{ k}' (0.349 \text{ lanes}) = 39.5 \text{ k}'$$

$$M_{ML80} = 136.5 \text{ k}' (0.349 \text{ lanes}) = 47.6 \text{ k}'$$

Shear: (AASHTO 13.3.1). Place wheels 3D from support = $3\left(\frac{11.5}{12}\right) = 2.81'$

$$V_{H20} = V_{HS20} = 0.325 \text{ lanes} \left(\frac{14.167' - 2.81'}{14.167'} \right) (32 \text{ k}) = 8.34 \text{ k}$$

$$V_{ML80} = 0.325 \text{ lanes} \left(\frac{11.357' + 7.357' + 3.357'}{14.167'} \right) (20.6 \text{ k}) = 10.43 \text{ k}$$

DEAD LOAD

$$W_{DL} = 0.011 \text{ k/ft} (2.79') + 0.046 \text{ k/ft} + 0.007 \text{ k/ft}$$

$$= 0.084 \text{ k/ft}$$

$$\text{Impact} = 1.30$$

INDEX NO. _____

SHEET NO. 20 OF 37

PROJECT T-649 OVER CSX Railroad COMP. BY DCT DATE: 10/17/95
 SAT. BA. No. 1062 BMS No. 04 7210 0649 8302 CHK'D BY AA DATE 10-25-95

Analysis of Timber Stringer (Span 4 Stringer S5) :

$$\text{kip} := 1000 \cdot \text{lbf} \quad \text{ksi} := 1000 \cdot \frac{\text{lbf}}{\text{in}^2} \quad \text{fbwood} := 1400 \cdot \text{psi} \quad \text{vhallow} := 105 \cdot \text{psi}$$

$$\text{Depth} := 11.5 \cdot \text{in}$$

Depth = Depth of Beam

$$\text{width} := 11.5 \cdot \text{in}$$

Width = Width of Beam

$$\text{spanlength} := 14.167 \cdot \text{ft}$$

spanlength = span length being investigated

Moment and Shears:

$$\text{Dead Loads:} \quad \text{wdl} := 0.084 \cdot \frac{\text{kip}}{\text{ft}}$$

$$\text{Mdl} := \frac{\text{wdl} \cdot \text{spanlength}^2}{8}$$

$$\text{Vdl} := \frac{\text{wdl} \cdot \text{spanlength}}{2} - (3 \cdot \text{Depth}) \cdot \text{wdl}$$

$$\text{Mdl} = 2.11 \cdot \text{kip} \cdot \text{ft}$$

$$\text{Vdl} = 0.35 \cdot \text{kip}$$

Live Loads:

$$\text{Vh20} := 8.34 \cdot \text{kip}$$

$$\text{Mh20} := 39.5 \cdot \text{kip} \cdot \text{ft}$$

$$\text{Vhs20} := 8.34 \cdot \text{kip}$$

$$\text{Mhs20} := 39.5 \cdot \text{kip} \cdot \text{ft}$$

$$\text{Vml80} := 10.43 \cdot \text{kip}$$

$$\text{Mml80} := 47.6 \cdot \text{kip} \cdot \text{ft}$$

$$S := \frac{\text{width} \cdot \text{Depth}^2}{6} \quad S = 253.48 \cdot \text{in}^3$$

$$\text{Av} := \text{width} \cdot \text{Depth}$$

$$\text{Av} = 132.25 \cdot \text{in}^2$$

Allowables:

$$\text{Mallow} := \text{fbwood} \cdot S \quad \text{Mallow} = 29.57 \cdot \text{kip} \cdot \text{ft}$$

$$\text{Vallow} := \frac{2}{3} \cdot \text{vhallow} \cdot \text{Av} \quad \text{Vallow} = 9.26 \cdot \text{kip} \quad (\text{Horizontal Shear Allowable})$$

PROJECT T-649 OVER CSX Railroad COMP. BY DCT DATE: 10/17/95
 SAI Br. No. 1062 BMS. No. 04 720 0649 8302 CHK'D BY AA DATE 10-25-95

Moment Rating Factors:

$$\text{H20: IRF} := \frac{\text{Mallow} - \text{Mdl}}{\text{Mh20}} \quad \text{IRF} = 0.7 \quad \text{IRF} \cdot 20 = 13.91 \quad \text{tons}$$

$$\text{ORF} := \frac{\text{Mallow} \cdot 1.33 - \text{Mdl}}{\text{Mh20}} \quad \text{ORF} = 0.94 \quad \text{ORF} \cdot 20 = 18.85 \quad \text{tons}$$

$$\text{HS20: Same as H20} \quad \text{IRF} \cdot 36 = 25.03 \quad \text{tons}$$

$$\text{ORF} \cdot 36 = 33.93 \quad \text{tons}$$

$$\text{ML80: IRF} := \frac{\text{Mallow} - \text{Mdl}}{\text{Mml80}} \quad \text{IRF} = 0.58 \quad \text{IRF} \cdot 37.74 = 21.78 \quad \text{tons}$$

$$\text{ORF} := \frac{\text{Mallow} \cdot 1.33 - \text{Mdl}}{\text{Mml80}} \quad \text{ORF} = 0.78 \quad \text{ORF} \cdot 37.74 = 29.51 \quad \text{tons}$$

Horizontal Shear Rating Factors:

$$\text{H20: IRF} := \frac{\text{Vallow} - \text{Vdl}}{\text{Vh20}} \quad \text{IRF} = 1.07 \quad \text{IRF} \cdot 20 = 21.35 \quad \text{tons}$$

$$\text{ORF} := \frac{\text{Vallow} \cdot 1.33 - \text{Vdl}}{\text{Vh20}} \quad \text{ORF} = 1.43 \quad \text{ORF} \cdot 20 = 28.68 \quad \text{tons}$$

$$\text{HS20: IRF} := \frac{\text{Vallow} - \text{Vdl}}{\text{Vhs20}} \quad \text{IRF} = 1.07 \quad \text{IRF} \cdot 36 = 38.43 \quad \text{tons}$$

$$\text{ORF} := \frac{\text{Vallow} \cdot 1.33 - \text{Vdl}}{\text{Vhs20}} \quad \text{ORF} = 1.43 \quad \text{ORF} \cdot 36 = 51.62 \quad \text{tons}$$

INDEX NO. _____

SHEET NO. 22 OF 37

PROJECT T-649 OVER CSX Railroad COMP. BY DCT DATE: 10/17/95

SAI. Be No. 1062 BMS. No. 04 7210 0649 8302 CHK'D BY AA DATE 10-25-95

ML80: $IRF := \frac{V_{allow} - V_{dl}}{V_{ml80}}$ IRF = 0.85 IRF · 37.74 = 32.22 tons

ORF := $\frac{V_{allow} \cdot 1.33 - V_{dl}}{V_{ml80}}$ ORF = 1.15 ORF · 37.74 = 43.27 tons

PROJECT T-649 OVER CSX RailroadCOMP. BY DCT DATE 10/18/95SAT Br. No. 1062 BMS. No. 04 7210 0649 8302PROPOSAL OR JOB NO. 9501CHK'D BY AA DATE 10-25-95SPAN 5 - STRINGER (S3) (TIMBER)

$$\text{Avg Spacing} = \left(\frac{2.354' + 4.385'}{2} \right) = 3.370'$$

$$\text{Span Length} = \underline{13'-10''}$$

DISTRIBUTION FACTORS:

$$\text{Moment} = \frac{S}{4.0} = \frac{3.370'}{4(2)} = 0.421 \text{ lanes.}$$

$$\text{Shear: (AASHTO 13.3.1)} = 0.5 (0.6 \text{ wheels} + 2(0.421 \text{ lanes})) = 0.721 \text{ whls} / 2 = 0.361 \text{ lanes.}$$

Live Loads:

Moment: (Based on AASHTO Table of Moments D.F. = 1.0 lanes)

$$M_{HL20} = M_{HS20} = 0.421 \text{ lanes } (110.67 \text{ k}') = 46.6 \text{ k}'$$

$$M_{ML80} = 0.421 \text{ lanes } (131.32 \text{ k}') = 55.3 \text{ k}'$$

Shear: (AASHTO 13.3.1) Place wheels 3D away from support = $3 \left(\frac{13.75}{12} \right) = 3.44'$

$$V_{HL20} = V_{HS20} = 0.361 \text{ lanes } (32 \text{ k}') \left(\frac{13.83' - 3.44'}{13.83'} \right) = 8.7 \text{ k}$$

$$V_{ML80} = 0.361 \text{ lanes } (20.6 \text{ k}') \left(\frac{10.396' + 6.396' + 2.396'}{13.83'} \right) = 10.3 \text{ k}$$

DEAD LOADS:

$$\begin{aligned} W_{DL} &= 0.011 \text{ k/ft}^2 (3.37') + 0.056 \text{ k/ft} + 0.007 \text{ k/ft} \\ &= 0.100 \text{ k/ft} \end{aligned}$$

INDEX NO. _____

SHEET NO. 24 OF 37

PROJECT T-649 OVER CSX Railroad COMP. BY DCT DATE: 10/17/95
 SAI BR. No. 1062 BMS. No. 04 7210 0649 8302 CHK'D BY AA DATE 10-25-95

Analysis of Timber Stringer (Span 5 Stringer S3) :

$$\text{kip} := 1000 \cdot \text{lbf} \quad \text{ksi} := 1000 \cdot \frac{\text{lbf}}{\text{in}^2} \quad \text{fbwood} := 1400 \cdot \text{psi} \quad \text{vallow} := 105 \cdot \text{psi}$$

$$\begin{aligned} \text{Depth} &:= 13.75 \cdot \text{in} & \text{Depth} &= \text{Depth of Beam} \\ \text{width} &:= 11.75 \cdot \text{in} & \text{Width} &= \text{Width of Beam} \\ \text{spanlength} &:= 13.83 \cdot \text{ft} & \text{spanlength} &= \text{span length being investigated} \end{aligned}$$

Moment and Shears:

$$\text{Dead Loads:} \quad \text{wdl} := 0.100 \cdot \frac{\text{kip}}{\text{ft}}$$

$$\text{Mdl} := \frac{\text{wdl} \cdot \text{spanlength}^2}{8} \quad \text{Vdl} := \frac{\text{wdl} \cdot \text{spanlength}}{2} - (3 \cdot \text{Depth}) \cdot \text{wdl}$$

$$\text{Mdl} = 2.39 \cdot \text{kip} \cdot \text{ft} \quad \text{Vdl} = 0.35 \cdot \text{kip}$$

Live Loads:

$$\begin{aligned} \text{Vh20} &:= 8.7 \cdot \text{kip} & \text{Mh20} &:= 46.6 \cdot \text{kip} \cdot \text{ft} \\ \text{Vhs20} &:= 8.7 \cdot \text{kip} & \text{Mhs20} &:= 46.6 \cdot \text{kip} \cdot \text{ft} \\ \text{Vml80} &:= 10.3 \cdot \text{kip} & \text{Mml80} &:= 55.3 \cdot \text{kip} \cdot \text{ft} \end{aligned}$$

$$\begin{aligned} S &:= \frac{\text{width} \cdot \text{Depth}^2}{6} & S &= 370.25 \cdot \text{in}^3 & \text{Av} &:= \text{width} \cdot \text{Depth} \\ & & & & \text{Av} &= 161.56 \cdot \text{in}^2 \end{aligned}$$

Allowables:

$$\text{Mallow} := \text{fbwood} \cdot S \quad \text{Mallow} = 43.2 \cdot \text{kip} \cdot \text{ft}$$

$$\text{Vallow} := \frac{2}{3} \cdot \text{vallow} \cdot \text{Av} \quad \text{Vallow} = 11.31 \cdot \text{kip} \quad (\text{Horizontal Shear Allowable})$$

PROJECT T-649 over CSX RailroadCOMP. BY DCJ DATE: 10/17/95SAT. Be. No. 1062 BMS. No. 04 720 0649 8302CHK'D BY AA DATE 10-25-95**Moment Rating Factors:**

$$\text{H20: IRF} := \frac{\text{Mallow} - \text{Mdl}}{\text{Mh20}} \quad \text{IRF} = 0.88 \quad \text{IRF} \cdot 20 = 17.51 \quad \text{tons}$$

$$\text{ORF} := \frac{\text{Mallow} \cdot 1.33 - \text{Mdl}}{\text{Mh20}} \quad \text{ORF} = 1.18 \quad \text{ORF} \cdot 20 = 23.63 \quad \text{tons}$$

$$\text{HS20: Same as H20} \quad \text{IRF} \cdot 36 = 31.52 \quad \text{tons}$$

$$\text{ORF} \cdot 36 = 42.53 \quad \text{tons}$$

$$\text{ML80: IRF} := \frac{\text{Mallow} - \text{Mdl}}{\text{Mml80}} \quad \text{IRF} = 0.74 \quad \text{IRF} \cdot 37.74 = 27.85 \quad \text{tons}$$

$$\text{ORF} := \frac{\text{Mallow} \cdot 1.33 - \text{Mdl}}{\text{Mml80}} \quad \text{ORF} = 1 \quad \text{ORF} \cdot 37.74 = 37.58 \quad \text{tons}$$

Horizontal Shear Rating Factors:

$$\text{H20: IRF} := \frac{\text{Vallow} - \text{Vdl}}{\text{Vh20}} \quad \text{IRF} = 1.26 \quad \text{IRF} \cdot 20 = 25.2 \quad \text{tons}$$

$$\text{ORF} := \frac{\text{Vallow} \cdot 1.33 - \text{Vdl}}{\text{Vh20}} \quad \text{ORF} = 1.69 \quad \text{ORF} \cdot 20 = 33.78 \quad \text{tons}$$

$$\text{HS20: IRF} := \frac{\text{Vallow} - \text{Vdl}}{\text{Vhs20}} \quad \text{IRF} = 1.26 \quad \text{IRF} \cdot 36 = 45.36 \quad \text{tons}$$

$$\text{ORF} := \frac{\text{Vallow} \cdot 1.33 - \text{Vdl}}{\text{Vhs20}} \quad \text{ORF} = 1.69 \quad \text{ORF} \cdot 36 = 60.8 \quad \text{tons}$$

INDEX NO. _____

SHEET NO. 26 OF 37

PROJECT T-649 over CSX Railroad COMP. BY DET DATE: 10/17/95

S&L BR. No. 1062 BMS. No. 04 7210 0649 8302 CHK'D BY AA DATE 10-25-95

ML80: $IRF := \frac{V_{allow} - V_{dl}}{V_{ml80}}$ IRF = 1.06 IRF · 37.74 = 40.16 tons

ORF := $\frac{V_{allow} \cdot 1.33 - V_{dl}}{V_{ml80}}$ ORF = 1.43 ORF · 37.74 = 53.84 tons



PROJECT T-649 OVER CSX Railroad

COMP. BY DCT DATE 10/18/95

SAI Be. No. 1062 BMS. No. 04 7210 0649 8302 PROPOSAL OR JOB NO 9501

CHK'D BY AA DATE 10-25-95

SPAN 3 - STEEL STRINGERS

Span Length = 35'-1"

7 Stringers with spacing ranging from 2'-0³/₄" to 2'-3¹/₂"

2³/₄" Deck Planking

8'4" x 4'4" Curb Blocks

2-L3x2¹/₂x¹/₄" Railings

L3x2¹/₂x¹/₄" Post @ 7' Spacing

ANALYZE STRINGER (S6)

$$\text{Avg. Spacing} = \left(\frac{2.29' + 2.23'}{2} \right) = 2.26'$$

DEAD LOADS:

$$W_{DL} = 0.011 \text{ k/ft} \uparrow \text{Deck} (2.26') + 0.007 \text{ k/ft} \uparrow \text{Curb \& Rails} = 0.032 \text{ k/ft}$$

Live Load Distribution Factors

$$\text{Moment: } \frac{S}{4} < \frac{2.26'}{4(2)} = 0.283 \text{ lanes.}$$

Shear: 0.50 lanes.

Deflection: 1 lane / 7 beams = 0.143 lanes.

Section Properties:

(Based on Inspection Measurements by SAI "95" Inspection Report)

24 WF 144: A = 42.38 in² t_f = (m = 1.272" n = 0.725")
 d = 25.88 in I = 4983.4 in⁴
 t_w = 0.610 in
 b_f = 13.73 in

BRIDGE ANALYSIS AND RATING (BAR7)

29/37
330376

PROGRAM P4353000

10/18/95 11:41

VERSION 7.5

LAST UPDATED 12/06/94

DOCUMENTATION 12/94

INPUT: T649.DAT

AA 10-25-95

STRUCTURE ID - T649 OVER CSX RAILROAD

BRIDGE TYPE	SLC LEVEL	LIVE LANES	LIVE LOAD	OUTPUT	IMPACT FACTOR	GAGE DIST	PASS DIST	CONC	FATIGUE	DECK SPEC	REDIST	DIR
GGG	0		H	3	0.00	0.0	0.0					

BRIDGE CROSS SECTION AND LOADING

DECK WIDTH	OVERHANG OR SPACING	CL OF GIRDER OR TRUSS TO CURB	ROADWAY WIDTH	DISTRIBUTION FACTORS		
				SHEAR	MOMENT	DEFLECT
0.00	2.26	0.00	0.00	0.500	0.283	0.143

SLAB THICKNESS	HAUNCH	DEAD LOADS		F'C	N	SYMMETRY
		DL1	DL2			
0.00	0.00	0.032	0.000	0.000	0.	Y

STRINGER DL1	FLOORBEAM DL1
0.000	0.000

SPAN LENGTHS (SIMPLE)

SPAN #	LENGTH
1	35.08

STEEL MEMBER PROPERTIES

S	T	WF BM	WF BM	FLANGE		WF BM						
G P	Y	M OF I	AREA	OR		V	OR WEB					
F A	P	OR VRT	OR HRZ	ANGLE	FLANGE	A	PLATE	WEB				
S N	RANGE	E	LEG	LEG	THICK	WIDTH	R	DEPTH	THICK			
G 1	17.54	W	4983.40	42.38	0.7250	13.730		25.88	0.6100			
			TPW	TPT	BPW	BPT	COMP	FY	FY TOP	FY BOT	CG TOP	CG BOT
			0.00	0.0000	0.00	0.0000	N	30.0	0.0	0.0	0.000	0.000

LATERAL BRACE POINTS AND STIFFENER SPACINGS

B OR S	C	O	NO.	C	O	NO.	C	O	NO.	C	O	NO.	
G OR F	D	OF	E	D	OF	E	D	OF	E	D	OF	E	
CODE	SPAN	SPCS	SPACING	SPCS	SPACING	SPCS	SPACING	SPCS	SPACING	SPCS	SPACING	SPCS	
BG	1	T	1	1.33	T	1	6.00	T	1	5.83	T	1	1.96
		T	1	6.08	T	1	6.00	T	1	1.75	T	1	4.75
G	1	T	1	1.33	B	1	35.08		0	0.00		0	0.00
			0	0.00		0	0.00		0	0.00		0	0.00

DEFAULT VALUES

SLC	GAGE	PASSING
LEVEL	DISTANCE	DISTANCE
I	6.0	4.0

```

+++++
+
+   G I R D E R   A N A L Y S I S   +
+
+++++
  
```

DEAD LOADS ACTING ON GIRDER

INPUT	GIRDER	SLAB	FL BEAM	STRINGER	FL BEAM	STRINGER	TOTAL	TOTAL
DL1	WEIGHT	WEIGHT	WEIGHT	WEIGHT	DL1	DL1	DL1	DL2
0.032	0.144	0.000	0.000	0.000	0.000	0.000	0.176	0.000

NOTE: IF A SECTION DOES NOT MEET FLANGE OR WEB BUCKLING CRITERIA OF CURRENT AASHTO SPECIFICATIONS FOR LOAD FACTOR METHOD, THE RATING FACTORS ARE REPRINTED AS 888.88. THIS INDICATES THAT THERE IS A POTENTIAL FATIGUE PROBLEM.

GIRDER SECTION PROPERTIES

NON-COMPOSITE	DEPTH	GROSS AREA	MOMENT OF INERTIA	C BOTTOM	SECTION TOP	MODULUS BOTTOM
	25.88	42.38	4983.40	12.94	385.12	385.12

```

*****
* GIRDER - LIVE LOAD H20 *
*****
  
```

MAXIMUM REACTIONS

SUPPORT	DL1	DL2	+(LL+I)	-(LL+I)	I.F.
1	3.1	0.0	22.6	0.0	1.30

NOTE: ALL SUPPORT REACTIONS AND END SHEARS IN EACH SPAN DUE TO A LIVE LOAD ARE CALCULATED BASED ON AASHTO ARTICLE 3.23.1 AS INTERPRETED IN SOL 431-93-05.

UNFACTORED MOMENTS AND SHEARS

SPAN 1 - LIVE LOAD IMPACT FACTORS : POS MOM 1.30 NEG MOM 0.00

X	DL1	DL2	+(LL+I)	-(LL+I)	DL1	DL2	+(LL+I)	-(LL+I)	I.F.
	MOMENT	MOMENT	MOMENT	MOMENT	SHEAR	SHEAR	SHEAR	SHEAR	
0.00	0.0	0.0	0.0	0.0	3.1	0.0	22.6	0.0	1.30
	SIMULT	SHEAR	0.0	0.0	SIMULT	MOM	0.0	0.0	
3.51	9.8	0.0	42.3	0.0	2.5	0.0	12.1	-1.2	1.30
	SIMULT	SHEAR	12.1	0.0	SIMULT	MOM	42.3	37.2	
7.02	17.3	0.0	74.4	0.0	1.9	0.0	10.6	-2.4	1.30
	SIMULT	SHEAR	10.6	0.0	SIMULT	MOM	74.4	66.1	
10.52	22.8	0.0	96.0	0.0	1.2	0.0	9.1	-3.5	1.30
	SIMULT	SHEAR	9.1	0.0	SIMULT	MOM	96.0	86.7	

14.03	26.0	0.0	107.4	0.0	0.6	0.0	7.7	-4.7	1.30
	SIMULT	SHEAR	7.7	0.0	SIMULT	MOM	107.4	99.2	
17.54	27.1	0.0	108.5	0.0	0.0	0.0	6.2	-6.2	1.30
	SIMULT	SHEAR	6.2	0.0	SIMULT	MOM	108.5	108.5	

STRENGTHS AND LOAD FACTOR RATINGS

SPAN 1
=====

X	MAX MOM STRENGTH	SERVICE STRENGTH	SHEAR STRENGTH	RATING FACTORS	
				IR	OR
0.00	853.5	C 770.2	259.3	5.22 V	8.70 V
3.51	853.5	C 770.2	259.3	9.17 T	15.28 T
7.02	853.5	C 770.2	259.3	5.16 T	8.60 T
10.52	853.5	C 770.2	259.3	3.96 T	6.60 T
14.03	853.5	C 770.2	259.3	3.52 T	5.87 T
17.54	853.5	C 770.2	259.3	3.48 T	5.80 T

* GIRDER - LIVE LOAD HS20 *

MAXIMUM REACTIONS

SUPPORT	DL1	DL2	+(LL+I)	-(LL+I)	I.F.
1	3.1	0.0	28.5	0.0	1.30

NOTE: ALL SUPPORT REACTIONS AND END SHEARS IN EACH SPAN DUE TO A LIVE LOAD ARE CALCULATED BASED ON AASHTO ARTICLE 3.23.1 AS INTERPRETED IN SOL 431-93-05.

UNFACTORED MOMENTS AND SHEARS

SPAN 1 - LIVE LOAD IMPACT FACTORS : POS MOM 1.30 NEG MOM 0.00
=====

X	MOMENT				SHEAR				I.F.
	DL1	DL2	+(LL+I)	-(LL+I)	DL1	DL2	+(LL+I)	-(LL+I)	
0.00	0.0	0.0	0.0	0.0	3.1	0.0	28.5	0.0	1.30
	SIMULT	SHEAR	0.0	0.0	SIMULT	MOM	0.0	0.0	
3.51	9.8	0.0	58.9	0.0	2.5	0.0	16.8	-1.2	1.30
	SIMULT	SHEAR	16.8	0.0	SIMULT	MOM	58.9	37.2	
7.02	17.3	0.0	99.2	0.0	1.9	0.0	14.1	-2.4	1.30
	SIMULT	SHEAR	14.1	0.0	SIMULT	MOM	99.2	66.1	
10.52	22.8	0.0	124.0	0.0	1.2	0.0	11.8	-3.5	1.30
	SIMULT	SHEAR	11.8	0.0	SIMULT	MOM	124.0	86.7	
14.03	26.0	0.0	132.4	0.0	0.6	0.0	9.4	-4.7	1.30
	SIMULT	SHEAR	9.4	0.0	SIMULT	MOM	132.3	99.3	
17.54	27.1	0.0	129.3	0.0	0.0	0.0	7.1	-7.1	1.30
	SIMULT	SHEAR	-6.8	0.0	SIMULT	MOM	124.1	124.1	

STRENGTHS AND LOAD FACTOR RATINGS

SPAN 1
=====

MAX MOM	SERVICE	SHEAR	RATING	FACTORS
---------	---------	-------	--------	---------

X	STRENGTH	STRENGTH	STRENGTH	IR	OR
0.00	853.5 C	770.2	259.3	4.14 V	6.90 V
3.51	853.5 C	770.2	259.3	6.59 T	10.98 T
7.02	853.5 C	770.2	259.3	3.87 T	6.44 T
10.52	853.5 C	770.2	259.3	3.07 T	5.11 T
14.03	853.5 C	770.2	259.3	2.86 T	4.76 T
17.54	853.5 C	770.2	259.3	2.92 T	4.87 T

 * GIRDER - LIVE LOAD ML80 *

MAXIMUM REACTIONS

SUPPORT	DL1	DL2	+(LL+I)	-(LL+I)	I.F.
1	3.1	0.0	28.4	0.0	1.30

NOTE: ALL SUPPORT REACTIONS AND END SHEARS IN EACH SPAN DUE TO A LIVE LOAD ARE CALCULATED BASED ON AASHTO ARTICLE 3.23.1 AS INTERPRETED IN SOL 431-93-05.

UNFACTORED MOMENTS AND SHEARS

SPAN 1 - LIVE LOAD IMPACT FACTORS : POS MOM 1.30 NEG MOM 0.00

X	DL1 MOMENT	DL2 MOMENT	+(LL+I) MOMENT	-(LL+I) MOMENT	DL1 SHEAR	DL2 SHEAR	+(LL+I) SHEAR	-(LL+I) SHEAR	I.F.
0.00	0.0	0.0	0.0	0.0	3.1	0.0	28.4	0.0	1.30
	SIMULT	SHEAR	0.0	0.0	SIMULT	MOM	0.0	0.0	
3.51	9.8	0.0	69.5	0.0	2.5	0.0	19.8	-0.8	1.30
	SIMULT	SHEAR	19.8	0.0	SIMULT	MOM	69.5	23.9	
7.02	17.3	0.0	119.6	0.0	1.9	0.0	17.0	-2.2	1.30
	SIMULT	SHEAR	17.0	0.0	SIMULT	MOM	119.6	60.8	
10.52	22.8	0.0	153.1	0.0	1.2	0.0	14.3	-4.2	1.30
	SIMULT	SHEAR	9.9	0.0	SIMULT	MOM	150.1	103.8	
14.03	26.0	0.0	175.3	0.0	0.6	0.0	11.5	-6.5	1.30
	SIMULT	SHEAR	7.1	0.0	SIMULT	MOM	161.2	136.9	
17.54	27.1	0.0	178.0	0.0	0.0	0.0	8.8	-8.8	1.30
	SIMULT	SHEAR	4.3	0.0	SIMULT	MOM	153.9	153.9	

STRENGTHS AND LOAD FACTOR RATINGS

SPAN 1

X	MAX MOM STRENGTH	SERVICE STRENGTH	SHEAR STRENGTH	RATING IR	FACTORS OR
0.00	853.5 C	770.2	259.3	4.15 V	6.91 V
3.51	853.5 C	770.2	259.3	5.58 T	9.30 T
7.02	853.5 C	770.2	259.3	3.21 T	5.35 T
10.52	853.5 C	770.2	259.3	2.48 T	4.14 T
14.03	853.5 C	770.2	259.3	2.16 T	3.60 T
17.54	853.5 C	770.2	259.3	2.12 T	3.54 T

 * GIRDER - LIVE LOAD P-82 *

MAXIMUM REACTIONS

SUPPORT	DL1	DL2	+(LL+I)	-(LL+I)	I.F.
1	3.1	0.0	40.6	0.0	1.30

NOTE: ALL SUPPORT REACTIONS AND END SHEARS IN EACH SPAN DUE TO A LIVE LOAD ARE CALCULATED BASED ON AASHTO ARTICLE 3.23.1 AS INTERPRETED IN SOL 431-93-05.

UNFACTORED MOMENTS AND SHEARS

SPAN 1 - LIVE LOAD IMPACT FACTORS : POS MOM 1.30 NEG MOM 0.00

=====

X	DL1 MOMENT	DL2 MOMENT	+(LL+I) MOMENT	-(LL+I) MOMENT	DL1 SHEAR	DL2 SHEAR	+(LL+I) SHEAR	-(LL+I) SHEAR	I.F.
0.00	0.0	0.0	0.0	0.0	3.1	0.0	40.6	0.0	1.30
	SIMULT	SHEAR	0.0	0.0	SIMULT	MOM	0.0	0.0	
3.51	9.8	0.0	101.6	0.0	2.5	0.0	29.0	-1.0	1.30
	SIMULT	SHEAR	29.0	0.0	SIMULT	MOM	101.6	31.4	
7.02	17.3	0.0	175.3	0.0	1.9	0.0	25.0	-2.8	1.30
	SIMULT	SHEAR	25.0	0.0	SIMULT	MOM	175.3	79.7	
10.52	22.8	0.0	229.1	0.0	1.2	0.0	21.0	-5.5	1.30
	SIMULT	SHEAR	15.6	0.0	SIMULT	MOM	221.2	136.1	
14.03	26.0	0.0	263.0	0.0	0.6	0.0	17.0	-9.1	1.30
	SIMULT	SHEAR	11.6	0.0	SIMULT	MOM	239.2	191.5	
17.54	27.1	0.0	269.0	0.0	0.0	0.0	13.1	-13.1	1.30
	SIMULT	SHEAR	-7.7	0.0	SIMULT	MOM	229.3	229.3	

STRENGTHS AND LOAD FACTOR RATINGS

SPAN 1

=====

X	MAX MOM STRENGTH	SERVICE STRENGTH	SHEAR STRENGTH	RATING FACTORS	
				IR	OR
0.00	853.5 C	770.2	259.3	2.91 V	4.84 V
3.51	853.5 C	770.2	259.3	3.82 T	6.37 T
7.02	853.5 C	770.2	259.3	2.19 T	3.65 T
10.52	853.5 C	770.2	259.3	1.66 T	2.77 T
14.03	853.5 C	770.2	259.3	1.44 T	2.40 T
17.54	853.5 C	770.2	259.3	1.40 T	2.34 T

++++
+
+ R A T I N G S U M M A R Y +
+
++++

MEMBER: GIRDER

LOAD FACTOR RATING

LOAD	IR	TONS	X	SPAN
H20	(DESIGN)	3.48 T	69.6	17.54 1
	OR (DESIGN)	5.80 T	116.1	17.54 1
HS20	(DESIGN)	2.86 T	102.9	14.03 1
	OR (DESIGN)	4.76 T	171.5	14.03 1

ML80	IR (DESIGN)	2.12	T	80.1	17.54	1
	OR (DESIGN)	3.54	T	133.5	17.54	1
P-82	IR (DESIGN)	1.40	T	143.2	17.54	1
	OR (DESIGN)	2.34	T	238.7	17.54	1

RATING FACTOR CODES:

- T - TOP STEEL STRESS/STRENGTH GOVERNS
- B - BOTTOM STEEL STRESS/STRENGTH GOVERNS
- C - CONCRETE STRESS/STRENGTH GOVERNS
- R - REINFORCEMENT STRESS/STRENGTH GOVERNS
- V - SHEAR STRESS/STRENGTH GOVERNS
- S - SERVICEABILITY STRENGTH GOVERNS
- I - MOMENT-SHEAR INTERACTION GOVERNS
- F - SECTION DOES NOT MEET FLANGE PROJECTION/THICKNESS RATIO CRITERIA
- W - SECTION DOES NOT MEET WEB DEPTH/THICKNESS RATIO CRITERIA

MAX MOM STRENGTH CODES:

- C - SECTION IS COMPACT
- B - SECTION IS BRACED NON-COMPACT
- U - SECTION IS UNBRACED NON-COMPACT
- T - SECTION IS IN TRANSITION BETWEEN COMPACT AND BRACED NON-COMPACT



PROJECT BRIDGE No. 1062


COMP. BY WBS DATE 9-29-95

BMS No. 04 7210 0649 8302

PROPOSAL OR JOB NO 9501

CHK'D BY _____ DATE _____

PLAN VIEW



REV. DATE	REV. DATE	REV. DATE	REV. DATE
BY	BY	BY	BY



PROJECT BRIDGE No. 1062

COMP. BY WBS DATE 9-29-95


BMS No. 047210 0649 8302

PROPOSAL OR JOB NO. 9501

CHK'D BY _____ DATE _____


CROSS SECTIONS

SPAN #1




REV. DATE	BY
REV. DATE	BY
REV. DATE	BY
REV. DATE	BY


SPAN #2



SPAN #3




SPAN #1 & #2 =



(ALL CORNERS) 11/16"

SPAN #3 =





PROJECT BRIDGE No. 1062


COMP. BY WBS DATE 9-29-95

BMS No. 04 2210 0649 8302





PROPOSAL OR JOB NO 9501 CHK'D BY _____ DATE _____

CROSS SECTIONS

SPAN #4




SPAN #5



- Ⓐ DECK PLANKS = 2 3/4" x 9" TO 9 1/2"
- Ⓑ CURB BLOCK = 8 1/4" x 4 1/4"
- Ⓒ RAILING ANGLES = 3" x 2 1/2" x 1/4"
- Ⓓ NAILER PLANK = 2 3/4" x 10"

BRACING MEMBERS FOR BENTS = 2 3/4" x 10" & 3 3/4" x 7 1/2" BENT COLUMNS = 11 3/4" x 12 3/4" & 12" x 12"



E SEC. AA E BENTS

BENT 2 APPROX. NAILER PLATE BOLT SPACINGS SPAN 3 BENT 3

REV. DATE	REV. DATE	REV. DATE	REV. DATE
BY	BY	BY	BY

ADDITIONAL INFORMATION

SHEET "AB"
PAGE 1

PADOT
Engineering Dist. 11-0
45 Thoms Run Road
Bridgeville, PA 15017-2853

Dear Mr. Ekiert,

As a result of the latest inspection by SAI CONSULTING ENGRS.,
the following action was taken by _____
for the bridge described below.

County: BEAVER; Road Name: T-649 (WEST ROAD)
BMS I.D. No.: 04 7210 0649 8302 (CSX RAILROAD BRIDGE)
Type of Structure: 5 SPAN STEEL AND TIMBER STRINGER BRIDGE
Other Descriptive Features: TIMBER SUBSTRUCTURE

The Inspection Report recommends the appropriate signing be
placed/replaced/removed immediately. (See Page 2)

The Signs Required are:

- 3 Bridge R12-1-2
- 4 Weight Limit 3 Tons R12-1
- _____ Except Combinations _____ Tons R12-4
- _____ Miles R12-1-1
- _____ Bridge Limited to One Truck
- _____ Narrow Bridge W5-2
- 2 One Lane Bridge W5-3
- _____ Bridge Closed
- _____ Barricades (Type III)
- _____ No Trespassing
- 2 Clearance Markers Right W16-2R
- 2 Clearance Markers Left W16-2L
- _____ Elevation Signs
- _____ Speed Limit _____ Miles Per Hour

**Municipality Representative - Please check (YES) or (NO)

The bridge was posted previously, but according to the
Engineer's recommendation, the posted weight limit needs to be
reduced.


Was action taken? YES () NO ()

The appropriate signing was placed on (date) _____
Municipality Representative Signature _____

* If there are any questions, please contact Ron Todorowski, Local
Bridge Posting Coordinator, at 429-4914.

* Upon completion of the proper signing, please sign and date this
form and return it to the District Office.

Required Bridge Signs



BRIDGE INFORMATION

B.M.S. Number 04 7210 0649 8302
 Municipality Name MARION TWP. BEAVER COUNTY
 Carrying Twp Road T-649 (WEST ROAD)
 Bridge Type 5 SPAN STEEL AND TIMBER STRINGER
(CSX RAILROAD BRIDGE)

NOTE: Sign Required

**LIST OF ADDITIONAL DATA ITEMS
REQUIRED BY FEDERAL HIGHWAY ADMINISTRATION**

BMS No. 04 7210 0649 8302

9-29-95

BMS

FHWA

Item 92 Critical Feature Inspections (Yes or No & Frequency)

A. Fracture Critical Details N — —

B. Underwater Inspection N — —

C. Other Special Features N — —

Item 93 Critical Feature Inspection Date (Mo. & Yr.)

A. Fracture Critical Details — — — —

B. Underwater Inspection — — — —

C. Other Special Features — — — —

A04 A Item 98A Border Bridge State Code — (N/A) —


A04 B 98B % Share — (N/A) —

A04 C Item 99 Border State Bridge No. — (N/A) —

C07 A Item 112 NBIS Bridge Length Yes No

E29 A Item 113 Scour Critical Bridge 6

Rev. Date	Rev. Date	Rev. Date	Rev. Date	Rev. Date	Rev. Date
By	By	By	By	By	By

**SAI**

HIGHWAYS • BRIDGES • CONSTRUCTION MANAGEMENT

CONSULTING ENGINEERS, Inc.

300 Sixth Avenue • Pittsburgh, Pennsylvania 15222-2511 • (412) 392-8750

NOVEMBER 7~~September 15, 1995~~

CSX Transportation
500 Water Street
Jacksonville, FL 32202

Attention: Mr. Carl Medors

RE: NBIS Bridge Inspections
Beaver County, PA
Roadway Bridge (T-649) over CSX's P&W Subdivision Mainline at
Milepost BG-35.59
(CSXT Bridge #355A/D.O.T. #BO 145-802C)

Gentlemen:

As I discussed with Mr. Dave Taubken of your Pittsburgh office, SAI Consulting Engineers, Inc. recently completed the field inspection and structural analysis of the above-referenced bridge under our contract with the Pennsylvania Department of Transportation.

Due to the capacity of the timber deck, *the bridge posting should be reduced immediately from 15 tons to three tons.*

The posting should be put into effect immediately to reduce the possibility of overstressing the structure and causing subsequent damage to the bridge. Affected parties that regularly use the bridge, such as school buses, utility companies, maintenance vehicles, delivery trucks, etc., should be notified of the change in posting.

Following the posting of the bridge, please contact Mr. Ron Todorowski, PaDOT Local Bridge Inspection Coordinator, at (412) 429-4914 and inform him of the date and the actual weight limit of the posting.

If you have any questions or require additional information, please contact me at (412) 392-8771.

Very truly yours,

Glenn D. Stickel
Project Manager

GDS:crc

cc: L. Ruzzi - PaDOT District 11-0
D. A. Miller
Reading File (3)
Design File 9501\csx.ltr