



An Exelon Company

Richard G. Webster, Jr.
Vice President

PECO
Regulatory Policy and Strategy
2301 Market Street
S15
Philadelphia, PA 19103

Telephone 215.841.4000
Fax 215.841.6208
www.peco.com
dick.webster@peco-energy.com

August 1, 2016

Rosemary Chiavetta, Secretary
Pennsylvania Public Utility Commission
Commonwealth Keystone Building
400 North Street
Harrisburg, Pennsylvania 17120

Re: PECO 2016 Second Quarter Reliability Report PUC Docket No. M-2016-2522508

Dear Secretary Chiavetta:

Enclosed is PECO's 2016 Quarterly Reliability Report for the period ending June 30, 2016 submitted pursuant to the Electric Service Reliability Regulations at 52 Pa. Code Chapter 57.

Because portions of the report contain sensitive and proprietary, PECO is filing two versions of the report, one public and one proprietary. PECO requests that the proprietary report, which has been separated and clearly marked with a "Confidential" header on each page, be kept confidential, pursuant to the Commission Order of March 20, 2006.

If you have any questions regarding this matter, please call me at 215-841-5777.


Sincerely,

A handwritten signature in black ink, appearing to read "REW" followed by a long, horizontal flourish.

Enclosure

MPB/mec

**PECO Energy Company
Quarterly Reliability Report
For Period Ending June 30, 2016**



August 1, 2016

PECO Energy ("PECO")

Quarterly Reliability Report for the Period Ending June 30, 2016 filed with the Pennsylvania Public Utility Commission.

Submitted per Rulemaking Re: Amending Electric Service, Docket No. M-2016-2522508 Reliability Regulations at 52 Pa.Code Chapter 57

Section 57.195(e)(1) "A description of each major event that occurred during the preceding quarter, including the time and duration of the event, the number of customers affected, the cause of the event and any modified procedures adopted in order to avoid or minimize the impact of similar events in the future."

PECO experienced no Major Events in the second quarter of 2016.

Section 57.195(e)(2) "Rolling 12-month reliability index values (SAIFI, CAIDI, SAIDI, and if available, MAIFI) for the EDC's service territory for the preceding quarter. The report shall include the data used in calculating the indices, namely the average number of customers served, the number of sustained customer interruptions, the number of customers affected, and the customer minutes of interruption. If MAIFI values are provided, the report shall also include the number of customer momentary interruptions."

PECO *Customers	Sustained Customer Interruptions	Sustained Customer Hours	Momentary Customer Interruptions	Sustained Customer Minutes	SAIFI	CAIDI	SAIDI	MAIFI
1,663,969	1,428,115	2,439,191	791,663	146,351,464	0.86	102	88	0.48

*Customer Count reflects a reduction due to the removal of inactive customer accounts
Data reflects 12 months ending 06/30/2016.

PECO Benchmarks and Rolling 12-Month Standards				
	SAIFI	CAIDI	SAIDI	MAIFI
Benchmark	1.23	112	138	N/A
Rolling 12-Month Standard	1.48	134	198	N/A

SAIFI, CAIDI and SAIDI are below their respective benchmarks and standards established on May 7, 2004. No benchmark or standard was established for MAIFI.

Section 57.195(e)(3) "Rolling 12-month reliability index values (SAIFI, CAIDI, SAIDI, and if available, MAIFI) and other pertinent information such as customers served, number of interruptions, customer minutes interrupted, number of lockouts, and so forth, for the worst performing 5% of the circuits in the system. An explanation of how the EDC defines its worst performing circuits shall be included."

PECO's worst performing 5% circuits were selected based on a weighted score combining customer interruptions, customer hours, SAIFI, SAIDI, and CEMI (Customers Experiencing Multiple Interruptions), due to outages on each circuit in a 12 month period. This measure is oriented toward contributions to system SAIFI, SAIDI and CAIDI, and local areas with high outage frequency or duration. In addition, circuits with a history of repeat appearance on worst performing lists were selectively included in the 5% list. Worst circuits and the rolling 12-month reliability index values requested are shown in Appendix A.

Section 57.195(e)(4) "Specific remedial efforts taken and planned for the worst performing 5% of the circuits as identified in paragraph (3)."

Remedial efforts taken or planned to date for PECO's worst performing 5% of circuits are shown in Appendix B.

Section 57.195(e)(5) "A Rolling 12-month breakdown and analysis of outage causes during the preceding quarter, including the number and percentage of service outages, the number of customers interrupted, and customer interruption minutes categorized by outage cause such as equipment failure, animal contact, tree related, and so forth. Proposed solutions to identified service problems shall be included."

12 Months Ending June 30, 2016					
Cause	Service Outages	% of Service Outages	Customer Interruptions	% of Customer Interruptions	Customer Minutes
Animal	1,289	10.70%	39,146	2.70%	2,783,499
Contact/Dig-In	110	0.90%	20,775	1.50%	1,302,051
Equipment Failure	4,731	39.20%	547,260	38.30%	52,629,506
Lightning	351	2.90%	45,809	3.20%	5,657,629
Other	1,352	11.20%	138,095	9.70%	7,332,062
T&S	12	0.10%	39,797	2.80%	1,759,843
Unknown	440	3.60%	32,321	2.30%	2,298,344
Vegetation-Broken/Uprooted	2,482	20.50%	391,090	27.40%	52,657,265
Vegetation-Ingrowth	940	7.80%	110,461	7.70%	14,686,918
Vehicles	374	3.10%	63,361	4.40%	5,244,346

*The data supplied is the number of interrupted customers for each interruption event summed for all events, also known as customer interruptions. A customer interrupted by three separate trouble cases represents three customer interruptions, but only one customer interrupted.

The largest contributors to customer interruptions were equipment failure and tree-related interruptions. The leading groups within the equipment failure category were aerial equipment and underground equipment. Most customer interruptions caused by trees came from broken branches and tree trunks or uprooted trees (20.5% of all customer interruptions), as opposed to ingrowth (7.8% of all outage customer interruptions). PECO has continued to supplement its regularly scheduled vegetation management cycle with mid-cycle and 34 kV pruning programs and a hazard tree removal program.

Section 57.195(e)(6). *“Quarterly and year to date information on progress toward meeting transmission and distribution inspection and maintenance goals /objectives” (For First, Second and Third Quarter reports only).”*

Predictive and Preventive Maintenance Program – status as of 6/30/2016					
	2 nd Quarter Tasks		YTD Tasks		2016 Total Planned
	Planned	Complete	Planned	Complete	
Recloser Inspections (Number of reclosers inspected)	51	90	102	203	199
Circuit Patrol & Thermography (Number of circuits patrolled)	356	1,322	966	1,932	966
Pole Inspections (Number of poles visually inspected)	1,973	1,625	32,763	39,262	32,763
Padmount Transformers (Number of transformers visually inspected)	2,820	3,082	4,840	6,870	9,733
Below Ground Transformers (Number of transformers visually inspected)	660	362	1,146	1,374	1,737
Substations (Number of substations inspections performed.(e.g. visual inspection, reading of currents, voltages, temperature etc) for a variety of substation components)	330	348	660	708	1,320
Unit Substations (Number of unit substations inspections performed .(e.g. visual inspection, reading of currents, voltages, temperature etc) for a variety of substation components)	768	783	1,535	1,607	3,070

Vegetation Management Preventive Maintenance Program – status as of 6/30/16					
	2 nd Quarter Miles		YTD Miles		2016 Total Planned
	Planned	Complete	Planned	Complete	
Distribution Lift and Manual Trimming	756	735	1,479	1,490	2,708
Transmission Trimming and Removals	40	50	77	91	160

Section 57.195(e)(7). *“Quarterly and year-to-date information on budgeted versus actual transmission and distribution operation and maintenance expenditures in total and detailed by the EDC’S own functional account code or FERC account code as available.” (For first, second and third quarter reports only.)*

\$Millions	Budgeted 2 nd Quarter	Actual 2 nd Quarter	Budgeted Year-to-Date	Actual Year-to-Date
New Business Connections	\$0.3	\$0.4	\$0.5	\$0.8
Capacity Expansion	\$0.2	\$0.2	\$0.5	\$0.8
System Performance	\$12.7	\$11.2	\$26.0	\$21.8
Facility Relocation	\$0.3	\$0.3	\$0.4	\$0.5
Maintenance	\$47.7	\$47.8	\$95.7	\$95.7
Total	\$61.2	\$59.9	\$123.1	\$119.6

Section 57.195(e)(8). *“Quarterly and year-to-date information on budgeted versus actual transmission and distribution capital expenditures in total and detailed by the EDC’S own functional account code or FERC account code as available.” (For first, second and third quarter reports only.)*

\$Millions	Budgeted 2 nd Quarter	Actual 2 nd Quarter	Budgeted Year-to-Date	Actual Year-to-Date
New Business Connections	\$13.7	\$12.6	\$26.9	\$25.4
Capacity Expansion	\$26.0	\$24.9	\$50.1	\$48.2
System Performance	\$36.4	\$31.6	\$58.5	\$55.7
Facility Relocation	\$4.3	\$3.2	\$6.6	\$4.8
Maintenance	\$25.4	\$21.1	\$50.4	\$44.4
Total	\$105.8	\$93.4	\$192.5	\$178.5

Section 57.195(e)(9). *“Dedicated staffing levels for transmission and distribution operation and maintenance at the end of the quarter, in total and by specific category (e.g., lineman, technician and electrician).”*

PECO’s full-time trade staff as of June 30, 2016 was as follows:

Aerial Lineman	374
Underground Lineman (Include UTS)	61
T&S Mechanics, Operators	104
Energy Technicians	100
Aerial Foreman	63
Underground Foreman	17
T&S Foreman	31
ET Foreman	5
	755

Contact Persons:

J. Coffman
 Director, Engineering
 (215) 841-4201
jearl.coffman@peco-energy.com

Dick Webster
 Vice President Regulatory Policy & Strategy
 (215) 841-5777
dick.webster@peco-energy.com

Appendix A
Rolling 12- month reliability index values for 5% worst performing circuits

CIRCUIT	CUSTOMERS ON CIRCUIT	12 Month Rolling Circuit SAIFI	12 Month Rolling Circuit CAIDI	12 Month Rolling Circuit SAIDI	12 Month Rolling Circuit MAIFI	12 Month Rolling Customers Interrupted	12 Month Rolling Customer Hours	12 Month Rolling Momentary Customers Interrupted
AIRY_004	670	0.18	304	55	0	121	614	0
BALA_132	1,504	1.44	121	174	0	2,161	4,358	93
BALA_135	1,152	3.70	73	270	1	4,260	5,179	616
BELLEVUE_001	573	1.25	349	434	3	714	4,149	1,707
BELLEVUE_002	621	3.61	122	442	1	2,244	4,572	624
BELLEVUE_134	784	3.61	94	338	2	2,833	4,416	1,429
BETHAYRES_002	487	3.15	54	171	2	1,534	1,386	1,008
BETHAYRES_135	744	5.52	36	197	4	4,105	2,439	2,654
BRADFORD_346	2,275	1.51	108	163	2	3,445	6,181	3,977
BRYAN_002	364	6.42	133	852	0	2,337	5,167	68
BRYN_MAWR_144	1,107	2.28	141	320	1	2,520	5,912	564
BUCKINGHAM_346	2,628	0.09	381	34	0	237	1,506	0
BUCKINGHAM_351	1,894	3.38	75	255	2	6,409	8,042	3,728
BYBERRY_143	518	0.09	307	28	0	47	241	0
CALLOWHILL_131	2,126	2.59	48	123	1	5,502	4,360	2,256
CALLOWHILL_142	1,365	1.98	49	97	0	2,706	2,210	0
CANAL_000	170	2.71	52	142	1	461	401	178
CHICHESTER_134	1,890	0.02	98	2	0	43	70	66
CHURCH_003	561	2.14	416	889	0	1,199	8,315	0
CLAY_343	1,498	3.92	54	210	0	5,865	5,245	733
COLWYN_132	2,305	1.22	41	50	0	2,823	1,923	22
CONCORD_351	1,773	3.26	116	377	0	5,785	11,143	451
COOPER_371	233	6.48	258	1,673	0	1,509	6,495	113
CROYDON_142	585	1.78	84	149	0	1,041	1,457	1
DALEVILLE_342	648	4.15	132	546	1	2,687	5,900	924
DAVISVILLE_004	813	0.02	5	0	0	13	1	0
DAVISVILLE_007	641	0.24	197	47	3	153	502	2,128
DURHAM_005	514	1.19	103	122	0	611	1,045	0
DUTTON_001	868	4.23	43	184	0	3,669	2,659	0
EDDINGTON_138	766	0.06	140	9	0	49	115	0
EDGMONT_001	605	2.05	34	69	2	1,240	695	1,226
ELMWOOD_135	2,868	0.85	94	80	1	2,437	3,816	1,945
EMILIE_010	248	2.09	49	103	0	518	424	0
EMILIE_017	523	2.09	176	367	0	1,092	3,197	0
EMILIE_134	910	4.47	54	243	1	4,066	3,688	1,042
FALLS_343	530	1.48	226	333	0	782	2,940	0
FIN_002	418	3.26	220	716	0	1,362	4,990	9
FLINT_132	1,114	1.83	75	137	0	2,040	2,535	513
FLINT_143	518	1.09	79	86	0	565	744	0
FLINT_144	840	2.68	121	325	1	2,254	4,548	647
FLINT_147	153	0.41	254	105	0	63	267	0
GARDENVILLE_000	306	5.19	183	948	0	1,588	4,837	3
GLADWYNE_133	592	2.34	94	219	3	1,383	2,163	1,774
HARMONY_001	343	2.08	378	788	0	715	4,503	45
HARMONY_008	941	2.59	76	197	0	2,438	3,094	21
HEATON_136	1,409	2.77	120	333	2	3,903	7,814	2,630

CIRCUIT	CUSTOMERS ON CIRCUIT	12 Month Rolling Circuit SAIFI	12 Month Rolling Circuit CAIDI	12 Month Rolling Circuit SAIDI	12 Month Rolling Circuit MAIFI	12 Month Rolling Customers Interrupted	12 Month Rolling Customer Hours	12 Month Rolling Momentary Customers Interrupted
HEATON_142	628	2.20	92	202	1	1,383	2,118	327
HEATON_163	917	0.34	156	53	0	310	804	36
JARRETT_135	569	0.18	205	37	0	103	351	15
JENKINTOWN_130	430	0.32	233	75	0	138	535	0
JENKINTOWN_135	942	0.44	119	53	0	416	827	9
JENKINTOWN_138	1,857	1.13	30	34	1	2,094	1,057	950
KEYSTONE_037	261	2.44	236	577	0	638	2,510	41
KING_135	390	3.01	98	296	2	1,172	1,921	644
KNOWLTON_001	327	1.55	268	416	0	508	2,267	0
KNOWLTON_003	432	2.81	229	642	0	1,213	4,626	198
LANE_002	739	1.38	99	137	0	1,021	1,689	190
LENAPE_342	1,821	1.41	88	124	0	2,561	3,754	26
LENAPE_351	1,713	5.69	100	568	5	9,739	16,212	8,046
LESTER_003	604	1.10	27	30	0	665	302	0
LINE_131_00WO	528	1.26	156	196	2	664	1,729	1,055
LINE_2266	166	0.02	159	3	0	3	8	0
LINE_2675	1,312	2.98	41	122	0	3,909	2,668	1
LINE_3308NT	1,195	3.37	111	375	1	4,022	7,462	624
LINE_3340	924	1.87	92	172	1	1,732	2,651	852
LINE_3500	194	2.36	190	448	0	458	1,447	80
LINE_7500PB	2,941	2.91	103	299	2	8,571	14,675	6,004
LLANERCH_161	1,200	0.50	450	226	0	603	4,522	44
LOMBARD_042	168	3.38	81	274	0	567	767	0
MACDADE_133	1,458	2.33	45	105	0	3,390	2,556	0
MACDADE_135	2,130	1.19	54	65	0	2,535	2,298	885
MACDADE_139	2,266	1.62	32	53	0	3,681	1,986	1,007
MACDADE_146	1,895	0.70	36	25	0	1,332	797	0
MAIN_000	49	2.39	167	399	0	117	326	0
MAINLAND_000	363	3.42	96	329	0	1,243	1,992	0
MALL_025	77	2.21	577	1,273	0	170	1,634	0
MIDDLETOWN_133	1,439	1.98	114	226	1	2,852	5,424	1,284
MIDDLETOWN_143	1,586	2.18	87	189	0	3,457	4,984	355
MIDDLETOWN_349	1,955	2.16	68	148	0	4,232	4,817	641
MIDWAY_003	688	0.22	115	26	1	153	294	686
NESHAMINY_133	933	1.79	100	179	1	1,674	2,778	1,259
NEWLINVILLE_342	1,985	2.46	66	162	4	4,882	5,348	6,938
NEWLINVILLE_352	2,274	2.31	69	159	2	5,259	6,032	3,942
NEWTOWN_SQUAR_136	1,254	6.46	119	768	0	8,100	16,049	0
NEWTOWN_SQUAR_146	1,247	2.64	361	952	1	3,288	19,792	1,851
OVERBROOK_131	2,974	1.58	29	47	2	4,701	2,311	5,074
PARRISH_139	1,194	0.43	113	49	-	517	971	0
PERKIOMEN_343	2,485	0.57	77	44	1	1,427	1,843	2,024
PIPER_000	368	4.23	107	451	2	1,555	2,763	762
PLYMOUTH_135	584	2.21	106	235	0	1,292	2,284	0
PLYMOUTH_164	1,352	1.95	98	191	1	2,637	4,298	929
PULASKI_014	941	1.78	67	119	0	1,674	1,874	91
RADNOR_131	31	6.03	109	655	2	187	338	75
RICHMOND_144	1,655	0.83	28	23	2	1,380	637	3,751
SPRUCE_028	379	2.46	62	152	0	932	959	0
SPRUCE_029	435	3.39	99	336	0	1,475	2,438	0

CIRCUIT	CUSTOMERS ON CIRCUIT	12 Month Rolling Circuit SAIFI	12 Month Rolling Circuit CAIDI	12 Month Rolling Circuit SAIDI	12 Month Rolling Circuit MAIFI	12 Month Rolling Customers Interrupted	12 Month Rolling Customer Hours	12 Month Rolling Momentary Customers Interrupted
SUNNYBURN_002	290	1.69	197	333	0	491	1,608	0
TABOR_135	2,026	0.87	80	70	0	1,769	2,358	0
TANGUY_000	310	3.62	159	575	1	1,121	2,969	344
TUNA_132	768	0.77	27	21	0	593	269	0
TUNA_142	1,324	1.06	34	37	1	1,406	806	1,472
TUNA_143	739	1.23	326	400	0	907	4,932	0
UNIVERSITY_012	194	1.15	117	135	1	224	436	236
UPPER_DARBY_139	2,310	0.54	51	27	0	1,247	1,058	109
UPPER_MERION_351	2,694	3.32	83	277	0	8,948	12,451	1,096
WARMINSTER_006	428	3.45	120	414	1	1,476	2,950	428
WARRINGTON_341	2,244	2.73	84	228	3	6,118	8,523	7,353
WASHINGTON_SQ_003	369	1.36	639	868	2	501	5,337	740
WAYNE_142	824	6.19	77	479	1	5,098	6,580	1,064
WAYNE_146	547	2.10	148	310	1	1,147	2,822	327
WORTH_000	270	2.23	96	215	0	603	965	0
WRIGHT_000	399	5.72	185	1,060	0	2,284	7,051	0
YEADON_134	1,762	1.14	80	91	1	2,001	2,670	1,010

The data supplied is the number of interrupted customers for each interruption event summed for all events, also known as customer interruptions. If a customer is interrupted by three separate trouble cases, they represent three customer interruptions, but only one customer interrupted.

Appendix B

Remedial efforts taken and planned for 5% worst performing circuits as of 06/30/16

AIRY_004

Montgomery County

Completed:

Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and corrected as needed
Performed regularly schedule tree clearance
Completed reliability corrective workorders
Installed aerial cable

Planned:

Remedial efforts completed

BALA_132

Delaware County

Completed:

Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and corrected as needed
Completed reliability corrective workorders

Planned:

Complete reliability corrective workorders

BALA_135

Delaware County

Completed:

Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and corrected as needed
Completed reliability corrective workorders
Tested / Inspected recloser operation

Planned:

Remedial efforts completed

BELLEVUE_001

Bucks County

Completed:

Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and corrected as needed
Completed reliability corrective workorders
Tested / Inspected recloser operation

Planned:

Remedial efforts completed

BELLEVUE_002

Bucks County

Completed:

Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and corrected as needed
Completed reliability corrective workorders

Planned

Remedial efforts completed

BELLEVUE_134

Bucks County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Replaced cable

Install additional fuses

Planned:

Complete reliability corrective workorders

BETHAYRES_002

Montgomery County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Planned:

Remedial efforts completed

BETHAYRES_135

Montgomery County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Complete regularly scheduled tree trimming

Completed reliability corrective workorders

Inspected- tested recloser operation

Installed additional wildlife protection

Planned:

Remedial efforts completed

BRADFORD_346

Chester County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Planned:

Remedial efforts completed

BRYAN_002

York County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Replaced fuses

Replaced cable

Completed reliability corrective workorders

Upgrade cable insulation

Planned:

Remedial efforts completed

BRYN_MAWR_144

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Installed additional fuses

Planned:

Remedial efforts completed

BUCKINGHAM_346

Bucks County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Installed additional lightning protection

Installed additional wildlife protection

Planned:

Remedial efforts completed

BUCKINGHAM_351

Bucks County

Completed:

Inspected circuit visually and with thermographic camera

Completed reliability corrective workorders

Inspected selected areas of circuit for vegetation issues and corrected as needed

Installed transformer

Installed additional lightning protection

Installed additional wildlife protection

Planned:

Remedial efforts completed

BYBERRY_143

Bucks County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Test inspect recloser operation

Planned:

Complete reliability corrective workorders

CALLOWHILL_131

Philadelphia County

Completed:

Inspected circuit visually and with thermographic camera

Completed reliability corrective workorders

Inspect selected areas of circuit for vegetation issues and corrected as needed

Replaced cable

Replaced lightning protection

Installed 3 phase recloser

Planned:

Remedial efforts completed

CALLOWHILL_142

Philadelphia County

Completed:

Inspected circuit visually and with thermographic camera

Inspect selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Installed transformer

Upgraded cable

Upgraded lightning protection

Installed additional fuses

Planned:

Complete reliability corrective workorders

CANAL_000

Bucks County

Completed:

Inspected circuit and with thermographic camera

Inspect selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Replaced lightning protection

Planned:

Remedial efforts completed

CHICHESTER_134

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Planned:

Remedial efforts completed

CLAY_343

Chester County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Installed switch

Test recloser operation

Planned:

Complete reliability corrective workorders

COLWYN_132

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Reconfigure circuit

Planned:

Remedial efforts completed

CONCORD_351

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Test/Inspect recloser operation

Repaired switch

Installed additional fuses

Planned:

Remedial efforts completed

COOPER_371

York County

Completed:

Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and corrected as needed
Completed reliability corrective workorders
Replaced switch
Tested /Inspected recloser

Planned:

Remedial efforts completed

CROYDON_142

Bucks County

Completed:

Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and corrected as needed
Completed reliability corrective workorders
Installed additional fuses
Complete reliability corrective workorders

Planned:

Remedial efforts completed

DALEVILLE_342

Chester County

Completed:

Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and corrected as needed
Completed reliability corrective workorders
Replaced switch

Planned:

Complete reliability corrective workorders
Inspect / Test breaker
Install additional transformer

DAVISVILLE_004

Montgomery County

Completed:

Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and corrected as needed
Completed reliability corrective workorders
Repaired switch
Installed additional fuses

Planned:

Remedial efforts completed

DAVISVILLE_007

Montgomery County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Installed additional fuses

Planned:

Remedial efforts completed

DURHAM_005

Bucks County

Completed:

Inspected circuit visually and with thermographic camera

Completed reliability corrective workorders

Inspected selected areas of circuit for vegetation issues and corrected as needed

Installed additional fuses

Upgraded lightning protection

Replaced secondary wires

Planned:

Remedial efforts completed

DUTTON_001

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Planned:

Inspect selected areas of circuit for vegetation issues and corrected as needed

EDDINGTON_138

Bucks County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Install animal protection

Planned:

Complete reliability corrective workorders

EDGEMONT_001

Delaware County

Completed:

Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and corrected as needed
Completed reliability corrective workorders
Replaced cable
Upgraded recloser communications
Installed & tested recloser operations

Planned:

Remedial efforts completed

ELMWOOD_135

Philadelphia County

Completed:

Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and corrected as needed
Completed reliability corrective workorders
Replaced cable
Installed additional lightning protection
Installed additional fuses

Planned:

Remedial efforts completed

EMILIE_010

Bucks County

Completed:

Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and corrected as needed
Completed reliability corrective workorders
Replaced Cable
Inspect breaker operation

Planned:

Remedial efforts completed

EMILIE_017

Bucks County

Completed:

Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and corrected as needed
Completed reliability corrective workorders

Planned:

Remedial efforts completed

EMILIE_134

Bucks County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Planned:

Remedial efforts completed

FALLS_343

Bucks County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Tested / Inspected recloser operation

Planned:

Remedial efforts completed

FIN_002

York County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Replaced cable

Planned:

Remedial efforts completed

FLINT_132

Montgomery County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Installed animal protection

Adjust recloser settings

Planned:

Remedial efforts completed

FLINT_143

Montgomery County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Inspect breaker operation

Planned:

Remedial efforts completed

FLINT_144

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Upgrade fuse

Installed animal protection

Planned:

Remedial efforts completed

FLINT_147

Delaware County

Completed:

Inspected circuit and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Install additional lightning protection

Inspect circuit breaker operation

Planned:

Upgrade cable

Install capacitor bank

Complete reliability corrective workorders

GARDENVILLE_000

Bucks County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Installed additional fuses

Tested / Repaired capacitor

Planned:

Remedial efforts completed

GLADWYNE_133

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Upgraded cable

Planned:

Remedial efforts completed

HARMONY_001

Chester County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Tested switch operation

Replaced cable section

Replaced recloser

Planned:

Remedial efforts completed

HARMONY_008

Chester County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Planned:

Remedial efforts completed

HEATON_136

Montgomery County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Upgrade secondary wires

Install additional fuses

Planned:

Complete reliability corrective workorders

HEATON_142

Montgomery County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Upgraded cable insulation

Planned:

Remedial efforts completed

HEATON_163

Montgomery County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Installed additional fuses

Planned:

Install 3 phase recloser

JARRETT_135

Montgomery County

Completed:

Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and corrected as needed
Completed reliability corrective workorders
Upgraded secondary wires

Planned:

Remedial efforts completed

JENKINTOWN_130

Montgomery County

Completed:

Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and corrected as needed
Completed reliability corrective workorders

Planned:

Remedial efforts completed

JENKINTOWN_135

Montgomery County

Completed:

Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and corrected as needed
Completed reliability corrective workorders
Installed tree wire
Installed additional fuses

Planned:

Remedial efforts completed

JENKINTOWN_138

Montgomery County

Completed:

Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and corrected as needed
Completed reliability corrective workorders
Replaced recloser
Replaced cable sections

Planned:

Completed reliability corrective workorders

KEYSTONE_037

Delaware County

Completed:

Inspected circuit visually and with thermographic camera
Completed reliability corrective workorders
Inspect switches
Install switch
Complete reliability corrective workorders

Planned:

Remedial efforts completed

KING_135

Montgomery County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Installed animal protection

Installed recloser

Planned:

Remedial efforts completed

KNOWLTON_001

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Planned:

Remedial efforts completed

KNOWLTON_003

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Planned:

Completed reliability corrective workorders

Upgraded secondary wire

LANE_002

Montgomery County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Upgrade fuses

Planned:

Remedial efforts completed

LENAPE_342

Chester County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Replaced cable

Planned:

Complete reliability corrective workorders

LENAPE_351

Chester County

Completed:

Inspected circuit and with thermographic camera

Completed reliability corrective workorders

Replace cable

Upgrade recloser

Planned:

Remedial efforts completed

LESTER_003

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Planned:

Remedial efforts completed

LINE_109_00

Bucks County

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Installed wildlife protection

Tested/ Inspected breaker operation

Completed:

Complete reliability corrective workorders

LINE_131_00WO

Bucks County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Planned:

Completed reliability corrective workorders

LINE_2266

Philadelphia County

Completed:

Inspected circuit visually and with thermographic camera

Completed reliability corrective workorders

Installed switch

Planned:

Remedial efforts completed

LINE_2675

Philadelphia County

Completed:

Inspected circuit visually and with thermographic camera

Completed reliability corrective workorders

Planned:

Install additional fuses

Completed reliability corrective workorders

LINE_3308NT

Chester County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Upgraded controller

Upgraded transformer

Upgraded lightning protection

Planned:

Complete reliability corrective workorders

Upgrade wires

LINE_3340

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Installed switch

Replaced cable

Planned:

Remedial efforts completed

LINE_3500

Bucks County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Planned:

Remedial efforts completed

LINE_7500PB

Chester County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Planned:

Complete reliability corrective workorders

LLANERCH_161

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Replaced cable

Planned:

Remedial efforts completed

LOMBARD_042

Philadelphia County

Completed:

Inspected circuit visually and with thermographic camera

Completed reliability corrective workorders

Installed faulted circuit indicators

Planned:

Completed reliability corrective workorders

MACDADE_133

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Upgraded secondary wires

Inspected breaker operation

Installed animal protection

Planned:

Remedial efforts completed

MACDADE_135

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Upgraded fuse

Planned:

Completed reliability corrective workorders

MACDADE_139

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Installed wildlife protection

Planned:

Remedial efforts completed

MACDADE_146

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Installed wildlife protection

Planned:

Remedial efforts completed

MAIN_000

Philadelphia County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Planned:

Transfer portion of load to supply circuit

Complete reliability corrective workorders

MAINLAND_000

Montgomery County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Planned:

Remedial efforts completed

MALL_025

Philadelphia County

Completed:

Inspected circuit visually and with thermographic camera

Completed reliability corrective workorders

Planned:

Installed switch

Replace cable stretch

MIDDLETOWN_133

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Replaced cable

Installed additional fuses

Planned:

Remedial efforts completed

MIDDLETOWN_143

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Installed wildlife protection

Planned:

Completed reliability corrective workorders

MIDDLETOWN_349

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Upgraded fuses

Tested / Inspected recloser operation

Planned:

Remedial efforts completed

MIDWAY_003

Bucks County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Planned:

Install additional fuses

Complete reliability corrective workorders

NESHAMINY_133

Bucks County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Replaced cable

Planned:

Remedial efforts completed

NEWLINVILLE_342

Chester County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Tested / Inspected recloser operations

Installed lightning protection

Planned:

Remedial efforts completed

NEWLINVILLE_352

Chester County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Installed 3 phase recloser

Replaced cable

Planned:

Remedial efforts completed

NEWTOWN_SQUARE_136

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Completed reliability corrective workorders

Inspected selected areas of circuit for vegetation issues and corrected as needed

Installed wildlife protection

Planned:

Remedial efforts completed

NEWTOWN_SQUARE_146

Delaware County

Completed:

Completed reliability corrective workorders

Inspected circuit visually and with thermographic camera

Inspect / Test recloser operation

Inspected selected areas of circuit for vegetation issues and corrected as needed

Planned:

Remedial efforts completed

OVERBROOK_131

Philadelphia County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Planned:

Install additional lightning protection

Install wildlife protection

Complete reliability corrective workorders

PARRISH_139

Philadelphia County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Install additional lightning protection

Install additional fuses

Planned:

Remedial efforts completed

PERKIOMEN_343

Montgomery County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Replaced 3 phase recloser

Installed 3 phase recloser

Planned:

Remedial efforts completed

PIPER_000

Bucks County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Planned:

Remedial efforts completed

PLYMOUTH_135

Montgomery County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Installed wildlife protection

Planned:

Remedial efforts completed

PLYMOUTH_164

Montgomery County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Upgraded fuse

Upgraded wires

Installed additional animal protection

Planned:

Remedial efforts completed

PULASKIE_014

Philadelphia County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Installed additional wildlife protection

Upgraded transformer

Planned:

Remedial efforts completed

RADNOR_131

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Installed additional wildlife protection

Replaced recloser

Planned:

Remedial efforts completed

RICHMOND_144

Philadelphia County

Completed:

Inspected circuit visually and with thermographic camera

Completed reliability corrective workorders

Inspected selected areas of circuit for vegetation issues and corrected as needed

Replaced cable

Installed wildlife protection

Installed additional fuses

Planned:

Install wildlife protection

Install additional fuses

Complete reliability corrective workorders

SPRUCE_028

Philadelphia County

Completed:

Inspected circuit visually and with thermographic camera

Completed reliability corrective workorders

Planned:

Replace switch

Replace cable section

Complete reliability corrective workorders

SPRUCE_029

Philadelphia County

Completed:

Inspected circuit visually and with thermographic camera

Completed reliability corrective workorders

Planned:

Replace cable section

Completed reliability corrective workorders

SUNNYBURN_002

York County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Planned:

Completed reliability corrective workorders

TABOR_135

Philadelphia County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Upgraded transformer

Installed additional fuses

Planned:

Complete reliability corrective workorders

TANGUY_000

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Installed additional fuses

Planned:

Install additional fuses

Complete reliability corrective workorders

TUNA_132

Philadelphia County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Inspected recloser operation

Installed transformer

Completed reliability corrective workorders

Planned:

Remedial efforts completed

TUNA_142

Philadelphia County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Replaced stretch of cable

Planned:

Complete reliability corrective workorders

TUNA_143

Philadelphia County

Completed:

Completed reliability corrective workorders

Installed vacuum fault interrupter

Planned:

Complete reliability corrective workorders

UNIVERSITY_012

Philadelphia County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Replaced stretch of cable

Upgraded transformer

Planned:

Completed reliability corrective workorders

UPPER_DARBY_139

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Installed additional fuses

Upgraded fuses

Planned:

Remedial efforts completed

UPPER_MERION_351

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Upgraded transformer

Inspect recloser operation

Planned:

Remedial efforts completed

WARMINSTER_006

Bucks County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Planned:

Remedial efforts completed

WARRINGTON_341

Bucks County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Installed additional fuses

Planned:

Remedial efforts completed

WASHINTON_SQUARE_003

Bucks County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Planned:

Completed reliability corrective workorders

WAYNE_142

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Planned:

Remedial efforts completed

WAYNE_146

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Replaced recloser

Upgraded wires

Replaced cable

Planned:

Remedial efforts completed

WORTH_000

Bucks County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Installed three phase recloser

Planned:

Coordinate fuses

Completed reliability corrective workorders

WRIGHT_000

Bucks County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Relocated transformer

Completed reliability corrective workorders

Planned:

Remedial efforts completed

YEADON_134

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Installed three phase recloser

Planned:

Remedial efforts completed

Appendix C

New Business Connections

This work category includes all the facility work required to add a new customer or to increase the load to an existing customer. The facility work will include the facilities required to directly connect the customer to the system and the upgrade/replacement of any existing facility to serve the requested additional load.

Capacity Expansion

This work category includes only capacity work generated by the system design engineer to prevent system failure and to assure the delivery of voltage as specified in the tariff. The addition of new substations and substation enlargements for future load growth will also be included in this project.

System Performance

This work category includes projects designed to upgrade, modify or improve the performance of the distribution system. Also included in this category are indirect costs in support of all categories and one-time accounting adjustment items.

Facility Relocation

This work category includes all requests for relocation of PECO facilities including municipal as well as customer related relocation requests.

Maintenance

This work category includes work performed to repair and restore equipment to its normal state of operation, along with planned preventive maintenance work such as visual and thermographic inspections and tree trimming around transmission and distribution lines.

Storm Funds

Incremental costs (primarily; overtime, contractors, mutual assistance, and meals) incurred while responding to major storms (storms that meet customer outage and duration criteria).