Pennsylvania Public Utility Commission

Damage Prevention Committee Meeting Case List
November 10, 2026

Omnibus Session

Case Number	Stakeholders	Summary	Violations & Recommendation
62589	**Facility Owner:** PEOPLES NATURAL GAS COMPANY LLC **Contractor/Excavator:** BILL THOMPSON UTILITY SERVICE **Project Owner:** ROBINSON TOWNSHIP ADMINISTRATION OFFICE	On 2/19/2026 12:30:00 AM at 1000 CHURCH HILL RD, ROBINSON TWP, ALLEGHENY The incident occurred on 2/19/2026 at 1000 CHURCH HILL RD in Robinson Township in Allegheny County. A gas line owned by Peoples Natural Gas was damaged. PEOPLES NATURAL GAS COMPANY LLC the facility owner, stated in their Alleged Violation Report (AVR) that, "Bill Thompson Utility Service struck and damaged a properly marked Peoples Gas service line while using mechanized equipment in the tolerance zone." They added that 911 was not notified immediately. Pictures were provided. BILL THOMPSON UTILITY SERVICE AND EXCAVATION INC, the excavator was mailed an AVR request letter on 3/10/2026. Questions were asked, including who hired them to do the work. Ticket 20260431254 listed BILL THOMPSON UTILITY SERVICE as the entity that the work was being done for. No AVR has been received. No contact has been made as of 5/13/2026. No mail was returned until on 6/09/2026, a letter, but the email was delivered successfully. Another address was found on-line and AVR request letter resent. This letter was also returned. Please also note that the original letter was sent on 3/11/2026. VIOLATIONS BILL THOMPSON UTILITY SERVICE AND EXCAVATION INC is in violation of: Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within 30 days of the receipt of the request. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or damaging a facility owner's line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid. Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: The penalties are applied. PUC compliance education is required for the excavators working onsite of this excavation or their replacements.	**BILL THOMPSON UTILITY SERVICE: $3,000.00** Section 5(17) 1st Offense $500.00 Section 5(16) 1st Offense $1,000.00 Section 5(8) 1st Offense $1,000.00 Section 5(4) 1st Offense $500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
62818	**Facility Owner:** Peoples Natural Gas **Contractor/Excavator:** W Construction **Project Owner:** COLOSIMO DEVELOPMENT CORP. **Other:** ALLSTATE MAPPING INC **Other:** BERKSHIRE HATHAWAY HOME SERVICES THE PREFERED REALTY **Other:** W Construction	On 3/3/2026 11:06:00 AM at 4051 BRIARWOOD DR, HEMPFIELD TWP, WESTMORELAND BERKSHIRE HATHAWAY HOME SERVICES THE PREFERED REALTY disagrees. On 10/14/2026 Colosimo Development Corp sent an email stating that they hired W Construction and that BERKSHIRE HATHAWAY was not involved in this. The violations for BERKSHIRE HATHAWAY are withdrawn. COLOSIMO DEVELOPMENT CORP. disagrees. On 10/14/2026 DPI Maki sent an email asking Colosimo about the project and contact information for W Construction. On 10/19/2026. Colosimo sent an email stating he does not want to come to the DPC meeting. ********** The incident occurred on 3/03/2026 at 4051 Briarwood Dr., in Hempfield Township, in Westmoreland Co. A 1" plastic gas line owned by Peoples Gas and other utilities were damaged. PEOPLES NATURAL GAS COMPANY LLC stated in their Alleged Violation Report (AVR) that "W Construction placed a one-call to install UG electric, gas and water lines when they struck a 1" plastic service at 4051 Briarwood dr. The original one-call was for an unnamed road. Contractor marked everything in white, contractor dug outside the one-call described on the ticket. Contractor hit multiple utilities and kept digging. Pictures show electric and gas ripped out. Contractor then placed a one-call for those addresses after the damage. PNG repaired the line". Peoples Gas also added that the excavator "Failed to immediately report any break, leak, dent, gouge, groove, or other damage to lines, made or discovered during the work §5(7)". AVR states that 911 was called by W Construction. Pictures were provided. See attachment named "4051 Briarwood dr 6" for multiple utilities damaged. No AVR's were submitted for any other damaged utilities on 3/03/2026. W Construction was sent an AVR request letter on 3/13/2026. No AVR or contact has been made as of 8/14/2026. No return mail has been received. COLOSIMO DEVELOPMENT CORP / COLOSIMO CONSRUCTION, the project owner was sent an AVR request letter on 3/30/2026. No AVR or Contact has been made as of 8/14/2026. On 10/14/2026 and email was received from Peter Colosimo, asking to have contact information updated and disagreeing with the case findings. Pete Colosimo, project owner for the survey that was requested to be done by Allstate Mapping Inc for this area, was sent an AVR request letter on 7/06/2026. No AVR or Contact has been made as of 8/14/2026. No mail has been returned. A new address was found and an AVR request was also sent to Pete Colisimo to 221 PLEASANT VALLEY RD, UNIT B, on 9/04/2026.	**COLOSIMO DEVELOPMENT CORP.: $1,500.00** Section 6.1(7) 1st Offense $1,000.00 Section 6.1(8) 1st Offense $500.00 **BERKSHIRE HATHAWAY HOME SERVICES THE PREFERED REALTY: $0.00** **W Construction: $2,750.00** Section 5(16) 1st Offense $1,000.00 Section 5(17) 1st Offense $500.00 Section 5(7) 1st Offense $1,000.00 Section 5(13) 1st Offense $250.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		ALLSTATE MAPPING INC, the surveyor for this project, stated in their AVR that, "I am unaware of any damage on the property. We were hired by Pete Colosimo at 4055 Briarwood Drive. The PUC letter states the address of damage is 4051 Briarwood Dr. We performed a boundary survey for Pete Colosimo in October 2025 and placed a PA One Call design ticket to retrieve utility information for the boundary survey map under Serial # 20253070818. We prepared the boundary survey and submitted it to Pete in December 2025. We have not been back to Pete's property since October 2025. On 7/02/2026 the AVR from AllState Mapping provided another address for Colosimo, which noted that this may be a home address. AVR request letter was mailed on this same day. No AVR or contact has been made. *Ticket 20260100226 was submitted on 1/10/2026 and the work site is listed as Unnamed Rd. and the location information on read "to THE NEAREST MAIN ROAD IS SR 0130. IF COMING OFF OF PLEASANT VALLEY RD TURN ONTO BRIARWOOD DR GO PAST HARROLD ST GO TO THE STOP SIGN FROM THE STOPSIGN MAKE A LEFT. PLEASE MARK FROM THE STOP SIGN TO THE CUL DE SAC ON BOTH SIDES OF THE UNNAMED RD. THERE ARE 2 ORANGE CONES AND WHITE PAINT AT THE ENTRANCE AND ALSO AT THE END. THERE IS A NEW TOWNHOUSE UNIT UNDER CONSTRUCTION IN THIS AREA. THERE WILL BE 3 TRENCHES FOR UG UTILITIES." See attached ticket 20260100226. **Emergency 20260621752 ticket and pictures show that the excavation was on Briarwood Rd, in front of 4051 and 4050 Briarwood Rd. ***Ticket 20260622513 was submitted by W Construction on 3/05/2026, two days after the damage. Ticket 20260622513 states that the work is being done between 4051 AND 4057 BRIARWOOD DR. Installing Gas, Electric and water lines. excavation work taking place and damaged underground facilities. Pictures show VIOLATIONS W Construction is in violation of: Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or damaging a facility owner's line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within 30 days of the receipt of the request. Section 5(7) – Failed to immediately report to the facility owner any break or leak in its lines, or any dent, gouge, groove, or other damage to such lines or to their coating or cathodic protection.	

Case Number	Stakeholders	Summary	Violations & Recommendation
		Section 5(13) – Excavator changed the location, scope, or duration of a proposed excavation without notifying the One call System. Recommendation: The penalties are applied. PUC compliance education is required for the excavators working onsite of this excavation or their replacements. COLOSIMO DEVELOPMENT CORP / COLOSIMO CONSRUCTION is in violation of: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike or damaging a facility owner's line during excavation or demolition work activities or if a project owner believes a violation of this act has been committed in association or demolition. Section 6.1(8) - Project Owner failed to comply with all requests for information by the commission relating to the commission's enforcement authority under this act within 30 days of receipt of written request. Recommendation: The penalties are applied. PUC project owner compliance education is required for the person responsible for submitting AVR or their replacement. BERKSHIRE HATHAWAY HOME SERVICES THE PREFERED REALTY is in violation of: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike or damaging a facility owner's line during excavation or demolition work activities or if a project owner believes a violation of this act has been committed in association or demolition. Section 6.1(8) - Project Owner failed to comply with all requests for information by the commission relating to the commission's enforcement authority under this act within 30 days of receipt of written request. Recommendation: The penalties are applied. PUC project owner compliance education is required for the person responsible for submitting AVR or their replacement.	
63523	**Facility Owner:** Verizon **Contractor/Excavator:** NATIONAL FUEL GAS **Project Owner:** NATIONAL FUEL GAS - **Other:** OWS ACQUISITION CO LLC	On 3/24/2026 11:30:00 AM at ALLEN ST, CHERRYTREE TWP, VENANGO The incident occurred on 3/24/2026 on Allen St in CHERRYTREE TWP in VENANGO Co. A Telecom line owned by Verizon was damaged. NATIONAL FUEL GAS stated in their Alleged Violation Report (AVR) that, "National Fuel struck a mismarked telecommunications facility while installing new natural gas facilities. Verizon responded Fiels Marked to both routine tickets 20260583032 and 20260583033. The orange flags in attachment named "IMG_2417" shows the orange flags outside of the required marking allowance. Verizon was sent an AVR request letter on 4/07/2026. No AVR or contact has been made as of 8/07/2026. *Ticket 20260583032 was submitted by National Fuel Gas on 2/27/2026 with a response due by 3/03/2026. Verizon responded, "field marked".	**Verizon: $5,500.00** Section 2(5)(i) Subsequent $2,000.00 Section 2(10) Subsequent $2,500.00 Section 2(11) 2nd Offense $1,000.00 **OWS ACQUISITION CO LLC: $250.00** Section 2(5)(v) 1st Offense $250.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		VIOLATIONS Verizon is in violation of: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. See attachment named "IMG_2417" , which shows the orange flags outside of the required marking allowance. This is a subsequent offense. Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner's lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. This is a subsequent offense. Section 2(11) – Facility Owner failed to comply with all requests for information by the Commission relation to the Commission's enforcement authority under this act within thirty days of the receipt of the request. This is a subsequent offense. Recommendation: The penalties are applied. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). OWS ACQUISITION CO LLC is in violation of: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20260583032 was submitted by National Fuel Gas on 2/27/2026 with a response due by 3/03/2026. OWS ACQUISITION CO LLC had no response until they responded "field marked" on 3/05/2026. Recommendation: The penalties are applied. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).	
63316	**Facility Owner:** City of Bethlehem **Contractor/Excavator:** Horizon Cable Construction Inc. **Project Owner:** BUCKLEY CABLE CONSTRUCTION **Other:** COMCAST **Other:** E M UTILITY CONTRACTORS **Other:** VERIZON	On 3/24/2026 4:04:00 PM at 3408 SHELTON AVE, BETHLEHEM TWP, NORTHAMPTON The incident occurred on 3/24/2026 at 3408 SHELTON AVE in BETHLEHEM TWP in NORTHAMPTON County. A Water service line owned by Bethlehem City was damaged. BETHLEHEM CITY, the facility owner, stated in their Alleged Violation Report (AVR) that, "Contractor was drilling to install CATV main and hit water service line at 3408 Shelton Ave." Picture file named " Shelton" is taken on 3/30/2026, but shows a very faded blue mark. Horizon Cable Construction Inc., the excavator, was sent an AVR request letter on 3/30/2026. See Buckley Cable Construction, who stated they represent Horizon Cable Construction Inc. No tickets have been submitted by Horizon Cable Construction Inc. for this event. BUCKLEY CABLE CONSTRUCTION, the project owner, was sent an AVR request letter on 3/30/2026. On 4/15/2026 DPI Maki returned a call to Ed Boyle from Buckley Cable Construction. He stated that E M Utility	**City of Bethlehem: $750.00** Section 2(5)(v.2) 1st Offense $250.00 Section 2(5)(i) 1st Offense $500.00 **Horizon Cable Construction Inc.: $1,000.00** Section 5(23) 1st Offense $500.00 Section 5(11.2) 1st Offense $500.00 **COMCAST: $1,000.00** Section 2(5)(v) Subsequent $1,000.00 **VERIZON: $3,500.00** Section 2(5)(iii.1) Subsequent $1,500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		places all the OneCall tickets and manages the Complex Project meetings. DPI Maki made Ed aware that each excavator needs to submit their own excavation ticket. The AVR report is required from the Buckley Cable construction, who was hired by Verizon. Ed from BUCKLEY CABLE CONSTRUCTION asked and was told to submit the AVR through the OneCall site and that he will need to sign in to do so. He stated that he will submit the AVR. BUCKLEY CABLE CONSTRUCTION stated in their AVR that they represent Comcast. They stated in their AVR that, "Our Underground contractor hit a water service while installing conduit." Project is 7500'. Reports were provided. E M UTILITY CONTRACTORS WAS sent an AVR request letter on 3/30/2026. E M UTILITY CONTRACTORS stated in their AVR that they represent Horizon Cable Construction Inc., and stated in their AVR that, "While the crew was working in the area, a water line was unintentionally damaged during the process of removing the equipment. The line had been properly marked, and the contact occurred while exiting the work area." VIOLATIONS Horizon Cable Construction Inc. is in violation of: Section 5(11.2) – When using trenchless technology, Excavator failed to utilize at a minimum, the best practices published by the Common Ground Alliance.CGA BEST PRACTICES 22.0, Chapter 5-29 which states that " CGA 5-29 The trenchless excavation operator confirms and maintains the path and minimum clearances established by the project owner and design engineer by tracking and recording the path of the trenchless excavation until complete. " Section 5(23) – Excavator may not delegate their duty to submit a locate request to the One Call System to another person. The excavator shall have sole responsibility to submit each locate request to the One Call System Recommendation: The penalty is applied. PUC compliance education is required for the excavators working onsite of this excavation or their replacements. Bethlehem City is in violation of: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Renotify ticket 20260722474-001 was submitted by E M UTILITY CONTRACTORS3/13/2026 asking for water to be marked, with a response due by 3/17/2026, who were working for BUCKLEY CABLE CONSTRUCTION and submitted the ticket on behalf of Horizon Cable Construction Inc. Ticket 20260722474-000 was submitted by E M UTILITY CONTRACTORS on 3/13/2026 with a response due by 3/17/2026. Picture file named " Shelton" is taken on 3/30/2026, and shows a very faded blue mark. The excavator, EM Utility Contractors, who was placing tickets for Buckley Cable Construction, requested this to be remarked on with	Section 2(5)(v) Subsequent $2,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		ticket 20260722474-000 submitted on 3/13/2026 and renotified on 3/25/2026. This line should have been remarked. It's possible that the first ticket the facility saw their own line and responded "filed marked" but renotify ticket 20260722474-001 was submitted by E M UTILITY CONTRACTORS working for BUCKLEY CABLE CONSTRUCTION on 3/13/2026 asking for water to be marked, with a response due by 3/17/2026. RNO remarks" ATTN WTR YOU RESPONDED AS FIELD MARKED. CALLER STATES THERE ARE NO MARKINGS ON SITE, PLEASE RECHECK AND MARK THE LINES." Recommendation: The penalty is applied. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). VERIZON is in violation of: Section 2(5)(iii.1) – Facility owner failed to propose a mutually agreeable scheduling by which the excavator, facility owner or designer may locate the facilities. Emergency ticket 20260834523 was submitted by BETHLEHEM CITY on 3/24/2026 at 17:17. Verizon responded "Insufficient Info. Do not dig." and never updated their response. There are no notes showing a mutual schedule agreement. This is a subsequent offense. Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket 20260722474-000 was submitted by E M UTILITY CONTRACTORS on 3/13/2026 with a response due by 3/17/2026. Verizon did not respond "clear" until 4/09/2026. This is a subsequent offense. Recommendation: The penalty is applied. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). COMCAST is in violation of: Section 2(5)(v) – Failed to respond to a routine One Call ticket. Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20260722474-000 was submitted by E M UTILITY CONTRACTORS on 3/13/2026 with a response due by 3/17/2026. Comcast did not respond "Clear" until 3/18/2026. This is a subsequent offense. Recommendation: The penalty is applied. PUC compliance education has been recently completed.	
63349	**Facility Owner:** Veolia Water **Contractor/Excavator:** MTV SOLUTIONS **Project Owner:** Coral Reef Partners **Other:** Everstream **Other:** Frontier Communications of Pa Inc **Other:** PPL Electric	On 3/24/2026 4:30:00 PM at 6350 BRACKBILL BLVD, HAMPDEN TWP, CUMBERLAND PPL accepts. They had disputed; the penalty was reduced as a one-time courtesy. Education is required, The emergency ticket was requested on 03/24/2026 at 4:34 PM. PPL (and Everstream and Frontier) all replied with "Insufficient Info. Do not Dig" all at the same time on 03/24/2026 at exactly 4:50:46 PM. None of the stakeholders circled back and responded clear or marked.	**MTV SOLUTIONS: $500.00** Section 5(23) 1st Offense $500.00 Section 5(16) 1st Offense $0.00 **Everstream: $0.00** **Frontier**

Case Number	Stakeholders	Summary	Violations & Recommendation
		Emergency ticket 20260834384 was requested on 03/24/2026. - PPL Electric responded “Insufficient Info. Do not Dig” on 03/24/2026 at 4:50:46 PM. - Everstream responded “Insufficient Info. Do not Dig” on 03/24/2026 at 4:50:46 PM. - Frontier Communications of Pa Inc. responded “Insufficient Info. Do not Dig” on 03/24/2026 at 4:50:46 PM. - There was no documented follow up with the excavator by these 3 stakeholders. ********* Everstream violation withdrawn. They submitted information indicating that the organization was no longer operating. ********* The incident occurred on March 24th, 2026, at approximately 4:30 PM, at 6350 Brackbill Blvd., located in Hampden Township, Cumberland County, Pennsylvania. A water line owned by Veolia Water was damaged. Veolia Water, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “One Call was placed over 5 months ago, with no follow-up calls to refresh markings after rain and snow. The last One Call was on 10/15/2025. The excavator did not appear to keep equipment on site during excavation, which would have required a new One Call request and re-marking of the lines. There were no visible lines or white lines in the excavation area, and no other utility lines were marked on site.” Photos were submitted. Their AVR lists Coral Reef Partners as the excavator. Coral Reef Partners submitted an AVR listing their role as, “Project Manager”. Their AVR states, “On March 24, 2026, at approximately 4:30 PM, an underground water facility was encountered and damaged during excavation/drilling activities associated with the Hampden Solar Project located at 6350 Brackbill Boulevard, Mechanicsburg, PA 17050. At the time of the event, excavation activities were being performed by MTV Solutions under its contracted scope of work. Upon discovery of the damaged facility, work was immediately stopped in the affected area, the location was secured, and site response procedures were initiated. Appropriate notifications were made, and assistance was requested to isolate the affected water service. Water service was shut down at approximately 5:50 PM. Prior to the commencement of excavation activities, a Pennsylvania One Call notification had been obtained and utility locate markings were present in the work area. Based on information currently available, there appears to be a discrepancy between the marked location of the facility and the actual location encountered in the field. However, the cause of the event has not yet been	**Communications of Pa Inc: $1,500.00** Section 2(5)(vii) 2nd Offense $1,500.00 **PPL Electric: $0.00** Section 2(5)(vii) 2nd Offense $0.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		determined and remains subject to review and verification by the facility owner, locating entity, excavator, and other involved parties. Coral Reef Partners is continuing to cooperate with all parties involved in the investigation and is providing this report based on information presently available. This report is not intended as an admission of liability, fault, or regulatory violation by any party. Coral Reef Partners expressly reserves all rights and the ability to supplement, revise, or amend this report should additional facts or documentation become available." Photos were submitted. Their AVR lists MTV Solutions as the excavator. MTV Solutions is the excavator. A courtesy AVR request letter was not sent. An AVR has not been filed as of 07/27/2026. The submitted photos show a significant amount of water actively coming out of the ground where the line was damaged (image0003.png). This resulted in a significant amount of flooding outside of a warehouse (image0001.png). In the submitted photos, blue paint and flags can be seen. However, those mark outs were not for a recently placed ticket. The most recent routine ticket was requested by Coral Reef Partners (Project Manager) on 10/09/2025. Coral Reef Partners placed an emergency ticket on 03/24/2026, after the water line was damaged. MTV Solutions did not have a Pa One Call ticket. The only tickets submitted for this location were requested by Coral Reef Partners. Pa One Call reported MTV Solutions has placed One Call tickets in the past, but there were no ticket requests in 2026. Pa One Call confirmed there were no tickets requested for the location of this incident. Emergency ticket 20260834384 was requested on 03/24/2026. - PPL Electric responded "Insufficient Info. Do not Dig" on 03/24/2026 at 4:50:46 PM. - Everstream responded "Insufficient Info. Do not Dig" on 03/24/2026 at 4:50:46 PM. - Frontier Communications of Pa Inc. responded "Insufficient Info. Do not Dig" on 03/24/2026 at 4:50:46 PM. - There was no documented follow up with the excavator by these 3 stakeholders. Act 127 of 2024, also known as the Underground Utility Line Protection Law states it shall be the duty of each excavator who intends to perform excavation or demolition work within this Commonwealth: - To not delegate the excavator's duty to submit a locate request to the One Call System to another person. The excavator shall have the sole responsibility to submit each locate request to the One Call System.	

Case Number	Stakeholders	Summary	Violations & Recommendation
		- Plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner's facilities in the construction area. - To submit a report of an alleged violation to the commission through the One Call System not more than thirty days after striking or damaging a facility owner's line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. The report of an alleged violation shall be in a form and manner as required by the commission. Violations: MTV Solutions- - Section 5(23) – Excavator may not delegate their duty to submit a locate request to the One Call System to another person. The excavator shall have sole responsibility to submit each locate request to the One Call System. - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. – Warning. No penalty applied for this violation. Recommendation: The penalty is applied. PUC online Compliance Training is required for the individual(s) responsible, or their replacement(s). PPL Electric- - Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Emergency ticket 20260834384. Recommendation: Penalty reduced to zero. PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Everstream- - Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Emergency ticket 20260834384. - Withdrawn. Recommendation: The penalty is applied. PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Frontier Communications of Pa Inc.- - Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Emergency ticket 20260834384. Recommendation: The penalty is applied. PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).	
63379	**Facility Owner:** Peoples Gas **Contractor/Excavator:** Mascaro Construction **Other:**	On 3/25/2026 9:00:00 AM at 901 Penn Ave and 9th St, PITTSBURGH CITY, ALLEGHENY The incident occurred on 3/25/2026 at the corner of 901 Penn Ave. NS 9th St., in Pittsburgh City, Allegheny County.	**Mascaro Construction: $2,000.00** Section 5(17) 1st Offense $500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
	Other: INDEPENDENCE EXCAVATING INC **Other:** MATCON DIAMOND	A Gas line owned by PEOPLES NATURAL GAS COMPANY LLC was damaged. PEOPLES NATURAL GAS COMPANY LLC, the facility owner, stated in their Alleged Violation Report (AVR) that “Mascaro Construction struck and damaged a Peoples Gas steel service line. A locate request was not placed”. Pictures were provided. 911 was not notified. Work is for site development. *Compliance research results: Mascaro has called in tickets. MASCARO CONSTRUCTION stated in their AVR that, “Mascaro Construction was the general contractor for the construction of new four (4) acre space, Arts Landing at 803 Penn Ave Pittsburgh, PA 15222. Part of the scope of work was sidewalk replacement including replacement of 9th Street sidewalk between Penn Ave and Ft Duquesne Blvd. Our subcontractors, Matcon Diamond and Independence Excavation placed PA OneCall's along 9th street prior beginning sidewalk replacement work (PA OneCall numbers 20252902001 and 20251340940 respectively). Matcon Diamond saw cut the existing 9th street sidewalk, and Independence Excavating removed the existing sidewalk. This work took place in October 2025 and neither during, nor after, were there any signs of this gas line as it was not uncovered or hit, nor was there any evidence of a leak. However, on 3-25-26, Mascaro Construction, with their own labor force, was backfilling 9th street and noticed a "gas smell" from approximate location 823 Penn Ave (area clouded on the attached drawing submitted with this application) and immediately called People's Gas company to report the gas smell. People's Gas Company came to project site and began searching for the gas leak and eventually appeared to have removed the gas line at the main line in the middle of the roadway on 9th Street. Please note, as can be seen on the attached C006 existing condition drawing, there is no existing gas line shown in the area where the leaking gas line was found nor was it marked by any utility company during the one call operations. Picture was provided. Mascaro Construction, the general contractor and excavator, was sent an AVR request letter on 4/01/2026, with questions about the project, including who engaged Mascaro Construction to excavate for this project, who the final designer was for this project, the cost of the project and if a complex project ticket was placed for this. These questions were never answered. On 8/11/2026, Damage Prevention Investigator (DPI) Maki sent an email, to Mascaro Construction and received a delivery complete message. On 8/11/2026, Mascaro sent an email stating that, “Please note that during our construction of the Arts Landing project located at 803 Penn Ave, we have had numerous PA OneCalls. The following are several OneCall's placed specific to the area identified in the letter”. Mascaro Construction provided tickets submitted by MATCON DIAMOND and INDEPENDENCE EXCAVATING	Section 5(2.1) 2nd Offense $1,500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		INC. With this additional information, AVR request letters were sent to these 2 excavators. Mascaro Construction added that "In addition, the address noted in the letter (901 Penn Ave) is not associated with our site, nor did we do work at that address. Within our construction site, while backfilling the sidewalk at address 823 Penn Ave, we exposed an existing leaking gas line. At that point, one of our personnel dialed 911 to alert them. People's Gas then arrived and began excavation at the address referenced in the letter, presumably to correct the issue." AVR request letter had questions that were not answered. MATCON DIAMOND submitted AVR2026AUG120010. They stated in their AVR that, "We received an email on 8-10 that a gas line was exposed when Mascaro was excavating the roadway in March asking if we placed a one call and to provide the one call number. Which we did and I sent 20252902001. Matcon sawcut on 9th st. between penn ave and duquesne blvd back in October of 2025. This email on 8-10 and a subsequent request for an AVR be submitted from PAPUC on 8-11-26 were the first I'm hearing about a utility line was struck in March on the project. Matcon was not on-site in March 2026." INDEPENDENCE EXCAVATING INC, the excavator, stated in their AVR that, "Independence Excavating or any associated subcontractors were not onsite at the date of the alleged violation." The pictures show an old, damaged pipe. Mascaro Construction called this damage in to Peoples Gas. Mascaro did not damage this pipe. Mascaro, an excavator, was backfilling without a valid PAOneCall ticket. VIOLATIONS Mascaro Construction is in violation of: Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within 30 days of the receipt of the request. When the AVR was submitted, most of the questions in the AVR request were not answered, including who engaged them to do this work. Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Recommendation: The penalties are applied. PUC compliance education is required for the excavators working onsite of this excavation or their replacements.	
63448	**Facility Owner:** PECO **Contractor/Excavator:** CADDICK UTILITIES LLC **Project Owner:** AQUA PENNSYLVANIA INC **Designer:** TOTAL ENGINEERING AND CONSULTING SERVICES LLC	On 3/25/2026 10:30:00 AM at 3343 BRYAN CT S, BENSALEM TWP, BUCKS The incident occurred on 3/25/2026 at 3343 BRYAN CT S, in Bensalem Township, in Bucks Co. An electric service line owned by PECO was damaged. PECO the facility owner, stated in their AVR that, "Locators marks were faded but visible, Contractor marked the lines in white with depth of the utility in	**CADDICK UTILITIES LLC: $500.00** Section 5(6)(ii) 1st Offense $500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		question. Locators marks were accurately in line with utility". Pictures and reports were provided. PECO AN EXELON COMPANY submitted another AVR which stated that, "Caddick Utilities damaged Secondary service. During excavation of a trench for new water main, operator damaged the Plastic Sheathing of the Electric Service Line. Locators marks were accurately in line with utility." CADDICK UTILITIES LLC, the excavator, stated in their Alleged Violation Report (AVR) that, "Damaged correctly marked electric line. LIne was previously located using vacuum techniques, but as operator was undermining the line, in the tolerance zone, a loose rock got pulled into the conduit, kinking it and causing the damage. Pictures and reports were provided. AQUA PENNSYLVANIA INC, the project owner stated that, "Aqua Contractor Caddick Utilities damaged correctly marked electric line. Line was previously located using vacuum techniques, but as operator was undermining the line, in the tolerance zone, a loose rock got pulled into the conduit, kinking it and causing the damage. 3343 Bryan Ct." PECO the facility owner, stated in their AVR that, "Locators marks were faded but visible, Contractor marked the lines in white with depth of the utility in question. Locators marks were accurately in line with utility". Pictures and reports were provided. PECO AN EXELON COMPANY submitted another AVR which stated that, "Caddick Utilities damaged Secondary service. During excavation of a trench for new water main, operator damaged the Plastic Sheathing of the Electric Service Line. Locators marks were accurately in line with utility." TOTAL ENGINEERING AND CONSULTING SERVICES LLC, the designer, stated in their AVR that, "Aqua Contractor Caddick Utilities damaged correctly marked electric line. Line was previously located using vacuum techniques, but as operator was undermining the line, in the tolerance zone, a loose rock got pulled into the conduit, kinking it and causing the damage. 3343 Bryan Ct." *Case is connected by ticket to case 63632 Other AVR's that were submitted: BUCKS COUNTY WATER AND SEWER AUTHORITY submitted an AVR stated "Caddick Utilities, for Aqua, was replacing water hydrants, services and mains in Bensalem Township. A PECO electric line was hit on March 25, 2026. BCWSA was not involved in this hit and marked out mains for the ticket." VIOLATIONS CADDICK UTILITIES LLC is in violation of: Section 5(6)(ii) – Excavator failed to provide support and mechanical protection for known facility owner's	

Case Number	Stakeholders	Summary	Violations & Recommendation
		lines at the construction work site. Attachment named "PECO faded red mark" shows that the red marking was in line with the facility. Per AVR from Caddick, they located the facility with a vac truck, but as they "undermined the line", with mechanical equipment in the tolerance zone, "a loose rock got pulled into the conduit" causing the damage. Pictures provided by PECO show the damage and area around the damage. See attachment named "AVR photos – 3343 Bryan Ct., Bensalem, AQUA pdf" Recommendation: The penalty is applied. PUC compliance education is required for the excavators working onsite of this excavation or their replacements.	
63987	**Facility Owner:** PECO **Contractor/Excavator:** Placeholder - Home owner **Project Owner:** Home Owner	On 3/26/2026 3:00:00 PM at 27 Lafayette Circle, UPPER UWCHLAN TWP, CHESTER The incident occurred on 3/26/2026, at 3:00 PM, on 27 Lafayette Circle, in Upper Uwchlan Twpchester, Chester County. An electric line owned by PECO was damaged. PECO is the facility owner. Their Alleged Violation Report (AVR) states, "On 3/13/26, Sean Storms was using an excavator and damaged an electric service." Sean Storms is the excavator listed on PECO's AVR report. He is the home owner, and project owner, at the location of the damage. An AVR was not filed and an AVR request was sent on 8/4/2026 to Sean. No information has been provided as of the date the report was submitted. Images submitted by PECO show the site, and damaged line. No equipment is shown, and no verification of who caused the excavation is shown. No information was provided by the homeowner Sean Storms. Sean is also the excavator listed on PECO's AVR. As no information was provided by the alleged Excavator, and confirmed Homeowner, a full investigation could not be completed. Act 127 of 2024 requires the Excavator, and the Project Owner, to submit an AVR within 30 days of an incident. SECTION 5. It shall be the duty of each excavator who intends to perform excavation or demolition work within this Commonwealth: (16)To submit a report of an alleged violation to the commission through the One Call System not more than thirty days after striking or damaging a facility owner's line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. The report of an alleged violation shall be in a form and manner as required by the commission. SECTION 6.1. It shall be the duty of each project owner who engages in excavation or demolition work to be done within this Commonwealth: (7)To submit a report of alleged violation to the commission through the One Call System not more than thirty days after striking or damaging a facility owner's line during excavation or demolition work activities, after a project owner's	**Home Owner: $1,000.00** Section 6.1(7) 1st Offense $1,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		contracted excavator strikes or damages a facility owner's line during excavation or demolition activities or if the project owner believes a violation of this act has been committed in association with excavation or demolition. The report of alleged violation shall be in a form and manner as required by the commission. Violations: Project Owner - Sean Storms: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement.	
63519	**Facility Owner:** UGI **Contractor/Excavator:** Dave Gutelius Excavating **Project Owner:** Pa American Water	On 3/30/2026 9:05:00 AM at KING STREET, POINT TWP, NORTHUMBERLAND The incident occurred on 3/30/2026 on King St in Point Township in Northumberland Co. A 2" plastic main line owned by UGI was damaged. UGI, the facility owner, stated in their AVR that," While performing work for PA American Water, a contractor struck and damaged an incorrectly marked gas main." They added that, "At some point there was a section of gas main that ran around a manhole box in the intersection. There was no record of this new section being installed." Pictures and reports were provided. DAVE GUTELIUS EXCAVATING INC, the excavator, stated in their Alleged Violation Report (AVR) that, "Working for PA American Water Company replacing water and services on King Street in Northumberland, Point Township, we hit a 2-inch plastic gas main owned by UGI that was mismarked by approximately 7 feet. 911 was called along with UGI and 811. The incident happened at the intersection of King Street and 11th Street." Project is >$400,000. With an area of 1900 LF. Pictures and reports were provided. PENNSYLVANIA AMERICAN WATER, the project owner, stated in their AVR that, "Contractor was excavating a trench to install a new water main. They were approaching a gas mark in the intersection of 11th St and were soon to stop to locate the main when they hit another gas main that was not marked. 911 and then 811 was called to report the damage". Project is >$400,000 and 1950'. Pictures and reports were provided. VIOLATIONS UGI is in violation of: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. This is a second offense. See attachment named "Converted pic 3." Recommendation: The penalty is applied. PUC compliance education has been recently completed.	**UGI: $1,000.00** Section 2(5)(i) 2nd Offense $1,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
63535	**Facility Owner:** Williamsport Municipal Water Authority **Contractor/Excavator:** Pipe Doctor **Project Owner:** HOMEOWNER	On 3/30/2026 11:00:00 AM at 523 HILL ST, SOUTH WILLIAMSPORT BORO, LYCOMING The incident occurred on 3/30/2026 at 523 HILL ST in SOUTH WILLIAMSPORT BORO in LYCOMING Co. A water service line owned by WILLIAMSPORT SANITARY AUTHORITY (WMWA) was damaged. WILLIAMSPORT SANITARY AUTHORITY stated in their Alleged Violation Report (AVR) that, "A contractor, Pipe Doctor, his a WMWA owned water service line while excavating for an owner sewer line repair." WILLIAMSPORT SANITARY AUTHORITY and Williamsport Water Authority have the same contact information. It was noted that 911 was called. Pipe Dr stated in their AVR that, "We were digging in the street to repair the sewer line to the main which was collapsed clay piping when we hit the water line that went to the customers house. The blue markings were off by about 2FT so we hit the water line and the Williamsport water authority came out and repaired the line." Homeowner was sent an AVR request letter on 4/07/2026. Homeowners' daughter responded to the AVR. Pictures show that the water line was marked in line with the damage. VIOLATIONS Pipe Doctor is in violation of: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Within the tolerance zone, the excavator shall employ prudent techniques, which may include hand-dug test holes, vacuum excavation or similar devices to ascertain the precise position of such facilities. Recommendation: The penalty is applied. PUC compliance education is required for the excavators working onsite of this excavation or their replacements.	**Pipe Doctor: $500.00** Section 5(4) 1st Offense $500.00
63480	**Facility Owner:** PENCOR SERVICES / BLUE RIDGE COMMUNICATION **Contractor/Excavator:** EROSION PROTECTIVE SERVICES **Project Owner:** COMCAST	On 3/30/2026 2:00:00 PM at WATAWGA WAY E, LEHIGH TWP, WAYNE The incident occurred on 3/30/2026 at WATAWGA WAY E in LEHIGH TWP in Wayne Co. A Communications line owned by PENCOR SERVICES / BLUE RIDGE COMMUNICATION was damaged. PENCOR SERVICES / BLUE RIDGE COMMUNICATION stated in their Alleged Violation Report (AVR) that, "Contractor hit underground conduit/facilities. The one call was completed properly, but the contractor dug within the tolerance zone." Report and pictures were provided. EROSION PROTECTIVE SERVICES AVR stated that, "We were digging with excavator and we damaged the Pencor Services/Blue Ridge Communication service	**EROSION PROTECTIVE SERVICES: $500.00** Section 5(4) 1st Offense $500.00 **COMCAST: $2,500.00** Section 6.1(7) 2nd Offense $1,500.00 Section 6.1(8) 2nd Offense $1,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		line. We called 811 and Blue Ridge fixed issue within 20 minutes." They added that, "lines were visible; however, location was off." The project is listed at 15,000', Pictures were provided. COMCAST the project owner was sent an AVR request letter on 4/03/2026. No AVR has been received as of 7/17/2026. VIOLATIONS Comcast is in violation of: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike or damaging a facility owner's line during excavation or demolition work activities or if a project owner believes a violation of this act has been committed in association or demolition. This is a second time offense. Section 6.1(8) - Project Owner failed to comply with all requests for information by the commission relating to the commission's enforcement authority under this act within 30 days of receipt of written request. This is a second time offense. Recommendation: The penalties are applied. PUC project owner compliance education is required for the person responsible for submitting AVR or their replacement. EROSION PROTECTIVE SERVICES is in violation of: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Within the tolerance zone, the excavator shall employ prudent techniques, which may include hand-dug test holes, vacuum excavation or similar devices to ascertain the precise position of such facilities. Recommendation: The penalty is applied. PUC compliance education is required for the excavators working onsite of this excavation or their replacements. *Ticket 20260290415 was provided because it is in the same area where the damage occurred, but this ticket does not have a direct connection to case 63480.	
64468	**Facility Owner:** COMCAST **Contractor/Excavator:** FRIENDLY UNDERGROUND CONSTRUCTION LLC **Project Owner:** BRIGHTSPEED **Designer:** PALNIES **Other:** METROPOLITAN EDISON / FIRSTENERGY	On 4/1/2026 12:00:00 AM at MEADOWVIEW CT, UNION TWP, ADAMS Met-Ed First Energy disagrees. On 10/27/2026 an email was received from Met Ed accepting the violation and penalty. ********** The incident occurred on 4/01/2026 at Meadowview Ct in Union Township in Adams Co. A communications line owned by Comcast was damaged. COMCAST stated in their Alleged Violation Report (AVR) that, "Contractors for brightspeed running fiber underground cut our cable." Pictures and reports were provided. On 7/21/2026 an email was received which stated that," The correct date is 4/1/26, the tech had the wrong date listed on the form."	**FRIENDLY UNDERGROUND CONSTRUCTION LLC: $1,500.00** Section 5(11.2) 1st Offense $500.00 Section 5(16) 1st Offense $1,000.00 **BRIGHTSPEED: $1,750.00** Section 6.1(7) 2nd Offense $1,500.00 Section 2(5)(iii.1) 1st Offense $250.00 **METROPOLITAN**

Case Number	Stakeholders	Summary	Violations & Recommendation
		FRIENDLY UNDGERGROUND CONSTRUCTION LLC stated in their AVR that, "Comcast line was damage will installing new conduit for Brightspeed." Pictures were provided. Brightspeed was sent an AVR request letter on 5/15/2026. No AVR has been submitted as of 7/17/2026. VIOLATIONS FRIENDLY UNDGERGROUND CONSTRUCTION LLC is in violation of: Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or damaging a facility owner's line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. FRIENDLY UNDERGROUND CONSTRUCTION LLC was sent an AVR request letter on 5/15/2026. AVR was due by 4/29/2026. FRIENDLY UNDGERGROUND CONSTRUCTION LLC submitted their AVR on 5/21/2026. Section 5(11.2) – When using trenchless technology, Excavator failed to utilize at a minimum, the best practices published by the Common Ground Alliance. CGA 5-29 The trenchless excavation operator confirms and maintains the path and minimum clearances established by the project owner and design engineer by tracking and recording the path of the trenchless excavation until complete. Recommendation: The penalties are applied. PUC compliance education is required for the excavators working onsite of this excavation or their replacements. BRIGHTSPEED is in violation of: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike or damaging a facility owner's line during excavation or demolition work activities or if a project owner believes a violation of this act has been committed in association or demolition. This is a second offense. Section 2(5)(iii.1) – Facility owner failed to propose a mutually agreeable scheduling by which the excavator, facility owner or designer may locate the facilities. Ticket 20260774953 was submitted on 3/18/2026 with a response due by 3/20/2026. The work to start at 49 Ashfield Dr and continue to 3 Ashfield Ct. Area was marked in pink. Brightspeed did not mark until 3/23/2026. This delay was not in mutual agreement with the excavator. There are no notes in the ticket response. Recommendation: The penalties are applied. PUC project owner compliance education is required for the person responsible for submitting AVR or their replacement. PUC facility owner compliance education has been recently completed. METROPOLITIN EDISON / FIRSTENERGY is in violation of: Section 2(5)(iii.1) – Facility owner failed to propose a mutually agreeable scheduling by which the excavator, facility owner or designer may locate the facilities.	**EDISON / FIRSTENERGY: $250.00** Section 2(5)(iii.1) 1st Offense $250.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Ticket 20260774953 was submitted on 3/18/2026 with a response due by 3/20/2026. The work to start at 49 Ashfield Dr and continue to 3 Ashfield Ct. Area was marked in pink. Metropolitan Edison Co / Firstenergy did not mark until 3/23/2026. This delay was not in mutual agreement with the excavator. There are no notes in the ticket response. Recommendation: The penalty is applied. PUC compliance education has been recently completed.	
63747	**Facility Owner:** UGI **Contractor/Excavator:** RLE Enterprises **Project Owner:** Pennsylvania American Water	On 4/2/2026 9:15:00 AM at WYOMING AVE, SCRANTON CITY, LACKAWANNA The incident occurred on April 2nd, 2026, at approximately 9:15 AM, on Wyoming Avenue, located in Scranton City, Lackawanna County, Pennsylvania. A gas line owned by UGI was damaged. UGI, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “Excavator struck and damaged correctly marked gas facility with mechanized equipment in the tolerance zone.” Photos were submitted. RLE Enterprises, the excavator, submitted an AVR. Their AVR states, “While digging for a new sewer main installation, our crew struck a miss marked 2" gas main. Our crew located the 2" gas main with vac excavation and while removing material 2 /1/2' above the exposed gas main, it was struck because the gas main had a 2 1/2' vertical by 18" offset that wasn't marked out. 911 and UGI were notified and arrived onsite. UGI made repairs and restored service in a timely manner.” Photos were submitted. PA American Water, the project owner, submitted an AVR. Their AVR states, "Existing gas main was vactor located and miss marked by 2 ft on 3/31, UGI was called back out on 3/31 and remarked mainline. Vactor was used and found where the main was located. 4/2 RLE was excavating and located the existing main again at a depth 6’5” and the 2 inch plastic was inserted into steel main. RLE was excavating above the existing mainline and found the 2 inch plastic h plastic 90 and drop pipe 2’4” higher than the existing mainline with the bucket of the machine. The vertical offset was not marked by UGI. Nor was it mentioned during the remark process on 3/31. The crew was told by UGI that the plastic main was inserted into an existing pipe, but this was not the case at the 2’4” offset location.” Photos were submitted. The submitted photos show the damaged gas line. Yellow paint was used to mark the gas line. The submitted photos show the damaged gas line was accurately marked using yellow paint. The most recent ticket (20260843142) was requested on 03/25/2026. UGI timely responded, ‘Field Marked’ on Thursday, 03/26/2026. (Damage occurred the following Thursday, 04/02/2026.) Both the excavator and project owner reported that the excavation area had been vac excavated on 03/31/2026. PA American Water reported in their	**RLE Enterprises: $250.00** Section 5(4) 1st Offense $250.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		AVR that UGI was called back out on 03/31/2026 to remark the mainline. There were no additional Pa One Call tickets located by PA One Call requesting UGI to return to remark the site. While excavating, a vertical offset of the gas line was damaged within the tolerance zone. Both the excavator and project owner noted in their AVRs that they were not made aware of the vertical offset/ it was not marked out. There was no report that the vertical offset was located when the vacuum excavation was completed. Act 127 of 2024, also known as the Underground Utility Line Protection Law states it shall be the duty of each excavator who intends to perform excavation or demolition work within this Commonwealth: - To exercise due care and to take all reasonable steps necessary to avoid injury to or otherwise interfere with all lines where positions have been provided to the excavator by the facility owners pursuant to section 2 (5). Within the tolerance zone the excavator shall employ prudent techniques, which may include hand-dug test holes, vacuum excavation or similar devices to ascertain the precise position of such facilities. Violations: RLE Enterprises- - Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: The penalty is applied. PUC online Compliance Training is required for the individual(s) responsible, or their replacement(s). Penalty reduced by 50% from $500 to $250 since vacuum excavation was utilized. However, the vacuum excavation was not performed to an extent that accurately determined the precise location of the entire facility within the excavation area.	
63639	**Facility Owner:** Brightspeed **Contractor/Excavator:** HET, Inc. **Project Owner:** Municipal Water Authority of Adams Township **Designer:** HERBERT ROWLAND AND GRUBIC INC **Other:** Armstrong **Other:** Peoples Natural Gas	On 4/3/2026 1:00:00 PM at cayman, PENN TWP, BUTLER Peoples Natural Gas provided additional documentation that the locator was on site. Violation reduced to a warning of $0 *** The incident occurred on 4/3/2026, at 1:00 PM, on Cayman Drive, in Penn Twp, Butler County. A communication line was damaged. An emergency ticket was entered for the damage. Armstrong and Brightspeed are the two communication companies on the tickets. Armstrong states, “Armstrong cable was not hit or notified of anything being hit.” Markout images were requested as the flag in the photo is a USIC flag. Markout images show the USIC flag was placed during these marks. The damage ticket entered states, "PER CALLER LINE IS A TELECOM LINE WHICH MAY BE ARMSTRONG WHICH WAS OUTSIDE OF THE TOLERANCE ZONE." Both Armstrong and Brightspeed responded "Clear" to the damage ticket.	**Brightspeed: $3,000.00** Section 2(5)(vii) 1st Offense $1,000.00 Section 2(5)(viii) 1st Offense $500.00 Section 2(10) 1st Offense $1,000.00 Section 2(14) 1st Offense $500.00 **HET, Inc.: $1,500.00** Section 5(4) 1st Offense $500.00 Section 5(16) 1st Offense $1,000.00 **Armstrong: $1,500.00** Section 2(5)(vii) 1st

Case Number	Stakeholders	Summary	Violations & Recommendation
		Brightspeed did not respond to the AVR request. HET Contracting Corp is the excavator. An AVR was not filed as of 06/01/2026 and an AVR request was sent the same day. HET has submitted AVRs in the past. An AVR was submitted the same day as the AVR request (59 days after the incident) that states, "We were digging a ditch for new waterline, when we encountered a cable line. It was struck and damaged. The line was approximately 2 feet from the center of the flags." The municipal water authority of Adams Township is the project owner. The AVR submitted by Herbert Rowland was also submitted on behalf of the project owner. Herbert Rowland And Grubic Inc is the designer. Their AVR states, "contractor was digging to uncover a marked telecom line on Cayman Drive (near house 105), when attempting to remove a rock from under line, a wire (without conduit) broke." Ticket #20260931956 was entered for the damage on 4/3/26 at 1:40 PM. Peoples Natural Gas' only response was "Field Marked" on 4/6/2026. Images submitted show the marks, and damaged line. The orange marks indicate the line that was damaged. There is no information provided that the line was located using prudent techniques prior to using mechanical excavation. Both Armstrong and Brightspeed responded "Clear" to the damage ticket. Both responded "Field Marked" to the routine ticket. Both responded "Will Attend Meeting" to the Complex Project ticket#20260142228 but neither of them are indicated on the sign in sheet. Armstrong responded on the AVR that it was not their line that was damaged. Brightspeed did not provide any information and is the only other communication provider. The Underground Utility Line Protection Law (UULPL) aka PA One Call Law, ACT 127, Responsibilities Of The Excavator, Section 5(16) states: To submit a report of an alleged violation to the commission through the One Call System not more than thirty days after striking or damaging a facility owner's line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. The report of an alleged violation shall be in a form and manner as required by the commission. The Underground Utility Line Protection Law (UULPL) aka PA One Call Law, ACT 127, Responsibilities Of The Facility Owner, Section 2(10) states: To submit a report of alleged violation to the commission through the One Call System not more than thirty business days after receipt of notice that the facility owner's lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been	Offense $1,000.00 Section 2(5)(viii) 1st Offense $500.00 **Peoples Natural Gas: $0.00** Section 2(5)(v.2) 3rd Offense $0.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		committed in association with excavation or demolition work. The report of alleged violation shall be in a form and manner as required by the commission. Violations: Facility – Brightspeed: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket #20260931956 Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner's lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. Section 2(14) – Facility Owner failed to comply with all requests for information by the Commission relation to the Commission's enforcement authority under this act within thirty days of the receipt of the request. PUC Online Compliance Training is required. Excavator - HET Contracting Corp: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements. Facility (other) - Armstrong: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket #20260931956 Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). Facility (other) - Peoples Natural Gas: Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Ticket #20260931956	
63731	**Facility Owner:** AQUA PENNSYLVANIA INC **Contractor/Excavator:** ANGIES CABLE **Project Owner:** Rhino Cable Services	On 4/6/2026 5:50:00 AM at TOWER LANE, LOWER MERION TWP, MONTGOMERY The non-damage incident occurred on April 6th, 2026, at approximately 5:50 AM, on Tower Lane, located in Lower Merion Township, Montgomery County, Pennsylvania. The excavator provided a misrepresentation of an emergency excavation.	**ANGIES CABLE: $1,000.00** Section 5(22) 1st Offense $500.00 Section 5(17) 1st Offense $500.00 **Rhino Cable Services:**

Case Number	Stakeholders	Summary	Violations & Recommendation
		Aqua Pennsylvania Inc., the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “Excavator submitted non-emergency emergency ticket to install CATV main. Previously submitted a Routine Ticket 20260793980 for the same work. Dig Dates were 3/25/26 to 4/3/26, so the original ticket had expired when they submitted the ticket on 4/6/26. Ticket indicates that a temporary line above ground." Angies Cable is the excavator. An AVR request letter was sent 06/01/2026. An AVR has not been filed as of 07/22/2026. Rhino Cable Services is the project owner. An AVR request letter was sent 06/01/2026. An AVR has not been filed as of 07/22/2026. Routine ticket 20260793980 was requested on 03/20/2026. The location information on the ticket stated: Please locate properties of 201/207 Tower Lane front and rear. Approx. 200 feet. The type of work was listed as: Install CATV main. Emergency ticket 20260960018 was requested on 04/06/2026. The location on the ticket stated: Please locate properties 207 and 201 properties. Back of properties. You will see a temporary main line above ground. The type of work was listed as: Install CATV main. Both the routine ticket from 03/20/2026 and the emergency ticket from 04/06/2026 are for the same location and type of work. Act 127 of 2024 states: "Emergency" means a sudden or unforeseen occurrence involving a clear and immediate danger to life, property or the environment, including, but not limited to, serious breaks or defects in a facility owner's lines. An emergency ticket to install CATV does not represent an emergency. Angies Cable and Rhino Cable Services did not respond to the Damage Prevention Investigator's letter sent on 06/01/2026, requesting additional information. Act 127 of 2024, also known as the Underground Utility Line Protection Law states it shall be the duty of each excavator who intends to perform excavation or demolition work within this Commonwealth: - To not provide a misrepresentation of an emergency excavation, subject to an administrative penalty imposed under section 7.10. - To comply with all requests for information by the commission relating to the commission's enforcement authority under this act within thirty days of the receipt of the request. Act 127 of 2024, also known as the Underground Utility Line Protection Law states it shall be the duty of each excavator who intends to perform excavation or demolition work within this Commonwealth it shall be	**$500.00** Section 6.1(8) 1st Offense $500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		the duty of each project owner who engages in excavation or demolition work to be done within this Commonwealth: - To comply with all requests for information by the commission relating to the commission's enforcement authority under this act within thirty days of receipt of the written request. Violations: Angies Cable- - Section 5(22) – Excavator provided a misrepresentation of an emergency excavation, subject to an administrative penalty imposed under section 7(10). Emergency ticket 20260960018. - Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. Recommendation: The penalty is applied. PUC online Compliance Training is required for the individual(s) responsible, or their replacement(s). Rhino Cable Services- - Section 6.1(8) - Project Owner failed to comply with all requests for information by the commission relating to the commission's enforcement authority under this act within 30 days of receipt of written request. Recommendation: The penalty is applied. PUC online Compliance Training is required for the individual(s) responsible, or their replacement(s).	
63936	**Facility Owner:** PECO **Contractor/Excavator:** Utility Line Services **Project Owner:** Aqua PA **Designer:** BRANDYWINE CAD DESIGN INC **Other:** Comcast **Other:** Verizon	On 4/6/2026 11:42:00 AM at 1111 REMINGTON RD, LOWER MERION TWP, MONTGOMERY The incident occurred on April 6th, 2026, at approximately 11:42 AM, at 1111 Remington Road, located in Lower Merion Township, Montgomery County, Pennsylvania. A gas line owned by PECO was damaged. PECO, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “On 04/06/2026, UTILITY LINE SERVICES INC damaged a gas service with an excavator”. Photos were submitted. Utility Line Services, the excavator, submitted an AVR. Their AVR states, “The crew was trenching in the area of 1111 Remington Road. They located a plastic service pipe by digging a test hole within the markings, then later damaged an unmarked PECO service about 24” away.” Photos were submitted. Aqua PA, the project owner, submitted an AVR. Their AVR states, "Aqua Contractor Utility Line Services, the crew was trenching in the area of 1111 Remington Road. They located a plastic service pipe by digging a test hole within the markings, then later damaged an unmarked PECO service about 24" away.” The submitted photos include photos of the mark outs using yellow paint prior to excavation, as well as two different underground utility lines. The photo submitted	**Comcast: $750.00** Section 2(5)(v) 3rd offense $750.00 **Verizon: $2,000.00** Section 2(5)(v) Subsequent $2,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		by Utility Line Services shows a yellow underground line. The photos submitted by PECO show a dark gray underground line with a black line swirling around the outside of it (similar to electrical tape). Underground gas lines tend to be yellow in color. Both the excavator and project owner reported in their AVRs that a plastic service pipe was located, then the gas line was damaged. The photos showing the gray utility line include a hit kit. The photos with the gas line do not include a hit kit, but instead a shovel. When comparing the gas line to the location of the yellow mark outs, there is about 18 inches. Without a hit kit, the investigator is unable to determine with certainty that the gas line was accurately marked. The excavator and project owner both reported that the excavator had completed test holes where the gray pipe was located, which was within the tolerance zone of the yellow mark outs. No violation applied for the damaged gas line. Investigator is unable to determine if the damaged gas line was within the tolerance zone of the painted yellow markouts. Routine ticket 20260780466, requested on 03/19/2026, had a response due date of 03/23/2026. - Comcast responded late, by entering the response 'Clear' on 03/25/2026. Routine ticket 20260893948, requested on 03/30/2026, had a response due date of 04/01/2026. - Verizon responded late, by entering 'Clear' on 04/13/2026. Routine PA One Call tickets are required to be responded to by the response due date listed on the ticket. Act 127 of 2024, also known as the Underground Utility Line Protection Law states it shall be the duty of each facility owner: Section 2– After receipt of a timely request from an excavator or operator who identifies the work site of excavation or demolition work he intends to perform and not later than the business day prior to the lawful start date of excavation: Section 2.5.v - To respond to all notices through the One Call System, provided the request is made in the time frame set forth under this act. The response shall be made not later than the end of the second business day following receipt of the notification by the One Call System, excluding the business day upon which the notification is received, or not later than the day prior to the lawful start date of excavation if the excavator specifies a later date or, in the case of an emergency, to respond through the One Call System as soon as practicable following receipt of notification of the emergency by the One Call System. Violations:	

Case Number	Stakeholders	Summary	Violations & Recommendation
		Comcast- - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Routine ticket 20260780466. Recommendation: The penalty is applied. PUC online Compliance Training was recently completed. Verizon- - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Routine ticket 20260893948. Recommendation: The penalty is applied. PUC online Compliance Training was recently completed.	
63660	**Facility Owner:** PECO **Contractor/Excavator:** Brubacher Excavating Inc. **Project Owner:** Aqua PA **Designer:** TOTAL ENGINEERING AND CONSULTING SERVICES LLC **Other:** **Other:** CROWN CASTLE **Other:** EDPO LLC (WOC Energy)	On 4/6/2026 12:55:00 PM at 1535 POORHOUSE RD, WEST BRADFORD TWP, CHESTER PECO disagreed and stated that they do not own this line. Both violations to PECO are withdrawn. PECO is not disputing. ********** The incident occurred on 4/06/2026 on POORHOUSE RD in WEST BRADFORD TWP in Chester Co. An electric line owned by PECO was damaged. BRUBACHER EXCAVATING INC stated in their Alleged Violation Report (AVR) that, "While excavating the trench for new water main installation on Broad Run Rd project, the crew encountered an unmarked electric line. A 3" diameter gray conduit was found at 2'- 8" deep. The excavation was in the street at 1535 Poorhouse Rd. The work was being performed for Aqua PA. Original Ticket #2026 069 2492 and the damage ticket #2026 096 3687." Pictures were provided. DPI Maki sent an email to Brubackers asking if they were charged for damaging this line. On 4/17/2026 Brubacher responded that they are getting this information. On 4/21/2026 an email was received stating that "At this time, no charges have been incurred. The ownership of the line remains unknown. The only responses received were from PECO and USIC, and neither was able to confirm ownership of the utility". AQUA PENNSYLVANIA INC stated in their AVR that, "Aqua Contractor Brubacher Excavating, while excavating the trench for new water main installation on Broad Run Rd project, the crew encountered an unmarked electric line. A 3" diameter gray conduit was found at 2'-8" deep. The excavating was in the street at 1535 Poorhouse Rd. TOTAL ENGINEERING AND CONSULTING SERVICES LLC stated in their AVR that, "Aqua Contractor, Brubacher Excavating, while excavating the trench for a new water main installation on Broad Run Rd project, the crew encountered an unmarked electric line. A 3" diameter gray conduit was found at 2'-8" deep. The excavating was in the street at 1535 Poorhouse Rd. PECO AN EXELON COMPANY, the facility owner, submitted an AVR and noted that this excavator failed to renotify the PAOneCall System of an unmarked facility. PECO did not provide any attachments.	**PECO: $0.00** **CROWN CASTLE: $500.00** Section 2(5)(v) 2nd offense $500.00 **EDPO LLC (WOC Energy): $250.00** Section 2(5)(v) 1st Offense $250.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Utilities of PA were listed in the AVR from Aqua and Brubackers. Utilities of PA stated that they only have sewer in this area. DPI Maki sent an email asking if they knew who has electric in this area. On 4/23/2026 an email named PECO as the provider in this area. PECO was sent an AVR request letter on 4/23/2026. AVR was due by 5/18/2026. In the letter it was asked if PECO could explain where their service ends, if they do not have service in the area, since emergency ticket 20260963687 was responded with "clear no facilities". Ticket 20260692492 was submitted by BRUBACHER EXCAVATING INC on 3/100/2026 with a response due by 3/12/2026. PECO responded "Field marked" on 3/12/2026. Emergency ticket 20260963687 was submitted by BRUBACHER EXCAVATING INC on 4/06/2026 stating that an unmarked utility line was damaged. PECO responded "clear. No facilities or facilities not involved". See attachment named "20260963687 E All responses. Pictures show that the excavator maintained the location of the electric line by using pink markings at a distance around the electric markings. Attachment 1000003820 and 1000003822 Show the red flag between the pink lines. VIOLATIONS PECO is in violation of: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. This is a subsequent offence. Section 2(5)(ix) – Facility owner failed to respond promptly to the site of an excavation where its underground line was damaged. Recommendation: The penalty is applied. PUC compliance education has been recently completed. EDPO LLC (WOC Energy) is in violation of: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time.Ticket 20260692492 was submitted by BRUBACHER EXCAVATING INC on 3/100/2026 with a response due by 3/12/2026. EDPO LLC (WOC Energy) did not respond "Field Marked" until 3/16/2026. Recommendation: The penalty is applied. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). CROWN CASTLE is in violation of: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. This is a second offense. Ticket 20260692492 was submitted by BRUBACHER EXCAVATING INC on 3/100/2026 with a response due by 3/12/2026. Crown Castle did not respond "Field Marked" until 3/16/2026.	

Case Number	Stakeholders	Summary	Violations & Recommendation
		Recommendation: The penalty is applied. PUC compliance education has been recently completed.	
64435	**Facility Owner:** PECO **Contractor/Excavator:** Lamberts Cable Splicing **Project Owner:** Verizon	On 4/7/2026 1:30:00 PM at Canal Rd, MIDDLETOWN TWP, BUCKS The incident occurred on 4/8/2026, at approximately 1:30 PM, on Canal Rd, in Middletown Twp, Bucks County. An electric line owned by PECO was damaged. PECO is the facility owner. Their Alleged Violation Report (AVR) states, "On 4/8/2026, Lamberts Cable Splicing was excavating when they struck a streetlight cable using an auger." Lamberts Cable Splicing is the excavator. An AVR was not filed as of 06/15/2026 and an AVR request was sent the same day. An AVR was submitted 69 days after the incident that states, "Lambert's Pole Set crew arrived on site and documented dig location. Noticed no markings at dig location and KARL responses stated field marked or no facilities for locate responses. The dig location was back easement of the residences. While auguring down to get to depth for the pole set with a Back Yard Machine (Track mounted digger derrick / Panther Unit) crew stopped when small electric line was contacted. Crew shut down and called supervisor's Steve Mason and Neil Campbell. Crew then contacted PECO and Middletown Public Works to verify if the line was abandoned or just unmarked. PECO spoke to Foreman on site who stated that PECO relayed this was not their line. Once line was not claimed by power or public works crew continued the pole set, wrapped, and braced once set in phase. Crew cleaned up site and exited back easement. Lamberts was contacted by PAPUC damage prevention in regards to Case #64435. Upon notification Lamberts began an internal investigation resulting in the information provided. Crew foreman and Supervisor both stated that because the line was unclaimed by PECO or any other facility owner it was considered abandoned / inactive and they did not think an AVR was necessary." Verizon is the project owner. An AVR was not filed as of 06/15/2026 and an AVR request was sent the same day. No AVR was submitted by Verizon as of 8/4/2026. Images show the site, excavation, and damaged line. There are no marks to indicate lines in the area. The utility pole directly beside the new pole being installed shows evidence of underground lines in the area. No renotify was entered by the excavator. Violations: Facility – PECO: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).	**PECO: $1,500.00** Section 2(5)(i) 3rd Offense $1,500.00 **Lamberts Cable Splicing: $1,750.00** Section 5(20) 1st Offense $250.00 Section 5(16) 2nd Offense $1,500.00 **Verizon: $1,500.00** Section 6.1(7) 2nd Offense $1,500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Excavator – Lamberts Cable Splicing: Section 5(20) – Excavator failed to renotify One Call of an unmarked or incorrectly marked facility upon arrival at a work site. PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement. Project Owner – Verizon: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement.	
64216	**Facility Owner:** Norfolk South Railroad **Other:** CARLISLE BORO	On 4/8/2026 11:00:00 AM at n hanover st and carlisle spring rd, CARLISLE BORO, CUMBERLAND Carlisle Borough received the Investigator Report and responded to the request for documentation on 10/1/2026 (request was sent on 6/8/2026 and 8/7/2026 to 3 different individuals at Carlisle Borough). The case is already in stakeholder review and the incident date does not allow this case to be reinvestigated and processed through the Damage Prevention Committee within the 270 day time limits under Act 127 of 2024. ***** The incident occurred on 4/8/2026, at approximately 11:00 AM, on N Hanover St And Carlisle Spring Rd, in Carlisle Boro, Cumberland County. Norfolk Southern locators are not following the uniform color code and set of marking symbols that is adopted nationwide, as set forth under CGA Best Practices 4.3. Carlisle Boro is a facility owner. Their Alleged Violation Report (AVR) states, “Issue Description: Recurring misidentification of underground utilities. Location: Intersection of N Hanover and Carlisle Spring Rd. Details: During the past year of construction, Norfolk Southern locators have repeatedly marked electric conduit using blue paint/flags instead of red. When notified, on-site personnel cited federal pre-emption as the reason for the deviation. However, this location has a high density of water lines. Using the "water" color (blue) for electric lines creates a high-risk environment for excavation teams. We are requesting an immediate correction to these marking practices to prevent a utility strike and ensure compliance with national safety standards.”. A request was sent to Carlisle Boro for more information and images on 6-8-26, and again on 8/7/2026. No response was received.	**CARLISLE BORO: $0.00** Section 2(14) 1st Offense $0.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		PA One Call indicates that Norfolk Southern is not a registered as a facility owner. Norfold Southern was sent an AVR request on 8/11/2026. No documentation was provided by Carlisle Boro, the only AVR submitted to report the incident, to verify the statements being investigated. SECTION 2. It shall be the duty of each facility owner: (14) To comply with all requests for information by the commission relating to the commission's enforcement authority under this act within thirty days of receipt of the request. Violations: Facility (other) - Carlisle Boro: Section 2(14) - Failed to comply with all requests for information by the commission relating to the commission's enforcement authority under this act within thirty days of receipt of the request. This violation is being reduced from $500 to a warning of $0. PUC Online Compliance Training is required.	
63984	**Facility Owner:** PECO **Contractor/Excavator:** ABBONIZIO CONTRACTORS INC **Project Owner:** Whitemarsh Township **Designer:** GILMORE AND ASSOCIATES INC **Other:** ASH ASSOCIATES	On 4/8/2026 1:27:00 PM at 4114 HAIN DR, WHITEMARSH TWP, MONTGOMERY The incident occurred on April 8th, 2026, at approximately 1:27 PM, at 4114 Hain Drive, located in Whitemarsh Township, Montgomery County, Pennsylvania. A gas line owned by PECO was damaged. PECO, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, "On 4/8/26, Abbonizio Contractors Inc severed a gas service using a track hoe." Photos were submitted. Abbonizio Contractors Inc., the excavator, submitted an AVR. Their AVR states, "Two gas service marks were given for 4114 Hain Drive. We encountered a service at the first mark which was in line with the meter box for the property. A second line was encountered at the second mark which was damaged. This line was an old service that was apparently slip lined with a new service." Whitemarsh Township was the project owner. Gilmore and Associates Inc. submitted their AVR on their behalf. Gilmore and Associates Inc., the designer, submitted an AVR, which also represents Whitemarsh Township. Their AVR states, "Two gas service marks were given for 4114 Hain Drive. We encountered a service at the first mark which was in line with the meter box for the property. A second line was encountered at the second mark which was damaged. This line was an old service that was apparently slip lined with a new service." In the photos of the excavation area, the damaged gas line can be seen. Yellow paint and a flag can be seen on the curb. On the opposite side of the street, there is also yellow paint on the curb, indicating the gas line continued across the street. There are white circles	**ABBONIZIO CONTRACTORS INC: $1,250.00** Section 5(4) 2nd Offense $1,000.00 Section 5(3) 1st Offense $250.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		drawn on the street. No additional mark outs can be seen in the submitted photos. All the submitted AVRs indicated that the lines were visible. The damage to the gas line occurred within the tolerance zone. All AVRs indicated that 911 was not called. Emergency ticket 20260983751 indicates that there was not a hazardous release. This project in its entirety included a large area, multiple work sites and streets. A preconstruction meeting should have been scheduled and conducted. The excavator, Abbonizio Contractors Inc. failed to hold a preconstruction meeting prior to beginning a complex project. This case is related to cases 063892 and 064102. - Tickets 20260141852, 20260490347, 20260651136 and 20260860232 had ticket violations applied on related case 064102. - Violations regarding releasing project to bid/ construction before final design was complete for this project was applied on related case 064102. Act 127 of 2024, also known as the Underground Utility Line Protection Law states it shall be the duty of each excavator who intends to perform excavation or demolition work within this Commonwealth: - To exercise due care and to take all reasonable steps necessary to avoid injury to or otherwise interfere with all lines where positions have been provided to the excavator by the facility owners pursuant to section 2 (5). Within the tolerance zone the excavator shall employ prudent techniques, which may include hand-dug test holes, vacuum excavation or similar devices to ascertain the precise position of such facilities. - In a complex project or if an excavator intends to perform work at multiple work sites or over a large area, to take reasonable steps to work with facility owners, including scheduling and conducting a preconstruction meeting, so that they may locate their facilities at a time reasonably in advance of the actual start of excavation or demolition work for each phase of the work. A preconstruction meeting may take place at any time prior to the commencement of excavation or demolition work, and the excavator, facility owners and designer, or their agents, shall attend the meeting. If the excavator does not believe that a preconstruction meeting is necessary under the circumstances of this clause it shall indicate such belief in its notice, but any facility owner with facilities at the work site may request a meeting with the excavator, and a meeting shall be held between the facility owner and the excavator. After commencement of excavation or demolition work, the excavator shall be responsible for protecting and preserving the staking, marking or other designation until no longer required for proper and safe excavation or demolition work at or near the underground facility or by contacting the One Call System to request that the facilities be marked again in	

Case Number	Stakeholders	Summary	Violations & Recommendation
		the event that the previous markings have been compromised or eliminated. Violations: Abbonizio Contractors Inc.- - Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. - Section 5(3) – Excavator failed to hold a preconstruction meeting prior to beginning a complex project. Recommendation: The penalty is applied. PUC online Compliance Training was recently completed.	
65010	**Facility Owner:** WEST PENN POWER-FIRSTENERGY **Contractor/Excavator:** FRIENDLY UNDGERGROUND CONSTRUCTION LLC **Project Owner:** SHENTEL COMMUNICATIONS LLC **Other:** COMCAST **Other:** MASTEC	On 4/8/2026 4:46:00 PM at 405 West Dr, HARRIS TWP, CENTRE The incident occurred on Wednesday, April 8, 2026, at 405 West Drive, in Harris Township, Centre County. An electric line owned by West Penn Power-FirstEnergy (WPP) was damaged by Friendly Underground Construction LLC. Pictures were provided. WPP reported an excavator issue as failed to request the location and type of facility owner thru the One Call System 3-10 business days in advance of beginning the work. WPP stated in their Alleged Violation Report (AVR), "On April 8, 2026, West Penn Power ("WPP") received a report of partial power at 405 West Drive, Harris Township, Centre County, Pennsylvania. WPP Operations investigated and located a damaged secondary line to the residence. USIC, WPP's Contract Locator, investigated and determined that MasTec, "Excavator," was using directional boring when they hit an underground electric line owned by West Penn Power and that the root cause of the damage was that the Excavator did not request the location and type of facility owner through the PA One Call System" On Monday, 7/20/2026, letters and emails were sent requesting AVR's from the project owner, Shentel Communications LLC, and the contractor, MasTec. Shentel Communications submitted their AVR on the same day. MasTec responded by email stating, "I am only project management the excavation was done by Friendly Underground I have spoke with them and they are filling an AVR today" Friendly Underground Construction LLC submitted their AVR on 7/22/2026. Shentel Communications reported an excavator issue as failed to exercise due care and take all reasonable steps necessary to avoid injury to or interference with all lines. Shentel Communications stated in their AVR, "The damage occurred due to the excavator while parallel boring with the directional drill damaged the electric power service when a rock that pushed into the cable causing it to short out. Damage is in the rear of 405 West Dr, Boalsburg, PA 16827	**FRIENDLY UNDGERGROUND CONSTRUCTION LLC: $1,500.00** Section 5(11.2) 1st Offense $500.00 Section 5(16) 1st Offense $1,000.00 **SHENTEL COMMUNICATIONS LLC: $500.00** Section 6.1(7) 1st Offense $500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		This job was to directional bore and install one 1-1/4" conduits in the rear easement for Glo-Fibers new fiber infrastructure. The Damage could be prevented by using care while parallel boring utilities with the directional drill and following the hand dig best practice laws/rules." Friendly Underground Construction reported an excavator issue as failed to exercise due care and take all reasonable steps necessary to avoid injury to or interference with all lines. Friendly Underground Construction stated in their AVR, "The damage occurred due to the excavator while parallel boring with the directional drill damaged the electric power service when a rock that pushed into the cable causing it to short out. Damage is in the rear of 405 West Dr, Boalsburg, PA 16827" Friendly Underground Construction placed a routine ticket, 20260852659, on 3/26/2026 at 1:35pm, duration of 5 days, and lawful start dates 4/1/2026 – 4/9/2026. Location Information- [STARTING FROM THE REAR OF PROPERTY 415 WEST DR, LOCATE N BEHIND THE BUILDINGS FOR APPX 445FT TO THE REAR OF PROPERTY 401 WEST DR. MARKING 25FT EACH SIDE OF THE WHITE LINED ROUTE, TO INCLUDE THE ROW AND UTILITY EASEMENT. USE PAINT AND FLAGS] West Penn Power responded as field marked on 3/31/2026. The Underground Utility Line Protection Law (UULPL) aka PA One Call Law, ACT 127, Responsibilities of The Excavator, Section 5(16) states: To submit a report of an alleged violation to the commission through the One Call System not more than thirty days after striking or damaging a facility owner's line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. The report of an alleged violation shall be in a form and manner as required by the commission. The Underground Utility Line Protection Law (UULPL) aka PA One Call Law, ACT 127, Responsibilities of The Project Owner, Section 6.1(7) states: To submit a report of alleged violation to the commission through the One Call System not more than thirty days after striking or damaging a facility owner's line during excavation or demolition work activities, after a project owner's contracted excavator strikes or damages a facility owner's line during excavation or demolition activities or if the project owner believes a violation of this act has been committed in association with excavation or demolition. The report of alleged violation shall be in a form and manner as required by the commission. Violations: *Friendly Underground Construction LLC is in violation of sections:	

Case Number	Stakeholders	Summary	Violations & Recommendation
		5(11.2) – When using trenchless technology, Excavator failed to utilize at a minimum, the best practices published by the Common Ground Alliance. (Common Ground Alliance (CGA), Chapter 5, Section 5.29 Trenchless Excavation) 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: Penalties applied and PUC Online Compliance Training is required for the Excavator(s) working onsite at this excavation, or their replacements. *Shentel Communications LLC is in violation of section: 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Recommendation: Penalty applied, reduced by 50% (from $1,000 to $500).	
64778	**Facility Owner:** PPL Electric Utilities **Contractor/Excavator:** R&D Home Services LLC **Project Owner:** Homeowner **Other:** Camp Hill Boro	On 4/9/2026 9:00:00 AM at 2806 FAIRVIEW RD, CAMP HILL BORO, CUMBERLAND ***** PPL 2(5)(i) violation withdrawn as they marked their line after being notified. ***** The incident occurred on 4/9/2026, at approximately 9:00 AM, on 2806 Fairview Rd, in Camp Hill Boro, Cumberland County. An unmarked electric line was encountered during excavation. PPL, the facility owner, was not notified on the new ticket due to their mapping. PPL is the facility owner. An Alleged Violation Report (AVR) was not filed as of 07/09/2026 and an AVR request was sent to PPL. Their AVR states, “PPL received a request to submit an AVR regarding a damage to PPL facilities on 04/09/2026 at 2806 Fairview Rd, Camp Hill Boro. No PPL facilities were damaged at this location. This was also confirmed with the excavator.” R And D Home Services L L C is the excavator. No AVR was submitted and an AVR request was sent on 7/10/2026. Michelle Raich is the project owner. The AVR submitted by the homeowner states, “On March 31, 2026, a PA One Call excavation request (Serial No. 20260900309) was submitted by the contractor (R and D Home Services LLC) on behalf of the homeowner for a residential fence installation project at 2806 Fairview Road, Camp Hill, PA. All facility owners were expected to be notified and mark underground utilities prior to excavation. By April 8, 2026, the ticket was marked “clear” by PA One Call indicating no conflicts and that excavation could proceed. Based on this clearance, excavation work began on April 9, 2026. Equipment (Bobcat and related equipment) was rented specifically for this work at a cost of $530.49, which was paid by the homeowner. During excavation, an unmarked underground line was encountered. Work was immediately stopped. Upon contacting PA One Call, it was determined that PPL Electric had not been notified of the excavation request and therefore had not marked	**PPL Electric Utilities: $250.00** Section 2(1)(ii)(A) 1st Offense $250.00 **R&D Home Services LLC: $500.00** Section 5(17) 1st Offense $500.00 **Camp Hill Boro: $250.00** Section 2(5)(v.2) 1st Offense $250.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		their underground facilities. PA One Call acknowledged the issue and assisted in contacting PPL to perform the required markings. As a direct result of this error, the scheduled work could not proceed, and a full day of equipment rental was lost, resulting in a financial loss of $530.49. Supporting documentation (rental receipt) is available. This report is being submitted to request reimbursement for damages incurred due to failure to notify all required facility owners and ensure proper utility marking prior to issuing clearance. I respectfully request reimbursement in the amount of $530.49." Ticket 20260900309-000 was entered with a response due date of 4/2/2026. Camp Hill Boro responded "Insufficient Information" on 4/1/2026. Renotify version -001 was entered on 4/10/2026 with the statement, "ATTN CAMP HILL BOROUGH, YOU RESPONDED AS INSUFFICIENT INFO DO NOT DIG, BUT THE CALLER STATES THAT THEY SPOKE TO A REPRESENTATIVE OF THE BOROUGH ABOUT THE SITE. PLEASE UPDATE YOUR RESPONSE AS SOON AS POSSIBLE. THANK YOU." Camp Hill Boro responded "Clear" on 4/10/2026. On the AVR request notification PPL was asked, "Why was PPL not notified on the New Routine ticket for this excavation?" PPL acknowledged this request in an email on 7/10/2026, "Ok, so you are requesting an AVR for me to explain why PPL was not on the original ticket?" No information was provided on why their mapping with PA One Call did not notify them for this ticket. PA One Call provided the following information on the incident, "PPL did not receive the serial number based on their mapping." Ticket 20260994298-000 and -001 state, "SPECIAL ATTN PPL CALLER STATES THERE IS AN UG WIRE FROM THE POLE TO THE HOUSE THAT NEEDS TO BE MARKED". PPL was not notified on this ticket. They then responded to Ticket 20260900309-002 "Field Marked" after originally responding "Clear". Violations: Facility Owner – PPL: Section 2(1)(ii)(A) – Failed to provide the One Call System with the counties, municipalities, and wards in which it lines are located. Ticket 20260994298 Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Ticket 20260900309-000 Excavator - R And D Home Services: Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement. Facility Owner (Other) – Camp Hill Boro:	

Case Number	Stakeholders	Summary	Violations & Recommendation
		Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket 20260900309-000 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).	
63818	**Facility Owner:** Upper Southampton Municpal Authority **Project Owner:** LIBERTY AND ASSOCIATESLIBERTY ROKSTAD POWER **Project Owner:** PECO	On 4/9/2026 10:45:00 AM at JUDITH DR, UPPER SOUTHAMPTON TWP, BUCKS The incident occurred on 4/09/2026 on JUDITH DR, in Upper Southampton Township, in Bucks Co. A water main owned by UPPER SOUTHAMPTON MUNICIPAL AUTHORITY was damaged. 10 customers did not have water. LIBERTY AND ASSOCIATESLIBERTY ROKSTAD POWER, the excavator, stated in their Alleged Violation Report (AVR) that, "On 4/9 a crew began digging with a valid one call ticket. Closest mark was over 3 ft away from site. Crew hit an unmarked water main. Crew called into Upper Southampton Municipal Authority. Upper Southampton Municipal arrived on scene to make repairs". Pictures were provided. PECO, the project owner, was sent an AVR request letter on 4/24/2026. No AVR has been received as of 7/22/2026. No contact has been made. UPPER SOUTHAMPTON MUNICIPAL AUTHORITY, the facility owner, was sent an AVR request letter on 4/24/2026. They stated in their AVR that," Liberty installing new poll at 346 Judith Drive. when auguring the hole the water main was hit and damaged. had 10 customer out of water during the repair." LIBERTY AND ASSOCIATES/LIBERTY ROKSTAD POWER submitted ticket 20260913593 on 4/01/2026 with a response due by 4/03/2026 to replace a pole. The excavation was scheduled for 4/06/2026. UPPER SOUTHAMPTON MUNICIPAL AUTHORITY responded with "Field Marked" timely, on 4/02/2026. Pictures provided show that the sewer line was marked, to the left of the pole and the damage occurred on the right side of the pole. There are no water markings. VIOLATIONS PECO is in violation of: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike or damaging a facility owner's line during excavation or demolition work activities or if a project owner believes a violation of this act has been committed in association or demolition. PECO did not submit an AVR. This is a third time offense. Section 6.1(8) - Project Owner failed to comply with all requests for information by the commission relating to the commission's enforcement authority under this act within 30 days of receipt of written request. PECO did not answer any of the questions that were asked in the	**Upper Southampton Municpal Authority: $500.00** Section 2(5)(i) 1st Offense $500.00 **PECO: $3,000.00** Section 6.1(7) 3rd Offense $2,000.00 Section 6.1(8) 2nd Offense $1,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		AVR. The questions were specific to PECO and the project. This is a second time offense. Recommendation: The penalty is applied. PUC compliance education has been recently completed. Upper Southampton Municipal Authority is in violation of: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Ticket 20260913593 was responded to as "filed marked" by Upper Southampton Municipal Authority. Pictures show that no water line was marked out. Recommendation: The penalties are applied. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).	
63793	**Facility Owner:** Peoples Gas Company **Contractor/Excavator:** B AND M HOME IMPROVEMENTS **Project Owner:** Homeowner	On 4/9/2026 12:23:00 PM at 113 PIEDMONT DR, NORTH VERSAILLES TWP, ALLEGHENY Incident occurred on 4/9/2026 at 12:23pm on 113 Piedmont Drive, North Versailles Township, Allegheny County. Incident: No PA1call Ticket for excavation. Gas line was damaged by excavator who was working off an expired homeowner ticket. Alleged Violation Reports (AVR): Facility Owner - Peoples' AVR states, "ON 4/9/26 B AND M HOME IMPROVEMENTS BRIEN MOORE WAS DIGGING NEAR PNG CURB BOX AT 113 PIEDMONT DR, NORTH VERSAILLES. THEY STRUCK THE PNG MAIN TO CURB GAS SERVICE LINE. B AND M HOME IMPROVEMENTS BRIEN MOORE DOES NOT HAVE A ONE CALL. DAMAGE OCCURED WITHIN 18 INCHES OF THE CURB BOX, PICTURES SHOW WHAT APPEARS TO HAVE BEEN POWER EQUIPMENT USED TO MOVE DIRT." PA1Call commented, "No records were found of B AND M HOME IMPROVEMENTS placing One Call notifications in the past, based on the company information provided above." Excavator - B and M Home Improvement's AVR states, "Dug a trench for new gas line for residence. First time ever needing to use this service. Home owner had called and had a marking done and we both thought it was taken care of. We contacted gas company and did their application as well. My lack of knowledge to the service and proper steps to take is the problem because I wasn't aware of rules.. dug the trench for new line and when I was finishing the dig near the riser with shovel and pick I hit the line creating a leak. I pinched line shut and called 911 and gas company . Gas company came and put new fitting on. To which they billed me for their service and it's since been paid" AVR notes 911 as being notified. AVR submission date: 6/22/26 Was the AVR submitted after 30 days? Yes	**B AND M HOME IMPROVEMENTS: $500.00** Section 5(2.1) 1st Offense $0.00 Section 5(23) 1st Offense $500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		PUC request for information sent on: 6/15/26 Project Owner - Homeowner's AVR states, “This is for an incident that occurred on 4/9/2026 at 113 Piedmont Drive. I am the homeowner. I am submitting this based upon a letter from the PUC dated 6/15/2026 requesting me to submit this report. The PA PUC's Case Number on the letter is 63793. The incident occurred on 4/9/2026 at approximately 1230 PM. B&M Home Improvements, a contractor hired by me, was doing some excavation to relocate the gas and water lines at my house. They unintentionally hit the gas line as part of the excavation. They immediately called 911 and People's Gas; while, at the same time, they put a clamp to stop the outflow of natural gas. People's Gas arrived within 15 minutes; they put the cap as depicted in the photo. This work was being done with the knowledge of People's Gas (as well as the local water utility). See the attached 3/30/2026 application and drawing submitted to People's Gas. The utilities were marked as part of PA One Calls in August and October 2025. See the attached photos of line markings. Since we had the previous photos and had been working directly with the gas and water utilities and had the line markings from the previous PA One Calls, we were not aware that we needed to submit a new PA One Call. After submitting the application with People's Gas on 3/30/2026, all of the follow up was done over the phone with People's Gas -- initially through their customer service number who put me in touch with the regional manager Seth (Do not have his last name), his phone number is 304-276-8642) and the local Technical Manager Jim Gardina (724-681-1212). They reviewed the application and drawing, discussed various solutions on placement of the meter, and approved us doing the relocation and told us to coordinate with People's gas customer service department. B&M Home Improvement's plumber coordinated the service line relocation with People's Gas.” AVR notes 911 as being notified. AVR submission date: 6/22/26 Was the AVR submitted after 30 days? Yes PUC request for information sent on: 6/15/26 Conclusion: Excavator piggybacked off homeowner's PA1call ticket. AVR notes 911 was notified after a line was damaged. Excavator claims that the damage was done with hand tools. Images show that mechanized equipment had also been used on site which requires a PA1call ticket. B & M Home Improvement has no records of placing a PA1call in the past. Homeowner's ticket was placed on 10/29/25 and damage was on 4/9/26. Recommended violations, penalties, and education: Excavator: B and M Home Improvement Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Section 5(23) – Excavator may not delegate their duty to submit a locate request to the One Call System to	

Case Number	Stakeholders	Summary	Violations & Recommendation
		another person. The excavator shall have sole responsibility to submit each locate request to the One Call System. 20253023015 -PUC compliance education is required for the excavators working onsite of this excavation or their replacements.	
64478	**Facility Owner:** UGI Utilities **Contractor/Excavator:** RUTLEDGE EXCAVATING **Project Owner:** Scranton City	On 4/9/2026 2:50:00 PM at RIDGEVIEW DR, SCRANTON CITY, LACKAWANNA Incident occurred on 4/9/26 at 2:50pm,124 Ridgeview, Scranton City, Lackawanna County. Incident: A UGI gas line was damaged by Rutledge Excavating. Alleged Violation Reports (AVR): Facility Owner - UGI's AVR states, “Excavator utilizing mechanized equipment, struck a correctly marked gas service. Excavator failed to maintain the marks placed by the one call ticket.” Excavator - Rutledge Excavating's AVR states, “4-9-26 at approximately 2:50 pm REI damaged 1/2" UGI gas service to house #124 Ridgeview Drive, Scranton, PA. I called PA One Call and UGI. PA One Call notified 911. No one was home at the house. UGI representative Jeff Kucharski told our superintendent, Mark Hessling that there was no leak due to the backflow preventer on the service. Related one call numbers are 20260993961, 202609520582, 20260981921 & 20260631452. Excavated trench materials were placed on gas service markings and valve box by mistake during the installation of new sewer lateral. Gas service was damaged.” Please note that after the gas line was ripped open Emergency ticket 20260993961 was called in which states, "EXCAVATOR HAZARDOUS RELEASE: YES CALLER ADVISED TO NOTIFY 911." UGI then responded to the emergency damage ticket. Rutledge Excavating's AVR stated that PA One Call notified UGI, but PA1call's ticket states the excavator was advised to call 911. Conclusion: IMG_0087.jpeg and IMG_0088.jpeg show that the line was marked within the tolerance zone. Excavator failed to notify 911. Additional information was requested from the Project Owner, City of Scranton, and no AVR or information was provided. Recommended violations, penalties, and education: Excavator: Rutledge Excavating Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid.	**RUTLEDGE EXCAVATING: $1,500.00** Section 5(4) 1st Offense $500.00 Section 5(8) 1st Offense $1,000.00 **Scranton City: $1,500.00** Section 6.1(7) 1st Offense $1,000.00 Section 6.1(8) 1st Offense $500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		-PUC compliance education is required for the excavators working onsite of this excavation or their replacements. Project Owner: City of Scranton Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Section 6.1(8) - Project Owner failed to comply with all requests for information by the commission relating to the commission's enforcement authority under this act within 30 days of receipt of written request. -PUC compliance education is required for the person responsible for submitting AVR or their replacement.	
64499	**Facility Owner:** UGI **Contractor/Excavator:** GHOST VALLEY MASONRY	On 4/10/2026 10:25:00 AM at 163 Carpenter Rd, HARVEYS LAKE BORO, LUZERNE The incident occurred on 4/10/2026, at approximately 10:25 AM, on 163 Carpenter Rd, in Harveys Lake Boro, Luzerne County. A gas line owned by UGI was damaged. PA One Call did not receive a ticket request for this location from any excavator. UGI indicates that 911 was not contacted. UGI is the facility owner. Their Alleged Violation Report (AVR) states, “Excavator utilizing mechanized equipment, struck an unmarked gas service while excavating without a vaild pa one call.” Ghost Valley Masonry is the excavator. An AVR was not filed as of 06/18/2026 and an AVR request was sent the same day. No AVR was submitted, and no contact was received from Ghost Valley. No information was provided to indicate a Project Owner, or Designer. Images provided show the site, and damage. No equipment is shown. No additional information is provided, since the alleged excavator did not submit an AVR, to fully investigate this incident. UGI confirmed the excavator was identified on site by their response crew. Violations: Excavator – Ghost Valley Masonry: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.	**GHOST VALLEY MASONRY: $3,750.00** Section 5(2.1) 1st Offense $1,000.00 Section 5(6)(i) 1st Offense $250.00 Section 5(16) 1st Offense $1,000.00 Section 5(17) 1st Offense $500.00 Section 5(8) 1st Offense $1,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements.	
63858	**Facility Owner:** Pencor Services / Blue Ridge Communication **Contractor/Excavator:** Linde Corporation **Project Owner:** Aqua PA **Designer:** G H D INC **Other:** KILEY ASSOCIATES LLC **Other:** LACKAWAXEN TOWNSHIP **Other:** WOODLOCH PINES INC.	On 4/10/2026 12:00:00 PM at PIN OAK CIRCLE, LACKAWAXEN TWP, PIKE The incident occurred on April 10th, 2026, at approximately.12:00 PM, on Pin Oak Circle, located in Lackawaxen Township, Pike County, Pennsylvania. A cable line owned by Blue Ridge Communication / Pencor Services was damaged. Blue Ridge Communication / Pencor Services, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “Damaged Underground CATV Truck Line due to Excavator strike. The line was marked and most of the marks were destroyed due to weather and excavation.” Photos were submitted. Linde Corporation, the excavator, submitted an AVR. Their AVR states, “Crew working at the Woodloch Aqua job discovered an mismarked utility while excavating for install of sewer main. marks were 4 ft of the markout from Blue Ridge communications.” Photos were submitted. Aqua PA, the project owner, submitted an AVR. Their AVR states, "Aqua Contractor Linde Corporation, crew working at the Woodloch Aqua job discovered an mismarked utility while excavating for install of sewer main. Marks were 4 ft off the mark out from Blue Ridge Communications”. G H D Inc., the designer, submitted an AVR. Their AVR states, "Excavator damaged mismarked Blue Ridge Communication cable TV line at approximately 11:00AM on 4/10/26. Markout was 4' away from line location. 811 was notified by Excavator and Blue Ridge Communication arrived on site to make repairs. Multiple residents were affected and the repair was completed around 12:30PM.” Photos were submitted. The submitted photos included images of the mark outs prior to excavation as well as photos of the damaged line and repair. Orange paint and an orange flag can be seen in the mark out photos dated 03/27/2026 (This date matches Blue Ridge Communication’s “Field Marked” response on the routine ticket). Additionally other utility mark outs can be seen in the mark out photos, including red and blue paint. In the photos of the damaged line, only a single orange flag can be seen in the immediate area. The area that had the blue paint (in the mark out photos) was not excavated and the paint was no longer visible on the ground in the photos dated 04/10/2026 (date the incident occurred). Blue Ridge Communication reported in their AVR that most of the marks at the location were destroyed due to weather and excavation.	**Linde Corporation: $500.00** Section 5(3) 1st Offense $500.00 **LACKAWAXEN TOWNSHIP: $500.00** Section 2(5)(vii) 1st Offense $500.00 **WOODLOCH PINES INC.: $125.00** Section 2(5)(v) 1st Offense $125.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		The AVRs submitted by Linde Corporation and Aqua reported the condition of the marks was 'readily visible'. When comparing the mark out photos to the damage photos, the cable line that was damaged was accurately marked (see photo labeled: compare mark outs to damage location). Based on the mark out photos dated 03/27/2026, in comparison to the damage photos taken 04/10/2026, the cable line was accurately marked and damaged within the tolerance zone. The blue paint that was visible in the mark out photos was no longer visible in the damage photos. Additionally, the area with the blue paint not being excavated, indicating the mark outs on the site were not preserved or there should have been a request to remark the lines. (All other mark outs in paint would have been within the excavation area.) Routine PA One Call ticket 20260842298 had a response due date of 03/27/2026. - Woodloch Pines Inc. responded 'clear' on 03/30/2026. Emergency PA One Call ticket 20261002630 had a response due date of 04/10/2026. - Lackawaxen Township did not respond to this ticket. Routine PA One Call tickets are required to be responded to by the response due date listed on the ticket. Emergency PA One Call tickets are required to be responded to as soon as practicable. Act 127 of 2024, also known as the Underground Utility Line Protection Law states it shall be the duty of each facility owner: Section 2 – After receipt of a timely request from an excavator or operator who identifies the work site of excavation or demolition work he intends to perform and not later than the business day prior to the lawful start date of excavation: Section 2.5.v - To respond to all notices through the One Call System, provided the request is made in the time frame set forth under this act. The response shall be made not later than the end of the second business day following receipt of the notification by the One Call System, excluding the business day upon which the notification is received, or not later than the day prior to the lawful start date of excavation if the excavator specifies a later date or, in the case of an emergency, to respond through the One Call System as soon as practicable following receipt of notification of the emergency by the One Call System. - Section 2.5.vii - To respond to emergency notifications as soon as practicable following receipt of notification of such emergency. The response by the facility owner shall be consistent with the nature of the emergency information received by the facility owner. Act 127 of 2024, also known as the Underground Utility Line Protection Law states it shall be the duty of each	

Case Number	Stakeholders	Summary	Violations & Recommendation
		excavator who intends to perform excavation or demolition work within this Commonwealth: - After commencement of excavation or demolition work, the excavator shall be responsible for protecting and preserving the staking, marking or other designation until no longer required for proper and safe excavation or demolition work at or near the underground facility or by contacting the One Call System to request that the facilities be marked again in the event that the previous markings have been compromised or eliminated. Violations: Linde Corporation- - Section 5(3) – Excavator failed to preserve mark-outs or request a remark. Recommendation: The penalty is applied. PUC online Compliance Training is required for the individual(s) responsible, or their replacement(s). Woodloch Pines Inc.- - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Routine PA One Call ticket 20260842298. Recommendation: The penalty is reduced by 50% from $250 to $125. No prior violations. PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Lackawaxen Township- - Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Emergency PA One Call ticket 20261002630. Recommendation: The penalty is applied. The penalty is reduced by 50% from $1,000 to $500. No prior violations. PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).	
63866	**Facility Owner:** Philadelphia Gas Works (PGW) **Contractor/Excavator:** Philadelphia City Water Department **Project Owner:** Philadelphia City Water Department - Placeholder	On 4/10/2026 2:30:00 PM at 3230 BELGRADE ST, PHILADELPHIA CITY, PHILADELPHIA The incident occurred on 4/10/2026, at 2:30 PM, on 3230 Belgrade St, in Philadelphia City, Philadelphia County. An emergency ticket was entered that did not meet the definition of "Emergency" as defined in Act 127 of 2024. Philadelphia Gas Works is the facility owner. Their Alleged Violation Report (AVR) states, "PWD put in an emergency ticket to install a new fire line to 3230 Belgrade, this should be planned work not an emergency." Philadelphia Water Department is the excavator. An AVR was requested on 6/2/2026 which included the following request, "Please provide documentation that supports the necessity for this to be an emergency ticket	**Philadelphia City Water Department: $1,750.00** Section 5(22) 2nd Offense $750.00 Section 5(17) 2nd Offense $1,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		versus a routine ticket. #20261003765". No AVR was submitted. An emergency ticket was entered on 4/10/2026 at 2:30 PM to, "INSTL 4IN FIRE CONNECTION". The Dig Date Proposed date was 4/13/26 at 9:00 AM and the system Dig Date Calculated was 4/12/26, 11:59 PM. 3 business days from 4/10/2026 is 4/15/2026. Act 127 of 2024 SECTION 5. It shall be the duty of each excavator who intends to perform excavation or demolition work within this Commonwealth: (2.1) To submit a locate request to identify the location and type of facility owner lines at each work site by notifying the facility owner through the One Call System. Notification shall be not less than three nor more than ten business days in advance of beginning excavation or demolition work. No work shall begin earlier than the lawful start date which shall be on or after the third business day after notification. The lawful start date shall exclude the date upon which notification was received by the One Call System and notification received on a Saturday, Sunday or holiday, which shall be processed on the following business day. "Emergency", as defined in Act 127 of 2024, means a sudden or unforeseen occurrence involving a clear and immediate danger to life, property or the environment, including, but not limited to, serious breaks or defects in a facility owner's lines. Violations: Excavator - Philadelphia Water Department: Section 5(22) – Excavator provided a misrepresentation of an emergency excavation, subject to an administrative penalty imposed under section 7(10). PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements. Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement.	
63965	**Facility Owner:** PEOPLES NATURAL GAS COMPANY LLC **Contractor/Excavator:** Palatial Concrete LTD **Project Owner:** Dalian Development **Other:** Franjo Construction **Other:** NACCARATI CONTRACTING	<u>On 4/13/2026 10:00:00 AM at 145 38th St, PITTSBURGH CITY, ALLEGHENY</u> Palatial Concrete LTD disagreed. This is a first-time offense and the $1000. penalty has been reduced to $500. On 10/16/2026 Palatial Concrete accepted violation, reduced penalty and education. ********** The incident occurred on 4/13/2026 at 145 38th St., in PITTSBURGH CITY, in ALLEGHENY Co. A gas service line owned by PEOPLES NATURAL GAS COMPANY LLC was damaged.	**Palatial Concrete LTD: $500.00** Section 5(2.1) 1st Offense $500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		PEOPLES NATURAL GAS COMPANY LLC stated in their Alleged Violation Report (AVR) that," Franjo Construction digging for a new building foundation struck and damaged a Peoples Gas service line while excavating without a locate request." Pictures were provided. DPI sent an email on 7/31/2026, asking Peoples if they had any evidence that 911 was not called by the excavator. Peoples responded with an email on 7/31/2026 that "Per our first responder, there were no signs of 911 being called. Franjo Construction squeezed the plastic service line with a pair of pliers of some sort. And Brad Carse of Franjo Construction called directly into the gas company. " Franjo Construction is the contractor in charge of the project. They submitted an AVR on behalf of Palatial Concrete LTD and on behalf of Dalian Development, the project owner. Franjo Construction stated for Palatial Concrete LTD, as the excavator, in their AVR that, "While excavating at our 38th Street project a Peoples Gas line that had been previously struck was struck again. When this line was hit Peoples was instructed to terminate the line outside of our building perimeter. They did not. they just capped it in place and left it inside the worksite. the photo's will show the relation to the street outside of our construction site." Pictures were provided. Project is over $400,000. Pictures were included. In the telephone conversation DPI Maki had with Franjo on 7/28/2026, Franjo clarified that there were 2 strikes within 14 hours. Franjo's AVR includes 2 strikes that occurred within 14 hours in their AVR. Both incidents occurred as Palatial Concrete was excavating. Palatial Concrete LTD is represented by Franjo Construction and stated that, " Regarding case # 63965 and Palatial Concrete. In speaking with Eva she requested that Palatial also file and AVR. I Jay Celaschi am filing this AVR on their behalf. On the original AVR I had listed them as the excavator. The summary in the original AVR remains the same." 911 was notified. Comments state that, " The gas line was supposed to be removed from the property line of the project. Palatial was digging inside the property line (at the edge) however still inside the property line. Due to this being a follow up on a previous AVR submission I am completing this AVR as a response to Case #63965 as requested by Eva Maki. There are photos submitted in the original AVR nothing has changed other than this follow up for Palatial Concrete LTD. Feel free to reach out with any questions or concerns." Dalian Development, also known as Incheon Ventures LLC is represented by Franjo Construction. VIOLATIONS Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe.	

Case Number	Stakeholders	Summary	Violations & Recommendation
		Recommendation: The penalty is applied. PUC compliance education is required for the excavators working onsite of this excavation or their replacements.	
63924	**Facility Owner:** ZAYO BANDWIDTH NE LLC **Facility Owner:** ZAYO GROUP (NEITS) **Contractor/Excavator:** Neffs Masonry **Project Owner:** Buloh Holdings, LLC	On 4/13/2026 2:00:00 PM at 5218 Main Street (RT 329), NORTH WHITEHALL TWP, LEHIGH Non damage incident occurred on 4/13/26 at 2pm on 5218 Main Street (RT 329), North Whitehall Township, Lehigh County. Incident: No PA1call was placed prior to excavation. Alleged Violation Reports (AVR): Facility Owner - Zayo Bandwidth's AVR states, “On (4/13/26) I was the damage prevention technician patrolling the area and found a local excavator digging in the State ROW, over our buried utility. We did not have a ticket in our queue for said work, so our technician stopped and confronted the excavatior. Work was halted after we called them out for working without an approved 811 ticket. They were going to call 811, and said they would resume work with a vaild ticket. We requested to be on-site, as our company policy requires our team to monitor any work within 5' of our buired fiber. We passed the location today (4/14/26) and the excavator had completeed the excavation and they were pouring a new concrete sidewalk. No ticket was received on our end. Work area: 5218 Main Street (Rt.329) Whitehall, PA. 18052 GPS:40.688824/-75.508377 Excavator: Neff's Masonry Excavator Address: 1295 N Cottonwood Rd, Danielsville, PA 18038 Excavator Phone: 610-392-7400” PA1Call commented, "Neffs Masonry has placed One Call notifications in the past. Last contact info matches the info provided above." Neff's left a voicemail indicating that they received the request for information from the PUC. Investigator also returned phone call multiple times, but no one answered. Screenshot of phone call is attached. Followed up phone call attempts with an email. Project Owner: Buloh Holdings, LLC's AVR states, "I contracted with Neffs Masonry to perform repair and replacement of the deteriorated existing sidewalk sections at the property. The work was undertaken after my commercial property insurer identified the sidewalk condition as requiring correction to maintain insurance coverage. I am submitting this report as the Project Owner in response to the PUC's request. The information provided is based on the information available to me at this time." Conclusion: Images show an excavator was used to dig without a PA1Call ticket. Neff's Masonry was sent a request for information, and no information or AVR has been received. Recommended violations, penalties, and education:	**Neffs Masonry: $2,500.00** Section 5(2.1) 1st Offense $1,000.00 Section 5(16) 1st Offense $1,000.00 Section 5(17) 1st Offense $500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Excavator: Neffs Masonry Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. -PUC compliance education is required for the excavators working onsite of this excavation or their replacements.	
63930	**Facility Owner:** Philadelphia Gas Works **Contractor/Excavator:** AP Construction **Project Owner:** Philadelphia Water Department **Designer:** Philadelphia Water Department (Placeholder) **Other:** AMERICAN ENGINEERS GROUP	On 4/14/2026 9:00:00 AM at S 41ST ST, PHILADELPHIA CITY, PHILADELPHIA The incident occurred on April 14th, 2026, at approximately 9:00 AM, on South 41st Street, located in Philadelphia City, Philadelphia County, Pennsylvania. A gas line owned by Philadelphia Gas Works was damaged. Excavation began prior to the lawful start date. 911 was not called. Philadelphia Gas Works, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “AP construction damaged 1 1/4 plastic gas line to 503 S 41ST with trackhoe. Also one call was no good here they were working off an old one call.” AP Construction, the excavator, submitted an AVR. Their AVR states, “A one inch low pressure plastic gas was damaged during excavating activities. Work had begun prematurely due to an onsite miscommunication involving when POC was called in and was clear to begin. Supervisor immediatly called in an emergency and conducted a site reveiw of safe practices related to one call 3 business minimum day wait before beginnig any excavation activities.” Philadelphia Water Department submitted two AVRs. They reported their roles as project owner, designer and clerk. Their AVR (AVR2026MAY120018) states, "A one-inch low pressure plastic gas main was damaged during excavating activities. Work had begun prematurely due to an onsite miscommunication involving when POC was in and was clear to begin. Supervisor immediately called in an emergency and conducted a site review of safe practices related to one call 3 business day minimum wait before beginning any excavation activities.” The second AVR (AVR2026JUL060038) states, “Contractor struck the gas service line while excavating trench for new water main on s.41st st b/w Baltimore Ave & Chester Ave. Contractor is not supposed to start the work, markings are not done on site.” American Engineers Group submitted an AVR. They reported their role as inspector. Their AVR states, "Contractor struck the gas service line while excavating trench for new water main on s.41st st b/w Baltimore	**AP Construction: $2,000.00** Section 1.1 1st Offense $1,000.00 Section 5(8) 1st Offense $1,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Ave & Chester Ave. Contractor is not supposed to start the work, markings are not done on site." Photos were submitted. Routine PA One Call ticket 20261033600 was requested on 04/13/2026, at 2:18 PM by AP Construction. The lawful start date for this ticket was 04/16/2026. The incident occurred on 04/14/2026, prior to the lawful start date for the ticket. Philadelphia Gas Works did not mark out their lines prior to the damage occurring. The submitted photos show the damaged gas line. AP Construction reported in their AVR that 911 was not called and they had the adjacent workers evacuate the area. Act 127 of 2024, also known as the Underground Utility Line Protection Law states it shall be the duty of each excavator who intends to perform excavation or demolition work within this Commonwealth: - Section 1.1- The lawful start date shall be three business days through ten business days following notification to the One Call System. - Section 5.8 - To immediately notify 911 and the facility owner if the damage results in the escape of any flammable, toxic or corrosive gas or liquid. The excavator shall take reasonable measures, based on its knowledge, training, resources, experience and understanding of the situation, to protect themselves and those in immediate danger, the general public, the property and the environment until the facility owner or emergency responders have arrived and completed their assessment and shall remain on the work site to convey any pertinent information to responders that may help them to safely mitigate the situation. Excavation using a routine PA One Call ticket may not begin until the lawful start date shown on the ticket. When a utility line is damaged and results in the escape of any flammable, toxic or corrosive gas or liquid, you are required to call 911. Violations: AP Construction- - Section 1.1 – Excavator did not begin within legal timeframe. - Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. Recommendation: The penalty is applied. PUC online Compliance Training is required for the individual(s) responsible, or their replacement(s).	
65147	**Facility Owner:** West Penn Power / First energy (WPP) **Contractor/Excavator:** TRUST IN FENCES	On 4/14/2026 9:06:00 AM at 3317 BROWNSVILLE RD EXT, SOUTH PARK TWP, ALLEGHENY The incident occurred on 4/14/2026 at 3317 BROWNSVILLE RD EXT in SOUTH PARK TWP in Allegheny Co.	

Case Number	Stakeholders	Summary	Violations & Recommendation
	PREVIOUSLY LAWN IN ORDER LANDSCAPES **Project Owner:** HOMEOWNER **Other:** COMCAST	An electric line was damaged, and another electric line was mismarked. WEST PENN POWER – FIRSTENERGY (WPP) stated in their Alleged Violation Report (AVR) that, "'On March 26, 2026, Lawn in Order Landscapes, Excavator, submitted PA One Call Ticket 20260852678 to install fencing at 3317 Brownsville Road EXT, South Park Township, Allegheny County, Pennsylvania. On 4/14/2026, a power outage was reported in the area of Brownsville Road to West Penn Power ("WPP"). WPP Operations located a damaged underground primary line. USIC, WPP's Contract Locator, investigated and determined that the line was correctly marked." ISIC report and tickets were provided." The summary of events states that the damage was done with a shovel, but the excavator explained that they were using a post driver. Pictures show the marked line, but do not show the line that was not located until after this line was hit and the locator marked the second line. Trust in Fences DBA LAWN IN ORDER LANDSCAPES stated in their AVR that, "Employees were installing a chain link fence. There was a marking that was close but not where were digging. Crew hand dug down 3' and did not see anything. Crew gave a gentle tap with post pounder to hold post steady for concrete. They bumped the line with that bump. Markings up front were not where we were digging but close to being the distance from which is acceptable. Once remarked upper markings were about 3' off of an old line that had no coating which was right where we were going to be putting the fence. Had we not bumped that post it could have been alot worse. Its our first damaged line so we did not take photos." Homeowner was sent an AVR request letter on 6/26/2026. On 7/06/2026 the homeowner left a message which stated that they were having a fence put in their yard and " the line was marked by pa call wrong and they The homeowner left a message which stated that "y hit the line since then the complete line has been it was patched then at that date and then about a month later the whole the whole hill here the whole neighborhood has been redone there's new lines and everything and when that happened i was told pa 1 was here and they investigate it and they said they would take care of everything…" Please see attachment named "DPI Derrick returned a call to PO" for the complete voice mail. DPI Maki returned a call to the homeowner who stated that the main line was not marked, but the neighbor's line that was under the fence and the line that went to the homeowner's house was marked. The main line fed into the box that serves 6 households and ran through the yard and was not marked. He stated that the excavator had white paint there. He also stated that the excavator's name has changed to "Trust in Fences". Homeowner stated that he would send an email providing this	

Case Number	Stakeholders	Summary	Violations & Recommendation
		information, but no email was received. DPI sent an email on 7/14/2026 to Lawn in order contact about the new name or relationship to "trust in Fences". Comcast submitted an AVR with informant for the ticket responses. All the pictures that were submitted were submitted by WPP. No VIOLATIONS were found. Hand tools were used. There was no evidence of the second unmarked line. Note that there is an underground transformer that is in the back of the building in line with the fence confirmed in an email sent on 7/31/2026 from WPP. No pictures were provided.	
64135	**Facility Owner:** UGI Utilities **Contractor/Excavator:** EZ SIGNS **Project Owner:** GCM Built	On 4/14/2026 10:20:00 AM at 5335 Carlisle Pike, HAMPDEN TWP, CUMBERLAND Incident occurred on 4/14/26 at 10:20am on 5335 Carlisle Pike, Hampden Township, Cumberland County. Incident: A gas line was damaged. Alleged Violation Reports (AVR): Facility Owner - UGI's AVR states, "EZ Signs was digging with mechanized equipment to install footers behind 5335 Carlisle Pike, Mechanicsburg. They failed to call in a PA One Call ticket prior to the start of excavation. As a result, they struck and damaged an unmarked gas service causing a release of gas. Emergency response efforts were carried out by the on-site landlord until 911 services and UGI arrived on-site. Katelyn Drayer with GCM Built called 911." PA1call commented, "Contractor has placed One Call notifications with PA One Call in the past." Conclusion: EZ Signs excavated using a mini excavator in the images. Property management company called 911. Property management company was not the project owner. EZ Signs was mailed and emailed a request for information along with the need for an AVR. No response was received. Recommended violations, penalties, and education: Excavator: EZ Signs Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. PUC compliance education is required for the excavators working onsite of this excavation or their replacements.	**EZ SIGNS: $2,500.00** Section 5(2.1) 1st Offense $1,000.00 Section 5(16) 1st Offense $1,000.00 Section 5(17) 1st Offense $500.00
64038	**Facility Owner:** NATIONAL FUEL GAS	On 4/14/2026 11:15:00 AM at 908 WINDFALL RD, ST MARYS CITY, ELK BLAIN DANIELS	**BLAIN DANIELS EXCAVATING:**

Case Number	Stakeholders	Summary	Violations & Recommendation
	DIST RC 350 **Contractor/Excavator:** BLAIN DANIELS EXCAVATING **Project Owner:** WINDFALL AUTO SALES	EXCAVATING disagrees. This is a first-time violation and the $500. for 5(4) penalty is reduced to a warning. The $1000 penalty cited for 5(8) Not immediately notifying 911 and the education requirement are maintained. On 11/06/2026 Blain and Windfall accepted the violations and education. They do not want to come to the DPC meeting. * WINDFALL AUTO SALES disagrees. On 9/24/52026 Windfall Auto Sales requested that BLAIN DANIELS EXCAVATING represent then at the Damage Prevention Committee (DPC) meeting. This is a first-time violation and the $1000. penalty is reduced to a warning. The education requirement is maintained. On 11/06/2026 Blain and Windfall accepted the violations and education. They do not want to come to the DPC meeting. ********** The incident occurred on 4/14/2026 at 908 WINDFALL RD in ST MARYS CITY in Elk County. A gas line owned by National Fuel Gas was damaged. NATIONAL FUEL GAS stated in their Alleged Violation Report (AVR) that, ‘ Excavator struck a properly marked natural gas distribution service line. Please see attachments.” Pictures were provided. 911 was not notified. WINDFALL AUTO SALES were sent an AVR request letter on 4/24/2026. NO AVR nor contact has been made as of 7/29/2026. No mail has been returned. DANIELS EXCAVATING provided a document and stated to “Please see attached Document.” This document states that, “Summary of Event: I was digging a drainage ditch on the edge of a parking lot. Located at 908 Windfall Road, Saint Marys, PA. On the parking lot side the maximum depth was 1 foot. On the other side was a steep bank which I dug down 2ft. The ditch surface was solid rock which made it hard to dig with a shovel. We had the pipe located near the squirt bottle as seen in the attached photo. The pipe dipped down 6 inches. I caught a hold of the line with the last tooth on the bucket. I only took one photo not knowing that I would have to make out a violation report. This is the first time in 49 years that I had to fill out a report and hopefully the last. I hope that I filled it out properly with the information that is needed.” A picture was provided in this document. VIOLATIONS BLAIN DANIELS EXCAVATING is in violation of: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Within the tolerance zone, the excavator shall employ prudent techniques, which may include hand-dug test holes, vacuum excavation or similar devices to ascertain the precise position of such facilities. This is a first-time violation and the $500. penalty is reduced to a warning.	**$1,000.00** Section 5(4) 1st Offense $0.00 Section 5(8) 1st Offense $1,000.00 **WINDFALL AUTO SALES: $0.00** Section 6.1(7) 1st Offense $0.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid. Recommendation: The penalties are applied. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). WINDFALL AUTO SALES is in violation of: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike or damaging a facility owner's line during excavation or demolition work activities or if a project owner believes a violation of this act has been committed in association or demolition. This is a first-time violation and the $1000. penalty is reduced to a warning. The education requirement is maintained.	
64186	**Facility Owner:** National Fuel Gas **Contractor/Excavator:** Harborcreek Township **Project Owner:** HARBORCREEK TWP	On 4/14/2026 2:39:00 PM at BERNWOOD DR, HARBORCREEK TWP, ERIE Incident occurred on 4/14/26 at 2:39pm along Bernwood Drive, Harborcreek Township, Erie County. Incident: A gas line was damaged. Alleged Violation Reports (AVR): Facility Owner - National Fuel Gas' AVR states, "Excavator failed to use prudent digging techniques and struck a properly marked NFG main causing service interruption to 28 customers" Excavator & Project Owner - Harborcreek Township's AVR states, "On April 14, 2026 Harborcreek Township road crew was digging a tree stump out of our right of way at the intersection of Bernwood and Greenbriar Drives. As we were digging the bucket caught a piece of the National Fuel Gas marked line and caused a gas release. An emergency one call was placed, National Fuel was notified immediately through cell-phone conversations with the area supervisor. The fire department and Harborcreek Township EMA were also notified." Was the AVR submitted after 30 days? Yes. PUC request for information sent on: 6/24/26 Conclusion: Harborcreek damaged an accurately marked gas line and submitted an AVR promptly after being asked for an AVR. Recommended violations, penalties, and education: Excavator: Harborcreek Township Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. AVR penalty reduced $1,000 to $0 for providing AVR after request as a 1st offense.	**Harborcreek Township: $500.00** Section 5(4) 1st Offense $500.00 Section 5(16) 1st Offense $0.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		-PUC compliance education is required for the excavators working onsite of this excavation or their replacements.	
64158	**Facility Owner:** Columbia Gas of PA - East **Contractor/Excavator:** CREEKSTONE LANDSCAPE AND EXCAVATING **Project Owner:** DRB Homes	On 4/16/2026 9:00:00 AM at 176 Heritage Drive, WEST MANHEIM TWP, YORK The near miss incident occurred on 4/16/2026 at 176 Heritage Drive in WEST MANHEIM TWP in York Co. A gas line owned by Columbia Gas was near an excavation which was taking place without a valid PAOneCall ticket. *NO DAMAGE Columbia Gas of PA stated in their Alleged Violation Report (AVR) that, "Damage Prevention arrived at a new development and found Creekstone excavating a very large trench without a valid PA One Call dig ticket. The crew was immediately stopped, and the three-person team was approached on site. A follow-up call was then made to the owner. No One Call dig ticket (e.g., #20261061234) had been placed to notify other facility owners. Fortunately, our gas main was not located on that side of the property, making this a near miss. Creekstone is an experienced contractor who has been educated on the law previously." Pictures were provided. Images show active excavation. Compliance Research Results: No tickets were found placed by contractor related to this AVR but contractor has placed one calls in the past. DRB HOMES stated in their AVR that, "Creekstone excavated without having the lines marked, no utilities were hit, there was no damage, they were just "close" to a utility. I do not know the date or time as we were never notified of an issue until the AVR request was received." Compliance Research Results: Not enough information to perform an accurate ticket search since no specific work site was provided. There are multiple tickets placed by Creekstone Landscape and Excavating for the Prinland Heights subdivision in 2025 and 2026. Most recent contact info on ticket: Creekstone Landscape and Excavating was sent an AVR request letter on 5/08/2026.No AVR has been received as of 7/29/2026. No mail has been returned. VIOLATIONS Creekstone Landscape and Excavating is in violation of: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or damaging a facility owner's line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. An AVR request letter was sent on 5/08/2026. No AVR has been received. No contact has been made. No letters have been returned. ACT 50 reads: To submit a report of alleged violation to the commission through the One Call System not more	**CREEKSTONE LANDSCAPE AND EXCAVATING: $2,500.00** Section 5(2.1) 1st Offense $1,000.00 Section 5(16) 1st Offense $1,000.00 Section 5(17) 1st Offense $500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		than 30 days after striking or damaging a facility owner's line during excavation or demolition or if the excavator believes a violation of this act had been committed in association with excavation or demolition work. The report of alleged violation shall be in a form and manner as required by the commission. Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within 30 days of the receipt of the request. Many questions were added to the AVR request letter that would provide information for this investigation. There has been no contact from this excavator. Recommendation: The penalties are applied. PUC compliance education is required for the excavators working onsite of this excavation or their replacements.	
64022	**Facility Owner:** Municipal Authority of Westmoreland County **Contractor/Excavator:** PLUM CONTRACTING **Project Owner:** PennDOT **Designer:** S P K ENGINEERING	On 4/16/2026 1:00:00 PM at MOUNT PLEASANT/MCCLURE INTERSECTION, UPPER TYRONE TWP, FAYETTE Incident occurred on 4/16/26 at 1pm at the intersection of Mount Pleasant & McClure, Upper Tyrone Township, Fayette County. Incident: A MAWC water line was damaged by Plum Contracting during a road widening project that also involved some drainage work. Alleged Violation Reports (AVR): Facility Owner -Westmoreland County Municipal Authority's AVR states, "Excavator, Plum contracting was working for Project Owner PENNDOT grading down Mt. Pleasant Road in Upper Tyrone Twp. The Municipal Authority of Westmoreland County (MAWC) cast iron water main was exposed, and this main appeared to have lifted creating a separation at a joint in the pipe. MAWC accurately marked this line and prudent digging techniques appeared to have been used. Plum contacted MAWC to report the leaking water main. MAWC responded and made the necessary repair." Excavator - Plum Contracting's AVR states, "This was purely an accident. The line was NOT field marked wrong. It was simply higher in the grade than what was depicted in our plans. We hit it and the utility owner had it repaired within an hour. MAWC did great dispatching a crew to repair as quickly as possible." Project Owner - PennDOT submitted an AVR without a summary but did attach images. Designer - S P K Engineering's AVR states, "I received an AVR notice last week and that's when I first heard of the event. I inquired and found out about the waterline being hit and that it was handled very quickly (within an hour) by MAWC. Not sure if it was a distribution or service line that was hit but according to the picture (from Plum) that I saw, it seemed shallow for a waterline. Also, this is large project and numerous PA 1 Calls (by others) have been placed since the Final Design ones that are listed on the plan."	**PLUM CONTRACTING: $500.00** Section 5(4) 1st Offense $500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Images show a backhoe bucket was being used when the damage occurred. Pre-excavation images show the main was marked running along the edge of the road. Mark out photos also show that the road is even and/or higher elevation than the grass at the edge. Damage photos show a worker standing in the deeper excavation zone that has had the road surface and sub surface removed. Conclusion: Plum Contracting Recommended violations, penalties, and education: Excavator: Plum Contracting Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. -PUC compliance education is required for the excavators working onsite of this excavation or their replacements.	
64748	**Facility Owner:** UGI Utilities Inc **Contractor/Excavator:** IDEAL FENCING **Project Owner:** Property Owner	On 4/16/2026 1:00:00 PM at 2018 Girard Ave, SPRING TWP, BERKS The incident occurred on April 16th, 2026, at approximately 1:00 PM, at 2018 Girard Avenue, located in Spring Township, Berks County, Pennsylvania. A gas line owned by UGI was damaged. 911 was not called. The excavator did not have a PA One Call ticket. UGI, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “Excavator utilizing mechanized equipment, struck an unmarked gas service while excavating without a valid paoc.” Photos were submitted. UGI reported in their AVR that 911 was not called. Ideal Fencing is the excavator. An AVR has not been filed as of 08/24/2026. An AVR request letter was sent 07/06/2026. The property owner was the project owner. An AVR request letter was not sent. An AVR has not been filed as of 08/24/2026. PA One Call (POC) reported Ideal Fencing has placed ticket requests in the past. POC also reported they were unable to locate any tickets submitted by Ideal Fencing for this location. The submitted photos show the damaged gas line. No utility mark outs are seen in the submitted photos. A gas meter is visible and near the damaged gas line. The gas meter is an indicator that there is an underground gas line in the immediate area. The photos also show the mechanized auger that was used at the location where the incident occurred. Ideal Fencing did not have a Pa One Call ticket; therefore, no underground utilities marked their lines. There is a visible gas meter in the immediate excavation area. A gas line was damaged. 911 was not called. 911 is	**IDEAL FENCING: $3,500.00** Section 5(2.1) 1st Offense $1,000.00 Section 5(8) 1st Offense $1,000.00 Section 5(16) 1st Offense $1,000.00 Section 5(17) 1st Offense $500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		required to be called anytime there is damage to a utility line that resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. The Public Utilities Commission (PUC) investigator requested Ideal Fencing to submit an AVR. Ideal Fencing failed to comply with all requests for information from PUC staff within thirty days of receipt of the request and did not file an AVR. Act 127 of 2024, also known as the Underground Utility Line Protection Law states it shall be the duty of each excavator who intends to perform excavation or demolition work within this Commonwealth: - Section 5(2.1) - To submit a locate request to identify the location and type of facility owner lines at each work site by notifying the facility owner through the One Call System. Notification shall be not less than three nor more than ten business days in advance of beginning excavation or demolition work. No work shall begin earlier than the lawful start date which shall be on or after the third business day after notification. The lawful start date shall exclude the date upon which notification was received by the One Call System and notification received on a Saturday, Sunday or holiday, which shall be processed on the following business day. - Section 5(8) - To immediately notify 911 and the facility owner if the damage results in the escape of any flammable, toxic or corrosive gas or liquid. The excavator shall take reasonable measures, based on its knowledge, training, resources, experience and understanding of the situation, to protect themselves and those in immediate danger, the general public, the property and the environment until the facility owner or emergency responders have arrived and completed their assessment and shall remain on the work site to convey any pertinent information to responders that may help them to safely mitigate the situation. - Section 5(16) – To submit a report of an alleged violation to the commission through the One Call System not more than thirty days after striking or damaging a facility owner's line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. - Section 5(17) - To comply with all requests for information by the commission relating to the commission's enforcement authority under this act within thirty days of the receipt of the request. Violations: Ideal Fencing- - Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe/ prior to excavation. - Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property.	

Case Number	Stakeholders	Summary	Violations & Recommendation
		- Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. - Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. Recommendation: The penalty is applied. PUC online Compliance Training is required for the individual(s) responsible, or their replacement(s).	
64069	**Contractor/Excavator:** ANGIES CABLE **Project Owner:** RHINO CABLE **Other:** AQUA PENNSYLVANIA INC **Other:** Verizon	On 4/17/2026 5:47:00 AM at NAVAJO DRIVE, LIMERICK TWP, MONTGOMERY The incident occurred on April 17th, 2026, at approximately 05:47 AM, on Navajo Drive, located in Limerick Township, Montgomery County, Pennsylvania. Non-damage incident. Emergency notification did not meet the requirements of "emergency". Aqua Pennsylvania Inc., a facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, "Excavator submitted an non-emergency emergency ticket working for Rhino Cable. Rhino Cable has previously called in a routine ticket for the same address and same work." Angies Cable is the excavator. An AVR has not been filed as of 08/24/2026. A courtesy AVR request letter was not sent. Rhino Cable is the project owner. An AVR has not been filed as of 08/24/2026. A courtesy AVR request letter was not sent. "Emergency" means a sudden or unforeseen occurrence involving a clear and immediate danger to life, property or the environment, including, but not limited to, serious breaks or defects in a facility owner's lines. Angies Cable, the excavator, requested an emergency PA One Call ticket (20261070018). The ticket lists the type of work as: Install CATV main. No damage was reported. This is an ongoing project as there was a previous routine PA One Call ticket (20260703816]) submitted by Rhino Cable for the same type of work for the same locations. This event does not meet the qualification of an emergency and therefore an emergency PA One Call ticket should not have been requested. The excavator should have used a routine ticket. Routine ticket 20260703816 version 000 had a response due date of 03/13/2026. - Verizon did not respond to this ticket. Renotify ticket 20260703816 version 001 was requested 03/20/2026 at 8:15 AM and had a response due date of 03/20/2026. This renotify ticket required stakeholders to directly contact the excavator within 2 hours.	**ANGIES CABLE: $0.00** Section 5(9) 1st Offense $0.00 **Verizon: $4,000.00** Section 2(5)(v) Subsequent $2,000.00 Section 2(5)(v.1) Subsequent $2,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		- Verizon responded more than 2 hours after the ticket was requested, at 1:01 PM (03/20/2026). Act 127 of 2024, also known as the Underground Utility Line Protection Law states it shall be the duty of each excavator who intends to perform excavation or demolition work within this Commonwealth: - Section 5.9 - To not provide a misrepresentation of an emergency excavation, subject to an administrative penalty imposed under section 7.10. Act 127 of 2024, also known as the Underground Utility Line Protection Law states it shall be the duty of each facility owner: - Section 2(5) - After receipt of a timely request from an excavator or operator who identifies the work site of excavation or demolition work he intends to perform and not later than the business day prior to the lawful start date of excavation: (v) – To respond to all notices through the One Call System, provided the request is made in the time frame set forth under this act. The response shall be made not later than the end of the second business day following receipt of the notification by the One Call System, excluding the business day upon which the notification is received, or not later than the day prior to the lawful start date of excavation if the excavator specifies a later date or, in the case of an emergency, to respond through the One Call System as soon as practicable following receipt of notification of the emergency by the One Call System. (v.1) – To, if a facility owner failed to respond to an original, proper, nonemergency locate request from the One Call System or to a renotification under section 5(20), communicate directly to the excavator within two hours after renotification of the information about its facility location and, if necessary and possible, go to the proposed work site to mark, stake or locate its underground lines or to verify to the excavator that the facility owner's underground lines are not within the area of the proposed work site. Violations: Angies Cable - - Section 5(9) – Emergency notification does not meet the requirements of “emergency”. Emergency ticket 20261070018. Recommendation: No penalty is applied; this is a warning. PUC online Compliance Training is required for the individual(s) responsible, or their replacement(s). No prior violations. Verizon- - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Routine ticket 20260703816 version 000. - Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Renotify ticket 20260703816 version 001.	

Case Number	Stakeholders	Summary	Violations & Recommendation
		Recommendation: The penalty is applied. PUC online Compliance Training was recently completed.	
64245	**Facility Owner:** Greater Johnstown Water Authority **Contractor/Excavator:** Penelec / First Energy **Project Owner:** Penelec / First Energy (Placeholder)	On 4/19/2026 10:30:00 PM at 461 GOVIER LN, CONEMAUGH TWP, SOMERSET Penelec / First Energy accepts. ********** The incident occurred on April 19th, 2026, at approximately 10:30 PM, at 461 Govier Lane, located in Conemaugh Township, Somerset County, Pennsylvania. A water line owned by Greater Johnstown Water Authority was damaged. Greater Johnstown Water Authority, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “FirstEnergy - Penelec was replacing an utility pole on Sunday, April 19, 2026 night around 10:30 PM around 461 Govier Lane when they put their auger through a 6" cast iron water main, that was accurately marked. Water crews responded Sunday night and continued through Monday morning repairing the damaged 6" cast iron water main. The repair took approximately 11 hours from notification of the damage till repair was completed. Due to after business hours, the response to the PA1Call system was delayed but it was marked within the 2-hours of ticket notification and staff reported to the scene within two hours of the damage ticket as well. The attached photographs show that the mark is readily visible even after excavation and a broken water line making the site muddy. Please note that in the photograph looking at the damaged pipe shows the blue mark is near the 1 foot line of the ruler and to the left of the mark cone and well within the 18" of the 6" cast iron main located around the 1-foot 3-inch mark. There is a second 12" PVC water main that runs 4" to the left of the 6" Cast Iron main and the marking for this line is not visible as its under the saw dust. The photograph facing the excavator, is the reverse angle of the previously discussed image.” Photos were submitted. Penelec, the excavator and project owner, submitted an AVR. Their AVR states, “On April 19, 2026, Penelec submitted New Excavation Emergency Ticket 20261090421 for the replacement of two broken utility poles at 461 Govier Lane, Conemaugh Township, Somerset County, Pennsylvania. While excavating, Penelec’s crew struck an unmarked water line, so they submitted Damage Emergency Ticket 20261090629. Penelec does not have any photos of the site available.” Photos were submitted. New excavation ticket 20261090421 was submitted by Penelec with the type of work listed as ‘pole replacement’. The ticket indicates that the method of excavation is drilling. This ticket was requested on 04/19/2026 at 4:04 PM. Greater Johnstown Water Authority responded to this ticket as ‘Field Marked’ on 04/19/2026 at 6:53 PM.	**Penelec / First Energy: $500.00** Section 5(4) 1st Offense $500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		In the submitted photos, a hit kit was used to identify the utility mark out in relation to the damaged utility line. Blue paint was used to mark the water line, as seen in the photos. The blue mark out had some sawdust on it. The water line was damaged within the tolerance zone. Act 127 of 2024, also known as the Underground Utility Line Protection Law states it shall be the duty of each excavator who intends to perform excavation or demolition work within this Commonwealth: - Section 5(4) - To exercise due care and to take all reasonable steps necessary to avoid injury to or otherwise interfere with all lines where positions have been provided to the excavator by the facility owners pursuant to section 2 (5). Within the tolerance zone the excavator shall employ prudent techniques, which may include hand-dug test holes, vacuum excavation or similar devices to ascertain the precise position of such facilities. Violations: Penelec – - Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: The penalty is applied. PUC online Compliance Training is required for the individual(s) responsible, or their replacement(s).	
64272	**Facility Owner:** UGI Utilities, Inc. **Contractor/Excavator:** Sensenig Excavating LLC **Project Owner:** Burkholder Tractor & Equipment LLC	On 4/20/2026 3:00:00 PM at 3200 STATE DR LEBANON PA, SOUTH LEBANON TWP, LEBANON The incident occurred on April 20th, 2026, at approximately 3:00 PM, at 3200 State Drive, located in South Lebanon Township, Lebanon County, Pennsylvania. A gas line owned by UGI was damaged. UGI Utilities, Inc., the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, "Sensenig Excavating LLC was digging with mechanized equipment along State Dr in Lebanon. While digging trench, they dug into a correctly marked gas service going to 3200 State Dr. There was not a release of gas. The excavator pulled on the service and kinked it but there was not a release of gas. The only PA One Call ticket number the excavator could provide was S# 20250870567 which was over a year old at the time of the damage. UGI had responded as clear to this ticket as when the ticket was called in, gas facilities didn't exist yet on this property. The service that was damaged had not even been installed when that original ticket was called in but was marked after installation." Photos were submitted. Sensenig Excavating LLC, the excavator, submitted an AVR. Their AVR states, "Excavator struck a live UGI gas service line, but did not break the pipe. UGI was contacted and repaired the line the same day."	**Sensenig Excavating LLC: $500.00** Section 5(4) 1st Offense $500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Burkholder Tractor & Equipment LLC, the project owner, submitted an AVR. Their AVR states, "I am the property owner, I was aware of, but not directly involved with the situation, the incident was very minor, occurred on 4/20/26 slight scuff on the gas line." The submitted photos show the gas line was marked using yellow flags. A hit kit can be seen in the photos, identifying where the damage occurred, in relation to the yellow flags. The damaged utility line was directly in line with the yellow flags and the damage occurred within the tolerance zone. The gas line was accurately marked. The photos also show the damaged/ kinked gas line. All 3 AVRs indicated that 911 was not called. UGI reported there was no release of gas. The excavator pulled on the line with mechanized equipment and kinked it, but there was no release of gas. UGI had responded 'clear' to routine tickets 20260681377 (version 000) and 20250870567. - Ticket 20260681377 (version 000) was requested on 03/09/2026. UGI responded to this ticket on 03/10/2026. - Ticket 20250870567 was requested on 03/28/2026. UGI responded to this ticket on 03/29/2026. The damage occurred on 04/20/2026. The most recent ticket that included UGI was responded to about 3 weeks prior to the damage. UGI noted in the AVR, "The gas service going to 3200 State Dr was marked correctly with yellow flags. At the time that this excavators PA One Call ticket was created, the gas service and main had not existed yet. The service was marked after installation in between the excavators only ticket and the day of the damage." The gas line was accurately marked using yellow flags. The excavator damaged the line within the tolerance zone using mechanized equipment. There was no release of gas. Act 127 of 2024, also known as the Underground Utility Line Protection Law states it shall be the duty of each excavator who intends to perform excavation or demolition work within this Commonwealth: - Section 5(4)- To exercise due care and to take all reasonable steps necessary to avoid injury to or otherwise interfere with all lines where positions have been provided to the excavator by the facility owners pursuant to section 2 (5). Within the tolerance zone the excavator shall employ prudent techniques, which may include hand-dug test holes, vacuum excavation or similar devices to ascertain the precise position of such facilities. Violations: Sensenig Excavating LLC-	

Case Number	Stakeholders	Summary	Violations & Recommendation
		- Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: The penalty is applied. PUC online Compliance Training is required for the individual(s) responsible, or their replacement(s).	
64232	**Facility Owner:** LEHIGH COUNTY AUTHORITY **Contractor/Excavator:** Mechanics Plus Towing and Transport INC. **Project Owner:** Mechanics Plus Towing and Transport INC -	On 4/22/2026 12:00:00 PM at 4701 Colebrook Ave, EMMAUS BORO, LEHIGH The incident occurred on 4/22/2026 at 4701 Colebrook Ave in EMMAUS BORO in LEHIGH Co. A Sanitary sewer overflow and manhole owned by LEHIGH COUNTY AUTHORITY was damaged. LEHIGH COUNTY AUTHORITY, the facility owner, stated in their Alleged Violation Report (AVR) that, "A construction company was moving earth on their property and failed to call in a Pa-1 Call and subsequently hit a sewer manhole filling it with debris causing a Sanitary sewer overflow and damage to the manhole." Pictures were provided. 11 customers were affected by the outage. This was verified by a telephone call on 8/05/2026 from Lehigh Co Authority. See case comments. *Compliance research Results: Mechanics Plus has placed One Call notifications in the past Mechanics Plus Towing and Transport INC., the excavator and the project owner, was sent an AVR request letter on 5/15/2026. No AVR has been received as of 7/29/2026. VIOLATIONS Mechanics Plus is in violation of: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. PA OneCall ticket was not submitted for work that was done using mechanical equipment. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or damaging a facility owner's line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. ACT 50 reads: To submit a report of alleged violation to the commission through the One Call System not more than 30 days after striking or damaging a facility owner's line during excavation or demolition or if the excavator believes a violation of this act had been committed in association with excavation or demolition work. The report of alleged violation shall be in a form and manner as required by the commission. Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within 30 days of the receipt of the request. Questions asked in the AVR request letter were not responded to. This excavator has not made any contact with the investigator. Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike or damaging a facility owner's line during excavation or	**Mechanics Plus Towing and Transport INC.: $3,500.00** Section 5(2.1) 1st Offense $1,000.00 Section 5(16) 1st Offense $1,000.00 Section 5(17) 1st Offense $500.00 Section 6.1(7) 1st Offense $1,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		demolition work activities or if a project owner believes a violation of this act has been committed in association or demolition. Recommendation: The penalties are applied. PUC project owner compliance education is required for the person responsible for submitting AVR or their replacement.	
64586	**Facility Owner:** PECO **Contractor/Excavator:** DELAWARE VALLEY SEPTIC INC **Project Owner:** Homeowner	On 4/23/2026 5:00:00 PM at 207 CARRIAGE LANE, NEWTOWN TWP, DELAWARE Incident occurred on 4/23/26 at 5pm on 207 Carriage Lane, Newtown Township, Delaware County. Incident: A mismarked PECO electric line was damaged. Alleged Violation Reports (AVR): Facility Owner - PECO's AVR states, "On 4/23/2026, Delaware Valley Septic Inc was using a mini excavator when they struck an electric service." Excavator - AVR states, "The electric line was marked incorrectly. As a result we hit the electrical line digging in another area where it actually was located. We had down time for our project which was under a strict timeline for the homeowner. We also ruined the boring equipment that we were renting and are waiting on a bill to pay for the replacement." Conclusion: Images show that the line was mismarked. Recommended violations, penalties, and education: Facility Owner: PECO Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. -PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).	**PECO: $1,500.00** Section 2(5)(i) 3rd Offense $1,500.00
64410	**Facility Owner:** LOCK HAVEN CITY **Contractor/Excavator:** Big Rock Construction Group **Contractor/Excavator:** Property Owner	On 4/25/2026 10:00:00 AM at 35 Sylvan Drive, LOCK HAVEN CITY, CLINTON This non-damage incident occurred on 4/25/26 at 10am on 35 Sylvan Drive, Lock Haven City, Clinton County. Incident: Property owner was excavating without a PA One Call ticket Alleged Violation Reports (AVR): Facility Owner - Lock Haven City's AVR states, "Property owner used rental equipment to grade and dig on property on 4/25 and 4/26." Statement from Ridley states, "We were contacted by the City of Lock Haven earlier this year due to damage a property owner at 35 Sylvan Drive caused to work we performed and completed last year in Sunset Pines neighborhood. We were contracted this year by the city of Lock Haven to regrade and topsoil/seed the	**Property Owner: $0.00** Section 5(2.1) 1st Offense $0.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		surrounding area that the neighbor destroyed by unauthorized excavation. We also had to remove and replace some of the Rip rap rock installed last year due to soil being pushed onto it from the adjoining neighbor. We did not complete any excavation on this site this year, we completed simple grading with a skid steer and replacement of rip rap stone that sat on the surface. I have attached our point of contact Carter Simcox from the City of Lock Haven to attest to what we are stating. " Conclusion: Images show a skid steer that was used for excavating. Township, Big Rock, and Ridley show that work was completed in 2025 and homeowner rented equipment and excavated without a PA1call ticket in 2026. Following that the township hired a company to come in again to do remedial work. Recommended violations, penalties, and education: Excavator - Homeowner Section 5(2.1) – Homeowner failed to submit a location request to One Call within the correct timeframe. Warning $0. -PUC compliance education is required for the excavators working onsite of this excavation or their replacements.	
64367	**Facility Owner:** PECO AN EXELON COMPANY **Contractor/Excavator:** ROAD CON **Project Owner:** PENNDOT **Designer:** GANNETT FLEMING HARRISBURG PA **Other:** CMC ENGINEERING	On 4/27/2026 7:30:00 AM at 11 E. RIDLEY AVE, RIDLEY PARK BORO, DELAWARE The incident occurred on Monday, April 27, 2026, at 11 E. Ridley Avenue, in Ridley Park Borough, Delaware County. A gas line owned by PECO and Exelon Company was damaged by Road Con. PECO reported an excavator issue as failed to protect and preserve the markings after beginning excavation, or contact the One Call System to request the facilities be marked again. PECO stated in their Alleged Violation Report (AVR), “On 4/27/2026, Road Con was using an excavator when they hit a gas service.” From the USIC fact based investigation report, “USIC was notified of a gas line that was hit at 11 E Ridley Ave in Ridley Park, Delaware County, PA. The investigation determined that the contractor was using an excavator under ticket# 20253032764 when they hit an unmarked Exelon 1/2" gas service. This ticket expired back in November of 2025.” On Wednesday, 7/22/2026, emails and letters were sent to Road Con, and the project owner, PennDOT. Road Con stated in their AVR, “During Excavation of the roadway, we hit a gas service to a house. Called PECO and they came out to fix it. Gas service was marked behind curb. Excavation was occurring within the roadway. The gas service was found approximately 1.5' below roadway grade with excavating for roadway subgrade. Photos are later in the	**ROAD CON: $1,500.00** Section 5(3) 1st Offense $500.00 Section 5(16) 1st Offense $1,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		afternoon finding the service at the main. Main was only a few inches below subgrade." CMC Engineering; representing PennDOT and Consultant Inspector, reported a facility owner issue as failure to locate point of connection to facility lines. CMC Engineering stated in their AVR, "The prime contractor, Road Con Inc, was utilizing a dozer to gently remove unsuitable material in the roadway and the clay material sheared from below the dozer blade. The dozer did not hit the utility directly. The pressure of the clay shearing had pushed the utility and caused it to break." Gannett Fleming stated in their AVR, "Contractor hit a gas service line during roadway excavation." 20253032764- Routine ticket was placed on 10/30/2025, lawful start dates 11/4/2025 – 11/14/2025, and for a duration of 8 months. PECO responded to on 10/31/2025 as field marked and pictures were taken of the locates (attachment- PECO locate pics 20253032764). There were no additional ticket notifications placed by Road Con, requesting remarks of the facilities. The Underground Utility Line Protection Law (UULPL) aka PA One Call Law, ACT 127, Responsibilities Of The Excavator, Section 5(16) states: To submit a report of an alleged violation to the commission through the One Call System not more than thirty days after striking or damaging a facility owner's line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. The report of an alleged violation shall be in a form and manner as required by the commission. The Underground Utility Line Protection Law (UULPL) aka PA One Call Law, ACT 127, Responsibilities of The Project Owner, Section 6.1(7) states: To submit a report of alleged violation to the commission through the One Call System not more than thirty days after striking or damaging a facility owner's line during excavation or demolition work activities, after a project owner's contracted excavator strikes or damages a facility owner's line during excavation or demolition activities or if the project owner believes a violation of this act has been committed in association with excavation or demolition. The report of alleged violation shall be in a form and manner as required by the commission. Violations: *Road Con is in violation of sections: 5(3) – Excavator failed to preserve mark-outs or request a remark. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: Penalties applied and PUC Online Compliance Training is required for the Excavator(s) working onsite at this excavation, or their replacements.	

Case Number	Stakeholders	Summary	Violations & Recommendation
64336	**Facility Owner:** Peoples Natural Gas **Contractor/Excavator:** PC CLEAR CONNECTIONS **Project Owner:** Communications Construction Group, LLC **Other:** VERIZON	On 4/27/2026 12:18:00 PM at GRANADA WAY, LOGAN TWP, BLAIR The incident occurred on 4/27/2026 at Granada Way in Logan Township in Blair Co. *No damage Multiple tickets were requested for a large complex project, and no complex project ticket was submitted to hold a Complex Project meeting. PEOPLES NATURAL GAS COMPANY LLC stated in their Alleged Violation Report (AVR) that. "PC CLEAR CONNECTIONS placed 5 one-calls without a complex ticket meeting. One ticket is 1800ft. All other tickets are close to 1000 ft. PNG is staying ahead of the contractor, but a complex ticket meeting should have been required. Contractor marked their path of excavation in white paint then started digging outside of the white paint." PC Connections were boring. Pictures were provided. PC CLEAR CONNECTIONS was sent an AVR request letter on 5/15/2026. DPI Maki returned a call to Paul with PC Clear Connections. DPI Maki explained the AVR and the process to submit an AVR. DPI Maki also explained why they were sent an AVR request letter and why a complex project is important. They stated that they did have a complex project. DPI Maki recommended that they add in the CP ticket number to their AVR. On 5/28/2026 DPI Maki requested information about the project owner. PC Clear Connections asking who the Project owner was and their contact information. An email was quickly returned stating that Communications Construction Group, LLC and the contact information was provided. PC Clear Connects did not provide a summary in their AVR but submitted pictures. Project is listed as <$400,000. VERIZON PENNSYLVANIA LLC stated in their AVR that, "We missed a locate time to cover another emergency request." No other information was provided. Ticket 20261124264 was submitted by PC CLEAR CONNECTIONS on 4/22/2026 with a response due by 4/24/2026, with a lawful start date of 4/27/226. Renotify ticket 20261124264001 was submitted by PC CLEAR CONNECTIONS on 4/27/2026 with RNO remarks: Attn Verizon you have not responded. DO HAVE LINES AT THE SITE THAT NEED TO BE MARKED. PLEASE GO TO THE SITE TOMARK THE LOCATION OF YOUR LINES ASAP AND ENTER YOUR RESPONSE AS FIELD MARKED WHEN YOU HAVE MARKED YOUR LINES. Verizon did not respond until on 5/13/2026 they responded "Insufficient Information. Do not dig. Communications Construction Group, LLC was mailed an emailed an AVR request letter on 5/28/2026. On 6/10/2026 DPI Maki returned a call to Matt Graybill and explained what an AVR is and why one is needed. DPI also explained how to submit an AVR through the	**PC CLEAR CONNECTIONS: $250.00** Section 5(3) 1st Offense $250.00 **VERIZON: $2,500.00** Section 2(5)(v) Subsequent $2,000.00 Section 2(5)(i) 1st Offense $500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		OneCAll system. Matt stated that he will submit an AVR. COMMUNICATIONS CONSTRUCTION GROUP stated in their AVR that," The project length is 2955. The excavation work is PNEUMONIC MISSLE (HOLEHOG, ETC.). Pictures were provided. VIOLATION: PC CLEAR CONNECTIONS is in violation of: Section 5(3) – Excavator failed to hold a preconstruction meeting prior to beginning a complex project. Recommendation: The penalty is applied. PUC compliance education is required for the excavators working onsite of this excavation or their replacements. Verizon is in violation of: Section 2(5)(v) – Failed to respond to a routine One Call ticket. This is a subsequent offense. Ticket 20261124264 was submitted by PC CLEAR CONNECTIONS on 4/22/2026 with a response due by 4/24/2026, with a lawful start date of 4/27/226. Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. This is a subsequent offense. Renotify ticket 20261124264001 was submitted by PC CLEAR CONNECTIONS on 4/27/2026 with RNO remarks: Attn Verizon you have not responded. DO HAVE LINES AT THE SITE THAT NEED TO BE MARKED. PLEASE GO TO THE SITE TOMARK THE LOCATION OF YOUR LINES ASAP AND ENTER YOUR RESPONSE AS FIELD MARKED WHEN YOU HAVE MARKED YOUR LINES.Verizon did not respond until on 5/13/2026 they responded "Insufficient Information. Do not dig. Recommendation: The penalty is applied. PUC compliance education has been recently completed.	
64522	**Facility Owner:** PPL ELECTRIC UTILITIES CORPORATION **Contractor/Excavator:** B R KREIDER AND SON INC **Project Owner:** HOMEOWNER **Other:** Comcast	On 4/28/2026 9:16:00 AM at 15 BRANSTOCK CT, WARWICK TWP, LANCASTER The incident occurred on Tuesday, April 28, 2026, at 15 Branstock Court, in Warwick Township, Lancaster County. An electric line owned by PPL Electric Utilities Corp. was damaged by B.R. Kreider & Son, Inc. Pictures are provided showing the mismarked damaged line. PPL reported a facility owner issue as marked incorrectly. PPL stated in their Alleged Violation Report (AVR), "On Tuesday, April 28th, 2026, at 9:16 am, a contractor (B R Kreider and Son INC) hit an unmarked electric line while installing a driveway. No injuries occurred, but the customer lost service. PPL responded, made the area safe, and restored power" B.R. Kreider and Son reported a facility owner issue as marked incorrectly. B.R. Kreider and Son stated in their AVR, "PPL and Comcast was not marked properly through the One Call system, both facilities were mis-marked by nearly 15 ft at 15 BRANSTOCK CT LANCASTER COUNTY, WARWICK TWP. The result	**PPL ELECTRIC UTILITIES CORPORATION: $500.00** Section 2(5)(i) 1st Offense $500.00 **Comcast: $500.00** Section 2(11) 2nd Offense $500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		of the mis-mark was PPL and Comcast facilities were struck causing a power outage at the residence." The Homeowner stated in an email, "the PPL power was restored within 3 hours of lines being hit. I do not have the Comcast services, I do not know if the Comcast line is or is not damaged." 20261060385- Routine ticket placed on 4/16/2026 at 7:45am. Comcast responded as clear no facilities. 20261180979- Damage emergency ticket placed on 4/28/2026 at 9:15am. Comcast responded as clear no facilities. On Thursday, 6/4/2026, an email and letter were sent to Comcast requesting an AVR. There was no response to the request and no AVR was submitted. Violations: *PPL Electric Utilities is in violation of section: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: Penalty applied *Comcast is in violation of section: 2(11) – Facility Owner failed to comply with all requests for information by the Commission relation to the Commission's enforcement authority under this act within thirty (30) days of the receipt of the request. Recommendation: Penalty applied as second offense and penalty reduced by 50% (from $1,000 to $500). Homeowner does not have service with Comcast.	
64444	**Facility Owner:** AQUA PENNSYLVANIA INC **Facility Owner:** Homeowner **Contractor/Excavator:** DANELLA POWER SERVICES **Project Owner:** PECO **Designer:** Mastec Advance Technologies **Other:** Comcast **Other:** Verizon	On 4/28/2026 4:00:00 PM at 1258 LEXINGTON DR, LOWER MAKEFIELD TWP, BUCKS PECO's violation and penalty was removed. **** Aqua's violation and penalty was removed. **** Incident occurred on 4/28/2026 at 4pm on 1258 Lexington Drive, Lower Wakefield Township, Bucks County. Incident: A sewer lateral was damaged while directional drilling. Alleged Violation Reports (AVR): Facility Owner - Aqua's AVR states, "Filing an AVR at the request of the PUC for Case 64444 for a damage that occurred at 1258 Lexington Dr on 4/28/2026. Aqua was not notified of any damage to a sewer line, no damage PA1 ticket was placed for this damage. Recent Field visit shows recent excavation was behind the curb and outside of the area of responsibility of Aqua's facilities." Excavator - Danella Power Services' AVR states, "On Tuesday, April 28th, 2026 at 4:00pm, a Danella Power Services Civil Drilling crew was working to complete a	**AQUA PENNSYLVANIA INC: $0.00** **DANELLA POWER SERVICES: $500.00** Section 5(11.2) 1st Offense $500.00 **PECO: $0.00** **Mastec Advance Technologies: $750.00** Section 4(4.1) 1st Offense $500.00 Section 4(4) 1st Offense $250.00 **Comcast: $750.00** Section 2(5)(v) 3rd offense $750.00 **Verizon: $1,000.00**

Case Number	Stakeholders	Summary	Violations & Recommendation
		directional drill shot on Lexington Drive in Yardley, Pa. Upon pullback completion and while working to restore equipment and supplies for the end of shift, crew members observed a mud pile accumulating in the front yard of 1258 Lexington Drive. Upon closer inspection, crew members found it to be sewage material coming from a buried sewer cleanout, uncovered at a depth of 4 inches. The crew then began digging within the area of the yard where the drill shot had occurred and found that upon pull back, the reamer made contact with the unmarked sewer lateral, found at a depth of 45". Notifications were made to Danella supervision and safety, PECO CM and 811. A plumber was also called to make repairs to the damaged sewer lateral. Repairs were completed later the day evening." Project Owner - PECO's AVR states, "On Tuesday, April 28th, 2026, Danella Power Services working for Peco stuck an unmarked sewer lateral." Designer - Mastec Advance Technologies' AVR states, "As the project designer, and not the project owner or excavator, we were not aware of the incident until contacted by the PUC regarding this Alleged Violation Report. The preliminary and final PA One Call responses provided to us identified the main utility facilities within the public right-of-way. The information available through those responses did not identify sewer service laterals. Based on information subsequently provided to us, the alleged damage involved a sewer service lateral that was struck during excavation." Conclusion: Designer stated that they do not provide designs for the location of sewer laterals. Image shows that the damage occurred in the middle of the homeowner's lawn. Images show that the line was only marked to the curb and there are no marks near the damage site. "Common Ground Alliance 4.21 Service Lines 34 Practice Statement: A service line is marked in response to a locate request to the operator who uses the service line to pursue a business that derives revenue by providing a product or service to an end-use customer via the service line. A service line is marked in response to a locate request to a governmental entity that provides a product or service to an end-use customer via the service line. Practice Description: A service line is a type of underground facility that is connected to a main facility. The service line is used by the following entities: An operator who provides a product or service within a right-of-way, an easement, or an allowed access to or through private property while pursuing a business that generates revenue by providing a product or service to an end-use customer (other than another operator of like kind or themselves)	Section 2(5)(v.2) 3rd Offense $1,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		A governmental entity that provides a product or service via that service line. The operator or the governmental entity locates and marks these service lines within the bounds of the locate request up to either 1) the point of their operational responsibility, 2) the point the service line enters a building, or 3) where the access to locate the line terminates, as designated by the prevailing law. " Ticket 2026091885: Comcast responded late. Verizon failed to respond. Recommended violations, penalties, and education: Facility Owner: Aqua Section 9 – Failed to make best efforts to comply with Common Ground Alliance Best Practices. Edition 22.0 CGA 4.21 Service Lines -PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). Excavator: Danella Power Services Section 5(11.2) – When using trenchless technology, Excavator failed to utilize at a minimum, the best practices published by the Common Ground Alliance. -PUC compliance education is required for the excavators working onsite of this excavation or their replacements Project Owner: PECO Section 6.1(1) – Failed to utilize sufficient quality levels of subsurface utility engineering or other similar techniques to properly determine the existence and positions of underground facilities when designing known complex projects having an estimated cost of ($400,000) or more. Designer did not identify sewer laterals. -PUC compliance education is required. Designer: Mastec Advance Technologies / Mastec Professional Services Section 4(4.1) - Failed to depict lines or facilities with the appropriate quality levels based on the complexity of the design and construction activities obtained through the SUE process in the planning and design phases in accordance with the American Society of Civil Engineers (ASCE) most recently published standard CI/ASCE 38. Section 4(4) – Failed to prepare construction drawings to avoid damage to and minimize interference with facilities in the construction area. -PUC compliance education is required for the designer(s) who worked on this project or their replacement(s). Facility Owner - Verizon Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. 20260981885	

Case Number	Stakeholders	Summary	Violations & Recommendation
		-PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). Facility Owner - Comcast Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. 20260981885 -PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).	
64417	**Facility Owner:** Comcast **Contractor/Excavator:** Ian Jonas Plumber **Other:** PHILADELPHIA WATER DEPARTMENT **Other:** Verizon	On 4/29/2026 9:00:00 AM at 9772 E ROOSEVELT BLVD, PHILADELPHIA CITY, PHILADELPHIA Incident occurred on 4/29/26 at 9am on 9772 East Roosevelt Boulevard, Philadelphia City, Philadelphia County. Incident: An unmarked cable line was damaged. Alleged Violation Reports (AVR): Facility Owner - Comcast's AVR states, “UG feeder was cut due to front yard being dug up for plumbing. Our cable was never marked out. Ran temp to get services restored. ticket cleared by Comcast” AVR submission date: 7/1/26 Was the AVR submitted after 30 business days? Yes. Excavator - Ian Jonas and Son Plumbing and Heating's AVR states, “we were doing a sewer job and we hit a cable wire that was not marked. when comcast came out to repair it they said they were going to bill the people who are supposed to mark it because they did not” AVR submission date: 7/20/26 Was the AVR submitted after 30 days? Yes. Project Owner - Philadelphia Water Department's AVR states, “At 9772 E Roosevelt Boulevard on 4/29/2026, Ian Jonas (Private Plumber) was performing an excavation and struck and damaged an unmarked Comcast line. The utility is in the front lawn of the property.” Conclusion: Comcast responded clear to ticket 20261101956, and the images show that the Comcast line was unmarked. Comcast failed to submit an AVR within 30 business days. Ian Jonas and Son Plumbing and Heating failed to submit an AVR within 30 days. Verizon failed to respond to ticket 20261101956. Recommended violations, penalties, and education: Facility Owner: Comcast Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a	**Comcast: $2,500.00** Section 2(5)(i) 2nd Offense $1,000.00 Section 2(10) 2nd Offense $1,500.00 **Ian Jonas Plumber: $0.00** Section 5(16) 1st Offense $0.00 **Verizon: $2,000.00** Section 2(5)(v) Subsequent $2,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		violation of this act has been committed in association with excavation or demolition work. -PUC compliance education is required for the person responsible for submitting AVR or their replacement. Excavator: Ian Jonas and Son Plumbing and Heating Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. Reduce to a warning $0. -PUC compliance education is required for the person responsible for submitting AVR or their replacement. Other Facility Owner: Verizon Section 2(5)(v) – Failed to respond to a routine One Call ticket. PUC compliance education is required.	
64511	**Facility Owner:** PECO **Contractor/Excavator:** STEVES BOBCAT SERVICES	On 4/30/2026 9:00:00 AM at 141 BARBERRY RD, UPPER GWYNEDD TWP, MONTGOMERY Incident occurred on 4/30/26 at 9am on 141 Barberry Road, Upper Gwynedd Township, Montgomery County. Incident: A mismarked PECO gas line was damaged by Steve's Bobcat Services. Alleged Violation Reports (AVR): Facility Owner - PECO's AVR states, “On 4/30/2026, Steves Bobcat Services was using a track hoe when they hit a gas service.” Excavator - Steve's Bobcat Services' AVR states, “Gas line was mismarked by 5'.” AVR notes that 911 was notified. Conclusion: Images show that the line was marked outside the tolerance zone and 911 was notified. Recommended violations, penalties, and education: Facility Owner: PECO Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. 20261143734 -PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).	**PECO: $1,500.00** Section 2(5)(i) 3rd Offense $1,500.00
64629	**Facility Owner:** Breezeline **Contractor/Excavator:** Guyer Brothers Inc. **Project Owner:** Frankstown Twp. **Designer:** LEVINE ENGINEERING LLC **Other:** VALLEY RURAL ELECTRIC COOPERATIVE INC	On 4/30/2026 4:32:00 PM at SYLVAN HEIGHTS DR, FRANKSTOWN TWP, BLAIR Valley Rural has provided details on how they are addressing the issue of accurately responding to tickets. This was a first offense. The violation has been reduced from $250 to a warning of $0. ***** The incident occurred on 4/30/2026, at approximately 4:30 PM, on Sylvan Heights Dr, in Frankstown Twp, Blair County. A cable line owned by Breezline was damaged. An emergency ticket was entered for the damage. Breezeline	**Breezeline: $1,250.00** Section 2(1)(ii)(A) 1st Offense $250.00 Section 2(5)(ix) 1st Offense $1,000.00 **Frankstown Twp.: $0.00** Section 6.1(7) 1st Offense $0.00 **VALLEY RURAL ELECTRIC COOPERATIVE INC:**

Case Number	Stakeholders	Summary	Violations & Recommendation
		responded "Clear" to the damage ticket where their line was damaged. Breezline is the facility owner. An Alleged Violation Report (AVR) was not filed as of 06/26/2026 and an AVR request was sent the same day. They submitted an AVR on 7/2/2026 that states, “No notification due to inaccurate or incomplete mapping.” Guyer Brothers is the excavator. Their AVR states, “While excavating to install a new sanitary sewer main behind 4135 Sylvan Springs Ln. we damaged an unmarked communications line owned by Breezline.” Additional information received from Guyer, “We spoke with the property owner and they informed us that it was a Breezeline line. Breezeline responded to the repair ticket and repaired the line. I don't have documentation of this.“ Frankstown Twp is the project owner. An AVR was not filed as of 06/26/2026 and an AVR request was sent the same day. An AVR was entered on 7/7/2026 that states, “Guyer Brothers was constructing a sewer line and broke a Breezeline cable when digging. Guyer Brothers contacted Breezeline directly.” Levine Engineering Llc is the designer. Their AVR states, “Contractor broke a Breezeline Cable at Manhole #3.5 area; it was not marked and about a foot deep and about 10’ passed the now Manhole #3.5 and about 325’ from the pole at the Sylvan Heights Drive Road S.R. 1003 going through the hay field. They called Breezeline around 4:30 pm and talked with them to report it.” Ticket # 20261204448 New – Damage – Emergency was entered on 4/30/2026 for the damaged line. Breezeline responded “Clear” on 5/4/2026 and stated, “BREEZELINE WAS NEVER NOTIFIED IN FIRST PLACE. STAKE CENTER HAS NO RECORD OF THIS ADDRESS EXCEPT FOR THIS DAMAGE TICKET.” Breezeline’s mapping in the PA One Call System was not accurate and did not allow them to be notified on the routine ticket for this excavation. Valley Rural Electric Cooperative’s only response was “Insufficient Information”. Violations: Facility – Breezeline: Section 2(1)(ii)(A) – Failed to provide the One Call System with the counties, municipalities, and wards in which it lines are located. Section 2(5)(ix) – Facility owner failed to respond promptly to the site of an excavation where its underground line was damaged. PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Project Owner - Frankstown Twp:	**$0.00** Section 2(5)(v.2) 1st Offense $0.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. This violation is reduced from $1000 to a warning of $0. PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement. Facility (other) - Valley Rural Electric Cooperative: Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket # 20261204448 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).	
65098	**Facility Owner:** PPL **Contractor/Excavator:** Garcia Cable Tech **Project Owner:** Mastec **Other:** Astound Broadband Powered by RCN **Other:** EMMAUS BOROUGH **Other:** Service Electric Cable TV & Communications (SECTV)	On 4/30/2026 5:21:00 PM at COLD STREAM CIR, EMMAUS BORO, LEHIGH Mastec submitted an AVR on 10/1/2026 "While drilling our sub-contractor hit an unmarked PPL Power line. An AVR was never filled out. Filling out AVR now." ***** PPL accepted the 2(5)(i) violation and disputes the 2(5)(v.2) violation. The lawful start date of Ticket# 20261125685 was 4/27/2026. PPL responded "Field Marked" on 4/29/2026. 2(5)(i) covers the violation for not marking by the lawful start date. v.2 is removed. ***** Garcia Cable Tech Submitted an AVR on 9-11-26 that states, "We were using a directional drill to install conduit for Comcast along the backside of 1070 cold stream cir, we exposed all utilities that were marked along our path. We got to our pull point then proceeded to pull back, as we were pulling back we heard an explosion sound come from the transformer and the strike alert system went off on our machine. We called in the damage to PA1call, I also notified PPL since it was clear it was electric that got damaged. There was outages on 2 buildings. Once USIC and PPL came out they realized one of the Main lines was not marked and got scraped by our bit. I'm having trouble uploading documents, I can email them if necessary." ***** The incident occurred on 4/30/2026, at approximately 5:21 PM, on Cold Stream Cir, in Emmaus Boro, Lehigh County. An electric line owned by PPL was damaged. An emergency ticket was entered for the damage. Ppl is the facility owner. Their Alleged Violation Report (AVR) states, "On Thursday, April 30th, 2026, at 5:21 PM, a non-PPL contractor (Garcia Cable Tech) was installing fiber when an unmarked primary electric line was struck. Fortunately, there were no injuries; however, power was lost for 80 customers. PPL responded by dispatching a crew to the site. Although the crew was unable to locate the damaged section of the line for immediate repairs, they successfully restored service to all customers by implementing a bypass."	**PPL: $2,000.00** Section 2(5)(i) Subsequent $2,000.00 **Garcia Cable Tech: $1,000.00** Section 5(16) 1st Offense $1,000.00 **Mastec: $1,000.00** Section 6.1(7) 1st Offense $1,000.00 **Astound Broadband Powered by RCN: $500.00** Section 2(5)(v.2) 2nd Offense $500.00 **EMMAUS BOROUGH: $250.00** Section 2(5)(v.2) 1st Offense $250.00 **Service Electric Cable TV & Communications (SECTV): $500.00** Section 2(5)(v.2) 2nd Offense $500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Garcia Cable Tech is the excavator. An AVR was not filed as of 08/05/2026 and an AVR request was sent the same day. Mastec is the project owner. An AVR was not filed as of 08/05/2026 and an AVR request was sent the same day. Ticket 20261125685 was entered for the routine excavation, with a response due date of 4/24/2026. Emmaus Borough, PPL, Service Electrical Cable, Astound Broadband all responded "Scheduled Date" on 4/24/2026. All responded "Field Marked" after the response due date. PPL provided images of the site, and marks. PPL was notified by the excavator through a damage emergency ticket placed through PA One Call. PPL's stated that the damaged electrical was not daylighted and power was restored through alternative measures to restore power to 80 customers. Violations: Facility Owner – PPL: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket# 20261125685 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Excavator – Garcia Cable Tech: Section 5(16) – Homeowner Failed to submit an Alleged Violation Report within 30 days of striking a line. PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement. Project Owner – Mastec: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement. Facility Owner (other) - EMMAUS BOROUGH Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket# 20261125685 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Facility Owner (other) - Astound Broadband Powered by RCN Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket# 20261125685 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).	

Case Number	Stakeholders	Summary	Violations & Recommendation
		Facility Owner (other) - Service Electric Cable TV & Communications (SECTV) Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket# 20261125685 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).	
64787	**Facility Owner:** PECO **Contractor/Excavator:** J&A Fence Inc **Project Owner:** Property Owner **Other:** FRANKLIN TOWNSHIP CHESTER COUNTY **Other:** Verizon	On 5/4/2026 8:45:00 AM at 115 JANINE WAY, FRANKLIN TWP, CHESTER The incident occurred on 5/4/2026, at approximately 8:45 AM, on 115 Janine Way, in Franklin Twp, Chester County. An electric line owned by PECO was damaged. An emergency ticket was entered for the damage. PECO is the facility owner. Their Alleged Violation Report (AVR) states, "On 5/4/2026, J and A Fence was using an auger when they hit an electric secondary." J And A Fence is the excavator. Their AVR states, "An unmarked electric line was hit despite digging occurring within lawful dig dates from PA One Call (original ticket #) OC #: 2026 118 3732 lawful start dates: 5/4-5/12 . Green utility box that the line came from was located on corner of property. No markings were present for any lines coming from the green utility box." Michelle White is the homeowner, and project owner. An AVR was not filed as of 07/13/2026. Ticket 20261241733 was entered for the damage on 5/4/2026. FRANKLIN TOWNSHIP CHESTER COUNTY responded "Clear" on 5/19/2026. Ticket 20261183732 was entered for the excavation with a response due date of 5/3/2026. A renotify was entered on 5/4/2026 after the damage occurred. "ATTENTION CHESTER WATER AUTHORITY YOU RESPONDED 003-FIELD MARKED 4/30/2026 1:05:33 PM. ATTENTION PECO AN EXELON COMPANY YOU RESPONDED 006-SCHEDULED MARK 5/5/2026 11:59:00 PM ON 5/3/2026 10:03:07 PM AND ATTENTION VERIZON PENNSYLVANIA LLC YOU DID NOT RESPOND 999-NO RESPONSE 5/4/2026 12:05:15AM. THE CALLER WAS INFORMED BY THE CREW ON SITE THERE ARE NO VISIBLE UTILITY MARKINGS. PLEASE RESPOND ASAP TO MARK ANY UNDERGROUND LINES AS THE WORK IS READY TO START." Verizon, and PECO did not mark their lines by the timelines required under Act 127 of 2024 Section 2(5)(i): "After receipt of a timely request from an excavator or operator who identifies the work site of excavation or demolition work he intends to perform and not later than the business day prior to the lawful start date of excavation:	**PECO: $1,500.00** Section 2(5)(i) 3rd Offense $1,500.00 Section 2(5)(v.2) 3rd Offense $0.00 **J&A Fence Inc: $250.00** Section 5(20) 1st Offense $250.00 **FRANKLIN TOWNSHIP CHESTER COUNTY: $250.00** Section 2(5)(v.2) 1st Offense $250.00 **Verizon: $1,500.00** Section 2(5)(v.2) Subsequent $1,500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		To mark, stake, locate or otherwise provide the position of the facility owner's underground lines at the work site within eighteen inches horizontally from the outside wall of such line…" The excavator lists the damage on 5/4/2026 at 8:45 AM. A renotify was entered at 9:19, and an emergency damage ticket was entered at 10:23. Upon arrival at the worksite, and checking ticket responses, the excavator did not call in a renotify when PECO did not indicate they marked their lines, and there were no physical marking at the location. An unmarked PECO line was then damaged by the excavator. Images provided support the statements in all AVRs. Violations: Excavator – J And A Fence: Section 5(20) – Excavator failed to renotify One Call of an unmarked or incorrectly marked facility upon arrival at a work site. PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements. Facility – PECO: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket 20261183732 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Facility (other) – Verizon: Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket 20261183732 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Facility (other) - FRANKLIN TOWNSHIP CHESTER COUNTY: Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket 20261241733 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).	
64967	**Facility Owner:** Columbia Gas **Contractor/Excavator:** BOBOSKY CONCRETE LLC **Project Owner:** Columbia Gas - **Designer:** Columbia Gas -	On 5/4/2026 1:35:00 PM at 815 Wampum Rd, ELLWOOD CITY BORO, LAWRENCE The incident occurred on 5/04/2026 at 815 Wampum Rd in ELLWOOD CITY BORO in LAWRENCE Co. The cap of a drip tank, on the main gas line, owned by Columbia Gas, was damaged. COLUMBIA GAS stated in their Alleged Violation Report (AVR) that, "Bobosky Concrete & Paving, performing restoration work for Columbia Gas on	**BOBOSKY CONCRETE LLC: $1,000.00** Section 5(2.1) 1st Offense $1,000.00 Section 5(16) 1st Offense $0.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Wampum Road and McKinley Avenue in Ellwood City, conducted excavation activities without an active One Call ticket. During the work, a skid-steer bucket struck the cap of a drip tank on the mainline in front of 815 Wampum Road while scraping hard surface material. There was no release of gas, and the crew immediately stopped work and contacted 911 and Columbia Gas, who responded promptly to secure the area and complete repairs. A Root Cause was conducted following the incident. The review reinforced the critical importance of placing a One Call notification prior to any excavation activity and adhering strictly to the lawful start date and time. This process ensures all facility owners have adequate time to mark their underground infrastructure, enabling crews to identify the precise location of utilities. By doing so, workers can properly respect the tolerance zone and perform all excavation activities prudently and safely." Pictures were submitted Compliance Research results: Contractor has placed One Call notifications with PA One Call in the past. Company contact record info for Bobosky Concrete LLC - Telephone: 7249717335 Address: 1043 MARR RD, PULASKI, PA 16143 Bobosky Concrete LLC and Asphalt were sent an AVR request letter on 6/23/2026. 6/03/2026 was 30 days from when the incident occurred. Bobosky Concrete LLC stated in their AVR that, "We were doing restoration for Columbia ga of pa without one call ticket on wampum rd and McKinley in Ellwood city and struck cap of dip tank on the main line at 815 Wampum rd with a skid steer bucket while escaping hard surface away. There was escape of gas, and the crew stopped work called 911 and Columbia gas immediately to make repairs." Reports were provided. Compliance Research Results: No tickets found placed by contractor related to this AVR, but contractor has placed one calls in the past. VIOLATIONS Bobosky Concrete LLC is in violation of: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or damaging a facility owner's line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. ACT127-2024 reads: To submit a report of alleged violation to the commission through the One Call System not more than 30 days after striking or damaging a facility owner's line during excavation or demolition or if the excavator believes a violation of this act had been committed in association with excavation or demolition work. The report of alleged violation shall be in a form and manner as required by the commission. Recommendations: The penalty for section 5(2.1) is applied and the $1000. Penalty for section 5(16) is reduced to a warning.	

Case Number	Stakeholders	Summary	Violations & Recommendation
64767	**Facility Owner:** EAST MARLBOROUGH TOWNSHIP **Contractor/Excavator:** CHESTER WATER AUTHORITY **Other:** PIERSON ENVIRONMENTAL SERVICES LLC	On 5/4/2026 2:55:00 PM at 514 MILL RD, EAST MARLBOROUGH TWP, CHESTER The Non-Damage violation occurred on Monday, May 4, 2026, at 514 Mill Road, in East Marlborough Township, Chester County. The non-damage violation was reported by East Marlborough Township. East Marlborough Township reported an excavator issue as provided a misrepresentation of an emergency excavation. East Marlborough Township stated in their Alleged Violation Report (AVR), "CWA submitted an emergency dig notification for a project that was planned since at least March 9, 2026 with ticket # 20260681339." On Thursday, 6/25/2026 a letter and an email was sent requesting an AVR from Chester Water Authority (CWA). CWA responded by email on Thursday, 7/2/2026. An AVR was submitted on Friday, 7/10/2026 and additional information by email (attachment- CWA additional info). CWA reported an excavator issue as provided a misrepresentation of an emergency excavation. CWA stated in their AVR, "Non- Damage Violation." Additional information submitted by email (attachment- CWA additional info): Why did Chester Water Authority place the excavation emergency ticket, 20261243928? "I placed excavation emergency ticket 20261243928 because I had scheduled the customer's service installation for 05/05/26, but I realized I had forgotten to submit the required PA One Call ticket with the three-day advance notice. Once I recognized the oversight, I placed the emergency excavation ticket so the work could proceed." The ticket, 20261243928 placed by Chester Water Authority is not considered an emergency, but excavation routine work which requires planning before the job. What planning was done by Chester Water Authority before the job? "I met with the customer several weeks before the scheduled installation to review the project and map out the work. The installation was planned in advance, including coordinating the service location and the scope of the excavation. The only oversight was that I failed to submit the required PA One Call ticket with the three-day advance notice." Violation: Chester Water Authority is in violation of section: 5(22) – Excavator provided a misrepresentation of an emergency excavation Recommendation: Penalty applied. (PUC Online Compliance Training issued on 7/14/2026, with a due date of 9/12/2026)	**CHESTER WATER AUTHORITY: $500.00** Section 5(22) 1st Offense $500.00
64844	**Facility Owner:** NATIONAL FUEL GAS **Contractor/Excavator:**	On 5/5/2026 6:23:00 PM at 10484 Krider Rd, VERNON TWP, CRAWFORD The incident occurred on 5/05/2026 at 10484 Krider Rd, in Vernon Township, Crawford Co.	**Homeowner: $0.00** Section 5(2.1) 1st Offense $0.00

Case Number	Stakeholders	Summary	Violations & Recommendation
	Homeowner **Project Owner:** HOMEOWNER	A gas line was damaged. There are no tickets associated with this incident. NATIONAL FUEL GAS stated in their Alleged Violation Report (AVR) that, "Excavator had no one call was pulling stumps out and damaged service line." 911 was not notified. Pictures were provided. PA One Call compliance provided information, there were no tickets found by the contractor related to this AVR and the contractor has not placed one calls in the past. Also, no past tickets were placed by the homeowner for the address listed Larry Wasson was sent an AVR request letter on 6/04/2026. Larry Wasson lists himself as the significant other of the homeowner and stated in his AVR that, "Removal of shrub next to house pulled out with an excavator, pulled out a shallow gasline. There was NO digging, the excavator thumb grabbed the shrub and pulled it out due to the shrub roots entangled in shallow gas line." 911 was not called. DPI Maki also requested an AVR from the homeowner and took her statement over the telephone on 8/19/2026. Additional Information On 6/11/2026 Damage Prevention Investigator (DPI) Maki returned a call to Larry Watson. Larry stated that he was pulling out a shrub at his girlfriend's house. DPI explained about the AVR and why one needs to be submitted. Larry stated that he owns an excavator and was only using to pull the shrub, he did no digging. Pictures show an electric hand tool in the hole where the shrub may have been. On 8/19/2026, DPI Maki returned a call to Cynthia the homeowner, and she confirmed that Larry is a resident at this address. She stated that they called the Gas hot line but did not call 911. She also confirmed that Larry owns his own excavator. VIOLATIONS Larry Wasson is in violation of: Section 5(2.1) – Homeowner failed to submit a location request to One Call within the correct timeframe. Recommendation: The $1000. penalty is reduced to a warning. PUC compliance education is required for the excavators working onsite of this excavation or their replacements. Section 5(8) – Homeowner failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid. Recommendation: The $1000. penalty is reduced to a warning. PUC compliance education is required for the excavators working onsite of this excavation or their replacements.	Section 5(8) 1st Offense $0.00
64661	**Facility Owner:** Columbia Gas **Contractor/Excavator:**	On 5/6/2026 10:00:00 AM at 3028 BRENTWOOD AVENUE, BRENTWOOD BORO, ALLEGHENY The incident occurred on 5/06/2026 on BRENTWOOD	**Columbia Gas: $1,500.00** Section 2(5)(i) 3rd Offense $1,500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
	W A PETRAKIS CONTRACTING COMPANY **Other:** PENNSYLVANIA AMERICAN WATER	AVENUE in BRENTWOOD BORO in Allegheny County. A 2" Aldyl-A gas service line owned by Columbia Gas was damaged. W A PETRAKIS CONTRACTING COMPANY stated in their Alleged Violation Report (AVR) that, “Crew excavating for new watermain in the roadway of Brentwood Avenue struck and damaged unmarked 2"-3" gas service servicing three residences. The 1" plastic inserted service that was marked 2 feet away was spotholed prior to excavating and located on the marks and painted to the curb box in the sidewalk for 3028 Brentwood Avenue. Fire response and Columbia repair crew notified for repair.” Pictures were provided. PENNSYLVANIA AMERICAN WATER stated in their AVR that, “Petrakis crew digging to install water main hit and damaged an unmarked Columbia Gas service line. The line that was hit was a 2" or 3" plastic line that appeared to feed 3 homes. The closest mark was 30" away and was potholed prior to excavation.” 911 was notified. Picture was provided. COLUMBIA GAS OF PA INC. stated in their AVR that,” Petrakis Contracting, working on behalf of PA American Water, was excavating to install a new water main when they struck and damaged an inaccurately marked 2" Aldyl-A gas service line. Columbia Gas records indicated that the service line was located approximately 2.5 feet from the marked position. The area had been marked, and an old steel service had been exposed by the excavator prior to the damage. Upon striking the facility, Petrakis Contracting immediately notified 911 and Columbia Gas. Columbia Gas plant and service crews responded promptly, completed all necessary repairs, and performed required safety checks." Project is listed at >$400,000. Project length is 2500. to install a NEW WATERMAIN in THE ROADWAY OF BRENTWOOD AVENUE FROM BELLECREST AVENUE TO ELROY WAY. VIOLATIONS COLUMBIA GAS OF PA INC. is in violation of: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. The line was more than 18” away from the marks in the pictures provided. This is a third offense. Recommendation: The penalties are applied. PUC compliance education was recently completed.	
64768	**Facility Owner:** UGI UTILITIES INC **Contractor/Excavator:** RealTree Landscaping LLC **Project Owner:** Homeowner	On 5/7/2026 1:30:00 PM at 296 Highland Dr, BEDFORD TWP, BEDFORD The incident occurred on Thursday, May 7, 2026, at 296 Highland Drive, in Bedford Township, Bedford County. A gas line owned by UGI Utilities was damaged. There are no tickets associated with this case.	**RealTree Landscaping LLC: $1,000.00** Section 5(2.1) 1st Offense $1,000.00 Section 5(16) 1st Offense $0.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		UGI reported excavator issues as failed to request the location and type of facility owner thru the One Call System 3-10 business days in advance of beginning the work, and failed to immediately notify 911 and the facility owner if damage results in the escape of any flammable, toxic, or corrosive gas or liquid. UGI stated in their Alleged Violation Report (AVR), "Real Tree Landscaping LLC was digging with a mini excavator at 296 Highland Dr in Bedford PA for landscaping/hardscaping purposes. The excavator failed to place a ticket with PA One Call prior to the start of excavation. As a result, they struck and damaged a 1" plastic gas service going to 296 Highland Dr. 911 was not notified." PA One Call compliance commented, RealTree Landscaping LLC has placed one call notifications in the past. UGI provided pictures showing the severed gas line. On Thursday 6/25/2026, an email and letter were sent requesting an AVR from Realtree Landscaping LLC. On Thursday 7/16/2026, a letter was sent requesting an AVR from the Homeowner. RealTree Landscaping AVR and the Homeowners summary of the incident were both completed on 7/25/2026. RealTree Landscaping, LLC reported an excavator issue as failed to request the location and type of facility owner thru the One Call System 3-10 business days in advance of beginning the work. Realtree Landscaping stated in their AVR, "RealTree Landscaping, LLC is a small family owned company. Formally owned by my husband until he passed away in 2023, I now own the business. With that being said, I am asking for mercy with this incident as I am still on a learning curve. We try to be very careful and safe, as we do not want anyone to be injured in any way, and we cannot afford costly mistakes. We also do our best to follow regulations and laws. However, we did make a poor judgement call with this incident, and we are very thankful no one was hurt. We assumed the area of this incident had already been cleared by 811 by the previous company who initially installed the waterfall. I did not file this AVR report sooner because I was unaware that I had to until the homeowner called and sent a picture of a letter. I have answered the following questions to the best of my knowledge, but will further discuss any details if necessary. The following is a summary of the event. We believe the background knowledge is important to this incident. RealTree Landscaping was hired to tear down and rebuild an existing failed waterfall built by another company. The waterfall was built with boulders that were set in a dug-out swale that was approximately four feet or more deeper than ground surface. Knowing the depth of the swale was 4 plus feet, we assumed that the area had already been cleared of underground lines by Pennsylvania One Call, a mistake we will never make	

Case Number	Stakeholders	Summary	Violations & Recommendation
		again. During this process, several employees were watching waiting for their next step, ready assist as needed. All eyes were on the boulder removal, guiding the excavator as needed. The entire process was slow and meticulous as we were working alongside another waterfall and in the midst of established landscaping. We were not haphazard. We carefully removed the boulders and waterfall liner. Then we gently smoothed the base but did not go deeper. There was no caution tape beneath the boulders or under the liner in the swale that had been dug by another company. As the bucket was sweeping across the surface of the base of the waterfall, the tooth bar caught the gas line which was covered in stone dust, snapping it in half. UGI and 911 were called immediately. The gas line was about an inch in diameter. There were no injuries and no immediate threat, so emergency personnel were not dispatched. RealTree Landscaping did not dig this swale. Because we had not seen any caution tape, we used our hands to dig into the sides of the swale that had been dug by the previous company. We were able to find caution tape that appeared to be cut/torn approximately two feet from the ground surface. Because the boulders and liner were deeper than the caution tape found in the sides of the swale, we believe when the original waterfall was built, the original builder/excavator must have removed the tape above the gas line in order to properly lay the liner and place each boulder. We have a picture showing the torn/cut tape in the side of the swale. It is circled. (attachment-RealTree pic1) When UGI arrived, they thought we had done the digging for the swale. We did not. We only removed the boulders, liner, and smoothed the base when our tooth bar caught the line. We always call Pennsylvania One call when using our excavator, but assumed this area had already been cleared by the original installer since the swale was as deep as it was. We definitely made an error in judgement and will not do it again. We received a bill from UGI in the amount of $3288.09 and paid it immediately. I completed this form to the best of my knowledge. I hope I was accurate with my responses, as I wasn't sure about everything that was being asked. We apologize for all of the inconvenience." The Homeowner stated in their letter, (attachment-Homeowner summary) "Real Tree Landscaping, LLC was hired to construct the waterfall and performed all excavation work." "During the excavation, the gas line was accidentally struck. Work stopped immediately, and UGI Utilities responded promptly to the property to repair the damaged line. The UGI representative in charge was extremely helpful and reassuring throughout the incident. He advised us that, as the homeowners, we were not responsible for the utility strike and that responsibility for the incident rested with the excavation contractor."	

Case Number	Stakeholders	Summary	Violations & Recommendation
		Violations: Real Tree Landscaping LLC is in violation of sections: 5(2.1) – Excavator failed to submit a location request to identify the location and type of facility owner lines at each work site by notifying the facility owner through the One Call System. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: Penalties applied, but for section 5(16) zero penalty but keep the violation. PUC Online Compliance Training is required for the Excavator(s) working onsite at this excavation, or their replacements	
64795	**Facility Owner:** National Fuel Gas Distribution **Contractor/Excavator:** EAGLEWAY COMMUNICATIONS LLC **Project Owner:** Velocity Network Communications Inc **Other:** Millcreek Township **Other:** Verizon North, LLC	On 5/8/2026 3:00:00 PM at W GORE RD, MILLCREEK TWP, ERIE The incident occurred on 5/8/2026, at approximately 3:00 PM, on W Gore Rd, in Millcreek Twp, Erie County. A gas line owned by National Fuel Gas was damaged. An emergency ticket was entered for the damage. National Fuel Gas is the facility owner. Their Alleged Violation Report (AVR) states, "Contractor vacced down on NFG mark and did not expose service line, contractor assumed that their depth was okay and continued with their boring operation, contractor struck and damaged an NFG service line, contractor failed to renotify after becoming aware of the possibility of an incorrectly marked facility within their work area." Eagleway Communications LLC is the excavator. Their AVR states, "During directional drilling operations, an underground gas facility was damaged. After exposing the facility and taking field measurements, it was determined that the gas line was located approximately 3 feet from the marked location, which exceeds the 18-inch tolerance zone required under PA One Call. Photos and measurements were taken onsite documenting the discrepancy between the marked alignment and the actual facility location. Field measurements taken after exposure showed the gas facility was approximately 3 feet from the marked alignment, exceeding the allowable 18-inch tolerance zone under PA One Call requirements. Paint marks were visible onsite at the time of excavation. Photos and measurements were documented" Velocity Net Communications Inc is the project owner. Their AVR states, "During directional drilling operations the sub contractor that works for Velocity Net Communications struck and damaged a underground gas line. After exposing the damaged gas line it was determined that the marks were off by approximately 3 ft. Pictures of the damage and markings being off will be attached to this." Common Ground Alliance Best Practices 5.21 Mismarked Facilities states: "The excavator notifies the facility owner/ operator directly or through the 811 center if an underground facility is not found where one	**National Fuel Gas Distribution: $1,250.00** Section 2(5)(i) 2nd Offense $1,000.00 Section 2(5)(v.2) 1st Offense $250.00 **EAGLEWAY COMMUNICATIONS LLC: $250.00** Section 9 1st Offense $250.00 **Millcreek Township: $250.00** Section 2(5)(v.2) 1st Offense $250.00 **Verizon North, LLC: $500.00** Section 2(5)(v.2) 2nd Offense $500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		has been marked or if an unmarked underground facility is found. Following this notification, the excavator may continue work if the excavation can be performed without damaging the facility, unless specified otherwise in state/provincial law." Images provided show the site, excavation, equipment, marks, and damaged line. Statements indicate the excavator attempted to locate the marked gas line but did not find it within the tolerance zone. No notification was made to the facility of the mismarked line. Excavation continued and an unmarked, and unexposed, gas line was damaged. Ticket # 20261214252 New – Excavation – Routine had a response due date of 5/5/2026. Millcreek Township responded "Field Marked" on 5/6/2026, National Fuel Gas responded "Conflict" on 5/5/2026 and "Field Marked" on 5/7/2026. Verizon North responded "Field Marked" on 5/8/2026. Violations: Facility Owner – National Fuel Gas: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket # 20261214252 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Excavator - Eagleway Communications: Section 9 – Failed to make best efforts to comply with Common Ground Alliance Best Practices. CGA Version 22 - 5.21 Mismarked Facilities PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements. Facility (other) - Millcreek Township: Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket # 20261214252 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Facility (other) - Verizon North: Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket # 20261214252 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).	
64806	**Facility Owner:** AQUA PENNSYLVANIA INC **Contractor/Excavator:** MOR CONSTRUCTION **Project Owner:** BIRMINGHAM TOWNSHIP	On 5/11/2026 10:52:00 AM at KNOLLS RD, BIRMINGHAM TWP, CHESTER The Non-Damage violation occurred on Monday, May 11, 2026, on Knolls Road, Birmingham Township, Chester County The Non-Damage violation was reported by Aqua PA Inc.	**MOR CONSTRUCTION: $500.00** Section 5(3) 1st Offense $500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
	Other: BUCKS COUNTY WATER AND SEWER AUTHORITY	Aqua reported an excavator issue as failed to request the location and type of facility owner thru the One Call System 3-10 business days in advance of beginning the work, or for a complex project. Aqua stated in their Alleged Violation Report (AVR), "Excavator failed to create a Complex Project Ticket and hold a pre-construction meeting prior to placing 16 tickets for storm water replacement" On Wednesday, 7/15/2026 an email and letter were sent requesting an AVR from MOR Construction. Their AVR was submitted on 7/28/2026. MOR Construction reported an excavator issue as failed to take reasonable steps to work with facility owners when working at multiple work sites over a large area including scheduling a preconstruction meeting or create a complex project. Bucks County Water and Sewer Authority stated in their AVR, "AVR was reported for an unknown utility on Knolls Road. BCWSA was not made aware of any hit to their utilities, and all related tickets were field marked so we should have no involvement. BCWSA crews marked our sanitary sewer mains on all the tickets. No Emergency ticket was provided for damage so unable to give more information, but I was never made aware of any involvement on our part" For all the routine tickets: Response Due Date--[13-May-26], Type of Work--[REPLACE STORM SEWER PIPE], Lawful Start Dates--[14-May-26] thru [26-May-26], Scheduled Excavation Date--[14-May-26], Dig Time--[0700]. (attachment- MOR CONSTRUCTION BIRMINGHAM TWP) Aqua responded- requested a meeting on 5/12/26 20261312054- 5/11/26 at 1051 20261312092- 5/11/26 at 1056 20261312126- 5/11/26 at 1100 20261312165- 5/11/26 at 1103 20261312197- 5/11/26 at 1107 20261312247- 5/11/26 at 1112 20261312274- 5/11/26 at 1116 20261312314- 5/11/26 at 1121 20261312339- 5/11/26 at 1125 20261312508- 5/11/26 at 1144 20261312531- 5/11/26 at 1147 20261312555- 5/11/26 at 1150 20261312574- 5/11/26 at 1152 20261312601- 5/11/26 at 1156 20261312628- 5/11/26 at 1159 20261312651- 5/11/26 at 1203 The Underground Utility Line Protection Law (UULPL) aka PA One Call Law, ACT 127, Responsibilities Of The Excavator, Section 5(3) states: In a complex project or if an excavator intends to perform work at multiple work sites or over a large area, to take reasonable steps to work with facility owners, including scheduling and	

Case Number	Stakeholders	Summary	Violations & Recommendation
		conducting a preconstruction meeting, so that they may locate their facilities at a time reasonably in advance of the actual start of excavation or demolition work for each phase of the work. Violation: MOR Construction is in violation of sections: 5(3) – Excavator failed to hold a preconstruction meeting prior to beginning a complex project. Recommendation: Penalty applied and PUC Online Compliance Training is required for the Excavator(s) working onsite at this excavation, or their replacements.	
64828	**Facility Owner:** UGI **Contractor/Excavator:** Leeward Construction, Inc. **Project Owner:** Pennsylvania American Water (PAWC)	On 5/12/2026 9:00:00 AM at NEWTON RD, SCRANTON CITY, LACKAWANNA The incident occurred on 5/12/2026, at approximately 9:10 AM, on Newton Rd, in Scranton City, Lackawanna County. A gas line owned by UGI was damaged due to lack of support and protection of the line after the line was exposed. UGI is the facility owner. Their Alleged Violation Report (AVR) states, “Excavator had gas facility exposed. Side wall of trench collapsed and damaged gas facility.” Leeward Construction is the excavator. Their AVR states, “On May 12, 2026 at approximately 9:10am, the crew had backfilled the prior stick of water main and was continuing the trench excavation in order to install the next stick of water main in front of 602 Newton Rd. Knowing there was a marked looped gas service, they utilized an air knife to expose the service. They identified the gas service tap, the service to the curb valve and the entirety of the looped service. They then continued excavating for the water main installation as the gas service was completely exposed. While digging, a portion of the excavation directly opposite of the curb valve riser broke off and fell into the excavation covering the previously exposed service and pushing the curb valve against the wall of the excavation causing a crack on the back side of the curb valve. At no time did the excavator cause damage to the buried facility.” Pennsylvania American Water is the project owner and designer. Their AVR states, “Leeward Construction Inc. was installing new 8" DICL water main on Newton Rd. As they were approaching the Fawnwood Dr. intersections,They excavated up to a tolerance zone and then exposed the service and the loop with an air knife until the tolerance zone on the other side before continuing to dig. While digging on the other side was going on, part of the trench sidewall in front of the exposed service fell in and pinched the service shutoff. Work was stopped immediately and crew was removed from the area of the gas leak. 911 (fire department) was called at approximately 9:06am and on scene at approximately 9:30 and UGI Utilities Co. had service pinched off shortly there after. Repairs were made by	**UGI: $1,000.00** Section 2(5)(v.2) 3rd Offense $1,000.00 **Leeward Construction, Inc.: $500.00** Section 5(6)(ii) 1st Offense $500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		UGI to the service before work resumed. Service struck was to 602 Newton Rd." Ticket #20261104117 New – Excavation – Routine was entered for the excavation with a response due date of 4/22/2026. UGI responded on 4/22/2026 with a scheduled mark date of 4/27/2026, and "Field Marked" on 4/24/2026. Act 127 of 2024 section 2(5)(i) - "After receipt of a timely request from an excavator or operator who identifies the work site of excavation or demolition work he intends to perform and not later than the business day prior to the lawful start date of excavation: To mark, stake, locate or otherwise provide the position of the facility owner's underground lines at the work site within eighteen inches horizontally from the outside wall of such line…" Images provided show the site, marks, excavation, and damaged line. The images support the AVR statements that the gas line was exposed and then later damaged due to lack of support and protection for a known line. Act 127 of 2024, section 5(6)(ii) - It shall be the duty of each excavator who intends to perform excavation or demolition work within this Commonwealth: After consulting with a facility owner, provide such support and mechanical protection for known facility owner's lines at the construction work site during the excavation or demolition work, including during backfilling operations, as may be reasonably necessary for the protection of such lines. Violations: Excavator – Leeward Construction: Section 5(6)(ii) – Excavator failed to provide support and mechanical protection for known facility owner's lines at the construction work site. PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements. Facility owner – UGI: Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket #20261104117 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).	
66251	**Facility Owner:** UGI Utilities Inc **Contractor/Excavator:** KLASE LANDSCAPE CONTRACTORS **Project Owner:** PROPERTY OWNER **Other:** LYONS BOROUGH MUNICIPAL AUTHORITY	On 5/12/2026 11:20:00 AM at 131 Portia Blvd, MAXATAWNY TWP, BERKS LYONS BOROUGH MUNICIPAL AUTHORITY - disputing. This is a first-time offense. The Section 2(5)(v) $500. penalty is reduced to a warning. On 10/16/2026, Lyons withdrew their dispute. ***** The incident occurred on 5/12/2026 at 131 Portia Blvd, in MAXATAWNY TWP, in BERKS Co.	**KLASE LANDSCAPE CONTRACTORS: $500.00** Section 5(2.1) 1st Offense $500.00 **LYONS BOROUGH MUNICIPAL AUTHORITY: $0.00**

Case Number	Stakeholders	Summary	Violations & Recommendation
		*No damage Excavation took place without a valid PAOneCall ticket. UGI UTILITIES INC stated in their AVR that, "Excavator utilizing mechanized equipment, excavating without a valid PAOC". Pictures were provided. Compliance Research Results: No tickets found placed by contractor related to this AVR. However, contractor has placed one calls in the past. Homeowner was sent an AVR request letter on 7/23/2026. Karen called in on 9/03/2026 asking about this incident stated that Klase Landscape Contractor was planting trees on their property, but that there was no damage. Tall Timbers Nursery Landscape was sent an AVR request letter on 7/23/2026. On 7/24/2026, DPI returned a call to Kevin from Klase Landscape Contractors, who stated that he is the owner of both Tall Timbers Landscape, which sells the landscaping items and KLASE LANDSCAPE CONTRACTORS, who were planting trees on 5/07/2026. VIOLATIONS: KLASE LANDSCAPE CONTRACTORS is in violation of: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Recommendation: the $1000. Penalty is reduced by half to be $500. PUC compliance education is required for the excavators working onsite of this excavation or their replacements. LYONS BOROUGH MUNICIPAL AUTHORITY is in violation of: Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket 20261322422 was submitted by Klase landscaping Contractors on 5/12/2026, with a response due by 5/14/2026. LYONS BOROUGH MUNICIPAL AUTHORITY never responded. Recommendation: The $500 penalty is reduced to a warning. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).	Section 2(5)(v) 1st Offense $0.00
64988	**Facility Owner:** National Fuel Gas Distribution **Contractor/Excavator:** Brandon C Kennedy Construction & Excavating **Project Owner:** J.C. Ziccardi Builders	<u>On 5/13/2026 12:40:00 AM at 12565 VENETIAN LN, SUMMIT TWP, CRAWFORD</u> NFG provided documentation showing the excavator agreed to NFG marking after the lawful start date. Violation is removed. ZICCARDI BUILDERS submitted an AVR on 8/6/2026. Their 6.1(7)Violation is reduced to a warning. ***** The incident occurred on 5/12/2026, at approximately 12:40 PM, on 12565 Venetian Ln, in Summit Twp, Crawford County. A gas line owned by National Fuel Gas was damaged. 911 was not contacted.	**National Fuel Gas Distribution: $0.00** **Brandon C Kennedy Construction & Excavating: $1,500.00** Section 5(4) 1st Offense $500.00 Section 5(8) 1st Offense $1,000.00 **J.C. Ziccardi Builders:**

Case Number	Stakeholders	Summary	Violations & Recommendation
		National Fuel Gas is the facility owner. Their Alleged Violation Report (AVR) states, "excavator failed to use prudent digging techniques within the tolerance zone and damaged a properly marked NFG service line". Brandon C Kennedy Construction & Excavating is the excavator. Their AVR states, "Hit gas service line while excavating for electrical service. Called NFG service rep. He arrived on scene within minutes. Line was repaired by NFG. Work continued on site without further incident.". ZICCARDI BUILDERS is the project owner listed on the routine ticket for this excavation. An AVR was not filed as of 08/05/2026. An AVR request was sent the same day. Ticket #20261265217 was entered for the excavation with a response due date of 5/8/2026. National Fuel Gas responded "Conflict" on 5/7/2026 and "Field Marked" on 5/12/2026. Images provided show the site, marks, damaged line, and excavation equipment. Mechanized equipment was used in the tolerance zone and a gas line within the tolerance zone of yellow marks was damaged. Violations: Facility Owner – National Fuel Gas: Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Excavator – Brandon C Kennedy Construction & Excavating: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements. Project Owner - ZICCARDI BUILDERS: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement.	**$0.00** Section 6.1(7) 1st Offense $0.00
65284	**Facility Owner:** MET-ED / FIRSTENERGY **Contractor/Excavator:** HOME RAZOR **Project Owner:** ABC HOME SALES	On 5/13/2026 8:00:00 AM at 2001 Red Bank Road, NEWBERRY TWP, YORK The incident occurred on Wednesday, May 13, 2026 at 2001 Red Bank Road, in Newberry Township, York County.	**HOME RAZOR: $1,500.00** Section 5(16) 1st Offense $500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		An electric line owned by Met-Ed/FirstEnergy was damaged by Home Razor. Met-Ed reported an excavator issue as failed to request the location and type of facility owner thru the One Call System 3-10 business days in advance of beginning the work Met-Ed stated in their Alleged Violation Report (AVR), "On May 13, 2026, Met-Ed was notified of an outage at 2001 Red Bank Road, Newberry Township, York County, Pennsylvania. USIC, Met-Ed's Contract Locator, investigated and determined that Home Razors, "Excavator," damaged an underground electric service line. The root cause of the damage was the Excavator failed to request the location and type of facility owner through the One Call System." Met-Ed provided pictures showing the augered holes and one showing the electrical meter base. Home Razor provided a video showing during augering an electrical was damaged and explaining how the electrical line is missed marked. Home Razor placed a routine ticket, 20260753737, on 3/16/2026, with Lawful Start Dates of [23-Mar-26] thru [30-Mar-26], Duration of [2-3 DAYS], and Type of Work was [INSTALL MOBILE HOMES]. Remarks-[WILL BE INSTALLING PIERS FOR THE MOBILE HOMES. ALSO WILL INSTALL ELECTRICAL FROM THE METER BASE.] Met-Ed/FirstEnergy responded as field marked. Home Razor placed a damage ticket, 20261332297, on 5/13/2026, at 11:15am. On Wednesday, 7/22/2026, an email and letter were sent requesting an AVR from Home Razor. Home Razor responded the same day by email stating, "I apologize for the delay; I had sent the last one to the guys on the ground to take care of. I will put it together and have my boss review and add anything I missed before sending. I was not on site that day, but he was." On Monday, 8/10/2026, Home Razor sent an email attaching the letter requesting an AVR, a video and the answers to the questions. Home Razor was sent a reply the same day requesting to submit an AVR through PA One Call's website, as instructed in the attach letter, Notice of Pending AVR, and attach all related pictures and documents. Home Razor did not submit their AVR, but responded by email with an attachment, answered the following questions: *Was the line marked within the tolerance zone? Yes, the lines were marked, and we were not near the marked lines. *Was the facility owner notified of the damaged line? Was 911 notified? Owners were notified. 911 was not	Section 5(2.1) 1st Offense $1,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		notified, as there was nothing that warranted 911that occurred. *Did the facility owner respond to repair the line? Yes, the power company came to repair the break. *Did the project have multiple work sites? 5 lots throughout the mobile home community *Home Razors placed a routine ticket, 20260753737, on 3/16/2026 with lawful start dates of 3/23/2026 – 3/30/2026, and duration of 2 -3 days. Did the excavation job actual start on time, and/or did the job take longer than expected? Please explain any delays and longer duration? The job was delayed due to scheduling conflicts and equipment rental. The job did start on 3/30/2026. *What planning did Home Razors do before the excavation job? We marked out the home placement to have a reference where the inground piers would need to be placed along with staking out the lot for the home placement. *Why didn't Home Razors place a ticket(s) to have the Facility Owners remark their lines? Lines that were marked were not close enough to present a hazard/obstacle for where we would be working below grade. *Was Home Razors using mechanized equipment within the tolerance zone when the damage occurred? If so, what type of mechanized equipment was used? A skid steer with an auger for drilling the holes for concrete piers. Why didn't Home Razors submit an Alleged Violation Report (AVR), within 30 days from when the electric line was hit and damaged, through the PA One Call website? It fell through the cracks. I shared it with the team member that was on site and failed to follow up on it. *Summarize what led to the hit and damaged electric line and if possible, provide pictures. We had finished up with concrete removal and rough grading for the home site. Completed the layout for the pier locations. Once the layout was completed the auger was placed on the skid steer and we proceeded to start drilling holes to be inspected before concrete. We hit the line for the first time, 30' from marks. Second strike was 12' from any marks. All marked lines were minimum 6' outside the digging. Violations: *Home Razor is in violation of sections: 5(2.1) – Excavator failed to submit a location request to identify the location and type of facility owner lines at each work site by notifying the facility owner through the One Call System.	

Case Number	Stakeholders	Summary	Violations & Recommendation
		5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: Penalty applied with 50% reduction ($1,000 to $500) Because word document summarizing the incident was provided, and PUC Online Compliance Training is required for the Excavator(s) working onsite at this excavation, or their replacements.	
64872	**Facility Owner:** PEOPLES NATURAL GAS COMPANY LLC **Contractor/Excavator:** LIBERTY FUEL AND SUPPLY	On 5/13/2026 1:30:00 PM at 1304 TELL ST, PITTSBURGH CITY, ALLEGHENY LIBERTY FUEL AND SUPPLY - 5(16) is reduced from $1000 to a warning of $0. 5(17) is withdrawn. 5(8) is withdrawn. on 10/16/2026 an email from Peoples Gas verified that Liberty did notify 911. Liberty sent an email on 10/16/2026 that they agree. ***** The incident occurred on 5/13/2026 at 1304 Tell St. in Pittsburgh City, in Allegheny Co. A gas line was damaged. PEOPLES NATURAL GAS COMPANY LLC, the facility owner, stated in their Alleged Violation Report (AVR) that, “LIBERTY FUEL AND SUPPLY working to do road restoration struck and damaged a Peoples Gas 6in steel mainline working without a locate request.” 911 was not notified. Picture was provided. On 8/25/2026 DPI Maki sent an email to Peoples Gas asking for more pictures or if Liberty Fuel and Supply were billed and paid for the damages at this location. Compliance research results: Contractor has placed One Call notifications with PA One Call in the past. Liberty Fuel and Supply. On 8/25/2025 DPI Maki asked Peoples Gas if a payment was made to Peoples for the damage. On 8/25/2026 Peoples Gas responded that, "Accounting just replied stating the invoice was paid on 7/30/2026 by Liberty Fuel and Supply". LIBERTY FUEL AND SUPPLY, the excavator, was sent an AVR request letter on 6/04/2026. No AVR has been received. No communication has been made. VIOLATIONS: LIBERTY FUEL AND SUPPLY are in violation of section: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or damaging a facility owner’s line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. An AVR request letter was sent on 6/04/2026. No AVR has been received. No communication has been made.	**LIBERTY FUEL AND SUPPLY: $1,000.00** Section 5(2.1) 1st Offense $1,000.00 Section 5(16) 1st Offense $0.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within 30 days of the receipt of the request. No questions written in the AVR request letter have been answered. Recommendation: The penalties are applied. PUC compliance education is required for the excavators working onsite of this excavation or their replacements.	
65046	**Facility Owner:** PECO AN EXELON COMPANY **Contractor/Excavator:** ROAD CON **Project Owner:** PENNDOT **Designer:** GANNETT FLEMING HARRISBURG PA **Other:** CMC ENGINEERING	On 5/14/2026 10:30:00 AM at 11 E. RIDLEY AVE, RIDLEY PARK BORO, DELAWARE The incident occurred on Thursday, May 14, 2026, at 11 E. Ridley Avenue, in Ridley Park Borough, Delaware County. A gas line owned by PECO and Exelon Company was damaged by Road Con. PECO reported an excavator issue as failed to use prudent techniques in the tolerance zone. PECO stated in their Alleged Violation Report (AVR), "On 5/14/2026, Road Con was using an excavator when they damaged a gas service." "USIC was notified of a hit gas line at 11 E Ridley Ave in Ridley Park Borough, Delaware County, PA. The investigation determined that the contractor ROAD CON was using an excavator under expired ticket# 20253032764 when they hit an accurately marked Exelon 1" plastic gas service. An email: "This one needs to show that it was marked accurately. We need to have notes in there that the contractor damaged the same service previously, and they haven't called in any updates or more current tickets." On Wednesday, 7/22/2026, emails and letters were sent to Road Con, and the project owner; PennDOT. Road Con reported an excavator issue as failed to exercise due care and take all reasonable steps necessary to avoid. Road Con stated in their AVR, "While excavating for pavement base drain. The gas service was pulled up with the geotextile fabric beneath the subbase. Called PECO to repair the service." CMC Engineering; representing PennDOT and Consultant Inspector, reported a facility owner issue as failure to locate point of connection to facility lines. CMC Engineering stated in their AVR, "The prime contractor, Road Con Inc, was on-site at PennDOT project 15306 SR2031 Sellers Ave over AMTRAK on E Ridley Ave to install pavement base drain. Crew utilized a backhoe to slowly dig for the the installation of the base drain and a gas service was encountered. The service was unknown at that location." Gannett Fleming stated in their AVR, "While contractor was excavating for pavement base drain, gas service was pulled up with the geotextile fabric beneath subbase." 20253032764- Routine ticket was placed on 10/30/2025, lawful start dates 11/4/2025 – 11/14/2025, and for a duration of 8 months.	**ROAD CON: $1,500.00** Section 5(4) 1st Offense $500.00 Section 5(16) 1st Offense $1,000.00 **PENNDOT: $1,000.00** Section 6.1(7) 1st Offense $1,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		PECO responded to on 10/31/2025 as field marked and pictures were taken of the locates (attachment- PECO locate pics 20253032764). There were no additional ticket notifications placed by Road Con, requesting remarks of the facilities. The Underground Utility Line Protection Law (UULPL) aka PA One Call Law, ACT 127, Responsibilities Of The Excavator, Section 5(16) states: To submit a report of an alleged violation to the commission through the One Call System not more than thirty days after striking or damaging a facility owner's line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. The report of an alleged violation shall be in a form and manner as required by the commission. The Underground Utility Line Protection Law (UULPL) aka PA One Call Law, ACT 127, Responsibilities of The Project Owner, Section 6.1(7) states: To submit a report of alleged violation to the commission through the One Call System not more than thirty days after striking or damaging a facility owner's line during excavation or demolition work activities, after a project owner's contracted excavator strikes or damages a facility owner's line during excavation or demolition activities or if the project owner believes a violation of this act has been committed in association with excavation or demolition. The report of alleged violation shall be in a form and manner as required by the commission. Violations: *Road Con is in violation of sections: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: Penalties applied and PUC Online Compliance Training is required for the Excavator(s) working onsite at this excavation, or their replacements. *PennDOT is in violation of section: 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Recommendation: Penalty applied and PUC Online Compliance Training is required for the Person responsible for submitting AVRs, or their replacement.	
64930	**Facility Owner:** Findlay Township Municipal Authority **Contractor/Excavator:** Mele & Mele & Sons **Project Owner:** Pennsylvania Department of Transportation (PennDOT) **Designer:** Pennsylvania Department of Transportation (PennDOT)	<u>On 5/15/2026 11:00:00 AM at Montour Run Rd., Moon, ALLEGHENY</u> The incident occurred on 5/15/2026, at approximately 11:00 AM, on Montour Run Rd., in Findlay Twp, Allegheny County. A water line owned by Findlay Township Municipal Authority was damaged. Findlay Township Municipal Authority is the facility owner. Their Alleged Violation Report (AVR) states, “On May 15 2026 around 11:30 am our water line was hit by Mele ,I did have all our air releases mark .I	**Findlay Township Municipal Authority: $500.00** Section 2(5)(i) 1st Offense $500.00 **Comcast: $1,000.00** Section 2(5)(v.2) 3rd Offense $1,000.00 **Moon Township: $500.00** Section 2(5)(v) 1st Offense

Case Number	Stakeholders	Summary	Violations & Recommendation
	- Placeholder **Other:** Comcast **Other:** Moon Township **Other:** Verizon PA LLC	thought that was all they needed and gave my business card to several people from there company to call if they needed any other marks .Unfortunately that didn't happen. Our crew then proceeded with the repair.". Mele Mele Sons is the excavator. Their AVR states, "Waterline was not marked. upon demolition of inlet box waterline was struck." Penndot is the project owner and designer. Their AVR states, "While performing excavation to install the 18" Thermal Plastic Pipe at the cross-pipe work where the station 125+80 RT located. Mele & Mele Contractor hit an existing 16 inches water ductile iron pipe and this 16" water pipe was not marked out during the PA One Call. The Findlay Township Municipal Authority (FTMA) were notified around 11AM on Friday May 15th, 2026, and the existing line was replaced by using the two 16" couple and C-900 pipe (thermal plastic type). This Friday afternoon, the FTMA performed all the pipe repairs on Montour Run Rd, Eastbound at station 125+80 RT of the SR 3072 A11." Ticket 20261140997 had a response due date of 4/28/2026. Verizon responded "Clear" on 5/18/2026. Ticket 20261173492 had a response due date of 4/29/2026. Verizon responded "Clear" on 5/18/2026. Ticket 20261173491 had a response due date of 4/29/2026. Verizon responded "Clear" on 5/18/2026. Moon Township responded "Field Marked" on 5/11/2026. Ticket 20261173490 had a response due date of 4/29/2026. Verizon responded "Clear" on 5/18/2026. Comcast responded "Clear" on 5/1/2026. Images submitted show the site, excavation, and damaged line. There are no marks to indicate the line. Violations: Facility Owner - Findlay Township Municipal Authority: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Facility (other) – Verizon Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket 20261140997 Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket 20261173492 Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket 20261173491 Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket 20261173490 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).	$500.00 **Verizon PA LLC: $8,000.00** Section 2(5)(v) Subsequent $2,000.00 Section 2(5)(v) Subsequent $2,000.00 Section 2(5)(v) Subsequent $2,000.00 Section 2(5)(v) Subsequent $2,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Facility (other) - Moon Township Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket 20261173491 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Facility (other) - Comcast Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket 20261173490 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).	
65308	**Facility Owner:** UGI UTILITIES INC **Contractor/Excavator:** MILLER PIPELINE **Project Owner:** UGI UTILITIES INC **Other:** CAPITAL REGION WATER **Other:** COMCAST **Other:** Zayo	On 5/18/2026 12:43:00 PM at SYCAMORE ST, SWATARA TWP, DAUPHIN The incident occurred on Monday, May 18, 2026, on Sycamore Street, in Swatara Township, Dauphin County. A gas line owned by UGI Utilities Inc was damaged. Pictures were submitted showing the damaged gas line. UGI reported an excavator issue as failed to exercise due care and take all reasonable steps necessary to avoid injury to or interference with all lines. UGI stated in their Alleged Violation Report (AVR), "Miller Pipeline was working on Sycamore St in Harrisburg to install a new gas main. Their excavator was positioned over top of the ditch when a large chunk of macadam began to crack and resulted in a ditch wall collapsing causing the excavator to fall into the trench and a large chunk of macadam breaking a 1/2" copper gas service causing a release of gas. Miller Pipeline made the appropriate calls to 911 and 811. Gas service going 2201 Sycamore St was marked accurately and exposed with prudent techniques. Excavation collapsed and damaged gas service" Miller Pipeline reported an excavator issue as failed to plan the excavation or demolition work to avoid damage or minimize interference with a facility owner's facilities in a construction area. Miller Pipeline stated in their AVR, "crew was installing 12" steel gas main for UGI. Prudent techniques were used the whole time. After the trench was dug the crew attempted to install the pipe when a small portion of the trench collapsed. The crew pulled the pipe out and reassessed the trench walls. The crew attempted to clean out the portion that collapsed with the excavator, while doing so a large piece (roughly 40 feet) of the trench and blacktop fell in and severed a gas service causing a release of natural gas. The crew immediately made the area safe and called 911 and made all other notifications" 20261242256- Routine ticket placed on 5/4/2026. No response from Zayo Bandwidth Formerly PPL Telcom LLC, they responded on 5/26/2026 as clear no facilities. Violations:	**MILLER PIPELINE: $500.00** Section 5(6)(ii) 1st Offense $500.00 **Zayo: $500.00** Section 2(5)(v) 1st Offense $500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		*Miler Pipeline is in violation of section: 5(6)(ii) – Excavator failed to provide support and mechanical protection for known facility owner's lines at the construction work site. Recommendation: Penalty applied and PUC Online Compliance Training is required for the Excavator(s) working onsite at this excavation, or their replacements. *Zayo is in violation of section: 2(5)(v) – Failed to respond to a routine One Call ticket. 20261242256 Recommendation: Penalty applied and PUC Online Compliance Training is required for the Individual(s) responsible to respond to locate for this ticket, or their replacement(s).	
64972	**Facility Owner:** PPL ELECTRIC UTILITIES CORPORATION **Contractor/Excavator:** RODRIGUEZ LANDSCAPING AND CONSTRUCTION INC **Project Owner:** FRONTIER COMMUNICATIONS OF PA INC **Other:** COMCAST **Other:** DRUMORE TOWNSHIP **Other:** PROVIDENCE TOWNSHIP **Other:** VELOCITY FIBER LLC	On 5/18/2026 2:00:00 PM at 174 River Road Martic Forge, MARTIC TWP, LANCASTER The incident occurred on Monday, May 18, 2026, at 174 River Road Martic Forge, in Martic Township, Lancaster County. An electric line owned by PPL Electric Utilities was damaged. Pictures were provided showing the facility marked incorrectly. Rodriguez Landscaping and Construction, Inc reported a facility owner issue as marked incorrectly. Rodriguez Landscaping and Construction stated in their Alleged Violation Report (AVR), "During drilling operations, the alarm was activated after a power line was struck. We were 2 feet off the mark." PPL Electric reported a facility owner issue as marked incorrectly. PPL Electric stated in their AVR, "On Monday, May 18th, 2026, at 2:14 PM, Rodriguez Landscaping and Construction was installing new fiber optics for Frontier when an unmarked primary electric line was struck by their directional drill. PPL was dispatched and made repairs" Violation: PPL Electric Utilities is in violation of section: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: Penalty applied.	**PPL ELECTRIC UTILITIES CORPORATION: $500.00** Section 2(5)(i) 1st Offense $500.00
65022	**Facility Owner:** PEOPLES NATURAL GAS **Contractor/Excavator:** SWANK CONSTRUCTION **Project Owner:** PEOPLES GAS - **Designer:** PEOPLES GAS - **Other:** D M CONTRACTING **Other:** GATEWAY ENGINEERS INC **Other:** Greater Johnstown Water Authority - GJWA.	On 5/19/2026 9:46:00 AM at 747 PARKVIEW DR, WESTMONT BORO, CAMBRIA The incident occurred on 5/19/2026 at 747 PARKVIEW DR in WESTMONT BORO in CAMBRIA Co. A gas service line owned by Peoples Gas was damaged. PEOPLES NATURAL GAS COMPANY LLC stated in their second version Alleged Vioaltion Report (AVR) that, "Swank Construction was saw cutting to do restoration from a previous gas installation when they saw cut through a 1" plastic service. 1" plastic service was inserted through steel at 747 Parkview dr Johnstown. The service was 14" deep at the curb box and went slightly more shallow towards the house. Service was hit curb to meter, service was marked."	**SWANK CONSTRUCTION: $500.00** Section 5(4) 1st Offense $500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
	R D M Johnstown LLC **Other:** RDM (Resource Development and Management) JOHNSTOWN LLC	Project is listed as 3000'. Pictures and reports were provided. The damage location is listed as Johnstown. Johnstown is the address that is listed in Google. Project length is listed as 3,000', SWANK CONSTRUCTION stated in their AVR that, "Saw cut through unmarked service gas line in driveway adjacent to roadway at 747 Parkview Dr. Johnstown, PA 15905" 911 was notified. AVR's requested notifications by PAOneCAll were submitted by: Greater Johnstown Water Authority is represented by RDM Johnstown. RDM (Resource Development and Management) JOHNSTOWN LLC stated in their AVR that, "Apparently D and M Contracting hit a gas service at 747 Parkview Dr on May 19, 2026. An emergency excavation ticket was put in by Peoples Natural Gas on May 19, 2026 at 9:41 AM. Associated with this project (CPA Project ID - 13686648); Greater Johnstown Water Authority (GJWA) provided preliminary design drawings (ticket 20251614644) on June 27, 2025 and final design (ticket 20253431327) drawings on December 15, 2025to the designers. GJWA also had two representatives (Connor Bunn and John Gustkey, Jr) attend the Complex Project Meeting (Ticket 20260063148) on January 15, 2026, at 9:00 AM on-site near 800 Parkview Dr. The Routine Tickets (20260902224, 20261241120) and the Emergency Dig ticket (20261391355) were all field marked prior to any excavation within the identified work sites and before the request due dates. In addition to the tickets; GJWA also met with D and M Contracting several times during construction activities to provide additional information and verify field marks at the excavator's request. Generally, GJWA and D and M Contracting have a good working relationship and communicate well with projects within GJWA's water and sewer networks. For the damage specific to AVR2026May190047, GJWA was only involved as far as providing the required field markings and coordination with the excavator. There was a water main located near the gas line damage but was not affected. Photos of the water line location relative to the gas excavation are attached. This AVR is only being submitted at the request of PUC as GJWA may have been affected." Picture and report were provided. Case is connected by tickets to case 62518. The pictures provided by Peoples Gas, with a file info of 5/15/2026, showed the gas lines were marked. VIOLATIONS Swank Construction is in violation of: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Within the tolerance zone, the excavator shall employ prudent techniques, which may include hand-dug test holes,	

Case Number	Stakeholders	Summary	Violations & Recommendation
		vacuum excavation or similar devices to ascertain the precise position of such facilities. PUC compliance education is required for the excavators working onsite of this excavation or their replacements. Recommendation: The penalty is applied. PUC compliance education is required for the excavators working onsite of this excavation or their replacements.	
65440	**Facility Owner:** National Fuel Gas Distribution **Contractor/Excavator:** Sallot Concrete Inc **Project Owner:** Homeowner	On 5/27/2026 10:46:00 AM at 340 WEST 8 STREET, ERIE CITY, ERIE The incident occurred on 5/27/2026, at approximately 10:46 AM, on 340 West 8 Street, in Erie City, Erie County. National Fuel Gas reported that excavation occurred prior to the due date of the PA One Call Ticket. No damage occurred. National Fuel Gas is the facility owner. Their Alleged Violation Report (AVR) states, “Excavator completed work prior to lawful start date on ticket, this excavator is an extreme repeat offender of this type of behavior incident was discovered on 5/27 lawful start date on ticket was 5/29”. NFG was asked, “Do you have any additional documents that show they used mechanized equipment to excavator prior to the ticket?” and they responded with, “we do not have any photos showing mechanized equipment being used.” Sallot Concrete Inc is the excavator. An AVR request was sent on 08/06/2026. They submitted an AVR that states, “On the day it was to be marked. We arrived on the job to see if it was Marc we seen that all the utilities were marked even yellow for the gas line. We later learned that was from the work that was done earlier in the year it was not the markings that were done that day when we got there there was nothing to dig with the machine. It was already dug out. We just clean the edges up where the sod was just so we could put the forms in it was a little piece of sidewalk 5‘ x 8‘ wasn’t very big we hand dug it while we were there of the gas company showed up National Fuel I spoke to the gentleman that was marking and explain to him what we were doing. He said, that’s OK as long as your hand digging try to make sure that we don’t do things unless it’s marked. The locator indicated to us that we were fine there was no violation. We were fine then later on I get this email. I don’t understand what’s going on.” Alan Dudinsky, the homeowner, is the project owner. An AVR request was sent on 08/06/2026. No information has been provided that shows mechanical excavation occurred at this location, by this excavator. Images provided show the sidewalk was completed prior to the mark out, and start date, of the ticket. No equipment, or signs that mechanical equipment, is visible at the site. Violations: None	

Case Number	Stakeholders	Summary	Violations & Recommendation
65453	**Facility Owner:** Peoples Natural Gas **Contractor/Excavator:** Jurkus Services **Project Owner:** Keystone Hospitality - Holiday Inn	On 6/1/2026 10:01:00 PM at 250 market st, JOHNSTOWN CITY, CAMBRIA The incident occurred on 6/1/2026, at approximately 10:01 PM, on 250 Market St, in Johnstown City, Cambria County. A gas line owned by Peoples Natural Gas was damaged. The Project Owner, Holiday Inn, submitted a damage ticket 2 hours after the damage occurred. Peoples Natural Gas Company is the facility owner. Their Alleged Violation Report (AVR) states, "Jurkus services was digging at 250 market st to install an outside patio. Contractor hit a 4" plastic gas service feeding this address. Contractor did NOT place a one-call. PNG crews arrived and shut off gas. PNG crews renewed 4" plastic gas service." Jurkus Services is the excavator. An AVR was not filed as of 08/07/2026 and an AVR was requested the same day. An AVR was not entered by Jurkus Services as of the date this report was submitted. Holiday Inn - Keystone Hospitality is the project owner. An AVR was not filed as of 08/07/2026 and an AVR was requested the same day. An AVR was submitted that states, "While removing concrete from the patio, our contractor hit a gas line." PA One Call did not receive an excavation request from Jurkus Services prior to excavation, and damage, occurring. Jurkus Services has not submitted a ticket in the past with PA One Call. Holiday Inn submitted the damage ticket for the incident. Images submitted show the site, excavation, equipment, and damaged line. Peoples Natural Gas indicates that 911 was not contacted. Violations: Excavator – Jurkus Services: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner's facilities in the construction area. Section 5(7) – Failed to immediately report to the facility owner any break or leak in its lines, or any dent, gouge, groove, or other damage to such lines or to their coating or cathodic protection. Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. Section 5(23) – Excavator may not delegate their duty to submit a locate request to the One Call System to another person. The excavator shall have sole responsibility to submit each locate request to the One Call System.	**Jurkus Services: $4,750.00** Section 5(2.1) 1st Offense $1,000.00 Section 5(6)(i) 1st Offense $250.00 Section 5(7) 1st Offense $1,000.00 Section 5(8) 1st Offense $1,000.00 Section 5(23) 1st Offense $500.00 Section 5(16) 1st Offense $1,000.00 **Keystone Hospitality - Holiday Inn: $0.00** Section 6.1(7) 1st Offense $0.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement. Project Owner - Keystone Hospitality: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. This violation is reduced from $1000 to a warning of $0.	
65960	**Facility Owner:** HAMILTON TOWNSHIP MUNICIPAL AUTHORITY **Contractor/Excavator:** JD Wagoner Excavating **Project Owner:** GOLDRIDGE CONSTRUCTION	On 6/2/2026 8:00:00 AM at 1372 FRANK RD, HAMILTON TWP, FRANKLIN The incident occurred on Tuesday, June 2, 2026, at 1372 Frank Road, in Hamilton Township, Franklin County. A sewer line owned by Hamilton Township Municipal Authority was damaged by J.D. Wagoner Excavating. Hamilton Twp MA provide pictures of the damage and repaired sewer line. Hamilton Twp MA reported an excavator issue as failed to exercise due care and take all reasonable steps necessary to avoid injury to or interference with all lines. Hamilton Twp MA stated in their Alleged Violation Report (AVR), “Contractor, JD Wagoner, was excavating to install two (2) new sewer connections to HTMA's existing gravity sewer main (approximately 18' to 20' deep), for a new 4-house townhome unit. During excavation, the contractor hit the existing emergency force main (approximately 4' to 5' deep) for Pump Station No. 4. It resulted in sewage entering the trench and filling it. Contractor contacted haulers to remove the sewage (Rosy's Waste Water Removal) until the flow lessened that the repair could be made to the force main.” “On May 20, 2026, the contractor excavated to install the first two sewer laterals to the existing HTMA gravity main, which also exposed the force main at that time. The contractor successfully located the force main and supported it during that installation.” Hamilton TWP MA additional information: “A new 4-unit townhouse is being constructed, and the contractor, JD Wagoner, was performing work for the property owner to install a total of four (4) sewer laterals, one for each unit. Due to concerns with the depth of the work (approx. 20’ deep for the gravity main) and in conjunction with the existing force main, (more shallow), HTMA had an Authority Engineer representative on site while these lateral connections were being made. Work initially occurred on May 20 & May 21, 2026 to install the first two laterals for the townhouse. The contractor, JD Wagoner, had successfully located and completed the first two connections. In making the first two lateral connections, they had knowledge from that	**JD Wagoner Excavating: $1,000.00** Section 5(4) 1st Offense $500.00 Section 5(16) 1st Offense $500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		experience in regard to the force main location, depth, etc. which was also applicable to the second two lateral installations planned for June 2, 2026. I have attached a copy of the PA One Call Ticket and a picture of the sewer markings for that ticket. The Authority Engineer's representative reported that on June 2nd, he observed JD Wagoner had stopped excavation with the equipment and began hand digging as they thought they were getting close to the force main. They quit hand digging and got back in the excavator; with the first deployment of the bucket, they struck the force main at a coupling, dislodging the rubber seal and damaging the force main. Work was then rescheduled for June 8, 2026, when the additional two (2) sewer lateral installations were completed. This resulted in a sizeable sanitary sewer overflow. It was determined that there were three homes in the area whose sole water source was well water. To date, testing has indicated one well has been impacted by this incident, as test results were oA the charts for both total coliform and E coli. Initial testing of two other homes initially disclosed total coliform exceeded recommended limits; however, the test results noted it was due to a group of naturally occurring microorganisms found in soil, vegetation, and the intestines of warm-blooded animals, not as a result from this incident. Follow up retesting of these two other homes have been conducted, but results have not yet been received." On Monday, 7/13/2026 an email and letter were sent requesting an AVR from J.D. Wagoner Excavating, and their AVR was submitted the next day. On Wednesday, 7/29/2026 an email was sent requesting additional information (attached JD Wagoner-requested info) from J.D. Wagoner Excavating because a summary of the incident was not provided in the AVR. J.D. Wagoner Excavating did not respond to email. In the AVR J.D. Wagoner Excavating noted Under Excavation Work: Marked in White: Yes, Method of Excavation: Digging, Equipment Used: Backhoe/Trackhoe, Type of Excavator: Utility, Did Excavator incur down time?: Yes, How much down time?: 3+ hours, Estimated cost of down time?: $1,001-$5,000, Was a response posted to the One Call System?: No, What level of subsurface utility engineering was utilized?: B (Utility Designation), Estimated cost of the entire project: Less than $400,00, What was the length of the entire project?: 40'feet Violations: J.D. Wagoner Excavating is in violation of sections: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line.	

Case Number	Stakeholders	Summary	Violations & Recommendation
		Recommendation: Penalties applied, Penalty for 5(16) reduced by 50% (from $1,000 to $500) but keep the violation, and PUC Online Compliance Training is required for the Excavator(s) working onsite at this excavation, or their replacements.	
65640	**Facility Owner:** Peoples Natural Gas **Contractor/Excavator:** Mele and Mele and Sons **Project Owner:** Pittsburgh Water PWSA **Designer:** JMT Johnson, Mirmiran and Thompson	On 6/2/2026 10:22:00 AM at FRIENDSHIP AVE, PITTSBURGH CITY, ALLEGHENY The incident occurred on 6/2/2026, at approximately 3:25 PM, on Friendship Ave, in Pittsburgh City, Allegheny County. A gas line owned by Peoples Natural Gas was damaged. Peoples Natural Gas is the facility owner. Their Alleged Violation Report (AVR) states, “Mele and Mele and Sons working for Pittsburgh Water struck and damaged a properly marked Peoples Gas service line at 4612 Friendship while using mechanized equipment in the tolerance zone.” Mele And Mele And Son is the excavator. Their AVR states, “The crew initially performed hand excavation within the marked two-foot tolerance zone. After extensive efforts to locate the facility without success, mechanical excavation was utilized. Tooth of the bucket ripped through a 1" CTS Peoples gas service for 4612 Friendship Ave. The gas line was later discovered at a depth significantly greater than the typical installation depth, which contributed to the difficulty in locating the facility during hand excavation. The hit occurred at approximately 10:22am. At that time Mele's superintendent immediately called 911 per protocol. All work was halted at this time. At 10:42 am fire showed up and made sure the scene was safe and secure. After about ten minutes, they departed. At 10:46, Alex Binkley, The People gas inspector showed up to examine the hit, and see what was needed to fix the service. He called for a crew to fix the line, and a 1' piece of 1"CTS was cut in with 2 stabs to rectify the problem and get the customer back in gas. Hit kit was set up by Peoples Gas Rep.” Pittsburgh Water is the project owner. Their AVR states the same information as Mele and Mele’s AVR. Johnson Mirmiran And Thompson is the designer. Their AVR states, the same information as Mele and Mele’s AVR and adds, “PNG provided records do not show location of service lines. Service line approximate location and gas curb box approximate location were shown on the drawings as per the survey delineation provided to JMT.” Images submitted show the site, excavation, equipment, marks, and damaged line. The line that was damage was indicated by yellow marks seen on the sidewalk in the damage photos. PNG provided images via email that shows the mark out prior to damage. The marks are covered with pink paint in the damage photos. The images support the statements in all AVRs that the line was marked and within the tolerance zone of the marks.	**Mele and Mele and Sons: $500.00** Section 5(4) 1st Offense $500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		This case is related to case #064126, and 065945 by tickets. Violations: Excavator – Mele and Mele: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.	
65594	**Facility Owner:** PECO **Contractor/Excavator:** MID ATLANTIC HIGH REACH LLC **Project Owner:** Mastec **Other:** Verizon PA LLC	On 6/5/2026 12:15:00 AM at 713 SCENIC DR, LOWER SALFORD TWP, MONTGOMERY The incident occurred on 6/4/2026, at approximately 12:15 PM, on 713 Scenic Dr, in Lower Salford Twp, Montgomery County. An electric line owned by PECO was damaged. An emergency ticket was entered for the damage. PECO is the facility owner. Their Alleged Violation Report (AVR) states, "On 6/4/2026 Mid Atlantic High Reach LLC was using a bore machine when they damaged an electric primary." Mid Atlantic High Reach is the excavator. Their AVR states, "While we were drilling we hit an unmarked electrical line." Mastec/Comcast is the project owner listed on the tickets. Mastec was the only Project Owner reported on the excavator's AVR. An AVR was not filed as of 08/10/2026 and an AVR request letter was sent to Mastec the same day. Ticket 20261300061-000 was entered on 5/10/2026 at 934 AM with a response due date of 5/13/2026. A renotify was entered 5/15/2026 at 957 AM requesting a 2 hour contact, with the remarks, "ONSITE MARKINGS ARE INCORRECT. PLEASE RETURN TO CORRECT THE MARKINGS." PECO did not respond to the original request, and responded "Field Marked" as their first response to the ticket, and renotify ticket, on 5/15/2026 at 3:48 PM. Verizon responded to the renotify request on 5/18/2026 at 2:19 PM. Ticket # 20261480220 was an update ticket entered on 5/28/2026 due to work not starting– Verizon responded after the response due date of 6/1/2026. Images and documents submitted support the statement in the AVRs that an unmarked electrical line was damaged. A document submitted by PECO also states, "During the investigation we determined and discovered that there is new electric primary not shown on the prints". This is the line that was damaged. Violations: Facility Owner – PECO: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.	**PECO: $2,500.00** Section 2(5)(i) 3rd Offense $1,500.00 Section 2(5)(v.2) 3rd Offense $1,000.00 **Mastec: $1,000.00** Section 6.1(7) 1st Offense $1,000.00 **Verizon PA LLC: $3,000.00** Section 2(5)(v.1) Subsequent $2,000.00 Section 2(5)(v.2) 3rd Offense $1,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket 20261300061-000 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Project Owner – Mastec: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement. Facility Owner (other) - Verizon Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Ticket 20261300061-001 Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket # 20261480220 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).	
65677	**Facility Owner:** PEOPLES NATURAL GAS COMPANY LLC **Contractor/Excavator:** TRUMBULL CORPORATION **Project Owner:** Pennsylvania Turnpike Commision **Designer:** HERBERT ROWLAND AND GRUBIC INC	On 6/5/2026 8:30:00 AM at INTERSECTION OF CAMP HOLLOW & LEBANON SCHOOL RD, WEST MIFFLIN BORO, ALLEGHENY The incident occurred on Friday, June 6, 2026, at the Intersection of Camp Hollow and Lebanon School Road, in West Mifflin Borough, Allegheny County. A gas line owned by Peoples Natural Gas Company (PNG) was damaged by Trumbull Corporation. Pictures were provided showing the damaged gas line. PNG reported an excavator issue as failed to protect and preserve the markings after beginning excavation, or contact the One Call System to request the facilities be marked again. PNG stated in their Alleged Violation Report (AVR), "On 6/5/26 Trumbull Corp struck a PNG 2-inch main line at the intersection of Camp Hollow & Lebanon School Rd. Trumbull Corp was working off a one call ticket from April 2025. Trumbull Corp failed to maintain marks or renotify PNG to remark facilities in the area. Trumbull Corp saw cut directly in line with a PNG tracer box for the 2-inch plastic main line, lifted the saw and continued to saw cut past the locate box. Also present were line markers on either side with vents for a casing that ran the through the area of excavation and Trumbull Corp still failed to renotify PNG of the missing marks due to the age of the one call ticket. Trumbull Corp notified 911 of damage. PNG was notified and arrived onsite for repairs." Routine ticket, 20250854485, was placed on 3/26/2025 at 1647, duration of 2 weeks, and lawful start dates 4/7/2025 thru 4/9/2025. Damage emergency ticket, 20261662381, was placed on 6/15/2026 at 11:46pm.	**TRUMBULL CORPORATION: $500.00** Section 5(3) 1st Offense $500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Trumbull Corporation reported an excavator issue as failed to call the One Call System for a new request after removing equipment and vacating a work site for more than 2 business days unless other arrangements were made directly with the involved facility owners. Trumbull Corp. stated in their AVR, “Trumbull Corporation crews were performing grading at 1075 Camp Hollow Rd West Mifflin, Pa for the Pennsylvania Turnpike Commission. A Peoples' 2" gas line was struck with an excavator. The gas line was at an abnormally shallow depth, within the subbase of the existing roadway and no warning tape was present/encountered.” Violation: Trumbull Corporation is in violation of section: 5(3) – Excavator failed to preserve mark-outs or request a remark. Recommendation: Penalty applied and PUC Online Compliance Training is required for the Excavator(s) working onsite at this excavation, or their replacements.	
65738	**Facility Owner:** PEOPLES NATURAL GAS COMPANY LLC **Contractor/Excavator:** THOMPSON ELECTRIC, INC **Project Owner:** Penn Power-FirstEnergy	On 6/9/2026 8:58:00 AM at N BROAD ST EXT, WOLF CREEK TWP, MERCER The incident occurred on Tuesday, June 9, 2026, on N. Broad Street Ext, in Wolf Creek Township, Mercer County. A gas line owned by Peoples Natural Gas Company (PNG) was damaged by Thompson Electric. PNG provided pictures of the unmarked damage line. PNG reported a facility owner issue as marked incorrectly. PNG stated in their Alleged Violation Report (AVR), “On 6/9/2026, Thompson Electric was digging to replace existing poles when they augered through an unmarked PNG 4" PL ML. PNG crews were called and repairs were made. PNG locator cleared the ticket. thought ticket scope was away from line.” Also, PNG provided additional information, "PNG was notified by Jason with Thompson Electric calling PNG’s Operations Center to report the damage. Per the first responder, there was no 911 onsite. There was no evidence of 911 being notified because gas was leaking upon arrival of the first responder. PNG took ownership of this damage due to the locator." PNG picture, PNG-IMG_8220 shows indicator of gas lines in the area. PNG placed an Excavation Emergency ticket, 20261601110, on 6/9/2026 at 9:22M, Type of Work--[REPAIRING GAS LEAK] PNG AVR noted 911 was not called On Monday, 7/27/26 a letter and email were sent requesting an AVR from Thompson Electric. Thompson Electric did not respond to the request and no AVR was submitted. Violations: *Peoples Natural Gas Company is in violation of section:	**PEOPLES NATURAL GAS COMPANY LLC: $2,000.00** Section 2(5)(i) Subsequent $2,000.00 **THOMPSON ELECTRIC, INC: $2,250.00** Section 5(8) 1st Offense $1,000.00 Section 5(20) 1st Offense $250.00 Section 5(16) 1st Offense $1,000.00 Section 5(17) 1st Offense $0.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: Penalty applied and PUC Online Compliance Training is required for the Individual(s) responsible to respond to locate for this ticket, or their replacement(s). *Thompson Electric is in violation of sections: 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid. 5(20) – Excavator failed to renotify One Call of an unmarked or incorrectly marked facility upon arrival at a work site. PNG picture, PNG-IMG_8220 shows indicator of gas lines in the area. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. Recommendation: Penalties applied and PUC Online Compliance Training is required for the Excavator(s) working onsite at this excavation, or their replacements. For section 5(17) zero penalty but keep the violation.	
65790	**Facility Owner:** Peoples Natural Gas **Contractor/Excavator:** Weaver Plumbing **Project Owner:** S B 100 LLC **Other:** GREATER JOHNSTOWN WATER AUTHORITY	On 6/11/2026 11:00:00 AM at 75 Central Ave, JOHNSTOWN CITY, CAMBRIA The incident occurred on 6/11/2026, at approximately 11:00 AM, on Autumn Ridge Rd, in Hanover Twp, Northampton County. A gas line owned by Peoples Natural Gas was damaged. 911 was not called for this damage. Peoples Natural Gas is the facility owner. Their Alleged Violation Report (AVR) states, “Syed Bokhari placed a one-call to replace his sewer line. A new Contractor (Weaver plumbing) dug the line without making his own one-call. Weaver plumbing did not place a one-call and was digging under the owners one call. Weaver plumbing hit a mismarked 1" plastic gas line. PNG arrived on site and cut off the service line. Property was not using the gas service at the time.” Weaver Plumbing is the excavator. Their AVR states, “I was contacted to excavate so that a new sewer lateral could be installed . The installer was the person who contacted me , he informed me that the excavator that was supposed to do the work could not . I was working directly for the building owner who had made a one call for the excavation , I was not contract to install the sewer lateral . I when to the job site the day before and saw that the utilities were clearly marked . I then went down the next morning to excavate the ditch , I then dug into the Gas service line , It was clearly marked but the marks were approx . 8 feet off of the actual line . We then called the gas co . , the gas was not leaking , they couldn't shut their curb stop off and brought in a crew to dig it and cut it off .” GREATER JOHNSTOWN WATER AUTHORITY submitted an AVR after PA One Call Systems emailed	**Peoples Natural Gas: $1,000.00** Section 2(5)(i) 2nd Offense $1,000.00 **Weaver Plumbing: $1,500.00** Section 5(23) 1st Offense $500.00 Section 5(8) 1st Offense $1,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		them. Their AVR states, "I recieved an email from PUC on Monday, June 29, 2026, asking if the Greater Johnstown Water Authority was involved in an incident associated with AVR AVR2026JUNE120015; where an excavator affected a gas line. I am preparing this AVR to provide the limited involvement that the Greater Johnstown Water Authority (GJW) and Johnstown Redevelopment Authority (JRA) had with this incident. As we respond to both GJW and JRA ticket requests and provide the markings. The limited involvement included just the mark-outs and response through the PA1Call system for the associated ticket with serial number 20261533617. Included is the survey completed by Connor Bunn, the contracted locator. All photos and response for the above identified ticket were completed on June 2, 2026 around 3:00 PM. No water or sanitary utilities were affected during this work. The property owner is the project owner. Images show the site, excavation, and damage. The excavator did not have a PA One Call ticket for this location and date. Act 127 of 2024 requires each excavator to have their own ticket, "To not delegate the excavator's duty to submit a locate request to the One Call System to another person. The excavator shall have the sole responsibility to submit each locate request to the One Call System." After the damage occurred the excavator entered a ticket for this location. A ticket was previously called in by the owner of the building. These marks are seen at the site where damage occurred. The line that was damaged was not marked on this ticket. Violations: Facility Owner – Peoples Natural Gas Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Ticket 20261533617. PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Excavator – Section 5(23) – Excavator may not delegate their duty to submit a locate request to the One Call System to another person. The excavator shall have sole responsibility to submit each locate request to the One Call System Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid. PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements.	
65925	**Facility Owner:** PEOPLES NATURAL GAS COMPANY LLC	On 6/15/2026 8:05:00 AM at 2177 VANTINE ST, WILKINSBURG BORO, ALLEGHENY The incident	**FRANK J ZOTTOLA CONSTRUCTION INC: $1,000.00**

Case Number	Stakeholders	Summary	Violations & Recommendation
	Contractor/Excavator: FRANK J ZOTTOLA CONSTRUCTION INC **Project Owner:** Wilkinsburg Penn Joint Water Authority	occurred on Monday, June 15, 2026, at 2179 Vantine Street, in Wilkinsburg Borough, Allegheny County. A gas line owned by Peoples Natural Gas (PNG) was damaged by Frank J. Zottola Construction Inc. PNG reported excavator issues as: failed to request the location and type of facility owner thru the One Call System 3-10 business days in advance of beginning the work, failed to protect and preserve the markings after beginning excavation, or contact the One Call System to request the facilities be marked again, and failed to use prudent techniques in the tolerance zone. PNG stated in their Alleged Violation Report (AVR), "Frank J Zottola working for Wilkinsburg Penn Joint Water struck and damaged a Peoples Gas plastic service line. This ticket was place in November. The line was damaged in June. There are still faded yellow markings indicating underground facilities." PNG pictures were provided showing the locate mark, the faded mark, and the damaged gas line within the tolerance zone. Images were provided showing the locate marks on 11/21/2025 for Ticket 20253241064. In the damage images, the yellow mark from the 11/21/2025 mark out is faded but still visible and indicates the line that was damaged. The excavator did not have a valid ticket for the location when the line was damaged." Frank J. Zottola Construction reported a facility owner issue as marked incorrectly. Frank J. Zottola Construction stated in their AVR, "The crew was digging on the road to restore pavement that was dug up in the past for a water line replacement. The crew only digs about 12 to 14" for stone, concrete and pavement. The crew just started to take up the cold patch when the struck this gas line. The gas line was about 8 to 10" under the cold patch." Frank J. Zottola Construction called 911. Violations: *Frank J. Zottola Construction Inc. is in violation of section: 5(2.1) – Excavator failed to submit a location request to identify the location and type of facility owner lines at each work site by notifying the facility owner through the One Call System Recommendation: Penalty applied and PUC Online Compliance Training is required for the Excavator(s) working onsite at this excavation, or their replacements.	Section 5(2.1) 1st Offense $1,000.00
65930	**Facility Owner:** Peoples Natural Gas **Contractor/Excavator:** YATES ELECTRIC **Project Owner:** Aliquippa Economic Development Corporation **Other:** Aliquippa Municipal Water	On 6/16/2026 9:00:00 AM at FRANKLIN AVE, ALIQUIPPA CITY, BEAVER The incident occurred on 6/16/2026, at approximately 9:00 AM, on Franklin Ave, in Aliquippa City, Beaver County. A gas line owned by Peoples Natural Gas was damaged. Peoples Natural Gas is the facility owner. Their Alleged Violation Report (AVR) states, "On 6/16/2026, Yates	**Peoples Natural Gas: $2,000.00** Section 2(5)(i) Subsequent $2,000.00 **YATES ELECTRIC: $250.00** Section 5(6)(i) 1st Offense $250.00

Case Number	Stakeholders	Summary	Violations & Recommendation
	Authority **Other:** Verizon PA LLC	Electric was digging and augering to install new conduit and poles when they struck two PNG mainlines running parallell to each other. Yates Electric was augering for a new light pole and the auger came down between the 8" and 4" which are only approx 6-10 inches apart from each other. The 4" LP has a hole down the sidewall of the pipe and is leaking. The 8" MP has auger marks but is not leaking. Crew will be replacing approx 4 feet of 8" pla and approx 8-10 feet of 4" plastic. Both PNG ML's were accuratley marked." Yates Electric is the excavator. Their AVR was submitted 42 days after the incident. Their AVR states, "While augering a 12" hole for a 6"x6" wooden post, our bit struck a 4" gas line. We believe our pictures show that where we drilled was significantly outside of the tolerance zone of the marks that People's Gas made." Aliquippa Economic Development Corp is the project owner listed on the tickets, and Yates' AVR. An AVR was not filed as of 08/28/2026 and an AVR request letter was sent the same day. An AVR was filed on 9/2/2026 that states, "I was not there and did not witness this. Yates Electric was there and they hit a gas line that was mismarked." Ticket # 20261551585 New – Excavation – Routine was entered on 6/4/26 with a response due date of 6/8/2026. Verizon responded "Field Marked" on 6/9/2026. ALIQUIPPA MUNICIPAL WATER responded "Field Marked" on 6/15/2026. Images submitted show the site, marks, excavation, equipment and damaged lines. IMG_0034 was taken from the excavator's cab and shows the auger and hole being drilled. Excavation is shown in this image next to the yellow marks. The excavator did not attempt to day light the lines prior to beginning excavation of "INSTL CONDUIT AND POLE". Excavation was not planned to avoid damage to or minimize interference with a facility owner's facilities in the construction area. Additional images taken after the 2 gas lines are exposed for repair show the lines were not within the tolerance zone of the marks. 911 was contacted for the gas leak. No Damage ticket was entered, and Peoples Natural Gas was informed about the damage by 911. Violations: Facility Owner – Peoples Natural Gas: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Excavator – Yates Electric:	Section 5(7) 1st Offense $0.00 Section 5(16) 1st Offense $0.00 **Aliquippa Economic Development Corporation: $0.00** Section 6.1(7) 1st Offense $0.00 **Aliquippa Municipal Water Authority: $500.00** Section 2(5)(v) 1st Offense $500.00 **Verizon PA LLC: $1,500.00** Section 2(5)(v.2) Subsequent $1,500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner's facilities in the construction area. Section 5(7) – Failed to immediately report to the facility owner any break or leak in its lines, or any dent, gouge, groove, or other damage to such lines or to their coating or cathodic protection. PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements. This violation is reduced from $1000 to a warning of $0. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. This violation is reduced from $1000 to a warning of $0. PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement. Project Owner - Aliquippa Economic Development Corp: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement. Facility Owner (other) -Verizon: Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket # 20261551585 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Facility Owner (other) - Aliquippa Municipal Water Authority: Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket # 20261551585 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).	
65941	**Facility Owner:** PEOPLES NATURAL GAS COMPANY LLC **Contractor/Excavator:** TRUMBULL CORPORATION **Project Owner:** Pennsylvania Turnpike Commission	On 6/17/2026 11:00:00 AM at 3000 LEBANON CHURCH RD, WEST MIFFLIN BORO, ALLEGHENY The incident occurred on Wednesday, June 17, 2026, 3000 Lebanon Church Road; near Camp Hollow Road, in West Mifflin Borough, Allegheny County. A gas line owned by Peoples Natural Gas Company (PNG) was damaged by Trumbull Corporation. PNG reported excavator issues as: Failed to use prudent techniques in the tolerance zone. Failed to protect and preserve the markings after beginning excavation, or contact the One Call System to request the facilities be marked again. Failed to plan the excavation or demolition work to avoid damage or minimize interference with a facility owner's facilities in a construction area.	

Case Number	Stakeholders	Summary	Violations & Recommendation
		PNG stated in their Alleged Violation Report (AVR), "Trumbull Corporation working for Pennsylvania Turnpike struck and damaged a Peoples Gas 2in distribution mainline causing an outage of 4 commercial buildings. There are no visible markings near the damage due to failure to maintain markings." Trumbull Corporation reported a facility owner issue as marked incorrectly. Trumbull Corporation stated in their AVR, "was grading for a roadway widening at 3000 Lebanon Church Rd, West Mifflin PA for the Pennsylvania Turnpike Commission. While using an excavator, a 3" Peoples Gas line was struck and pulled out of the compression fitting. The One-Call line mark was 4' from the location of the line strike. The one call marks indicated there were no utilities within the proposed excavation area. Provided one-call marks indicated the line continued straight, however there was a bend in the line that was not portrayed by the surface marks." No Violations: Trumbull Corporation called 911 and the Fire Department responded to the worksite. PNG and Trumbull Corporation provided pictures of the damaged line and locate marks. Trumbull Corporation was excavating when the gas line was hit because it was curved from the locate mark; "was a bend in the line that was not portrayed by the surface marks." Picture- Trumbull Corp-IMG_7536, is showing the gas line curving (bend) from the locate mark. PNG located and field marked based off their records.	
66161	**Facility Owner:** PEOPLES NATURAL GAS COMPANY LLC **Contractor/Excavator:** INDEPENDENT ENTERPRISES INC **Project Owner:** Pittsburgh Water **Other:** PITTSBURGH CITY DEPT OF MOBILITY & INFRASTRUCTURE	<u>On 6/24/2026 2:15:00 PM at PAULSON AVE, PITTSBURGH CITY, ALLEGHENY</u> Peoples Gas disagreed. They provided documents showing that this line was installed in 2005. ********** The incident occurred on 6/24/2026 at 1301 Paulson Ave in PITTSBURGH CITY in ALLEGHENY Co. A 1-inch plastic gas service line owned by Peoples Gas was damaged. PEOPLES NATURAL GAS COMPANY LLC stated in their Alleged Violation Report (AVR) that," Independent Enterprises working for Pittsburgh Water struck and damaged a mismarked Peoples Gas service line at 1301 Paulson. The line was marked via measurements as required in 2(5)(i) due to no tracer wire. The line had an undocumented lateral swing. Pictures and report were submitted. INDEPENDENT ENTERPRISES INC stated in their AVR that, " While excavating for a water service line verification at 1301 Paulson Ave., a 1-inch yellow plastic gas service line was struck by the excavator bucket at approximately 11:10 AM. The excavator operator was utilizing a spotter during the excavation. Work was immediately stopped, and 911 non-emergency was notified. The Pittsburgh Fire Department arrived on	**PEOPLES NATURAL GAS COMPANY LLC: $0.00** **PITTSBURGH CITY DEPT OF MOBILITY & INFRASTRUCTURE: $500.00** Section 2(5)(viii) 1st Offense $500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		site at approximately 11:20 AM, followed by Peoples Gas Company at approximately 11:35 AM. Upon investigation, it was determined that the damaged public gas service line was unmarked. The nearest PA One Call utility markings were located approximately 6 to 7 feet away from the actual location of the damaged facility. Peoples Gas completed the repair of the public gas service line at approximately 12:30 PM. No injuries occurred, and no additional property damage was reported. Project is listed as >$400,000. Duration of the project is expected to be 1 year. Report and pictures were provided. PITTSBURGH WATER & SEWER AUTHORITY stated in their AVR that," While excavating for a water service line verification at 1301 Paulson Ave., a 1-inch yellow plastic gas service line was struck by the excavator bucket at approximately 11:10 AM. The excavator operator was utilizing a spotter during the excavation. Work was immediately stopped, and 911 non-emergency was notified. The Pittsburgh Fire Department arrived on site at approximately 11:20 AM, followed by Peoples Gas Company at approximately 11:35 AM. Upon investigation, it was determined that the damaged public gas service line was unmarked. The nearest PA One Call utility markings were located approximately 6 to 7 feet away from the actual location of the damaged facility. Peoples Gas completed the repair of the public gas service line at approximately 12:30 PM. No injuries occurred, and no additional property damage was reported. Project is listed as >$400,000. Duration of the project is expected to be 1 year. Report and pictures were provided. Statements and pictures show that the gas line was not marked. VIOLATIONS PEOPLES NATURAL GAS COMPANY LLC is in violation of: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. This is a subsequent offense. Recommendation: The penalty is applied. PUC compliance education has been recently completed. PITTSBURGH CITY DEPT OF MOBILITY & INFRASTRUCTURE is in violation of: Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). Complex project ticket 20261313596 was submitted by INDEPENDENT ENTERPRISES INC] on 5/11/2026 with a response due by 5/17/2026. The meeting was held on 5/18/2026 at 11 a.m. PITTSBURGH CITY DEPT OF M OBILITY & INFRASTRUCTURE did not respond "clear" until 5/22/2026. Recommendation: The penalty is applied. PUC compliance education is required for the individual(s)	

Case Number	Stakeholders	Summary	Violations & Recommendation
		responsible to perform the locate for this ticket or their replacement(s).	
66312	**Facility Owner:** Pennsylvania American Water (PAWC) **Contractor/Excavator:** Charles Construction Co.	On 6/25/2026 8:00:00 AM at 1122 PARK AVE, PINE CREEK TWP, CLINTON The incident occurred on 6/25/2026, at approximately 8:00 AM, on 1122 Park Ave, in Pine Creek Twp, Clinton County. Excavation occurred without a PA One Call Ticket. Pennsylvania American Water (PAWC) is the facility owner. Their Alleged Violation Report (AVR) states, "Charles construction employees were observed completing an excavation at 1122 Park Ave 6-25-26. No Pa One Call was completed prior to the start of this work. PAWC stopped at the job location to see if they hit anything, they found our curb box that was located in the open excavation. Listed Affected Operation as Water but nothing was damaged". Charles Construction Company is the excavator. An AVR request letter was sent on 7/2/2026 and an AVR was submitted the same day that states, "We scraped sod off of an existing driveway approximately 2" deep with a skid steer. We had located the water valve and did not disturb it and dug around it by hand. Then we placed stone in the driveway. Nothing was harmed/ no incident." No information was provided to confirm the Project Owner. Images submitted show the site, excavation, and mechanized equipment being used for excavation. No One Call Ticket was entered for this excavation. Violations: Excavator - Charles Construction Company: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements. This violation is being reduced from $1000 to $500 as a first-time offense.	**Charles Construction Co.: $500.00** Section 5(2.1) 1st Offense $500.00
66856	**Facility Owner:** Ridley Township Public Works **Contractor/Excavator:** UTILITY LINE SERVICES **Project Owner:** PECO AN EXELON COMPANY **Designer:** PECO AN EXELON COMPANY - Spacesaver **Other:** VERIZON	On 7/9/2026 10:56:00 AM at MILMONT AVE, RIDLEY TWP, DELAWARE Utility Line Services (ULS) disagrees. On 10/16/2026 an email was received from ULS, accepting the violation and penalty. ********** The incident occurred on 7/09/2026 on MILMONT AVE in RIDLEY TWP in DELAWARE Co. A traffic loop conduit was damaged. UTILITY LINE SERVICES, the excavator, stated in their Alleged Violation Report (AVR) that, "While the crew was digging at the intersection of MacDade Boulevard and Milmont Avenue, they damaged an unmarked traffic light conduit. Notice via One Call was sent and responded to prior to the crew digging. A phone call was also made to the township 1 week prior to	**Ridley Township Public Works: $500.00** Section 2(5)(i.1) 1st Offense $250.00 Section 2(5)(i.2) 1st Offense $250.00 **UTILITY LINE SERVICES: $250.00** Section 5(6) 1st Offense $250.00 **PECO AN EXELON COMPANY: $2,000.00** Section 6.1(3) 2nd Offense $1,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		digging. The township was not certain where their facilities were." Pictures and reports were provided. On 8/19/2026 DPI Maki sent an email to ULS asking about any communication about the TSC that was unlocatable, as stated in the AVR. PECO AN EXELON COMPANY, the project owner, stated in their AVR that, "On 07/09/2026 UTILITY LINE SERVICES working for PECO damaged an unmarked traffic light conduit. All notifications were made." RIDLEY TOWNSHIP OF stated in their AVR that, "An emergency Pa. one call came in for Milmont Ave. and Mac Dade Blvd. where Utility Line Services were working saying the pulled a conduit up that went to the red light. When we got there within 30 minutes we noticed that the lights were out on the intersection and the conduit was pulled up out of the ground and the wires were stretched inside the conduit which made the lights in the intersection go out. My guys cut the pipe and made the repairs to the light and had it up and running within a couple of hours. On 8/19/2026 DPI Maki sent an email to Ridley Twp asking when ULS knew about the unlocatable line and was there a plan to locate it. An email was received on 8/21/2026 stating that ," My guy went by and talked to the foremen on the job and let him know the conduit went through the street on all four sides. They were fine on the one side of MacDade Blvd. on milmont and when they move to the other side they pulled the conduit out of the ground about twelve inches above the road. The conduit was buried about fifteen to eighteen inches below grade so I don't think the operator was taking his time looking for the conduit and my guy also asked the foreman if he needed anything else from him before he left and the foreman told my guy that they were good he shouldn't have any problems." On 8/24/2026, DPI Maki asked if there are any maps showing these lines and when the traffic signal conduit was installed. An email was received on 8/26/2026 stating that they thought the lines were installed in 1988. *Complex project ticket 20260291337 was submitted by UTILITY LINE SERVICES on 1/29/2026 and stated that an in-person meeting was not required. Ridley Township responded "Clear, no facilities involved". *Ticket 20261773820 was submitted by UTILITY LINE SERVICES on 6/26/2026, with a response due by 6/30/2026. Ridley Township responded "field marked" Verizon responded with "Conflict" on 7/01/2026. Emergency ticket 20261901844 was submitted by UTILITY LINE SERVICES on 7/09/2026 at 11:18 Remarks: [ATTENTION RIDLEY TWP THE CALLER STATES THE CREW ON SITE WAS SPOTTING	Section 4(2) 2nd Offense $1,000.00 **VERIZON: $1,000.00** Section 2(5)(v) Subsequent $1,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		UTILITIES AND THEYT HIT A LINE WHICH WAS UNMARKED. THIS LINE MAY BE ELECTRIC FOR THE TRAFFIC LIGHTS. THE CALLER CONTACTED RIDLEY TWP PREVIOUSLY AND THE RESPRESENTATIVE WAS NOT ABLE FIND OR MARK LINE AT THAT TIME. PLEASE RESPOND ASAP AND CONTACT JOHN LANNON AT HIS CELL 610 333 9978 WITH ANY QUESTIONS. FACILITY TYPE: UNKNOWN-OWNER NOT GIVEN Photos do not show a point of connection to the traffic loop marked out. One picture named "Macdade blvd & milmont ave folsom pa unmarked traffic signal wire 2", shows an electric facility in the distance, running parallel to the damaged line. VIOLATIONS Ridley Township Public Works is in violation of: Section 2(5)(i.1) – Failed to locate an actually known facility's point of connection to its facilities. Per Ridley Township, the lines for the traffic loop were installed around 1988, but there are no markouts in the pictures that show the point of connection to the traffic loop. Section 2(5)(i.2) – Failed to document Communications between a Facility Owner and Excavator to ensure the excavator is aware of a facility owner's inability to locate it's facilities. Recommendation: The penalties are applied. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). UTILITY LINE SERVICES is in violation of: Section 5(6) – Excavator failed to inform each operator employed by the excavator at the work site of the information obtained. Recommendation: The penalty is applied. PUC compliance education has been recently completed. PECO AN EXELON COMPANY is in violation of: Section 4(2) – Designer failed to request the line and facility information prescribed by section 2(4) from the One Call System not less than ten nor more than ninety business days before final design is to be completed. Section 6.1(3) – Released a project to bid or construction before final design was complete. NO Final Design was submitted through PAOneCall. Recommendation: The penalties are applied. PUC compliance education has been recently completed. Verizon is in violation of: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. *Ticket 20261773820 was submitted by UTILITY LINE SERVICES on 6/26/2026, with a response due by 6/30/2026. Verizon responded with "Conflict" on 7/01/2026. Recommendation: The penalty is applied. PUC compliance education has been recently completed.	

Case Number	Stakeholders	Summary	Violations & Recommendation
67159	**Facility Owner:** Columbia Gas Inc **Contractor/Excavator:** Golden Triangle Construction **Project Owner:** Pennsylvania American Water Company	On 7/14/2026 6:30:00 PM at 434.5 HAYES AVENUE, MT OLIVER BORO, ALLEGHENY The incident occurred on 7/14/2026 at 434.5 Hayes Ave., in MT OLIVER BORO, in ALLEGHENY Co. A 2-inch plastic gas main was damaged. COLUMBIA GAS OF PA INC., the facility owner, stated in their Alleged Violation Report (AVR) that, "On July 14, at approximately 1830 hours, Golden Triangle Construction, working on behalf of Pennsylvania American Water, damaged a Columbia Gas 2-inch plastic natural gas main. The Golden Triangle Construction crew on site observed fresh facility markings near the roadway, as well as older markings near the residence in the vicinity of the damage location. However, no updated or refreshed markings had been placed in the work area since the facilities were previously marked in July 2025. Updated markings would have indicated that the newer 2-inch plastic gas main was located within the planned excavation path for the water service installations. Upon damaging the natural gas main, the crew immediately notified 911 and Columbia Gas. Columbia Gas plant and service personnel responded to the scene and completed all necessary safety assessments, repairs, and restoration activities. The following day, Golden Triangle Construction submitted a new One Call ticket for the remainder of the project to ensure that all underground facilities were freshly marked prior to continuing work." They added that, "Original locate marks from July 2025 were accurate. The marks were faded/not visible at the time of excavation due to the length of time that had passed. 911 was notified. Report and pictures were provided. On 8/28/2026 an email was received that stated that "The 2" gas main in question, which serves 434 Hays Ave and several neighboring properties, was outside the scope of the original ticket. During the locate, the locator spoke with the contractor onsite to clarify the work area and received a list of effected addresses. The original email was over a year ago.. "At that time, the excavation was expected to extend from the main in the roadway to the sidewalk and curb boxes. The rear portion of the main serving 434 Hays Ave was not identified as part of the planned work, and the contractor was advised to place an additional One Call request if work was going to extend to those addresses." "The post-locate photos show markings for the active 2" plastic gas main running through the easement. The marking that was believed to be an older mark for the active main was actually associated with an abandoned 2" steel gas main. Those paint dots were remnants from a previous project where oil-based locate paint had been used and remained visible. The photo below shows the abandoned 2" steel main after it was cut off, along with the active 2" main that had been painted out. This is most likely why their appeared to be multiple markings in the area."	**Golden Triangle Construction: $1,000.00** Section 5(2.1) 1st Offense $1,000.00 **Pennsylvania American Water Company: $500.00** Section 6.1(1) 1st Offense $500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		GOLDEN TRIANGLE CONSTRUCTION, the excavator, stated in their AVR that, “Project History: GTC is subcontracted by Pennsylvania American Water Company to complete lead water service line replacements in the Mt. Oliver & City of Pittsburgh, Ward 29 area. There are multiple streets and hundreds of addresses that will be worked on with this project. The work flow is verify service at curb-stop location, if lead is found get an agreement signed by the property owner, and then perform the service replacement, followed by restoration. For 434.5 Hays Avenue, the water service was marked as a 2" feed going through a right-of-way to the property 434.5 Hays Avenue, which was subdivided into 4 separate properties with 4 separate owners. From the markings and exploratory verification at the curb stop, a 2" water line feed to a meter pit towards the end of the right of way that branched into (4) 3/4" water services lines that ran into the property. The One Call for 434.5 Hays Avenue was placed on 7/15/2025 with a 7/29/2025 start date. GTC parked equipment on Hays Avenue as it was a central location for work in the area. GTC verified the service was galvanized via hydro-excavation. GTC then attempted to get agreements signed by all 4 owners of the property. It was not until June 22, 2026, that GTC got the final agreement signed. GTC coordinated with the PA American Water Company to perform the service work starting on 7/13/2026, since the property would have to have a temporary water supply while the work was complete. On 7/14/2026, GTC was in the process of replacing the water service lines. At 4:24PM. GTC struck a 2" plastic gas service while excavating to set the new meter pits for the water services. GTC foreman called 911 and Mt. Oliver fire department arrive 6 min later. At 5:54PM Columbia Gas arrived on site to shut off the critical valve. Columbia Gas repair crews began arriving at 6PM to begin repairs. At 7:50PM, Columbia Gas employees and GTC personnel left site due to a non-related shooting event that occurred nearby for safety concerns. GTC and Columba Gas arrived back on site on 7/15/2026, with repairs being completed by 10:45AM. From GTC's investigation, it was note that GTC struck a 2" plastic service line. A visible gas service mark showed the damage 3FT off where the gas service should have been. There were no visible markings or flags on the new brick sidewalk or of what the material was except for right downhill off the gate at the street, where we hydroexcavated and found a steel line in line with the gas markings. The ground the visibly undisturbed and the plastic service line had no sand encasement or caution tape. When Columbia Gas remarked after the hit, the new markings show the original markings had been on the wrong service line. GTC acknowledges that our One Call ticket should have been re-notified but our equipment remained on the project for the duration of the project, not violating the law. Columbia Gas's new markings after the hit were 36" off the original mark. GTC believe the original markings were incorrect.” The project is listed as >$400,000. Pictures were provided.	

Case Number	Stakeholders	Summary	Violations & Recommendation
		Pennsylvania American Water Company, the project owner, sated in their AVR that," Golden Triangle working on the PA American Water lead service program hit and damaged a mis-marked Columbia Gas plastic 2" service. The line marked was the old steel gas line and the plastic that was not marked was 3' away. The service was damaged outside of the tolerance zone. 811's stance/view is because this was a complex project and the marks were still present, the excavator shouldn't have to update the one call even though it was expired." Project cost is listed at >$400,000. And the length is listed at 11000'. Report and pictures were provided. Case 54985 is connected by tickets. VIOLATIONS Golden Triangle Construction is in violation of: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Routine ticket 20251963011 was submitted for hydro vac excavation. The duration of the ticket is for 2 months. The ticket requests the CURB STOP, FRONT YARD, AND STREET to be marked out. The damage occurred with an excavator digging in the rear side of the building. Note that ticket 20261962016 submitted after the damage also does not include the side or back of the building. Recommendation: The penalty is applied. PUC compliance education is required for the excavators working onsite of this excavation or their replacements. Pennsylvania American Water Company is in violation of: Section 6.1(1) – Failed to utilize sufficient quality levels of subsurface utility engineering or other similar techniques to properly determine the existence and positions of underground facilities when designing known complex projects having an estimated cost of ($400,000) or more. This is a massive project for no planning to be done.	

Full Session

Case Number	Stakeholders	Summary	Violations & Recommendation
63814	**Facility Owner:** Columbia Gas of PA **Contractor/Excavator:** South Strabane Twp **Project Owner:** South Strabane Twp Placeholder	On 3/24/2026 10:15:00 AM at QUARRY RD, SOUTH STRABANE TWP, WASHINGTON Columbia Gas is disputing that mark out was incorrect but done to records. Columbia Gas emailed to withdraw dispute. **** Incident occurred on March 24, 2026, at 10:15am along Quarry Road, South Strabane Township, Washington County. Incident: A mismarked Columbia Gas line was damaged by South Strabane Township. Alleged Violation Reports (AVR):	**Columbia Gas of PA: $1,000.00** Section 2(5)(i) 2nd Offense $1,000.00 **South Strabane Twp: $0.00** Section 5(16) 1st Offense $0.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Facility Owner - Columbia Gas' AVR states, "South Strabane Twp working on drainage damaged a 1" plastic service. This service was marked by records, measurements and marker balls. There was wire at the meter, but signal was lost in the yard. This information was incorrect and a damage occurred. South Strabane Twp contacted the fire department and Columbia Gas. Columbia Gas crew and service tech responded, completed safety checks and repaired the line. Crew added a locate station after the repair to make this locatable. South Strabane Twp will be having a Damage Prevention review/safety talk with Columbia Gas, DPS the week of March 31." Project Owner & Excavator - South Strabane township's AVR states, "03/24/2026 we hit a service line that was mark out of the location mark" Was the AVR submitted after 30 days? Yes. PUC request for information sent on: 6/10/26 and AVR was submitted on 6/11/26. Conclusion: Images show that the gas line was marked outside the tolerance zone. Emergency services were marked as being notified. South Strabane Township did not submit an AVR with in 30 days, but they did respond immediately to the request for information. Recommended violations, penalties, and education: Facility Owner: Columbia Gas Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. -PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). Excavator: South Strabane Township Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. Reduced to warning $0 first offence. -PUC compliance education is required for the person responsible for submitting AVR or their replacement.	
63320	**Facility Owner:** AT&T **Facility Owner:** Comcast **Facility Owner:** Verizon **Contractor/Excavator:** SIGNARAMA MONTCO	On 3/25/2026 9:00:00 AM at W MAIN STREET, WEST NORRITON TWP, MONTGOMERY On 11/10/2026, The Damage Prevention Committee (DPC) voted to accept the investigator's recommendations and no changes were made. ********** AT&T is disputing. ********** Multiple non-damage ticket incidents occurred on March 25th, 2026, for West Main Street, located in West Norriton Township, Montgomery County, Pennsylvania. There were multiple non-responses from multiple stakeholders to PA One Call tickets.	**AT&T: $4,000.00** Section 2(5)(v) 2nd Offense $1,000.00 Section 2(5)(v) 2nd Offense $1,000.00 Section 2(5)(v) 2nd Offense $1,000.00 Section 2(5)(v) 2nd Offense $1,000.00 **Comcast: $10,500.00** Section 2(5)(v) 3rd offense $750.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Signarama Montco, the excavator, submitted three separate Alleged Violation Reports (AVR). Each AVR references non-responses to PA One Call tickets. Photos were submitted with all three AVRs. AVR2026MAR250010 states, "Comcast did not respond to the following excavation tickets: 20260792603 20260792604 20260793200 20260793201 20260793275 20260793276 20260793447 20260793448 20260793549 20260793550 20260793586 20260793587 20260793666 20260793667". AVR2026MAR250011 states, "AT&T did not respond to the following excavation tickets: 20260792604 20260793201 20260793276 20260793448". AVR2026MAR250012 states, "Verizon did not respond to the following excavation tickets: 20260792603 20260792604 20260793200 20260793201 20260793586 20260793587 20260793666". This case is related to cases 059735 and 061096. The tickets for this case, due dates and untimely responses: 20260792603 Routine – Due date 03/24/2026. Verizon responded 04/13/2026. Comcast responded 03/25/2026. 20260793549 Routine – Due date 03/24/2026. Comcast responded 03/25/2026. 20260793667 Routine – Due date 03/24/2026. Comcast responded 03/25/2026. 20260793666 Routine – Due date 03/24/2026. Comcast responded 03/25/2026. 20260793587 Routine – Due date 03/24/2026. Verizon responded 04/13/2026. Comcast responded 03/25/2026. 20260793586 Routine – Due date 03/24/2026. Verizon responded 04/13/2026. Comcast responded 03/25/2026. 20260793550 Routine – Due date 03/24/2026. Comcast responded 03/25/2026. 20260793448 Routine – Due date 03/24/2026. Comcast responded 03/25/2026. AT&T did not respond. 20260793200 Routine – Due date 03/24/2026. Verizon responded 04/13/2026. Comcast responded 03/25/2026. 20260793276 Routine – Due date 03/24/2026. Comcast responded 03/25/2026. AT&T did not respond. 20260793275 Routine – Due date 03/24/2026. Comcast responded 03/25/2026. 20260793201 Routine – Due date 03/24/2026. Verizon responded 04/13/2026. Comcast responded 03/25/2026. AT&T did not respond. 20252804294 - Violation for Verizon, AT&T, PAWC and Lumen applied on case 059735. 20260792604 Routine – Due date 03/24/2026. Verizon responded 04/13/2026. Comcast responded 03/25/2026. AT&T did not respond. 20252804133 – Violation for AT&T applied on case 061096. Violation for Verizon applied on case 059735. 20260793447 Routine – Due date 03/24/2026. Comcast responded 03/25/2026.	Section 2(5)(v) 3rd offense $750.00 Section 2(5)(v) 3rd offense $750.00 Section 2(5)(v) 3rd offense $750.00 Section 2(5)(v) 3rd offense $750.00 Section 2(5)(v) 3rd offense $750.00 Section 2(5)(v) 3rd offense $750.00 Section 2(5)(v) 3rd offense $750.00 Section 2(5)(v) 3rd offense $750.00 Section 2(5)(v) 3rd offense $750.00 Section 2(5)(v) 3rd offense $750.00 Section 2(5)(v) 3rd offense $750.00 Section 2(5)(v) 3rd offense $750.00 **Verizon: $12,000.00** Section 2(5)(v) Subsequent $2,000.00 Section 2(5)(v) Subsequent $2,000.00 Section 2(5)(v) Subsequent $2,000.00 Section 2(5)(v) Subsequent $2,000.00 Section 2(5)(v) Subsequent $2,000.00 Section 2(5)(v) Subsequent $2,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Act 127 of 2024, also known as the Underground Utility Line Protection Law states it shall be the duty of each facility owner: - To respond to all notices through the One Call System, provided the request is made in the time frame set forth under this act. The response shall be made not later than the end of the second business day following receipt of the notification by the One Call System, excluding the business day upon which the notification is received, or not later than the day prior to the lawful start date of excavation if the excavator specifies a later date or, in the case of an emergency, to respond through the One Call System as soon as practicable following receipt of notification of the emergency by the One Call System. Violations: Comcast- - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Routine ticket 20260792603. - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Routine ticket 20260793549. - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Routine ticket 20260793667. - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Routine ticket 20260793666. - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Routine ticket 20260793587. - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Routine ticket 20260793586. - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Routine ticket 20260793550. - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Routine ticket 20260793448. - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Routine ticket 20260793200. - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Routine ticket 20260793276. - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Routine ticket 20260793275. - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Routine ticket 20260793201. - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Routine ticket 20260792604.	

Case Number	Stakeholders	Summary	Violations & Recommendation
		- Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Routine ticket 20260793447. Recommendation: The penalty is applied. PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Verizon- - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Routine ticket 20260792603. - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Routine ticket 20260793587. - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Routine ticket 20260793586. - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Routine ticket 20260793200. - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Routine ticket 20260793201. - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Routine ticket 20260792604. Recommendation: The penalty is applied. PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). AT&T- - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Routine ticket 20260793448. - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Routine ticket 20260793276. - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Routine ticket 20260793201. - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Routine ticket 20260792604. Recommendation: The penalty is applied. PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).	
64015	**Facility Owner:** Chester Water Authority **Contractor/Excavator:** Richard E Pierson Construction Co **Project Owner:** Pennsylvania Department of Transportation (PennDOT) **Designer:** ALFRED BENESCH AND COMPANY **Other:** CMC ENGINEERING **Other:** PECO **Other:** Verizon	On 3/26/2026 12:00:00 AM at Bethel Ave and Rt. 322, UPPER CHICHESTER TWP, DELAWARE On 11-10-2026 the Damage Prevention Committee voted to accept Richard E Pierson Construction's 5(16) and 5(17) violation as presented in the Investigation Report, and remove the 5(6)(i) violation. ***** Richard E Pierson Construction Co did not respond to the AVR courtesy letter sent 6/8/2026. Richard E Pierson Construction Co responded on 9/18/2026 to the Investigator Report sent on 9/8/2026 to the same address and email addresses. They are disputing the violations and provided documentation showing the line was not supported during excavation, and that additional lines were damaged during their excavation. There is no documentation that those lines were reported as damaged to the facility owners. No AVR has been submitted to date. *** The incident occurred on 3/26/2026, at 2:00 AM, on Bethel Ave And Rt. 322, in Upper Chichester Twp, Delaware County when a water line owned by Chester	**Richard E Pierson Construction Co: $1,500.00** Section 5(16) 1st Offense $1,000.00 Section 5(17) 1st Offense $500.00 **PECO: $1,000.00** Section 2(5)(v.2) 3rd Offense $1,000.00 **Verizon: $250.00** Section 2(5)(v.2) 1st Offense $250.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Water Authority broke. Excavation occurred at the site prior to the day of the damage. Chester Water Authority is the facility owner. Their Alleged Violation Report (AVR) states, “A 12-inch transmission main failed off a 24-inch transmission main within the construction zone at SR 322 and Bethel Avenue in Upper Chichester Township, Delaware County, on March 26, 2026, with SCADA indicating the break began at approximately 2:09 AM and field crews confirming the location at approximately 3:17 AM, resulting in a high-volume discharge and rapid system pressure loss. Due to limited valve isolation in the immediate area, the event was prolonged, resulting in significant water loss and widespread service impacts across the system. A contractor had been working in the area the day prior excavating for a storm sewer, and based on available images, the excavation of material removed extended near and significantly below the elevation of the water main.” Additional information in the AVR states, “The alleged violation we believe occurred on Monday March 23, 2026 in the (Rt. 322 Conchester Hwy. Project zone) at Bethel Ave and Rt. 322 across from Cherrytree Rd. behind concrete barrier. One of the contractor's excavator was digging around Chester Water Authority's facilities where our 12" Cast Iron (CI) pipe and 24" Prestressed Concrete Cylinder Pipe interconnect and exposed them and didn't backfill and support them properly. Which caused a major failure on the 12" CI pipe at about 2am on the morning of March 26,2026.” Richard E Pierson Construction Co is the excavator. An AVR was not filed as of 06/05/2026 and an AVR request was sent the same day. No AVR was submitted. Richard E Pierson Construction Co has previously submitted AVRs. Penndot is the project owner. An AVR was submitted by CMC Engineering for PennDOT that states, “At approximately 2:00 AM on Thursday morning March 26th 2026, while no work was being performed on-site, a Chester Water Authority 12" water main ruptured on SR0322 EB at the intersection of Bethel Ave/Cherry Tree Rd at the SWC. The main was compromised from 2:00 AM Thursday until late Friday evening. No undermining or damage occurred to the adjacent 322 roadway and traffic was not disrupted at any time. CWA responded by installing two line stops on either side of the rupture in order to assess the damage and perform repairs.” Alfred Benesch And Company is the designer. Their AVR states, “Benesch is the design firm. Benesch staff were not on site at the time of the event, and we have no additional information than what was provided when we were notified via email from ComplianceCoordinator@pa1call.org on Wednesday 5/6/2026. Benesch cannot determine the type or reason of alleged violation because we were not present for the	

Case Number	Stakeholders	Summary	Violations & Recommendation
		event; however, we input facility owner issue and "Failed best efforts to follow Common Ground Best Practices" because a selection is required in the form." Ticket 20260471435 was the routine ticket for this location. It covers an area over 1000 feet, and multiple intersections. The new-routine ticket had a response due date of 2-19-2026. PECO responded "Clear on 3/6/2026. Verizon responded "Field Marked" on 2/24/2026. A renotify was entered on 3/9/2026 at 9:04 AM and did not require direct contact with the excavator within 2 hours. The water transmission main failure occurred on 3/26/2026. Images provided shows recent excavation occurred at the location, and the line was not supported during excavation. Statements in AVRs indicate the incident occurred due to excavation by Richard E Pierson Construction Co. Violations: Excavator - Richard E Pierson Construction Co: Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner's facilities in the construction area. PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement. Facility (other) – PECO: Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Facility (other) – Verizon: Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).	
63845	**Facility Owner:** PEOPLES NATURAL GAS COMPANY LLC **Contractor/Excavator:** R&J Adams Enterprises **Project Owner:** R&J	<u>On 4/10/2026 4:04:00 PM at 943 Pinegrove Lane and 943 Menoher Blvd, SOUTHMONT BORO, CAMBRIA</u> On 11/10/2026 The Damage Prevention Committee (DPC) voted to maintain the violations and penalty to R&J Adams Enterprises. * R&J Adams Enterprises is disputing.	**R&J Adams Enterprises: $1,000.00** Section 5(2.1) 1st Offense $1,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
	Adams Enterprises - Spacesaver	***** The incident occurred on 4/10/2026 at 943 Pinegrove Lane and on 943 Menoher Blvd in SOUTHMONT BORO in CAMBRIA Co. 2 plastic 1.25" lines that ran to a house were damaged. PEOPLES NATURAL GAS COMPANY LLC stated in their Alleged Violation Report (AVR) that, “Property owner Ryan Adams, R & J Adams Enterprises, LLC, dug without a PA 1 call and hit 2 buried plastic house lines to 943 Pinegrove ln and 943 Menoher Blvd. Fire department had the gas meters shut off when PNG arrived on site. House lines were plastic 1.25". NO ONE CALL. This affected 2-10 customers. 911 was notified. Pictures were provided. Compliance research Results: Contractor has placed notifications with PA One Call in the past. R&J Adams Enterprises was mailed an AVR request to 2 addresses; his business and property where the incident occurred, and his home address. DPI Maki returned a call to Ryan from R and J Adams Enterprises, on 5/05/2026. Ryan stated that he was going to do a small project on his land about a year ago. Meanwhile Peoples Gas wanted to move their gas line. He stated that while Peoples was out on his property looking at their project, he asked where the gas line was and they told him it was in the land and not in the hill where he wanted to work. He keeps equipment on this property but had moved the equipment that he used to dig with. Ryan stated that Peoples sent him a check after the line was damaged. DPI Maki stated to include all the information he has and any pictures, including the original ticket. Ryan also stated that he did call 911 when the line was hit. He stated that he will submit an AVR today. DPI Maki let him know that there is $1000. Penalty for not submitting an AVR and explained what an AVR is. DPI Maki explained how simple it is to submit an AVR online at the PAOneCall site. DPI Maki gave him the number to call in to submit an AVR, since his message stated that he does not use computers very much and feels uncomfortable using them. DPI Maki sent an email following up with what was discussed and attachments of AVR submitting, Copy of ACT 127 f 2024, and the contact list of the PAOneCall liaisons. R&J Adams Enterprises stated in his AVR that, “Had meeting with executives of peoples gas to talk about running new gas lines on my property and I ask if the lines where i wanted to dig would be clear. Was told it should be but it wasn't apparently. Had a ticket for a one call back in 2024 ticket # 20241003375 which i new gas lines where in that area but wanted to confirm if it was buried below ground or not. Was told they should be. But it wasn't. Did call peoples gas the day we hit lines and 911 was called as well. We have since had the line fix within 3 days of the incident. And peoples gas did wright me out a check to cover my expenses to pay for	

Case Number	Stakeholders	Summary	Violations & Recommendation
		the incident which I did not request for that but they were willing to do which I really appreciated. The incident dates do not match, but the incident and location and information about the incident does match. *Ticket 20241003375 was submitted on 4/09/2024 to install a gas line and dig out Hillside. The project was expected to take about a month. VIOLATIONS R&J Adams Enterprises is in violation: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Recommendation: The penalty is applied. PUC compliance education is required for the excavators working onsite of this excavation or their replacements.	
64073	**Facility Owner:** PEOPLES NATURAL GAS COMPANY LLC **Contractor/Excavator:** A. Folino Construction Inc **Project Owner:** Pittsburgh Water	On 4/20/2026 7:00:00 AM at SANDUSKY ST and MULTIPLE LOCATIONS, PITTSBURGH CITY, ALLEGHENY On 11/10/2026, The Damage Prevention Committee (DPC) voted to accept the investigator's recommendations and no changes were made. ********** Disputing is A Folino ********** The Non-Damage violation occurred on Monday, April 20, 2026, on Sandusky Street and Multiple Locations, in Pittsburgh City, Allegheny County. A Non-Damage violation was reported by Peoples Natural Gas Company (PNG). PNG reported an excavator issue as failed to take reasonable steps to work with facility owners when working at multiple work sites over a large area including scheduling a preconstruction meeting or create a complex project. PNG stated in their Alleged Violation Report (AVR), "A Folino called in 57 ticket all within the Northside neighborhood of Pittsburgh for street restoration with no complex project meeting." Additional information: "there was a meeting requested by the PNG locator. This was documented on the tickets). After receiving the notification of the 092 Karl code, Ernesto Carns and Anton Zupancic of Folino called me to come to an agreement. I explained why the tickets received an 092 Karl code response, we came to a mutual agreement while on the phone, then I supplied Folino with the two Damage Prevention Supervisor's contact name, number, and email, so they too could agree on the locate schedule and where Folino would begin work." AVR's were requested from A. Folino Construction and Pittsburgh Water; the project owner, on Friday, 7/17/2026 and Tuesday, 7/21/2026. A. Folino Construction stated in their AVR, "PA 1 Calls (62) placed on April 16 to 17 were in Wards 22, 24, 25,	**A. Folino Construction Inc: $250.00** Section 5(3) 1st Offense $250.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		26 by me for PWSA 2026 Surface Restoration – OPS/ Folino 26-62001 This was in preparation for the actual physical work to start on this project. ? Attached: o OTM report directly from PA 1 Calls with cross streets o GIS placement of call locations. Complex Project: Was never discussed as a complex project from Owner or CM Tean (Hatch) through Preconstruction meetings or site visits Project focused on restoration sites from PWSA OPS work locations Planning: Folino Walked work sites with CM Team to confirm locations and paint out limits of each restoration site. CM Team then issued Sites via GIS with a 45- day completion on each site within associated Ward(s) List (hand written then from GIS list maintained by CM (Hatch) for PWSA was given to E. Carns, and one calls placed. Note: PWSA Contract requires: ? Contract Milestone – "Minimum of 400 sites restored by July 17th 2026." (Page 1 of 8) o Contract Volume doubled from previous years site restorations ? 5 restoration crews per day on Project work Sites – Potential restoration work of 5-6 sites per day per crew o Saw cutters (1 to 2 in addition to restoration crews), out ahead of Crews and can work on 9 – 12 sites per day o Sites could be unavailable due to obstructions (cars parked within work zone), water leaks or unforeseen conditions/changes from CM/ owner" Pittsburgh Water stated in their AVR, "This AVR is for Folino saw cutting misc. locations for road restoration. There were no damaged facilities. 20261065331, 20261065372, 20261065427, 20261065441, 20261065461, 20261065487, 20261065519, 20261065537, 20261065544, 20261070444, 20261073882. All of these1 call numbers are for different locations. Folino put in 57 tickets in a day because they are able to saw cut 24 locations in 1 day. These restoration sites are for misc. 5x5,6x8,8x10 ft areas. These tickets are not for paving and milling entire streets and its not a complex project. Pittsburgh Water Attn: Joe Tewell and William McFaddin 1200 Penn Ave. Pittsburgh, PA 15222 Re: Please Submit an Alleged Violation Report with Pictures - Case Number: 64073 IN REPLY PLEASE REFER TO 811 We have received a report that a violation allegedly occurred in connection with the job site at SANDUSKY ST, PITTSBURGH CITY, ALLEGHENY. PA1Call Ticket Number: 20261065331, 20261065372, 20261065427, 20261065441, 20261065461, 20261065487, 20261065519, 20261065537, 20261065544, 20261070444, 20261073882 To Whom It May Concern, We received an Alleged Violation Report indicating an underground utility violation has occurred. With the Underground Utility Line Protection Law, Act 127 of 2024, anytime an underground facility violation has been reported, you as a stakeholder are required to submit an Alleged Violation Report thru the Pennsylvania One Call website, www.pa1call.org within thirty (30) calendar days of the utility violation date. Please submit an AVR immediately"	

Case Number	Stakeholders	Summary	Violations & Recommendation
		Some of the routine tickets are listed: duration 2 weeks, Type of Work--[REPAIR ROAD BASE, MILL/PAVE, SIDEWALK/CURB] *20261065331- 4/16/26 at 2115, SANDUSKY ST *20261065372- 4/16/26 at 2135, JACKSONIA ST *20261065427- 4/16/26 at 2211, BUENA VISTA ST *20261065441- 4/16/26 at 2216, BRIGHTON RD *20261065461- 4/16/26 at 2225, CALIFORNIA AVE *20261065487- 4/16/26 at 2238, HOLYOKE ST *20261065519- 4/16/26 at 2304, UNIVERSITY AVE *20261065537- 4/16/26 at 2324, MEADVILLE ST *20261065544- 4/16/26 at 2342, CARRIE ST *20261070444- 4/17/26 at 0815, SPRAIN ST *20261073882- 4/17/26 at 1628, HEMLOCK ST The Underground Utility Line Protection Law (UULPL) aka PA One Call Law, ACT 127, Responsibilities Of The Excavator, Section 5(3) states: In a complex project or if an excavator intends to perform work at multiple work sites or over a large area, to take reasonable steps to work with facility owners, including scheduling and conducting a preconstruction meeting, so that they may locate their facilities at a time reasonably in advance of the actual start of excavation or demolition work for each phase of the work. Violation: Folino Construction is in violation of section: 5(3) – Excavator failed to hold a preconstruction meeting prior to beginning a complex project. Recommendation: Penalty applied with PUC Online Compliance Training is required for the Excavator(s) working onsite at this excavation, or their replacements. Because when requested they did meet with PNG after the tickets were placed and “came to a mutual agreement”.	
64075	**Facility Owner:** AT&T **Facility Owner:** PECO **Contractor/Excavator:** BRUBACHER EXCAVATING INC **Project Owner:** AQUA PENNSYLVANIA INC **Designer:** GFT INFRASTRUCTURE, INC.	<u>On 4/20/2026 7:15:00 AM at KNOX RD, TREDYFFRIN TWP, CHESTER</u> On 11/10/26 The DPC voted to remove the violation and penalty for PECO. *** PECO is disputing 2(5)(v.2) for ticket 20260684511. 0 KF PECO AN EXELON COMPANY KF-SCHEDULED MARK 3/11/26, 9:50 AM CLS-WEBSVC N/A 0 KF PECO AN EXELON COMPANY KF-SCHEDULED MARK 3/23/26, 1:37 PM CLS-WEBSVC N/A 0 KF PECO AN EXELON COMPANY KF-FIELD MARKED 3/30/26, 1:06 PM AAA-WEBSVC N/A 2(5)(ix) was removed after PECO provided photo proof. **** Incident occurred on 4/20/26 at 7:15am along 677 Knox Road, Tredyffrin Township, Chester County. Incident: A PECO Gas line was hit by Brubacher Excavating.	**AT&T: $1,000.00** Section 2(5)(v) 2nd Offense $1,000.00 **PECO: $3,000.00** Section 2(5)(i) 3rd Offense $1,500.00 Section 2(10) 2nd Offense $1,500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Case is related to 64266 & 64317. Alleged Violation Reports (AVR): Facility Owner - PECO's AVR states, “On 04/20/2026, Brubacher Excavating was using an excavator when they damaged a gas service line. PECO was not aware of this damage. Submitting Alleged Violation Report per request from the PUC.” AVR submission date: 6/23/26 Was the AVR submitted after 30 business days? Yes, please note the excavator submitted an emergency ticket that PECO responded to. Excavator - Brubacher Excavating's AVR states, “While excavating the trench for new water main installation on Knox Rd project, the crew encountered an unmarked gas service. A 1" diameter steel pipe with 1/2" plastic pipe was found at 2'- 6" deep. The excavation was in the street at 677 Knox Rd. The work was being performed for Aqua PA. Original Ticket #2026 068 4511 and the damage ticket #2026 110 0280. No smell and no blowing.” Project Owner - Aqua's AVR states, “Aqua Contractor Brubacher Excavating, while excavating the trench for new water main installation on Knox Rd project, the crew encountered an unmarked gas service. A 1" diameter steel pipe with 1/2" plastic pipe was found at 2' 6" deep. The excavation was in the street at 677 Knox Rd. No smell and no blowing.” Designer - GFT Infrastructure's AVR states, “Aqua Contractor Brubacher Excavating crew, while excavating the trench for new water main installation on Knox Rd project, encountered an unmarked gas service. A 1" diameter steel pipe with 1/2" plastic pipe was found at 2' 6" deep. The excavation was in the street at 677 Knox Rd. No smell and no blowing. GFT as a designer was not involved with construction phase of this project. GFT was not involved in the bidding of this project, and therefore does not know if any modifications were made to the bid documents/final design package provided by Aqua to the Contractor. GFT was not on site and had no knowledge of the incident until it received an email notification by PA One Call Compliance Coordinator on Thursday May 7, 2026. GFT is submitting this AVR in compliance with its requirements under Act 50, and based on information provided to GFT by Aqua.” Conclusion: Emergency ticket 20261100280, "CREW IS ON SITE. DAMAGED A GAS SVC LINE. 1IN STEEL WITH 1/2IN PLASTIC FACILITY TYPE: NATURAL GAS-PECO EXCAVATION EQUIPMENT: EXCAVATOR HAZARDOUS RELEASE: NO" PECO responded Clear no facilities to this emergency notification. Damage photo's do not show markings on the street for this gas lateral. Routine Ticket 20260684511:	

Case Number	Stakeholders	Summary	Violations & Recommendation
		AT&T - "No Response" PECO - 3/11/26 Scheduled Mark, 3/23/26 Scheduled Mark, and 3/30/26 Scheduled Mark. Act 127 Section 2.5.v states: "To respond to all notices through the One Call System, provided the request is made in the time frame set forth under this act. The response shall be made not later than the end of the second business day following receipt of the notification by the One Call System, excluding the business day upon which the notification is received, or not later than the day prior to the lawful start date of excavation if the excavator specifies a later date or, in the case of an emergency, to respond through the One Call System as soon as practicable following receipt of notification of the emergency by the One Call System." Recommended violations, penalties, and education: Facility Owner: PECO Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. 20260684511. Section 2(5)(ix) – Facility owner failed to respond promptly to the site of an excavation where its underground line was damaged. 2026110280. Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner's lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. -PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). -PUC compliance education is required for the person responsible for submitting AVR or their replacement. Facility Owner: AT&T Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20260684511 PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).	
64347	**TABLED**	**TABLED BY DPC**	
64830	**Facility Owner:** PEOPLES NATURAL GAS COMPANY LLC **Contractor/Excavator:** DUQUESNE LIGHT COMPANY **Project Owner:** DUQUESNE LIGHT COMPANY	On 5/11/2026 11:28:00 AM at NEUTRAL WAY / 207 WHITAKER ST IN REAR, WHITAKER BORO, ALLEGHENY On 11/10/2026, The Damage Prevention Committee (DPC) voted to remove Duquesne Light Company's violation and penalty. ********** Dispute- Duquesne Light Company is disputing the penalty and violation ********** The incident occurred on Monday, May 11, 2026, Neutral Way, 207 Whitaker Street Rear, in Whitaker Borough, Allegheny County.	**PEOPLES NATURAL GAS COMPANY LLC: $2,000.00** Section 2(5)(i) Subsequent $2,000.00 **DUQUESNE LIGHT COMPANY: $0.00**

Case Number	Stakeholders	Summary	Violations & Recommendation
		A gas line owned by Peoples Natural Gas Company (PNG) was damaged. PNG reported a facility owner issue as failure to locate point of connection to facility lines. PNG stated in their Alleged Violation Report (AVR), "On 5/11/26 Duquesne Light Company working on Neutral Way, Whitaker in the rear of 207 Whitaker St struck an unmarked PNG main to curb service line while augering to install new utility pole. PNG service had EFV and closed upon damage. Duquesne Light Company notified 811 and 911. PNG crews arrived onsite and made repairs." "Main line was marked failed to mark service line" Duquesne Light Company (DLC) reported a facility owner issue as failed to document communications, ensure the excavator is aware of a facility owner's inability to locate its facilities. DLC stated in their AVR, "Duquesne Light Overhead crew were digging to to place a pole when they struck an unmarked gas service line. A Damage One Call ticket was placed and Peoples Natural Gas responded back to the site. According to the notes written by the responding DLC Supervisor, PNG responded to the site and reported that the line was a cut and capped service line and the meter was removed. As a result, the line to the home was not marked." Pictures were provided showing the located mainline and damage service line. In PNG photo, PNG pic2 it shows a gas curb stop in the grass. DLC did not place a remark ticket for the gas curb stop. Violations: *Peoples Natural Gas Company is in violation of section: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Because the "Main line was marked failed to mark service line" Recommendation: Penalty applied. *Duquesne Light Company is in violation of section: 5(3) – Excavator failed to preserve mark-outs or request a remark. Because in PNG pic2 it shows a gas curb stop in the grass. DLC did not place a remark ticket for the gas curb stop. Recommendation: Penalty applied.	
65044	**Facility Owner:** PHILADELPHIA GAS WORKS **Contractor/Excavator:** JPC GROUP **Project Owner:** PHILADELPHIA CITY WATER DEPARTMENT **Other:** CARR AND DUFF INC **Other:** Verizon PA LLC	On 5/13/2026 10:21:00 AM at 4600 Ridge Ave, PHILADELPHIA CITY, PHILADELPHIA On 11/10/2026, The Damage Prevention Committee (DPC) voted to remove Philadelphia Gas Works' violation and penalty. ********** Disputing- Philadelphia Gas Works is disputing. See attachment. ********** The incident occurred on Wednesday, May 13, 2026, at 4600 Ridge Ave, in Philadelphia City.	**PHILADELPHIA GAS WORKS: $0.00** **Verizon PA LLC: $1,000.00** Section 2(5)(v) 2nd Offense $1,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		An unmarked gas line owned by Philadelphia Gas Works (PGW) was damaged by JPC Group, Inc. PGW reported an excavator issue as failed to request the location and type of facility owner thru the One Call System 3-10 business days in advance of beginning the work. PGW stated in their AVR, “Carr and Duff damaged 1" plastic gas line to 4540”, “excavated without a one call.” Carr & Duff stated in an email, “Carr & Duff was not the excavator who performed the work. We subcontracted the work to JPC 20260691489, Routine ticket placed on 3/10/2026, by JPC Group. PGW responded as Clear No Facilities, but in their AVR they mentioned a 1-inch gas line was damaged. No Response from Verizon PA LLC Philadelphia City Water Department (PWD), the project owner, reported an excavator issue as failed to exercise due care and take all reasonable steps necessary to avoid injury to or interference with all lines. PWD stated in their Alleged Violation Report (AVR), “On 05-13-2026, JPC Group Inc. was performing excavation work for the Queen Lane RWPS Generator Project (WO# 64072) at the PWD facility located at 4600 Ridge Avenue, Philadelphia, PA 19129. JPC Group (sub-contractor to Carr & Duff) was excavating beneath an existing oil pipeline in order to install conduit for the duct bank work shown in Section “CC” of the contract drawing E-08. The contractor maintained the required 48-inch excavation depth through the work area; however, additional excavation depth was required in order to pass beneath the existing oil pipeline. At approximately 10:21 AM, while excavating beyond the 48-inch depth, JPC struck and damaged an existing 1-inch gas feed line entering the facility. The damaged gas line fed a clothes dryer inside the facility. No injuries were reported, and no other equipment or appliances were identified as affected. The One Call serial number for the PA One Call mark-out was 20260691489. 911 was called at approximately 10:25 AM, and the PWD facility was evacuated by approximately 10:28 AM. The Site Engineer, Tony Lo, was notified at approximately 10:40 AM. The Philadelphia Fire Department arrived on site at approximately 10:45 AM, followed by Philadelphia Gas Works at approximately 10:52 AM. The gas line was temporarily plugged around 12:00 PM, and the Fire Department left the site at approximately 1:10 PM. PGW closed the gas main valve at approximately 4:16 PM, at which time the gas was no longer leaking. Gas line repair began at approximately 5:00 PM, and the gas main was restored by approximately 8:11 PM. All activities ceased, and personnel were off site by approximately 8:52 PM. PWD Security was on site at approximately 9:00 PM to lock and secure the facility gates.”	

Case Number	Stakeholders	Summary	Violations & Recommendation
		JPC Group reported a project owner issue as failed to install color-coded permanent markers to indicate the type and location of all laterals installed by the project owner or their agent. JPC Group stated in their AVR, "On 5/13/26, our company (JPC Group, Inc.) was performing excavation activities as a subcontractor for the general contractor (Carr & Duff) on a Philadelphia Water Department private project located at 4600 Ridge Ave, Philadelphia, PA 19129. Prior to excavation, a valid Pennsylvania One Call notification had been obtained for the project area (Ticket #20260691489). Because utility mark-outs by facility owners terminated at or near the public curb line, a private utility locating contractor (GPRS) was separately retained to identify and mark underground utilities within the private property limits of the site. Before excavation commenced, the work area was inspected for utility markings and reviewed against the available site plans and utility information provided to JPC. No markings indicating the presence of a gas service were observed within the excavation area, and the gas service was not depicted on the plans or utility information available to the excavating contractor. During excavation operations, an unmarked underground gas service was encountered and damaged. Work was immediately stopped in the affected area, the condition was reported, and appropriate emergency and utility notifications were made. This AVR is being submitted because the underground gas facility that was damaged was not identified or marked in the field and was not shown on the available plans or utility documentation reviewed prior to excavation. JPC had relied upon the utility markings and information provided before excavation activities commenced. It should be noted that prior to mechanical excavation, JPC completed test digs via hand-digging to locate and identify any potential unmarked underground utilities. While doing so, JPC crew had encountered and exposed an unmarked steel 1" gas line via hand-digging. It should also be noted that complete hand-digging efforts were not possible due to the brick/concrete footing consistency of material to be excavated. Supporting documentation, including photographs, One Call ticket information, utility locate records, and project plans, can be provided upon request." JPC Group additional information: "This date, I was detailed to Queen Lane Pump Station in regard to a strike of unmarked gas line, during excavation for conduit placement. Upon arrival I met with Operator O'Neill and Supervisor Hurley. Area of strike was explored. Gas line was encased in brick wall/footing and was not readily visible. Depth to area where gas was venting from ground found to be approximately 41 inches and approximately 15 feet from East wall of pump station. On site were personnel from Philadelphia Fire and PGW. PGW supervisor was reviewing site plans in effort to locate shut off valve. Additional PGW personnel arrived on site and conducted	

Case Number	Stakeholders	Summary	Violations & Recommendation
		digging in area of East fence line in attempt to locate shut off valve. Crews dug and probed for the three hours I was on site with no success in locating shutoff valve. During attempts to locate shut off, small crew was sent to area of strike and attempt to plug leak was made. Leak was partially plugged, but blow by continued." "Walked job site with crew members in attempt to identify mark out of utilities, both by 811 and GPRS. Water and sewer mark outs were found on parking lot on East side of pump house. Gas mark outs did not exist in area of excavation. Gas marks were found in range from 60 to 90 feet from work area in area of East and North curbs in area of fence lines. Those marks found to run perpendicular to curbs and not in direction of pump station. See accompanying photos." "I was advised by crew that an unmarked steel 1 inch gas line had been found in area of excavation. This line was hand dug to expose and painted to allow visual location. That line ran at an approximate 45 degree angle toward valve on wall of pump station. No mark outs found to identify that line. This date the crew was attempting to remove a brick wall/ footing buried in ground as part of excavation. Operator was scratching bricks from top of footing and encased when unmarked gas line was struck. No sand in area of line, line contained within brick structure. Upon break, crew evacuated area and contacted Philadelphia Fire and PGW." "I was advised by JPC and Carr & Duff personnel that neither the line struck this date, nor the one accidentally discovered and hand dug were present on site plans. Crew at time of strike was not aware of presence of gas lines as it was not marked out, nor appears on site plans. 811 mark-out call had been made for perimeter utility, GPRS was hired for on-site utility mark outs. Area of site was photographed and those photographs accompany this file." Violations: *Philadelphia Gas Works is in violation of section: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. PGW responded to the worksite and repaired the damage line. Recommendation: Penalty applied *Verizon PA LLC is in violation of section: 2(5)(v) – Failed to respond to a routine One Call ticket. 20260691489 Recommendation: Penalty applied	
65035	**Facility Owner:** PECO AN EXELON COMPANY **Contractor/Excavator:** ANGIES CABLE LLC **Project Owner:** RHINO CABLE	<u>On 5/20/2026 5:50:00 AM at DAVENPORT ROAD, KENNETT TWP, CHESTER</u> On 11/10/2026, ANGIES CABLE LLC was not in attendance at the Damage Prevention Committee (DPC) meeting. The DPC voted to accept the investigator's recommendation and add an additional $250.00 penalty to 5(22) for not attending the DPC meeting. The penalty for 5(22) was increased from $500.00 to $750.00.	**ANGIES CABLE LLC: $1,750.00** Section 5(2.1) 1st Offense $1,000.00 Section 5(22) 1st Offense $750.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		********** Disputing- ANGIES CABLE LLC is disputing stating, "Hello My name is Alfredo Flores Vargas owner of Angies Cable LLC. I got an Email of an DPI Report. Unfortunately there was an Incident on the fact that the Job was interpreted as an Emergency me not knowing at all. I cannot afford the payment. It was an honest mistake that was interpreted as an emergency. I would like to Present my case with The DPI or have a training meeting." ********** The Non-Damage violation occurred on Wednesday, May 20, 2026, on Davenport Road, in Kennett Township, Chester County. The Non-Damage violation was reported by PECO an Exelon Company. PECO reported an excavator issue as provided a misrepresentation of an emergency excavation. PECO stated in their Alleged Violation Report (AVR), “false emergency one call” 20261400048- Excavation Emergency ticket was placed on 5/20/2026 at 5:50am, Work For--[RHINO CABLE], Type of Work--[INSTALL CATV MAIN], Method of Excavation--[TRENCHING], Scheduled Excavation Date and time: 5/20/2026 at 8:00am. On Monday, 7/20/2026 an email and letter were sent requesting an AVR and asking additional questions from the contractor, Angies Cable. Angies Cable responded by email on 7/21/2026 stating, “There was never a violation done on my part on my work done on that address.. We replace a main line but never hit or damage anything. I have been trying to contact somebody on the AVR Violation program or what not but nothing. Angies cable just came to the jobsite and finished replacing a comcast line. But again nothing was damage or reported damage. We don't understand why a violation has been reported.” Their email was responded to on 7/22/2026, stating this is a Non-Damage violation and attached was the original letter requesting an AVR and asking the additional questions. (attachments- Angies Cable-requesting additional info 7-22-26, EX- Angies Cable- letter requesting AVR) Angies Cable submitted an AVR on 7/22/2026. On Wednesday, 7/29/2026 an email was sent to Angies Cable requesting additional information because their AVR did provide answers to the questions, and attached was the original letter requesting an AVR and to answer questions, and their submitted AVR. Angies Cable never responded to the 7/29/2026 email. In the AVR Angies Cable noted Under Excavation Work:	

Case Number	Stakeholders	Summary	Violations & Recommendation
		Method of Excavation: DIRECTIONAL Equipment Used: DIRECTIONAL DRILLING Type of Excavator: Other The Underground Utility Line Protection Law (UULPL) aka PA One Call Law, ACT 127, definition: "Emergency" means a sudden or unforeseen occurrence involving a clear and immediate danger to life, property and the environment, including, but not limited to, serious breaks or defects in a facility owner's lines. The Underground Utility Line Protection Law (UULPL) aka PA One Call Law, ACT 127, Responsibilities of The Excavator, Section 5(2.1) states: To submit a locate request to identify the location and type of facility owner lines at each work site by notifying the facility owner through the One Call System. Notification shall be not less than three nor more than ten business days in advance of beginning excavation or demolition work. No work shall begin earlier than the lawful start date which shall be on or after the third business day after notification. The lawful start date shall exclude the date upon which notification was received by the One Call System and notification received on a Saturday, Sunday or holiday, which shall be processed on the following business day. In the case of a complex project, notification shall not be less than ten business days in advance of the beginning of excavation or demolition work Violations: Angies Cable is in violation of sections: 5(2.1) – Excavator failed to submit a location request to identify the location and type of facility owner lines at each work site by notifying the facility owner through the One Call System. Angies Cable did not submit a routine ticket as required 5(22) – Excavator provided a misrepresentation of an emergency excavation Recommendation: Penalties applied and PUC Online Compliance Training is required for the Excavator(s) working onsite at this excavation, or their replacements.	
65506	**Facility Owner:** TC Energy **Contractor/Excavator:** A-N-O OILFIELD SERVICE LLC. **Other:** HIGHLAND TOWNSHIP ELK COUNTY **Other:** National Fuel Gas Distribution	On 6/2/2026 7:50:00 AM at OWLS NEST RD, HIGHLAND TWP, ELK On 11-10-2026 the Damage Prevention Committee voted to remove National Fuel Gas' 2(5)(v.2) violation. ***** National Fuel Gas is disputing the violation and penalty. ***** The incident occurred on 6/2/2026, at approximately 7:50 AM, on Owls Nest Rd, in Highland Twp, Elk County. An emergency ticket was entered for a non-emergency excavation. TC Energy is the facility owner. Their Alleged Violation Report (AVR) states, “Was contacted about the emergency one call. Looked up the ticket and seen it was for grading and ditching roadway. Contacted Jordan	**A-N-O OILFIELD SERVICE LLC.: $500.00** Section 5(22) 1st Offense $500.00 **HIGHLAND TOWNSHIP ELK COUNTY: $250.00** Section 2(5)(v.2) 1st Offense $250.00 **National Fuel Gas Distribution: $0.00**

Case Number	Stakeholders	Summary	Violations & Recommendation
		Copley and asked what work was taking place. He said grading and ditching the roadway for a logging job. I asked what the emergency was. He said as far as life threatening there was no emergency. They just want to get the job done." A-N-O Oilfield Service is the excavator. An AVR was not filed as of 08/07/2026 and an AVR request was sent the same day. An AVR was submitted within 30 days of being requested that states, "In the early evening of June 1st 2026 we received a call about potential emergency road work approximately 1.5 miles down FR 329. Upon driving to the location, numerous water drainage issues were observed. Upon arriving at the 1.34 mile marker, roughly .06 miles of roadway was impassable. From mile marker 1.24 to 1.42 the downhill grade is approximately 10%-12%. A severe washout had occurred causing deep ruts, piles of debris and road material. The road was in bad enough shape that ATV's were by-passing the road and traveling on the bank/berm of the road. The 2023 Ram 3500 4x4 truck that was onsite would not navigate the road. We had walked approximately 1 mile to the 2.2 mile marker and observed another wash out area on a down hill section of road but did not appear to be in as bad of condition at the wash out at mile marker 1.34. The decision to place an emergency 1 call was due the road being impassible in 1 to 2 sections, the gate being open to the public for access and the particular sections of road affected by the wash outs were part of an ATV trail system which is open to the public. From mile marker 1.13 to mile marker 3.55 the road is a "dual use" road allowing vehicle traffic and ATV traffic simultaneously. The particular cause of the wash outs and general drainage issues is believed to be as a result of ARG Resources shutting down in 2019 – 2020. With no oil and gas related traffic of the particular road to spot potential areas of concern and no road maintenance of any kind being performed, the sections of road became impassible and a hazard." Ticket #20261530507 was an emergency ticket for "ROAD WORK (GRADING & DITCHING) BEING PERFORMED ON ANF ROAD 329". National Fuel Gas entered "Conflict" as their only response. Highland Township Elk County did not respond. The PA One Call System informs the user of the definition of an emergency prior to them being able to submit the Emergency Ticket. No images were submitted showing the road prior to excavation occurring. The excavator submitted a separate document that indicated why the emergency ticket was placed, "The decision to place an emergency 1 call was due the road being impassible in 1 to 2 sections, the gate being open to the public for access and the particular sections of road affected by the wash outs were part of an ATV trail system which is open to the public."	

Case Number	Stakeholders	Summary	Violations & Recommendation
		An emergency, as defined by Act 127 of 2024, "means a sudden or unforeseen occurrence involving a clear and immediate danger to life, property or the environment, including, but not limited to, serious breaks or defects in a facility owner's lines…" Violations: Excavator - A-N-O Oilfield Service: Section 5(22) – Excavator provided a misrepresentation of an emergency excavation, subject to an administrative penalty imposed under section 7(10). PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements. Facility Owner (other) - National Fuel Gas Distribution Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket 20261530507 Facility Owner (other) - HIGHLAND TOWNSHIP ELK COUNTY Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket 20261530507 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).	
65619	**Facility Owner:** Peoples Natural Gas **Contractor/Excavator:** INDEPENDENT ENTERPRISES **Project Owner:** Pittsburgh Water **Other:** GAI CONSULTANTS INC **Other:** Verizon PA LLC	On 6/4/2026 2:30:00 PM at VALONIA ST, PITTSBURGH CITY, ALLEGHENY INDEPENDENT ENTERPRISES did not attend the 11-10-2026 Damage Prevention Committee meeting. The DPC voted to accept INDEPENDENT ENTERPRISES' violation as presented in the Investigation Report and add $250 due to INDEPENDENT ENTERPRISES not attending the meeting. ***** INDEPENDENT ENTERPRISES disputing. ***** The incident occurred on 6/4/2026, at approximately 2:30 PM, on Valonia St, in Pittsburgh City, Allegheny County. A gas line owned by Peoples Natural Gas was damaged. An emergency ticket was entered for the damage. Peoples Natural Gas is the facility owner. Their Alleged Violation Report (AVR) states, "Independent Enterprises working for Pittsburgh Water struck and damaged a Peoples Gas 4in plastic main with mechanized equipment. All markings had been removed by the excavator. The attached locate and damage pictures will show that. This was the first of 4 damages to Peoples Gas mainlines within a 5 business day span by Independent (6/4/2026-6/10/2026). In addition, the damage ticket called in for this damage stated "Caller states line was not marked. Gas main was hit." The line was marked and the excavator failed to maintain markings. The fact that the markings were not visible due to the excavator removing them does not mean the line was not marked."	**INDEPENDENT ENTERPRISES: $750.00** Section 5(4) 1st Offense $750.00 **Verizon PA LLC: $1,000.00** Section 2(5)(v.2) 3rd Offense $1,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Independent Enterprises is the excavator. Their AVR states, “While excavating an exploratory on Valonia/Lorenz, contractor struck an unmarked 4" plastic main gas line at approximately 2:30 PM. The nearest marking was approximately 13 LF away from the damaged line. The field coordinator, Vic Murphy, was on site and notified when the incident occurred. Immediately after gas line was hit, contractor called 911 and contacted People's Gas. Fire department arrived on site at 2:37 PM. People's gas arrived on site at 3:05 PM to repair damaged gas line. People's gas stayed after hours to complete the repair. Gas line was fixed and trench was backfilled by People's Gas.” Pittsburgh Water & Sewer Authority is the project owner. Their AVR states, “While excavating an exploratory on Valonia/Lorenz, contractor struck an unmarked 4" plastic main gas line at approximately 2:30 PM. The nearest marking was approximately 13 LF away from the damaged line. The field coordinator, Vic Murphy, was on site and notified when the incident occurred. Immediately after gas line was hit, contractor called 911 and contacted People's Gas. Fire department arrived on site at 2:37 PM. People's gas arrived on site at 3:05 PM to repair damaged gas line. People's gas stayed after hours to complete the repair. Gas line was fixed and trench was backfilled by People's Gas.” GAI Consultants Inc is the designer. Their AVR states, “While excavating an exploratory on Valonia/Lorenz, contractor struck an unmarked 4" plastic main gas line at approximately 2:30 PM. The nearest marking was approximately 13 LF away from the damaged line. The field coordinator, Vic Murphy, was on site and notified when the incident occurred. Immediately after gas line was hit, contractor called 911 and contacted Peoples Gas. Fire department arrived on site at 2:37 PM. People's gas arrived on site at 3:05 PM to repair damaged gas line. Peoples gas stayed after hours to complete the repair. Gas line was fixed and trench was backfilled by Peoples Gas. Final Design One Call was run by GAI Consultants on 11/10/2025, which was within the required 10 to 90-day window prior to the end of final design. PA One Call info and Utility List were noted on the plan. The total project value is over $400,000. During design, SUE up to Quality Level (QL) A was performed. Record Drawing Research (QL-D) was done by the whole project team as the project moved through design. The surface expressions of utilities such as manholes, curb boxes, and valve boxes were surveyed (QL-C). The project owner had GAI include the cost to hire a utility locator as a subconsultant. Subconsultant Lexis Group ran an electric current through locate wires and metallic pipes to mark utility locations across the job (QL-B). Lexis Group surveyed the paint markings. GAI identified places where the QL-B needed clarification and had Lexis do Test Pits (QL-A) there.” Peoples Natural Gas marked their lines on the Routine Ticket for this excavation on 5/1/2026. Images are	

Case Number	Stakeholders	Summary	Violations & Recommendation
		submitted showing the marks placed on 5/1/2026. The excavator, and damage, occurred directly over a yellow mark placed on 5/1/2026. In the damage images the asphalt has been removed where the yellow mark was placed. The excavator also exposed the 4" line at another spot close to where the damage occurred. Marks are also shown for this line in the mark out images. Multiple images show the marks and damage, though image "400 lorenz markup" shows the comparison of the mark out and damage images. Routine Ticket# 20261180740 – Verizon did not enter a response by the response due date of 5/3/2026. This case is related to cases 044579, and 055772 by design tickets. Violations: Excavator - Independent Enterprises: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements. Facility Owner (Other) – Verizon: Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. T20261180740 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).	
65621	**Facility Owner:** Philadelphia Gas Works (PGW) **Contractor/Excavator:** UTILITY LINE SERVICES **Project Owner:** Philadelphia Gas Works (PGW) - Placeholder **Designer:** Philadelphia Gas Works (PGW) - Placeholder **Other:** Verizon PA LLC	On 6/8/2026 10:00:00 AM at W HUNTINGDON ST, PHILADELPHIA CITY, PHILADELPHIA On 11-10-2026 the Damage Prevention Committee voted to remove UTILITY LINE SERVICES' 5(4) violation. ***** "Utility Line Services (ULS) acknowledges the receipt of the attached invoice and would like to dispute the report. Are we able to be scheduled for a DPC meeting to discuss the allegations?" Additional information was provided after the original dispute that states, "We're only disputing 5(4). Additional pictures are attached. Regarding 5(8). We acknowledge that 911 was not called and our crews have since been trained that 911 should always be called if there's a gas leak based on the law." See ULS Images of damage for the pictures they provided. ***** The incident occurred on 6/8/2026, at approximately 10:00 AM, on W Huntingdon St, in Philadelphia City, Philadelphia County. A gas line owned by Philadelphia Gas Works was damaged. 911 was not contacted. Philadelphia Gas Works is the facility owner, project owner, and designer. Their AVR states, "Contractor	**UTILITY LINE SERVICES: $1,000.00** Section 5(8) 1st Offense $1,000.00 **Verizon PA LLC: $1,500.00** Section 2(5)(v.2) Subsequent $1,500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Utility Line Services struck properly marked gas service to 1227 W Huntingdon St using backhoe bucket. It was known ahead of time that service is shallow. CONTRACTOR ULS DAMAGED 1" PLASTIC SVC TO 1227 W HUNTINGDON". Utility Line Services is the excavator. Their AVR states, "Our crew was working in the area of 1227 Huntingdon Street. While stripping out the blacktop with the backhoe we pulled and damaged the gas service at 12" cover. The asphalt was thicker than normal. The service was marked but we believe this was a faulty installation as the standard is typically 18"." Ticket# 20261490794 had a response due date of 6/2/2026. Verizon responded "Field Marked" on 6/4/2026. Images submitted show the site, marks, excavation, and damaged line. The line that was damaged was within the tolerance zone of yellow marks. Violations: Excavator – Utility Line Services: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements. Facility 0wner (other) – Verizon: Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket# 20261490794 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).	