



Pennsylvania Public Utility Commission

**Damage Prevention Committee Meeting Case List
Oct. 8, 2024**

Omnibus Session

Case Number	Stakeholders	Summary	Violations & Recommendation
38880	<p>Facility Owner: PPL Electric Utilities</p> <p>Contractor/Excavator: EHC ASSOCIATES INC - Thousand Trails Circle M Resort</p> <p>Project Owner: EHC ASSOCIATES INC - Thousand Trails Circle M Resort - Placeholder</p>	<p><u>On 4/19/2023 2:57:00 PM at 2111 Millersville Road, PEQUEA TWP, LANCASTER</u> The incident occurred on 4/19/2023, at 2:57pm, at 2111 Millersville Road, Pequea Twp., Lancaster County.</p> <p>A PPL Electrical Line was damaged.</p> <p>PPL's alleged violation report (AVR) states "On Wednesday, 4/19/2023 at approximately 1457 a non-PPL employee of Thousand Trails Circle M Resort contacted an underground primary electric cable with a backhoe while digging to install a post at 2111 Millersville Road, Pequea Township, Lancaster County. There were no reported injuries. Four customers lost electrical service. The excavator did not place a PA One Call. PPL Public Safety spoke with employee William Button who stated they were digging to install a 4x4 post for a sign with a post hole digger. However, when PPL crews arrived on site, they observed a backhoe at the excavation and damage marks indicative of being caused by a backhoe. PPL crews installed a splice as a permanent repair. PPL One Call to work the site was made under ticket number 20231094524."</p> <p>On 12/21/2023 an AVR Letter was mailed to Thousand Trails Circle M Resort.</p> <p>EHC ASSOCIATES INC.'s alleged violation report (AVR) states "On 19 Apr 2023 the Maintenance staff was digging two holes to install a bulletin sign. They were digging by hand with a post hole digger when they struck the distribution line approximately 16" deep that support a section of campsites at Circle M Campground. 811 was never requested to make out the site prior to the dig." PA One Call noted at the bottom of the AVR that "ECH ASSOCIATES and Circle M Campground has not placed notifications with PA One Call in the past. ECH Associates and Circle M Campground are not Members of PA One Call."</p> <p>EHC ASSOCIATES INC. states in their AVR that the method of excavation was hand tools, but the pictures provided by both parties show an excavator and bucket/teeth marks in the dirt. EHC Associates Inc. is the owner of the resort, Thousand Trails Circle M Resort is the brand they acquired during acquisition.</p> <p>EHC ASSOCIATES INC. is in violation of sections: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe.</p>	<p>EHC ASSOCIATES INC - Thousand Trails Circle M Resort: \$1,750.00</p> <p>Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(16) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area.</p> <p>Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. Line strike was on 4/19/23, AVR was filed on 1/16/24.</p> <p>Recommendation: Education Required; penalties applied</p>	
38284	<p>Facility Owner: AMS ENERGY / HERMAN OIL AND GAS Facility Owner: AT&T LOCAL SERVICES Facility Owner: BLX INC / REDMILL DRILLING Facility Owner: BRIGHTON TOWNSHIP/BRIGHTON TOWNSHIP SEWAGE AUTHORITY/BRIGHTON TOWNSHIP MUNICIPAL Facility Owner: COMCAST CABLEVISION Facility Owner: GLASGOW BOROUGH Facility Owner: KRIEBEL MINERALS INC Facility Owner: NEW KINSINGTON CITY MUNICIPAL AUTHORITY Facility Owner: OHIOVILLE BOROUGH MUNICIPAL AUTHORITY Facility Owner: PENN TELECOM (CONSOLIDATED COMMUNICATIONS) Facility Owner: PITTSBURGH WATER AND SEWER AUTHORITY Facility Owner: PLUM BOROUGH Facility Owner: PLUM BOROUGH MUNICIPAL AUTHORITY Facility Owner: Verizon Facility Owner: West Penn Power / First Energy Facility Owner: WINDSTREAM Contractor/Excavator: OSMOSE UTILITIES</p>	<p>On 5/3/2023 8:00:00 AM at Multiple, <u>CARNEGIE BORO, ALLEGHENY</u> BLX disagreed and sent in documentation that they do not fall under ACT 50 law. This was confirmed by Rob. The violation Section v2(5)(v) is withdrawn.</p> <p>**First Energy disputes the violations and penalties saying that USIC attended the Complex Project Meetings on their behalf. None of the sign in sheets provided by the excavator show USIC or First Energy/West Penn Power attending and no comments are made about either entity in the notes. DPS Locke informed First Energy and asked if they wish to continue their dispute. ***** KRIEBEL MINERALS INC violation and penalty is removed. ***** *No Damage*</p> <p>A Complex Project telephone Conference was held and multiple facility owners did not respond to the ticket requests for the Complex project nor did they attend the Complex Project Meeting.</p> <p>* Alleged Violation Report (AVR) was not requested from the facility owners, which are listed as “other “in most cases and are not sent an AVR request letter. The Alleged Violation Report was submitted because of the issue that the excavator was having because the facility owners were not responding to tickets.</p> <p>OSMOSE UTILITIES SERVICES INC stated in their Alleged Violation Report (AVR) that “The following utility companies failed to respond through the AP One Call System or attend the pre construction meeting for an DLC Complex project held on 05/03/2023 at 8:00a.m. Serial Number 20231171235 AT&T Serial Number 20231172163 PENN TELLECOM AT&T Comcast Serial Number 20231171564 AMS Energy BLX Inc/Redmill Drilling Kriebel Minerals PENN TELLECOM West Penn Power Windstream Comcast Serial Number 20231171726 Ohioville Boro” See attached WORD document for a list of non attendees to the pre-construction teleconference call on Wednesday 05/03/2023 @ 8:00 A.M.</p> <p>Duquesne Light Company (DLC), the project owner was sent an AVR request on 11/05/2023. 12/04/2023 an email from DLC stated “I reached out to Rebecca from Osmose and my engineering team and I</p>	<p>AMS ENERGY / HERMAN OIL AND GAS: \$500.00 Section 2(5)(viii) 1st Offense \$500.00</p> <p>AT&T LOCAL SERVICES: \$3,000.00 Section 2(5)(viii) 3rd Offense \$1,500.00</p> <p>Section 2(5)(viii) 3rd Offense \$1,500.00</p> <p>BLX INC / REDMILL DRILLING: \$0.00</p> <p>BRIGHTON TOWNSHIP/BRIGHTON TOWNSHIP SEWAGE AUTHORITY/BRIGHTON TOWNSHIP MUNICIPAL: \$0.00</p> <p>COMCAST CABLEVISION: \$1,000.00 Section 2(5)(viii) 1st Offense \$500.00</p> <p>Section 2(5)(viii) 1st Offense \$500.00</p> <p>GLASGOW BOROUGH: \$500.00 Section 2(5)(viii) 1st Offense \$500.00</p> <p>KRIEBEL MINERALS INC: \$0.00</p> <p>NEW KINSINGTON CITY MUNICIPAL AUTHORITY: \$500.00 Section 2(5)(viii) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>SERVICES INC Project Owner: DUQUESNE LIGHT COMPANY Designer: DUQUESNE LIGHT COMPANY - Spaceholder</p>	<p>will do my best to answer your questions and submit an AVR, but I wanted to reach out to you to see if there was still a need for an AVR. This is a tough one to explain but I will do my best. Please feel free to call me to talk this out, sometimes my own verbal vomit even confuses me. So each pole that Osmose has worked on for DLC is considered its own project and has its own purchase order. Poles are considered independent assets and there was no plan as to which poles were worked on. As each pole was inspected it either passed or failed, which resulted in it being added to the list of poles Osmose would do their thing to. I was told there should be approx. 260 poles that Osmose worked on for us and none of them cost over \$400,000. With that price tag and it not being “planned work”, I take it to mean that we were not required to do a complex project, place a Prelim or Final Design ticket, or use SUE. Even though there was over 200 poles/work orders/One Call tickets created, the complex meeting was scheduled by Osmose as a courtesy to contact the local facility owners to discuss the extent of their work. There was no design ticket process followed because the project itself was simply modifying the existing poles by hand digging down 3 feet and either pounding a steel ‘C’ truss around the pole an additional 3ft deep or wrapping the pole in what they call FiberWrap. I have attached a snip I pulled of our workorder listing, you can see the cash amount paid out. Even the highest paid out was still under \$400,000, and the extent of the work does not warrant SUE to be used. Like I said above, they hand dug down 3ft around the pole and either drove in the steel truss or wrapped the pole in the FiberWrap. I understand now that Osmose submitted an AVR because of the lack of participation at the meeting, I was never told back in May that they submitted an AVR. And I will still submit one if you think it still needs done. I wanted to write this up for you to have some insight on what I’ve been working on and why it has taken so long for me to respond. Trying to track down work being done for my company by an outside vendor is more complicated that I thought it would be. DLC stated in their AVR that “Osmose Utilities Services Inc were hired by Duquesne Light Company to reinforce DLC's overhead poles that did not pass inspection. The Complex Meeting was to take place on 3 May 2023 but many Facility Owners did not respond or attend the meeting. We were asked to submit an AVR in response to the AVR Osmose submitted as the Excavator. They list the project as <\$400.000. They list the project as hand digging using hand tools. A report was provided. ***** *CP Ticket 20231171564 was submitted on 4/27/2023 with a response due by 5/02/2023 and the teleconference meeting to be held on 5/03/2023 at 8:00 a.m. Comcast did not respond clear until 5/4/2023. They did attend the meeting. Penn Telecom Inc did not respond clear until 5/04/2023.</p>	<p>OHIOVILLE BOROUGH MUNICIPAL AUTHORITY: \$500.00 Section 2(5)(viii) 1st Offense \$500.00</p> <p>PENN TELECOM (CONSOLIDATED COMMUNICATIONS): \$2,000.00 Section 2(5)(viii) 2nd Offense \$1,000.00</p> <p>Section 2(5)(viii) 2nd Offense \$1,000.00</p> <p>PITTSBURGH WATER AND SEWER AUTHORITY: \$0.00</p> <p>PLUM BOROUGH: \$500.00 Section 2(5)(viii) 1st Offense \$500.00</p> <p>Verizon: \$2,000.00 Section 2(5)(viii) Subsequent \$2,000.00</p> <p>West Penn Power / First Energy: \$0.00</p> <p>WINDSTREAM: \$500.00 Section 2(5)(viii) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>New Kensington City Municipal Authority had no response.</p> <p>Kriebel Minerals Inc. did not respond clear until 5/4/2023.</p> <p>Eastern Gas Trans responded that they would attend meeting. This needs to be updated after meeting is attended.</p> <p>Plum Borough had no response.</p> <p>Plum Borough Municipal Authority will attend meeting, but they are not signed in on the CPM sheet</p> <p>Verizon responded that they would attend meeting. This needs to be updated after meeting is attended. They are on the sign in sheet.</p> <p>AMS Energy LLC had no response.</p> <p>Windstream had no response until 5/4/2023. They are on the sign in sheet.</p> <p>BLX INC had no response.</p> <p>*CP Ticket 20231171726 was submitted on 4/27/2023 with a response due by 5/02/2023 and the teleconference meeting to be held on 5/03/2023 at 8:00 a.m.</p> <p>Ohioville Borough Municipal Authority never responded.</p> <p>Columbia Gas responded that they would attend meeting. This needs to be updated after meeting is attended. They are signed in on the CPMeeting sheet.</p> <p>Eastern Gas Transmission and Storage Inc responded that they would attend meeting. This needs to be updated after meeting is attended. They are signed in on the CPMeeting sheet.</p> <p>Glasgow Borough never responded.</p> <p>Brighton Twp will attend the meeting, but they are not on the sign in sheet.</p> <p>Beaver Gas will attend the meeting. This needs to be updated after meeting is attended. They are signed in on the CPMeeting sheet.</p> <p>Verizon responded not marked/ no access. This is not an appropriate response for a complex project meeting request. They are signed in on the CPMeeting sheet.</p> <p>*CP Ticket 20231172163 was submitted on 4/27/2023 with a response due by 5/02/2023 and the teleconference meeting to be held on 5/03/2023 at 8:00 a.m.</p> <p>Penn Telecom did not respond until 5/04/2023</p> <p>Pittsburgh Water and Sewer did not respond “Did not attend meeting DCTF” until 5/4/2023. They are not on the CP sign in sheet.</p> <p>AT&T never responded.</p> <p>Comcast did not respond Clear no facilities until 5/4/2023, although they did attend the meeting.</p> <p>*CPTicket 20231171235 was submitted on 4/27/2023 with a response due by 5/02/2023 and the teleconference meeting to be held on 5/03/2023 at 8:00 a.m.</p> <p>AT&T had no response.</p> <p>Complex Project Meeting Attendees: Osiose, Eastern Gas, Buckeye Pipeline, PA American Water, Columbia Gas, Comcast, PA Power, Peoples Gas, Marathon Pipeline, Allegheny Sanitary Sewer</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Authority, Westview Water Authority, GeoPetro / Beaver Gas Gathering and Verizon. ***** *****</p> <p>COMCAST CABLEVISION is in violation of Section: 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). Tickets 20231171564 and 20231171726 were not responded to. They are logged in on the CP meeting sheet. They were represented byUSIC. Recommendation: Penalty is applied. (Facility Owner/Locator education completed and passed by Comcast on 6/25/2024.)</p> <p>WINDSTREAM is in violation of Section: 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). Tickets 20231171564 was not responded to. They are not on the CPM sign-in sheet. Recommendation: Penalty is applied. (Facility owner and locator education was completed and passed by Windstream on 05/23/2024.)</p> <p>AMS ENERGY / HERMAN OIL AND GAS is in violation of Section: 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). Tickets 20231171564 was not responded to. They are not on the CPM sign-in sheet. Recommendation: Penalty is applied. Education is required.</p> <p>PENN TELECOM (CONSOLIDATED COMMUNICATIONS) is in violation of Section: 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). Tickets 20231171564 and 20231172163 were not responded to. They are not on the CPM sign-in sheet. Recommendation: Penalty is applied. Education is required.</p> <p>NEW KINSINGTON CITY MUNICIPAL AUTHORITY is in violation of Section: 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). Tickets 20231171564 and was not responded to. They are not on the CPM sign-in sheet. Recommendation: Penalty is applied. Education is required.</p> <p>PLUM BOROUGH is in violation of Section: 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). Tickets 20231171564 and was not responded to. They are not on the CPM sign-in sheet. Recommendation: Penalty is applied. Education is required.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>VERIZON PA LLC is in violation of Section: OHIOVILLE BOROUGH is in violation of Section: 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). Tickets 20231171726 and was not responded to. They are on the CPM sign-in sheet. Recommendation: Penalty is applied. Education is required.</p> <p>PLUM BOROUGH MUNICIPAL AUTHORITY is in violation of Section: 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). Tickets 20231171564 and was not responded to. They are not on the CPM sign-in sheet. Recommendation: Penalty is applied. Education is required.</p> <p>Glasgow Borough is in violation of Section: 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). Tickets 20231171564 and was not responded to. They are not on the CPM sign-in sheet. Recommendation: Penalty is applied. Education is required.</p> <p>AT&T Local Services are in violation of Section: 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). Tickets 20231171726 and 20231171235 was not responded to. They are not on the CPM sign-in sheet. Recommendation: Penalty is applied. (The facility owner/ locator education was completed and passed by AT&T on 02/22/2024.)</p>	
38366	<p>Facility Owner: UGI Contractor/Excavator: Wexcon, Inc Project Owner: JD Eckman Project Owner: PennDOT Designer: RKR HESS ASSOCIATES</p>	<p><u>On 5/3/2023 8:25:00 AM at BROADHEAD AVE, EAST STROUDSBURG BORO, MONROE</u> Incident occurred on 5/3/2023 at 8:25am at Brodhead Ave., East Stroudsburg Boro., Monroe County.</p> <p>A UGI gas line was hit.</p> <p>UGI's alleged violation report (AVR) states "WEXCON INC. WAS DIGGING TO INSTALL WATER MAIN. WHEN DOING SO THEY STRUCK A GAS SERVICE FACILITY CREATING A DAMAGE. WEXCON DID NOT MAINTAIN THE GAS MARKING FROM THE ORIGINAL LOCATE."</p> <p>Wexcon, Inc's alleged violation report (AVR) states "The Wexcon crew saw no markings for a gas service at this location so we were not anticipating any to be encountered. Markings for other gas lines were easily visible on the opposite side of the street curb. With no reason to believe there was a service in our trench area we did not hand dig the area. The excavator bucket caught the 1/2" plastic service and pulled it apart."</p>	<p>Wexcon, Inc: \$750.00 Section 5(3) 1st Offense \$500.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>On 11/21/23 an AVR request letter was mailed and e-mailed to JD Eckman and PennDOT. No AVR has been received by JD Eckman to date.</p> <p>PennDOT's alleged violation report (AVR) states "The Wexcon crew saw no markings for a gas service at this location so we were not anticipating any to be encountered. Markings for other gas lines were easily visible on the opposite side of the street curb. With no reason to believe there was a service in our trench area we did not hand dig the area. The excavator bucket caught the 1/2" plastic service and pulled it apart."</p> <p>On 3/7/2024 and AVR Request letter was mailed and e-mailed to RKR HESS ASSOCIATES.</p> <p>RKR HESS ASSOCIATES alleged violation report (AVR) states "Did not witness actual incident / Spot checking. Gas main was shown on plan / Lateral connections were not."</p> <p>Wexcon, Inc. is in violation of sections: Section 5(3) – Excavator failed to preserve mark-outs or request a remark. There are marking in the area of where the work was performed, but in the pictures provided, it does look like some of the original markings were removed throughout the project. Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. Recommendation: Penalties applied. (Wexcon completed and passed the excavator education on 08/26/2024.)</p>	
39698	<p>Facility Owner: Comcast Contractor/Excavator: Peoples Gas Project Owner: Peoples Gas - Placeholder</p>	<p>On 6/19/2023 10:00:00 AM at 517 Arthur Pl, GREENSBURG CITY, WESTMORELAND Peoples Gas disputed - after further investigation, DPI agreed to remove the violation and penalty.</p> <p>*****</p> <p>The incident occurred on 6/19/2023, at 10:00am, at 517 Arthur Pl., Greensburg City, Westmoreland County.</p> <p>A Comcast cable line was damaged.</p> <p>Comcast's alleged violation report (AVR) states "Failed to expose marked facilities, contractor cut an accurately marked Comcast feeder when they were digging to install new gas services."</p> <p>On 1/9/2024 an AVR Request Letter was mailed and e-mailed to Peoples Gas.</p> <p>Peoples Gas' alleged violation report (AVR) states "Peoples Gas had a crew renewing the gas service line at 519 Arthur Place in Greensburg when they stuck and damaged a mismarked Comcast buried cable line. The cable line was mis-marked by 48" per the crew excavating to renew the gas service line. The photos</p>	<p>Comcast: \$4,000.00 Section 2(5)(i) Subsequent \$2,000.00</p> <p>Section 2(5)(vii) 3rd Offense \$2,000.00</p> <p>Peoples Gas: \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>show the markings (flags) for the Comcast buried cable line being mis-marked in comparison to the damage."</p> <p>Comcast is in violation of sections: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Flags were in the vicinity, but not within 18 inches of the tolerance zone. Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification for Ticket 20231701717. Did not respond through Pa One Call. Recommendation: Penalties applied (Facility Owner/Locator education completed and passed by Comcast on 6/25/2024.)</p> <p>Peoples Gas is in violation of sections: Section 5(9) – Emergency notification does not meet the requirements of “emergency” as defined in Section 1 – Excavator Ticket. Damaging a cable line is not clear and immediate danger to life, property and environment. Recommendation: penalties applied (Excavator education completed and passed by Peoples Gas on 8/19/2024.)</p>	
40394	<p>Facility Owner: COLUMBIA GAS Contractor/Excavator: North Huntingdon Township - Spacesaver Project Owner: North Huntingdon Township</p>	<p><u>On 6/21/2023 8:15:00 AM at 1014 REBECCA ST, NORTH HUNTINGDON TWP, WESTMORELAND</u> Incident occurred on 6/21/2023 at 1014 Rebecca St., in North Huntingdon Township in Westmoreland County.</p> <p>A gas line was hit and damaged. This is the second gas line in the past 6 months that was hit by this same excavator. See case 39675.</p> <p>Columbia Gas, the facility owner, stated in their Alleged Violation Report (AVR) that “North Huntingdon Township was replacing storm sewer when they struck and damaged the accurately marked 1" plastic, low pressure, gas service feeding 1014 Rebecca St., North Huntingdon. They notified 911 and Columbia Gas when the damage occurred. Columbia Gas responded immediately to make the area safe and complete repairs. This is the second gas line damage on this project where the excavator failed to use prudent digging techniques within the tolerance zone to spot the line. Please see AVR2023JUN190019”. 911 was notified.</p> <p>North Huntingdon Township, the project owner, and excavator, was sent an AVR request letter on 6/21/2023. DPI also sent a request to Compliance Coordinator to verify that this is the townships project and not the Authorities. An email to the township also was sent and an External read receipt was received on 2/09/2024 – see attached. No AVR has been received to date. *Note that no AVR was submitted for case 39675 where a gas line was hit, damaged and repaired with duct tape, by this same excavator. The designer was not provided, even though this information was requested in the AVR request letter. *****</p>	<p>North Huntingdon Township: \$1,750.00 Section 5(16) 1st Offense \$500.00</p> <p>Section 5(4) 1st Offense \$500.00</p> <p>Section 5(17) 1st Offense \$250.00</p> <p>Section 6.1(3) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>*Ticket 20231421504 is also listed in case 39675 and was requested by North Huntingdon Township on 5/22/2023 with a response due by 5/24/2023.</p> <p>Ticket 20231652787 was requested by North Huntingdon Township to replace the storm sewer at 1014 Rebecca St. on 6/14/2023, with a response due by 6/16/2023. All facility owners responded timely. North Huntingdon Township is in violation of sections: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. 6.1(3) – Released a project to bid or construction before final design was complete. Recommendation: The penalties are applied and education is required.</p>	
39503	<p>Facility Owner: Husted Township Municipal Authority Contractor/Excavator: FRANCIS J. PALO INC. Project Owner: PENNDOT Designer: PENNDOT - SPACESAVER Other: NATIONAL FUEL GAS</p>	<p>On 6/22/2023 4:00:00 PM at SR 0255, HUSTON TWP, CLEARFIELD Incident occurred on 6/22/2023 on SR0255 in Huston Twp., in Clearfield County.</p> <p>A water line was hit and damaged. No One Call ticket was submitted for excavation.</p> <p>PENNDOT, the project owner and designer stated in their Alleged Violation Report (AVR) that the project cost was >\$400,000. The length of the project was 3.84 miles. Level “C” Subsurface Utility Engineering (SUE) was utilized. They note that prudent techniques were not being used in the tolerance zone. Pictures and documents were provided.</p> <p>FRANCIS J PALO INC, the excavator stated in their AVR that “/24/23 Utility Meeting Onsite/ D-419- See attached 4/10/23 PA One Call- See attached 4/10/23-6/22/23 and continuing. Numerous onsite meetings and phone calls with onsite Francis Palo Inc. Supervisor and Huston Township Water Authority. Good communication and Utility Coordination between the two parties. 6/22/23 Segment 320- Offset 1725. (see attached sheet 37 of 39) (Please note that the plan design shows waterline on the left side of the road which was incorrect) - Huston Township marked it on the right side of the road but unfortunately was off by 36" from the centerline of the flag. 2:45 Excavation and potholing at incident site 3:15 Excavation was clear and outside the tolerance zone- Waterline was determined to be below elevations required. 3:30 Waterline was laying directly overtop of the remaining existing 48" drain pipe required to be removed and was actually flexed over it and was damage unexpectedly. Palo notified and called John Kruel immediately. 4:00 Waterline turned off- Huston Township started repair process 8:00 Waterline turned back on. Pictures and documents were provided. Additional comments: 8" PVC waterline was located by witching method- line was placed in 1973 very few records exist.</p>	<p>FRANCIS J. PALO INC.: \$1,000.00 Section 5(2.1) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Compliance Research results: Francis J Palo Inc has placed notifications with PA One Call in the past.</p> <p>Husted Township Municipal Authority, the facility owner stated in their AVR that “Palo Construction was doing a job for PennDOT installing cross drains, when one of their excavators struck our water line. We, the Municipal Authority were notified and were on scene within 10 minutes and shut the water off. Our line was marked on the edge of tolerance. Palo agreed to dig up the rest of the pipe for the Authority to make the repair. The repairs were made with materials on hand. The estimated cost of the materials was \$1,100.00. Palo has not hit 2 or more of our lines within a 6 month period”.</p> <p>Complex Project meeting was held on 2/24/2023. This is prior to the time that the complex project ticket was submitted. CPM attendees: HTMA, Penelec, and PennDOT. Noted as not attending are: National Fuel Gas, Windstream Communications and Zito Communications, LLC. National Fuel Gas had responded to the ticket with conflict and then responded to the ticket with engineering completed. They should have attended the Complex Project meeting if they have facilities, or are planning with engineering, to have facilities in the area.</p> <p>*****</p> <p>Preliminary Design Ticket 20220911862 was submitted by PennDOT on 4/1/2022 with a response due by 4/15/2022. Details: WORKING ON SR 255 FROM INTER OF SR 153 TO CLEARFIELD COUNTY ELK COUNTY LINE APPX 3 AND 3/4MI JUST BEYOND TOWN OF HOLLYWOOD. MULTIPLE LOCATIONS ON SR 255 ON EITHER SIDE. COORDINATES FOR STARTING POINT AND APPROXIMATE ENDING POINT. REMOVING HEADWALLS INSTALLING NEW HEADWALLS REMOVING DETERIOTATED PIPE INSTALLING NEW PIPE AND IN SOME CASES EXTENDING 4FT. All responses were timely. Huston Township Municipal Authority field marked.</p> <p>Complex Project Ticket 20231002324 was submitted by FRANCIS J PALO INC on 4/10/2023 with no meeting requested stating that the meeting was already held on 2/24/2023. Response was due by 4/23/2023. National Fuel Gas responded clear on 4/10/2023, Conflict on 4/11/2023 and Field marked on 6/12/2023. Huston Township Municipal Authority field marked.</p> <p>Preliminary Design Ticket 20220911862 was requested by PennDOT for drainage work on 4/01/2022 with a response due by 4/15/2022. All facilities responded timely.</p> <p>*No Final Design Ticket. * No excavation ticket</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>***** **</p> <p>Francis J Palo Inc is in violation of Section: 5(2.1) Excavator failed to submit a location request to One Call within the correct timeframe. Recommendation: Penalty is applied. Education is required.</p>	
39749	<p>Facility Owner: Verizon Contractor/Excavator: Shainline Excavating, Inc. Project Owner: Upper Southampton Water Authority</p>	<p><u>On 6/29/2023 12:30:00 PM at PEARL DRIVE, UPPER SOUTHAMPTON TWP, BUCKS</u> The incident occurred on 6/29/2023, at 12:30pm, at Pearl Drive, Upper Southampton Twp., Bucks County.</p> <p>A Verizon cable line was damaged.</p> <p>Shainline Excavating, Inc.'s alleged violation report (AVR) states "During excavation on 6/29/2023 our backhoe hit an unmarked fiber optic verizon line. This occurred around 1230pm. A verizon personal responded to see if someone needed to come out. At 530pm this line was still not repaired. Homeowner was very angry due to his internet not working. Homeowner, concontractor, Pa1, and township all notified Verizon to make them aware. At 530pm contractor contacted Verizon again to express concern that this line was still not repaired and the owner was without his internet. On 6/28/2023 a renotify was placed to verizon and no one responded. Pa 1 Notified"</p> <p>On 1/9/2024 an AVR Request Letter was e-mailed and mailed to Verizon and Upper Southampton Water Authority.</p> <p>Verizon's alleged violation report (AVR) states "Per Verizon Local Manager, Al Warnick, Verizon is not aware of any damage to Verizon facilities at this location."</p> <p>Upper Southampton Water Authority's alleged violation report (AVR) states "On 6/29/2023, our contractor hit an unmarked fiber optic Verizon line at about 12:30pm. A rep from Verizon responded to the site. The homeowner who was working from his house was extremely upset that Verizon that it took Verizon several hours to restore his service."</p> <p>Verizon is in violation of sections: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3) for Ticket 20231564381. Did not respond in a timely manner, response was due 6/11/23. Then responded "Clear" on 6/24/23, a few days before their line was hit. Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3) for Ticket 20231564382. Did not respond in a timely manner, response was due</p>	<p>Verizon: \$7,000.00 Section 2(5)(i) Subsequent \$2,000.00</p> <p>Section 2(5)(viii) Subsequent \$2,000.00</p> <p>Section 2(5)(viii) Subsequent \$2,000.00</p> <p>Section 2(5)(v) Subsequent \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>6/11/23. Then responded "Clear" on 6/24/23, a few days before their line was hit. Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time for Ticket 20231672618. Initially responded "Clear" on 6/16/23. A renotify ticket went out, Verizon did not respond to the renotify, response was due 6/28/23. Verizon responded "Clear" to the renotify Ticket on 6/29/23. Recommendation: penalties applied</p>	
39866	<p>Facility Owner: Columbia Gas of PA Facility Owner: Peoples Gas Contractor/Excavator: Proscap Landscape Supply LLC Project Owner: Lindy Paving Other: Dormont Borough</p>	<p><u>On 6/30/2023 7:50:00 AM at 3053 GRASSMERE AVE, DORMONT BORO, ALLEGHENY</u> The incident occurred on 6/30/2023, at 7:50am, at 3053 Grassmere Ave., Dormont Boro., Allegheny County.</p> <p>A Columbia Gas line was damaged. 911 was called.</p> <p>Peoples Gas' alleged violation report (AVR) states "Proscap was completing brick street replacement on Grassmere Ave. when they struck and damaged a properly marked 1" plastic low pressure gas service line 6" from the marks, well within the tolerance zone. Proscap failed to exercise due care and take all reasonable steps to prevent damaging an underground facility."</p> <p>Columbia Gas' alleged violation report (AVR) states "Proscap damaged an accurately marked 1" plastic, low pressure gas service line with a backhoe while doing restoration work for Lindy Paving. Proscap notified 911, and Columbia Gas was notified by an employee with Peoples Gas. Columbia Gas responded immediately to make the area safe and complete repairs. The local Field Operations Leader from Columbia Gas reminded the crew that they are required to use prudent digging techniques when digging around any underground facilities."</p> <p>Proscap's alleged violation report (AVR) states "Apparently whilst digging to the proper road base depth gas was smelled and excavation ceased."</p> <p>On 2/5/2024 an AVR Request Letter was mailed and e-mailed to Lindy Paving.</p> <p>Lindy Paving's alleged violation report (AVR) states "Digging for road base repair with an excavator working to a depth of 12". Did notice the smell of gas and stopped digging"</p> <p>Proscap Landscape Supply LLC is in violation of sections: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: penalties applied</p> <p>Dormont Borough is in violation of sections: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time for Ticket 20231143497. Responded "Clear" on 4/27/23. Response was due 4/26/23.</p>	<p>Proscap Landscape Supply LLC: \$500.00 Section 5(4) 1st Offense \$500.00</p> <p>Dormont Borough: \$1,500.00 Section 2(5)(v) 1st Offense \$250.00</p> <p>Section 2(5)(v) 1st Offense \$250.00</p> <p>Section 2(5)(vii) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time for Ticket 20231601272. Responded "Clear" on 6/17/23. Response was due 6/13/23.</p> <p>Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification for Ticket 20231810987. Responded "Clear" on 7/3/23. Response was due 6/30/23.</p> <p>Recommendation: Education Required; penalties applied</p>	
39721	<p>Facility Owner: UGI Contractor/Excavator: S&M General Services Project Owner: Homeowner</p>	<p><u>On 7/7/2023 8:41:00 AM at 430 WILLIAMS ST., EASTON CITY, NORTHAMPTON</u> The incident occurred on 7/7/2023, at 8:41am, at 430 Williams St., Easton City, Northampton County.</p> <p>A UGI gas line was damaged. 911 was called.</p> <p>UGI's alleged violation report (AVR) states "S&M GENERAL CONTRACTING WAS DIGGING WITHOUT A PA ONE CALL TICKET AND WHEN DIGGING TO REPAIR SIDEWALK THEY STRUCK A GAS SERVICE FACILITY."</p> <p>On 1/9/2024 an AVR Request Letter was mailed and e-mailed to S&M General Services and a letter mailed to the homeowner.</p> <p>Homeowner's alleged violation report (AVR) states "while contractor was digging up sidewalk excavator pulled up gas line. Position wasn't marked. They called UGI First guy did air check. Check valve in street shut gas off. Second crew dug up street connection. they repaired tubing."</p> <p>S&M General Services alleged violation report (AVR) states "On July 7 2023, i was excavating the old city sidewalks at 430 Williams Street in Easton Pa. I hit the gas line for the property that was only 9 inches down, i called 911 right away to have the gas shut off so it could be repaired."</p> <p>S&M General Services is in violation of sections: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. Section 5(9) – Emergency notification does not meet the requirements of “emergency” as defined in Section 1 – Excavator Ticket. Type of Work--[REPL SIDEWALKS] is what is listed on Emergency Ticket 20231881158. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. Line hit was on 7/7/23, AVR was filed 1/16/24. Recommendation: Education Required; penalties applied</p>	<p>S&M General Services: \$2,750.00 Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(9) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$500.00</p>
39807	<p>Facility Owner: Comcast Contractor/Excavator: Kriger Pipeline Project Owner: Aqua PA</p>	<p><u>On 7/10/2023 10:00:00 AM at 157 EDGEWOOD DR E, SOUTH ABINGTON TWP, LACKAWANNA</u> Withdrew Comcast's violation due to not having enough information - Conflicting date of emergency/damage and location/address of the damage.</p>	<p>Comcast: \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	Designer: ENTECH ENGINEERING	<p>*****</p> <p>The incident occurred on 7/10/2023, at 10:00am, at 157 Edgewood Dr. E, South Abington Twp., Lackawanna County.</p> <p>A Comcast cable line was damaged.</p> <p>Aqua's alleged violation report (AVR) states "Aqua Contractor Kriger Pipeline damaged unmarked cable wire. Other facilities were located, this cable was on its own away from the other field marks. 157 Edgewood East."</p> <p>Kriger Pipeline's alleged violation report (AVR) states "This was an unmarked cable wire. The pictures show other facilities that were located. This cable was on its own away from the other field marks."</p> <p>Entech Engineering's alleged violation report (AVR) states "This was an unmarked cable wire. The pictures show other facilities that were located. This cable was on its own away from the other field marks."</p> <p>On 2/5/2024 an AVR Request Letter was mailed and e-mailed to Comcast. No AVR has been received from Comcast to date.</p> <p>Comcast is in violation of sections: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: Penalties applied (Facility Owner/Locator education completed and passed by Comcast on 6/25/2024.)</p>	
40181	Facility Owner: Columbia Gas Contractor/Excavator: Mortimer Excavating Project Owner: Pennsylvania American Water (PAWC) Other: Verizon	<p>On 7/14/2023 9:05:00 AM at FAIRGREEN AVE, NESHANNOCK TWP, LAWRENCE Columbia Gas disputed - DPI reviewed the information submitted by Columbia Gas and withdrew the violation and penalty.</p> <p>*****</p> <p>The incident occurred on 7/14/2023, at 9:05am, at Fairgreen Ave., Neshannock Twp., Lawrence County.</p> <p>A Columbia Gas line was damaged.</p> <p>Columbia Gas' alleged violation report (AVR) states "Mortimer Excavating was working on a water project when they struck and damaged an unmarked 1" plastic, idle stub. They notified the Columbia Gas locator when the damage occurred, but did not immediately notify 911. Columbia responded immediately upon notification to make the area safe and complete repairs. The Columbia crew abandoned the idle stub at the gas main. Records have been updated. The local Damage Prevention Specialist reminded Mortimer of the requirement to also notify 911 immediately whenever there is a release of gas. The active gas facilities within the scope of this ticket were located accurately. The locator did notify the excavator of the existence of</p>	<p>Columbia Gas: \$0.00</p> <p>Mortimer Excavating: \$1,000.00 Section 5(8) 1st Offense \$1,000.00</p> <p>Verizon: \$1,500.00 Section 2(4) Subsequent \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>known abandoned lines that were unable to be located. There was no reason to believe that this gas service had not been abandoned at the gas main."</p> <p>On 2/6/2024 an AVR Request Letter was mailed and e-mailed to Mortimer Excavating and Pennsylvania American Water (PAWC).</p> <p>Mortimer Excavating's alleged violation report (AVR) states "Digging for new water main on fairgreen avenue, hit live unmarked gas line service in the road approximately 32" deep. Line was running into house number 412 that was not supposed to have gas supply. Gas company was notified when damaged."</p> <p>Pennsylvania American Water (PAWC)'s alleged violation report (AVR) states "Contractor of PAAW was installing new water main along Fairgreen Ave. While trenching in front of 412 Fairgreen Ave they hit an unmarked live gas line."</p> <p>Columbia Gas is in violation of sections: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: penalties applied</p> <p>Mortimer Excavating is in violation of sections: Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. Did not call 911. Recommendation: Education Required; penalties applied</p> <p>Verizon is in violation of sections: Section 2(4) – Failed to respond to designer’s request for information within 10 business days for Ticket 20222443032. Did not respond through Pa One Call. Recommendation: penalties applied</p>	
40378	<p>Facility Owner: UGI Contractor/Excavator: KENETIC Project Owner: WINDSTREAM Other: COMCAST CABLEVISION Other: PPL Other: UGI</p>	<p><u>On 7/19/2023 12:55:00 PM at STARTING FROM 71 WASHINGTON ST TO 105 CHERRY TREE. AT 71 WASHINGTON ST STARTING AT PED 3103-015 GOING TO RISER POLE 3101-002 AND EXTENDNING TO PED 3103-035., TURBOTVILLE BORO, NORTHUMBERLAND</u> For Comcast Cablevision, PPL Electric and UGI the, 2(5)(v)20231370996, All Penalties and Violations have been Removed because they all responded to their agreed Scheduled Mark By Dates. See attached the All Responses- 20231370996</p> <p>*****</p> <p>Incident occurred on 7/19/2023 at 40 Cherry Tree Ln. in Turbotville in Northumberland County.</p> <p>A gas service line was hit and damaged. 911 was notified.</p> <p>UGI UTILITIES INC stated in their Alleged Violation Report (AVR) that “Contractor hit and damaged a 1/2" plastic service while using a drilling machine. There was</p>	<p>WINDSTREAM: \$2,000.00 Section 2(5)(v) 1st Offense \$250.00</p> <p>Section 6.1(3) 1st Offense \$500.00</p> <p>Section 9 1st Offense \$250.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(16) 1st Offense \$500.00</p> <p>Section 2(5)(v) 1st Offense \$250.00</p> <p>COMCAST CABLEVISION: \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>no 1-call in this area of work”. Pictures were provided. Pictures show work done in the cul-du-sac.</p> <p>*Note that Kenetic who is listed in the AVR submitted by UGI as the excavator. Kenetic is a subsidiary of Windstream. Windstream lists themselves as the excavator and Project owner in their AVR.</p> <p>Compliance Research results: Kenetic has not placed notifications with PA One Call in the past.</p> <p>Kenetic was emailed and mailed an AVR request on 2/6/2024. Email was returned non deliverable. Per on-line information, Kenetic is part of Windstream.</p> <p>WINDSTREAM was emailed and mailed an AVR request on 2/6/2024. AVR was received on 2/29/2024. This is past the 10-working-days requirement to file an AVR when an excavator hits or damages an underground line.</p> <p>Windstream stated in their AVR that “Windstream was digging outside the scope of work on the ticket and hit a gas line”. *****</p> <p>*Ticket 20231872013 was requested by Windstream Communications inc., on 7/06/2023 with a response due by 7/10/2023. This is an update ticket to Plow Directional Drill and Trencher. Project is expected to take 1 week. All facility owners responded timely.</p> <p>*Ticket 20231370996-*000 was requested by Windstream Communications Inc. on 5/17/2023 with a response due by 5/19/2023. This was for a project that was expected to last 1 week for Plowings, Directional Drill and Trencher. The specific area was starting from 71 Washington St. to 105 Cherry Tree and from 71 Washington St. at PED 3103-035 going to riser pole 3101-002 and extending to PED 3103-035. UGI field marked late on 5/24/2023. There are no notes showing that this was in mutual agreement. Windstream field marked on 5/30/2023. On 5/19/2023 the excavator was contacted, and the due date was extended. The contact was 2 days after the ticket due date. Comcast was flagged late in the work area on 5/30/2023. There are no notes showing that the late mark-out is in mutual agreement. PPL Electric marked late on 5/30/2023. There are no notes showing that the late mark-out is in mutual agreement.</p> <p>*20231370996-*001 was requested by Windstream Communications Inc. with a response due by 5/30/2023. Work Site is Washington St. RNO Remarks – ATTN: Comcast Cable and PPL Electric, you responded as insufficient Information DO Not Dig. Please respond to recheck and mark lines and</p>	<p>PPL: \$0.00</p> <p>UGI: \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>call with any questions. Attn; Windstream, please respond to mark lines and respond in the Karl System. Comcast was flagged late in the work area on 5/30/2023. There are no notes showing that the late mark-out is in mutual agreement.</p> <p>PPL Electric marked late on 5/30/2023. There are no notes showing that the late mark-out is in mutual agreement.</p> <p>Windstream field marked on 5/30/2023. On 5/19/2023 the excavator was contacted, and the due date was extended. The contact was 2 days after the ticket due date.</p> <p>*****</p> <p>Windstream is in violation of Sections: 2(5)(v) 2(5)(v) Failed to respond to a routine One Call ticket 20231370996-001 within the required amount of time. 6.1(3) – Released a project to bid or construction before final design was complete. 9 – Failed to make best efforts to comply with Common Ground Alliance Best Practices. Common Ground Alliance (CGA) Best Practices 15.0 (5-29) Trenchless Excavation. 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. This excavator, who is also the project townner and designer, notified the facility owner and 911. An AVR was not provided until the Damage Prevention Investigator sent a courtesy request letter. Recommendation: The penalties are applied. Education is required. (Windstream completed and passed excavator education on 08/26/2024.)</p>	
42066	<p>Facility Owner: UGI Utilities Contractor/Excavator: H&K Group Project Owner: PennDOT Designer: McCormick Taylor Other: Verizon</p>	<p><u>On 10/2/2023 8:50:00 AM at SR443, LEHIGHTON BORO, CARBON</u> Incident occurred on October 2nd, 2023, at 8:50am along State Route 443, Lehighnton Boro, Carbon County.</p> <p>A gas line was damaged.</p> <p>UGI's Alleged Violation Report states, "H&K WAS DIGGING TO INSTALL SEWER LINE AND WHEN DOING SO THEY STRUCK A CORRECTLY MARKED GAS SERVICE FACILITY TO ADDRESS 35 BLAKESLEE BLVD. CREATING A LEAK AND A DAMAGE. H&K WAS DIGGING IN THE TOLERANCE ZONE." AVR notes that 911 was notified.</p> <p>UGI's pictures show that the line was marked within the tolerance zone.</p> <p>PennDOT's AVR states, "Excavator was installing drain lines and hit a gas service that was uncovered and located while the utility owner was present."</p>	<p>H&K Group: \$1,000.00 Section 5(16) 1st Offense \$500.00</p> <p>Section 5(4) 1st Offense \$500.00</p> <p>McCormick Taylor: \$500.00 Section 4(2) 1st Offense \$500.00</p> <p>Verizon: \$500.00 Section 2(5)(viii) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Final Design Ticket numbers: 20142651924, 20142651925, 20142651926 and 20142721317 Designer: Taylor Wiseman Taylor Utility Clearance Received: 4/20/2020 Project was Let: 9/03/2020</p> <p>H&K was mailed and emailed to complete an AVR on 2/15/2024. Received an email stating they were in Texas and would submit AVR upon return. No AVR was submitted 10 business days after the line strike or since the courtesy email and letter were sent.</p> <p>Verizon failed to respond to complex ticket 20210072259.</p> <p>Violations:</p> <p>H&K Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Education is required. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. Education is required.</p> <p>McCormick Taylor Section 4(2) – Designer failed to request the line and facility information prescribed by section 2(4) from the One Call System not less than ten nor more than ninety business days before final design is to be completed. Education is required.</p> <p>Verizon Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3).</p>	
42123	<p>Facility Owner: Comcast Contractor/Excavator: PRECISION PIPELINE SOLUTIONS Project Owner: Columbia Gas of PA - East</p>	<p><u>On 10/2/2023 11:45:00 AM at 39 WASHINGTON RD, NEW FREEDOM BORO, YORK</u> Incident occurred on October 2nd, 2023, at 11:45am, 39 Washington road, New Freedom Boro, York County.</p> <p>Precision Pipeline Solutions' Alleged Violation Report (AVR) states, "The was installing a new gas service and while digging a pit around the gas main they hit an unmarked Comcast line."</p> <p>UGI's AVR states, "Precision Pipeline Solutions, working on behalf of Columbia Gas, was installing a 1" plastic gas service to 39 Washington Rd., New Freedom, when they damaged an unmarked Comcast line with their mini excavator. They notified 911 when the damage occurred. There were two cable lines that ran on both sides of the road. The USIC Locater had marked the one line on the same side of the road as the property but forgot to mark the line on the opposite side. The locate marks in the attached damage pictures were placed after the damage notification."</p> <p>Comcast was mailed and emailed a request to submit an AVR on 2/27/24. Precision Pipeline has hit two or more</p>	<p>Comcast: \$2,500.00 Section 2(5)(i) Subsequent \$2,000.00</p> <p>Section 2(10) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Comcast lines within six months. Comcast AVR2024FEB020027 from case 44186 confirms that Precision Pipeline also hit a line on 1/05/2024. No AVR has been received from Comcast. Comcast was notified a second time to submit an AVR. An AVR was submitted on 4/4/24.</p> <p>Comcast's AVR states, "CUT UG 500 CABLE."</p> <p>Violations:</p> <p>Comcast Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. (Facility Owner/Locator education completed and passed by Comcast on 6/25/2024.) Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. (Facility Owner/Locator education completed and passed by Comcast on 6/25/2024.)</p>	
42118	<p>Facility Owner: UGI Utilities Contractor/Excavator: GENXC GROUP Project Owner: FASTBRIDGE FIBER Designer: Genxc group</p>	<p><u>On 10/3/2023 8:00:00 AM at 1618 ELLIOTT ST, LOYALSOCK TWP, LYCOMING</u> Incident occurred on October 3rd, 2023 at 8am at 1618 Elliot Street, Loyalsock Township, Lycoming County.</p> <p>A gas line was hit.</p> <p>UGI's Alleged Violation Report (AVR) states, "Contractor hit and damaged an accurately marked 1/2" plastic service with a mole. Service was not exposed for the passing of the mole." 911 was notified.</p> <p>Fastbridge Fiber's AVR states, "October 3rd, GenXC struck a gas line in a few places. Please see the attached images that were provided by a contractor for FastBridge. GenXC provided the report to FastBridge on October 18th per the attached report .pdf files and email correspondence. We have no further details at this time." 911 was notified.</p> <p>Genxc was mailed and emailed a request for an AVR on 2/26/24. Genxc submitted a blank AVR on 3/14/2024. Genxc Group is the designer and excavator. AVR request letter asked for the following along with a completed AVR to www.palcall.org: What was the total cost of the project? What was the total length of the project? What process of SUE was used? Please upload/send a copy of the design. Please upload pertinent pre – excavation photos and damage photos with your AVR.</p> <p>36 tickets including the complex meeting ticket were placed prior to the final design ticket 20231242055.</p>	<p>GENXC GROUP: \$3,000.00 Section 4(2) 1st Offense \$500.00</p> <p>Section 4(4) 1st Offense \$250.00</p> <p>Section 4(8) 1st Offense \$500.00</p> <p>Section 5(4) 1st Offense \$500.00</p> <p>Section 5(11.2) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$500.00</p> <p>Section 5(17) 1st Offense \$250.00</p> <p>FASTBRIDGE FIBER: \$1,500.00 Section 6.1(1) 1st Offense \$500.00</p> <p>Section 6.1(3) 2nd Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Violations:</p> <p>Fastbridge Fiber Section 6.1(1) – Failed to utilize sufficient quality levels of subsurface utility engineering or other similar techniques to properly determine the existence and positions of underground facilities when designing known complex projects having an estimated cost of (\$400,000) or more. Education is required. Section 6.1(3) – Released a project to bid or construction before final design was complete. Education is required.</p> <p>GENXC Group Section 4(2) – Designer failed to request the line and facility information prescribed by section 2(4) from the One Call System not less than ten nor more than ninety business days before final design is to be completed. Education is required. Section 4(4) – Failed to prepare construction drawings to avoid damage to and minimize interference with facilities in the construction area. Education is required. Section 4(8) – Designer failed to submit an Alleged Violation Report through the One Call System within 30 business days of being notified or aware that a violation of this act may have been committed. Education is required. Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. (Excavator education completed and passed by GenXC Group on 7/11/2024.) Section 5(11.2) – When using Horizontal Directional Drilling (HDD), Excavator failed to utilize the best practices published by the HDD Consortium. (Excavator education completed and passed by GenXC Group on 7/11/2024.) Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. (Excavator education completed and passed by GenXC Group on 7/11/2024.) Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. (Excavator education completed and passed by GenXC Group on 7/11/2024.)</p>	
43070	<p>Facility Owner: UGI UTILITIES INC Contractor/Excavator: RENEWABLE PROCESSING, INC Project Owner: Homeowner</p>	<p><u>On 11/8/2023 8:29:00 AM at 10795, State Route 44, Watsontown, WATSONTOWN BORO, NORTHUMBERLAND</u> Incident occurred on 11/08/2023, at 8:29 AM, on State Route 44 in Watsontown Boro, Northumberland County.</p> <p>A gas line was hit and damaged. A PA One Call ticket was not placed.</p> <p>UGI submitted an Alleged Violation Report (AVR) on 11/14/2023. Their AVR states, "No 1-Call had been placed. Contractor was digging for a retaining wall when they hit and damaged a gas service." Photos were submitted.</p> <p>RENEWABLE PROCESSING, INC. submitted an AVR on 02/28/2024, in response to the AVR request letter</p>	<p>RENEWABLE PROCESSING, INC: \$2,000.00 Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$500.00</p> <p>Section 5(17) 1st Offense \$250.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>sent 02/15/2024. Their AVR states, "Renewal Processing Inc. was installing a retaining wall and ruptured the gas service lateral for Renewal Processing's facility." AVR states the project owner is the 'Property Owner'.</p> <p>An AVR was not requested from the Project Owner/ Property Owner.</p> <p>Violations:</p> <p>RENEWABLE PROCESSING, INC- (No prior violations located.)</p> <ul style="list-style-type: none"> - Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Recommendation: Education required, and penalty applied. - Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. Education required, and penalty applied. - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. Education required, and penalty applied. - Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. Education required, and penalty applied. (Additional questions in the AVR courtesy notice.) 	
43072	<p>Facility Owner: UGI UTILITIES</p> <p>Contractor/Excavator: Dave Gutelius Excavating Inc</p> <p>Project Owner: PJ Holdings, LLC</p>	<p><u>On 11/9/2023 8:00:00 AM at 1308 PARK AVE, WILLIAMSPORT CITY, LYCOMING</u> Incident occurred on 11/09/2023, at 8:00 AM, at 1308 Park Ave, Williamsport City, Lycoming County.</p> <p>A gas line was hit. Utility markings were not maintained.</p> <p>UGI UTILITIES submitted an Alleged Violation Report (AVR) on 11/14/2023. Their AVR states, "Contractor hit, and damaged a gas service due to not maintaining the marks." Photos were submitted.</p> <p>DAVE GUTELIUS EXCAVATING INC submitted an AVR on 11/16/2023. Their AVR states, "Excavating landscape islands in a new parking lot area for placing topsoil and hit a 2" gas service. The site was One Called and the utilities were marked. When the paving was completed, it covered over all the One Call marks. We were then asked to scratch out 4 landscape islands to make room for some topsoil and that's when the gas line was damaged." Photos were submitted.</p> <p>PJ Holdings, LLC. submitted an AVR in response to the AVR request letter by email and USPS on 02/21/2024. Their AVR states, "A new parking lot was being built. A gas line runs under the lot and ran through a shade tree island. The lot was fully paved when the incident occurred. The excavator was preparing the tree pit and hit the gas line." An emailed response was received 02/21/2023 from PJ Holdings, LLC. They answered the bolded questions on the AVR to the best of their</p>	<p>Dave Gutelius Excavating Inc: \$500.00 Section 5(6)(i) 1st Offense \$0.00</p> <p>Section 5(3) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>knowledge and stated they couldn't complete an AVR without a login. An email reply was sent advising that an account would need to be established with PA One Call, to file an AVR.</p> <p>Violations:</p> <p>DAVE GUTELIUS EXCAVATING INC- - Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. Recommendation: Education required, and penalty applied. (No prior violation of 5(6)(i) located.) - Section 5(3) – Excavator failed to preserve mark-outs or request a remark. Recommendation: Education required, and penalty applied. (No prior violation of 5(3) located.)</p>	
43041	<p>Facility Owner: Peoples Natural Gas Contractor/Excavator: LAMBERT CABLE SPLICING Contractor/Excavator: Lonestar Line Construction - Sub Contractor Project Owner: Verizon Other: Perry Township Jefferson County</p>	<p><u>On 11/10/2023 10:15:00 AM at 10687 SR 0536, PERRY TWP, JEFFERSON</u> Incident occurred on 11/10/2023 at 10:15 AM, at 10687, SR 0536, near the intersection of Hamilton Markton Road, in Perry Township, Jefferson County.</p> <p>A 2" steel main gas line was hit with Hand Tools</p> <p>Peoples Natural Gas submitted an Alleged Violation Report (AVR) on 11/13/2023. Their AVR states, "Contractor was digging around a pole when they started to smell gas. Contractor stated they were using hand tools but the pictures look as if an auger hit the gas line. Lonestar was working for Verizon. Contractor hit a 2" steel medium pressure main line".</p> <p>Lonestar Line Construction submitted an AVR on 03/14/2024, in response to the AVR request letter sent 02/21/2024. Their AVR states, "Lonestar Line construction LLC is a sub contractor for Lamberts Cable splicing LLC. Lamberts is a prime contactor for Verizon Wireline in the state of PA. On 11/10/23 Lonestar was dispatched on an short notice emergency pole set. The Verizon owned utility pole had power and telecommunications lines attached to it. It was struck by lightning. Crew responded daylight on 11/10 and began to hand dig. Excavation for the new utility pole was approx. 4' wide (circular) and needed to be 6.5' deep. Upon digging to that depth crew contacted a gas line, shut down the site, and called PAOC alerting the facility owner and local protective services. Gas company responded and secured / repaired damaged line. Once repairs were complete; new pole placement was location moved and pole placed. Gas company placed a marker new marker post as well once pole was set. Before dig pictures attached show no apparent utilities or markers in the area and contractor was using soft dig techniques (Hand Digging) to perform the work. Sub Contractor did not notify Lamberts (Prime Contractor) of the alleged damage due to them hand digging. Once Lamberts was notified of the damage an investigation was conducted, information gathered and AVR submitted. Before dig</p>	<p>Verizon: \$3,000.00 Section 2(5)(vii) 2nd Offense \$1,500.00</p> <p>Section 2(5)(vii) 2nd Offense \$1,500.00</p> <p>Perry Township Jefferson County: \$2,000.00 Section 2(5)(vii) 1st Offense \$1,000.00</p> <p>Section 2(5)(vii) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>pictures and post dig pictures are attached. Verizon work order number was EWO 1A6EC1E, and this was a short notice emergency set. Lonestar Line Construction is scheduled to complete a refresher course called "Dig Safe" provided by Lambert's as a follow up action for their construction crews as well as a debrief meeting with their management and owner as a follow up with their leadership."</p> <p>Verizon submitted an AVR in response to the AVR request letter sent 02/21/2024. Their AVR states, " Verizon Contractor - Lambert's Construction subcontracted this job to another contractor Lonestar Line construction. This job was an emergency pole placement." An email was received on 4/8/2024, stating an AVR was submitted- AVR2024APR080007.</p> <p>No violations were issued for the line hit, as the damage was a result of hand tools.</p> <p>Emergency Ticket 20233140968- PERRY TOWNSHIP JEFFERSON COUNTY had no response and VERIZON did not respond until 11/13/2023. Emergency Ticket 20233141309- PERRY TOWNSHIP JEFFERSON COUNTY had no response and VERIZON did not respond until 11/13/2023.</p> <p>Violations-</p> <p>Verizon-</p> <ul style="list-style-type: none"> - Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket 20233140968. Recommendation: Penalty applied. (Facility Owner/Locator education completed and passed by Verizon on 6/26/2024.) - Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket 20233141309. Recommendation: Penalty applied. (Facility Owner/Locator education completed and passed by Verizon on 6/26/2024.) <p>Perry Township Jefferson County- (No prior violations located.)</p> <ul style="list-style-type: none"> - Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket 20233140968. Recommendation: Education required, and penalty applied. - Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket 20233141309. Recommendation: Education required, and penalty applied. 	
43042	<p>Facility Owner: PECO Contractor/Excavator: Caddick Utilities Project Owner: Aqua PA Other: Verizon</p>	<p><u>On 11/13/2023 9:00:00 AM at ARROWMINK RD, LOWER MERION TWP, MONTGOMERY</u> PECO is accepting the violation and penalty.</p> <p>*****</p> <p>Incident occurred on 11/13/2023, at 9:00 AM, on Arrowmink Road, near the intersection of Mount</p>	<p>PECO: \$2,000.00 Section 2(5)(i) Subsequent \$2,000.00</p> <p>Verizon: \$4,000.00 Section 2(5)(v) Subsequent \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Pleasant Road, in Lower Merion Township, Montgomery County.</p> <p>An unmarked 4" coated steel gas line was damaged. The coating was damaged, and the pipe was dented, but there was no gas leak.</p> <p>PECO - To date, an Alleged Violation Report (AVR) has not been filed. A courtesy letter, requesting an AVR to be completed was sent by email and mail on 02/27/2024.</p> <p>Caddick Utilities submitted an Alleged Violation Report (AVR) on 11/13/2023. Their AVR states, "Damaged unmarked 4" coated steel line. The coating was damaged and the pipe ws dented but there was no leak." Photos were submitted.</p> <p>Aqua PA submitted an AVR on 11/14/2023. Their AVR states, "Aqua Contractor Caddick Utilities damaged unmarked 4" coated steel line. The coating was damaged and the pipe was dented but there was no leak. Cabin Rd & Arrowmink Rd".</p> <p>Violations-</p> <p>PECO-</p> <ul style="list-style-type: none"> - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: Penalty applied. (Facility Owner/Locator education completed and passed on 6/20/2024.) <p>Verizon-</p> <ul style="list-style-type: none"> - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket 20233070313. Recommendation: Penalty applied. (Facility Owner/Locator education completed and passed by Verizon on 6/26/2024.) - Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). Ticket 20231450198. Recommendation: Penalty applied. (Facility Owner/Locator education completed and passed by Verizon on 6/26/2024.) 	<p>Section 2(5)(viii) Subsequent \$2,000.00</p>
43083	<p>Facility Owner: Monroeville Municipal Authority</p> <p>Contractor/Excavator: Golden Triangle Construction</p> <p>Project Owner: PennDOT</p>	<p><u>On 11/14/2023 8:00:00 AM at WILLIAM PENN HWY, MONROEVILLE MUNIC, ALLEGHENY</u> Monroeville Municipal Authority submitted information regarding the case, including an attachment, but stated that they are not requesting a DPC hearing. Reviewed information and withdrew violation and penalty.</p> <p>*****</p> <p>Incident occurred on 11/14/2024, at 8:00 AM along William Penn Highway, Monroeville Munic, Allegheny County, near the intersection of Northern Pike Bridge.</p> <p>An unmarked water service line was hit. The main lines were marked, but the laterals or tap locations were not.</p>	<p>Monroeville Municipal Authority: \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Monroeville Municipal Authority submitted an AVR in response to the AVR request letter sent 03/04/2024. Their AVR states, " The MMA field marked the water and sanitary sewers that it owns and operates for both PA 1 Calls 20232980284 (10/26/2023) and 20232540246 (9/13/2023). Additional notes were added to the field marked response for 20232540246 alerting the excavator to use caution due to the challenging locate. A 6-inch CIP service line and associated 6-inch service valve in addition to a hydrant stub were painted and flagged in the field (see attached photo). A previously unrecorded private 2-inch copper water service line was not field marked. This service line was installed parallel to and within 18-24 inches of the field marked 6-inch service. It ran up and over the existing storm culvert. On 11/14/2023, Golden Triangle Construction struck and damaged this private 2-inch copper water service line. The 2-inch copper is owned by 3813 William Penn Highway and therefore considered private. Even if the MAM had records of the service line, it is the policy of the MMA to not field mark private facilities. Golden Triangle Construction contacted the MMA on 11/14/2023 when the damage occurred. MMA crews responded and repaired the damaged water service line." There was an additional comment on the AVR stating, "A 2-inch copper private water service was not field marked because it was an unknow/unrecorded line and it was too close to the field marked 6-inch to detect/locate a separate line."</p> <p>Golden Triangle Construction submitted an AVR that states, "GTC was installing RCP combination storm sewer. At 8:00AM GTC struck a unmarked 1" unmarked service line tapped into the main. Water authority was on site at 8:15AM to begin repairs. MMA marked out the mains but did not mark out the laterals or tap locations." Photos were submitted.</p> <p>PennDOT submitted an AVR that states, "GTC was installing RCP combination storm sewer. At 8:00AM GTC struck a unmarked 1" unmarked service line tapped into the main. Water authority was on site at 8:15AM to begin repairs. MMA marked out the mains but did not mark out the laterals or tap locations."</p> <p>This case is related to cases 042438 and 043084.</p>	
43620	<p>Facility Owner: Pittsburgh Water and Sewer (PWSA) Contractor/Excavator: W A PETRAKIS CONTRACTING COMPANY Project Owner: Peoples Gas Other: Verizon</p>	<p>On 12/1/2023 2:00:00 PM at 1411 Cooper Ave, <u>PITTSBURGH CITY, ALLEGHENY</u> Incident occurred on 12/01/2023 at 2:00 PM, at 1411 Cooper Ave., in Pittsburgh City, Allegheny County.</p> <p>An unmarked water line was hit. Pittsburgh Water and Sewer (PWSA) had responded to the routine ticket 20233040827 'Field Marked', on 11/09/2023.</p> <p>Pittsburgh Water and Sewer (PWSA) submitted an Alleged Violation Report (AVR) on 12/11/2023. Their AVR states, "Petrakis contracting working for Peoples Gas and hit an unmarked lead service line. PWSA responded, crimped line, and ran a new pex service line.</p>	<p>Pittsburgh Water and Sewer (PWSA): \$1,000.00 Section 2(4) 1st Offense \$250.00 Section 2(5)(v) 1st Offense \$250.00 Section 2(5)(i) 1st Offense \$500.00 W A PETRAKIS CONTRACTING</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>However, this hit was at 1411 Cooper Ave. This location is way down the road from the info and location what was stated on Petrakis 1 call ticket." Photos were submitted.</p> <p>W A PETRAKIS CONTRACTING COMPANY submitted an AVR on 03/11/2024, in response to an AVR request sent on 03/08/2024. Their AVR states, "While excavating trench in paved surface for installing Mainline for Peoples gas, the Excavator encountered an unmarked water service for 1411 Cooper Ave. The water service was damaged by the excavator and the facility owner (PWSA) was informed of the damage and sent a crew to repair the service." Photos were submitted.</p> <p>Peoples Gas LLC submitted an AVR on 03/12/2024, in response to the AVR request letter sent 03/08/2024. Their AVR states, "A PNG 2nd party contractor (W.A Petrakis) was working to install a new gas line for PNG when they struck an unmarked 1" lead service line for 1411 Cooper Ave." Photos were submitted.</p> <p>Routine ticket 2023283367 is referenced by Pittsburgh Water and Sewer (PWSA). This ticket is for Morrell Street (different location).</p> <p>The correct routine ticket for the location where the damage occurred is 20233040827, which is for Cooper Ave. - This ticket states: Work Site--[COOPER AVE] Lawful Start Dates--[06-Nov-23] thru [15-Nov-23] Response Due Date--[05-Nov-23] Scheduled Excavation Date--[06-Nov-23] Dig Time--[0700] Duration--[3-4 WEEKS]</p> <p>- Final Design ticket 20231422089 - Late responses from Verizon 7/13/2023 and PITTSBURGH WATER & SEWER AUTHORITY THE on 6/13/2023. - Routine ticket 20233040827 - Response Due Date--[05-Nov-23] - Late responses from Verizon 11/06/2023 and PITTSBURGH WATER & SEWER AUTHORITY THE on 11/06/2023 they replied SCHEDULED DATE & TIME LINES WILL BE MARKED BY: 07 Nov 2023 0100 however they did not reply Field Marked until 11/09/2023 making them late to respond to the ticket and late to mark.</p> <p>Violations-</p> <p>Pittsburgh Water and Sewer (PWSA) - - Section 2(4) – Failed to respond to designer’s request for information within 10 business days. Ticket 20231422089. Recommendation: Penalty applied. (Facility owner/ locator education was completed and passed by PWSA on 07/17/2024.) - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20233040827. Recommendation: Penalty applied. (Facility owner/ locator education was completed and passed by PWSA on 07/17/2024.)</p>	<p>COMPANY: \$500.00 Section 5(16) 1st Offense \$500.00</p> <p>Verizon: \$2,500.00 Section 2(5)(v) Subsequent \$1,000.00</p> <p>Section 2(4) Subsequent \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>- Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Ticket 20233040827. Recommendation: Penalty applied. (Facility owner/ locator education was completed and passed by PWSA on 07/17/2024.)</p> <p>W A PETRAKIS CONTRACTING COMPANY - - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. Recommendation: Education required, and penalty applied. (No prior violation of 5(16) located.)</p> <p>Verizon- - Section 2(4) – Failed to respond to designer’s request for information within 10 business days. Ticket 20231422089. Recommendation: Penalty applied. (Facility Owner/Locator education completed and passed by Verizon on 6/26/2024.)</p> <p>- Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20233040827. Recommendation: Penalty applied. (Facility Owner/Locator education completed and passed by Verizon on 6/26/2024.)</p>	
43587	<p>Facility Owner: PENNSYLVANIA AMERICAN WATER</p> <p>Contractor/Excavator: Peoples Gas</p> <p>Project Owner: PEOPLES NATURAL GAS - Placeholder</p>	<p><u>On 12/5/2023 12:15:00 AM at 102 MAPLE AVE, CARROLL TWP, WASHINGTON</u> The incident occurred on 12/05/2023, at 12:15 AM, at 102 Maple Ave., Carroll Township, Washington County.</p> <p>A water line was hit twice.</p> <p>PENNSYLVANIA AMERICAN WATER submitted an AVR on 03/22/2024, in response to the AVR request letter sent 03/06/2024. Their AVR states, "Damage occurred on 12/05/2023 by People's Gas. The line was marked correctly. PAWC was unaware that this damage occurred at the time."</p> <p>Peoples Natural Gas submitted an AVR on 12/08/2023. Their AVR states, "ON 12/5/23 AT 00:15 PNG WORKING TO REPAIR GAS LINE, HIT A MISS MARKED WATER SERVICE LINE, MARKS WERE OFF 7 FEET, PA AMERICAN WATER WAS NOTIFIED AND RESPONDED TO WORK SITE FOR REPAIRS, AT THIS TIME CREW WAS ADVISED THEY COULD CONTINUE DIGGING, WHILE DIGGING PNG CREW HIT THE SAME SERVICE AGAIN AS IT HORSESHOED OFF OF THEIR MAIN LINE WHICH WAS DISCOVERED TO BE BELOW OUR GAS MAIN AND NOT ACROSS THE STREET AS ADVISED PRIOR."</p> <p>No photos were submitted. Peoples Gas submitted a sketch for the day the damage occurred.</p> <p>No violations/penalties were assigned due to the conflicting information provided by the stakeholders and being unable to determine if the line was marked correctly. No photos were submitted for review.</p>	
44249	<p>Facility Owner: PEOPLES GAS</p>	<p><u>On 12/12/2023 2:50:00 PM at FREELAND ST, MCKEESPORT CITY, ALLEGHENY</u> Incident</p>	<p>BETTERS COMPANY: \$2,750.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>Contractor/Excavator: BETTERS COMPANY Project Owner: CITY OF MCKEESPORT</p>	<p>occurred on December 12th, 2023 at 2:50pm along Freeland Street, McKeesport City, Allegheny County.</p> <p>A gas line was hit.</p> <p>Peoples Gas Company's Alleged Violation Report (AVR) states, "Bettters Company was razing the home at 2908 Freeland St. in McKeesport for the City of McKeesport. During the razing of the building, Bettters Company broke the meter set riser causing gas to blow. Bettters Company caused this damage on 12/12/23 at 2:50 pm. The lawful dig date on the PA One Call Ticket was 12/14/23 with a response due date of 12/13/2023. Bettters Company worked before the lawful dig date causing this damage." AVR notes that 911 was not notified.</p> <p>Peoples' pictures are date stamped with 12/12/2023 at 4:46pm. Bettters Company's ticket had Lawful Start Dates--[14-Dec-23] thru [26-Dec-23]. Ticket states work for: City of McKeesport.</p> <p>Bettters Company and the City of McKeesport were mailed and emailed a request for an AVR on 3/8/2024. Email delivery receipts are attached. No AVR have been submitted as of 4/18/2024.</p> <p>City of McKeesport called and DPI returned their call and left message.</p> <p>Violations:</p> <p>Bettters Company Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Education is required. Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. Education is required. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. Education is required. Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. Education is required.</p> <p>City of McKeesport Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 10 Business Days of a line strike. Education is required. The City of McKeesport is delinquent on DPC ordered education from 2022 and 2023. The DPC ordered McKeesport to education on 2/14/2023 for case 029493 and on 3/8/2022 for case 012519. Fines raised to \$2500.</p>	<p>Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$500.00</p> <p>Section 5(17) 1st Offense \$250.00</p> <p>CITY OF MCKEESPORT: \$2,500.00 Section 6.1(7) 1st Offense \$2,500.00</p>
43737	<p>Facility Owner: UGI Utilities Contractor/Excavator:</p>	<p><u>On 12/14/2023 1:05:00 PM at 10 ABBEY LN, EAST PENNSBORO TWP, CUMBERLAND</u> UGI - Without admitting or denying UGI violated the Act, UGI accepts</p>	<p>UGI Utilities: \$1,000.00 Section 2(5)(i) 2nd Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>E.K. Services Inc Project Owner: PENNSYLVANIA AMERICAN WATER</p>	<p>the remedial action and will remit the designated payment amount.</p> <p>*****</p> <p>Incident occurred on 12/14/2023 at 1:08 PM, at 10 Abbey Lane, East Pennsboro Township, Cumberland County.</p> <p>An unmarked gas line was hit.</p> <p>UGI Utilities, Inc. submitted an Alleged Violation Report (AVR) on 12/20/2023. Their AVR states, "PAOC ticket was designated "Clear-No Facilities" and was not marked. 1/2" gas service was struck and damaged." Photos were submitted.</p> <p>E.K. Services Inc. submitted an AVR on 12/19/2023. Their AVR states, "Crew was onsite to repair a water line leak. Crew was attempting to hand to dig but due to difficult digging and not having the Vac Truck, they used powered equipment to excavate to stop the leaking water utility. A visible water line mark was within the tolerance zone where they were excavating. In the process they struck an unmarked gas line approx 30" down. The utility affected 1 person, no evacuation. UGI was able to fix the line, the crew backfilled the area." Photos were submitted.</p> <p>PENNSYLVANIA AMERICAN WATER submitted an AVR on 12/20/2023. Their AVR states, "Crew was onsite to repair a water line leak. Crew was attempting to hand dig but due to difficult digging and not having the Vac Truck, they used powered equipment to excavate. A visible water line mark was within the tolerance zone where they were excavating. In the process they struck an unmarked gas line approximately 30 inches below surface. The utility affected 1 person, no evacuation. UGI was able to fix the line, the crew the backfilled the area."</p> <p>Violations:</p> <p>UGI Utilities, Inc.- - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: Education required, and penalty applied.</p>	
43753	<p>Facility Owner: Columbia Gas of PA - North</p> <p>Contractor/Excavator: SIMONSON CONSTRUCTION SERVICES</p> <p>Project Owner: Armstrong Cable Inc</p> <p>Other: Brightspeed</p> <p>Other: CRANBERRY TOWNSHIP BUTLER</p>	<p><u>On 12/18/2023 10:00:00 AM at 514 WALNUT GROVE, CRANBERRY TWP, BUTLER PENN</u> POWER CO / First Energy withdrew their dispute.</p> <p>*****</p> <p>Incident occurred on 12/18/2023, at 10:00 AM, at 514 Walnut Grove, Cranberry Township, Butler County.</p> <p>An accurately marked gas line was hit while hand digging to expose the line for directional drilling.</p>	<p>Armstrong Cable Inc: \$250.00 Section 2(5)(v) 1st Offense \$250.00</p> <p>Brightspeed: \$250.00 Section 2(5)(v) 1st Offense \$250.00</p> <p>CRANBERRY TOWNSHIP BUTLER COUNTY: \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>COUNTY Other: PENN POWER CO / First Energy</p>	<p>Columbia Gas of PA submitted an Alleged Violation Report (AVR) on 12/21/2023. Their AVR states, "Simonson Construction, working on behalf of Armstrong Utilities, was hand digging to expose an accurately marked 1" plastic company-owned gas service for their bore shot when they struck and damaged the gas service. They notified 911, 811, and Columbia Gas when the damage occurred. Columbia Gas responded immediately to make the area safe and complete repairs." Photos were submitted.</p> <p>SIMONSON CONSTRUCTION SERVICES submitted an AVR on 12/18/2023. Their AVR states, "Service gas line was damaged while directional drilling."</p> <p>Armstrong Utilities, Inc submitted an AVR on 12/27/2023. Their AVR states, "Service gas line was hit and damaged while directional drilling".</p> <p>This case is related to cases: 039706, 041051, 041680, 042134, 042378, 043067.</p> <p>No violations for the line damage because it was a result of hand tools.</p> <p>Violations:</p> <p>Armstrong Cable - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20233320048. Recommendation: Education required, and penalty applied.NOTE Armstrong is delinquent for education ordered by the DPC on August 8, 2023 for case 31067.</p> <p>PENNSYLVANIA POWER CO- - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20233320048. Recommendation: Education required, and penalty applied. Response Due Date--[30-Nov-23] Penn Power responded "Field Marked" 12/06/2023.</p> <p>BRIGHTSPEED- - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20233320048. Recommendation: Penalty applied. (Facility Owner/Locator education completed and passed by Brightspeed on 9/18/2024.)</p> <p>CRANBERRY TOWNSHIP BUTLER COUNTY- - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20233320048. Recommendation: Education required, and penalty applied.</p>	<p>Section 2(5)(v) 1st Offense \$250.00</p> <p>PENN POWER CO / First Energy: \$250.00 Section 2(5)(v) 1st Offense \$250.00</p>
43864	<p>Facility Owner: Verizon Contractor/Excavator: Duda Cable Construction Project Owner: Comcast</p>	<p><u>On 12/20/2023 10:00:00 AM at 102 MAID MARION LN, PETERS TWP, WASHINGTON</u> Incident occurred on 12/20/2023 at 10:00 AM, at 102 Maid Marion Lane, Peters Township, Washington County.</p> <p>An unmarked fiber line was hit.</p>	<p>Verizon: \$2,000.00 Section 2(5)(i) Subsequent \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Verizon submitted an Alleged Violation Report (AVR), in response to an AVR request letter was sent on 03/21/2024. Their AVR states, "Verizon completed the Routine ticket on 12/14/2023 with a comment of No Conflict. Subsequently, a Verizon Customer experienced a damage Fios drop line to their house, leaving the customer out of service. Verizon contacted a local manager immediately to restore the customer's service. The cost of repair was less than \$400,000. No pictures or other details available."</p> <p>Duda Cable Construction submitted an AVR on 12/21/2023. Their AVR states, "Duda Cable struck an unmarked Verizon fiber line. The line was buried approx. 6 - 8 inches deep. Attached pictures show that no communication markings were present within the excavation area." Photos were submitted.</p> <p>Comcast submitted an AVR on 12/22/2023. Their AVR states, "duda cable struck an unmarked verizon fiber line. the line was buried approx 6 to 8 inches deep. attached pictures show that no communication's markings were present within the excavation area". Photos were submitted (same as Duda Cable Construction's photos).</p> <p>Please note that Verizon responded, "BD-CLEAR. NO FACILITIES OR FACIL NOT INVOLVED" to routine ticket 20233463396.</p> <p>Violations-</p> <p>Verizon-</p> <p>- Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: Penalty applied. (Facility Owner/Locator education completed and passed by Verizon on 6/26/2024.)</p>	
43990	<p>Facility Owner: Upper Providence Twp Contractor/Excavator: Utility Line Services Project Owner: Aqua PA Other: Comcast Other: LUMEN FORMERLY LEVEL 3 Other: PECO Other: Verizon</p>	<p><u>On 1/2/2024 12:01:00 PM at 503 IDLEWILD CIR, UPPER PROVIDENCE TWP, DELAWARE</u> PECO accepts violation and penalty.</p> <p>LUMEN FORMERLY LEVEL 3 - withdrew violation and penalty per additional information.</p> <p>*****</p> <p>Incident occurred on 01/02/2024, at 12:01 PM, 503 Idlewild Circle, Upper Providence Township, Delaware County.</p> <p>A mismarked sewer lateral was hit.</p> <p>Upper Providence Twp - To date, Alleged Violation Report (AVR) has not been filed. An AVR request letter was sent by email and USPS on 03/21/2024.</p> <p>Utility Line Services submitted an AVR on 01/04/2024. Their AVR states, "While the crew was working in the area of 503 Idlewild Circle to install a water main they</p>	<p>Upper Providence Twp: \$500.00 Section 2(5)(i) 1st Offense \$500.00</p> <p>Comcast: \$1,500.00 Section 2(5)(viii) 3rd Offense \$1,500.00</p> <p>LUMEN FORMERLY LEVEL 3: \$0.00</p> <p>PECO: \$1,000.00 Section 2(5)(v) Subsequent \$1,000.00</p> <p>Verizon: \$2,000.00 Section 2(5)(viii) Subsequent \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>damaged a forced sewer lateral that was 30' off the mark." Photos were submitted.</p> <p>Aqua PA submitted an AVR on 01/04/2024. Their AVR states, "Aqua Contractor Utility Line Services, while the crew was working in the area of 503 Idlewild Circle to install a water main, they damaged a forced sewer lateral that was 30ft off the mark."</p> <p>This case is related to case 025573.</p> <p>- Final Design ticket 20202103355 had a Response Due Date--[11-Aug-20] - No response from LUMEN FORMERLY LEVEL 3.</p> <p>- Final Design ticket 20221291253 had a Response Due Date--[23-May-22] - No response from LUMEN FORMERLY LEVEL 3.</p> <p>- Complex Project ticket 20232960426 had a Response Due Date--[05-Nov-23] - Late responses from Verizon 11/24/2023 and Comcast on 11/07/2023.</p> <p>- Routine ticket 20233550487 had a Response Due Date--[26-Dec-23] - Late response from PECO on 12/27/2023.</p> <p>Violations-</p> <p>Upper Providence Twp-</p> <p>- Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: Education required, and penalty applied. (No prior violation of 2(5)(i) located.)</p> <p>Verizon-</p> <p>- Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). Ticket 20232960426. Recommendation: Penalty applied. (Facility Owner/Locator education completed and passed by Verizon on 6/26/2024.)</p> <p>Comcast-</p> <p>- Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). Ticket 20232960426. Recommendation: Penalty applied. (Facility Owner/Locator education completed and passed by Comcast on 6/25/2024.)</p> <p>PECO-</p> <p>- Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20233550487. Recommendation: Penalty applied.</p>	
44082	<p>Facility Owner: Columbia Gas of PA - Central</p> <p>Contractor/Excavator: CASPER COLOSIMO AND SON INC</p> <p>Project Owner: PENNSYLVANIA</p>	<p><u>On 1/4/2024 9:50:00 AM at 2713 CUSTER AVE, BALDWIN BORO and PITTSBURGH CITY WARD 29, ALLEGHENY</u> Dispute- Allegheny County Dept. Public Works is disputing section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification and Recommendation: Education Required and Penalty Applied. See their attached letter</p>	<p>Columbia Gas of PA - Central: \$500.00 Section 2(5)(i) 1st Offense \$500.00</p> <p>CASPER COLOSIMO AND SON INC: \$750.00 Section 5(4) 1st Offense</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>AMERICAN WATER Other: Allegheny County Department of Public Works</p>	<p>*****</p> <p>The incident occurred on Thursday, January 4, 2024, at 2713 Custer Avenue, in Baldwin Borough Pittsburgh City Ward 29, Allegheny County.</p> <p>Columbia Gas line was damaged by Casper Colosimo and Son Inc (CCSI), working for PA American Water Company (PAWC). Columbia Gas stated, CCSI failed to renotify One Call of an unmarked or incorrectly marked facility and the Columbia Gas had missing or incorrect facility line maps or records. Columbia Gas explained, CCSI was digging to install water mainline when they struck and damaged a 1-inch plastic gas service line. CCSI crew found and exposed a steel gas service that lined up with the locate marks, believing it to be the active gas service, and they proceeded to dig and struck the active plastic gas service approximately 30-inches away. CCSI notified 911, 811, and Columbia Gas when the damage occurred. An investigation was conducted to determine what led to the inaccurate locate, and Columbia Gas explained that the Locator hooked up to the wire at the meter and had a strong signal to the middle of the road before losing signal. There was also a marker ball documented over the tap, so the Locator straight lined from where he lost the signal to the marker ball. Unfortunately, both the marker ball and the wire at the meter toned out the old steel gas service. Columbia Gas records have been updated.</p> <p>PAWC stated, CCSI failed to use prudent techniques in the tolerance zone and explained that they were excavating to install a water mainline, when a Columbia Gas service line was hit and damaged. The line was vac by CCSI, and they identified 2 service lines prior to the start of excavation. There were 2 service lines in the ditch but only 1 mark on the asphalt.</p> <p>CCSI stated, they failed best efforts to follow CGA Best Practices, and explained they were excavating to install a new water main for PAWC when they struck a Columbia Gas line that was within the tolerance zone.</p> <p>Photos were provide of the locate mark and damage line.</p> <p>~20240040771- Damage Emergency ticket was placed on 1/4/2024, at 9:51am, Baldwin Borough. Late Response from Allegheny County Department of Public Works on 1/5/2024, at 9:38am.</p> <p>*Columbia Gas is in violation of section: 2(5)(i) – Missing or incorrect facility line maps or records. Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: Penalty Applied</p> <p>*Casper Colosimo and Son Inc is in violation of sections: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.</p>	<p>\$500.00</p> <p>Section 5(20) 1st Offense \$250.00</p> <p>Allegheny County Department of Public Works: \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>5(20) – Excavator failed to renotify One Call of an unmarked or incorrectly marked facility upon arrival at a work site. Recommendation: Penalties Applied</p> <p>*Allegheny County Department of Public Works is in violation of section: 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Recommendation: Education Required and Penalty Applied</p>	
44057	<p>Facility Owner: Windstream</p> <p>Contractor/Excavator: LINDY PAVING INC</p> <p>Project Owner: EQT</p> <p>Designer: Dieffenbauch & Hritz, LLC</p> <p>Other: West Penn Power/FirstEnergy</p> <p>Other: West Side Telecommunications</p>	<p><u>On 1/8/2024 8:00:00 AM at HAINES RIDGE RD, PERRY TWP, GREENE</u> The incident occurred on Monday, January 8, 2024, on Haines Ridge Road, in Perry Township, Greene County.</p> <p>A communications line was damaged.</p> <p>Windstream communication line was damaged by Lindy Paving, hired by EQT for a road widening project. Lindy Paving and EQT represented by Lindy stated, Windstream mismarked their facility and explained in their Alleged Violation Report (AVR), on 1/8/2024, approximately 7:45am, the spotter observed what appeared to be a severed telecom line. A Damage Emergency ticket, 20240080576, was placed and Windstream was contacted. Windstream stated they created a work order to repair the line and their crew would be dispatched. USIC, contracted to locate for Windstream, told Lindy they were unable to locate along that section of the roadway. USIC representative arrived onsite and took pictures of the severed line. As of 1:30PM no Windstream crews have arrived to repair the line.</p> <p>Windstream stated Lindy Paving failed to renotify One Call of any unmarked or incorrectly marked facility, and explained in their AVR, Lindy placed a Routine ticket, 20233462506, on 12/12/2023, Windstream facilities were marked by USIC on 12/29/2023. On 1/02/2024, related Update Routine ticket, 20240021955 was placed and Windstream cleared it in house because there was a remark on the ticket from Lindy Paving stating, work in progress no additional mark outs needed.</p> <p>Dieffenbauch & Hritz stated in their AVR that they provided EQT Production Company with engineering services for preliminary turning movements, design plans for any needed road upgrades to facilitate traffic, landowner exhibits and survey services for utilities, drainage structures and field walk stakeout. Dieffenbauch & Hritz was not part of the excavation or construction inspection.</p> <p>On Tuesday, March 26, 2024, emails and letters were sent requesting AVR's from the facility owner; Windstream, the project owner; EQT Production, and the designer; Dieffenbauch & Hritz. Windstream and Dieffenbauch & Hritz submitted their AVR's on 3/28/2024.</p>	<p>Windstream: \$750.00 Section 2(5)(i) 1st Offense \$500.00</p> <p>Section 2(5)(v) 1st Offense \$250.00</p> <p>LINDY PAVING INC: \$500.00 Section 5(3) 1st Offense \$500.00</p> <p>West Penn Power/FirstEnergy: \$500.00 Section 2(5)(v) 2nd offense \$500.00</p> <p>West Side Telecommunications: \$250.00 Section 2(5)(v) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Lindy Paving submitted an updated AVR representing EQT on 4/10/2024. Photos were provided showing the damaged line</p> <p>~20233462506- Routine ticket placed on 12/12/2023. Late Responses on 12/29/2023, from: West Side Telecommunications, West Penn Power, and Windstream.</p> <p>~20240021955- Update Routine ticket placed on 1/2/2024. Remark: work in progress no additional mark outs needed.</p> <p>*Lindy Paving is in violation of section: 5(3) – Excavator failed to preserve mark-outs or request a remark. 20240021955- Remark: work in progress no additional mark outs needed. Recommendations: Education Required and Penalty Applied NOTE: Lindy Paving is more than 1 year delinquent on education ordered by the DPC on 12/13/2022 for case 018440. (Excavator education completed and passed by Lindy Paving on 7/26/2024.)</p> <p>*Windstream is in violation of sections: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. 20233462506 Recommendations: Penalties Applied</p> <p>*West Side Telecommunications is in violation of section: 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. 20233462506 Recommendations: Education Required and Penalty Applied</p> <p>*West Penn Power/FirstEnergy is in violation of section: 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. 20233462506 Recommendations: Education Required and Penalty Applied</p>	
44127	<p>Facility Owner: UGI Utilities Contractor/Excavator: R L E ENTERPRISES Project Owner: PA American Water Company</p>	<p><u>On 1/11/2024 7:30:00 AM at 202 E Grand St., NANTICOKE CITY, LUZERNE</u> The incident occurred on Thursday, January 11, 2024, at the intersection of S. Walnut and E. Grand Streets (damage line to 202 E. Grand Street), in Nanticoke City, Luzerne County.</p> <p>A gas line was hit.</p> <p>UGI Utilities' gas line was damaged by RLE Enterprises while working for PA American Water Company (PAWC) RLE Enterprises stated, while removing blacktop from the road to install a new water service line the crew hit and damaged an unmarked gas service line. The gas service was hit at a depth of 12-inches from the top of the blacktop. The Fire and Police Departments responded to the 911 call and UGI arrived on site. PAWC stated, while excavating for tie in at the intersection of S. Walnut and E. Grand Streets, RLE</p>	<p>UGI Utilities: \$500.00 Section 2(5)(i) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Enterprises hit and broke an unmarked gas service line for 202 E. Grand Street, the gas line was approximately 10-12-inches below surface of the roadway. UGI stated, RLE Enterprises hit and damaged an unmarked gas service line. Photos were provided of the damaged unmarked gas service line.</p> <p>*UGI Utilities is in violation of section: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: Penalty Applied</p>	
44137	<p>Facility Owner: PEOPLES GAS COMPANY LLC Contractor/Excavator: CASPER COLOSIMO AND SON INC Project Owner: PENNSYLVANIA AMERICAN WATER</p>	<p><u>On 1/11/2024 8:00:00 AM at PYRAMID AVE, BRENTWOOD BORO, ALLEGHENY</u> The incident occurred on Thursday, January 11, 2024, at 3011 Pyramid Avenue, in Brentwood Borough, Allegheny County.</p> <p>a gas line was damaged.</p> <p>Peoples Gas line was damage by Casper Colosimo and Son Inc (CCSI) while installing water line for PA American Water Company (PAWC). CCSI and PAWC stated, when excavating to install a new water mainline and was sloping the ditch to install shoring, when a gas service line was hit. Also, PAWC said the gas line was vac excavated prior to the start of the excavation. Peoples Gas stated that CCSI failed to use prudent excavation techniques within the tolerance zone. CCSI hit and damaged a properly marked 1-inch plastic low pressure gas service line. Photos were provided showing the damaged gas line and locate marks. The Fire and Police Departments responded to the 911 call and gas service was interrupted for 1-6 hours affecting 1 customer.</p> <p>*Casper Colosimo and Son Inc is in violation of section: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: Penalty Applied. Education is required. The education was due by 1/9/2024. The incident occurred on 1/11/2024.</p> <p>Note: Related Case 44113</p>	<p>CASPER COLOSIMO AND SON INC: \$500.00 Section 5(4) 1st Offense \$500.00</p>
44514	<p>Facility Owner: PEOPLES GAS Contractor/Excavator: PENNSYLVANIA AMERICAN WATER Project Owner: PENNSYLVANIA AMERICAN WATER - Placeholder</p>	<p><u>On 1/22/2024 5:14:00 PM at 48 CALVERT ST, BRIDGEVILLE BORO, ALLEGHENY</u> PAWC disputed and provided additional information that included photos. Violation, penalty and education requirement were withdrawn based on the additional information that was provided.</p> <p>*****</p> <p>The incident occurred 01/22/2024 at 5:14 PM, at 48 Calvert Street, Bridgeville Borough, Allegheny County.</p> <p>A gas line owned by Peoples Gas was damaged. 911 was called.</p>	<p>PENNSYLVANIA AMERICAN WATER: \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>PENNSYLVANIA AMERICAN WATER was on site for an emergency repair of a water main, when the gas line was hit.</p> <p>PEOPLES GAS submitted an Alleged Violation Report (AVR) on 02/19/2024. Their AVR states, "Pennsylvania American Water was repairing a water leak near 193 Calvert St. when they struck and damaged a properly marked 1" gas service line and fitting for 193 Calvert St. The service line, curb box, and valve was properly marked and the damage occurred within the tolerance zone of the markings, 15", whereas Pennsylvania American Water should have been exercising better due care to prevent damaging the gas service line. The damage could have been prevented." Photos were submitted.</p> <p>PENNSYLVANIA AMERICAN WATER submitted an AVR on 02/01/2024. Their AVR states, "PA American crew while digging to repair a water main break hit and damaged a Peoples Gas main that was mis-marked by 30". The crew did not disturb that soil where Peoples had marked their main."</p> <p>Violations -</p> <p>PENNSYLVANIA AMERICAN WATER- - Section 5(4) – withdrawn based on additional information that was submitted.</p>	
44327	<p>Facility Owner: UGI Utilities Contractor/Excavator: J M DIRTWORX LLC. Other: Zayo Bandwidth</p>	<p><u>On 1/23/2024 11:40:00 AM at 5877 HAMILTON BLVD, LOWER MACUNGIE TWP, LEHIGH</u> This non-damage violation occurred on January 23rd at 1140am at 5877 Hamilton Boulevard, Lower Macungie Township, Lehigh County.</p> <p>UGI's Alleged Violation Report (AVR) states, "J M DIRTWORX LLC. WAS DIGGING BEFORE THEIR LEGAL DIG DATE. UGI LOCATOR WENT TO THIS SITE TODAY 1/23/2024 TO PERFORM THIS LOCATE AND DID. WHEN UGI LOCATOR ARRIVED HE FOUND THIS CREW DIGGING AND PERFORMING THEIR WORK. I ARRIVE AND CHECKED THEIR PA ONE CALL TICKET AND CONFIRMED IT WAS NOT IN THE LEGAL DATE. I HAD TOLD THIS CREW THEY HAD TO STOP THE WORK AND WAIT UNTIL THERE LEGAL DIG DATE.</p> <p>Two pictures were provided by UGI.</p> <p>J M Dirtworx was mailed and emailed a request for an AVR on 3/6/24.</p> <p>J M Dirtworx's AVR stated, "We started the job a day early nothing was damaged because we dug in this area before on another ticket number the utility we were digging to install was over top of the gas line and incased in concrete We were just asked to stop and wait until the next day (legal Start Date) so we didn't take pictures I am sorry I didn't know to file this with in 10</p>	<p>J M DIRTWORX LLC.: \$1,000.00 Section 5(2.1) 1st Offense \$1,000.00</p> <p>Zayo Bandwidth: \$250.00 Section 2(5)(v) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>days we have changed our PA one call process so this doesn't happen again."</p> <p>Ticket 20240220960 had a legal start date of 1/25/24. Ticket 20240232627 had a legal start date of 1/26/24.</p> <p>Violation:</p> <p>J M Dirtworx Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Education is required.</p> <p>Zayo Bandwidth Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time to ticket 20240232627.</p>	
44445	<p>Facility Owner: UGI Utilities Contractor/Excavator: R L E ENTERPRISES Project Owner: PENNSYLVANIA AMERICAN WATER</p>	<p><u>On 1/25/2024 11:00:00 AM at S WALNUT ST, NANTICOKE CITY, LUZERNE</u> UGI disputed and the penalty and violation has been withdrawn *****</p> <p>The incident occurred on Thursday, January 25, 2024, at 547 S. Walnut Street, in Nanticoke City, Luzerne County.</p> <p>UGI Utilities gas line was damaged by RLE Enterprises while working for PA American Water Company (PAWC)</p> <p>RLE Enterprises explained, while excavating for new water service lines our crew found an unmarked 1-inch steel gas service line which was assumed to be retired. Our crew vac excavated all marked gas services and located every line which were new plastic services. All of the old retired gas services were steel and had to be cut out of the way. Prior to finding the unmarked active steel gas service, the previous 8 steel gas services were retired which is why it was assumed this 1-inch steel gas line was retired and could be cut out of the way.</p> <p>PAWC explained, RLE Enterprises found an unmarked steel gas service line. The Inspector verbally advocated that RLE leave the gas service alone and untouched as it was not in the way for installation of water mainline. The Inspector left crew to observe another crew for the same contractor two streets away. The Operator called the Inspector to notify of a gas hit. Upon arriving at the excavation site, the Inspector discovered that the RLE crew had used a Sawzall to cut the gas service, and inside the steel service was a 1/2" gas service for house 547 S. Walnut Street.</p> <p>UGI stated, RLE Enterprises exposed a correctly marked gas facility and then proceeded to cut through the steel line with a Sawzall damaging the active plastic gas service. The gas service was inserted through the steel casing pipe. In an email UGI stated, "RLE Enterprises had the pipe exposed and cut through it with a saw. This would not be an excavation damage."</p>	<p>UGI Utilities: \$0.00</p> <p>R L E ENTERPRISES: \$500.00 Section 5(6)(ii) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Photos were provided of the damaged line. The Police and Fire Departments responded to the 911 call and UGI was notified of incident.</p> <p>On Tuesday, April 2, 2024, an email was sent requesting an Alleged Violation Report (AVR) from UGI Utilities. On 4/3/2024, UGI responded to the AVR request by email explaining what happened and stated, "Do you still want me to fill out an AVR and explain it there?" The email was replied to on the same day asking UGI to submit a completed AVR with the information that was provided and any additional information and/or photos regarding the incident.</p> <p>UGI submitted an AVR on 4/9/2023, with a photo of the damaged line.</p> <p>*UGI Utilities is in violation of section: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: Penalty Applied</p> <p>*RLE Enterprises is in violation of section: 5(6)(ii) – Excavator failed to provide support and mechanical protection for known facility owner’s lines at the construction work site. Recommendation: Education Required and Penalty Applied</p>	
44579	<p>Facility Owner: PEOPLES GAS COMPANY LLC</p> <p>Contractor/Excavator: INDEPENDENT ENTERPRISE</p> <p>Project Owner: Pittsburgh Water and Sewer (PWSA)</p> <p>Designer: GAI Consultants</p> <p>Designer: JOHNSON MIRMIRAN AND THOMPSON J M T</p> <p>Other: AT&T</p> <p>Other: Lumen LKC</p> <p>Other: Verizon</p>	<p><u>On 1/26/2024 9:30:00 AM at UVILLA ST, PITTSBURGH CITY, ALLEGHENY</u> Peoples' violation and penalty was removed after providing new photos with CGA mark outs.</p> <p>*****</p> <p>PWSA & JMT's Violation was removed. " JMT submitted final design tickets through the Pennsylvania One Call System on March 8, 2023 and the final design was bid by Pittsburgh Water & Sewer Authority on March 23, 2023."</p> <p>*****</p> <p>Incident occurred on January 26th, 2024 at 9:30am at 1014 Uvilla Street, Pittsburgh City, Allegheny County.</p> <p>A gas line was damaged.</p> <p>Peoples Gas Company's Alleged Violation Report (AVR) states, "Independent Enterprises was installing new water facilities for PWSA under a project consisting over 10 city blocks in the west end neighborhood when they struck and damaged a properly marked 1" plastic low pressure gas service line for 1014 Uvilla St 7" from the markings for the gas service line. Peoples Gas dispatched an O&M crew to make the necessary repairs. Independent Enterprises failed to use prudent digging techniques in the tolerance zone of the markings and exercise due care to prevent damaging the marked gas facility." AVR notes that 911 was notified.</p> <p>Independent Enterprises' AVR states, "IEI was excavating area for water main replacement near 1014 Uvilla ST. A yellow marking was on roadway indicating a gas service was in the excavation area. Approx 3 ft</p>	<p>PEOPLES GAS COMPANY LLC: \$0.00</p> <p>Pittsburgh Water and Sewer (PWSA): \$0.00</p> <p>JOHNSON MIRMIRAN AND THOMPSON J M T: \$0.00</p> <p>AT&T: \$500.00 Section 2(5)(viii) 1st Offense \$500.00</p> <p>Lumen LKC: \$0.00 Section 2(4) 1st Offense \$0.00</p> <p>Verizon: \$750.00 Section 2(4) 1st Offense \$250.00</p> <p>Section 2(4) 1st Offense \$250.00</p> <p>Section 2(4) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>down an old steel line with plastic sleeve insert was located during excavation. IEI hand dug approx 2 ft around discovered utility to ensure no other lines were in area. Next to excavation area at 1012 Uvilla St excavation area had 3 service lines going into it so to take precaution hand digging was done. After hand digging was performed and nothing else was located in excavated area IEI believed they had discovered the live service and continued to excavate using bucket. Upon digging deeper underneath discovered steel/plastic line to continue with water main installation a 3/4" plastic service was struck and gas was leaking. 911 and one call were immediately called and Peoples Gas was onsite within 30 mins. Service was fixed and restored within the hour. The house at 1014 Uvilla St is an abandoned property and no one was inside at the time of the utility strike. The markings on the road indicated only one service was in the area hence the continuation of excavation due to the discovery of the what is now to be believed the abandoned service which was carefully hand dug around. The live 3/4" service was approx 1 ft directly below the discovered steel service."</p> <p>PWSA and JMT's AVR's were the same as Independent Enterprises AVR.</p> <p>Pictures that were provided do not show the material type for the line. Line was marked on JMT's design plans. Final Design ticket 20230671129 was placed on 3/8/2023 and the complex project was placed on 11/1/23. GAI Consultants placed preliminary design tickets 20230883580 and 20230883581 on 3/29/23. No final design ticket was placed afterwards.</p> <p>Violations:</p> <p>Peoples Section 2(5)(vi) – Lines were not marked in compliance with the Common Ground Alliance Best Practices for Temporary Marking set forth in ANSI standard Z535.1.</p> <p>PWSA Section 6.1(3) – Released a project to bid or construction before final design was complete. (Project owner and designer education was completed and passed on 07/19/2024.)</p> <p>JMT Section 4(2) – Designer failed to request the line and facility information prescribed by section 2(4) from the One Call System not less than ten nor more than ninety business days before final design is to be completed. Education is required.</p> <p>AT&T Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20233050371. (The facility owner/ locator education was completed and passed by AT&T on 02/22/2024.)</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Verizon Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20230671129 Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20222493781 Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20220811102</p> <p>Lumen LKC Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20230671129. Fixed response issues in May 2023 reduce penalty to \$0.</p>	
44463	<p>Facility Owner: UGI Contractor/Excavator: R L E ENTERPRISES Project Owner: PENNSYLVANIA AMERICAN WATER</p>	<p><u>On 1/29/2024 10:45:00 AM at 374 E GROVE ST, NANTICOKE CITY, LUZERNE</u> The incident occurred on Monday, January 29, 2024, on Ridge and S. Walnut Streets, in Nanticoke City, Luzerne County.</p> <p>UGI Utilities gas line was damaged by RLE Enterprises while working for PA American Water Company (PAWC) RLE Enterprises stated, while excavating for a new water services line on E. Ridge Street, our crew hit an unmarked gas service line. All marked gas services were vac excavated and located. We located a marked gas service which was right on the mark and continued to dig and struck the unmarked gas service. 911 and UGI were notified and arrived onsite. UGI made repairs and restored the gas service in a timely manner. PAWC stated, while RLE Enterprises was excavating for the new water mainline installation they hit an incorrectly marked gas service line for 347 Grove Street. UGI Stated, RLE Enterprises hit and damaged an incorrectly marked gas service line. Photos were provided showing the damaged mismarked gas line.</p> <p>*UGI Utilities is in violation of section: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: Penalty Applied</p>	<p>UGI: \$500.00 Section 2(5)(i) 1st Offense \$500.00</p>
45089	<p>Facility Owner: PEOPLES GAS COMPANY LLC Contractor/Excavator: INDEPENDENT ENTERPRISE Project Owner: Pittsburgh Water and Sewer (PWSA) Designer: JOHNSON MIRMIRAN AND THOMPSON J M T Other: Verizon</p>	<p><u>On 2/9/2024 10:00:00 AM at MARENA ST, PITTSBURGH CITY, ALLEGHENY</u> Incident occurred on February 2nd, 2024, at 10am along Marena Street, Pittsburgh City, Allegheny County.</p> <p>A gas line was damaged.</p> <p>Peoples' Alleged Violation Report (AVR) states, "Independent Enterprises was installing new water facilities for PWSA on Marena St. when they struck and damaged a mis-marked 1" plastic low pressure gas service line with no wire that was marked by measurements due to the locator locating and marking the main line and curb box and the measurements on the service line card equaling the measured distance between the main and curb box found in the field. Section Section 2(5)(i) permits the locator to mark facilities using records. The Project Owner failed to complete the proper level of SUE for a project this size."</p>	<p>PEOPLES GAS COMPANY LLC: \$500.00 Section 2(5)(i) 1st Offense \$500.00</p> <p>Verizon: \$3,000.00 Section 2(4) Subsequent \$1,500.00 Section 2(4) Subsequent \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Independent Enterprises' Alleged Violation Report (AVR) states, "During excavation for new water mainline contractor was digging near the mark given on the road and began to hand dig in its location. An old steel gas line was discovered and prudently dug around. No other markings were on the road so excavation continued then that is when excavator bucket hit 1" yellow plastic gas line approx 18ft off of the mark that was given on the road in one called area. Peoples Gas and 911 were called immediately. 911 arrived in approx 5-10mins and Peoples arrived within 15 mins. Peoples Gas had service restored within 2 hrs. Excavation for new mainline installation continued."</p> <p>PWSA's AVR states, "During excavation for new water mainline contractor was digging near the mark given on the road and began to hand dig in its location. An old steel gas line was discovered and prudently dug around. No other markings were on the road so excavation continued then that is when excavator bucket hit 1" yellow plastic gas line approx 18ft off of the mark that was given on the road in one called area. Peoples Gas and 911 were called immediately. 911 arrived in approx 5-10mins and Peoples arrived within 15 mins. Peoples Gas had service restored within 2 hrs. Excavation for new mainline installation continued."</p> <p>JMT's AVR states, "During excavation for new water mainline contractor was digging near the mark given on the road and began to hand dig in its location. An old steel gas line was discovered and prudently dug around. No other markings were on the road so excavation continued then that is when excavator bucket hit 1" yellow plastic gas line approx 18ft off of the mark that was given on the road in one called area. Peoples Gas and 911 were called immediately. 911 arrived in approx 5-10mins and Peoples arrived within 15 mins. Peoples Gas had service restored within 2 hrs. Excavation for new mainline installation continued. During design, JMT located the old steel gas line but not the 1" plastic line. Locations of service lines were not provided by PNG."</p> <p>Verizon failed to respond within 10 business days to design tickets 20222500885 and 20220811253.</p> <p>Violations:</p> <p>Peoples Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.</p> <p>Verizon Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20222500885 Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20220811253</p> <p>Case is related to case 44579.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
44965	<p>Facility Owner: UGI Utilities Contractor/Excavator: BETHLEHEM CITY Project Owner: BETHLEHEM CITY</p>	<p><u>On 2/17/2024 3:50:00 AM at 812 E WASHINGTON AVE, BETHLEHEM CITY, NORTHAMPTON</u> The incident occurred on Saturday, February 17, 2024, at 812 E. Washington Avenue, in Bethlehem City, Northampton County.</p> <p>UGI Utilities gas line was damaged by Bethlehem City excavation crew.</p> <p>Bethlehem City placed an Excavation Emergency ticket, 20240472623, on 2/16/2024 at 2211, to repair a water line. Water was coming out of the ground near the curb, and it was determined to be a water service leak on the City side. UGI responded and marked out their gas service line for 812 E Washington Avenue and the gas mainline. It was asked if there was gas service for 814 E Washington Avenue and the Locator stated there was none. The water services for the 812 and 814 E Washington Avenue are side by side on the property line. The marked gas service was approximately 18-inches west of the water service line so excavation proceeded on the east side, next to 814 water service line. During the excavation an unmarked gas service line to 814 E Washington Avenue was hit and damaged. The nearest gas mark was for 812 E Washington Avenue, which was 3-feet to 3.5-feet from the struck line. The Fire Department responded to the 911 call and when UGI arrived onsite they disconnected the damaged gas service line at the mainline so the Bethlehem City crew could proceed with repairing the water line.</p> <p>UGI explained, Bethlehem City was excavating to repair a water service line and when doing so an unmarked gas stub to house 814 E Washington Avenue was struck creating a leak. The gas stub was not on UGI records and mapping. The surrounding gas services were marked with yellow paint.</p> <p>*UGI Utilities is in violation of section: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. This is a second offense violation. Recommendations: Penalties Applied</p>	<p>UGI Utilities: \$1,000.00 Section 2(5)(i) 2nd Offense \$1,000.00</p>
45112	<p>Facility Owner: PPL ELECTRIC UTILITIES CORPORATION Contractor/Excavator: Doli Construction Project Owner: Halifax Area Water and Sewer Authority Designer: Herbert Rowland and Grubic</p>	<p><u>On 2/20/2024 1:00:00 PM at HILL DR, HALIFAX TWP, DAUPHIN</u> Incident occurred on February 20th, 2024 at 1pm along Hill Drive, Halifax Township, Dauphin County.</p> <p>PPL Electric's AVR states, "On Tuesday February 20th at 1:45 pm a non-PPL contractor (Doli Construction) was installing sanitary sewer when they came in contact with an unmarked electric primary line with their backhoe. No one was hurt or injured but the damage did cause an outage of 13 homes. PPL first responders arrived onsite and made the area safe, the repairs that were made are temporary to get everyone back in power. A new primary line will have to be installed. USIC did not have the primary properly marked and they will be held liable for this damage."</p>	<p>PPL ELECTRIC UTILITIES CORPORATION: \$1,000.00 Section 2(5)(i) 2nd Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Doli Construction's AVR states, "Crew hit PPL line 10 feet off the mark."</p> <p>Halifax Area Water and Sewer Authority's AVR states, "LATE ON REPORTING AVR, DIDNT KNOW LINE WAS HIIT WAITING FOR CONTRACTOR."</p> <p>HRG's AVR states, "1:00 pm RPR was on onsite during excavation and observing the work completed placement of 8" SDR-35 Sewer main. 1:30pm Contractor moved to the ROW on the Property of 52 Hill Dr. to excavate and place 6" SDR-35 Sewer Lateral pipe. RPR noticed Utilities (Electric and Cable) were marked by USIC within the excavation area of the ROW of property 52 Hill Dr. Contractor started excavation using 138 Komatsu and hand shovels to located and cleared comcast cable and PPL electric. Comcast cable was located and cleared using shovels. Contractor continued hand digging to located the PPL Electric. While the excavator continued to move east into the roadway. Approx. 0+09' from the Comcast and PPL marked location operator notice a resistance, a pop, and stopped excavation at approx. 30" from existing grade. 1:45pm A homeowner walked outside and stated the power was out. Contractor (Doli) Forman notified USIC/ 811 of a struck PPL Electric. 2:20 PPL arrived onsite, confirmed the stuck line and rerouted power to all other residents that can be restored. Transformer located at 52 Hill and 72 Hill Dr. were grounded, repairs made to struck line by PPL. 5:00pm power restored to Hill Dr. 5:30 PPL and RPR left site. Photos of location and USIC marked locations provided.</p> <p>Case is related to 44243 and 44768.</p> <p>Violations:</p> <p>PPL Electric Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.</p>	
45054	<p>Facility Owner: UGI Utilities Contractor/Excavator: EVERHART AND HOOVER Project Owner: PPL ELECTRIC UTILITIES CORPORATION Other: East Hempfield Township</p>	<p><u>On 2/21/2024 9:30:00 AM at MILL MAR RD, EAST HEMPFIELD TWP, LANCASTER</u> The incident occurred on Wednesday, February 21, 2024, on Mill Mar Road, in East Hempfield Township, Lancaster County.</p> <p>UGI Utilities gas line was damaged by contractor, Everhart & Hoover, working for PPL Electric. Everhart & Hoover and PPL stated, while boring with a directional drill to install electric facilities, an unmarked gas service stub was struck and damaged. UGI stated, Everhart & Hoover utilizing mechanized drilling equipment, and struck an unmarked service stub while replacing electric lines. The Everhart & Hoover crew evacuated the immediate area, called 911, and One Call. Photos were provided showing the unmarked line damage.</p> <p>~20240432827- Routine ticket placed on 2/12/2024. No Response from East Hempfield Township.</p>	<p>UGI Utilities: \$500.00 Section 2(5)(i) 1st Offense \$500.00</p> <p>East Hempfield Township: \$500.00 Section 2(5)(v) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>~20240432827-001- Renotify Excavation Insufficient ticket placed on 2/20/2024.</p> <p>~20240520959- Damage Emergency ticket placed on 2/21/2024 at 9:41am.</p> <p>*UGI Utilities is in violation of section: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendations: Penalties Applied</p> <p>*East Hempfield Township is in violation of section: 2(5)(v) – Failed to respond to a routine One Call ticket. 20240432827 Recommendations: Education Required and Penalties Applied</p>	
45209	<p>Facility Owner: UGI Utilities Contractor/Excavator: HENKELS AND MCCOY Project Owner: UGI Utilities</p>	<p>On <u>2/22/2024 8:30:00 AM at 1123 ARCADIA ST, BETHLEHEM CITY, NORTHAMPTON</u> The incident occurred on Thursday, February 22, 2024, at 1123 Arcadia Street, in Bethlehem City, Northampton County.</p> <p>UGI Utilities gas line was damaged by contractor, Henkels and McCoy (H & M). H & M was trenching to install a new gas mainline when unmarked gas service line was hit and damaged. UGI stated, H & M hit an unmarked gas service and the line was marked based off incorrect records.</p> <p>*UGI Utilities is in violation of section: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendations: Penalties Applied</p>	<p>UGI Utilities: \$500.00 Section 2(5)(i) 1st Offense \$500.00</p>
45105	<p>Facility Owner: PECO an Exelon Company Contractor/Excavator: ANRICH INC Project Owner: PENNSYLVANIA AMERICAN WATER Other: Verizon, PA LLC</p>	<p>On <u>2/23/2024 8:30:00 AM at 316 WEST ROBERTS ST, NORRISTOWN BORO, MONTGOMERY</u> The incident occurred on Friday, February 23, 2024, at 316 West Roberts Street, in Norristown Borough, Montgomery County.</p> <p>PECO’s gas line was damaged by contractor Anrich, working for PA American Water Company (PAWC). Anrich and PAWC explained, there were gas locate marks completed by USIC and two days prior to excavating a trench, the Anrich crew located one gas service by a vac track. Anrich crew exposed the gas line and believed it was the correct service line, and 2 feet away a plastic gas service line was hit and damaged. PECO stated, they were notified that a 1/2” plastic gas service was severed. The investigation determined that the severed gas service was 20-inches off the mark out. The Mark out was correct based on the sketch and measurements. This damage was the result of inaccurate prints.</p> <p>~20240431004- Routine ticket placed on 2/12/2024. There was No Response from Verizon PA LLC.</p> <p>*PECO an Exelon Company is in violation of section: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendations: Penalty Applied</p>	<p>PECO an Exelon Company: \$500.00 Section 2(5)(i) 1st Offense \$500.00</p> <p>Verizon, PA LLC: \$1,500.00 Section 2(5)(v) 3rd Offense \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		*Verizon PA LLC is in violation of section: 2(5)(v) – Failed to respond to a routine One Call ticket. 20240431004 Recommendations: Penalty Applied	
45989	Facility Owner: UGI Utilities Contractor/Excavator: HENKELS AND MCCOY Project Owner: UGI Utilities	<u>On 3/27/2024 9:30:00 AM at PEMBROKE RD, BETHLEHEM CITY, NORTHAMPTON</u> The incident occurred on Wednesday, March 27, 2024, on Pembroke Road, in Bethlehem City, Northampton County. A gas line was hit. UGI Utilities gas line was damaged by contractor, Henkels and McCoy (H & M). H & M stated that their crew was excavating a trench to install 4-inch gas mainline pipe by direct bury, when an unmarked 1.25-inch steel LP was damaged. This service/stub was not located. UGI stated, an unmarked gas service stub was hit and damaged while H & M was excavating a trench to install a gas mainline. The gas stub was not on UGI's records or mapping. *UGI Utilities is in violation of section: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendations: Penalties Applied	UGI Utilities: \$500.00 Section 2(5)(i) 1st Offense \$500.00

Full Session

Case Number	Stakeholders	Summary	Violations & Recommendation
39785	Facility Owner: Pittsburgh Water and Sewer (PWSA) Contractor/Excavator: Frank J. Zottola Construction, Inc. Project Owner: Energy Center Pittsburgh LLC/Cordia Designer: VENTURE ENGINEERING Other: AT&T Other: Comcast Other: Extenet Systems LLC Other: LUMOS NETWORKS Other: PACT Stanwix Plant Other: Penn Telecom Inc Other: Verizon Business	<u>On 6/28/2023 7:09:00 AM at WILLIAM PENN PL, PITTSBURGH CITY, ALLEGHENY</u> On Tuesday, October 8, 2024, at the DPC meeting- AT&T was disputing and it was voted to Accept the DPI's recommendations. ***** AT&T is disputing ***** The incident occurred on 6/28/2023, at 7:09am, at William Penn Pl., Pittsburgh City, Allegheny County. A Pittsburgh Water and Sewer (PWSA) water line was damaged. Pittsburgh Water and Sewer (PWSA)'s alleged violation report (AVR) states "Zottola contracting working for Cordia installing steam lines and hit an accurate marked 12" DI water main with the hoe ram. PWSA shut down 12" main, had the contractors expose the damage and PWSA made repair with a 12" stainless. Contractor was careless digging." Frank J. Zottola Construction, Inc.'s alleged violation report (AVR) states "While hammering to remove concrete from a steam tunnel, a ho-ram struck a PWSA water line that was embedded in the concrete roof. PWSA was called and the line was repaired within 3 hours. No injuries."	Pittsburgh Water and Sewer (PWSA): \$1,000.00 Section 2(5)(v) Subsequent \$1,000.00 Frank J. Zottola Construction, Inc.: \$500.00 Section 5(4) 1st Offense \$500.00 Energy Center Pittsburgh LLC/Cordia: \$1,000.00 Section 6.1(3) 1st Offense \$500.00 Section 6.1(7) 1st Offense \$500.00 AT&T: \$750.00 Section 2(5)(v) 3rd offense \$750.00 Comcast: \$1,000.00 Section 2(5)(v) Subsequent \$1,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>On 1/9/2024 an AVR Request Letter was mailed and e-mailed to Energy Center Pittsburgh LLC/Cordia and VENTURE ENGINEERING. No AVR has been submitted for Energy Center Pittsburgh LLC/Cordia to date.</p> <p>VENTURE ENGINEERING's alleged violation report (AVR) states "While FJ Zottola was in the process of jack hammering the concrete roof off of an existing steam utility tunnel. The water line was embedded inside the concrete roof. The hammer punched a hole in the water line. The water line was repaired that morning. The utility was embedded within another utility which was being demolished. The marking on the street was showing the utility was not in the correct location."</p> <p>Frank J. Zottola Construction, Inc. is in violation of sections: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Based on the pictures provided it does appear that the water lines were marked within the tolerance zone. Recommendation: penalties applied</p> <p>Energy Center Pittsburgh LLC/Cordia is in violation of sections: Section 6.1(3) – Released a project to bid or construction before final design was complete. Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 10 Business Days of a line strike. Recommendation: Education Required; penalties applied Verizon Business is in violation of sections: Section 2(4) – Failed to respond to designer’s request for information within 10 business days for Ticket 20211740457. Did not respond through Pa One Call. Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time for Ticket 20231593483. Responded "Field Marked" on 6/13/23. Response was due 6/12/23. Recommendation: penalties applied</p> <p>Pittsburgh Water and Sewer (PWSA) is in violation of sections: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time for Ticket 20231593483. Responded "Field Marked" on 6/14/23. Response was due 6/12/23. Recommendation: penalties applied</p> <p>AT&T is in violation of sections: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time for Ticket 20231593483. Responded "Conflict" on 6/9/23. Conflict is not a final response to a ticket. Response was due 6/12/23. Recommendation: penalties applied</p> <p>Extenet Systems LLC is in violation of sections:</p>	<p>Extenet Systems LLC: \$250.00 Section 2(5)(v) 1st Offense \$250.00</p> <p>LUMOS NETWORKS: \$250.00 Section 2(5)(v) 1st Offense \$250.00</p> <p>PACT Stanwix Plant: \$0.00</p> <p>Penn Telecom Inc: \$250.00 Section 2(5)(v) 1st Offense \$250.00</p> <p>Verizon Business: \$750.00 Section 2(4) 2nd Offense \$500.00</p> <p>Section 2(5)(v) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time for Ticket 20231593483. Responded "Clear" on 6/16/23. Response was due 6/12/23. Recommendation: Education Required; penalties applied</p> <p>LUMOS NETWORKS is in violation of sections: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time for Ticket 20231593483. Responded "Clear" on 6/16/23. Response was due 6/12/23. Recommendation: penalties applied</p> <p>Comcast is in violation of sections: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time for Ticket 20231593483. Responded "Clear" on 6/16/23. Response was due 6/12/23. Recommendation: penalties applied</p> <p>Penn Telecom Inc is in violation of sections: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time for Ticket 20231593483. Responded "Clear" on 6/16/23. Response was due 6/12/23. Recommendation: Education Required; penalties applied</p> <p>PACT Stanwix Plant is in violation of sections: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time for Ticket 20231593483. Responded "Conflict" on 6/9/23. Conflict is not a final response to a ticket. Response was due 6/12/23. Recommendation: Education Required; penalties applied</p>	
39855	<p>Facility Owner: Columbia Gas of PA</p> <p>Contractor/Excavator: PennDOT</p> <p>Project Owner: PennDOT - Placeholder</p> <p>Other: BRADFORD TOWNSHIP MCKEAN COUNTY</p> <p>Other: Lewis Run Borough/Lewis Run Borough Sewer Authority</p>	<p><u>On 6/28/2023 9:25:00 AM at 660 Minard Run (SR 0770), BRADFORD TWP, MCKEAN</u> On Tuesday, October 8, 2024, at the DPC meeting- Bradford Twp McKean County was disputing and it was voted to Accept the DPI's recommendations. ***** Bradford Township McKean County is disputing. *****</p> <p>The incident occurred on 6/28/2023, at 9:25am, at 660 Minard Run (SR 0770), Bradford Twp., McKean County.</p> <p>A Columbia Gas line was damaged.</p> <p>Columbia Gas' alleged violation report (AVR) states "PennDOT was performing clean up in existing ditches when they damaged an unmarked 1" plastic company-side gas service. They notified 911 and Columbia Gas when the damage occurred. Columbia Gas responded immediately to make the area safe and complete repairs. Columbia does not have any post-locate pictures to prove that the line was marked at the time of the ticket being placed, but would like to draw attention to the ticket being almost two months old. Columbia does not believe PennDOT was onsite for that duration and should have placed a new locate request."</p>	<p>PennDOT: \$3,000.00 Section 5(2.1) 3rd Offense \$2,000.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(16) 2nd Offense \$750.00</p> <p>BRADFORD TOWNSHIP MCKEAN COUNTY: \$500.00 Section 2(5)(v) 1st Offense \$500.00</p> <p>Lewis Run Borough/Lewis Run Borough Sewer Authority: \$1,000.00 Section 2(5)(vii) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>On 2/5/2024 an AVR Request Letter was mailed and e-mailed to PennDOT.</p> <p>PennDOT's alleged violation report (AVR) states "Crew was cleaning parallel ditches along SR 770/Minard Run Rd. with an excavator. Excavator exposed and crushed a service line at #660 Minard Run Rd. Service line was not marked so no hand digging was done within the tolerance zone of the line. Gas company was called immediately to notify of the damages. No gas leaked from the line. Gas company repaired the line. Distribution line that runs parallel with SR 770/Minard Run Rd. was marked. Service line to house was not marked in yellow."</p> <p>PennDOT is in violation of sections: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Ticket 20231312283 had a lawful start date of 5/16/23 thru 5/25/23 with a duration 4 days, the line was hit on 6/28/23. Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. Line hit was 6/28/23 and AVR was filed 2/14/24. Recommendation: penalties applied</p> <p>Bradford Township Mckean County is in violation of sections: Section 2(5)(v) – Failed to respond to a routine One Call ticket for Ticket 20231312283. Did not respond through Pa One Call. Recommendation: Education Required; penalties applied Lewis Run Borough/Lewis Run Borough Sewer Authority is in violation of sections: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification for Ticket 20231791550. Did not respond through Pa One Call. Recommendation: Education Required; penalties applied</p>	
40182	Facility Owner: PEOPLES GAS Contractor/Excavator: VIGLIOTTI LANDSCAPING Project Owner: Homeowner	<p><u>On 6/29/2023 11:30:00 AM at 6308 WILKINS AVE, PITTSBURGH CITY, ALLEGHENY</u> On Tuesday, October 8, 2024, at the DPC meeting- Vigliotti Landscaping was disputing and it was voted to keep the violations and reduce all penalties by 50% and keep education. ***** Vigliotti Landscaping is disputing. ***** The incident occurred on 6/29/2023, at 11:30am, at 6308 Wilkins Ave., Pittsburgh City, Allegheny County.</p> <p>No Pa One Call Ticket.</p> <p>A Peoples Gas line was leaking. According to Peoples Gas the gas line was not damaged but found to be leaking. 911 was not called.</p>	VIGLIOTTI LANDSCAPING: \$875.00 Section 5(2.1) 1st Offense \$500.00 Section 5(16) 1st Offense \$250.00 Section 5(17) 1st Offense \$125.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Peoples Gas' alleged violation report (AVR) states "Vigliotti Landscaping was completing landscaping work at 6308 Wilkins Ave. and uncovered a leaking company owned steel gas service line. However, Vigliotti did not place a PA One Call before digging with mechanized equipment on this project." Pa One Call noted under the comments that, "Contractor has placed One Call notifications with PA One Call in the past. Vigliotti Landscape telephone number 412-247-5563."</p> <p>On 2/6/2024 an AVR Request Letter was mailed to VIGLIOTTI LANDSCAPING and the Homeowner. No AVR's have been received to date.</p> <p>Vigliotti Landscaping is in violation of sections: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Was working without a Pa One Call Ticket. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of request. Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. Did not fill out an Alleged Violation Report. Recommendation: Education Required; penalties applied</p>	
39822	<p>Facility Owner: PPL Contractor/Excavator: Latona Trucking and Excavation Project Owner: PennDOT Other: Amerigas Propane Other: Chestnuthill Township Other: First Energy/MetEd Other: Uniti Fiber</p>	<p><u>On 7/10/2023 10:00:00 AM at 1747 SR 0209, CHESTNUTHILL TWP, MONROE</u> On Tuesday, October 8, 2024, at the DPC meeting- Met-Ed/FirstEnergy was disputing and it was voted to Remove the penalty but keep the violation. ***** First Energy/MetEd is disputing. *****</p> <p>The incident occurred on 7/10/2023, at 10:00am, at 1747 SR 0209, Chestnut Hill Twp., Monroe County.</p> <p>A PPL electrical line was damaged.</p> <p>PPL's alleged violation report (AVR) states "On Monday the 10th of July, Latona Trucking and Excavation was working on State Route 209 doing road reconstruction on a PA one call ticket from February with no updates called in. While they were excavating they hit electric service feeding 1747 SR 209, when speaking with the contractor they noticed the line coming down the pole and did not call in for remarks and continued digging that when they hit the service line. The service to the building could not be repaired and a bypass was laid down to get them back into service."</p> <p>On 2/5/2024 an AVR Request Letter was mailed and e-mailed to Latona Trucking and Excavation and PennDOT.</p> <p>Latona Trucking and Excavation's alleged violation report (AVR) states "On 07/10/2023, Latona trucking began the roadway widening construction on SR</p>	<p>PPL: \$1,000.00 Section 2(5)(i) 2nd Offense \$1,000.00</p> <p>Amerigas Propane: \$250.00 Section 2(4) 1st Offense \$250.00</p> <p>Chestnuthill Township: \$1,000.00 Section 2(5)(vii) 1st Offense \$1,000.00</p> <p>First Energy/MetEd: \$0.00 Section 2(5)(vii) 1st Offense \$0.00</p> <p>Uniti Fiber: \$250.00 Section 2(4) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
40341	<p>Facility Owner: PEOPLES GAS COMPANY LLC</p> <p>Contractor/Excavator: ORLANDO PLUMBING COMPANY</p> <p>Project Owner: HOMEOWNER</p> <p>Other: WEST HOMESTEAD BOROUGH</p>	<p><u>On 7/11/2023 11:00:00 AM at 3437 PINWOOD DR, WEST HOMESTEAD BORO, ALLEGHENY</u> On 10/08/2024 the Damage Prevention Committee voted to keep the violation and remove the penalty but to keep the required education that was recommended to West Homestead Borough.</p> <p>West Homestead Borough is disagreeing and stated that they accept the violation but request a consideration for a reduction in the penalty. They also stated that the Borough Representative responsible for the One Call response, will be taking the training. *****</p> <p>Incident occurred on 7/11/2023 at 3437 Pinewood Dr., at 11 a.m. in West Homestead Borough in Allegheny County.</p> <p>A Gas line was hit and damaged.</p> <p>PEOPLES GAS COMPANY LLC stated in their Alleged Violation Report (AVR) that “Orlando Plumbing Company was working for the homeowner at 3437 Pinewood installing a new gas service line when they struck and damaged the active unmarked medium pressure gas service line. The active gas line was unmarked due to Orlando Plumbing failing to place a PA One Call prior to beginning excavation and damaging the active gas line. Orlando Plumbing placed an emergency PA One call after the damage occurred.</p> <p>ORLANDO PLUMBING COMPANY was emailed and mailed an AVR request letter on 2/06/2024. No contact or AVR has been received to date. No return mail has been received. No undeliverable email was received. This letter is considered delivered.</p> <p>The homeowners were sent an AVR request letter on 2/06/2024. No AVR or contact has been made. There is no email on file. Mail was returned on 7/23/2024 and resent to forwarding address. Address was updated in case. *****</p> <p>*Emergency Ticket 20231922118 was requested by Orlando Plumbing Company on 7/11/2024 at 11:48. This is after the Peoples Gas line was damaged. West Homestead Borough never responded. *****</p> <p>ORLANDO PLUMBING COMPANY are in violation of Section:</p> <p>5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of notification of a violation of ACT 50. The penalty is applied. Education is required.</p> <p>5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. The penalty is applied. Education is required.</p> <p>5(8) Excavator failed to notify 911.</p> <p>Recommendation: The penalty is applied. Education is required.</p>	<p>ORLANDO PLUMBING COMPANY: \$2,500.00 Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$500.00</p> <p>Section 5(2.1) 1st Offense \$1,000.00</p> <p>HOMEOWNER: \$0.00 Section 6.1(7) 1st Offense \$0.00</p> <p>WEST HOMESTEAD BOROUGH: \$0.00 Section 2(5)(vii) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>The homeowners who are the Project Owners are in violation of Section: 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 10 Business Days of a line strike. This is a first-time violation and the \$500. Penalty is reduced to a warning. *****</p> <p>Listed below are facility owners in violation of Act 50, Section 2(5)(vii) failed to respond to an emergency ticket within the required amount of time.</p> <p>WEST HOMESTEAD BOROUGH are in violation of Section: 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. The penalty is applied. Education is required.</p>	
42342	<p>Facility Owner: Columbia Gas Contractor/Excavator: Ken Poff Project Owner: Hagens Electric Project Owner: Homeowner</p>	<p><u>On 10/2/2023 9:50:00 AM at 2051 LOG CABIN RD, WEST MANCHESTER TWP, YORK</u> On 10/8/24 the DPC voted to: Section 5(2.1)- Keep violation, reduce penalty by 50% from \$1,000 to \$500. Section 5(8) – Remove violation and penalty. Section 5(16) - Keep violation, reduce penalty by 50% from \$500 to \$250. Section 5(17) - Keep violation and penalty as is.</p> <p>*****</p> <p>Ken Poff is disputing. His email states, "the findings of this "investigation" as there are untrue statements and accusations and no mention of the fact of there being multiple 811 calls put in place by MetED for the electric line that was being ran, along with the homeowners and Hagens Electric who I was doing the job for. Since I was doing the work for Hagens I should have been covered under their 811 ticket." *****</p> <p>Incident occurred October 2nd, 2023 9:50am, 2051 Log Cabin Road, West Manchester Township, York County.</p> <p>A gas line was damaged.</p> <p>Columbia Gas Company's Alleged Violation Report (AVR) states, "Ken Poff, subcontracted by Hagens Electric, was digging a new trench for electric from the house to a new pole when he struck and damaged an inaccurately marked 1" plastic gas service. The property owner notified Columbia Gas when the damage occurred. Columbia Gas responded immediately to make the area safe and complete repairs. 911 and 811 were not notified. The local Damage Prevention Specialist spoke with Ken Poff about the requirement to notify 911 when there is a release of gas, as well as not being permitted to piggyback off another contractor's One Call ticket. Mr. Poff refused to provide address information at the time of the damage."</p> <p>PA1call ticket 20232632315 is for Hagen's Electric. 911 was not notified according to the AVRs received to date.</p>	<p>Ken Poff: \$1,000.00 Section 5(2.1) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$250.00</p> <p>Section 5(17) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Homeowner was mailed a request for an AVR on 3/6/2024. Excavator, Ken Poff, was emailed a request for an AVR on 3/6/2024. No AVR has been received to date. Email delivery to the server is attached. Hagens Electric was mailed and emailed a request for an AVR on 3/4/2024. No AVR has been received to date.</p> <p>Homeowner's AVR states, "I am submitting this in response to your letter to me dated March 6th with case number 042342.</p> <ol style="list-style-type: none"> "Did Hagens Electric or their subcontractor, Ken Poff, hit the utility?" Ken hit the utility. The utility was marked incorrectly, approx. 22 ft to the west (see attached image "map") along what appeared to be an old, inactive utility. Where he hit was unmarked. "Was 911 and/or the Facility Owner notified?" Yes, the facility owner, Columbia Gas, was immediately notified. "Did your excavator have ask you as the homeowner to place a PA1call?" I was never asked by the excavator to place a PA1call. <p>Attached images: "gas" and "gas2" are looking eastward. See yellow marked line in foreground over inactive line. In background see Columbia Gas employees repairing active line that was unmarked. "gas3" shows active line that was severed, looking eastward. "gas4" and "gas5" show inactive line that is marked with yellow looking towards house. "gas6" shows after repair by Columbia Gas in undeveloped ally east of my property. Blacked out markings show where original markings were, yellow are the corrected markings which were marked after incident. "map" is not to scale but shows where incident occurred in relation to markings.</p> <p>Called Hagen's Electric and left voicemail for Ken Poff's address.</p> <p>Violations:</p> <p>Ken Poff Excavating Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Education is required. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. Education is required. Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. Education is required.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
42126	<p>Facility Owner: NATIONAL FUEL GAS</p> <p>Contractor/Excavator: ERIE CITY OF</p> <p>Other: Erie Water Works</p> <p>Other: Everstream</p> <p>Other: First Energy - Penelec, Penn Power</p>	<p><u>On 10/5/2023 9:00:00 AM at 4115 WARSAW AVE, ERIE CITY, ERIE</u> On 10/8/2024 the DPC voted Motion by Ditty because its less than 18 inches – remove the violation and penalty. *****</p> <p>City of Erie is disputing due to the situation becoming an emergency. *****</p> <p>This non damage Incident occurred on October 5th, 2023, at 9am at 4115 Warsaw Avenue, Erie City, Erie County.</p> <p>***Non-Damage Event***</p> <p>National Fuel Gas' Alleged Violation Report (AVR) states, "One call ticket had a lawful start date of 10/6 when an NFG employee arrived onsite on 10/5 it was discovered that the excavation was already underway."</p> <p>Erie City's AVR states, "We had to remove the slabs of Concrete a day early because the slab of concrete street broke off and was standing up causing and unsafe road condition in the middle of street. It became emergency at that point where if a car would of hit that it would of cause an accident with damage or bodily harm if some stepped in it would of cause bodily harm. All we did is removed the concrete slabs and did not disturb or dig into the subbase of the road. After the removal of the effect areas, we filled the areas in with asphalt."</p> <p>The picture provided by NFG is date stamped October 5th, 2023, at 8:52am. Ticket 20232760869 had a legal start date of 10/6/23. A large section of the road was already excavated by the time this picture was taken.</p> <p>The following facility owners failed to give a final response to ticket 20232760869: 0 LV PENNSYLVANIA ELECTRIC CO LV-SCHEDULED MARK 10/5/2023 5:52:39 PM MBR-WEBSVC 0 EWA ERIE WATER WORKS EWA-SCHEDULED MARK 10/5/2023 5:51:35 PM CLS-WEBSVC 0 EVS EVERSTREAM EVS-SCHEDULED MARK 10/5/2023 5:51:35 PM CLS-WEBSVC</p> <p>Violation:</p> <p>Erie City Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Education is required. (Has completed Facility Owner Training, but not Excavator training.)</p> <p>Penn Electric Section 2(5)(v) – Failed to respond to a routine One Call ticket.</p> <p>Erie Water Works</p>	<p>ERIE CITY OF: \$0.00</p> <p>Erie Water Works: \$500.00 Section 2(5)(v) 1st Offense \$500.00</p> <p>Everstream: \$500.00 Section 2(5)(v) 1st Offense \$500.00</p> <p>First Energy - Penelec, Penn Power: \$500.00 Section 2(5)(v) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(v) – Failed to respond to a routine One Call ticket. Education is required.</p> <p>Everstream Section 2(5)(v) – Failed to respond to a routine One Call ticket. Education is required. Delinquent on Facility owner training as of 4/5/2024.</p>	
43600	<p>Facility Owner: PA American Water Contractor/Excavator: Desoto Line Service Project Owner: Columbia Gas of PA Designer: Campos Other: Verizon Other: WASHINGTON CITY OF</p>	<p><u>On 12/4/2023 12:30:00 PM at 659 S MAIN ST, Washington City, WASHINGTON</u> On 10/08/2024: The DPC voted to remove all violations and penalties for PA American Water.</p> <p>*****</p> <p>PAWC is disputing, stating, "I have attached the PA One Call tickets which show we marked to the extent the information was on our records on the due date of 06/12/2023. Under the law we are responsible to make a reasonable effort to locate or notify excavators of the existence of abandoned lines. If we do not have any record of such we cannot. We were unaware of the abandoned line; we did not have any record of it. In the law the definition of "Abandoned" is no longer in service and physically disconnected from a line, our ability to locate abandoned lines is limited because these lines have been disconnected from the new line. We have now added the line to our GIS as retired."</p> <p>*****</p> <p>Incident occurred on 12/04/2023, at 12:30 PM, at 659 S. Main Street, North Franklin Township, Washington County.</p> <p>An unmarked water service line was hit.</p> <p>PA American Water submitted an AVR on 03/26/2024, in response to the AVR request letter sent 03/07/2024. Their AVR states, "Utility was marked, but there was a second line that was not on our maps that had been covered by concrete that was not marked. The line has since been added to our maps for future digs."</p> <p>Desoto Line Service submitted an AVR on 12/08/2023. Their AVR states, "Desoto Line Services, working on behalf of Columbia Gas for an infrastructure replacement project, struck and damaged an unmarked water service. The closest water mark was 12 feet from where the line was damaged. Proper notifications were made." Photos were submitted.</p> <p>Columbia Gas of PA submitted an AVR on 12/06/2023. Their AVR states, "Desoto was working for columbia gas on a infrastructure replacement project, when the unmarked service was struck. The closest water mark was 12ft from where the line was damaged".</p> <p>Campos- An AVR was not requested from the designer.</p> <p>Violations-</p>	<p>PA American Water: \$0.00</p> <p>Verizon: \$9,000.00 Section 2(4) Subsequent \$1,500.00</p> <p>Section 2(4) Subsequent \$1,500.00</p> <p>WASHINGTON CITY OF: \$500.00 Section 2(4) 1st Offense \$250.00</p> <p>Section 2(5)(v) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Verizon-</p> <ul style="list-style-type: none"> - Section 2(4) – Failed to respond to designer’s request for information within 10 business days. Design Ticket 20220322097. Recommendation: penalty applied. - Section 2(4) – Failed to respond to designer’s request for information within 10 business days. Design Ticket 20220322098. Recommendation: penalty applied. - Section 2(4) – Failed to respond to designer’s request for information within 10 business days. Design Ticket 20222072770. Recommendation: penalty applied. - Section 2(4) – Failed to respond to designer’s request for information within 10 business days. Design Ticket 20222072771. Recommendation: penalty applied. - Section 2(4) – Failed to respond to designer’s request for information within 10 business days. Design Ticket 20223360933. Recommendation: penalty applied. - Section 2(4) – Failed to respond to designer’s request for information within 10 business days. Design Ticket 20223360934. Recommendation: penalty applied. <p>Washington City Of-</p> <ul style="list-style-type: none"> - Section 2(4) – Failed to respond to designer’s request for information within 10 business days. Design Ticket 20220322098. Recommendation: Penalty applied. (No prior violations of 2(4) located.) (Facility owner and locator education was completed by City of Washington on 05/23/2024.) - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20231591232. Recommendation: Penalty applied. (Facility owner and locator education was completed by City of Washington on 05/23/2024.) 	

Committee Review

No cases scheduled.