



Pennsylvania Public Utility Commission

**Damage Prevention Committee Meeting Case List
July 8, 2025**

Omnibus Session

Case Number	Stakeholders	Summary	Violations & Recommendation
51435	<p>Facility Owner: UGI UTILITIES Contractor/Excavator: North Central Pennsylvania Equipment LLC Project Owner: Unknown Other: G.H PASTOR</p>	<p><u>On 11/13/2024 9:24:00 AM at 1289 S Main St, MANSFIELD BORO, TIOGA</u> North Central Pennsylvania Equipment LLC submitted additional information with a dispute. Upon review of this information, a PA One call ticket was located and the photos support their dispute. The violations and penalties were withdrawn.</p> <p>*****</p> <p>The incident occurred on 11/13/2024, at 9:24 AM, at 1289 South Main Street, in Mansfield Borough, Tioga County.</p> <p>A gas line owned by UGI Utilities was damaged.</p> <p>UGI Utilities submitted an Alleged Violation Report (AVR). Their AVR states, "Contractor without a PA-1 Call hit and damaged a 1" plastic service. This line was marked out by UGI due to it being a new service that had been installed. Marks were accurate." Photos were submitted.</p> <p>G.H PASTOR was initially identified as the excavator. They submitted a dispute stating they were the general contractor and subcontracted the excavator (NCP Equipment & Land Management).</p> <p>North Central Pennsylvania Equipment LLC - AVR has not been received as of 04/17/2025.</p> <p>The project owner is unknown.</p> <p>There was not a PA One Call ticket.</p> <p>There was no indication that 911 was called in UGI's AVR or photos.</p> <p>Violations:</p> <p>G.H PASTOR - Violations withdrawn. They were not the excavator for this project.</p> <ul style="list-style-type: none"> - Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. - Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner's facilities in the construction area. - Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the 	<p>North Central Pennsylvania Equipment LLC: \$0.00</p> <p>G.H PASTOR: \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property.</p> <ul style="list-style-type: none"> - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line.- Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. <p>North Central Pennsylvania Equipment LLC – Withdrawn.</p> <ul style="list-style-type: none"> - Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. - Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. - Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. 	
51958	<p>Facility Owner: PWSA Contractor/Excavator: MONGIOVI AND SON PLUMBING AND EXCAVATING Project Owner: MONGIOVI AND SON PLUMBING AND EXCAVATING - Spacesaver</p>	<p><u>On 12/23/2024 9:00:00 AM at 137 S 12TH ST, PITTSBURGH CITY, ALLEGHENY</u> The incident occurred on 12/23/2024 at 137 S 12TH ST in Pittsburgh City in Allegheny County.</p> <p>A water main was hit and damaged.</p> <p>PITTSBURGH WATER & SEWER AUTHORITY the facility owner stated in their Alleged Violation Report (AVR) that “Contractor digging and hit an accurate marked water main. PWSA responded and made repairs. Careless digging”. Pictures were provided.</p> <p>MONGIOVI AND SON PLUMBING AND EXCAVATING the excavator and listed project owner on ticket 20243441541 have not submitted an AVR as of 3/14/2025.</p> <p>VIOLATIONS MONGIOVI AND SON PLUMBING AND EXCAVATING are in violation of: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 business days of striking a line. Recommendation: The penalties are applied. Excavator and Project Owner education is required.</p>	<p>MONGIOVI AND SON PLUMBING AND EXCAVATING: \$1,500.00 Section 5(4) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>
51978	<p>Facility Owner: UGI Contractor/Excavator: LEHIGH COUNTY AUTHORITY Project Owner: LEHIGH COUNTY AUTHORITY - Spacesaver</p>	<p><u>On 12/27/2024 3:03:00 PM at 2549 S CARBON ST, ALLENTOWN CITY, LEHIGH</u> The incident occurred on 12/27/2024 at 2549 S CARBON ST in Allentown City in Lehigh County.</p> <p>A gas line was hit and crimped, there was no escape of gas.</p> <p>LEHIGH COUNTY AUTHORITY stated in their Alleged Violation Report (AVR) that “Digging for a</p>	<p>UGI: \$1,500.00 Section 2(5)(i) 3rd Offense \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>water main break in the cul-de-sac off of S. Carbon St. Followed marks and dug over 4 feet away from them to be out of the tolerance zone. While digging outside the tolerance zone a gas line was crimped. The UGI markings had no size of main or lateral or company name marked on them also". Pictures were provided.</p> <p>UGI UTILITIES INC stated in their AVR that "LEHIGH COUNTY AUTHORITY WAS DIGGING TO REPAIR WATER LEAK AND WHEN DOING SO THEY STRUCK A INCORRECTLY MARKED GAS SERVICE FACILITY CREATING A DAMAGE. THERE WAS NO GAS LEAK FROM THIS DAMAGE. FIRE DEPARTMENT WAS NOT CALLED DUE TO NO LEAKS FROM THE DAMAGE. UGI LOCATOR MIS MARKED THE GAS SERVICE HOUSE 2549 S. CARBON ST". Pictures were provided.</p> <p>UGI is in violation of: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. This is a third offense.</p> <p>Recommendation: The penalties are applied.</p>	
52113	<p>Facility Owner: Comcast Contractor/Excavator: CHAMPION CONSTRUCTION SERVICES Project Owner: RHP PROPERTIES INC Other: AUDUBON WATER CO Other: VERIZON PA LLC</p>	<p><u>On 12/30/2024 1:00:00 PM at 108 Whitley Dr. NORRISTOWN BORO, MONTGOMERY RHP</u> Properties disagreed stating that the two entities are one and the same. DPI sent an email on 6/03/2025 asking which 2 entities are being referred to. On 6/04/2025 DPI Maki sent an email asking if RHP is still wanting to disagree, since they sent an email asking about if they can pay by check. No response has been heard as of 6/10/2025, except "understood"</p> <p>RHP is not disputing as of 6/15/2025. Case moved to Omnibus list. ***** The incident occurred on 12/30/2024 at 108 Whitley Dr., in Norristown Borough in Montgomery County.</p> <p>A Comcast Communications line was damaged.</p> <p>Comcast stated in their Alleged Violation Report (AVR) that "Feeder cut by backhoe. Installing power line in area". Pictures were provided. Compliance Research: No tickets found for address references but one found for a different address # on same street, different municipality; similar contractor name but different contractor address/phone. May or may not be related.</p> <p>Danielle from Champion Construction asked for a call back on 2/28/2025. DPI returned a call to Champion Construction who stated that they just submitted the AVR yesterday. Danielle had to do some digging to find out what happened, because they were working at 112 Whitley Dr. The person that was the lead at the dig site had left the company, so it took a while for the information to get down the chain.</p>	<p>CHAMPION CONSTRUCTION SERVICES: \$1,000.00 Section 5(2.1) 1st Offense \$1,000.00</p> <p>RHP PROPERTIES INC: \$1,500.00 Section 6.1(7) 1st Offense \$1,000.00</p> <p>Section 6.1(8) 1st Offense \$500.00</p> <p>AUDUBON WATER CO: \$250.00 Section 2(5)(v.2) 1st Offense \$250.00</p> <p>VERIZON PA LLC: \$750.00 Section 2(5)(v) 3rd offense \$750.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Champion Construction Services stated in their AVR that they were “Digging for installation of electrical conduit for 112 Whitley. Meter location was at 108 Whitley. Dig call was only made for and marked on 112 Whitley. Communication wires were hit for home at 108. Homeowner call communication company and had fixed right away. I have no pictures at this point but can get in the next couple days”. The project is listed at <\$400,000. No pictures have been received to date. DPI Maki sent an email asking for a physical address for RPH on 2/28/2025.</p> <p>RHP Properties INC (RHP) the project owner was emailed an AVR request with questions on 2/28/2025. The AVR request letter was mailed on Tuesday 3/04/2025. On Sunday 3/02/2025 an email was received that “This communication has been received. Currently we are investigating this matter and will report/respond to the notification as required quickly”. This came from RHP Properties inc. Address is updated with what was provided in the email. On 3/05/2025 a read receipt was received from D West. Answers to questions in the AVR request letter were due by 3/30/2025. No questions answered nor AVR has been received as of 3/30/2025. AVR was due by 1/29/2025. On 4/18/2025 and AVR was received from Valley Forge Limited Partnership. They stated that "Manufactured home community employed Champion Construction to install a new home at 112 Whitley. While digging to run a new utility line the contractor crossed unmarked areas and hit a comcast communication line. The line affected service to site 108 Whitley. The owner of site 108 Whitley called Comcast and services were restored".</p> <p>*****</p> <p>*Ticket 20243262051 was submitted by Champion Construction on 11/21/2024 with a response due by 11/25/2024. Ticket is for excavation of footers by auguring. Work is listed as being done for RHP. Verizon did not respond until 11/26/2024. Audubon Water Company did not respond “conflict “until 11/28/2025 and never provided a final response.</p> <p>VIOLATIONS CHAMPION CONSTRUCTION SERVICES are in violation of: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Recommendation: The penalty is applied. Education is required.</p> <p>RHP PROPERTIES are in violation of: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Section 6.1(8) - Project Owner failed to comply with all requests for information by the commission relating to the commission's enforcement authority under this act within 30 days of receipt of written request. Recommendation: The penalties are applied. Education is required</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Listed below are facility owners in violation of Act 127-2024, Section 2(5)(v) Failed to respond to a routine One Call ticket within the required amount of time.</p> <p>AUTOBON WATER CO is in violation of: Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. See ticket 20243262051 details above. Recommendation: The penalty is applied. Education is required</p> <p>VERIZON PA LLC is in violation of: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. This is a third offense. See ticket 20243262051 details above. Recommendation: The penalty is applied.</p>	
52377	<p>Contractor/Excavator: CRS Contracting LLC</p> <p>Project Owner: JEFFERSON TOWNSHIP -BUTLER CO</p> <p>Other: HERBERT ROWLAND AND GRUBIC INC</p> <p>Other: HOMEOWNER</p> <p>Other: West Penn Power / First Energy</p>	<p>On 1/7/2025 12:00:00 AM at 204 JANICE LN, JEFFERSON TWP, BUTLER Jefferson Twp accepted a reduced penalty and are not disagreeing. see attached emails *****</p> <p>Dispute- JEFFERSON TOWNSHIP -BUTLER CO wants to dispute all violations and penalties. See attached email. *****</p> <p>The incident occurred on 1-07-2025 at 204 Janice Ln in Jefferson Township, Butler County.</p> <p>A West Penn Electric line was hit and damaged.</p> <p>WEST PENN POWER/FIRSTENERGY the facility owner stated in their Alleged Violation Report (AVR) that On October 30, 2024, CRS Contracting LLC, Excavator, submitted POCS Routine Ticket 20243040874 for an excavation to replace existing culverts on Janice Lane between Fisher Road and Brian Lane, Jefferson Township, Butler County, Pennsylvania. On January 7, 2025, West Penn Power was notified of an outage in the area. USIC, West Penn Power’s Contract Locator, investigated and determined that there was snow on the ground and the marks were no longer visible at the time of the dig in. The root cause of the damage is the Excavator failed to submit an update request to have the underground facilities remarked.</p> <p>CRS Contracting LLC the excavator were mailed and emailed an AVR request letter on 3/13/2025. On 4/02/2025 and AVR was received. CRS Contracting stated in their AVR that “We started off the day with a tool box talk. In our culvert crossing we had to add concrete block bulkheads (2’x2’x6’) to the rip rap area. To do this we started by stripping the rip rap back so we could place the bulk heads. Once the riprap was stripped back we needed to go a little deeper to set the bulkhead in the ground about 2" below stream surface. As we started to do this the electric line was hit. The spotter stopped the work and PA One call was notified. Talking with the service provider the line should be much more than 2"-4" below stream grade. West Penn Power</p>	<p>CRS Contracting LLC: \$2,250.00 Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(3) 1st Offense \$500.00</p> <p>Section 5(4) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>JEFFERSON TOWNSHIP -BUTLER CO: \$750.00 Section 6.1(3) 1st Offense \$250.00</p> <p>Section 6.1(7) 1st Offense \$500.00</p> <p>HERBERT ROWLAND AND GRUBIC INC: \$250.00 Section 4(2.2) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>provided us with a warning letter which is attached. Also attached is a measurement from the top of the conduit to the surface of the water.</p> <p>HERBERT ROWLAND AND GRUBIC INC, the designer were mailed and emailed an AVR request letter on 3/13/2025.</p> <p>HERBERT ROWLAND AND GRUBIC INC stated in their AVR that” “HRG was not on site during this event. Submitting as designer requirements”. Project is listed as <\$400,000. With level “D” Subsurface Utility Engineering (SUE) used. Report was provided.</p> <p>On 1/07/2025 HRG provided new contact information for this case. DPI responded with an email asking if we could have one contact for HRG.</p> <p>JEFFERSON TOWNSHIP -BUTLER CO the project owner AVR request letter was mailed and emailed on 3/14/2025.</p> <p>On 3/28/2025 and AVR was received and stated that “Jefferson Township was notified the day of incident by West Penn Power Co. Jefferson Township Representative, nor the Township Engineer was present the day of the damage”. Report was provided. Please note that the day of this incident is 1/07/2025. On D/PI Maki returned a call to Jefferson Township and spoke with the Secretary - Lois, who provided an email for Leo Rosenbauer. DPI followed up with an email to Leo and William about the stakeholder review notice and if they want to disagree, it must be in writing. On 6/05/2025 DPI Maki returned a call to Jefferson Township Butler Co and explained that we need to have something in writing stating that they disagree, before we can make any changes. DPI agreed that this is a first offense and could consider lowering the penalties but cannot make any changes until a disagreement is received in writing. Office email was given. The manager asked to be included in our contacts, and the email was updated in the case and the contacts list.</p> <p>Homeowner of 204 Janice Lane was mailed an AVR request letter on 3/13/2025. On 4/02/2025 DPI Maki returned a call to the homeowner, who left a voice message stating that “this was done by the Township, Jefferson Township. They were digging, I'm not sure what they were doing. They made a mess of my yard. I know that, but this was not something that we scheduled or had these people come and do this stuff. They just did. It was really like it was a drain underneath the road that they widened”.</p> <p>VIOLATIONS</p> <p>CRS Contracting LLC is in violation of:/ Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 5(3) – Excavator failed to preserve mark-outs or request a remark. Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 business days of striking a line. Recommendation: The penalties are applied. Education is required.</p> <p>JEFFERSON TOWNSHIP -BUTLER CO is in violation of: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Section 6.1(3) – Released a project to bid or construction before final design was complete. Recommendation: Penalties reduced 50% for first time ever offender. Education is required.</p> <p>HERBERT ROWLAND AND GRUBIC INC is in violation of: Section 4(2.2) – Failed to submit a design notification through the One Call System when a design drawing is completed Recommendation: The penalties are applied. Education is required.</p>	
52120	<p>Facility Owner: UGI UTILITIES INC. - SPACESAVER Contractor/Excavator: UGI Project Owner: UGI - SPACESAVER Other: HELLERTOWN BORO AUTHORITY / Hellertown Boro</p>	<p><u>On 1/7/2025 11:07:00 AM at 301 TOBIAS DR, HELLERTOWN BORO, NORTHAMPTON</u> HELLERTOWN BORO AUTHORITY / Hellertown Boro disagreed. On 5/07/2025 DPI Maki sent an email offering to reduce the penalty by 1/2 and sent the Emergency ticket information. On 5/21/2025 Hellertown Borough accepted the offer to reduce the penalty from \$1000. to \$500. and to pass the compliance education. ***** The incident occurred on 1/07/2025 at 301 Tobias Dr. in Hellertown Borough in Northampton.</p> <p>A Gas line was hit and damaged.</p> <p>UGI the project owner, facility owner and excavator, stated in their Alleged Violation Report (AVR) that "UGI CREW WAS DIGGING TO RENEW A GAS SERVICE AND WHEN DOING SO THEY STRUCK A GAS SERVICE FACILITY TO HOUSE 301 CREATING A DAMAGE AND A LEAK. DIGGING IN THE TOLERACNE ZONE". 911 was notified. UGI noted that they were not digging prudently in the tolerance zone. ***** *Emergency Ticket 20250020140 was submitted by UGI on 1/02/2025 at 7:16 to repair a gas leak. HELLERTOWN BORO AUTHORITY / Hellertown Boro did not respond until 1/07/2025.</p> <p>*Emergency Ticket 20250070985 was submitted by UGI on 1/07/2025 at 11:01 by UGI. Caller has notified 911. All responses were timely. ***** VIOLATIONS</p>	<p>UGI: \$500.00 Section 5(4) 1st Offense \$500.00</p> <p>HELLERTOWN BORO AUTHORITY / Hellertown Boro: \$500.00 Section 2(5)(vii) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>UGI is in violation of: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: The penalty is applied.</p> <p>Listed below are facility owners in violation of Act 127-2024, Section 2(5)(vii) Failed to respond to an emergency One Call ticket as soon as practicable.</p> <p>HELLERTOWN BORO AUTHORITY / Hellertown Boro is in violation of: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Recommendation: The penalty of \$1000 is reduced to \$500. Compliance education is required.</p>	
52232	<p>Facility Owner: Peoples Gas Contractor/Excavator: Independent Enterprises Inc Project Owner: PITTSBURGH WATER & SEWER AUTHORITY (PWSA) Other: GAI CONSULTANTS Other: MONALOH BASIN ENGINEERS</p>	<p><u>On 1/9/2025 8:30:00 AM at WAPELLO ST, PITTSBURGH CITY, ALLEGHENY</u> The incident occurred on 01/09/2025 at 8:30 AM, on Wapello Street, Pittsburgh City, Allegheny County.</p> <p>A gas line owned by Peoples Gas was damaged. 911 was called.</p> <p>Peoples Gas, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, "On 1/9/2024, Independent Enterprises struck an accurately marked PNG SL. PNG crews were called and repairs were made." Photos were submitted.</p> <p>Independent Enterprises Inc, the excavator and designer, submitted an AVR. Their AVR states, "Crew arrived on site at 3729 Wapello St to do a public water service replacement. While digging the road excavation the operator struck the 1" plastic gas line. Crew immediately shut down work and the Foreman called Columbia gas, once off the phone with the gas company the Foreman called 911 dispatch. Pittsburgh Fire Dept. arrived on site at 8:37am. Columbia Gas and Peoples Gas arrived on site at 9:15am. The gas line ended up belonging to Peoples Gas Co. Peoples Gas repaired the 1" plastic gas line at 10am." Photos were submitted.</p> <p>PITTSBURGH WATER & SEWER AUTHORITY, the project owner, submitted an AVR. Their AVR states, "Crew arrived on site at 3729 Wapello St to do a public water service replacement. While digging the road excavation the operator struck the 1" plastic gas line. Crew immediately shut down work and the Foreman called Columbia gas, once off the phone with the gas company the Foreman called 911 dispatch. Pittsburgh Fire Dept. arrived on site at 8:37am. Columbia Gas and Peoples Gas arrived on site at 9:15am. The gas line ended up belonging to Peoples Gas Co. Peoples Gas repaired the 1" plastic gas line at 10am." Photos were submitted.</p> <p>GAI CONSULTANTS INC. submitted an AVR. Their AVR states, "Crew arrived on site at 3729 Wapello St to do a public water service replacement. While digging the road excavation the operator struck the 1" plastic gas</p>	<p>Independent Enterprises Inc: \$1,500.00 Section 5(4) 2nd Offense \$1,000.00</p> <p>Section 5(3) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>line. Crew immediately shut down work and the Foreman called Columbia gas, once off the phone with the gas company the Foreman called 911 dispatch. Pittsburgh Fire Dept. arrived on site at 8:37am. Columbia Gas and Peoples Gas arrived on site at 9:15am. The gas line ended up belonging to Peoples Gas Co. Peoples Gas repaired the 1" plastic gas line at 10am. Final Design One Call was run by GAI Consultants on Thurs 2.6.2024, which was within the required 10 to 90-day window prior to the end of final design. Final Design ended on Tues 3.18.2024. The bid date was Thurs 3.28.2024. The total project value is over \$400,000 and during design SUE up to Quality Level (QL) A was performed. Record Drawing Research (QL-D) was done by the whole project team as the project moved through design. The surface expressions of utilities such as manholes, curb boxes, and valve boxes were surveyed (QL-C). The project owner had GAI include the cost to hire a utility locator as a subcontractor. That was Lexis Group. They connected to the locate wires and metallic pipes to use mark utility locations across the job (QL-B). The surveyor surveyed the paint markings. GAI identified places where the QL-B needed clarification and had Lexis do Test Pits (QL-A) there. Training was previously assigned to GAI for Case 17347 (training completed on Fri 6.10.2022) and Case 030748 (training completed on Fri 3.17.2023).” Photos were submitted.</p> <p>This case is related to cases: 050637, 050810, 050939.</p> <p>A faded yellow line mark is visible in Peoples Gas’ photos, showing damage occurred within the tolerance zone. The most recent ticket requested prior to the damage that occurred on 01/09/2025 was routine ticket 20242904782. This ticket was requested on 10/16/2024, 86 days prior to the damage. Peoples Gas responded, ‘Field Marked’ to this ticket on 10/18/2024. Although the emergency ticket states that damage occurred on Cornell Street, the photos and Google Maps show the damage occurred at 3716 Wapello Street. (This location was included in the routine ticket 20242904782.)</p> <p>Violations:</p> <p>Independent Enterprises Inc - - Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. - Section 5(3) – Excavator failed to preserve mark-outs or request a remark.</p> <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
52611	Facility Owner: COMCAST Contractor/Excavator: PLUG UTILITIES Project Owner: VERIZON Designer: VERIZON - SPACESAVER	<p><u>On 1/9/2025 8:30:00 AM at 213 BUNNY LN, EAST HANOVER TWP, DAUPHIN</u> 2 incidents occurred one on 1/09/2025 at 8:30 and another at 10:40 on 213 Bunny Lane in East Hannover Township in Dauphin County.</p> <p>A communications line was hit and damaged.</p>	<p>PLUG UTILITIES: \$2,250.00 Section 5(11.2) 1st Offense \$500.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Comcast stated in their first Alleged Violation Report (AVR2025FEB060015) that “EXCAVATOR HIT AN ACCURATLY MARKED FEEDER CABLE” 2-10 customers were affected. Pictures and reports were provided.</p> <p>Comcast stated in their second Alleged Violation Report (AVR2025FEB060013) that “EXCAVATOR HIT AN ACCURATLY MARKED FEEDER CABLE” 2-10 customers were affected. Pictures and reports were provided.</p> <p>PLUG UTILITIES the excavator AVR was due by 2/08/2025. As of 3/30/2025, no AVR has been submitted for this incident.</p> <p>VERIZON the project owner AVR was due by 2/08/2025. As of 3/30/2025, no AVR has been submitted for this incident.</p> <p>VIOLATIONS PLUG UTILITIES is in violation of: Section 5(11.2) – When using trenchless technology, Excavator failed to utilize at a minimum, the best practices published by the Common Ground Alliance. 21.0 Section 9 5-20 Trenchless Excavation – The trenchless excavation operator confirms and maintains the path and minimum clearance established by the project owner and design engineer by tracking and recording the path of the trenchless excavation until complete.</p> <p>Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 business days of striking a line. Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. After hitting the Comcast line and submitting emergency ticket 20250090671, they continued to excavate without waiting for a positive ticket response to the emergency ticket and hit a comcast line again. Recommendation: The penalties are applied. Education is required.</p> <p>VERIZON is in violation of: Section 6.1(3) – Released a project to bid or construction before final design was complete. Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Section 4(2.2) – Failed to submit a design notification through the One Call System when a design drawing is completed Section 4(5) – Designer’s drawing does not include One Call’s toll-free number and the serial number of the ticket.</p>	<p>Section 5(16) 1st Offense \$1,000.00</p> <p>Section 5(4) 1st Offense \$500.00</p> <p>VERIZON: \$2,750.00</p> <p>Section 6.1(3) 1st Offense \$500.00</p> <p>Section 6.1(7) 1st Offense \$1,000.00</p> <p>Section 4(2.2) 1st Offense \$250.00</p> <p>Section 4(5) 1st Offense \$250.00</p> <p>Section 4(3) 1st Offense \$250.00</p> <p>Section 4(4) 1st Offense \$250.00</p> <p>Section 9 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 4(3) – Designer’s drawing does not show the position and type of each facility owner’s line, and the name of the facility.</p> <p>Section 9 - CGA 21.0 - 2.3 Identifying Existing Facilities in Planning and Design and CGA 21.0 – 2.13 Trenchless Excavation. During the planning phase of the project, all available information is gathered from facility owners/operators. This includes maps of existing, abandoned, and out-of-service facilities; cathodic protection and grounding systems; as-builts of facilities in the area if the maps are not current; proposed project designs; and schedules of other work in the area. This information is gathered for the purpose of route selection and preliminary neighborhood impacts and as part of the process of impact analysis when evaluating different design possibilities</p> <p>Section 4(4) – Failed to prepare construction drawings to avoid damage to and minimize interference with facilities in the construction area.</p> <p>Recommendation: The penalties are applied. Project Owner and designer education is required.</p>	
52236	<p>Facility Owner: Columbia Gas</p> <p>Contractor/Excavator: Independent Enterprises Inc</p> <p>Project Owner: Pittsburgh Water formerly Pittsburgh Water and Sewer Authority (PWSA)</p> <p>Other: PITTSBURGH DEPARTMENT OF MOBILITY AND INFRASTRUCTURE</p>	<p><u>On 1/10/2025 5:00:00 PM at 1953 ARLINGTON AVE, PITTSBURGH CITY, ALLEGHENY</u> Pittsburgh Water (formerly Pittsburgh Water and Sewer Authority or PWSA) disagreed and provided detailed statement of the replacement work done. Both of the violations to Pittsburgh Water are withdrawn. *****</p> <p>The incident occurred on 1/10/2025 at 1953 Arlington Ave between the intersections of S 18th St. and St. Patrick St. in Pittsburgh City in Allegheny County.</p> <p>A 4” medium pressure gas main was hit while boring. The people that were in 5 houses were evacuated and the power company was notified to turn off the electricity.</p> <p>Independent Enterprises Inc the excavator who was using a pneumatic missile stated in their Alleged Violation Report (AVR) that “As the contractor was shooting the mole they hit a 4-inch existing gas main. The gas main was hit at approximately 5 pm. Work was stopped & 911 was called. Fire fighters arrived on scene at 5:15pm as the site is right outside of fire station #22. Columbia Gas representatives arrived on site at 6:10pm to inspect the damage. City police officers arrived on site at 6:15 to shut down the road. At 6:30 pm Columbia Gas asked the tenants and homeowners in the surrounding area to evacuate due to high levels of gas being emitted from the dig site. They were sent to a hotel in South Side to remain for the night. At 7pm DLC arrived on site to shut down the power to the area. At 7:15 pm the Columbia Gas service crews arrived on site. At 7:30 pm DLC shut off the power to the area per Columbia Gas request to avoid any potential fire hazards due to electrical spark. At 8:10 pm the street lights were restored by DLC once they deemed the are was safe. At 8:40 pm the contractor contacted the homeowner in an attempt to gain access to the basement to put the home on a temporary water service. The owner stated that he was not in town and would contact the tenants. The</p>	<p>Independent Enterprises Inc: \$750.00 Section 5(11.2) 1st Offense \$500.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p>Pittsburgh Water formerly Pittsburgh Water and Sewer Authority (PWSA): \$0.00</p> <p>PITTSBURGH DEPARTMENT OF MOBILITY AND INFRASTRUCTURE: \$1,500.00 Section 2(5)(vii) 2nd Offense \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>tenants were evacuated by the gas company and could not be reached. The officers left at 9 pm. At 9:15 pm the gas main was found on the down hill side of the incident site. At 10:15 pm the gas main was found on the up hill side of the potential incident site. The gas company estimated that the repair would not be completed until 5am and that no work was permitted to take place until the repair work was complete. At this point the contractor decided to leave for the night. At 11:30 pm the contractor plated the water main hole and put plywood caution tape and cones indicating sidewalk closed on the sidewalk hole. Additionally a note was left on the door for the tenants to contact the contractor when they arrived so they could install a temporary water service. At 12pm once all areas were safe the contractor went home for the night to come back in the morning to put residents on a temporary water service. At 5am Columbia Gas completed the repairs to the main and backfilled the road. At 9am the tenants contracted the contractor and stated they had returned to the property. The contractor returned to the site and began preparing for a temporary service. A 1" piece of PEX was connected to a hose bib neighboring Fire Station #22 with permission of the fire chief. After the temporary water service was installed, it was wrapped in concrete blankets to prevent water from freezing". This affected an unknown number of people for 12-24 hours. They state that the line was marked incorrectly. Pictures were provided.</p> <p>Columbia Gas the facility owner stated in their AVR that "Independent Enterprises, working on behalf of Pittsburgh Sewer and Water Authority (PWSA), was boring to install water lines when they struck and damaged an accurately marked 4" medium pressure gas main. They notified 911 and Columbia Gas when the damage occurred. Columbia Gas responded immediately to make the area safe and complete repairs. Five houses were evacuated for safety, and the power company was called to turn off electricity. The original One Call was placed on 11/05/2024, and the update ticket placed on 11/14/2024 stated no additional markouts needed. Marks were faded, but locate pictures from 11/05/2024 are attached. Proper picture taking techniques has been reviewed with all plant crews". Pictures were submitted. 911 was notified.</p> <p>Pittsburgh Water and Sewer Authority (PWSA) the project owner stated in their AVR that "As the contractor was shooting the mole they hit a 4-inch existing gas main. The gas main was hit at approximately 5 pm. Work was stopped & 911 was called. Fire fighters arrived on scene at 5:15pm as the site is right outside of fire station #22. Columbia Gas representatives arrived on site at 6:10pm to inspect the damage. City police officers arrived on site at 6:15 to shut down the road. At 6:30 pm Columbia Gas asked the tenants and homeowners in the surrounding area to evacuate due to high levels of gas being emitted from the dig site. They were sent to a hotel in South Side to remain for the night. At 7pm DLC</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>arrived on site to shut down the power to the area. At 7:15 pm the Columbia Gas service crews arrived on site. At 7:30 pm DLC shut off the power to the area per Columbia Gas request to avoid any potential fire hazards due to electrical spark. At 8:10 pm the street lights were restored by DLC once they deemed the area was safe. At 8:40 pm the contractor contacted the homeowner in an attempt to gain access to the basement to put the home on a temporary water service. The owner stated that he was not in town and would contact the tenants. The tenants were alerted by the gas company and could not be reached. The officers left at 9 pm. At 9:15 pm the gas main was found on the down hill side of the incident site. At 10:15 pm the gas main was found on the up hill side of the potential incident site. The gas company estimated that the repair would not be completed until 5am and that no work was permitted to take place until the repair work was complete. At this point the contractor decided to leave for the night. At 11:30 pm the contractor plated the water main hole and put plywood caution tape and cones indicating sidewalk closed on the sidewalk hole. Additionally a note was left on the door for the tenants to contact the contractor when they arrived so they could install a temporary water service. At 12pm once all areas were safe the contractor went home for the night to come back in the morning to put residents on a temporary water service. At 5am Columbia Gas completed the repairs to the main and backfilled the road. At 9am the tenants contacted the contractor and stated they had returned to the property. The contractor returned to the site and began preparing for a temporary service. A 1" piece of PEX was connected to a hose bib neighboring Fire Station #22 with permission of the fire chief. After the temporary water service was installed, it was wrapped in concrete blankets to prevent water from freezing". This project is listed as >\$400,000. And expected to take 6 months to complete. Pictures were provided.</p> <p>*Emergency ticket 20250102561 was submitted by Columbia Gas to fix their own line on 1/10/2025 at 18:32. PITTSBURGH DEPARTMENT OF MOBILITY AND INFRASTRUCTURE never responded to ticket 20250102561.</p> <p>VIOLATIONS Independent Enterprises Inc is in violation of: Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. Section 5(11.2) – When using trenchless technology, Excavator failed to utilize at a minimum, the best practices published by the Common Ground Alliance. Recommendations: The penalties are applied. Education is required. Pittsburgh Water and Sewer Authority (PWSA) is in violation of:</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 6.1(3) – Released a project to bid or construction before final design was complete. Section 9 2-13. The project owner and design engineer establish line and grade of the proposed excavation to maintain the established minimum clearances (See also Best Practices 4-19 and 5-29). Recommendations: The penalties are applied. Education is required. *Listed below are facility owners in violation of Act 127-2024, Section 2(5)(vii) Failed to respond to an emergency One Call ticket as soon as practicable.</p> <p>PITTSBURGH DEPARTMENT OF MOBILITY AND INFRASTRUCTURE is in violation of: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. PITTSBURGH DEPARTMENT OF MOBILITY AND INFRASTRUCTURE never responded to ticket 20250102561. This is a second time offense. Recommendations: The penalties are applied. Education is required.</p>	
52619	<p>Facility Owner: Comcast Contractor/Excavator: JDA UNDERGROUND LLC</p>	<p><u>On 1/13/2025 9:30:00 AM at 201 PALM CITY PARK, SOUTH ANNVILLE TWP, LEBANON</u> Incident occurred on January 13th, 2025, at 9:30am at 901 Palm City Park, South Annville Township, Lebanon County.</p> <p>A cable line was damaged.</p> <p>Comcast's Alleged Violation Report states, "CONTRACTOR DAMAGED A MISMARKED CABLE LINE"</p> <p>No AVR has been submitted by JDA Underground as of 4/3/2025. No project owner was listed. DPI emailed Comcast who stated they were not the project owner.</p> <p>Violations:</p> <p>Comcast Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. PUC compliance education is required.</p> <p>JDA Underground Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required.</p>	<p>Comcast: \$500.00 Section 2(5)(i) 1st Offense \$500.00</p> <p>JDA UNDERGROUND LLC: \$1,000.00 Section 5(16) 1st Offense \$1,000.00</p>
52333	<p>Contractor/Excavator: UTILITY FIBER CONNECT CORPORATION Project Owner: COMCAST Designer: Comcast - spacesaver Other: BRIGHTSPEED Other: Columbia Gas of PA - North</p>	<p><u>On 1/13/2025 2:00:00 PM at 509 SWORD DANCE PL, CRANBERRY TWP, BUTLER</u> The incident occurred on 1/13/2025 at 509 Sword Dance Pl. in Cranberry Township in Butler County.</p> <p>A gas line was damaged.</p> <p>Comcast the project owner and designer stated in their Alleged Violation Report (AVR) that “Comcast hired Duda cable construction to do our market expansion build. Duda cable hired UTILITY FIBER CONNECT CORPORATION to do this underground part of the build. I was notified that the crews hit a service line</p>	<p>UTILITY FIBER CONNECT CORPORATION: \$500.00 Section 5(11.2) 1st Offense \$500.00</p> <p>BRIGHTSPEED: \$1,250.00 Section 9 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>while crossing it. they spotted the line and the marks was correct". 911 was notified. 1 person was affected. They added that prudent techniques were not used in the tolerance zone. Reports were provided.</p> <p>UTILITY FIBER CONNECT CORPORATION stated in their AVR that "While potholing to expose utilities, a gas line was hit with a shovel. Columbia Gas and 911 were notified immediately and gas line was fixed by the city". They also stated that they failed to use due care and take all reasonable steps necessary to avoid injury to or interference with all lines. Photo and report was provided.</p> <p>Columbia Gas stated in their AVR that "Utility Fiber Connect, working on behalf of Comcast, was shooting a mole to install main fiber when they struck and damaged an accurately marked, 1" plastic, company-side gas service. They did pothole over the facility prior to shooting the mole. They notified 911 and Columbia Gas when the damage occurred. Columbia Gas responded immediately to make the area safe and complete repairs. The local Damage Prevention Specialist (DPS) met with Mr. Volosen onsite regarding the snow covering marks. The DPS advised if they need marks refreshed to please reach out. Mr. Volosen said they dug right over the flag and had found the gas service before shooting their mole. Pictures and report was provided.</p> <p>*Investigation is related by tickets to case 51833. See Comcast violations for project owner and designer in case 51833. *****</p> <p>Emergency ticket 20250132493 was submitted on 1/13/2025 at 14:55 by Columbia Gas to repair their gas line. BrightSpeed never responded. *****</p> <p>VIOLATIONS</p> <p>UTILITY FIBER CONNECT CORPORATION is in violation of Section: Section 5(11.2) – When using trenchless technology, Excavator failed to utilize at a minimum, the best practices published by the Common Ground Alliance. Recommendation: The penalty is applied. Education is required. **</p> <p>Listed below are facility owners in violation of Act 127-2024, Section 2(5)(vii) Failed to respond to an emergency One Call ticket as soon as practicable. BRIGHTSPEED Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Section 9 – Failed to make the best efforts to comply with the Common Ground Alliance Best Practices – CGA 5-16 Federal and State Regulations for required training. Recommendation: The penalties are applied. Facility owner and project owner education is required.</p>	<p>Section 2(5)(vii) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
52321	<p>Facility Owner: PPL Contractor/Excavator: HOMEOWNER Contractor/Excavator: W E B CONTRACTING INC Project Owner: John Pittenger - spacesaver</p>	<p><u>On 1/14/2025 12:47:00 PM at 8 EUROPEANA CIR, EAST PENNSBORO TWP, CUMBERLAND</u> The incident occurred on 1/14/2025 at 8 Europeana Cir. at EAST PENNSBORO TWP, in Camp Hill, in Cumberland County.</p> <p>An electric line was hit and damaged.</p> <p>PPL ELECTRIC UTILITIES CORPORATION stated in their Alleged Violation Report (AVR) that “On Tuesday the 14th day of January 2025 a non-PPL contractor (John Pittenger) was installing water and sewer lines when they hit an electric service with their backhoe going to the home at 8 Europeana Circle. No one was hurt or injured but power was lost going to the home. PPL arrived at the scene and was able to make the area safe an underground crew was called in to make repairs to the conduit, service line and the transformer needed to be replaced all due to this damage. John Pittenger will be held liable for these repairs as he was working on an expired one call and started his excavation after his legal date had ended. Repair costs were verified to be \$5,500. 2-10 customers were affected. Pictures were provided. On 3/27/2025 DPI Maki sent an email to PPL asking for a verification of the cost of the damage. On 3/27/2025 PPL asked for a call and on 3/28/2025 DPI Maki returned the call and Louis from PPL verified the damage to be under \$5,000. PPL is switching their computer system, so a receipt was not possible to get at this time. Louis will send an email, when his computer is back up to verify the cost of damage was. On 3/28/2025 PPL verified the cost of damage to be \$5,500.</p> <p>Wesley “John” Pittenger was mailed an AVR request letter on 3/07/2025 and emailed an AVR request letter on 3/09/2025. AVR was due by 2/13/2025. Questions are due by 4/06/2025. DPI Maki returned a call to John Pittenger, who stated that he called in the OneCall ticket for WEB. He also stated that they were both doing work on this new house that he is building. He stated that he started his work a day after the ticket lawful dig date. John said that he owns a backhoe and excavates, but that he hired WEB to dig out the basement for this project. It was on the last day of work, when the line got hit. John notified Louis Zoeller from PPL about the damage. PPL got his insurance information. DPI stated that each excavator would need their own OneCall ticket. John gave his email address and verified the address for WEB.</p> <p>On 3/15/2025 and email with 2 pictures was received. John stated in his email that “This is concerning case number 52321 and is a summary of the underground electric line getting hit on January 14th 2025 by W.E.B.contracting incorporated of 642 Mountain street Enola, PA 17025 owned by William Brougher. New excavation ticket confirm POCS #20243611575-000 was made on December 26th at 15:24 for excavation of water and sewer lines at 8 Europeana circle camp hill Pennsylvania 17011.</p>	<p>HOMEOWNER: \$0.00 Section 5(2.1) 1st Offense \$0.00</p> <p>W E B CONTRACTING INC: \$1,875.00 Section 5(7) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$500.00</p> <p>Section 5(23) 1st Offense \$250.00</p> <p>Section 5(2.1) 1st Offense \$500.00</p> <p>Section 5(11) 1st Offense \$125.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Due to freezing conditions, the first week we weren't able to start as expected. Excavation started on Monday, January 13th 2025. I am new to this and somehow I thought there was a 2 week window for excavation so I didn't think starting January 13th would be a problem. The 4 inch conduit piping for the underground electric was installed a few months prior and inspected, but no lines were in them when the markout request was given. P. P. L installed the lines on Friday, January 10th 2025. The excavation started the following Monday January 13th. The electric conduit was not marked out however, due to the fact, no lines were present in them, but we didn't know that circumstance at the time. The excavator hit the line accidentally on Tuesday, January 14th. I am the owner of the house and contracted WEB contracting incorporated to do the work. I was on-site at the time of the accident but inside the house. I was the one who contacted PPL to report the accident. Thankfully no one was hurt and no damage to any equipment. PPL came immediately to assess the accident and returned the next day to restore electric to the house. The cost of the job for sewer and water was \$7400 and it took 2 days. The excavator who was digging at the time of the accident was William Brougher, the owner of the company. This was a very unfortunate incident and sad to say it had happened. There was no purposeful defiance of the rules involved. On 3/19/2025 DPI Maki responded that an AVR is still needed to be submitted through the OneCall system.</p> <p>John Pittenger AVR was received on 3/20/2025. John stated in his AVR that “ This was most unfortunate and a first time for the excavator. There was no markings for the electric conduit that was in the ground but still had no wires in it. And when I called in about the accident, I was informed that they don't mark it unless there are lines in the conduit. Ironically the lines were installed the work day before the digging in the afternoon”. He added that “ There was a four inch conduit for the underground electric lines to the house but without wires in them at the time of mark out but they didn't mark it. Ironically ppl installed the line Friday, jan 10th in the afternoon and Monday morning 8::00 started digging”. Pictures were submitted.</p> <p>W E B. CONTRACTING INC was mailed an AVR request letter on 3/07/2025. AVR was due by 2/13/2025. Questions are due by 4/06/2025. DPI Maki received a call from the current owner of 11 Fortuna Ln, who stated that W.E.B. Contracting has moved from this location. DPI found another address and resent the AVR request letter on 3/13/2025.</p> <p>W E B. CONTRACTING INC submitted an AVR on 3/24/2025. AVR was due by 2/13/2025.</p> <p>W E B CONTRACTING INC stated in their AVR that “This was my first incident in over 35 years of being in business and I truly have even more of a respect of all facets with the excavation process. I am a firefighter with one of the local fire companies and I have responded on dozens of calls for the same type of incident and totally "get" what goes on with this type of</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>incident. I am still taken back and think about this incident everyday and I wouldn't wish this on anyone. I also apologize for not doing this AVR sooner and I accept the outcome of what may be. Please feel free to call me for any clarifications or any information you may need. Again, I apologize for this happening. I am better than what this incident has shown, and I will be more diligent going forward with this extremely important process. Mr. Pittenger provided pictures of the area with his report. W E B added that ““A 4" gray conduit for underground electric was in the ground without wires when the mark out was completed but wasn't marked by the locator. The electric line was installed January 10th and excavation started January 13th about 0800”.</p> <p>Compliance Coordinator verified that W.E.B. Contracting has been placing OneCall notifications. *****</p> <p>Ticket 20243611575 was submitted by John Pittenger on 12/26/2024 with a response due by 1/01/2025 (a holiday) and the excavation due to begin on 1/02/2025. The Lawful start dates: 1/02/2025 thru 1/10/2025. For an expected 1 day project.</p> <p>All facility owners marked timely.</p> <p>Per AVR from John, The excavation began on Monday 1/13/2025.</p> <p>Emergency ticket was submitted by John Pittenger on 1/14/2025 at 12:45. The named excavator is John Pittenger, but in communication with both John and WEB Contracting Inc, they were both excavating and WEB Contracting Inc damaged the electric line. *****</p> <p>VIOLATIONS</p> <p>W E B CONTRACTING INC is in violation of:</p> <p>Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. The \$1000. penalty is reduced to \$500.</p> <p>Section 5(23) – Excavator may not delegate their duty to submit a locate request to the One Call System to another person. The excavator shall have sole responsibility to submit each locate request to the One Call System. The \$500. Penalty is reduced too \$250.</p> <p>Section 5(7) – Failed to immediately report to the facility owner any break or leak in its lines, or any dent, gouge, groove, or other damage to such lines or to their coating or cathodic protection. The \$1000. penalty is reduced to \$500.</p> <p>Section 5(11) – Excavator failed to use the color white to mark a proposed excavation work site when exact work site information cannot be provided. The \$250. penalty is reduced to \$125.</p> <p>Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 business days of striking a line. The \$1000. penalty is reduced to \$500.</p> <p>Recommendation: This is a first-time violation. The penalties are applied, but all are reduced by 50% . The total penalties of \$3750 are reduced to \$1875. Education is required.</p> <p>Wesley "John" Pittenger is in violation of:</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 5(2.1) – Homeowner failed to submit a location request to One Call within the correct timeframe. Please note that this homeowner owns an excavator. Recommendation: Education is required. The \$1000. penalty is reduced to a warning.</p>	
52200	<p>Facility Owner: PPL Contractor/Excavator: Doli Construction Corporation Designer: HERBERT ROWLAND AND GRUBIC INC Other: LOWER PAXTON TOWNSHIP AUTHORITY</p>	<p><u>On 1/15/2025 12:00:00 PM at 5579 BAINBRIDGE DR., LOWER PAXTON TWP, DAUPHIN</u> PPL disagreed and stated that "To clarify, there was never any report of damage done to electric lines. The tickets attached are for damage unknown and exposed electric lines. However, the line shown in the photo being pulled is an unmapped line that does not serve any customers. Our lines were all located properly on both tickets, and there was no need to file an AVR since there was no damage done to any of our lines". Given these circumstances, I kindly request that all fines and violations be removed. Pictures were submitted. DPI withdrew the 2 violations to PPL. ***** The incident occurred on 1/15/2025 at 5579 Bainbridge Dr. in Lower Paxton Township in Dauphin County. An electric conduit was hit and damaged. DOLI CONSTRUCTION the excavator stated in their Alleged Violation Report (AVR) that “Crew was digging for a sewer lateral and hit electric conduit. Conduit was 8' off the mark”. Pictures and reports provided. On 3/20/2025 DPI asked Doli about multiple electric line hits to PPL and PPL having 1 AVR that is on a different date. Doli responded to this in an email received on 3/20/2025. HERBERT ROWLAND AND GRUBIC INC the designer stated in their AVR that “While excavating for a sewer lateral the Contractor hit an electric conduit that was 8' off the paint mark”. Pictures and reports provided. On 3/18/2025 DPI Maki sent an email asking HRG about PPL in the design. HRG sent in the design showing PPL information in the legend and the underground utility lines in the drawings. LOWER PAXTON TOWNSHIP AUTHORITY the Project Owner stated in their AVR that “Doli's crew was excavating for a sewer lateral and hit an electric conduit that was 8' off of the mark”. Pictures and reports were provided. PPL the facility owner did not submit an AVR. In an email received from PPL on 3/20/2025, PPL stated that they had no damage on that date, but they did show damage on another day. On 3/20/2025 DPI sent a list of dates that AVR's were submitted for hits to a PPL line. There is also 1 date with only an AVR from PPL. On 3/20/2025 PPL sent an email verifying that the line that was hit was inactive and that they have not submitted AVR's for inactive lines. DPI responded that it is in ACT 127-2024 to submit AVR's for all underground utility line damage.</p>	PPL: \$0.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>VIOLATIONS</p> <p>PPL is in violation of:</p> <p>Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work.</p> <p>Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.</p> <p>Recommendation: The penalty is applied. Education is required.</p>	
52541	<p>Facility Owner: PECO</p> <p>Contractor/Excavator: BEST CHOICE PLUMBING</p>	<p><u>On 1/22/2025 12:00:00 PM at 9475 ASHTON RD, PHILADELPHIA CITY, PHILADELPHIA</u> Incident occurred on January 22, 2025, at 12pm at 9475 Ashton Road, Philadelphia City, Philadelphia County.</p> <p>An electrical line was damaged.</p> <p>PECO's Alleged Violation Report (AVR) states, "BEST CHOICE PLUMBING REPLACING A WATER LINE STRUCK THE SECONDARY MAIN WITH AN EXCAVATOR. CONTRACTOR DID NOT HAVE A PA ONE CALL."</p> <p>PECO damage report states, "On 1/22/25 at 8:12 PM USIC was notified by Peco of an electric damage at 9475 Ashton Road Philadelphia City Philadelphia PA, During the investigation it was found that BEST CHOICE was excavating with unknown equipment to repair or replace the water service line feeding 9475 Aston Rd when they severed the unmarked secondary main. It was found that BEST CHOICE PLUMBING did not have an active PA One Call/ Locate request prior to excavating, resulting in the unmarked secondary main being severed and in need of repair. After reviewing tickets for 9475 Aston Rd IT was found that BEST CHOICE PLUMBING called in a locate request 20250222895 after the damage occurred."</p> <p>Emergency ticket says hand tools and damage report states unknown equipment. Pictures do not show definitive signs of powered equipment.</p> <p>No violations.</p>	
52451	<p>Facility Owner: PPL</p> <p>Contractor/Excavator: Foundations First INC</p> <p>Project Owner: BURKENTINE LAND DEVELOPMENT</p> <p>Designer: UNKNOWN</p>	<p><u>On 1/23/2025 9:30:00 AM at Hidden Meadows, CARLISLE BORO, CUMBERLAND</u> The incident occurred on 1/23/2025 at Hidden Meadows in Carlisle Borough in Cumberland County.</p> <p>An Electric conduit and primary were damaged.</p> <p>PECO stated in their Alleged Violation Report (AVR) that “On Thursday the 23rd day of January 2025, a non-PPL contractor (Foundations First INC) was installing a foundation at lot 7 in the hidden meadows development when they hit a primary line with their backhoe. No one was hurt or injured but the conduit and primary were damaged. PPL crew arrived on scene and made the area</p>	<p>Foundations First INC: \$2,000.00 Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>BURKENTINE LAND DEVELOPMENT: \$1,500.00 Section 6.1(7) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>safe. The primary line and conduit were repaired onsite, and no further repairs are needed. Foundations First INC will be held liable for the damage and repair due to the fact they did not have a valid PA One Call". No pictures were provided. On 3/31/2025 PPL email verified that there were no photos.</p> <p>Foundations First INC the excavator AVR was due by 2/22/2025. As of 3/30/2025, no AVR has been received</p> <p>BURKENTINE BUILDERS the project owner AVR was due by 2/22/2025. As of 3/30/2025, no AVR has been received. On 4/07/2025m an email was received after the stakeholder review went out asking what this is about. DPI responded with an email and also updated the name of the company to the name in the email - Burkentine Land Development. Please note that the Burkentine Builders was found online and the email was sent through their website.</p> <p>*****</p> <p>Routine Ticket 20250220760 was submitted on 1/22/2025 by Foundations First Inc. to excavate for footing foundations at Health Circle 14-24 building 003 Townhouse. The incident occurred on 1/23/2025.</p> <p>****</p> <p>VIOLATIONS Foundations First INC is in violation of: 5(2.1) - Began excavation work before the lawful start day (on ticket). Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 business days of striking a line. Recommendation: The penalties are applied. Education is required.</p> <p>BURKENTINE BUILDERS is in violation of: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Section 6.1(3) – Released a project to bid or construction before final design was complete. Recommendation: The penalties are applied. Education is required.</p>	<p>Section 6.1(3) 1st Offense \$500.00</p>
52378	<p>Facility Owner: Comcast Contractor/Excavator: M. O'Herron Co Project Owner: Penn Township of Westmoreland County Other: Verizon Other: WESTMORELAND CO MUNI AUTH</p>	<p>On 1/23/2025 10:30:00 AM at PENNTOWNE DR, PENN TWP, WESTMORELAND Municipal Authority of Westmoreland County (MAWC) provided additional information and the violation was withdrawn</p> <p>*****</p> <p>The incident occurred on 01/23/2025 at 10:30 AM, on Penntowne Drive, in Penn Township, Westmoreland County.</p> <p>A cable line owned by Comcast was damaged.</p> <p>Comcast, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, "CONTRACTOR DAMAGED UG CABLE WHILE PUTTING IN STORM DRAINS. MARKS WERE GONE AND NEEDED TO BE REFRESHED," Photos were submitted.</p>	<p>M. O'Herron Co: \$500.00 Section 5(3) 1st Offense \$500.00</p> <p>Penn Township of Westmoreland County: \$1,000.00 Section 6.1(7) 1st Offense \$1,000.00</p> <p>Verizon: \$500.00 Section 2(5)(v) 2nd offense \$500.00</p> <p>WESTMORELAND CO MUNI AUTH: \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>M. O'Herron Co., the excavator, submitted an AVR. Their AVR states, "M. O'Herron Co digging for storm drain replacement along edge of road in front of 40 Penntowne Dr at intersection with Ben Franklin Dr. Damaged unmarked Comcast cables in conduit teeing off marked path in ROW in front of houses on Penntowne approximately 6' back from edge of road. No markings seen for this line crossing road and heading towards center of road on Ben Franklin. Comcast responded to damage and repaired cables." Photos were submitted.</p> <p>Penn Township of Westmoreland County is the project owner. An AVR has not been filed as of 03/27/2025.</p> <p>Routine ticket 20243391721 was placed on 12/04/2024. Comcast marked the lines on 12/05/2024 using paint and submitted photos of their line markings. The photos of Comcast's line markings are date and time stamped as 12/05/2024. The damage occurred on 01/23/2025, well over a month after the lines were originally marked. The photos of the damage do not show Comcast's line markings.</p> <p>This case is related to cases 050822, 051213, 051635, 051728.</p> <p>Routine ticket 20243391721 had a response due date of 12/06/2024. WESTMORELAND CO MUNI AUTH responded 'Scheduled Mark by 12/06/2024 23:59' on 12/06/2024. They did not respond, 'Field Marked' until 02/03/2025. Verizon responded, 'Field Marked' on 12/12/2024.</p> <p>Violations:</p> <p>Penn Township of Westmoreland County - - Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>WESTMORELAND CO MUNI AUTH – Withdrawn. - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Routine ticket 20243391721.</p> <p>Verizon – - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Routine ticket 20243391721. Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>M. O'Herron Co. – - Section 5(3) – Excavator failed to preserve mark-outs or request a remark. Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
52468	Facility Owner: National Fuel	<u>On 1/24/2025 9:00:00 AM at NORRIS AVE, SHARON CITY, MERCER</u> The non damage event occurred on	S and S Fiber Optics: \$750.00

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>Contractor/Excavator: S and S Fiber Optics Project Owner: ADB Companies Designer: Omni Fiber</p>	<p>01/24/2024 at 9:00 AM, on Norris Avenue, in Sharon City, Mercer County. The nearest intersection was Quarry Place.</p> <p>A design ticket and complex project ticket were not requested. – Multiple routine tickets were requested, and only upon the lines being marked by the facility owners, was it determined that the proposed excavation areas would need to have a redesign of the planned work, and no excavation was performed.</p> <p>National Fuel submitted an Alleged Violation Report (AVR). Their AVR states, "Omni Fiber, Project Owner, submitted multiple routine ticket requests for the continuing complex project in the local area. Upon mark out of facilities, Omni Fiber determined that the proposed excavation areas would need to have a redesign of their planned work, resulting in the routine tickets to not have excavation performed. This is a failure in not submitting a design ticket or complex project to the PA One Call System. Omni Fiber was advised of submitting a design ticket multiple times and was also advised to submit another complex project to mitigate any variances that may cause a delay in the field. Please see attachments. Attachments were taken as of today, 29 January. Original Complex Project Ticket # 20240602212 Project ID: 6353492 Affected POCS Tickets:20250072547, 20250072549, 20250091473, 20250091487, 20250091499, 20250091511, 20250091518, 20250091310, 20250091358, 20250091406, 20250101747". Photos were submitted.</p> <p>S and S Fiber - An AVR has not been filed as of 03/26/2025. An AVR request letter was mailed and emailed on 02/24/2025.</p> <p>ADB Companies - An AVR has not been filed as of 03/26/2025.</p> <p>Omni Fiber - An AVR has not been filed as of 03/26/2025. An AVR request letter was mailed and emailed on 02/24/2025.</p> <p>This case is related to cases: 045394, 046597, 046914, 048359, 048458, 050069, 050555, 051239, 051559, 051599.</p> <p>Violations:</p> <p>S and S Fiber – - Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. - Section 5(3) – Excavator failed to hold a preconstruction meeting prior to beginning a complex project. Recommendation: The penalty is applied. PUC compliance training education is required. ADB Companies –</p>	<p>Section 5(17) 1st Offense \$500.00</p> <p>Section 5(3) 1st Offense \$250.00</p> <p>ADB Companies: \$1,000.00 Section 6.1(3) 1st Offense \$500.00</p> <p>Section 6.1(4) 1st Offense \$500.00</p> <p>Omni Fiber: \$500.00 Section 4(4) 1st Offense \$250.00</p> <p>Section 4(6) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>- Section 6.1(3) – Released a project to bid or construction before final design was complete.</p> <p>- Section 6.1(4) – Failed to participate in design and preconstruction meetings.</p> <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Omni Fiber –</p> <p>- Section 4(4) – Failed to prepare construction drawings to avoid damage to and minimize interference with facilities in the construction area.</p> <p>- Section 4(6) - Designer changed the work site of a proposed excavation, but did not follow the obligations impose by Act 127 of 2024.</p> <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
52516	<p>Facility Owner: UGI Utilities Inc.</p> <p>Contractor/Excavator: Miller Pipeline CORP</p> <p>Project Owner: UGI - SPACESAVER</p> <p>Designer: UGI - SPACESAVER</p> <p>Other: AED ENERGY SERVICES</p>	<p><u>On 1/27/2025 9:00:00 AM at 142 S PEARL ST, LANCASTER CITY, LANCASTER</u> The incident occurred on 1/27/2025 on 142 S Pearl St in Lancaster City in Lancaster County.</p> <p>A Gas line was hit.</p> <p>MILLER PIPELINE the excavator stated in their Alleged Violation Report (AVR) that “the crew was redigging a hole that had been backfilled due to snow . while the crew was digging the frost was very hard and ran deep. in an attempt to loosen the hard service they used a jackhammer and at that point the jackhammer bit came into contact with a 1" plastic service causing damage and a release of gas the crew made all appropriate notifications”. 911 was notified. 1 customer was affected.</p> <p>UGI UTILITIES INC the facility owner, project owner, and designer stated in their AVR that “Excavator utilizing mechanized equipment, struck a correctly marked gas service while operating inside the tolerance zone”. UGI lists this project as >\$400,000. And that level “A” Subsurface Utility Engineering (SUE) was used. 911 was notified. Pictures and reports were provided.</p> <p>VIOLATIONS</p> <p>Miller Pipeline CORP is in violation of:</p> <p>Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.</p> <p>Education is required. As of 4/22/2025 the required education that was due by 12/11/2023 and another that was due by 9/10/2024 have not been completed.</p>	<p>Miller Pipeline CORP: \$500.00</p> <p>Section 5(4) 1st Offense \$500.00</p>
52600	<p>Facility Owner: CARLISLE BOROUGH MUNICIPAL AUTHORITY</p> <p>Contractor/Excavator: J F KIELY CONSTRUCTION</p> <p>Project Owner: UGI Utilities</p> <p>Designer: UGI Utilities (Placeholder)</p>	<p><u>On 1/27/2025 9:00:00 AM at W HIGH ST, CARLISLE BORO, CUMBERLAND</u> The incident occurred on 01/27/2025 at 9:00 AM, on West High Street, in Carlisle Borough, Cumberland County.</p> <p>An electric line owned by CARLISLE BOROUGH was damaged.</p> <p>CARLISLE BOROUGH, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “This contractor saw cut the line the Friday before and</p>	<p>J F KIELY CONSTRUCTION: \$2,000.00</p> <p>Section 5(4) 2nd Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>was fixed. Monday they started to dig and hit the same line with the trachoe pulling the lines out of the ditch.” A photo was submitted.</p> <p>J F KIELY CONSTRUCTION is the excavator. An AVR has not been filed as of 03/24/2025.</p> <p>UGI Utilities, the project owner and designer, submitted an AVR. Their AVR states, "Contractor states that they hit and damaged a street light wire. Contractor did not provide any information on the markings.”</p> <p>Violations:</p> <p>J F KIELY CONSTRUCTION -</p> <ul style="list-style-type: none"> - Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>JF Kiely is delinquent on multiple excavator education requirements.</p> <p>Case 31899 due 10/9/2023, Case 32120, also due 10/9/23. Kiely also has education for 48656 outstanding, but not delinquent until after 6/10/25.</p> <p>Kiely has taken project owner education for caes 33689 on 5/24/24, but this does ont cover the excavator ed. requirements.</p>	
52467	<p>Facility Owner: Texas Eastern Transmission, LP</p> <p>Contractor/Excavator: Bustleton Services, Inc.</p> <p>Project Owner: Texas Eastern Transmission, LP (Placeholder)</p>	<p><u>On 1/27/2025 2:00:00 PM at 6310 Passyunk Ave, PHILADELPHIA CITY, PHILADELPHIA</u> This occurred on 01/27/2025 at 2:00 PM, at 6310 Passyunk Avenue, in Philadelphia City, Philadelphia County.</p> <p>Non-damage event. Digging on a natural gas transmission pipeline right-of-way without a One Call ticket.</p> <p>Texas Eastern Transmission, LP, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “Third-party landscaping contractor planted trees on the Texas Eastern natural gas transmission pipeline right-of-way using a bobcat mounted auger without a One Call and without authorization from Texas Eastern. No damage found.” Photo was submitted.</p> <p>Bustleton Services, Inc. is the excavator. An AVR has not been filed as of 03/19/2025.</p> <p>A Pa One Call ticket was not requested.</p> <p>Violations:</p> <p>Bustleton Services, Inc. -</p> <ul style="list-style-type: none"> - Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been 	<p>Bustleton Services, Inc.: \$2,000.00 Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>committed in association with excavation or demolition work. Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
52411	<p>Facility Owner: Ashley Borough Contractor/Excavator: R L E ENTERPRISES Project Owner: Pennsylvania American Water Company (PAWC) Designer: PAWC Other: Verizon PA LLC</p>	<p><u>On 1/28/2025 9:00:00 AM at 42 Cook St., ASHLEY BORO, LUZERNE</u> Incident occurred on January 28th, 2025, at 9am at 42 Cook Street, Ashley Boro, Luzerne County.</p> <p>A sewer line was damaged.</p> <p>RLE Enterprises' Alleged Violation Report (AVR) states, "While digging for a new water main, our crew struck an unmarked sewer lateral for house # 42 Cook St. RLE made repairs and restored service in a timely manner."</p> <p>R L E's pictures show the repaired sewer lateral with no visible mark outs.</p> <p>PAWC's AVR states, "R.L.E was installing new water main on Cook St, Ashley. While excavating they hit an 6" unmarked sewer lateral to house #42 Cook St. R.L.E made the repairs to the unmarked lateral."</p> <p>No AVR has been received by Ashley Borough as of 3/13/25.</p> <p>Violations:</p> <p>Ashley Borough Section 2(5)(i.1) – Failed to locate an actually known facility’s point of connection to its facilities. PUC compliance education is required. Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. PUC compliance education is required.</p> <p>Verizon Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3).</p>	<p>Ashley Borough: \$1,250.00 Section 2(5)(i.1) 1st Offense \$250.00</p> <p>Section 2(10) 1st Offense \$1,000.00</p> <p>Verizon PA LLC: \$2,000.00 Section 2(5)(viii) Subsequent \$2,000.00</p>
52563	<p>Facility Owner: Pennsylvania American Water Company Contractor/Excavator: WILLIAMS EXCAVATION Project Owner: Pittsburgh Water and Sewer (PWSA) Designer: MONALOH BASIN ENGINEERS</p>	<p><u>On 1/28/2025 10:00:00 AM at 506 BRINWOOD AVE, PITTSBURGH CITY, ALLEGHENY</u> PAWC submitted an AVR on 5/6/25 states, "Williams excavating had a lot of work in the City of Pittsburgh 29th ward which should have made their PWSA project complex, they did not hold a meeting. Their one call 20243182961 for 506 Brinwood was marked by Joe Sphar on 11/15/24 and the dig dates were 11/18/24 thru 11/27/24 and the damage occurred on 1/28/25. They also had a one call for 500 Brinwood which was marked on 2/14/24 with lawful dates of 2/15/24 thru 2/27/24. By law, Williams failed to maintain the marks if they didn’t vacate the road. If they vacated, then they did not have a valid one call to dig.</p>	<p>Pennsylvania American Water Company: \$1,000.00 Section 2(10) 1st Offense \$1,000.00</p> <p>WILLIAMS EXCAVATION: \$750.00 Section 5(6)(ii) 1st Offense \$500.00</p> <p>Section 5(20) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>We did not have to place a one call for the repair because Williams' excavation was large, and the crew was able to make repairs without any additional digging. The repair was not completed until the next day because Williams' excavation was approximately 20' deep, the afternoon crew had to give to daylight the next day because they had to wait until Williams backfilled to the level of the service line. All of Williams' one call tickets for Brinwood were placed (due dates) between 2/14/24 and 11/15/24. The one ticket placed in 2025 was for concrete repairs."</p> <p>PAWC provided dated mark out photos of the marked line. Removed 2(5)(i).</p> <p>GPD Group submitted an AVR on 4/28/25 stating, "During excavation related to repair of a damaged sanitary sewer, the crew encountered and unmarked water service line. The equipment operator excavated around the line to complete the sewer repair. The trench wall then collapsed, causing damage to the water service line. The supervisor notified the facility owner (PA American Water) that there was damage; the owner responded and repaired the damaged service line." ***</p> <p>Incident occurred on January 28th, 2025, at 10am at 506 Brinwood Avenue, Pittsburgh City, Allegheny County.</p> <p>A water line was damaged.</p> <p>Williams Excavating's Alleged Violation Report (AVR) states, "WHILE EXCAVATING FOR A DAMAGED SANITARY SEWER MAINLINE, EXCAVATOR LOCATED UNMARKED WATER SERVICE LINE. EXCAVATOR DUG AROUND LINE TO COMPLETE THE REPAIR OF SANITARY SEWER LINE. THE WALL OF THE TRENCH COLLAPSED AND RESULTED IN THE WATER SERVICE BEING DAMAGED. EXCAVATOR NOTIFIED FACILITY OWNER OF DAMAGE.FACILITY OWNER RESPONDED AND FIXED DAMAGED SERVICE LINE."</p> <p>Pittsburgh Water and Sewer Authority's AVR states, "WHILE EXCAVATING FOR A DAMAGED SANITARY SEWER MAINLINE, EXCAVATOR LOCATED UNMARKED WATER SERVICE LINE. EXCAVATOR DUG AROUND LINE TO COMPLETE THE REPAIR OF SANITARY SEWER LINE. THE WALL OF THE TRENCH COLLAPSED AND RESULTED IN THE WATER SERVICE BEING DAMAGED. EXCAVATOR NOTIFIED FACILITY OWNER OF DAMAGE.FACILITY OWNER RESPONDED AND FIXED DAMAGED SERVICE LINE."</p> <p>PWSA submitted two AVRs.</p> <p>Pennsylvania American Water Company (PAWC) has not submitted an AVR as of 3/24/2025.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Routine ticket was called in on 11/13/2024. Damage was done on 1/28/2025. No requests were made by the excavator for marking unmarked lines or for refreshing old marks.</p> <p>Pictures show the damaged water line that was exposed prior to damage according to the excavator.</p> <p>Violations:</p> <p>Wilson Excavating Section 5(6)(ii) – Excavator failed to provide support and mechanical protection for known facility owner’s lines at the construction work site. PUC compliance education is required.</p> <p>Section 5(20) – Excavator failed to renotify One Call of an unmarked or incorrectly marked facility upon arrival at a work site. PUC compliance education is required.</p> <p>PAWC Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. PUC compliance education is required.</p> <p>Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. PUC compliance education is required.</p>	
52455	<p>Facility Owner: Brightspeed</p> <p>Facility Owner: PPL ELECTRIC UTILITIES CORPORATION</p> <p>Facility Owner: West Donegal Township</p> <p>Contractor/Excavator: EVERHART AND HOOVER</p> <p>Project Owner: PPL - Placeholder</p>	<p><u>On 1/28/2025 10:05:00 AM at HILLCREST LN, WEST DONEGAL TWP, LANCASTER</u> Incident occurred on January 28th, 2025, at 10:05am along Hillcrest Lane, West Donegal Township, Lancaster County.</p> <p>An electric line was damaged.</p> <p>PPL's Alleged Violation Report (AVR) states, "On Tuesday the 28th day of January at 10:05 am, a PPL contractor (Everhart and Hoover) was installing a new electric for a streetlight when they struck an unmarked single-phase primary with their bore machine. No one was hurt or injured but 22 homes did lose power. PPL arrived on site and made the area safe and was able to do a switch over to get power restored. After an investigation into the damage, it was determined that a new line will have to be bored in to replace the damaged primary. USIC will be held liable for this damage, please see their damage claim number 21120250128006."</p> <p>Everhart and Hoover's AVR states, "Crew was boring to install new Street Light service to pole 31440S28770 from Pad Mount Transformer. The damage was on Hillcrest Lane, Elizabethtown."</p> <p>PPL's pictures show that the line was damaged outside of the tolerance zone. Pictures show that companies marked out with paint and flags in the snow.</p>	<p>Brightspeed: \$250.00 Section 2(5)(v.2) 1st Offense \$250.00</p> <p>PPL ELECTRIC UTILITIES CORPORATION: \$500.00 Section 2(5)(i) 1st Offense \$500.00</p> <p>West Donegal Township: \$500.00 Section 2(5)(v.2) 1st Offense \$250.00 Section 9 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Violations:</p> <p>PPL Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.</p> <p>Brightspeed Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. 20250222721. PUC compliance education is required.</p> <p>West Donegal Township Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. 20250222721. PUC compliance education is required.</p> <p>Section 9 – Failed to make best efforts to comply with Common Ground Alliance Best Practices Version 21.0. West Donegal Township has not completed the required education from case 40715 that was due on 2/12/2025. PUC compliance education is required.</p>	
52565	<p>Facility Owner: Columbia Gas</p> <p>Contractor/Excavator: North Fayette County Municipal Authority</p> <p>Project Owner: North Fayette County Municipal Authority (Placeholder)</p> <p>Other: OMNI Fiber LLC</p>	<p><u>On 1/28/2025 10:50:00 AM at 61 MULLEN ST, SOUTH UNION TWP, FAYETTE</u> The incident occurred on 01/28/2025 at 10:50 AM, at 61 Mullen Street, in South Union Township, Fayette County.</p> <p>A gas line owned by Columbia Gas was damaged. 911 was called.</p> <p>Columbia Gas, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “North Fayette County Municipal Authority was digging on an emergency ticket to repair a broken water line when they struck and damaged an accurately marked 1" plastic gas service with their backhoe. They notified 911, 811, and Columbia Gas when the damage occurred. Columbia Gas responded immediately to make the area safe and complete repairs.” Photos were submitted.</p> <p>North Fayette County Municipal Authority, the excavator and project owner, submitted an AVR. Their AVR states, “The guys were aware of the gas service line in the work zone. They had actually uncovered it by hand and decided to take a little more dirt of the top with the backhoe. At this point is when the operator caught the gas service with his tooth.” Photos were submitted.</p> <p>Emergency tickets: 20250272352 - Omni Fiber did not respond to the ticket. 20250281489 - Omni Fiber did not respond to the ticket. 20250282078 - Omni Fiber did not respond to the ticket.</p> <p>Violations:</p> <p>North Fayette County Municipal Authority – - Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: The penalty is applied. PUC compliance training education is required. OMNI Fiber LLC –</p>	<p>North Fayette County Municipal Authority: \$500.00 Section 5(4) 1st Offense \$500.00</p> <p>OMNI Fiber LLC: \$4,500.00 Section 2(5)(vii) 2nd Offense \$1,500.00</p> <p>Section 2(5)(vii) 2nd Offense \$1,500.00</p> <p>Section 2(5)(vii) 2nd Offense \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>- Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket 20250272352.</p> <p>- Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket 20250281489.</p> <p>- Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket 20250282078.</p> <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
53876	<p>Facility Owner: PECO AN EXELON COMPANY Contractor/Excavator: McKee Builders</p>	<p><u>On 1/28/2025 11:00:00 AM at 1019 HALTER RD, DOWNINGTOWN BORO, CHESTER</u> The incident occurred on Tuesday, January 28, 2025, at 1019 Halter Road, in Downingtown Borough, Chester County.</p> <p>PECO an Exelon Company gas line was damaged. There are no tickets associated with this incident.</p> <p>PECO stated in their alleged violation report (AVR), during USIC investigation it was found that McKee Builders was driving-in ground rods, when they punctured the unmarked 1" plastic gas service line. McKee Builders did not have a locate request prior to driving-in the ground rods resulting in the gas service being punctured and in need of repair. PECO provided photos with an investigation report, and PECO noted that 911 was called. McKee Builders did not submit an AVR within 30 days of striking a line.</p> <p>No Violations- we have no evidence that McKee Builders was using mechanized equipment.</p>	
52520	<p>Facility Owner: UGI Contractor/Excavator: PA WATER - SPACESAVER Project Owner: PENNSYLVANIA AMERICAN WATER</p>	<p><u>On 1/28/2025 12:30:00 PM at 105 CUSTER, WILKES BARRE CITY, LUZERNE</u> The incident occurred on 1/28/2025 at 108 Custer in Wilkes Barre City in Luzern County.</p> <p>A Gas line was hit and damaged.</p> <p>UGI the facility owner stated in their Alleged Violation Report (AVR) that “Excavator struck and damaged a correctly marked gas facility while digging in the tolerance zone”. 911 was notified. Pictures were provided.</p> <p>PENNSYLVANIA AMERICAN WATER the project owner and excavator stated in their AVR that "Emergency one Call was placed to 108 Custer on the date of January 28th 2025 to excavate and shut water off for a flooding basement. Upon research of historical tap records it was decided upon to Replace the service due to the likely-hood of a future leak. During setup of excavation company excavator removed the black top then began to dig, with in first bucket gas service was damaged. The gas main is marked across the street on the closer side of 108 , where our water main is was on the farther side closer to the 109 side . The tap and main to 109 was marked in the street however the curb box and and curb were not marked on the day of the</p>	<p>PENNSYLVANIA AMERICAN WATER: \$500.00 Section 5(4) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>emergency one call and not readily visible . As it will be shown in the picture some of the other gas service were dotted across the road and the curb/ curb boxes were marked. However this was not case and point of the line that was struck. Gas company took over excavation after the fact . The mark that was found on the curb for the service that was struck was uncovered by the gas company upon second arrival to the site ." No pictures were provided.</p> <p>VIOLATIONS: PA American Water is in violation of: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.</p>	
52614	<p>Facility Owner: MASONTOWN BOROUGH MUNICIPAL AUTHORITY Contractor/Excavator: NLP Great Lakes LLC Other: COLUMBIA GAS Other: Masontown Borough Other: NORTHERN PIPELINE CONSTRUCTION (NPC)</p>	<p><u>On 1/28/2025 1:00:00 PM at 217 N Water Street, MASONTOWN BORO, FAYETTE</u> The Incident occurred on 1/28/2025 at 217 N Water St. in Masontown Borough in Fayette County.</p> <p>A ¾” plastic water service line was damaged.</p> <p>NPL GREAT LAKES LLC is another name of NORTHERN PIPELINE CONSTRUCTION (NPC), but in a different region. They are the excavator and stated in their Alleged Violation Report (AVR) that “NPL was digging for a 4" PL gas mainline when they came across and damaged a mismarked 3/4-inch plastic water service line. The mark for this service line was 15 feet away from the point of contact. Masontown Borough was called and made the repair and restored service. Project is listed at >\$400,000. And the project length is 13,540 FT. Subsurface Utility Engineering i(SUE) is described as level “C”. Report was provided. On 4/22/2025 DPI sent an email asking if NPL had submitted any tickets. On 4/23/2025 an email was received with 2 tickets that were submitted by NPC. DPI responded to the email asking for what the relationship is between the two companies. The NPL Quality manager was added to the case and email.</p> <p>Columbia Gas the project owner and designer stated in their AVR that “NPL was digging for a 4" PL gas mainline when they came across and damaged a mismarked 3/4-inch plastic water service line. The mark for this service line was 15 feet away from the point of contact. Masontown Borough was called and made the repair and restored service. Project is listed at >\$400,000. And the project length is 13,540 FT. SUE is described as level “C”. Pictures and a report were provided.</p> <p>MASONTOWN Borough Authority the facility owner did not submit an AVR as of 4/22/2025. Their AVR was due by 3/12/2025. ***** *Ticket 20250221438 was submitted by Northern Pipeline Construction on 1/22/2025 with a response due by 1/24/2025. MASONNTOWN Borough Authority did not respond until 1/29/2025.</p>	<p>MASONTOWN BOROUGH MUNICIPAL AUTHORITY: \$2,500.00 Section 2(10) 1st Offense \$1,000.00</p> <p>Section 2(5)(i) 1st Offense \$500.00</p> <p>Section 2(5)(i.1) 1st Offense \$250.00</p> <p>Section 2(5)(v) 1st Offense \$250.00</p> <p>Section 2(5)(v) 1st Offense \$500.00</p> <p>Masontown Borough: \$250.00 Section 2(5)(v) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>*Ticket 202500092047 was submitted by Northern Pipeline Construction on 1/09/2025 with a response due by 1/13/2025. MASONNTOWN Borough Authority did not respond until 1/31/2025. *****</p> <p>VIOLATIONS Masontown Borough Municipal Authority is in violation of: Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. Section 2(5)(v) – Failed to respond to routine One Call ticket 20250221438 within the required amount of time. *Please see ticket 20250221438 for ticket details. Section 2(5)(v) – Failed to respond to routine One Call ticket 202500092047. *Please see ticket 202500092047 details above. Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Section 2(5)(i.1) – Failed to locate an actually known facility’s point of connection to its facilities. Recommendation: The penalty is applied. Education is required. Masontown Borough Municipal Authority has past due required education dating back to 12/11/2023.</p> <p>Listed below are facility owners in violation of Act 127-2024, Section 2(5)(v) Failed to respond to a routine One Call ticket within the required amount of time.</p> <p>Masontown Borough is in violation of: Section 2(5)(v) – Failed to respond to routine One Call ticket 20250221438 within the required amount of time. *Please see ticket 20250221438 details above. Recommendation: The penalty is applied. Education is required.</p>	
52450	<p>Facility Owner: Greater Johnstown Water Authority Contractor/Excavator: S&C PIPELINES INC Project Owner: PEOPLES NATURAL GAS</p>	<p><u>On 1/28/2025 1:50:00 PM at BARNHART STREET, JOHNSTOWN CITY, CAMBRIA</u> The incident occurred on 1/28/2025 on Barnhart St in Johnstown City in Cambria County.</p> <p>A service lateral water line was damaged.</p> <p>PEOPLES GAS COMPANY LLC the project owner stated in their Alleged Violation Report (AVR) that “S&C was digging a bell hole over a new 4" plastic gas main for service installation to house 116. The service was not found on the initial mainline install as it was slightly deeper and was hit in the bell hole while digging a tap for the service. The water authority rep indicated too much time and snow fall voided the mark out and the contractor should have called for a remark or maintained the original markings”. Report and pictures were provided.</p> <p>S AND C PIPELINE INC stated in their AVR that “Our crew was working to install a gas service to house</p>	<p>S&C PIPELINES INC: \$750.00 Section 5(3) 1st Offense \$500.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>number 116. Upon doing so we dug next to the gas line and the operator hit an unmarked water line. When the water company marks out the water lines, they paint the box and mark the curb as well as the road. None of which were visible at the time of the hit. The water company said it was marked and that we should have called for a remark but the gas marking where all visible to our workers.if our workers would have had any indication of a water line they would have call to have it remarked”. Pictures were provided.</p> <p>GREATER JOHNSTOWN WATER AUTHORITY stated in their AVR that “S&C PIPELINES FAILED TO RENOTIFY THE UNDERGROUND UTILITIES TO REMARK THE WORK AREA WHEN MARKS WERE NO LONGER VISIBLE. DURING EXCAVATION, THE CURB BOX WAS COVERED WITH SNOW AND THEN DIRT SO THAT THE ONLY MARK REMAINING WOULD NOT BE SEEN AS WELL. WITHOUT VISIBLE MARKS, THE SERVICE LATERAL WAS STRUCK AND DAMAGED. S&C PIPELINES NOTIFIED GJWA IMMEDIATELY AND A CREW WAS SENT TO THE WORK SITE TO REPAIR THE DAMAGE WITHIN THE EXISTING TRENCH. NO ADDITIONAL EXCAVATION WAS REQUIRED. 1 RESIDENT WAS TEMPORARILY OUT OF WATER SERVICE UNTIL THE REPAIR WAS FINISHED. NO COMPLAINTS WERE FILED BY THE RESIDENT CONCERNING DIRTY WATER OR DAMAGED PROPERTY. PHOTOS ARE ATTACHED SHOWING THE LIMITED/ABSENCE OF VISIBILE MARKS IN THE WORK ZONE”. Report and pictures were provided.</p> <p>Cases connected by ticket: 52544. JOHNSTOWN CITY OF violation 2(5)(v) for ticket 20243660132 in case 52544.</p> <p>VIOLATIONS S&C PIPELINES INC is in violation of section: Section 5(3) – Excavator failed to preserve mark-outs or request a remark. There are no blue marks in any of the pictures provided. Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. Recommendation: The penalties are applied. Education is required.</p>	
52496	<p>Facility Owner: Lancaster City Water Authority - LU Contractor/Excavator: Kinsley Construction LLC Project Owner: UGI Utilities Designer: RETTEW</p>	<p><u>On 1/29/2025 9:10:00 AM at 867 FOUNTAIN AVE, LANCASTER CITY, LANCASTER</u> The incident occurred on 01/29/2025 at 9:10 AM, at 867 Fountain Avenue, in Lancaster City, Lancaster County.</p> <p>A water line owned by Lancaster City Water Authority was damaged.</p> <p>Lancaster City Water Authority is the facility owner. An Alleged Violation Report (AVR) has not been filed as of 03/26/2025.</p>	<p>Lancaster City Water Authority - LU: \$2,250.00 Section 2(5)(i) 2nd Offense \$1,000.00</p> <p>Section 2(10) 1st Offense \$1,000.00</p> <p>Section 2(5)(v) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Kinsley Construction LLC, the excavator, submitted an AVR. Their AVR states, "Onsite crew utilized vac truck to spot marked utility facilities prior to trench excavation. 2 water services were not marked and operator pulled on one of the copper services with the excavator bucket when digging trench. While clearing around damaged service, using prudent digging techniques, crew uncovered a second copper service. Damaged water service was to 867 Fountain AVE, Lancaster. 811 notified and water authority responded. Water crew made repairs by re-rounding service line. Water authority then marked the 2 services with blue paint. Pictures provided." Photos were submitted.</p> <p>UGI Utilities, the project owner, submitted an AVR. Their AVR states, "Contractor states that the crew utilized vac truck to spot marked utility facilities prior to trench excavation. 2 water services were not marked and operator pulled on one of the copper services with the excavator bucket when digging trench. While clearing around damaged service, using prudent digging techniques, crew uncovered a second copper service. Damaged water service was to 867 Fountain AVE, Lancaster. 811 notified and water authority responded. Water crew made repairs by re-rounding service line. Water authority then marked the 2 services with blue paint."</p> <p>This case is related to case 050602.</p> <p>Routine ticket 20250070258 had a response due date of 01/09/2025. LANCASTER CITY OF WATER responded 'Field Marked' on 01/14/2025 – late response.</p> <p>Violations:</p> <p>Lancaster City Water Authority –</p> <ul style="list-style-type: none"> - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. - Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20250070258. <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
52469	<p>Facility Owner: Ashley Borough Contractor/Excavator: R L E ENTERPRISES Project Owner: Pennsylvania American Water Company (PAWC)</p>	<p><u>On 1/29/2025 12:00:00 PM at 52 Cook St., ASHLEY BORO, LUZERNE</u> Ashley Boro wanted to dispute late on 6/11/25. Let them know they could dispute post DPC. Ashley Borough Submitted an AVR on 6/27/25 stating, "RLE did not report these damages to the Borough." ***</p>	<p>Ashley Borough: \$1,250.00 Section 2(5)(i.1) 1st Offense \$250.00 Section 2(10) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Incident occurred on January 29th, 2025, at 12pm at 52 Cook Street, Ashley Boro, Luzerne County.</p> <p>A sewer line was damaged.</p> <p>R L E Enterprises Alleged Violation Report (AVR) states, "WHILE DIGGING FOR A NEW WATER MAIN INSTALLATION OUR CREW STRUCK (2) UNMARKED SEWER LATERALS FOR HOUSE #52. RLE MADE REPAIRS AND RESTORED SERVICE IN A TIMELY MANNER."</p> <p>PAWC's AVR states, "R.L.E. was installing new water main on Cook St, Ashley. While excavating they hit an 4" unmarked sewer lateral to house #52 Cook St. R.L.E made the repairs to the unmarked lateral."</p> <p>Ashley Boro has not submitted an AVR as of 3/19/2025. Case is related to 52411.</p> <p>Pictures show the unmarked damaged line.</p> <p>Violations:</p> <p>Ashley Boro Section 2(5)(i.1) – Failed to locate an actually known facility’s point of connection to its facilities. PUC compliance education is required. 20250021506 Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. PUC compliance education is required.</p> <p>R L E Enterprises Section 5(20) – Excavator failed to renotify One Call of an unmarked or incorrectly marked facility upon arrival at a work site. 20250021506. PUC compliance education is required Section 9 – Failed to make best efforts to comply with Common Ground Alliance Best Practices. R L E Enterprises has not completed PUC Compliance Education for cases 46541, 44445, 32261, 30312, 30947. These education requirements go back as far as 2023.</p>	<p>R L E ENTERPRISES: \$500.00 Section 5(20) 1st Offense \$250.00</p> <p>Section 9 1st Offense \$250.00</p>
52828	<p>Facility Owner: Breezeline Contractor/Excavator: Kukurin Contracting, Inc. Project Owner: Frankstown Township Designer: Stiffler McGraw and Associates</p>	<p><u>On 1/29/2025 3:00:00 PM at AGGIE STREET (MH A10 TO C4), FRANKSTOWN TWP, BLAIR</u> The incident occurred on 01/29/2025 at 3:00 PM, on Aggie Street (MH A10 TO C4), in Frankstown Township, Blair County.</p> <p>A cable TV line owned by Breezeline was damaged.</p> <p>Breezeline is the facility owner. An Alleged Violation Report (AVR) has not been filed as of 03/25/2025.</p> <p>Kukurin Contracting, Inc., the excavator, submitted an AVR. Their AVR states, “At 3pm on January 29, while</p>	<p>Breezeline: \$1,500.00 Section 2(5)(i) 1st Offense \$500.00</p> <p>Section 2(10) 1st Offense \$1,000.00</p> <p>Frankstown Township: \$500.00 Section 2(5)(v.2) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>excavating along the berm to install a sanitary sewer main near 204 Aggie Street, Kukurin struck a mismarked Breezeline cable tv cable. The closest mark was 8'-0" away." Photos were submitted.</p> <p>Frankstown Township, the project owner, submitted an AVR. Their AVR states, "I WAS ADVISED THAT A BREEZELINE CABLE TV LINE WAS DAMAGED DURING EXCAVATION. I WAS NOT PRESENT FOR THIS INCIDENT." A second AVR was received that stated, "Contractor hit an unmarked Breezeline cable."</p> <p>Stiffler McGraw and Associates, the designer, submitted an AVR. Their AVR states, "At 3:00 PM on January 29 while excavating along the shoulder to install sanitary sewer main at 204 Aggie street the excavator broke a mismarked Breezeline cable. 3 breezeline cables were uncovered along the roadway. The marks for the active line were miss marked."</p> <p>Routine ticket 20250100339 had a response due date of 01/14/2025. FRANKSTOWN TOWNSHIP responded, 'SCHEDULED DATE & TIME LINES WILL BE MARKED BY:13 Jan 2025 1115', but did not provide a final response.</p> <p>Emergency ticket 20250292917 had a response due date of 01/29/2025. FRANKSTOWN TOWNSHIP responded, 'SCHEDULED DATE & TIME LINES WILL BE MARKED BY: 29 Jan 2025 1814', but did not provide a final response.</p> <p>Violations:</p> <p>Breezeline -</p> <ul style="list-style-type: none"> - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. - Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Frankstown Township – (No prior violations.)</p> <ul style="list-style-type: none"> - Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket 20250100339. - Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Emergency ticket 20250292917. <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p>	<p>Section 2(5)(v.2) 1st Offense \$250.00</p>
52544	<p>Facility Owner: Peoples Gas Company Contractor/Excavator: S AND C PIPELINE</p>	<p><u>On 1/30/2025 12:50:00 PM at BARNHART STREET, JOHNSTOWN CITY, CAMBRIA</u> Incident occurred on January 30th, 2025, at 12:50pm along Barnhart Street, Johnstown City, Cambria County.</p>	<p>S AND C PIPELINE: \$2,000.00 Section 5(3) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>Project Owner: PEOPLES PLACEHOLDER Other: Johnstown City</p>	<p>A gas line was damaged.</p> <p>Peoples Gas Company's Alleged Violation Report (AVR) states, "S AND C PIPELINE was digging to install new gas main and services when they struck a 1.25" steel service for 121 Barnhart st. Contractor crossed this line 2 days prior. Ticket should've been updated, you cannot see anything marks on the road. Marks were accurate. Pictures show the service pulled up." AVR notes that 911 was notified.</p> <p>S and C Pipeline has not submitted an AVR as of 3/21/25.</p> <p>Peoples Gas Company's pictures show that the line was damaged in the tolerance zone. Mark out curves closer to the excavation as it gets closer to the point of connection to the main in the street.</p> <p>Violations:</p> <p>S and C Pipeline Section 5(3) – Excavator failed to preserve mark-outs or request a remark. PUC compliance education is required. Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. PUC compliance education is required. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required.</p> <p>Johnstown City Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20243660132. PUC compliance education is required. Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20250301979. PUC compliance education is required.</p>	<p>Section 5(4) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>Johnstown City: \$1,500.00 Section 2(5)(v) 1st Offense \$500.00</p> <p>Section 2(5)(vii) 1st Offense \$1,000.00</p>
52700	<p>Facility Owner: Pennsylvania American Water (PAWC) Contractor/Excavator: Northern Pipeline Construction Project Owner: Columbia Gas of PA Designer: Columbia Gas of PA (Placeholder) Other: C S DAVIDSON INC Other: KINSLEY CONSTRUCTION</p>	<p><u>On 1/30/2025 1:00:00 PM at KELLY DR, YORK CITY, YORK</u> The incident occurred on 01/30/2025 at 1:00 PM, on Kelly Drive, in York City, York County.</p> <p>A sewer line owned by PA American Water was damaged.</p> <p>PA American Water is the facility owner. An Alleged Violation Report (AVR) has not been filed as of 03/30/2025.</p> <p>Northern Pipeline Construction, the excavator, submitted an AVR. Their AVR states, “NPL Construction was digging putting in a gas main for Columbia Gas. As the Crew open a manhole to check how deep the sewer was it measure at 6 foot. Continuing on with ditch line, they dug down to about approximately 5 foot as they flat bucket the ditch to move some loose material they came across and struck the top of the terra-cotta sewer line.”</p>	<p>Pennsylvania American Water (PAWC): \$1,000.00 Section 2(10) 1st Offense \$1,000.00</p> <p>Northern Pipeline Construction: \$500.00 Section 5(4) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Columbia Gas of PA, the project owner and designer, submitted an AVR. Their AVR states, "Northern Pipeline Construction (NPL), working on behalf of Columbia Gas for an infrastructure replacement project, damaged a gravity sewer while crossing it for the new gas main lay line. NPL had opened the sewer lid and measured the depth to the pipe, determining it to be 6 feet. Using this measurement, they began crossing Fahs St. The sewer was not spotted at this time. While digging down to the depth for the gas main, the crew used the excavator bucket to scrape the bottom of the trench to flatten it out and hit the top of the sewer pipe at 5 feet 11 inches. The sewer material was terracotta with a 48-inch diameter, and a 5-inch hole broke out on top. The crew promptly stopped work and notified 811 and Columbia Gas of the damage." Photos were submitted.</p> <p>Violations:</p> <p>PA American Water – - Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Northern Pipeline Construction – - Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
52586	<p>Facility Owner: Peoples Gas Company Contractor/Excavator: Pittsburgh Water Project Owner: PWSA</p>	<p><u>On 2/3/2025 10:00:00 AM at 211 EDMOND ST, PITTSBURGH CITY, ALLEGHENY</u> Pittsburgh Water disputed and DPI removed violation and penalty for section 1.1. ***** Incident occurred on February 3rd, 2025, at 10am at 211 Edmond Street, Pittsburgh City, Allegheny County.</p> <p>A gas line was damaged.</p> <p>Peoples Gas Company's Alleged Violation Report (AVR) states, "Pittsburgh Water and Sewer Authority working on an emergency request struck and damaged a Peoples Gas service line. There is clear evidence of underground utilities in the work area and the line was struck with mechanized equipment. Pittsburgh Water and Sewer called this ticket in as an emergency three times within three days and twice as a routine within those same days."</p> <p>PWSA's AVR states, "PWSA was digging curb box and hit mismarked plastic gas service line. PWSA called dispatch and Peoples Gas responded and made repairs. Fire department did not show up."</p>	<p>Pittsburgh Water: \$500.00 Section 5(4) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>PWSA called in two routine and two emergency dig tickets for this dig site between 1/31/25 and 2/2/25 not including the emergency damage ticket on 2/3/25. The last ticket placed by PWSA prior to excavating was routine ticket 20250330354 with a lawful start date of 2/5/25.</p> <p>The lateral leading to 211 Edmond Steet was damaged. PWSA's pictures are measuring the main's mark out lines to where the damage occurred on the lateral. Peoples marked the lateral and their pictures show the hit kit measuring the lateral mark out to the damage on the lateral line. People's pictures also show the pre-excavation mark outs. PWSA & Peoples AVRs state that one customer was affected which further confirms it was the lateral that was damaged and not the main which PWSA's pictures are showing the measurement of.</p> <p>Violations:</p> <p>PWSA Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. PUC compliance education is required. Section 1.1 – Excavator did not begin within legal timeframe. PUC compliance education is required. 20250330354</p>	
52635	<p>Facility Owner: UGI Utilities Inc Contractor/Excavator: MOUNT PENN MUNICIPAL AUTH Project Owner: MOUNT PENN MUNICIPAL AUTH (Placeholder)</p>	<p><u>On 2/4/2025 8:50:00 AM at 3551 JACKSONWALD AVE, ST LAWRENCE BORO, BERKS</u> UGI accepts.</p> <p>*****</p> <p>The incident occurred on 02/04/2025 at 8:50 AM, at 3551 Jacksonwald Avenue, in Saint Lawrence Borough, Berks County.</p> <p>A gas line owned by UGI Utilities was damaged. 911 was called.</p> <p>UGI Utilities, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “Excavator utilizing mechanized equipment, struck an incorrectly marked gas service while digging to repair a water leak.” Photos were submitted.</p> <p>MOUNT PENN MUNICIPAL AUTH is the excavator and project owner. An AVR has not been filed as of 03/28/2025.</p> <p>Violations:</p> <p>MOUNT PENN MUNICIPAL AUTH - - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: The penalty is applied. PUC compliance training education is required. UGI Utilities – - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: The penalty is applied. PUC compliance training education is required.</p>	<p>UGI Utilities Inc: \$500.00 Section 2(5)(i) 1st Offense \$500.00</p> <p>MOUNT PENN MUNICIPAL AUTH: \$1,000.00 Section 5(16) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
52585	<p>Facility Owner: Hanover Borough Water Contractor/Excavator: Kinsley Construction Project Owner: Columbia Gas of PA Other: RETTEW</p>	<p><u>On 2/4/2025 10:00:00 AM at 101 OAK ST, HANOVER BORO, YORK</u> The incident occurred on 02/04/2025 at 10:00 AM, at 101 Oak Street, in Hanover Borough, York County.</p> <p>A water line owned by Hanover Borough Water was damaged.</p> <p>Hanover Borough Water, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, "101 Oak St. 2-4-25 Troy Forry (Kinsley) called Zac (Hanover Water) at 9:56 AM that a service was struck. Zac and Dustin were on site at 10:12 AM. Hanover Water had the water stopped at 10:45 AM. Hanover was unable to make the repair in the ditch without further excavation. Troy said they would remove anything we wanted because they had a god PA-1 Call. They removed blacktop and concrete so we could dig down and make the service repair. Hanover Sewer brought the Vac Truck out to help with excavation. During this event there was only 1 house out of service. 101 Oak St. was the house out of water. Kinsley was installing new gas main for Colombia Gas. The service was marked 3 ft. off the actual location. Hanover finished the repair at 2:30 PM. And put the customer back in service. Hanover backfilled behind the curb and Kinsley took care of the hole in the road. The project they are working on is about 4,500 feet long and this is just another example of how well we work together. We mark everything to the best of our ability. We have maps, cards and locators. This was one of about 350 services marked on this project. We have a great working relationship with Columbia and every contractor they use. We are hoping that we can just move forward and continue communicating and working together without fines. Onsite was Zac Stiles – Hanover Water Dustin Smith – Hanover Water Harlon Leppo – Hanover Sewer Troy Forry – Kinsley Austin Frey – Kinsley Pujols (Frank) – Colombia Gas Hannah – PUC".</p> <p>Kinsley Construction, the excavator, submitted an AVR. Their AVR states, "Kinsley Construction, working on behalf of Columbia Gas on an infrastructure replacement project, was digging a new gas main line when they damaged a mismarked water service line leading to 101 Oak St. The marks were off by 30 inches. The damage occurred before the curb valve located in the sidewalk. Upon discovering the damage, the Kinsley foreman immediately notified Hanover Water and 811 to report the incident." Photos were submitted.</p> <p>Columbia Gas, the project owner and designer, submitted an AVR. Their AVR states, "Kinsley Construction, working on behalf of Columbia Gas for an infrastructure replacement project, was digging their trench for new gas main when they struck and damaged a mismarked water service feeding 101 Oak St., Hanover. The closest marks were 30" away. The Kinsley Foreman immediately contacted Hanover Water and 811 to report the incident." Photos were submitted.</p>	<p>Hanover Borough Water: \$500.00 Section 2(5)(i) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Violations:</p> <p>Hanover Borough Water - - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
52933	<p>Facility Owner: UGI Utilities Contractor/Excavator: LEEWARD CONSTRUCTION Project Owner: Pennsylvania American Water Company (PAWC) Other: Dunmore Borough</p>	<p><u>On 2/4/2025 10:00:00 AM at HOLLISTER AVE, SCRANTON CITY, LACKAWANNA</u> Violations for UGI were removed after clarifying pictures with accurate mark outs.</p> <p>****</p> <p>Incident occurred on February 2nd, 2025, at 10am along Hollister Avenue, Scranton Avenue, Lackawanna County.</p> <p>A gas line was damaged.</p> <p>UGI's Alleged Violation Report (AVR) states, "While excavating for water main replacement on the 200 block of Hollister Ave, Scranton, the contractor pinched an inserted 1" gas service for house #256. The service was not broken, however, UGI was notified and dispatched a crew to make a repair on the line. Though the marks were visible, at the house (curb) side of the service, the marks were 6" off and at the main side of the service the marks were approximately 25" off. UGI made the repair to the pinched gas service and water main replacement work resumed."</p> <p>Leeward Construction's AVR states, "On February 4, 2025, the crew installing water main along Hollister Ave. in the vicinity if 256 Hollister Ave struck the outer wall of an inserted gas service. UGI was notified that the line the service was inserted into was damaged and they were requested to inspect the service to either make sure it was still functional or needed to be replaced. Upon further investigation, UGI replaced the damaged portion if the service. At no time was gas blowing."</p> <p>PAWC's AVR states, "While excavating for water main replacement on the 200 block of Hollister Ave, Scranton, the contractor pinched an inserted 1" gas service for house #256. The service was not broken, however, UGI was notified and dispatched a crew to make a repair on the line. Though the marks were visible, at the house (curb) side of the service, the marks were 6" off and at the main side of the service the marks were approximately 25" off. UGI made the repair to the pinched gas service and water main replacement work resumed."</p> <p>Violations:</p> <p>UGI Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. PUC compliance education is required.</p>	<p>UGI Utilities: \$0.00</p> <p>Dunmore Borough: \$500.00 Section 2(5)(viii) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Dunmore Borough Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). PUC compliance education is required.</p>	
52592	<p>Facility Owner: Peoples Gas Company Contractor/Excavator: INDEPENDENT ENTERPRISES</p>	<p><u>On 2/4/2025 11:00:00 AM at BISMARCK ST, PITTSBURGH CITY, ALLEGHENY</u> Incident occurred on February 2nd, 2025, at 11am along Bismarck Street, Pittsburgh City, Allegheny County.</p> <p>A gas line was damaged.</p> <p>Peoples Gas Company's Alleged Violation Report (AVR) states, "INDEPENDENT ENTERPRISES working for Pittsburgh Water and Sewer Authority struck and damaged a Peoples Gas main line. INDEPENDENT ENTERPRISES was using mechanized equipment in the tolerance zone and uncovered a properly marked and labeled 1.25inch plastic line inserted into 4inch steel. The markings clearly state that this line was inserted. INDEPENDENT ENTERPRISES proceeded to use a power saw to cut through the steel line and completely severed the plastic line within."</p> <p>Independent Enterprises' AVR states, "Contractor began digging for emergency sewer repair. Upon digging it was discovered to be what it seemed as an abandoned gas line. Contractor did investigation which seemed that it was clear to remove abandoned gas line. a 1 1/2" plastic service was discovered within the steel gas line. Contractor called 911 and 811 and repair was made."</p> <p>Pictures from Peoples' show that the line was exposed and cut within the tolerance zone. Investigating if a line is active or abandoned by cutting the line is not a safe practice. This line was marked accurately and noted properly per CGA guidelines as a 1 1/4 pla in 4" STL CASE. Please see Peoples locate 3 picture. The line was clearly exposed prior to the excavator planning to saw cut the line.</p> <p>Violations:</p> <p>Independent Enterprises Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. PUC compliance education is required. Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. PUC compliance education is required.</p>	<p>INDEPENDENT ENTERPRISES: \$750.00 Section 5(4) 1st Offense \$500.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p>
52583	<p>Facility Owner: Cranberry Township Butler County Contractor/Excavator: Patino Construction</p>	<p><u>On 2/4/2025 4:00:00 PM at 223 CASHMERE CT, CRANBERRY TWP, BUTLER</u> Brightspeed accepts the findings.</p> <p>*****</p>	<p>Cranberry Township Butler County: \$1,500.00 Section 2(5)(i) 1st Offense \$500.00</p> <p>Section 2(10) 1st Offense</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>Project Owner: Comcast Other: Brightspeed</p>	<p>The incident occurred on 02/04/2025 at 4:00 PM, at 223 Cashmere Court, in Cranberry Township, Butler County.</p> <p>A water line owned by Cranberry Township Butler County was damaged.</p> <p>Cranberry Township Butler County is the facility owner. An Alleged Violation Report (AVR) has not been filed as of 03/26/2025.</p> <p>Patino Construction is the excavator. An AVR has not been filed as of 03/26/2025.</p> <p>Comcast, the project owner, submitted an AVR. Their AVR states, "crews hit a unmarked service line . it was a small hit and caused a small leak . Cranberry township was onsite and saw the marks where off." Photo submitted.</p> <p>Emergency ticket 20250353224 had a response due date of 02/04/2025. Brightspeed did not respond to this ticket.</p> <p>Violations:</p> <p>Cranberry Township Butler County-</p> <ul style="list-style-type: none"> - Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: The penalty is applied. PUC compliance training education is required. <p>Patino Construction –</p> <ul style="list-style-type: none"> - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: The penalty is applied. PUC compliance training education is required. <p>Brightspeed –</p> <ul style="list-style-type: none"> - Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Emergency ticket 20250353224. Recommendation: The penalty is applied. PUC compliance training education is required. 	<p>\$1,000.00</p> <p>Patino Construction: \$1,500.00 Section 5(16) 2nd Offense \$1,500.00</p> <p>Brightspeed: \$1,000.00 Section 2(5)(vii) 1st Offense \$1,000.00</p>
52612	<p>Contractor/Excavator: Utility Line Services Project Owner: Aqua PA Designer: TOTAL ENGINEERING AND CONSULTING LLC Other: LOWER MERION TOWNSHIP Other: PECO Other: PennDot</p>	<p><u>On 2/5/2025 8:00:00 AM at YOUNGS FORD RD, LOWER MERION TWP, MONTGOMERY</u> The non-damage event occurred on 02/05/2025, on Young Ford Road, in Lower Merion Township, Montgomery County.</p> <p>Utility line mark outs were not completed and a renotify ticket was requested, causing several hours of downtime.</p> <p>Utility Line Services, the excavator, submitted an AVR. Their AVR states, “Crew arrived onsite and noticed no mark outs were provided in the area of 1115 Youngs Ford Road for upcoming water main installation. USIC was contacted directly by ULS on 02/04/25 and</p>	<p>LOWER MERION TOWNSHIP: \$500.00 Section 2(5)(v.1) 1st Offense \$500.00</p> <p>PECO: \$500.00 Section 2(5)(v.1) 1st Offense \$500.00</p> <p>PennDot: \$500.00 Section 2(5)(v.1) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>informed of incomplete mark outs. ULS crew returned on 02/05/25 and still no mark outs had been provided so 811 was contacted at approximately 9:00 am for Renotification and several hours passed before Locator arrived on site causing the crew hours in downtime.”</p> <p>Aqua PA, the project owner, submitted an AVR. Their AVR states, "Aqua Contractor Utility Line Services, crew arrived onsite and noticed no mark outs were provided in the area of 1115 Youngsford Rd for upcoming water main installation. USIC was contacted directly by ULS on 2/4/25 and informed of incomplete mark outs. ULS Crew returned and still no mark outs had been provided so 811 was contacted at approximately 9:00 am for Renotification and several hours passed before Locator arrived on site causing the crew hours in downtime.”</p> <p>TOTAL ENGINEERING AND CONSULTING LLC is the designer. An AVR has not been filed as of 04/02/2025.</p> <p>There were not any complex project meeting agreements for complex project 20242490135.</p> <p>Renotify ticket 20250292600-001 was requested on 02/05/2025 at 09:25. PennDOT did respond to the ticket. PECO did not respond ‘Field Marked’ until 02/05/2025 at 6:57 PM. Lower Merion Township did not respond ‘Field Marked’ until 02/05/2025 at 11:56:43 AM.</p> <p>Violations:</p> <p>PennDOT - - Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Renotify ticket 20250292600-001. Recommendation: The penalty is applied.</p> <p>PECO - - Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Renotify ticket 20250292600-001. Recommendation: The penalty is applied.</p> <p>Lower Merion Township – - Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Renotify ticket 20250292600-001. Recommendation: The penalty is applied.</p>	
52596	<p>Facility Owner: KLINE TOWNSHIP MUNICIPAL AUTHORITY Contractor/Excavator: Premium Utility Contractor Project Owner: PPL ELECTRIC UTILITIES</p>	<p><u>On 2/5/2025 9:00:00 AM at N LINCOLN ST, MCADOO BORO, SCHUYLKILL</u> Incident occurred on February 2nd, 2025, at 9am along North Lincoln Street, McAdoo Boro, Schuylkill County.</p> <p>This is a non-damage incident.</p> <p>Kline Township Municipal Authority's Alleged Violation Report (AVR) states, "Ticket has been</p>	<p>Premium Utility Contractor: \$1,000.00 Section 5(9) 1st Offense \$1,000.00</p> <p>MCADOO BOROUGH: \$500.00 Section 2(5)(v) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>CORPORATION Designer: KATAPULT ENGINEERING Other: MCADOO BOROUGH Other: MCADOO BOROUGH SEWER AUTHORITY</p>	<p>submitted for work and marked out several times over the past couple months. Ticket was called in today as an emergency because the excavator is ready to do the work tomorrow and the paint lines have worn off. I feel this is abuse of the emergency call as I am the only one here to take care of our system and mark lines. This "emergency" pulled me away from other work when as I stated this has been marked out several times already."</p> <p>The initial ticket placed by Premium Utility Contractor was a routine dig ticket under 20250240381. Work was not completed under this routine ticket and it expired. Premium Utility Contractor then placed emergency ticket 20250362267. Both the routine and emergency ticket are to REPLACE ANCHOR AT POLE GRID 48657S57693. This project includes a design ticket which shows it was preplanned and does not meet the guidelines for an emergency.</p> <p>Design ticket is 20241981896, REPLACING ANCHOR AT PPL POLE #48657S57693 ALONG NORTH LINCOLN STREET. GOOGLE 40.903872 -75.989211 FOR MAP OF LOCATION.</p> <p>Violations:</p> <p>Premium Utility Contractor Section 5(9) – Emergency notification does not meet the requirements of “emergency” as defined in Section 1 – Excavator Ticket. 20250362267. PUC compliance education is required.</p> <p>McAdoo Borough Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20250240381. PUC compliance education is required.</p> <p>McAdoo Borough Sewer Authority Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20250240381. PUC compliance education is required.</p>	<p>MCADOO BOROUGH SEWER AUTHORITY: \$500.00 Section 2(5)(v) 1st Offense \$500.00</p>
52599	<p>Contractor/Excavator: CARR AND DUFF Project Owner: PECO AN EXELON COMPANY</p>	<p><u>On 2/5/2025 11:00:00 AM at OVERBROOK AVE, PHILADELPHIA CITY, PHILADELPHIA</u> The incident occurred on Wednesday, February 5, 2025, on Overbrook Avenue, in Philadelphia City, Philadelphia County.</p> <p>A sewer line was damaged by digging with a Hand Tool.</p> <p>Contractor, Carr and Duff’s, stated in their Alleged Violation Report, our “Foreman was hand digging at Sheet 8Location 49 Pole 31910, while using a digging bar and shovel. [The] Foreman removed a piece of concrete with the digging bar and broke open an unmarked sewer line. Water and other things flowed into the hole. [The] Foreman notified his General Foreman, Construction manager, Safety Dept, and 811. PA-1 issued an emergency report# 20250361583. [The] Foreman also notified Phila Water Dept.” Carr and Duff provided photos of the damaged line-Sheet 8 Loc 49 Before Pics and Damage Pics</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
52690	<p>Facility Owner: PEOPLES GAS COMPANY LLC</p> <p>Contractor/Excavator: PITTSBURGH WATER</p> <p>Project Owner: PITTSBURGH WATER</p> <p>Other: Verizon, PA LLC</p>	<p>No Violation. Hand Tool Damage.</p> <p><u>On 2/10/2025 10:00:00 AM at 1330 GOETTMAN ST, PITTSBURGH CITY, ALLEGHENY</u> The incident occurred on Monday, February 10, 2025, at 1330 Goettman Street, in Pittsburgh City, Allegheny County.</p> <p>A gas line was damaged.</p> <p>Pittsburgh Water and Sewer Authority (PWSA) failed to use prudent techniques within the tolerance zone. PWSA stated in their Alleged Violation Report (AVR) that they were digging and hit an accurate marked gas mainline, and 911 was called. Peoples Gas Company responded and made repairs. PWSA provided photos.</p> <p>Peoples Gas stated in their AVR that PWSA was working on an Excavation Emergency ticket, 20250381896, placed on 2/7/2025, and worked on 2/10/2025. PWSA struck and damaged a properly marked Peoples Gas line while using mechanized equipment in the tolerance zone. Peoples Gas provided photos.</p> <p>20250371078- Routine ticket placed on 2/6/2025, with response due date of 2/10/2025. Late Response from- Verizon PA LLC they responded on 2/14/2025 as Clear No Facilities.</p> <p>Violations:</p> <p>*Pittsburgh Water and Sewer Authority is in violation of section: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: Penalty Applied</p> <p>*Verizon PA LLC is in violation of section: 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. 20250371078 Recommendation: Penalty Applied</p>	<p>PITTSBURGH WATER: \$1,500.00 Section 5(4) 3rd Offense \$1,500.00</p> <p>Verizon, PA LLC: \$1,000.00 Section 2(5)(v) Subsequent \$1,000.00</p>
52683	<p>Facility Owner: Municipal Authority of Westmoreland County</p> <p>Contractor/Excavator: W. A. Petrakis</p> <p>Project Owner: Peoples Gas Company</p> <p>Designer: PEOPLES</p>	<p><u>On 2/10/2025 11:30:00 AM at COLUMBUS ST, HEMPFIELD TWP, WESTMORELAND</u> Incident occurred on February 10th, 2025, at 11:30am along Columbus Street, Hempfield Township, Westmoreland County.</p> <p>A water line was damaged.</p> <p>Municipal Authority of Westmoreland County's (MAWC) Alleged Violation Report (AVR) states, "Excavator, W.A. Petrakis Contracting was digging for Project Owner, Peoples Gas to install a new gas mainline along Columbus St. W.A. Petrakis hit a Municipal Authority of Westmoreland County (MAWC) service line that MAWC feels was located within the tolerance zone. When MAWC responded to the damage, it's previous marks were not visible."</p> <p>Peoples Gas Company's AVR states, "W A PETRAKIS CONTRACTING COMPANY was digging to install a</p>	<p>Municipal Authority of Westmoreland County: \$500.00 Section 2(5)(i) 1st Offense \$500.00</p> <p>W. A. Petrakis: \$1,000.00 Section 5(16) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>new gas main and services when they struck a water main and service. Marks were 2' off. According to the pictures it was a copper water line."</p> <p>No AVR has been submitted by W A Petrakis as of 3/27/2025.</p> <p>Peoples' pictures show faded blue paint marked outside the tolerance zone of the damaged line. Compare Peoples' Columbus St pictures with faint blue mark out against MAWC Columbus St 1 & 2 or view Image.docx file.</p> <p>Violations:</p> <p>MAWC Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.</p> <p>W A Petrakis Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required.</p>	
52768	<p>Facility Owner: Columbia Gas of PA - East</p> <p>Contractor/Excavator: ALLEGHENY CONTRACTING</p> <p>Project Owner: Columbia Gas of PA - East</p> <p>Other: YORK WATER COMPANY</p>	<p><u>On 2/10/2025 1:39:00 PM at 2449 RALEIGH DR, SPRINGETTSBURY TWP, YORK</u> The incident occurred on Monday, February 10, 2025, at 2449 Raleigh Drive, Springettsbury Township, York County.</p> <p>A gas service line was damaged.</p> <p>Allegheny Contracting, working for Columbia gas for an infrastructure replacement project, damaged a 1-inch plastic gas service line at 2449 Raleigh Drive. Allegheny Contracting explained in their Alleged Violation Report, “that their crew was in the process of running a new service line to 2452 Raleigh Drive, directly across the street. They had initially dug down using hand tools to expose the tee before using mechanized equipment. During excavation, water runoff began to pool in the trench. Before continuing with the service line installation, an operator and a spotter were tasked with clearing the section of the new main where the tee was to be fitted, removing water and mud. The crew lowered the bucket into the ditch to clean it up, but in the process, they lost sight of the service line to 2449, which became covered with mud and slurry. The excavator was positioned on the backside of the service line to 2449, with the bucket curling towards the live gas service. While pulling the bucket up, the teeth caught the 1” plastic service line, causing gas to blow. The crew acted immediately to shut down the tee and notify 911 and 811 of the damage. Columbia Gas arrived on site and repaired the gas service.”</p> <p>Allegheny Contracting provided photos of the damaged service line.</p> <p>Columbia Gas stated in their AVR, Allegheny Contracting hit and damage an accurately marked, 1-inch plastic gas service line feeding 2449 Raleigh Drive, with their excavator bucket. Their crew immediately</p>	<p>ALLEGHENY CONTRACTING: \$1,000.00 Section 5(4) 1st Offense \$500.00</p> <p>Section 5(6)(ii) 1st Offense \$500.00</p> <p>YORK WATER COMPANY: \$250.00 Section 2(5)(v) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>shut down the tee and notified 911, 811, and Columbia Gas when the damage occurred. Columbia Gas Operations completed the repair, and a root cause investigation was conducted, and it was determined Excavator Negligence. Columbia Gas provided photos of the damaged service line.</p> <p>20250080314- Routine ticket placed on 1/8/2025. York Water Company responded as “Not Marked Due to No Access”, but they did not finalize the ticket with “Field Marked” or “Clear No Facilities”.</p> <p>Violations:</p> <p>*Allegheny Contracting is in violation of sections: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. 5(6)(ii) – Excavator failed to provide support and mechanical protection for known facility owner’s lines at the construction work site. Recommendation: Penalties Applied</p> <p>*York Water Company is in violation of section: 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. 20250080314 Recommendation: PUC Compliance Education Required and Penalty Applied</p>	
52694	<p>Facility Owner: Peoples Gas Company Contractor/Excavator: S AND C PIPELINE Project Owner: PEOPLES Designer: PEOPLES Other: Greater Johnstown Water Authority</p>	<p><u>On 2/11/2025 1:00:00 PM at MARY DR, WESTMONT BORO, CAMBRIA GJWA</u> Removed: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. 20250240471. PUC compliance education is required. Removed: Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20250360045. PUC compliance education is required. *** Peoples Gas violation and penalty was removed after showing communications and agreement with the excavator. *** Incident occurred on February 11th, 2025, at 1pm along Mary Drive, Westmont Boro, Cambria County. A gas line was damaged. Peoples Gas Company's Alleged Violation Report states, "S&C Pipeline hit a plastic service to 1501 Mary dr. This was a 1" plastic service. This service was marked correctly. Png crews came to fix the line. All services and main lines are getting replaced by S&C." S & C Pipeline's AVR states, "we where install a service to house number 1501 we a snow squall moved into the area an completely covered to marking up on the road the service line was already being install before the snow squall hit. as the operator was digging he hit a 1 inch plastic gas that have no indicaton that it was there. the</p>	<p>Peoples Gas Company: \$0.00</p> <p>S AND C PIPELINE: \$1,000.00 Section 5(3) 1st Offense \$500.00 Section 5(4) 1st Offense \$500.00</p> <p>Greater Johnstown Water Authority: \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>marks were completely covered and no caution tape was used or dust to indicate the pipe was there."</p> <p>Pictures from Peoples Gas Company show that the line was marked within the tolerance zone with paint on the road and flags in the yard.</p> <p>Violations:</p> <p>S & C Pipeline Section 5(3) – Excavator failed to preserve mark-outs or request a remark. PUC compliance education is required. Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. PUC compliance education is required.</p> <p>Peoples Gas Company Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. 20250240471. PUC compliance education is required.</p> <p>Greater Johnstown Water Authority Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. 20250240471. PUC compliance education is required. Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20250360045. PUC compliance education is required.</p>	
52997	<p>Facility Owner: WEST PENN POWER-FIRSTENERGY Contractor/Excavator: Igor Millei- Excavator Project Owner: Igor Millei- Excavator</p>	<p><u>On 2/12/2025 8:00:00 AM at 15460 Wedgewood Drive, GREENCASTLE BORO, FRANKLIN</u> On Friday 6/13/25- I returned a call, 619-707-2339, to Igor Millei- the Excavator and said wrong number and hung up on me. I tried a second time so I could leave VM but he did not answer and declined my call and I couldn't leave a VM. ***** The incident occurred on Wednesday, February 12, 2025, at 15460 Wedgewood Drive, in Greencastle Borough, Franklin County.</p> <p>West Penn Power/FirstEnergy underground electric line was damaged. There are no tickets associated with this incident.</p> <p>West Penn Power was notified of an outage at 15460 Wedgewood Drive. USIC, West Penn Power's Contract Locator, investigated and determined that an underground electric secondary service was damaged and that there were no visible markings at the site. The root cause of the damage is the Excavator, Igor Millei, did not submit a locate request through the PA One Call System.</p> <p>In the USIC investigation report, it stated, there were no locate request for this worksite, but there was 1 ticket placed 2 months ago by a contractor for new home construction. This job, with the electric damage, was for installing water service line by a subcontractor that did not have a locate request and the old locate marks were long gone. Marks in damage photos were from the tech marking for FirstEnergy, to repair the line.</p>	<p>Igor Millei- Excavator: \$2,000.00 Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>West Penn Power provided photos of the damage.</p> <p>The PA One Call Compliance commented, Excavator has placed One Call notifications with PA One Call in the past. There are no tickets associated with this incident.</p> <p>Igor Millei did not submitted an Alleged Violation Report.</p> <p>*Igor Millei is in violation of sections: 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: PUC Compliance Education Required and Penalties Applied</p>	
52835	<p>Facility Owner: Pittsburgh Water (PWSA)</p> <p>Contractor/Excavator: Duquesne Light</p> <p>Project Owner: Duquesne Light - Placeholder</p>	<p><u>On 2/12/2025 3:40:00 PM at N DALLAS AVE, PITTSBURGH CITY, ALLEGHENY</u> DLC accepts the findings of the report.</p> <p>*****</p> <p>AVR for Duquesne Light was located. It had an incorrect incident date of 02/21/2025 and therefore did not properly link to Pittsburgh Water (PWSA) for the incident that occurred on 02/12/2025. The violation for Duquesne Light, for not submitting an AVR, was withdrawn.</p> <p>*****</p> <p>The incident occurred on 02/12/2025 at 3:40 PM, on North Dallas Avenue, in Pittsburgh City, Allegheny County.</p> <p>A water line owned by Pittsburgh Water (PWSA) was damaged.</p> <p>Pittsburgh Water (PWSA), the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “DLC drilling to install a telephone pole. They drill right through an accurate marked water line. This flooded a home as well. PWSA responded, shut down the main and made repairs. Total negligence on DLC's part.” Photos were submitted.</p> <p>Duquesne Light is the excavator and project owner. Their AVR states, “Duquesne Light Company overhead crew were excavating to replace a pole when they struck and damaged a marked water line. A Damage One Call ticket was placed and PWSA responded to the job site.” Photos were submitted.</p> <p>Blue locate marks are visible in the submitted photos. The water line was damaged within the tolerance zone. PWSA noted that because of the damaged water line, a home was flooded. (The cost of the property repair due to the flooding was not noted.)</p> <p>Violations:</p>	<p>Duquesne Light: \$500.00 Section 5(4) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Duquesne Light –</p> <ul style="list-style-type: none"> - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. [Withdrawn. An AVR was located.] - Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
52802	<p>Facility Owner: UGI UTILITIES INC Contractor/Excavator: LINDE CORPORATION Project Owner: UGI UTILITIES INC Designer: RETTEW ASSOCIATES INC Designer: UGI UTILITIES INC</p>	<p><u>On 2/13/2025 12:50:00 AM at FERRY ST, EASTON CITY, NORTHAMPTON</u> The incident occurred on Thursday, February 13, 2025, at 1403 Ferry Street, in Easton City, Northampton County.</p> <p>A gas service line was damaged. 911 was not called.</p> <p>Linde Corporation, working on behalf of UGI Utilities, was digging to install a gas mainline and “encountered a large boulder that was under the marked [gas] service line. The service was exposed and visible. The crew was attempting to move the boulder form underneath the service line when the boulder rolled, causing the service to pull away from the tee at the main. The Crew then stopped the leak and notified the utility owner, [UGI].” UGI stated, Linde Corporation failed to protect the exposed gas service line and explained, “Linde was removing a large rock from there excavation and when doing so the rock fell into the excavation and damaged a gas service facility creating a damage and a leak.” Linde Corporation and UGI both provided photos of the damaged service line.</p> <p>Violations:</p> <p>*Linde Corporation is in violation of section: 5(6)(ii) – Excavator failed to provide support and mechanical protection for known facility owner’s lines at the construction work site. 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid. Recommendation: PUC Compliance Education Required and Penalties Applied</p>	<p>LINDE CORPORATION: \$1,500.00 Section 5(6)(ii) 1st Offense \$500.00</p> <p>Section 5(8) 1st Offense \$1,000.00</p>
52758	<p>Facility Owner: EMMAUS BOROUGH Contractor/Excavator: GREAT WESTERN SERVICES Project Owner: UGI UTILITIES INC</p>	<p><u>On 2/13/2025 8:30:00 AM at RIDGE STREET, EMMAUS BORO, LEHIGH</u> The incident occurred on Thursday, February 13, 2025, on Ridge Street, in Emmaus Borough, Lehigh County.</p> <p>A water line was damaged.</p> <p>Great Western Services (GWS), working for UGI Utilities, failed to use prudent techniques within the tolerance zone. GWS and UGI stated in their Alleged Violation Report’s (AVR), while the crew was trenching across the road, a marked water mainline was hit and damaged. The damage was 2-feet off of the mark, but the crew still hit the mainline.</p>	<p>EMMAUS BOROUGH: \$500.00 Section 2(5)(v) 2nd offense \$500.00</p> <p>GREAT WESTERN SERVICES: \$500.00 Section 5(4) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Emmaus Borough, the facility owner, stated in their AVR that GWS was trenching in the area of the water mainline, and line was struck with the backhoe. GWS provided photos of the damaged mainline.</p> <p>20250211774- Routine ticket placed on 1/21/2025, with a response due date of 1/23/2025. Late Response from- Emmaus Borough responded on 1/27/2025 as field marked.</p> <p>Violations:</p> <p>*Great Western Services is in violation of section: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: PUC Compliance Education Required and Penalty Applied.</p> <p>*Emmaus Borough is in violation of section: 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. 20250211774 Recommendation: PUC Compliance Education Required and Penalty Applied.</p>	
52813	<p>Facility Owner: PEOPLES GAS COMPANY LLC</p> <p>Contractor/Excavator: INDEPENDENT ENTERPRISES</p> <p>Project Owner: Pittsburgh Water</p> <p>Designer: WHITMAN REQUARDT AND ASSOCIATES LLP</p>	<p><u>On 2/17/2025 8:55:00 AM at 1926 JANE ST, PITTSBURGH CITY, ALLEGHENY</u> Removed Pittsburgh Water violation and penalty, see their attachment. *****</p> <p>The incident occurred on Monday, February 17, 2025, at 1926 Jane Street, in Pittsburgh City, Allegheny County.</p> <p>A gas service line was damaged.</p> <p>Peoples Gas Company stated that Independent Enterprises Inc (IEI) failed to use prudent techniques within the tolerance zone, when they hit and damaged a Peoples Gas owned service line at 1926 Jane Street, and has not been abiding by the complex project meeting agreement and has been working out of the order that was agreed to at the meeting.</p> <p>Peoples Gas explained in an email, “Independent Enterprises did not make meet or contact once the Peoples Gas locator entered the “092” Karl Code. The Peoples Gas locator made contact, along with other locators because Independent Enterprises was not abiding by what was agreed upon as far as when the phase 1 complex project meeting was held. No new meeting was held for additional addresses and streets being added, along with adding more crews. When the Peoples Gas locator asked why Independent Enterprises was not following the agreed upon schedule, Shane of Independent Enterprises stated they were just getting the work done to move on to other projects now. And PWSA added additional addresses to this project to complete. So he was brining more crews to get the work completed and that is why he called in the entire project. This came from the Peoples Gas locator. I added the notes entered on the one call ticket by the Peoples Gas locator and a list of tickets called in the same day for this project. Note: Independent has dropped their second phase all at once giving PNG no time to mark</p>	<p>INDEPENDENT ENTERPRISES: \$2,750.00 Section 5(3) 1st Offense \$500.00</p> <p>Section 5(3) 1st Offense \$500.00</p> <p>Section 5(4) 3rd Offense \$1,500.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p>Pittsburgh Water: \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>accordingly. PNG staying ahead of contractor according to mapped overhead that was agreed upon at complex project. It was not agreed upon for Independent to submit their entire second phase. Marks are ongoing will try and stay ahead. Independent is still working on their first phase.”</p> <p>“The 2nd list is a new list of current one call tickets called in by Independent Enterprises with no complex project meeting as well all in the same locator’s area that will receive an “092” Karl Code, but once again, he will contact Shane to determine where they plan on starting and begin marking to try and avoid a damaged facility. This is daily with Independent Enterprises.”</p> <p>Independent Enterprises Inc stated, “While digging in the sidewalk for a scheduled private service line replacement an unmarked gas service line was hit and damaged with the excavator bucket at a depth of 3.75’ The damaged gas service line was identified as the gas service line for 1926 Jane Street and is owned by Peoples Gas Company. The damage occurred on the Northern side of Jane Street near 1927 Jane Street at the sidewalk location at 8:45am. Independent foreman Doug notified 911 as well as Peoples Gas. Pittsburgh Fire Department arrived at 8:55am and Peoples Gas arrived at 9:00 am. The repair was completed at 10:00am and IEI was cleared to continue work on 1927 Jane Street.”</p> <p>On Wednesday, March 26, 2025, Alleged Violation Reports (AVR) were requested from Pittsburgh Water and Sewer Authority (PWSA), the project owner, and Whitman Requardt and Associates LLP (WRA), the designer.</p> <p>PWSA stated in an email, in response to the AVR request, “This was stuck in our CM’s out box to us because of the file size. Therefore, we never received the information to file.”</p> <p>PWSA submitted their AVR on 3/28/2025 and stated, “While digging in the sidewalk for a scheduled private service line replacement an unmarked gas service line was hit and damaged with the excavator bucket at a depth of 3.75’ The damaged gas service line was identified as the gas service line for 1926 Jane Street and is owned by Peoples Gas Company. The damage occurred on the Northern side of Jane Street near 1927 Jane Street at the sidewalk location at 8:45am. Independent foreman Doug notified 911 as well as Peoples Gas. Pittsburgh Fire Department arrived at 8:55am and Peoples Gas arrived at 9:00 am. The repair was completed at 10:00am and IEI was cleared to continue work on 1927 Jane Street.”</p> <p>WRA responded by email and stated, “WRA is working on a water main replacement project with Pittsburgh Water. This incident occurred outside of our project area. Our project area for PA One Call ticket number 20242123359 is attached. The red pin represents the referenced gas line strike, while our project area is within the black box. Additionally, we are still in the</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>design phase of this project, so no work or excavation has occurred thus far.”</p> <p>20250211214- Routine ticket placed on 1/21/2025, with a duration of 6 months. Peoples Gas requested a meeting on 1/31/2025, and Field Marked on 2/7/2025.</p> <p>No requests were made by the excavator for marking unmarked lines or for refreshing old marks. The provided photos show the damaged and repaired line, and mark outs.</p> <p>Peoples Gas explaining provided photos: “Attached photos from Google Earth of the area, more pictures of the damage, and pictures from the locator’s mark out. Google picture #1 show the addresses circled in black, 1925 and 1927. Also circled in black is the damaged porch. This is important because in locate picture #4, you can see the same damaged porch with this sidewalk pad dug out already by Independent Enterprises. This is the same excavation that the damaged service line for 1926 Jane St. occurred in. And Independent Enterprises did not backfill the hole, they only covered it with plywood as shown in the other locate photos attached. And the damage occurred only 12 inches from the 6” plastic gas main line in the sidewalk as well. The locator could not “tee” the service line because Independent Enterprises had the sidewalk pad already excavated, along with other sidewalk pads as shown in the photos. And just a reminder, Independent Enterprises did not follow the agreed upon schedule at the complex project meeting. I have attached the notes by the PNG locator that was written on ticket 20250211214.”</p> <p>Violations:</p> <p>*Independent Enterprises Inc is in violation of sections: 5(3) – Excavator failed to preserve mark-outs or request a remark. 5(3) – In a complex project, Excavator failed to meet with facility owner upon facility owner’s request. 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. Recommendation: PUC Compliance Education Required and Penalties Applied</p> <p>*Pittsburgh Water and Sewer Authority is in violation of section: 6.1(3) – Released a project to bid or construction before final design was complete. Recommendation: PUC Compliance Education Required and Penalty Applied</p>	
52872	Facility Owner: Scranton City Contractor/Excavator: PIONEER	On 2/17/2025 10:30:00 AM at PITTSTON AVE, SCRANTON CITY, LACKAWANNA Removed Lackawanna County's violation and penalty *****	Scranton City: \$1,250.00 Section 2(1)(ii)(A) 1st Offense \$250.00

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>CONSTRUCTION CO INC Project Owner: PENNSYLVANIA AMERICAN WATER Other: Lackawanna County Other: Verizon, PA LLC</p>	<p>The incident occurred on Monday, February 17, 2025, on Pittston Avenue, in Scranton City, Lackawanna County.</p> <p>A traffic loop conduit line was damaged, and photos of the damage are provided.</p> <p>PA American Water Company (PAWC), the project owner stated in their Alleged Violation Report (AVR), “Pioneer Construction Company was doing an emergency repair on a collapsed storm basin that belongs to us, while excavating they hit an unmarked traffic loop conduit.”</p> <p>Pioneer Construction stated in their AVR, the crew was removing blacktop to install a new inlet where the existing one was creating a road hazard. The Operator struck an unmarked conduit. Promptly after the traffic lights started flashing caution. After reviewing the ICall ticket, City of Scranton was NOT on the ticket for having facilities in the area. These unmarked lines belong to them and control the lights. Damage to the conduit line. This incident happened at approximately 10:30 am, witnesses included operators, laborers and Supervision, and Josh called Safety Director Larissa, who then called 811 and notified City of Scranton. Yes, all proper safety gear was being followed. Pioneer had a legal one call in place to be digging, Excavation Emergency ticket, 20250480109, damage ticket, 20250480865. The root cause is the City of Scranton having many updates to their traffic lights and not getting them mapped with Pa ICall. After this incident I reached out to Maria White, and she is helping them get everything updated.</p> <p>Scranton City and Lackawanna County did not get notified when the Emergency Tickets were placed because they are showing no facilities in the area- 20250450102, 20250480109 and 20250480865.</p> <p>PA One Call Compliance commented in an email- Scranton City are a member of One Call. Lackawanna County are Not a member of One Call, but did receive a prospective member package in May 2024.</p> <p>20250480865- Damage Emergency ticket placed on 2/17/2025. Response: Verizon PA LLC responded on 2/18/2025 as -INSUFF INFO DO NOT DIG. They did not finalize ticket with “Clear No Facilities” or “Field Marked”.</p> <p>Violations:</p> <p>*Scranton City is in violation of sections: 2(1)(ii)(A) – Failed to provide the One Call System with the counties, municipalities, and wards in which it lines are located. 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility</p>	<p>Section 2(10) 1st Offense \$1,000.00</p> <p>Lackawanna County: \$0.00</p> <p>Verizon, PA LLC: \$2,500.00 Section 2(5)(vii) Subsequent \$2,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>owner's lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: PUC Compliance Education Required and Penalties Applied</p> <p>*Lackawanna County is in violation of sections: 2(1) – Facility owner is not a member of One Call. Recommendation: PUC Compliance Education Required and Penalty Applied</p> <p>*Verizon PA LLC is in violation of section: 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20250480865 Recommendation: Penalty Applied</p>	
53947	<p>Facility Owner: PHILADELPHIA CITY WATER DEPARTMENT Contractor/Excavator: Just Plumbing and Heating</p>	<p>On 2/18/2025 9:45:00 AM at 1605 S 12TH ST, PHILADELPHIA CITY, PHILADELPHIA The Near Miss event occurred on Tuesday, February 18, 2025, at 1605 S. 12th Street, in Philadelphia City, Philadelphia County.</p> <p>There was a Near Miss of the Philadelphia Water Department's (PWD) sewer line. There are no tickets associated with this event.</p> <p>PWD explained in their alleged violation report, on "2/13/25: Terrance Gullette paid for and was issued a sewer later repair permit at 1605 S 12TH ST. 2/18/25: PWD Customer Service received a call reporting a broken sewer main; PWD arrived onsite to discover an abandoned plumber's ditch in the street directly across from 1605 S 12TH ST adjacent and above PWD's sewer. The ditch was left uncovered and unsafe with a pile of soil blocking the sidewalk of the east of the block.PWD covered the ditch and cordon off with cones." "Over the following days/weeks, these protection measures were repeatedly moved and removed by unknown members of the public accordingly to multiple public complaints - Photos Attached." "In addition to not submitting a 1CALL request for this excavation, the plumber also violated the conditions of his sewer lateral repair permit with PWD. The plumber was required to schedule an inspection with PWD to oversee their work, but that did not occur." "Over the past few weeks, PWD has been in contact with Mr. Gullette informing him that he must address this situation and make this location safe. On 3/11/25, the Plumber contacted PWD to schedule an inspection for 3/19/25. On 3/19/25, the Plumber claimed that they were unable to make the lateral repair due to a sewer collapse. PWD reinspected this location on 3/19/25 the ditch open with the boards covering it - Photos attached." "On 3/26/25, PWD reinspected to find the ditch had been backfilled (presumably by the plumber) - Photos attached." "On 4/2/25, the plumber contacted PWD to schedule an inspection for 4/15/25."</p>	<p>Just Plumbing and Heating: \$1,000.00 Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>On 4/8/25, an email was sent to PWD asking, was there an actual damage caused by the plumber, or only a line needing repaired by the plumber, or both? PWD replied, "That is still TBD because the plumber has not returned to complete their work. The primary reason for my AVR was the fact that the plumber did not place a 1CALL with POCS. The "near miss" was referring to our facilities, as well as the significant public, health, and safety risk posed by the large open ditch left in the middle of a busy residential block in South Philadelphia."</p> <p>Violations:</p> <p>*Just Plumbing and Heating is in violation of section: 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking or damaging a facility owner's line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.</p> <p>Recommendation: PUC Compliance Education Required and Penalty Applied to 5(2.1) and for 5(16) zero penalty but keep the violation.</p>	
53056	<p>Facility Owner: PECO Contractor/Excavator: DAVID JATNIEL LLC Project Owner: Verizon Designer: Verizon</p>	<p><u>On 2/19/2025 12:00:00 PM at JEFFERSON CT, BENSALEM TWP, BUCKS</u> Incident occurred on February 19th, 2025, at 12pm along Jefferson Court, Bensalem Township, Bucks County.</p> <p>A gas line was damaged.</p> <p>PECO's Alleged Violation Report (AVR) states, "CONTRACTOR WORKING FOR VERIZON TO INSTALL CABLE AND CONDUIT DAMAGED THE 2" PX GAS MAIN. LOCATOR MARKS DESTROYED." AVR notes that 911 was notified.</p> <p>David Jatniel, LLC and Verizon have not submitted AVRs of 4/21/25.</p> <p>Pictures from PECO show that the line was accurately marked.</p> <p>Violations:</p> <p>David Jatniel, LLC Section 5(11.2) – When using trenchless technology, Excavator failed to utilize at a minimum, the best practices published by the Common Ground Alliance. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required.</p> <p>Verizon Section 4(2) – Designer failed to request the line and facility information prescribed by section 2(4) from the One Call System not less than ten nor more than ninety</p>	<p>DAVID JATNIEL LLC: \$1,500.00 Section 5(11.2) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>Verizon: \$6,500.00 Section 4(2) Subsequent \$2,000.00</p> <p>Section 6.1(3) Subsequent \$2,000.00</p> <p>Section 6.1(7) Subsequent \$2,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>business days before final design is to be completed. PUC compliance education is required.</p> <p>Section 6.1(3) – Released a project to bid or construction before final design was complete. PUC compliance education is required.</p> <p>Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. PUC compliance education is required.</p>	
53000	<p>Facility Owner: Sharpsville Borough-Water Department</p> <p>Contractor/Excavator: S and S FIBER OPTICS</p> <p>Project Owner: A D B COMPANIES</p> <p>Designer: A D B COMPANIES</p> <p>Other: Zito Media LP</p>	<p><u>On 2/21/2025 6:15:00 PM at 133 Pierce Ave., SHARPSVILLE BORO, MERCER</u> The incident occurred on Friday, February 21, 2025, at 133 Pierce Avenue, in Sharpsville Borough, Mercer County.</p> <p>A water line was damaged.</p> <p>ADB Companies, the project owner and designer, stated in their Alleged Violation Report (AVR) that the locate marks were correct and S and S Fiber Optics were aware of the water line's location. The service line was accidentally snagged by mini excavator while digging near the water line. The damaged water service line was too close to the mainline for the S and S Fiber Optics to repair themselves, so 811 Sharpsville Borough Water Department were notified.</p> <p>ADB Companies provided photos of the damage.</p> <p>S and S Fiber Optics, and Sharpsville City Water Department did not submit their AVR's. S and S Fiber Optics AVR was due within 30 days of striking a line, and Sharpsville City Water Department was due within 30 business days after receipt of notice of a facility line damage.</p> <p>20250302068- Final Design ticket 1/30/2025. No Response from- Zito Media Communications</p> <p>Violations:</p> <p>*S and S Fiber Optics is in violation of sections: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: PUC Compliance Education Required and Penalties Applied</p> <p>*Sharpsville City Water Department is in violation of section: 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner's lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: PUC Compliance Education Required and Penalty Applied</p> <p>*Zito Media Communications is in violation of section: 2(4) – Failed to respond to designer's request for information within 10 business days. 20250302068</p>	<p>Sharpsville Borough-Water Department: \$1,000.00 Section 2(10) 1st Offense \$1,000.00</p> <p>S and S FIBER OPTICS: \$1,500.00 Section 5(4) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>Zito Media LP: \$250.00 Section 2(4) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
53054	<p>Facility Owner: Peoples Gas Company</p> <p>Contractor/Excavator: Pennsylvania American Water Company (PAWC)</p> <p>Project Owner: (PAWC)</p> <p>Other: Pittsburgh Department of Mobility and Infrastructure</p>	<p>Recommendation: PUC Compliance Education Required and Penalty Applied</p> <p><u>On 2/22/2025 9:30:00 AM at 801 GALLION AVE, PITTSBURGH CITY, ALLEGHENY</u> Peoples agrees. ***</p> <p>Incident occurred on February 22nd, 2025, at 9:30am at 801 Gallion Avenue, Pittsburgh City, Allegheny County.</p> <p>Two gas line strikes happened. The first line strike was the lateral from the curb stop to the residence of 801. The second line strike was between the curb stop and the main on the opposite side of the street.</p> <p>Peoples Gas Company's Alleged Violation Report (AVR) states, "PENNSYLVANIA AMERICAN WATER working on an emergency ticket struck and damaged an improperly marked Peoples Gas service line. Upon arrival, Peoples Gas employees noted that the line was damaged in two separate areas. There was initial damage that in the grass area near the water curb box. As shown in the attached pictures, there is damage to the line in the grass. There is also damage to the line in the street. Based on where the PENNSYLVANIA AMERICAN WATER equipment is parked over the damage in the street, the line in the grass was struck first and PENNSYLVANIA AMERICAN WATER then did not call in that damage or a renotify about exposed unknown or damage unknown. The damage in the street could possibly have been prevented had PENNSYLVANIA AMERICAN WATER called in when the line in the grass was exposed."</p> <p>Pennsylvania American Water Company (PAWC) AVR states, "Pa American crew while digging to replace a water service hit and damaged a People's Gas service. The damage occurred approximately 15' from where the line was marked." 911 was called.</p> <p>Pictures from Peoples Gas Company show the initial line was damaged prior to the excavation equipment being moved. Excavation was not stopped and 911 was not notified until the second damage occurred.</p> <p>Violations:</p> <p>PAWC</p> <p>Section 5(7) – Failed to immediately report to the facility owner any break or leak in its lines, or any dent, gouge, groove, or other damage to such lines or to their coating or cathodic protection. PUC compliance education is required.</p> <p>Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid. PUC compliance education is required.</p> <p>Peoples</p> <p>Section 2(5)(i.1) – Failed to locate an actually known facility's point of connection to its facilities. PUC compliance education is required.</p>	<p>Peoples Gas Company: \$250.00</p> <p>Section 2(5)(i.1) 1st Offense \$250.00</p> <p>Pennsylvania American Water Company (PAWC): \$2,000.00</p> <p>Section 5(7) 1st Offense \$1,000.00</p> <p>Section 5(8) 1st Offense \$1,000.00</p> <p>Pittsburgh Department of Mobility and Infrastructure: \$2,000.00</p> <p>Section 2(5)(vii) 1st Offense \$1,000.00</p> <p>Section 2(5)(vii) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. PUC compliance education is required. Removed.</p> <p>Pittsburgh Department of Mobility and Infrastructure Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20250530024. PUC compliance education is required. Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20250530085. PUC compliance education is required.</p>	
53042	<p>Facility Owner: UGI Utilities Inc Contractor/Excavator: HENKELS AND MCCOY Project Owner: UGI Utilities Other: Astound Broadband Powered By RCN</p>	<p><u>On 2/24/2025 10:30:00 AM at 407 BATH AVE, CATASAUQUA BORO, LEHIGH</u> The incident occurred on Monday, February 24, 2025, at 407 Bath Avenue, in Catasauqua Borough, Lehigh County.</p> <p>UGI Utilities gas line was damaged.</p> <p>UGI stated in their alleged violation report (AVR) that Henkels was digging to install a new gas mainline and when doing so they struck an unmarked gas service facility creating a damage and a leak. Incorrect records on UGI mapping and records. Henkels and McCoy stated in their AVR that while trenching to install plastic 6" mainline an unmarked gas service line was damaged. Maps and Records issue of UGI.</p> <p>20241932618- Final Design ticket placed on 7/11/2024. Response from- Astound Broadband Powered By RCN- responded as CONFLICT DCTF BY FO they did not finalize a response. 20241001897- Final Design ticket placed on 4/9/2024. Response from- Astound Broadband Powered By RCN- responded as CONFLICT DCTF BY FO they did not finalize a response.</p> <p>Violations:</p> <p>*UGI Utilities is in violation of section: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: Penalty Applied</p> <p>*Astound Broadband Powered By RCN is in violation of sections: 2(4) – Failed to respond to designer’s request for information within 10 business days. 20241932618 2(4) – Failed to respond to designer’s request for information within 10 business days. 20241001897 Recommendation: PUC Compliance Education Required and Penalties Applied</p>	<p>UGI Utilities Inc: \$2,000.00 Section 2(5)(i) Subsequent \$2,000.00</p> <p>Astound Broadband Powered By RCN: \$500.00 Section 2(4) 1st Offense \$250.00 Section 2(4) 1st Offense \$250.00</p>
52981	<p>Facility Owner: Comcast Contractor/Excavator: GOLDEN TRIANGLE CONSTRUCTION Project Owner: PENNSYLVANIA AMERICAN WATER</p>	<p><u>On 2/24/2025 10:40:00 AM at HIDDEN VALLEY ROAD, PETERS TWP, WASHINGTON</u> Incident occurred on February 24th, 2025, at 10:40am along Hidden Valley Road, Peters Township, Washington County.</p> <p>A telecom line was damaged.</p>	<p>Comcast: \$2,500.00 Section 2(5)(i) 2nd Offense \$1,000.00</p> <p>Section 2(10) 2nd Offense \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Golden Triangle Construction's Alleged Violation Report (AVR) states, "GTC was beginning excavation on Hidden Valley Road for a 8-inch water main in front of a water vault. GTC started excavation at 7AM. At 10:40AM, GTC pulled a black, plastic coated cable that ran perpendicular to our trench in front of the vault. The cable was about 3/4" diameter, 2.5FT deep. There was no markings, indication, or evidence of a telecom line crossing the the trench. GTC called Verizon first since they attended the Complex meeting and Verizon sent a representative and confirmed the cable was not theirs, but it was Comcasts. Comcast had marked "Clear" on their response and did not attend the complex meeting. GTC contacted Comcast and Comcast sent a representative confirming the line was theirs and it was damaged needing replacement. Comcast set a temporary line to provide Valley Brook Country Club with cable and internet. Comcast returned on 2/25/2025 to install a permanent repaired cable."</p> <p>GTC's pictures show that a telecom line was marked out on the opposite side of the road.</p> <p>PAWC's AVR states, "GTC was beginning excavation on Hidden Valley Road for a 8-inchwater main in front of a water vault. GTC started excavation at 7AM. At 10:40AM, GTC pulled a black, plastic coated cable that ran perpendicular to our trench in front of the vault. The cable was about 3/4" diameter, 2.5FT deep. There was no markings, indication, or evidence of a telecom line crossing the the trench. GTC called Verizon first since they attended the Complex meeting and Verizon sent a representative and confirmed the cable was not theirs, but it was Comcast. Comcast had marked "Clear" on their response and did not attend the complex meeting. GTC contacted Comcast and Comcast sent a representative confirming the line was theirs and it was damaged needing replacement. Comcast set a temporary line to provide Valley Brook Country Club with cable and Internet. Comcast returned on 2/25/2025 to install a permanent repaired cable."</p> <p>No AVR has been submitted by Comcast as of 4/18/25. Comcast responded Clear no facilities to ticket 20250451232.</p> <p>Violations:</p> <p>Comcast Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. PUC compliance education is required. Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. PUC compliance education is required.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
53033	<p>Facility Owner: Sharpsville Borough-Water Department Contractor/Excavator: S and S Fiber Optics Project Owner: A D B COMPANIES Designer: A D B COMPANIES</p>	<p><u>On 2/25/2025 6:30:00 PM at 466 S Mercer Ave. SHARPSVILLE BORO, MERCER</u> The incident occurred on Tuesday, February 25, 2025, at 466 S. Mercer Avenue, in Sharpsville Borough, Mercer County. A water line was damaged.</p> <p>ADB Companies, the project owner and designer, stated in their Alleged Violation Report (AVR) that the “Water line was marked accurately by the water dept., but was hit by contractor due to lack of proper potholing prior to drilling. The damage was caused around 6:30pm, 2-25-25. Temporary repair was conducted by the city of Sharpsville shortly after on the same night to restore service to the homeowner. Final repairs were completed the following morning, on 2-26-25.”</p> <p>ADB Companies provided photos of the work area and locate marks</p> <p>S and S Fiber Optics, and Sharpsville City Water Department did not submit their AVR’s. S and S Fiber Optics AVR was due within 30 days of striking a line, and Sharpsville City Water Department was due within 30 business days after receipt of notice of a facility line damage.</p> <p>Violations:</p> <p>*S and S Fiber Optics is in violation of sections: 5(11.2) – When using trenchless technology, Excavator failed to utilize at a minimum, the best practices published by the Common Ground Alliance. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: PUC Compliance Education Required and Penalties Applied</p> <p>*Sharpsville City Water Department is in violation of section: 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: PUC Compliance Education Required and Penalty Applied</p>	<p>Sharpsville Borough-Water Department: \$1,000.00 Section 2(10) 1st Offense \$1,000.00</p> <p>S and S Fiber Optics: \$1,500.00 Section 5(11.2) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>
53162	<p>Facility Owner: Columbia Gas Contractor/Excavator: Golden Triangle Construction Co Project Owner: QES Other: Comcast Other: GANNETT FLEMING Other: PennDOT Other: Rostraver Township</p>	<p><u>On 2/27/2025 9:00:00 AM at 4263 SR 51, ROSTRAVER TWP, WESTMORELAND</u> Comcast accepts.</p> <p>*****</p> <p>The incident occurred on 02/27/2025, on 4263 State Route 51, in Rostraver Township, Westmoreland County.</p> <p>A gas line owned by Columbia Gas was damaged.</p> <p>Columbia Gas, the facility owner. submitted an Alleged Violation Report (AVR). Their AVR states, “Golden</p>	<p>Golden Triangle Construction Co: \$2,500.00 Section 5(16) 1st Offense \$1,000.00</p> <p>Section 5(4) 1st Offense \$500.00</p> <p>Section 1.1 1st Offense \$1,000.00</p> <p>Comcast: \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Triangle Construction was digging as part of a roadway widening project when they struck and damaged an accurately marked 1" plastic gas service feeding 4263 SR 51, Belle Vernon. They notified 911 and Columbia Gas when the damage occurred. Columbia Gas responded immediately to make the area safe and complete repairs. Golden Triangle Construction is working on a large project to widen the roads in this area. They placed a new ticket for the area on 02/26/2025 with a response due date of 02/28/2025 and a lawful start date of 03/03/2025 because they removed portions of the roadway that had locate marks on it. They did not wait for the marks to be completed and proceeded to dig before their lawful start date. Marks were present and accurate on the untouched portion of roadway at the time of damage from their most recent ticket in the area; routine ticket # 20243471107." They also noted on their AVR, "Golden Triangle Construction placed routine ticket # 20250570920 on 02/26/2025 with a response due date of 02/28/2025 and a lawful start date of 03/03/2025. The damage occurred on 02/27/2025. Marks were present and accurate on the untouched portion of roadway at the time of damage from their most recent ticket in the area; routine ticket # 20243471107." Photos were submitted.</p> <p>Golden Triangle Construction Co. is the excavator. An AVR has not been filed as of 04/22/2025.</p> <p>QES the project owner, submitted an AVR. Their AVR states, " One Call unknowingly marked an existing abandoned line and Golden Triangle unknowingly located said line by hydro-demolition. During excavation the real in use line was hit and broken." Their AVR noted that they are submitting it on behalf of PennDOT.</p> <p>PennDOT: QES submitted an AVR on behalf of PennDOT.</p> <p>Gannett Fleming, the designer, submitted an AVR. Their AVR states, "On 3/13/2025, PennDOT construction field staff contacted Gannett Fleming (Designer) to notify us that a 1" plastic gas service line was hit during excavation for a drainage pipe along SR 51. Gannett Fleming is unaware of the date and time that the pipe was struck. We were told that the gas company is coming out today (3/14) or Monday (3/17) to lower the service line for the drainage pipe run installation to continue."</p> <p>Routine ticket 20243471107 location of work was listed as 51 south bound. Starting at Finley Road, going south to Ridge Road. Work includes grading and drainage. Lawful Start Dates--[17-Dec-24]</p> <p>Routine ticket 20250570920 location of work was listed as SR51 south bound starting at Ridge Road and going to the Finley/981 intersection. Lawful Start Dates--[03-Mar-25]</p>	<p>Section 2(5)(v) Subsequent \$2,000.00</p> <p>Rostraver Township: \$250.00 Section 2(5)(v) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Faded, but visible yellow locate line can be seen in the photos. The damage occurred within the tolerance zone. The lawful start date for the ticket that covered this location was 03/03/2025. The damage occurred on 02/27/2025, prior to the lawful start date.</p> <p>Routine ticket 20250561238 had a response due date of 02/27/2025. Rostraver Township did not respond until 03/03/2025. Comcast did not respond to this ticket.</p> <p>Violations:</p> <p>Golden Triangle Construction Co. – - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. - Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. - Section 1.1 – Excavator did not begin within legal timeframe. Ticket 20250570920. Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Rostraver Township – - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20250561238. Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Comcast – - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket 20250561238. Recommendation: The penalty is applied.</p>	
53165	<p>Facility Owner: Columbia Gas of PA - East</p> <p>Contractor/Excavator: E. K. Services, Inc.</p> <p>Project Owner: MANCHESTER TOWNSHIP</p> <p>Other: Zayo Bandwidth</p>	<p><u>On 2/28/2025 2:35:00 PM at 3289 N SUSQUEHANNA TRAIL, MANCHESTER TWP, YORK</u> The incident occurred on 02/28/2025 at 2:35 PM, at 3289 North Susquehanna Trail, in Manchester Township, York County.</p> <p>A gas line owned by Columbia Gas was damaged. 911 was called.</p> <p>Columbia Gas, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “EK Services was installing a sewer main on N Susquehanna Tr., York. During the process of backfilling their ditch line, they used a hydraulic plate tamper attachment on their backhoe to create a flat bench in the ditch next to the exposed 1” plastic gas service feeding 3289 N Susquehanna Tr., York. While the tamper was being pulled out of the ditch in an upward motion, a corner of the machine caught the exposed gas service and ripped it in half. EK Services notified 911 and 811 when the damage occurred. 911 notified Columbia Gas, and Columbia Gas responded immediately to make the area safe and complete repairs. The locate marks were</p>	<p>E. K. Services, Inc.: \$500.00 Section 5(4) 1st Offense \$500.00</p> <p>MANCHESTER TOWNSHIP: \$1,000.00 Section 6.1(7) 1st Offense \$1,000.00</p> <p>Zayo Bandwidth: \$1,000.00 Section 2(5)(vii) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>accurate, and the gas service was exposed at the time of the damage.” Photos were submitted.</p> <p>E. K. Services, Inc., the excavator, submitted an AVR. Their AVR states, “Crew was working to backfill and compact the area after placing sewer main. While compacting the area the operator lost site of the utility and went to stop and pull out of the location, while trying to remove the equipment didn't realize it was within the tolerance zone and pulled back pulling against the utility and breaking the line. Crew was coached on proper procedures to ensure that there is not a repeat of the matter.”</p> <p>Manchester Township is the project owner. An AVR has not been filed as of 04/19/2025.</p> <p>Yellow locate lines can be seen in the submitted photos. Damage occurred within the tolerance zone.</p> <p>Emergency ticket 20250592845 was requested on 02/28/2025. Zayo Bandwidth did not respond until 03/03/2025.</p> <p>Violations:</p> <p>Manchester Township – - Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Zayo Bandwidth – - Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket 20250592845. Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>E. K. Services, Inc. – - Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
53821	<p>Facility Owner: PECO AN EXELON COMPANY Contractor/Excavator: McClain Bros.</p>	<p><u>On 2/28/2025 7:00:00 PM at 535 PRINCESS AVE, BRISTOL BORO, BUCKS</u> The incident occurred on Friday, February 28, 2025, 535 Princess Avenue, in Bristol Township, Bucks County.</p> <p>PECO an Exelon Company gas line was damaged. There are no tickets associated with this incident.</p> <p>PECO stated in their alleged violation report (AVR), during USIC investigation it was found that McClain Bros. was excavating with mechanized equipment to remove trees and grading when they damaged the unmarked 1/2" plastic gas service line. McClain Bros. did not have a locate request to be excavating, which resulted in the 1/2" plastic service being damaged and needed repair.</p>	<p>McClain Bros.: \$2,000.00 Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>PECO provided photos with an investigation report, and PECO noted that 911 was called.</p> <p>McClain Bros. did not submit an AVR within 30 days of striking a line.</p> <p>Violations:</p> <p>*McClain Bros. is in violation of sections: 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: PUC Compliance Education Required and Penalties Applied</p>	
53126	<p>Facility Owner: PITTSBURGH WATER AND SEWER AUTHORITY (PWSA)</p> <p>Contractor/Excavator: A. Folino Construction, Inc.</p> <p>Project Owner: PITTSBURGH WATER AND SEWER AUTHORITY (PWSA) - Spacesaver</p> <p>Other: VERIZON PA LLC</p>	<p>On 3/3/2025 9:00:00 AM at BUENA VISTA ST, PITTSBURGH CITY, ALLEGHENY DPI Maki has withdrawn violations that were cited to PWSA and A. Folino. After the case was completed, more information was received. The information in case 53126 is related to a case that is with the PUC legal department. Cases connected by tickets: 50944, 51995, 53218, 23282, and 53459.</p> <p>Pittsburgh Water disagreed. Pittsburgh Water would like reconsideration of Violation 2 (5) (i) for not locating lines within 18 inches horizontally of the outside wall of line. All of Pittsburgh Water’s underground utilities were appropriately marked in the relevant area on 2/21/2025 – prior to the 2/24/2025 deadline. The photos of those utility markings are attached here. An AVR was never filed on this issue by Pittsburgh Water because (1) Pittsburgh Water was never made aware of any issue with the utility locating in this location, and (2) there were no assets damaged in this location. On 5/09/2025 Damage Prevention Investigator Maki responded: "I Have marked PGH Water as disagreeing. Thank you for the pictures. I have attached them to case 53126. There was snow on the ground when PWSA marked out the main lines. The snow melted. On 4/01/2025 A Folino sent in pictures with no main lines marked and that “A Folino did not request any renotify tickets through PA One Call. Since PWSA is the facility and project owner for this project, Folino brought the issue to PWSA and Construction Management Teams attention. During this time in the project, PWSA’s 3rd party line locating company had recently cut ties with the Authority. PWSA then directed Folino to locate any unmarked facilities using contract items(U-5 Exploratory Excavation). Folino did comply with this direction to locate any mismarked or unmarked lines as it was within the Project Owner’s rights to direct such work. However, Folino did not agree with the method of payment and believed that PennDOT Pub 408 Force Account was the correct form of payment for such a scope. This was the start of disagreements between Folino and PWSA and resulted in the sveral letters being exchanged that were included in the first email”.</p>	<p>PITTSBURGH WATER AND SEWER AUTHORITY (PWSA): \$0.00</p> <p>A. Folino Construction, Inc.: \$0.00</p> <p>VERIZON PA LLC: \$500.00 Section 2(5)(v) 2nd offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>A Folino disagreed. Folino did not request any renotify tickets through PA One Call. Since PWSA is the facility and project owner for this project, Folino brought the issue to PWSA and Construction Management Teams attention. During this time in the project, PWSA’s 3rd party line locating company had recently cut ties with the Authority. PWSA then directed Folino to locate any unmarked facilities using contract items(U-5 Exploratory Excavation). Folino did comply with this direction to locate any mismarked or unmarked lines as it was within the Project Owner’s rights to direct such work. However, Folino did not agree with the method of payment and believed that PennDOT Pub 408 Force Account was the correct form of payment for such a scope. This was the start of disagreements between Folino and PWSA and resulted in the serval letters being exchanged that were included in the first email. A Folino submitted a bill to PWSA for the work that they were asked to do locating underground utility lines. See attachment named " A Folino is asked to locate PWSA lines". The violation section 5(20) is withdrawn.</p> <p>*****</p> <p>The incident occurred on 3/03/2025 at BUENA VISTA ST in Pittsburgh City in Allegheny County. *No damage Sewer lines were not marked.</p> <p>A FOLINO CONSTRUCTION stated in their Alleged Violation Report (AVR) that “A. Folino Construction was preparing for a water service line replacement when we noticed PWSA's failure to properly mark their utility's. We could not proceed with work because PWSA did not mark their main sewer line. They also only provided one faint mark for their main water line, no other marks to indicate where it goes. The curb box for the water service line was marked, but no other marks to indicate where that goes either, or where it ties in with the main water line”. Report and pictures were provided.</p> <p>PITTSBURGH WATER AND SEWER AUTHORITY AVR was due by 3/26/2025. On 4/03/2025, DPI Maki sent an email to Joe and BJ stating that I have not received an AVR for multiple locations. The case numbers and locations were listed. No AVR has been submitted to date.</p> <p>*****</p> <p>*Ticket 20250512326 was submitted by A Folino on 2/20/2025 with a response due by 2/24/2025. Verizon did not respond “clear” until 2/27/2025, ****</p> <p>VIOLATIONS PITTSBURGH WATER AND SEWER AUTHORITY is in violation of: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. This is a third time offense. Recommendation: The penalty is applied. Facility owner education is required.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>A Folino Construction, Inc. Section 5(20) – Excavator failed to renotify One Call of an unmarked or incorrectly marked facility upon arrival at a work site.</p>	
53247	<p>Facility Owner: Shentel Communications LLC. Contractor/Excavator: EM Utility Contractors Project Owner: PPL Electric</p>	<p><u>On 3/4/2025 10:30:00 AM at 603 NORTHLAWN DR, EAST HEMPFIELD TWP, LANCASTER</u> The incident occurred on 03/04/2025 at 10:30 AM, at 603 Northlawn Drive, in East Hempfield Township, Lancaster County.</p> <p>A telecom line owned by Shentel Communications LLC. was damaged.</p> <p>Shentel Communications LLC., the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “The excavator was using a directional drill to do a street crossing. They hit the miss marked Glo Fiber conduit approx. 48" before the marks. Only the conduit was damaged, and the fiber was not damaged.” Photos were submitted.</p> <p>EM Utility Contractors is the excavator. An AVR has not been filed as of 04/23/2025.</p> <p>PPL Electric, the project owner, submitted an AVR. Their AVR states, "EM Utility Contractors was working for PPL and while installing a new electric line they damaged the conduit of the fiber line, the line was not marked, and the fiber itself was not damaged.”</p> <p>Violations:</p> <p>EM Utility Contractors - - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Shentel Communications LLC. - - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: The penalty is applied.</p>	<p>Shentel Communications LLC.: \$1,000.00 Section 2(5)(i) 2nd Offense \$1,000.00</p> <p>EM Utility Contractors: \$1,000.00 Section 5(16) 1st Offense \$1,000.00</p>
53185	<p>Facility Owner: PECO AN EXELON COMPANY Contractor/Excavator: JPC GROUP INC. Designer: PENNONI Other: DREXEL UNIVERSITY Other: HUNTER ROBERTS CONSTRUCTION GROUP</p>	<p><u>On 3/4/2025 12:00:00 PM at 33RD ST, PHILADELPHIA CITY, PHILADELPHIA</u> Drexel violation removed. Property was previously a soccer field but Drexel is not the owner of the building being constructed. *** Located JPC AVR submitted within 30 days and removed violation for 5(16). *** Incident occurred on March 4th, 2025, at 12pm along 33rd Street, Philadelphia City, Philadelphia County.</p> <p>An electric line was damaged.</p>	<p>JPC GROUP INC.: \$1,250.00 Section 5(4) 1st Offense \$500.00</p> <p>Section 5(6)(ii) 1st Offense \$500.00</p> <p>Section 9 1st Offense \$250.00</p> <p>DREXEL UNIVERSITY: \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>PECO's Alleged Violation Report (AVR) states, "JPC GROUP INC.UNCOVERED AN ACCURATELY MARKED TRANSMISSION LINE. CONTRACTOR INCORRECTLY DRILLED INTO THE LINE TO VERIFY IF IT WAS WATER OR GAS. J P C GROUP INC was excavating with an excavator to install Storm water lateral under ticket number 20250582092 it was found that while J P C GROUP INC was excavating to install Storm Sewer when they punctured the correctly marked Peco transmission line, it was found that J P C GROUP INC failed to expose the correctly marked electric resulting in the transmission main being punctured and in need of repair"</p> <p>PECO's pictures show that the electric conduit was accurately marked within the tolerance zone. See attachment: Damage_details.</p> <p>JPC Group Inc, Hunter Roberts Construction Group, and Drexel University were mailed and email a request for an AVR on 3/14/2025.</p> <p>JPC Group's AVR states, "After exposing the damaged line, the foreman mistook the electrical transmission line for a ductile iron water main. As noted above, the transmission line did not have the typical backfill or marking tape associated with electrical lines. The electrical conduit located above the transmission line was assumed to be the utility associated with the markings on the ground."</p> <p>JPC Email states that they used a powered hand drill to drill into the pipe. See attached email.</p> <p>Hunter Roberts Construction Group's AVR states, "Hunter Roberts Construction Group hired JPC Group, Inc. to provide site excavation and utility work. Between 5 and 5:30 pm on March 4th our superintendent was notified of a leak in a pipe at the bottom of a utility excavation. I investigated and noted oil was leaking. We suspected a transmission line was hit and JPC Group notified PECO immediately. On investigation there was a conduit exposed above the transmission line and JPC assumed this was the power line marked on the drawings. There was no mention on the civil design drawings that a high power transmission line was on our site. JPC sent photos with their report." AVR is noted as Other: Project Manager.</p> <p>Pennoni Associates' AVR states, "On April 3, 2025, Pennoni was informed by Braxton Cooper, PAPUC's damage prevention investigator, that PAPUC had received an AVR indicating that an underground utility line had been struck. PAPUC requested Pennoni to submit an AVR regarding the matter. Until that date, Pennoni was unaware of this incident, as it had not been communicated by any other involved parties. At this time, Pennoni does not have further details about the incident beyond those provided by PAPUC and as stated in the Hunter Roberts Construction Group AVR report</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>(AVR2025MAR280023), which Pennoni obtained after being notified by Braxton Cooper. In response to the question regarding whether the design serial number appeared on the plans or bid documents, the design serial number was included on the Pennoni prepared survey plan (attached) during the design process. However, it was inadvertently omitted from the final issued-for-construction plan set. The survey plan, which included the serial number, was shared as part of the project documentation but was not part of the drawing set Issued for Construction. What level of SUE was utilized on this project? Please justify the level of SUE used. A combination of C and D. Accurate records are kept and provided by city agencies and by the various utility owners, and these are matched to surface expressions documented on the land survey, which justifies this approach. When was the project released for bid? October 2022 What was the total estimated cost of this project? \$400M What was the total length of the project? 26 months (From start to anticipated finish) Did the excavator seek medical attention? No Do the contracts violate section 5.15 of Act 50/Act 127 of 2024? Pennoni was not in privity of contract with the excavator and, at this time, does not have knowledge of nor has it reviewed the excavator's contract with the project owner. Therefore, Pennoni cannot determine whether the contracts in question violate Section 5.15 of Act 50/Act 127 of 2024. We have no knowledge of and have never reviewed the contractors' contracts with the owner."</p> <p>No AVR was submitted by Drexel University as of 4/18/2025.</p> <p>Violations:</p> <p>JPC Group Inc Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. PUC compliance education is required. Section 5(6)(ii) – Excavator failed to provide support and mechanical protection for known facility owner's lines at the construction work site. PUC compliance education is required. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required. Removed. Section 9 – Failed to make best efforts to comply with Common Ground Alliance Best Practices. JPC is delinquent on PUC compliance education for case 34667 from October 2023. PUC compliance education is required.</p> <p>Drexel University Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Violation removed. Drexel no longer owns.</p>	
53268	Facility Owner: AQUA PENNSYLVANIA INC Contractor/Excavator:	<u>On 3/11/2025 10:00:00 AM at ORMOND AVE, UPPER DARBY TWP, DELAWARE</u> The incident occurred on	DELMONT UTILITIES COMPANY: \$500.00 Section 5(3) 1st Offense

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>DELMONT UTILITIES COMPANY Designer: BRANDYWINE CAD DESIGN INC Other: Upper Darby Township</p>	<p>Tuesday, March 11, 2025, on Ormand Avenue, in Upper Darby Township, Delaware County.</p> <p>Aqua PA Inc., the project owner, line was damaged.</p> <p>Delmont Utilities Company and Aqua stated in their alleged violation reports that Delmont was digging to install a water mainline, when a water service line was hit, that was on the mark. The mark was faded and was not seen prior to digging. Photos are provided showing the damage and no mark leading up to the service line.</p> <p>20250220053- Routine ticket placed on 1/22/2025, with a response due date of 1/24/2025. Late Response from- Upper Darby Township responded on 1/28/2025 as Field Marked.</p> <p>20250131968- Complex Project Meeting ticket 1/13/2025, meeting on 1/22/2025. No Response from- Upper Darby Township responded on 2/20/2025 as Will Attend Meeting.</p> <p>Violations:</p> <p>*Delmont Utilities Company is in violation of section: 5(3) – Excavator failed to preserve mark-outs or request a remark. Recommendation: PUC Compliance Education Required and Penalty Applied</p> <p>*Upper Darby Township is in violation of sections: 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. 20250220053 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20250131968 Recommendation: PUC Compliance Education Required and Penalties Applied</p>	<p>\$500.00</p> <p>Upper Darby Township: \$750.00 Section 2(5)(v) 1st Offense \$250.00</p> <p>Section 2(5)(viii) 1st Offense \$500.00</p>
53305	<p>Facility Owner: PEOPLES GAS COMPANY LLC Contractor/Excavator: WILSON EXCAVATING - LINDY COMPANY Project Owner: PENNSYLVANIA AMERICAN WATER</p>	<p><u>On 3/12/2025 9:43:00 AM at 214 MCCLELLAND ROAD, NORTH STRABANE TWP, WASHINGTON</u> The incident occurred on Wednesday, March 12, 2025, at 214 McClelland Road, in North Strabane Township, Washington County.</p> <p>A gas line was damaged.</p> <p>Wilson Excavating stated in their Alleged Violation Report (AVR) that they were performing work for PA American Water Company (PAWC) when a marked Peoples Gas line was struck and damaged. The crew was digging at 214 McClelland Road when they encountered a 1-inch plastic gas service line. The line was struck with the excavator inside the tolerance zone. The line was punctured and had a small hole. The foreman called 911 immediately and notified the facility owner as well.</p> <p>PAWC stated in their AVR that Wilson Excavating was installing a water service line, when a marked Peoples Gas line was struck and damaged. The 1-inch plastic gas</p>	<p>WILSON EXCAVATING - LINDY COMPANY: \$1,000.00 Section 5(4) 2nd Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>line was struck within the tolerance zone, and 911 was called and the facility owner was notified.</p> <p>Peoples Gas stated in their AVR and an email that Wilson Excavating was struck a Peoples Gas line while digging prudently with shovel. The shovel caused a pin hole in the service line. PNG crews were notified and arrived onsite for repairs.</p> <p>Photos were provided showing the damaged line.</p> <p>Violations: *Wilson Excavating is in violation of section: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: Penalty Applied</p>	
53333	<p>Facility Owner: Columbia Gas of PA - North</p> <p>Contractor/Excavator: MOON TOWNSHIP MUNICIPAL AUTHORITY</p> <p>Project Owner: MOON TOWNSHIP MUNICIPAL AUTHORITY</p>	<p><u>On 3/12/2025 1:30:00 PM at 3301 WARWICK CT, MOON TWP, ALLEGHENY</u> The incident occurred on Wednesday, March 12, 2025, at 3301 Warwick Court, in Moon Township, Allegheny County.</p> <p>A gas line was damaged.</p> <p>Moon Township Municipal Authority (MTMA) stated in their Alleged Violation Report (AVR) that they were shoveling prudently to locate the gas line, then using an excavator to remove spoils. The gas line was previously backfilled in rock during development. No sand or tape present. We were gently removing larger rocks from above the gas line with an excavator when the bucket slipped off a rock and damaged the gas line. Columbia Gas stated in their AVR that MTMA was digging on an emergency ticket to repair water main and services. While removing a rock from the excavation, they struck and damaged the accurately marked 2" plastic gas main with their backhoe. They notified 911 and Columbia Gas when the damage occurred. Columbia Gas responded immediately to make the area safe and complete repairs. Columbia Gas provided photos of the damaged line.</p> <p>Violations: *Moon Township Municipal Authority is in violation of sections: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. at the construction work site. Recommendation: PUC Compliance Education Required and Penalty Applied</p>	<p>MOON TOWNSHIP MUNICIPAL AUTHORITY: \$1,000.00 Section 5(4) 2nd Offense \$1,000.00</p>

Full Session

Case Number	Stakeholders	Summary	Violations & Recommendation
52425	<p>Facility Owner: Reserve Township</p> <p>Contractor/Excavator: Metarko Excavating LLC</p> <p>Project Owner: Amani</p>	<p><u>On 10/14/2024 6:00:00 PM at Haser Place Waterline, RESERVE TWP, ALLEGHENY</u> On 07/08/2025: The Damage Prevention Committee (DPC) voted to remove Metarko Excavating LLC's violations of 5(16) and 5(7) and the associated penalties.</p>	<p>Reserve Township: \$0.00 Section 2(5)(v) 1st Offense \$0.00</p> <p>Metarko Excavating</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>Development, LLC Designer: RED SWING GROUP Other: Verizon</p>	<p>***** Metarko Excavating LLC is disputing. They submitted multiple exhibits to support their dispute.</p> <p>Reserve Township submitted additional information. Upon review of the additional information, the violation and penalty were reduced to a warning.</p> <p>***** The incident occurred on approximately 10/14/2024, on Guyer Street, Reserve Township, Allegheny County. (Damage was discovered on 01/24/2025. Excavation in the area took place approximately 10/14/2025.)</p> <p>A sewer line owned by Reserve Township was damaged.</p> <p>Reserve Township, the facility owner, submitted two Alleged Violation Reports (AVRs).</p> <p>Their AVR (AVR2025JAN280033) states, “Developer was installing a new 8" water main to service a new development on Geyer Road. Excavator dug through the Reserve Township 8" VCP Sanitary main and installed the waterline about 6" below where the Sanitary had been. In doing so, they removed a 6-foot section of the Sanitary line. Nothing was reported and no AVR was filed. The Township only became aware when a nearby homeowner reported a sewage backup in their basement on 1/24/25. Upon excavation, Township Public Works discovered that the 6-foot section of Sanitary had been removed during the waterline installation. Pictures attached.” Photos were submitted.</p> <p>Their AVR (AVR2025MAR210015) states, “Resident at 3880 Mount Troy Road called a plumber to investigate a sewer backup in their basement. Plumber identified a complete blockage in the customer's lateral at the same location of the trench line excavated to install a new waterline by Metarko Excavating under contract to Amani Development to service a new housing plan. Attached email is from the plumber describing the situation to the developer. Developer is claiming it's not his responsibility because lateral was not marked. Damage to line was not reported at time of occurrence.” Photo was submitted.</p> <p>Metarko Excavating LLC is the excavator. An AVR has not been filed as of 04/02/2025.</p> <p>Amani Development LLC is the project owner. An AVR has not been filed as of 04/02/2025.</p> <p>A 6-foot section of the sanitary line was removed, causing sewage to back up into a homeowner’s basement on 01/24/2025. The missing section of the sanitary line was in the same location as the trench line excavated to install a new waterline by Metarko Excavating under contract to Amani Development.</p>	<p>LLC: \$0.00</p> <p>Amani Development, LLC: \$1,000.00 Section 6.1(7) 1st Offense \$1,000.00</p> <p>Verizon: \$250.00 Section 2(5)(v) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Routine ticket 20242843477 had a response due date of 10/15/2024. RESERVE TOWNSHIP did not respond to this ticket. Verizon responded 'Clear' on 10/16/2024 - Late response.</p> <p>Violations:</p> <p>RESERVE TOWNSHIP - - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket 20242843477. Warning.</p> <p>Verizon – - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20242843477. Recommendation: The penalty is applied.</p> <p>Metarko Excavating LLC – - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. [Withdrawn per DPC meeting] - Section 5(7) – Failed to immediately report to the facility owner any break or leak in its lines, or any dent, gouge, groove, or other damage to such lines or to their coating or cathodic protection. [Withdrawn per DPC meeting] Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Amani Development, LLC – - Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
52108	<p>Facility Owner: COMCAST</p> <p>Contractor/Excavator: BEST CHOICE PLUMBING</p> <p>Project Owner: BEN FRANKLIN IN HOME SERVICES</p> <p>Other: ASTOUND BROADBAND</p> <p>Other: PHILADELPHIA CITY DEPARTMENT OF STREETS</p> <p>Other: PHILADELPHIA CITY WATER DEPARTMENT</p> <p>Other: PHILADELPHIA GAS WORKS</p>	<p><u>On 11/27/2024 11:27:00 AM at 340 s 24th st, PHILADELPHIA CITY, PHILADELPHIA</u> On 7/08/2025 Phila Dept of Streets was not in attendance. The Damage Prevention Committee (DPC) voted to Keep the violation and penalty and to add education.</p> <p>On 5/21/2025 Phila Water sent in a disagreement and pictures of the mark out area. They stated that "Following up on our conversation yesterday regarding case 052108, I am providing the following information to support of dispute of this penalty. In response to 20243262394, PWD located all facilities on 11/25/24 as depicted in the attached photos, prior to the incident which occurred in the afternoon of 11/27/24. PWD concedes that we were late in responding to 20243322017. However, because PWD did locate our facilities and our facilities were not directly involved in the incident, we are requesting that the penalties be rescinded in favor of training. On 5/21/2025 DPI Maki emailed a response that the information has been added to the case and considered. There were no changes made and information of how to disagree after the DPC vote was detailed.</p> <p>*****</p>	<p>COMCAST: \$500.00 Section 2(5)(v) 2nd offense \$500.00</p> <p>BEST CHOICE PLUMBING: \$1,750.00 Section 5(16) 1st Offense \$1,000.00</p> <p>Section 9 1st Offense \$250.00</p> <p>Section 5(4) 1st Offense \$500.00</p> <p>BEN FRANKLIN IN HOME SERVICES: \$1,000.00 Section 6.1(7) 1st Offense \$1,000.00</p> <p>ASTOUND BROADBAND: \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Philadelphia Gas Works (PGW) disagreed and stated that "I received the notice this morning attach you will find comments from our locator for the ticket they spoke with the on-site person, and they were told that work was not starting until 2 Days later". 2 screenshots were provided. And there's also a comment on there for the damaged it was marked out and the locator spoke with the person on site and it happened a day after they hit the line. PGW provided the contact information showing that this work would not start until 11/27/2024. Violation 2(5)(v) is withdrawn.</p> <p>Philadelphia Dept of Streets disputes saying they are not a 24 hour operation and they want this 2nd offense violation and penalty waived. *****</p> <p>The incident occurred on 11/27/2024, at 340 S. 24th Street, in Philadelphia City, Philadelphia County.</p> <p>A communications line was hit and damaged.</p> <p>Comcast stated in their Alleged Violation Report (AVR) that "Plumbing company (Best Choice Plumbing) dug up and ripped out feeder. mark out was accurate". Pictures were provided.</p> <p>Best Choice Plumbing (BCP) the excavator AVR was due by 1/08/2025. On 3/13/2025 DPI Maki returned a call to Dina at Best Choice Plumbing and helped her find the AVR on the OneCall site. The best contact for the company was provided and updated. AVR2025MAR140007 was received on 3/14/2025. BCP stated in their AVR that "During excavation, after exposing all marked utilities. A communication line was disturbed about 4' away from marking". Pictures were submitted.</p> <p>BEN FRANKLIN IN HOME SERVICES (BFIHS) the project owner AVR was due by 1/08/2025. No AVR has been received to date. DPI Maki emailed an AVR request letter asking for a mailing address on 2/10/2025. On 2/12/2025 DPI Braxton spoke with Olive from BFIHS on how to file an AVR and followed up with an email. *****</p> <p>*Ticket 20243262394 was submitted by Best Choice Plumbing on 11/21/2024 with a response due by 11/25/2024.</p> <p>Philadelphia City Water Works, scheduled mark, but did not mark until 12/04/2024, This was not in mutual agreement.</p> <p>Comcast did not mark until 11/26/2024 at 11:05. Philadelphia Gas Works did not respond until 11/26/2024 at 11:05</p> <p>*Emergency Ticket 20243322017 was submitted by Best Choice Plumbing on 11/27/2024 at 12:59.</p>	<p>Section 2(5)(vii) 1st Offense \$1,000.00</p> <p>PHILADELPHIA CITY DEPARTMENT OF STREETS: \$1,500.00</p> <p>Section 2(5)(vii) 2nd Offense \$1,500.00</p> <p>PHILADELPHIA CITY WATER DEPARTMENT: \$1,750.00</p> <p>Section 2(5)(vii) 2nd Offense \$1,500.00</p> <p>Section 2(5)(v) 1st Offense \$250.00</p> <p>PHILADELPHIA GAS WORKS: \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Philadelphia City Water did not respond until 1/08/2025, when they scheduled a mark, and did not mark out until 1/09/2025.</p> <p>Philadelphia City Department of Streets did not respond clear until 12/02/2024.</p> <p>Astound Broadband did not respond until 12/01/2024 *****</p> <p>BEN FRANKLIN IN HOME SERVICES is in violation of: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Recommendation: The penalty is applied. Education is required.</p> <p>BEST CHOICE PLUMBING is in violation of: Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 business days of striking a line. Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Section 9 – Failed to make the best efforts to comply with the Common Ground Alliance Best Practices – CGA 5-16 Federal and State Regulations for required training. The required PUC education was due by 8/07/2023. This has not been completed to date. Recommendation: The penalties are applied. Education is required. *****</p> <p>Listed below are facility owners in violation of Act 127-2024, Section 2(5)(vii) Failed to respond to an emergency One Call ticket as soon as practicable and Section 2(5)(v) Failed to respond to a routine One Call ticket within the required amount of time.</p> <p>COMCAST CABLEVISION is in violation of: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. See ticket 20243262394 details above. This is a second offense. Recommendation: The penalty is applied.</p> <p>PHILADELPHIA GAS WORKS is in violation of: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. See ticket 20243262394 details above. Recommendation: The penalty is applied. The required excavator education that was due by 2/23/2025, has not been completed to date and facility owner education is required.</p> <p>PHILADELPHIA CITY WATER DEPARTMENT is in violation of: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. See ticket 20243262394 and Emergency ticket 20243322017 details above. Recommendation: The penalty is applied. Education is required.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>ASTOUND BROADBAND is in violation of: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. See Emergency ticket 20243322017 details above. Recommendation: The penalty is applied. Education is required.</p> <p>PHILADELPHIA CITY DEPARTMENT OF STREETS is in violation of: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. This is a second offense violation. See Emergency ticket 20243322017 details above. Recommendation: The penalty is applied. Education is required.</p>	
52242	<p>Facility Owner: Peoples Natural Gas Contractor/Excavator: PENN LINE SERVICE Project Owner: PennDOT Other: A. LIBERONI CONSTRUCTION</p>	<p><u>On 12/23/2024 8:45:00 AM at SR 3077, MOON TWP, ALLEGHENY</u> On 07/08/2025: The Damage Prevention Committee (DPC) voted to remove Penn Line Services' violation of 5(4) and the associated penalty.</p> <p>*****</p> <p>Penn Line Service, Inc. is disputing. They submitted additional photos.</p> <p>A. LIBERONI CONSTRUCTION violation was withdrawn, as they are not the project owner. PennDOT is the correct project owner.</p> <p>*****</p> <p>The incident occurred on 12/23/2024 at 8:45 AM, on SR 3077, in Moon Township, Allegheny County. The nearest intersection was Olde Manor Lane.</p> <p>A gas line owned by Peoples Gas was damaged. 911 was called.</p> <p>Peoples Gas, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, "On 12/23/204, Penn Line Service was working to install Guide Rail along Beaver Grade Road in Moon Twp. Allegheny County. Penn Line struck a PNG 6" plastic ML within the tolerance zone while driving in the guide rail. Penn Line failed to pothole and use prudent techniques within the tolerance zone. Additionally, Penn Line failed to preserve markings prior to performing work." Photos were submitted.</p> <p>Penn Line Service, Inc, the excavator, submitted an AVR. Their AVR states, "Penn Line Crew installing replacement guiderail when they smelled gas".</p> <p>A. LIBERONI CONSTRUCTION is the project owner. An AVR has not been filed as of 02/28/2025.</p> <p>Photos show Peoples Gas marking on the pavement, which included the size and material of their line. There was a flag placed in the glass to mark the line as well. Photos of the damage show the flag is fallen over and laying on the ground.</p> <p>Violations:</p>	<p>PENN LINE SERVICE: \$0.00</p> <p>A. LIBERONI CONSTRUCTION: \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>A. LIBERONI CONSTRUCTION - Withdrawn. - Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike.</p> <p>PENN LINE SERVICE – - Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. [Withdrawn per DPC meeting.] Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
52394	<p>Facility Owner: ROSCOE BOROUGH</p> <p>Contractor/Excavator: BRITTON & SONS INC</p> <p>Project Owner: THE MUNICIPAL AUTHORITY OF THE TOWNSHIP OF WASHINGTON (MAWT)</p> <p>Designer: BANKSON ENGINEERS INC</p> <p>Other: COLUMBIA GAS OF PA INC</p> <p>Other: MID MON VALLEY WATER POLLUTION CNTRL AUTHORITY (MMVWPCA)</p> <p>Other: THE MUNICIPAL AUTHORITY OF THE TOWNSHIP OF WASHINGTON - spacesaver</p>	<p>On 12/30/2024 9:00:00 AM at LYNN ST, ROSCOE BORO, WASHINGTON On 7/08/2025 Britton and Son's were not in attendance. The Damage Prevention Committee (DPC) voted to keep the recommendations as presented.</p> <p>Britton & Sons, Inc. disagreed and stated that "Britton & Sons, Inc. will reject payment of your invoice #052394-009588 in the amount of \$750. I wish to contest charges for alleged violation.</p> <p>* Columbia Gas disagreed and stated that "Columbia Gas respectfully requests reconsideration of the violations cited under Sections 2(5)(v) and 2(5)v(iii) in the above-referenced matter. While we acknowledge that the ticket response was submitted after the due date, we would like to clarify that the facility was marked prior to the start of excavation, and we believe the timing of the response did not contribute to the damage that occurred. Additionally, our locator documented communication with the excavator in our ticket management system while actively working to complete the ticket. Due to the size and complexity of the locate area, the locator was unable to complete the markings within the standard timeframe and requested additional time to ensure the work was performed accurately and safely. In light of recent updates to the Pennsylvania Underground Utility Line Protection Law, 7.8 B.1, which emphasize a review of the root cause of alleged violations and the findings of the damage prevention investigator, we respectfully request that the penalty associated with this violation be reconsidered. On 5/22/2025 DPI Maki responded to Columbia Gas email with the ticket responses. Columbia Gas responded "conflict" a day late. Ticket was due by 12/10/2024 and Columbia responded on 12/11/2024. No mutual agreement was provided. See attachment named " DPI to Columbia Gas - late response and would need mutual agreement. On 5/28/2025 Nisource sent the telephone log and stated that all the coordination was done by telephone. DPI responded that mutual coordination with the excavator is needed.</p> <p>* Bankson Engineering disagreed. They provided documents and the violations section 4(5) and 4(2.2) were withdrawn. The violation section 4(4) is maintained, because Roscoe Borough never responded to any of the design ticket requests. Bankson Engineering prepared a design without this information. Bankson</p>	<p>ROSCOE BOROUGH: \$1,250.00 Section 2(5)(i) 1st Offense \$500.00</p> <p>Section 9 1st Offense \$250.00</p> <p>Section 2(5)(v) 1st Offense \$500.00</p> <p>BRITTON & SONS INC: \$750.00 Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(3) 1st Offense \$250.00</p> <p>Section 5(20) 1st Offense \$250.00</p> <p>THE MUNICIPAL AUTHORITY OF THE TOWNSHIP OF WASHINGTON (MAWT): \$125.00 Section 2(5)(v) 1st Offense \$125.00</p> <p>BANKSON ENGINEERS INC: \$125.00 Section 4(4) 1st Offense \$125.00</p> <p>COLUMBIA GAS OF PA INC: \$500.00 Section 2(5)(v) 1st Offense \$250.00</p> <p>Section 2(5)(iii.1) 1st Offense \$250.00</p> <p>MID MON VALLEY WATER POLLUTION CNTRL AUTHORITY (MMVWPCA): \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Engineering would have been prudent to contact Roscoe Borough. This is a first-time violation to Bankson Engineering and DPI Maki offered to reduce the penalty by half, if they agree to this. No reduction to the penalty has been made as of now. BE sent an email on 5/05/2025 stating that "Thank you for the prompt response to our disagreement. We were unaware of any standards that required us as the designer to reach out to utility owners who don't provide a response through the Pa One Call system after a ticket has been submitted. Section 4 (4) states that we are to make a reasonable effort to prepare construction drawings to avoid damage and minimize interference, so we were under the impression that submitting preliminary and final design tickets was adequate for preparing construction drawings. If there is information we're missing, can you please provide us with it to avoid this in the future"? On 5/05/2025 DPI maki returned the email stating that "Please see section 4(4) in ACT 127 – 2024. I have attached it to this email. Section 4(4) reads: To make a reasonable effort to prepare the construction drawings to avoid damage to and minimize interference with a facility owner's facilities in the construction area by maintaining the clearance as provided for in applicable easement condition or an eighteen-inch clearance of the facility owner's facilities if no easement restriction exists". Also in Common Ground Alliance (CGA) There is an entire chapter about the designer's responsibilities. In CGA Best Practices 2-2 states that the designer uses all reasonable methods of obtaining information about underground facilities in the area and lists methods of gathering information for design purposes states that notifying the OneCall system is one way to get this information, but to contact the entities to get that information. Was there any attempt to get that information from Roscoe Borough? I maintain that it is hard to minimize interference with a facility owner's facilities if Roscoe Borough did not respond to both the preliminary design and final design". On 5/06/2025 Bankson Engineering sent an email agreeing to the violation of 4(4) and the reduced amount of \$125.</p> <p>*</p> <p>The Municipal Authority of Washington Township (MAWT) disagrees and stated that "I am making a timely response to case 052394. I reject the DPI report and the listed violations.</p> <p>Attached are final design drawings that show that the final design was completed before sending the project to bid.</p> <p>Secondly, the attached email is the response Bankson received from One Call after submitting the final design ticket showing that Washington Township field marked the area. The violation of Section 6.1(3) has been withdrawn. This is a first-time violation. DPI offered to reduce the penalty by half for section 2(5)(v). On 5/05/2025 MAWT agreed to the reduced penalty and asked some questions about the ticket responses. DPI Maki reduced the penalty of \$250. to \$125 for violation 2(5)(v).</p> <p>*****</p>	<p>Section 2(5)(v) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>The incident occurred on 12/30/2024 on Lynn St. in Roscoe Borough in Washington County.</p> <p>Tickets were not responded to, and an underground sewer line was not marked.</p> <p>BRITTON AND SONS stated in their Alleged Violation Report (AVR) that a ticket was not responded to. No project information was filled out in the AVR. They state that the cost of the repair was between \$5,000. And \$25,000. Reports were provided. No pictures were provided.</p> <p>WASHINGTON TOWNSHIP MUNICIPAL AUTHORITY the project owner stated in their AVR that " Roscoe Boro did not respond to a PA One Call to mark their sewer lines and the contractor working on a project for the MAWT damaged their sewer line and incurred cost over \$5,000.00. No Project information was filled out in the AVR. Reports were provided. No pictures were provided.</p> <p>BANKSON ENGINEERS INC the designer stated that "During Lynn St. water line project, a sewer line was struck during excavation". The project is listed to be <\$400,000. The length is listed as 1493 Ft and the Subsurface Utility Engineering (SUE) level is stated to be "C". Reports were provided. No pictures were provided.</p> <p>*Washington Township states that Roscoe Boro did not mark their lines. Both Bankson Engineers and Britton and Sons stated that Roscoe did not respond to the notification. Roscoe Borough did not respond to ticket 20243410523.</p> <p>*****</p> <p>*Ticket 20243410523 was submitted by Britton and sons on 12/06/2024 with a response due by 12/10/2024. Columbia gas responded with a conflict which was a late response "Conflict" which is also not a final response and there is nothing in writing showing that a mutual agreement was had with the excavator Britton and Sons. ROSCOE BOROUGH never responded. MID MON VALLEY WATER POLLUTION CNTRL AUTHORITY never responded. WASHINGTON TOWNSHIP MUNICIPAL AUTHORITY responded with "Field Marked" late on 12/12/2025.</p> <p>*****</p> <p>VIOLATIONS BRITTON & SONS INC Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. Section 5(3) – Excavator failed to schedule work as agreed upon during a preconstruction meeting. Section 5(20) – Excavator failed to renotify One Call of an unmarked or incorrectly marked facility upon arrival</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>at a work site. Roscoe Borough did not respond to ticket 20243410523. Recommendation: The penalties are applied. Education is required.</p> <p>THE MUNICIPAL AUTHORITY OF THE TOWNSHIP OF WASHINGTON Section 6.1(3) – Released a project to bid or construction before final design was complete. Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Recommendation: The penalties are applied. Education is required.</p> <p>BANKSON ENGINEERS INC Section 4(2.2) – Failed to submit a design notification through the One Call System when a design drawing is completed Section 4(5) – Designer’s drawing does not include One Call’s toll-free number and the serial number of the ticket. Section 4(4) – Failed to prepare construction drawings to avoid damage to and minimize interference with facilities in the construction area. Recommendation: The penalties are applied. Education is required.</p> <p>ROSCOE BOROUGH Section 2(5)(v) – Failed to respond to a routine One Call ticket. Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Section 9 – Failed to make the best efforts to comply with the Common Ground Alliance Best Practices – CGA 5-16 Federal and State Regulations for required training. The required facility owner education was due by 10/12/2022. This has not been completed to date. Recommendation: The penalties are applied. Education is required. Roscoe Borough is delinquent on Facility Owner education for case 016073. The DPC sent them to education on 7/12/2022.</p> <p>Listed below are facility owners in violation of Act 127-2024, Section 2(5)(v) Failed to respond to a routine One Call ticket and 2(5)(v) Failed to respond to a routine One Call ticket within the required amount of time,</p> <p>MID MON VALLEY WATER POLLUTION CNTRL AUTHORITY (MMVWPCA) Section 2(5)(v) – Failed to respond to a routine One Call ticket. The penalty is applied. Education is required.</p> <p>COLUMBIA GAS OF PA INC Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Section 2(5)(iii.1) – Facility owner failed to propose a mutually agreeable scheduling by which the excavator, facility owner or designer may locate the facilities.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
52265	<p>Facility Owner: PECO Contractor/Excavator: K B C CONSTRUCTION LLC Project Owner: HATFIELD BOROUGH</p>	<p>Recommendation: The penalties are applied. Education is required.</p> <p><u>On 1/7/2025 12:00:00 PM at W BROAD ST, HATFIELD BORO, MONTGOMERY</u> On 7/08/2025 the Damage Prevention Committee (DPC) voted to Keep the violation and to reduce the penalties by half to Hatfield Borough. Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. \$1000. penalty is reduced to \$500. Section 6.1(3) – Released a project to bid or construction before final design was complete. The \$500. penalty is reduced to \$250. Compliance education is maintained.</p> <p>Hatfield Borough disputed - no reason given. *****</p> <p>The incident occurred on 1/07/2025 at W Broad St in Hatfield Borough in Montgomery County.</p> <p>A ½” Gas service line was damaged.</p> <p>PECO stated in their Alleged Violation Report (AVR) that “On 1/7/2025 KBC was excavating with a trackhoe when they damaged an accurately marked ½” gas service for the above address. Despite the PA 1 Ticket being 77 days old marks were still visible. 911 was notified. USIC report with pictures was provided on 2/27/2025 after the DPI requested pictures.</p> <p>K B C CONSTRUCTION LLC AVR was due by 2/06/2025. No AVR has been submitted to date.</p> <p>HATFIELD BOROUGH AVR was due by 2/06/2025. No AVR has been submitted to date. *****</p> <p>Routine ticket 20242883217 states that the project is 2000 X 5’. *****</p> <p>VIOLATIONS K B C CONSTRUCTION LLC is in violation of: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. This is a \$500. penalty. Section 5(3) – Excavator failed to hold a preconstruction meeting prior to beginning a complex project. This is a \$250. penalty. Recommendation: The penalties are applied. Education is required.</p> <p>HATFIELD BOROUGH is in violation of: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Section 6.1(3) – Released a project to bid or construction before final design was complete. Recommendation: The penalties are applied. Education is required.</p>	<p>K B C CONSTRUCTION LLC: \$750.00 Section 5(4) 1st Offense \$500.00</p> <p>Section 5(3) 1st Offense \$250.00</p> <p>HATFIELD BOROUGH: \$750.00 Section 6.1(7) 1st Offense \$500.00</p> <p>Section 6.1(3) 1st Offense \$250.00</p>
52343	<p>Facility Owner: PECO Contractor/Excavator: LANDIS EXCAVATING LLC Project Owner:</p>	<p><u>On 1/10/2025 12:00:00 PM at Crum Ledge LN, SWARTHMORE BORO, DELAWARE</u> On 7/8/2025 the DPC voted to: Landis Excavating, LLC not in attendance. 5(3)- Accept the DPI’s recommendation.</p>	<p>LANDIS EXCAVATING LLC: \$1,500.00 Section 5(3) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>Swarthmore College Designer: Gilmore & Associates, Inc. Other: RMF Engineering</p>	<p>5(16)- Accept the DPI's recommendation.</p> <p>*****</p> <p>Swarthmore College agreed to the following and has worked with 811 to be compliant with the law. Keep, but 50% reduction \$250 to \$125. Section 2(1) – Facility owner is not a member of One Call. PUC compliance education is required. Removed Section 6.1(3) – Released a project to bid or construction before final design was complete. PUC compliance education is required. Keep, but 50% reduction \$1,000 to \$500. Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. PUC compliance education is required.</p> <p>***</p> <p>Landis Excavating is disputing. Submitted an AVR on 4/11/25 during the stakeholder review phase.</p> <p>**</p> <p>Gilmore and Associates provided their final design ticket that was placed in the correct time frame. Removing the violation and penalty for Gilmore and Associates. Also removing Section 6.1(3) for Swarthmore College as it is related to the final design ticket. Gilmore and Associates submitted an AVR within the parameters of Act 127.</p> <p>**</p> <p>RMF Engineering and Warfel provided proof that RMF was not involved on this section of the project. Gilmore Associates were the designer on this part of the college project.</p> <p>*****</p> <p>Incident occurred on January 10th, 2025, at 12pm along Crum Ledge Lane, Swarthmore Boro, Delaware County.</p> <p>A gas line was damaged.</p> <p>PECO's Alleged Violation Report (AVR) states, "Landis Excavating LLC working for WARFEL construction to replace water, elec., & other site work. Contractor destroyed marks on scene and failed to call in for renotification." AVR notes that 911 was contacted.</p> <p>Pictures show the excavation trench and damage site along Crum Ledge Lane along with pre-excavation mark outs. Routine ticket was placed on 11/25/24 and damage occurred on 1/10/25.</p> <p>Emergency ticket stated, "COR PORP ADDRESS OF THE PROP IS 505 FIELDHOUSE LN DAMAGE IS ALONG CRUM LEDGE LN."</p> <p>No AVRs have been submitted by Landis Excavating, Swarthmore College, or RMF Engineering as of 3/7/2025.</p> <p>Swarthmore College was not contacted via 811 on the tickets provided and therefore not a member of 811. All other utilities besides Comcast and PECO responded clear no facilities which leaves underground facilities to</p>	<p>Section 5(16) 1st Offense \$1,000.00</p> <p>Swarthmore College: \$625.00 Section 2(1) 1st Offense \$125.00</p> <p>Section 6.1(7) 1st Offense \$500.00</p> <p>Gilmore & Associates, Inc.: \$0.00</p> <p>RMF Engineering: \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>be controlled by the college. RMF Engineering screenshot is attached that describes the underground utility improvement project going on for Swarthmore's campus. Campus aerial screenshot is attached that shows where the construction sites are.</p> <p>No design tickets were located on the initial AVR for this area.</p> <p>Violations:</p> <p>Landis Excavating Section 5(3) – Excavator failed to preserve mark-outs or request a remark. PUC compliance education is required. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required.</p> <p>Swarthmore College Section 2(1) – Facility owner is not a member of One Call. PUC compliance education is required. Section 6.1(3) – Released a project to bid or construction before final design was complete. PUC compliance education is required. Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. PUC compliance education is required.</p> <p>Gilmore & Associates Section 4(2) – Designer failed to request the line and facility information prescribed by section 2(4) from the One Call System not less than ten nor more than ninety business days before final design is to be completed. PUC compliance education is required.</p>	
52193	<p>Facility Owner: Peoples Gas Contractor/Excavator: PROLINE PIPELINE INC Project Owner: Peoples Gas - Placeholder</p>	<p><u>On 1/14/2025 10:00:00 AM at 4618 PENN AVE, PITTSBURGH CITY, ALLEGHENY</u> On 06/10/2025: The Damage Prevention Committee (DPC) voted to accept the DPI's recommendation and make no changes to Proline Pipeline Inc. violations and penalties. Proline Pipeline Inc. was not in attendance.</p> <p>*****</p> <p>PROLINE PIPELINE INC is disputing 5(4) and 5(16). The violation of 5(8) was withdrawn after additional information was submitted.</p> <p>*****</p> <p>The incident occurred on 01/14/2025 at 10:00 AM, at 4618 Penn Avenue, in Pittsburgh City, in Allegheny County.</p> <p>A gas line owned by Peoples Gas was damaged. 911 was not called.</p> <p>Peoples Gas, the facility owner and project owner, submitted an Alleged Violation Report (AVR). Their AVR states, "PROLINE PIPELINE working for Peoples Gas struck and damaged a properly marked Peoples Gas service line at 4618 Penn Ave while using mechanized equipment in the tolerance zone." Photo was submitted.</p>	<p>PROLINE PIPELINE INC: \$1,500.00 Section 5(16) 1st Offense \$1,000.00</p> <p>Section 5(4) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>PROLINE PIPELINE INC is the excavator. An AVR has not been filed as of 03/15/2025.</p> <p>No indication 911 was called based on Peoples Gas AVR, emergency ticket and the submitted photo.</p> <p>Violations:</p> <p>PROLINE PIPELINE INC - No prior violations.</p> <ul style="list-style-type: none"> - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 business days of striking a line. - Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. - Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. - Withdrawn. <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
52258	<p>Facility Owner: Columbia Gas of PA - East</p> <p>Contractor/Excavator: Leonard S Fiore Inc</p> <p>Project Owner: 1725 N ATHERTON ST ASSOCIATES / HFL CORPORATION (HFL)</p> <p>Designer: PENNTERRA ENGINEERING INC</p> <p>Other: PATTON TOWNSHIP</p>	<p><u>On 1/17/2025 9:00:00 AM at 1742 N ATHERTON ST, PATTON TWP, CENTRE</u> On 7/08/2025 the Damage Prevention Committee (DPC) voted to Keep the violation and reduce the penalty by half for Patton Township.</p> <p>PATTON TOWNSHIP disagreed and sent in an email stating that "they are not the owner of the facility, nor did they receive any OneCalls for the incident. The incident occurred on private property, off of a state highway (Atherton Street)". Attachments were provided. They added that " Please note the only thing we did for this project was to sponsor a grant for work done in the right of way along Atherton Street. All work was completed by private contractors and the Township had no involvement or ownership of it". On 4/30/2025 multiple emails were sent back and forth with Ms. Farkas insisting that we remove the penalty and violation. Damage Prevention Supervisor (DPS) sent Ms. Farkas the information to reach out to OneCall to help fix the map and buffer zone.</p> <p>*****</p> <p>The incident occurred on 1/17/2025 at 1742 N Atherton St., in Patton Township in Center County.</p> <p>A gas line was hit and damaged.</p> <p>Leonard S. Fiore Inc (LSF) stated in their Alleged Violation Report (AVR) that “LSF was operating a trackhoe to excavate a trench to install electrical conduit. The ground crew member had gone to the restroom and the operator continued to excavate the trench. While continuing to excavate the trench, the operator struck the gas line that was clearly marked. 911 was notified. Pictures were provided.</p>	<p>Leonard S Fiore Inc: \$500.00 Section 5(4) 1st Offense \$500.00</p> <p>PATTON TOWNSHIP: \$500.00 Section 2(5)(vii) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>On 2/27/2025 DPI Maki sent an email asking if LSF could provide contact information for the Project Owner (PO) and designer.</p> <p>Columbia Gas stated in their AVR that “LS Fiore was digging a trench to install conduit when they struck and damaged an accurately marked 4" plastic gas main with their bucket. They notified 911 and Columbia Gas when the damage occurred. Columbia Gas responded immediately to make the area safe and complete repairs. The local Damage Prevention Specialist (DPS) followed up with LS Fiore to review the root cause of the damage. They were digging in the tolerance zone of an accurately marked facility without hand digging to fully exposing it prior to using equipment. Damage Prevention has provided prior gas safety trainings and maintains open communication with them on active jobsites. LS Fiore has since reviewed this damage and root cause with all field employees. Pictures were provided.</p> <p>Leonard S. Fiore Incorporated’s stated that “contract is with 1752 N Atherton St. Associates LP. They should be listed as the owner”.</p> <p>1752 N Atherton St. Associates, LLC / HFL Corporation LP, the Project Owner was emailed and mailed an AVR request letter on 2/27/2025 and on 3/04/2025. On 3/12/2025 an AVR was submitted which stated that “LSF was operating a trackhoe to excavate a trench to install electrical conduit. The ground crew member had gone to the restroom and the operator continued to excavate the trench. While continuing to excavate the trench, the operator struck the gas line that was clearly marked. 911 was notified. The project is listed at <\$400,000.</p> <p>An email was received on 3/13/2025 stating that “1752 North Atherton Street Associates, LP is the owner of the project. HFL Corporation is a partner in 1752 and acts as a Construction Manager for the projects at this site. You could say 1752 and HFL are both responsible for the management of this specific project”.</p> <p>PENN TERRA ENGINEERING INC the Designer was emailed and mailed AVR request letter on 3/04/2025. An email was received from Penn Terra- including the AVR that was submitted by Leonard S Fiore Inc. pictures were also included. DPI responded with an email that Penn Terra is required to submit their own AVR with Design and project information. On 3-06-2025 and email was received stating that Penn Terra will complete AVR ASAP. On 3/06/2025 Penn Terra sent an email stating they could not find how to fill out an AVR. On 3/07/2025 DPI Maki sent a complete list of information including a OneCall video of how to complete an AVR and the OneCall call-in number to complete an AVR. PennTerra stated in their AVR that “Contractor was using a trackhoe to install electrical and telecommunication conduits across the gas line. The ground crew member was absent as the operator continued to dig. The operator subsequently struck the gas line that was clearly marked”. On 3/14/2025 DPI</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Maki sent an email asking if a design ticket was submitted for this work.</p> <p>VIOLATIONS Leonard S Fiore Inc is in violation of: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: The penalty is applied. Education is required.</p> <p>Listed below are facility owners in violation of Act 127-2024, Section 2(5)(vii) Failed to respond to an emergency One Call ticket as soon as practicable. PATTON TOWNSHIP is in violation of: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. They never responded to Emergency ticket 20250170915. Recommendation: The penalty is applied. Education is required.</p>	
52589	<p>Facility Owner: Columbia Gas of PA Contractor/Excavator: Lee's Plumbing Project Owner: HOMEOWNER Other: CALIFORNIA BOROUGH Other: CENTER-WEST JOINT SEWER AUTHORITY Other: West Penn Power / First Energy</p>	<p><u>On 1/22/2025 10:36:00 AM at 178 HILLCREST DR, CALIFORNIA BORO, WASHINGTON</u> On 7/08/2025 the Damage Prevention Committee (DPC) voted to withdraw the penalty section 2(5)(vii) to West Penn Power/ First Energy. On 7/08/2025 the Damage Prevention Committee (DPC) voted to keep the penalty section 2(5)(vii) to Center West Joint Authority.</p> <p>First Energy / West Penn Power disagreed. They stated that they made contact with the excavator withing 2 hours of the submission of the emergency ticket. They sent a letter describing reasons why they should not have a violation for case 52589, including that not responding timely to this emergency ticket was not a root cause for the damage. Please see attachment named "WP OneCall - Case 52589 Dispute violation --FILED 5.6.25. * Center West Joint Sewer Authority is disputing. They did not give a reason. ***** The incident occurred on 1/22/2025 at 178 HILLCREST DR in California Borough in Washington County.</p> <p>A 1” gas service line was hit and damaged.</p> <p>Columbia Gas stated in their Alleged Violation Report (AVR) that Lee's Plumbing was repairing a sewer line outside of 178 Hillcrest Dr., California, when they struck and damaged the accurately marked 1" gas service. They notified 911 and Columbia Gas when the damage occurred. Columbia Gas responded immediately to make the area safe and complete repairs. Columbia would also like to note that Lee's Plumbing had the homeowner place the One Call ticket. They did not have their own One Call ticket. Pictures were provided. Compliance Research results: Contractor has placed One Call notifications with PA One Call in the past. Listed info is most recent on file for Lees Plumbing.</p>	<p>Lee's Plumbing: \$2,750.00 Section 5(2.1) 1st Offense \$1,000.00 Section 5(23) 1st Offense \$500.00 Section 5(16) 1st Offense \$1,000.00 Section 9 1st Offense \$250.00 HOMEOWNER: \$0.00 Section 6.1(7) 1st Offense \$0.00 CALIFORNIA BOROUGH: \$1,000.00 Section 2(5)(vii) 1st Offense \$1,000.00 CENTER-WEST JOINT SEWER AUTHORITY: \$1,000.00 Section 2(5)(vii) 1st Offense \$1,000.00 West Penn Power / First Energy: \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Lees Plumbing the excavator AVR was due by 3/16/2025. No AVR has been received as of 3/27/2025.</p> <p>Homeowner and project owner AVR was due by 3/16/2025. No AVR has been received as of 3/27/2025. *****</p> <p>Emergency ticket 20250201294 was submitted on 1/20/2025 by Homeowner Christopher Hayes for Contractor Lees Plumbing to repair a sewer line. The excavation was scheduled for 1/21/2025 at 8 a.m.</p> <p>West Penn Power and PA American Water did not respond “clear” until 1/21/2025 at 9:13. They did respond scheduled mark, but this was not in mutual agreement with the excavator. This is also not a final response. The final response “clear” was given on 1/21/2021 at 9:13.</p> <p>California Borough did not respond until 1/22/2025 at 11:58, when they field marked.</p> <p>West Center Joint Sewer Authority did not respond until 1/22/2025 at 11:41 when they responded clear. No facilities involved.</p> <p>Columbia Gas did not respond until 1/21/2025 at 13:32. They submitted the ticket and did respond timely after the work was completed. ****</p> <p>VIOLATIONS</p> <p>Lee's Plumbing is in violation of: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Section 5(23) – Excavator may not delegate their duty to submit a locate request to the One Call System to another person. The excavator shall have sole responsibility to submit each locate request to the One Call System Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 business days of striking a line. Section 9 – Failed to make the best efforts to comply with the Common Ground Alliance Best Practices – CGA 5-16 Federal and State Regulations for required training. The required education in case 33050 was due by 3/12/2024 and has not been taken to date Recommendation: The penalties are applied. Education is required. Note that In case 14947 a 5(4) violation was reduced to a warning.</p> <p>HOMEOWNER is in violation of: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Recommendation: The \$1000. Penalty is reduced to a warning. *</p> <p>Listed below are facility owners in violation of Act 127-2024, Section 2(5)(vii) Failed to respond to an emergency One Call ticket as soon as practicable. Please see emergency notification 20250201294 details above. West Penn Power / First Energy is in violation of:</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(vii) – Failed to respond to emergency notification 20250201294 as soon as practicable following notification. Recommendation: the penalty is applied. Education is required.</p> <p>CALIFORNIA BOROUGH is in violation of: Section 2(5)(vii) – Failed to respond to emergency notification 20250201294 as soon as practicable following notification. Recommendation: the penalty is applied. Education is required.</p> <p>WEST CENTER JOINT SEWER AUTHORITY is in violation of: Section 2(5)(vii) – Failed to respond to emergency notification 20250201294 as soon as practicable following notification. Recommendation: the penalty is applied. Education is required.</p>	
52353	<p>Facility Owner: Columbia Gas</p> <p>Contractor/Excavator: A Team Trenching</p> <p>Project Owner: ADB Companies</p> <p>Other: Omni Fiber LLC</p>	<p>On 1/23/2025 12:35:00 PM at 110 HERITAGE HILLS RD, SOUTH UNION TWP, FAYETTE On 07/08/2025: The Damage Prevention Committee (DPC) voted to keep Columbia Gas' violation of 2(5)(v) and remove the penalty.</p> <p>*****</p> <p>Columbia gas accepted violation of 2(5)(i). They disputed violation 2(5)(v). Education requirement waived.</p> <p>*****</p> <p>The incident occurred on 01/23/2025 at 12:35 PM, at 110 Heritage Hills Road, in South Union Township, Fayette County.</p> <p>A gas line owned by Columbia Gas was damaged. 911 was called.</p> <p>Columbia Gas, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, "A Team Trenching was installing conduit in front of 110 Heritage Hills Rd., Uniontown, when they struck and damaged an inaccurately marked 2" medium pressure gas main with their bore machine. They notified 911, 811, and Columbia Gas when the damage occurred. Columbia Gas responded immediately to make the area safe and complete repairs. An onsite root cause investigation was conducted to review the events leading up to the damage. A Team Trenching had spot holes along their entire run of the bore path and had spotted the gas main. The gas main ran along the curb until 110 Heritage Hills Rd., when it "kicked out" approximately 6' into the property. However, the gas main continued to be marked straight. There was wire on the gas main, and after the damage, it did tone accurately. The initial locate was unable to replicated. Therefore, this damage was deemed to be locator error and coaching has been provided." Photos were submitted.</p>	<p>Columbia Gas: \$500.00 Section 2(5)(i) 1st Offense \$500.00</p> <p>Section 2(5)(v) 1st Offense \$0.00</p> <p>A Team Trenching: \$1,500.00 Section 5(16) 2nd Offense \$1,500.00</p> <p>ADB Companies: \$500.00 Section 6.1(3) 1st Offense \$500.00</p> <p>Omni Fiber LLC: \$2,000.00 Section 2(5)(vii) 1st Offense \$1,000.00</p> <p>Section 2(5)(vii) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>A Team Trenching is the excavator. An AVR has not been filed as of 03/26/2025.</p> <p>ADB Companies, lists themselves on the AVR as the project manager, submitted an AVR. Their AVR states, "While directional drilling in front of 110 Heritage Hills Rd the gas main was hit the point of impact was 6' off the initial mark out done by the utility owner". Photos were submitted.</p> <p>No design information was submitted. The coordinate PA reports list out all the tickets for the project. No design tickets were listed.</p> <p>Emergency ticket 20250231724 had a response due date of 01/23/2025. Omni Fiber did not respond to this ticket.</p> <p>Emergency ticket 20250231454 had a response due date of 01/23/2025. Omni Fiber did not respond to this ticket.</p> <p>Routine ticket 20243401545 had a response due date of 12/10/2024. COLUMBIA GAS responded 'Field Marked' on 12/16/2024. – Late response.</p> <p>Violations:</p> <p>A Team – - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 business days of striking a line Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Columbia Gas – - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. [No education required.] - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20243401545. [No education required.] Recommendation: The penalty is applied.</p> <p>ADB Companies – - Section 6.1(3) – Released a project to bid or construction before final design was complete. Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Omni Fiber – - Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket 20250231724. - Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket 20250231454. Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
52521	Facility Owner: Columbia Gas of PA - South Contractor/Excavator: West Penn Power / First	<u>On 1/24/2025 9:55:00 AM at 169 HOPWOOD COOLSPRING RD, NORTH UNION TWP, FAYETTE</u> On 07/08/2025: The Damage Prevention Committee (DPC) voted to accept the DPI's recommendations for	Columbia Gas of PA - South: \$500.00 Section 2(5)(v) 2nd offense \$500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>Energy Project Owner: West Penn Power / First Energy - Place holder</p>	<p>Columbia Gas. No changes to their violations or penalties.</p> <p>*****</p> <p>Columbia Gas is disputing both violations.</p> <p>West Penn Power / First Energy accepts.</p> <p>*****</p> <p>The incident occurred on 01/24/2025 at 9:55 AM, at 169 Hopwood Coolspring Road, in North Union Township, Fayette County.</p> <p>A gas line owned by Columbia Gas was damaged. 911 was called.</p> <p>Columbia Gas, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “West Penn Power was onsite to replace a pole when they augured through an accurately marked 1" plastic gas service. They notified 911, 811, and Columbia Gas when the damage occurred. Columbia Gas responded immediately to make the area safe and complete repairs.” Photos were submitted.</p> <p>West Penn Power / First Energy, the excavator and project owner, submitted an AVR. Their AVR states, “On January 14, 2025, West Penn Power submitted PA One Call ticket 20250141536 for a pole replacement near 169 Hopwood Coolspring Road, Hopwood, Fayette County, PA 15445. ?On January 24, 2025, while auguring through black top for a new pole that needed to be placed within the Tolerance Zone,?West Penn Power struck a natural gas line owned by Columbia Gas. The root cause of the damage was that West Penn Power failed to avoid damage to the known gas line.” Photos were submitted.</p> <p>Routine ticket 20250141536 had a response due date of 01/16/2025. Columbia Gas responded, 'Field Marked' on 01/17/2025.</p> <p>Emergency ticket 20250241021 – Columbia Gas did not respond to this ticket. Ticket notes COLUMBIA GAS REPRESENTATIVE IS ON SITE AND EMERGENCY PERSONNEL IS ALSO ON SITE.</p> <p>Violations:</p> <p>Columbia Gas –</p> <ul style="list-style-type: none"> - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20250141536. - Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Emergency ticket 20250241021. This is a warning since the ticket noted that Columbia Gas was on already site. <p>Recommendation: The penalty is applied.</p>	<p>Section 2(5)(vii) 1st Offense \$0.00</p> <p>West Penn Power / First Energy: \$500.00 Section 5(4) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>West Penn Power / First Energy – - Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
52998	<p>Facility Owner: First Energy - Penn Power Contractor/Excavator: D R Sevacko Plumbing and Heating Project Owner: Property Owner</p>	<p><u>On 1/29/2025 1:34:00 PM at 307 BROOKSTON DR, CRANBERRY TWP, BUTLER</u> On 7/8/2025 the DPC voted to: D R Sevacko Plumbing and Heating was not in attendance. 5(4)- Accept the DPI’s recommendation. 5(16)- Accept the DPI’s recommendation.</p> <p>*** D R Sevacko Plumbing and Heating is disputing. ***</p> <p>Incident occurred on January 29th, 2025, at 1:34pm at 307 Brookston Drive, Cranberry Township, Butler County.</p> <p>An electric line was damaged.</p> <p>First Energy - Penn Power's Alleged Violation Report (AVR) states, "On January 28, 2025, D R Sevacko Plumbing and Heating, Excavator, submitted POCS Emergency Ticket 20250282914 to replace a water line at 307 Brookston Drive, Cranberry Township, Butler County, Pennsylvania. On January 29, 2025, at 1:34 PM, Penn Power was notified of another dig in and outage near this location. USIC, Penn Power’s Contract Locator, investigated and determined that the Excavator damaged an accurately marked secondary service electric line. The root cause of the damage is the Excavator failed to dig prudently within the Tolerance Zone."</p> <p>Damage details from First Energy show that the line was accurately marked.</p> <p>No AVR has been submitted by D R Sevacko Plumbing and Heating as of 4/20/25.</p> <p>Violations:</p> <p>D R Sevacko Plumbing and Heating Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. PUC compliance education is required. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required.</p> <p>Homeowner Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Homeowner penalty reduced to warning \$0.</p>	<p>D R Sevacko Plumbing and Heating: \$1,500.00 Section 5(4) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>Property Owner: \$0.00 Section 6.1(7) 1st Offense \$0.00</p>
52652	<p>Facility Owner: PECO Contractor/Excavator: Caribbean Blue Pools & Spas</p>	<p><u>On 1/31/2025 12:00:00 PM at 237 SECOND AVENUE, ROYERSFORD BORO, MONTGOMERY</u> On 07/08/2025: The Damage Prevention Committee (DPC) voted to accept the DPI’s recommendation for Carribean</p>	<p>Caribbean Blue Pools & Spas: \$2,750.00 Section 5(2.1) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>Project Owner: Homeowner</p>	<p>Blue Pools and Spas. No changes to their violations or penalties. Carribbean Blue Pools and Spas was not in attendance.</p> <p>*****</p> <p>Caribbean Blue Pools is disputing. *****</p> <p>The incident occurred on 01/31/2025 at 12:00 PM, at 237 2nd Avenue, in Royersford Borough, Montgomery County.</p> <p>A gas line owned by PECO was damaged. 911 was called. No PA One Call ticket for excavator.</p> <p>PECO, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “On 1/31/25 Carrabean Blue Pools did not submit PA1 call.” Photos were submitted.</p> <p>Caribbean Blue Pools & Spas was the excavator. An AVR has not been filed as of 04/03/2025.</p> <p>There was another excavator (G M Pool Services) who a locate request (Ticket #20250171344) for demolition of row homes after a fire occurred. Caribbean Blue Pools & Spas did not have a locate request to be excavating at 237 2nd Ave.</p> <p>Act 127 of 2024 – PA One Call law requires states to not delegate the excavator’s duty to submit a locate request to the One Call System to another person. The excavator shall have the sole responsibility to submit each locate request to the One Call System.</p> <p>Violations:</p> <p>Caribbean Blue Pools & Spas –</p> <ul style="list-style-type: none"> - Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. - Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. - Section 5(23) – Excavator may not delegate their duty to submit a locate request to the One Call System to another person. The excavator shall have sole responsibility to submit each locate request to the One Call System. <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p>	<p>Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>Section 5(23) 1st Offense \$500.00</p>
52595	<p>Facility Owner: West Penn Power / First Energy Contractor/Excavator: Municipal Authority of</p>	<p><u>On 2/1/2025 11:00:00 AM at 3663 FORBES TRAIL DR, MURRYSVILLE MUNIC, WESTMORELAND</u> On 07/08/2025: The Damage Prevention Committee (DPC) voted to remove the violation and penalty.</p>	<p>West Penn Power / First Energy: \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>Westmoreland County Project Owner: Municipal Authority of Westmoreland County (Placeholder) Other: Comcast Cablevision Other: MURRYSVILLE MUNICIPALITY Other: Peoples Gas Other: WINDSTREAM</p>	<p>***** West Penn Power / First Energy is disputing.</p> <p>WINDSTREAM: - Accepted 2(5). - Additional information was submitted for 2(5)(v.2). Reduced to a warning with no penalty. - Education requirement was removed since Windstream completed facility owner/locator education on 05/02/2025. (Also completed education for this case on 05/27/2025, even though education was not required.)</p> <p>Peoples Gas violation withdrawn after review of additional information.</p> <p>***** The incident occurred on 02/01/2025 at 11:00 AM, at 3663 Forbes Trail Drive, in Murrysville Munic, Westmoreland County.</p> <p>An electrical line owned by West Penn Power was damaged.</p> <p>West Penn Power, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, "On February 1, 2025, Westmoreland County Municipal Authority (WCMA), submitted PA One Call New Excavation Emergency Ticket 20250320035 to repair a water main leak. A second PA One Call New Excavation Emergency Ticket 20250320149 was submitted after an employee from WCMA stated they heard a loud pop. West Penn Power was notified and confirmed damage to the secondary line and repairs were made. The root cause of the damage was WCMA failed to expose marked facilities and dig prudently within the Tolerance Zone." Photos were submitted.</p> <p>Municipal Authority of Westmoreland County, the excavator and project owner, submitted an AVR. Their AVR states, "***AVR2025FEB030005 was a draft and was submitted in error, please allow this AVR to replace AVR2025FEB030005** Project Owner and Excavator Municipal Authority of Westmoreland County (MAWC) was working to repair a leaking water service at 3663 Forbes Trail Dr. The MAWC backhoe struck an unmarked/mismarked West Penn Power line. This line was more than 3' away from the closest power line markings. MAWC shut down its work and contacted 811 to report this damaged mismarked/unmarked facility". Photos were submitted.</p> <p>Photos submitted by Municipal Authority of Westmoreland County include the electrical line that was damaged (outside of the tolerance zone), and the red mark outs/ flags.</p> <p>Emergency ticket # 20250320035 was requested 02/01/2025 at 7:43 AM. MURRYSVILLE</p>	<p>Comcast Cablevision: \$250.00 Section 2(5)(v.2) 1st Offense \$250.00</p> <p>MURRYSVILLE MUNICIPALITY: \$2,000.00 Section 2(5)(vii) 1st Offense \$1,000.00</p> <p>Section 2(5)(vii) 1st Offense \$1,000.00</p> <p>Peoples Gas: \$0.00</p> <p>WINDSTREAM: \$1,000.00 Section 2(5)(vii) 1st Offense \$1,000.00</p> <p>Section 2(5)(v.2) Warning \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>MUNICIPALITY responded 'Clear' on 02/11/2025. WINDSTREAM responded 'Clear on 02/03/2025.</p> <p>Emergency ticket # 20250320149 was requested on 02/01/2025 at 11:47 AM. MURRYSVILLE MUNICIPALITY responded 'Clear' on 02/05/2025. Peoples Gas responded "Clear" on 02/03/2025. Comcast and Windstream did not provide a final response to the ticket. 'Insufficient Information. Do Not Dig' is an interim response and is not a final response.</p> <p>Violations:</p> <p>West Penn Power / First Energy – - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>MURRYSVILLE MUNICIPALITY - - Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket 20250320035. - Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket 20250320149. Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>WINDSTREAM - - Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket 20250320035. Education is not required. - Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket 20250320149. This is a warning. No penalty is applied. Education is not required. Recommendation: The penalty is applied for 2(5)(vii) only.</p> <p>Peoples Gas – Withdrawn. - Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket 20250320149.</p> <p>Comcast – - Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket 20250320149. Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
52571	<p>Facility Owner: UGI Utilities Contractor/Excavator: J.F. KIELY CONSTRUCTION Project Owner: UGI</p>	<p><u>On 2/3/2025 11:30:00 AM at S CARLISLE ST, ALLENTOWN CITY, LEHIGH</u> On 7/8/2025 the DPC voted to: J F Kiely Construction 5(4)- Accept the DPI’s recommendation. Section 9- Accept the DPI’s recommendation.</p> <p>**** UGI Accepts **</p>	<p>UGI Utilities: \$500.00 Section 2(5)(v) 1st Offense \$500.00</p> <p>J.F. KIELY CONSTRUCTION: \$750.00 Section 5(4) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>J F Kiely Construction is disputing with additional photos of damage. "When we approached the marked service, we then hand spotted the marked service. This service was on the mark and verified that it was the proper size and material. After the marked line was located, we then proceeded to excavate the trench, when the other unmarked gas service was discovered." *****</p> <p>Incident occurred on February 3, 2025, at 11:30am along South Carlisle Street, Allentown City, Lehigh County.</p> <p>A gas line was damaged.</p> <p>UGI's Alleged Violation Report (AVR) states, "J.F. KIELY WAS DIGGING A TRENCH LINE TO INSTALL NEW GAS MAIN AND WHEN DOING SO THEY STRUCK A CORRECTLY MARKED GAS SERVICE FACILITY CREATING A DAMAGE AND A LEAK. DIGGING IN THE TOLERANZE ZONE."</p> <p>J.F. Kiely Construction's AVR states, "Crew damaged a gas line with an excavator at 208 S Carlisle St" 911 was notified.</p> <p>Pictures from UGI show that the line was damaged within the tolerance zone.</p> <p>Violations:</p> <p>J.F. Kiely Construction Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. PUC compliance education is required. Section 9 – Failed to make best efforts to comply with Common Ground Alliance Best Practices. Excavator education is overdue from case 31899 & 32120. PUC compliance education is required.</p> <p>UGI Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20250290755</p>	<p>Section 9 1st Offense \$250.00</p>
52721	<p>Facility Owner: NATIONAL FUEL GAS DIST RC 350 Contractor/Excavator: JB Line Construction LLC Project Owner: Verizon PA LLC</p>	<p><u>On 2/6/2025 4:00:00 PM at 446 S. 5TH AVE, CLARION TWP, CLARION</u> On Tuesday, July 8, 2025, at the DPC meeting, JB Line Construction LLC was disputing and the DPC voted to remove the penalty and violation for 5(13), and to accept the DPI's recommendation for 5(16) with education. *****</p> <p>Dispute- JB Line Construction LLC wants to dispute both violations because The scope of this project was not changed. The dig was in an area cleared by the one call system. The line was ridded out by the field foreman and a representative of National Fuel. The National Fuel rep was onsite for the job. Photos show this was the fault of the one call system for not locating the gas line in its entirety. We did not think we had to fill out a report since the gas representative had been on site and knew where all staked locations were. They are at fault and repaired their own line. We did not move dig location at anytime.</p>	<p>JB Line Construction LLC: \$1,000.00 Section 5(16) 1st Offense \$1,000.00</p> <p>Verizon PA LLC: \$1,000.00 Section 6.1(7) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>*****</p> <p>The incident occurred Thursday, February 6, 2025, at 446 S. 5th Avenue, in Clarion Township, Clarion County.</p> <p>A gas line was damaged.</p> <p>National Fuel Gas (NFG) said the excavator, JB Line Construction, was working outside of the proposed worksite. NFG explained in their Alleged Violation Report (AVR), that the Excavator auger through a natural gas distribution mainline. The Excavator was working outside of the proposed excavation area listed on the Routine ticket, 20250281017. The location information requested a 100 ft locate on the West Side of 5th Avenue, between the intersections of Trout Run and Fraternity Court. The natural gas damage occurred north of proposed work area. On January 8, 2025, the excavator placed a Routine ticket, 20250081848 for 588 S 5th Avenue, the proposed area that was later hit on February 6th, that routine ticket had expired. Additionally, the excavator was advised of National Fuel to be present during excavation and specifically for Pole #33, annotated on the location information. The excavator acknowledged the receipt of this message and documented on National Fuel's ticket management system on January 10th. National Fuel was never contacted or notified before the excavator performed the work near the high priority facility. NFG provided photos of the damage worksite.</p> <p>20250081848- Routine ticket placed on 1/8/2025. Work Site- 588 S. 5th Ave. Type of Work- PLACING 3 POLES. Location Information-- REPL 3 POLES WHICH ARE MARKED WITH WHITE X'S. POLES 33 34 AND 35. WORK IS ACROSS FROM FRATERNITY DR ALONG THE RD. EXISTING POLES WILL BE MOVED BACK 30FT. Lawful Start Dates--[13-Jan-25] thru [23-Jan-25]</p> <p>20250281017- Routine ticket placed on 1/28/2025. Work Site- S. 5th Ave. Type of Work- PLACING 7 POLES AND 4 ANCHORS. Location Information-- S. 5TH AVE IS SR 0068. AREA IS MARKED WITH WHITE STAKES. THE LOCATIONS ARE BEHIND THE EXISTING POLE LINE. LOCATE ALL LINES WITHIN 100FT W OF S 5TH AVE. TROUT RUN CT IS THE 1ST ROAD N OF FRATERNITY DR OFF THE W SIDE OF 5TH AVE. Lawful Start Dates--[31-Jan-25] thru [11-Feb-25]</p> <p>The map on the ticket shows the working area Working in- street, private property and private front</p> <p>JB Line Construction and Verizon did not submit their AVR's within 30 days of the line hit.</p> <p>Violations:</p> <p>*JB Line Construction LLC is in violation of section:</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>5(13) – Excavator changed the location, scope, or duration of a proposed excavation without notifying the One call System</p> <p>5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: PUC Compliance Education Required and Penalty Applied</p> <p>*Verizon PA LLC is in violation of section: 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Recommendation: PUC Compliance Education Required and Penalty Applied</p>	
52858	<p>Facility Owner: UGI UTILITIES INC</p> <p>Contractor/Excavator: HIGH TECH UNDERGROUND</p> <p>Project Owner: FASTBRIDGE FIBER</p> <p>Other: Bloomsburg Municipal Authority</p> <p>Other: Bloomsburg Town</p> <p>Other: Homeowner</p>	<p><u>On 2/11/2025 3:37:00 PM at 646 SUNSET DR, BLOOMSBURG TOWN OF, COLUMBIA</u> On Tuesday, July 8, 2025, at the DPC meeting disputing was FastBridge Fiber. FastBridge Fiber was NO SHOW. It was voted to Accept the DPI’s recommendations. *****</p> <p>Dispute- FASTBRIDGE FIBER is disputing all penalties and violations. See their attached letter *****</p> <p>The incident occurred on Tuesday, February 11, 2025, at 646 Sunset Drive, in Bloomsburg Town, Columbia County.</p> <p>UGI Utilities gas line was damaged. UGI and the Homeowner provided photos of the damage.</p> <p>UGI stated that the excavator, High Tech Underground, failed to exercise due care and take all reasonable steps necessary to avoid injury to or interference with all lines, and failed to use best practices when using trenchless technology. UGI explained in their Alleged Violation Report (AVR), “A crew [High Tech Underground] installing fiber facilities was attempting to install plastic conduit under a concrete driveway by utilizing a pneumatic underground piercing tool. An accurately marked gas service tee was damaged by the pneumatic piercing tool. A 4" plastic mainline had to be shutdown causing a 12 customer outage.”</p> <p>The Homeowner stated in their AVR, “Fast Bridge Fiber (FBF) came here on 2/11/25 to install internet lines under my concrete driveway. [The] Gas line under my driveway was hit and leak caused, which supplies gas to homes in my entire development (I do not use gas myself here). UGI was called here to excavate my driveway in order to repair the gas leak around 5 PM, the same day (2/11/25). UGI fixed the leak the next morning around 0430 on 2/12/25. Around 9 AM on 2/12/25, FBF came again here to install a conduit across my driveway, which involved more excavation, which I did not know more excavation was needed for a conduit as a lay person. Now I have 2 holes in one area of my driveway, and 2 small peep holes. Although FBF only dug 1 hole, their company caused the leak and UGI only came here as an emergency. Thankfully we were not evacuated. I am hearing FBF is paying to repair my driveway now, originally was told UGI was paying for it. However, only 1/2 of my driveway will be replaced. Are of 8</p>	<p>HIGH TECH UNDERGROUND: \$1,750.00 Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(11.2) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>FASTBRIDGE FIBER: \$2,250.00 Section 6.1(7) 1st Offense \$1,000.00</p> <p>Section 4(2) 1st Offense \$500.00</p> <p>Section 4(4) 1st Offense \$250.00</p> <p>Section 6.1(3) 1st Offense \$500.00</p> <p>Bloomsburg Municipal Authority: \$250.00 Section 2(5)(v) 1st Offense \$250.00</p> <p>Bloomsburg Town: \$1,000.00 Section 2(5)(vii) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>blocks in total measuring 20x22 feet. Only paying to replace 4 of the 8 blocks. Concrete driveway is 22 years old and the color will not match the old concrete.”</p> <p>High Tech Underground and FastBridge Fiber submitted their AVR’s on 3/26/2025. AVR’s are due within 30 days of striking a line. The incident occurred on 2/11/2025</p> <p>FastBridge Fiber, the project owner, stated in their AVR, “High Tech was attempting to missile under the driveway at 646 Sunset Dr. in Bloomsburg. During this process, a UGI Gas line was damaged. At this point all work was stopped, the work area was made safe and 911 was called. This was followed by placing of a phone call to 811. The Utility facility was notified, and repairs were made upon, their arrival. Apparently, the missile was diverted during this process. Fredy of High Tech appears to have followed proper steps after the accident occurred.”</p> <p>High Tech Underground did not provide a summary in their AVR, but mention Type of Alleged Violation as Excavator Issue as- Failed to use prudent techniques in the tolerance zone, Method of excavation was Boring, and they provided photos of the damage.</p> <p>~20250422873- Damage Emergency ticket placed on 2/11/2025. Late Response from- Bloomsburg Town, they responded on 2/20/2025 as Clear No Facilities.</p> <p>~20250312475- Routine ticket placed on 1/31/2025, response due date 2/4/2025. Late Response from - Bloomsburg Municipal Authority the Town of responded on 2/5/2025 as Field Marked.</p> <p>Violations:</p> <p>*High Tech Underground is in violation of sections: 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. 5(11.2) – When using trenchless technology, Excavator failed to utilize at a minimum, the best practices published by the Common Ground Alliance. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: PUC Compliance Education Required and Penalties Applied</p> <p>*FastBridge Fiber is in violation of sections: 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. 6.1(3) – Released a project to bid or construction before final design was complete. 4(2) – Designer failed to request the line and facility information prescribed by section 2(4) from the One Call</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>System not less than ten nor more than ninety business days before final design is to be completed. 4(4) – Failed to prepare construction drawings to avoid damage to and minimize interference with facilities in the construction area. Recommendation: PUC Compliance Education Required and Penalties Applied</p> <p>*Bloomsburg Town is in violation of section: 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20250422873 Recommendation: PUC Compliance Education Required and Penalty Applied</p> <p>*Bloomsburg Municipal Authority is in violation of section: 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. 20250312475 Recommendation: PUC Compliance Education Required and Penalty Applied</p>	
52885	<p>Facility Owner: PEOPLES GAS COMPANY Contractor/Excavator: BUTLER COUNTY Project Owner: BUTLER COUNTY</p>	<p>On 2/14/2025 10:03:00 AM at OLD ROUTE 8 N., MIDDLESEX TWP, BUTLER On Tuesday, July 8, 2025, at the DPC meeting, disputing was Butler County and it was voted to accept the DPI’s recommendations. ***** Dispute- Butler County is disputing 5(4) and 5(6)(i). See attached letter ***** Butler County penalty and violation was removed, 2(1) – Facility owner is not a member of One Call. Because within Butler County there are Townships and Boroughs, and they are the facility owners ***** The incident occurred on Friday, February 14, 2025, on Old Route 8 N., in Middlesex Township, Butler County. A gas mainline was damaged. Peoples Gas Company stated in their Alleged Violation Report (AVR) that Butler County failed to use prudent techniques within the tolerance zone, and explained that they were working to repair/replace guiderail when they struck an accurately marked PNG 4" ML. Butler County drove the guiderail post through 4" PL ML. PNG crews were notified and made repairs. Butler County failed to spot the facility. Butler County stated in their AVR that they were driving guiderail outside of the marked area of the gas line, nicked the gas line. Photos provided show the damaged gas line and damage occurred within the tolerance zone. An email was sent requesting Butler County's contact information and the Routine ticket, 20250420414, they placed was attached. PA One Call Compliance commented, not having Butler County as a member, and the only information we have is the same on the ticket since they are not a member of One Call.</p>	<p>BUTLER COUNTY: \$750.00 Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(4) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Violations:</p> <p>*Butler County is in violation of sections: 2(1) – Facility owner is not a member of One Call 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. (Butler County failed to spot the facility.)</p> <p>Recommendation: PUC Compliance Education Required and Penalties Applied</p>	
52965	<p>Contractor/Excavator: OSMOSE UTILITIES SERVICES INC Other: AT&T Other: Comcast Other: Cranberry Township Butler County Other: Eastern Gas Transmission and Storage Inc / BVR Station Other: North Beaver Township Municipal Authority Other: PA American Water Other: Seven Fields Borough Other: UGI Energy Services / UGI Pennant Trunkline Gathering</p>	<p><u>On 2/19/2025 8:15:00 AM at MULTIPLE, CRANBERRY TWP, BUTLER</u> On Tuesday, July 8, 2025, at the DPC meeting, the disputing stakeholders were PAWC, Seven Fields Borough, and UGI Energy Services. Seven Fields Borough was NO SHOW. It was voted to accept the DPI’s recommendation for PAWC and Seven Fields Borough, and for UGI Energy Services remove the penalty but keep the violation. FYI Seven Fields Borough withdrew their dispute on 6/13/25, that's why they were No Show, see attached email, which was uploaded on 6/13/25.</p> <p>*****</p> <p>Dispute- UGI Energy Services wants to dispute and stated- I am writing you in response to the PAPUC letter regarding the Notification of Damage Prevention Investigator Report, ticket numbers: 20250431127 and 20250431128. I ask that the fine be reduced or even possibly eliminated. I received an Excel spreadsheet from OSMOSE (Jajuanna Ohara) prior to the meeting. Utilizing the GPS coordinates in the Excel spreadsheet, I was able to clear my facilities from the locations prior to the meeting. I saved this information and can provide it at your request.</p> <p>*****</p> <p>Dispute- PA American Water Company wants to dispute and stated, PAWC disagrees with the April 28, 2025, DPI Report that alleges PAWC violated Section 2(5)(viii). PAWC timely responded “clear” to the complex ticket number 20250431127. For this project, the complex project meeting date was February 19, 2025, via teleconference, and PAWC did attend the complex meeting. The response to the complex ticket was due by noon on February 18, 2028. PAWC responded “cleared” at 8:49 a.m. on February 18, 2025. See attached documentation.</p> <p>*****</p> <p>Dispute- Seven Fields Borough is disputing the recommended violation, penalty and education, they gave no reason why.</p> <p>*****</p> <p>The Non-Damage event occurred on 2/19/2025 at 8:15am, Teleconference Complex Project Meeting.</p> <p>Osiose Utilities Services Inc, placed Complex Project Meeting tickets: 20250431127- Cranberry Township, Butler County and 20250431128- North Beaver</p>	<p>AT&T: \$0.00 Section 2(5)(viii) 1st Offense \$0.00</p> <p>Comcast: \$500.00 Section 2(5)(viii) 1st Offense \$500.00</p> <p>Cranberry Township Butler County: \$500.00 Section 2(5)(viii) 1st Offense \$500.00</p> <p>Eastern Gas Transmission and Storage Inc / BVR Station: \$500.00 Section 2(5)(viii) 1st Offense \$500.00</p> <p>North Beaver Township Municipal Authority: \$500.00 Section 2(5)(viii) 1st Offense \$500.00</p> <p>PA American Water: \$500.00 Section 2(5)(viii) 1st Offense \$500.00</p> <p>Seven Fields Borough: \$500.00 Section 2(5)(viii) 1st Offense \$500.00</p> <p>UGI Energy Services / UGI Pennant Trunkline Gathering: \$0.00 Section 2(5)(viii) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Township, Lawrence County. The type of work is pole restoration, reinforcing utility poles with steel. Both tickets were placed on the same day and time, with jobs crossing two counties. Osmose Utilities Services stated some facility owners failed to respond to the pre-construction meeting tickets and failed to attend the pre-construction teleconference (held on 2/19/2025 at 8:15am), and they provided a list showing the responses and the non-attendance.</p> <p>~20250431127- Complex Project Meeting ticket placed on 2/12/2025. No Response from: AT&T, and Comcast Cable Communications Inc</p> <p>~20250431128- Complex Project Meeting ticket placed on 2/12/2025. No Response from: Comcast, and North Beaver Township Municipal Authority</p> <p>The Following Facility Owners Did Not Attend the Meeting: AT&T Comcast Cranberry Township Butler County Eastern Gas Transmission and Storage Inc / BVR Station North Beaver Township Municipal Authority Pennsylvania American Water Seven Fields Borough UGI Energy Services / UGI Pennant Trunkline Gathering</p> <p>Violations:</p> <p>*AT&T is in violation of section: 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20250431127. AT&T was having issues with their ticket management software but their technician did attend the meeting. Fine reduced to a warning. Recommendation: PUC Compliance Education Required and Penalty Applied</p> <p>*Comcast is in violation of section: 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20250431127, 20250431128 Recommendation: PUC Compliance Education Required. Violation and Penalty Applied Only to 1 Ticket, because both tickets were placed on the same day, time, same meeting, and for the same job.</p> <p>*Cranberry Township Butler County is in violation of section: 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20250431127 Recommendation: PUC Compliance Education Required and Penalty Applied</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>*Eastern Gas Transmission and Storage Inc / BVR Station is in violation of section: 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20250431127 Recommendation: PUC Compliance Education Required and Penalty Applied</p> <p>*North Beaver Township Municipal Authority is in violation of section: 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20250431127 Recommendation: PUC Compliance Education Required and Penalty Applied</p> <p>*Pennsylvania American Water is in violation of section: 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20250431127, 20250431128 Recommendation: PUC Compliance Education Required. Violation and Penalty Applied Only to 1 Ticket, because both tickets were placed on the same day, time, same meeting, and for the same job.</p> <p>*Seven Fields Borough is in violation of section: 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20250431127 Recommendation: PUC Compliance Education Required and Penalty Applied</p> <p>*UGI Energy Services / UGI Pennant Trunkline Gathering is in violation of section: 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20250431128 Recommendation: PUC Compliance Education Required and Penalty Applied</p>	
52904	<p>Facility Owner: AQUA PENNSYLVANIA INC Contractor/Excavator: S and S FIBER OPTICS Project Owner: ADB COMPANIES Designer: ADB COMPANIES Other: Charter Communications Other: INVOLTA Other: Pin Oak Energy Partners LLC Other: Verizon, PA LLC</p>	<p><u>On 2/21/2025 12:00:00 PM at 1975 HIGHLAND RD, HERMITAGE CITY, MERCER</u> On Tuesday, July 8, 2025, at the DPC meeting disputing was Charter Communications. Charter Communications was NO SHOW. It was voted to remove the penalty but keep the violation and education. ***** Disputing- Charter Communications is disputing they stated, "The AVR notes that Charter failed to respond to the designer's request for information within 10 business days. This is not the case. Charter auto processes design ticket responses and the response is sent out automatically to the excavator." See attached response timeline for the request for information. ***** The incident occurred on Friday, February 21, 2025, at 1975 Highland Road, in Hermitage City, Mercer County. Aqua PA water service line was damaged. Aqua stated that S and S Fiber Optics hit and damaged a service line at 1975 Highland Road, while using a horizontal drill. The service line was properly marked. S and S Fiber Optics did not spot the service line before</p>	<p>S and S FIBER OPTICS: \$2,000.00 Section 5(3) 1st Offense \$500.00</p> <p>Section 5(11.2) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>Charter Communications: \$0.00 Section 2(4) 1st Offense \$0.00</p> <p>INVOLTA: \$250.00 Section 2(4) 1st Offense \$250.00</p> <p>Pin Oak Energy Partners LLC: \$250.00 Section 2(4) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>drilling across. It recently snowed and S and S Fiber Optics did not make effort to find the marks and paint on the sidewalk; the flag was laying.</p> <p>ADB Companies, the project owner, stated that they received a call from S and S Fiber Optics reporting that they hit a water line. Upon arriving at the work site and investigating, water was observed gushing out and washing away the sidewalk. The drill head of the equipment was located next to a water service line, and there was blue paint next to the service. S and S Fiber Optics mentioned that the area was covered in snow, which prevented the crew from seeing any paint and didn't see any flags. Once the issue was discovered, the crew capped the cut copper line and installed a new one.</p> <p>Damage Photos were provided by both Aqua and ADB Companies</p> <p>20250292000- Final Design ticket placed on 1/29/2025. Responses but these facility owners did not have a final response: Verizon PA LLC- INSUFF INFO DO NOT DIG Pin Oak Energy Partners LLC- CONFLICT DCTF BY FO Charter Communications- DESIGN CONFLICT SEND PLANS Involta- NO RESPONSE</p> <p>Violations:</p> <p>*S and S Fiber Optics is in violation of sections: 5(3) – Excavator failed to preserve mark-outs or request a remark. 5(11.2) – When using trenchless technology, Excavator failed to utilize at a minimum, the best practices published by the Common Ground Alliance. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: PUC Compliance Education Required and Penalties Applied</p> <p>*Verizon PA LLC is in violation of section: 2(4) – Failed to respond to designer's request for information within 10 business days. 20250292000 Recommendation: PUC Compliance Education Required and Penalty Applied</p> <p>*Pin Oak Energy Partners LLC is in violation of section: 2(4) – Failed to respond to designer's request for information within 10 business days. 20250292000 Recommendation: PUC Compliance Education Required and Penalty Applied</p> <p>*Charter Communications is in violation of section: 2(4) – Failed to respond to designer's request for information within 10 business days. 20250292000 Recommendation: PUC Compliance Education Required and Penalty Applied</p> <p>*Involta is in violation of section: 2(4) – Failed to respond to designer's request for information within 10 business days. 20250292000</p>	<p>Verizon, PA LLC: \$1,500.00 Section 2(4) Subsequent \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Recommendation: PUC Compliance Education Required and Penalty Applied</p>	
52963	<p>Facility Owner: PEOPLES GAS COMPANY LLC</p> <p>Contractor/Excavator: WILSON EXCAVATING - LINDY COMPANY</p> <p>Project Owner: PENNSYLVANIA AMERICAN WATER</p> <p>Other: North Strabane Township Municipal Auth</p>	<p><u>On 2/25/2025 10:00:00 AM at 219 MCCLELLAND ROAD, NORTH STRABANE TWP, WASHINGTON</u></p> <p>On Tuesday, July 8, 2025, at the DPC meeting disputing was North Strabane Twp MA. It was voted to remove the penalties but keep the violations and education. *****</p> <p>Dispute- North Strabane Township Municipal Authority wants to dispute all penalties and violations. see attached letter *****</p> <p>The incident occurred on Tuesday, February 25, 2025, at 219 McClelland Road, in North Strabane Township, Washington County.</p> <p>A gas line was damaged.</p> <p>Wilson Excavating and PA American Water Company (PAWC) stated in their alleged violation reports (AVR) that Wilson Excavating failed to use prudent techniques within the tolerance zone, and explained while performing work for PAWC, a marked Peoples Gas line was struck and damaged. The Operator was using an excavator to jackhammer the hard surface for removal. A 1" plastic gas line was struck as it was immediately under the hard surface. The facility owner was notified and 911 was called.</p> <p>Peoples Gas stated in their AVR that Wilson Excavating was jack hammering asphalt from the work area, when they struck marked PNG Company side service line. Wilson Excavating called 911 and PNG was notified. PNG crews arrived onsite and made repairs.</p> <p>20250271538- Routine ticket placed on 1/27/2025. No Response from: North Strabane Township Municipal Authority, they responded on 3/11/2025, at 2:03pm as Field Marked</p> <p>20243440569- Complex Project meeting ticket placed on 12/9/2024. No Response from: North Strabane Township Municipal Authority, they responded on 3/11/2025, at 9:26am, as Clear No Facilities</p> <p>No violation for Wison Excavating of 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. They stated in their AVR, "A 1" plastic gas line was struck as it was immediately under the hard surface." See the photos.</p> <p>Violations:</p> <p>*North Strabane Township Municipal Authority is in violation of sections: 2(5)(v) – Failed to respond to a routine One Call ticket. 20250271538 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20243440569</p>	<p>North Strabane Township Municipal Auth: \$0.00</p> <p>Section 2(5)(v) 1st Offense \$0.00</p> <p>Section 2(5)(viii) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		Recommendation: PUC Compliance Education Required and Penalties Applied	
53249	<p>Facility Owner: PPL Contractor/Excavator: Heim Construction Company INC Project Owner: Heim Construction Company INC (Placeholder) Other: Comcast Other: Orwigsburg Borough Other: Verizon</p>	<p><u>On 3/10/2025 2:11:00 PM at 123 WOODVIEW RD, ORWIGSBURG BORO, SCHUYLKILL</u> On 07/08/2025: The Damage Prevention Committee (DPC) voted for Orwigsburg Borough to: 2(5)(v)- Keep the violation and penalty. 2(5)(vii)- Keep the violation and remove the penalty.</p> <p>***** Orwigsburg Borough is disputing, stating they did not receive the One Call Notices.</p> <p>Comcast accepts.</p> <p>PPL will be accepting the fines and violation in case 53249.</p> <p>Heim Construction Company accepts the violations and penalties. I returned their call, and I left a note in the comment section ***** The incident occurred on 03/10/2025 at 2:11 PM, at 123 Woodview Road, in Orwigsburg Borough, Schuylkill County.</p> <p>An electrical line owned by PPL was damaged.</p> <p>PPL, the facility owner, submitted two Alleged Violation Reports (AVR):</p> <p>PPL AVR2025MAR110025 states, "A marked electric service was hit no one was hurt or injured." Photos were submitted.</p> <p>PPL AVR2025MAR110027 states "On Monday February 10th, 2025, at 2:11 pm a non-PPL contractor (Heim Construction Company INC) was installing a sewer line when they came in contact will a marked electric line. No one was hurt or injured but the home did loss power. PPL was called and when the crew arrived, they were able to make the area safe, and they were also able make the proper repairs to restore service to the home. The repairs that were made are permanent no follow up is needed. Heim Construction will be held liable for this damage and its repairs." Photos were submitted.</p> <p>Heim Construction Company INC. is the excavator and project owner. An AVR has not been filed as of 04/23/2025.</p> <p>Routine ticket 20250620084 had a response due date of 03/05/2025. - On 03/05/2025, Comcast responded, 'Schedule Date and time lines will be marked by: 03/05/2025 23:59', but did not respond 'Field Marked' until 03/08/2025. - On 03/05/2025, PPL responded, 'Schedule Date and time lines will be marked by: 03/05/2025. 23:59', but did not respond 'Field Marked' until 03/08/2025.</p>	<p>PPL: \$250.00 Section 2(5)(v) 1st Offense \$250.00</p> <p>Heim Construction Company INC: \$1,500.00 Section 5(16) 1st Offense \$1,000.00</p> <p>Section 5(4) 1st Offense \$500.00</p> <p>Comcast: \$1,000.00 Section 2(5)(v) Subsequent \$1,000.00</p> <p>Orwigsburg Borough: \$500.00 Section 2(5)(v) 1st Offense \$500.00</p> <p>Section 2(5)(vii) 1st Offense \$0.00</p> <p>Verizon: \$1,250.00 Section 2(5)(v) Subsequent \$1,000.00</p> <p>Section 2(5)(v.2) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>- Orwigsburg Borough did not respond to the ticket. - Verizon responded 'Clear' on 03/06/2025.</p> <p>Emergency ticket 20250692799 was requested on 03/10/2025 at 2:06 PM. - Orwigsburg Borough did not respond to the ticket. - Verizon did not provide a final response to this ticket. They had responded, 'Insufficient information. Do not Dig', which is an interim response.</p> <p>Violations:</p> <p>Heim Construction Company INC. - - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. - Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Comcast – - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20250620084. Recommendation: The penalty is applied.</p> <p>PPL – - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20250620084. Recommendation: The penalty is applied.</p> <p>Orwigsburg Borough – - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket 20250620084. - Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket 20250692799. Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Verizon – - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20250620084. - Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket 20250692799. Recommendation: The penalty is applied.</p>	