



**Pennsylvania Public Utility Commission**

**Damage Prevention Committee Meeting Case List  
September 9, 2025**

**Omnibus Session**

Case Number	Stakeholders	Summary	Violations & Recommendation
52212	<b>Facility Owner:</b> Peoples Gas <b>Contractor/Excavator:</b> Kelley's Masonry and Remodeling, LLC	<p><u>On 1/7/2025 12:30:00 PM at 1826 S 18th St, PITTSBURGH CITY, ALLEGHENY</u> The incident occurred on 1/7/2025 at 12:30:00 PM, on 1826 S 18Th St, in Pittsburgh City, Allegheny County.</p> <p>-Hand Tools-</p> <p>A gas line owned by Peoples Gas Company LLC was damaged.</p> <p>Peoples Gas Company LLC is the facility owner. Their Alleged Violation Report (AVR) states, "Kelley's Masonry and Remodeling, LLC working at 1826 S 18th Street in Pittsburgh failed to place a locate request and struck and damaged a Peoples Gas service line."</p> <p>Kelley's Masonry And Remodeling, LLC is the excavator. An AVR has not been filed as of 05-27-2025.</p> <p>2 photos of the damage and location were submitted with Peoples Gas AVR. No mechanized equipment or use of mechanized equipment is shown. Kelley's Masonry And Remodeling has been contacted by Peoples Gas about the incident and has stated they were not using mechanized equipment.</p> <p>Violations: None: Hand Tools</p>	
52384	<b>Facility Owner:</b> BUCKS COUNTY WATER AND SEWER AUTHORITY (BCWSA) <b>Contractor/Excavator:</b> HENKELS AND MCCOY <b>Project Owner:</b> PECO <b>Designer:</b> MASTEC PROFESSIONAL SERVICES <b>Other:</b> K D M ENGINEERING	<p><u>On 1/24/2025 10:50:00 AM at 922 BUSTLETON PIKE, LOWER SOUTHAMPTON TWP, BUCKS</u> Bucks County Water and Sewer Authority- (BCWSA) disagreed and stated that " We are disputing the finding and fine that an AVR was required for this. BCWSA crews performed the repair once we were called out, we only had Henkles dig around the area for us to do the repair. I believe AVR's may not be reported if the damage cost is less than \$2,500, which I can't imagine this digging would have amounted to.</p> <p>Also, we dispute the claim that the service was 5'1" off the mark. While the line could have been there, the service was marked in the direction of where it came off the main. Unknown to us, it was not a straight shot to the property but was angled off the curb box to the building. Under the Good Samaritan clause of PA ONE law, we marked the service to the best of our ability, even though we do not own the service line. We only own the water main itself. The attached pictures were taken at the time we marked ticket 20250081790". Pictures were provided. On 7/11/2025 DPI responded to BCWSA noting that compliance education was completed in 2025 and the ACT 127-2024 update took effect in Oct 2024.</p>	<p><b>BUCKS COUNTY WATER AND SEWER AUTHORITY (BCWSA): \$1,000.00</b>            Section 2(10) 1st Offense \$1,000.00</p> <p><b>PECO: \$3,000.00</b>            Section 6.1(3) 1st Offense \$500.00</p> <p>Section 6.1(7) 1st Offense \$1,000.00</p> <p>Section 2(5)(i) 3rd Offense \$1,500.00</p> <p><b>MASTEC PROFESSIONAL SERVICES: \$250.00</b>            Section 4(2.2) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>The new requirement is that the facility owner needs to submit an AVR for all damages and violations. DPI asked if the facility owner made any contact with the excavator during the time of the ticket requests that were not responded to. Email received on 7/11/2025 stated that BCWSA will find out if there was any contact. On 7/14/2025 DPI Maki sent an email to Henkles and McCoy asking if any agreements were made to mark out. DPS Locke removed the 3 violations for 2(5)(i) because this is a service line and they are correct.</p> <p>*****</p> <p>The incident occurred on 1/24/2025 at 922 Bustleton Pike in Lower Southampton Township in Bucks County.</p> <p>A Water service line was hit and damaged.</p> <p>HENKELS AND MCCOY the excavator stated in their Alleged Violation Report (AVR) referring to LOWER BUCKS COUNTY JOINT MUNICIPAL AUTHORITY (LBCJMA) that “While hammering rock with excavator we hit the water service that was 5’1” off the mark and pulled the water service out of the curb stop. Call pa 1 call, PECO, and Lower South Hampton water department. There was no loss of water due to the copper line was squeezed shut at time of hit. Shut job down till utility showed up. They marked out what they want to dig. We hammered there dig area. Dug out ruff and started to hand dig to help water department on marking repair. After repair was made, we back filled with stone and cold patch”. Pictures and reports were provided.</p> <p>**Please note that the facility owner is Bucks County Water and Sewer Authority (BCWSA) and they repaired this damage.</p> <p>Mastec Professional Services is the final designer which was confirmed by PECO and a preliminary design ticket was provided. K D M ENGINEERING was not the final designer.</p> <p>Bucks County Water and Sewer Authority (BCWSA) the facility owner did not submit an AVR as of 5/20/2025. BCWSA AVR was received on 7/21/2025. The stakeholder review was sent on 7/01/2025. BCWA stated in their AVR that “Line strike of water service at 922 Bustleton Pike in Lower Southampton. Henkles and McCoy was the contractor doing the work and hit the water service in Bustleton Pike. When the hit was discovered, BCWSA was called out to assist. BCWSA had H&amp;K dig out the area for us to do the repair, took about an hour or two to fix. Line was marked on Bustleton but service did a turn after curb box that was unknown”.</p> <p>PECO the project owner did not submit an AVR as of 5/20/2025. Emergency ticket was responded to by PECO on 1/24/2025. DPI emailed PECO on 4/28/2025 asking who the final designer was for the incident occurred on 1/24/2025 at Bustleton Pike in Lower Southampton</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Township in Bucks County. A Water service line was hit and damaged. No AVR has been submitted as of 5/22/2025.</p> <p>K D M ENGINEERING was sent an email on 4/01/2025 asking if they are the final designer for this project, since they did submit a preliminary design ticket and if BUCKS COUNTY WATER AND SEWER AUTHORITY and Verizon ever responded to the designer's request for information. AVR and answers were due by 5/13/2025. No response was received as of 5/20/2025.</p> <p>*****</p> <p>*Ticket 20250081790 - 000 was submitted by Henkles and McCoy on 1/08/2025 at 12:30 with a response due by 1/10/2025.</p> <p>Bucks County Water and Sewer Authority (BCWSA) responded field marked on 1/09/2025. 2 renotify tickets were sent afterwards and BCWSA was asked to mark their lines.</p> <p>*Renotify Ticket 20250081790 - 001 was submitted by Henkles and McCoy on 1/15/2025 at 9:07. RNO Remarks—[Attention PECO you responded field marked. Caller advised cannot locate markings at 922 Bustelton Pike. Please return to site and mark property ASAP.</p> <p>PECO responded on 1/15/2025. PECO was renotified to respond to this ticket.</p> <p>*Renotify Ticket 20250081790 - 002 was submitted by Henkles and McCoy on 1/23/2025 at 8:54.</p> <p>RNO Remarks-- [ATTN ALL WATER AND SEWER CALLER STATES YOUR MARKINGS ARE GONE. PLEASE RETURN TO THE SITE AND REMARK YOUR LINES AND UPDATE YOUR RESPONSE. THANK YOU.]</p> <p>Bucks County Water and Sewer responded on 1/09/2025, but never responded to this second renotify ticket. They did respond after the damage occurred.</p> <p>*Ticket 20243301647-001 was submitted by Henkles and McCoy on 12/03/2024 at 12:30 RNO Remarks-- [ATTN UTILITIES. YOU RESPONDED AS FIELD MARKED. CALLER STATES THERE ARE NO MARKINGS ON SITE. PLEASE MARK YOUR LINES ASAP AS WORK IS STARTING TOMORROW MORNING. THERE WILL BE A TRAFFIC PATTERN SET UP BTWN 0900-1500 FOR FIELD MARKINGS. THANK YOU.]</p> <p>Lower Southampton Township responded "field marked" late on 12/04/2024. No violation was given for this late response.</p> <p>*Ticket 20243301647-000 was submitted by Henkles and McCoy on 11/25/2024 with a response due by 11/27/2024.</p> <p>Bucks County responded field marked on 11/25/2024, but were asked to mark when ticket 20243301647-001 was submitted. They never responded.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>*Renotify Ticket 20243301647-001 was submitted by Henkles and McCoy on 12/03/2024 with a response due by 12/03/2024</p> <p>*Preliminary Design ticket 20222552157 was submitted by MASTEC PROFESSIONAL SERVICES on 5/24/2023 with a response due by 6/08/2023. Bucks County Water and Sewer Authority did not respond through PA OneCall. Verizon responded with a conflict.</p> <p>VIOLATIONS Mastec Professional Services is in violation of: Section 4(2.2) – Failed to submit a design notification through the One Call System when a design drawing is completed. Recommendation: The penalty is applied. Compliance education is required.</p> <p>BUCKS COUNTY JOINT MUNICIPAL AUTHORITY (BCJMA) the facility owner never submitted an AVR. Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. 3X - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. See tickets 20250081790-000, 20250081790-001, 20250081790-002, where the excavator states that the water lines need to be marked. Recommendation: The penalties are applied. Online Compliance Training was recently completed</p> <p>PECO the project owner Section 6.1(3) – Released a project to bid or construction before final design was complete. Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Ticket 20250081790 – 001 names PECO as needing to mark their lines. Recommendation: The penalties are applied. Online Compliance Training was recently completed *****</p> <p>This violation was not cited in the case: K D M ENGINEERING is in violation of: Section 4(2.5) – Failed to comply with all requests for information by the commission relating to the commission's enforcement authority under this act within 30 days of receipt of request. An email was sent to dwalkes@dmengineering.com; cwilliams@kdmengineering.com on 4/01/2025 asking about the final designer and if BUCKS COUNTY WATER AND SEWER AUTHORITY and Verizon ever responded to the designer’s request for information.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>AVR and answers were due by 5/13/2025. No response was received as of 5/20/2025. PECO was also sent the question of who the final designer was and they responded on 5/20/2025 that Mastec Professional Services was the final designer. KDM never responded. KDM is a preliminary designer for this project.</p>	
52696	<p><b>Facility Owner:</b> VERIZON PA LLC <b>Contractor/Excavator:</b> Lower Paxton Township Authority <b>Other:</b> HERBERT ROWLAND AND GRUBIC INC (HRG)</p>	<p><u>On 2/5/2025 12:00:00 PM at MELBOURNE DR, LOWER PAXTON TWP, DAUPHIN</u> The incident occurred on 2/05/2025 on Melborne dr. between Scheffield Cir. And Continental Dr.</p> <p>A telecom line which cross bored into a storm sewer was discovered.</p> <p>LOWER PAXTON TOWNSHIP AUTHORITY the facility owner and excavator stated in their Alleged Violation Report (AVR) that While performing an emergency repair to the sewer stormwater system, it was found that telecom line shad been cross bored through the stormwater pipe and these lines were not properly marked as the existing lines were about 28" away from the painted marks on the street. Pictures were provided.</p> <p>HERBERT ROWLAND AND GRUBIC INC (HRG) was emailed and mailed and AVR request letter with questions which is due on 6/16/2025. Compliance Research provided design tickets for this area. On 4/28/2025 an email was received explaining that “The project is still be designed and permitted. Yes this is in an area that we are currently designing. The only information we have about the Verizon line is that LPT staff found it when a pipe a storm pipe opened up the ground surface and required an emergency repair. Do we still need to submit an AVR even though we have no involvement with the initial AVR, just overlapping project areas”. On 4/28/2025 DPI responded that no AVR is needed from HRG, since this emergency had nothing to do with the design. There is no designer for this isolated incident.</p> <p>Verizon the facility owner who was cross bored into the Sewer stormwater system was emailed and mailed an AVR request letter on 4/24/2025. No AVR nor contact has been made as of 6/11/2025. ***** *Emergency ticket 20250342075 was submitted by LOWER PAXTON TOWNSHIP AUTHORITY on 2/03/2025 with a response due by 2/06/2025. Comcast and Verizon responded, “field marked”.</p> <p><b>VIOLATIONS</b> VERIZON is in violation of: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work.</p>	<p><b>VERIZON PA LLC:</b> <b>\$4,500.00</b> Section 2(5)(i) Subsequent \$2,000.00</p> <p>Section 2(14) 1st Offense \$500.00</p> <p>Section 2(10) 3rd Offense \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		Section 2(14) - Failed to comply with all requests for information by the commission relating to the commission's enforcement authority under this act within 30 days of receipt of request.	
53578	<p><b>Facility Owner:</b> Columbia Gas of PA - North</p> <p><b>Contractor/Excavator:</b> James Johnson LLC</p> <p><b>Project Owner:</b> Armstrong</p> <p><b>Other:</b> Comcast</p> <p><b>Other:</b> Cranberry Township Butler County</p> <p><b>Other:</b> Penn Power / FirstEnergy</p>	<p><u>On 3/12/2025 11:07:00 AM at 525 GREENSPIRE CT, CRANBERRY TWP, BUTLER</u> Undisputed- Penn Power / FirstEnergy mailed a check. see attached info. *****</p> <p>Dispute- Penn Power/FirstEnergy is disputing penalty amount and requested a reduction of \$1,000. Penn Power said, Based on Penn Power’s investigation, Penn Power does not intend to dispute findings and penalties for the violations related to PA One Call ticket 20250621428. Since Penn Power’s line was not damaged, I am requesting your consideration of a reduced penalty from the \$1,000 imposed amount. See their attached letter. *****</p> <p>The incident occurred on Wednesday, March 12, 2025, at 525 Greenspire Court, in Cranberry Township, Butler County.</p> <p>A gas service line was damaged.</p> <p>Columbia Gas stated in their Alleged Violation Report (AVR) that “James Johnson LLC, working on behalf of Armstrong Cable, was directional drilling under a driveway to install a new cable drop to the residence when their drill head struck and damaged an accurately marked 2” plastic, medium pressure gas main. The gas main was not spotted prior to boring despite the gas main being in direct conflict. They notified 911, and 911 notified Columbia Gas when the damage occurred. Columbia Gas responded immediately to make the area safe and complete repairs. The local Field Operations Leaders and Damage Prevention Specialist met with the crew onsite regarding the requirement to spot all known facilities in the bore path to the depth of the planned bore prior to beginning. They advised that if there is anything unclear, they should renotify or call Columbia Gas directly to come back out. It was suggested that they move their bore path outside the tolerance zone of the gas main.” Columbia Gas provided photos of the damaged line and locate marks.</p> <p>James Johnson LLC and Armstrong, the project owner did not submit an AVR within 30 days of a line strike.</p> <p>20250621428- Routine ticket placed on 3/3/2025. No Response: the following Facility Owners did not finalize their response with “Field Marked” or “Clear No Facilities”. First response was “Scheduled Mark” on 3/5/2025, then second response was “Insufficient Information Do Not Dig” on 3/18/2025- Penn Power, Comcast Cable, Armstrong, Cranberry Township Butler County</p> <p>Violations:</p>	<p><b>James Johnson LLC: \$1,500.00</b> Section 5(11.2) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p><b>Armstrong: \$1,500.00</b> Section 6.1(7) 1st Offense \$1,000.00</p> <p>Section 2(5)(v) 1st Offense \$500.00</p> <p><b>Comcast: \$1,500.00</b> Section 2(5)(v) 3rd Offense \$1,500.00</p> <p><b>Cranberry Township Butler County: \$500.00</b> Section 2(5)(v) 1st Offense \$500.00</p> <p><b>Penn Power / FirstEnergy: \$1,000.00</b> Section 2(5)(v) 2nd Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>*James Johnson LLC is in violation of sections:  Section 5(11.2) – When using trenchless technology, Excavator failed to utilize at a minimum, the best practices published by the Common Ground Alliance, section 5.29 Trenchless Excavation.  Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line.  Recommendation: PUC Compliance Education Required and Penalties Applied</p> <p>*Armstrong is in violation of sections:  6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike.  2(5)(v) – Failed to respond to a routine One Call ticket. 20250621428  Recommendation: PUC Compliance Education Required and Penalties Applied</p> <p>*Penn Power is in violation of section:  2(5)(v) – Failed to respond to a routine One Call ticket. 20250621428  Recommendation: PUC Compliance Education Required and Penalty Applied</p> <p>*Comcast is in violation of section:  2(5)(v) – Failed to respond to a routine One Call ticket. 20250621428  Recommendation: PUC Compliance Education Required and Penalties Applied</p> <p>*Cranberry Township Butler County is in violation of section:  2(5)(v) – Failed to respond to a routine One Call ticket. 20250621428  Recommendation: PUC Compliance Education Required and Penalty Applied</p>	
54549	<p><b>Facility Owner:</b>  FIRSTENERGY / PENELEC  <b>Contractor/Excavator:</b>  Paul Somsky  <b>Project Owner:</b>  HILLCREST COMMONS  <b>Other:</b> REGION 9 HOUSING CORP  <b>Other:</b> VERIZON PA LLC</p>	<p><u>On 3/19/2025 8:00:00 AM at 1035A HILL ST, CHESTER HILL BORO, CLEARFIELD</u> Paul Somsky (excavator) is disputing. DPS Locke agreed to reduce all violations by 50% for first time offender who is attending education.</p> <p>*****  The incident occurred on 3/19/2025 at 1035A HILL ST. in CHESTER HILL BOROUGH in Clearfield Co.</p> <p>A Firstenergy / Penelec Primary Electric line was hit and damaged. No injuries occurred.</p> <p>FIRSTENERGY the facility owner stated in their Alleged Violation Report (AVR) that ” On March 13, 2025, Hillcrest Commons, Excavator, submitted POCS Routine ticket 20250722186 to repair a water line at 1035A Hill Street in Chester Hill Boro, Pennsylvania. On March 19, 2025, Penelec was notified that the Excavator dug into a primary electric line and made repairs.USIC, Penelec’s Contract Locator, investigated and determined the facilities were marked incorrectly”. Pictures and reports were provided.  An email was sent to Compliance Specialist on 5/28/2025 asking about any OneCall tickets that have</p>	<p><b>Paul Somsky: \$875.00</b>  Section 5(16) 1st Offense \$500.00</p> <p>Section 5(23) 1st Offense \$250.00</p> <p>Section 5(21) 1st Offense \$125.00</p> <p><b>HILLCREST COMMONS: \$1,000.00</b>  Section 6.1(7) 1st Offense \$1,000.00</p> <p><b>VERIZON PA LLC: \$1,000.00</b>  Section 2(5)(vii) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>been submitted by Paul Somski. On 6/02/2025 the OneCall Compliance Specialist responded that "I do not have any record of Paul Somsy having placed one call notifications in the past".</p> <p>DPI Maki spoke with Jim Eltringham, the person who submitted the one call ticket. Jim stated he was not the excavator, but he is the supervisor. He stated that Paul Somsy was the excavator. Jim had never heard of ACT 127-2024 or ACT 50. Jim had hired Paul Somsy to do the work.</p> <p>HILLCREST COMMONS is the project owner who employs Jim. AVR was due by 4/19/2025 and received on 5/21/2025. The AVR stated that "Jim Eltringham, the property superintendent, notified PA One Call before excavation was started to come mark the line. Jim marked the area in white that was to be excavated. PAOne Call came out and Jim met them on site and then directed also where the white lines were and the work was to be done. They used a sensor and marked electric lines but nothing in this particular area where the work was being done. A representative First Energy said it was the locating One Call service's fault when Jim showed them the photo of the marks and white lines before digging. An electric line was hit. Power went out on the property for five or six hours. Nobody was hurt. Power was restored, and the work was completed the next day. &gt;51 people were affected". On 5/28/2025 an email was received stating that "Hillcrest Commons is owned and managed by Region Nine Housing Corp. There are 80 units that all lost power at the site for several hours. The office lost power as well. This is how many people were affected".</p> <p>REGION 9 HOUSING CORP is the company that manages and owns Hillcrest Commons. On 5/20/2025 DPI Maki spoke with Holly and added her contact info to the case. Holly stated that she will fill out an AVR tomorrow and notify DPI Maki when that is completed</p> <p>DPI called Paul Somsy on 5/21/2025. Paul asked that I speak with his wife Lori and stated that she is better at paperwork. DPI explained what the AVR is and why one is needed. Lori stated that Paul has his own small business.</p> <p>Paul Somsy the excavator stated in his AVR that "Everything was marked with cones and white paint. The maintenance supervisor even showed him where we were going to dig and has pictures of everything before we started to dig. When the guy came back to remark the lines he put red marks where there wasn't any power just so he was covered. He was mad that he had to come back after we hit the line. His putting the extra red lines caused us a lot of unnecessary hand digging". The AVR lists Region 9 Corporation as the Project Owner. &gt;51 people were affected.</p> <p>VIOLATIONS Paul Somsy is in violation of:</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 5(23) – Excavator may not delegate their duty to submit a locate request to the One Call System to another person. The excavator shall have sole responsibility to submit each locate request to the One Call System</p> <p>Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line.</p> <p>Section 5(21) – Excavator failed to pay the annual fee for service provided by the One Call System.</p> <p>Recommendation: The penalty is applied. Compliance education is required.</p> <p>Violations reduced by 50% during stakeholder review to \$500, 250, and 125 - total \$850.00 first time offender who attended education.</p> <p>HILLCREST COMMONS is in violation of: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike or damaging a facility owner’s line during excavation or demolition work activities or if a project owner believes a violation of this act has been committed in association or demolition.</p> <p>Recommendation: The penalty is applied. Compliance education is required.</p> <p>Listed below are facility owners in violation of Act 127-2024, Section 2(5)(vii) Failed to respond to an emergency One Call ticket as soon as practicable.</p> <p>Verizon is in violation of: Section 2(5)(vii) – Failed to respond to emergency notification 20250783348 as soon as practicable following notification. Emergency ticket 20250783348 was requested on 3/19/2025 at 14:11. Verizon did not respond field marked until 3/21/2025.</p> <p>Recommendation: The penalty is applied. PUC Online Compliance Training was recently completed.</p>	
53910	<p><b>Facility Owner:</b> Peoples Gas Company <b>Contractor/Excavator:</b> Legendary lawn care <b>Project Owner:</b> HOMEOWNER</p>	<p><u>On 3/24/2025 2:00:00 PM at 236 EASTERN ST, NEW KENSINGTON CITY, WESTMORELAND</u> Legendary Lawn Care is disputing 5(2.1).</p> <p>DPI removed 5(8). Peoples reached out to 911 and clarified that 911 was contacted. Peoples AVR had 911 as not called. ****</p> <p>Incident occurred on March 24th, 2025, at 2pm on 236 Eastern Street, New Kensington City, Westmoreland County.</p> <p>A gas line was damaged.</p> <p>Peoples Gas Company's Alleged Violation Report (AVR) states, "contractor while installing block wall hit service line. Contractor did not have a 1 call but homeowner did that is why it was marked and correctly marked. The home owners ticket was 20250740215." AVR notes that 911 was not notified.</p> <p>811 comments note, "Legendary Lawn Care has not placed notifications with PA One Call in the past."</p>	<p><b>Legendary lawn care:</b> <b>\$2,500.00</b> Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>Section 5(23) 1st Offense \$500.00</p> <p><b>HOMEOWNER: \$0.00</b> Section 6.1(7) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Pictures from Peoples Gas Company show an excavator and line marked out from the homeowner's dig ticket.</p> <p>Legendary Lawn Care and the Homeowner have not submitted an AVR as of 5/19/2025.</p> <p>Violations:</p> <p>Legendary Lawn Care Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. PUC compliance education is required. Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid. PUC compliance education is required. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required. Section 5(23) – Excavator may not delegate their duty to submit a locate request to the One Call System to another person. The excavator shall have sole responsibility to submit each locate request to the One Call System. PUC compliance education is required.</p> <p>Homeowner Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Homeowner violation reduced to \$0 warning.</p>	
53762	<p><b>Facility Owner:</b> Penelec / First Energy <b>Contractor/Excavator:</b> Eagleway Communications <b>Project Owner:</b> Velocity Communications <b>Other:</b> Charter Communications <b>Other:</b> Erie Water Works <b>Other:</b> Everstream <b>Other:</b> Verizon</p>	<p><u>On 3/28/2025 9:00:00 AM at 5008 Sir Lancelot Dr, MILLCREEK TWP, ERIE</u> Penelec was previously disputing violation of 2(5)(v) only but are now accepting. They previously accepted 2(5)(i).</p> <p>Charter Communications accepts.</p> <p>The incident occurred on 03/28/2025 at 9:00 AM, at 5008 Sir Lancelot Drive, in Millcreek Township, Erie County.</p> <p>An electrical line owned by Penelec was damaged.</p> <p>Penelec, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “On 3/12/25 Eagleway Communications LLC, Excavator, submitted Routine ticket 20250714781 for Sir Lancelot Dr Millcreek Twp, Erie County, PA. Excavator was installing fiber and conduit for Velocity Network. On 3/28/25, the Excavator contacted Penelec to report a power outage at 4962 Sir Hue Drive due to a dig in while excavating. Penelec investigated and located a damaged unmarked underground secondary going to the residence. Penelec’s Contract Locator, USIC, investigated and determined that the root cause of the dig in was that the secondary line was marked just outside the tolerance zone by their technician.” Photos were submitted.</p> <p>Eagleway Communications, the excavator, submitted an AVR. Their AVR states, “During excavation, we struck</p>	<p><b>Penelec / First Energy: \$750.00</b> Section 2(5)(i) 1st Offense \$500.00</p> <p>Section 2(5)(v) 1st Offense \$250.00</p> <p><b>Charter Communications: \$250.00</b> Section 2(5)(v) 1st Offense \$250.00</p> <p><b>Erie Water Works: \$500.00</b> Section 2(5)(v) 2nd offense \$500.00</p> <p><b>Everstream: \$250.00</b> Section 2(5)(v) 1st Offense \$250.00</p> <p><b>Verizon: \$1,000.00</b> Section 2(5)(v) 2nd Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>a service power line that was marked incorrectly. Our crew was digging approximately 3 feet away from the marked line. The locate was inaccurate and led directly to the utility strike”. A photo was submitted.</p> <p>Velocity Communications, the project owner, submitted an AVR. Their AVR states, "The contractor states that the line got damaged when he put the anchor for his drill in the ground. The marks for the electric line were over 18 inches off from where they actually were and thus the break”. A photo was submitted.</p> <p>Routine ticket 20250714781 had a response due date of 03/14/2025.</p> <ul style="list-style-type: none"> <li>- Verizon did not respond to the ticket until 04/01/2025.</li> <li>- Penelec replied scheduled mark on 03/14/2025, stating they would mark by 03/19/2025 17:37. The line was not field marked until 03/26/2025.</li> <li>- Erie Water Works replied scheduled mark on 03/14/2025, stating they would mark by 03/19/2025 17:37. The line was not field marked until 03/27/2025.</li> <li>- Everstream replied scheduled mark on 03/14/2025, stating they would mark by 03/19/2025 17:37. The line was not field marked until 03/26/2025.</li> <li>- Charter Communications replied scheduled mark on 03/14/2025, stating they would mark by 03/19/2025 17:37. The line was not field marked until 03/26/2025.</li> </ul> <p>Violations:</p> <p>Penelec –</p> <ul style="list-style-type: none"> <li>- Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.</li> <li>- Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20250714781.</li> </ul> <p>Recommendation: The penalty is applied.</p> <p>Erie Water Works –</p> <ul style="list-style-type: none"> <li>- Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20250714781.</li> </ul> <p>Recommendation: The penalty is applied.</p> <p>Everstream –</p> <ul style="list-style-type: none"> <li>- Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20250714781.</li> </ul> <p>Recommendation: The penalty is applied.</p> <p>Charter Communications –</p> <ul style="list-style-type: none"> <li>- Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20250714781.</li> </ul> <p>Recommendation: The penalty is applied.</p> <p>Verizon -</p> <ul style="list-style-type: none"> <li>- Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket 20250714781.</li> </ul> <p>Recommendation: The penalty is applied.</p>	
53956	<b>Facility Owner:</b> National Fuel	On 4/1/2025 11:00:00 AM at 27 LIBERTY ST, FREDONIA BORO, MERCER The incident occurred	<b>JMR Excavating:</b> <b>\$4,000.00</b>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p><b>Contractor/Excavator:</b> JMR Excavating</p> <p><b>Project Owner:</b> FREDONIA BOROUGH</p>	<p>on 04/01/2025 at 11:00 AM, at 27 Liberty Street, in Fredonia Borough, Mercer County.</p> <p>A gas line owned by National Fuel was damaged. 911 was not notified.</p> <p>National Fuel, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, "Excavator struck natural gas distribution using power equipment while working within the tolerance zone. Please see attachments." Photos were submitted.</p> <p>JMR Excavating is the excavator. An AVR has not been filed as of 05/30/2025.</p> <p>Fredonia Borough is the project owner. An AVR has not been filed as of 05/30/2025.</p> <p>The submitted photos show the gas line marked using paint. The damage occurred within the tolerance zone.</p> <p>No indication that 911 was notified. National Fuel did not report if 911 was called in their AVR. An emergency ticket was not requested. An AVR was not received from the excavator. The submitted photos do not show any evidence of 911 being called.</p> <p>Ticket 20250871606 was entered as an insufficient ticket. (An insufficient ticket indicates the caller is stating they will begin their NON-emergency excavation before the minimum 3 business days.) The lawful start date listed on the ticket was 04/02/2025. Damage occurred on 04/01/2025.</p> <p>Ticket 20250871606 was requested by the project owner, Fredonia Borough. The excavator, JMR Excavating, did not submit a ticket request. (Excavator may not delegate their duty to submit a locate request to the One Call System to another person.)</p> <p>Ticket 20250871606 had a response due date of 04/01/2025. Fredonia Borough did not respond to this ticket.</p> <p>Violations:</p> <p>JMR Excavating–</p> <ul style="list-style-type: none"> <li>- Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.</li> <li>- Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe.</li> <li>- Section 5(23) – Excavator may not delegate their duty to submit a locate request to the One Call System to another person. The excavator shall have sole responsibility to submit each locate request to the One Call System.</li> <li>- Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been</li> </ul>	<p>Section 5(4) 1st Offense \$500.00</p> <p>Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(23) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>Section 5(8) 1st Offense \$1,000.00</p> <p><b>FREDONIA BOROUGH: \$1,500.00</b> Section 6.1(7) 1st Offense \$1,000.00</p> <p>Section 2(5)(v) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>committed in association with excavation or demolition work.</p> <ul style="list-style-type: none"> <li>- Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property.</li> </ul> <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Fredonia Borough-</p> <ul style="list-style-type: none"> <li>- Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike.</li> <li>- Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket 20250871606.</li> </ul> <p>Recommendation: The penalty is applied. PUC compliance training education is required. Facility owner/locator and project owner.</p>	
54000	<p><b>Facility Owner:</b> Peoples Gas  <b>Contractor/Excavator:</b> Independent Enterprises Inc.  <b>Project Owner:</b> Edgewood Borough  <b>Designer:</b> LENNON SMITH SOULERET ENGINEERING INC</p>	<p><u>On 4/4/2025 11:40:00 AM at ELMER ST, EDGEWOOD BORO, ALLEGHENY</u> The incident occurred on 4-4-25 at 12:00 PM, on Elmer street, in Edgewood Borough, Allegheny County.</p> <p>A gas line owned by Peoples Gas Company LLC was damaged.</p> <p>Peoples Gas Company LLC, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “INDEPENDENT ENTERPRISES working for Edgewood Borough struck and damaged a Peoples Gas service line. The service line was marked via measurements due to no signal from tracer wire. Peoples Gas used a VAC truck to spot the service line at the curb box and to attempt to find tracer wire. The wire at the curb box did not give useable signal and the line was marked via measurements. INDEPENDENT ENTERPRISES had field notice of a problem locate as show in the picture where the locator mark NO WIRE and PNG VAC to alert PNG VAC crews on where to work. In that same picture, you can see that there are water markings near where the damage occurred and prudent digging techniques should have been being used. In addition, there are no visible markings from any utility on the street to alert the crews that lines are in the area and an update ticket should have been placed.”</p> <p>Independent Enterprises, the excavator, submitted an AVR. Their AVR states, “Contractor was excavating to install new storm sewer when a 1" plastic gas service was struck. At 1 ft deep A longside Service line was running across ditchline and was off its mark 7ft. Address for service was 428 Elmer St. Contractor called 911 and Peoples Gas responded and fixed service line.”</p> <p>Edgewood Borough, the project owner, submitted an AVR. Their AVR has no summary.</p> <p>Lennon Smith Souleret Engineering Inc, the designer, submitted an AVR. Their AVR has no summary but does include a Supplement Info attachment with a summary of the event.</p>	<p><b>Peoples Gas: \$500.00</b>  Section 2(5)(i) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>The damage occurred on a brick paved street. PGC submitted 5 photos, and Independent Enterprises submitted 4, of the location with their AVR. Of PGC's photos, 3 show the site after the damage occurred, and 2 are of their marks prior to excavation, though the date of the picture cannot be determined. All 4 Independent Enterprises' photos are after the damage occurred and no marks remain on the road that are shown in PGC's photos taken prior to the damage occurring. The damage is indicated by a Hit Kit marker, and is within the tolerance zone of a blue mark shown in PGC's pre-damage photo, though no yellow mark is within the tolerance zone. Ticket #20250643640 New – Excavation – Routine was submitted on 3-5-25, with PGC responding "Field Marked" on 3-7-25. The damage occurred on 4-4-25. No additional renotify/remark tickets were submitted between Ticket #20250643640 New – Excavation – Routine on 3-5-25 and Ticket #20250942029 New – Damage – Emergency 4-4-25.</p> <p>Violations: Facility- PGC: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: PUC compliance training education was recently completed.</p>	
54090	<p><b>Facility Owner:</b> Hampton Shaler Water Authority <b>Contractor/Excavator:</b> Nigrelli Plumbing <b>Project Owner:</b> UNKNOWN</p>	<p><u>On 4/8/2025 9:41:00 AM at 35 Locust St, ETNA BORO, ALLEGHENY</u> The incident occurred on 4/08/2025 at 35 Locust St. in Etna Borough in Allegheny County.</p> <p>A water main was damaged. 37 addresses were affected.</p> <p>HAMPTON SHALER WATER AUTH stated in their Alleged Violation Report (AVR) that On April 8, 2025, Mike from Nigrelli Plumbing called the Hampton Shaler Water Authority office. Hampton Shaler Water Authority responded to the site and saw that the water service line was ripped out of the water main. This caused us to shut down the water main and make repairs. The excavator was digging on an expired one-call". Project is listed at &gt;\$400,000. And Level "A" Subsurface Utility Engineering (SUE) is noted. Pictures were provided. On 5/12/2025 an email was received with an attachment showing the affected area. DPI Maki counted 37 addresses that were affected per the sheet provided by the HSWA. . Compliance Research Results: No record of contractor placing One Call notifications with PA One Call in the past.</p> <p>Nigrelli Plumbing did not submit an AVR as of 6/11/2025. On 5/09/2025 DPI Maki emailed an AVR request letter and mailed an AVR request letter on 5/12/2025. Nigrelli Plumbing called right away and left a detailed message. A few minutes later, DPI Maki returned a call to Negrili Plumbing who stated that it was not Negrili who was excavating. He stated that they worked there and did</p>	<p><b>Nigrelli Plumbing:</b> <b>\$3,000.00</b> Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(17) 1st Offense \$500.00</p> <p>Section 5(21) 1st Offense \$250.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>have OneCall tickets. He will submit an AVR and get the tickets to me. He stated that they found the water under the plate, but did not hit it. He works for affordable Homes and described that he was working inside and outside. He also stated that Etna could not afford the upkeep of the water lines, so sold that utility to Hampton Shafer Water Authority. The water plates pop off all the time he says. He also stated that he can get a statement from Etna about this issue. He will submit an AVR.</p> <p>On 5/12/2025 DPI Maki mailed an AVR request letter to the address where the incident occurred. AVR was due by 6/12/2025. 35 Locust St. in Etna is a rental property. No AVR was submitted, no letter was returned.</p> <p><b>VIOLATIONS</b>  Nigrelli Plumbing is in violation of:  Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe.  Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area.  Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or damaging a facility owner’s line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.  Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within 30 days of the receipt of the request.  Section 5(21) – Excavator failed to pay the annual fee for service provided by the One Call System.  Recommendation: The penalty is applied. Compliance education is required.</p>	
54320	<p><b>Facility Owner:</b> AQUA PENNSYLVANIA INC.  <b>Contractor/Excavator:</b> RNS PLUMBING  <b>Project Owner:</b> HOMEOWNER</p>	<p><u>On 4/9/2025 8:00:00 AM at 202 JANET AVE, BRISTOL TWP, BUCKS</u> The incident occurred on 4/09/2025 at 202 Janet Ave in Bristol Township in Bucks County.</p> <p>A water line owned by Aqua PA Inc. was damaged.</p> <p>Aqua Pennsylvania Inc. stated in their Alleged Violation Report (AVR) that “ EXCAVATOR HIT WATER SERVICE LINE THAT WAS MARKED CORRECTLY” Pictures were provided.</p> <p>RNS Plumbing AVR was due by 5/09/2025. No AVR has been received as of 5/30/2025.</p> <p>Lisa Mezicco is the homeowner and project owner. No AVR was requested.  *****  *Ticket 20250792094 was submitted by RNS Plumbing on 3/20/2025 stating that the work is at 202 Janet Ave. Working from the sidewalk to the Street. Asking to mark public sidewalk, right of way and the</p>	<p><b>RNS PLUMBING:</b>  <b>\$1,500.00</b>  Section 5(16) 1st Offense \$1,000.00</p> <p>Section 5(4) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>street. Please include the grass area before the street. The responses were due by 3/24/2025.  *Emergency ticket 20250950124 was submitted by RNS Plumbing on 4/05/2025 at 10:50 a.m.  Aqua PA field marked on 4/05/2025 at 7:11 pm.  *Emergency ticket 20250990723 was submitted by Aqua Pennsylvania inc. on 4/09/2025 at 8:35 a.m.</p> <p>VIOLATIONS  Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or damaging a facility owner’s line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.  Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.  Recommendation: The penalties are applied. PUC Compliance Education is required.</p>	
54273	<p><b>Facility Owner:</b> Comcast  <b>Facility Owner:</b> First Energy - Met-Ed  <b>Facility Owner:</b> UGI Utilities  <b>Contractor/Excavator:</b> M &amp; A Excavating  <b>Project Owner:</b> homeowner  <b>Other:</b> Neighbor</p>	<p>On 4/9/2025 8:00:00 AM at 6 Tully Lane, Reading, PA 19601, BERN TWP, BERKS Incident occurred on April 8th,9th, and 16th of 2025 on 6 Tully Lane, Bern Township, Berks County.</p> <p>A gas was damaged on 4/8/25.  An electric line was damaged on 4/9/25.  A cable line was damaged on 5/16/25.</p> <p>Email from UGI states that they have no record of a gas line damage. No pictures for a gas line damage. Damage Prevention Investigator (DPI) provided additional information for UGI. UGI reached out for their local region who confirmed a line was damaged.</p> <p>UGI's AVR stated, "Excavator dug a sewer trench with mechanized equipment. In the process the trench collapsed and damaged our gas service. UGI was working next door and repaired the service. After further investigation, no paoc ticket can be found for M and A."</p> <p>Met-Ed's Alleged Violation Report (AVR) states, "On November 13, 2024, M and A Excavating LLC, Excavator, submitted POCS Routine Ticket 20243183049 to excavate for a new home construction at 6 Tully Lane, Bern Township, Berks County, Pennsylvania. On April 9, 2025, Met-Ed was notified of an outage at 4 Tully Lane. USIC, Met-Ed’s Contract Locator, investigated and determined that the Excavator damaged an accurately marked primary line near a transformer. The root cause of the damage is the Excavator failed to dig prudently within the Tolerance Zone."</p> <p>Comcast's AVR states, "CONTRACTOR WORKING AT 6 TULLY LN DAMAGED LINE AT 8 TULLY LN."</p> <p>Neighbor submitted three AVRs that state:  Incident 1 - "Excavator broke gas line while digging sewer or gas line for new home. THIS IS THE FIRST of</p>	<p><b>UGI Utilities: \$1,000.00</b>  Section 2(10) 1st Offense \$1,000.00</p> <p><b>M &amp; A Excavating: \$2,750.00</b>  Section 5(3) 1st Offense \$500.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(4) 1st Offense \$500.00</p> <p>Section 5(4) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p><b>homeowner: \$0.00</b>  Section 6.1(7) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>THREE INCIDENTS OF OUR UTILITY LINES BEING CUT BY EXCAVATOR. On 4/9/25 our electric line was severed while excavating and on 4/16/25 our cable/internet main was cut. Separate violation reports will be filed for those incidents."</p> <p>Incident 2 - "THIS IS THE SECOND of THREE INCIDENTS OF OUR UTILITY LINES BEING CUT BY EXCAVATOR AND UTILITY SERVICES BEING INTERRUPTED TO OUR HOUSE. On 4/8/25 our gas line was broken while excavating and on 4/16/25 our cable/internet main was cut. Separate violation reports will be filed for those incidents."</p> <p>Incident 3 - "Excavator cut the main cable/internet line and told me that "since it didn't spark when I cut it, I didn't worry about it." Service was out 6+ plus hours until I discovered it and inquired with excavator. THIS IS THE THIRD INCIDENT OF OUR UTILITY LINES BEING CUT BY EXCAVATOR. On 4/8/25 our gas line was broken while excavating. And on 4/9/25 our electric line was severed while excavating. Separate violation reports will be filed for those incidents."</p> <p>Pictures from Met-Ed show that the electric and cable lines were marked out in the tolerance zone. Other pictures also show an excavator being used.</p> <p>Violations:</p> <p>M &amp; A Excavating  Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. Gas. PUC compliance education is required.  Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Electric. PUC compliance education is required.  Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Cable. PUC compliance education is required.  Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required.  Section 5(3) – Excavator failed to preserve mark-outs or request a remark. Gas. PUC compliance education is required.</p> <p>Homeowner  Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike.</p> <p>UGI  Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
54217	<p><b>Facility Owner:</b> National Fuel Gas  <b>Contractor/Excavator:</b> High Tech Underground  <b>Project Owner:</b> Velocity Net  <b>Designer:</b> Velocity Net Placeholder</p>	<p>violation of this act has been committed in association with excavation or demolition work.</p> <p><u>On 4/10/2025 12:00:00 PM at DEVON LN, MILLCREEK TWP, ERIE</u> Non-damage incident occurred on April 10th, 2025, at 12pm along Devon Lane, Millcreek Township, Erie County.</p> <p>Gas lines were not potholed.</p> <p>National Fuel Gas' Alleged Violation Report (AVR) states, "Excavator performing trenchless excavation without potholing nearby National Fuel facilities. National Fuel has continuously expressed the need to pothole all affiliated areas near the excavators path of excavation. Please see attachments."</p> <p>Pictures from National Fuel Gas show trenchless technology being used to install Velocity Net Fiber lines across gas marks that were not potholed.</p> <p>High Tech Underground and Velocity Net were mailed and emailed a request for an AVR on 5/30/25.</p> <p>High Tech Underground submitted an AVR that included pictures and videos of them potholing Devon Lane.</p> <p>Velocity Net Communications' AVR states, "I was contacted a few days prior to this date that High Tech Underground were too close to the NFG lines and not potholing the lines. It was decided between myself and a representative from NFG that we would meet with High Tech and go over the situation. The three companies had a meeting on site to discuss what High Tech needed to do to follow the rules that NFG has about maintaining proper distance away from their lines and to go over options of routes that could be taken. All parties walked away from this meeting with a better understanding of how High Tech would proceed with the job. I was not made aware that an AVR was being put in and thought this was being taken care of just between the 3 companies, that is why my AVR is late."</p> <p>Documents indicate that High Tech Underground met with National Fuel Gas and Velocity Net about potholing techniques. Date of 4/9/25 was overlayed on High Tech Underground's images and videos that show them potholing and trenching with shovels. Extra pictures submitted by NFG are from Wynburne Avenue.</p> <p>No violations found due to dates of images and video showing potholing prior to incident date.</p>	
54165	<p><b>Facility Owner:</b> PECO  <b>Contractor/Excavator:</b> D E HARRIS SERVICES INC  <b>Project Owner:</b> Home Owner  <b>Other:</b> Chester Water Authority</p>	<p><u>On 4/14/2025 12:00:00 AM at 4947 CHESTER CREEK RD, BROOKHAVEN BORO, DELAWARE</u> Chester Water Authority - 2(5)(vii) Violation removed Southwest Delaware County Municipal Authority - 2(5)(vii) Reduced from \$1000 to warning - \$0  *****</p>	<p><b>PECO: \$1,000.00</b>  Section 2(5)(i) 2nd Offense \$1,000.00</p> <p><b>D E HARRIS SERVICES INC: \$2,000.00</b>  Section 5(6)(i) 1st Offense</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p><b>Other:</b> SOUTHWEST DELAWARE COUNTY MUNICIPAL AUTH</p>	<p>The incident occurred on 4/14/2025 at 12:00, at 4947 Chester Creek Rd, in Brookhaven Borough, Delaware County.</p> <p>A gas line owned by PECO was damaged. 911 was contacted.</p> <p>PECO An Exelon Company, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, "D E HARRIS SERVICES INC was excavating with an excavator to replace the sewer service under ticket number 20251040015 when they exposed a steel line 15.2 ' away from the gas mark outs instead of calling in an exposed unknown or re note the original ticket D E HARRIS SERVICES INC proceeded to cut into the steel sleeve that housed the 1/" plastic gas service with a saw while cutting into the steel sleeve they cut into the 1/2" plastic gas service., it was found that D E HARRIS SERVICES INC was not digging prudently and cut into the exposed gas service." Photos submitted show marks before the excavation and after the damage occurred. There are no marks within 18 inches of the damage, indicated by a hit kit.</p> <p>D E Harris Services INC, the excavator. An AVR request letter and email was sent on 5/14/2025. No AVR has been submitted as of 6/17/2025.</p> <p>Brian Otruba is the homeowner/project owner.</p> <p>Ticket # 20251040015 had a response due date of 4/14/2025. CHESTER WATER AUTHORITY AHRs responded "Field Marked" on 4/24/2025. SOUTHWEST DELAWARE COUNTY MUNICIPAL AUTH responded "Field Marked" on 4/21/2025,</p> <p>Violations:  Facility – PECO:  Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.  Recommendation: PUC Online Compliance Training was recently completed.</p> <p>Excavator - D E Harris Services INC:  Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area.  Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.  Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request.  Section 5(20) – Excavator failed to renotify One Call of an unmarked or incorrectly marked facility upon arrival at a work site.</p>	<p>\$250.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>Section 5(17) 1st Offense \$500.00</p> <p>Section 5(20) 1st Offense \$250.00</p> <p><b>Chester Water Authority: \$0.00</b></p> <p><b>SOUTHWEST DELAWARE COUNTY MUNICIPAL AUTH: \$0.00</b></p> <p>Section 2(5)(vii) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Recommendation: PUC Online Compliance Training is required.  Facility(Other)- SOUTHWEST DELAWARE COUNTY MUNICIPAL AUTH  Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification.  Recommendation: PUC Online Compliance Training is required.</p> <p>Facility(Other)- Chester Water Authority  Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification.  Recommendation: PUC Online Compliance Training is required.</p>	
54276	<p><b>Facility Owner:</b> PECO  <b>Contractor/Excavator:</b> DANELLA POWER SERVICES  <b>Project Owner:</b> PECO - SPACESAVER  <b>Designer:</b> PRIMERA ENGINEERS  <b>Other:</b> VERIZON</p>	<p><u>On 4/14/2025 12:00:00 AM at LINDEN WAY, UPPER MERION TWP, MONTGOMERY</u> The incident occurred on 4/14/2025 on Linden Way in Upper Merion Township in Montgomery County.</p> <p>A secondary electric line was damaged.</p> <p>PECO the project owner and facility owner stated in their Alleged Violation Report (AVR) that “Danella Power Services was excavating with an excavator to install electric for Peco under project ticket number 20250870457 when they pulled the secondary in front of transformer between addresses 2005 Linden Way and 1901 Linden Way, During the investigation on 4/16/2025 it was found that the prints provided at the time of the locate do not reflect the secondary running into the front of the transformer all electric prints show the electric entering the sides of the transformers not the front due to the mapping discrepancy the secondary was pulled”. 911 was notified. Directional Drilling was used. PECO added that there were Missing or incorrect facility line maps or records. No project information was provided.</p> <p>USIC report provided the Summary of the Event:” On 4/15/2025 USIC was notified by Peco of a damage that occurred on 4/14/2025 at 2005 Linden Way Upper Marion Twp Montgomery County PA, During the investigation it was found that Danella Power Services was excavating with an excavator to install electric for Peco under project ticket number 20250870457 when they pulled the secondary in front of transformer between addresses 2005 Linden Way and 1901 Linden Way, During the investigation on 4/16/2025 it was found that the prints provided at the time of the locate do not reflect the secondary running into the front of the transformer all electric prints show the electric entering the sides of the transformers not the front due to the mapping discrepancy the secondary was pulled. PECO submitted another AVR that stated “ON MONDAY, APRIL 14, 2025, AT APPROXIMATELY 5PM, A DANELLA CREW CONTACTED AN UNMARKED SECONDARY WIRE WHILE TRENCHING FOR INSTALLATION 3" CONDUIT. DURING THE TRENCHING PROCESS WITH THE MINI EXCAVATOR THE CREW STRUCK THE</p>	<p><b>PECO: \$1,500.00</b>  Section 6.1(3) 1st Offense \$500.00</p> <p>Section 2(5)(i.2) 1st Offense \$250.00</p> <p>Section 2(5)(i) 1st Offense \$500.00</p> <p>Section 9 1st Offense \$250.00</p> <p><b>PRIMERA ENGINEERS: \$750.00</b>  Section 4(2.2) 1st Offense \$250.00</p> <p>Section 4(3) 1st Offense \$250.00</p> <p>Section 4(5) 1st Offense \$250.00</p> <p><b>VERIZON: \$2,000.00</b>  Section 2(5)(v) Subsequent \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>UNMARKED SECONDARY WIRE". Report was provided.</p> <p>On 5/06/2027 DPI Maki asked PECO who the final designer was for this project and for the final design ticket#. PECO responded right away and stated that Primera is the final designer for this project. PECO did not know the final design number for this project. On 6/10/2025 PECO responded that the designer was not likely notified for this electric damage.</p> <p>DANELLA POWER SERVICES the excavator stated in their AVR that "On Monday, April 14, 2025, at approximately 5PM, a Danella crew contacted an unmarked secondary wire while trenching for installation 3" conduit. During the trenching process with the mini excavator the crew struck the unmarked secondary wire. The incident was not reported to Danella management or the Constitution Manager prior to the crew's departure on April 14, 2025.No project information was provided. Report was provided.</p> <p>Primera Engineers, the designer, did not submit an AVR.</p> <p>*Complex Project ticket 20242612489 was submitted by Danella power Services on 9/17/2024 and stated that "Complex Project meeting held on 9/24/2024 at 14:00 and states to refer to the comments, which gives the directions for lines be marked, 50 ft in all directions on multiple streets. Lawful start date on 10/01/2024". No facility owner responded that they requested a meeting.</p> <p><b>VIOLATIONS</b>  PECO is in violation of:  Section 6.1(3) – Released a project to bid or construction before final design was complete.  Section 2(5)(i.2) – Failed to document Communications between a Facility Owner and Excavator to ensure the excavator is aware of a facility owner's inability to locate it's facilities.  Recommendation: The penalties are applied. Facility owner and project owner compliance education is required..</p> <p>.Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.  Section 9 – Failed to make best efforts to comply with the Common Ground Alliance Best Practices Chapter 7(1)(B) Mandatory Education is considered as an alternative or supplement to penalties for offenders of the damage prevention laws and regulations. Compliance education has been due since 7/13/2025.  Recommendation: The penalties are applied. Facility owner and project owner compliance education is required.</p> <p>PRIMERA ENGINEERS is in violation of:  4(2.2) – Failed to submit a design notification through the One Call System when a design drawing is completed. This is a second offense.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 4(3) – Designer’s drawing does not show the position and type of each facility owner’s line, and the name of the facility.</p> <p>Section 4(5) – Designer’s drawing does not include One Call’s toll-free number and the serial number of the ticket.</p> <p>Recommendation: The penalties are applied. Designer compliance education was recently completed.</p> <p>VERIZON is in violation of:  Section 2(5)(v) – Failed to respond to routine One Call ticket 20250870457. Ticket response was due by 4/01/2025. Verizon did not respond ‘Field marked” until 4/15/2025. This is a subsequent offense.  Recommendation: The penalty is applied. Compliance education was recently completed.</p>	
54368	<p><b>Facility Owner:</b>  WESTMORELAND CO  MUNI AUTH  <b>Contractor/Excavator:</b> S &amp; E Utility Contracting  <b>Project Owner:</b> Penn Township of Westmoreland County  <b>Designer:</b> GIBSON THOMAS ENGINEERING CO INC</p>	<p><u>On 4/14/2025 11:00:00 AM at 2 HAWTHORNE LN, PENN TWP, WESTMORELAND</u> The incident occurred Monday, April 14, 2025, at 2 Hawthorne Lane, in Penn Township, Westmoreland County.</p> <p>A water line was damaged.</p> <p>Westmoreland County Municipal Authority (MAWC) stated that S &amp; E Utility Contracting failed to protect and preserve the markings during excavation, and failed to exercise due care and use prudent techniques within the tolerance zone. MAWC explained in their Alleged Violation Report (AVR) “S&amp;E Contracting was working for Project Owner Penn Township to install new storm sewer lines along Hawthorn Ln in Penn Township. S&amp;E struck an accurately marked Municipal Authority of Westmoreland County (MAWC) water service at 2 Hawthorn Ln. at approximately 11AM. MAWC received a phone call from the S&amp;E inspector at approximately 4pm notifying MAWC of the hit. MAWC responded and made the necessary repair. MAWC notes that the markings were barely visible due to dirt on street from construction activity.”  MAWC provided photos</p> <p>S &amp; E Utility Contracting and Penn Township of Westmoreland County did not submit their AVR's within 30 days of a line strike.</p> <p>The photos provided cannot determine violations of 5(3) or 5(4).  5(3) – Excavator failed to preserve mark-outs or request a remark.  5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.</p> <p>Violations:</p> <p>*S &amp; E Utility Contracting is in violation of sections:  5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line.  Recommendation: PUC Compliance Education Required and Penalty Applied.</p>	<p><b>S &amp; E Utility Contracting: \$1,000.00</b>  Section 5(16) 1st Offense \$1,000.00</p> <p><b>Penn Township of Westmoreland County: \$1,000.00</b>  Section 6.1(7) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>*Penn Township of Westmoreland County is in violation of section: 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike Recommendation: PUC Compliance Education Required and Penalty Applied.</p>	
54292	<p><b>Facility Owner:</b> Pennsylvania American Water (PAWC) <b>Contractor/Excavator:</b> Wilson Excavating <b>Project Owner:</b> Peoples Gas</p>	<p><u>On 4/14/2025 3:00:00 PM at 123 ALTADENA DR, MT LEBANON TWP, ALLEGHENY</u> The incident occurred on 04/14/2025 at 3:00 PM, on 123 Altadena Drive, In Mt Lebanon Township, Allegheny County.</p> <p>A water line owned by Pennsylvania American Water was damaged.</p> <p>Pennsylvania American Water, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “Wilson while digging to lay gas main for Peoples Gas hit and damaged a water service that was marked incorrectly. The service was mis-marked by approximately 3’. PAWC employee was told by Wilson contact that their crew vacuum excavated to locate and hand dug 2’ on both sides of mark and did not locate. Wilson did not call nor re-notify for additional marks.”</p> <p>Wilson Excavating, the excavator, submitted an AVR. Their AVR states, “Wilson Excavating was performing work on Altadena Dr in Pittsburgh when a mismarked PAW line was struck and damaged. The crew was digging to install 6" main line and after spotting 2 feet on either side of the marks and finding no line, the crew began to dig carefully outside the tolerance zone with the excavator. A copper service 3 feet away from the mark was struck and damaged. The facility owner was notified and came to the site to make repairs.” Photos were submitted.</p> <p>Peoples Gas, the project owner, submitted an AVR. Their AVR states, "Wilson Excavating was performing work on Altadena Dr in Pittsburgh when a mismarked PAW line was struck and damaged. The crew was digging to install 6" main line and after spotting 2 feet on either side of the marks and finding no line, the crew began to dig carefully outside the tolerance zone with the excavator. A copper service 3 feet away from the mark was struck and damaged. The facility owner was notified and came to the site to make repairs.”</p> <p>The submitted photos show the line was incorrectly marked. The mark was about 3 feet away from where the damage occurred.</p> <p>Violations:</p> <p>Pennsylvania American Water - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: The penalty is applied. (PUC compliance training education was recently completed.)</p>	<p><b>Pennsylvania American Water (PAWC):</b> <b>\$1,000.00</b> Section 2(5)(i) 2nd Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
54729	<p><b>Facility Owner:</b> COLUMBIA GAS OF PA INC_Central</p> <p><b>Contractor/Excavator:</b> THEAKSTON CONTRACTING</p> <p><b>Project Owner:</b> UPPER ST CLAIR TOWNSHIP</p>	<p><u>On 4/15/2025 10:40:00 AM at 344 OAKLAWN DR, UPPER ST CLAIR TWP, ALLEGHENY</u> The incident occurred on Tuesday, April 15, 2025, at 344 Oaklawn Drive, in Upper St. Clair Township, Allegheny County.</p> <p>A gas line was damaged</p> <p>Columbia Gas stated in their Alleged Violation Report (AVR) that Theakston Contracting working on behalf of Upper St. Clair Township, damaged an accurately marked company-side service line while excavating for a drainage ditch. The service line had been correctly marked by a Columbia Gas locator. The damage was reported to Columbia Gas by the locator, and both a Service Technician and Plant Crew were dispatched to the site. All necessary repairs and safety checks were completed. A Columbia Gas Damage Prevention Specialist (DPS) spoke with the crew and foreman on-site to review safe digging practices within the tolerance zone. The DPS also advised that an AVR would need to be completed for this incident and offered assistance with the process if needed. Columbia Gas provided photos of the damage</p> <p>Upper St. Clair Township stated in their AVR, Theakston Contracting was excavating at the provided located, and hit a gas line.</p> <p>Theakston Contracting did not submit an AVR within 30 days of striking the gas line.</p> <p>Violations:</p> <p>*Theakston Contracting is in violation of sections: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: PUC Compliance Education Required and Penalties Applied.</p>	<p><b>THEAKSTON CONTRACTING:</b> <b>\$1,500.00</b> Section 5(4) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>
54369	<p><b>Facility Owner:</b> WESTMORELAND CO MUNI AUTH OF</p> <p><b>Contractor/Excavator:</b> S &amp; E Utility Contracting</p> <p><b>Project Owner:</b> Penn Township of Westmoreland County</p> <p><b>Designer:</b> GIBSON THOMAS ENGINEERING CO INC</p>	<p><u>On 4/15/2025 2:00:00 PM at 4 HAWTHORNE LN, PENN TWP, WESTMORELAND</u> The incident occurred Tuesday, April 15, 2025, at 4 Hawthorne Lane, in Penn Township, Westmoreland County.</p> <p>A water line was damaged.</p> <p>Westmoreland County Municipal Authority (MAWC) stated that S &amp; E Utility Contracting failed to protect and preserve the markings during excavation, and failed to exercise due care and use prudent techniques within the tolerance zone. MAWC explained in their Alleged Violation Report (AVR) that “Excavator, S&amp;E Contracting was digging to install new storm sewer lines for Project Owner Penn Township Municipal Authority along Hawthorn Ln. in Penn Township. S&amp;E struck an accurately marked Municipal Authority of Westmoreland County water service at 4 Hawthorn Ln. Marks were very difficult to see due to the dirt on the street due to construction.”</p>	<p><b>S &amp; E Utility Contracting: \$1,000.00</b> Section 5(16) 1st Offense \$1,000.00</p> <p><b>Penn Township of Westmoreland County: \$1,000.00</b> Section 6.1(7) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>MAWC provided photos.</p> <p>S &amp; E Utility Contracting and Penn Township of Westmoreland County did not submit their AVR's within 30 days of a line strike.</p> <p>The photos provided cannot determine violations of 5(3) or 5(4).            5(3) – Excavator failed to preserve mark-outs or request a remark.            5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.</p> <p>Violations:</p> <p>*S &amp; E Utility Contracting is in violation of sections:            5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line.            Recommendation: PUC Compliance Education Required and Penalty Applied.            *Penn Township of Westmoreland County is in violation of section:            6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike            Recommendation: PUC Compliance Education Required and Penalty Applied.</p>	
54218	<p><b>Facility Owner:</b> Peoples Gas  <b>Contractor/Excavator:</b> INDEPENDENT ENTERPRISES  <b>Project Owner:</b> EDGEWOOD BOROUGH  <b>Designer:</b> Lennon Smith Souleret Engineering</p>	<p><u>On 4/16/2025 12:00:00 AM at WALNUT ST, EDGEWOOD BORO, ALLEGHENY</u> The incident occurred on 4/16/2025 at 2:57 PM, on Walnut St, in Edgewood Borough, Allegheny County.</p> <p>-No Damage-</p> <p>Peoples Gas Company LLC, a facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “INDEPENDENT ENTERPRISES working for EDGEWOOD BOROUGH placed 2 emergency locate requests for an ongoing project where they have damaged facilities multiple times. Rather than placing a routine update ticket, Independent has placed these 2 emergency tickets, for two different streets as emergencies.”            Coordinate PA documents provided show that the areas listed on the 2 Emergency Tickets are within the scope of a Complex Project started in 2024.</p> <p>Independent Enterprises is the excavator.</p> <p>Edgewood Borough is the project owner.</p> <p>Lennon Smith Souleret Engineering is the designer.</p> <p>Ticket #20251063784 New – Excavation– Emergency - “INSTALLING NEW SEWER MAIN, CATCH BASINS, AND MANHOLES. STARTING AT INTERSECTION OF BEECH AND WALNUT DOWN TO INTERSECTION OF WALNUT AND DEWEY STREET. REPLACING ENTIRE STREET CURB TO CURB- SPECIAL ATTN GAS COMPANY.”</p>	<p><b>INDEPENDENT ENTERPRISES:</b>  <b>\$1,000.00</b>            Section 5(22) 1st Offense \$500.00</p> <p>Section 5(22) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Ticket #20251063816 New – Excavation– Emergency – “INSTALLING NEW SEWER MAIN AND RESTORING ROAD CUBR TO CURB. - SPECIAL ATTN GAS.”</p> <p>No information was presented that shows an emergency existed, as defined in Act 127 of 2024. Additionally, the excavation locations were part of a complex project being planned since 2024.</p> <p>""Emergency' means a sudden or unforeseen occurrence involving a clear and immediate danger to life, property or the environment, including, but not limited to, serious breaks or defects in a facility owner's lines."</p> <p>Violations: Excavator - Independent Enterprises: Section 5(22) – Excavator provided a misrepresentation of an emergency excavation, subject to an administrative penalty imposed under section 7(10). Ticket # 20251063784</p> <p>Recommendation: PUC compliance training education is required. Section 5(22) – Excavator provided a misrepresentation of an emergency excavation, subject to an administrative penalty imposed under section 7(10). Ticket #20251063816</p> <p>Recommendation: PUC compliance training education is required.</p>	
55337	<p><b>Facility Owner:</b> Met Ed / First Energy <b>Contractor/Excavator:</b> JDA Underground LLC <b>Project Owner:</b> JDA Underground LLC - Placeholder <b>Other:</b> Comcast</p>	<p><u>On 4/16/2025 10:00:00 AM at 622 MEADOW DR, SOUTH LEBANON TWP, LEBANON</u> The incident occurred on 4/16/2025 at 10:00 AM, on 622 Meadow Dr, in South Lebanon Twp, Lebanon County.</p> <p>An electric line owned by Met Ed was damaged.</p> <p>Met Ed is the facility owner. Their Alleged Violation Report (AVR) states, “On April 1, 2025, JDA Underground LLC, Excavator, submitted POCS Routine Ticket 20250914573 to install new fiber lines at 626 Meadow Drive, Lebanon, Lebanon County, Pennsylvania. On April 16, 2025, Met-Ed was notified that Excavator damaged a marked secondary service while excavating and Met-Ed made repairs. USIC, Met-Ed’s Contract Locator, investigated and determined the root cause is that the Excavator failed to use prudent techniques while digging within the Tolerance Zone.” Met Ed submitted a damage report with pictures. The markout photos show an orange and red mark that have been painted over in black in the post-damage photo with what appears to be asphalt sealer. A side by side comparison of the before and after damage photos shows the damage was within the tolerance zone. A hit kit is used to show measurement.</p> <p>JDA Underground LLC is the excavator. An AVR has not been filed as of 06-17-2025. JDA Underground indicates themselves as the Project Owner in all Tickets and documents.</p> <p>Ticket #20250914573 had a response due date of 4/3/2025. Comcast and Metropolitan Edison Co / First Energy responded “SCHEDULED DATE &amp; TIME</p>	<p><b>Met Ed / First Energy:</b> <b>\$250.00</b> Section 2(5)(v) 1st Offense \$250.00</p> <p><b>JDA Underground LLC:</b> <b>\$1,500.00</b> Section 5(4) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p><b>Comcast: \$750.00</b> Section 2(5)(v) 3rd offense \$750.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>LINES WILL BE MARKED BY:04 Apr 2025 2359” on 4/3/2025, and “FIELD MARKED.” On 4/8/2025.</p> <p>Violations:  Excavator – JDA Underground LLC:  Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.  Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.  Recommendation: PUC Online Compliance Training is required.  Facility(other) – Comcast:  Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time.  Recommendation: PUC Online Compliance Training is required.  Facility(other) - Metropolitan Edison Co / First Energy:  Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time.  Recommendation: PUC Online Compliance Training is required.</p>	
54725	<p><b>Facility Owner:</b> COLUMBIA GAS OF PA</p> <p><b>Contractor/Excavator:</b> SMITH ELECTRIC SERVICE</p> <p><b>Project Owner:</b> Camp Trees Partners</p>	<p><u>On 4/16/2025 3:00:00 PM at 161 CAMP TRES RD, CRANBERRY TWP, BUTLER</u> Camp Trees Partners - provided information showing they are not the Project Owner - Removed Violation and Penalty  ****</p> <p>The incident occurred on 4/16/2025 at 3:00 PM, on 161 Camp Trees Rd, in Cranberry Twp, Butler County.</p> <p>A gas line owned by Columbia Gas was damaged. 911 was contacted.</p> <p>Columbia Gas, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “Smith Electric was performing excavation work on Camp Trees Road to install a light pole using a skid steer with an auger attachment when they struck and damaged a 4-inch plastic mainline owned by Columbia Gas. It was determined that no 811 One Call ticket had been placed prior to digging. Smith Electric immediately contacted 911, and Columbia Gas responded quickly to secure the area and complete the necessary repairs. Following the incident, Columbia Gas spoke with the crew on-site about the importance of calling 811 before any excavation. Additionally, the Damage Prevention team reached out to Rick from Smith Electric to further discuss the situation, explain the 811 law, and guide him through the Alleged Violation Report (AVR) process. A training presentation was offered to review safe digging practices and proper ticket placement. Rick agreed to follow up with a time and location for the presentation. Columbia Gas is currently awaiting confirmation and monitoring for AVR submission. Smith Electric was working for the HOA to install signs”. Columbia Gas submitted multiple photos showing the site, damage, and Excavator’s equipment.</p>	<p><b>SMITH ELECTRIC SERVICE: \$2,250.00</b>  Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p><b>Camp Trees Partners: \$0.00</b></p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Smith Electric Service is the excavator. An AVR has not been filed as of 5/19/2025.</p> <p>The Village at Camp Trees/ Camp Trees Partners is the project owner. An AVR has not been filed as of 5/19/2025.</p> <p>No tickets were located for this site.</p> <p>Violations:  Excavator – Smith Electric Service:  Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe.  Section 5(6)(i) – Excavator failed to inform each operator employed by the excavator at the work site of the information obtained.  Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.  Recommendation: PUC Online Compliance Training is required.</p> <p>Project Owner – Camp Trees Partners:  Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike.  Recommendation: PUC Online Compliance Training is required.</p>	
54441	<p><b>Facility Owner:</b> PECO  <b>Contractor/Excavator:</b> Homeowner  <b>Project Owner:</b> WALTER RYBAS  Placeholder  <b>Other:</b> Comcast</p>	<p><u>On 4/21/2025 12:00:00 AM at 900 6TH AVE, BRISTOL TWP, BUCKS</u> Incident occurred on April 21st, 2025, at 12am on 900 6th Avenue, Bristol Township, Bucks County.</p> <p>A gas line was damaged.</p> <p>PECO's Alleged Violation Report (AVR) states, "WALTER RYBAS was excavating with a backhoe under ticket number 20251111059 to install a water meter and tying in the sewer when they severed the unmarked 1/2 plastic gas service feeding 830 6th Ave, after reviewing tickets for this location and contractor it was found that WALTER RYBAS was working before his ticket was due, resulting in the line not being marked and being severed." AVR notes that 911 was notified.</p> <p>Routine ricket 20251111059 was placed 4/21/25 at 9:24 am and the damage was done on 4/21/25. PECO responded field mark on 4/23/25 and pictures are date stamped as 4/23/25. Legal start date was 4/24/25. Ticket also notes that excavator was installing underground utility laterals to the new home.</p> <p>Phone number matches the number for Walte Rybas &amp; Sons Construction. Ticket was placed as a homeowner and property records show excavator as the current owner.</p> <p>Violations:</p>	<p><b>Homeowner: \$1,000.00</b>  Section 1.1 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$0.00</p> <p><b>Comcast: \$750.00</b>  Section 2(5)(v) 3rd offense \$750.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Watler Rybas Section 1.1 – Excavator did not begin within legal timeframe. PUC compliance education is required. 20251111059</p> <p>Section 5(16) – Homeowner Failed to submit an Alleged Violation Report within 30 days of striking a line. PUC compliance education is required.</p> <p>Comcast Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time.</p>	
54345	<p><b>Facility Owner:</b> Peoples Gas Company <b>Contractor/Excavator:</b> D AND M CONTRACTING CASTELLI DEVELOPMENT <b>Project Owner:</b> ALTOONA WATER AUTHORITY WATER DIVISION <b>Designer:</b> GWIN DOBSON AND FOREMAN</p>	<p>On 4/21/2025 5:00:00 PM at 113 James Way, FRANKSTOWN TWP, BLAIR Altoona Water disputed 6.1(7). Violation was listed as a 6.1(3) in the synopsis but a 6.1(7) under the violation drop down. DPI removed the violation and penalty. ***</p> <p>GDF Disputed. DPI removed 4(2.4), 4(3), and 4(5) from documents. GDF is disputing 4(2). ****</p> <p>Peoples provided a pre excavation photo that accurately marks out the line. Violation for 2(5)(i) was removed. Picture is date stamped on the file information with 11/21/2024. This is the markout for ticket 20243241908. *****</p> <p>Incident occurred on April 21st, 2025, at 5pm along 113 James Way, Frankstown Township, Blair County.</p> <p>A gas line was damaged.</p> <p>D and M Contracting's Alleged Violation Report (AVR) states, "THE INSTALLATION OF THE WATER SERVICE TO HOUSE 113 JAMES WAY, PIT WAS DUG THEN WHILE USING THE HOLE HOG TO PUNCH ACROSS THE ROADWAY TO THE WATER MAINLINE, THE SMELL OF GAS WAS NOTICED." AVR notes that 911 was called.</p> <p>Allentown Water Authority Division's AVR states, "THE INSTALLATION OF THE WATER SERVICE TO HOUSE 113 JAMES WAY, PIT WAS DUG THEN D &amp; M EXPOSED AN 8 INCH STEEL PIPE ON THE SAME SIDE AS WERE DAMAGED 8 INCH PLASTIC PIPE WAS WHILE USING THE HOLE HOG TO PUNCH ACROSS THE ROADWAY TO THE WATER MAINLINE THE SMELL OF GAS WAS NOTICED"</p> <p>Gwin, Dobson, &amp; Foreman's AVR states, "While D&amp;M Contracting, Inc. was installing a water service at 113 James Way, they hit an 8" plastic gas main. The gas main was unmarked. The design drawings showed there was a gas line in this area. D&amp;M Contracting, Inc. performed exploratory excavation and located an 8" steel gas main. D&amp;M Contracting, Inc. was installing the water service when they hit an 8" plastic gas line, approximately 2 ft away from the steel gas main they had located. It was later determined that the 8" steel gas main was abandoned. Design One Call information from</p>	<p><b>Peoples Gas Company:</b> <b>\$1,000.00</b> Section 2(10) 1st Offense \$1,000.00</p> <p><b>D AND M CONTRACTING CASTELLI DEVELOPMENT:</b> <b>\$1,250.00</b> Section 5(4) 1st Offense \$500.00</p> <p>Section 5(20) 1st Offense \$250.00</p> <p>Section 5(3) 1st Offense \$500.00</p> <p><b>ALTOONA WATER AUTHORITY WATER DIVISION: \$0.00</b></p> <p><b>GWIN DOBSON AND FOREMAN: \$500.00</b> Section 4(2) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Peoples Natural Gas did not indicate there were two gas mains, one abandoned and one active, or what type of pipe it was, steel or plastic. It only indicated one gas line and D&amp;M Contracting, Inc. believed they had located it. Gwin, Dobson &amp; Foreman, Inc. was not notified until after the problem was resolved and the gas line was repaired and backfilled. Attached photos were provided by D&amp;M Contracting, Inc. and the Altoona Water Authority. Reference Alleged Violation Report (AVR) from D&amp;M Contracting, Inc. - Temporary AVR Number AT20251120011"</p> <p>DPI requested an AVR from Peoples on 6/6/25.</p> <p>Peoples Gas Company's AVR states, "TICKET WAS FIVE MONTH OLD SO MARKS WERE NOT THERE ANYMORE BUT THEY SPOTTED THE OLD BARE STEEL THINKING IT WAS OUR LINE. OUR LINE WAS PLASTIC. THEY SHOULD HAVE CALLED FOR A REMARK."</p> <p>Routine ticket was placed on 11/19/2024 and the damage occurred on 4/21/25. No update tickets or remarks were requested by D and M Contracting. D and M submitted screenshots of a video showing no marks, but there is no date stamp to show if the screenshots of the video were taken in November of 2024 or April of 2025. No gas or telecom marks are visible but google street view shows mark outs that identify the area of the steel line as telecom conduit and the gas line marked out at the road. Keep in mind the gas marks are fresh in the May Google Streetview. No final design tickets were placed by Gwin Dobson &amp; Foreman. Flag in the yard indicates the lateral.</p> <p>Violations:</p> <p>Peoples Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.</p> <p>D and M Contracting Section 5(20) – Excavator failed to renotify One Call of an unmarked or incorrectly marked facility upon arrival at a work site. PUC compliance education is required. Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. PUC compliance education is required. PUC compliance education is required. Section 5(3) – Excavator failed to preserve mark-outs or request a remark. PUC compliance education is required. PUC compliance education is required.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Gwin Dobson and Foreman  Section 4(2) – Designer failed to request the line and facility information prescribed by section 2(4) from the One Call System not less than ten nor more than ninety business days before final design is to be completed. PUC compliance education is required.  Section 4(3) – Designer’s drawing does not show the position and type of each facility owner’s line, and the name of the facility. PUC compliance education is required.  Section 4(5) – Designer’s drawing does not include One Call’s toll-free number and the serial number of the ticket. PUC compliance education is required.  Section 4(2.4) – Failed to inform the project owner of the project owner's duties under sections 5(15) and 6.1(1). PUC compliance education is required.</p> <p>ALTOONA WATER AUTHORITY WATER DIVISION  Section 6.1(3) – Released a project to bid or construction before final design was complete.</p>	
55017	<p><b>Facility Owner:</b> PEOPLES GAS  <b>Contractor/Excavator:</b> CURRY AND KEPPLER INC  <b>Project Owner:</b> New Kensington City Municipal Authority  <b>Designer:</b> GIBSON THOMAS ENGINEERING CO INC</p>	<p><u>On 4/22/2025 9:00:00 AM at 1565 FAIRMONT DR, NEW KENSINGTON CITY, WESTMORELAND</u>  Kerry And Kepple - 5(7) reduced to warning of \$0  *****  The incident occurred on 4/22/2025 at 9:00 AM, on Fairmont Dr, in New Kensington City, Westmoreland County.</p> <p>A gas line owned by Peoples Gas was damaged. 911 was contacted.</p> <p>Peoples Gas is the facility owner. Their Alleged Violation Report (AVR) states, “MARKED BY MEASUREMENT DUE TO NO WIRE AT LOCATION. THE MEASUREMENTS WERE 36 INCHES OFF FROM WERE THE SERVICE WAS ACTUALLY AT.” Additional information obtained through email indicates that Curry &amp; Kepple Inc did not directly notify Peoples Gas of the damage.</p> <p>Curry And Kepple Inc is the excavator. Their AVR states, “the operator and laborer was looking for the gas line inside the tolerance zone and struck the lie line 3 feet from mark”.</p> <p>Municipal Authority Of The City Of New Kensington is the project owner. Their AVR states, “While digging to install new water main, the excavator struck the gas service line to 1565 Fairmont Street. The marking for the gas service was off by 3 feet.”</p> <p>Gibson Thomas Engineering Co Inc is the designer. Their AVR states, “Excavating to find a marked gas service line. Line was struck 3' from mark on pavement.”</p> <p>Multiple photos were submitted showing the site and damage. The yellow mark is over 3' away from the damage, as shown using a Hit Kit.</p>	<p><b>PEOPLES GAS: \$1,000.00</b>  Section 2(5)(i) 2nd Offense \$1,000.00</p> <p><b>CURRY AND KEPPLER INC: \$0.00</b>  Section 5(7) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>This case is related to case 054914 by Ticket#20250772685 and #20250974165.</p> <p>Violations:  Facility - Peoples Gas:  Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.  Recommendation: PUC compliance training was recently completed.</p> <p>Excavator - Curry And Kepple Inc:  Section 5(7) – Failed to immediately report to the facility owner any break or leak in its lines, or any dent, gouge, groove, or other damage to such lines or to their coating or cathodic protection.  Recommendation: PUC compliance training education is required.</p>	
54355	<p><b>Facility Owner:</b> Verizon  <b>Contractor/Excavator:</b> PEOPLES NATURAL GAS  <b>Project Owner:</b> PEOPLES NATURAL GAS (Placeholder)</p>	<p><u>On 4/22/2025 12:40:00 PM at 104 JAMES ST, NORTH UNION TWP, FAYETTE</u> Peoples Gas accepts.</p> <p>*****</p> <p>The incident occurred on 04/22/2025 at 12:40 PM, at 104 James Street, in North Union Township, Fayette County.</p> <p>A telecom line owned by Verizon was damaged.</p> <p>Verizon is the facility owner. An Alleged Violation Report (AVR) has not been filed as of 06/06/2025.</p> <p>Peoples Gas, the excavator and project owner, submitted an AVR. Their AVR states, “On 4/22/25 at 12:40 PNG construction crew working to install gas line struck a marked Verizon line. PNG crew was attempting to clean out ditch with excavator and curled bucket into Verizon line severing it. PNG notified 811 of damage and Verizon arrived onsite and made repairs.” Photos were submitted.</p> <p>The submitted photos show orange paint and flags. The line damage occurred within the tolerance zone.</p> <p>Violations:</p> <p>Peoples Gas-  - Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.  Recommendation: The penalty is applied. [No education requirement as Peoples Gas has recently completed the excavator education.]</p> <p>Verizon-  - Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work.</p>	<p><b>Verizon: \$1,500.00</b>  Section 2(10) 2nd Offense  \$1,500.00</p> <p><b>PEOPLES NATURAL GAS: \$500.00</b>  Section 5(4) 1st Offense  \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Recommendation: The penalty is applied. [No education requirement as Verizon has recently completed the facility owner/locator education.]</p>	
54501	<p><b>Facility Owner:</b> Middletown Township Public Works <b>Contractor/Excavator:</b> Utility Line Services <b>Project Owner:</b> AQUA PENNSYLVANIA INC <b>Designer:</b> Total Engineering And Consulting LLC <b>Other:</b> PECO</p>	<p><u>On 4/23/2025 10:00:00 AM at PARKMOUNT RD, MIDDLETOWN TWP, DELAWARE</u> The incident occurred on 4/23/2025 at 10:00 AM, on Parkmount Rd, in Middletown Twp, Delaware County.</p> <p>An electric line was damaged. The facility was notified of the damage.</p> <p>Middletown Township Delaware County is the facility owner. Their Alleged Violation Report (AVR) states, “Contractor struck electric line for traffic signal, while prepping work site. Traffic flow was interrupted until repairs were made by owners contractor. Owner was contacted by Utility company via phone call and emergency One-Call notification, after the strike and service damage.” PA One Call has indicated that Middletown Township Delaware County Public Works is not a member of PA One Call. The only Middletown Township facility included on the Tickets for this location is Middletown TWP Delaware Co. Sewer Auth.</p> <p>Utility Line Services Inc is the excavator. Their AVR states, “While the saw cutters were cutting a test hole in the area of Parkmount Road near Pennell Road they cut through an unmarked conduit containing electric wires controlling the traffic light. The road is 17" thick and the conduit was just 12" deep.” Photos submitted with the AVR do not show any marks within the tolerance zone of the excavation.</p> <p>Aqua Pennsylvania Inc is the project owner. Their AVR states, “While the saw cutters were cutting a test hole in the area of Parkmount Rd near Pennell Rd they cut through an unmarked conduit containing electric wires controlling the traffic light. The road is 17" thick and the conduit was just 12" deep.”</p> <p>Total Engineering And Consulting LLC is the designer. An AVR has not been filed as of 6-9-2025.</p> <p>Ticket #20251051884 -01 Renotify – Excavation – Insufficient was entered at 6:43 AM on 4/23/2025. PECO responded “Clear.” at 11:13 AM. Previous response to 20251051884-00 on 4/18/2025 was “Field Marked”, which was after the Response Due Date of 4/17/2025.</p> <p>This Case is related by Ticket# 20251051884 to Case 054860.</p> <p>Violations: Facility - Middletown Township Delaware County: Section 2(1) – Facility owner is not a member of One Call. Section 2(1)(ii)(A) – Failed to provide the One Call System with the counties, municipalities, and wards in which it lines are located.</p>	<p><b>Middletown Township Public Works: \$1,000.00</b> Section 2(5)(i) 1st Offense \$500.00</p> <p>Section 2(1)(ii)(A) 1st Offense \$250.00</p> <p>Section 2(1) 1st Offense \$250.00</p> <p><b>PECO: \$500.00</b> Section 2(5)(v.1) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: PUC Online Compliance Training is required.</p> <p>Facility(other) – PECO:            Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification.            #20251051884-01            Recommendation: PUC Online Compliance Training was recently completed.</p>	
54416	<p><b>Facility Owner:</b> UGI  <b>Contractor/Excavator:</b> KINSLEY CONSTRUCTION  <b>Project Owner:</b> UGI- Placeholder  <b>Designer:</b> UGI- Placeholder  <b>Other:</b> ZAYO Group</p>	<p><u>On 4/23/2025 10:51:14 AM at 906 FOUNTAIN AVE, MANHEIM TWP, LANCASTER</u> The incident occurred on 4/23/2025 at 10:51:00 AM, on Fountain Ave, in Manheim Twp, Lancaster County.</p> <p>A gas line owned by UGI Utilities was damaged. 911 was contacted.            Number Evacuated - 5            Repair Cost \$1,001-\$5,000</p> <p>UGI Utilities, Inc is the facility owner, project owner, and designer. Their AVR states, “Excavator utilizing mechanized equipment, struck a correctly marked gas service at the main, resulting in damage to the main.” UGI was not contacted directly by the Kinsley Construction when the damage occurred.</p> <p>Kinsley Construction LLC is the excavator. Their AVR states, “On 4/23/2025, Connor Ekis was operating a mini excavator while digging in the tolerance zone of a gas service. Connor did have a spotter with him, who was complicit in the breach of the tolerance zone with mechanized equipment. Connor stated he assumed the service was at 39" due to finding a service at that depth on another section of the street. Connor stated he was digging at 25" and thought he had space before the service. I, Blair Stevens, informed both Thomas, the spotter, and Connor that even though he was at 25", he was still well within the tolerance zone of the gas service even if the depth was 39", as he believed. Connor and Thomas simply replied "oh". Connor also stated he was using the mini excavator to "make Thomas' life easier" regarding hand digging. These statements imply gross negligence on the part of the operator and spotter. After the damage, emergency services were alerted and responded to the job site. 811 was also notified, with a UGI crew responding to make the necessary repairs. Gas flow to the damaged section on the gas main was stopped by placing (2) 6-inch bags into the pipe. The damaged section on the gas main was cut and abandoned, with an end cap being placed on the main. A nitrogen slug was placed in the main to clear it of any residual gas. Repairs began at 1030 and were completed at 1600. Members of the crew assisted safety in alerting residents on both sides of the street. The residences of 903, 905, 906, and 910 Fountain Ave. were evacuated.”</p>	<p><b>KINSLEY CONSTRUCTION:</b>  <b>\$1,000.00</b>            Section 5(4) 2nd Offense            \$1,000.00</p> <p><b>ZAYO Group: \$250.00</b>            Section 2(5)(v) 1st Offense            \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Multiple photos were submitted of the site and damage. The damage is within the tolerance zone of the yellow marks, as shown using a hit kit.</p> <p>Ticket # 20250773019 had a response due date of 3/20/2025. ZAYO BANDWIDTH FORMERLY PPL TELCOM LLC responded “Clear” on 3/26/2025.</p> <p>This case is related to Case: 050602, and 052496 by Final Design Ticket #20240330380.</p> <p>This case is related to Case: 054034 by Final Design Ticket #20221650930.</p> <p>Violations:</p> <p>Excavator- Kinsley Construction LLC: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: PUC compliance training was recently completed.</p> <p>Facility (Other) - ZAYO BANDWIDTH FORMERLY PPL TELCOM LLC: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket # 20250773019 Recommendation: PUC compliance training education is required.</p>	
54674	<p><b>Facility Owner:</b> Pennsylvania American Water (PAWC)</p> <p><b>Contractor/Excavator:</b> UGI UTILITIES, INC.</p> <p><b>Project Owner:</b> UGI Utilities, Inc - Placeholder</p> <p><b>Other:</b> Dunmore Borough</p>	<p><u>On 4/24/2025 1:19:00 AM at 207 E DRINKER ST, DUNMORE BORO, LACKAWANNA</u> The incident occurred on 4/24/2025 at 1:19:00 PM, on 207 E Drinker St, in Dunmore Borough, Lackawanna County.</p> <p>A water line owned by PA American Water was damaged.</p> <p>PA American Water is the facility owner. An Alleged Violation Report (AVR) has not been filed as of 6-23-2025</p> <p>UGI Utilities, Inc is the excavator and project owner. Their AVR states, “UGI crew struck and damaged an incorrectly marked water main”. UGI submitted 2 photos of the site and damage. A Hit Kit is shown indicating the damage was over 3’ away from the visible blue mark.</p> <p>Dunmore Borough (DMR) did not respond to ticket # 20251140008 New – Damage – Emergency through PA One Call.</p> <p>Violations: Facility - PA American Water: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a</p>	<p><b>Pennsylvania American Water (PAWC):</b> <b>\$2,000.00</b> Section 2(5)(i) 2nd Offense \$1,000.00</p> <p>Section 2(10) 1st Offense \$1,000.00</p> <p><b>Dunmore Borough:</b> <b>\$1,000.00</b> Section 2(5)(v) 2nd Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>violation of this act has been committed in association with excavation or demolition work. Recommendation: PUC compliance training education is required.</p> <p>Facility(other) - Dunmore Borough (DMR): Section 2(5)(v) – Failed to respond to a routine One Call ticket. Recommendation: PUC compliance training education is required.</p>	
54444	<p><b>Facility Owner:</b> PEOPLES GAS COMPANY <b>Contractor/Excavator:</b> A LIBERONI <b>Project Owner:</b> PENNDOT</p>	<p><u>On 4/24/2025 10:00:00 AM at 4092 MOUNT ROYAL BLVD, HAMPTON TWP, ALLEGHENY</u> The incident occurred Friday, April 24, 2025, at 4092 Mount Royal Blvd, in Hampton Township, Allegheny County.</p> <p>A gas line was damaged.</p> <p>Peoples Gas Company stated in their Alleged Violation Report (AVR) that contractor, A. Liberoni struck an accurately marked PNG 4" PL ML while doing drainage work. PNG crews were called and repairs were made. A.Liberoni stated in their AVR, Excavator struck gas line while digging out pipe. PennDOT did not submit an AVR within 30 days of the line strike. Peoples Gas provided photos of the damage line. The Fire department responded to the 911 call and service was interrupted for 1 - &lt; 6 hours.</p> <p>Violations:</p> <p>*A.Liberoni is in violation of section: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: Penalty Applied.</p> <p>*PennDOT is in violation of section: 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Recommendation: PUC Compliance Education Required and Penalty Applied.</p>	<p><b>A LIBERONI: \$1,000.00</b> Section 5(4) 2nd Offense \$1,000.00</p> <p><b>PENNDOT: \$1,000.00</b> Section 6.1(7) 1st Offense \$1,000.00</p>
55111	<p><b>Facility Owner:</b> Peoples Gas Company <b>Contractor/Excavator:</b> A FOLINO CONSTRUCTION INC <b>Project Owner:</b> Pittsburgh Department of Mobility and Infrastructure</p>	<p><u>On 4/24/2025 10:45:00 AM at NORTH BRADDOCK AVE, PITTSBURGH CITY, ALLEGHENY</u> The incident occurred on 4/24/2025 at NORTH BRADDOCK AVE between Hamilton Ave. and Fleury Way in Pittsburgh City in Allegheny County.</p> <p>A gas line owned by Peoples Gas was damaged.</p> <p>A FOLINO CONSTRUCTION stated in their Alleged Violation Report (AVR) that “A. Folino Construction was digging at the corner of N Braddock Ave and Kelly St to prep to pour new road base when we hit an unmarked gas service line. 911 was called and a damage ticket was made through 811. Peoples Gas responded and claimed the line as theirs. Peoples Gas had a crew come out and make the repairs”. 911 was notified. Pictures were provided.</p>	<p><b>Peoples Gas Company: \$2,000.00</b> Section 2(5)(i) Subsequent \$2,000.00</p> <p><b>A FOLINO CONSTRUCTION INC: \$250.00</b> Section 5(2.2) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>PEOPLES GAS COMPANY LLC stated in their AVR that “A FOLINO working for Pittsburgh Department of Mobility and Infrastructure struck and damaged a Peoples Gas service line. The work area was outline in white and Peoples Gas marked the facilities near the white marked area. As shown in the pictures, the damage occurred well outside the white marked area. Had this area been marked in white, Peoples Gas would have located the damaged service line prior to excavation starting. Picture of the area marked in white was provided.</p> <p>PITTSBURGH CITY DEPT OF MOBILITY &amp; INFRA stated in their AVR that “A. Folino Construction was digging at the corner of N. Braddock Ave and Kelly Street to repair base for upcoming paving. The backhoe pulled a gas line that was not marked. 911 was called and a damage ticket was made through 811. Peoples gas came out and repaired the line”. 911 was notified. Work was done for road maintenance.</p> <p>VIOLATIONS</p> <p>A FOLINO CONSTRUCTION is in violation of: Section 5(2.2) – Excavator failed to provide exact information to identify the worksite. Ticket 20251002668 reads that the worksite is North Braddock Ave between Hamilton Ave and Fleury Way. Ticket is checked showing that it is not at intersections, not between intersections and not marked in white or pink. Recommendation: The penalty is applied. Compliance Education was recently attended.</p> <p>Peoples Gas is in violation of: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. 2 tickets that were submitted with the case responded “NO” to marked in white. Ticket 20251051290 states that the excavation site is marked in pink. *Emergency ticket 20251141597 states that the site was marked in pink. Peoples Gas stated that the area of the damage was not marked in white, so they did not locate in that area where the damage occurred. They stated that they did mark the other area that was marked in white. Please see AVR2025MAY010012 statement. Peoples Gas should have confirmed that the white markings showing the construction area were the correct ones to mark. This is a subsequent offense. Recommendation: The penalty is applied. Compliance education was recently completed.</p> <p>*AVR’s that were submitted by A Folino and Peoples Gas check that white marks were used.</p>	
54449	<p><b>Facility Owner:</b> UGI Utilities  <b>Contractor/Excavator:</b> G and M Crawford Inc  <b>Project Owner:</b> Veolia</p>	<p><u>On 4/24/2025 11:00:00 AM at VILLA ST FROM ACADEMY AVE TO S. HUNTINGTON AVE, MAHONING TWP, MONTOUR</u> The incident occurred on 04/24/2025 at 11:00 AM, on Villa Street from Academy Avenue to South Huntington Avenue, in Mahoning Township, Montour County.</p>	<p><b>UGI Utilities: \$500.00</b>  Section 2(5)(i.1) 2nd Offense \$500.00</p> <p><b>Veolia: \$1,500.00</b></p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p><b>Designer:</b> GHD Engineering</p>	<p>A gas line owned by UGI Utilities was damaged. 911 was called.</p> <p>UGI Utilities, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “A gas service was struck and damaged at 742 Bloom St, Bloomsburg. UGI is unable to prove that the service line was marked, however, the One Call ticket was 37 days old at the time of the damage. There was no update ticket placed, and it appeared that utility markings were not maintained. (See images of overall project)”. Photos were submitted.</p> <p>G and M Crawford Inc, the excavator, submitted an AVR. Their AVR states, “Main line was marked; we located main by hand digging. started to excavate on other side of main and hit service lateral that was not marked”. Photos were submitted.</p> <p>Veolia is the project owner. An AVR has not been filed as of 06/18/2025.</p> <p>Violations:</p> <p>UGI Utilities-</p> <ul style="list-style-type: none"> <li>- Section 2(5)(i.1) – Failed to locate an actually known facility’s point of connection to its facilities.</li> </ul> <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Veolia-</p> <ul style="list-style-type: none"> <li>- Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike.</li> </ul> <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Veolia is delinquent on project owner education ordered by the DPC on 2/2/24 for case 44580.</p>	<p>Section 6.1(7) 2nd Offense \$1,500.00</p>
54479	<p><b>Facility Owner:</b> PEOPLES GAS COMPANY LLC <b>Contractor/Excavator:</b> INDEPENDENT ENTERPRISES <b>Project Owner:</b> Edgewood Borough <b>Other:</b> Wilkinsburg Penn Joint Water Authority</p>	<p><u>On 4/24/2025 12:00:00 PM at 434 ELMER ST, EDGEWOOD BORO, ALLEGHENY</u> The incident occurred on Thursday, April 24, 2025, on 434 Elmer Street, in Edgewood Borough, Allegheny County.</p> <p>A gas line was damaged.</p> <p>Peoples Gas Company stated in their Alleged Violation Report (AVR), Independent Enterprises Edgewood Borough to install new sanitary sewer and Wilkinsburg Penn Joint Water Authority to install new water lines struck and damaged a properly marked Peoples Gas owned service line to 434 Elmer Street. This damage occurred 5 business days after an emergency request was placed. INDEPENDENT ENTERPRISES has been working on this street for over a month doing sewer work. On Wednesday 4-16-25, INDEPENDENT ENTERPRISES called in an emergency ticket for install sewer mains and laterals with an excavation start date and time of Thursday, 4-17 at 0700. This is the completion notes from the Peoples Gas locator when</p>	<p><b>INDEPENDENT ENTERPRISES:</b> <b>\$3,500.00</b> Section 5(3) 1st Offense \$500.00</p> <p>Section 5(4) 2nd Offense \$1,000.00</p> <p>Section 5(22) 1st Offense \$500.00</p> <p>Section 5(16) 2nd Offense \$1,500.00</p> <p><b>Edgewood Borough:</b> <b>\$2,000.00</b> Section 6.1(7) 1st Offense \$1,000.00</p> <p>Section 2(5)(vii) 1st</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>they responded to this emergency ticket for Sewer work. Spoke with Ryan the caller. He has no idea what is going on with this emergency. Spoke with crew on site and they have no idea. Finally spoke to Neil, he stated this is an "emergency" water line job. THIS IS IN FACT NOT AN EMERGENCY. No one is out of water and there is no threat to life or property. This one call does not even state they are doing the water line so there is no active one call for the water line currently. Stated to Neil that Ryan needs a NEW ROUTINE one call for the water line. INDEPENDENT ENTERPRISES to date has NOT placed a Routine ticket for Water line or an update after the emergency ticket placed 4-16-2025.</p> <p>AVR's were not submitted, within 30 days of a line hit, by Independent Enterprises, nor Edgewood Borough (The Borough is listed on the ticket, Independent Enterprises doing work for.).</p> <p>One customer's service was interrupted for 1 - &lt; 6 hours, and the Fire Department responded to the 911 call. Peoples Gas provided photos of the damage line.</p> <p>~20251063816, Excavation Emergency ticket placed on 4/16/2025 at 3:00pm. Late Response from: Wilksburg Penn Joint Water Authority, on 4/17/2025, at 4:18pm, as Field Marked. Edgewood Borough, on 4/17/2025, at 9:36am, as Clear No Facilities.</p> <p>Violations:</p> <p>*Independent Enterprises is in violation of sections: 5(3) – Excavator failed to preserve mark-outs or request a remark 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques 5(22) – Excavator provided a misrepresentation of an emergency excavation 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: PUC Compliance Education Required and Penalties Applied. Independent Enterprises is delinquent on education for cases 46863 (Ordered 2/11/25) and 50857 (Ordered 3/11/25)</p> <p>*Edgewood Borough is in violation of sections: 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. The Borough is listed on the ticket, Independent Enterprises doing work for. 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20251063816 Recommendation: PUC Compliance Education Required and Penalties Applied.</p>	<p>Offense \$1,000.00</p> <p><b>Wilksburg Penn Joint Water Authority:</b> <b>\$1,000.00</b> Section 2(5)(vii) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>*Wilksburg Penn Joint Water Authority is in violation of sections: 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20251063816 Recommendation: PUC Compliance Education Required and Penalty Applied.</p>	
54512	<p><b>Contractor/Excavator:</b> L&amp;N Zimmerman Excavating <b>Project Owner:</b> KBC CONSTRUCTION LLC <b>Other:</b> Comcast <b>Other:</b> Verizon, PA LLC</p>	<p><u>On 4/28/2025 1:29:00 AM at 2501 BATH RD, BRISTOL TWP, BUCKS</u> L&amp;N Zimmerman Excavating - Disputing 5(22) KBC Contracting disputed they were the project manager not the project owner. Project owner was Bristol Township. DPI removed KBC Contracting's violation and penalty. *** The incident occurred on 4/28/2025 at 1:29 AM, on 2501 Bath Rd, in Bristol Twp, Bucks County.  No damage was reported.  L&amp;N Zimmerman Excavating is the excavator. Their Alleged Violation Report (AVR) states, “Renotify was called on the morning of 4-28-25, to alert communication facility owners that there may be communication lines in the area. No contact was made by any communications locator”. No photos or additional documentation was provided. Additional information on the New – Damage – Emergency Ticket#20251190089, and the project owner, was requested from L&amp;N Zimmerman on 5/29/2025. They responded on 6/12/2025, “The project was being done for Bristol Twp Senior center. We were a sub-contractor to KBC Construction to install fire main as well as a domestic water service. There was no damage to the line, I submitted the AVR due to the lack of mark out of communications cables, even after a renotify. After we exposed a duct bank with our vac truck, and called in an unknown/exposed line, we finally got a response and mark out.” All Tickets referenced in this case were submitted by L&amp;N Zimmerman.  KBC CONSTRUCTION is listed as the project owner by L&amp;N Zimmerman on Ticket #20251064814 and #20251190089, and indicated by L&amp;N Zimmerman in their statements as the Project Owner. An AVR has not been filed as of 6-13-2025.  Ticket #20251064814-00 had a response due date of 4/18/2025. Verizon did not respond to this Ticket. Comcast responded “Clear” on 4/23/2025. Ticket #20251064814-01, which is a renotify, was entered on 4/28/2025. Verizon responded “Clear” on 5/1/2025. Ticket # 20251190089 New – Damage – Emergency – was entered on 4/29/2025. The map area for this ticket encompasses a larger area. All facilities responded on 4/29/2025. Note on the ticket, “TICKET IS FOR EXPOSED LINE” and does not indicate damage occurred, or that there is an emergency as defined in Act 127 of 2024, “a sudden or unforeseen occurrence</p>	<p><b>L&amp;N Zimmerman Excavating: \$500.00</b> Section 5(22) 1st Offense \$500.00  <b>KBC CONSTRUCTION LLC: \$0.00</b>  <b>Comcast: \$750.00</b> Section 2(5)(v) 3rd offense \$750.00  <b>Verizon, PA LLC: \$500.00</b> Section 2(5)(v) 1st Offense \$250.00  Section 2(5)(v) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>involving a clear and immediate danger to life, property or the environment, including, but not limited to, serious breaks or defects in a facility owner's lines.”</p> <p>Violations:  Excavator - L And N Zimmerman:  Section 5(22) – Excavator provided a misrepresentation of an emergency excavation, subject to an administrative penalty imposed under section 7(10).  # 20251190089  Recommendation: PUC compliance training education is required.</p> <p>Project owner - KBC CONSTRUCTION:  Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. (Removed Violation, penalty, and education.)  Recommendation: PUC compliance training education is required.</p> <p>Facility (Other)-Comcast:  Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket #20251064814-00  Recommendation: PUC compliance training was recently completed.</p> <p>Facility (Other) – Verizon:  Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket #20251064814-00  Recommendation: PUC compliance training was recently completed.  Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time.  Ticket #20251064814-01  Recommendation: PUC compliance training was recently completed.</p>	
54570	<p><b>Facility Owner:</b>  LANCASTER CITY  WATER- LU  <b>Contractor/Excavator:</b>  KINSLEY  CONSTRUCTION LLC  <b>Project Owner:</b> UGI  UTILITIES, INC.</p>	<p><u>On 4/28/2025 10:00:00 AM at N PINE ST, LANCASTER CITY, LANCASTER</u> The incident occurred on Monday, April 28, 2025, on N. Pine Street, in Lancaster City, Lancaster County.</p> <p>A water line was damaged.</p> <p>Kinsley Construction and the project owner, UGI Utilities stated in their Alleged Violation Report’s (AVR) that an unmarked water service line 4' away from the curb stop, was hit and damaged. It was determined the water service ran 90 degrees parallel to the street from the curb stop. The foreman, Aaron Tupper, checked the basement of 744 N. Pine St. and found nothing. The resident had low water pressure, which Lancaster City Water was made aware of. Once the service line was repaired the homeowner's water pressure returned to normal.  Kinsley Construction submitted photos.</p> <p>Lancaster City Water did not submit an AVR within 30 business days of a line strike.</p>	<p><b>LANCASTER CITY WATER- LU: \$2,000.00</b>  Section 2(5)(i) 2nd Offense \$1,000.00</p> <p>Section 2(10) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Violations:</p> <p>*Lancaster City Water is in violation of sections:            2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.            2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work.            Recommendation: PUC Compliance Education Required and Penalties Applied.</p>	
54608	<p><b>Facility Owner:</b> Duquesne Light</p> <p><b>Contractor/Excavator:</b> WILSON EXCAVATING AND UTILITY CONSTRUCTION LLC</p> <p><b>Project Owner:</b> Peoples Gas</p> <p><b>Designer:</b> Peoples Gas - Placeholder</p>	<p><u>On 4/28/2025 12:00:00 PM at S NEGLEY AVE, PITTSBURGH CITY, ALLEGHENY</u> The incident occurred on 4/28/2025 at 12:00:00 PM, on S Negley Ave, in Pittsburgh City, Allegheny County.</p> <p>An electric line owned by Duquesne Light was damaged.</p> <p>Duquesne Light is the facility owner. An Alleged Violation Report (AVR) has not been filed as of 05-29-2025. Duquesne Light responded “Clear” to Ticket # 20250860747 that is referenced for this site.</p> <p>Wilson Excavating And Utility Construction is the excavator. Their AVR states, “Wilson Excavating was performing work for Peoples Gas at the intersection of S. Negley and 5th Ave in Pittsburgh when an unmarked Duquesne Light conduit was struck and damaged. The Operator was hammering out a ditch line for 20" steel mainline install and hammered through an unmarked conduit belonging to Duquesne Light. It was originally thought to be a water line due to the amount of water in the ditch. However, after repairs were started by PWSA, it was discovered that the manhole this conduit ran to was filled with water which caused water to flow up and out of the conduit. The conduit was empty and after further investigation was discovered to belong to Duquesne Light. They came to the site and did agree the conduit was theirs and that it was not marked. Repairs were made and new marks were made.” Multiple photos of the site were submitted with their AVR. There are faded marks visible outside of the tolerance zone.</p> <p>Peoples Gas is the project owner and designer. Their AVR states the same information provided in Wilson Excavating And Utility Construction’s AVR summary.</p> <p>Violations:            Facility -Duquesne Light:            Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.            Recommendation: PUC compliance training education is required.            Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner</p>	<p><b>Duquesne Light:</b>  <b>\$1,500.00</b>            Section 2(5)(i) 1st Offense \$500.00</p> <p>Section 2(10) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: PUC compliance training education is required.</p>	
54610	<p><b>Facility Owner:</b> PECO <b>Contractor/Excavator:</b> JMC CONTRACTORS INC <b>Project Owner:</b> UPPER PROVIDENCE TWP</p>	<p><u>On 4/29/2025 12:00:00 AM at MEDIA STATION RD, UPPER PROVIDENCE TWP, DELAWARE</u> The incident occurred on 4/29/2025 at 12:00 AM, on Media Station Rd, in Upper Providence Twp, Delaware County.</p> <p>A gas line owned by PECO was damaged.</p> <p>PECO is the facility owner. Their Alleged Violation Report (AVR) states, "J M C CONTRACTORS INC was excavating to install new storm sewer with a backhoe under ticket number 20250931341 when they severed the 1/2" plastic gas service, During the investigation it was found that the Sketch and measurement details for the service feeding 316 Media Station are inaccurate and no tracer wire was found at the gas riser the sketch provided at the time of the locate she the service at 2' West of the East House the actual placement of the meter is 5'8" and the service detail card shows the tap at 3' West of the East the service was damaged at 3" East of the West House, there is also a hill fronting 316 Media station and the property sits on a blind curve for vehicles without accurate measurements and or Tracer wire this service is difficult to locate".</p> <p>PECO submitted a damage report with pictures. The yellow marks shown in pre and post damage photos are not within the tolerance zone of the damage. Their AVR states 911 was contacted.</p> <p>J M C Contractors Inc is the excavator. An AVR has not been filed as of 06-06-2025.</p> <p>Upper Providence Twp is the project owner. An AVR has not been filed as of 06-06-2025</p> <p>Ticket #20250931341 had a response due date of 4/7/2025 (NOTE: The below are addressed on Case #054599) PECO and UPPER PROVIDENCE TSA DELAWARE CO responded, "SCHEDULED DATE &amp; TIME LINES WILL BE MARKED BY: 07 Apr 2025 2359" on 4/7/2025, and responded, "FIELD MARKED." on 4/22/2025. UPPER PROVIDENCE TOWNSHIP DELAWARE COUNTY responded "FIELD MARKED." On 4/9/2025. AQUA PENNSYLVANIA INC responded "FIELD MARKED." on 4/16/2025 with a note "2025/04/07 23:59 CONTRACTORS DIDNT ANSWER LEFT A VOICE MESSAGE 2025/04/07 23:59 RESCHEDULE APPROVED BY: JOE COSTANTINI 6103611850." No interim response was recorded.</p> <p>This Case is related to Case #054599 by Ticket # 20250931341.</p> <p>Violations:</p>	<p><b>PECO: \$500.00</b> Section 2(5)(i) 1st Offense \$500.00</p> <p><b>JMC CONTRACTORS INC: \$1,000.00</b> Section 5(16) 1st Offense \$1,000.00</p> <p><b>UPPER PROVIDENCE TWP: \$1,000.00</b> Section 6.1(7) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Facility – PECO: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. #20250931341 Recommendation: PUC Online Compliance Training was recently completed.</p> <p>Excavator - J M C Contractors Inc: Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Recommendation:PUC Online Compliance Training is required.</p> <p>Project Owner - Upper Providence Twp: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Recommendation:PUC Online Compliance Training is required.</p>	
54946	<p><b>Facility Owner:</b> Bloomfield Borough <b>Contractor/Excavator:</b> JVI Group, Inc. <b>Project Owner:</b> PennDOT <b>Designer:</b> GIBSON THOMAS ENGINEERING CO INC <b>Other:</b> Brightspeed</p>	<p><u>On 4/29/2025 9:00:00 AM at SR 34, BLOOMFIELD BORO, PERRY</u> The incident occurred on 4/29/2025 at 9:00 AM, on Sr 34, in Bloomfield Borough, Perry County.</p> <p>A sewer line owned by Bloomfield Borough was damaged.</p> <p>Bloomfield Borough is the facility owner. Their AVR has no summary, pictures or attachments.</p> <p>JVI Group Inc is the excavator. Their AVR states, “JVI Group was excavating for a water line relocation and hit an unmarked sewer lateral service for Pennian Bank owned by the borough. The sewer laterals were not shown on contract plans and the Bloomfield Sewer Authority did not mark the line. The 6" lateral was located 30" below roadway grade and was made of terracotta. JVI used fernco fittings and pvc pipe to repair the 7ft section that was damaged.”</p> <p>PennDOT is the project owner. Their AVR was submitted by Johnson Mirmiran &amp; Thompson and states the same information as JVI Group Inc.’s AVR.</p> <p>Gibson Thomas Engineering Co Inc is the designer. Their AVR states the same information as JVI Group Inc.’s AVR.</p> <p>Ticket# 20250653477 had a response due date of 3/10/2025. Brightspeed responded “Clear” on 3/19/2025.</p> <p>Violations:</p> <p>Facility - Bloomfield Borough: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: PUC Online Compliance Training is required.</p>	<p><b>Bloomfield Borough: \$500.00</b> Section 2(5)(i) 1st Offense \$500.00</p> <p><b>Brightspeed: \$750.00</b> Section 2(5)(v) 3rd offense \$750.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		Facility (other) – Brightspeed: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket#20250653477 Recommendation: PUC Online Compliance Training was recently completed.	
54625	<b>Facility Owner:</b> Peoples Gas <b>Contractor/Excavator:</b> Pittsburgh Water and Sewer Authority (PWSA) <b>Project Owner:</b> Pittsburgh Water and Sewer Authority (PWSA) (Placeholder)	<p>On 4/29/2025 12:00:00 PM at <u>MILLBRIDGE ST, PITTSBURGH CITY, ALLEGHENY</u> Peoples Gas disputed with additional information. Violation and penalty were withdrawn.</p> <p>*****</p> <p>The incident occurred on 04/29/2025 at 12:00 PM, on Millbridge Street, in Pittsburgh City, Allegheny County.</p> <p>A gas line owned by Peoples Gas was damaged. 911 was called.</p> <p>Peoples Gas, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “Pittsburgh Water and Sewer Authority struck and damaged a Peoples Gas owned plastic service line while working with no One Call request. PWSA placed a request to replace a hydrant with a dig date and time of April 30 at 8 AM, that was placed at 810 AM on April 29th. At 1035 on April 29th, PWSA called in a damage gas and an immediate dig request to replace the hydrant. A Peoples Gas locator responded to the requests and found that PWSA had already dug prior to a lawful locate request.” Photos were submitted.</p> <p>Pittsburgh Water and Sewer Authority (PWSA), the excavator and project owner, submitted an AVR. Their AVR states, “Emergency 1-call placed at 8:04 AM. Cleared at 10:04 AM. Excavation started at 10:16 AM and an unmarked gas line hit at 10:30 AM. 911 notified and engine co. 27 responded to our location and waited for both gas co. To respond. It was Peoples Gas. Peoples Gas capped the service line and cleared us to continue excavation.” Photos were submitted.</p> <p>- Emergency New Excavation 20251190605 – Requested 4/29/2025 @ 8:04 AM. Peoples Gas responded Field Marked on 4/29/2025 @ 12:13 PM.</p> <p>- Emergency New Excavation 20251191735 – Requested 4/29/2025 @ 10:31 AM. Peoples Gas responded Field Marked on 4/29/2025 @ 12:19 PM.</p> <p>- Emergency New Damage 20251191786 – Requested 4/29/2025 @ 10:38 AM. Peoples Gas responded Field Marked on 4/29/2025 @ 12:13 PM.</p> <p>Peoples Gas did not respond to the original emergency excavation ticket 20251190605 within 2 hours. PWSA submitted a new emergency excavation ticket 20251191735. The gas line was damaged prior to Peoples Gas marking the line.</p>	<b>Peoples Gas: \$0.00</b>  <b>Pittsburgh Water and Sewer Authority (PWSA): \$500.00</b> Section 5(5) 1st Offense \$500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Violations:</p> <p>Pittsburgh Water and Sewer Authority (PWSA)-  - Section 5(5) – Excavator failed to exercise due care when facility owner is unable to mark within a mutually agreeable time frame. (Original Ticket 20251190605)  Recommendation: The penalty is applied. (PUC online compliance training/education was recently completed.)</p> <p>Peoples Gas- Withdrawn.  - Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. (Ticket 20251190605)</p>	
54994	<p><b>Facility Owner:</b> UGI UTILITIES INC.  <b>Contractor/Excavator:</b> JD Eckman Inc  <b>Project Owner:</b> PennDOT  <b>Other:</b> EAST STROUDSBURG UNIVERSITY  <b>Other:</b> Verizon, PA LLC</p>	<p><u>On 5/7/2025 10:00:00 AM at PROSPECT ST, EAST STROUDSBURG BORO, MONROE</u> The incident occurred on 5/7/2025 at 10:00 AM, on Prospect St, in East Stroudsburg Boro, Monroe County.</p> <p>A gas line owned by UGI Utilities, Inc was damaged. 1 Customer affected.  Duration of Service Interruption 1 - &lt; 6 hrs.  911 was contacted.</p> <p>UGI Utilities, Inc is the facility owner. Their Alleged Violation Report (AVR) states, “JD ECKMAN WAS DIGGING TO WORK ON SIDEWALKS AND WHEN DOING THEY STRUCK A CORRECTLY MARKED GAS SERVICE FACILTY CREATING A DAMAGE. DIGGING IN THE TOLERANCE ZONE.” UGI submitted photos of the site, damage, and marks. Yellow marks are seen on both sides of the excavated area, with the damage within the tolerance zone of the marks.</p> <p>JD Eckman Inc is the excavator. Their AVR states, “The operator was instructed to take off the curb and sidewalk with an excavator. He turned his flat bucket to lift the curb off and struck the half inch gas line 11 in. under the surface. It was marked 18 in. at the asphalt and rose to 11 in. near the curb where it was struck.”</p> <p>Penndot is the project owner. Their AVR states, “The operator was instructed to take off the curb and sidewalk withan excavator. He turned his flat bucket to lift the curb off and struckthe half inch gas line 11 in. under the surface. It was marked 18 in.at the asphalt and rose to 11 in. near the curb where it was struck.”</p> <p>Ticket # 20251222364 had a response due date of 5/6/2025. EAST STROUDSBURG UNIVERSITY responded “Clear” on 5/7/2025, and VERIZON PENNSYLVANIA LLC responded “Conflict” on 5/23/25 and did not enter a final response.</p> <p>This case is related to Case number #038366 by Ticket # 20220550792, 20220550817, and 20220603540.</p> <p>Violations:</p> <p>Excavator - JD Eckman Inc:</p>	<p><b>JD Eckman Inc:</b>  <b>\$1,000.00</b>  Section 5(4) 2nd Offense  \$1,000.00</p> <p><b>EAST STROUDSBURG UNIVERSITY: \$250.00</b>  Section 2(5)(v) 1st Offense  \$250.00</p> <p><b>Verizon, PA LLC:</b>  <b>\$2,000.00</b>  Section 2(5)(v)  Subsequent \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.  Recommendation: PUC Online Compliance Training was recently completed.  Facility (Other) - EAST STROUDSBURG UNIVERSITY</p> <p>Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time.  Ticket # 20251222364  Recommendation: PUC Online Compliance Training is required.</p> <p>Facility (Other) – VERIZON  Section 2(5)(v) – Failed to respond to a routine One Call ticket.  Ticket # 20251222364  Recommendation: PUC Online Compliance Training was recently completed.</p>	
54914	<p><b>Facility Owner:</b> Peoples Gas  <b>Contractor/Excavator:</b> Curry and Kepple  <b>Project Owner:</b> New Kensington City Municipal Authority  <b>Other:</b> Gibson Thomas Engineering</p>	<p>On 5/8/2025 1:00:00 PM at 38 7TH ST EXT, NEW KENSINGTON CITY, WESTMORELAND Peoples Gas accepts.</p> <p>*****</p> <p>The incident occurred on 05/08/2025, at 38 7th Street EXT, in New Kensington City, Westmoreland County.</p> <p>A gas line owned by Peoples Gas was damaged.</p> <p>Peoples Gas, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “Hooked up at meter at house and the locator was about 3 feet off of were the line was.”</p> <p>Curry and Kepple, the excavator, submitted an AVR. Their AVR states, “Digging to locate a service line struck line over 3 feet away from marks”. Photos were submitted.</p> <p>New Kensington City Municipal Authority, the project owner, submitted an AVR. Their AVR states, "Contractor was installing new water main and struck a gas service line that was mismarked by 3'."</p> <p>Gibson Thomas Engineering, the designer, submitted an AVR. Their AVR states, "Contractor was excavating marks were observed. Excavator struck line 3' from existing from marked location." Photos were submitted.</p> <p>The submitted photos show the closest marked gas line is over 3 feet away from the damage.</p> <p>This case is related to case 055017 by tickets 20250974165 Routine and 20250772685 Complex.</p> <p>Violations:</p> <p>Peoples Gas -  - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.</p>	<p><b>Peoples Gas: \$1,000.00</b>  Section 2(5)(i) 2nd  Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
54853	<p><b>Facility Owner:</b> PEOPLES GAS COMPANY LLC</p> <p><b>Contractor/Excavator:</b> S &amp; E Utility Contracting</p> <p><b>Project Owner:</b> PENN TOWNSHIP OF WESTMORELAND COUNTY</p> <p><b>Other:</b> Verizon PA LLC</p> <p><b>Other:</b> WESTMORELAND CO MUNI AUTH</p>	<p>Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p><u>On 5/8/2025 3:31:00 PM at 11 ARBOR CT, PENN TWP, WESTMORELAND</u> Peoples Gas penalties and violations has been removed. They emailed their dispute with attachments. *****</p> <p>MAWC emailed their dispute with exhibits. With the provided information the penalties and violations has been removed. See attachment Exhibit-1 *****</p> <p>The incident occurred on Thursday, May 8, 2025, at 11 Arbor Court, in Penn Township, Westmoreland County.</p> <p>A gas line was damaged.</p> <p>Peoples Gas Company stated S &amp; E Utility Contracting failed to use prudent techniques within the tolerance zone, and explained in their Alleged Violation Report (AVR), S&amp;E Utility Contracting working for Penn Township installing storm sewer struck PNG 1 inch plastic service line. S&amp;E failed to spot service. Service line was marked and marks were good. S&amp;E notified PNG and PNG crews arrived onsite for repairs.</p> <p>Penn Township stated in their AVR that the contractor, S &amp; E Utility Contracting had their pipe layer mark 30-inch on either side of yellow mark, he dug without caution on either side down to grade at 7' deep, then excavated 2' down on top of gas line marks. They hand dug one time about 6" then broke gas service with machine.</p> <p>S &amp; E Utility Contracting did not submit an AVR within 30 days of the line strike.</p> <p>20250722038-002- Routine ticket placed on 3/20/2025 at 9:31am. Peoples Gas Company- No Response. Westmoreland County Municipal Authority- Responded as scheduled date &amp; time lines will be marked by 3/18/2025, but responded as Field Marked on 3/20/2025.</p> <p>20250722054-002- Routine ticket placed on 3/20/2025 at 9:26am. Peoples Gas Company- No Response. Westmoreland County Municipal Authority- Responded as scheduled date &amp; time lines will be marked by 3/18/2025, but responded as Field Marked on 3/20/2025.</p> <p>Violations:</p> <p>*S &amp; E Utility Contracting is in violation of sections: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. 5(8) – Excavator vacated worksite after causing damage that resulted in the escape of any flammable, toxic or corrosive gas or liquid. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: PUC Compliance Education Required and Penalties Applied.</p>	<p><b>PEOPLES GAS COMPANY LLC: \$0.00</b></p> <p><b>S &amp; E Utility Contracting: \$2,500.00</b> Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(4) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p><b>Verizon PA LLC: \$1,000.00</b> Section 2(5)(vii) 1st Offense \$1,000.00</p> <p><b>WESTMORELAND CO MUNI AUTH: \$0.00</b></p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>*Peoples Gas Company is in violation of sections: 2(5)(v.2) – Failed to timely enter a final response to all locate requests. 20250722038-002 2(5)(v.2) – Failed to timely enter a final response to all locate requests. 20250722054-002 Recommendation: Penalties Applied.</p> <p>*Westmoreland County Municipal Authority is in violation of sections: 2(5)(v.2) – Failed to timely enter a final response to all locate requests. 20250722038-002 2(5)(v.2) – Failed to timely enter a final response to all locate requests. 20250722054-002 Recommendation: Penalties Applied.</p> <p>*Verizon PA LLC is in violation of sections: 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20251284236 Recommendation: Penalty Applied.</p>	
54911	<p><b>Facility Owner:</b> Peoples Natural Gas <b>Contractor/Excavator:</b> INDEPENDENCE EXCAVATING <b>Project Owner:</b> PennDot <b>Designer:</b> MARKOSKY ENGINEERING GROUP INC</p>	<p>On 5/9/2025 7:00:00 AM at SR 0228, ADAMS TWP, BUTLER Peoples Gas - 2(5)(i) - Withdrawn ***** The incident occurred on 5/9/2025 at 7:00 AM, on Sr 0228, in Adams Twp, Butler County.</p> <p>A gas line owned by Peoples Gas Company was damaged.</p> <p>Peoples Gas Company is the facility owner. Their Alleged Violation Report (AVR) states, “On 5/9/2025, Independence Excavating struck an unmarked PNG tap tee on a ML road crossing. Independence has been working on Route 228 for a couple of months and will continue to do so for the remainder of the year. Independence routinely calls in update tickets requesting facilities to be remarked. Per agreement with PNG locator and Independence, they will call PNG with any new marks that are needed. Independence failed to call PNG for markings.” Additional information provided by Peoples Gas on 6/17/2025, “I have attached a copy of the PA One Call ticket 20251194748 showing the documentation that the PNG locator, Tom Jackson, made notes that he and the onsite contact for Independence Excavating, Dylan Bongiorno had agreed for Dylan to contact Tom if additional markings were needed due to Independence Excavating calling in the entire project, approximately 3 miles, every two weeks, when work was not taking place on the entire project daily. I have attached the screenshot from the ticket showing the work area drawn by Independence Excavating for ticket 20251194748 as well. “</p> <p>Independence Excavating is the excavator. An AVR has not been filed as of 06-17-2025.</p> <p>PennDot is the project owner. Their AVR states, “Line was directionally bored as part of a relocation so as to not be in conflict with new drainage facilities however,</p>	<p><b>Peoples Natural Gas:</b> <b>\$0.00</b></p> <p><b>INDEPENDENCE EXCAVATING:</b> <b>\$1,250.00</b> Section 5(16) 1st Offense \$1,000.00</p> <p>Section 5(3) 1st Offense \$0.00</p> <p>Section 5(20) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>the line was not bored to a depth to allow the new drainage to be above the gas line.”</p> <p>The Markosky Engineering Group Inc is the designer. Their AVR states, “Gas line was directionally bored as part of a relocation, so as to not be in conflict with new drainage facilities however, the line was not bored to a depth to allow the new drainage to be above the gas line.”</p> <p>Multiple photos of the site were included. The site and damage are shown. Most of the area has already been excavated and is disturbed dirt and stone. No markings are visible.</p> <p>On Ticket # 20251194747 and #20251194748, the most recent Update Tickets for the site prior to the damage, People Gas responded clear on 5/1/2025.</p> <p>This case is related by Ticket# 20230300749 Complex Project to case #050666</p> <p>Violations:  Facility – Peoples Gas  Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.  Recommendation: PUC Online Compliance Training was recently completed.</p> <p>Excavator - Independence Excavating:  Section 5(3) – Excavator failed to schedule work as agreed upon during a preconstruction meeting.  Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.  Section 5(20) – Excavator failed to renotify One Call of an unmarked or incorrectly marked facility upon arrival at a work site.  Recommendation: PUC Online Compliance Training is required.</p>	
55068	<p><b>Facility Owner:</b> West Penn Power  <b>Contractor/Excavator:</b> Susco  <b>Project Owner:</b> Armstrong Utilities  <b>Designer:</b> Armstrong Utilities - placeholder</p>	<p>On 5/12/2025 8:00:00 AM at HUNTER RIDGE RD, CLAY TWP, BUTLER Susco - 5(19) - Reduced from \$250 to a warning of \$0. - Not disputing  *****</p> <p>The incident occurred on 5/12/25, 8:00 AM, on 100 and 104 Hunter Ridge Rd, in Clay Twp, Butler County.</p> <p>An electric line owned by West Penn Power was damaged.</p> <p>West Penn Power is the facility owner. Their Alleged Violation Report (AVR) states, “On April 23, 2025, Susco, “Excavator”, submitted POCS Routine Ticket 20251133822 to install fiber optic cable on Hunter Ridge Road, Clay Township, Butler County, Pennsylvania. On May 12, 2025, West Penn Power was notified of an outage at this location. USIC, West Penn Power’s Contract Locator, investigated and determined that the</p>	<p><b>West Penn Power:</b>  <b>\$1,000.00</b>  Section 2(5)(vii) 1st Offense \$1,000.00</p> <p><b>Susco: \$0.00</b>  Section 5(19) 1st Offense \$0.00</p> <p><b>Armstrong Utilities:</b>  <b>\$1,000.00</b>  Section 2(5)(vii) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Excavator damaged a marked underground electric line with a directional drill. The root cause of the damage was the Excavator failed to dig prudently within the tolerance zone.” AVR2025MAY200022</p> <p>Susco and Armstrong listed 5/5/2025 as the incident date in their AVRs, which is not the correct date. The incident occurred on 5/12/2025. Additional information was requested from Susco on the date in their AVR, but they did not respond.</p> <p>Susco is the excavator. Their AVR states, “Set up drill made sure we were 3ft or more away from closest utility. started boring made it almost to the end of the bore shot when strike alert went off stopped bore. Pulled back bore head to make it safe for operator to get off drill call 811 for a power hit and to notify west penn power. West penn power responded let us finish are bore shot and ran a temp line to restore power to everyone.”</p> <p>Armstrong is the project owner. Their AVR states, “Set up drill made sure we were 3ft or more away from close utilities. Started boring made it almost to the end of the bore shotwhen strike alert went off stopped bore. Pulled back bore head to make it safe for operator to get off drill call 811 for a power hit and to notify West Penn Power. West Penn Power responded let us finish are bore shot and ran a temp line to restore power to everyone. Photos attached”.</p> <p>Photos submitted by Susco and Armstrong show the site and marks. A hit kit is used to show the damage was indicated at over 3 feet from the red marks, and over 18 inches from the orange marks. The pylon showing the damage in these photos is on undisturbed ground, and does not show physical damage to a line.</p> <p>The damage report created by USIC, West Penn Power’s locator, and submitted with West Penn Power’s AVR shows the damage at a different location than where the excavator’s photos indicate. The damage location is where a hole has been dug, and is within the tolerance zone of red and orange marks. An exposed line is visible in the photos near where a hit kit indicates the damage. No physical damage is indicated, or can be seen in West Penn’s photos. Additional photos were requested from West Penn, and were provided, but do not indicate the exact location of the damage.</p> <p>With the location of the damage being indicated at different locations between the excavator and facility, and no visual evidence provided of where the damage occurred, it cannot be determined which stakeholder was at fault for this damage incident.</p> <p>Ticket # 20251322115 New – Damage – Emergency 5/12/2025 12:16 PM had a response due time of 2:16 PM and stated, “CALLER STATES THEY BELIEVE THIS IS A PRIMARY ELECTRIC LINE.” Armstrong and West Penn Power responded, “SCHEDULED</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>DATE &amp; TIME LINES WILL BE MARKED BY: 13 May 2025 1416” on 5/12/2025 at 2:31 PM, and then entered the final response of “CLEAR. NO FACILITIES OR FACILITIES NOT INVOLVED BASED ON TICKET INFORMATION.” On 5/13/2025 at 2:38 PM.</p> <p>Violations:</p> <p>Facility - West Penn Power Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket # 20251322115 Recommendation: PUC Online Compliance Training was recently completed.</p> <p>Excavator – Susco: Section 5(19) – Excavator failed to provide accurate information to the One Call System. Recommendation: PUC Online Compliance Training is required.</p> <p>Facility (Other) – Armstrong Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket # 20251322115 Recommendation: PUC Online Compliance Training was recently completed.</p>	
55164	<p><b>Facility Owner:</b> Columbia Gas</p> <p><b>Contractor/Excavator:</b> Independent Enterprises Inc</p> <p><b>Project Owner:</b> Pittsburgh Water</p>	<p><u>On 5/12/2025 9:00:00 AM at S 13TH ST, PITTSBURGH CITY, ALLEGHENY</u> The incident occurred on 5/12/2025 at 9:00 AM, on S 13Th St, in Pittsburgh City, Allegheny County.</p> <p>A gas line owned by Columbia Gas Of Pa was damaged. Customers Affected – 2 ; 1- &lt;6 Hours</p> <p>Columbia Gas Of PA is the facility owner. Their Alleged Violation Report (AVR) states, “Independent Enterprises, working on behalf of Pittsburgh Water &amp; Sewer, damaged a clearly marked, inserted company-side service line while attempting to remove the curb using mechanical equipment within the tolerance zone of the marked gas service. Upon discovery of the damage, 911, 811, and Columbia Gas were promptly notified. Columbia Gas responded quickly, secured the area, and completed the necessary repairs.”</p> <p>Independent Enterprises is the excavator. Their AVR states, “While verifying 107 S 13th St a gas service line was struck and damaged by the excavator bucket at 9:30am. It was 16" down from the top of the curb directly under the concrete road base. Work was stopped and 911 was called. The fire department arrived at 9:38 am. Peoples Gas arrived at 10am, truck # 215871. The gas representative determined it was the public side of 107 S 13th St that was struck, and it belonged to Columbia gas. Columbia gas arrived at 10:35, truck # 4443. They made their assessment and called for a repair crew. Colombia gas repair crew, truck # 1312, arrived at 12:40pm. The repair was completed at 12:55 and they left the site at 1:05pm.”</p>	<p><b>Independent Enterprises Inc: \$1,500.00</b> Section 5(4) 3rd Offense \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Pittsburgh Water is the project owner. Their AVR states, “While verifying 107 S 13th St a gas service line was struck and damaged by the excavator bucket at 9:30am. It was 16" down from the top of the curb directly under the concrete road base. Work was stopped and 911 was called. The fire department arrived at 9:38 am. Peoples Gas arrived at 10am, truck # 215871. The gas representative determined it was the public side of 107 S 13th St that was struck, and it belonged to Columbia gas. Columbia gas arrived at 10:35, truck # 4443. They made their assessment and called for a repair crew. Colombia gas repair crew, truck # 1312, arrived at 12:40pm. The repair was completed at 12:55 and they left the site at 1:05pm.”</p> <p>Multiple photos of the site were submitted. A yellow mark, blue mark, and a water curb stop, are visible. The damage is within the tolerance zone of the marks. A hit kit is also shown indicating the location and measurements.</p> <p>Violations:</p> <p>Excavator - Independent Enterprises: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: PUC Online Compliance Training is required NOTE: Independent Enterprises is delinquent on DPC ordered education for cases 46803 and 50857.</p>	
55459	<p><b>Facility Owner:</b> PPL <b>Contractor/Excavator:</b> DOLI Construction Corporation <b>Project Owner:</b> Lower Paxton Township Authority <b>Other:</b> Herbert Rowland and Grubic Inc (HRG INC)</p>	<p><u>On 5/27/2025 10:00:00 AM at 562 BLANCHESTER RD, LOWER PAXTON TWP, DAUPHIN</u> The incident occurred on 5/27/2025 at 562 Blanchester Rd. in Lower Paxton Township in Dauphin County.</p> <p>*No damage Underground lines owned by PPL were marked but PPL Ticket response was “Clear”.</p> <p>DOLI CONSTRUCTION stated in their Alleged Violation Report (AVR) that Looked for electric that was marked. Went 6'deep and 2' on both sides of mark and did not find anything. No pictures were provided. Many copies of the designs were provided. Jake was CCed on the email to HRG.</p> <p>HRG INC stated in their AVR that Contractor looked for electric that was marked. Dug 6' deep and 2' on both sides of mark and did not find anything. On 6/11/2025 DPI sent and email and cced Doli, asking if there was electric on the design for this area in question. Ticket 20251290547 was responded to by PPL with “Clear” no utilities. On 6/12/2025, an email was received which included an attachment of the design. This design shows that there are electric lines that run across 562 Blanchester Rd. Please see attachment named “Close-up of design showing electric lines”.</p>	<p><b>PPL: \$2,000.00</b> Section 2(5)(i) Subsequent \$2,000.00</p> <p><b>DOLI Construction Corporation: \$250.00</b> Section 5(20) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>LOWER PAXTON TOWNSHIP AUTHORITY stated in their AVR that “Doli looked for electric that was marked. They went 6' deep and 2' on both sides of the mark and did not find anything”. On 6/04/2025 an email was received from LOWER PAXTON TOWNSHIP AUTHORITY stating that the date in the AVR was mistakenly submitted as 6/27/2025 and could this please be updated to 5/27/2025. See email attachment named “AVR date updated”</p> <p>VIOLATIONS:  PPL is in violation of:  PPL is in violation of:  Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Ticket 20251290547 was responded to as “Clear no facilities involved” but the PPL lines were marked at the dig site. The excavator did not find any lines where the lines were marked. The PPL Lines are noted in the section on the design. Please see attachment named “Close-up of design showing electric lines”.</p> <p>DOLI Construction Corporation is in violation of:  Section 5(20) – Excavator failed to renotify One Call of an unmarked or incorrectly marked facility upon arrival at a work site. Ticket 20251290547 was responded to as “Clear no facilities involved” but the PPL lines were marked but there were no lines where the markings were. Please also consider that the ticket response was conflicting with the information on the design and on the ground. A renotify ticket submitted when this information was discovered may have saved time, money and frustration. Section 5(20) states that An excavator may not begin excavating in the affected area of the work site until after receiving sufficient information from the facility owner to safely excavate.</p>	

**Full Session**

Case Number	Stakeholders	Summary	Violations & Recommendation
54267	<p><b>Facility Owner:</b> PPL Electric Utilities  <b>Contractor/Excavator:</b> Barrasso Excavation  <b>Project Owner:</b> Lower Macungie Twp</p>	<p><u>On 3/6/2025 10:23:00 AM at BOGIE AVE, LOWER MACUNGIE TWP, LEHIGH</u> On 09/9/2025: The Damage Prevention Committee (DPC) voted:</p> <p>Barrasso Excavation:  5(16)- keep violation, remove penalty.</p> <p>Lower Macungie Twp:  6.1(7)- keep violation, remove penalty.</p> <p>*****  Barasso Excavating is disputing.</p> <p>Lower Macungie Township is disputing.</p> <p>PPL accepts.  *****</p>	<p><b>PPL Electric Utilities:</b>  <b>\$500.00</b>  Section 2(5)(i) 1st Offense  \$500.00</p> <p><b>Barrasso Excavation:</b>  <b>\$0.00</b>  Section 5(16) 1st Offense  \$0.00</p> <p><b>Lower Macungie Twp:</b>  <b>\$0.00</b>  Section 6.1(7) 1st Offense  \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>The incident occurred on 03/06/2025, at 10:23 AM, on Bogie Avenue, in Lower Macungie Township, Lehigh County.</p> <p>An electrical line owned by PPL Electric was damaged.</p> <p>PPL Electric, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “On Thursday 3/6/3035 at approximately 10:23 AM Barrasso Excavation contacted an unmarked underground primary along Bogie Ave while excavating for Lower Macungie Township.” Photos were submitted. PPL Electric noted in their AVR that this was a facility owner issue - Marked Incorrectly.</p> <p>Barrasso Excavation is the excavator. An AVR has not been filed as of 05/30/2025.</p> <p>Lower Macungie Twp. is the project owner. An AVR has not been filed as of 05/30/2025.</p> <p>PPL Electric respond to the routine ticket 20250582138 as ‘Field Marked’ on 03/03/2025. The photos of the damage do not show any electrical mark outs near the damaged line, or the surrounding area.</p> <p>Violations:</p> <p>PPL Electric- - Section2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Barrasso Excavation- -Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Lower Macungie Twp.- -Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
53584	<p><b>Facility Owner:</b> UGI Utilities, Inc. <b>Contractor/Excavator:</b> Mountain Ridge Landscaping <b>Project Owner:</b> Homeowner</p>	<p><u>On 3/20/2025 11:50:00 AM at 120 Milky Way, SOUTHAMPTON TWP, CUMBERLAND</u> On September 9th, 2025, the Damage Prevention Committee voted on Mountain Ridge Landscaping's violations to remove the violation and penalty for 5(2.1),and reduce the penalty from \$1000 to \$0 on 5(16) and keep education. **** Mountain Ridge Landscaping is disputing.  ***** The incident occurred on 3/20/2025 at 11:50 AM, on 120 Milky Way, in Southampton Twp, Cumberland County.</p>	<p><b>Mountain Ridge Landscaping: \$0.00</b> Section 5(16) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>**No damage was reported. The incident references no One Call ticket.</p> <p>UGI Utilities Inc, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “While performing daily work, a UGI employee observed excavation activity in the backyard of 120 Milky Way. Excavator was using mini excavator to dig holes to plant trees. UGI employee stopped and asked excavator for a PA One Call serial number. Excavator did not provide a valid ticket. Excavator said he had made a call to PA One Call awhile ago. The only ticket that could be found was from 5/21/2024 and this ticket was no longer valid and there were no facility markings on the property the day of the stop. UGI employee shut the job down until they made a valid ticket.” UGI submitted photos with their AVR showing the excavated site, an excavator, and a trailer with Mountain Ridge Landscaping listed on the side.</p> <p>Mountain Ridge Landscaping is the excavator. An AVR has not been filed as of 5/28/2025. An AVR request letter was mailed and emailed to Mountain Ridge Landscaping on 4/28/2025. Multiple responses were received from Josh Proctor mtnridgelandscap@yahoo.com. “I didn't do anything wrong prove I did”, “Also I'm not doing an investigation for you on my time. I pay you yearly for 1 calls so do a fake investigation on nothing on your time”</p> <p>Christian and Christina Fow are the homeowner and project owner. An AVR has not been filed as of 5/28/2025</p> <p>No tickets were submitted by Mountain Ridge Landscaping for the excavation at 120 Milky Way for this excavation. The Excavator was aware a ticket was required as they submitted a ticket for the same location in 2024. The Excavator was aware an AVR was required as they were informed via email and mail. They responded multiple times via email and were informed again of the AVR requirements, and given instructions on how to complete the AVR.</p> <p>Violations: Excavator: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: The penalties are applied. PUC compliance training education is required.</p>	
53642	<b>Facility Owner:</b> PENNSYLVANIA AMERICAN WATER	<u>On 3/25/2025 1:30:00 PM at 279 STONE CHURCH RD, UNION TWP, WASHINGTON</u> On 9/09/2025 the Damage Prevention Committee (DPC) voted to	<b>PENNSYLVANIA AMERICAN WATER (PAWC): \$250.00</b>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>(PAWC)  <b>Contractor/Excavator:</b>  PEOPLES NATURAL GAS  <b>Project Owner:</b>  PEOPLES NATURAL GAS - Spacesaver  <b>Designer:</b> PEOPLES NATURAL GAS - Spacesaver  <b>Other:</b> VERIZON PA LLC</p>	<p>withdraw 2(5)(i)- Remove violation and penalty and 2(5)(i.1)- Remove violation and penalty to PA American Water.  *</p> <p>PA American Water disagreed and stated that "PAWC disputes the alleged violations identified in the Damage Prevention Investigator Report for Case No. 053642. PAWC disputes the alleged violations of Section 2(5)(i)-failure to locate underground lines at the work site within 18 inches horizontally of the outside wall of line, and Section 2(5)(i.1)-failure to locate an actually known facility's point of connection to its facilities. PAWC disputes these violations because it marked its facilities located at the work site identified on the ticket, which was 279 Stone Church. The damage occurred in front 277 Stone Church, which was not the identified work site. PAWC accepts the alleged violation for Section 2(10). - PENNSYLVANIA AMERICAN WATER (PAWC) submitted an email with 4 photos.  *****</p> <p>The incident occurred on 3/25/2025 at 279 Stone Church Rd. in Union Township in Washington County.</p> <p>An unmarked water service line was damaged.</p> <p>PEOPLES GAS COMPANY LLC the project owner, desiner and excavator- stated in their AVR that "ON 3/25/25 AT 1330 PNG CREW DIGGING A TIE IN HOLE IN FRONT OF 277 STONE CHURCH RD PULLED A UNMARKED WATER SERVICE LINE CAUSING A KINK AND BREAK. PA AMERICAN WATER WAS NOTFIED AND PA WATER CREWS ARRIVED ONSITE AND MADE REPAIRS. Pictures, reports and plans were provided". ON 5/07/2025 DPI Maki asked Peoples if they have any pictures showing any markings and asked what was meant when Peoples sated that "No response to an excavation notification" by PA American, since they did respond "field marked" in the ticket. On 5/14/2025 an email was received from Peoples stating that "I spoke with the local Damage Prevention Supervisor and Supervisor of the crew that caused the damage. The Supervisor of the crew that caused the damage personally marked the area for 1 call and had flags placed for the excavation area. The local Supervisor of the crew that damaged the unmarked water service line did not take pictures of the area prior to excavation. He will moving forward. However; he did state there was water marked further down the street and stopped. This is not out of the ordinary in the rural areas for a water main to only go so far up a road and dead end. There was no visible water curb boxes or gate boxes to make the crew think the water main continued and there was a water service line in the area after the markings that were visible. This is the reason the crew did not renotify the ticket when the water markings stopped and no more water markings were visible". On 5/21/2025 DPI Maki asked for the final design page that would show the water line. A final design ticket was</p>	<p>Section 2(5)(i.1) 1st Offense \$250.00</p> <p><b>VERIZON PA LLC:</b>  <b>\$1,000.00</b>  Section 2(5)(v)  Subsequent \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>submitted, but only a preliminary design was submitted for this case.</p> <p>PENNSYLVANIA AMERICAN WATER the facility owner AVR was due by 5/6/2025. No AVR has been received as of 5/23/2025.</p> <p>VIOLATIONS</p> <p>PENNSYLVANIA AMERICAN WATER is in violation of:</p> <p>Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work.</p> <p>Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.</p> <p>Section 2(5)(i.1) – Failed to locate an actually known facility’s point of connection to its facilities.</p> <p>Recommendations: The penalty is applied.</p> <p>Verizon is in violation of:</p> <p>Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20250762541 was due by 3/23/2025. Verizon did not respond “Clear” until 3/24/2025. This is a subsequent offense.</p> <p>Recommendations: The penalty is applied.</p>	
55016	<p><b>Facility Owner:</b> COMCAST</p> <p><b>Contractor/Excavator:</b> RILLS CONSTRUCTION SERVICES</p> <p><b>Project Owner:</b> Brightspeed</p> <p><b>Other:</b> Reading Township Municipal Authority</p> <p><b>Other:</b> Verizon North</p>	<p><u>On 3/31/2025 9:17:00 AM at KIMBERLY LN, READING TWP, ADAMS</u> On September 9th, 2025, the Damage Prevention Committee voted on Rills Construction's violations to keep the violation for 5(4) and 5(16), and increase the penalty on 5(4) from \$500 to \$1000, and 5(16) from \$1000 to \$1500 for a total of \$2500 in penalties. Rills Construction did not attend the Damage Prevention Committee meeting.</p> <p>*****</p> <p>Rills Construction - Disputing 5(16) and 5(4)</p> <p>-----</p> <p>The incident occurred on 3/31/2025 at 9:17 AM, on Kimberly Ln, in Reading Twp, Adams County.</p> <p>A communication line owned by Comcast was damaged. Approximate Number of Customers Affected 11 – 50 Duration of Service Interruption 1 - &lt; 6 hrs</p> <p>Comcast, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “CONTRACTOR HIT AN ACCURATELY MARKED LINE”. Comcast submitted photos, as well as a damage report from their contracted locater USIC. The photos show the orange markings on 3/4/2025 at the site, a Hit Kit on 4/1/2025 with the damage in the tolerance zone, as well as multiple other photos showing the markings and damage location.</p> <p>Rills Construction Services is the excavator. An Alleged Violation Report (AVR) has not been filed as of 5/16/2025.</p>	<p><b>RILLS CONSTRUCTION SERVICES: \$2,500.00</b> Section 5(4) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,500.00</p> <p><b>Brightspeed: \$1,750.00</b> Section 6.1(7) 2nd Offense \$1,500.00</p> <p>Section 2(5)(v.2) 1st Offense \$250.00</p> <p><b>Reading Township Municipal Authority: \$250.00</b> Section 2(5)(v.2) 1st Offense \$250.00</p> <p><b>Verizon North: \$250.00</b> Section 2(5)(v.2) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Brightspeed is the project owner. An AVR has not been filed as of 5/16/2025.</p> <p>Ticket #20250573215 New – Excavation – Routine had a response due date of 3/4/2025. Brightspeed BSD did not respond “Clear.” Until 3/21/2025. Reading Township Municipal Authority did not respond “Clear.” Until 3/7/2025. Verizon North did not respond “Clear” until 3/21/2025.</p> <p>Violations:</p> <p>Excavator - Rills Construction Services: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: PUC Online Compliance Training is required.</p> <p>Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: PUC Online Compliance Training is required.</p> <p>Project Owner – Brightspeed: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Recommendation: PUC Online Compliance Training was recently completed.</p> <p>Facility(Other) – Brightspeed: Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Recommendation: PUC Online Compliance Training was recently completed.</p> <p>Facility (other) - Reading Township: Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Recommendation: PUC Online Compliance Training is required.</p> <p>Facility (other) - Verizon North: Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Recommendation: PUC Online Compliance Training is required.</p>	
54067	<p><b>Facility Owner:</b> National Fuel Gas <b>Contractor/Excavator:</b> PASSAUER EXCAVATION <b>Project Owner:</b> West Hickory Sportsman’s Bar <b>Other:</b> TATONKA OIL COMPANY LLC</p>	<p><u>On 4/1/2025 10:00:00 AM at 3573 MAIN ST, HARMONY TWP, FOREST</u> On 09/9/2025: The Damage Prevention Committee (DPC) voted to remove PASSAUER EXCAVATION's violation and penalty.</p> <p>***** PASSAUER EXCAVATION is disputing. - Routine ticket 20250871129 lists the type of work as 'Expanding Parking Lot' and lists the location as 'VLG OF WEST</p>	<p><b>PASSAUER EXCAVATION: \$0.00</b></p> <p><b>TATONKA OIL COMPANY LLC: \$500.00</b> Section 2(5)(v) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>HICKORY. N SIDE OF PROP IN THE GRASSY LOT NEXT TO SPORTSMANS BAR.' Submitted photos show the parking lot was expanded and grass was removed. A before photo from google maps shows the same location from 2024 with grass. Submitted photos also show a truck with the excavating company's name on site.</p> <p>*****</p> <p>The non-damage event occurred on 04/01/2025, at 10:00 AM, at 3573 Main Street, in Harmony Township, Forest County.</p> <p>Non-damage event. Excavating prior to the lawful start date listed on PA One Call ticket.</p> <p>National Fuel Gas, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, "Excavator working before lawful start date and over top of National Fuel facilities. Please see attachments." Photos were submitted.</p> <p>Passauer Excavation is the excavator. An AVR has not been filed as of 05/29/2025.</p> <p>West Hickory Sportsman's Bar is the project owner, per routine ticket 20250871129. An AVR has not been filed as of 05/29/2025.</p> <p>The submitted photos show excavation was started prior to the lawful start date listed on the routine ticket. National Fuel Gas went to the site on 04/01/2025 to mark their lines and discovered that excavation had already started. The lawful start dates listed on the ticket were 04/02/2025 through 04/11/2025.</p> <p>Routine ticket 20250871129 had a response due date of 04/01/2025. - Tatonka Oil Company LLC did not respond to this ticket.</p> <p>Violations:</p> <p>Passauer Excavation – - Section 1.1 – Excavator did not begin within legal timeframe. Routine ticket 20250871129. Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Tatonka Oil Company LLC- - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket 20250871129. Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
53841	<p><b>Facility Owner:</b> PECO  <b>Contractor/Excavator:</b> RIGGS DISTLER  <b>Project Owner:</b> PECO - Placeholder  <b>Other:</b> Comcast</p>	<p><u>On 4/1/2025 4:00:00 PM at 30 WYNMERE DR, HORSHAM TWP, MONTGOMERY</u> On September 9th, 2025, the Damage Prevention Committee voted to remove the 5(4) violation and penalty for Riggs Distler.  *****  Riggs Distler - Disputing 5(4)</p>	<p><b>RIGGS DISTLER: \$0.00</b></p> <p><b>Comcast: \$1,500.00</b>  Section 2(5)(v) 3rd offense  \$750.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>*****</p> <p>The incident occurred on 4/1/2025 at 4:00 PM, at 30 Wynmere Dr, in Horsham Twp, Montgomery County.</p> <p>A gas line owned by Peco An Exelon Company was damaged. 911 was contacted. Damage info: 1 - &lt; 6 hrs - 1 customer listed</p> <p>PECO An Exelon Company, the facility and project owner, submitted an Alleged Violation Report (AVR). Their AVR states, "RIGGS DISTLER was excavating with a Directional Drill to install new electric cable for Peco under ticket number 20250793333 when they drilled into the 1/2 " plastic gas service within the tolerance zone of 18", while onsite it was found that RIGGS DISTLER soft dug and exposed the service for 30 Wynmere prior to crossing it with the drill it was found that when RIGGS DISTLER exposed the marked gas service but did not drill where they exposed the service resulting in Riggs Distler not seeing that the depth changed on the gas service so when Riggs Distler went to go under the service they were not aware of the depth change resulting in the service being damaged 14" from the gas markout and the service needing to be repaired." PECO submitted a pdf Investigation Report, including photos, created by their contracted locator USIC. The photos show where the damage occurred with a Hit Kit indicating the damage was within the tolerance zone.</p> <p>Riggs Distler, the excavator, submitted an AVR. Their AVR states, "A Riggs Distler HDD crew was directional drilling when a mismarked gas service was damaged. While roughly 3' from the exposed gas test pit, the crew smelled gas and proceeded to stop all work. There were no injuries associated with this event." No photos were submitted with the report.</p> <p>Ticket #20250793333 had a response due date of 3-24-2025. Comcast did not respond "Field Marked" until 3-31-2025. Ticket #20250900747 had a response due date of 4-2-2025. Comcast did not respond "Field Marked" until 4-3-2025.</p> <p>Violations:</p> <p>Excavator - Riggs Distler Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Facility (other) – Comcast Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time.</p>	<p>Section 2(5)(v) 3rd offense \$750.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time.  Recommendation: The penalties are applied. PUC compliance training was recently completed.</p>	
54170	<p><b>Facility Owner:</b> UGI UTILITIES INC  <b>Contractor/Excavator:</b> Green Valley Landscaping</p>	<p><u>On 4/2/2025 10:30:00 AM at 21 Atherton Ave., WYOMING BORO, LUZERNE</u> At the Tuesday 9/9/2025, DPC meeting, disputing was Green Valley Landscaping, and it was voted to remove all penalties and violations.  *****  Disputing- Green Valley Landscaping Inc, they gave no reason why. See attached emails disputing and additional info  *****  The incident occurred on Wednesday, April 2, 2025, at 21 Atherton Avenue, in Wyoming Borough, Luzerne County.   A gas line was damaged. There are no tickets associated with this incident.   UGI Utilities stated in their Alleged Violation Report (AVR) that the excavator, Green Valley Landscaping was working without a One Call ticket, and explain they were using a skid steer to remove grass when they struck a piece of concrete that was poured around the gas service line, resulting in damage.  UGI provided photos of the damaged severed line, and there is no indication that 911 was called  The PA One Call Compliance commented that the contractor has placed One Call notifications with PA One Call in the past. Listed contact information for Green Valley Landscaping is the most recent contact info on file. There are no tickets associated with this incident.   Green Valley Landscaping did not submit an AVR within 30 days of striking a line.   Violations:   *Green Valley Landscaping is in violation of sections:  5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe.  5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid.  5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line.  Recommendation: PUC Compliance Education Required and Penalties Applied</p>	<p><b>Green Valley Landscaping: \$0.00</b></p>
53940	<p><b>Facility Owner:</b> HANOVER TOWNSHIP LUZERNE COUNTY  <b>Contractor/Excavator:</b> RLE ENTERPRISES  <b>Project Owner:</b> Pennsylvania American Water (PAWC)</p>	<p><u>On 4/3/2025 11:00:00 AM at OAKLAWN AVE., HANOVER TWP, LUZERNE</u> On September 9th, 2025, the Damage Prevention Committee (DPC) voted to keep the three 2(5)(i) violations and education, and remove the 2(10) violation for Hanover Township. The DPC also voted to keep the violations and education for RLE Enterprises, and increase each violation from \$250 to \$500 for a total of \$1500. RLE did not attend the DPC meeting.</p>	<p><b>HANOVER TOWNSHIP LUZERNE COUNTY:</b>  <b>\$1,500.00</b>  Section 2(5)(i) 1st Offense \$500.00   Section 2(5)(i) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>*****</p> <p>HANOVER TOWNSHIP LUZERNE COUNTY - Disputing 2(5)(i), 2(5)(i), 2(5)(i), 2(10) RLE - Disputing - 5(20), 5(20), 5(20) Pennsylvania American Water (PAWC) - 2(5)(v.2) - Penalty by 50% from \$250 to \$125, Agrees to Education; 2(5)(v.2) - Penalty by 50% from \$250 to \$125, Agrees to Education</p> <p>****</p> <p>The incident occurred on 4/3/2025 at 11:00 AM, on Oaklawn Ave, in Hanover Twp, Luzerne County.</p> <p>A sewer line owned by Hanover Township was damaged.</p> <p>Hanover Township Luzerne County, is a facility owner. An Alleged Violation Report (AVR) has not been submitted as of 5/19/2025.</p> <p>PENNSYLVANIA AMERICAN WATER, the project owner, submitted an AVR. Their AVR states, "R.L.E was installing new water main on Oaklawn Ave, Hanover. While excavating they hit an 6" unmarked sewer lateral to house #21 &amp; #20. R.L.E made the repairs to the unmarked laterals."</p> <p>Ticket #20250792701 had a response due date of 03-24-2025. Pennsylvania American Water Wilkes Barre, responded on 3-24-2025, "Scheduled Date &amp; Time Lines Will Be Marked By: 05 Apr 2025 1300" and their final response of "Field Marked" was on 4-10-2025.</p> <p>Ticket #20250713607 had a response due date of 03-14-2025. Pennsylvania American Water Wilkes Barre, responded on 3-14-2025, "Scheduled Date &amp; Time Lines Will Be Marked By: 15 Mar 2025 1500" and their final response of "Field Marked" was on 4-10-2025.</p> <p>R L E Enterprises, the excavator, submitted an AVR. Their AVR states, "WHILE DIGGING FOR A NEW WATER MAIN INSTALLATION, OUR CREW STRUCK AN UNMARKED SEWER LATERAL FOR HOUSE #23 OAKLAWN AVE. RLE MADE REPAIRS AND RESTORED SERVICE IN A TIMELY MANNER."</p> <p>RLE submitted 2 additional AVRs for #21, and #20 OAKLAWN AVE., as well as 5 photos total of the site. The excavation is within a township, and the photos show the work site is in a residential area where a reasonable person would believe the homes are connected to public sewer, as there are water curb stops in front of homes in the area. There are visible blue and yellow markings present in front of 23 Oaklawn Ave, and a blue marking on a curb stop in front of 21 Oaklawn Ave. No green markings are shown in the photos. The excavation and damage was under the road surface.</p> <p>R L E Enterprises allegedly damaged 3 sewer lines at 13, 14, and 15 Oaklawn Ave on 4-7-2025 at 9:00 AM during</p>	<p>Section 2(5)(i) 1st Offense \$500.00</p> <p><b>RLE ENTERPRISES: \$1,500.00</b></p> <p>Section 5(20) 1st Offense \$500.00</p> <p>Section 5(20) 1st Offense \$500.00</p> <p>Section 5(20) 1st Offense \$500.00</p> <p><b>Pennsylvania American Water (PAWC): \$250.00</b></p> <p>Section 2(5)(v.2) 1st Offense \$125.00</p> <p>Section 2(5)(v.2) 1st Offense \$125.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>the same project. Reference Case #053965 for this incident.</p> <p>Violations:            Facility – Hanover Township:            Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.            20 Oaklawn Ave            Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.            21 Oaklawn Ave            Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.            23 Oaklawn Ave            Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work.            Recommendation: The penalties are applied. PUC compliance training education is required.</p> <p>Facility – Pennsylvania American Water:            Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Tickets: 20250713607            Recommendation: The penalty is applied. PUC compliance training was completed recently.            Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Tickets: 20250792701            These violations will be assessed on Case #053940.            Recommendation: The penalty is applied. PUC compliance training was completed recently.</p> <p>Excavator - R L E Enterprises:            Section 5(20) – Excavator failed to renotify One Call of an unmarked or incorrectly marked facility upon arrival at a work site. 20 Oaklawn Ave            Section 5(20) – Excavator failed to renotify One Call of an unmarked or incorrectly marked facility upon arrival at a work site. 21 Oaklawn Ave            Section 5(20) – Excavator failed to renotify One Call of an unmarked or incorrectly marked facility upon arrival at a work site. 23 Oaklawn Ave            Recommendation: The penalties are applied. PUC compliance training education is required.</p>	
54221	<p><b>Facility Owner:</b> First Energy - Penelec  <b>Contractor/Excavator:</b> KUKURIN CONTRACTING INC  <b>Project Owner:</b> FRANKSTOWN TOWNSHIP  <b>Designer:</b> STIFFLER MCGRAW AND ASSOCIATES</p>	<p><u>On 4/7/2025 8:20:00 AM at AGGIE STREET (MH C6 TO C9), FRANKSTOWN TWP, BLAIR</u> On 09/9/2025: The Damage Prevention Committee (DPC) voted to remove Kukurin Contracting's violation and penalty.</p> <p>***            Kukurin Contracting is disputing.</p> <p>Submitted complex meeting notes with highlight of: "Rep from Penelec stated the prints are just a guide."</p> <p>***</p>	<p><b>KUKURIN CONTRACTING INC:</b>  <b>\$0.00</b></p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Incident occurred on April 7th, 2025, at 8:20am along Aggie Street, Frankstown Township, Blair County.</p> <p>An electric line was damaged.</p> <p>Penelec's Alleged Violation Report (AVR) states, "On January 14, 2025, Kukurin Contracting Inc, "Excavator", submitted POCS Routine Ticket 20250140441 to replace the sanitary sewer on Aggie Street (MH C6 to C9), Frankstown Township, Blair County, Pennsylvania. On April 3, 2025, Penelec was notified of an outage at 431 Aggie Street. USIC, Penelec's Contract Locator, investigated and determined that the Excavator damaged an underground primary line. The root cause of the damage is the Excavator did not submit an Update request through the PA One Call System to refresh the marks that were placed back in January."</p> <p>Kukurin Contracting's AVR states, "ON 4/7/25, WHILE EXCAVATING TO INSTALL A SANITARY SEWER LATERAL NEAR 347 AGGIE STREET, KUKURIN STRUCK A MISMARKED PENELEC CABLE THAT WAS 10 FT OFF ITS MARKS. SEE INCLUDED PHOTOS. BASED ON USIC'S MARKS, THE ELECTRICAL LINE WAS SHOWN BEHIND THE SEWER CLEANOUT WE WERE DIGGING TOWARDS. HOWEVER, IT WAS 10 FT CLOSER TO THE STREET AND WE STRUCK IT AS WE EXCAVATED FROM THE SEWER MAIN IN THE STREET TOWARDS THE CLEANOUT."</p> <p>Frankstown Township's AVR states, "CONTRACTOR STRUCK A N ELECTRIC CABLE THAT WAS MIS-MARKED BY APPROXIMATELY 10'."</p> <p>Stiffler McGraw &amp; Associates' AVR states, "The contractor, Kukurin was excavating to install the service lateral for 347 Aggie Street and while excavating they struck a penelec line that was not marked. The original mark for the power line was approximately 10 feet away from the line that was struck. The excavator stopped worked."</p> <p>Designs on S9 from Stiffler McGraw &amp; Associates show the electric main running parallel with the road and in line with the lower portion of the UBOX. Penelec pictures show a flag off the lower end of the UBOX within the tolerance zone of the damaged line. See page 6 of the Damage Report from Penelec. Kukurin Contracting pictures show the lateral markout to the home.</p> <p>Case is related to 52828.</p> <p>Violations:</p> <p>Kukurin Contracting Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
53965	<p><b>Facility Owner:</b>  HANOVER TOWNSHIP  LUZERNE COUNTY</p> <p><b>Contractor/Excavator:</b>  RLE ENTERPRISES</p> <p><b>Project Owner:</b>  Pennsylvania American Water (PAWC) - Placeholder</p> <p><b>Other:</b> Pennsylvania American Water (PAWC)</p>	<p><u>On 4/7/2025 9:00:00 AM at 14 OAKLAWN AVE., HANOVER TWP, LUZERNE</u> On September 9th, 2025, the Damage Prevention Committee (DPC) voted to keep the three 2(5)(i) violations and education, and remove the 2(10) violation for Hanover Township. The DPC also voted to keep the violations and education for RLE Enterprises, and increase each violation from \$250 to \$500 for a total of \$1500. RLE did not attend the DPC meeting.</p> <p>*****</p> <p>HANOVER TOWNSHIP LUZERNE COUNTY - Disputing 2(5)(i), 2(5)(i), 2(5)(i), 2(10) RLE - Disputing - 5(20), 5(20), 5(20)</p> <p>*****</p> <p>The incident occurred on 4-7-2025 at 9:00 AM, at 13, 14, and 15 Oaklawn Ave., in Hanover Twp., Luzerne County.</p> <p>A sewer line owned by Hanover Township Luzerne County was damaged.</p> <p>Hanover Township Luzerne County, the facility owner, has not submitted an Alleged Violation Report (AVR) as of 5/19/2025.</p> <p>R L E Enterprises, the excavator, submitted an AVR. Their AVR states, "WHILE DIGGING FOR A NEW WATER MAIN INSTALLATION, OUR CREW STRUCK AN UNMARKED SEWER LATERIAL FOR HOUSE # 13 OAKLAWN AVE. RLE MADE REPAIRS AND RESTORED SERVICE IN A TIMELY MANNER." 2 additional AVRs were submitted for 14 and 15 Oaklawn Ave.</p> <p>RLE submitted 5 photos of the site. The excavation is within a township, and the photos show the work site is in a residential area where a reasonable person would believe the homes are connected to public sewer, as there are water curb stops in front of homes in the area. 15 Oaklawn Ave. has no visible marks on the unexcavated road. The photo of 14 Oaklawn Ave. has a yellow marking visible that is not within the tolerance zone where the damage occurred.</p> <p>R L E Enterprises allegedly damaged 3 sewer lines at 20, 21, and 23 Oaklawn Ave on 4/3/2025 at 11:00 AM during the same project. Reference Case #053940 for this incident.</p> <p>Pennsylvania American Water, facility/other and project owner, submitted an AVR. Their AVR states, "R.L.E was installing new water main on Oaklawn Ave, Hanover. While excavating they hit three 6" unmarked sewer lateral to house #13,#14 &amp; #15. R.L.E made the repairs to the unmarked laterals."</p> <p>Ticket #20250792701 had a response due date of 03-14-2025. Pennsylvania American Water Wilkes Barre, responded on 3-24-2025, "Scheduled Date &amp; Time Lines Will Be Marked By: 05 Apr 2025 1300" and their final response of "Field Marked" was on 4-10-2025.</p>	<p><b>HANOVER TOWNSHIP LUZERNE COUNTY:</b>  <b>\$1,500.00</b>  Section 2(5)(i) 1st Offense \$500.00</p> <p>Section 2(5)(i) 1st Offense \$500.00</p> <p>Section 2(5)(i) 1st Offense \$500.00</p> <p><b>RLE ENTERPRISES:</b>  <b>\$1,500.00</b>  Section 5(20) 1st Offense \$500.00</p> <p>Section 5(20) 1st Offense \$500.00</p> <p>Section 5(20) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Ticket #20250713607 had a response due date of 03-24-2025. Pennsylvania American Water Wilkes Barre, responded on 3-14-2025, "Scheduled Date &amp; Time Lines Will Be Marked By: 15 Mar 2025 1500" and their final response of "Field Marked" was on 4-10-2025.</p> <p>The ticket response alleged violations by Pennsylvania American Water will be addressed further on case 053940 as it precedes the current case of 053965, and is within the same work site for Ticket #20250713607 and #20250792701.</p> <p>Violations:  Facility – Hanover Township:  Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. 13 Oaklawn Ave  Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. 14 Oaklawn Ave  Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. 15 Oaklawn Ave  Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work.  Recommendation: The penalties are applied. PUC compliance training education is required.  Excavator - R L E Enterprises:  Section 5(20) – Excavator failed to renotify One Call of an unmarked or incorrectly marked facility upon arrival at a work site. 13 Oaklawn Ave  Section 5(20) – Excavator failed to renotify One Call of an unmarked or incorrectly marked facility upon arrival at a work site. 14 Oaklawn Ave  Section 5(20) – Excavator failed to renotify One Call of an unmarked or incorrectly marked facility upon arrival at a work site. 15 Oaklawn Ave  Recommendation: The penalties are applied. PUC compliance training education is required.</p>	
54626	<p><b>Facility Owner:</b> West Penn Power / FIRSTENERGY  <b>Contractor/Excavator:</b> J Kriebel Contracting  <b>Project Owner:</b> HOMEOWNER  <b>Other:</b> LIMESTONE TOWNSHIP - CLARION CO</p>	<p><u>On 4/8/2025 8:00:00 AM at 12085 E REIDSBURG RD, LIMESTONE TWP, CLARION</u> On 9/09/2025 Limestone township was a "No Show". The Damage Prevention Committee (DPC) voted to accept the Damage Prevention investigators (DPI) recommendations.</p> <p>Limestone township disagreed and stated that "Limestone Township would like to reject the DPI Report and present our case before the DPC. Limestone Township had a previous offense as we were in between secretaries. I was under the understanding that the tickets need responded to within 5 days, I have since corrected this. Our Township only has office hours on Mondays and Tuesday 4:30 - 8:00, I have begun checking them</p>	<p><b>West Penn Power / FIRSTENERGY:</b>  <b>\$500.00</b>  Section 2(5)(i) 1st Offense \$500.00</p> <p><b>J Kriebel Contracting:</b>  <b>\$0.00</b>  Section 5(16) 1st Offense \$0.00</p> <p><b>LIMESTONE TOWNSHIP - CLARION CO: \$250.00</b></p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>daily from home to prevent this in the future. I have also tried to contact 811 Liaison, Kevin via phone, he is on vacation. I will continue to communicate with him to have our map updated as 12085 E Reidsburg Road is located off of Limestone Township's right of way, it located on a state road. Thank you for your consideration. Please let me know if there is any other information needed in this matter.</p> <p>Kriebel Accepted. Kriebel disputed, completed an AVR, and education. DPI reduced penalty to \$0.</p> <p>West Penn accepts. *****</p> <p>The incident occurred on 4/08/2025 at 12085 E REIDSBURG RD in Limestone Township in Clarion County.</p> <p>An electric line owned by West Penn Power/FIRSTENERGY was damaged.</p> <p>West Penn Power/FIRSTENERGY stated in their Alleged Violation Report (AVR) that “On March 26, 2025, J Kriebel Contracting, Excavator, submitted POCS Routine Ticket 20250854994 to perform grading work at 12085 E Reidsburg Road, Limestone Township, Clarion County, Pennsylvania. On April 7, 2025, West Penn Power was notified of an outage at this location. USIC, West Penn Power’s Contract Locator, investigated and determined that the Excavator damaged an underground electric secondary service line. The root cause of the damage is USIC incorrectly marked West Penn Power’s facilities. Pictures and report were provided.</p> <p>J Kriebel Contracting AVR was due by 5/08/2025. No AVR has been received as of 5/29/2025.</p> <p>*Ticket 20250854994 was requested by J Kriebel Contracting on 3/26/2025 with a response due by 3/28/2025. Limestone Township Clarion County did not respond “clear” until 3/31/2025 at 4:51pm. Excavation was scheduled for 3/31/2025 9:00 a.m.</p> <p>*Emergency ticket 20250972830 was submitted by J Kriebel Contracting On 4/07/2025.</p> <p>*Emergency ticket 20250972830-001 is a renotify Emergency ticket that was submitted by J Kriebel Contracting. RNO Remarks: [ATTN WEST PENN POWER. CREW ON SITE. THE DAMAGE OCCURRED EARLIER WHEN THE LINE WAS UNMARKED. SINCE THEN A USIC REPRESENTATIVE ARRIVED AND MARKED THE UG LINE. THERE IS AN EXPOSED BARE WIRE STICKING UP OUT OF THE GROUND WHICH IS A DEAD END WIRE BUT IS STILL ENERGIZED. CALLER NEEDS THE LINE DE-ENERGIZED ASAP TO CONTINUE. PLEASE NOTIFY JOSHUA KRIEBEL 724-991-3563 WITH A CONTACT</p>	<p>Section 2(5)(v) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>NUMBER FOR WEST PENN POWER TO DE-ENERGIZE THE LINE ASAP. THANK YOU.]</p> <p>VIOLATIONS</p> <p>J Kriebel Contracting is in violation of: Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: The penalty is applied. Compliance Education is required.</p> <p>West Penn Power/FIRSTENERGY is in violation of: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: The penalties are applied.</p> <p>LIMESTONE TOWNSHIP - CLARION CO is in violation of: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Limestone Township Clarion County did not respond “clear” to ticket 20250854994 until 3/31/2025 at 4:51pm. Excavation was scheduled for 3/31/2025 9:00 a.m. Ticket was due by 3/28/2025. Recommendation: The penalty is applied. Compliance education is required. DPI returned a call to Bonnie from Limestone Township, who explained that this ticket area is not a part of their area.</p>	
54115	<p><b>Contractor/Excavator:</b> OSMOSE UTILITIES SERVICES INC <b>Project Owner:</b> FIRST ENERGY - Placeholder <b>Other:</b> ALLEN ENERGY LLC <b>Other:</b> APEX ENERGY (PA) LLC <b>Other:</b> ARMSTRONG <b>Other:</b> AT&amp;T <b>Other:</b> CNX MIDSTREAM PARTNERS <b>Other:</b> Columbia Gas <b>Other:</b> COMCAST <b>Other:</b> Everstream <b>Other:</b> GODDARD PARK VACATIONLAND CAMPGROUND <b>Other:</b> GREENSBURG CITY OF <b>Other:</b> J M G ENERGY LLC <b>Other:</b> KRIEBEL MINERALS INC <b>Other:</b> LAUREL MOUNTAIN MIDSTREAM LLC <b>Other:</b> Lumen <b>Other:</b> LUMOS NETWORKS OF WV</p>	<p><u>On 4/9/2025 8:15:00 AM at MULTIPLE, MULTIPLE, ERIE</u> On September 9th, 2025, the Damage Prevention Committee voted to keep the violations, and reduce the penalties to \$0, for 2(5)(v) and 2(5)(viii) for both Laurel Mountain Midstream and Allen Energy. ***** Laurel Mountain MidStream - Disputing Section 2(5)(v) and Section 2(5)(viii). Allen Energy - Disputing Section 2(5)(v) and Section 2(5)(viii). ***** Penelec accepted 2(5)(viii) and DPI removed 2(5)(v). Penelec is no longer disputing. Municipal Authority of Westmoreland County:Section 2(5)(v) – Reduced from \$250 to warning / Section 2(5)(viii) – Reduced from \$500 to warning TEXAS EASTERN/SPECTRA - Section 2(5)(v) – Reduced from \$250 to warning / Section 2(5)(viii) - Reduced from \$500 to warning GODDARD PARK VACATIONLAND CAMPGROUND - Reduced 2(5)(v) from \$250 to Warning PENNECO - Violation and Penalty Withdrawn - Not a Facility UNITY TOWNSHIP MUNICIPAL AUTHORITY - 2(5)(v) - Fine reduced from \$250 to Warning 2(5)(viii) - Reduced from \$500 to warning Kriebel Energy - Violation and Penalty Withdrawn - Not a Facility Everstream - 2(5)(v) - Fine reduced from \$250 to Warning</p>	<p><b>ALLEN ENERGY LLC: \$0.00</b> Section 2(5)(v) 1st Offense \$0.00</p> <p>Section 2(5)(viii) 1st Offense \$0.00</p> <p><b>APEX ENERGY (PA) LLC: \$1,000.00</b> Section 2(5)(v) 1st Offense \$500.00</p> <p>Section 2(5)(viii) 1st Offense \$500.00</p> <p><b>ARMSTRONG: \$500.00</b> Section 2(5)(viii) 1st Offense \$500.00</p> <p><b>AT&amp;T: \$2,000.00</b> Section 2(5)(v) 2nd Offense \$1,000.00</p> <p>Section 2(5)(viii) 2nd Offense \$1,000.00</p> <p><b>CNX MIDSTREAM PARTNERS: \$1,000.00</b> Section 2(5)(viii) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>FORMERLY NTELOS  <b>Other:</b> MURPHY PRODUCTION INC  <b>Other:</b> NORTH PENN TELEPHONE COMPANY  <b>Other:</b> PENN TELECOM INC  <b>Other:</b> PENNECO PIPELINE CORPORATION  <b>Other:</b> Pennsylvania Electric Company - First Energy  <b>Other:</b> TEXAS EASTERN/SPECTRA  <b>Other:</b> UNITI FIBER TOWNSHIP MUNICIPAL AUTHORITY  <b>Other:</b> Verizon Business  <b>Other:</b> Westmoreland County Municipal Authority  <b>Other:</b> WINDSTREAM ENTERPRISE</p>	<p>Uniti Fiber - 2(5)(v) - Fine reduced from \$250 to Warning  Uniti Fiber - 2(5)(viii) - Fine reduced from \$500 to Warning  *****  The incident occurred on 4-9-2025 at 8:15 AM, and is in reference to a complex project meeting for pole restoration by Osmose Utilities, for First Energy, at 3 separate locations across western Pennsylvania.</p> <p>Osmose Utilities Services INC, the excavator, submitted an AVR. Their AVR states, "See attached WORD document for a list of non respondents/ non-attendees to the pre-construction teleconference call for the PA_FIRST ENERGY_COMPLEX PLAN 2 on Wednesday 4/9/2025 @ 8:15 A.M. Thank you, Jajuanna O'Hara One Call Locator 60 Amlajack Blvd, Ste 500   Newnan, GA 30265 Office: 770-632-6775" It was then confirmed with Jajuanna O'Hara on 5/8/2025 that the list was correct and accurate. Jajuanna replied, "All the utilities listed on the word document did not attend the meeting. Thank you for asking. I currently check the attendance list from the meeting and do not list any utility that attended the meeting, even if they did not code the response correctly."</p> <p>First Energy, the project owner, is being represented by Osmose Utilities in their AVR.</p> <p>No designer has been identified.</p> <p>The only AVR received was from Osmose Utilities, which included First Energy as the Project Owner. Facilities that did not attend the Complex Project Meeting, or enter a final response to Ticket 20250931366, 20250931364 or 2025093136 will be listed in the violation section below.</p> <p>Entering a response to all notices through the One Call System, as well as attending a complex project meeting is required by Act 127 of 2024.</p> <p>SECTION 2. It shall be the duty of each facility owner:  (v)To respond to all notices through the One Call System, provided the request is made in the time frame set forth under this act. The response shall be made not later than the end of the second business day following receipt of the notification by the One Call System, excluding the business day upon which the notification is received, or not later than the day prior to the lawful start date of excavation if the excavator specifies a later date or, in the case of an emergency, to respond through the One Call System as soon as practicable following receipt of notification of the emergency by the One Call System.  (viii)To participate in preconstruction meetings for a complex project or as described in section 5(3).</p>	<p>Section 2(5)(v) 1st Offense \$500.00</p> <p><b>Columbia Gas: \$250.00</b>  Section 2(5)(v) 1st Offense \$250.00</p> <p><b>COMCAST: \$1,000.00</b>  Section 2(5)(v) 1st Offense \$500.00</p> <p>Section 2(5)(viii) 1st Offense \$500.00</p> <p><b>Everstream: \$500.00</b>  Section 2(5)(v) 1st Offense \$0.00</p> <p>Section 2(5)(viii) 1st Offense \$500.00</p> <p><b>GODDARD PARK VACATIONLAND CAMPGROUND: \$500.00</b>  Section 2(5)(v) 1st Offense \$0.00</p> <p>Section 2(5)(viii) 1st Offense \$500.00</p> <p><b>GREENSBURG CITY OF: \$750.00</b>  Section 2(5)(v) 1st Offense \$250.00</p> <p>Section 2(5)(viii) 1st Offense \$500.00</p> <p><b>J M G ENERGY LLC: \$750.00</b>  Section 2(5)(v) 1st Offense \$250.00</p> <p>Section 2(5)(viii) 1st Offense \$500.00</p> <p><b>KRIEBEL MINERALS INC: \$0.00</b></p> <p><b>LAUREL MOUNTAIN MIDSTREAM LLC: \$0.00</b>  Section 2(5)(viii) 1st Offense \$0.00</p> <p>Section 2(5)(v) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>SECTION 5. It shall be the duty of each excavator who intends to perform excavation or demolition work within this Commonwealth:</p> <p>(3) In a complex project or if an excavator intends to perform work at multiple work sites or over a large area, to take reasonable steps to work with facility owners, including scheduling and conducting a preconstruction meeting, so that they may locate their facilities at a time reasonably in advance of the actual start of excavation or demolition work for each phase of the work. A preconstruction meeting may take place at any time prior to the commencement of excavation or demolition work, and the excavator, facility owners and designer, or their agents, shall attend the meeting. Notice of the meeting shall be given sufficiently in advance so as to permit attendance, either in person or electronically, by the excavator, facility owners and designer, or their agents, and shall include information sufficient to identify the scope of work.</p> <p>Violations: Facilities listed by Ticket:</p> <p>Ticket #20250931306: CDC Member Name ATM AT&amp;T: Section 2(5)(v) – Failed to respond to a routine One Call ticket. Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). EVS EVERSTREAM: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). LKC LUMEN FORMERLY LEVEL 3: Section 2(5)(v) – Failed to respond to a routine One Call ticket. LV PENNSYLVANIA ELECTRIC CO: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). PEG UNITI FIBER: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). QD1 NORTH PENN TELEPHONE COMPANY: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket #20250931364: CDC Member Name AEP APEX ENERGY (PA) LLC:</p>	<p><b>Lumen: \$500.00</b> Section 2(5)(v) 1st Offense \$500.00</p> <p><b>LUMOS NETWORKS OF WV FORMERLY NTELOS: \$500.00</b> Section 2(5)(viii) 1st Offense \$500.00</p> <p><b>MURPHY PRODUCTION INC: \$750.00</b> Section 2(5)(viii) 1st Offense \$500.00</p> <p>Section 2(5)(v) 1st Offense \$250.00</p> <p><b>NORTH PENN TELEPHONE COMPANY: \$250.00</b> Section 2(5)(v) 1st Offense \$250.00</p> <p><b>PENN TELECOM INC: \$500.00</b> Section 2(5)(viii) 1st Offense \$500.00</p> <p><b>PENNECO PIPELINE CORPORATION: \$0.00</b></p> <p><b>Pennsylvania Electric Company - First Energy: \$500.00</b> Section 2(5)(viii) 1st Offense \$500.00</p> <p><b>TEXAS EASTERN/SPECTRA: \$0.00</b> Section 2(5)(viii) 1st Offense \$0.00</p> <p>Section 2(5)(v) 1st Offense \$0.00</p> <p><b>UNITI FIBER: \$0.00</b> Section 2(5)(v) 1st Offense \$0.00</p> <p>Section 2(5)(viii) 1st Offense \$0.00</p> <p><b>UNITY TOWNSHIP MUNICIPAL AUTHORITY: \$0.00</b> Section 2(5)(v) 1st Offense</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(v) – Failed to respond to a routine One Call ticket.</p> <p>Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3).</p> <p>APM CNX MIDSTREAM PARTNERS: Section 2(5)(v) – Failed to respond to a routine One Call ticket.</p> <p>Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3).</p> <p>ATM AT&amp;T: Violation on Ticket 20250931306</p> <p>BD VERIZON PENNSYLVANIA LLC: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time.</p> <p>Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3).</p> <p>CGR COLUMBIA GAS OF PA INC JEANNETTE: Section 2(5)(v) – Failed to respond to a routine One Call ticket,</p> <p>CSA COLUMBIA GAS OF PA INC: Violation listed on CSA</p> <p>CUC WINDSTREAM ENTERPRISE/WHOLESALE: Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3).</p> <p>GSB GREENSBURG CITY OF: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time.</p> <p>Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3).</p> <p>IO COMCAST: Section 2(5)(v) – Failed to respond to a routine One Call ticket.</p> <p>Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3).</p> <p>JR WESTMORELAND CO MUNI AUTH OF: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time.</p> <p>Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3).</p> <p>JRM WESTMORELAND CO MUNI AUTH OF: Violation listed on JR</p> <p>JU WESTMORELAND CO MUNI AUTH OF:: Violation listed on JR</p> <p>KMI KRIEBEL MINERALS INC: Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3).</p> <p>LLI LAUREL MOUNTAIN MIDSTREAM LLC: Section 2(5)(v) – Failed to respond to a routine One Call ticket.</p> <p>Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3).</p> <p>MPR MURPHY PRODUCTION INC:</p>	<p>\$0.00</p> <p>Section 2(5)(viii) 1st Offense \$0.00</p> <p><b>Verizon Business:</b> <b>\$2,000.00</b></p> <p>Section 2(5)(viii) 2nd Offense \$1,000.00</p> <p>Section 2(5)(v) Subsequent \$1,000.00</p> <p><b>Westmoreland County Municipal Authority:</b> <b>\$0.00</b></p> <p>Section 2(5)(viii) 1st Offense \$0.00</p> <p>Section 2(5)(v) 1st Offense \$0.00</p> <p><b>WINDSTREAM ENTERPRISE: \$500.00</b></p> <p>Section 2(5)(viii) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time.</p> <p>Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3).</p> <p>NCC ARMSTRONG:</p> <p>Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3).</p> <p>NTE LUMOS NETWORKS OF WV FORMERLY NTELOS:</p> <p>Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3).</p> <p>PEC PENNECO PIPELINE CORPORATION:</p> <p>Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time.</p> <p>Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3).</p> <p>PTI PENN TELECOM INC:</p> <p>Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3).</p> <p>TX TEXAS EASTERN/SPECTRA:</p> <p>Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time.</p> <p>Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3).</p> <p>UN UNITY TOWNSHIP MUNICIPAL AUTHORITY:</p> <p>Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time.</p> <p>Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3).</p> <p>WCV WESTMORELAND CO MUNI AUTH OF: listed under JR</p> <p>Ticket #20250931366:</p> <p>CDC Member Name</p> <p>AEI ALLEN ENERGY LLC:</p> <p>Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time.</p> <p>Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3).</p> <p>GPC GODDARD PARK VACATIONLAND CAMPGROUND:</p> <p>Section 2(5)(v) – Failed to respond to a routine One Call ticket.</p> <p>Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3).</p> <p>JMG J M G ENERGY LLC:</p> <p>Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time.</p> <p>Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3).</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
54156	<p><b>Facility Owner:</b> PECO AN EXELON COMPANY</p> <p><b>Contractor/Excavator:</b> J LYONS MECHANICAL</p> <p><b>Project Owner:</b> DAVID DESIMONE</p> <p><b>Other:</b> Coatesville City</p>	<p><u>On 4/10/2025 12:00:00 AM at 330-334 E CHESTNUT ST, COATESVILLE CITY, CHESTER</u> At the Tuesday 9/9/2025 DPC meeting, disputing was Coatesville City, and it was voted to accept the DPI's recommendations. *****</p> <p>Dispute- Coatesville City stated, Due to the fact I responded to the request and we was clear of utilities in that area. See attached email. *****</p> <p>The incident occurred on Thursday, April 10, 2025, at 330-334 E. Chestnut Street, in Coatesville City, Chester County.</p> <p>PECO an Exelon Company's underground electric line was damaged.</p> <p>PECO stated in their Alleged Violation Report (AVR) that J Lyons Mechanical was excavating with a Gradeall to install water meter pits in the front of 330-334 E. Chestnut Street when they severed the correctly marked secondary main, after reviewing the post locate photos it was observed that J Lyons Mechanical had already started excavation at 330-334 E. Chestnut, it was found that J Lyons Mechanical did not expose the correctly marked secondary underneath the sidewalk resulting in the secondary being severed and in need of repair. PECO provided a detailed report and photos of the damaged line.</p> <p>J Lyons Mechanical did not submit an AVR within 30 days of striking a line.</p> <p>20250930028- Routine ticket placed on 4/3/2025. Late Response from- Coatesville City responded on 4/24/2025 as Clear No Facilities</p> <p>Violations:</p> <p>*J Lyons Mechanical is in violation of sections: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: PUC Compliance Education Required and Penalties Applied</p> <p>*Coatesville City is in violation of section: 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. 20250930028 Recommendation: PUC Compliance Education Required and Penalty Applied</p>	<p><b>J LYONS MECHANICAL:</b> <b>\$1,500.00</b> Section 5(4) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p><b>Coatesville City: \$250.00</b> Section 2(5)(v) 1st Offense \$250.00</p>
54200	<p><b>Facility Owner:</b> UGI UTILITIES, INC.</p> <p><b>Contractor/Excavator:</b> WILLIAM KUNSMAN &amp; SON PAVING &amp; SEALCOATING, LLC</p>	<p><u>On 4/15/2025 9:31:00 AM at 706 W MARKET ST, BETHLEHEM CITY, LEHIGH</u> At the 9/9/2025 DPC meeting, disputing was William Kunsman &amp; Son Paving &amp; Sealcoating, and they were NO SHOW. The DPC voted to Accept the DPI's recommendations and increase each penalty/violation by \$500. Section 5(4) 1st offense \$500 + \$500, total \$1,000. Section 5(16) 1st offense \$1,000 + \$500, total \$1,500. *****</p>	<p><b>WILLIAM KUNSMAN &amp; SON PAVING &amp; SEALCOATING, LLC:</b> <b>\$2,500.00</b> Section 5(4) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Disputing- WILLIAM KUNSMAN &amp; SON PAVING &amp; SEALCOATING and stated in an email, We do not agree with this letter. The gas line was touching the curb located about 6 inches underground, touching the bottom of the curb. Curb was bumped and small nick on the pipeline. When UGI came to investigate we were told that the UGI rep was surprised that the gas line was located that close to the curb.</p> <p>*****</p> <p>The incident occurred on Tuesday, April 15, 2025, at 706 W. Market Street, in Bethlehem City, Lehigh County.</p> <p>A gas line was damaged</p> <p>UGI Utilities stated in their Alleged Violation Report (AVR) that Kunsman and Sons Paving was digging to repair curbing and when doing so they struck a correctly marked gas service facility creating a damage. Kunsman was digging in the tolerance zone. UGI provided photos of the damaged line.</p> <p>Kunsman and Sons Paving placed a Damage Emergency ticket, 20251051186 and called 911. Kunsman and Sons Paving did not submit an AVR within 30 days of striking a line.</p> <p>Violations:</p> <p>*Kunsman and Sons Paving is in violation of sections:  5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.  5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line.  Recommendation: PUC Compliance Education Required and Penalties Applied</p>	
54974	<p><b>Facility Owner:</b> PITTSBURGH WATER</p> <p><b>Contractor/Excavator:</b> M OHERRON COMPANY</p> <p><b>Project Owner:</b> Peoples Gas Company</p> <p><b>Designer:</b> Peoples Gas Co - Placeholder</p> <p><b>Other:</b> Crown Castle</p>	<p>On 4/21/2025 12:00:00 PM at <u>S LINDEN AVE, PITTSBURGH CITY, ALLEGHENY</u> On September 9th, 2025, the Damage Prevention Committee voted to remove the 2(5)(v) violation and penalty for Peoples Gas.</p> <p>*****</p> <p>Peoples - Disputing 2(5)(v)</p> <p>*****</p> <p>The incident occurred on 4/21/2025 at 12:00:00 PM, on S Linden Ave, in Pittsburgh City, Allegheny County.</p> <p>A water line owned by Pittsburgh Water &amp; Sewer Authority was damaged.</p> <p>Approximate Number of Customers Affected-1  Repair Cost \$1,001-\$5,000  Duration of Service Interruption 1 - &lt; 6 hrs</p> <p>Pittsburgh Water is the facility owner. Their Alleged Violation Report (AVR) states, “M O Herron digging and hit accurate marked copper service water line. PWSA responded and made repairs. Carless digging in tolerance zone.”</p> <p>M Oherron Company is the excavator. Their AVR states, “M. O'Herron Co digging hole in street at for gas service</p>	<p><b>M OHERRON COMPANY: \$500.00</b>  Section 5(4) 1st Offense \$500.00</p> <p><b>Peoples Gas Company: \$0.00</b></p> <p><b>Crown Castle: \$250.00</b>  Section 2(5)(v) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>line renewal to new install gas main for 126 S. Linden. Water main was in sidewalk down street to this point with water services not crossing road. Beginning at this house there were dual mains with second water main in road, some houses were tapped off street water main and not sidewalk water main from this point. Sidewalk water mark behind tree and dump truck parked over top of street mark. Crew failed to notice service was tapped to street instead of sidewalk.”</p> <p>Peoples Gas Company LLC is the project owner and designer. Their AVR states, “M. O'Herron Co digging hole in street at for gas service line renewal to new install gas main for 126 S. Linden. Water main was in sidewalk down street to this point with water services not crossing road. Beginning at this house there were dual mains with second water main in road, some houses were tapped off street water main and not sidewalk water main from this point. Sidewalk water mark behind tree and dump truck parked over top of street mark. Crew failed to notice service was tapped to street instead of sidewalk.”</p> <p>Multiple photos were submitted of the site and damage. There are blue marks within the tolerance zone of the damage, indicated by a Hit Kit.</p> <p>Ticket #20250901160 had a response due date of 4/2/2025. People’s Gas responded “Field Marked” on 4/3/2025. Crown Castle responded “Insufficient Information” on 4/3/2025 and “Field Marked” on 4/4/2025.</p> <p>Violations: Excavator - M Oherron Company: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: PUC compliance training education is required.</p> <p>Facility- People’s Gas (Other): Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. #20250901160 Recommendation: PUC compliance training was recently completed.</p> <p>Facility- Crown Castle ASL (Other): Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. #20250901160 Recommendation: PUC compliance training was recently completed.</p>	
54468	<p><b>Facility Owner:</b> Philadelphia Gas Works <b>Contractor/Excavator:</b> Philadelphia City Department of Streets <b>Project Owner:</b> City of Philadelphia</p>	<p><u>On 4/25/2025 1:32:00 PM at E DUNCANNON AVE, PHILADELPHIA CITY, PHILADELPHIA</u> On September 9th, 2025, the Damage Prevention Committee (DPC) voted to keep the violations for Philadelphia City Department of Streets, and increase the penalty from \$500 to \$1000 for 5(22), and increase the penalty from \$250 to \$750 for 2(5)(v). Philadelphia City Department of Streets did not attend the DPC. The DPC voted to</p>	<p><b>Philadelphia City Department of Streets:</b> <b>\$1,750.00</b> Section 5(22) 1st Offense \$1,000.00  Section 2(5)(v) 1st Offense \$750.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p><b>Other:</b> Philadelphia City Water Department</p>	<p>remove the 2(5)(v) violation and penalty for Philadelphia City Water Department.</p> <p>*****</p> <p>Philadelphia Water Department is disputing. ***</p> <p>Philadelphia Department of Streets is disputing.</p> <p>***</p> <p>The incident occurred on 4/25/2025 at 1:32 PM, on E Duncannon Ave, in Philadelphia City, Philadelphia County.</p> <p>* No damage *</p> <p>Philadelphia Gas Works submitted an Alleged Violation Report (AVR) stating, “Streets department put in a fake emergency ticket for this location and all they are doing here is installing street signs this is not an emergency and goes against the one call rules.”</p> <p>Philadelphia City Department of Streets is the excavator. An AVR has not been filed.</p> <p>City Of Philadelphia is the project owner.</p> <p>Ticket # 20251152441 New – Excavation– Emergency was entered on 4/25/2025 at 1:32 PM. The Ticket notes, “INSTALL NEW SIGN POLES INFRONT OF 123 AND ACROSS THE STREEET OF 121 AND 147 E DUNCANNON AVE”. Philadelphia City Water Department responded Field Marked on 5/22/2025, and Philadelphia City Department Of Streets responded “Clear” on 4/28/2025.</p> <p>Violations: Excavator - Philadelphia City Department of Streets: Section 5(22) – Excavator provided a misrepresentation of an emergency excavation, subject to an administrative penalty imposed under section 7(10). Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket # 20251152441 Recommendation: PUC Online Compliance Training is required. Facility(other) - Philadelphia City Water Department: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket # 20251152441 Recommendation: PUC Online Compliance Training is required.</p>	<p><b>Philadelphia City Water Department: \$0.00</b></p>
54562	<p><b>Facility Owner:</b> UGI Utilities, Inc. <b>Contractor/Excavator:</b> Interstate Paving LLC <b>Other:</b> ADAMS ELECTRIC COOPERATIVE INC <b>Other:</b> BRIGHTSPEED</p>	<p><u>On 4/28/2025 9:53:00 AM at 963 Baltimore Rd, SOUTHAMPTON TWP, CUMBERLAND</u> On 9/09/2025 Interstate Paving was not in attendance. The Damage Prevention Committee (DPC) voted to accept the Damage Prevention investigators (DPI) recommendations: 5(2.1)- Accept the DPIs recommendation. Increase the penalty by \$500 due to not attending.</p>	<p><b>Interstate Paving LLC: \$3,000.00</b> Section 5(2.1) 1st Offense \$1,500.00  Section 5(16) 1st Offense \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p><b>Other:</b> COMCAST CABLEVISION <b>Other:</b> HOMEOWNER <b>Other:</b> MET ED / FIRST ENERGY <b>Other:</b> PENELEC/ FIRST ENERGY</p>	<p>5(16)- Accept the DPIs recommendation. Increase the penalty by \$500 due to not attending. Met Ed / First Energy: 2(5)(vii)- Accept the DPIs recommendation. Penelec/ First Energy: 2(5)(vii)- Accept the DPIs recommendation. Adams Electric Cooperative Inc: 2(5)(i.2)- Accept the DPIs recommendation. 2(5)(v.2)- Accept the DPIs recommendation. ***** Interstate Paving is disputing.</p> <p>Comcast accepts. ****</p> <p>Met Ed and Penelec are disputing. Penelec is asking for a reduced penalty. Met Ed is working to update their mapping due to not owning lines in the area. Both companies never responded to the emergency ticket called in by the gas company for markouts. **** Adams Electric is disputing. **** ADAMS ELECTRIC COOPERATIVE INC disagreed and stated that USIC says that not all emergency tickets need to be responded to and "that it is not their practice to locate for "a No One Call Emergency ticket", such as ticket #20251181413". DPI Maki emailed a copy of ACT 127-2024 and asked to have USIC find where they do not need to enter a final response to all locate tickets. *****</p> <p>The incident occurred on 4/28/2025, at 963 Baltimore Road, in SOUTHAMPTON TWP, Cumberland County.</p> <p>*No Damage Mechanized equipment was being used by an excavator. Gas lines owned by UGI were not marked.</p> <p>UGI the facility owner stated in their Alleged Violation Report (AVR) that "UGI employee noticed Interstate Paving grading a driveway and using a jackhammer without the presence of marks. UGI employee stopped the work and asked excavator to place a ticket with PA One Call. Gas main and service exist on property". UGI placed a No One Call Emergency ticket, 20251181413. Pictures were submitted. PA One Call Compliance commented: Contractor has placed One Call notifications with PA One Call in the past.</p> <p>Interstate Paving LLC the excavator AVR was due on 5/28/2025. No AVR has been received. No contact has been made as of 5/30/2025.</p> <p>Homeowner is the project owner. The excavation was done on the private driveway. No AVR was requested. ***** *Emergency ticket 20251181413 was submitted by UGI on 4/28/2025 at 9:53am.</p>	<p><b>ADAMS ELECTRIC COOPERATIVE INC: \$500.00</b> Section 2(5)(v.2) 1st Offense \$250.00</p> <p>Section 2(5)(i.2) 1st Offense \$250.00</p> <p><b>BRIGHTSPEED: \$500.00</b> Section 2(5)(i.2) 1st Offense \$250.00</p> <p>Section 2(5)(v.2) 1st Offense \$250.00</p> <p><b>COMCAST CABLEVISION: \$500.00</b> Section 2(5)(v.2) 1st Offense \$250.00</p> <p>Section 2(5)(i.2) 1st Offense \$250.00</p> <p><b>MET ED / FIRST ENERGY: \$1,000.00</b> Section 2(5)(vii) 1st Offense \$1,000.00</p> <p><b>PENELEC/ FIRST ENERGY: \$1,000.00</b> Section 2(5)(vii) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>COMCAST responded with Insuff.Info. and this was never updated with a final response.  MET ED / FIRST ENERGY and PENELEC / FIRST ENERGY never responded.  BRIGHTSPEED responded- Not Marked. No Access. This response was not updated.  ADAMS ELECTRIC responded “conflict. DCTF by FO” This response was not updated.</p> <p>VIOLATIONS:</p> <p>Interstate Paving LLC is in violation of:  Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe.  Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or damaging a facility owner’s line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Please note that the excavator was told by an UGI employee that a ticket needs to be submitted. It is a violation to not submit a OneCall ticket prior to excavating.  Recommendation: The penalties are applied.  Compliance Education is required.</p> <p>COMCAST CABLEVISION is in violation of:  Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests*Emergency ticket 20251181413 was submitted by UGI on 4/28/2025 at 9:53. COMCAST responded with Insuff.Info. and this was never updated to a final response.  Section 2(5)(i.2) – Failed to document Communications between a Facility Owner and Excavator to ensure the excavator is aware of a facility owner’s inability to locate its facilities.  Recommendation: The penalties are applied.</p> <p>MET ED / FIRST ENERGY is in violation of:  Section 2(5)(vii) – Failed to respond to emergency notification 20251181413 as soon as practicable following notification. MET ED / FIRST ENERGY never responded.  Recommendation: The penalty is applied. Compliance Education is required.</p> <p>PENELEC/ FIRST ENERGY is in violation of:  Section 2(5)(vii) – Failed to respond to emergency notification 20251181413 as soon as practicable following notification. PENELEC / FIRST ENERGY never responded.  Recommendation: The penalty is applied. Compliance Education is required.</p> <p>BRIGHTSPEED is in violation of:  Section 2(5)(i.2) – Failed to document Communications between a Facility Owner and Excavator to ensure the excavator is aware of a facility owner’s inability to locate its facilities.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests            BRIGHTSPEED responded- Not Marked. No Access. This response was not updated in emergency notification 20251181413.            Recommendation: The penalties are applied.</p> <p>ADAMS ELECTRIC COOPERATIVE INC is in violation of:            Section 2(5)(i.2) – Failed to document Communications between a Facility Owner and Excavator to ensure the excavator is aware of a facility owner’s inability to locate its facilities.            Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests ADAMS ELECTRIC responded “conflict. DCTF by FO” to emergency notification 20251181413. This response was not updated.            Recommendation: The penalties are applied.            Compliance Education is required.</p>	
54774	<p><b>Facility Owner:</b> Peoples Natural Gas  <b>Contractor/Excavator:</b> A. Folino Construction, Inc.  <b>Project Owner:</b> Pittsburgh Water</p>	<p><u>On 4/30/2025 2:15:00 PM at MORRISEY ST, PITTSBURGH CITY, ALLEGHENY</u> On September 9th, 2025, the Damage Prevention Committee (DPC) voted to remove the 2(5)(v) violation and penalty for Peoples Gas. The DPC also voted to keep the 5(3) and 5(7) violations, add PUC Online Compliance Training, and remove the 5(7) violation for A.Folino.</p> <p>*****            Peoples Gas Company - Disputing 2(5)(v). Peoples sent 5 new exhibits            A. Folino Construction, Inc. - Disputing - 5(3), 5(5), and 5(7)            *****</p> <p>The incident occurred on 4/30/2025 at 2:15 PM, on Morrissey St, in Pittsburgh City, Allegheny County.</p> <p>A gas line owned by Peoples Gas Company was damaged. A. Felino did not notify a facility of the damaged line.</p> <p>Peoples Gas Company is the facility owner. Their Alleged Violation Report (AVR) states, “On 4/30, A Folino struck an unmarked PNG service line along Morrissey St (main to curb). A Folino put in numerous one calls without a complex meeting. PNG locator has been working with A Folino crews to ensure streets are marked prior to A Folino starting in a certain area. A Folino failed to notify PNG locator prior to starting work on Morrissey resulting in a damage with no marks”. PNG provided a list of Tickets called in by A Folino from 3/31/2025 to 4/9/2025. PNG stated, “The PNG locator was in contact with Folino and made sure that they had marks prior to moving to a new street. This contact was never made prior to working on Morrissey.”</p> <p>A Folino Construction is the excavator. Their AVR states, “A. Folino Construction was digging on Morrissey St for a water service line verification when we hit an unmarked gas service line for 283 Morrissey St. 911 was</p>	<p><b>Peoples Natural Gas: \$0.00</b></p> <p><b>A. Folino Construction, Inc.: \$1,000.00</b>            Section 5(3) 1st Offense \$500.00</p> <p>Section 5(5) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>called and a damage ticket was made through 811. Peoples Gas responded and claimed the line as theirs. Peoples Gas had a crew come out and made the repairs”. A. Felino indicates they contacted 911, and 811, and waited for a facility to respond to “claim the line as theirs.”</p> <p>Pittsburgh Water &amp; Sewer Authority is the project owner. Their AVR states, “A. Folino Construction was digging on Morrissey St for a water service line verification when we hit an unmarked gas service line for 283 Morrissey St. 911 was called and a damage ticket was made through 811. Peoples Gas responded and claimed the line as theirs. Peoples Gas had a crew come out and made the repairs”.</p> <p>Multiple photos of the site were submitted. There is a blue mark shown on the road heading towards the home at 283 Morrissey St, and a curb stop in the excavated pit and one directly outside of the pit. The excavated area is partially within the tolerance zone of the blue mark. There is a faded “PNG” mark shown next to the excavated area, which is also seen on Google Maps from 10/2024. Excavator teeth marks are seen in the sidewall of the dirt within the pit.</p> <p>Ticket # 20251124604 had a response due date of 4/27/2025. People’s Gas responded “CONFLICT. LINES NEARBY. DIRECT CONTACT TO FOLLOW BY FACILITY OWNER” on 4/25/25, and “FIELD MARKED” on 5/2/25. No renotify tickets were found for this location.</p> <p>Act 127 of 2024 Section 5(3)  In a complex project or if an excavator intends to perform work at multiple work sites or over a large area, to take reasonable steps to work with facility owners, including scheduling and conducting a preconstruction meeting, so that they may locate their facilities at a time reasonably in advance of the actual start of excavation or demolition work for each phase of the work.</p> <p>Violations:</p> <p>Facility - Peoples Gas Company:  Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time.  Recommendation: PUC Online Compliance Training was recently completed.</p> <p>Excavator – A. Folino:  Section 5(3) – Excavator failed to schedule work as agreed upon during a preconstruction meeting.  Recommendation: PUC Online Compliance Training was recently completed.  Section 5(5) – Excavator failed to exercise due care when facility owner is unable to mark within a mutually agreeable time frame.  Recommendation: PUC Online Compliance Training was recently completed.</p>	

<b>Case Number</b>	<b>Stakeholders</b>	<b>Summary</b>	<b>Violations &amp; Recommendation</b>
		Section 5(7) – Failed to immediately report to the facility owner any break or leak in its lines, or any dent, gouge, groove, or other damage to such lines or to their coating or cathodic protection. Recommendation: PUC Online Compliance Training was recently completed.	