



Pennsylvania Public Utility Commission

**Damage Prevention Committee Meeting Case List
January 13, 2026**

Omnibus Session

Case Number	Stakeholders	Summary	Violations & Recommendation
54836	<p>Facility Owner: Selinsgrove Borough Contractor/Excavator: J F Kiely Construction Project Owner: UGI Utilities, Inc Designer: HERBERT ROWLAND AND GRUBIC INC</p>	<p><u>On 5/7/2025 11:50:00 AM at HOWER ST, PENN TWP, SNYDER</u> The incident occurred on 5/7/2025 at 12:19 PM, on Hower St, in Penn Twp, Snyder County.</p> <p>A water line owned by Selinsgrove Borough was damaged.</p> <p>Selinsgrove Borough is the facility owner. Their Alleged Violation Report (AVR) states, “Contractor struck a water service line that was not marked. We assumed the service came off another street but it came out the back of the house and ran over 100 yards to tie into the water main on Hower Street.”</p> <p>Selinsgrove Borough did not provide any images of the incident with their AVR. A request was sent to them on 7-30-2025 for more information but no response was received as of 9-5-2025.</p> <p>J F Kiely Construction is the excavator. Their AVR states, “crew damaged an unmarked water service with an excavator”. Images provided show the site, marks, and damage. The damaged line is not within the tolerance zone of the blue marks, as shown using a measuring tape, and a hit kit.</p> <p>Ugi Utilities, Inc. is the project owner. Their AVR states, “Contractor stated: Crew damaged an unmarked water service with excavator.”</p> <p>Herbert Rowland And Grubic Inc is the designer. Their AVR states, “Contractor struck an unmarked water service line with excavator.”</p> <p>This case is related to case 054580 by Ticket 20251062641.</p> <p>Violations: Facility – Selinsgrove Borough Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Section 2(14) - Failed to comply with all requests for information by the commission relating to the commission’s enforcement authority under this act within thirty days of receipt of the request. Penalty reduced from \$500 to a warning of \$0. Recommendation: PUC Online Compliance Training is required.</p>	<p>Selinsgrove Borough: \$500.00 Section 2(5)(i) 1st Offense \$500.00</p> <p>Section 2(14) 1st Offense \$0.00</p>
56122	<p>Facility Owner: National Fuel Contractor/Excavator: Lovetts Mobile Home Park</p>	<p><u>On 5/29/2025 10:00:00 AM at LISA LN, WASHINGTON TWP, ERIE</u> The incident occurred on 5/29/2025 at 10:00 AM, on Lisa Ln, in Washington Twp, Erie County.</p>	<p>Lovetts Mobile Home Park: \$2,500.00 Section 5(4) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>Project Owner: Lovetts Mobile Home Park - placeholder</p> <p>Other: Verizon North</p>	<p>A gas line owned by National Fuel Gas was damaged.</p> <p>National Fuel Gas is the facility owner. Their Alleged Violation Report (AVR) states, “ Excavator struck properly marked natural gas distribution line. Please see attachments.”</p> <p>Images submitted show the site, excavation, and flags. The damage is shown and is within the tolerance zone of the yellow flags.</p> <p>Lovetts Mobile Home Park is the excavator and project owner. An AVR Request letter was mailed to Lovetts on 8/1/2025. An AVR has not been filed as of 9/5/2025</p> <p>Ticket #20251410594 had a response due date of 5/25/2025. Verizon North responded Clear on 5/29/2025.</p> <p>Violations: Excavator - Lovetts Mobile Home Park: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: PUC Online Compliance Training is required.</p>	<p>Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>Verizon North: \$500.00 Section 2(5)(v) 2nd offense \$500.00</p>
57949	<p>Facility Owner: Cooper Township Municipal Authority- Placeholder</p> <p>Contractor/Excavator: Cooper Township Municipal Authority</p> <p>Other: Homeowner</p>	<p><u>On 5/30/2025 12:00:00 PM at 38 OUR LANE, COOPER TWP, CLEARFIELD</u> Incident occurred on May 30th, 2025, at 12pm on 38 Our Lane, Cooper Township, Clearfield County.</p> <p>No PA1 call for dig.</p> <p>Homeowner states, "I am a homeowner at 38 our lane in winburne, pa. On May 27, 2025 I called cooper township municipal authority (CTMA) about a billing issue and to ask about a prior excavation they did on my property without notice or 1call ticket last February and did not fix my yard. I asked the secretary, Brenda, to have Rob Reem (water operator) to call me. On May 30, 2025 I received a voicemail at approximately 2:30 PM from Rob stating they found my “leak” and that they needed to shut my water off and that it was my side of the main so I was responsible to fix. I disagreed with that as there were no signs of a leak prior and I had no water to my house the days prior to this. I was also never notified that they were even going to be digging at my line. I documented the excavation when I got home on the same day by video. On June 2, 2025 I sent a text to message to Rob requesting the 1call serial numbers for the dig. I got no response so I called the office a day or</p>	<p>Cooper Township Municipal Authority: \$1,500.00 Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>so later and Brenda said she would get them from Rob. After another 5-10 days of no response I called again and was directed to call their solicitor (heather bozovich) as they were instructed to not talk to me or give information. I talked to attorney bozovich and requested the 1call information. After about a week of no response I called her office again. Approx 3-4 weeks later I received a letter in the mail that also contained 2 1 call tickets that I requested. Neither seemed valid but the one for this report was dated June 2,2025 with a dig time of 1930. The request to get them from CTMA was June 2nd at 4:15 pm and the actual excavation took place 4 days prior on May 30, 2025. The serial number provided within was what was on the ticket they pulled AFTER they dug and my line "leaked". I have also attached the voicemail from May 30, video/photos of May 30, the timestamped text requesting the 1call info.—(after trying to attach the pictures etc, I get error codes that say something went wrong during upload. If needed I can send these documents another way."</p> <p>Follow up email with the homeowner states that they dug in February of 2024 as well.</p> <p>Date stamped iPhone gallery pictures show's that excavation with a backhoe took place on May 30th, 2025. Cooper Township Municipal Authority placed an emergency ticket on June 2nd, 2025, to dig with a backhoe.</p> <p>Cooper Township Municipal Authority's AVR states, "A new meter heard a leak noise on the lateral, CTMA (Cooper Township Municipal Authority) dug our owned facility side to determine where the leak was occurring, after careful excavation it was found that the leak was on the customers side (38 Our Lane) of shut off which is galvanized that connected to our (CTMA) copper shut off valve. We then proceeded to shut off customers (38 Our Lane) and the leak stopped. As of 09/16/2025 the customer has yet to fix/ repair his water line as this customer has been very rude and blaming CTMA for breaking his line as not the case as the meter detected the leak noise before we even dug.</p> <p>The PA 1 call was placed after we dug due to excessive loss of water down Our Lane, CTMA (Cooper Township Municipal Authority) placed the PA1 call immediately after as this was an emergency and office manager was not available in the office.</p> <p>Was a PA 1 call placed for that dig? No. Did CTMA excavate with mechanized equipment on May 30th, 2025 at the above address? Yes. "</p> <p>CTMA attached a photo at the bottom of their pdf showing the water line. CTMA did not file an AVR within 30 days of violating Act 127 of 2024 but did file an AVR after being notified by the DPI.</p> <p>Violations:</p> <p>Cooper Township Municipal Authority</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. PUC compliance education is required.</p> <p>Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required. 50% reduction from \$1,000 to \$500 for filing within 24 hours of DPI request.</p>	
55601	<p>Facility Owner: Peoples Gas</p> <p>Contractor/Excavator: Allison Park Contractors</p> <p>Project Owner: PennDOT</p>	<p><u>On 6/9/2025 9:30:00 AM at WASHINGTON PIKE, COLLIER TWP, ALLEGHENY</u> PennDOT accepts. *****</p> <p>The incident occurred on June 9th, 2025, at 9:30 AM, on Washington Pike, in Collier Township, Allegheny County.</p> <p>A gas line owned by Peoples Gas was damaged.</p> <p>Peoples Gas, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “Allison Park Contracting (APC) struck and damaged a customer side gas service line. As shown in the pictures, Peoples Gas spoke with APC about the work on the most recent ticket for a project that has been going on for PennDOT for approximately a year. The stated work would be on the other side on Washington Pike from where the damage occurred. The address on the damage was also outside the drawn dig box provided by the contractor for this ticket.” Photos were submitted.</p> <p>Allison Park Contractors is the excavator. An AVR has not been filed as of 10/01/2025.</p> <p>PennDOT is the project owner. An AVR has not been filed as of 10/01/2025.</p> <p>Peoples Gas AVR indicated that 911 was not called.</p> <p>The location information listed on ticket 20251412611 – Work Site--[WASHINGTON PIKE] Nearest Intersection--[VANADIUM RD] Location Information--[AT THE COR OF VANADIUM RD. WITHIN 150FT OF VANADIUM RD GOING BOTH WAYS. BETWEEN STAFFORD AVE AND THE ON RAMP FOR I 79]</p> <p>The damage occurred outside of drawn dig box provided by the contractor for this ticket. Additionally, the approximant distance from the corner of Vanadium Rd to the damage location is 263 feet (well beyond the 150 feet listed on the ticket under location information.) The damaged occurred to a customer owned gas service line.</p> <p>Violations:</p> <p>Allison Park Contractors- - Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the</p>	<p>Allison Park Contractors: \$2,250.00 Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(19) 1st Offense \$250.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>PennDOT: \$1,500.00 Section 6.1(7) 2nd Offense \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property.</p> <p>- Section 5(19) – Excavator failed to provide accurate information to the One Call System.</p> <p>- Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.</p> <p>Recommendation: The penalty is applied. PUC compliance training education was recently completed. PennDOT-</p> <p>- Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Recommendation: The penalty is applied. PUC compliance training education was recently completed.</p>	
56265	<p>Facility Owner: Peoples Gas Company Contractor/Excavator: Independent Enterprises Inc Project Owner: Pittsburgh Water</p>	<p><u>On 6/23/2025 9:30:00 AM at BERTHA ST, PITTSBURGH CITY, ALLEGHENY</u> The incident occurred on 6/23/2025, at 9:30 AM, on Bertha St, in Pittsburgh City, Allegheny County.</p> <p>No damage occurred. AVRs submitted due to leaking gas line that was not damaged by an excavator using mechanized equipment.</p> <p>Peoples Gas is the facility owner, their AVR states, “Peoples Gas was sent a request to file an AVR for damaging its own facility on 6/23/2025 at Bertha St., Pittsburgh. The associated ticket with the letter was 20251741292. This damage notification ticket was called in by Independent Enterprises for an exposed leaking steel gas line during construction. PNG received a call from PGH Fire stating the line was hit by Independent Enterprises. Upon the arrival of PNG's first responder, he determined the line to be uncovered corrosion leaks, and not damaged. Called for an O&M crew to make the necessary repairs, and completed the orders. After speaking with both the O&M crew's and first responder's supervisors, who spoke with each, PNG has compiled no evidence from either of a damage from its own O&M crew on its own facility while onsite responding and repairing this exposed leaking facility. There are no damage photos. At this time, PNG could only input into the AVR what information we know and received from the crew and first responder onsite.”</p> <p>Independent Enterprises is the excavator. Their AVR states, “On 6/23/25, at approximately 9:25 AM, a replacement crew was engaged in a lead water service line replacement located at 206 Bertha St. During their work, the crew detected the smell of gas, indicating a potential gas leak. The foreman promptly initiated safety protocols to address the situation. No injuries occurred. 9:25 AM: The replacement crew, while performing the lead water service line replacement, noticed a strong odor of gas. The foreman attempted to locate the source of the leak but was unable to do so. It was observed that the gas line appeared to be mis-marked; the gas line was indicated in blue, while the water service line was marked in yellow, leading to confusion in identifying the</p>	<p>Peoples Gas Company: \$0.00 Section 2(5)(vii) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>correct line. 9:30 AM: The foreman immediately called 911 to report the gas leak and informed Peoples Gas of the situation, ensuring that emergency services were on their way to address the potential hazard. 9:30 AM: Peoples Gas responded promptly, arriving on-site with truck 216345. 9:40 AM: A second Peoples Gas truck, numbered 216477, arrived to assist with the situation. 9:50 AM: Peoples Gas truck 216345 departed the site after assessing the situation. 10:47 AM: Peoples Gas delivered an excavator to the site to facilitate further investigation and excavation of the area. 10:59 AM: The operator from Peoples Gas began excavation efforts in search of the gas mainline, aiming to locate the source of the leak. 11:29 AM: After thorough excavation, the Peoples Gas team successfully located the gas main. 12:16 PM: Upon inspection, it was determined that the leaking gas service line was an old gas service line. The leak was identified in the roadway. Peoples Gas took immediate action to terminate the service line and cap the gas main to prevent any further gas escape. 12:23 PM: Peoples Gas completed the backfilling of the excavation site. They placed cold patch material in the roadway to restore the surface and ensure safety for vehicular traffic. Following the completion of their work, the Peoples Gas team left the site. The incident was managed effectively with prompt reporting and response from both the replacement crew and Peoples Gas. The mismarking of the gas line contributed to initial confusion but was resolved through diligent investigation. The leak was successfully located and addressed, ensuring the safety of the area. All necessary measures were taken to mitigate the situation, and the site was restored to a safe condition.”</p> <p>Pittsburgh Water & Sewer Authority The is the project owner. Their AVR states, “9:25 AM: The replacement crew , while performing the lead water service line replacement, noticed a strong odor of gas. The foreman attempted to locate the source of the leak but was unable to do so. It was observed that the gas line appeared to be mis-marked; the gas line was indicated in blue, while the water service line was marked in yellow , leading to confusion in identifying the correct line. 9:30 AM: The foreman immediately called 91 1 to report the gas leak and informed Peoples Gas of the situation, ensuring that emergency services were on their way to address the potential hazard. 9:30 AM: Peoples Gas responded promptly , arriving on-site with truck 216345. 9:40 AM: A second Peoples Gas truck, numbered 216477, arrived to assist with the situation. 9:50 AM: Peoples Gas truck 216345 departed the site after assessing the situation. 10:47 AM: Peoples Gas delivered an excavator to the site to facilitate further investigation and excavation of the area. 10:59 AM: The operator from Peoples Gas began excavation ef forts in search of the gas mainline, aiming to locate the source of the leak.1 1:29 AM: After thorough excavation, the Peoples Gas team successfully located the gas main. 12:16 PM: Upon inspection, it was determined that the leaking gas service line was an old gas service line. The leak was identified in the roadway .</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Peoples Gas took immediate action to terminate the service line and cap the gas main to prevent any further gas escape. 12:23 PM: Peoples Gas completed the backfilling of the excavation site. They placed cold patch material in the roadway to restore the surface and ensure safety for vehicular traffic. Following the completion of their work, the Peoples Gas team left the site. The incident was managed effectively with prompt reporting and response from both the replacement crew and Peoples Gas. The mismarking of the gas line contributed to initial confusion but was resolved through diligent investigation. The leak was successfully located and addressed, ensuring the safety of the area. All necessary measures were taken to mitigate the situation, and the site was restored to a safe condition. If more space is needed, attach additional pages or documents. 06.23.25 Gas Leak Public Side at 206 Bertha St 3.jpeg”.</p> <p>Photos submitted show the site and excavation, but do not show proof that any lines were mismarked as referenced in certain AVRs.</p> <p>Ticket #20251741181 New – Excavation– Emergency was entered by Peoples Gas to repair the leaking line, but Peoples Gas did not respond to this ticket through PA One Call.</p> <p>Violations: Facility Owner – Peoples Gas: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket #20251741181 Recommendation: PUC Online Compliance Training was recently completed.</p>	
56625	<p>Facility Owner: PECO An Exelon Company Contractor/Excavator: RIDLEY TOWNSHIP Project Owner: Ridley TWP placeholder</p>	<p><u>On 6/24/2025 12:00:00 AM at 2ND AVE. & SUTTON AVE., RIDLEY TWP, DELAWARE</u> Incident occurred on June 24, 2025, at 12am at the intersection of 2nd and Sutton Avenue, Ridley Township, Delaware County.</p> <p>A gas line was damaged.</p> <p>PECO's Alleged Violation Report (AVR) states, "RIDLEY TWP. MUNICIPAL INSTALLING A STORM DRAIN DAMAGED THE 1" SERVICE WITH AN EXCAVATOR. DAMAGE OCCURRED BECAUSE CONTRACTOR FAILED TO MAKE A PA ONE CALL." AVR notes that 911 was notified.</p> <p>No AVR has been submitted by Ridley Township as of 9/19/25.</p> <p>Violations: Ridley Township Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. PUC compliance education is required. Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. PUC compliance education is required</p>	<p>RIDLEY TOWNSHIP: \$2,000.00 Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 6.1(7) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
57167	Facility Owner: PENN POWER / FIRSTENERGY Contractor/Excavator: James Johnson LLC Project Owner: Armstrong	<p><u>On 6/24/2025 11:58:00 AM at 119 HEATHERCROFT DR, CRANBERRY TWP, BUTLER</u> The incident occurred on Tuesday, June 24, 2025, at 119 Heathercroft Drive, in Cranberry Township, Butler County.</p> <p>An electric line was damaged.</p> <p>Penn Power/FirstEnergy, stated in their Alleged Violation Report (AVR), On June 16, 2025, James Johnson LLC, "Excavator" submitted POCS Routine Ticket 20251672340 to install fiber at 119 Heathercroft Drive. On June 24, 2025, Penn Power was notified of an outage. USIC, Penn Power's Contract Locator, investigated and determined that the Excavator damaged an electric line while installing a new fiber line using a directional drill. The root cause of the damage was that USIC did not mark the electric line correctly.</p> <p>James Johnson LLC placed a Damage Excavation ticket, 20251752302, work for Armstrong, remarks- damage to unmarked electric mainline. Penn Power on site. Facility Type: electric-Penn. Power Excavation Equipment: directional drilling.</p> <p>Violations:</p> <p>*Penn Power/FirstEnergy is in violation of section: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line Recommendation: Penalty Applied</p> <p>*James Johnson LLC is in violation of section: 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line Recommendation: PUC Compliance Education Required and Penalty Applied</p>	<p>PENN POWER / FIRSTENERGY: \$500.00 Section 2(5)(i) 1st Offense \$500.00</p> <p>James Johnson LLC: \$1,500.00 Section 5(16) 2nd Offense \$1,500.00</p>
56656	Facility Owner: Aqua PA Contractor/Excavator: CADDICK UTILITIES LLC Project Owner: Aqua Placeholder Designer: Total Engineering Other: Bristol Borough Other: Verizon	<p><u>On 6/25/2025 8:00:00 AM at DORRANCE ST, BRISTOL BORO, BUCKS</u> Aqua is accepting.</p> <p>****</p> <p>Incident occurred on June 25th, 2025, 8am along Dorrance Street, Bristol Boro, Bucks County.</p> <p>A water line was damaged.</p> <p>Aqua's Alleged Violation Report (AVR) states, "Aqua Contractor Caddick Utilities, damaged incorrectly marked water service. Repaired by crew right away."</p> <p>Caddick Utilities AVR states, "Damaged incorrectly marked water service. Repaired by crew right away."</p> <p>Images show that the damaged line was mismarked. Complex Sign-in Sheet shows that Bristol Boro participated in the meeting.</p> <p>Violations:</p> <p>Aqua</p>	<p>Aqua PA: \$1,000.00 Section 2(5)(i) 2nd Offense \$1,000.00</p> <p>Verizon: \$4,000.00 Section 2(5)(v) Subsequent \$2,000.00</p> <p>Section 2(5)(v) Subsequent \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.</p> <p>Verizon</p> <p>Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20251691249</p> <p>Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20251573326</p>	
56792	<p>Facility Owner: UGI Utilities</p> <p>Contractor/Excavator: Scranton Roofing</p> <p>Project Owner: Homeowner</p>	<p><u>On 6/25/2025 4:30:00 PM at 2334 Prospect Ave., SCRANTON CITY, LACKAWANNA</u> Incident occurred on June 25, 2025, at 4:30pm on 2334 Prospect Avenue, Scranton City, Lackawanna County.</p> <p>A gas line was damaged.</p> <p>UGI's Alleged Violation Report (AVR) states, "Excavator struck and damaged a gas facility while digging without a one call." AVR notes that 911 was not notified.</p> <p>POCS commented, "I did not find a record of Scranton Roofing having placed one call notifications in the past."</p> <p>No AVR has been submitted by Scranton Roofing as of 9/26/25.</p> <p>Violations:</p> <p>Scranton Roofing</p> <p>Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. PUC compliance education is required.</p> <p>Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid. PUC compliance education is required.</p> <p>Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required.</p>	<p>Scranton Roofing: \$2,500.00</p> <p>Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(4) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>
56315	<p>Facility Owner: PEOPLES GAS COMPANY LLC</p> <p>Contractor/Excavator: FRANK J. ZOTTOLA CONSTRUCTION</p> <p>Project Owner: Wilkesburg-Penn Joint Water Authority</p> <p>Other: Swissvale Borough</p>	<p><u>On 7/2/2025 10:30:00 AM at 2402 S. BRADDOCK AVE, SWISSVALE BORO, ALLEGHENY</u> The incident occurred on Wednesday, July 2, 2025, at 2402 S. Braddock Avenue, in Swissvale Borough, Allegheny County.</p> <p>Peoples Gas Company's line was damaged.</p> <p>Peoples Gas stated in their Alleged Violation Report (AVR), Frank J. Zottola Construction was working for Wilkesburg Penn Joint Water Authority when they struck and damaged a properly marked Peoples Gas service line while using mechanized equipment in the tolerance zone.</p> <p>Frank J. Zottola Construction placed an Emergency Damage ticket, 2025183190, and it indicated that they called 911.</p> <p>Peoples Gas provided photos showing the damage within the tolerance zone.</p> <p>Frank J. Zottola Construction did not submit an AVR.</p>	<p>FRANK J. ZOTTOLA CONSTRUCTION: \$2,000.00</p> <p>Section 5(4) 2nd Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>Wilkesburg-Penn Joint Water Authority: \$1,000.00</p> <p>Section 6.1(7) 1st Offense \$1,000.00</p> <p>Swissvale Borough: \$1,500.00</p> <p>Section 2(5)(vii) 2nd Offense \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Wilkinsburg Penn Joint Water Authority, the project owner, did not submit an AVR.</p> <p>20251831901- Damage Emergency ticket placed on 7/2/2025, at 11:25am, there was No Response from Swissvale Borough.</p> <p>Violations:</p> <p>*Frank J. Zottola Construction is in violation of sections: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: PUC Compliance Education Required and Penalties Applied</p> <p>*Wilkinsburg Penn Joint Water Authority is in violation of section: 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Recommendation: PUC Compliance Education Required and Penalty Applied</p> <p>*Swissvale Borough is in violation of section: 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Recommendation: PUC Compliance Education Required and Penalty Applied</p>	
57136	<p>Facility Owner: UGI Utilities Inc Contractor/Excavator: Kinsley Construction Project Owner: UGI Utilities Inc. (placeholder)</p>	<p><u>On 7/3/2025 9:32:00 AM at N BROAD ST, MANHEIM TWP, LANCASTER</u> UGI accepts.</p> <p>*****</p> <p>The incident occurred on July 3rd, 2025, at 9:32 AM, on North Broad Street, in Manheim Township, Lancaster County.</p> <p>A gas line owned by UGI Utilities was damaged. 911 was called.</p> <p>UGI Utilities Inc, the facility owner and project owner, submitted an Alleged Violation Report (AVR). Their AVR states, “Excavator utilizing mechanized equipment, struck an unmarked service.” Photos were submitted.</p> <p>Kinsley Construction is the excavator. An AVR has not been filed as of 09/30/2025.</p> <p>The submitted photos show the damaged line. No mark outs for this line can be seen in the submitted photos.</p> <p>Violations:</p> <p>UGI Utilities Inc.- - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: The penalty is applied. PUC compliance training education was recently completed.</p> <p>Kinsley Construction-</p>	<p>UGI Utilities Inc: \$2,000.00 Section 2(5)(i) Subsequent \$2,000.00</p> <p>Kinsley Construction: \$1,000.00 Section 5(16) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>- Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.</p> <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
56475	<p>Facility Owner: First Energy - Met-Ed, Contractor/Excavator: DRILLMASTERS LLC Project Owner: First Energy - Placeholder</p>	<p><u>On 7/3/2025 2:30:00 PM at E 8TH ST, BIRDSBORO BORO, BERKS MET ED WITHDREW THEIR DISPUTE BARELY 24 HOURS BEFORE THE JANUARY DPC MEETING***Met-Ed is disputing with they do not allow their locators to mark hard surfaces of private property. DPI asked why offset marks were not used going vertically up the driveway and why a dot was painted on the driveway after the damage.</u></p> <p>***</p> <p>Incident occurred on July 3rd, 2025, at 2:30pm on East 8th Street, Birdsboro Boro, Berks County.</p> <p>An electric line was damaged.</p> <p>Met-Ed's Alleged Violation Report (AVR) states, "On June 13, 2025, Drillmasters LLC, Excavator, submitted a PA One Call ticket 20251641432 to install new electric services for Met-Ed on E 8th Street, Birdsboro, Berks County, PA. On 07/03/2025 customers on E 8th Street reported no power. Met-Ed crew investigated and located a damaged secondary under the driveway at 520 E 8th Street. Met-Ed's contract locator, USIC, investigated and determined that the Excavator damaged Met-Ed's accurately marked underground secondary and failed to expose marked facilities."</p> <p>Drillmasters, LLC's AVR states, "We were installing a new electric service located 524 E. 8th Street in Birdsboro. We hit an UNMARKED electric service going to 520 E. 8th Street. We immediately contacted MetEd and PA One Call. USIC sent out George, their locator who marked out the location prior to excavation. George indicated that he knew where the unmarked electric service was located underground because he traced it out across the driveway. When my foreman asked why he did not put any paint marks down, George told him that the company does not allow us to paint driveways. George acknowledged that he should've put some marks down to indicate the underground electric line."</p> <p>Drillmasters' pre-excavation photos show that the lateral was not marked. Met-ed's post damage photos have a single red dot marked. The single red dot mark is consistent with the facility owner's usage of post damage marks to show where the damage occurred. Dot marks outs do not meet CGA best practices therefore the facility owner uses them for post damage mark locations.</p> <p>Violations:</p> <p>Met-Ed</p>	<p>First Energy - Met-Ed,: \$1,000.00 Section 2(5)(i) 2nd Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
57154	Facility Owner: UGI UTILITIES INC Contractor/Excavator: Kiser Excavating Project Owner: Homeowner	<p>Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. 20251814649. PUC compliance education is required.</p> <p><u>On 7/4/2025 8:00:00 AM at 545 E HIGH STREET, ELIZABETHTOWN BORO, LANCASTER</u> The incident occurred on Friday, July 4, 2025, at 545 E. High Street, in Elizabethtown Borough, Lancaster County.</p> <p>UGI Utilities gas line was damaged.</p> <p>UGI stated in their Alleged Violation Report (AVR) that the excavator, Kiser Excavating, utilizing mechanized equipment, struck a correctly marked gas service line while digging. UGI provided photos of the excavation.</p> <p>Kiser Excavating did not submit an AVR.</p> <p>Violations: *Kiser Excavating is in violation of sections: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: PUC Compliance Education Required and Penalties Applied</p>	<p>Kiser Excavating: \$1,500.00 Section 5(4) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>
57008	Facility Owner: Columbia Gas Contractor/Excavator: Horst and Son	<p><u>On 7/7/2025 7:35:00 AM at Buckingham Blvd, LOWER WINDSOR TWP, YORK</u> The incident occurred on 7/7/2025, at 7:35 AM, on Buckingham Blvd, in Lower Windsor Twp, York County.</p> <p>A gas line owned by Columbia Gas was damaged. 911 was contacted and the facility owner was notified of the damage. Customers Affected - 1 Duration of Service Interruption 1 - < 6 hrs</p> <p>Columbia Gas is the facility owner. Their Alleged Violation Report (AVR) states, “The excavator was digging to install a stop sign when they struck a 4" plastic gas main using a backhoe. Upon impact, they immediately contacted Columbia Gas and notified 911. Both the local fire department and Columbia Gas responded to the scene, secured the area, and completed the necessary repairs. Damage Prevention conducted an on-site investigation, which determined that no one call had been placed prior to excavation. As part of the response, education was provided on the importance of calling 811 before digging, along with guidance on the AVR (Apparent Violation Report) process.” Images submitted show the site, damage, and excavation equipment. Mechanized equipment is showing actively excavating at the damage location. No PA One Call ticket was located.</p> <p>Horst And Son is the excavator. An AVR has not been filed as of 09/08/2025. PA One Call indicates they have placed one calls in the past</p> <p>Violations:</p>	<p>Horst and Son: \$2,250.00 Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Horst and Son: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: PUC Online Compliance Training is required.</p>	
56432	<p>Facility Owner: Verizon Contractor/Excavator: Duda Cable Construction Project Owner: Comcast</p>	<p><u>On 7/8/2025 12:00:00 PM at 2687 MARSHFIELD DR, UPPER ST CLAIR TWP, ALLEGHENY</u> The incident occurred on 7/08/2025 at 2687 MARSHFIELD DR. in UPPER ST CLAIR TWP in Allegheny County.</p> <p>2 Communication cables were damaged.</p> <p>DUDA CABLE CONSTRUCTION submitted an Alleged Violation Report and stated that they are also representing Comcast. In the AVR they stated that “Duda Cable struck 2 unmarked fiber drops. We have struggled with getting Verizon to respond to mark their lines on this ticket and the one prior (expired) and we have done several renotifies to them at this location over the last few weeks. They did respond to mark their main line and 2 of the apparent 4 drops The foreman said there appears to be 2 lines running parallel to each other and going to the same house so it could be possible that one is dead There are no visible communication (orange) makings in the area. The nearest mark to the fiber drop was power, which was 3+ feet away. See attached pictures”.</p> <p>Comcast submitted an AVR that stated that “Duda Cable struck 2 unmarked fiber drops. We have struggled with getting Verizon to respond to mark their lines on this ticket and the one prior (expired) and we have done several renotifies to them at this location over the last few weeks. They did respond to mark their main line and 2 of the apparent 4 drops The foreman said there appears to be 2 lines running parallel to each other and going to the same house so it could be possible that one is dead There are no visible communication (orange) makings in the area. The nearest mark to the fiber drop was power, which was 3+ feet away. See attached pictures”.</p> <p>Verizon did not submit an AVR. Their line was damaged.</p> <p>Ticket 20251700368 was submitted by Duda Cable Construction on 6/19/2025 with a response due by 6/24/2025 to repair a CATV main for work that had not yet started.</p> <p>Renotify Ticket 20251700368 was submitted by Duda Cable Construction on 7/07/2025 with a response due by 7/07/2025 “RNO Remarks-- [ATTN VERIZON</p>	<p>Verizon: \$8,000.00 Section 2(5)(i) Subsequent \$2,000.00</p> <p>Section 2(10) Subsequent \$2,500.00</p> <p>Section 2(5)(v) Subsequent \$1,000.00</p> <p>Section 2(5)(i) Subsequent \$2,000.00</p> <p>Section 2(5)(iii.1) 2nd Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>PENNSYLVANIA YOU RESPONDED AS FIELD MARKED BUT CALLER STATES THERE ARE FIOS LINES THAT ARE NOT MARKED ON SITE. PLEASE REPORT TO THE SITE ASAP AND MARK OUT YOUR FIOS LINES AS YOU ARE INVOLVED AND MARKINGS ARE NEEDED FOR THE WORK TO BEGIN SAFELY". Direct contact with excavator within 2 hours is checked as "No". Verizon did not respond until on 7/8/2025 they responded field marked.</p> <p>VIOLATIONS Verizon is in violation of: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. This is for 1 of 2 lines that were located and not marked. This is a subsequent offense. Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. This is cited for the second of 2 lines that were not marked. This is a subsequent offense. Section 2(5)(iii.1) – Facility owner failed to propose a mutually agreeable scheduling by which the excavator, facility owner or designer may locate the facilities. Emergency ticket 20251892239 was responded to as "CONFLICT" no other information was noted. This is a second offense. Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. This is a subsequent offense. Section 2(5)(v) – Failed to respond to routine OneCall ticket 20251700368 within the required amount of time. Ticket response was due by 7/07/2025. Verizon did not respond until 7/08/2025. This is a subsequent offense. Recommendation: The penalties are applied. The required education was recently completed.</p>	
56455	<p>Facility Owner: UGI UTILITIES INC Contractor/Excavator: H.L. Bowman, Inc.</p>	<p><u>On 7/9/2025 10:50:00 AM at 397 Pitt Street, EAST PENNSBORO TWP, CUMBERLAND</u> The incident occurred on Wednesday, July 9, 2025, at 397 Pitt Street, in East Pennsboro Township, Cumberland County.</p> <p>UGI Utilities gas line was damaged. No tickets associated with is case</p> <p>UGI stated in their alleged violation report (AVR), H.L. Bowman Inc. was using a ditch witch to trench without notifying PA One Call. As a result, they struck and damaged an unmarked gas service causing a release of gas. The Excavator failed to call 911. The homeowner of the property called 911. PA One Call Compliance commented, H. L. Bowman has placed PA One Call notifications in the past. There are no tickets associated with is case.</p>	<p>H.L. Bowman, Inc.: \$3,500.00 Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>Section 5(17) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>On Thursday, July 31, 2025, a letter was mailed to H.L. Bowman requesting an AVR. They did not submit their AVR.</p> <p>Violations:</p> <p>*H.L. Bowman Inc. is in violation of sections: 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid. 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: PUC Compliance Education Required and Penalties Applied</p>	
57038	<p>Facility Owner: Columbia Gas</p> <p>Contractor/Excavator: First Call Remodeling & Roofing LLC</p> <p>Project Owner: Homeowner</p>	<p><u>On 7/9/2025 10:50:00 AM at 3624 Armory Lane, NORTH CODORUS TWP, YORK</u> Incident occurred on July 9th, 2025, at 10:50am on 3624 Armory Lane, North Cordorus Township, York County.</p> <p>A gas line was damaged.</p> <p>Columbia Gas Company's Alleged Violation Report (AVR) states, "During the installation of a deck, a contractor using a powered auger struck a 1-inch plastic gas service line. The gas facility was not marked because the excavator failed to place a PA One Call ticket prior to beginning work. Upon striking the line, the contractor immediately contacted Columbia Gas using the phone number displayed on a visible marker post located in the backyard. Columbia Gas responded promptly, secured the area, and completed the necessary repairs. Damage Prevention personnel conducted an on-site investigation and provided education to the contractor regarding the PA One Call law, the requirement to call 911 when a gas line is struck, and the Alleged Violation Report (AVR) process. The team also emphasized the importance of recognizing visible indicators such as gas meters and marker posts, and reinforced the legal obligation to have a PA One Call ticket before operating any powered equipment." AVR notes that 911 was not notified.</p> <p>PA1call commented that, "FIRST CALL REMODELING AND ROOFING LLC has placed one call notifications with PA One Call in the past."</p> <p>No AVR has been submitted by First Call Remodeling & Roofing. Images show the damaged line along with a permanent Columbia Gas marker in the yard.</p> <p>Violations:</p> <p>First Call Remodeling & Roofing Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. PUC compliance education is required.</p>	<p>First Call Remodeling & Roofing LLC: \$3,000.00</p> <p>Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid. PUC compliance education is required.</p> <p>Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required.</p>	
56702	<p>Facility Owner: Peoples Gas Contractor/Excavator: Curry and Kepple Project Owner: New Kensington Water Authority Designer: GIBSON THOMAS ENGINEERING CO INC</p>	<p><u>On 7/9/2025 1:30:00 PM at 262 7th Street Extension, NEW KENSINGTON CITY, WESTMORELAND</u> Peoples Gas disputed and provided additional information. Violation was withdrawn. ***** The incident occurred on July 9th, 2025, at 262 7th Street Extension, in New Kensington City, Westmoreland County.</p> <p>A gas line was damaged. 911 was called.</p> <p>Peoples Gas, the facility owner, submitted two Alleged Violation Reports (AVR). Photos were submitted. - AVR2025JUL170042 states, “MARKS WERE OFF BY 18 INCH SO STILL IN THE TOLERANCE ZONE OF THE 4 INCH PIPE BUT THEY EXPOSED THE MAIN AND DRILLED A HOLE IN IT TO SEE IF IT WAS LIVE”. - AVR2025JUL170047 states, “OUR LOCATOR MISSED A SERVICE LINE FOR THIS HOUSE”.</p> <p>Curry and Kepple, the excavator, submitted an AVR. Their AVR states, “digging for waterline and the gas line was mis marked by 14 feet this is house number 262 7th st ext”. Photos were submitted.</p> <p>New Kensington Water Authority, the project owner, submitted an AVR. Their AVR did not include a summary. Photos were submitted.</p> <p>Gibson Thomas Engineering Co. Inc., the designer, submitted an AVR. Their AVR states, " Mis-Marked 1-1/4" gas service line for House 262 7th Street was struck by Contractor”. Photos were submitted. They noted on their AVR that they are representing New Kensington Water Authority.</p> <p>The submitted photos show multiple yellow flags. The damage to the service line was not within the tolerance zone. The gas service line was not properly marked.</p> <p>This case is related to cases 054914 and 055313.</p> <p>Violations:</p> <p>Peoples Gas- - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line-withdrawn.</p>	<p>Peoples Gas: \$0.00</p>
56939	<p>Facility Owner: COLUMBIA GAS OF PA INC Central</p>	<p><u>On 7/10/2025 9:30:00 AM at CLAUSE AVE, PITTSBURGH CITY, ALLEGHENY</u> Incident occurred</p>	<p>CASPER COLOSIMO AND SON INC: \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>Contractor/Excavator: CASPER COLOSIMO AND SON INC</p> <p>Project Owner: Pennsylvania American Water Company (PAWC)</p> <p>Other: Verizon</p>	<p>on July 10th, 2025, at 9:30am on Clause Avenue, Pittsburgh City, Allegheny County.</p> <p>A gas line was damaged.</p> <p>Columbia Gas' Alleged Violation Report (AVR) stated, "Casper Colosimo, working on behalf of PA American Water, damaged a 3-inch steel main line while using a hoe ram to break up the hard surface and sidewalk. The main line was accurately marked, and the damage occurred within the designated tolerance zone. Emergency services, including 911 and Columbia Gas, were notified and responded to the scene. All required safety checks were completed, and the necessary repairs were made."</p> <p>Casper Colosimo's AVR states, "Casper Colosimo crew was working at house number 35 Claus Ave in the city of Pittsburgh installing a new water service from the main to the curb box in the sidewalk. While removing the sidewalk with a small hammer so our vac truck could expose the lines that were marked, we damaged a Columbia Gas main. The main was directly under the sidewalk 5 inches deep. PA Best Practices allow the use of mechanical methods to remove the hard surface pavement. There was no indication that this line was not buried to proper depth."</p> <p>PAWC's AVR states, "Casper Colosimo crew was working at house number 35 Claus Ave in the city of Pittsburgh installing a new water service from the main to the curb box in the sidewalk. While removing the sidewalk with a small hammer so our vac truck could expose the lines that were marked, we damaged a Columbia Gas main. The main was directly under the sidewalk 5 inches deep. PA Best Practices allow the use of mechanical methods to remove the hard surface pavement. There was no indication that this line was not buried to proper depth."</p> <p>Images show that the line was accurately marked out along with the excavator in the background that was used according to Casper Colosimo. AVRs note that 911 was notified.</p> <p>Violations:</p> <p>Casper Colosimo Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. PUC compliance education is required.</p> <p>Verizon Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20250994280. PUC compliance education is required.</p>	<p>Section 5(4) 3rd Offense \$1,500.00</p> <p>Verizon: \$2,000.00 Section 2(5)(viii) Subsequent \$2,000.00</p>
56463	<p>Facility Owner: PEOPLES GAS COMPANY LLC</p>	<p><u>On 7/10/2025 10:21:00 AM at 1617 DUCHESS LN, SOUTH PARK TWP, ALLEGHENY</u> The incident</p>	<p>FRANKS LANDSCAPING, LLC: \$2,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>Contractor/Excavator: FRANKS LANDSCAPING, LLC</p> <p>Project Owner: HOMEOWNER</p>	<p>occurred on Thursday, July 10, 2025, at 1617 Duchess Lane, in South Park Township, Allegheny County.</p> <p>Peoples Gas Company’s line was damaged. There are no tickets associated with this incident.</p> <p>People Gas stated in their Alleged Violation Report (AVR) that Franks Landscaping, LLC was working for the Homeowner, at 1617 Duchess Lane, when they hit the customers side gas service line. Franks Landscaping notified 911, and the PNG crew arrived onsite and they shut the gas off. Franks Landscaping provided a one call ticket, 20250870681, to PNG as their active ticket for the project.</p> <p>PNG never received this ticket, which was for 600 Trotwood Circle, out of PNG’s operating area. Franks Landscaping failed to place a one call for the affected customers address. Franks Landscaping is responsible for replacing customers’ side service line.</p> <p>There are no tickets associated with this incident. The routine ticket that Franks Landscaping provided to Peoples Gas, 20250870681, was placed on 3/28/2025, for worksite 600 Trotwood Circle, in Upper St Clair Township. The Damage occurred about 6-7 miles away, at 1617 Duchess Lane, in South Park Township, Allegheny County; an excavation ticket was not placed for this worksite.</p> <p>On Thursday, July 31, 2025, a letter was mailed to Franks Landscaping requesting an AVR. They did not submit their AVR.</p> <p>Violations:</p> <p>*Franks Landscaping, LLC is in violation of sections: 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: PUC Compliance Education Required and Penalties Applied</p>	<p>Section 5(17) 1st Offense \$500.00</p> <p>Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>
58314	<p>Facility Owner: Windstream</p> <p>Other: CLAY TOWNSHIP LANCASTER COUNTY</p>	<p><u>On 7/10/2025 3:00:00 PM at 1495 Laurel Drive, Clay Township, Lancaster</u> The incident occurred on 7/10/2025, at 3:00 PM, on 1495 Laurel Drive, in Clay Twp, Lancaster County.</p> <p>A communications line owned by Windstream was damaged.</p> <p>Windstream is the facility owner. Their Alleged Violation Report (AVR) states, “Per Locate Company: On 07/10/2025 at 1545, were notified by our customer, Windstream / CMR, about a damaged telephone line. Clay Township was doing drainage work on Laurel Drive. While excavating, they severed a 50pr phone line near 1495 Laurel Drive.”</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Images were provided but are of poor quality and do not add to the investigation.</p> <p>Windstream was contacted for further information on how they determined that Clay Township was the excavator who damaged their line. Their statement was, “We have reviewed this incident further. While there is currently a damage claim open and under investigation with our claims manager, we have no additional details to provide at this time other than what was already provided in the AVR.”</p> <p>Clay Township is listed as the excavator in Windstream's AVR. An AVR was not filed by Clay Township as of 10/01/2025. An AVR request letter was sent on 10/1/2025. Bruce from Clay Township contacted the PUC on 10/3/2025 stating they do not have any records of the damage and will be investigating it internally and submitting a report by 10/10/2025. Their AVR was submitted on 10/10/2025 and states, “After reasonable investigation Clay Township determined there was no Township activity at 1495 Laurel Drive, Clay Township on 7/10/2025. Information in this report is completed to the extent possible given there was no project or excavation known to Clay Township.”</p> <p>No tickets were found by PA One Call for the site.</p> <p>*While damage occurred, there is no evidence to determine who caused the damage.*</p>	
56754	<p>Facility Owner: PA American Water Contractor/Excavator: NORTHEAST SITE CONTRACTORS Project Owner: PA American Water (Placeholder) Other: Verizon</p>	<p><u>On 7/11/2025 7:00:00 AM at 458 COUNTRY PLACE DR, COOLBAUGH TWP, MONROE</u> The non-damage incident occurred on July 11th, 2025, at 458 Country Place Drive, in Coolbaugh Township, Monroe County.</p> <p>Non-damage. Non-response to tickets.</p> <p>PA American Water is the facility owner and project owner. An Alleged Violation Report (AVR) has not been filed as of 09/18/2025.</p> <p>Northeast Site Contractors, the excavator, submitted an AVR. Their AVR states, “We put in a request on 7/8 to have utilities marked out before excavation. The scheduled start date was 7/11. Verizon did not contact us or make any markings for their utility in the required time frame and we are still waiting for a response from Verizon. We contacted PA1call for follow-up and they updated ticket. I contacted our PA1call local rep. who also reached out to Verizon and called their trouble locate number and reported the ticket. The representative said she pushed it back into the field. Waiting for Verizon so project can move forward.”</p> <p>Routine ticket 20251894614-000 had a response due date of 07/10/2025. - Verizon did not respond to this ticket until 07/22/2025.</p>	<p>Verizon: \$3,000.00 Section 2(5)(v) Subsequent \$2,000.00</p> <p>Section 2(5)(v.1) 2nd Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Insufficient renotify ticket 20251894614-001 had a response due date of 07/15/2025. - Verizon did not respond to this ticket until 07/22/2025.</p> <p>The renotify insufficient ticket 20251894614-001 states, “ATTN VERIZON, YOU HAVE NOT RESPONDED. PLEASE REPORT TO THE SITE TO MARKYOUR LINE ASAP.”</p> <p>Violations:</p> <p>Verizon-</p> <ul style="list-style-type: none"> - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Routine ticket 20251894614-000. - Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. <p>Recommendation: The penalty is applied. PUC compliance training education was recently completed.</p>	
56942	<p>Facility Owner: Columbia Gas</p> <p>Contractor/Excavator: Hufnagel Excavating</p> <p>Project Owner: PA American Water</p> <p>Other: MCMILLEN ENGINEERING</p>	<p>On 7/11/2025 8:30:00 AM at 311 S PITTSBURGH ST, <u>CONNELLSVILLE CITY, FAYETTE</u> The incident occurred on 07/11/2025 at 8:30 AM, at 311 South Pittsburgh Street, in Connellsville City, Fayette County.</p> <p>A gas line owned by Columbia Gas was damaged. 911 was called.</p> <p>Columbia Gas, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “Hufnagel Excavating used mechanized equipment within the tolerance zone of an accurately marked gas service line, resulting in damage to the line. Columbia Gas responded promptly to secure the area and complete the necessary repairs. Photos were submitted.</p> <p>Hufnagel Excavating, the excavator, submitted an AVR. Their AVR states, “Excavator came in contact with and damaged gas service line Excavator stated that gas service was located within the road base no indication of depth. While working to remove the road base to utilize more prudent techniques to locate the gas service excavator damaged the gas service. Given the thickness of road base and depth of gas service the line was damaged.” Photo submitted.</p> <p>PA American Water is the project owner. An AVR has not been filed as of 09/17/2025.</p> <p>The submitted photos show the gas line marked with yellow paint. The gas line was damaged within the tolerance zone.</p> <p>This case is related to case 044582.</p> <p>Violations:</p> <p>Hufnagel Excavating-</p> <ul style="list-style-type: none"> - Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. 	<p>Hufnagel Excavating: \$500.00 Section 5(4) 1st Offense \$500.00</p> <p>PA American Water: \$1,500.00 Section 6.1(7) 2nd Offense \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>PA American Water- - Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike.</p> <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
57407	<p>Facility Owner: First Energy - West Penn Power Contractor/Excavator: Homeowner Other: Comcast</p>	<p><u>On 7/12/2025 4:48:00 PM at 206 KING RICHARD DR, PETERS TWP, WASHINGTON</u> Incident occurred on July 12th, 2025 at 4:48pm on 206 King Richard Drive, Peters Township, Washington County.</p> <p>An unmarked electrical line was damaged.</p> <p>First Energy - West Penn Power's Alleged Violation Report (AVR) states, "On June 23, 2025, Robert Stevens, Homeowner, submitted PA One Call Routine ticket 20251744031 for 206 King Richard Dr, McMurray, Washington County, PA. On July 12, 2025, the Homeowner notified West Penn Power ("WPP") of no power at the location. The WPP crew investigated and located a damaged underground electric secondary cable. WPP's Contract Locator, USIC, investigated determined that the Excavator did not submit a renotify ticket as there was clear evidence of underground facilities near the dig site."</p> <p>First Energy responses to routine ticket 20251744031: 0 KN WEST PENN POWER KN-CLEAR. NO FACILITIES OR FACIL NOT INVOLVED 7/12/25, 7:35 AM MBR-WEBSVC N/A 0 KN WEST PENN POWER KN-SCHEDULED MARK 6/30/25, 6:35 PM MBR-WEBSVC N/A</p> <p>Timeline Ticket called in by Homeowner 6/23/25 5:31pm First Energy - WPP responds Scheduled Mark 7 days later on 6/30/2025 6:34pm. First Energy -WPP responds Clear No Facilities at 7:35am on 7/12/25. Images show that a First Energy - WPP line was unmarked and damaged. Line should have been field marked and responded to with a final response of field marked.</p> <p>Comcast also responded Scheduled Mark on 6/30 and clear on 7/12 despite having underground lines.</p> <p>Violations:</p> <p>First Energy - West Penn Power Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. 20251744031. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. 20251744031. PUC compliance education is required for</p>	<p>First Energy - West Penn Power: \$1,250.00 Section 2(5)(i) 2nd Offense \$1,000.00</p> <p>Section 2(5)(v.2) 1st Offense \$250.00</p> <p>Comcast: \$500.00 Section 2(5)(v.2) 2nd Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p> <p>Comcast Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. 20251744031. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p>	
56684	<p>Facility Owner: Verizon Contractor/Excavator: DOLI CONSTRUCTION Contractor/Excavator: REAMSTOWN EXCAVATING Project Owner: LOWER PAXTON TOWNSHIP AUTHORITY Other: HRG INC</p>	<p><u>On 7/14/2025 8:00:00 AM at 5591 BANBRIDGE DR, LOWER PAXTON TWP, DAUPHIN</u> Incident occurred on July 14th, 2025, at 8am on 5591 Banbridge Drive, Lower Paxton Township, Dauphin County.</p> <p>A telecom line was damaged.</p> <p>Reamstown Excavating's Alleged Violation Report (AVR) states, "Hit a verizon line that was not marked correctly and was 2" underground in front of 5591 Banbridge dr. When the repair man showed up he agreed that it was not correctly marked and our operator helped him expose and get line deeper."</p> <p>AVR request letters were mailed to Lower Paxton Township Authority and Verizon on 9/26/25.</p> <p>Lower Paxton Township Authority submitted an AVR on 9/29/25 stating, "Reamstown Excavating hit a Verizon line that was not marked correctly and was 2" underground in front of Banbridge Dr. The Verizon repair man showed up and agreed that it was not marked correctly so the Reamstown Excavating operator helped him expose and get the service deeper."</p> <p>HRG's AVR states, "From excavator: "Hit a verizon line that was not marked correctly and was 2" underground in front of 5591 Banbridge dr. When the repair man showed up he agreed that it was not correctly marked and our operator helped him expose and get line deeper."</p> <p>Verizon responded had a no response to the complex meeting ticket 20242762847 then followed up with clear no facilities. Verizon also responded clear to complex meeting ticket 20243450596.</p> <p>Case is related to 52101,52187, 52200, 52431, 54080, and 56426.</p> <p>Verizon submitted an AVR on October 16th stating, "I requested information from the Verizon local manager, Bruce Jenkins, regarding this damage claim. According to Bruce Jenkins, there was no damage to any existing Verizon lines and no repair was needed for this incident. The damage line in question is most likely an old line that is no longer in use. No customers were out of service for this incident."</p> <p>Damage image shows a flag with Verizon on it.</p> <p>Violations:</p>	<p>Verizon: \$4,500.00 Section 2(5)(i) Subsequent \$2,000.00</p> <p>Section 2(10) Subsequent \$2,500.00</p> <p>LOWER PAXTON TOWNSHIP AUTHORITY: \$0.00 Section 6.1(7) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Verizon Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work.</p> <p>Lower Paxton Township Authority Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Filed AVR promptly after receiving notice. Reduced to \$0 warning. LPTA has also filed multiple AVRs during this project. PUC compliance education is required.</p>	
56599	<p>Contractor/Excavator: GERHARTS LANDSCAPING SERVICES L L C Project Owner: WYNDHAM WOODS Homeowners Association Other: NONE</p>	<p>On 7/14/2025 10:00:00 AM at 177 Wyndham Woods Way, HATFIELD TWP, MONTGOMERY DPI Michael contacted North Penn Real Estate who manages the property at the HOA. They indicated that Gifford Tree Service removed the tree. Gifford Tree Service was contacted and they provided a letter and invoice that indicates that that subcontracted the stump removal to GSR Holdings. The violation and penalty for Gerharts was removed. ***** The incident occurred on 7/14/2025 at 177 Wyndham Woods Way in Hatfield Township in Montgomery County. *No Damage Homeowner Debra Mackey the homeowner stated in her Alleged Violation Report (AVR) that “My HOA authorized stump grinding and root removal in limited common elements over and adjacent to my gas water and sewer lines. 811 was not notified by The Wyndham Woods Way Homeowners Association or it’s Representative Mr. Reeves Miller North Penn Real Estate. 215-855-9526 ex. 119, reevesm@northpennrealestate.com. 2131 North Broad St.ste 102, Lansdale, PA 19446. I do not know who the contractor was. I am a new homeowner so not yet living at this address. On Friday July 11th I learned that the tree in front of my home was to be taken down. On Sunday July 13th I saw it had been removed without my knowledge. On Monday July 14th the stump was ground out without my knowledge. So I had no opportunity to question or call. When I spoke with a board member I was told that stump grinding is not digging”. No pictures were provided. GERHARTS LANDSCAPING SERVICES L L C is the excavator who submitted ticket 20251811496. AVR was not requested. WYNDHAM WOODS Homeowners Association is the project owner. AVR was not requested. Ticket</p>	<p>GERHARTS LANDSCAPING SERVICES L L C: \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>20251811496 was submitted on 6/30/2025 by GERHARTS LANDSCAPING SERVICES L L C with a response due by 7/02/2025. The area requested in this ticket is “WORKING IN THE COMMON AREA BEHIND HOUSE NUMBER 147, WHICH IS ACROSS FROM THE MAILBOX COLLECTOR. SITE IS APPX 200FT FROM THE INTER OF OAK PARK RD ON LEFT SIDE”. Please see attachment named “177 Wyndham Woods Way Compare” and “147 and 177 on Google Map”. The ticket does not include the time frame and area of grinding for the location of the violation.</p> <p>VIOLATIONS: GERHARTS LANDSCAPING SERVICES L L C is in violation of: Section 5(2.1) – Excavator failed to submit a location request to OneCall within the correct timeframe. Recommendation: The penalty is applied. Education is required.</p>	
56903	<p>Facility Owner: Unknown Contractor/Excavator: Independence Excavating Inc. Project Owner: PennDOT Designer: THE MARKOSKY ENGINEERING GROUP INC</p>	<p><u>On 7/14/2025 4:00:00 PM at ECMS 91286 - THREE DEGREE RD/228, ADAMS TWP, BUTLER</u> The incident occurred on July 14th, 2025, at 4:00 PM, on ECMS 91286 - Three Degree Road/228, in Adams Township, Butler County.</p> <p>A telecom line was damaged.</p> <p>The facility owner is unknown. All the submitted Alleged Violation Reports state that the facility owner of the damaged line was Firstlight. An AVR was not filed by Firstlight. Firstlight was not listed on any of the tickets related to this incident and therefore would not have been notified to mark any lines in the area/ submit information for the design. Additional online research indicates that Firstlight does not offer services in the area where the damage occurred. The submitted design indicates that the utilities on the plans are overhead lines, and a buried fiber line is not shown.</p> <p>Independence Excavating Inc., the excavator, submitted an AVR. Their AVR states, “On Monday July 14th, 2025 Independence Excavating (IX) started excavating the existing roadway of Three Degree Road. At 4:00pm the excavator pulled out a communication line that serviced the Mars Area middle school. The fiber line was direct bury under the asphalt road at a depth between 12" to 24". The line was not marked. All other communication utilities serviced the school via overhead lines. IX was notified by the school district that there internet supplier was FirstLight. IX reached out to FirstLight to notify of the damaged fiber at 4:24pm. A subcontractor of FirstLight repaired the fiber line the following day on Tuesday July 15th, 2025 at approximately 1:00pm. Attached to the report is a picture showing the unmarked line as well as a plan view showing all other communications overhead.” Photo was submitted.</p> <p>PennDOT, the project owner, submitted an AVR. Their AVR states, "On Monday July 14th, 2025 Independence</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Excavating (IX) started excavating the existing roadway of Three Degree Road. At 4:00pm the excavator pulled out a communication line that serviced the Mars Area middle school. The fiber line was direct bury under the asphalt road at a depth between 12" to 24". The line was not marked. All other communication utilities serviced the school via overhead lines. IX was notified by the school district that there internet supplier was FirstLight. IX reached out to FirstLight to notify of the damaged fiber at 4:24pm. A subcontractor of FirstLight repaired the fiber line the following day on Tuesday July 15th, 2025 at approximately 1:00pm. Attached to the report is a picture showing the unmarked line as well as a plan view showing all other communications overhead.”</p> <p>The Markosky Engineering Group Inc., the designer, submitted an AVR. Their AVR states, "On Monday 7/14/2025, Independence Excavating (IX) started excavating the existing roadway of Three Degree Road. The excavator impacted a communication service line to the Mars Area Middle School. This service line was determined to be a FirstLight service line. Underground service line location was not provided to designer during project design.”</p> <p>This case is related to cases 050666 and 054911.</p> <p>No violations were accessed as the facility owner is unknown. The line is not shown on the design.</p>	
56603	<p>Facility Owner: Peoples Gas Company Contractor/Excavator: A.P. Wise Excavating, LLC Project Owner: Redevelopment Authority of the County of Washington</p>	<p><u>On 7/14/2025 6:03:00 PM at 277 BUCKINGHAM RD, DEEMSTON BORO, WASHINGTON</u> Incident occurred on July 14th, 2025 at 6:03pm, on 227 Buckingham Road, Deemston Boro, Washington County.</p> <p>A gas line was damaged.</p> <p>Peoples Gas Company's Alleged Violation Report (AVR) states, "on 7/14/25 at 18:03 png recieved a call from Washington County 911 for a gas line that was hit at, 277 Buckingham rd, Fredericktown. Fire dept arrived onsite and found 1 inch gas line severed and notified png. When fire dept arrived the contractor left the area. Png arrived onsite and made safe and was unable to get contractors info. Damage ocured to unmarked customer side service line. Contractor was demoing the structure for Washington County Redovelopment Authority. Png made contact with Redevelopment auth and they advised contractor was A P WISE EXCAVATING. A P WISE EXCAVATING was working off old marks from ticket # 20250540126 from 2/27/25."</p> <p>Pictures show the damaged line and mark outs at the road. No AVRs have been submitted by A.P. Wise Excavating, LLC or Redevelopment Authority of Washington County as of 9/18/2025.</p> <p>Case 52055 sites that PA One Call Compliance Research Results: Contractor has placed one calls in the past under A P WISE EXCAVATING, same address as above,</p>	<p>A.P. Wise Excavating, LLC: \$4,000.00 Section 5(2.1) 2nd Offense \$1,500.00</p> <p>Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(16) 2nd Offense \$1,500.00</p> <p>Redevelopment Authority of the County of Washington: \$500.00 Section 6.1(7) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>email apwise2@gmail.com and phone (724) 352-6214. Identical truck and excavator are in the damage photos of case 52055.</p> <p>DPC voted to require education which has not been completed as of 9/18/25.</p> <p>Violations:</p> <p>A.P. Wise Excavating, LLC Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. PUC compliance education is required.</p> <p>Section 5(8) – Excavator vacated worksite after causing damage that resulted in the escape of any flammable, toxic or corrosive gas or liquid. PUC compliance education is required.</p> <p>Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required.</p> <p>AP Wise was sent for education by the DPC for case 52055 on 5/12/2025, and education is currently delinquent.</p> <p>Redevelopment Authority of Washington County Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. PUC compliance education is required.</p>	
56687	<p>Facility Owner: Peoples Gas Contractor/Excavator: Critzer Brothers Concrete & Construction Contractor/Excavator: JS BOVA EXCAVATING LLC Project Owner: FORD CITY BOROUGH Designer: Stiffler-Mcgraw</p>	<p><u>On 7/14/2025 6:20:00 PM at 10TH ST, FORD CITY BORO, ARMSTRONG</u> The incident occurred on July 14th, 2025, at 6:20 PM, on 10th Street, in Ford City Borough, Armstrong County.</p> <p>A gas line owned by Peoples Gas was damaged by hand tools. 911 was called.</p> <p>Peoples Gas, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “Critzter Brothers Concrete and Constr LLC drove a concrete pin into our service line that was marked correctly”. Photos were submitted.</p> <p>JS Bova Excavating LLC, the excavator, submitted an AVR. Their AVR states, “Incident Took Place On Monday July 14th 2025. Subcontractor Put a Concrete Pin In A Gas Service Line. The Service Was Located At 38 10th Ave, Ford City, Pa.”</p> <p>Critzter Brothers Concrete & Construction, the concrete contractor, submitted an AVR. Their AVR states, “Subcontractors employee hit a gas line with a concrete pin that was used to form concrete curb.”</p> <p>Ford City Borough, the project owner, submitted an AVR. Their AVR states, " Contractor pounded concrete pin through gas service. He called 811 and could not get through. 911 Called at 6:22 PM. Peoples Gas repaired service.”</p> <p>Stiffler-McGraw, the designer, submitted an AVR. Their AVR states, " Contractor pounded a concrete through</p>	<p>FORD CITY BOROUGH: \$250.00 Section 2(5)(v) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>gas service. Called 811 and could not get through. 911 was called at 6:22 pm. Peoples gas company was called and repaired service. Unsure the service was marked or unmarked as contractor did not notify me of the incident until 1 week later. No photos of the incident.”</p> <p>The submitted photos show the gas line marked using yellow paint. The line was damaged within the tolerance zone by a concrete pin. The submitted photos show the pin in the line. Damage was caused by hand tools.</p> <p>This case is related to cases 051368 & 051438. Cases are related by the complex project ticket 20242142245.</p> <p>Routine ticket 20251711420 had a response due date of 06/24/2025. - Ford City Borough did not respond until 06/25/2025.</p> <p>Violations:</p> <p>Ford City Borough- - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20251711420.</p> <p>Recommendation: The penalty is applied. PUC compliance training education was recently completed.</p>	
56955	<p>Facility Owner: National Fuel Gas Contractor/Excavator: J AND C ALLIED CONTRACTING Project Owner: City of Warren Other: GREENMAN-PEDERSEN, INC.</p>	<p><u>On 7/15/2025 8:15:00 AM at GLENWOOD ST, WARREN CITY, WARREN</u> The incident occurred on 7/15/2025 on GLENWOOD St. between Jackson Ave and Buchanan St., in Warren City, in Warren County.</p> <p>A gas line owned by National Fuel Gas was damaged.</p> <p>NATIONAL FUEL GAS the facility owner, stated in their Alleged Violation Report (AVR) that Excavator struck accurately marked natural gas distribution service. Reports and pictures were provided. Please see attachment.1 customer was affected.</p> <p>WARREN CITY the project owner stated in their AVR that “During excavation of sub base material of the roadway a National Fuel Gas line was previously and properly exposed, 3.9 feet below grade within the tolerance zone by J & C Allied Contracting on June 18, 2025. J & C Allied had to leave job site for three weeks and covered gas line with # 8 stone. J & C Allied arrived back on the job site on July 15, 2025 and found clay had fallen into the trench from the side walls. J & C Allied used an excavator to remove the clay and a tooth of the bucket struck and damaged the gas service line. 911 was immediately notified and National Fuel Gas arrived on scene to fix and restore service. J & C Allied failed to use prudent hand digging techniques in the tolerance zone to locate the gas line for a second time. They had knowledge of the depth of the gas line as they had previously exposed it, three weeks earlier. The City of Warren had also completed subsurface utility engineering, Hydro Excavation Level A of utility services prior to the start of the roadway construction</p>	<p>J AND C ALLIED CONTRACTING: \$500.00 Section 5(4) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>project. Project is >\$400,000. 780 ft in length. 911 was notified. Reports and pictures were provided.</p> <p>J AND C ALLIED CONTRACTING the excavator stated in their AVR that “J & C Allied Contracting, Inc. started working on a reconstruction project on Glenwood St in Warren, PA on 6/9/25. One facet of this project is replacement of storm sewer. On 6/18/25, J & C uncovered a gas service supplying 14 Glenwood St in the storm sewer pipe trench. It was determined that the gas service would be directly under the proposed storm sewer. Storm pipe placement stopped just short of this gas service, but the geotextile placed in the pipe trench extended beyond the placed pipe and covered this service. J & C was forced to leave this project shortly thereafter for a different project. On 7/15/25, J & C resumed work on the Glenwood St project. During this absence, the pipe trench experienced minor cave ins and the previously placed geotextile became covered with material. While excavating the material on the geotextile from the cave in, J & C struck the previously located gas service line, which was directly underneath the geotextile. Reports and pictures were provided.</p> <p>GREENMAN-PEDERSEN, INC. stated in their AVR that “Gas service line severed on Glenwood St in Warren, PA. Service line was previously uncovered by hand. Contractor placed geotextile and #8 stone over gas line and left jobsite for 3 weeks. 3 week work stoppage caused debris to fall into excavated area. After returning to jobsite, contractor used excavator to remove debris and the tooth from the bucket caught the service line. Service line was severed. National fuel was contacted as well as the City of Warren and 911. Reports and pictures were provided.</p> <p>VIOLATIONS J AND C ALLIED CONTRACTING is in violation of: Section 5(6)(ii) – Excavator failed to exercise due care and employ prudent techniques. Recommendation: The penalty is applied. Education is required.</p>	
56614	Facility Owner: PECO An Exelon Company Contractor/Excavator: KBC Construction, LLC Project Owner: NORWOOD BORO	<p>On 7/15/2025 8:30:00 AM at 616 SENECA AVE, NORWOOD BORO, DELAWARE The incident occurred on 7/15/2025 at 616 SENECA AVE in Norwood Borough in Delaware County.</p> <p>A ½ gas service line was damaged.</p> <p>KBC CONSTRUCTION LLC stated in their Alleged Violation Report (AVR) that “A gas service was damaged due to it being miss marked”.</p> <p>KBC CONSTRUCTION LLC stated in their AVR that “LINE HIT WAS MISMARKED. PECO IS ON SITE. FACILITY TYPE: NATURAL GAS-PECO EXCAVATION EQUIPMENT: EXCAVATOR HAZARDOUS RELEASE: NO”</p>	<p>PECO An Exelon Company: \$2,000.00 Section 2(5)(i) Subsequent \$2,000.00</p> <p>NORWOOD BORO: \$1,000.00 Section 6.1(7) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>PECO stated in their AVR that “Contractor KBC construction hit gas service with mechanical means due to mismarked service”.</p> <p>USIC Damage Report was provided. Damage Reported “On 7/15/2025 at 9:01 AM USIC was notified by KBC CONSTRUCTION LLC of a gas damage at 618 Seneca Ave Norwood Boro Delaware County PA, During the investigation it was found that KBC CONSTRUCTION LLC was excavating with a mini excavator to make repairs to the sewer service at 616 Seneca when they severed the 1/2 plastic gas line feeding 618 Seneca 3' from the gas mark outs, while onsite it was found that the records provided at the time of the locate do not accuralty depict the true path of the gas service resulting in the service being severed while I was onsite and reviewing the prints I found a marker ball on the service 3' behind the curb line I located the marker ball at that location but the damage was 3' from where the marker ball was due to the mapping discrepancy this service was severed and in need of repair”. Pictures were provided. 911 was notified.</p> <p>NORWOOD BOROUGH the project owner did not submit an AVR.</p> <p>VIOLATIONS NORWOOD BOROUGH Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike or damaging a facility owner’s line during excavation or demolition work activities or if a project owner believes a violation of this act has been committed in association or demolition. Recommendation: The penalty is applied. Education is required.</p> <p>PECO Section 2(5)(i) – Failed to locate underground lines within 18” horizontally of the outside of the wall. This is a subsequent offense. Recommendation: The penalty is applied. The required education has been recently completed.</p>	
56632	<p>Facility Owner: PECO Contractor/Excavator: DELMONT UTILITIES COMPANY Project Owner: AQUA PENNSYLVANIA INC Designer: CHESTER VALLEY ENGINEERS Other: Astound powered by RCN Other: Upper Darby Township Other: Verizon</p>	<p><u>On 7/15/2025 11:00:00 AM at BARRINGTON RD, UPPER DARBY TWP, DELAWARE</u> Incident to occurred on July 15th, 2025, at 11am along Barrington Road, Upper Darby Township, Delaware County.</p> <p>A gas line was damaged.</p> <p>PECO's Alleged Violation Report (AVR) states, "Delmont Utilites working for Aqua, was digging on marks with mechanical means."</p> <p>Delmont Utilities AVR states, "DIGGING TO INSTALL WATER MAIN AT 137 BARRINGTON RD AND WE FOUND A GAS SERVICE ON THE MARK. THIS HOLE WAS ALSO DUG PREVOISLY WITH THE VAC TRUCK. THERE WAS ANOTHER PLASTIC LINE WITHIN THE TOLERANCE ZONE AND WE HIT IT AFTER FINDING THE ORGINAL SERVICE."</p>	<p>DELMONT UTILITIES COMPANY: \$500.00 Section 5(4) 1st Offense \$500.00</p> <p>Astound powered by RCN: \$500.00 Section 2(4) 2nd Offense \$500.00</p> <p>Upper Darby Township: \$1,500.00 Section 2(4) 2nd Offense \$500.00</p> <p>Section 2(5)(viii) 2nd Offense \$1,000.00</p> <p>Verizon: \$6,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Aqua's AVR states, "Aqua Contractor Delmont Utilities, while digging to install water main at 137 Barrington Rd, crew found a gas service on the mark. The hole was also dug previously with the vac truck. There was another plastic line within the tolerance zone and crew hit it after finding the original service."</p> <p>Pictures show that the road had been potholed prior. The newest locate marks for the gas line did not go through the previously potholed location.</p> <p>Violations:</p> <p>Delmont Utilities Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. 20251892104. PUC compliance education is required.</p> <p>Verizon Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20251892104. PUC compliance education is required. Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20251060625. PUC compliance education is required. Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20251060625. PUC compliance education is required.</p> <p>Upper Darby Township Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20250701159. PUC compliance education is required. Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20251060625. PUC compliance education is required.</p> <p>Astound Broadband Powered by RCN - Completed education on 9/7/25. Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20250701159. PUC compliance education is required.</p>	<p>Section 2(5)(v) Subsequent \$2,000.00</p> <p>Section 2(5)(v) Subsequent \$2,000.00</p> <p>Section 2(5)(viii) Subsequent \$2,000.00</p>
56679	<p>Facility Owner: JESSUP BOROUGH OF</p> <p>Contractor/Excavator: I B ABEL INC</p> <p>Project Owner: PPL ELECTRIC UTILITIES CORPORATION</p>	<p><u>On 7/16/2025 1:10:00 PM at 313 CHURCH ST, JESSUP BORO, LACKAWANNA</u> Incident occurred on July 16th, 2025, at 1:05pm on 313 Church Street, Jessup Boro, Lackawanna County.</p> <p>An electric line was damaged.</p> <p>Jessup Borough's Alleged Violation Report (AVR) states, "I B Abel, Inc. called around 1:10 P.M. on July 16, 2025, to notify me that they hit the electric wires that power the streetlights on Church Street in front of 313. They were using an auger to replace a pole for PPL Electric. I immediately went to the location to evaluate the situation. The breaker box that feeds power to the lights was turned off. The only power impacted was the power to the streetlights and damage was limited to the</p>	<p>JESSUP BOROUGH OF: \$500.00</p> <p>Section 2(5)(i) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>wires feeding the pole style streetlights. I attached photos of the location when I arrived and additional photos of the location when work continued. The PA One Call generated on 5/7/2025 ticket 20251274646 was responded to by Robert Vislosky as clear. The PA One Call generated on 5/16/2025 ticket 20251360367 was responded to by Tyler Havrilak as field market. Red paint was placed on the sidewalk next to the existing pole at 313 Church Street. The PA One Call generated on 5/29/2025 ticket 20251494143 was responded to by Tyler Havrilak as field marked. The red paint remained on the sidewalk. The PA One Call generated on 6/9/2025 ticket 20251600216 was responded to by Robert Vislosky as clear. The PA One Call generated on 6/19/2025 ticket 20251701705 was responded to by Tyler Havrilak as field marked. The red paint remained on the sidewalk. The PA One generated on 7/3/2025 ticket 20251840175 was responded to by Robert Vislosky as clear. The PA One Call generated on 7/16/2025 ticket 20251973240 was the damage report responded to by me. New red markings were painted over the existing marks and new marks were made where the damage occurred. Under the event impact section of this report everything is marked no. That is incorrect. I do not have the answers to those questions, and I am unable to make the circles blank. Under the locator information I am only able to list one name but there were two employees who responded on different dates. Robert Vislosky and Tyler Havrilak."</p> <p>I B Abel Inc's AVR states, "While auguring a new hole for a pole replacement job, we made contact with unmarked underground street light wiring. We reported the dig-in. Jessup Borough reported to the site and confirmed it was their wiring - the responded "Clear" on our valid dig-ticket."</p> <p>PPL's AVR states, "I B Abel was setting a pole and hit an unmarked electric line owned by Jessup Boro."</p> <p>Images show that the line was mismarked.</p> <p>Violations:</p> <p>Jessup Borough Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. PUC compliance education is required.</p>	
56723	<p>Facility Owner: Peoples Gas Contractor/Excavator: KOLTON CONSTRUCTION AND LAND MANAGEMENT Project Owner: KOLTON CONSTRUCTION AND LAND MANAGEMENT (Placeholder) Designer: THE</p>	<p><u>On 7/16/2025 1:51:00 PM at 28 WOODLAND DRIVE, MT LEBANON TWP, ALLEGHENY</u> The incident occurred on 07/16/2025 at 1:51 PM, at 28 Woodland Drive, in Mt Lebanon Township, Allegheny County.</p> <p>-Hand tools-</p> <p>A gas line owned by Peoples Gas was damaged by hand tools. 911 was called.</p> <p>Peoples Gas, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, "On 7/16/25</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
	GATEWAY ENGINEERS INC	<p>Kolton Construction and Land Management working to install new concrete sidewalks drove form pin thru marked PNG main to curb service line, Kolton Construction and Land Management notified PNG and 911. PNG crews arrived onsite and made repairs.”</p> <p>Kolton Construction and Land Management is the excavator and project owner. An AVR has not been filed as of 09/12/2025.</p> <p>The submitted photos show the gas line was marked using flags and yellow paint. The gas line was damaged within the tolerance zone by hand tools. There were 3 photos submitted by Peoples Gas, which do not indicate that mechanized equipment was used. The line was shown to have a single circular puncture hole, consistent with a pin. Peoples Gas AVR also indicated the damage was caused by hand tools.</p>	
57203	<p>Facility Owner: Comcast</p> <p>Contractor/Excavator: DOLI CONSTRUCTION</p> <p>Project Owner: Lower Paxton Township Authority</p> <p>Designer: HRG INC</p> <p>Other: PPL ELECTRIC UTILITIES CORPORATION</p>	<p>On 7/16/2025 4:15:00 PM at RYAN DR, LOWER PAXTON TWP, DAUPHIN Incident occurred on July 16th, 2025, at 4:15pm along Ryan Drive, Lower Paxton Township, Dauphin County.</p> <p>A telecom line was damaged.</p> <p>Doli Construction's Alleged Violation Report (AVR) states, "1" conduit buried 1" below grass ran up against back side of side walk. Located with vac truck. When cutting sidewalk blocks it was cut through. Not on plans."</p> <p>Lower Paxton Township Authority's AVR states, "From excavator: "1" conduit buried 1" below grass ran up against back side of side walk. Located with vac truck. When cutting sidewalk blocks it was cut through. Not on plans."</p> <p>HRG's AVR states, "1" Conduit was buried 1" below the grass and ran up against the back side of the sidewalk. Doli located it with the vac truck. Doli cut through the line when cutting the sidewalk sections."</p> <p>Case is related to 052101, 052187, 052200, 052431, 054080, 056426, 056684, and 057951.</p> <p>Comcast, PPL, and Lower Paxton Township Authority responded to ticket 20251831309 with "SCHEDULED MARK" placed at 5:49pm for each entity. No final response of field marked or clear no facilities was placed by the law timeframe given by Act 127 of 2024. Image shows a damaged telecom line. AVRs from Doli, Lower Paxton Township Authority, and HRG notes that the line was marked accurately.</p> <p>Comcast has not submitted an AVR within 30 business days.</p> <p>Violations:</p> <p>Comcast</p>	<p>Comcast: \$2,500.00 Section 2(5)(v.2) 2nd Offense \$500.00</p> <p>Section 2(10) 3rd Offense \$2,000.00</p> <p>DOLI CONSTRUCTION: \$1,000.00 Section 5(4) 2nd Offense \$1,000.00</p> <p>Lower Paxton Township Authority: \$500.00 Section 2(5)(v.2) 2nd Offense \$500.00</p> <p>PPL ELECTRIC UTILITIES CORPORATION: \$500.00 Section 2(5)(v.2) 2nd Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. 20251831309. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p> <p>Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. PUC compliance education is required for the person responsible for submitting AVR or their replacement.</p> <p>Doli Construction Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. 20251831309.</p> <p>Lower Paxton Township Authority Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. 20251831309. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p> <p>PPL Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. 20251831309. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p>	
56674	<p>Facility Owner: Myerstown Water Authority Contractor/Excavator: JW DIDADO Project Owner: Met Ed / First Energy</p>	<p><u>On 7/17/2025 9:30:00 AM at W MAPLE AVE, MYERSTOWN BORO, LEBANON</u> The non-damage event occurred on July 17th, 2025, on West Maple Avenue, in Myerstown Borough, Lebanon County.</p> <p>Non-damage event. Excavating prior to lawful start date.</p> <p>Myerstown Water Authority, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “Received a ticket (20251975167) on July 16, 2025. The response due date was July 18, 2025. We went out to mark and the work was ALREADY DONE. Scheduled Excavation date was July 21, 2025.”</p> <p>JW DIDADO is the excavator. An AVR has not been filed as of 09/12/2025.</p> <p>Met Ed is the project owner. An AVR has not been filed as of 09/12/2025.</p> <p>The facility owner responded to the routine ticket 20251975167 on 07/18/2025 as ‘Field Marked’. Upon arrival at the site to mark their lines, it was discovered that the work was already complete. The lawful start date for the ticket was 07/21/2025. The equipment type listed on the ticket was an auger truck.</p>	<p>JW DIDADO: \$0.00 Section 1.1 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Per Act 127 of 2024, Section 5.1 – It shall be the duty of each excavator who intends to perform excavation or demolition work within this Commonwealth: To submit a locate request to identify the location and type of facility owner lines at each work site by notifying the facility owner through the One Call System. Notification shall be not less than three nor more than ten business days in advance of beginning excavation or demolition work. No work shall begin earlier than the lawful start date which shall be on or after the third business day after notification. The lawful start date shall exclude the date upon which notification was received by the One Call System and notification received on a Saturday, Sunday or holiday, which shall be processed on the following business day. In the case of a complex project, notification shall not be less than ten business days in advance of the beginning of excavation or demolition work.</p> <p>Violations:</p> <p>JW DIDADO- - Section 1.1 – Excavator did not begin within legal timeframe.</p> <p>Recommendation: The is a warning. PUC compliance training education is required.</p>	
57338	<p>Facility Owner: PPL Contractor/Excavator: MR Kirby Plumbing Project Owner: Homeowner</p>	<p><u>On 7/17/2025 10:01:00 AM at 3326 MARGATE ROAD, BETHLEHEM TWP, NORTHAMPTON</u> The incident occurred on 7/17/2025, at 10:01 AM, on 3326 Margate Road, in Bethlehem Twp, Northampton County.</p> <p>An electric line owned by PPL was damaged. The facility was notified of the damage.</p> <p>PPL is the facility owner. Their Alleged Violation Report (AVR) states, “On Thursday the 17th of July 2025 at 10:01 am a non-PPL contractor (MR Kirby Plumbing) Was repairing A sewer lateral when they came in contact with an underground electric service. No one was hurt or injured but the home did lose service. PPL was contacted and when the first responders arrived on site, they were able to make the area safe and begin the repair. I spoke with Mr. Kirby who informed me that the electric service was marked properly, and they accidentally hit it with their backhoe. I spoke with our first responder who was on site. They made me aware that they were able to make a repair by splicing the service back together and no follow-up is needed. Mr. Kirby plumbing will be held liable for this damage and repair.”</p> <p>Images were submitted showing the location, excavation equipment, and damaged line. The ticket was marked out on 6-24-2025 according to the ticket responses. There are no pre-excavation images available, and all images are from 7-17-2025. There are white marks added by USIC after the damage, which are an attempt to indicate where marks were, but no marks can be seen that indicate the damaged line was marked. No update or</p>	<p>MR Kirby Plumbing: \$1,250.00 Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>renotify ticket was located by PA One Call for this location. New marks were added after the damage occurred, and are seen in 2 of the images.</p> <p>Mr Kirby Plumbing is the excavator. An AVR has not been filed as of 09/22/2025.</p> <p>The homeowner is the project owner. An AVR has not been filed as of 09/22/2025.</p> <p>Violations: Excavator - Mr Kirby Plumbing: Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: PUC Online Compliance Training is required.</p>	
57587	<p>Facility Owner: PECO AN EXELON COMPANY Contractor/Excavator: CHESTER WATER AUTHORITY Project Owner: CHESTER WATER AUTHORITY</p>	<p><u>On 7/17/2025 11:59:00 PM at 1917 HILLENDALE RD, KENNETT TWP, CHESTER</u> Chester Water Authority accepted the removal of 1 violation and penalty of section 5(16), but keep the other 5(16) violation and penalty with compliance training and test. See attachments. ***** The incident occurred on Thursday, July 17, 2025, at 1917 Hillendale Road, in Kennett Township, Chester County.</p> <p>A gas and an electric line owned by PECO An Exelon Company were damaged. PECO provided two alleged violation report’s (AVR),</p> <p>PECO stated in their first AVR, Chester Water Authority hit the .5" gas service that was 17' off the marks due to inaccurate prints. PECO explained, on 7/17/2025, at 11:59pm they were notified of a gas damage at 1917 Hillendale Road and during the investigation it was found that Chester Water Authority was excavating with a backhoe under Routine ticket, 20251970173, to install a 1" water service. Chester Water Authority severed the 1/2" plastic gas service line, that was 17' from the gas mark outs. While onsite it was found that due to trees in the front of the house and blocking the view of the house to get an accurate measurement while onsite and trying to get the proper measurements it took 2 people to try and locate the gas service by measurements after attempting to measure the service with the measurements provided on the gas sketch it still came out to be 5' from where the marks where due the trees in the yard and the incorrect tap measurement this service was severed 17' from the gas mark outs and needing repair. They said, Root Cause Analysis: Untoneable / Difficult to Locate, (procedures used).</p>	<p>PECO AN EXELON COMPANY: \$4,000.00 Section 2(5)(i) Subsequent \$2,000.00</p> <p>Section 2(5)(i) Subsequent \$2,000.00</p> <p>CHESTER WATER AUTHORITY: \$1,000.00 Section 5(16) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>PECO stated in their second AVR, on 7/17/2025, at 3:32pm they were notified that Chester Water Authority was excavating with a backhoe to install a new 1" water service to 1916 Hillendale Rd when they severed the mis-marked electric secondary feeding 1917 Hillendale Road. While onsite it was found that this secondary was mis-marked by 17' on the original Routine ticket, 20251970173 resulting in the electric being severed and needing repair. They said, Root Cause Analysis: Did not verify path.</p> <p>PECO provided photos of the damage sites. Chester Water Authority, the excavator and project owner, did not submit AVR's.</p> <p>Violations:</p> <p>*PECO An Exelon Company is in violation of sections: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Gas Damage 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Electric Damage Recommendation: Penalties Applied</p> <p>*Chester Water Authority is in violation of sections: 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Gas Damage 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Electric Damage Recommendation: PUC Compliance Education Required and Penalties Applied</p>	
56799	<p>Facility Owner: Peoples Gas Company LLC Contractor/Excavator: M O'Herron Company Project Owner: Peoples Gas - SPACESAVER Designer: Peoples Gas Company LLC - Spacesaver Other: GATEWAY ENGINEERS</p>	<p><u>On 7/21/2025 12:00:00 AM at E GARDEN RD, BRENTWOOD BORO, ALLEGHENY</u> Peoples gas disagreed and provided the communication with the excavator. They also stated that the issue of not updating in the OneCall system has been fixed. The violation is maintained, but the \$1000. penalty is reduced to a warning. On 11/07/2025 an email confirmed that Peoples accepted the violation with a warning. *****</p> <p>The incident occurred on 7/21/2025 on E Garden Rd in Brentwood Borough in Allegheny County.</p> <p>A gas line owned by Peoples Gas Company was damaged.</p> <p>PEOPLES GAS COMPANY LLC the facility owner and project owner stated in their Alleged Violation Report (AVR) that "M O'Herron working for Peoples Gas to install new gas main and service struck and damaged a properly marked Peoples Gas service line while using mechanized equipment in the tolerance zone. Peoples Gas employees were on site at the time of the damage and immediately stopped the flow of gas". Project cost is listed as <\$400,000. 911 was called by the excavator. Pictures and report were provided.</p>	<p>Peoples Gas Company LLC: \$0.00 Section 2(5)(v) Subsequent \$0.00</p> <p>M O'Herron Company: \$2,000.00 Section 5(16) 2nd Offense \$1,500.00</p> <p>Section 5(11.2) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>M O'Herron Company the excavator did not submit an AVR as of 9/11/2025.</p> <p>VIOLATIONS: M O'Herron Company is in violation of: Section 5(11.2) – When using trenchless technology, Excavator failed to utilize at a minimum, the best practices published by the Common Ground Alliance. CGA Best Practices 9) 5-29 The excavator requests the location of underground facilities at the entrance pit, trenchless excavation path and the exit pit by notifying the facility owner/operator through the 811 center. The trenchless equipment operator performs a site inspection, walking the trenchless excavation path prior to commencing work, and has a good understanding of the job. The trenchless excavation operator confirms and maintains the path and minimum clearances established by the project owner and design engineer by tracking and recording the path of the trenchless excavation until complete. Means of trenchless excavation include electronic locating/guidance devices, pipe lasers, water levels, visual inspection, ect.</p> <p>Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or damaging a facility owner’s line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. This is a second-time offense. Recommendation: The penalty is applied. Education has been completed recently.</p> <p>Peoples Gas is in violation of Section 2(5)(v) Failed to respond to Onecall ticket 20251641078 in the required amount of time. Ticket 20251641078 was submitted by M O'Herron on 6/13/2025 with a response due by 6/17/2025. Peoples Gas did not respond "field marked" until 6/23/2025. This is a subsequent offense. Recommendation: The penalty is applied. The required education has been recently completed.</p>	
56774	<p>Facility Owner: COMCAST</p> <p>Contractor/Excavator: STAFURSKY PAVING</p> <p>Project Owner: ARCHBALD BOROUGH</p> <p>Designer: KBA ENGINEERING</p>	<p><u>On 7/21/2025 8:25:00 AM at OakHill Drive, ARCHBALD BORO, LACKAWANNA</u> The incident occurred on Monday, July 21, 2025, on Oak Hill Drive, in Archbald Borough, Lackawanna County.</p> <p>A communication cable was damaged.</p> <p>Stafursky Paving stated in their alleged violation report (AVR), while they were excavating for a new storm line, their crew dug up unmarked Comcast cable line. Per one call, facility owner responded “clear no facilities. Stafursky Paving provided pictures of the damaged cable.</p> <p>Archbald Borough, the project owner, stated in their AVR, Stafursky Paving hit and damaged an unmarked Comcast cable line.</p> <p>An email was sent to Comcast on Friday, August 19, 2025, requesting an AVR, and they submit it the next day. Comcast did not provide a summary, but provided</p>	<p>COMCAST: \$2,000.00 Section 2(5)(i) Subsequent \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>photos and locating information, responding that lines were Not Marked.</p> <p>Comcast responded as “Clear No Facilities” to all tickets except for the Damage Emergency, which they responded as “Field Marked”.</p> <p>Violation:</p> <p>*Comcast is in violation of sections: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: Penalty Applied</p>	
57294	<p>Facility Owner: UGI Utilities, Inc.</p> <p>Contractor/Excavator: Shippensburg Borough Authority</p> <p>Project Owner: Shippensburg Borough Authority (Placeholder)</p> <p>Designer: RETTEW</p> <p>Other: Crown Castle</p>	<p><u>On 7/21/2025 9:05:00 AM at RICHARD AVE, SHIPPENSBURG TWP, CUMBERLAND</u> UGI disputed the violation of 2(5)(v.2) and submitted additional information. Violation of 2(5)(v.2) was withdrawn. UGI accepted the penalty for 2(5)(i).</p> <p>*****</p> <p>The incident occurred on July 21st, 2025, at 9:05 AM, on Richard Avenue, in Shippensburg Township, Cumberland County.</p> <p>A gas line owned by UGI Utilities, Inc. was damaged. 911 was called.</p> <p>UGI Utilities, Inc., the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “Shippensburg Borough was trenching down Richard Ave to install new water main. They struck and damaged an incorrectly marked gas service going to 207 N. Prince St.” Photos were submitted.</p> <p>Shippensburg Borough Authority is the excavator and project owner. An AVR has not been filed as of 10/08/2025.</p> <p>The submitted photos show that the damaged gas line was not marked. The closest mark out was several feet away from where the damage occurred.</p> <p>Routine ticket 20251741994 was due 06/25/2025.</p> <ul style="list-style-type: none"> - UGI did not mark the line until 07/17/2025. They responded 5 times with scheduled mark dates. - Crown Castle did not respond until 06/26/2025 (as insufficient info) and then responded clear on 07/11/2025. <p>Violations:</p> <p>UGI-</p> <ul style="list-style-type: none"> - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. - Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket 20251741994. (Withdrawn) <p>Recommendation: The penalty is applied. PUC compliance training education was recently completed.</p>	<p>UGI Utilities, Inc.: \$2,000.00 Section 2(5)(i) Subsequent \$2,000.00</p> <p>Shippensburg Borough Authority: \$1,000.00 Section 5(16) 1st Offense \$1,000.00</p> <p>Crown Castle: \$500.00 Section 2(5)(v) 2nd offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Shippensburg Borough Authority- - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Crown Castle- - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20251741994. Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
56898	<p>Facility Owner: WILKINSBURG-PENN JOINT WATER AUTHORITY Contractor/Excavator: M O'HERRON COMPANY Project Owner: Peoples Gas Designer: MONALOH BASIN ENGINEERS</p>	<p><u>On 7/21/2025 9:15:00 AM at CHURCHILL RD, CHURCHILL BORO, ALLEGHENY</u> Peoples Gas disputed the violation of 2(5)(v) and accepted the violation of 6.1(7). Additional information was submitted and the violation of 2(5)(v) was withdrawn.</p> <p>*****</p> <p>The incident occurred on July 21st, 2025, on Churchill Road, in Churchill Borough, Allegheny County.</p> <p>A water line owned by Wilkinsburg-Penn Joint Water Authority was damaged.</p> <p>Wilkinsburg-Penn Joint Water Authority, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, "M OHerron Company performing gas line work for PNG. Excavation material fell on exposed WPJWA 12" ductile iron water main causing damage. Nearest address #2408 Churchill Road Churchill." Photos were submitted.</p> <p>M O'Herron Company is the excavator. An AVR has not been filed as of 09/25/2025.</p> <p>Peoples Gas is the project owner. An AVR has not been filed as of 09/25/2025.</p> <p>Monaloh Basin Engineers is the designer. An AVR has not been filed as of 09/25/2025.</p> <p>The submitted photos show the line was visible and uncovered. The facility owner noted in their AVR that, "Excavation material fell on exposed WPJWA 12" ductile iron water main causing damage."</p> <p>Routine ticket 20251601626, had a response due date of 06/11/2025. - Peoples Gas did not respond until 06/17/2025.</p> <p>Violations:</p> <p>M O'Herron Company- - Section 5(6)(ii) – Excavator failed to provide support and mechanical protection for known facility owner's lines at the construction work site.</p>	<p>M O'HERRON COMPANY: \$2,000.00 Section 5(6)(ii) 1st Offense \$500.00</p> <p>Section 5(16) 2nd Offense \$1,500.00</p> <p>Peoples Gas: \$1,500.00 Section 6.1(7) 2nd Offense \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>- Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: The penalty is applied. PUC compliance training education was recently completed.</p> <p>Peoples Gas-</p> <p>- Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20251601626. - Withdrawn. Recommendation: The penalty is applied. PUC Project Owner compliance training education is required. PUC Facility Owner compliance training education was recently completed.</p>	
56933	<p>Facility Owner: Municipal Authority of Westmoreland County Contractor/Excavator: Grit Industry Project Owner: West Leechburg Borough Designer: Bove Engineering Designer: HRG INC</p>	<p><u>On 7/21/2025 9:45:00 AM at 1127 Gosser Street in front of the house. WEST LEECHBURG BORO. WESTMORELAND</u> Incident occurred on July 21st, 2025, at 9:45am on 1127 Gesser Street, West Leechburg Boro, Westmoreland County.</p> <p>A was line was damaged.</p> <p>HRG's Alleged Violation Report (AVR) states, "While digging to place a new sanitary sewer lateral, for 1127 Gosser St a 4" steel waterline end cap was exposed. Digging near the thrush block for the line the end cap blew off. MAWC was called the shut off the waterline then placed on new end cap and new thrust blocking."</p> <p>Case is related to 56915 and 57060.</p> <p>West Leechburg Borough's AVR states, "While digging to place a new sanitary sewer lateral, for 1127 Gosser St a 4" steel waterline end cap was exposed. Digging near the thrush block for the line the end cap blew off. MAWC was called the shut off the waterline then placed on new end cap and new thrust blocking."</p> <p>Municipal Authority of Westmoreland County's AVR states, "On October 6, 2025 The Municipal Authority of Westmoreland County (MAWC) received a request for an AVR from the PUC related to an incident at 1127 Gosser St. West Leechburg, PA occurring on 7/21/2025. MAWC's records show that MAWC repaired a water main leak at 1127 Gosser St. on 7/21/2025, MAWC also repaired a water man leak at 1125 Gosser St. on 7/24/2025. MAWC field personnel documented these incidents as leaks, not damaged facilities. MAWC observed that a sewer contractor had been working in the area, and performed excavations near the marked MAWC 4" transite water main. MAWC acknowledges that these leaks could have occurred as a result of the sewage contractor failing to support the MAWC main as they worked around it. MAWC during its repairs found no evidence that the water main was actually hit using powered equipment. MAWC did not submit an AVR to</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>the PUC because MAWC documented this incident as a main line leak, not a damaged facility."</p> <p>No violations.</p>	
57270	<p>Facility Owner: West Penn Power Contractor/Excavator: Pennsylvania American Water (PAWC) Other: Comcast</p>	<p><u>On 7/21/2025 9:52:00 AM at 112 WOODSIDE DR, PETERS TWP, WASHINGTON</u> The incident occurred on 7/21/2025, at 9:52 AM, on 112 Woodside Dr, in Peters Twp, Washington County.</p> <p>An electrical line owned by West Penn Power - First Energy was damaged.</p> <p>West Penn Power - First Energy is the facility owner. Their Alleged Violation Report (AVR) states, "On July 15, 2025, Pennsylvania American Water, Excavator, requested PA One Call Routine ticket 20251962518 to repair a water main at 106 Woodside Dr, McMurray, Washington County, PA. On July 21, 2025, customers on Woodside Dr. reported no power. West Penn Power's ("WPP") crew investigated and located a damaged underground primary electric cable. WPP's Contract Locator, USIC, investigated and determined that the Excavator did not exercise due care while digging within the tolerance zone."</p> <p>Pennsylvania American Water is the excavator and project owner. Their AVR states, "PAWC crew was working on site fixing a leak on a mainline when crew struck an electric line in the tolerance zone. Operator didn't see line. The damaged line was just a ground wire not an active line."</p> <p>Images submitted show the site, pre-excavation mark out, and post-excavation damaged lines. Excavating equipment is shown on site, as well as indication of it being used within the tolerance zone of the marks. The damaged lines are within 18 inches of the marks, as shown using a hit kit.</p> <p>Ticket # 20252021210 New – Damage – Emergency 7/21/25, 9:46 AM: Comcast responded "Insufficient information. Do not dig." on 7/21/2025 at 12:23 PM. No final response was entered. Verizon responded "clear" to this Ticket.</p> <p>Violations: Excavator – West Penn Power: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: PUC Online Compliance Training is required. Facility (other) – Comcast: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket # 20252021210 Recommendation: PUC Online Compliance Training is required.</p>	<p>Pennsylvania American Water (PAWC): \$1,000.00 Section 5(4) 2nd Offense \$1,000.00</p> <p>Comcast: \$2,000.00 Section 2(5)(vii) 3rd Offense \$2,000.00</p>
57007	<p>Facility Owner: COLUMBIA GAS OF PA INC - North</p>	<p><u>On 7/21/2025 10:08:00 AM at 1432 DAVIS AVE, PITTSBURGH CITY, ALLEGHENY</u> Pittsburgh Water and Sewer Authority disagreed and stated that they did</p>	<p>Independent Enterprises: \$4,500.00 Section 5(4) Subsequent</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>Contractor/Excavator: Independent Enterprises</p> <p>Project Owner: Pittsburgh Water</p> <p>Designer: G A I Consultants</p> <p>Other: VERIZON</p>	<p>submit an Alleged Violation Report (AVR). The AVR was located by the AVR number and added to the case. The tickets in the AVR and the site information was different, so this AVR was not attached to the case prior to knowing the AVR number. Violation Section 6.1(7) to PWSA has been withdrawn.</p> <p>*****</p> <p>The incident occurred on 7/21/2025 at 1432 Davis Ave in Pittsburgh City in Allegheny County.</p> <p>A Gas line owned by Columbia Gas was damaged.</p> <p>COLUMBIA GAS OF PA, stated in their Alleged Violation Report (AVR) that “While performing excavation work to install a new water line at 1432 Davis Ave, Independent Enterprise struck a 1" plastic company service line. The excavation took place within the designated tolerance zone, and utility marks at the site were confirmed to be accurate. A Columbia Crew responded promptly to the scene and completed repairs to the damaged service line”. 911 was notified. 1 customer was affected.</p> <p>Pittsburgh Water and Sewer Authority, the project owner has not submitted an AVR as of 9/12/2025. An email was received after the stakeholder notices went out. AVR’s were submitted and not attached to case 57007 because the names of the streets were different and the ticket numbers submitted did not match the existing tickets in the case. PWSA stated I their AVR that “Plastic gas service line approximately under a 2' steel gas service line. Contractor did not realize there was a 2nd gas line underneath the steel gas line. The contractor was digging underneath the marked 2 inch steel gas service line when they hit and ripped out a 1 inch plastic gas service line directly under the 2" gas service line going to 1432 Davis Avenue. The contractor immediately called 911 and the fire department showed up at the site. Peoples Gas was the first gas company to show up at the site and they determine that the gas service line was owned by Columbia Gas. Columbia Gas came and fixed the gas service line”.</p> <p>Independent Enterprise, the excavator has not submitted an AVR as of 9/12/2025. INDEPENDENT ENTERPRISES. An email was received after the stakeholder notices went out that an AVR was submitted. AVR was located with a different address and ticket number, so was not connected when doing an AVR search. “Plastic gas service line approximately under a 2' steel gas service line. Contractor did not realize there was a 2nd gas line underneath the steel gas line. The contractor was digging underneath the marked 2 inch steel gas service line when they hit and ripped out a 1 inch plastic gas service line directly under the 2" gas service line going to 1432 Davis Avenue. The contractor immediately called 911 and the fire department showed up at the site. Peoples Gas was the first gas company to show up at the site and they determine that the gas</p>	<p>\$2,000.00</p> <p>Section 5(16) Subsequent \$2,500.00</p> <p>Pittsburgh Water: \$0.00</p> <p>VERIZON: \$1,500.00 Section 2(5)(viii) 3rd Offense \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>service line was owned by Columbia Gas. Columbia Gas came and fixed the gas service line". Pictures were provided.</p> <p>Case 56713 is an investigation connected by tickets.</p> <p>VIOLATIONS: Pittsburgh Water and Sewer Authority is in violation of: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike or damaging a facility owner’s line during excavation or demolition work activities or if a project owner believes a violation of this act has been committed in association or demolition. This is a subsequent violation. Recommendation: The penalty is applied. The required project owner education was recently completed.</p> <p>Independent Enterprise is in violation of: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. This is a subsequent offense. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or damaging a facility owner’s line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. This is a subsequent offense. Recommendation: The penalty is applied. Education is required.</p> <p>Verizon is in violation of: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Complex Project ticket 20251250961 was requested by Independent Enterprises on 5/05/2025 with a response due by 5/08/2025. Verizon never responded. The meeting was held on 5/09/2025 at 11:00. This is a 3rd offense. Recommendation: The penalty is applied.</p>	
56982	<p>Facility Owner: PECO Contractor/Excavator: LAMBERTS CABLE SPLICING LLC Project Owner: VERIZON</p>	<p><u>On 7/21/2025 1:33:00 PM at HILLSIDE LN, NORTH COVENTRY TWP, CHESTER</u> The incident occurred on HILLSIDE LN in NORTH COVENTRY TWP in CHESTER County.</p> <p>Non-Damage. An emergency ticket was submitted by an excavation company for non-emergency work.</p> <p>PECO AN EXELON COMPANY stated in their Alleged Violation Report (AVR) that “On July 21st, 2025 at approx. 1133 hours, Lamberts Cable Splicing placed an emergency ticket to replace Verizon handhole boxes. The ticket spanned nearly the entire length of Hillside Ln, roughly 675ft from 116 Hillside Ln to 120 Hillside Ln. The ticket was almost marked white but when investigated, found only the hand holes located at 116 & 120 Hillside needed to be marked. The remainder of the ticket did not. Also, at the time of this report approx. 1424 hours, the work had yet to begin.</p>	<p>LAMBERTS CABLE SPLICING LLC: \$2,500.00 Section 5(16) 1st Offense \$1,000.00 Section 5(9) 1st Offense \$1,000.00 Section 5(17) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>LAMBERTS CABLE SPLICING LLC, a professional excavating company, was sent an email on 9/15/2025 asking about emergency ticket and pictures – due 10/15. On 9/17/2025, DPI Maki again asked why the emergency ticket was submitted and if any mechanical equipment was used. An email was received on 9/17/2025 stating that “One of my employees brought these inquiries to my attention today and I wanted to reach out to get you what you need on them, and was hoping you could clarify. My understanding so far is an AVR was submitted through PAOC due to an emergency one call being placed on one of our job sites. I wanted to clarify what the AVR was for? I've confirmed that we have no reports of any damages caused by us, the excavator, in relation to this ticket and site. PECO was field marked and close to our excavation but never in conflict with the dig itself. Reason for the emergency one call I can provide either via email, or AVR if you'd like. It was my understanding AVR's were for damages only. Method of digging was by hand with no mechanical equipment used directly for the excavation. Please let me know if you can clarify and I'm more than happy to get this sorted out. Anything you need from Lamberts I'm always willing to address or get to the appropriate party in the future. DPI Maki responded with an email on the same day explaining why an AVR is needed and asked for confirmation of a physical address. Lamberts is a professional excavating company.</p> <p>VERIZON is the project owner. They were not requested to submit an AVR.</p> <p>VIOLATIONS:</p> <p>LAMBERTS CABLE SPLICING is in violation of: Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or damaging a facility owner’s line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. DPI Maki requested that an AVR be submitted and explained why this is important. Section 5(9) – Emergency notification does not meet the requirements of “emergency” as defined in Section 1 – Excavator Ticket. Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within 30 days of the receipt of the request. On 9/17/2025 DPI Maki requested an AVR to be submitted and asked for a physical address to be confirmed, since the contact information had changed. This has not been addressed to date. Lamberts Cable Splicing LLC is a professional excavator. Recommendations: The penalties are applied. Excavator training is required.</p>	
57086	Facility Owner: PPL Contractor/Excavator: Columbia Water Company	<u>On 7/21/2025 1:40:00 PM at JAY LANE, WEST HEMPFIELD TWP, LANCASTER</u> The incident	PPL: \$6,500.00 Section 2(5)(i) Subsequent \$2,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>Project Owner: Columbia Water Company - Placeholder</p> <p>Designer: Columbia Water Company - Placeholder</p> <p>Other: Brightspeed</p> <p>Other: Comcast</p>	<p>occurred on 7/21/2025, at 1:40 PM, on Jay Lane, in West Hempfield Twp, Lancaster County.</p> <p>An electrical line owned by PPL was damaged. 30 Customers were affected for 1-6 hours</p> <p>PPL is the facility owner. Their Alleged Violation Report (AVR) states, “On July 21, 2025, at about 13:45, PPL Dispatch reported damage to an electric line near 398 Jay Drive caused by Columbia Water Company's excavation. PPL secured the site; no injuries occurred, but 30 customers lost power. The line will remain inactive until Columbia Water completes its work, after which repairs were made and no further action is needed. USIC will be held liable for the repair to the unmarked primary accordance with our contract.”</p> <p>Columbia Water Company is the excavator, designer, and project owner. Their AVR states, “While digging to install water line our crew hit an unmarked electric line within the dig area . One call was notified and USIC and PPL responded to the site.”</p> <p>Images show the site, excavation, equipment, and damage. No marks are visible in the vicinity of the damage.</p> <p>Ticket #20251890492 New – Excavation – Routine was entered on 7/8/25 at 0800 AM. A renotify was entered on 7/14/2025 at 1117 AM indicating Brightspeed, PPL and Comcast responses. A second renotify was entered on 7/16/2025 0750AM indicating Brightspeed did not respond. PPL and Comcast entered “Scheduled Date and Time by 7/14/2025” on 7/11/2025. They did not respond to the 1st renotify, and entered a final response of Field Marked on 7/16/2025 at 7:39AM. Brightspeed did not respond through PA One Call until they entered a final response of Field Marked on 7/16/2025 at 9:37 AM.</p> <p>Ticket # 20252030436 -000 New – Damage – Emergency had a response due date of 7/22/2025 at 9:49AM. A renotify was entered on this ticket on 7/24/2025 at 1:02PM. Comcast and PPL did not respond to either notification until 8/8/2025.</p> <p>Violations: Facility– PPL: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket #20251890492-000 Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Ticket #20251890492-001</p>	<p>Section 2(5)(v) 2nd Offense \$1,000.00</p> <p>Section 2(5)(v.1) 2nd Offense \$1,000.00</p> <p>Section 2(5)(vii) 2nd Offense \$1,500.00</p> <p>Section 2(5)(v.1) 2nd Offense \$1,000.00</p> <p>Brightspeed: \$3,500.00 Section 2(5)(v) Subsequent \$2,000.00</p> <p>Section 2(5)(v.1) 3rd Offense \$1,500.00</p> <p>Comcast: \$5,000.00 Section 2(5)(vii) 3rd Offense \$2,000.00</p> <p>Section 2(5)(v) Subsequent \$2,000.00</p> <p>Section 2(5)(v.1) 1st Offense \$500.00</p> <p>Section 2(5)(v.1) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket # 20252030436 -000</p> <p>Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Ticket # 20252030436 -001</p> <p>Recommendation: PUC Online Compliance Training is required.</p> <p>Facility (other) – Comcast:</p> <p>Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket # 20252030436 -000</p> <p>Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket #20251890492-000</p> <p>Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Ticket #20251890492-001</p> <p>Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Ticket # 20252030436 -001</p> <p>Recommendation: PUC Online Compliance Training is required.</p> <p>Facility (other) – Brightspeed:</p> <p>Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket #20251890492-000</p> <p>Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Ticket #20251890492-001</p> <p>Recommendation: PUC Online Compliance Training is required.</p>	
56891	<p>Facility Owner: PECO</p> <p>Contractor/Excavator: LOFTUS CONSTRUCTION INC</p> <p>Project Owner: MONTGOMERY COUNTY</p> <p>Designer: MICHAEL BAKER INTERNATIONAL</p>	<p><u>On 7/21/2025 2:30:00 PM at EASTON RD, ABINGTON TWP, MONTGOMERY</u> PECO accepts.</p> <p>*****</p> <p>The incident occurred on July 21st, 2025, on Easton Road, in Abington Township, Montgomery County.</p> <p>A gas line owned by PECO was damaged.</p> <p>PECO, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “LOFTUS CONSTRUCTION damaged a gas service for obligated ticket 20251972755. Gas service was miss marked. Site was marked by measurements from the gas records. Gas record measurements are incorrect. Marks are approximately 3 feet from where the gas service was damaged. Damage was due to a records issue.” Photos were submitted.</p> <p>Loftus Construction Inc. is the excavator. An AVR has not been filed as of 09/26/2025.</p> <p>Montgomery County is the project owner. An AVR has not been filed as of 09/26/2025.</p> <p>PECO’s AVR did not indicate that 911 was called.</p> <p>The submitted photos show where the gas line was marked in relation to where the damage occurred. The damage did not occur within the tolerance zone. PECO</p>	<p>PECO: \$2,000.00 Section 2(5)(i) Subsequent \$2,000.00</p> <p>LOFTUS CONSTRUCTION INC: \$2,000.00 Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>MONTGOMERY COUNTY: \$1,000.00 Section 6.1(7) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>noted in their AVR that the line was mismarked due to mapping.</p> <p>Violations:</p> <p>PECO- Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: The penalty is applied. PUC compliance training education was recently completed.</p> <p>Loftus Construction Inc. - Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Montgomery County - Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
56915	<p>Facility Owner: PEOPLES GAS COMPANY LLC</p> <p>Contractor/Excavator: GRIT INDUSTRY</p> <p>Project Owner: West Leechburg Borough</p> <p>Designer: BOVE ENGINEERING CO</p> <p>Designer: HRG INC</p> <p>Other: LUTTERMAN EXCAVATING, LLC</p>	<p><u>On 7/22/2025 8:30:00 AM at 1125 Gosser Street in front of the house, WEST LEECHBURG BORO, WESTMORELAND</u> Removed- PNG violation and penalty have been removed. See attachments *****</p> <p>The incident occurred on Tuesday, July 22, 2025, at 1125 Gosser Street, in West Leechburg Borough, Westmoreland County.</p> <p>Peoples Gas Company’s line was damaged.</p> <p>Peoples Gas stated in their Alleged Violation Report (AVR), Lutterman Excavating installed new mainline for West Leechburg Borough and Grit Industry (the subcontractor) was contracted (by Lutterman Excavating) to put the new service laterals in. While doing so Grit Industry struck one of our services that were marked correctly.</p> <p>HRG Inc, and West Leechburg Borough, stated in their AVR's, Grit Industry was digging near the tee in the main 8-inch sanitary sewer. The gas service for 1125 Gosser Street was painted on the road and also the grass showing the location of service. There was a piece of caution tape found that was 3-feet off the painted line. The crew hand dug and did not find the gas service at 4-foot depth. While curling the bucket they broke the gas service; it was marked on the ground, 911 was notified and the Fire Department came on site and Peoples Gas came and fixed the broken service line.</p>	<p>PEOPLES GAS COMPANY LLC: \$0.00</p> <p>GRIT INDUSTRY: \$1,500.00 Section 5(4) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>The provided photos show the damage and repair of the gas line.</p> <p>Grit Industry did not submit an AVR.</p> <p>Violations:</p> <p>*Peoples Gas Company is in violation of section: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: Penalty Applied</p> <p>*Grit Industry is in violation of sections: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: PUC Compliance Education Required and Penalties Applied</p>	
56866	<p>Facility Owner: Municipal Authority of Westmoreland County</p> <p>Contractor/Excavator: Roice Construction</p> <p>Project Owner: Max Construction</p> <p>Other: Verizon North</p>	<p><u>On 7/22/2025 11:08:00 AM at 10TH ST, CONEMAUGH TWP, INDIANA</u> Max Construction submitted a dispute. They have completed the required education. I have reduced the violation and penalty to a warning.</p> <p>Roice Construction submitted a dispute. They have completed the required education. I have reduced the violations and penalties to a warning.</p> <p>*****</p> <p>The incident occurred on July 22nd, 2025, at 11:08 AM, on 10th Street, in Conemaugh Township, Indiana County.</p> <p>A water line owned by Municipal Authority of Westmoreland County was damaged. No PA One Call ticket.</p> <p>Municipal Authority of Westmoreland County, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “Excavator, Roice Construction contacted the Municipal Authority of Westmoreland County (MAWC) at approximately 11:00AM on July 22, 2025 to notify MAWC of damage to its 8" water main. MAWC responded and observed that Roice was digging without a PA One Call ticket. MAWC made the necessary repair. Roice then placed PA One Call ticket 20252034110 at 3:55 PM on July 22, 2025 for this location.” Photos were submitted.</p> <p>Roice Construction is the excavator. An AVR has not been filed as of 09/16/2025.</p> <p>Max Construction is the project owner. An AVR has not been filed as of 09/16/2025.</p> <p>There was not a PA One ticket. The routine ticket 20252034110 was not placed until after damage occurred on 07/22/2025.</p>	<p>Roice Construction: \$0.00 Section 5(2.1) 1st Offense \$0.00</p> <p>Section 5(6)(i) 1st Offense \$0.00</p> <p>Section 5(16) 1st Offense \$0.00</p> <p>Max Construction: \$0.00 Section 6.1(7) 1st Offense \$0.00</p> <p>Verizon North: \$250.00 Section 2(4) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Preliminary Design ticket 20251760999 had a response due date of 07/10/2025. -Verizon North did not respond to this ticket.</p> <p>Violations:</p> <p>Roice Construction- - Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. - Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: This is a warning. PUC compliance training education was completed for this case.</p> <p>Max Construction – - Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Recommendation: This is a warning. PUC compliance training education was completed for this case.</p> <p>Verizon North - Section 2(4) – Failed to respond to designer’s request for information within 10 business days. Ticket 20251760999. Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
57080	<p>Facility Owner: UGI UTILITIES, INC. Contractor/Excavator: Steffan Enterprises, Inc. Project Owner: Homeowner</p>	<p><u>On 7/23/2025 7:30:00 AM at 432 W PINE ST, CLEARFIELD BORO, CLEARFIELD</u> The incident occurred on Wednesday, July 23, 2025, at 432 W. Pine Street, in Clearfield Borough, Clearfield County.</p> <p>UGI Utilities gas line was damaged.</p> <p>UGI stated in their Alleged Violation Report (AVR), Contractor, Steffen Enterprises Inc struck and damaged a correctly marked gas service while excavating for sewer lateral installation. The Contractor did not have his own One Call ticket. The Homeowner/Customer called in a ticket on the Contractor's behalf.</p> <p>On Thursday, September 18, 2025, emails were sent to Steffen Enterprises and to the Homeowner requesting AVR’s. Steffen Enterprises submitted their AVR on Sunday, 9/21/2025.</p> <p>Steffen Enterprises stated in their AVR, On July 23, 2025, I broke an underground gas line at 432 W. Pine Street. Before starting the broken sewer line project, the homeowner called a PA 1 call in and they came and marked the utility lines. I was onsite when they marked the utility lines. The gas line was marked and we were told it was 18-inches below grade. I uncovered the gas</p>	<p>Steffan Enterprises, Inc.: \$1,000.00 Section 5(23) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>line with a shovel to confirm that. It was located at 18 inches. I then removed a small amount of cover and dug down again with a shovel to find the gas line, which I did. I then went to remove another small amount of dirt and hit the gas line at 8 - 10 inches under the ground. All of this took place less than 4-feet from the home. I immediately shut off the excavator and called it in to UGI. They arrived shortly and installed a clamp on the broken line. I stopped all work until they said it was safe to continue. When UGI said it was safe to continue I excavated the broken sewer pipe that was below the gas line and repaired the damaged sewer line.</p> <p>20251970716- Routine ticket placed on 7/16/2025 at, type of work- repair sewer line, method of excavation- power equipment, place by Homeowner.</p> <p>Violations:</p> <p>*Steffen Enterprises Inc is in violation of sections: 5(23) – Excavator may not delegate their duty to submit a locate request to the One Call System to another person. The excavator shall have sole responsibility to submit each locate request to the One Call System. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: Penalties Applied with section 5(16) penalty reduced by 50% (\$1,000 to \$500). PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements.</p>	
56929	<p>Facility Owner: COMCAST</p> <p>Contractor/Excavator: MELE & MELE & SONS INC</p> <p>Project Owner: PITTSBURGH WATER</p> <p>Designer: JOHNSON MIRMIRAN & THOMPSON</p>	<p><u>On 7/23/2025 11:00:00 AM at 1345 BENNINGTON AVE, PITTSBURGH CITY, ALLEGHENY</u> The incident occurred on Wednesday, July 23, 2025, at 1345 Bennington Avenue, in Pittsburgh City, Allegheny County.</p> <p>Comcast line was damaged.</p> <p>Mele & Mele & Sons, Inc. stated in their Alleged Violation Report (AVR), that during the mainline excavation they struck a marked underground direct bury telecommunications wire. The Mele crew called 811 and Verizon responded at 12:00pm and did not claim line, stating it was a Comcast line. Comcast responded and arrived on site at 2:00pm. Comcast began repairing line by splicing and reconnecting, and the line was repaired by 3:30pm.</p> <p>Pittsburgh Water; the project owner and Johnson Mirmiran & Thompson (J M T); the designer, stated in their AVR's that during a mainline excavation Mele & Mele & Sons struck a marked underground direct bury telecommunications wire. Mele & Mele & Sons crew called 811 and Verizon responded at 12:00pm and did not claim line, stating it was a Comcast line. Comcast responded and arrived on site at 2:00pm. Comcast began repairing line by splicing and reconnecting, and the line was repaired by 3:30pm. Also, JMT stated that the lines are shown on the bid documents.</p>	<p>COMCAST: \$2,500.00 Section 2(10) Subsequent \$2,500.00</p> <p>MELE & MELE & SONS INC: \$1,000.00 Section 5(4) 2nd Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>The provided photos show the damage and repair of the Comcast line.</p> <p>Violations:</p> <p>*Mele & Mele & Sons, Inc is in violation of section: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: Penalty Applied</p> <p>*Comcast is in violation of section: 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: PUC Compliance Education Required and Penalty Applied</p>	
57305	<p>Facility Owner: Peoples Natural Gas Contractor/Excavator: Independent Enterprises Project Owner: Pittsburgh Water Designer: GAI Consultants, Inc.</p>	<p><u>On 7/23/2025 1:15:00 PM at SHADELAND AVE, PITTSBURGH CITY, ALLEGHENY</u> Peoples provided the AVR they submitted, in a timely manner, for this incident. 2(10) - Facility owner failed to submit an Alleged Violation Report is withdrawn. GAI provided documents that show information is on their plans. Violation withdrawn. ----- The incident occurred on 7/23/2025, at 1:15 PM, on Shadeland Ave, in Pittsburgh City, Allegheny County.</p> <p>A gas line owned by Peoples Gas was damaged. The facility was notified by a damage ticket.</p> <p>Peoples Gas is the facility owner. An Alleged Violation Report (AVR) has not been filed as of 09/19/2025.</p> <p>Independent Enterprises is the excavator. Their AVR states, “ The contractor was excavating to install waterline along Davis Ave when they ripped through a live unmarked Gas Service Line at 18 " Depth. At 1:20 PM 911 was called and at 1:23 PM the Fire department came to the work site. Peoples Gas was contacted by fire department and came to the site at 1:30 PM”.</p> <p>Images submitted show the site, excavation, and damage. No marks are seen within the tolerance zone of the damaged gas line.</p> <p>Pittsburgh Water & Sewer Authority is the project owner. Their AVR states the same information as Independent Enterprises AVR.</p> <p>G A I Consultants Inc is the designer. An AVR has not been filed as of 09/19/2025. The first Final Design ticket entered was on 3/12/24, and the last Final Design ticket entered as on 12/19/2024. Design documents do not list 811 contact information.</p>	<p>Peoples Natural Gas: \$2,000.00 Section 2(5)(i) Subsequent \$2,000.00</p> <p>GAI Consultants, Inc.: \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>This case is related to case 057007, and 057069 by tickets.</p> <p>Violations:</p> <p>Facility Owner– Peoples Gas: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: PUC Online Compliance Training is required.</p> <p>Designer - G A I Consultants Inc: Section 4(5) – Designer’s drawing does not include One Call’s toll-free number and the serial number of the ticket. Recommendation: PUC Online Compliance Training is required.</p>	
57123	<p>Facility Owner: Pittsburgh Water</p> <p>Contractor/Excavator: PEOPLES GAS COMPANY LLC</p> <p>Project Owner: PEOPLES GAS COMPANY LLC - SPACESAVER</p>	<p><u>On 7/24/2025 1:00:00 AM at 5123 BUTLER ST, PITTSBURGH CITY, ALLEGHENY</u> Pittsburgh Water disagreed and stated that they do not own the commercial lines. The violation of 2(5)(i) is withdrawn. *****</p> <p>The incident occurred on 7/24/2025 at 5123 BUTLER ST. in PITTSBURGH CITY, ALLEGHENY Co</p> <p>A water service line owned by Pittsburgh Water was damaged.</p> <p>PEOPLES GAS COMPANY LLC the project owner and excavator stated in their Alleged Violation Report (AVR) that Peoples Gas working on an emergency gas repair struck and damaged an unmarked water service line. Peoples Gas digging and hit an unmarked water service line. PWSA responded and made repairs.</p> <p>PITTSBURGH WATER the facility owner stated in their AVR that “Peoples Gas digging and hit unmarked water service line. Curb box was not visible. PWSA responded and made repairs”. Pictures were provided.</p> <p>VIOLATIONS Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. This is a subsequent offense. Recommendation: The penalties are applied. The recommended education has recently been completed.</p>	<p>Pittsburgh Water: \$0.00</p>
56989	<p>Facility Owner: PEOPLES GAS COMPANY</p> <p>Contractor/Excavator: PennDOT</p> <p>Project Owner: PennDOT - Placeholder</p>	<p><u>On 7/24/2025 8:39:00 AM at SR 1004, STONEBORO BORO, MERCER</u> The incident occurred on Thursday, July 24, 2025, on SR 1004, in Stoneboro Borough, Mercer County.</p> <p>Peoples Gas Company’s line was damaged.</p>	<p>PennDOT: \$2,000.00 Section 5(4) 2nd Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Peoples Gas stated in their Alleged Violation Report (AVR), Penn Dot was working to replace cross-pipe when they struck an accurately marked PNG 2” PLA ML. PNG Crews were called, and repairs were made. Peoples Gas provide photos of the damage and repaired line.</p> <p>PennDOT placed a Damage Emergency ticket, 20252050303, at 7:35am, with Remarks: Attention Peoples Gas the caller states the crew on site hit at gas line near the gas markings. The line was kinked. Please respond asap and contact Larry Turner at his cell above with any questions. Facility Type: natural gas- Peoples Gas Excavation Equipment: excavator Hazardous Release: NO</p> <p>PennDOT, the excavator and project owner, did not submit an AVR.</p> <p>Violations:</p> <p>*PennDOT is in violation of sections: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: PUC Compliance Education Required and Penalties Applied</p>	
57347	<p>Facility Owner: UGI UTILITIES INC Contractor/Excavator: Wassertech Engineering Limited Project Owner: Department of Military and Veteran Affairs</p>	<p><u>On 7/24/2025 10:10:00 AM at FISHER AVE, UNION TWP, LEBANON</u> The incident occurred on Thursday, July 24, 2025, on Fisher Avenue, in Union Township, Lebanon County.</p> <p>UGI Utilities gas line was damaged.</p> <p>UGI stated in their alleged violation report (AVR) that Wassertech Engineering Limited was digging a trench to install an electrical conduit with a mini excavator when they struck and damaged a correctly marked gas service. Excavation was within the tolerance zone of yellow marks. Branch gas service serving two buildings was marked accurately with yellow paint and yellow flags. UGI provided photos of the damaged gas line. Wassertech Engineering Limited did not submit an AVR.</p> <p>Violations:</p> <p>*Wassertech Engineering Limited is in violation of sections: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: PUC Compliance Education Required and Penalties Applied</p>	<p>Wassertech Engineering Limited: \$1,500.00 Section 5(4) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>
56983	<p>Facility Owner: PECO Contractor/Excavator: Utility Line Services</p>	<p><u>On 7/24/2025 10:18:00 AM at LANCASTER AVE, RADNOR TWP, DELAWARE</u> PECO accepts.</p>	<p>PECO: \$2,000.00 Section 2(5)(i) Subsequent \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>Project Owner: Aqua PA Designer: GILMORE AND ASSOCIATES INC Other: Verizon</p>	<p>*****</p> <p>The incident occurred on July 24th, 2025, at 10:18 AM, on Lancaster Avenue, in Radnor Township, Delaware County.</p> <p>A gas line owned by PECO was damaged. 911 was called.</p> <p>PECO, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, "ULS INSTALLING WATER MAIN FOR AQUA HIT A T STUB NOT ON PRINTS." Photos were submitted.</p> <p>Utility Line Services, the excavator, submitted an AVR. Their AVR states, "While the crew was trenching in the area of Lancaster Ave and St David's they damaged an unmarked 4" gas stub with a T on top." Photos were submitted.</p> <p>Aqua PA, the project owner, submitted an AVR. Their AVR states, "Aqua contractor Utility Line Services, while the crew was trenching in the area of Lancaster Ave and St David's they damaged an unmarked 4" gas stub with a T on top."</p> <p>The submitted photos show the damaged gas line was not marked.</p> <p>Routine ticket 20251960069 had a response due date of 07/017/2025. - Verizon did not respond to this ticket.</p> <p>Violations:</p> <p>PECO- - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: The penalty is applied. PUC compliance training education was completed recently.</p> <p>Verizon- - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket 20251960069. Recommendation: The penalty is applied. PUC compliance training education was completed recently.</p>	<p>Verizon: \$2,000.00 Section 2(5)(v) Subsequent \$2,000.00</p>
56949	<p>Facility Owner: Plymouth Township Montgomery County Contractor/Excavator: Aqua PA Project Owner: Aqua PA (Placeholder) Other: Comcast Other: Verizon PA LLC</p>	<p><u>On 7/24/2025 1:00:00 PM at CARLAND RD, PLYMOUTH TWP, MONTGOMERY</u> Comcast accepts.</p> <p>Plymouth Township Montgomery County submitted an untimely dispute. The dispute to the DPC was due by 11/13/2025. Their dispute was submitted 12/15/2025.</p> <p>*****</p> <p>The incident occurred on July 24th, 2025, at 1:00 PM, on Carland Road, in Plymouth Township, Montgomery County.</p> <p>A sewer line owned by Plymouth Township was damaged.</p>	<p>Plymouth Township Montgomery County: \$1,500.00 Section 2(5)(i) 1st Offense \$500.00</p> <p>Section 2(10) 1st Offense \$1,000.00</p> <p>Comcast: \$1,000.00 Section 2(5)(v) Subsequent \$1,000.00</p> <p>Verizon PA LLC: \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Plymouth Township is the facility owner. An Alleged Violation Report (AVR) has not been filed as of 09/18/2025.</p> <p>Aqua PA, the excavator and project owner, submitted two AVRs with photos.</p> <ul style="list-style-type: none"> - AVR2025JUL250028 states, "Hit unmarked sanitary sewer main while excavating water main for relocation." - AVR2025AUG010034 states, "Sewer main was mismarked. Sewer ran through corner of hole. Plymouth Twp had contractor make repairs. Working on the Carland Rd side of 1403 Ridge Pike". <p>The submitted photos show the damaged sewer main was not within the tolerance zone of the mark outs.</p> <p>Routine ticket 20251833992 had a response due date of 07/07/2025.</p> <ul style="list-style-type: none"> - Verizon did not respond until 07/23/2025. - Comcast responded late on 07/08/2025. <p>Violations:</p> <p>Plymouth Township-</p> <ul style="list-style-type: none"> - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. - Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Verizon-</p> <ul style="list-style-type: none"> - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket 20251833992. <p>Recommendation: The penalty is applied. PUC compliance training education was recently completed.</p> <p>Comcast-</p> <ul style="list-style-type: none"> - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20251833992. <p>Recommendation: The penalty is applied. PUC compliance training education was recently completed.</p>	<p>Section 2(5)(v) Subsequent \$2,000.00</p>
57006	<p>Facility Owner: National Fuel Gas Contractor/Excavator: E E Austin & Son Inc</p>	<p><u>On 7/25/2025 12:00:00 PM at 221 W 6th Street, ERIE CITY, ERIE</u> E E Austin & Son Inc disputed, stating they were not the excavator on site. They hired a subcontractor who they allowed to use their equipment. Additional information was submitted by E E Austin & Son Inc. Violation and penalty were withdrawn.</p> <p>*****</p> <p>The non-damage incident occurred on July 25th, 2025, at 12:00 PM, at 221 West 6th Street, in Erie City, Erie County.</p>	<p>E E Austin & Son Inc: \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Non-damage. Excavator digging without a PA One Call ticket.</p> <p>National Fuel Gas, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, "Excavator working without POCS ticket request and near National Fuel facilities. Please see attachments." Photos were submitted.</p> <p>E E Austin & Son Inc is the excavator. An AVR has not been filed as of 09/19/2025.</p> <p>The project owner is unknown.</p> <p>PA One Call stated that no tickets were found, but EE Austin does place one call notifications. The submitted photos show the ground has been excavated. Multiple pieces of excavation equipment can be seen in the photos.</p> <p>Violations:</p> <p>E E Austin & Son Inc - - Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. - Withdrawn.</p>	
57083	<p>Facility Owner: UGI Utilities, Inc. Contractor/Excavator: Linford Zimmerman Project Owner: HOMEOWNER</p>	<p><u>On 7/25/2025 1:55:00 PM at 11064 RT 287, WELLSBORO BORO, TIOGA</u> The incident occurred on 7/25/2025 at 11064 RT 287 in WELLSBORO BOROUGH in TIOGA Co.</p> <p>A gas line was damaged. No One call ticket was submitted.</p> <p>UGI Utilities, Inc the facility owner stated in their Alleged Violation Report (AVR) that Contractor struck and damaged an unmarked gas service line while installing fence with mechanized equipment (auger). Contractor did not notify One Call system prior to excavation. Pictures were provided.</p> <p>Linford Zimmerman the excavator did not submit an AVR.</p> <p>Homeowner did not submit an AVR.</p> <p>The routine ticket was placed after UGI came to fix the damage.</p> <p>VIOLATIONS Linford Zimmerman is in violation of: Section 5(2.1) - Began excavation work before the lawful start day. Ticket 20252063354 was submitted on 7/25/2025 to install a fence. The lawful start date is 7/30/2025. The ticket states hand digging. Pictures show a detached auger. UGI photos show the different colored dirt evenly distributed around the circle edge. Auger bit is in the attachment named auger. UGI had to come out because of the damage. In UGI's AVR mechanized equipment is stated as used.</p>	<p>Linford Zimmerman: \$2,000.00 Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>5(16) Excavator failed to submit an Alleged Violation Report 9AVR) within 30 days of striking a line. Recommendation: The penalties are applied. Education is required.</p>	
56980	<p>Facility Owner: Homeowner Contractor/Excavator: Mitchell Plumbing and Heating Other: Peoples Natural Gas</p>	<p><u>On 7/25/2025 11:30:00 PM at 818 Eisenhower Dr, MT LEBANON TWP, ALLEGHENY</u> The incident occurred on 7/25/2025 at 11:30 PM, on 818 Eisenhower Dr, in Mt Lebanon Twp, Allegheny County.</p> <p>A gas line owned by the homeowner at 818 Eisenhower Dr was damaged.</p> <p>Peoples Gas Company is a facility owner who was aware of this incident. Their Alleged Violation Report (AVR) states, "MITCHELL PLUMBING AND HEATING struck and damage a customer owned gas service line with visible evidence of facilities in the area. MITCHELL PLUMBING AND HEATING Did not place a One Call request." Images submitted show the site and damage location. Indication of mechanized equipment is shown. Peoples Gas lists a backhoe/trackhoe as the equipment used. No Tickets are found for this location by PA One Call.</p> <p>Mitchell Plumbing And Heating is the excavator. An AVR has not been filed as of 09/04/2025.</p> <p>Violations: Excavator - Mitchell Plumbing And Heating: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: PUC Online Compliance Training is required.</p>	<p>Mitchell Plumbing and Heating: \$2,250.00 Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>
57133	<p>Facility Owner: UGI UTILITIES INC Contractor/Excavator: LEEWARD CONSTRUCTION Project Owner: AQUA PENNSYLVANIA INC Designer: ENTECH ENGINEERING INC Other: Verizon PA LLC</p>	<p><u>On 7/29/2025 7:30:00 AM at 10TH ST, HONESDALE BORO, WAYNE</u> The incident occurred on Tuesday, July 29, 2025, at 10th Street, in Honesdale Borough, Wayne County.</p> <p>UGI Utilities gas line was damaged.</p> <p>UGI stated in their Alleged Violation Report (AVR), Excavator, Leeward Construction struck and damaged a correctly marked gas facility while digging in the tolerance zone with mechanized equipment.</p> <p>Leeward Construction and Aqua; the project owner, stated in their AVR’s, at approximately 8am, the crew was installing a water mainline on 10th Street, when the crew struck a marked gas service line for 306 Church Street. The operator was heeling material off the top of</p>	<p>LEEWARD CONSTRUCTION: \$500.00 Section 5(4) 1st Offense \$500.00</p> <p>Verizon PA LLC: \$2,000.00 Section 2(5)(viii) Subsequent \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>the excavation when the gas service line was struck and damaged.</p> <p>Entech Engineering stated in their AVR, the contractor, Leeward Construction hit a gas service line at 306 10th Street, while removing material with the heel of the bucket to accommodate the air knife to proceed with prudent measures. The heel of the bucket caught the gas service causing a leak in the service.</p> <p>Complex Project Meeting ticket, 20251622745, No Response from Verizon PA LLC.</p> <p>Violations:</p> <p>*Leeward Construction is in violation of section: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: PUC Compliance Education Required and Penalty Applied</p> <p>*Verizon PA LLC is in violation of section: 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project 20251622745 Recommendation: PUC Compliance Education Required and Penalty Applied</p>	
57289	<p>Facility Owner: VALLEY ENERGY INC Contractor/Excavator: STANLEY BLACKTOP Project Owner: Blue Spruce Trailer Park Other: ATHENS TOWNSHIP AUTHORITY Other: L STANLEY PAVING Other: STEPHENS ENTERPRISE Other: VERIZON</p>	<p><u>On 7/29/2025 8:45:00 AM at 248 BLUE SPRUCE LN, ATHENS TWP, BRADFORD</u> The incident occurred on 7/29/2025 on BLUE SPRUCE LN in Athens Township in Bradford Co.</p> <p>A gas line owned by Valley Energy Inc was damaged. 54 households were affected.</p> <p>STANLEY BLACKTOP stated in their Alleged Violation Report (AVR) that “Damage to utilities occurred due to unmarked underground line”. They add that the damage affected 11-50 customers. They added that “Area was marked in white paint and cleared by all on the dig ticket including valley Energy. A gas line was unmarked directly through the middle of the dig area. the locator was on site after the damage and claimed that he did not see the white marks. all other utilities had no problem finding and marking the area Valley energy was the only unmarked. The dig ticket indicated that valley energy marked and cleared the site. being that there were no marks the site was assumed to be cleared for digging. The line was damaged at the start of digging and resulted in a full day cost of down time to the project”. Pictures were not provided. 911 was not notified.</p> <p>On 9/18/2025 DPI sent an email with questions which is due by 10/18/2025. On 10/03/2025 DPI sent an email reminder asking questions and contact information. On 10/03/2025 Bill from Stanly Blacktop left a message. DPI Maki returned a call to Bill Stanley who works for Stanley Blacktop LLC. He also clarified that L Stanley Paving name has been updated to be Stanley Blacktop LLC. DPI Maki stated that she has information that STEVENS ENTERPRISES was digging when the line was hit. Bill stated that Stevens Enterprises was helping them out. DPI Maki stated that they would need their own ticket and Stanley said that they might just have</p>	<p>VALLEY ENERGY INC: \$750.00 Section 2(5)(i) 1st Offense \$750.00</p> <p>STANLEY BLACKTOP: \$2,000.00 Section 5(16) 1st Offense \$1,000.00</p> <p>Section 5(8) 1st Offense \$1,000.00</p> <p>ATHENS TOWNSHIP AUTHORITY: \$500.00 Section 2(5)(v) 1st Offense \$500.00</p> <p>VERIZON: \$1,500.00 Section 2(5)(vii) 2nd Offense \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>delivered equipment and that he really does not recall who was digging and what happened. Bill agreed to send an email with contact information of Stevens Enterprises, Blue Spruce Trainer Park and an explanation of who was digging when the line was damaged.</p> <p>On 10/03/2025 an email was received from William Stanley as a follow up to our telephone conversation. William stated that Stanley Blacktop 1 LLC and L Stanley Paving is the same company. He also stated that Stanley Blacktop is the company who called in the ticket and did the digging. Please note that the name on the ticket is L Stanley Paving. DPI Maki called the telephone number 570-500-9790 given by Stanley Blacktop for James Bender at Blue Spruce Mobile Home Park twice because the message received was that this number is not in service. On 10/06/2025 DPI Maki sent another email again asking for contact information for Blue Spruce Mobile Home Park and STEVENS ENTERPRISES, which was asked for in the original email and not provided. She also asked for an explanation of why no gas markings did not raise some concerns. Ticket 20251904821 shows that Valley Energy Inc was field marked and there is a gas meter in line with the whole with the damage.</p> <p>VALLEY ENERGY INC stated in their AVR that “On 7/29/2025, Stanley Blacktop was digging to installing a dry well in the front area of lot 248 in the Blue Spruce Trailer Court, Athens PA. While they were digging they struck Valley Energy's 2" Gas Main. Although the area in front of lot 248 was marked, the portion of the gas main that was struck was not marked. There are some odd factors with this hit line. One being the 811 ticket expired prior to excavation activity. Another is that the excavator that was digging is a contractor working for Stanley Blacktop, and did not have his own 811 ticket. They added that “The areas of excavation was completely under water at the time of the locate. The excavator indicated verbally that they would be digging in front of lot 248 between the cinder blocks. There was a white arrow indicating the area that the dry well was going to be installed. The excavation occurred outside of that area, it was not marked and therefore hit”. Pictures were provided. On 9/18/2025 DPI sent an email with questions which is due by 10/18/2025. On 10/03/2025 the information was received, and Stevens Enterprise was named as the excavator who was excavating at the time the gas line was damaged. There were no first responders that were seen by Valley Energy Inc.</p> <p>STEPHENS ENTERPRISE was mailed an AVR request letter on 10/06/2025. On 10/07/2025 a telephone number was provided for Stevens Enterprise. DPI called him and connected with Freeman Stephens who stated he was at the site delivering equipment for Stanley Blacktop, because Stanley Blacktop did not have the means to get the equipment to the site. Freeman stated that he did not digging. He also stated that the excavation area did not have markings showing that there was a gas line in the</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>area. He also mentioned that a person from Valley Energy had seen him there, but he was not excavating. DPI did ask if he would send an email with this information. Freeman said he would try but is very busy.</p> <p>Ticket 20251904821 was submitted by L Stanley Paving with a response due by 7/11/2025, to install a dry well. They state they are working where there is a huge puddle and state that the site is marked white. The work is being done for James Bender. Valley Energy Inc responded “filed marked” on 7/10/2025.</p> <p>Athens Township Authority did not respond “clear” until 7/19/2025.</p> <p>VIOLATIONS</p> <p>VALLEY ENERGY INC is in violation of: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. There are white markings in many of the pictures. Other facility owners marked the area where the damage occurred. Valley Energy did not mark out to this area as per their AVR and what is in the pictures. Over 50 households were affected. A Fine Factor of .5 has been calculated into the penalty as per the .59Bureau of Investigation and Enforcement Damage Prevention Section Fine Factor Determination Sheet. Recommendation: The penalty is applied. Education is required.</p> <p>STANLEY BLACKTOP is in violation of: Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or damaging a facility owner’s line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. AVR was filed late, after DPI Maki sent an email asking for an AVR. Section 5(8) – Excavator vacated worksite after causing damage that resulted in the escape of any flammable, toxic or corrosive gas or liquid. Both AVR’s listed that 911 was not called. Emergency ticket 20252100863 reads that caller advised to notify 911. On 10/07/2025 DPI Maki sent an email asking Stanley Blacktop if 911 was notified. There has been no response to date. Recommendation: The penalty is applied. Education is required.</p> <p>Athens Township Authority is in violation of: Section 2(5)(v) – Failed to respond to a routine One Call Ticket 20251904821, which was requested by L Stanley Paving on 7/09/2025 with a response due by 7/11/2025. Athens Township Authority did not respond “clear” until 7/19/2025. This is over a week. Recommendation: The penalty is applied. Education is required.</p> <p>Verizon is in violation of:</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(vii) – Failed to respond to an emergency notification 2025100863 as soon as practicable following notification. Emergency ticket 2025100863 was submitted by L Stanley Paving on 7/29/2025 at 9:00 a.m. Verizon did not respond “Clear” until 7/31/2025. Recommendation: The penalty is applied. The required education was recently completed.</p>	
57100	<p>Facility Owner: Comcast Contractor/Excavator: JR Contracting Project Owner: Pennsylvania American Water Company (PAWC) Other: First Energy - West Penn Power</p>	<p><u>On 7/29/2025 8:45:00 AM at 905 HURL DRIVE, SOUTH PARK TWP, ALLEGHENY</u> Incident occurred on July 29th, 2025, at 8:45am on 905 Hurl Drive, South Park Township, Allegheny County.</p> <p>A telecom line was damaged.</p> <p>JR Contracting's Alleged Violation Report (AVR) states, "JR Contracting, LLC completed and exercised due care and employed prudent excavation techniques. While working to renew the water service to 905 Hurl Drive, an UNMARKED Comcast Facility was struck by JR Contracting and damaged occurred to the UNMARKED Comcast facility in the front yard of 905 Hurl Drive. The facility was approximately 8 inches outside the paved surface of the road and was running parallel with the road. USIC locator Eric Hasis was nearby and responded immediately and confirmed that the damaged Comcast facility was NOT MARKED. JR Contracting had hydro-excavated in the area and located a marked gas main and electric lines approximately 7 feet from where the UNMARKED Comcast line was located. JR Contracting attempted to complete the excavation of the water service by means of hydro-excitation but was unable to hydro-excavate through solid rock. While prudently digging with an excavator in an area with no utility marks, JR Contracting struck and damaged this UNMARKED Comcast facility. JR Contracting Supervisor Sean Douglas contacted PA One Call to report the damage. Comcast repair technician Al Ferry arrived onsite at approximately 9:26am and made repairs to the facility."</p> <p>PAWC's AVR states, "JR crew while digging to install a water service hit and damage an unmarked Comcast line. Because this line was not marked for the initial/start of the project it was never vacuum excavated therefore unknown to the excavator."</p> <p>Images show the damaged line was not marked out. Pre-excavation photos also show that the line was unmarked, but the design documents show two telecom lines running parallel in front of the house where the line was damaged. Case is related to 55081 and 55851. No AVR has been submitted by Comcast as of 10/6/25.</p> <p>Violations:</p> <p>Comcast Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. PUC compliance education is required. 20251964139. PUC compliance education is required.</p>	<p>Comcast: \$4,500.00 Section 2(5)(i) Subsequent \$2,000.00</p> <p>Section 2(5)(v.2) 2nd Offense \$500.00</p> <p>Section 2(10) 3rd Offense \$2,000.00</p> <p>First Energy - West Penn Power: \$250.00 Section 2(5)(v.2) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. 20251964139. PUC compliance education is required. Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. 20252101065. PUC compliance education is required.</p> <p>West Penn Power Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. 20251964139. PUC compliance education is required.</p>	
57077	<p>Facility Owner: Peoples Gas Contractor/Excavator: Pennsylvania American Water Project Owner: Pennsylvania American Water (Placeholder) Other: Pittsburgh Water (PWSA)</p>	<p><u>On 7/29/2025 11:15:00 AM at EVAN DR, PITTSBURGH CITY, ALLEGHENY</u> Peoples Gas accepts</p> <p>Pennsylvania American Water disputed Section 5(4) and provided additional information. Withdrew 5(4) violation. They accepted Section 5(16).</p> <p>Pittsburgh Water (PWSA) disputed violation of 2(5)(v). There are two violations of 2(5)(v). They submitted additional information. 1 violation of 2(5)(v) was withdrawn and they accept the remaining 1 violation of 2(5)(v).</p> <p>*****</p> <p>The incident occurred on July 29th, 2025, at 11:15 AM, on Evan Drive, in Pittsburgh City, Allegheny County.</p> <p>A gas line owned by Peoples Gas was damaged. 911 was called.</p> <p>Peoples Gas, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “Pennsylvania American Water struck and damaged a Peoples Gas service line. Excavation was taking place within the tolerance zone with mechanized equipment causing the damage.”</p> <p>Pennsylvania American Water is the excavator and project owner. An AVR has not been filed as of 09/30/2025.</p> <p>The submitted photos show the gas lateral was not marked. The line was damaged within the tolerance zone of the marked main line, which was uncovered.</p> <p>Routine tickets 20251712200 and 20251712201 both had a response due date of 06/24/2025. Pittsburgh Water & Sewer Authority responded late to both tickets, on 06/25/2025.</p> <p>Violations:</p>	<p>Peoples Gas: \$500.00 Section 2(5)(i.1) 2nd Offense \$500.00</p> <p>Pennsylvania American Water: \$1,500.00 Section 5(16) 2nd Offense \$1,500.00</p> <p>Pittsburgh Water (PWSA): \$500.00 Section 2(5)(v) 2nd offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Pennsylvania American Water-</p> <ul style="list-style-type: none"> - Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. - Withdrawn. - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. <p>Recommendation: The penalty is applied. PUC compliance training education was recently completed.</p> <p>Peoples Gas-</p> <ul style="list-style-type: none"> - Section 2(5)(i.1) – Failed to locate an actually known facility’s point of connection to its facilities. <p>Recommendation: The penalty is applied. PUC compliance training education was recently completed.</p> <p>Pittsburgh Water & Sewer Authority</p> <ul style="list-style-type: none"> - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20251712200. - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20251712201. - Withdrawn <p>Recommendation: The penalty is applied. PUC compliance training education was recently completed.</p>	
57060	<p>Facility Owner: PEOPLES GAS COMPANY LLC</p> <p>Contractor/Excavator: GRIT INDUSTRY</p> <p>Project Owner: WEST LEECHBURG BORO</p> <p>Designer: BOVE ENGINEERING CO</p> <p>Designer: HRG INC</p> <p>Other: LUTTERMAN EXCAVATING, LLC</p>	<p><u>On 7/29/2025 11:45:00 AM at GOSSER STREET, WEST LEECHBURG BORO, WESTMORELAND</u> The incident occurred on Tuesday, July 29, 2025, on Gosse Street, in West Leechburg Borough, Westmoreland County.</p> <p>Peoples Gas Company’s line was damaged.</p> <p>Peoples Gas stated in their Alleged Violation Report (AVR), Grit Industry was digging over top of Peoples Gas service line, but they never spotted it. Then the Grit Industry crew ripped it out and bent it 3-feet back from where it was located.</p> <p>HRG Inc, and on the behalf of West Leechburg Borough, stated in their AVR that a 1-1/4" steel gas line was broken located near a curb box at 1119 Gosser Street, the gas line was struck at approximately 11:45am. The gas line was struck and pulled by an excavator as the operator was digging through gravel to trench down to a sanitary main. The Grit Industry operator immediately called the facility owner, Peoples Gas, and they arrived on site at approximately 12:30pm to plug the gas leak, the gas pipe was shut off at 2 pm. Initially it appeared as if the gas line was curved and approximately 2-feet from the surface markings. However, it also appeared to have been pulled by the excavator, so it is difficult to tell whether the locator mark was not marked correctly or if the excavator pulled it away.</p> <p>The provided photos show the damage and repair of the gas line.</p> <p>Grit Industry, the subcontractor, was hired by Lutterman Excavating to install sewer laterals, as noted in the</p>	<p>GRIT INDUSTRY: \$2,500.00 Section 5(4) 1st Offense \$500.00</p> <p>Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Routine ticket, 20251922734. Grit Industry did not submit an AVR.</p> <p>Violations:</p> <p>Grit Industry is in violation of sections: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: PUC Compliance Education Required and Penalties Applied</p>	
57025	<p>Facility Owner: Aqua PA Contractor/Excavator: Melcar Project Owner: PECO Other: CARR AND DUFF Other: Comcast Other: East Goshen Twp/East Goshen Muni Auth Other: Verizon</p>	<p><u>On 7/29/2025 1:04:00 PM at 1515 ALISON DR, EAST GOSHEN TWP, CHESTER</u> PECO accepts.</p> <p>East Goshen Twp/East Goshen Muni Auth is no longer disputing and accepts.</p> <p>*****</p> <p>The incident occurred on July 29th, 2025, at 1:04 PM, at 1515 Alison Drive, in East Goshen Township, Chester County.</p> <p>A water line owned by Aqua PA was damaged.</p> <p>Aqua PA, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “Excavator hit unmarked water service at 1515 Alison Dr. Water service was marked out according to plans but no record existed for the 2nd unmarked water service which turned out to be the active line. Line that was marked was a run to curb.” Photos were submitted.</p> <p>Melcar, the excavator, submitted an AVR. Their AVR states, “On 7/29/25 our crew was installing conduit for underground cable along Alison Dr. After all marked utilities were identified we began to drill. At approximately 1pm the crew was drilling in front of 1515 Alison Dr when they began to see water coming out of the ground. We stopped immediately and notified our oversite and the office. PA-1 was called to report the damage as well as Aqua. It was determined that Aqua marked the old inactive line to the property and not the new active line that was approximately 13ft away.” Photos were submitted.</p> <p>PECO is the project owner. An AVR has not been filed as of 10/14/2025.</p> <p>CARR AND DUFF submitted an AVR and indicated they were representing Melcar. Their AVR did not include a summary of the event. Photos were submitted.</p> <p>Routine ticket 20251974552- Version 000 had a response due date of 07/18/2025. - Verizon did not respond. - Comcast did not respond.</p>	<p>Aqua PA: \$1,000.00 Section 2(5)(i) 2nd Offense \$1,000.00</p> <p>PECO: \$2,000.00 Section 6.1(7) 3rd Offense \$2,000.00</p> <p>Comcast: \$2,500.00 Section 2(5)(v) Subsequent \$2,000.00</p> <p>Section 2(5)(v.1) 1st Offense \$500.00</p> <p>East Goshen Twp/East Goshen Muni Auth: \$500.00 Section 2(5)(v) 1st Offense \$250.00</p> <p>Section 2(5)(v) 1st Offense \$250.00</p> <p>Verizon: \$7,500.00 Section 2(5)(v) Subsequent \$2,000.00</p> <p>Section 2(5)(v.1) 2nd Offense \$1,000.00</p> <p>Section 2(5)(v) Subsequent \$2,000.00</p> <p>Section 2(5)(vii) Subsequent \$2,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>- East Goshen Twp/East Goshen Muni Auth responded 07/21/2025.</p> <p>Insufficient 20251974552- Version 001 had a response due date of 07/21/2025, 2 hours after request.</p> <p>- Verizon did not respond.</p> <p>- Comcast responded on 07/23/2025.</p> <p>Routine ticket 20252094184 had a response due date of 07/30/2025.</p> <p>- Verizon responded 08/13/2025.</p> <p>- East Goshen Twp/East Goshen Muni Auth responded 07/31/25.</p> <p>Emergency ticket 20252102866 had a response due date of 07/29/2025.</p> <p>- Verizon responded 08/06/25.</p> <p>Violations:</p> <p>Aqua PA-</p> <p>- Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>PECO-</p> <p>- Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Recommendation: The penalty is applied. PUC compliance training education was recently completed.</p> <p>Verizon-</p> <p>- Section 2(5)(v) – Failed to respond to a routine One Call ticket. Routine ticket 20251974552- Version 000.</p> <p>- Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Insufficient 20251974552- Version 001.</p> <p>- Section 2(5)(v) – Failed to respond to a routine One Call ticket. Routine ticket 20252094184.</p> <p>- Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Emergency ticket 20252102866. Recommendation: The penalty is applied. PUC compliance training education was recently completed.</p> <p>Comcast-</p> <p>- Section 2(5)(v) – Failed to respond to a routine One Call ticket. Routine ticket 20251974552- Version 000.</p> <p>- Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Insufficient 20251974552- Version 001. Recommendation: The penalty is applied. PUC compliance training education was recently completed.</p> <p>East Goshen Twp/East Goshen Muni Auth-</p> <p>- Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Routine ticket 20251974552- Version 000.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>- Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Routine ticket 20252094184.</p> <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
57826	<p>Facility Owner: Peoples Natural Gas</p> <p>Contractor/Excavator: Frankie's Hauling and Excavating</p> <p>Project Owner: Boswell Borough</p>	<p><u>On 7/29/2025 3:57:00 PM at 400 center st, BOSWELL BORO, SOMERSET</u> Boswell Borough disputed stating that the Borough did not engage the contractor. They blamed the Redevelopment Authority who has already blamed Boswell. We have no proof that Boswell is the true project owner, and their violation and penalty was removed during stakeholder review.</p> <p>*****</p> <p>The incident occurred on 7/29/2025 at 400 Center St. in Boswell Borough in Somerset County.</p> <p>A gas meter set was damaged. No Demolition ticket was submitted.</p> <p>PEOPLES GAS COMPANY LLC the facility owner stated in their Alleged Violation Report (AVR) that “Frankies hauling and excavating was demolishing a building at 400 center st Boswell when they hit the meterset. Contractor did not put in a demo ticket. This was an above ground facility. Contractor did not have a one-call. DEMO TICKET”. 911 was not notified. Pictures were submitted. On 11/13/2025, the last day of stakeholder review, Steve Spokane from the Somerset County Redevelopment Authority called to say that they paid for the demolition and hired the excavator, but that Boswell Borough owns the property and requested the demolition funding from the Redevelopment Authority. See comments for more info.</p> <p>Franks Hauling and Excavating did not submit an AVR as of 9/18/2025.</p> <p>VIOLATIONS:</p> <p>Franks Hauling and Excavating is in violation of: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or damaging a facility owner’s line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: The penalties are applied. Education is required.</p> <p>Boswell Borough is in violation of: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike or damaging a facility owner’s line during excavation or demolition work activities or if a project owner believes a violation of this act has been committed in association or demolition. Recommendation: The penalty is applied. Education is required.</p>	<p>Frankie's Hauling and Excavating: \$2,000.00</p> <p>Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>Boswell Borough: \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
57064	<p>Facility Owner: Peoples Gas Company Contractor/Excavator: PITTSBURGH WATER</p>	<p><u>On 7/30/2025 2:15:00 AM at 2612 STELLA ST, PITTSBURGH CITY, ALLEGHENY</u> Incident occurred on July 30th, 2025, at 2:15am at 2615 Stella Street, Pittsburgh City, Allegheny County.</p> <p>A gas line was damaged.</p> <p>Peoples Gas Company's Alleged Violation Report (AVR) states, "Pittsburgh Water and Sewer working on an emergency ticket struck and damaged a Peoples Gas service. The service line was marked via records and those records did not show that the line had an offset."</p> <p>Pittsburgh Water's AVR states, "PWSA digging and hit mismarked gas main."</p> <p>AVR from Peoples states that 911 was not notified. AVR from PWSA says 911 was notified. DPI emailed both stakeholders to see if and at what time 911 was notified.</p> <p>Peoples emailed back about 911 and stated, "The internal damage report indicates 911 was not called. We have no record of 911 being called. PWSA's dispatch notified PNG's Operations Center by phone of the damage. Upon arrival by the first responder, there was no presence of 911 personnel onsite, per the internal damage report. There was a release of gas, and PWSA's crew applied the duct tape to the facility as shown on the damage picture. "</p> <p>Email from Pittsburgh Water states, "911 was called around 5:50am." The damage occurred at 2:15am. 911 was called 3 hours and 35 minutes after the damage according to Pittsburgh Water.</p> <p>Images show that the line was damaged outside the tolerance zone.</p> <p>Violations:</p> <p>Peoples Gas Company Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. 20252104749.</p> <p>Pittsburgh Water Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid. PUC compliance education is required.</p>	<p>Peoples Gas Company: \$500.00 Section 2(5)(i) 1st Offense \$500.00</p> <p>PITTSBURGH WATER: \$1,500.00 Section 5(8) 2nd Offense \$1,500.00</p>
57109	<p>Facility Owner: Peoples Gas Company Project Owner: Pennsylvania American Water Company (PAWC) Other: ALEX E PARIS CONTRACTING COMPANY</p>	<p><u>On 7/30/2025 8:30:00 AM at 6824 RIDGEVUE DR, SOUTH PARK TWP, ALLEGHENY</u> Incident occurred on July 30th, 2025, at 8:30am on 6824 Ridgeway Drive, South Park Township, Allegheny County.</p> <p>A gas line was damaged.</p> <p>Peoples Gas Company's Alleged Violation Report (AVR) states, "ON 7/30/25 ALEX PARIS CONTRACTING WORKING FOR PA AMERICAN</p>	<p>Peoples Gas Company: \$1,500.00 Section 2(5)(i) 3rd Offense \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>WATER, INSTALLING WATER SERVICE LINES STRUCK PNG GAS SERVICE LINE. ALEX PARIS NOTIFIED 911 AND PNG. PNG CREWS ARRIVED ONSITE FOR REPAIRS."</p> <p>ALEX E PARIS CONTRACTING COMPANY's AVR states, "Excavator struck mismarked gas service at 6824 Ridgevue Dr. Paint marking was straight lined and service veered out of tolerance zone into lay path of water service. Ben Muir from Peoples Gas was on location and verified that it was approximately 30" off the mark. 911 was notified. Broughton and Library Fire responded."</p> <p>PAWC's AVR states, "Paris crew while digging hit and damaged a People's Gas service line that was straight lined but was on an angle and came into the ditch where they were digging. According to the Paris crew the line was approximately 30" off of the mark where it was hit."</p> <p>Images show that the line bent away from the straight-line mark was outside the tolerance zone.</p> <p>Case is related to 55787.</p> <p>Violation:</p> <p>Peoples Gas Company Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. 20251911110</p>	
57271	<p>Facility Owner: Citizens Fiber</p> <p>Contractor/Excavator: Municipal Authority of Westmoreland County</p> <p>Project Owner: Municipal Authority of Westmoreland County (Placeholder)</p> <p>Other: UNITY TOWNSHIP</p> <p>Other: Verizon</p>	<p><u>On 7/30/2025 10:00:00 AM at VALLEY GREEN RD, HEMPFIELD TWP, WESTMORELAND</u> The incident occurred on July 30th, 2025, at 10:00 AM, on Valley Green Road, in Hempfield Township, Westmoreland County.</p> <p>A line owned by Citizens Fiber was damaged.</p> <p>Citizens Fiber is the facility owner. Alleged Violation Report (AVR) has not been filed as of 10/07/2025.</p> <p>Municipal Authority of Westmoreland County, the excavator and project owner, submitted an AVR. Their AVR states, "Project Owner and Excavator, Municipal Authority of Westmoreland County (MAWC) was digging to install a new water service for two homes in the new Valley Green Plan. Due to the number of utilities in the area of excavation, MAWC used a vac truck to locate marked lines. The MAWC backhoe was cleaning out ditch line and caught a section of unmarked cable line inserted in conduit that was looped and was 3' away from the closest marks. 811 was notified and Citizens Fiber repaired the damaged conduit." Photos were submitted.</p> <p>The submitted photos show there were no markings in the tolerance zone to mark the damaged line.</p>	<p>Citizens Fiber: \$1,500.00 Section 2(5)(i) 1st Offense \$500.00</p> <p>Section 2(10) 1st Offense \$1,000.00</p> <p>UNITY TOWNSHIP: \$1,000.00 Section 2(5)(vii) 1st Offense \$1,000.00</p> <p>Verizon: \$1,000.00 Section 2(5)(v) Subsequent \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Routine ticket 20251980453 had a response due date of 07/21/2025. - Verizon responded on 07/22/2025.</p> <p>Emergency ticket 20252111943 had a response due date of 07/30/2025. - UNITY TOWNSHIP responded 08/05/2025.</p> <p>Violations:</p> <p>Citizens Fiber-</p> <ul style="list-style-type: none"> - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. - Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Verizon-</p> <ul style="list-style-type: none"> - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20251980453. <p>Recommendation: The penalty is applied. PUC compliance training education was recently completed.</p> <p>UNITY TOWNSHIP-</p> <ul style="list-style-type: none"> - Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Emergency ticket 20252111943. <p>Recommendation: The penalty is applied. PUC compliance training education was recently completed.</p>	
57069	<p>Facility Owner: Peoples Natural Gas Contractor/Excavator: Independent Enterprises Inc Project Owner: Pittsburgh Water Designer: G A I Consultants</p>	<p><u>On 7/30/2025 11:11:00 AM at MCCLURE AVE, PITTSBURGH CITY, ALLEGHENY</u> PNG provided information on ticket response - penalty reduced from \$500 to a warning of \$0. PNG accepts violations and penalties. ***** The incident occurred on 7/30/2025, at 11:17 AM, on McClure Ave, in Pittsburgh City, Allegheny County.</p> <p>A gas line owned by Peoples Gas was damaged. 911 was contacted.</p> <p>Peoples Gas is the facility owner. Their Alleged Violation Report (AVR) states, “On 7/30/2025, Independent Enterprises struck a mismarked PNG SL (main to curb). PNG PL SL mismarked by 72 inches.”</p> <p>Independent Enterprises is the excavator. Their AVR states, “The contractor was placing new water main along McClure avenue when they ripped out a miss marked gas line going to 3544 McClure Ave. At 11:10 AM the contractor immediately called 911 and the fire department arrived at the site at 11:15 AM. The fire department immediately called People's Gas. People's</p>	<p>Peoples Natural Gas: \$2,000.00 Section 2(5)(i) Subsequent \$2,000.00</p> <p>Section 2(5)(v) 2nd offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Gas arrived at the work site at 11:35 a.m. Once people's gas came to the work site, they determined that an excavation crew was required to repair the gas line. After excavating the road and making an initial gas line repair the crew was finding a gas leak. The gas line repair crew started digging up the sidewalk area where the initial water line verification was done. The gas company ran a new gas line curb stop and box but did not hook up the line to the home because the private side of the gas line is in poor condition.”</p> <p>Pittsburgh Water & Sewer Authority is the project owner. Their AVR states the same information as Independent Enterprises.</p> <p>G A I CONSULTANTS INC is the designer. An AVR has not been filed as of 09/16/2025.</p> <p>Images submitted show the site, excavation, damage, and marks. A hit kit is used to show the line was not within 18” of the yellow marks, and that the damage occurred roughly 6 feet from the mark.</p> <p>Ticket #20251750594 New – Excavation – Routine had a response due date of 6/26/2025. Peoples Gas responded Field Marked on 7/1/2025.</p> <p>This case is related to case #057007 by design tickets.</p> <p>Violations:</p> <p>Facility Owner- Peoples Natural Gas: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket #20251750594 Recommendation: PUC Online Compliance Training is required.</p>	
57063	<p>Facility Owner: Peoples Natural Gas Contractor/Excavator: H E T CORPORATION Project Owner: BLACKTHORNE INVESTORS Other: Comcast Other: West Penn Power / First Energy Other: Windstream</p>	<p><u>On 7/30/2025 11:48:00 AM at COUNTRY CLUB DR, PENN TWP, WESTMORELAND</u> West Penn Power / First Energy accepts.</p> <p>Comcast accepts.</p> <p>Windstream accepts.</p> <p>***** The incident occurred on July 30th, 2025, at 11:48 AM, on Country Club Drive, in Penn Township, Westmoreland County.</p> <p>A gas line owned by Peoples Natural Gas was damaged.</p> <p>Peoples Natural Gas, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “H E T Corporation was digging to replace storm sewer when they struck a 1" plastic service at 1012 country club rd in Jeanette. This service was marked correctly. PNG crews fixed the line.” Photos were submitted.</p>	<p>H E T CORPORATION: \$2,500.00 Section 5(4) 1st Offense \$500.00</p> <p>Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>BLACKTHORNE INVESTORS: \$1,000.00 Section 6.1(7) 1st Offense \$1,000.00</p> <p>Comcast: \$2,000.00 Section 2(5)(v) Subsequent \$2,000.00</p> <p>West Penn Power / First</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Peoples Gas did not indicate in their AVR that 911 was called.</p> <p>H E T Corporation is the excavator. An AVR has not been filed as of 09/25/2025.</p> <p>Blackthorne Investors is the project owner. An AVR has not been filed as of 09/25/2025.</p> <p>The submitted photos show a yellow flag. The damage occurred within the tolerance zone of the flag. Peoples Gas' AVR stated they marked their lines using paint and flags.</p> <p>Routine ticket 20251891439 had a response due date of 07/13/2025.</p> <ul style="list-style-type: none"> - Comcast did not respond to this ticket. - Windstream did not reply until 07/25/2025. - West Penn Power did not respond to this ticket. <p>Violations:</p> <p>H E T Corporation-</p> <ul style="list-style-type: none"> - Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. - Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Blackthorne Investors-</p> <ul style="list-style-type: none"> - Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Comcast-</p> <ul style="list-style-type: none"> - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket 20251891439. <p>Recommendation: The penalty is applied. PUC compliance training education was recently completed.</p> <p>Windstream-</p> <ul style="list-style-type: none"> - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket 20251891439. <p>Recommendation: The penalty is applied. PUC compliance training education was recently completed.</p> <p>West Penn Power</p> <ul style="list-style-type: none"> - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket 20251891439. <p>Recommendation: The penalty is applied. PUC compliance training education was recently completed.</p>	<p>Energy: \$500.00 Section 2(5)(v) 1st Offense \$500.00</p> <p>Windstream: \$500.00 Section 2(5)(v) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
57174	<p>Facility Owner: Peoples Gas Company Contractor/Excavator: First Energy - West Penn Power Project Owner: West Penn Power Placeholder</p>	<p><u>On 7/31/2025 9:44:00 AM at 1856 MOREY RD, DEEMSTON BORO, WASHINGTON</u> Incident occurred on July 31st, 2025, at 9:44am on 1856 Morey Road, Deemstown Boro, Washington County.</p> <p>Peoples Gas Company's Alleged Violation Report (AVR) states, "ON 7/31/25 WPP AUGERING TO INSTALL NEW POLE STRUCK MARKED PNG GAS MAIN LINE. 1 HOUSE WAS EVACUATED FOR APPROX 2 HOURS AND 15 MINUTES. WPP NOTIFIED 911 AND PNG. PNG ARRIVED ONSITE AND SHUT DOWN MAIN LINE CAUSING 11 CUSTOMER OUTAGE. PNG CREWS MADE REPAIRS AND TURNED CUSTOMERS BACK ON."</p> <p>Images show that the line was damaged within the tolerance zone with an auger. No AVR has been submitted by First Energy - West Penn Power as of 10/8/2025. Auger was placed within the tolerance zone to dig.</p> <p>Education letter if applied states those involved and or their replacement must attend education.</p> <p>Violations:</p> <p>First Energy - West Penn Power Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. PUC compliance education is required for the excavators onsite of this dig. Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. PUC compliance education is required for the excavators onsite of this dig. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required for the excavators onsite of this dig.</p>	<p>First Energy - West Penn Power: \$2,250.00 Section 5(4) 2nd Offense \$1,000.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>
57085	<p>Facility Owner: PEOPLES GAS COMPANY Contractor/Excavator: HAMPTON TOWNSHIP Project Owner: HAMPTON TOWNSHIP</p>	<p><u>On 7/31/2025 10:54:00 AM at RIDGEWAY DR, HAMPTON TWP, ALLEGHENY</u> The incident occurred on Thursday, July 31, 2025, at 3842 Ridgeway Drive, in Hampton Township, Allegheny County.</p> <p>Peoples Gas Company’s line was damaged.</p> <p>Peoples Gas stated in their Alleged Violation Report (AVR), Hampton Township struck a mismarked Peoples Gas PLA SL main to the curb. Peoples Gas mismarked it by 24-inches.</p> <p>Peoples Gas provided photos of the damaged, mismarked line.</p> <p>Peoples Gas AVR does not mention that 911 was called. Hampton Township placed a Damage Emergency ticket, 20252120996, with Remarks: Facility Type: natural gas- Peoples Gas, Excavation Equipment: excavator, Hazardous Release: Yes, Caller Advised to Notify 911.</p>	<p>PEOPLES GAS COMPANY: \$2,000.00 Section 2(5)(i) Subsequent \$2,000.00</p> <p>HAMPTON TOWNSHIP: \$2,000.00 Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Routine ticket, 20252043491, placed by Hampton Township to install a storm sewer and work for Hampton Township. Hampton Township did submit an AVR.</p> <p>Violations:</p> <p>*Peoples Gas Company is in violation of section: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: Penalty Applied</p> <p>*Hampton Township is in violation of sections: 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: PUC Compliance Education Required and Penalties Applied</p>	
57243	<p>Facility Owner: Comcast Contractor/Excavator: Underground Communications Technologies Project Owner: Lamberts Cable Splicing Other: Verizon</p>	<p><u>On 7/31/2025 1:00:00 PM at MEADOWBROOK DR, ABINGTON TWP, MONTGOMERY</u> The incident occurred on July 31st, 2025, at 1:00 PM, on Meadowbrook Drive, In Abington Township, Montgomery County.</p> <p>A cable line owned by Comcast was damaged.</p> <p>Comcast is the facility owner. An Alleged Violation Report (AVR) has not been filed as of 10/09/2025.</p> <p>Underground Communications Technologies, the excavator, submitted an AVR. Their AVR states, “On 7/31 at approximately 1PM, our excavating crew found an unmarked fiber optic main line in a test hole while preparing to bore a span of conduit in front of building #26. Immediately after which, Comcast showed up to the work site. The same line they had just found was damaged on a previous span that was just completed, somewhere under the driveway entrance. Utiliquest, who was responsible for marking Comcast on this project, only marked the existing coax/copper lines underground, and never marked any of the newer fiber optics which were also present on site. After calling 811 and reporting the damage, our entire project was put in for remarks which has resulted in 3 days of downtime.”</p> <p>Lamberts Cable Splicing is the project owner. An AVR has not been filed as of 10/09/2025.</p> <p>The submitted photos show the damaged line was not marked. There were no orange marks/ flags near the damage location.</p> <p>Routine ticket 20251910406 had a response due date of 07/17/2025. - Verizon did not respond until 07/28/2025. - Comcast did not respond until 07/22/2025.</p> <p>Emergency ticket 20252122512 had a response due date of 07/31/2025.</p>	<p>Comcast: \$6,000.00 Section 2(5)(i) Subsequent \$2,000.00</p> <p>Section 2(10) 3rd Offense \$2,000.00</p> <p>Section 2(5)(v) Subsequent \$2,000.00</p> <p>Lamberts Cable Splicing: \$1,000.00 Section 6.1(7) 1st Offense \$1,000.00</p> <p>Verizon: \$3,500.00 Section 2(5)(v) Subsequent \$1,000.00</p> <p>Section 2(5)(vii) Subsequent \$2,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>- Verizon did not respond until 08/13/2025.</p> <p>This case is related to case 058409.</p> <p>Violations:</p> <p>Comcast-</p> <ul style="list-style-type: none"> - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. - Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket 20251910406. <p>Recommendation: The penalty is applied. PUC compliance training education was recently completed.</p> <p>Lamberts Cable Splicing-</p> <ul style="list-style-type: none"> - Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Verizon –</p> <ul style="list-style-type: none"> - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20251910406. - Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket 20252122512. <p>Recommendation: The penalty is applied. PUC compliance training education was recently completed.</p>	
57105	<p>Facility Owner: PHILADELPHIA GAS WORKS Contractor/Excavator: GENERAL ASPHALT PAVING Project Owner: Verizon</p>	<p><u>On 8/1/2025 6:04:00 AM at W CHELTEN AVE, PHILADELPHIA CITY, PHILADELPHIA</u> General Asphalt Paving accepts.</p> <p>*****</p> <p>The non-damage incident occurred on 08/01/2025, on West Cheltenham Avenue, in Philadelphia City, Philadelphia County.</p> <p>Emergency tickets were requested for non-emergency work.</p> <p>Philadelphia Gas Works, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “This is to install a 4" conduit for Verizon. This is planned work, not an emergency. PA Act 287 of 1974, as amended defines an Emergency as: "...a sudden or unforeseen occurrence involving a clear and immediate danger to life, property, and the environment, including, but not limited to, serious breaks or defects in a facility owner's lines”</p> <p>General Asphalt Paving is the excavator. An AVR has not been filed as of 10/01/2025.</p>	<p>GENERAL ASPHALT PAVING: \$500.00 Section 5(22) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Verizon is the project owner. An AVR has not been filed as of 10/01/2025.</p> <p>Both emergency tickets list the type of work as, "PLACING 4IN CONDUIT". This is not considered an emergency.</p> <p>"Emergency" means a sudden or unforeseen occurrence involving a clear and immediate danger to life, property or the environment, including, but not limited to, serious breaks or defects in a facility owner's lines.</p> <p>Both emergency tickets were requested at the same time, for the same location. A second ticket was generated due to different wards being listed on the tickets. (Wards 59 / 12)</p> <p>Violations:</p> <p>General Asphalt Paving- - Section 5(22) – Excavator provided a misrepresentation of an emergency excavation, subject to an administrative penalty imposed under section 7(10). Emergency tickets 20252130048 and 20252130049. Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
57142	<p>Facility Owner: PHILADELPHIA GAS WORKS Contractor/Excavator: BM CONSULTING SERVICE INC Project Owner: Finch Development</p>	<p><u>On 8/1/2025 7:21:00 AM at 2132 N 10TH ST, PHILADELPHIA CITY, PHILADELPHIA</u> This non-damage incident occurred on August 1st, 2025, at 7:21am on 2132 North 10th Street, Philadelphia City, Philadelphia County.</p> <p>A non-valid emergency ticket was placed.</p> <p>Philadelphia Gas Works' Alleged Violation Report states, "This is to install a fire suppression system in a new building. This is planned work and a fake planned emergency. PA Act 287 of 1974, as amended, defines an Emergency as:"... a sudden or unforeseen occurrence involving a clear and immediate danger to life, property, and the environment, including, but not limited to, serious breaks or defects in a facility owner's lines"</p> <p>Emergency ticket 20252130165 placed by BM Consulting Service Inc states, "Type INSTL FIRE SUPPRESSION SVC Depth 5FT Extent 4FT X 15FT Main Method DIGGING Excavation Equipment BH." Finch Development is the project owner of this new rental apartment building and BM Consulting was hired to install a new line. This does not meet the definition of an emergency ticket under Act 127 of 2024.</p> <p>DPI spoke with Sandy who said they were out there to inspect a leak and install a new svc if necessary. Asked for additional documentation from Sandy to support that claim. Gave her the damage prevention email along with mine to CC with new documents.</p>	<p>BM CONSULTING SERVICE INC: \$2,750.00 Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>Section 5(22) 1st Offense \$500.00</p> <p>Finch Development: \$1,000.00 Section 6.1(7) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>DPI sent an AVR request letter to BM Consulting and Finch Development. BM Consulting's AVR was submitted on 10/17/25.</p> <p>BM Consulting's AVR states, "Received notice there was a water leak on fire suppression service at 2132 N 10th St. Once onsite there was no leak detected." Email with a handwritten work order that states the same.</p> <p>Date stamped images from PGW show that the fire suppression system was installed and the street was excavated where it had been marked out in white prior by BM Consulting. Google Streetview also shows the new building prior to the install. BM Consulting put in for a permit with PWD that is attached to install a fire suppression unit at the new property. Permit was issued on 11/9/2024 and the emergency dig ticket was placed on 8/1/2025. BM Consulting failed to plan ahead by calling in a routine ticket prior to excavation.</p> <p>Follow up emails were made to BM Consulting. BM Consulting stated in an email that they do not know when the fire suppression unit was installed and that they don't know who installed it. PWD Permit to install unit was placed and paid for by BM Consulting. BM Consulting emergency ticket also states they are installing a fire suppression unit. White marks show BM spray painted for dig site.</p> <p>Violation:</p> <p>BM Consulting Service Inc. Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. PUC compliance education is required. Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. PUC compliance education is required. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required. Section 5(22) – Excavator provided a misrepresentation of an emergency excavation, subject to an administrative penalty imposed under section 7(10). 20252130165. PUC compliance education is required.</p> <p>Finch Development Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike or violation. PUC compliance education is required.</p>	
57178	<p>Facility Owner: Verizon North Contractor/Excavator: ERIE WATER WORKS Project Owner: Erie water works placeholder Other: Uniti Fiber</p>	<p><u>On 8/1/2025 9:26:00 AM at 1218 W GORE RD, MILLCREEK TWP, ERIE</u> Incident occurred on August 1st, 2025, at 9:26am on 1218 West Gore Road, Millcreek Township, Erie County.</p> <p>A telecom line was damaged.</p>	<p>Verizon North: \$4,500.00 Section 2(5)(i) 1st Offense \$500.00</p> <p>Section 2(5)(v) 2nd Offense \$1,000.00</p> <p>Section 2(5)(vii) 1st</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Erie Water Works' Alleged Violation Report (AVR) states, "Verizon Facilities we hit when excavating. Verizon had marked clear on 1-call. Downtime incurred while waiting on Verizon to respond. They took several hours to respond to the hit line."</p> <p>Images provided show the unmarked damaged line.</p> <p>Verizon Responses: Routine Ticket 20252102695 - Clear No Facilities Emergency Ticket 20252130858-00 - No Response Renotify Emergency Ticket 20252130858-01 - Scheduled Mark on 8/1/25 followed by an incorrect final response of Clear No Facilities on 8/4/25.</p> <p>Verizon responded clear twice even though their website shows service is available at the damage site address. Emergency damage ticket was placed at 9:26 am, and Verizon scheduled a response for 5:10pm after a no response and renotify was placed.</p> <p>Violations:</p> <p>Verizon North Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. 20252102695. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20252102695. PUC compliance education is required for the individual(s) responsible to respond to this ticket or their replacement(s). Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20252130858-00. PUC compliance education is required for the individual(s) responsible to respond to this ticket or their replacement(s). Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20252130858-01. PUC compliance education is required for the individual(s) responsible to respond to this ticket or their replacement(s). Section 2(5)(ix) – Facility owner failed to respond promptly to the site of an excavation where its underground line was damaged. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p> <p>Uniti Fiber Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20252130858-00. PUC compliance education is required for the individual(s) responsible to respond to this ticket or their replacement(s).</p>	<p>Offense \$1,000.00</p> <p>Section 2(5)(vii) 1st Offense \$1,000.00</p> <p>Section 2(5)(ix) 1st Offense \$1,000.00</p> <p>Uniti Fiber: \$1,000.00</p> <p>Section 2(5)(vii) 1st Offense \$1,000.00</p>
57280	<p>Facility Owner: National Fuel Contractor/Excavator: CCB Excavating</p>	<p><u>On 8/1/2025 1:30:00 PM at 112 N Vot Lane, BRADYS BEND TWP, ARMSTRONG</u> The incident occurred on August 1st, 2025, at 1:30 PM, at 112 N Vot Lane, in Bradys Bend Township, Armstrong County.</p>	<p>CCB Excavating: \$3,000.00 Section 5(2.1) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>Project Owner: Donna Hillwig</p>	<p>A gas line owned by National Fuel was damaged. 911 was not called. There was not a Pa One Call ticket when the damage occurred.</p> <p>National Fuel, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, "Excavator struck natural gas distribution service. Excavator failed to submit a POCS ticket request. Please see attachments." Photos were submitted.</p> <p>CCB Excavating is the excavator. An AVR has not been filed as of 10/08/2025.</p> <p>The ticket (20252150359) placed after the damage occurred lists the work is being done for Donna Hillwig. An AVR has not been filed as of 10/08/2025.</p> <p>The submitted photos show the damaged line. There are no utility markings.</p> <p>No indication in National Fuel's AVR or their submitted photos that 911 was called.</p> <p>There was not a Pa One Call ticket. Ticket 20252150359 was not requested until 08/03/2025 (2 days after the damage).</p> <p>Violations:</p> <p>CCB Excavating-</p> <ul style="list-style-type: none"> - Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. - Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p>	<p>Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>
57152	<p>Contractor/Excavator: Roto Rooter</p> <p>Other: UNITY TOWNSHIP MUNICIPAL AUTHORITY</p>	<p><u>On 8/2/2025 10:26:00 AM at 1210 MURRAY AVE, UNITY TWP, WESTMORELAND</u> The non-damage incident occurred on 07/21/2025, on Richard Avenue, in Shippensburg Township, Cumberland County.</p> <p>An emergency PA One Call ticket was requested. The type of work does not meet the requirements of an emergency.</p> <p>Unity Township Municipal Authority, a facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, "Emergency excavation was filled on 8/2/25 at 10:26 a.m. for a scheduled excavation start on 8/4/25 at 8 a.m. to hand dig downspouts. This does not fit the definition of an emergency."</p>	<p>Roto Rooter: \$0.00</p> <p>Section 5(22) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Roto Rooter is the excavator. An AVR has not been filed as of 10/09/2025.</p> <p>The emergency ticket (20252140119) listed the type of work as, "Spot repair on downspout". This does not meet the requirements of an emergency. Act 127 of 2024 defines an emergency as: A sudden or unforeseen occurrence involving a clear and immediate danger to life, property or the environment, including, but not limited to, serious breaks or defects in a facility owner's lines.</p> <p>The equipment used is listed as hand tools on the ticket and within Unity Township Municipal Authority's AVR.</p> <p>Violation:</p> <p>Roto Rooter- - Section 5(22) – Excavator provided a misrepresentation of an emergency excavation, subject to an administrative penalty imposed under section 7(10). Recommendation: No penalty is applied. This is a warning.</p>	
57262	<p>Facility Owner: Verizon Contractor/Excavator: FROIOS LAWN AND LANDSCAPE Project Owner: Homeowner</p>	<p><u>On 8/4/2025 7:00:00 AM at 1102 FIELDING DR, WESTTOWN TWP, CHESTER</u> Incident occurred on August 4th, 2025, at 7am on 1102 Fielding Drive, Westtown Township, Chester County.</p> <p>Non damage violation.</p> <p>Froios Lawn and Landscape's Alleged Violation Report (AVR) states, "request to mark utilities on 7/31 and no response. Put in a renotify on 8/4 and 8/6 with no response."</p> <p>20252110779-00 to 04 had a no response from Verizon -01, [ATTN VERIZON, YOU HAVE NOT RESPONDED. PLEASE REPORT TO THE SITE TO MARK YOUR LINE ASAP.] -02, [ATTN VERIZON, NO RESPONSE HAS BEEN MADE, THIS IS THE 2ND RENOTIFICATION. PLEASE MARK IF INVOLVED ASAP AND RESPOND TO THE KARL SYSTEM ASAP. WORK IS BEING DELAYED DUE TO NO RESPONSE. THANK YOU.] -03, [ATTN VERIZON PA YOU HAVE NOT RESPONDED. PLEASE VISIT THE SITE ASAP TO CHECK AND MARK ALL UG LINES AND POST A FINAL RESPONSE AS AUGUST 4 WAS THE 1ST LAWFUL START AND RENOTIFIES WERE DONE ON THE 4TH AND AND 6TH OF AUGUST. CALLER STATES THAT SHE HAS CALLED THE VERIZON CALL ALSO BUT NO ONE HAS COME TO THE SITE. PLEASE VISIT THE SITE ASAP MARK LINES AND POST A FINAL RESPONSE AS THIS IS 4TH RENOTIFY ON THIS TICKET AND THE JOB HAS BEEN DELAYED FOR A WEEK.] -04, [ATTN VERIZON PENNSYLVANIA YOU DID NOT RESPOND TO THIS TICKET AND IT IS WELL</p>	<p>Verizon: \$6,000.00 Section 2(5)(v) Subsequent \$2,000.00</p> <p>Section 2(5)(v.1) 2nd Offense \$1,000.00</p> <p>Section 2(5)(v.1) 2nd Offense \$1,000.00</p> <p>Section 2(5)(v.1) 2nd Offense \$1,000.00</p> <p>Section 2(5)(v.1) 2nd Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>WITHIN ITS LAWFUL START DATES. THERE HAVE BEEN MULTIPLE RENOTIFIES AND COMMUNICATION WITH VERIZON ABOUT GETTING THIS SITE MARKED AND NO ONE HAS RESPONDED. PLEASE SUBMIT A FINAL RESPONSE ASAP SO THAT THE WORK CAN BEGIN SAFELY AS IT IS REQUIRED. THANK YOU.]</p> <p>The first final response of field marked came in from Verizon on 8/8/2025 at 5:32pm.</p> <p>Violations:</p> <p>Verizon Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20252110779-00. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. 20252110779-01. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. 20252110779-02. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. 20252110779-03. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. 20252110779-04. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p>	
57245	<p>Contractor/Excavator: CKC Landscaping Project Owner: Homeowner Other: PECO Other: Verizon</p>	<p><u>On 8/4/2025 8:00:00 AM at 615 S CONCORD RD, WEST GOSHEN TWP, CHESTER</u> The incident occurred on 8/4/2025, at 8:00 AM, on 615 S Concord Rd, in West Goshen Twp, Chester County.</p> <p>This is a non-damage incident involving ticket responses.</p> <p>CKC Landscaping is the excavator listed on the project owner’s AVRs. An AVR has not been received as of 9/18/2025. No tickets were submitted by this excavator for this location. PA One Call indicates this company is a PA One Call member.</p> <p>Homeowner Mike Giduck is project owner. He submitted 3 AVR stating the same information, “I recently used PA 1 Call for some excavation work that was to be performed at my home. Things did not go well with the response from the utilities. I felt they were nonchalant and unconcerned. Reference: Serial Number 20252104160. I called 811 on Tuesday, July 29th for</p>	<p>CKC Landscaping: \$500.00 Section 5(23) 1st Offense \$500.00</p> <p>PECO: \$250.00 Section 2(5)(iii.1) 1st Offense \$250.00</p> <p>Verizon: \$2,500.00 Section 2(5)(i) Subsequent \$2,000.00</p> <p>Section 2(5)(v.1) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>excavation work that was to start on Monday, August 4th. I got a response shortly thereafter from Verizon that they had no utilities in the excavation area. I knew this was incorrect since I knew where the Verizon line came into my house. I called PA 1 Call and told them. They said they would re-contact Verizon. On Friday, August 1st I still hadn't heard from Verizon. I called PA 1 Call again to tell them. They said they would re-contact Verizon for the 3rd time. I was also told that them that they had until Sunday night, August 3rd to comply. Come Sunday night I call PA 1 Call again to state I still hadn't heard from Verizon. PA 1 Call gave me number to call for Verizon. I was told someone would be there at 08:00 on Monday. Verizon did arrive around 08:00 and marked their line. Here are my issues. Verizon: Their initial response was that "Verizon has determined that the excavation location and scope of work you have identified does not conflict with our underground facilities." How could they report this when it was obviously wrong. Suppose I wasn't aware of the existence of their underground line and it got cut. Who would have been responsible to repair that? Not to mention it would have severed communication with my and my wife's computer which we need for business reasons. When I first went onto the 811 web site it stated that 3 business days' notice was required. I made the call 4 business days before work was to start. I am extremely dissatisfied with the lackadaisical response from Verizon. Something needs to be corrected. What did go well was the interactions I had with those at PA 1 Call. I called for times and each time they showed concern with my issue, were very courteous & helpful, and took steps to try and resolve my problems."</p> <p>The project owner entered a routine ticket on 7/29/2025 with a response due date of 8/3/2025, a renotify on 7/30/2025, 8/1/2025, and 8/4/2025 (9:59 AM). Verizon responded "Clear" on 7/29/2025 to the routine ticket. The renotify -001 and -002 tickets indicate Verizon in the remarks,</p> <p>Ticket #20252104160 – 001 Entered on 7/30/2025 "ATTN VERIZON PA YOU RESPONDED CLEAR NO FACILITIES. HOWEVER CALLER STATES YOU ARE INVOLVED AND HAVE UG LINES AT THE SITE. PLEASE MARK YOUR LINES AND UPDATE YOUR RESPONSE. PLEASE CALL THE ONSITE CONTACT TO CLARIFY YOUR INVOLVEMENT AT THE SITE. THANK YOU."</p> <p>Ticket #20252104160 – 002 – entered on 8/1/2025 "ATTN VERIZON THIS IS THE SECOND RENOTIFY. HOMEOWNER KNOWS HIS VERIZON SERVICE ENTERS PROPERTY UNDERGROUND. PLEASE REPORT TO PROPERTY AND MARK LINES. WORK TO BEGIN FIRST THING MONDAY MORNING."</p> <p>Verizon responded "Field Marked" on 8/4/2025 at 8:26 AM, and "Clear" on 8/15/2025.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Ticket #20252104160 – 003 – indicates PECO-“ATTN PECO. YOU RESPONDED SCHEDULED TO MARK BY END OF DAY 8/4. HOWEVER 8/4 IS FIRST LAWFUL DATE. PLEASE MARK LINES AT SITE ASAP AND UPDATE RESPONSE. THANK YOU.”</p> <p>PECO responded Scheduled date and time: August 4th on 8/3/2025, and “Field Marked” on 8/4/2025 at 10:19. There is no information showing an agreement was reached to schedule the mark out past the response due date.</p> <p>Violations: Excavator – CKC Landscaping: Section 5(23) – Excavator may not delegate their duty to submit a locate request to the One Call System to another person. The excavator shall have sole responsibility to submit each locate request to the One Call System. Recommendation: PUC Online Compliance Training is required.</p> <p>Facility (other) – Verizon: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Ticket # 20252104160-000 Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Ticket # 20252104160-001 Recommendation: PUC Online Compliance Training is required.</p> <p>Facility (other) – PECO: Section 2(5)(iii.1) – Facility owner failed to propose a mutually agreeable scheduling by which the excavator, facility owner or designer may locate the facilities. Ticket # 20252104160 Recommendation: PUC Online Compliance Training is required.</p>	
57542	<p>Facility Owner: Verizon North Contractor/Excavator: Dominguez Services LLC. Project Owner: Shentel Communications Other: Comcast Other: West Manchester Township</p>	<p><u>On 8/4/2025 10:30:00 AM at 39 WESTVIEW MANOR, WEST MANCHESTER TWP, YORK</u> The incident occurred on 8/4/2025, at 10:35 AM, on 39 Westview Manor, in West Manchester Twp, York County.</p> <p>A communication line owned by Verizon was damaged.</p> <p>Verizon is the facility owner. An Alleged Violation Report (AVR) has not been filed as of 09/29/2025.</p> <p>Dominguez Services is the excavator. Their AVR states, “Verizon line was damaged. Routine and Renotify tickets were not responded”.</p> <p>Shentel Glo Fiber is the project owner. Their AVR states, “The primary reason the damage occurred is that Verizon did not mark their facilities on ticket #20252094209. The ticket was coded 999 did not respond through the PA One Call. The excavator called in a renotify 8/4/2025 @ 7:19am since there was clear evidence of pedestals in the scope of the PA811 ticket. At 9:21 am on 8/4/2025 the ticket had a response of Did not respond through PA One Call. The excavator waited</p>	<p>Verizon North: \$3,000.00 Section 2(5)(i) 1st Offense \$500.00</p> <p>Section 2(5)(v) 2nd Offense \$1,000.00</p> <p>Section 2(5)(v.1) 1st Offense \$500.00</p> <p>Section 2(10) 1st Offense \$1,000.00</p> <p>Comcast: \$2,000.00 Section 2(5)(vii) 3rd Offense \$2,000.00</p> <p>West Manchester Township: \$250.00 Section 2(5)(v) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>their 3 hours then proceeded to excavate. The damage occurred due to the excavator while exposing the marked power lines struck and damaged the unmarked Verizon main line cable. All the orange paint in the pictures is for the Comcast facilities mainline and drops in the area. No complex project needed since this was from intersection to intersection along the same street, within the same political subdivision.”</p> <p>Images show the area, marks, and damage. There are multiple marks shown in the area of the damage. The excavator was hand digging a test pit in the tolerance zone of the marks when they struck the Verizon line. Verizon did not respond to the routine or renotify ticket prior to the damage occurring.</p> <p>Ticket #20252094209-000 had a response due date of 7/30/2025. West Manchester Township responded “Clear” on 7/31/2025 at 12:28 PM and Verizon responded “Clear” on 8/9/2025. A renotify was entered on 8/4/2025. Verizon responded “Clear” on 8/9/2025.</p> <p>Ticket # 20252161637 New – Damage – Emergency – Verizon responded “Field Marked”, but indicates on the routine tickets that the area was “Clear”. Comcast responded “Insufficient Information. Do Not Dig” on 8/4/2025 at 10:51AM” as their only response.</p> <p>Violations: Facility (other) – Verizon: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket #20252094209-000 Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Ticket #20252094209-001 Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: PUC Online Compliance Training is required.</p> <p>Facility(other) - Comcast: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket # 20252161637 Recommendation: PUC Online Compliance Training is required.</p> <p>Facility (other) - West Manchester Township: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket #20252094209-000 Recommendation: PUC Online Compliance Training is required.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
57341	<p>Facility Owner: UGI Contractor/Excavator: Rogele, Inc. Project Owner: Capital Region Water Designer: ACT ONE AND ASSOCIATES Designer: HERBERT ROWLAND AND GRUBIC INC</p>	<p><u>On 8/4/2025 11:17:00 AM at 47 North 18th Street, HARRISBURG CITY, DAUPHIN</u> The incident occurred on August 4th, 2025, at 47 North 18th Street, in Harrisburg City, Dauphin County.</p> <p>A gas line owned by UGI was damaged. 911 was called.</p> <p>UGI, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “Rogele Inc. was digging to install sewer main on N. 18th St, Harrisburg when they damaged a correctly marked gas service going to 47 N. 18th St. Rogele Inc. was using mechanized equipment to remove road surface when a chunk of road material was pushed into gas service, damaging the line and causing a release of gas.” Photos were submitted.</p> <p>Rogele, Inc., the excavator, submitted an AVR. Their AVR states, “Rogele crew was excavating to remove blacktop and concrete sub-base. After removal of this 14inches of material, 2 laborers entered the ditch to hand dig. At this time, the odor of natural gas had become present. They shifted approx. 3" of material and exposed a 3/4" black/yllw plastic gas line that was leaking. The line appeared to have been gouged possibly by a sharp piece of stray concrete that could have been pushed into it while removing the concrete sub-base. All other gas service lines encountered to this point have been at least 24"s deep and also surrounded by "stone dust"...this line was found at 17" deep and no dust.” Photo was submitted.</p> <p>Capital Region Water, the project owner, submitted an AVR. Their AVR did not include a summary. Photos were submitted.</p> <p>Herbert Rowland And Grubic Inc., the designer, submitted an AVR. Their AVR states, "While removing concrete sub-base from atop the proposed 36" Sewer trench line, Rogele ruptured the existing gas lateral servicing 47 North 18th Street. The Excavator did not come into contact with the service line. It is believed that the existing road base snagged the uncovered line. The Gas service line was directly below the sub-base with no stone dust (Note 17" depth 3/4" service line).” Photos were submitted.</p> <p>The submitted photos show the gas line was properly marked with yellow paint and the line was damaged within the tolerance zone.</p> <p>Violations:</p> <p>Rogele, Inc.- - Section 5(6)(ii) – Excavator failed to provide support and mechanical protection for known facility owner’s lines at the construction work site. Recommendation: The penalty is applied. PUC compliance training education is required.</p>	<p>Rogele, Inc.: \$500.00 Section 5(6)(ii) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
57183	<p>Facility Owner: PECO AN EXELON COMPANY</p> <p>Contractor/Excavator: SACKS & SONS INC</p> <p>Project Owner: SCHWENKSVILLE BOROUGH AUTHORITY</p> <p>Designer: GILMORE and ASSOCIATES</p>	<p><u>On 8/4/2025 1:50:00 PM at 809 SUMMIT AVE, SCHWENKSVILLE BORO, MONTGOMERY</u> The incident occurred on Monday, August 4, 2025, at 809 Summit Avenue, in Schwenksville Borough, Montgomery County.</p> <p>A gas line was damaged.</p> <p>The contractor, Sacks & Sons Inc, doing work for Schwensville Borough, stated in their alleged violation report (AVR), a 3/4"(?) home service gas line was snapped with the back of the excavator bucket while trying to clean up trench to install new curbing and sidewalk, along Summit Avenue, over gas service line location. The gas line was capped and we notified 911 immediately. We sat on hold with PA 1 call for roughly 20 minutes before our call was taken to notify PA 1 call and contact PECO for repair. Upon ticket submission to PA 1 Call, the 1 Call ticket operator provided a phone number for PECO Gas that turned out to be a dead number. PECO subsequently responded quickly to the call and made a quick repair.</p> <p>PECO An Exelon Company stated in their AVR, on 8/4/2025 PECO responded to a damaged 1/2" PX gas service at 809 Summit Avenue. The investigation found that the service line was damaged as a result of Sacks & Sons digging with mechanical means inside the tolerance zone of a properly marked gas service line.</p> <p>Violation: *Sacks & Sons Inc is in violation of section: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: PUC Compliance Education Required and Penalty Applied</p>	<p>SACKS & SONS INC: \$500.00 Section 5(4) 1st Offense \$500.00</p>
57745	<p>Facility Owner: UGI</p> <p>Contractor/Excavator: Zenex</p> <p>Project Owner: Homeowner</p> <p>Other: Comcast</p> <p>Other: Moosic Borough</p>	<p><u>On 8/4/2025 4:26:00 PM at 636 RIVER STREET, MOOSIC BORO, LACKAWANNA</u> The incident occurred on 8/4/2025, at 4:26 PM, on 636 River Street, in Moosic Boro, Lackawanna County.</p> <p>A gas line owned by UGI was damaged.</p> <p>UGI is the facility owner. Their Alleged Violation Report (AVR) states, “Excavator struck and damaged a correctly marked gas facility while digging in the tolerance zone. Excavator squeezed off blowing gas facility with vise grips after it was struck as well as failed to maintain locate marks of gas facility after the driveway was removed.”</p> <p>Zenex is the excavator. An AVR has not been filed as of 09/30/2025.</p> <p>The homeowner is the project owner.</p> <p>Images submitted show the site, excavation. and damaged line. The old driveway has been removed and the only yellow mark remaining is a faded mark on the road. Bucket marks are seen in the excavated dirt in the</p>	<p>Zenex: \$1,500.00 Section 5(4) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>Comcast: \$2,000.00 Section 2(5)(v) Subsequent \$2,000.00</p> <p>Moosic Borough: \$1,000.00 Section 2(5)(v) 1st Offense \$500.00</p> <p>Section 2(5)(v) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>driveway indicating mechanized equipment was used. The ticket also indicates “power equip”. The home is shown with a gas meter on the side. The damage is directly in line with a faded mark on the road, and the gas meter.</p> <p>Ticket # 20252090880 New – Excavation – Routine had a response due date of 7/30/2025. Comcast responded “Clear,” on 8/29/2025. Moosic Borough did not respond to the ticket.</p> <p>Ticket #20251884011 New – Excavation – Routine - Moosic Borough did not respond to the ticket. Violations:</p> <p>Excavator – Zenex: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: PUC Online Compliance Training is required.</p> <p>Facility(other) – Moosic Borough: Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket # 20252090880 Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket #20251884011 Recommendation: PUC Online Compliance Training is required.</p> <p>Facility(other) –Comcast: Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket # 20252090880 Recommendation: PUC Online Compliance Training is required.</p>	
58067	<p>Facility Owner: UGI Contractor/Excavator: Hurst Excavating Project Owner: GARMAN BUILDERS</p>	<p><u>On 8/4/2025 4:44:00 PM at 529 Stevens Rd, EPHRATA TWP, LANCASTER</u> The incident occurred on 8/4/2025, at 4:44 PM, on 529 Stevens Rd, in Ephrata Twp, Lancaster County.</p> <p>A gas line owned by UGI was damaged.</p> <p>UGI is the facility owner. Their Alleged Violation Report (AVR) states, “Excavator was utilizing mechanized equipment, and struck a correctly marked gas service. The marks were obliterated in the dig site. Gas service was struck in 3 separate places and the work continued without calling immediately to notify 911 or 811 of a damage.” UGI indicates on their AVR that 911 was not contacted. An emergency-damage ticket was submitted.</p> <p>Multiple images of the site, excavation, damage, and marks were submitted. The marks shown in the pre-excavation photos are not visible in the damage photos as the excavation was at most of the site. There is one visible flag remaining in the post-damage photos. There is no evidence that test holes were dug at any of the</p>	<p>Hurst Excavating: \$2,500.00 Section 5(4) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>Section 5(8) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>marked locations. The line that was damaged is shown pulled out of the ground, and damaged, in multiple locations across the excavation.</p> <p>Hurst Excavating is the excavator. An AVR has not been filed as of 09/30/2025.</p> <p>Garman Builders is the project owner. An AVR has not been filed as of 09/30/2025.</p> <p>Violations: Excavator - Hurst Excavating: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. Recommendation: PUC Online Compliance Training is required.</p>	
57293	<p>Facility Owner: PECO Contractor/Excavator: MALVERN BOROUGH</p>	<p><u>On 8/5/2025 2:25:00 PM at 225 E BROAD, MALVERN BORO, CHESTER</u> The incident occurred on 8/5/2025, at 2:25 PM, on 225 E Broad, in Malvern Boro, Chester County.</p> <p>A gas line owned by PECO was damaged. 911 was contacted according to Malvern Borough.</p> <p>PECO is the facility owner. Their Alleged Violation Report (AVR) states, “MALVERN BOROUGH WAS DIGGING IN THE STREET TO REPLACE STORM DRAIN BOX. ONSITE FOREMAN WALT DAVIS SPOKE WITH INVESTIGATOR AND CONFRIMED THEY DID NOT HAVE A PA 1 CALL.”</p> <p>Malvern Borough is the excavator. An AVR has not been filed as of 09/19/2025. An AVR request letter was sent on 9/19/2025 and they completed the report promptly.</p> <p>No project owner was identified. PA One Call did not find any tickets related to this location.</p> <p>PECO provided a damage report showing images of the excavation, damage, and mechanized equipment. The damaged gas main is shown with a clamp on the line. No marks are seen in the images.</p> <p>Violations: Excavator - Malvern Borough: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize</p>	<p>MALVERN BOROUGH: \$1,250.00 Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(16) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>interference with a facility owner’s facilities in the construction area.</p> <p>Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Penalty is reduced from \$1000 to a \$0 warning. Recommendation: PUC Online Compliance Training is required.</p>	
57295	<p>Facility Owner: PECO AN EXELON COMPANY</p> <p>Contractor/Excavator: A&R CONCRETE and MASONRY</p> <p>Project Owner: PROPERTY OWNER</p> <p>Other: Ridley Park Borough</p>	<p><u>On 8/6/2025 9:45:00 AM at 15 W RIDLEY AVE, RIDLEY PARK BORO, DELAWARE</u> The incident occurred on Wednesday, August 6, 2025, at 15 W. Ridley Avenue, in Ridley Park Borough, Delaware County.</p> <p>PECO An Exelon Company gas line was damaged.</p> <p>PECO stated in their alleged violation report (AVR) and investigation report that the contractor, A&R Concrete and Masonry, hit a gas service line due to inaccurate prints. The contractor was excavating with a mini excavator and hand tools; to replace the curb on W. Ridley Avenue, when they severed the 1/2" plastic gas service 23-feet from the gas service locate mark-outs. “It was found that the records and sketch provided at the time of the locate do not accurately depict the true path of the gas service resulting in the service being severed and in need of repair. While reviewing the gas service records it was found that the sketch is a field est only and shows the gas exciting the residence on the East side of the house this is an indoor meter and it is actually 21 'East of the West House due to the mapping discrepancy and the indoor meter this service was severed.”</p> <p>20252161640- Routine ticket placed on 8/4/2025, No Response from Ridley Park Borough. PECO did not say that 911 was called. A&R Concrete and Masonry did not submit an AVR.</p> <p>Violations:</p> <p>*PECO An Exelon Company is in violation of section: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: Penalty Applied</p> <p>*A&R Concrete and Masonry is in violation of sections. 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: PUC Compliance Education Required and Penalties Applied</p> <p>*Ridley Park Borough is in violation of section: 2(5)(v) – Failed to respond to a routine One Call ticket. 20252161640 Recommendation: PUC Compliance Education Required and Penalty Applied</p>	<p>PECO AN EXELON COMPANY: \$2,000.00 Section 2(5)(i) Subsequent \$2,000.00</p> <p>A&R CONCRETE and MASONRY: \$2,000.00 Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>Ridley Park Borough: \$500.00 Section 2(5)(v) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
57372	<p>Facility Owner: WILKINSBURG-PENN JOINT WATER AUTHORITY</p> <p>Contractor/Excavator: BANKS GAS SERVICE</p> <p>Project Owner: Peoples Natural Gas</p> <p>Designer: Total Engineering And Consulting Services</p> <p>Other: Comcast</p> <p>Other: FOREST HILLS BOROUGH</p>	<p><u>On 8/6/2025 11:00:00 AM at EDGEWOOD RD, FOREST HILLS BORO, ALLEGHENY</u> The incident occurred on 8/6/2025, at 1:15 PM, on Edgewood Rd, in Forest Hills Boro, Allegheny County.</p> <p>A water line owned by Wilkinsburg Penn Joint Water was damaged. The facility was notified of the damage.</p> <p>Wilkinsburg Penn Joint Water is the facility owner. Their Alleged Violation Report (AVR) states, “Banks Gas Service uncovering utility lines for PNG project AT #422 Edgewood Road Forest Hills. Crew struck WPJWA 1" copper service line. Damage occurred within the tolerance zone. Ticket submitted by M Oherron Company, damage caused by Banks Gas Service. WPJWA first responder believed line was damaged by a jack hammer/breaker.”</p> <p>Banks Gas Services is the excavator. Their AVR states, “Our Crew was attempting to spot a water service line. The Crew was digging through rock and slag and was unable to use hand tools. Attempts to use prudent techniques were taken and a digging bar was used. Unfortunately while using a digging bar the line was hit and damaged.”</p> <p>Peoples Natural Gas is the project owner. An AVR has not been filed as of 09/23/2025. Images are provided showing the site, excavation and damage.</p> <p>Both Total Engineering and Consulting Services, and Peoples Gas are shown as designers on tickets for this location. An AVR has not been filed by either as of 09/23/2025.</p> <p>Forest Hills Borough did not respond to Routine Ticket #20251813521 and Ticket #20251813522.</p> <p>Ticket # 20252183208 New – Damage – Emergency, and #20252184432 New – Excavation– Emergency: Comcast responded “Clear” on August 29, 2025. The response was due on August 6, 2025.</p> <p>Violations: Excavator - Banks Gas Services: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: PUC Online Compliance Training is required. Project Owner - Peoples Natural Gas: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Recommendation: PUC Online Compliance Training is required. Facility (other) – Comcast: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. #20252183208</p>	<p>BANKS GAS SERVICE: \$1,000.00 Section 5(4) 2nd Offense \$1,000.00</p> <p>Peoples Natural Gas: \$1,500.00 Section 6.1(7) 2nd Offense \$1,500.00</p> <p>Comcast: \$4,000.00 Section 2(5)(vii) 3rd Offense \$2,000.00</p> <p>Section 2(5)(vii) 3rd Offense \$2,000.00</p> <p>FOREST HILLS BOROUGH: \$500.00 Section 2(5)(v) 1st Offense \$250.00</p> <p>Section 2(5)(v) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. #20252184432 Recommendation: PUC Online Compliance Training is required.</p> <p>Facility (other) - Forest Hills Borough: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. #20251813521 Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. #20251813522 Recommendation: PUC Online Compliance Training is required.</p>	
57351	<p>Facility Owner: Peoples Gas Company Contractor/Excavator: A LIBERONI Project Owner: PennDOT</p>	<p><u>On 8/7/2025 9:12:00 AM at HARTS RUN RD, HAMPTON TWP, ALLEGHENY</u> Incident occurred on August 7th, 2025, at 9:12am, Harts Run Road, Hampton Township, Allegheny County.</p> <p>A gas line was damaged.</p> <p>Peoples Gas Company's Alleged Violation Report (AVR) states, "On 8/7/2025, A Liberoni Inc struck an unmarked PNG SL main to curb while performing roadwork along Harts Run Road. PNG crews were called and repairs were made. All ML was marked in the work area. No SL's were marked."</p> <p>A. Liberoni's AVR states, "Liberoni was performing shoulder reconstruction on shoulder of the west bound lane. While digging an unmarked service line that crossed the road was hit. The service line had been marked on the edge of the shoulder in the east bound lane but the marks were not carried through to the west bound lane." AVR notes 911 was notified.</p> <p>PennDOT's AVR states, "The contractor began excavation for shoulder reconstruction, the gas line was hit by the excavator bucket at approximately 22 inches below the roadway. This location was not marked during the previously requested 1 call."</p> <p>Images show that the service line was not marked withing the tolerance zone.</p> <p>Violation:</p> <p>Peoples Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.</p>	<p>Peoples Gas Company: \$1,500.00 Section 2(5)(i) 3rd Offense \$1,500.00</p>
57387	<p>Facility Owner: Peoples Gas Company Contractor/Excavator: KANAAN COMMUNICATIONS LLC Project Owner: Comcast</p>	<p><u>On 8/7/2025 11:38:00 AM at 1389 DEEP WOOD DR, UPPER ST CLAIR TWP, ALLEGHENY</u> Incident occurred on August 7th, 2025, at 11:38am on 1389 Deep Wood Drive, Upper Saint Clair Township, Allegheny County.</p> <p>A gas line was damaged. Case is related to 57690.</p> <p>Peoples Gas Company's Alleged Violation Report (AVR) states, "ON 8/7/25 KANAAN</p>	<p>KANAAN COMMUNICATIONS LLC: \$1,750.00 Section 5(4) 1st Offense \$500.00</p> <p>Section 5(11.1) 1st Offense \$250.00</p> <p>Section 5(16) 1st Offense</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>COMMUNICATIONS BORING FOR COMCAST STRUCK PNG 3 INCH MAIN LINE. KANAAN COMMUNICATIONS FAILED TO USE GUIDELINES AND SPOT UTILITY EVERY 25 FEET DUE TO BEING WITH IN 3 FEET OF MAIN. WHILE CROSSING 2 SERVICES THEY FAILED TO SPOT DRILL HEAD PASS OVER/UNDER PNG SERVICE LINE. KANAAN COMMUNICATIONS NOTIFIED 811 AND 911 WHEN THEY SMELLED GAS. PNG CREWS ARRIVED ONSITE AND SHUT OFF 2 CUSTOMERS AND MONTIORED GAS LEAK UNDER PNG CREWS COULD EXPOSE LEAK AND INSTALL BYPASSES DUE TO 1 WAY FEED. REPAIRS WERE MADE AND CUSTOMERS WERE TURNED BACK ON."</p> <p>20252100634-01: ATTN WEST PENN POWER YOU HAVE NOT RESPONDED TO THIS TICKET OR PRIOR TICKETS ISSUED FOR LOCATION. PLEASE MARK YOUR LINES AND RESPOND IN THE KARL SYSTEM ASAP AS CREW IS ON SITE AND PREPARED TO EXCAVATE. THANK YOU.</p> <p>No AVR was submitted within 30 days of the incident by Comcast or Kanaan Communications, LLC. No design tickets were located. Images show the line with tracer wire was accurately marked.</p> <p>Violations:</p> <p>Kanaan Communications, LLC. Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. PUC compliance education is required for the excavators working onsite of this excavation or their replacements. Section 5(11.2) – When using trenchless technology, Excavator failed to utilize at a minimum, the best practices published by the Common Ground Alliance. PUC compliance education is required for the excavators working onsite of this excavation or their replacements. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required for the person responsible for submitting AVR or their replacement.</p> <p>Comcast Section 4(2) – Designer failed to request the line and facility information prescribed by section 2(4) from the One Call System not less than ten nor more than ninety business days before final design is to be completed. PUC compliance education is required for the designer(s) who worked on this project or their replacement(s). Section 4(4) – Failed to prepare construction drawings to avoid damage to and minimize interference with facilities in the construction area. PUC compliance education is required for the designer(s) who worked on this project or their replacement(s).</p>	<p>\$1,000.00</p> <p>Comcast: \$5,000.00 Section 4(2) 3rd Offense \$1,500.00</p> <p>Section 6.1(3) 2nd Offense \$1,000.00</p> <p>Section 6.1(7) 2nd Offense \$1,500.00</p> <p>Section 4(4) 3rd Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 6.1(3) – Released a project to bid or construction before final design was complete. PUC compliance education is required.</p> <p>Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. PUC compliance education is required for the person responsible for submitting AVR or their replacement.</p>	
57430	<p>Facility Owner: National Fuel</p> <p>Contractor/Excavator: Empire Landscaping</p>	<p>On 8/8/2025 5:09:00 PM at 6026 Schultz Rd, <u>MILLCREEK TWP, ERIE</u> The incident occurred on 08/08/2025 at 5:09 PM, at 6026 Schultz Road, in Millcreek Township, Erie County.</p> <p>A gas line owned by National Fuel was damaged. There was not a One Call ticket.</p> <p>National Fuel, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “Excavator working with no one call, is a repeat offender. Damaged an NFG service line.” Photos were submitted.</p> <p>Empire Landscaping is the excavator. An AVR has not been filed as of 10/17/2025. An AVR request letter was mailed and emailed on 08/20/2025, specifically asking the excavator to confirm who the project owner was.</p> <p>The project owner is unknown. An AVR has not been filed as of 08/20/2025.</p> <p>No PA One Call tickets were located. PA One Call advised that they did not find any record of Empire Landscaping placing One Call notifications in the past.</p> <p>National Fuel’s AVR did not indicate if 911 was called.</p> <p>The submitted photos show no utility marked outs.</p> <p>Violations:</p> <p>Empire Landscaping-</p> <ul style="list-style-type: none"> - Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. - Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. - Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. - Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p>	<p>Empire Landscaping: \$3,750.00 Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>Section 5(17) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
58197	<p>Facility Owner: Wrightsville Borough Municipal Authority</p> <p>Contractor/Excavator: Columbia Gas of PA - East</p> <p>Project Owner: Columbia Gas of PA - East</p> <p>Other: Comcast</p>	<p><u>On 8/11/2025 9:00:00 AM at LOCUST ST, WRIGHTSVILLE BORO, YORK</u> The incident occurred on Monday, August 11, 2025, on Locust Street, in Wrightsville Borough, York County.</p> <p>Wrightsville Borough Municipal Authority water line was damaged.</p> <p>Columbia Gas explained in their Alleged Violation Report (AVR), on 8/11/2025, our crew responded to a gas leak in Wrightsville Borough. During excavation efforts, the team began removing hard surface and digging with a mini-excavator outside the tolerance zone of our gas main in extremely rocky conditions. While digging, the crew struck the top of an unmarked water service line. The crew immediately notified Damage Prevention and their field leader, and promptly contacted both 811 and Wrightsville Borough to report the water line strike. Once the water flow was stopped, a large vacuum truck was brought in to assist with repairs in coordination with the Borough. Damage Prevention conducted a root cause analysis on site and determined that the unknown water service had been pulled from the water main. Further investigation revealed that the tap was located within the tolerance zone of the water main locate marks. A root cause review was held the following day with crew members and leadership to evaluate the event and reinforce safe digging practices. Full plant huddle was conducted to discuss safe digging practices and hand digging within the tolerance zone. Columbia Gas provided photos.</p> <p>Wrightsville Borough Municipal Authority did not submit an AVR.</p> <p>20252231196- Damage Emergency ticket placed on 8/11/2025, No Response from Comcast, responded late on 8/29/2025 as Field Marked.</p> <p>20252110762- Routine ticket placed on 7/30/2025, with response due date as 8/1/2025. Late Response from Comcast, responded late on 8/29/2025 as Clear No Facilities.</p> <p>Violations:</p> <p>*Columbia Gas is in violation of section: 5(6)(ii) – Excavator failed to provide support and mechanical protection for known facility owner’s lines at the construction work site. Recommendation: Penalty Applied, and PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements.</p> <p>*Wrightsville Borough Municipal Authority is in violation of section: 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a</p>	<p>Wrightsville Borough Municipal Authority: \$500.00 Section 2(10) 1st Offense \$500.00</p> <p>Columbia Gas of PA - East: \$500.00 Section 5(6)(ii) 1st Offense \$500.00</p> <p>Comcast: \$2,500.00 Section 2(5)(vii) 2nd Offense \$1,500.00</p> <p>Section 2(5)(v) Subsequent \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>violation of this act has been committed in association with excavation or demolition work. Recommendation: Penalty Applied with penalty reduced by 50% (\$1,000 to \$500), and PUC online Compliance Training is required for the person responsible for submitting AVRs</p> <p>*Comcast is in violation of sections: 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20252231196 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. 20252110762 Recommendation: Penalties Applied, and PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).</p>	
57454	<p>Facility Owner: UNITY TOWNSHIP MUNICIPAL AUTHORITY Contractor/Excavator: Caribbean Pools Project Owner: Homeowner</p>	<p><u>On 8/11/2025 10:02:00 AM at 1249 MYERS RD, UNITY TWP, WESTMORELAND</u> Incident occurred on August 11th, 2025, at 10:02 am on 1249 Myers Road, Unity Township, Westmoreland County.</p> <p>Non-damage incident.</p> <p>Unity Township Municipal Authority's Alleged Violation Report (AVR) states, "The homeowner placed one call for Caribbean Pools, the contractor. No contact information is available for the contractor; only the homeowner's contact information is provided."</p> <p>PA1call commented, "Caribbean Pools has placed one call notifications in the past."</p> <p>No other tickets were located at this site by PA1call. Ticket 20252231458 was placed by the homeowner and called for contractor--[CARRIBEAN POOLS].</p> <p>Email from the homeowner states, "I placed the call and Caribbean Pools did all the work including the excavation. All utilities were cleared."</p> <p>Violation:</p> <p>Caribbean Pools Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. PUC compliance education is required. Section 5(23) – Excavator may not delegate their duty to submit a locate request to the One Call System to another person. The excavator shall have sole responsibility to submit each locate request to the One Call System. 20252231458. PUC compliance education is required.</p>	<p>Caribbean Pools: \$1,500.00 Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(23) 1st Offense \$500.00</p>
57404	<p>Facility Owner: UGI UTILITIES, INC. Contractor/Excavator: ROSSI ROOTER Project Owner: Customer</p>	<p><u>On 8/11/2025 11:03:00 AM at 261 E GROVE ST, CLARKS GREEN BORO, LACKAWANNA</u> The incident occurred on Monday, August 11, 2025, at 261 E. Grove Street, in Clarks Green Borough, Lackawanna County.</p> <p>A gas line was damaged.</p>	<p>ROSSI ROOTER: \$1,000.00 Section 5(4) 2nd Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Rossi Rooter stated in their alleged violation report (AVR), at approximately 11:03am, the technician, Juan, was excavating a customer's private sewer lateral when he struck the gas service going to the building of the customer, 911 and PA 1Call were both immediately notified of the incident. All technicians on site vacated area until informed it was safe to return.</p> <p>In their AVR, Rossi Rooter provided Locating Information- Line Marked?: Accurately, Offset Markings Used?: No, Condition of Marks: Readily Visible, Facilities Visible?: Yes, Color Code Standards Used?: Yes, Marked by Response Due Date?: Yes, Excavation in Tolerance Zone?: Yes, Meter Pedestal Number: Valve Box, Types of Marks Present: Paint, Locate Methods: Records.</p> <p>UGI stated in their AVR, the contractor, Rossi Rooter failed to use prudent techniques within the tolerance zone. UGI explained, while digging to replace a sewer lateral Rossi Rooter struck and damaged a correctly marked gas service line with a track hoe.</p> <p>Photos were provided of the damaged gas line.</p> <p>Violation: *Rossi Rooter is in violation of section: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: PUC Compliance Education Required and Penalty Applied</p>	
57507	<p>Facility Owner: PEOPLES GAS COMPANY Contractor/Excavator: M. O'HERRON COMPANY Project Owner: PEOPLES GAS COMPANY</p>	<p><u>On 8/11/2025 11:20:00 AM at HAVELOCK WAY, PITTSBURGH CITY, ALLEGHENY PNG-</u> penalty and violation have been removed. See attachments. *****</p> <p>The incident occurred on Monday, August 11, 2025, on Havelock Way, in Pittsburgh City, Allegheny County.</p> <p>A gas line was damaged.</p> <p>Peoples Gas Company stated in their alleged violation report (AVR), on 8/11/2025, M. O'Herron Company was doing work for PNG when they struck a mismarked PNG SL main to curb, it was mismarked by 4'. M. O'Herron Company stated in their AVR that they were digging for new gas mainline installation. Digging and sawcut the trench in the parallel to dual meter service to 327/329 Havelock Way and approximately 2 1/2' away from gas line markings. Trench dug 2 1/2' away from marks not seeing any indication of it before encountering it crossing ditch-line at sharp angle. The service line came off at the end of the mainline and looped 5' out into middle of the alley to go to the meters on other side of the house.</p> <p>Photos were provided by Peoples Gas and M. O'Herron showing the mis-marked damaged line.</p> <p>Violation: *Peoples Gas Company is in violation of section:</p>	<p>PEOPLES GAS COMPANY: \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: Penalty Applied</p>	
57549	<p>Facility Owner: Comcast Project Owner: VERIZON Other: DUQUESNE LIGHT CO Other: PLUG UTILITIES</p>	<p><u>On 8/12/2025 8:30:00 AM at TIMBER DR, TRAFFORD BORO, WESTMORELAND</u> On 11/13/2025 Duquesne Light Company (DLC) sent an email accepting all of the violations and penalties. On 11/13/2025 Comcast sent an email accepting all of the violations and penalties. ***** The incident occurred on 8/12/2025 on Timber Dr. in Trafford Borough in Westmoreland Co.</p> <p>3 Communication lines were damaged. 47 residential customers were affected.</p> <p>PLUG UTILITIES stated in their Alleged Violation Report (AVR) that “While installing conduit, the crew struck an unmarked Comcast line. Comcast had been asked to mark their lines by the complex project’s due date and was also notified the crew was on site ready to begin working. However, they did not respond, left the site unmarked, and consequently the crew interrupted the Comcast service line”. Reports and pictures were provided.</p> <p>PLUG UTILITIES submitted another AVR which stated that “While installing conduit, the crew struck an unmarked cable line, either Comcast or Verizon. Both had been asked to mark their lines by the complex project’s due date and were also notified the crew was on site ready to begin working. However, they did not respond, left the site unmarked, and consequently the crew interrupted the service line at 221 and 223 Timber Dr”. More reports and pictures were provided.</p> <p>PLUG UTILITIES submitted another AVR which stated that “While installing conduit, the crew struck an unmarked cable line, either Comcast or Verizon. Both had been asked to mark their lines by the complex project’s due date and were also notified the crew was on site ready to begin working. However, they did not respond, left the site unmarked, and consequently the crew interrupted the service line at 217 TO 229 Timber Dr”.</p> <p>COMCAST submitted an AVR with no Summary but added that the event impact was that 11-50 people were affected for 6-12 hours. On 9/19/2025 DPI Maki sent an email to Comcast asking to verify how many people were affected. An email was received on 9/22/2025 that 47 Residential customers were affected.</p> <p>VIOLATIONS Comcast is in violation of: Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket 20252150050-000 was requested by Plug Utilities on 8/03/2025 with a response due by 8/11/2025. Comcast never responded. This is a subsequent offense.</p>	<p>Comcast: \$14,500.00 Section 2(5)(viii) Subsequent \$2,000.00</p> <p>Section 2(5)(i) Subsequent \$2,000.00</p> <p>Section 2(5)(v) Subsequent \$2,000.00</p> <p>Section 2(5)(v.1) 3rd Offense \$1,500.00</p> <p>Section 2(5)(iii.1) 3rd Offense \$1,000.00</p> <p>Section 2(5)(i) Subsequent \$2,000.00</p> <p>Section 2(5)(i) Subsequent \$2,000.00</p> <p>Section 2(5)(i) Subsequent \$2,000.00</p> <p>VERIZON: \$13,750.00 Section 2(5)(i) Subsequent \$2,000.00</p> <p>Section 6.1(7) Subsequent \$2,500.00</p> <p>Section 9 3rd Offense \$750.00</p> <p>Section 2(5)(v.1) 2nd Offense \$1,000.00</p> <p>Section 2(5)(iii.1) 2nd Offense \$500.00</p> <p>Section 2(5)(i) Subsequent \$2,000.00</p> <p>Section 2(5)(i) Subsequent \$2,000.00</p> <p>Section 2(5)(i) Subsequent \$2,000.00</p> <p>Section 2(5)(v) Subsequent \$1,000.00</p> <p>DUQUESNE LIGHT CO: \$500.00 Section 2(5)(viii) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Renotify ticket 2025150050-001 was submitted on 8/12/2025 at 8:10 a.m. stating that onsite markings are incomplete. Please return to complete the markings. Comcast never responded. This is a subsequent offense.</p> <p>Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Renotify ticket 2025150050-001 was submitted on 8/12/2025 at 8:10 a.m. stating that onsite markings are incomplete. Please return to complete the markings. Direct contact with excavator required within 2 hours. Ticket response due by 10:10 a.m. Comcast never responded.</p> <p>Section 2(5)(iii.1) – Facility owner failed to propose a mutually agreeable scheduling by which the excavator, facility owner or designer may locate the facilities. There are no comments or any more information in the Complex Project ticket 20252102301 responses. See attachment named: Complex Project ticket 20252102301 All Responses. This is a third offense.</p> <p>Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Emergency ticket 20252243070 was submitted on 8/12/2025 at 13:28 stating “customers are without Comcast service” Comcast responded on 8/12/2025 at 14:54 “Insuff Info. Do Not Dig”. Renotify ticket 2025150050-001 was submitted on 8/12/2025 at 8:10 a.m. Excavation began after the 3 hour required waiting period for a renotification ticket response. Comcast did not mark their lines. This is a subsequent offense.</p> <p>Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Emergency ticket 20252242294 was submitted on 8/12/2025 at 11:41 stating that an “unmarked cable communication line was damaged, either Comcast or Verizon”. Comcast responded on 8/12/2025 at 14:58 with “Insuff Info. Do Not Dig”. Lines were not marked. *Renotify ticket 2025150050-001 was submitted on 8/12/2025 at 8:10 a.m. The incident occurred over the 3 hour allowable time for a facility to mark their lines after submitting a renotify ticket. This is a subsequent offense.</p> <p>Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. *Emergency ticket 20252241070 was submitted on 8/12/2025 at 13:28. Comcast responded on 8/12/2025 at 14:54 “Insuff Info. Do Not Dig”. *Renotify ticket 2025150050-001 was submitted on 8/12/2025 at 8:10 a.m. *The incident occurred over the 3 hour allowable time for a facility to mark their lines after submitting a renotify ticket. following a renotify ticket. Plug Utilities waited 3 hours before excavation started. Comcast did not mark their lines. This is a subsequent offense.</p> <p>Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). Complex Project ticket. Complex Project ticket 20252102301 was submitted on 7/29/2025 at 12:05. The meeting was to be held on 8/01/2025. The response was due by 7/31/2025. Comcast did not respond until on 8/02/2025 when they responded “Clear”. No other communication was shared, and their</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>line was hit. 47 customers were verified to be without Comcast communication. This is a subsequent offense. Recommendation: The penalties are applied. The required education was recently completed.</p> <p>VERIZON</p> <p>Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Ticket 2025150050-000 was submitted by Plug Utilities on 8/03/2025 with a response due by 8/11/2025. Renotify ticket 2025150050-001 was submitted on 8/12/2025 at 8:10 a.m. stating that onsite markings are incomplete. Please return to complete the markings. Direct contact with excavator required within 2 hours. Ticket response due by 10:10 a.m. Verizon responded “field marked” late on 8/14/2025. This is a third offense.</p> <p>Section 2(5)(iii.1) – Facility owner failed to propose a mutually agreeable scheduling by which the excavator, facility owner or designer may locate the facilities. There are no comments or any more information in the Complex Project ticket 20252102301 responses. See attachment named: Complex Project ticket 20252102301 All Responses. This is a second time offense.</p> <p>Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Ticket 20252150050-000 was not marked out by Verizon, so renotify ticket 20252150050-001 was submitted stating that crew is on site and for Comcast and Verizon to please return and complete their markings. This is a subsequent violation.</p> <p>Section 2(5)(v) Failed to respond to ticket 20252150050 within the required amount of time. Ticket 20252150050-000 was requested by Plug Utilities on 8/03/2025 with a response due by 8/11/2025. Verizon did not respond until they responded “field marked” on 8/14/2025. This is a late response. This is a subsequent offense.</p> <p>Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Emergency ticket 20252243070 was submitted on 8/12/2025 at 13:28 stating “ customers are without Comcast service” Excavation began after the 3 hour required waiting period for a renotification ticket response. Verizon responded late on 8/13/2025 “Insuff Info. Do Not Dig”. *Renotify ticket 2025150050-001 was submitted on 8/12/2025 at 8:10 a.m. This occurred over the 2 hour allowable time for a facility to mark out following a renotify ticket. Plug Utilities waited 3 hours before excavation started. Verizon did not mark their lines. This is a subsequent violation.</p> <p>Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. *Emergency ticket 20252241070 was submitted on 8/12/2025 at 13:28. Verizon responded late on 8/13/2025 at 11:35 “Insuff Info. Do Not Dig”. *This occurred over the 2 hour allowable time. They did not mark their lines. This is over the 2 hour allowable time for a facility to mark out following a renotify ticket. Plug Utilities waited 3 hours before excavation started. Verizon did not mark their lines. This is a subsequent violation.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Emergency ticket 20252242294 was submitted on 8/12/2025 at 11:41 stating that an “unmarked cable communication line was damaged, either Comcast or Verizon”. Verizon did not responded until 8/13/2025 at 11:34 with “Insuff Info. Do Not Dig”. Lines were not marked. *This incident occurred over the 2 hour allowable time for a facility to mark out following a renotify ticket. Plug Utilities waited 3 hours before excavation started. Verizon did not mark their lines. This is a subsequent violation.</p> <p>Section 6.1(7) Project owner failed to submit an Alleged Violation Report within 30 days of a line strike or other violation. This is a subsequent violation.</p> <p>Section 9 - Common Ground Alliance (CGA) Best Practices 2-13 The project owner and design engineer take prudent measures to make the determination to use trenchless excavation installation. The project owner and design engineer coordinate with facility owners to design projects that maintain minimum radial clearances between the new facility and existing facilities. Minimum clearances are equal to or greater than applicable standards. There are no design drawings that were submitted through the OneCall System for this Complex Project with 2 phases, using trenchless excavation. This is a third time offense.</p> <p>Recommendation: The penalties are applied. The required education has recently been completed.</p> <p>DUQUESNE LIGHT CO is in violation of: Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). Complex project ticket 20252102301 was submitted on 7/29/2025 at 12:05. The meeting was to be held on 8/01/2025. The response was due by 7/31/2025. Duquesne Light Company did not respond until 8/01/2025 they will not attend the meeting. Recommendation: The penalty is applied. Education is required.</p>	
58438	<p>Facility Owner: COMCAST</p> <p>Contractor/Excavator: BRIAN SCHMUCKER GENERAL CONTRACTOR</p> <p>Project Owner: West Penn Power</p>	<p><u>On 8/12/2025 10:40:00 AM at WESTCHESTER DR, NORTH HUNTINGDON TWP, WESTMORELAND</u> The incident occurred on 8/12/2025, at 10:40 AM, on Westchester Dr, in North Huntingdon Twp, Westmoreland County.</p> <p>A cable tv line owned by Comcast was damaged.</p> <p>Comcast is the facility owner. Their Alleged Violation Report (AVR) has no Summary or comments, but does list 51+ customers lost services for 1-6 hours. The attached images show the line marked on 8-5-2025, and then after the damage occurred and was repaired, on 8-18-2025. The area and marks are shown. The damaged line is indicated by a hit kit pylon, but the line itself is not shown. Additional information was requested to show the damaged line. One photo was provided showing an unearthed line, but the image is zoomed in and the location cannot be determined. Comcast stated that was the only image they could provide.</p>	<p>BRIAN SCHMUCKER GENERAL CONTRACTOR: \$1,000.00 Section 5(9) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Brian Schmucker General Contractor is the excavator. An AVR has not been filed as of 10/01/2025.</p> <p>West Penn Power is the project owner. An AVR has not been filed as of 10/01/2025.</p> <p>Ticket # 20252170464 New – Excavation– Emergency was entered by Brian Schmucker General Contractor for “INSTL NEW ELECTRIC LINE” for one week at location “BERWYN PA. START AT 949 WESTCHESTER DR, EXTENDING IN THE FRONT YARD TO 909 W CHESTER DR.” No information is provided to show that this meets the definition of Emergency.</p> <p>"Emergency" means a sudden or unforeseen occurrence involving a clear and immediate danger to life, property or the environment, including, but not limited to, serious breaks or defects in a facility owner's lines.</p> <p>*The location of the damage in relation to the marks could not be determined by the information provided*</p> <p>Violations: Excavator - Brian Schmucker General Contractor: Section 5(9) – Emergency notification does not meet the requirements of “emergency” as defined in Section 1 – Excavator Ticket. Ticket # 20252170464 Recommendation: PUC Online Compliance Training is required.</p>	
57504	<p>Facility Owner: PEOPLES GAS COMPANY Contractor/Excavator: Independent Enterprises Project Owner: Pittsburgh Water</p>	<p><u>On 8/12/2025 1:20:00 PM at ORANMORE ST, PITTSBURGH CITY, ALLEGHENY</u> PNG- penalty and violation has been removed. See attachments *****</p> <p>The incident occurred on Tuesday, August 12, 2025, on Oranmore Street, in Pittsburgh City, Allegheny County.</p> <p>A gas line was damaged.</p> <p>Peoples Gas Company stated in their alleged violation report (AVR), on 8/12/2025, Independence Enterprises was working to repair sewer lines and laterals for Pittsburgh Water, when they struck a mismarked PNG SL main to curb, SL mismarked by 3'.</p> <p>Peoples Gas stated in an email, there was a gas leak and Independence Enterprises called 911. Peoples Gas provide photos of the mismarked damaged line. Independence Enterprises did not submit an AVR.</p> <p>Violations:</p> <p>*Peoples Gas Company is in violation of section: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation Penalty Applied</p> <p>*Independence Enterprises is in violation of section: 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line.</p>	<p>PEOPLES GAS COMPANY: \$0.00</p> <p>Independent Enterprises: \$1,500.00 Section 5(16) 2nd Offense \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		Recommendation: PUC Compliance Education Required and Penalty Applied	
57514	<p>Facility Owner: Central Electric Cooperative</p> <p>Contractor/Excavator: Susco</p> <p>Project Owner: Armstrong</p> <p>Designer: Armstrong - Placeholder</p>	<p><u>On 8/12/2025 4:08:00 PM at SHINGLE OAK LN, FRANKLIN TWP, BUTLER</u> The incident occurred on 8/12/2025, at 4:08 PM, on Shingle Oak Ln, in Franklin Twp, Butler County.</p> <p>An electric line owned by Central Electric Cooperative Inc was damaged.</p> <p>Central Electric Cooperative Inc is the facility owner. Their Alleged Violation Report (AVR) states, “SUSCO, LLC was directional boring fiber optic cable for Armstrong along Shingle Oak Ln in Butler County Franklin Twp. on 8/12/25. At 16:21, SUSCO's directional bore hit one of Central Electric Cooperative's secondary underground service lines. This damage resulted in a service outage to a cooperative member(consumer). Central Electric's lines had been located and marked prior to this incident. Repairs were necessary to restore power to the member.” “Line was located on 7-23-25 using an electronic cable locator by an employee of Central Electric Cooperative. Red paint and flags were used to mark the lines. Lines are visible in the images attached just beside the incident area. In addition, transformer that provides power to customer whose service line was damaged, is readily visible with red locate marks coming from it across the road where the line was hit. Photos with 8-21-2025 in the title were taken after damage was repaired to give reference to photos taken on day of the incident. Marks are still clearly visible though slightly faded around the damage location. Also shown are pictures of the damage from the cross bore that needed to be repaired. Included is a very rudimentary map of the site with objects that can be referenced in the images. Line was hit where contractor was boring was within the 18"tolerance zone as seen in the image with our locate mark shown at the bottom and the damage cone and measurement tape (2025-08-13_10-02-59_283).”</p> <p>Susco is the excavator. Their AVR states, “drilling at address 405 shingle oak lane hit an unmarked power line”.</p> <p>Armstrong is the project owner and designer. An AVR has not been filed as of 09/26/2025.</p> <p>Multiple photos of the site, both before and after damage, were submitted. Faded marks are seen crossing the road, which appear to be orange and match orange flags in the grass area. The damage occurred close to the road but in the grass, between 2 sets of marks crossing the road, but the damaged line was not within 18” of these marks. No red marks are visible in pre-damage photos (see August 7th photos of the site).</p> <p>Vibrant red marks are seen on 8-13-2025, which is after the damage occurred, and after Ticket # 20252244375 (New – Damage – Emergency entered on 8/12/25 at 5:47</p>	<p>Central Electric Cooperative: \$500.00</p> <p>Section 2(5)(i) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>PM) was entered in which the lines would have been marked. There are no images that show the damage lines were marked within 18” prior to the damage occurring.</p> <p>This case is related to Case #055068 by tickets.</p> <p>Violations: Facility - Central Electric Cooperative Inc: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: PUC Online Compliance Training is required.</p>	
57516	<p>Facility Owner: North Fayette County Mun. Auth. Contractor/Excavator: Verizon North Project Owner: Verizon North - Placeholder Other: GEORGES TOWNSHIP</p>	<p><u>On 8/13/2025 9:45:00 AM at 2850 MORGANTOWN RD, GEORGES TWP, FAYETTE</u> The incident occurred on 8/13/2025, at 9:45 AM, on 2850 Morgantown Rd, in Georges Twp, Fayette County.</p> <p>A water line owned by North Fayette County Municipal Authority was damaged.</p> <p>North Fayette County Municipal Authority is the facility owner. Their Alleged Violation Report (AVR) states, “Verizon Wireless hit our 12" water main while drilling a 24" hole inside our tolerance zone. Verizon hit our line and left once we responded. They never called 811 to report the damage, I submitted the damage report.”</p> <p>Verizon North is the excavator and project owner. An AVR has not been filed as of 09/26/2025.</p> <p>Images submitted show the site, marks, and damage. Blue marks are seen at the site, with the excavation and damage occurring within the tolerance zone of those marks. The damaged line is shown with noticeable auger marks on the line.</p> <p>Ticket #20252251864 New – Damage – Emergency: Georges Township did not respond. Ticket # 20252241034 New – Excavation– Emergency: Georges Township did not respond. Ticket # 20252251826 New – Excavation– Emergency: Georges Township did not respond.</p> <p>Violations: Excavator – Verizon: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: PUC Online Compliance Training is required. Facility(other) - Georges Township: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket # 20252251826</p>	<p>Verizon North: \$1,500.00 Section 5(4) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>GEORGES TOWNSHIP: \$1,000.00 Section 2(5)(vii) 1st Offense \$1,000.00</p> <p>Section 2(5)(vii) 1st Offense \$0.00</p> <p>Section 2(5)(vii) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket # 20252241034</p> <p>Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket #20252251864</p> <p>Recommendation: PUC Online Compliance Training is required.</p>	
57817	<p>Facility Owner: National Fuel GAS</p> <p>Contractor/Excavator: Marsh Heating and Cooling</p>	<p><u>On 8/13/2025 1:00:00 PM at 7140 US 322, CRANBERRY TWP, VENANGO</u> The incident occurred on 8/13/2025 at 7140 US 322 in Cranberry Township in Venango Co.</p> <p>A gas main owned by National Fuel Gas was hit and damaged.</p> <p>NATIONAL FUEL GAS stated in their Alleged Violation Report (AVR) that “Excavator damaged natural gas distribution main line. National Fuel discovered excavator working without a POCS ticket on 8/4/2025. National Fuel advised excavator to submit a POCS ticket request. National Fuel marked out facilities in the meantime. It was then discovered on 8/13/2025 that the excavator had damaged the main line when National Fuel responded to a POCS locate request at the same address and for a different excavator. Please see attachments”.</p> <p>Marsh Heating and Cooling did not submit an AVR or a OneCall ticket. Research results noted that Marsh Heating and Cooling has placed OneCall notifications in the past.</p> <p>VIOLATIONS</p> <p>Marsh Heating and Cooling is in violation of:</p> <p>Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe.</p> <p>Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area.</p> <p>Section 5(7) – Failed to immediately report to the facility owner any break or leak in its lines, or any dent, gouge, groove, or other damage to such lines or to their coating or cathodic protection</p> <p>Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or damaging a facility owner’s line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.</p> <p>Recommendation: The penalty is applied. Education is required.</p>	<p>Marsh Heating and Cooling: \$3,250.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(7) 1st Offense \$1,000.00</p>
57744	<p>Facility Owner: UGI UTILITIES INC</p> <p>Contractor/Excavator: KINSLEY CONSTRUCTION LLC</p> <p>Project Owner: MOUNT JOY TOWNSHIP</p>	<p><u>On 8/14/2025 8:33:00 AM at ABERDEEN RD, MOUNT JOY TWP, LANCASTER</u> The incident occurred on Thursday, August 14, 2025, on Aberdeen Road, in Mount Joy Township, Lancaster County.</p> <p>A gas wire was damaged.</p>	<p>UGI UTILITIES INC: \$2,000.00</p> <p>Section 2(5)(i) Subsequent \$2,000.00</p> <p>Comcast: \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>Designer: Lancaster Civil Engineering Company Other: Comcast</p>	<p>UGI Utilities stated in their Alleged Violation Report (AVR), excavator, Kinsley Construction utilizing mechanized equipment, struck and unmarked anode wire.</p> <p>Kinsley Construction stated in their AVR, the crew was milling blacktop and came upon a gas line tracer wire, the depth was 11-inches. Active ticket and no markings to indicate underground utilities; marks were elsewhere on the job.</p> <p>The designer, Lancaster Civil Engineering Company; representing the project owner, Mount Joy Township, stated in their AVR, a gas line tracer wire, approximately 11 inches deep, was damaged during milling of existing roadway/shoulder. There was an active ticket and no markings to indicate underground utilities in this area. There were One Call marks elsewhere on the project. The facility owner, UGI repaired the damaged line/wire prior to installation of stone subbase and asphalt.</p> <p>Photos were provided showing the damage. 20252191353- Routine ticket placed on 8/7/2025, UGI respond as Clear No Facilities. 20252260408- Damage Emergency ticket placed on 8/14/2025 at 8:11am, UGI responded as Field Marked. 20250381665- Final Design ticket placed on 2/7/2025 at 1:13pm. No Response from Comcast.</p> <p>Violations:</p> <p>*UGI Utilities is in violation of section: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: Penalty Applied *Comcast is in violation of section: 2(4) – Failed to respond to designer’s request for information within 10 business days. 20250381665 Recommendation: Penalty Applied</p>	<p>Section 2(4) Subsequent \$1,500.00</p>
57503	<p>Facility Owner: Veolia Water Contractor/Excavator: Miller Pipeline Project Owner: UGI Other: Comcast</p>	<p><u>On 8/14/2025 8:39:00 AM at N 6TH ST, SUSQUEHANNA TWP, DAUPHIN</u> UGI provided documentation on communication with excavator, and approval of mark out schedule. Violations withdrawn. ***** The incident occurred on 8/14/2025, at 8:39 AM, on N 6Th St, in Susquehanna Twp, Dauphin County.</p> <p>A water line owned by Veolia Water Pennsylvania Inc was damaged.</p> <p>Veolia Water Pennsylvania Inc is the facility owner. Their Alleged Violation Report (AVR) states, “miller pipe hit a unmarked service line”.</p> <p>Miller Pipeline is the excavator. Their AVR states, “crew was digging to install gas main for UGI. The crew came into contact with a unmarked 1" steel water service causing damage. The crew called 811, facility owner and all proper notifications. the water company came out to run a new water service”</p>	<p>Veolia Water: \$1,500.00 Section 2(5)(i) 3rd Offense \$1,500.00</p> <p>UGI: \$0.00</p> <p>Comcast: \$2,000.00 Section 2(5)(vii) 3rd Offense \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>UGI is the project owner and designer. Their AVR states, "Contractor states 'crew was digging to install gas main for UGI. The crew came into contact with a unmarked 1" steel water service causing damage. The crew called 811, facility owner and all proper notifications. the water company came out to run a new water service'."</p> <p>Ticket#20252172661 had an original response due date of 8/7/2025. UGI responded "conflict" on 8/7/2025 at 3:32PM, and then - Scheduled date and time lines will be marked by: Aug 11 2025 – on 8/8/2025 at 6:43 AM. A renotify was entered on 8/8/2025 at 7:05 AM which stated, "Attn ugi, you did respond with a conflict, caller stated the markings are incomplete for the gas main. Locater only marked 150ft of the gas main. Please respond asap to recheck and complete the markings for gas main. Please see crew on site if any questions." UGI did not respond to the renotify. UGI entered Field Marked on 8/11/2025 to the Routine and Renotify ticket.</p> <p>Ticket#20252172662 had an original response due date of 8/7/2025. UGI responded "conflict" on 8/7/2025 at 3:30 PM. A renotify was entered on 8/8/2025 at 7:05 AM. UGI responded field marked at 1:07PM.</p> <p>Ticket # 20252260537 New – Damage – Emergency was entered on 8/14/25 at 8:39 AM. Comcast responded "Clear" on 8/29/2025.</p> <p>Violations:</p> <p>Facility - Veolia Water: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: PUC Online Compliance Training is required.</p> <p>Facility (other) – UGI Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Ticket#20252172662-001 Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Ticket#20252172661-001 Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket#20252172661-000 Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket#20252172662-000 Recommendation: PUC Online Compliance Training is required.</p> <p>Facility (other) – Comcast: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket # 20252260537 Recommendation: PUC Online Compliance Training is required.</p>	
58409	Facility Owner: Comcast Contractor/Excavator: UNDERGROUND	<u>On 8/15/2025 10:00:00 AM at MEADOWBROOK DR, ABINGTON TWP, MONTGOMERY</u> The incident	Comcast: \$4,500.00 Section 2(5)(i) Subsequent \$2,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>COMMUNICATIONS TECHNOLOGIES Project Owner: Lamberts Cable Splicing</p>	<p>occurred on Friday, August 15, 2025, on Meadowbrook Drive, in Abington Township, Montgomery County.</p> <p>Comcast fiber line was damaged.</p> <p>Underground Communications Technologies stated in their alleged violation report (AVR), on Friday, 8/15/2025, at approximately 10am, our crew working in the Meadowbrook Apartments when unmarked Comcast fiber line was hit. Comcast only located their old copper lines and never marked the newer fiber line; this was relayed to them when the project started. They were on site to repair the fiber line before we knew it was damaged. Damage occurred on side of building 21. Only the old copper lines were marked approx. 6-feet up from the curb. They didn't know there was fiber in that section. The line we hit was a new conduit placed along the curb.</p> <p>Underground Communications Technologies provided photos of the damaged line and locate marks.</p> <p>Violations:</p> <p>*Comcast is in violation of sections: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. 20251910540, 20252122664 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work.</p> <p>Recommendation: Penalties Applied, and PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).</p>	<p>Section 2(10) Subsequent \$2,500.00</p>
57736	<p>Facility Owner: UGI UTILITIES, INC. Contractor/Excavator: NOLDER EXCAVATING Project Owner: Catasauqua Borough Other: BARKER & BARKER PAVING</p>	<p><u>On 8/18/2025 10:19:00 AM at Bridge St., CATASAUQUA BORO, LEHIGH</u> The incident occurred on Monday, August 18, 2025, on Bridge Street, in Catasauqua Borough, Lehigh County.</p> <p>UGI Utilities gas line was damaged.</p> <p>UGI stated in their alleged violation report (AVR), Nolder Excavating was digging without a PA One Call Ticket. When digging they struck a gas facility creating a damage and a leak. Nolder Excavating was piggybacking off another PA One Call Routine Ticket, 20252172730.</p> <p>Nolder Excavating called 911 and the Fire Department arrived at the worksite.</p> <p>Routine ticket, 20252172730, was placed on 8/5/2025, by Barker & Barker Paving, working for Catasauqua Borough, to remove and replacing sidewalk.</p> <p>Nolder Excavating placed a Routine ticket, 20252312962, on 8/19/2025; the day after the damage, working for Barker & Barker Paving, to install sidewalk.</p>	<p>NOLDER EXCAVATING: \$2,000.00 Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>UGI provide photos of the damaged gas line. Nolder Excavating did not submit an AVR.</p> <p>Violations:</p> <p>*Nolder Excavating is in violation of sections: 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: PUC Compliance Education Required and Penalties Applied</p>	
57612	<p>Facility Owner: VERIZON PA LLC</p> <p>Contractor/Excavator: PLUG UTILITIES</p> <p>Project Owner: VERIZON PA LLC</p> <p>Other: Hemlock Farms Community Association</p> <p>Other: PPL Electric Utilities</p>	<p><u>On 8/18/2025 12:15:00 PM at BROADMOOR DR, BLOOMING GROVE TWP, PIKE</u> Removed PPL Electric penalty and violation. See attachment *****</p> <p>The incident occurred on Monday, August 18, 2025, on Broadmoor Drive, in Blooming Grove Township, Pick County.</p> <p>Verizon PA LLC line was damaged.</p> <p>Plug Utilities, working for Verizon, stated in their alleged violation report (AVR) that they were installing conduit when the crew struck an unmarked Verizon cable line. Consequently, the crew interrupted the service line at 139-141 Broadmoor Drive. Plug Utilities provided photos of the mismarked, damaged cable. Verizon PA LLC did not submit an AVR.</p> <p>20252302666- Excavation Emergency placed on 8/18/2025 at 12:43pm, Plug Utilities placed the ticket as a Damage Emergency. Location Information-- front of 139 and 141 Broadmoor Drive- Verizon service line has been exposed and damaged. No Response from Hemlock Farms Community Association</p> <p>20252234615-001- Renotify Excavation Insufficient ticket placed on 8/18/2025 at 11:27am. Remarks-- [ATTN PPL ELECTRIC UTILITIES CORPORATION, YOU HAVE RESPONDED AS FIELD MARKED FOR THIS SITE HOWEVER THE CREW ON SITE HAS INFORMED THE CALLER THAT THERE IS AN ELEC COVER FOR A MANHOLE AT THE INTERSECTION OF BROADMOOR DRIVE AND WHIPPLE TREE LANE THAT IS EXPOSED WITH WIRES INSIDE OF IT THAT HAS NOT BEEN MARKED OUT. PLEASE REVISIT THE SITE AND MARK YOUR LINES THAT ARE ASSOCIATED WITH THIS MANHOLE SO THAT EXCAVATION CAN SAFELY CONTINUE. IF YOU HAVE ANY QUESTIONS PLEASE REACH OUT TO THE ONSITE CONTACT. THANK YOU]</p> <p>20251982235- Complex Project meeting ticket placed 7/17/2025. No Response from Hemlock Farms Community Association</p>	<p>VERIZON PA LLC: \$3,000.00 Section 2(5)(i) Subsequent \$2,000.00</p> <p>Section 2(10) 1st Offense \$1,000.00</p> <p>Hemlock Farms Community Association: \$1,500.00 Section 2(5)(vii) 1st Offense \$1,000.00</p> <p>Section 2(5)(viii) 1st Offense \$500.00</p> <p>PPL Electric Utilities: \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Violations:</p> <p>*Verizon PA LLC is in violation of sections: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: Penalties Applies</p> <p>*Hemlock Farms Community Association is in violation of sections: 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20252302666 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project. 20251982235 Recommendation: PUC Compliance Education Required and Penalties Applied</p> <p>*PPL Electric Utilities is in violation of sections: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. 20252234615 Recommendation: Penalty Applied</p>	
57686	<p>Facility Owner: LANCASTER CITY WATER - LU</p> <p>Contractor/Excavator: KINSLEY CONSTRUCTION LLC</p> <p>Project Owner: UGI UTILITIES INC.</p> <p>Other: COMCAST</p> <p>Other: FRONTIER COMMUNICATIONS OF PA INC</p> <p>Other: LANCASTER CITY ELECTRIC TRAFFIC</p> <p>Other: Rettew Associates Inc</p> <p>Other: VERIZON</p>	<p><u>On 8/18/2025 11:00:00 PM at 1138 MANHEIM PIKE, MANHEIM TWP, LANCASTER</u> The incident occurred on 8/18/2025 at 1138 MANHEIM PIKE in Manheim Township in Lancaster County.</p> <p>A water service line owned by LANCASTER CITY OF WATER was damaged.</p> <p>LANCASTER CITY OF WATER submitted 2 Alleged Violation Reports (AVR) which both stated that “contractor hit a water service line while digging. Lines were marked”. Pictures were provided. They added that the excavator did not use prudent techniques in the tolerance zone. On 9/02/2025 DPI Maki asked if the service line was owned by the city or private. City of Lancaster Water sent an email on 9/09/2025 that the damage was on the facility owners service side, not the customers side.</p> <p>KINSLEY CONSTRUCTION LLC stated in their AVR that “ On 08/18/2025, Collin Snyder was using the bucket of the mini-x to smooth out the bottom of an excavation when he struck an unmarked water line. 811 was notified and the utility owner, Lancaster City Water, responded to the job site to make the necessary repairs. Pictures were provided. They added that the lines were not marked. On 9/02/2025 DPI Maki sent an email asking if there was a mutual agreement for the late mark outs of some of the facility owners. An email was received on 9/04/2025 from Kinsley Construction stating that Lancaster City Water to mark out by 26 JUL 25, but they never cleared the ticket. On 9/10/2025 Kinsley</p>	<p>LANCASTER CITY WATER - LU: \$250.00 Section 2(5)(i.1) 1st Offense \$250.00</p> <p>COMCAST: \$4,000.00 Section 2(5)(v.1) 1st Offense \$500.00</p> <p>Section 2(5)(iii.1) 2nd Offense \$500.00</p> <p>Section 2(5)(v.1) 1st Offense \$500.00</p> <p>Section 2(5)(i) Subsequent \$2,000.00</p> <p>Section 2(5)(iii.1) 2nd Offense \$500.00</p> <p>FRONTIER COMMUNICATIONS OF PA INC: \$2,500.00 Section 2(5)(iii.1) 1st Offense \$250.00</p> <p>Section 2(5)(i) 2nd Offense \$1,000.00</p> <p>Section 2(5)(v.1) 1st</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>added that “we were in communication with UGI, but we were not given any information from Lancaster City Water. Also, the water line was unmarked”.</p> <p>UGI UTILITIES INC stated in their AVR that “Contractor states 'Operator was using bucket of mini-x to smooth out the bottom of an excavation when he struck an unmarked water line. 811 was notified and the utility owner, Lancaster City Water, responded to the job site to make the necessary repairs.' No project information was provided. They added that there was a failure to locate the point of connection to the facility lines.</p> <p>TICKET 20252024845 DETAILS</p> <p>*Ticket 20252024845-000 was submitted by Kinsley Construction on 7/21/2025 at 19:21, with a response due by 7/23/2025. On 7/27/2025 *renotification ticket 20252024845-001 was submitted which stated that 1 of 3 tickets are being submitted and to “contact for copy of plans”. RNO Remarks: ATTN VERIZON, COMCAST, FRONTIER, AND LANCASTER CITY ELEC THERE IS A POLEWITHCOMMUNICATION LINES THAT LEAD UG AND NONE OF THEM ARE MARKED. PLEASECOME TO THE SITE ASAP AND MARK THESE OUT. Direct contact was required with the excavator within 2 hours. Also see company detailed responses under violations.</p> <p>Lancaster City Water scheduled a mark out to be completed by 7/26/2025. An email was received on 9/04/2025 stating that Lancaster City Water had an agreement to mark out late, agreement was to mark out by 26 JUL 25. Please note that communication needs to be in writing.</p> <p>UGI did not respond until 7/24/2025, when they gave a scheduled time of 7/31/2025 that they will mark the lines. Kinsley stated that they were in communication with UGI. Please note that communication needs to be in writing.</p> <p>TICKET 20252024846 DETAILS</p> <p>*Ticket 20252024846-000 was submitted by Kinsley Construction on 7/21/2025 at 19:20, with a response due by 7/23/2025.</p> <p>*Renotify ticket 20252024846-001 was submitted by Kinsley Construction on 7/27/2025 at 20:08, with a response due by 7/27/2025. Remarks: ATTN VERIZON, COMCAST, FRONTIER, AND LANCASTER CITY ELEC THERE IS A POLE WITH COMMUNICATION LINES THAT LEAD UG AND NONE OF THEM ARE MARKED. PLEASE COME TO THE SITE ASAP AND MARK THESE OUT. Direct contact with excavator is required within 2 hours.</p> <p>VIOLATIONS</p> <p>LANCASTER CITY WATER – LU is in violation of: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.</p>	<p>Offense \$500.00</p> <p>Section 2(5)(v.1) 1st Offense \$500.00</p> <p>Section 2(5)(iii.1) 1st Offense \$250.00</p> <p>LANCASTER CITY ELECTRIC TRAFFIC: \$1,500.00</p> <p>Section 2(5)(v.1) 1st Offense \$500.00</p> <p>Section 2(5)(iii.1) 1st Offense \$250.00</p> <p>Section 2(5)(v.1) 1st Offense \$500.00</p> <p>Section 2(5)(iii.1) 1st Offense \$250.00</p> <p>VERIZON: \$5,000.00</p> <p>Section 2(5)(iii.1) 2nd Offense \$500.00</p> <p>Section 2(5)(v.1) 2nd Offense \$1,000.00</p> <p>Section 2(5)(iii.1) 2nd Offense \$500.00</p> <p>Section 2(5)(v.1) 2nd Offense \$1,000.00</p> <p>Section 2(5)(i) Subsequent \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Recommendation: The penalty is applied. Facility owner training was recently completed.</p> <p>COMCAST is in violation of: Section 2(5)(iii.1) – Facility owner failed to propose a mutually agreeable scheduling by which the excavator, facility owner or designer may locate the facilities. Ticket 20252024845 - Comcast marked “clear” on 7/23/2025, but on 7/27/2025 “scheduled mark” and field marked on 7/28/2025. This was not in mutual agreement. This is a second offense. Section 2(5)(iii.1) – Facility owner failed to propose a mutually agreeable scheduling by which the excavator, facility owner or designer may locate the facilities. 20252024846 This is a second offense. Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. This is a subsequent offense. Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. 20252024845 Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. *Renotify ticket 20252024846 - Comcast responded, “filed marked” on 7/23/2025, then on 7/27/2025 they “scheduled mark” and finally “field marked” on 7/28/2025 at 16:14. Recommendation: The penalty is applied. Facility owner training was recently completed.</p> <p>FRONTIER COMMUNICATIONS OF PA INC is in violation of: Section 2(5)(iii.1) – Facility owner failed to propose a mutually agreeable scheduling by which the excavator, facility owner or designer may locate the facilities. Ticket 20252024845 - Frontier Communication marked “clear” on 7/23/2025, but on 7/27/2025 “scheduled mark” and field marked on 7/28/2025. This was not in mutual agreement. Section 2(5)(iii.1) – Facility owner failed to propose a mutually agreeable scheduling by which the excavator, facility owner or designer may locate the facilities. 20252024846 Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. 20252024845 Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. *Renotify Ticket 20252024846 - Frontier Communications did not “filed mark” until 7/28/2025 at 16:14.</p> <p>Recommendation: The penalties are applied. Facility owner training is required.</p> <p>LANCASTER CITY ELECTRIC TRAFFIC is in violation of: Section 2(5)(iii.1) – Facility owner failed to propose a mutually agreeable scheduling by which the excavator, facility owner or designer may locate the facilities. *Ticket 20252024845 - Lancaster City Electric “field</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>marked” on 7/22/2025, but after the renotification responded on 8/08/2025 with “clear no facilities”. This was not in mutual agreement.</p> <p>Section 2(5)(iii.1) – Facility owner failed to propose a mutually agreeable scheduling by which the excavator, facility owner or designer may locate the facilities.</p> <p>Ticket 20252024846 -</p> <p>Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Ticket 20252024845 - Lancaster City Electric did not respond until 8/08/2025 at 6:42 am</p> <p>Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Ticket 20252024846 - Frontier Communications responded “clear no facilities” on 7/23/2025 and on did not “filed mark” until 7/28/2025 at 16:14.</p> <p>Recommendation: The penalties are applied. Facility owner training is required.</p> <p>VERIZON is in violation of:</p> <p>Section 2(5)(iii.1) – Facility owner failed to propose a mutually agreeable scheduling by which the excavator, facility owner or designer may locate the facilities.</p> <p>Ticket 20252024845 - Verizon responded “field marked” on 7/22/2025 but were asked to mark their lines when ticket 20252024845-001 was submitted. They then did not respond by the due date of 7/27/2025 on the renotify ticket, but “filed marked” on 7/28/2025. This is a second offense.</p> <p>Section 2(5)(iii.1) – Facility owner failed to propose a mutually agreeable scheduling by which the excavator, facility owner or designer may locate the facilities.</p> <p>20252024846 This is a second offense.</p> <p>Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. This is a subsequent offense. Verizon is asked to mark out their lines in ticket 20252024845-001</p> <p>Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. 20252024845 This is a second offence.</p> <p>Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Ticket 20252024846 - Verizon did not “field mark” until 7/28/2025 at 8:03.</p> <p>This is a second offence.</p> <p>Recommendation: The penalties are applied. Facility owner training was recently completed.</p>	
57768	<p>Facility Owner: Peoples Natural Gas</p> <p>Contractor/Excavator: Independent Enterprises Inc</p> <p>Project Owner: Pittsburgh Water</p> <p>Designer: GAI</p> <p>Other: Comcast</p>	<p>On 8/19/2025 7:15:00 AM at FAIRLEE ST, PITTSBURGH CITY, ALLEGHENY The incident occurred on 8/19/2025, at 7:15 AM, on Fairlee St, in Pittsburgh City, Allegheny County.</p> <p>A gas line owned by Peoples Gas Company was damaged.</p> <p>Peoples Gas Company is the facility owner. Their Alleged Violation Report (AVR) states, “On 8/19/2025, Independent Enterprises was digging to install water mains and services when they struck an accurately marked PNG SL main to curb.”</p>	<p>Independent Enterprises Inc: \$2,000.00 Section 5(4) Subsequent \$2,000.00</p> <p>Comcast: \$2,000.00 Section 2(5)(vii) 3rd Offense \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Independent Enterprises is the excavator. Their AVR states, "The contractor was excavating for new 8" mainline. When operator pulled back rd base gas line was snagged Josh Lozecki Foreman called 911 at 7:16am. Firemen arrived @ 7:20am. People's gas arrived @ 8:20am. Gas restored @ 9:20am"</p> <p>Pittsburgh Water is the project owner. Their AVR states the same information in the summary as Independent Enterprises' AVR.</p> <p>G A I Consultants is the designer. An AVR has not been filed as of 10/14/2025.</p> <p>Images submitted show the site, marks, and damaged line. The damaged line is within the tolerance zone of the yellow marks. The images show the damage line at 7:26AM and the dirt immediately around the line has not been excavated. At 9:09AM the 8" water line has been installed, stone has been spread, and water line caution tape is visible under the repaired gas line.</p> <p>Ticket #20252310346 New – Damage – Emergency was entered on 8/19/25. Comcast responded "Clear" on 8/29/2025.</p> <p>Ticket #20252053856 New – Excavation – Routine had a response due date of 7/30/2025. Peoples Gas responded "Field Marked" on 7/31/2025. Verizon responded "Clear" on 8/6/2025. Comcast responded "Clear" on 8/29/2025. These are addressed on Case #057764.</p> <p>This case is related to the following cases by tickets: 057007, 057069, 057305, 057764</p> <p>Violations: Excavator – Independent Enterprises: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements.</p> <p>Facility(other)-Comcast: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket #20252053856 Recommendation: PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).</p>	
58396	<p>Facility Owner: COLUMBIA GAS OF PA INC_Central Contractor/Excavator: BAIANO CONSTRUCTION INC Project Owner: PITTSBURGH CITY</p>	<p><u>On 8/19/2025 11:00:00 AM at 218 CHESTON ST, PITTSBURGH CITY, ALLEGHENY</u> The incident occurred on Tuesday, August 19, 2025, at 218 Cheston Street, in Pittsburgh City, Allegheny County.</p> <p>A gas line was damaged.</p>	<p>BAIANO CONSTRUCTION INC: \$1,500.00 Section 5(4) 3rd Offense \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	DEPT OF PUBLIC WORKS	<p>Baiano Construction, Inc (BCI) and the project owner, The City of Pittsburgh stated in their alleged violation report's (AVR), a gas service line was damaged at 218 Cheston Street. The line was slightly kinked as debris were removed from around it. This line was right on the edge of the tolerance zone and could have gone either way. No disruption of service or leakage took place. The proper facility owner was notified and Columbia Gas reported to the worksite. The facility was found safely beforehand and again while removing debris it was slightly kinked and breaking it, but warranted a call and repair.</p> <p>Columbia Gas stated in their AVR, BCI, working on behalf of the City of Pittsburgh, under a valid One Call routine ticket for roadway reconstruction. BCI struck and damaged a marked 1" inserted plastic gas service line during excavation. Columbia Gas was promptly notified and responded to the scene. All necessary safety checks were completed, and the damaged line was repaired by Columbia Gas.</p> <p>Photos were provided of the damaged line.</p> <p>Violation:</p> <p>*Baiano Construction, Inc is in violation of section: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.</p> <p>Recommendation: Penalty Applied</p>	
57741	<p>Facility Owner: COLUMBIA GAS</p> <p>Contractor/Excavator: Casper Colosimo & Son, Inc.</p> <p>Project Owner: Pennsylvania American Water (PAWC)</p> <p>Other: Comcast</p>	<p><u>On 8/20/2025 11:30:00 AM at PETUNIA STREET, PITTSBURGH CITY, ALLEGHENY</u> The incident occurred on 8/20/2025, at 11:30 AM, on Petunia Street, in Pittsburgh City, Allegheny County.</p> <p>A gas line owned by Columbia Gas was damaged.</p> <p>Columbia Gas is the facility owner. Their Alleged Violation Report (AVR) states, "While working on behalf of PA American Water to replace water lines, Casper Colosimo and Sons Inc. (CCSI) damaged a correctly marked 2-inch plastic medium pressure gas main. The damage occurred while mechanized equipment was being operated within the tolerance zone. Emergency services (911) and Columbia Gas were immediately notified and responded to the scene. Columbia Gas service technicians conducted all required safety checks, and the crew successfully repaired the damaged gas main. No customers were impacted by the incident."</p> <p>Casper Colosimo And Son is the excavator. Their AVR states, "Casper Colosimo crew run by Mike Petrilli Jr was installing a new ¾" water service line from the curb box at house number 1630 Petunia St to the new water main that we had just installed on the other side of the street. There was a 4" plastic gas main that ran parallel to our new main throughout the project that we vacuum test pitted many times. While excavating across the street towards the 4" gas main we struck and damaged an unmarked 2" plastic gas main. The closest mark was</p>	<p>COLUMBIA GAS: \$1,000.00 Section 2(5)(i) 2nd Offense \$1,000.00</p> <p>Comcast: \$4,000.00 Section 2(5)(vii) 3rd Offense \$2,000.00</p> <p>Section 2(5)(vii) 3rd Offense \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>28” away from the unmarked 2” main line. This 2” main was out of the tolerance zone and there was no indication of the 2” gas main on any part of the project.”</p> <p>Pennsylvania American Water is the project owner and designer. Their AVR states, “Casper Colosimo crew run by Mike Petrilli Jr was installing a new ¾” water service line from the curb box at house number 1630 Petunia St to the new water main that we had just installed on the other side of the street. There was a 4” plastic gas main that ran parallel to our new main throughout the project that we vacuum test pitted many times. While excavating across the street towards the 4” gas main we struck and damaged an unmarked 2” plastic gas main. The closest mark was 28” away from the unmarked 2” main line. This 2” main was out of the tolerance zone and there was no indication of the 2” gas main on any part of the project.”</p> <p>Images submitted show the site, marks, lines, and damage. There is a yellow mark indicating a 4” line, and the line is shown and exposed. The line that was damaged was close to the 4” line but the exact distance cannot be determined by the images submitted. The damaged line is listed as a 2" line in the AVRs. The damaged line was not marked.</p> <p>Ticket #20252322155 New – Excavation– Emergency was entered on 8/20/25 – Comcast responded “Clear” on 8/29/2025.</p> <p>Ticket # 20252322048 New – Damage – Emergency was entered on 8/20/25 – Comcast responded “Clear” on 8/29/2025.</p> <p>Violations: Facility – Columbia Gas: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: PUC Online Compliance Training is required. Facility(other) – Comcast: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket #20252322155 Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket # 20252322048 Recommendation: PUC Online Compliance Training is required.</p>	
57956	Facility Owner: UGI Contractor/Excavator: Leeward Construction Project Owner: PENNSYLVANIA AMERICAN WATER Designer: PENNSYLVANIA AMERICAN WATER - Spacesaver	<p><u>On 8/21/2025 7:40:00 AM at S LINCOLN AVE, SCRANTON CITY, LACKAWANNA</u> UGI's violation for 2(5)(i.1) was removed because it is the wrong violation. This violation is for customer owned lines. UGI should have been cited for failure to mark their own line within 18 inches. ***** The incident occurred on 8/21/2025 on S. Lincoln Ave in Scranton City in Lackawanna County.</p>	<p>UGI: \$0.00</p> <p>Leeward Construction: \$1,000.00 Section 5(16) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>A Gas service line was hit and damaged.</p> <p>PENNSYLVANIA AMERICAN WATER stated in their Alleged Violation Report (AVR) that “LEEWARD CONST WAS DIGGING EXCCAATOR WAS WELL OVER 2 FEET OFF MARKS WHEN THEY HIT GAS GOING TO HOUSE 140-142 @ 7:40 AM PHIL CALL 911 @ 7:42 AM SCRANTION WAS ON SITE @7:50 AM UGI WAS ON SITE BY 8:00 AM TO 10:00 AM TO FIX SERVICE LINE”. 911 was notified. Reports were provided.</p> <p>UGI UTILITIES INC stated in their AVR that “Excavator struck and damaged a mismarked gas facility”. 911 was notified. Pictures and reports were provided.</p> <p>Leeward Construction the excavator did not submit an AVR.</p> <p>VIOLATIONS UGI is in violation of: Section 2(5)(i.1) – Failed to locate an actually known facility’s point of connection to its facilities. This is a third time offense. Recommendation: The penalty is applied. The required education was recently completed.</p> <p>Leeward Construction is in violation of: Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or damaging a facility owner’s line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: The penalty is applied. Education is required. The required education due by 8/13/2024 and another that was due by 6/12/2023 was never completed.</p>	
57837	<p>Facility Owner: Aqua Contractor/Excavator: WILSON EXCAVATING AND UTILITY CONSTRUCTION LLC Project Owner: Aqua - Spacesaver Designer: WALLACEPANCHER GROUP Other: SHEFFLER AND COMPANY</p>	<p><u>On 8/21/2025 9:45:00 AM at REED ST, SHARON CITY, MERCER</u> The incident occurred on 8/21/2025 on Reed St in Sharon City in Mercer County.</p> <p>A Water main line owned by the project owner Aqua, was hit and damaged.</p> <p>WILSON EXCAVATING AND UTILITY CONSTRUCTION LLC the excavator stated in their Alleged Violation Report (AVR) that “Wilson Excavating was performing work for Aqua in Sharon when an unmarked/mismarked Aqua line was struck and damaged. The crew was installing new water main to replace the existing on Reed Street near house #409. The unmarked/mismarked water line crossed into the trench for the new water line and was struck by the excavator. Facility owner was notified. Pictures and reports were provided.</p> <p>AQUA PENNSYLVANIA INC the project owner and facility owner stated in their AVR that “Aqua Contractor Wilson Excavating was performing work for Aqua in</p>	<p>Aqua: \$1,000.00 Section 2(5)(i) 2nd Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Sharon when an unmarked/mismarked Aqua line was struck and damaged. The crew was installing new water main to replace the existing on Reed St near house #409. The unmarked/mismarked water line crossed into the trench for the new water line and was struck by the excavator. Facility owner was notified". No pictures were provided.</p> <p>WALLACEPANCHER GROUP is the designer.</p> <p>VIOLATIONS Aqua is in violation of: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. This is a second offense. Recommendation: The penalty is applied. The required education was recently completed.</p>	
57970	<p>Facility Owner: Peoples NATURAL Gas Contractor/Excavator: A Folino Construction Project Owner: PITTSBURGH WATER (FORMERLY PWSA)</p>	<p><u>On 8/22/2025 8:30:00 AM at 6919 KELLY ST, PITTSBURGH CITY, ALLEGHENY</u> The incident occurred on 8/22/2025 at 6919 KELLY ST in Pittsburgh City in Allegheny County.</p> <p>No One call ticket was submitted. An abandoned gas line was hit.</p> <p>PEOPLES GAS COMPANY LLC the facility owner stated in their Alleged Violation Report (AVR) that "A Folino doing street restoration for Pittsburgh Water and Sewer Authority struck and damaged an abandoned Peoples Gas line while working without a One Call request. There was no gas in the line". No pictures were provided.</p> <p>A FOLINO CONSTRUCTION the excavator stated in their AVR that "A. Folino Construction was digging to prep to pour new road base when we hit a gas service line. 911 was called. Peoples Gas responded and claimed the line as theirs. Peoples Gas determined it was abandoned and went to an abandoned lot". 911 is noted as notified. Pictures were provided.</p> <p>PWSA is the project owner. AVR request letter was not sent.</p> <p>VIOLATIONS Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Recommendation: The penalty is applied. The required excavator training was recently completed.</p>	<p>A Folino Construction: \$1,000.00 Section 5(2.1) 1st Offense \$1,000.00</p>
58962	<p>Facility Owner: Aqua PA Contractor/Excavator: WILSON EXCAVATING AND UTILITY CONSTRUCTION LLC Project Owner: AQUA - SPACESAVER</p>	<p><u>On 8/25/2025 10:00:00 AM at REED ST, SHARON CITY, MERCER</u> The incident occurred on 8/25/2025 on Reed St in Sharon City in Mercer County.</p> <p>A Water service line was damaged.</p> <p>WILSON EXCAVATING AND UTILITY CONSTRUCTION LLC the excavator stated in their Alleged Violation Report (AVR) that "Wilson was performing work for Aqua when a mismarked Aqua water service was struck about 5 feet from where it was</p>	<p>Aqua PA: \$500.00 Section 2(5)(i.1) 1st Offense \$250.00</p> <p>Section 2(5)(i.2) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>marked. The facility owner was notified. Pictures were provided.</p> <p>AQUA PENNSYLVANIA INC the project owner and facility owner stated in their AVR that “Aqua Contractor Wilson Excavating, struck a mismarked Aqua water service line about 5 feet from where it was marked. The facility owner was notified. AVR filed when information was received”. They added that they had missing or incorrect facility line maps. No pictures or reports were provided.</p> <p>VIOLATIONS AQUA PENNSYLVANIA INC is in violation of: Section 2(5)(i.1) – Failed to locate an actually known facility’s point of connection to its facilities. Section 2(5)(i.2) – Failed to document Communications between a Facility Owner and Excavator to ensure the excavator is aware of a facility owner’s inability to locate it’s facilities. Recommendation: The penalties are applied. Facility owner training is required.</p>	
57900	<p>Facility Owner: COMCAST</p> <p>Facility Owner: PEOPLES GAS COMPANY LLC</p> <p>Contractor/Excavator: PLUG UTILITIES</p> <p>Project Owner: VERIZON PA LLC</p> <p>Designer: PIKE TELECOM</p> <p>Other: West Mifflin Borough</p>	<p><u>On 8/26/2025 12:09:00 PM at 149 and 138 SHARA DR, WEST MIFFLIN BORO, ALLEGHENY</u> The incident occurred on Tuesday, August 26, 2025, at 149, 138 Shara Drive, in West Mifflin Borough, Allegheny County.</p> <p>A gas line at 149 Shara Drive, and a communication line at 138 Shara Drive were damaged.</p> <p>Plug Utilities damaged a Peoples Gas line. Plug Utilities stated in their alleged violation report (AVR), while installing conduit; working for Verizon, the crew struck a gas line. The crew was about 24 inches deep when they interrupted the service line at address 149 Shara Drive. There were visible marks across the road from where the crew was working. The video shows where damage occurred.</p> <p>Peoples Gas stated in their AVR, on 8/26/2025, Plug Utilities failed to renotify 811 that their original plan of work had changed to across the street near 149 Shara Drive, West Mifflin. As agreed, in complex project PNG was to mark facilities along predetermined drawing for utility install and white marks. Plug Utilities moved across the street and struck PNG main to curb. This area was not marked by PNG locators due to agreements made at complex meeting. Plug Utilities called 911 and 811, and PNG crews arrived onsite and made repairs. 2 - 10 customer's service was interrupted for 6 - < 12 hours, 8 HOMES HAD TO BE EVACUATED, and the Fire and Police Departments responded to the 911 call to the worksite, and traffic was stopped.</p> <p>Plug Utilities and Peoples Gas provided photos, and Plug Utilities provided a video.</p> <p>20252261355- Routine ticket placed on 8/14/2025, with Location Information: BEGIN AT THE FRONT OF 101 SHARA DR AND CONTINUE TO 100 SHARA AND</p>	<p>COMCAST: \$3,000.00 Section 2(5)(vii) 2nd Offense \$1,500.00</p> <p>Section 2(10) 2nd Offense \$1,500.00</p> <p>PLUG UTILITIES: \$250.00 Section 5(20) 1st Offense \$250.00</p> <p>West Mifflin Borough: \$2,000.00 Section 2(5)(vii) 1st Offense \$1,000.00</p> <p>Section 2(5)(vii) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>THE REST OF THE EVEN NUMBERED HOUSES UP TO THE FRONT OF 150 SHARA DR. APPROXIMATELY 1225 FT. MARK FROM THE EDGE TO 25FT BEHIND THE EDGE. PLEASE MARK A 50 FT RADIUS AT BOTH INTERSECTIONS WITH SHOPE DR AND MELODY DR. PLEASE USE PAINT AND FLAGS AS WELL.</p> <p>20252382631- Gas Damage Emergency ticket placed on 8/26/2025, at 12:18pm. No Response from West Mifflin Borough.</p> <p>Plug Utilities damaged a Comcast line. Plug Utilities stated in their AVR, while installing conduit, a customer came out complaining of being out of service by Comcast. The exact location where the damage occurred is unknown. The crew was digging between 18-48 inches deep when they interrupted the service at address 138 Shara Drive.</p> <p>Plug Utilities provided photos show communication locate marks, but the photos cannot determine where the damage occurred and/or if the line was mis-marked. Comcast did not submit an AVR.</p> <p>20252383118- Cable TV Damage Emergency ticket placed on 8/26/2025, at 1:28pm. No Responses from: WEST MIFFLIN BOROUGH, and COMCAST responded late on 8/28/25 as Field Marked.</p> <p>Violations:</p> <p>*Plug Utilities is in violation of section: 5(20) – Excavator failed to renotify One Call of an unmarked or incorrectly marked facility upon arrival at a work site. Recommendation: PUC Compliance Education Required and Penalty Applied</p> <p>*Comcast is in violation of sections: 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20252383118 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. 20252383118 Recommendation: Penalties Applied</p> <p>*West Mifflin Borough is in violation of sections: 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20252382631 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20252383118 Recommendation: PUC Compliance Education Required and Penalties Applied</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
58274	<p>Facility Owner: Knox Energy Coop (Utility Pipeline)</p> <p>Contractor/Excavator: WILSON EXCAVATING AND UTILITY CONSTRUCTION LLC</p> <p>Project Owner: Aqua America</p> <p>Designer: GHD INC</p>	<p><u>On 8/27/2025 8:45:00 AM at SR 6, MOUNT JEWETT BORO, MCKEAN</u> Aqua provided additional information and their violation was reduced from \$250 to a warning of \$0. *****</p> <p>The incident occurred on 8/27/2025, at 8:45 AM, on SR 6, in Mount Jewett Boro, Mckean County.</p> <p>A gas line owned by Knox Energy was damaged.</p> <p>Knox Energy Coop (Utility Pipeline) is the facility owner. An Alleged Violation Report (AVR) has not been filed as of 10/10/2025. They responded to Ticket#20252330820 “Field Marked”.</p> <p>Wilson Excavating is the excavator. Their AVR states, “Wilson Excavating was performing work for Aqua on Route 6 in Mt Jewett when a mismarked Utility Pipeline gas line was struck and damaged. The crew was digging to install a fire hydrant when they struck a 2" plastic gas main with the excavator. The closest mark was 23 feet away from the gas main. Facility owner notified and 911 was called.”</p> <p>Aqua America is the project owner. Their AVR states, “Aqua Contractor Wilson Excavating was performing work for Aqua on Route 6 in Mt Jewett when a mismarked Utility Pipeline gas line was struck and damaged. The crew was digging to install a fire hydrant when the struck a 2" plastic gas main with the excavator. The closest mark was 23 feet away from the gas main. Facility owner notified and 911 was called.”</p> <p>GHD Inc is the designer. Their AVR states, “Gasline damaged during new watermain installation - See attached report”.</p> <p>Images of the site, excavation, damage, and marks are shown. There are no yellow marks near the damage. The closest mark is red and is over 24” away.</p> <p>Ticket #20252330820 New – Excavation – Routine had a response due date of 8/25/2025. Aqua responded “Field Marked” on 8/26/2025 at 8:46 AM.</p> <p>Ticket # 20252330819 was included during the Initial Research by PA One Call and is not relevant to this investigation.</p> <p>This case is related to #058060 by tickets</p> <p>Violations: Facility – Knox Energy Coop (Utility Pipeline): Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a</p>	<p>Knox Energy Coop (Utility Pipeline): \$1,500.00 Section 2(5)(i) 1st Offense \$500.00</p> <p>Section 2(10) 1st Offense \$1,000.00</p> <p>Aqua America: \$0.00 Section 2(5)(v) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>violation of this act has been committed in association with excavation or demolition work. Recommendation: PUC Online Compliance Training is required. Facility(other) – Aqua: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket #20252330820 Recommendation: PUC Online Compliance Training is required.</p>	
57988	<p>Facility Owner: UGI UTILITIES INC Contractor/Excavator: J F Kiely Construction Project Owner: UGI UTILITIES INC</p>	<p><u>On 8/27/2025 10:51:00 AM at N STEVENS ST, SHINGLEHOUSE BORO, POTTER</u> The incident occurred on Wednesday, August 27, 2025, on N. Stevens Street; near Academy Street, in Shinglehouse Borough, Potter County.</p> <p>UGI Utilities, Inc gas line was damaged.</p> <p>JF Kiely Construction stated in their alleged violation report (AVR), our crew damaged a mismarked gas line that was 3ft off the marks with a horizontal directional drilling machine on N. Stevens Street, in front of 604 Academy Street.</p> <p>UGI stated in their AVR, while directional drilling, JF Kiely Construction struck and damaged an unmarked main. There were two 2-in steel mains in the area, one was abandoned and one was live. Locator had marked abandoned main and excavator had spotted abandoned main before drilling. There was no record of abandonment of a main in area.</p> <p>Violation:</p> <p>*UGI Utilities, Inc is in violation of section: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: Penalty Applied</p>	<p>UGI UTILITIES INC: \$2,000.00 Section 2(5)(i) Subsequent \$2,000.00</p>
57999	<p>Facility Owner: PETROLEUM VALLEY REGIONAL WATER AUTHORITY Other: PennDOT</p>	<p><u>On 8/28/2025 12:00:00 PM at Haysville Rd @ Hooker Rd, FAIRVIEW TWP, BUTLER</u> The incident occurred on 8/28/2025, at 12:00 PM, on Haysville Rd, in Fairview Twp, Butler County.</p> <p>A water line owned by Petroleum Valley Regional Water Authority was damaged.</p> <p>Petroleum Valley Regional Water Authority is the facility owner. Their Alleged Violation Report (AVR) states, “PENNDOT graded the sides of the roadways without a PA One Call and hit/damaged PVRWA water valves.”</p> <p>PennDOT submitted an AVR which states, “A shoulder cutting operation was being performed on SR 1013 in Butler County and an unmarked water line above the ground was struck, within our right of way. There was no excavation being performed, just grading shoulders.”</p> <p>Images submitted show that PennDOT was performing minor routine maintenance. The term excavation, under</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		Act 127 of 2024, does not include minor routine maintenance.	
58258	<p>Facility Owner: UGI UTILITIES INC</p> <p>Contractor/Excavator: Verizon Pennsylvania LLC</p> <p>Project Owner: Verizon Pennsylvania LLC</p>	<p><u>On 8/29/2025 11:59:00 PM at N. PENN ST., PALMYRA BORO, LEBANON</u> The incident occurred on Friday, August 29, 2025, on N. Penn Street, in Palmyra Borough, Lebanon County.</p> <p>UGI Utilities gas line was damaged.</p> <p>UGI stated in their alleged violation report (AVR), Verizon Pennsylvania LLC drove a long pin into the ground 1' away from yellow marks. The Excavator had failed to use prudent techniques within the established tolerance zone. As a result, the 2" PLA gas main was punctured resulting in a release of gas. The 2"PLA main inserted in 4" CI was marked accurately. The Excavator drove long pin into ground 1' away from marks and struck gas mainline.</p> <p>UGI provided photos of the damaged line. Verizon PA LLC called 911 and 811, 2-10 customers service was interrupted for 1 - < 6 hours, and the Fire Department responded to the 911 call and to the worksite.</p> <p>Verizon PA LLC did not submit an AVR. An Excavation Emergency ticket was placed on 8/29/2025, by Verizon PA LLC to replace 3 poles and Install 1 anchor.</p> <p>Violations:</p> <p>*Verizon PA, LLC is in violation of sections: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. 5(9) – Emergency notification does not meet the requirements of “emergency” as defined in Section 1 – Excavator Ticket. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: Penalties Applied, and PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements.</p>	<p>Verizon Pennsylvania LLC: \$2,500.00 Section 5(4) 1st Offense \$500.00</p> <p>Section 5(9) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>
58235	<p>Facility Owner: VERIZON</p> <p>Contractor/Excavator: Caddick Utilities LLC</p> <p>Project Owner: AQUA PENNSYLVANIA INC</p> <p>Designer: BRANDYWINE CAD DESIGN INC</p>	<p><u>On 9/2/2025 10:00:00 AM at ROBIN RD, UWCHLAN TWP, CHESTER</u> The incident occurred on 9/02/2025 on Biddle Rd., near the intersection of Robin Rd in UWCHLAN TWP in Chester Co.</p> <p>2 Communication lines were damaged.</p> <p>CADDICK UTILITIES LLC stated in their Alleged Violation Report (AVR) that “Damaged 2 unmarked telecom lines. No response crews showed up”. Pictures and reports were provided.</p> <p>AQUA PENNSYLVANIA INC stated in their AVR that “Aqua Contractor Caddick Utilities damaged 2 unmarked telecom lines. No response crews showed up. - 128 Biddle Rd”. Reports were provided.</p> <p>VIOLATIONS</p>	<p>VERIZON: \$7,500.00 Section 2(5)(v) Subsequent \$1,000.00</p> <p>Section 2(5)(vii) Subsequent \$2,500.00</p> <p>Section 2(5)(i) Subsequent \$2,000.00</p> <p>Section 2(5)(ix) 3rd Offense \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. This is a subsequent offense.</p> <p>*Ticket 20252302874 -000 was submitted by Caddick Utilities on 8/18/2025 at 13:10 with a response due by 8/20/2025. Work in progress remark lines. Location specified to mark all sides of the road including 150’ of the intersection from Whitford Rd. to Biddle Rd. Verizon responded “field marked” on 8/22/2025.</p> <p>Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. This is a subsequent offense.</p> <p>*Renotify Ticket 20252302874 - 001 was submitted by Caddick Utilities on 9/02/2025 at 9:08 with a response due by 11:08, and excavation permitted by 12:08. Ticket noted: SPECIAL ATTN VERIZON, YOU RESPONDED MARKED, HOWEVER, CALLER STATES YOUR MARKINGS ARE INCOMPLETE. PLEASE RETURN TO SITE FOR FURTHER MARKINGS. Verizon never responded to this renotify ticket until 9/03/2025 at 17:22.</p> <p>Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. This is a subsequent offense.</p> <p>*Emergency ticket 20252452058 was submitted by CADDICK UTILITIES LLC on 9/02/2025 at 11:28. Verizon never responded. All other communication companies responded “clear”.</p> <p>Section 2(5)(ix) – Facility owner failed to respond promptly to the site of an excavation where its underground line was damaged. Both AVR’s that were submitted state that No Verizon response crews showed up. This is a third time offense.</p> <p>Recommendation: The penalties are applied. The Required facility owner education has been recently completed.</p>	
58189	<p>Facility Owner: Peoples Gas Contractor/Excavator: Mele & Mele & Sons Project Owner: Pittsburgh Water Designer: Johnson, Mirmiran and Thompson (JMT)</p>	<p><u>On 9/3/2025 8:50:00 AM at THOMAS BLVD, PITTSBURGH CITY, ALLEGHENY</u> The incident occurred on 9/3/2025, at 9:00 AM, on Thomas Blvd, in Pittsburgh City, Allegheny County.</p> <p>A gas line owned by Peoples Gas was damaged.</p> <p>Peoples Gas is the facility owner. Their Alleged Violation Report (AVR) states, “Mele and Mele and Sons working for Pittsburgh Water and Sewer struck and damaged a Peoples Gas service line, pulling it from the main line, while using mechanized equipment within the tolerance zone.”</p> <p>Mele And Mele And Sons is the excavator. Their AVR states, “The utility was hit while digging out the service line for 218 N Dallas Ave. There was a gas curb box directly behind the water curb box. Gas line was marked out by one call. Laborers were being utilized to watch while digging but the service line did a 180° coming directly out of the top of the main. Operator just caught the tooth of his bucket on the steel service line. Foreman notified 911 at 8:55 am. CM was notified at this time of the ongoing incident. Smell of gas was strong in the</p>	<p>Mele & Mele & Sons: \$1,000.00 Section 5(4) 2nd Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>proximity of the excavation area, so stop work was called. Pittsburgh Fire on site at 9:06 am. They then notified People's Gas. At 9:10 am, People's supervisor arrived on site to assess the damage. He used a wooden stake and some rags to plug the leaking main. People's repair crew on site at 9:45 am to begin repairing gas line. Mele contractors were given the option to keep working on a different service location down the street but opted to wait for People's to make their repair. No crew time was paid out during this time. People's made their repair by 12:15 pm and Mele continued working on water service replacement at this time.”</p> <p>Pittsburgh Water is the project owner. Their AVR states, “The utility was hit while digging out the service line for 218 N Dallas Ave. There was a gas curb box directly behind the water curb box. Gas line was marked out by one call. Laborers were being utilized to watch while digging but the service line did a 180° coming directly out of the top of the main. Operator just caught the tooth of his bucket on the steel service line. Foreman notified 911 at 8:55 am. CM was notified at this time of the ongoing incident. Smell of gas was strong in the proximity of the excavation area, so stop work was called. Pittsburgh Fire on site at 9:06 am. They then notified People's Gas. At 9:10 am, People's supervisor arrived on site to assess the damage. He used a wooden stake and some rags to plug the leaking main. People's repair crew on site at 9:45 am to begin repairing gas line. Mele contractors were given the option to keep working on a different service location down the street but opted to wait for People's to make their repair. No crew time was paid out during this time. People's made their repair by 12:15 pm and Mele continued working on water service replacement at this time.”</p> <p>J M T is the designer. Their AVR has the same information as Pittsburgh Water and adds the following, “The gas curb box and service line were unable to be located during quality level B Utility Designation, and utilities were shown on the drawings as per the survey delineations provided to JMT. PNG provided records do not show the location of gas service lines.”</p> <p>Images submitted show the site, marks, and damage. Excavation and damaged line are in the tolerance zone of the marks.</p> <p>Violations: Excavator – Mele and Mele and Sons Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: PUC Online Compliance Training is required.</p>	
58211	Facility Owner: Columbia gas Contractor/Excavator: A. Liberoni Project Owner: Whitehall Borough	<u>On 9/3/2025 2:00:00 PM at SOUTH PASSAGE DR, WHITEHALL BORO, ALLEGHENY</u> The incident occurred on 9/3/2025, at 2:00 PM, on 5091 South Passage Dr, in Whitehall Boro, Allegheny County.	Columbia gas: \$1,000.00 Section 2(5)(i) 2nd Offense \$1,000.00 Whitehall Borough: \$1,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>Designer: THE GATEWAY ENGINEERS INC</p>	<p>A gas line owned by Columbia Gas was damaged. The facility was notified and 911 was contacted.</p> <p>Columbia Gas is the facility owner. Their Alleged Violation Report (AVR) states, “While working for Whitehall Borough, a crew from A. Liberoni drove a concrete pin through a correctly marked company-side gas service line. Columbia Gas was notified and responded promptly to secure the site and complete all necessary repairs.”</p> <p>A Liberoni Inc is the excavator. Their AVR states, “The gasline was hit while driving a concrete pin that held curb forms in place , but didn't leak until the pin was pulled out. The Locators paint markings were off by 2 foot and the line was 8 inches below the roadway. see attached photo.”</p> <p>Images provided show the site, marks, and damaged line. The mark shown is faded and the pin was not in the tolerance zone of the mark, as shown using a measuring tape. After the line was unearthed it is shown to be in the same location as the pin was in previous images. In the image showing the line, the closer mark to the damage was removed with the road surface while uncovering the damaged line, but a further back mark is shown. Measurements are not provided in the images when the line is shown.</p> <p>Whitehall Borough is the project owner. An AVR has not been filed as of 10/01/2025.</p> <p>The Gateway Engineers Inc is the designer. Their AVR has no summary.</p> <p>Ticket #20252464173 New – Excavation– Emergency was entered on 9/3/25. Whitehall Borough responded “Clear” on 9/10/2025.</p> <p>Violations: Facility - Columbia Gas: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: PUC Online Compliance Training is required. Project Owner and Facility – Whitehall Borough: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket #20252464173 Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. – This violation has been reduced from a \$1000 penalty to a warning of \$0. Recommendation: PUC Online Compliance Training is required.</p>	<p>Section 2(5)(vii) 1st Offense \$1,000.00</p> <p>Section 6.1(7) 1st Offense \$0.00</p>
58214	<p>Facility Owner: Peoples Natural Gas Contractor/Excavator: SUPERIOR UTILITY EXCAVATING INC</p>	<p><u>On 9/5/2025 10:17:00 AM at 317 BRUSH CREEK RD, HEMPFIELD TWP, WESTMORELAND</u> Peoples violation and penalty removed after providing communication documents. *****</p>	<p>Peoples Natural Gas: \$0.00</p> <p>SUPERIOR UTILITY</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>Project Owner: Peoples Natural Gas - Spacesaver Designer: Peoples - Spacesaver Other: EADS GROUP Other: Kriebel Minerals Inc. Other: WESTMORELAND COUNTY MUNICIPAL AUTHORITY</p>	<p>Kriebel Minerals Inc. provided information that they are not a facility owner as they only operate production lines from stripper wells. Violation and penalty withdrawn.</p> <p>WESTMORELAND COUNTY MUNICIPAL AUTHORITY disputed. They submitted additional information with their dispute. The violations were withdrawn.</p> <p>*****</p> <p>The incident occurred on 9/05/2025 at 317 Bush Creek Rd in Hempfield Township in Westmoreland Co.</p> <p>A gas distribution line was damaged.</p> <p>PEOPLES NATURAL GAS COMPANY LLC stated in their Alleged Violation Report (AVR) that “SUPERIOR UTILITY EXCAVATING INC was digging to install new gas mains and services when they struck a 1" plastic service line. Line was spotted, contractor pulled on service. Plastic was replaced. address was 317 Brush creek rd”. 1 Customer was affected. 911 was not notified. The Gas inspector was on site at the time of the damage.</p> <p>SUPERIOR UTILITY EXCAVATING INC stated I their AVR that “New gas service line was being installed next to the existing gas service line. The locate marks for the existing gas service line were disturbed when the gravel was moved to the side to be saved and reused in the trench. The marks were lost when the gravel was moved. The gas service line was shut off at the curb by the PNG Inspector. The repair was made to the existing service line”. 911 was not called. Reports and pictures were provided.</p> <p>VIOLATIONS Peoples Natural Gas is in violation of: Section 2(5)(i.2) – Failed to document Communications between a Facility Owner and Excavator to ensure the excavator is aware of a facility owner’s inability to locate it’s facilities. Ticket 20252374210 was requested by SUPERIOR UTILITY EXCAVATING INC on 8/25/2025 with a response due by 8/28/2025. Peoples Gas responded “scheduled mark by 8/27/2025, and “field marked” on 9/02/2025, There is no written communication showing a mutual agreement for this late mark out. Recommendation: The penalty is applied. The required education was recently completed.</p> <p>SUPERIOR UTILITY EXCAVATING INC is in violation of: Section 5(11.2) – When using trenchless technology, Excavator failed to utilize at a minimum, the best practices published by the Common Ground Alliance (CGA) 9 (5-20) Excavation within the tolerance zone: Practice Statement: When excavation is to take place within the specified tolerance zone, the excavator exercises such reasonable care as may be necessary for</p>	<p>EXCAVATING INC: \$750.00 Section 5(11.2) 1st Offense \$500.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p>Kriebel Minerals Inc.: \$0.00</p> <p>WESTMORELAND COUNTY MUNICIPAL AUTHORITY: \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>the protection of any underground facility in or near the excavation area. Methods to consider, based on certain climate or geographical conditions, include potholing, hand digging when practical, soft digging, vacuum excavation methods, pneumatic hand tools, other mechanical methods with the approval of the facility owner/operator, or other technical methods that may be developed.</p> <p>Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area.</p> <p>Recommendation: The penalty is applied. Education is required. The required education was due by 7/13/2025 and has not been completed as of 10/07/2025.</p> <p>Kriebel Minerals Inc. is in violation of: Section 2(5)(iii.1) – Facility owner failed to propose a mutually agreeable scheduling by which the excavator, facility owner or designer may locate the facilities. Ticket 20252374210 was requested by SUE inc on 8/25/2025 with a response due by 8/27/2025. Kriebel Minerals Inc responded “Insufficient Info” on 8/27/2025 with no further written communication. Recommendation: The penalty is applied. Education is required.</p> <p>WESTMORELAND COUNTY MUNICIPAL AUTHORITY is in violation of: Section 2(5)(iii.1) – Facility owner failed to propose a mutually agreeable scheduling by which the excavator, facility owner or designer may locate the facilities. Ticket 20252374210 was requested by SUE inc on 8/25/2025 with a response due by 8/27/2025. WESTMORELAND COUNTY MUNICIPAL AUTHORITY responded “scheduled mark” on 8/27/2025 with no further written communication. - Withdrawn.</p> <p>Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). Complex Project ticket 20252253882 meeting was scheduled for 8/19/2025 at 10:00 a.m. Westmoreland County Municipal Authority responded that they will attend the meeting but are not on the CP sign-in sheet. There are no notes showing that there was any information shared. This is a second offense. - Withdrawn.</p>	
58529	<p>Facility Owner: Columbia Gas Contractor/Excavator: RJ Steele Other: Canonsburg Borough</p>	<p>On 9/6/2025 8:20:00 AM at 634 EUCLID AVE, CANONSBURG BORO, WASHINGTON Canonsburg Borough provided information after the dispute deadline. Their 2(5)(vii) violation is reduced from \$1000 to a warning of \$0. Columbia Gas violation 2(5)(vii) reduced from \$1500 to a warning of \$0. ***** The incident occurred on 9/6/2025, at 8:20 AM, on 634 Euclid Ave, in Canonsburg Borough, Washington County. A gas line owned by Columbia Gas was damaged.</p>	<p>Columbia Gas: \$0.00 Section 2(5)(vii) 2nd Offense \$0.00</p> <p>RJ Steele: \$2,250.00 Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Columbia Gas is the facility owner. Their Alleged Violation Report (AVR) states, “While attempting to work on a drainpipe, R J Steele damaged a 2-inch plastic medium pressure gas main using a backhoe. The contractor did not have a valid One Call ticket for this work; however, due to other nearby projects, locate marks were present on the ground. Additionally, a gas line marker was located approximately 13 feet from the point of damage, providing clear visual evidence of the gas line’s presence. 911 and Columbia Gas were notified and responded promptly. Columbia Gas’s plant department completed the necessary repairs, and a service technician conducted all required safety checks to ensure the site was secure.”</p> <p>R J Steele Construction. An AVR has not been filed as of 10/06/2025.</p> <p>No project owner or designer have been indicated.</p> <p>Images provided show the site, equipment, damage, and marks from the ticket called in by Columbia Gas for repairs. A pipeline pylon is partially visible in the images, and Google street view confirms there is a pylon at the excavation site (July 2025). Columbia Gas indicates a backhoe/trackhoe was used for excavation, which can be seen in the images. No tickets were located for this site and excavator.</p> <p>Ticket #20252490059 New – Excavation– Emergency was entered on 9/6/25 at 9:18 AM. This was for Columbia Gas to repair their damaged line. Canonsburg Borough responded “Clear” on 9/8/2025. Columbia Gas responded “Field Marked” on 9/8/2025.</p> <p>Violations: Excavator – R J Steele: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: PUC Online Compliance Training is required. Facility (other) – Columbia: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket #20252490059 Recommendation: PUC Online Compliance Training is required. Facility(other) - Canonsburg Borough: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket #20252490059</p>	<p>Canonsburg Borough: \$0.00 Section 2(5)(vii) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
58311	<p>Facility Owner: City of Allentown Contractor/Excavator: UGI Utilities, Inc. Project Owner: UGI - spacesaver</p>	<p>Recommendation: PUC Online Compliance Training is required.</p> <p><u>On 9/8/2025 12:10:00 PM at 1450 LIBERTY ST, ALLENTOWN CITY, LEHIGH</u> UGI disagrees. Violations section 5(6)(i) and 5(13) were withdrawn. On 12/12/2025 UGI accepted the violation section 5(11) and withdrew the request to meet with the Damage Prevention Committee (DPC). ***** The incident occurred on 9/08/2025 at 1450 LIBERTY ST in ALLENTOWN CITY in LEHIGH Co.</p> <p>A traffic conduit was damaged.</p> <p>UGI UTILITIES INC stated in their Alleged Violation Report (AVR) that “While excavating for natural gas, a UGI crew struck and damaged unmarked traffic light wires”. They added that This was a facility owner issue and that the facility owner failed to mark the point of connection. No pictures were provided.</p> <p>ALLENTOWN CITY OF stated in their AVR that “UGI drilled through an unmarked traffic conduit”. They added that this was a excavator issue and that UGI failed to provide the OneCall Sytem with exact information to identify the work site. They state that the service was interrupted for 12-24 hours. Pictures were provided. Ticket 20252381754 requests marking at address 1450 Liberty St. The corner addresses are 1452 and 1453 Liberty St. Ticket states that the area is not marked in white. Pictures show work is being done near the corner of the block.</p> <p>VIOLATIONS UGI is in violation of: Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. Section 5(11) – Excavator failed to use the color white to mark a proposed excavation work site when exact work site information cannot be provided. Section 5(13) – Excavator changed the location, scope, or duration of a proposed excavation without notifying the One call System. Recommendation: The penalties are applied. The required facility owner education was recently completed.</p>	<p>UGI Utilities, Inc.: \$250.00 Section 5(11) 1st Offense \$250.00</p>
58354	<p>Facility Owner: Columbia Gas Contractor/Excavator: Lindy Paving Project Owner: PennDOT Designer: The Markosky Engineering Group Inc</p>	<p><u>On 9/11/2025 10:30:00 AM at 511 Virginia Ave., ROCHESTER BORO, BEAVER</u> Lindy Paving - 5(4) violation reduced to a 1st offense violation of \$500. **** The incident occurred on 9/11/2025, at 10:30 AM, on 511 Virginia Ave., in Rochester Borough, Beaver County.</p> <p>A gas line owned by Columbia Gas was damaged.</p> <p>Columbia Gas is the facility owner. Their Alleged Violation Report (AVR) states, “Lindy Paving, working</p>	<p>Lindy Paving: \$1,500.00 Section 5(4) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>on behalf of PennDOT, struck and severed an accurately marked 1" PL company service line while excavating with a Gradall within the tolerance zone. The crew was removing hard surface material as part of a road reconstruction project. Emergency notifications were made immediately to 911, 811, and Columbia Gas. Columbia Gas responded promptly, secured the area, and completed all necessary repairs. This section of main had been daylighted with a hydro vac one week prior, with this specific address identified as having the shallowest service at a depth of 16.5 inches below the hard surface. Despite being fully aware of the service depths, Lindy Paving failed to excavate prudently and used mechanized equipment within the tolerance zone.”</p> <p>Lindy Paving is the excavator. An AVR has not been filed as of 10/06/2025.</p> <p>PennDOT is the project owner. Their AVR states, “Contractor hit gas service line at 511 Virginia Ave.”</p> <p>The Markosky Engineering Group Inc is the designer. An AVR has not been filed as of 10/06/2025.</p> <p>Images provided show the site, marks, and damage. A mark out image shows the yellow marks on the road. In damage images the road has been excavated and no marks are visible on the road, but the marks on the sides of the road are still visible and show where the line crosses. The damaged line is within the tolerance zone of the yellow marks, as shown using a hit kit.</p> <p>Violations: Excavator – Lindy Paving: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: PUC Online Compliance Training is required.</p>	
58616	<p>Facility Owner: Verizon Contractor/Excavator: Philadelphia Water Department Project Owner: Philadelphia Water Department - Placeholder</p>	<p>On 9/15/2025 11:00:00 AM at Kane rd, PHILADELPHIA CITY, PHILADELPHIA The incident occurred on 9/15/2025, at 11:00 AM, on Kane Rd, in Philadelphia City, Philadelphia County.</p> <p>A communications line owned by Verizon was damaged. Over 6500 customers were affected. The duration of service interruption was 24-48 hours.</p> <p>Verizon is the facility owner. Their Alleged Violation Report (AVR) states, “On September 15th, 2025, Verizon was notified that Philadelphia water department was excavating on Kane rd & knights rd in the city of Philadelphia without a permit or using the PA 1 call process to notify facility owners of their intention to replace a fire hydrant. The Philadelphia water department hit an 864 fiber that was ran that the location</p>	<p>Philadelphia Water Department: \$1,250.00 Section 5(2.1) 1st Offense \$1,000.00 Section 5(6)(i) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>in conduit causing a catastrophic failure knocking out service to over 6500 customers. Our technicians responded to the location to find them pumping water out of the area and the adjacent manholes that were being affected. Approx 2000 hrs PWD submitted an emergency locate request even though they had already dug and our technicians were already on site with the damaged cable, where they claimed they were hand digging when in fact they used a backhoe. Restoration took an additional 27 hours.”</p> <p>Philadelphia Water Department is the excavator and project owner. An AVR was not filed as of 09/23/2025. An AVR request letter was sent to PWD and they submitted one the same day. Their AVR has no summary.</p> <p>All information provided shows no ticket was submitted prior to this excavation. Images show the excavation and damaged lines. Philadelphia Water Department indicates a backhoe was used for excavation. An emergency excavation ticket was submitted by Philadelphia City Water at 8PM the same day after the damage. Philadelphia Water Department indicates in their AVR that they were using a trackhoe/backhoe for excavation.</p> <p>Violations: Excavator - Philadelphia Water Department: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. Recommendation: PUC Online Compliance Training is required.</p>	
58515	<p>Facility Owner: UGI Utilities Contractor/Excavator: Great Western Services</p>	<p><u>On 9/16/2025 10:20:00 AM at W MAIN ST, BATH BORO, NORTHAMPTON</u> The incident occurred on 9/16/2025, at 10:30 AM, on W Main St, in Bath Boro, Northampton County.</p> <p>A gas line owned by UGI was damaged. The facility was notified / not notified of the damage.</p> <p>UGI is the facility owner, project owner, and designer. Their Alleged Violation Report (AVR) states, “Great Western was digging to install new gas main and when digging they struck a unmarked gas service facility creating a damage and a leak. This service was not marked by locator.”</p> <p>Great Western Services is the excavator. Their AVR states, “While the crew was excavating to install 4" PE, the Operator struck and pulled a 3/4" PE medium pressure gas service on the north side of Main St. in front of 374 Main St. The service line was unmarked. When the gas started to leak from the service, the crew began evacuating the homes and apartments nearby. 911 was called. 911 was called. To stop the flow of gas, they</p>	<p>UGI Utilities: \$3,500.00 Section 2(5)(i) Subsequent \$2,000.00</p> <p>Section 2(5)(vii) 2nd Offense \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>shut off a valve on the west side of Northampton and Main St. This shut off gas to about 10 customers.”</p> <p>Pictures submitted show the site, marks, damage, and excavation. No images indicate the damage was within the tolerance zone of a mark.</p> <p>Ticket #20252591674 New – Damage – Emergency was entered on 9/16/25 at 10:39 AM. UGI responded “Field Marked” on 9/17/2025 at 6:39 AM.</p> <p>Violations:</p> <p>Facility – UGI: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket #20252591674 Recommendation: PUC Online Compliance Training is required.</p>	
58755	<p>Facility Owner: People's Gas Contractor/Excavator: J S BOVA EXCAVATING Project Owner: FORD CITY BOROUGH Designer: Stiffler McGraw</p>	<p><u>On 9/16/2025 12:59:00 PM at 6TH STREET, FORD CITY BORO, ARMSTRONG</u> The incident occurred on 9/16/2025, at 12:55 PM, on 6Th Street, in Ford City Boro, Armstrong County.</p> <p>A gas line owned by Peoples Gas was damaged.</p> <p>Peoples Gas is the facility owner. Their Alleged Violation Report (AVR) states, “our locator missed locating a service while locating the job for Bova”.</p> <p>J S Bova Excavating is the excavator. Their AVR states, “HIT AN UNMARKED GAS LINE ON 6TH ST THAT SERVICES HOUSE AT 600 4TH AVE. HOUSE SITS ON THE CORNER. THERE WERE NO MARKS ON 6TH”</p> <p>Ford City Borough is the project owner. Their AVR states, “Contractor hit unmarked gas service on 6th St for 600 4th Ave at 12:59. 911 and Peoples gas were both notified.”</p> <p>Stiffler McGraw is the designer. Their AVR states, “Contractor hit unmarked gas service on 6th St for 600 4th Ave at 12:59. 911 and Peoples gas were both notified.”</p> <p>This case is related by tickets to the following cases: 051368, 051438, 056687</p> <p>Violations: Facility – Peoples Gas: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).</p>	<p>People's Gas: \$2,000.00 Section 2(5)(i) Subsequent \$2,000.00</p>
58530	<p>Facility Owner: National Fuel</p>	<p><u>On 9/16/2025 3:00:00 PM at 752 BIG FOUR RD, GLADE TWP, WARREN</u> The incident occurred on</p>	<p>Homeowner: \$0.00 Section 5(4) 1st Offense</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>Contractor/Excavator: Homeowner</p> <p>Project Owner: Homeowner - placeholder</p>	<p>9/16/2025, at 3:00 PM, on 752 Big Four Rd, in Glade Twp, Warren County.</p> <p>A gas line owned by National Fuel Gas was damaged.</p> <p>National Fuel Gas is the facility owner. Their Alleged Violation Report (AVR) states, "Homeowner struck properly marked natural gas distribution service within the tolerance zone"</p> <p>Mike Sherrard is the homeowner, excavator, and project owner. An AVR has not been filed as of 10/17/2025.</p> <p>Images submitted show the site, marks, damage, and mechanized equipment used for excavation. The damage is in the tolerance zone of the marks.</p> <p>Violations: Excavator -Mike Sherrard: Section 5(4) – Homeowner failed to exercise due care and employ prudent excavation techniques. Section 5(16) – Homeowner Failed to submit an Alleged Violation Report within 30 days of striking a line. These violations are issued as warnings with no monetary penalty. PUC Online Compliance Training is required at: https://www.pa1call.org/enforcement</p>	<p>\$0.00</p> <p>Section 5(16) 1st Offense \$0.00</p>
58582	<p>Facility Owner: Peoples Natural Gas</p> <p>Contractor/Excavator: Konzel construction</p> <p>Project Owner: Blawnox Borough</p> <p>Other: Comcast</p>	<p><u>On 9/17/2025 7:55:00 AM at 1145 CABLE AVE, BLAWNOX BORO, ALLEGHENY</u> Update - Blawnox did not respond to Ticket #20252044630 by the response due date - violation 2(5)(v) *****</p> <p>Peoples provided additional information after the case was submitted. The violations are withdrawn. *****</p> <p>After the case was submitted, Blawnox Borough submitted an AVR on 10/30/2025. ****</p> <p>The incident occurred on 9/17/2025, at 7:55 AM, on 1145 Cable Ave, in Blawnox Boro, Allegheny County.</p> <p>A gas line owned by Peoples Natural Gas was damaged.</p> <p>Peoples Natural Gas is the facility owner. Their Alleged Violation Report (AVR) states, "On 9/17/2025, Konzel Construction struck an accurately marked 2" PNG PL ML. Konzel was digging for water job."</p> <p>Konzel Construction is the excavator. Their AVR states, "Digging a hole with a hydraulic excavator to install surge relief pipe out the side of a vault. Was aware of gas service running on side of drive way and gas service running along matter dr, no obvious marks marking the gas line next to the vault where we were digging. excavator tooth went into 2" plastic gas line at about a 4 ft depth."</p> <p>Borough Of Blawnox is the project owner. An AVR has not been filed as of 10/17/2025.</p>	<p>Peoples Natural Gas: \$0.00</p> <p>Blawnox Borough: \$250.00 Section 2(5)(v) 1st Offense \$250.00</p> <p>Section 6.1(7) 1st Offense \$0.00</p> <p>Comcast: \$2,000.00 Section 2(5)(v) Subsequent \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Images submitted show the site, marks, excavation equipment, and damage. The damage occurred directly beside a water vault as you can see the concrete vault in the damage photos. Images show there were no marks at the water vault to indicate the presence of the line that was damaged.</p> <p>Ticket #20252044631 New – Excavation – Routine had a response due date of 7/25/2025. Comcast responded “Clear” to the ticket on 8/29/2025. Peoples Natural Gas responded “Field Marked” on 7/29/2025.</p> <p>Ticket #20252044631 New – Excavation – Routine had a response due date of 7/25/2025. Blawnox Borough responded “Field Marked” to the ticket on 8/1/2025. Peoples Natural Gas responded “Field Marked” on 7/29/2025.</p> <p>Violations: Facility – People Natural Gas: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket #20252044631 Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket #20252044631 Recommendation: PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).</p> <p>Facility – Blawnox Borough: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket #20252044631 Recommendation:PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. This violation was issued as a warning. The penalty was reduced from \$1000 to \$0. Recommendation:PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement.</p> <p>Facility – Comcast: Section 2(5)(v) – Failed to respond to a routine One Call ticket. Recommendation:PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Ticket #20252044631</p>	
58595	Facility Owner: UGI Utilities, Inc Contractor/Excavator: J M F Underground Project Owner: UGI Utilities, Inc - Spacesaver	<p><u>On 9/17/2025 10:20:00 AM at 25 N 24TH ST, PENBROOK BORO. DAUPHIN</u> The incident occurred on 9/17/2025 at 25 N 24th St. in Pennbrook Borough in Dauphin County.</p> <p>A gas line was damaged.</p>	J M F Underground: \$500.00 Section 5(4) 1st Offense \$500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>UGI UTILITIES, INC stated in their Alleged Violation Report (AVR) that “While replacing a gas service, contractor struck and damaged a correctly marked gas service tee”. 11-50 people were affected. 25 people were evacuated. 911 was notified. Pictures were provided.</p> <p>J M F UNDERGROUND INC stated in their AVR that “While excavating for a gas service install, an old service tee was damaged and unplanned gas release happened. 911 was notified.</p> <p>VIOLATIONS J M F UNDERGROUND INC is in violation of: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: The penalty is applied. Excavator training is required. The most recent training was completed prior to this incident.</p>	

Full Session

Case Number	Stakeholders	Summary	Violations & Recommendation
56622	<p>Facility Owner: UGI Utilities Contractor/Excavator: Scranton Craftsman Project Owner: Heritage Homes Other: Verizon</p>	<p><u>On 6/24/2025 9:30:00 AM at 411 5TH ST, TAYLOR BORO, LACKAWANNA</u> On 1/13/2026 the DPC voted to:</p> <p>Scranton Craftsman</p> <p>Motion by Wiltshire to: 5(4)- Accept the DPIs recommendation. 5(8)- Accept the DPIs recommendation. 5(16)- Keep violation, reduce the penalty to \$500.00. Education is required.</p> <p>*** Scranton Craftsman is disputing with a letter where their attorney printed a dispute letter on 11/6/2025.</p> <p>*** Incident occurred on June 24th, 2025, at 9:30am on 411 5th Street, Taylor Boro, Lackawanna County.</p> <p>A gas line was damaged.</p> <p>UGI's Alleged Violation Report (AVR) states, "Excavator struck and damaged a correctly marked gas facility while digging in the tolerance zone." AVR notes that 911 was not notified.</p> <p>UGI's pictures show that the pinched off gas line was marked accurately. No AVRs have been submitted by Scranton Craftsman or Heritage Homes as of 9/19/25.</p> <p>Violations: Scranton Craftsman</p>	<p>Scranton Craftsman: \$2,000.00 Section 5(4) 1st Offense \$500.00</p> <p>Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$500.00</p> <p>Heritage Homes: \$1,000.00 Section 6.1(7) 1st Offense \$1,000.00</p> <p>Verizon: \$2,500.00 Section 2(5)(v) Subsequent \$2,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. PUC compliance education is required.</p> <p>Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid. PUC compliance education is required.</p> <p>Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required.</p> <p>Heritage Homes Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. PUC compliance education is required.</p> <p>Verizon Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20251693417. PUC compliance education is required.</p>	
56895	<p>Facility Owner: PECO Contractor/Excavator: JOSEPH W DAVIS INC Project Owner: Heritage Crown Realty, LLC Designer: Showalter and Associates Other: Verizon</p>	<p><u>On 6/27/2025 12:00:00 AM at 341 W BUTLER AVE, NEW BRITAIN BORO, BUCKS</u> On 1/13/2026 the DPC voted to:</p> <p>Joseph W. Davis Inc. - \$1000.00 + Education Section 5(16) failure to submit an AVR within 30 days of striking a line – 1st offense - \$1000.00 + Education.</p> <p>Motion by Ditty to keep the violation and remove the penalty. Keep the education requirement.</p> <p>*** Joseph A Davis Inc is disputing. ****</p> <p>Incident occurred on June 27th, 202 at 12am, 341 West Butler Avenue, New Britain Boro, Bucks County.</p> <p>A gas line was damaged.</p> <p>PECO's Alleged Violation Report (AVR) states, "JOSEPH DAVIS INC WORKING FOR GREEN TREE BUILDERS FOR NEW SUBDIVISION WAS EXCAVATING WITH A BACKHOE AND STRUCK THE UNMARKED SERVICE." AVR does not note if 911 was notified.</p> <p>Images show no markings for the lateral going to the Veterinary Clinic but no lateral going to the new townhome site.</p> <p>No AVRs have been submitted by Joseph W. Davis Inc as of 10/1/25. DPI emailed PECO for both mark out photos and damage report from their contracted locator. PECO provided mark out photos that match google maps June 2025 Streetview. DPI emailed PECO again for the USIC damage photos. Images show that the lateral was not marked. DPI emailed PECO to ask if there was a release of gas and if 911 was notified. PECO responded that there was a release of gas, 911 was called, and the Veterinary Hospital was evacuated. PECO's AVR did</p>	<p>PECO: \$3,000.00 Section 2(5)(i) Subsequent \$2,000.00</p> <p>Section 2(5)(v) Subsequent \$1,000.00</p> <p>JOSEPH W DAVIS INC: \$0.00 Section 5(16) 1st Offense \$0.00</p> <p>Verizon: \$2,000.00 Section 2(5)(v) Subsequent \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>not include images, if there was a hazardous release of gas, or if 911 was notified.</p> <p>No AVR has been received from Joseph W Davis, Inc or Heritage Crown Realty, LLC as of 10/3/025. No address found for Heritage Crown Realty due to state website being down.</p> <p>DPI spoke with Showalter and Associates who stated they completed designs for the prior owner who then sold the property but leases a section.</p> <p>Violations:</p> <p>PECO Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. PUC compliance education is required. Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. 20251080453. PUC compliance education is required.</p> <p>Joseph W Davis Inc Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required.</p> <p>Verizon Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20251080453. PUC compliance education is required.</p>	
56577	<p>Facility Owner: PECO Contractor/Excavator: DONALD A PUSEY INC Project Owner: Altman Group Other: Norristown Municipal Waste Authority Other: Uniti Fiber Other: Verizon</p>	<p><u>On 6/30/2025 12:00:00 AM at POWELL ST, NORRISTOWN BORO, MONTGOMERY</u> On 1/13/2026 the DPC voted to:</p> <p>Motion by Haupt to: PECO 2(5)(i) - remove the violation and penalty. 2(5)(v.2) - remove the violation and penalty. ***</p> <p>PECO is disputing case 56577. DPI asked PECO if an agreement was reached with the excavator? ***</p> <p>Incident occurred on June 30th, 2025, at 12am along Powell Street, Norristown Boro, Montgomery County.</p> <p>A gas line was damaged.</p> <p>PECO's AVR states, "Donald Pusey Inc was digging in advance of POC locate request which had been lawfully extneded by 1 day when they struck the newly installed Gas Service." Additional documents state, ". Locator extended the ticket from 6/29/2025 to 6/30/2025. Damage occurred on 6/30/2025 before the site was marked." AVR notes that 911 was notified.</p> <p>Ticket 20251752837 was placed on 6/24/25 at 2:14pm with a final response due date of [29-Jun-25]. Damage photos show that the damage occurred on 6/30/25. No</p>	<p>PECO: \$0.00</p> <p>DONALD A PUSEY INC: \$1,250.00 Section 5(20) 1st Offense \$250.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>Altman Group: \$1,000.00 Section 6.1(7) 1st Offense \$1,000.00</p> <p>Norristown Municipal Waste Authority: \$250.00 Section 2(5)(v.2) 1st Offense \$250.00</p> <p>Uniti Fiber: \$250.00 Section 2(5)(v.2) 1st Offense \$250.00</p> <p>Verizon: \$1,500.00 Section 2(5)(v.2) Subsequent \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>marks are present for the gas company. PECO gave a final response of Field Mark on 6/30/25.</p> <p>No AVRs were submitted by Donald A. Pusey, Inc or the Altman Group as of 9/12/25.</p> <p>Violations:</p> <p>PECO Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. PUC compliance education is required. Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. PUC compliance education is required.</p> <p>Donald A Pusey Inc. Section 5(20) – Excavator failed to renotify One Call of an unmarked or incorrectly marked facility upon arrival at a work site. PUC compliance education is required. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required.</p> <p>Altman Group Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. PUC compliance education is required.</p> <p>Verizon Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. 20251752837. PUC compliance education is required.</p> <p>Norristown Municipal Waste Authority Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. 20251752837. PUC compliance education is required.</p> <p>Uniti Fiber Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. 20251752837. PUC compliance education is required. At the time this case was submitted, Uniti had 3 delinquent education requirements, and 1 that was outstanding but not late. Uniti has never met any education requirements the DPC has recommended.</p>	
56993	<p>Facility Owner: PITTSBURGH WATER Contractor/Excavator: WILSON EXCAVATING AND UTILITY CONSTRUCTION LLC Project Owner: Peoples Gas Company Designer: Peoples Placeholder Designer: The Gateway Engineers Other: Verizon</p>	<p>On 7/16/2025 11:49:00 AM at S NEGLEY AVE, PITTSBURGH CITY, ALLEGHENY On 1/13/2026 the DPC voted to:</p> <p>Motion by Dacey to: 2(5)(i)- Accept the DPI’s recommendation. 2(5)(viii)- Accept the DPI’s recommendation.</p> <p>*** Pittsburgh Water is disputing. ***</p>	<p>PITTSBURGH WATER: \$3,000.00 Section 2(5)(i) Subsequent \$2,000.00</p> <p>Section 2(5)(viii) 2nd Offense \$1,000.00</p> <p>Verizon: \$3,500.00 Section 2(5)(viii) Subsequent \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Incident occurred on July 16th, 2025, at 11:49am on South Negley Avenue, Pittsburgh City, Allegheny County.</p> <p>A water line was damaged. Case is related to case 54608.</p> <p>Pittsburgh Water's Alleged Violation Report (AVR) states, "Wilson excavation digging and hit an unmarked copper commercial service line. PWSA responded and made repairs. Wilson excavation saw the curb box next to curb. They should have known and seen curb box and should have been more careful."</p> <p>Wilson Excavating's AVR states, "Wilson Excavating was performing work for Peoples Gas on S. Negley Ave in Pittsburgh when a mismarked Pittsburgh Water & Sewer Authority line was struck. The Operator was digging for mainline installation and caught a mismarked copper water service owned by PWSA. The facility owner was notified and they came out to make repairs. The service was fixed the same day. Everyone agreed the line was mismarked by several feet."</p> <p>Peoples Gas Company's AVR states, "Wilson Excavating was performing work for Peoples Gas on S. Negley Ave in Pittsburgh when a mismarked Pittsburgh Water & Sewer Authority line was struck. The Operator was digging for mainline installation and caught a mismarked copper water service owned by PWSA. The facility owner was notified and they came out to make repairs. The service was fixed the same day. Everyone agreed the line was mismarked by several feet."</p> <p>Images show that the line was damaged outside of the tolerance zone. Duquesne Light Company signed Complex meeting sign-in sheet.</p> <p>Violations:</p> <p>Pittsburgh Water Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. PUC compliance education is required. Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20250643755. PUC compliance education is required.</p> <p>Verizon Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20250643755. PUC compliance education is required. Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20251670499. PUC compliance education is required.</p>	<p>Section 2(4) Subsequent \$1,500.00</p>
57032	<p>Facility Owner: UGI Utilities, Inc Contractor/Excavator:</p>	<p><u>On 7/16/2025 2:30:00 PM at ALLEGHENY ST, JERSEY SHORE BORO, LYCOMING</u> On 1/13/2026:</p>	<p>Harger Utility Contractors, Inc: \$500.00 Section 5(4) 1st Offense</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>Harger Utility Contractors, Inc Project Owner: Leece Electric Designer: R K WEBSTER LLC Other: Jersey Shore Borough Other: Verizon</p>	<p>The Damage Prevention Committee (DPC) voted on Leece Electric's violation: 6.1(7)- remove the violation and penalty.</p> <p>***** Leece Electric is disputing.</p> <p>***** The incident occurred on July 16th, 2025, at 2:30 PM, on Allegheny Street, in Jersey Shore Borough, Lycoming County.</p> <p>A gas line owned by UGI Utilities, Inc. was damaged. 911 was called.</p> <p>UGI Utilities, Inc., the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, "HDD crew struck a correctly marked gas main. Rob Reem (Superintendent-HUC Inc) and Matt Crawford (Project Manager-HUC Inc) stated (on site after damage occurred) that crew had been instructed to spot main within tolerance zone with vac truck. While Rob and Matt were not on site, crew decided not to expose main with vac truck and drilled into the correctly marked main." Photos were submitted.</p> <p>Harger Utility Contractors, Inc., the excavator, submitted an AVR. Their AVR states, "While Drilling for a new utility for the traffic lights. We hit a gas line." Photos were submitted.</p> <p>Leece Electric is the project owner. An AVR has not been filed as of 10/01/2025.</p> <p>The submitted photos show the gas line was properly marked and damaged within the tolerance zone.</p> <p>Routine ticket 20251763814 had a response due date of 06/27/2025. - Jersey Shore Borough did not respond until 06/30/2025. - Verizon did not respond until 07/02/2025.</p> <p>Violations:</p> <p>Harger Utility Contractors, Inc.- - Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Leece Electric- - Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Jersey Shore Borough-</p>	<p>\$500.00</p> <p>Leece Electric: \$0.00</p> <p>Jersey Shore Borough: \$250.00 Section 2(5)(v) 1st Offense \$250.00</p> <p>Verizon: \$1,000.00 Section 2(5)(v) Subsequent \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>- Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Routine ticket 20251763814. Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Verizon- - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Routine ticket 20251763814. Recommendation: The penalty is applied. PUC compliance training education was recently completed.</p>	
57336	<p>Facility Owner: PPL ELECTRIC UTILITIES CORPORATION Contractor/Excavator: Trinity Solar</p>	<p><u>On 7/17/2025 12:07:00 PM at 3228 OLD BETHLEHEM PIKE, SPRINGFIELD TWP, BUCKS</u> On 1/13/2026 the DPC voted to:</p> <p>Trinity Solar - \$1000.00 + Education Section 5(16) failure to submit an AVR after striking a line. – 1st offense - \$1000.00 + Education.</p> <p>Motion by Ditty to keep the violation and penalty and add additional \$250.00 penalty for not attending the DPC meeting. Not in attendance</p> <p>*** Trinity Solar is disputing.</p> <p>**** Incident occurred on July 17th, 2025, at 12:07pm on 3228 Old Bethlehem Pike, Springfield Township, Bucks County.</p> <p>An electric line was damaged.</p> <p>PPL Electric's Alleged Violation Report (AVR) states, "Contractor hit a PPL service line. On Thursday July 17th, 2025, at 12:07 pm a non-PPL contractor (Trinity Solar) was Installing solar panels and conduit, while in the process of trenching with their ditch witch the contractor encountered an underground service wire going to the home. No one was hurt or injured but the home did lose service. PPL Was contacted and when first responders arrived on scene, they were able to make the area safe and start their investigation and repair, after a quick investigation the first responder found a severed electrical service going to the property, the line was not properly marked which led to the damage. After discussion with Our first responder, they were able to make the repair to the service line and get the customer back in service No follow up work will be needed. I spoke with USIC and made them aware they would be liable for this damage. Please reference USIC damage claim number 40220250717017."</p> <p>Ticket 20251952086 states that excavator was trenching with a ditch witch. Trinity Solar failed to submit an AVR within 30 days. Images show the line was marked going another direction.</p>	<p>PPL ELECTRIC UTILITIES CORPORATION: \$1,000.00 Section 2(5)(i) 2nd Offense \$1,000.00</p> <p>Trinity Solar: \$1,250.00 Section 5(16) 1st Offense \$1,250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Violations:</p> <p>PPL Electric Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. 20251952086. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p> <p>Trinity Solar Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required for the person responsible for submitting AVR or their replacement.</p>	
56899	<p>Facility Owner: Peoples Gas Company Contractor/Excavator: Crews Control, LLC Contractor/Excavator: Swank Construction Company Project Owner: PEOPLES GAS COMPANY Placeholder Designer: Gateway Engineers Designer: PEOPLES Designer Placeholder Other: Pittsburgh Department of Mobility and Infrastructure</p>	<p><u>On 7/18/2025 12:00:00 PM at 5624 MAPLE HEIGHTS RD, PITTSBURGH CITY, ALLEGHENY</u> On 1/13/2026 the DPC voted to:</p> <p>Swank Construction Company</p> <p>Motion by Dacey to: 5(4)- Remove the violation and penalty. 5(8)- Remove the violation and penalty. 5(16)- Remove the violation and penalty.</p> <p>*** Swank Construction is disputing. DPI removed 5(2.1) after Swank provided a ticket for Maple Ct. Swank is disputing the additional violations and penalties with the DPC.</p> <p>****</p> <p>Incident occurred on July 18th - 23rd, 2025, at 12pm on 5624 Maple Heights Road, Pittsburgh City, Allegheny County.</p> <p>A gas line was damaged.</p> <p>Peoples Gas Company's Alleged Violation Report states, "On or about 7-21-2025 a contractor saw cut through a properly marked Peoples Gas service line serving 5624 Maple Heights Ct Pittsburgh. The customer called in to report that they had no gas and that there was a faint odor of gas in the air. Peoples Gas just replaced the gas main and services here and is now at the road restoration phase. Lindy Paving has subbed out both Crews Control LLC and Swank Construction to do the saw cutting. Both Swank and Crews Control have put in One Call requests for the saw cutting and Peoples Gas marked the lines for the requests. There was no equipment on site and no report to 811, 911 or Peoples Gas that this line was cut. The attached pictures showing excavation are from peoples Gas crews digging the line up."</p> <p>DPI asked both Crews Control and Swank via emails to speak with their employees to locate the areas where they saw cut. Emails are attached.</p>	<p>Crews Control, LLC: \$500.00 Section 5(17) 1st Offense \$500.00</p> <p>Swank Construction Company: \$0.00</p> <p>Pittsburgh Department of Mobility and Infrastructure: \$1,000.00 Section 2(5)(vii) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Swank Construction's AVR states, "Swank received an email from PA One Call on 10/3 stating an AVR needed filled out for Maple Heights Dr. Swank was unaware of any utility disturbances on that project until we received the email. Swank was unaware of any disturbances on the project when we were on site. Swank was told to fill out an AVR anyway. Due to the fact that Swank was unaware of any utilities being disrupted on the project it is difficult to accurately provide any information."</p> <p>Swank responded via email to state, "To the best of our crews memory, they think they were instructed to make several cuts longitudinally and transversely in the Cul de sac area of the picture you sent. We don't know how many cuts were made and specifically where, but they remember cutting multiple passes in the Cul de sac area."</p> <p>Images show that the line was cut with a saw. Swank Constructions routine ticket does not cover the area where the line was damaged. Crews Control ticket does cover the area for their company only.</p> <p>911 and the facility owner were not notified. No AVR was filed within 30 days of the damage by the excavator. AVR requests were sent to Swank and Crews Control. Crews Control never responded.</p> <p>Violations:</p> <p>Swank Construction Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. PUC compliance education is required. Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. PUC compliance education is required. Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid. PUC compliance education is required. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required.</p> <p>Pittsburgh Department of Mobility and Infrastructure Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20252024966. PUC compliance education is required.</p> <p>Crews Control, llc Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. PUC compliance education is required. Crews Control is delinquent on education required by the Damage Prevention Committee from August of 2024.</p>	
56824	Facility Owner: National Fuel GAS Contractor/Excavator:	<u>On 7/21/2025 12:29:00 PM at E. 32ND ST, ERIE CITY, ERIE</u> On 1/13/2026 Konzel Construction was a "no show". The Damage Prevention Committee (DPC) voted	Konzel Construction: \$4,375.00 Section 5(4) 1st Offense

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>Konzel Construction Project Owner: Erie Water Works Designer: K L H ENGINEERS Other: VERIZON</p>	<p>to keep the violations as presented and add an additional \$250.00 penalty to violation section 5(4) for not attending the DPC meeting. * Konzel Construction is disputing.</p> <p>5(4): Labor did not hand dig to locate marked utility. After incident labor was removed from the project.</p> <p>5(6)(i): Work involves replacing existing water service and location of water service can not be moved.</p> <p>5(7): NFG was immediately notified of hit at 12:00 Noon on 7/21/2025. Konzel Construction turn off all equipment and was on standby until 3:00 PM when the hit was fixed.</p> <p>5(8): Since Incident Crews have been notified that 911 must be notified if hazardous utilities are hit.</p> <p>5(16): AVR was not completed. EWW was not notified of incident, and therefore they were ignorant to the fact that hey needed to complete an AVR due to Konzel Construction's actions.</p> <p>***</p> <p>The incident occurred on 7/21/2025 at E. 32ND ST in Erie City in Erie County.</p> <p>A gas main owned by National Fuel Gas (NFG), was damaged. 911 was not notified. 82 customers- were affected</p> <p>NATIONAL FUEL GAS THE FACILITY OWNER stated in their Alleged Violation Report (AVR) that Konzel was using improper digging techniques to expose a correctly marked 2in plastic gas main. The main was damaged causing a significant outage. 911 was not notified. There was an evacuation. Pictures and reports were provided. An email to NFG was sent on 9/12/2025 asking about 911, and how NFG found out about the damage. DPI Maki also asked for verification of the number of people that were affected by this outage. On 9/15/2025 NFG responded that “ The total number of customers affected by the damage would have been determined by our field personnel as part of the damage investigation. To the best of my knowledge 911 was not notified and NFG was not notified by the contractor onsite that the damaged had occurred. I do not have any photos at this time with equipment, but we will continue to look. Please let me know if you need anything else. On 9/15/2025. DPI Maki sent an email asking for the damage report. On 9/17/2025 A screenshot of the damage report was provided.</p> <p>Konzel Construction the excavator, has not submitted an AVR as of 9/12/2025. On 12/03/2025 Konzel Construction submitted an AVR that stated that “Konzel Construction hit active Gas Line at 12:00 noon, NFG</p>	<p>\$1,125.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(7) 1st Offense \$1,000.00</p> <p>Erie Water Works: \$1,000.00 Section 6.1(7) 1st Offense \$1,000.00</p> <p>VERIZON: \$500.00 Section 2(5)(v) 2nd offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>was notified and was fixed hit by 3:00 PM". Project cost is listed at >\$400,000. Subsurface Utility Engineering (SUE) level is noted as above ground survey, which is consistent with level "C" description in The American Society of Civil Engineers (ASCE) who has developed a National Consensus Standard titled ASCE C-I 38-02 and is referred to in CGA 21.0.</p> <p>Erie Water Works the project owner, has not submitted an AVR as of 9/12/2025. On 12/03/2025 Erie Water Works submitted an AVR which stated that "Konzel Construction hit active Gas Line at 12:00 noon, NFG was notified and was fixed hit by 3:00 PM". Project cost is listed at >\$400,000. Subsurface Utility Engineering (SUE) level is noted as above ground survey, which is consistent with level "C" description in The American Society of Civil Engineers (ASCE) who has developed a National Consensus Standard titled ASCE C-I 38-02 and is referred to in CGA 21.0.</p> <p>VIOLATIONS Konzel Construction is in violation of: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. A fine factor of .5 has been added as per the .59 Bureau of Investigation and Enforcement Damage Prevention Section Fine Factor Determination chart. Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. Section 5(7) – Failed to immediately report to the facility owner any break or leak in its lines, or any dent, gouge, groove, or other damage to such lines or to their coating or cathodic protection. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or damaging a facility owner’s line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid. Recommendation: The penalties are applied. Education is required. Education that was due by 9/10/2024 has not been completed as of 10/03/2025.</p> <p>Erie Water Works is in violation of: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike or damaging a facility owner’s line during excavation or demolition work activities or if a project owner believes a violation of this act has been committed in association or demolition. Recommendation: The penalty is applied. The education requirement has been recently completed.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>VERIZON is in violation of: Section 2(5)(v) – Failed to respond to a routine One Call ticket.</p> <p>Ticket 20251744553 was requested by Konzel Construction on 6/23/2025 with a response due by 6/25/2025. Verizon did not respond until they field marked on 7/07/2025. This is over 7 days. Historically the Damage Prevention Committee (DPC) has considered anything over a week as a non-response to a ticket. This is a second offense.</p> <p>Recommendation: The penalty is applied. Education is required.</p>	
56834	<p>Facility Owner: PECO Contractor/Excavator: PA Tent Rental, LLC</p>	<p><u>On 7/22/2025 11:00:00 AM at 7 N COMMERCE DR, CHESTER TWP, DELAWARE</u> On 1/13/2026 the DPC voted to:</p> <p>Section 5(22) excavator provided a misrepresentation of an emergency excavation – 1st offense - \$500.00 + Education</p> <p>Motion by Dacey to keep the violation and remove the penalty. Keep education.</p> <p>*** PA Tent is disputing.</p> <p>*** Incident occurred on July 22nd, 2025, at 11am, on 7 North Commerce Drive, Chester Township, Delaware County.</p> <p>A non-emergency ticket was submitted.</p> <p>PECO's Alleged Violation Report (AVR) states, "SUBMITTED FALSE EMG TCKET."</p> <p>Insufficient Ticket 20252030570 was placed on 7/22/25 at 8:10am with Excavation Equipment STAKE DRIVER. Emergency ticket 20252032131 was placed on 7/22/25 at 11:40 am.</p> <p>Violation:</p> <p>PA Tent Rental, LLC Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. PUC compliance education is required. Section 5(22) – Excavator provided a misrepresentation of an emergency excavation, subject to an administrative penalty imposed under section 7(10). PUC compliance education is required.</p>	<p>PA Tent Rental, LLC: \$0.00 Section 5(22) 1st Offense \$0.00</p>
56999	<p>Facility Owner: Peoples Gas Company Contractor/Excavator: Terry's Plumbing Project Owner: Homeowner</p>	<p><u>On 7/23/2025 11:20:00 AM at 122 SEWICKLEY OAKMONT RD, ROSS TWP, ALLEGHENY</u> On 1/13/2026 the DPC voted to:</p> <p>Terry's Plumbing</p> <p>Motion by Dacey to: 5(8)- Keep the violation and penalty. The education requirement.</p>	<p>Peoples Gas Company: \$3,000.00 Section 2(5)(i) 3rd Offense \$1,500.00</p> <p>Section 2(5)(vii) 2nd Offense \$1,500.00</p> <p>Terry's Plumbing:</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>5(16) – Keep the violation and penalty. 5(20) – Remove violation and penalty.</p> <p>*** Terry's Plumbing is disputing.</p> <p>**** Incident occurred on July 23rd, 2025, at 11:20am on 122 Sewickley Oakmont Road, Ross Township, Allegheny County.</p> <p>A gas line was damaged.</p> <p>Peoples Gas Company's Alleged Violation Report (AVR) states, "Terry's plumbing called in an emergency one call ticket on 7/23 @ 8:16AM. PNG locator did not see the emergency ticket. Terry's plumbing started digging after waiting the two hours. Struck unmarked 3" ML. Terry's plumbing failed to renotify the ticket before digging." AVR does not note if 911 was notified.</p> <p>Emergency ticket 20252042093 notes, "EXCAVATOR HAZARDOUS RELEASE: YES CALLER ADVISED TO NOTIFY 911."</p> <p>Images show the damaged unmarked line. No AVR has been submitted by Terry's Plumbing as of 10/6/25.</p> <p>Violations:</p> <p>Peoples Gas Company Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. PUC compliance education is required. Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. PUC compliance education is required.</p> <p>Terry's Plumbing Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid. PUC compliance education is required. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required. Section 5(20) – Excavator failed to renotify One Call of an unmarked or incorrectly marked facility upon arrival at a work site. PUC compliance education is required.</p>	<p>\$2,000.00 Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>
56974	<p>Facility Owner: Peoples Natural Gas Contractor/Excavator: KP Builders LLC Project Owner: MONESSEN HIGH SCHOOL</p>	<p><u>On 7/24/2025 10:00:00 AM at 1245 State Rd. MONESSEN CITY, WESTMORELAND</u> On 1/13/2026 the Damage Prevention Committee (DPC) voted to Accept the violations and penalties as written in the recommendation by the investigator.</p> <p>* KP Builders is disputing. On 12/11/2025 DPI Maki sent a copy of Act 127-2024 and the liaison's contact information. DPI asked if there was anything that they found as "new" in chapter 5. DPI also requested some of the attachments "Tickets Placed</p>	<p>KP Builders LLC: \$2,250.00 Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>by" to be resent another way, because they are not able to be opened in the current format.</p> <p>***</p> <p>The incident occurred on 7/24/2025 at 1245 State Road, in MONESSEN CITY, WESTMORELAND County.</p> <p>A gas line owned by Peoples Gas was damaged, and 25 people were evacuated from school.</p> <p>PEOPLES GAS COMPANY LLC stated in their Alleged Violation Report (AVR) that “KP Builders working without a One Call locate request struck and damaged a pressured gas service line owned by Monessen School District. This damage caused an evacuation of 25 people in the school at the time. Peoples Gas responded and stopped the flow of gas at the curb valve. 911 was notified. Pictures were provided.</p> <p>KP BUILDERS have not submitted an AVR as of 10/16/2025.</p> <p>MONESSEN HIGH SCHOOL did not submit an AVR as of 10/16/2025. Damage Prevention Investigator, Maki called MONESSEN HIGH SCHOOL on 9/17/2025 and left a message with her contact asking who's the best contact person regarding this incident. There has not been any returned contact as of 10/16/2025.</p> <p>VIOLATIONS: KP Builders LLC is in violation of: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Incident occurred on 7/24/2025. Ticket 20252093075 and 20252093074 were submitted on 7/28/2025. Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or damaging a facility owner’s line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: The penalties are applied. Excavator education is required.</p>	
57464	<p>Facility Owner: Quakertown Borough</p> <p>Contractor/Excavator: SUPERIOR FENCE AND RAIL OF SOUTHEAST PA</p> <p>Project Owner: Homeowner</p>	<p><u>On 7/25/2025 10:22:00 AM at 14 BRAITHWAITE LN, QUAKERTOWN BORO, BUCKS</u> On 1/13/2026 the DPC voted to:</p> <p>Quakertown Borough</p> <p>Motion by Dacey to: 2(5)(v.2)- Accept the DPI’s recommendation. 2(10)- Accept the DPI’s recommendation. 9- Accept the DPI’s recommendation.</p> <p>***</p>	<p>Quakertown Borough: \$1,500.00 Section 2(5)(v.2) 1st Offense \$250.00</p> <p>Section 2(10) 1st Offense \$1,000.00</p> <p>Section 9 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>0 HS1 QUAKERTOWN BOROUGH HS1-CLEAR. NO FACILITIES OR FACIL NOT INVOLVED 7/1/25, 2:25 PM SA-OTM N/A</p> <p>0 HS1 QUAKERTOWN BOROUGH HS1-NO RESPONSE 3/31/25, 12:05 AM Auto-KARL N/A</p> <p>Please note the fence was installed in "end of March beginning of April." ****</p> <p>Incident occurred on July 25th, 2025, at 10:22am on 14 Braithwaite Lane, Quakertown Boro, Bucks County.</p> <p>An electric line was damaged.</p> <p>Superior Fence and Rail of South East PA's Alleged Violation Report (AVR) states, "We installed this fence end of March beginning of April. On July 25, 2025 the homeowner reached out and stated Quakertown Borough reached out and informed him that we damaged a Quakertown utility line 4 months ago. He asked us to remove 2 sections so Quakertown and service the line and reinstall after. We hand dug the entire project and did not notice any utility lines. I asked Robert Odonnel for his email so I could email him the ticket responses of "clear" but he refused and continued to scream and berate me. Quakertown marked their line as clear. Robert claims there is sever departments in Quakertown who respond and he absolutely marked it in red. He told me to show him a picture of it not marked in red. I replied "show me a picture where it is marked in red. you reported to PA ONE CALL your utilities were clear, we installed accordingly" He then accused us of using power equipment and that is incorrect. He was never on site to see anything for himself. We hand dig every project."</p> <p>Quakertown Borough gave a final response of clear no facilities to ticket 20250800995 on 7/1/25. The ticket was placed on 3/21/25. No AVR for the alleged damage was submitted by Quakertown Borough.</p> <p>Quakertown Borough was sent to education on case 38267 on 3/12/24 and our records indicate that the education has not been completed as of 10/17/25. Education letter from 38267 is attached.</p> <p>Violations:</p> <p>Quakertown Borough Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. Section 9 of Act 127 of 2024 states, “Except as otherwise provided for by this act, persons shall use their</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>best efforts to comply with the Common Ground Alliance best practices.” Chapter 7.01 of the Common Ground Alliance best practices Version 21 states, “Practice Statement: Mandatory education is considered as an alternative or supplement to penalties for offenders of the damage prevention laws and regulations.</p>	
57068	<p>Facility Owner: PECO Contractor/Excavator: REMCON INC Project Owner: COATESVILLE AREA SCHOOL DISTRICT</p>	<p><u>On 7/29/2025 7:30:00 AM at 256 REECEVILLE RD, WEST BRANDYWINE TWP, CHESTER</u> On 1/13/2026: The Damage Prevention Committee (DPC) voted on REMCON INC's violations: 5(4)- Keep violation and penalty. 5(3)- Remove violation and penalty. 5(16)- Keep violation and penalty.</p> <p>***** REMCON INC is disputing. Violation of Section 5(8) was withdrawn. *****</p> <p>The incident occurred on July 29th, 2025, at 7:30 AM, at 256 Reeceville Road, in West Brandywine Township, Chester County.</p> <p>A gas line owned by PECO was damaged.</p> <p>PECO, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “contractor Remcon inc working for the Reeceville elementary school doing site work and foundation work, hit the accurately marked 2" high pressure plastic service to the building within 6 feet of the meeter.” Photos were submitted.</p> <p>Remcon Inc. is the excavator. An AVR has not been filed as of 10/10/2025.</p> <p>Coatesville Area School District is the project owner. An AVR has not been filed as of 10/10/2025.</p> <p>The submitted photos show the gas line was marked when the ticket was requested in November 2024. A renotify ticket was not requested. Damage then occurred on July 29th, 2025. The damaged gas line was within the tolerance zone.</p> <p>PECO’s AVR and submitted photos did not indicate 911 was called. (Documentation has since been submitted to show 911 was called.)</p> <p>Violations:</p> <p>Remcon Inc.- - Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. - Section 5(3) – Excavator failed to preserve mark-outs or request a remark. - Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the</p>	<p>REMCON INC: \$1,500.00 Section 5(4) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>COATESVILLE AREA SCHOOL DISTRICT: \$0.00 Section 6.1(7) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. (Withdrawn.) - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Coatesville Area School District- - Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Recommendation: Warning. PUC compliance training education is required.</p>	
57300	<p>Facility Owner: PEOPLES GAS COMPANY LLC Contractor/Excavator: TEDESCO EXCAVATING & PAVING Project Owner: Crafton Borough Designer: GATEWAY ENGINEERS INC</p>	<p><u>On 8/5/2025 3:00:00 PM at STEUBEN ST, CRAFTON BORO, ALLEGHENY</u> On Tuesday, 1/13/2026, at the Virtual DPC Meeting, disputing party was Tedesco Excavating & Paving. It was voted: 5(4)- Remove the violation and penalty, 5(16)- remove the penalty but keep the violation, and Education is required. ***** Tedesco disputes. This is all our fault because the line wasn't deep enough and he should not have to file an AVR. ***** The incident occurred on Tuesday, August 5, 2025, on W. Steuben Street, in Crafton Borough, Allegheny County.</p> <p>Peoples Gas Company’s line was damaged.</p> <p>Peoples Gas stated in their alleged violation report (AVR), Tedesco Excavating, working for Crafton Borough struck and damaged a properly marked Peoples Gas service line servicing address 13 Afton Street, on Steuben Street. Mechanized equipment was being used in the tolerance zone. Peoples Gas provide photos. Tedesco Excavating & Paving placed a Damage Excavation notification, 20252172914, on 8/5/2025, at 1:40pm. Remarks from the notification-- Caller states the hit a 1in gas service line and the line is live, and they plugged it with wood and gas is still leaking. Facility Type: natural gas- Peoples. Excavation Equipment: excavator. Hazardous Release: yes. Caller has notified 911.</p> <p>Tedesco Excavating & Paving did not submit an AVR.</p> <p>Violation:</p> <p>*Tedesco Excavating & Paving is in violation of section: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: PUC Compliance Education Required and Penalties Applied</p>	<p>TEDESCO EXCAVATING & PAVING: \$0.00 Section 5(16) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
57458	<p>Facility Owner: National Fuel</p> <p>Contractor/Excavator: Empire Snow Management</p> <p>Project Owner: Erie Land Bank</p>	<p><u>On 8/6/2025 9:10:00 AM at 256 / 258 W 18TH ST, ERIE CITY, ERIE</u> On 1/13/2026: The Damage Prevention Committee (DPC) voted on Erie Land Bank's violations:</p> <p>6.1(7)- Keep violation, remove penalty. 6.1(8)- Keep violation, remove penalty.</p> <p>*****</p> <p>Erie Land Bank is disputing.</p> <p>*****</p> <p>The incident occurred on 08/06/2025 at 9:10 AM, at 256 / 258 (Duplex) West 18th Street, in Erie City, Erie County.</p> <p>A gas line owned by National Fuel was damaged during demolition. 911 was not called and the site was vacated.</p> <p>National Fuel, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, "Excavator called in ticket on 6/3/25 and never started work. Excavator never called in a new ticket and demolished the structure on 8/6 and damaged an NFG service line. Excavator never notified NFG of the damage, NFG was not made aware of the damage until 8/7 when we received a no gas call from a customer on 8/7. The gas was left blowing for over 24 hours and created a very hazardous situation." Photos were submitted.</p> <p>Empire Snow Management is the excavator. An AVR was submitted after a request letter was mailed and emailed 08/20/2025. Their AVR did not include a summary. Photos were submitted.</p> <p>Erie Land Bank is the project owner. An AVR has not been filed as of 10/16/2025. An AVR request letter was mailed and emailed 08/20/2025.</p> <p>Both National Fuel's and Empire Snow Management indicate that 911 was not called.</p> <p>The excavator did not begin within the legal timeframe listed on the routine ticket (20251542598). The Lawful Start Dates listed on the ticket are 06/06/2025 through 06/17/2025. Damage occurred in August 2025.</p> <p>Violations:</p> <p>Empire Snow Management-</p> <ul style="list-style-type: none"> - Section 1.1 – Excavator did not begin within legal timeframe. Ticket 20251542598. - Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner's facilities in the construction area. - Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. 	<p>Empire Snow Management: \$3,250.00</p> <p>Section 1.1 1st Offense \$1,000.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(8) 1st Offense \$1,000.00</p> <p>Erie Land Bank: \$0.00</p> <p>Section 6.1(7) 1st Offense \$0.00</p> <p>Section 6.1(8) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>- Section 5(8) – Excavator vacated worksite after causing damage that resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Erie Land Bank-</p> <p>- Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike.</p> <p>- Section 6.1(8) - Project Owner failed to comply with all requests for information by the commission relating to the commission's enforcement authority under this act within 30 days of receipt of written request. Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
57400	<p>Facility Owner: Pittsburgh Water</p> <p>Contractor/Excavator: PEOPLES NATURAL GAS COMPANY</p> <p>Project Owner: PEOPLES NATURAL GAS COMPANY</p> <p>Designer: PEOPLES NATURAL GAS COMPANY</p> <p>Other: PITTSBURGH CITY DEPT OF MOBILITY & INFRASTRUCTURE</p>	<p>On 8/6/2025 3:31:00 PM at 329 DOWNING ST, PITTSBURGH CITY, ALLEGHENY On Tuesday, 1/13/2026, at the Virtual DPC Meeting, disputing party was Peoples Natural Gas. It was voted to Remove all Penalties and Violations. ***** Dispute- PNG is disputing all penalties and violations. see attached email. ***** The incident occurred on Wednesday, August 6, 2025, at 329 Downing Street, in Pittsburgh City, Allegheny County.</p> <p>A water line was damaged.</p> <p>Peoples Gas Company stated in their Alleged Violation Report (AVR), PNG crews were installing a new 4" PL ML when they struck a Pittsburgh Water company 1" lead water SL. The water mainline was marked, but the service/curb box was not.</p> <p>Pittsburgh Water stated in their AVR, Peoples Gas digging and hit an accurate marked lead active water service line. PWSA responded, made repairs, and restored water- Excavation Emergency ticket, 20252184304. Careless digging by Peoples Gas. Photos were provided by Pittsburgh Water and Peoples Gas, showing the damaged water service line, and visible water curb box.</p> <p>20252184304- Excavation Emergency placed on 8/6/2025, No Response from Pittsburgh City Dept of Mobility & Infrastructure.</p> <p>Violations:</p> <p>*Peoples Gas Company is in violation of section: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. 5(20) – Excavator failed to renotify One Call of an unmarked or incorrectly marked facility upon arrival at a work site. Recommendation: Penalties Applied. PUC Online Compliance Training is required for the Excavator(s) working onsite at this excavation, or their replacements.</p>	<p>PEOPLES NATURAL GAS COMPANY: \$0.00</p> <p>PITTSBURGH CITY DEPT OF MOBILITY & INFRASTRUCTURE: \$1,000.00 Section 2(5)(vii) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>*Pittsburgh City Dept of Mobility & Infrastructure is in violation of section: (5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20252184304 Recommendation: PUC Compliance Education Required and Penalty Applied</p>	
57764	<p>Facility Owner: Peoples Natural Gas Contractor/Excavator: Independent Enterprises Inc Project Owner: Pittsburgh Water Designer: GAI Other: Comcast Other: Verizon</p>	<p><u>On 8/18/2025 10:50:00 AM at FAIRLEE ST, PITTSBURGH CITY, ALLEGHENY</u> On 1/13/2026 the DPC voted to: Peoples Gas 2(5)(v)- remove violation and penalty.</p> <p>Independent Enterprises did not attend the meeting: 5(4)- Keep violation and penalty. Increase the penalty from \$2000 to \$2250 for not attending DPC meeting</p> <p>***** People Natural Gas - Disputing based on Irth issue that was to be resolved in July Independent Enterprise - Disputing based on depth of line ***** The incident occurred on 8/18/2025, at 10:50 AM, on Fairlee St, in Pittsburgh City, Allegheny County.</p> <p>A gas line owned by Peoples Gas Company was damaged.</p> <p>Peoples Gas Company is the facility owner. Their Alleged Violation Report (AVR) states, “On 8/18/2025, Independed Enterprises was working to install water services and mains when they struck an accuratley marked PNG SL. Main to curb.”</p> <p>Independent Enterprises is the excavator. Their AVR states, “Plastic gas service line was too shallow and directly under the concrete road base. The contractor was placing new 8" water along Fairlee St when the the operator lifted up the asphalt/concrete road base he snagged the shallow gas line going 1804 Fairlee St. The contractor immediately called 911 immediately after the gas service line was hit. At 11:10 AM People's Gas came to the work site and verified that the gas line was theirs. At 11:35 AM People's Gas arrived at the work site to make the gas line repair. People's Gas completed the gas service line repair at 1:30 PM.”</p> <p>Pittsburgh Water is the project owner. Their AVR states the same information as is in the summary of Independent Enterprises’ AVR.</p> <p>Images submitted show the site, marks, and damaged line. The damaged line is within the tolerance zone of the yellow marks. The line appears to have been uncovered previously as the dirt in the area around and underneath has already been removed at 11:26 AM.</p> <p>G A I Consultants is the designer. An AVR has not been filed as of 10/14/2025.</p>	<p>Peoples Natural Gas: \$0.00</p> <p>Independent Enterprises Inc: \$2,250.00 Section 5(4) Subsequent \$2,250.00</p> <p>Comcast: \$2,000.00 Section 2(5)(v) Subsequent \$2,000.00</p> <p>Verizon: \$1,000.00 Section 2(5)(v) Subsequent \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Ticket #20252053856 New – Excavation – Routine had a response due date of 7/30/2025. Peoples Gas responded “Field Marked” on 7/31/2025. Verizon responded “Clear” on 8/6/2025. Comcast responded “Clear” on 8/29/2025.</p> <p>This case is related to the following cases by Tickets: 057007, 057069, 057305, 057768</p> <p>Violations: Excavator – Independent Enterprises: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements.</p> <p>Facility-Peoples Natural Gas: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket #20252053856 Recommendation: PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).</p> <p>Facility (other) -Comcast: Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket #20252053856 Recommendation: PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).</p> <p>Facility (other) -Verizon: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket #20252053856 Recommendation: PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).</p>	
57804	<p>Facility Owner: Comcast Contractor/Excavator: SIPPEL DEVELOPMENT CO, INC Project Owner: WALKER TOWNSHIP WATER ASSOCIATION, INC. Other: WALKER TOWNSHIP CENTRE COUNTY Other: West Penn Power Other: Zito Media</p>	<p><u>On 8/19/2025 12:00:00 PM at E COLLEGE AVE, WALKER TWP, CENTRE</u> On 1/13/2026 the DPC voted to remove the violations and penalties for West Penn Power and Sippel Development. ***** West Penn Power disputing - provided note from locator that excavator was contacted about not marking by due date, but no documentation that excavator approved. Sippel Development - disputing - no additional information provided. ***** The incident occurred on 8/19/2025, at 12:00 PM, on E College Ave and Zion Back Road, in Walker Twp, Centre County.</p> <p>A communication line owned by Comcast was damaged.</p> <p>Comcast is the facility owner. Their Alleged Violation Report (AVR) was submitted on 10/7/2025 and does not have a summary or information on the damage. An</p>	<p>Comcast: \$5,500.00 Section 2(10) 3rd Offense \$2,000.00</p> <p>Section 2(5)(v.2) Subsequent \$1,500.00</p> <p>Section 2(5)(vii) 3rd Offense \$2,000.00</p> <p>SIPPEL DEVELOPMENT CO, INC: \$0.00</p> <p>WALKER TOWNSHIP WATER ASSOCIATION, INC.: \$0.00 Section 6.1(7) 1st Offense</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>attachment included with their AVR has images of the marks and damage.</p> <p>Sippel Development is the excavator. Their AVR states, "THE DAMAGE IS IN THE PENNDOT R/W ALONG THE EDGE OF THE RD. THE CLOSEST ADDRESS IS 1645 E COLLEGE AVE, BELLEFONTE, PA. LOCATED ACROSS COLLEGE AVE FROM THIS ADDRESS. THE DAMAGE OCCURED AT ZION BACK RD AND E COLLEGE AVE INTERSECTION. THE COMCAST LINE WAS NOT MARKED AND THE ORIGINAL ONE CALL TICKET INDICATED COMCAST FACILITIES WERE CLEAR." Sippel did not provide images or additional documentation.</p> <p>Walker Twp Water Authority is the project owner. An AVR has not been filed as of 10/15/2025.</p> <p>Herbert Rowland And Grubic Inc is the designer. An AVR has not been filed as of 10/15/2025.</p> <p>Images provided show the mark out photos on 7/15/2025 with orange marks at the location where the damaged occurred on 8/19/2025. The photos from 8/19/2025 show the area of the damage, and the damaged line. The area where the marks were on 7/15/2025 has been excavated, or no visible marks remain where the area was not excavated. No evidence of hand digging or soft excavation techniques in the tolerance zone.</p> <p>Ticket #20252313225 New – Damage – Emergency was entered on 8/19/25 at 1:56 PM. Comcast responded "Insufficient information." On 8/19/2025 at 3:23PM as their only response. Walker Township Centre County responded "Clear" on 8/26/2025.</p> <p>Ticket # 20251890446 New – Excavation – Routine had a response due date of 7/13/2025. Comcast and West Penn Power responded that lines would be marked by 7/15/2025, and then responded "Clear" on 7/15/2025. *Comcast's line is the line that was damaged.* Zito Media responded "Clear" on 7/16/2025. Walker Township Centre County responded "Clear" on 7/14/2025 at 1:49PM.</p> <p>Violations: Comcast – Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner's lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket # 20251890446 Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket #20252313225</p>	<p>\$0.00</p> <p>WALKER TOWNSHIP CENTRE COUNTY: \$1,250.00 Section 2(5)(v) 1st Offense \$250.00</p> <p>Section 2(5)(vii) 1st Offense \$1,000.00</p> <p>West Penn Power: \$0.00</p> <p>Zito Media: \$500.00 Section 2(5)(v) 2nd offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).</p> <p>Excavator -Sippel Development: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements.</p> <p>Project Owner - Walker Twp Water Authority: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. PUC Online Compliance Training is required. The penalty has been reduced from \$1000 to a warning of \$0.</p> <p>Facility(other) – West Penn Power: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket # 20251890446 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).</p> <p>Facility(other) -Walker Township Centre County Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket # 20251890446</p>	
57690	<p>Facility Owner: PEOPLES NATURAL GAS SUPPLIER for Homeowner</p> <p>Contractor/Excavator: KANAAN COMMUNICATIONS LLC</p> <p>Project Owner: COMCAST</p> <p>Other: WEST PENN POWER / FIRST ENERGY</p>	<p><u>On 8/19/2025 5:26:00 PM at 1421 DEEP WOOD DR, UPPER ST CLAIR TWP, ALLEGHENY</u> On 1/13/2026 the Damage Prevention Committee (DPC) voted to accept the DPI recommendation for the 2(5)(i) violation to West Penn Power / First Energy and withdraw the 2(5)(iii.1) violation.</p> <p>*</p> <p>First Energy's West Penn Power is disputing. ****</p> <p>The incident occurred on 8/19/2025 at 1421 DEEP WOOD DR at UPPER ST CLAIR TWP in Allegheny County.</p> <p>A gas service line was damaged.</p> <p>PEOPLES NATURAL GAS SUPPLIER submitted an AVR for the Homeowner, stated in their Alleged Violation Report (AVR) that “on 8/19/25 KANAAN COMMUNICATIONS BORING FOR COMCAST STRUCK THE CUSTOMERSIDE GAS SERVICE LINE AT 1421 DEEPWOOD DR. KANAAN COMMUNICATIONS HAS CUSTOMER SIDE SERVICE SPOTTED. WHILE PULLING BACK ON DRILL, DRILL HEAD CAME INTO CONTACT WITH LINE AND SEVERED IT. KANAAN COMMUNICATIONS NOTIFIED 911 AND 811 AND PNG ARRIVED ONSITE AND MADE SAFE. KANAAN COMMUNICATIONS NEEDS TO REPAIR/REPLACE CUSTOMER SERVICE LINE”. 911 was notified. Pictures were provided.</p>	<p>KANAAN COMMUNICATIONS LLC: \$1,750.00 Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(11.2) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>WEST PENN POWER / FIRST ENERGY: \$1,500.00 Section 2(5)(i) 3rd Offense \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>KANAAN COMMUNICATIONS LLC did not submit an AVR as of 10/09/2025.</p> <p>Comcast the project owner did not submit an AVR. AVR request letter was not sent.</p> <p>VIOLATIONS KANAAN COMMUNICATIONS LLC is in violation of:</p> <p>Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or damaging a facility owner’s line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.</p> <p>Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area.</p> <p>Section 5(11.2) – When using trenchless technology, Excavator failed to utilize at a minimum, the best practices published by the Common Ground Alliance CGA 21.0 Section 9(5-29) The excavator requests the location of underground facilities at the entrance pit, trenchless excavation path and the exit pit by notifying the facility owner/operator through the 811 center. The trenchless equipment operator performs a site inspection, walking the trenchless excavation path prior to commencing work, and has a good understanding of the job. The trenchless excavation operator confirms and maintains the path and minimum clearances established by the project owner and design engineer by tracking and recording the path of the trenchless excavation until complete. Means of trenchless excavation include electronic locating/guidance devices, pipe lasers, water levels, visual inspection, ect.</p> <p>Emergency ticket 20252314426 was submitted on 8/19/2025 for 1412 Deep Wood Dr. Damage occurred while directional drilling. Pictures show the damage in line with the markout.</p> <p>Recommendation: The penalties are applied. Excavator training is required.</p> <p>WEST PENN POWER is in violation of:</p> <p>Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Ticket 20252100634-000 was submitted by Kanaan Communications LLC on 7/29/2025 with a response due by 7/31/2025. Location is Deep Wood Dr. and the area is noted as marked in white. West Penn Power is asked to mark the lines with the remarks that Attn West Penn Power responded clear on the previous ticket, caller is aware that you are involved. This is a third time offense.</p> <p>Section 2(5)(iii.1) – Facility owner failed to propose a mutually agreeable scheduling by which the excavator, facility owner or designer may locate the facilities. Ticket 20252100634-001 was submitted by Kanaan Communications LLC on 8/07/2025 with a response due by 7/31/2025. Work is noted as not starting yet. Location is Deep Wood Dr. and the area is noted as marked in</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>white. West Penn Power is asked to mark the lines with the remarks that Attn West Penn Power responded clear on the previous ticket, but caller is aware that you are involved.</p> <p>West Penn Power responded on 7/31/2025 “scheduled mark”, then on 8/07/2025 “field marked”.</p> <p>Recommendation: The penalties are applied. Facility owner training was recently completed.</p>	
58191	<p>Facility Owner: PEOPLES GAS COMPANY LLC</p> <p>Contractor/Excavator: Shields Paving</p> <p>Project Owner: SEWICKLEY HILLS BORO</p>	<p><u>On 8/25/2025 1:52:00 PM at 47 TROTTER CIR, SEWICKLEY HILLS BORO, ALLEGHENY</u> On Tuesday, 1/13/2026, at the Virtual DPC Meeting, disputing party was Shields Paving. It was voted to accept the DPI’s recommendations. *****</p> <p>Disputing is Shields Paving, disputes any responsibility for payment. *****</p> <p>The incident occurred on Monday, August 25, 2025, at 47 Trotter Circle, in Sewickley Hills Borough, Allegheny County.</p> <p>Peoples Gas Company line was damaged.</p> <p>Peoples Gas stated in their Alleged Violation Report (AVR), on 8/25/2025, Shields Paving struck an unmarked PNG SL main to curb, the SL was 7" deep. On Friday 8/22/2025, PNG responded 006, Scheduled Mark- scheduled date and time the line will be marked by: 8/25/2025 at 1:36m, and on 8/25/2025, at 12:58pm, PNG responded as Field Marked.</p> <p>On Monday 8/25/2025, When PNG made a phone call to the onsite contact person, Nick with Shields Paving, they told PNG that they are very close to finishing up the job. PNG locator could not gain access to mark site due to active work taking place. The SL was struck an hour later from phone conversation.</p> <p>Peoples Gas provided photos of the damaged line. Shields Paving did not submit an AVR.</p> <p>Violations:</p> <p>*Shields Paving is in violation of sections: 5(20) – Excavator failed to renotify One Call of an unmarked or incorrectly marked facility upon arrival at a work site. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line.</p> <p>Recommendation: Penalties Applied, and PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements.</p>	<p>Shields Paving: \$1,250.00 Section 5(20) 1st Offense \$250.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>
58369	<p>Facility Owner: UGI Utilities Inc</p> <p>Contractor/Excavator: R III Construction INC</p> <p>Project Owner: SCHUYLKILL COUNTY MUNICIPAL AUTHORITY</p> <p>Designer: GANNETT</p>	<p><u>On 8/26/2025 2:05:00 PM at PIERCE ST, POTTSVILLE CITY, SCHUYLKILL</u> On 1/13/2026 the Damage Prevention Committee (DPC) voted to keep the violation and reduce the penalty to a warning. Education is maintained. *</p> <p>R III Construction INC is disputing 5(16) - Excavator failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. R III submitted</p>	<p>UGI Utilities Inc: \$0.00</p> <p>R III Construction INC: \$0.00 Section 5(16) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	FLEMING WATER RESOURCES	<p>an AVR on 10/13/2025 after an AVR request letter was sent. R III has previous violations for 5(16).</p> <p>*****</p> <p>Both UGI violations removed. 2(5)(i.1) is not correct because UGI owns the line, so they should have been cited for not marking the lateral within 18 inches. 2(5)(i) is for customer owned lines that tap into a main. 2(5)(i.2) UGI said there are no communications to document.</p> <p>*****</p> <p>The incident occurred on 8/25/2025 on PIERCE ST in Pottsville City in Schuylkill County.</p> <p>A gas service line was damaged.</p> <p>UGI UTILITIES INC the facility owner stated in their Alleged Violation Report (AVR) that “Excavator utilizing mechanized equipment, struck and unmarked gas service”. They added as the reason for the damage was the facility was marked incorrectly. 911 was notified. Report and pictures were provided.</p> <p>R III Construction the excavator was sent an AVR request letter on 10/09/2025. DPI returned a call to Phil from RIII Construction. He stated that he has been in this business long time and has never had to do this before. DPI gave him the www.paonecall.org and the OneCall telephone number and extension, if he has any trouble submitting it online. AVR was submitted on 10/13/2025. The incident date was 8/26/2025 and the AVR should have been submitted by 9/26/2025. They stated in their AVR that “There was an unmarked gas line that was hit when excavating for a water main which was being installed for Pottsville Water Authority”. They list the project as >\$400,000. This project was expected to take 8 mo to complete for the installation of 8000’ of pipe. Pictures were submitted.</p> <p>GFT Construction Services also known as GANNETT FLEMING WATER RESOURCES GFT stated the designer sent in an AVR on 8/26/2025 stating that they are also representing SCHUYLKILL COUNTY MUNICIPAL AUTHORITY (SCMA) the project owner. They summarized that “R-III pulled an active gas service from 600 Pierce Street. The service was NOT marked /indicated anywhere at curb or roadway”. They also noted that this was a facility owner issue because the lines were not marked correctly. Picture was provided. *Case 55426 is related by ticket</p> <p>SCHUYLKILL COUNTY MUNICIPAL AUTHORITY (SCMA) the project owner was represented by the AVR from GFT Construction Services.</p> <p>VIOLATIONS UGI Utilities Inc is in violation of: Section 2(5)(i.1) – Failed to locate an actually known facility’s point of connection to its facilities. This is a second time offense.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(i.2) – Failed to document Communications between a Facility Owner and Excavator to ensure the excavator is aware of a facility owner’s inability to locate it’s facilities.</p> <p>Recommendations: The penalties are applied. The facility owner required education was recently completed.</p> <p>R III Construction INC is in violation of: Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or damaging a facility owner’s line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. AVR was submitted late and after DPI Maki requested an AVR to be submitted. Recommendation: \$1000. Penalty is reduced by half to \$500. Excavator education is required.</p>	
58183	<p>Facility Owner: Penelec Contractor/Excavator: Randy Scouten Contracting Project Owner: Homeowner</p>	<p><u>On 8/29/2025 2:49:00 PM at 22896 TITUSVILLE RD, OILCREEK TWP, VENANGO</u> On 1/13/2026 the DPC voted on Penelec's violations and penalties: 2(5)(v.1)- Remove the violation and penalty. 2(5)(v.2)- Remove the violation and penalty.</p> <p>***** Penelec is disputing *****</p> <p>The incident occurred on 8/29/2025, at 22896 Titusville Rd, in Oilcreek Twp, Venango County.</p> <p>An electric line owned by Penelec was not marked by the response due date of both the routine and renotify ticket.</p> <p>Penelec is the facility owner. Their Alleged Violation Report (AVR)states, “On August 26, 2025, Randy Scouten Contracting, Excavator, submitted PA One Call ticket 20252385099 for 22896 Titusville Rd, Oilcreek Township, Venango County to install a sewer system for a new mobile home at the location. On August 28, 2025, Penelec’s Contract Locator, USIC, responded “not marked due to no access,” USIC explained that it cannot send technicians to the site without a police escort because of armed death threats made by the occupant of the location to the technician during prior site marks. The Pennsylvania State Police will not assist in escorting the technician to the site. Early in September, an article indicated that charges had been filed against the property owner for making threats to a utility worker. Neither Penelec nor USIC believe it is safe to go to the site without formal protection while this occupant is present. In addition, the response date for the aforementioned ticket was August 28, 2025. Penelec is submitting this AVR within 30 business days of the ticket response date and should not be considered out of compliance.”</p> <p>Randy Scouten Contracting is the excavator. Their AVR states, “Requested a line to be located & locating company refuses to mark the line.”</p>	Penelec: \$0.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Homeowner , Nancy Kelly, is the project owner. An AVR has not been filed as of 09/12/2025.</p> <p>Ticket #20252385099 New – Excavation – Routine – Penelec responded “Not marked due to no access” on 8/28/2025. A renotify ticket was entered on 9/3/2025 at 6:25PM and Penelec responded“ Request meeting” on 9/4/2025 at 7:31 AM.</p> <p>The information provided by Penelec shows they received the renotify on 9/3/2025 and created an internal note on the markout on 9/4/2025 stating, “Spoke with Contractor last week, told him we are not sending anyone out to this location. we are not putting our techs lifes at risk. Randy is aware he needs to contact first energy to have this handled. This is and ongoing problem. We were told to never come back, if so we would be killed. WE ARE NOT LOCATING THIS AREA.” Their next internal note on 9/4/2025 at 2:00PM states, “Left a message for Randy, to set up a Time to locate with a Police escort 9/4/2025 @1:55pm”.</p> <p>The news report that could be located was from August 7th, 2025 and states, “According to court documents, 73-year-old Daniel Alan Eakin, of Pleasantville, was arrested on Tuesday morning after a reported threat was made to an electric company regarding service at his Harmony Township, Forest County residence.” The report lists a Neiltown Road address, but doesn’t specify the house number. Neiltown road is roughly 6 miles away from the address on the ticket. Additionally, no properties at the ticket address list Mr. Eakin as the owner. The ticket also lists Nancy Kelly, the property owner listed on Venango County’s tax website, as who the work is being done for.</p> <p>Violations: Facility owner – Penelec: Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket #20252385099-000 Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Ticket #20252385099-001 Recommendation: PUC Online Compliance Training is required.</p>	
58357	Facility Owner: Peoples Natural Gas Contractor/Excavator: TOY PIPELINE CONTRACTORS INC	<p><u>On 9/5/2025 3:43:00 PM at 4TH AVE, NEW KENSINGTON CITY, WESTMORELAND</u> On 1/13/2026 the DPC voted to: Keep the violation and penalty for Peoples Gas Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time - Routine Ticket 20252190251 – 2nd offense - \$500.00 + Education (2 days late)</p> <p>Toy Pipeline Contractors Inc.- Keep the violation but reduce the penalty from \$1000 to \$0 for Section 5(16) failure to submit an AVR within 30 days of striking a line or other violation –</p>	<p>Peoples Natural Gas: \$500.00 Section 2(5)(v) 2nd offense \$500.00</p> <p>TOY PIPELINE CONTRACTORS INC: \$0.00 Section 5(16) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>*****</p> <p>Toy Pipeline Contractors emailed information on the damage on 12/5/2025. No AVR was submitted for this incident to date. The information they provided showed there were additional white marks not seen in the images provided by Peoples Gas. Peoples Gas did not mark the line that was damaged. 5(2.2), 5(6)(i), and 5(8) were withdrawn. 5(16) is not changed as Toy had all the information for the incident but has not submit an AVR to date.</p> <p>****</p> <p>Peoples Gas - disputing -This incident occurred almost a month after Peoples indicated they provided training to their staff in July of 2025 to correct the issues that caused the ticket to not be responded to correctly.</p> <p>*****</p> <p>The incident occurred on 9/5/2025, at 3:43 PM, on 4Th Ave, in New Kensington City, Westmoreland County.</p> <p>A gas line owned by Peoples Gas was damaged.</p> <p>Peoples Gas is the facility owner, project owner, and designer. Their Alleged Violation Report (AVR) states, “THE SITE WAS MARKED TO THE WHITE ARROWS AND THEY DECIDED TO DIG 15 FEET OUTSIDE OF THE MARKINGS. THEY SHOULD HAVE CALLED FOR MARKS BEFORE DIGGING BEYOND THE ARROWS OF THE ONE CALL.” Peoples indicates that 911 was not contacted.</p> <p>Toy Pipeline Contractors is the excavator. An AVR has not been filed as of 10/03/2025.</p> <p>Ticket # 20252190251 New – Excavation – Routine had a response due date of 8/12/2025. Peoples Gas responded “Field Marked” on 8/13/2025 at 1:28 PM.</p> <p>Locating information for Ticket # 20252190251: INSTALLING TWO PARALLEL NATURAL GAS MAINLINES ON 4TH AVE BETWEEN 9TH AND 10 TH STREET. THE TIE-IN ON THE 9TH STREET END WILL BE APPROXIMATELY 100 FT SOUTH OF THE INTERSECTION OF 4TH AVE AND 9TH STREET. SERVICE LINES TO THE BUILDINGS ALONG THE PROJECT ROUTE MAY ALSO BE REPLACED.]</p> <p>The damage occurred at the intersection of 9th and 4th street. The excavator did not request this location to be marked for this ticket. No other ticket was located for this site and excavation. Images were provided that show the site, excavation with mechanized equipment, marks, and damage. There is a white arrow pointing south at the intersection of 4th and 9th and the damage is north of that indication. The excavator was working outside of the scope of the ticket.</p> <p>Violations: Excavator - Toy Pipeline Contractors:</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 5(2.2) – Excavator failed to provide exact information to identify the worksite.</p> <p>Section 5(6) – Excavator failed to inform each operator employed by the excavator at the work site of the information obtained.</p> <p>Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property.</p> <p>Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.</p> <p>Recommendation: PUC Online Compliance Training is required.</p> <p>Facility (other)-Peoples Gas:</p> <p>Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket # 20252190251</p> <p>Recommendation: PUC Online Compliance Training is required.</p>	