



**Pennsylvania Public Utility Commission**

**Damage Prevention Committee Meeting Case List  
Tuesday, May 12, 2026**

**Omnibus Session**

Case Number	Stakeholders	Summary	Violations & Recommendation
57297	<p><b>Facility Owner:</b> PECO  <b>Contractor/Excavator:</b> Presti Grounds Care  <b>Project Owner:</b> PROPERTY OWNER  <b>Other:</b> Comcast  <b>Other:</b> KEVIN CARNEY PLUMBING HEATING AND COOLING</p>	<p><u>On 8/6/2025 12:07:00 PM at 209 HUNTER LN, UPPER GWYNEDD TWP, MONTGOMERY</u> Presti Grounds Care had originally disputed this case, but has withdrawn their dispute and are now accepting.</p> <p>*****</p> <p>The incident occurred on August 6th, 2025, at 12:07 PM, at 209 Hunter Lane, in Upper Gwynedd Township, Montgomery County.</p> <p>A gas line owned by PECO was damaged.</p> <p>PECO, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, "Carney Plumbing and Heating was digging to repair a sewer lateral with mechanical means inside the tolerance zone of a properly marked gas service when they struck the service causing damage." Photos were submitted.</p> <p>Kevin Carney Plumbing Heating and Cooling was originally listed as the excavator and disputed to the DPC. Upon discussion at the DPC meeting, it was determined the digging and damage was caused by a subcontractor, Presti Grounds Care. Both Kevin Carney Plumbing Heating and Cooling and Presti Grounds Care were present at the DPC meeting on 02/10/2026.</p> <p>Presti Grounds Care is the excavator. An AVR has not been filed as of 02/18/2026.</p> <p>The property owner is the project owner. An AVR has not been filed as of 02/18/2026.</p> <p>The submitted photos show utility locates. The utility locates are from a different stakeholder's ticket request. Presti Grounds Care did not request their own Pa One Call ticket.</p> <p>Emergency ticket 20252182876 had a response due date of 08/06/2025.  - Comcast replied to the ticket on 08/29/2025.</p> <p>PECO's AVR did not indicate if 911 was called. The emergency ticket noted that the excavator was advised to call 911. Presti Grounds Care noted in their dispute they did contact 911.</p> <p>Violations:</p>	<p><b>Presti Grounds Care: \$500.00</b>  Section 5(23) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$0.00</p> <p><b>Comcast: \$2,500.00</b>  Section 2(5)(vii) Subsequent \$2,500.00</p> <p><b>KEVIN CARNEY PLUMBING HEATING AND COOLING: \$0.00</b></p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Presti Grounds Care-</p> <ul style="list-style-type: none"> <li>- Section 5(23) – Excavator may not delegate their duty to submit a locate request to the One Call System to another person. The excavator shall have sole responsibility to submit each locate request to the One Call System.</li> <li>- Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.</li> </ul> <p>Recommendation: The penalty is applied. PUC compliance training education was recently completed.</p> <p>Kevin Carney Plumbing Heating and Cooling- Violations withdrawn. Not the excavator performing</p> <ul style="list-style-type: none"> <li>- Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.</li> <li>- Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.</li> </ul> <p>Comcast-</p> <ul style="list-style-type: none"> <li>- Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Emergency ticket 20252182876.</li> </ul> <p>Recommendation: The penalty is applied. PUC compliance training education was recently completed.</p>	
58721	<p><b>Facility Owner:</b> UGI Utilities, Inc. <b>Contractor/Excavator:</b> Superior Pocahontas LLC <b>Other:</b> Comcast <b>Other:</b> Met Ed / First Energy <b>Other:</b> North Lebanon Township</p>	<p><u>On 9/23/2025 11:35:00 AM at OAK LN, NORTH LEBANON TWP, LEBANON</u> North Lebanon Township submitted a dispute with additional information. The violation was reduced from a first offense to a warning, no penalty. Education is required.</p> <p>Comcast accepts.</p> <p>First Energy Accepts.</p> <p>*****</p> <p>The incident occurred on September 23rd, 2025, at 11:35 AM, on Oak Lane, in North Lebanon Township, Lebanon County.</p> <p>A gas line owned by UGI was damaged. 911 was called.</p> <p>UGI, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “Superior Pocahontas LLC was directional drilling to replace electric line. They failed to use prudent techniques to expose correctly marked gas service line before drilling activities. As a result, the gas service line was struck and damaged.” Photos were submitted.</p> <p>Superior Pocahontas LLC is the excavator. An AVR has not been filed as of 01/20/2026. An AVR request letter was sent 01/06/2026.</p>	<p><b>Superior Pocahontas LLC: \$1,500.00</b> Section 5(4) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p><b>Comcast: \$1,500.00</b> Section 2(5)(v) 1st Offense \$500.00</p> <p>Section 2(5)(vii) 1st Offense \$1,000.00</p> <p><b>Met Ed / First Energy: \$500.00</b> Section 2(5)(v) 1st Offense \$500.00</p> <p><b>North Lebanon Township: \$0.00</b> Section 2(5)(v) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>The project owner is unknown. The AVR request letter that was sent to the excavator, requested the name and contact information for the project owner.</p> <p>The submitted photos show the damaged gas line was correctly marked using yellow paint. The gas line was damaged within the tolerance zone.</p> <p>Routine ticket 20252133458 had a response due date of 08/05/2025. - North Lebanon Township responded 08/07/2025.</p> <p>Routine ticket 20252301457 had a response due date of 08/20/2025. - Comcast responded on 08/20/2025, with the response, "SCHEDULED DATE &amp; TIME LINES WILL BE MARKED BY: 20 Aug 2025 2359", but did not respond field marked until 09/04/2025. - Met Ed responded on 08/20/2025, with the response, "SCHEDULED DATE &amp; TIME LINES WILL BE MARKED BY: 20 Aug 2025 2359", but did not respond field marked until 09/04/2025.</p> <p>Emergency ticket 20252661839 had a response due date of 09/23/2025. - Comcast responded 09/28/2025.</p> <p>Violations:</p> <p>Superior Pocahontas LLC- - Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>North Lebanon Township- - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20252133458. Recommendation: This is a warning. No penalty applied. PUC compliance training education is required.</p> <p>Met Ed- - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Routine ticket 20252301457. Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Comcast- - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Routine ticket 20252301457. - Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Emergency ticket 20252661839. Recommendation: The penalty is applied. PUC compliance training education is required.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
58826	<p><b>Facility Owner:</b> West Penn Power / First Energy  <b>Contractor/Excavator:</b> A Liberoni, INC  <b>Project Owner:</b> Hempfield Township  <b>Other:</b> Verizon</p>	<p><u>On 9/24/2025 11:22:00 AM at SPRUCE ST, HEMPFIELD TWP, WESTMORELAND</u> First Energy Accepts.</p> <p>*****</p> <p>The incident occurred on September 24th, 2025, at 11:22 AM, on Spruce Street, in Hempfield Township, Westmoreland County.</p> <p>An electrical line owned by West Penn Power was damaged.</p> <p>West Penn Power, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “On September 19, 2025, Rich Swartz, “Excavator,” working for Hempfield Township submitted POCS Routine Ticket 20252621299 to repair roadway base on Spruce Street, Hempfield Township, Greensburg, Westmoreland County, PA. On September 24, 2025, West Penn Power (WPP) was notified of an outage at 1070 Spruce Street. WPP investigated and located a broken neutral cable. USIC, WPP’s Contract Locator, investigated and determined that the Excavator hit and damaged an unmarked underground line. The root cause of the damage was that the technician cleared the ticket and did not mark WPP’s underground facilities.” Photos were submitted.</p> <p>A Liberoni, Inc., the excavator, submitted an AVR. Their AVR states, “We were base repairing Spruce Street in Hempfield Township/Greensburg. The base repairs were extensive and painted out prior to placing the once call. We milled out for the base repair and broke the unmarked electric line. Photos attached.” Photos were submitted.</p> <p>Hempfield Township is the project owner. An AVR request letter was sent 01/06/2026. An AVR was submitted and states, “A. Liberoni, working on behalf of Hempfield Township, were conducting base repairs on Spruce Street in Hempfield Township. The base repairs were extensive and painted out prior to placing the one call. While milling for the base repair, they broke the unmarked electric line.” Photos were submitted.</p> <p>West Penn Power replied to the routine ticket 20252621299 on 09/23/2025, with “Clear – No Facilities or Facilities not involved”. The damaged utility line was not marked.</p> <p>Routine ticket 20252621299 had a response due date of 09/23/2025.  - Verizon did not respond to this ticket until 09/24/2025. (1 day late)</p> <p>Violations:</p> <p>West Penn Power-</p>	<p><b>West Penn Power / First Energy: \$500.00</b>  Section 2(5)(i) 1st Offense \$500.00</p> <p><b>Verizon: \$250.00</b>  Section 2(5)(v) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>- Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Verizon-</p> <p>- Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Routine ticket 20252621299. Recommendation: The penalty is applied.</p>	
59001	<p><b>Facility Owner:</b> PECO  <b>Project Owner:</b> ALLIANCE PRO MASONRY</p>	<p><u>On 9/29/2025 12:00:00 AM at 2087 FLOWING SPRINGS RD, WEST VINCENT TWP, CHESTER</u> The incident occurred on 9/29/2025, at 12:00 AM, on 2087 Flowing Springs Rd, in West Vincent Twp, Chester County.</p> <p>An electric line owned by PECO was damaged.</p> <p>PECO is the facility owner. Their Alleged Violation Report (AVR) states, “Alliance Pro masonry IS WORKING FOR HOMEOWNER TO INSTALL A STONE WALL/GATE ACROSS DRIVEWAY. NO PA ONE CALL AT TIME OF DAMAGE.” A damage report with pictures was provided. The damaged line is shown. PECO added in a subsequent email, “ The Concrete company was the GC on-site and took responsibility for the damage. He said that he did not dig, he hired someone to dig, but he wanted to take full responsibility, he shared all of his company info with the PECO responder.”</p> <p>Alliance Pro Masonry is the excavator and a project owner. An AVR has not been filed as of 12/12/2025 and an AVR request was sent the same day. Nothing has been received from them as of 1/15/2026.</p> <p>No tickets were located by PA One Call for this site and timeframe.</p> <p>Images provided show the site, excavation, and damaged line. There are 2 orange flags seen in the vicinity of the damage but no tickets were found by PA One Call. Use of mechanized equipment is shown. The excavator, Alliance Pro Masonry, has not submit an AVR or replied to any requests for information.</p> <p>Violations:  Alliance Pro Masonry:  Section 1.1 – Excavator did not begin within legal timeframe.  “The lawful start date shall be three business days through ten business days following notification to the One Call System.”  Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe.  Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area.</p>	<p><b>ALLIANCE PRO MASONRY: \$4,000.00</b>  Section 1.1 1st Offense \$1,000.00</p> <p>Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 6.1(7) 1st Offense \$1,000.00</p> <p>Section 6.1(8) 1st Offense \$500.00</p> <p>Section 5(21) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike.</p> <p>Section 6.1(8) - Project Owner failed to comply with all requests for information by the commission relating to the commission's enforcement authority under this act within 30 days of receipt of written request.</p> <p>Section 5(21) – Excavator failed to pay the annual fee for service provided by the One Call System.</p> <p>Recommendation: PUC Online Compliance Training is required.</p>	
58896	<p><b>Facility Owner:</b> Fiber AssetCo (Previously Crown Castle)</p> <p><b>Contractor/Excavator:</b> Buckley Cable Construction</p> <p><b>Project Owner:</b> Buckley Cable Construction (Placeholder)</p> <p><b>Designer:</b> AMERICOMM LLC</p>	<p><u>On 9/29/2025 9:00:00 AM at 1011 W BALTIMORE PIKE, PENN TWP, CHESTER</u> The non-damage event occurred on September 29th, 2025, at 9:00 AM, at 1011 West Baltimore Pike, in Penn Township, Chester County.</p> <p>Non-responses to PA One Call Tickets.</p> <p>Crown Castle is the facility owner. An Alleged Violation Report (AVR) has not been filed as of 01/27/2026. An AVR request letter was sent 01/06/2026.</p> <p>Buckley Cable Construction, the excavator and project owner, submitted an AVR. Their AVR states, “Stake Center is not coming out to mark the utilities they are responsible for. They marked one ticket 20252163065, we did not get too this work in time. So I called a second ticket 20252670104. This ticket has gone unheard. PA ONE submitted a ticket on Monday Sept 29th to re notify crown castle that they aren't marked out. I reached out to crown castle on Tuesday Sept 30th and spoke to them 4 separate times 3x between 630 653. I asked that they mark out the ticket, that i would begin construction at 9am. I did not start construction due to them not showing up, not marking their utility”.</p> <p>AMERICOMM LLC is the designer. An AVR has not be filed as of 01/27/2026.</p> <p>Routine ticket 20252670104 – version 000 had a response due date of 09/26/2025.</p> <p>- On 09/26/2025 at 11:21:55 PM, Crown Castle responded to the ticket with, “Insufficient information. Do not dig.” – This is considered an interim response. A final response was not received. There were no notes on the ticket from Crown Castle.</p> <p>Renotify Routine ticket 20252670104 – version 001 was requested on 09/29/2025 at 06:37 AM. The remarks on the renotify ticket states, “Attention Crown Castle you responded 004-insuff info. Do not dig 9/26/2025 11:21 PM. Please respond asap to mark any underground lines as the crew en route will be on site in appx 1 hour to start the work. Please contact Nicholas George at his cell xxx xxx 3662 with any questions Thank you.”</p> <p>- Crown Castle did not respond to this ticket.</p> <p>Renotify Routine ticket 20252670104 – version 002 was requested 10/01/2025 at 06:34 AM. The remarks on the renotify ticket states, “Attn Crown Castle you did not</p>	<p><b>Fiber AssetCo (Previously Crown Castle): \$1,250.00</b></p> <p>Section 2(5)(v.2) 1st Offense \$250.00</p> <p>Section 2(5)(v.1) 1st Offense \$500.00</p> <p>Section 2(5)(v.1) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>respond to the ticket. Crew will be on site within the hour. Please go to the site asap mark your lines if involved and update your response or respond to the ticket.”</p> <p>- On 10/01/2025 at 12:21 PM, Crown Castle responded to the ticket with, “Insufficient information. Do not dig.” – There were no notes on the ticket from Crown Castle.</p> <p>- On 10/03/2025 at 11:03 AM, Crown Castle responded, “Field Marked”.</p> <p>The excavator made multiple attempts to have Crown Castle mark their lines and reported they were unable to start their project due to the unmarked lines.</p> <p>Violations:</p> <p>Crown Castle-</p> <p>- Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket 20252670104 – version 000.</p> <p>- Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. 20252670104 – version 001.</p> <p>- Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. 20252670104 – version 002.</p> <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
61136	<p><b>Facility Owner:</b> WEST PENN POWER / FIRSTENERGY</p> <p><b>Contractor/Excavator:</b> Eby Paving and Construction</p> <p><b>Project Owner:</b> Berks Homes</p> <p><b>Other:</b> Comcast</p>	<p><u>On 10/1/2025 8:00:00 AM at 246 Acer Avenue, State College, PA, BENNER TWP, CENTRE</u> Met Ed requested a reduced or removed penalty since they submitted the first AVR for this incident. Met Ed was previously provided a reduced penalty for the same reason, and that occurred prior to the events for this incident.</p> <p>*****</p> <p>The incident occurred on 10/1/2025, at 8:00 AM, on 246 Acer Avenue, in Benner Twp, Centre County.</p> <p>An electric line owned by West Penn Power was damaged. No One Call ticket was placed prior to the damage. An emergency ticket was called in after the damage occurred.</p> <p>West Penn Power is the facility owner. Their Alleged Violation Report (AVR) was submitted on 12/15/2025 and states, “On October 1, 2025, West Penn Power was notified of an outage at 246 Acre Avenue, Benner Township, Centre County, Pennsylvania. USIC, West Penn Power’s Contract Locator, investigated and determined that Eby Paving and Construction Inc., “Excavator”, damaged a conduit and a single-phase primary line. The root cause of the damage was that the Excavator failed to request the location and type of facility owner through the One Call System.”</p> <p>Eby Paving And Construction is the excavator. An AVR was not filed as of 01/29/2026 and an AVR request was sent the same day. An AVR was filed on 1/30/2026 that states, “While excavating for a sewer, we struck a power</p>	<p><b>WEST PENN POWER / FIRSTENERGY:</b>  <b>\$1,000.00</b>  Section 2(10) 1st Offense  \$1,000.00</p> <p><b>Eby Paving and Construction: \$2,250.00</b>  Section 5(2.1) 1st Offense  \$1,000.00</p> <p>Section 5(6)(i) 1st Offense  \$250.00</p> <p>Section 5(16) 1st Offense  \$1,000.00</p> <p><b>Berks Homes: \$1,000.00</b>  Section 6.1(7) 1st Offense  \$1,000.00</p> <p><b>Comcast: \$1,000.00</b>  Section 2(5)(vii) 1st Offense  \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>conduit. Without interrupting service, we only broke the conduit. The power company was notified, and we repaired it as instructed by them.”</p> <p>Berks Homes is the project owner. An AVR was not filed as of 01/29/2026 and an AVR request was sent the same day. No AVR was submitted, or contact made, as of 2/11/2026.</p> <p>Images submitted show the site, excavation, and damage. There are no marks in the vicinity of the damage, which would be expected as there was no valid ticket for this excavation.</p> <p>Ticket #20252744475 New – Damage – Emergency was entered on 10/1/25 at 3:58 PM. Comcast’s only response was “Clear” on 10/4/2025.</p> <p>Violations:  Facility – West Penn Power:  Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work.  PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement.</p> <p>Excavator - Eby Paving And Construction:  Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe.  Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area.  PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements.  Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.  PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement.</p> <p>Project Owner - Berks Homes:  Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike.  PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement.</p> <p>Facility(other) – Comcast:  Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).	
58944	<p><b>Facility Owner:</b> Peoples Gas</p> <p><b>Contractor/Excavator:</b> Mele &amp; Mele &amp; Sons, Inc.</p> <p><b>Project Owner:</b> Pittsburgh Water and Sewer Authority</p> <p><b>Designer:</b> MS CONSULTANTS</p> <p><b>Other:</b> JOHNSON MIRMIRAN AND THOMPSON J M T</p>	<p><u>On 10/1/2025 8:15:00 AM at 4558 CARROLL ST, PITTSBURGH CITY, ALLEGHENY</u> The incident occurred on October 1st, 2025, at 8:15 AM, at 4558 Carroll Street, in Pittsburgh City, Allegheny County.</p> <p>A gas line owned by Peoples Gas was damaged. 911 was not called.</p> <p>Peoples Gas, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “Mele and Mele and Sons working for Pittsburgh Water and Sewer struck and damaged a marked Peoples Gas service line. The lines were marked back in May. There have been no updates for this ticket. Per the Peoples Gas first responder, Mele admitted to exposing the service previously and knowing it was in the area and still damaged it.” Photos were submitted.</p> <p>Mele and Mele and Sons, the excavator, submitted an AVR. Their AVR states, “Crews were digging for a proposed sanitary sewer, during excavations, the tooth caught a 1" service line. Peoples Gas was contacted around 0900 AM, and the repair was made around 1100 AM. Emergency response form Peoples Gas cinched the line to prevent gas dispersing in the area.”</p> <p>Pittsburgh Water and Sewer, the project owner, submitted an AVR. Their AVR states, "Mele hit a marked Peoples Gas service line.” Photos were submitted.</p> <p>MS Consultants, the designer, submitted an AVR. Their AVR states, "Mele &amp; Mele &amp; Sons were digging for a proposed 15-inch sewer. During the excavation, tooth caught a 1-inch gas service line. Peoples Gas was contacted around 9:00 AM and the repair was made around 11:00 AM. Emergency response from Peoples Gas cinched the gas line to prevent gas dispersing in the area.”</p> <p>Mele and Mele and Sons and Pittsburgh Water and Sewer reported on their AVRs that 911 was not called.</p> <p>The line hit occurred on 10/01/2025. The most recent ticket (20251191543) for the location where the damage occurred, was requested on 04/29/2025. – Peoples Gas timely responded to this ticket on 05/01/2025, with the response of ‘Field Marked’. The ticket notes the duration of the work as 60-days to repair sanitary sewer.</p> <p>The submitted photos show the damaged gas line. There are not any visible utility mark outs in the submitted photos. A renotify ticket was not requested.</p> <p>A gas curb stop is visible in the submitted photos, indicating there are underground gas lines in the area. Google Street view shows the gas meter is located at the</p>	<p><b>Mele &amp; Mele &amp; Sons, Inc.: \$1,750.00</b> Section 5(3) 1st Offense \$500.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(8) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>front of the home located at 4558 Carroll St., where the damage occurred.</p> <p>Routine tickets 20252270723 and 20252391199 were for work being completed on Comrie Way and do not cover the location where the damage occurred, and therefore unrelated.</p> <p>This case is related to cases 030410 and 059085.</p> <p>Violations:</p> <p>Mele and Mele and Sons-</p> <ul style="list-style-type: none"> <li>- Section 5(3) – Excavator failed to preserve mark-outs or request a remark.</li> <li>- Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area.</li> <li>- Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property.</li> </ul> <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
58948	<p><b>Facility Owner:</b> PEOPLES NATURAL GAS COMPANY LLC</p> <p><b>Contractor/Excavator:</b> PETER J CARUSO AND SONS</p> <p><b>Project Owner:</b> McGann and Chester Towing</p> <p><b>Other:</b> COMCAST</p>	<p><u>On 10/1/2025 8:30:00 AM at 70 INDUSTRIAL WAY, COLLIER TWP, ALLEGHENY</u> McGann and Chester Towing disagrees. DPI Maki responded in an email and also returned a call. An email was received on 3/05/2026 that an AVR was submitted. They stated in their AVR that “On October 1, 2025, at approximately 8:40 am, the main office received notification of an incident at McGann and Chesters’ Pittsburgh Truck Center, 70 Industrial Way, Collier Twp, 15106. Robert McGann, Owner, and Ryan McGann, Operations Manager, responded from the main office. Once on site at 70 Industrial Way, Collier Twp, PA 15106, the management team confirmed with onsite management and Peter J Caruso and Sons onsite representatives that the emergency services were notified immediately at the time of the incident by Peter J Caruso and Sons employees. The structure and surrounding area were evacuated, and all pilot lights and sources of ignition were confirmed to be off by onsite management. The management team coordinated with emergency responders and utility representatives to resolve the incident as safely and expeditiously as possible. After Incident meeting with Peter J Caruso and Sons onsite management showed that an accidental strike of the line had resulted from shifting debris during excavation. Peter J Caruso and Sons management staff advised McGann and Chester LLC management staff that they were handling all of the incident related reporting. There were no injuries or fatalities reported to McGann and Chester related to this incident. Pictures were provided. The penalties for violations of 6.1(7) and 6.1(8) are reduced to a warning. Education is maintained to McGann and Chester Towing.</p>	<p><b>PETER J CARUSO AND SONS: \$500.00</b> Section 5(6)(ii) 1st Offense \$500.00</p> <p><b>McGann and Chester Towing: \$0.00</b> Section 6.1(7) 1st Offense \$0.00</p> <p>Section 6.1(8) 1st Offense \$0.00</p> <p><b>COMCAST: \$500.00</b> Section 2(5)(v) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>*****</p> <p>The incident occurred on 10/01/2025 at 70 Industrial Way in Collier Township in Allegheny County.</p> <p>A gas service line was damaged.</p> <p>PEOPLES NATURAL GAS COMPANY LLC reported that "PETER J CARUSO AND SONS working for McGann and Chester Towing struck and damaged an accurately marked 3in customer side service line. PETER J CARUSO AND SONS noted on the one call that they knew the gas line was within the excavation area. Peoples Gas accurately marked the service line and PETER J CARUSO AND SONS damaged the line while using mechanized equipment within the tolerance zone while the service line was exposed". 911 was notified. Pictures were provided.</p> <p>PETER J CARUSO AND SONS stated in their AVR that "Our company was digging to repair a collapsed drain line section. The line ran over top of the gas service line. We specifically called to locate that service and hand dug around it to expose it. The material we were digging through was very hard and a piece of rock approximately 1' x 1', broke loose and fell on top of the service, puncturing it". No project owner provided. Pictures were provided.</p> <p>AVR LETTER WAS SENT TO PO McGann and Chester Towing on 10/08/2025. No AVR has been received as of 1/23/2026.</p> <p><b>VIOLATIONS</b></p> <p>PETER J CARUSO AND SONS is in violation of: Section 5(6)(ii) – Excavator failed to provide support and mechanical protection for known facility owner’s lines at the construction work site.  Recommendation: The penalty is applied. PUC compliance education is required for the excavators working onsite of this excavation or their replacements.</p> <p>McGann and Chester Towing is in violation of: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike or damaging a facility owner’s line during excavation or demolition work activities or if a project owner believes a violation of this act has been committed in association or demolition. No AVR has been received as of 1/23/2026.</p> <p>Section 6.1(8) - Project Owner failed to comply with all requests for information by the commission relating to the commission's enforcement authority under this act within 30 days of receipt of written request. Questions in the AVR request letter waws not responded to.  Recommendation: The penalty is applied. PUC project owner compliance education is required for the person responsible for submitting AVR or their replacement.</p> <p>COMCAST is in violation of:</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(v) – Failed to respond to routine One Call ticket 20252622733, which was submitted on 9/19/2025 at 13:49 by Peter J Caruso and Sons and the response was due by 9/23/2025. Comcast never responded. Recommendation: The penalty is applied. The required PUC education was recently completed.</p>	
59004	<p><b>Facility Owner:</b> BOROUGH OF WEST CHESTER</p> <p><b>Contractor/Excavator:</b> Brubacher Excavating Inc</p> <p><b>Project Owner:</b> AQUA PENNSYLVANIA INC</p> <p><b>Designer:</b> BRANDYWINE CAD DESIGN</p> <p><b>Other:</b> VERIZON</p>	<p><u>On 10/3/2025 10:00:00 AM at GOSHEN RD, WEST GOSHEN TWP, CHESTER</u> Brandywine CAD Design (BCD) disagreed. This is a first-time offense. The penalties to Brandywine CAD are reduced by half. On 3/19/2026 BCD accepted the violations and reduced penalty. *****</p> <p>The incident occurred on 10/03/2025 on Goshen Rd. in West Goshen Township in Chester Co.</p> <p>A sewer line owned by West Chester Borough was damaged.</p> <p>BRUBACHER EXCAVATING INC stated in their Alleged Violation Report (AVR) that “While excavating the trench for new water main installation on Aqua Goshen Road project, the crew encountered an unmarked sewer line. An 8" diameter red/brown line was found at 4'- 2" deep. The excavation was in the street at intersection of Goshen Rd and Hillside Drive. The work was being performed for Aqua PA. Original Ticket #2025 258 0378 (Goshen Twp) and 2025 258 0379 (W Chester Boro) the damage ticket #2025 276 1149 (Goshen Twp) and 2025 276 1150 (W Chester Boro). West Goshen Twp was notified and sending someone out to investigate". Pictures were provided.</p> <p>*WEST GOSHEN SEWER AUTHORITY was mailed an AVR request letter on 12/16/2025. They returned a call stating that the Borough of Westchester owns the sewer lines in this area.</p> <p>Aqua PA stated in their AVR that “ Aqua Contractor Brubacher Excavating, while excavating the trench for new water main installation on Goshen Rd project, the crew encountered an unmarked sewer line. An 8" diameter red/brown line was found at 4' 2" deep. The excavation was in the street at intersection of Goshen Rd &amp; Hillside Dr. West Goshen Twp was notified and sending someone out to investigate”. Report and map was provided.</p> <p>WEST CHESTER BOROUGH submitted an AVR with no Summary but noted that this line was “marked incorrectly”. DPI had asked questions in the AVR request letter. None of the questions asked in the AVR request letter were answered. AVR was due by 11/18/2025. AVR was received on 1/05/2026.</p> <p>BRANDYWINE CAD DESIGN was sent an AVR request letter on 12/16/2025. AVR was due by 11/18/2025. No AVR has been received as of 1/23/2026. None of the questions asked in the AVR request letter were answered.</p>	<p><b>BOROUGH OF WEST CHESTER: \$2,000.00</b> Section 2(10) 1st Offense \$1,000.00</p> <p>Section 2(14) 1st Offense \$500.00</p> <p>Section 2(5)(i) 1st Offense \$500.00</p> <p><b>BRANDYWINE CAD DESIGN: \$875.00</b> Section 4(2.5) 1st Offense \$250.00</p> <p>Section 4(8) 1st Offense \$500.00</p> <p>Section 4(3) 1st Offense \$125.00</p> <p><b>VERIZON: \$500.00</b> Section 2(5)(v) 2nd offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>The construction start date is listed as 8/09/2024. The Bid date is listed as 8/18/2024. The most current final design was submitted on 3/08/2024. That is 108 business days from the construction date.</p> <p><b>VIOLATIONS</b>  WEST CHESTER BOROUGH is in violation of:  Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.  Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work.  Section 2(14) - Failed to comply with all requests for information by the commission relating to the commission's enforcement authority under this act within 30 days of receipt of request.  Recommendation: The penalties are applied. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p> <p>BRANDYWINE CAD DESIGN is in violation of:  Section 4(2.5) – Failed to comply with all requests for information by the commission relating to the commission's enforcement authority under this act within 30 days of receipt of request. The penalty of \$500. is reduced to \$250.  Section 4(8) – Designer failed to submit an Alleged Violation Report through the One Call System within 30 business days of being notified or aware that a violation of this act may have been committed. The penalty of \$1000. is reduced to \$500.  Section 4(3) – Designer’s drawing does not show the position and type of each facility owner’s line, and the name of the facility. The design in the report only shows the water line details. The penalty of \$250. is reduced to \$125.  Recommendation: The penalties are reduced by half. PUC compliance education is required for the designer(s) who worked on this project or their replacement(s).</p> <p>VERIZON is in violation of:  Ticket 200252580378 was submitted by BRUBACHER EXCAVATING INC on 9/15/2025 with a response due by 9/17/20025. Verizon did not respond until they “field marked” on 9/18/2025.  Recommendation: The penalty is applied. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p>	
59176	<b>Facility Owner:</b> UGI Utilities Inc. <b>Contractor/Excavator:</b> Grace Industries Inc.	<u>On 10/7/2025 8:25:00 AM at SR 2025, EASTON CITY, NORTHAMPTON</u> The incident occurred on October 7th, 2025, at approximately 8:25 AM, on SR 2025, in Easton City, Northampton County.	<b>Grace Industries Inc.:</b> <b>\$500.00</b> Section 5(4) 1st Offense \$500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p><b>Project Owner:</b> Traffic Planning and Design, INC.  <b>Designer:</b> PENNONI  <b>Other:</b> PennDOT</p>	<p>A gas line owned by UGI Utilities Inc. was damaged. 911 was called.</p> <p>UGI Utilities Inc., the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, "Grace Industries was digging and when doing so they struck a correctly marked gas service facility creating a damage. They were digging in the tolerance zone." Photos were submitted.</p> <p>Grace Industries Inc. is the excavator. An AVR request letter was sent 01/07/2026. They submitted an AVR that states, "A gas line was hit while removing stone from curblines at 106 Cattell St."</p> <p>Traffic Planning and Design Inc. (representing the City of Easton) is the project owner. An AVR request letter was sent 01/07/2026. They submitted an AVR that states, "Contractor excavated the existing sidewalk (PA One Call marks were on the sidewalk) and placed Subbase material. The contractor was grading the subbase and hit the service line with the tooth of the excavator." They reported on their AVR they are representing the City of Easton.</p> <p>PENNONI is the designer. An AVR request letter was sent 01/07/2026. They submitted an AVR that states, "Pennoni was not notified or aware of the incident until receiving the AVR request on January 8, 2026, and did not have an opportunity to document photo/video evidence of the damage. Pennoni was the final designer for the project. Project estimated cost was ~\$600,000. Utilities were field surveyed and PA1Call design request was submitted. The project also went through the PennDOT URMS system for utility clearance. The attached plans show the known utilities displayed on the plan. The excavator did not request additional compensation to our knowledge. The project was bid through PennDOT's ECMS system, all contract documents can be found under ECMS#118435, the original advertised contract is attached. The final design cover plan and plan sheet #3 show the standard PA1Call notes, including the legend. As previously stated, Pennoni was not notified of the incident by the contractor, inspector, City or owner and was not able to document any damages."</p> <p>PennDOT submitted an email stating, "The associated project is a FAM/Municipal type project where the Municipality (City of Easton) holds the contract with Grace Industries. PennDOT's role in this ECMS 118435 project is oversight to ensure it meets federal requirements (i.e. materials, testing, documentation, etc.) per the reimbursement agreement. Therefore, I believe the Project Owner is actually the City of Easton, not PennDOT."</p> <p>The submitted photos show the gas line marked using yellow paint. The damaged gas line was within the</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>tolerance zone. Three of the submitted AVR's noted that the damage was caused by a backhoe/track hoe. Two of the AVRs specifically listed the damage was caused by a Road Builder excavator.</p> <p>Violations:</p> <p>Grace Industries Inc.-  - Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.  Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
59454	<p><b>Facility Owner:</b> UGI Utilities, Inc.  <b>Contractor/Excavator:</b> Deer Ridge Construction, LLC  <b>Project Owner:</b> Property Owner</p>	<p><u>On 10/11/2025 9:40:00 AM at 300 N. 24th St, CAMP HILL BORO, CUMBERLAND</u> The non-damage event occurred on October 11th, 2025, at 9:40 AM, at 300 N. 24th Street, in Camp Hill Borough, Cumberland County.</p> <p>Non-damage. Excavation taking place without a Pa One Call ticket.</p> <p>UGI Utilities, Inc., the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, "Deer Ridge Construction was excavating at 300 N. 24th St in Camp Hill, PA to install a stoop at front door. The homeowner of the property called into UGI concerned about how close they were digging to where they believed the gas line to be. Upon the arrival of the UGI first responder, he discovered the excavation to be very close to the gas line. There were no marks on the ground at this point. The UGI first responder called into 811 to report the No One Call. The UGI first responder put paint on the ground for reference to see how close excavation was to gas service." Photos were submitted.</p> <p>Deer Ridge Construction, LLC is the excavator. An AVR has not been filed as of 01/14/2026.</p> <p>The homeowner is the project owner. An AVR has not been filed as of 01/14/2026.</p> <p>A Pa One Call ticket was not requested by Deer Ridge Construction, LLC. The submitted photos show excavation work has started outside a single-family home. A mini excavator can be seen in the photos. A gas curb stop is visible in the photos, indicating there is an underground gas line.</p> <p>Pa One Call reported Deer Ridge Construction does place one call notifications.</p> <p>Violations:</p> <p>Deer Ridge Construction, LLC-  - Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. (No prior violations.)  Recommendation: The penalty is applied. PUC compliance training education is required.</p>	<p><b>Deer Ridge Construction, LLC: \$1,000.00</b>  Section 5(2.1) 1st Offense  \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
59949	<p><b>Facility Owner:</b> PECO AN EXELON COMPANY  <b>Contractor/Excavator:</b> W.K. FRAME &amp; SONS INC  <b>Project Owner:</b> JAKE PREMIER LLC  <b>Designer:</b> JAKE PREMIER LLC  <b>Designer:</b> PADULA ENGINEERING COMPANY</p>	<p><u>On 10/14/2025 10:00:00 AM at 824 JUNIPER DR, WHITEMARSH TWP, MONTGOMERY</u> The incident occurred on Tuesday, October 14, 2025, at 824 Juniper Drive, in Whitemarsh Township, Montgomery County.</p> <p>A gas line owned by PECO An Exelon Company was damaged.</p> <p>PECO stated in their damage investigation report, on 10/14/2025 at 824 Juniper Dr Lafayette Hills, contractor WK Frame &amp; Son damaged a plastic gas main for obligated ticket 20252654269. Site was not completely marked out. Marks do not extend to the damage location. The closest mark for the gas main is approximately 15 feet from where the damage occurred. Locator did not mark the full scope of the ticket. Determination: USIC at Issue</p> <p>The project owner, Jake Premier stated in their Alleged Violation Report (AVR), Hit an unmarked gas line while excavating water curb valve.</p> <p>W.K. Frame and Sons stated in their AVR, digging in the front yard for sewer lateral and water line connections and the excavator bucket rubbed against the side of the gas line.</p> <p>On Tuesday, 1/6/2026, an email and letter were sent to W.K. Frame and Sons requesting an AVR. They submitted their AVR on 1/6/2026, not within 30 days of the 10/14/2025 incident.</p> <p>Violations:</p> <p>*PECO An Exelon Company is in violation of section: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.  Recommendation: Penalty Applied</p> <p>*W.K. Frame and Sons is in violation of section: 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line.  Recommendation: Penalty Applied, and PUC Online Compliance Training is required for the Excavator(s) working onsite at this excavation, or their replacements. (W.K. Frame and Sons did not take education for from 2022, related cases 16534 and 20175. Also, 4 years delinquent on paying invoice 016534-004025)</p>	<p><b>PECO AN EXELON COMPANY: \$500.00</b>  Section 2(5)(i) 1st Offense \$500.00</p> <p><b>W.K. FRAME &amp; SONS INC: \$1,000.00</b>  Section 5(16) 1st Offense \$1,000.00</p>
59509	<p><b>Facility Owner:</b> PECO  <b>Contractor/Excavator:</b> DELMONT UTILITIES COMPANY  <b>Project Owner:</b> Aqua AMERICA  <b>Designer:</b> CHESTER VALLEY ENGINEERS  <b>Other:</b> Upper Darby  <b>Other:</b> VERIZON</p>	<p><u>On 10/14/2025 10:15:00 AM at COPLEY RD, UPPER DARBY TWP, DELAWARE</u> The incident occurred on 10/14/2025 on Copley Rd in UPPER DARBY TWP in Delaware Co.</p> <p>Electric lines owned by PECO were unmarked.  Gas lines owned by PECO were located and not damaged.</p> <p>DELMONT UTILITIES COMPANY (DUC) stated in their AVR that “WORKING AT THE INTERSECTION OF COPLEY ST AND MARKET ST. DIGGING OUT CUT TRENCH TO INSTALL 8" WATER MAIN. AND CAME ACROSS A CONCRETE BASE IN THE</p>	<p><b>PECO: \$250.00</b>  Section 9 1st Offense \$250.00</p> <p><b>Upper Darby: \$1,000.00</b>  Section 2(5)(vii) 1st Offense \$1,000.00</p> <p><b>VERIZON: \$500.00</b>  Section 2(5)(v.2) 2nd Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>BOTTOM OF THE TRENCH AT 4'2" COVER. CALLED PECO AND THEY CAME OUT AND MARKED THE ELECTRIC. WE HAD TO MOVE OUR TRENCH". Pictures were provided.</p> <p>DELMONT UTILITIES COMPANY (DUC) submitted another AVR that stated that "WORKING TO INSTALL WATER MAIN AT COPLEY RD AND MARKET ST AND CAME ACROSS A GAS MAIN MARK. WE PRUDENTLY DUG OUT ON THE MARK AND 5 FEET ON EITHER SIDE OF THE MARK. DID NOT FIND GAS MAIN. WASTED TIME". They added that this line was marked incorrectly.</p> <p>We called PECO after we could not find the gas main on the mark. We vac excavated at the mark and hand dug 18 inches on both sides of mark and did not find the main. When We called Peco they came out and remarked and also vac excavated to look for it and initially did not find. They made an incision on the pipe and traced it and finally found the main ON THE MARK. We also very much appreciate Ryan and Matt. As my foreman put it, they are a super bowl team when they work together. It sounds like all parties had a difficult time finding the main. Some closer pictures from the foreman are attached". Another email was received on 1/13/2025 with more pictures.</p> <p>AQUA PENNSYLVANIA INC stated in their AVR that "Aqua Contractor Delmont Utilities, working at the intersection of Copley St and Market St. Digging out cut trench to install 8" water main. Crew came across a concrete base in the bottom of the trench at 4'2" cover. Called PECO and they came out and marked the electric. Crew had to move their trench". Report was provided.</p> <p>AQUA PENNSYLVANIA INC submitted another AVR which stated that " AQUA CONTRACTOR DELMONT UTILITIES, WORKING TO INSTALL WATER MAIN AT COPLEY RD AND MARKET ST CAME ACROSS A GAS MAIN MARK. CREW PRUDENTLY DUG OUT ON THE MARK AND 5 FEET ON EITHER SIDE OF THE MARK. CREW DID NOT FIND GAS MAIN".</p> <p>Peco was sent an AVR request letter on 12/19/2025. PECO AN EXELON COMPANY stated in their AVR that "PECO was working with Delmont Utilities in Upper Darby to locate our electric lines while Demont was installing water lines. PECO COC was installing the new electric in front of Delmont, there was a mutual agreement that the lines would be marked as they were installed, no as built were turned in due to the work being so new, so it took time to have everything located in front Delmont. Delmont field was okay with this, but clearly that was not communicated with their office". On 1/05/2025 DPI Maki asked PECO about the gas line incident and if the new facilities were marked as they were going in. DPI also asked for documentation of any agreements. PECO was sent an AVR request letter on 12/19/2025. On 12/30/2025 an email was received asking for more information about this incident. DPI</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Maki replied with more details and questions. It was found that PECO had submitted an AVR for the electric issue with this same excavator. The AVR's were combined</p> <p>On 1/07/2025 PECO sent an email explaining what occurred at this site and stated that when they brought their vac trucks out, they located the gas lines" on the marks". PECO added that "Joe and his crew did not clear the tolerance zone with their vac trucks and literally missed the services in a few locations by inches". DPI Maki sent an email asking for any photos from PECO. On 1/8/2026 PECO responded that they had no pictures to provide.</p> <p>CHESTER VALLEY ENGINEERS stated in their AVR that "There were two incidents for this emergency ticket1. The gas main could not be located. Mains were marked in the field but could not be found after contractor performed a test hole location. PECO (gas facility owner) was called out to the field to help locate the mains. 2. 3 unmarked electric lines were hit. There was no damage to the services lines themselves, just the plastic and concrete casing, and Upper Darby (electric service owner) was able to repair the casing on site. The lines are for the traffic lights. Both utility companies were called to assist with the incidents". Plans and pictures were provided.</p> <p>PECO was sent an AVR request letter on 12/19/2025. On 12/30/2025 an email was received asking for more information about this incident. DPI Maki replied with more details and questions.</p> <p>*No violations for the gas line issue. The excavator could not locate it by using soft digging techniques and notified PECO. PECO came out and located their line. No damage.</p> <p>* Emergency ticket 20252893148 was submitted with AVR2026JAN050012 on 1/27/2026 and is for an incident which occurred on 10/16/2025, so the damage violations are not presented in this case. The ticket responses are considered. Emergency ticket 20252893148 was submitted by Delmont Utilities on 10/16/2025 at 14:13. Remarks state that " THERE WERE 3 LINES INCASED IN CONCRETE. 2 OF THE CONDUITS ARE BROKEN, BUT THE CALLER STATES THAT THE LINES ALL APPEAR TO NOT BE DAMAGED. THE DAMAGED CONDUITS ARE THE CROSSWALK WIRING AND TRAFFIC LIGHT LINES OWNED BY UPPER DARBY".</p> <p>VIOLATIONS PECO is in violation of: Section 9 CGA compliance Section 21.0. 4-22: Marking Newly Installed Facilities. Practice description: In areas of continued excavation, newly installed facilities can be damaged, and safety compromised if the facilities are not marked. Marking facilities upon installation gives notice to other excavators of the newly installed facilities that may not otherwise be marked in response to a notice of intent to excavate. PECO had this same violation Section</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>9 for not marking newly installed facilities in case 31321.  Recommendation: The penalty is applied. The required PUC education was recently completed.</p> <p>Upper Darby is in violation of:  Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Emergency ticket 20252893148 was submitted by Delmont Utilities on 10/16/2025 at 14:13. Remarks state that “ THERE WERE 3 LINES INCASED IN CONCRETE. 2 OF THE CONDUITS ARE BROKEN, BUT THE CALLER STATES THAT THE LINES ALL APPEAR TO NOT BE DAMAGED. THE DAMAGED CONDUITS ARE THE CROSSWALK WIRING AND TRAFFIC LIGHT LINES OWNED BY UPPER DARBY”. Upper Darby Township did not respond “Field Marked” until 10/20/2025. This was an Upper Darby facility.  Recommendation: The penalty is applied. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). Upper Darby has not yet completed the training that was required to be completed by 9/07/2025.</p> <p>VERIZON is in violation of:  Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Emergency ticket 20252893148 was submitted by Delmont Utilities on 10/16/2025 at 14:13. Remarks. VERIZON RESPONDED WITH “conflict”. This is a second offense.  Recommendation: The penalty is applied. The Required PUC training has recently been completed.</p>	
59435	<p><b>Facility Owner:</b>  PENCORE SERVICES / Blue Ridge Communications  <b>Contractor/Excavator:</b> R L E ENTERPRISES  <b>Project Owner:</b>  PENNSYLVANIA AMERICAN WATER (PAWC)  <b>Other:</b> COOLBAUGH TOWNSHIP  <b>Other:</b> PPL  <b>Other:</b> WINDSTREAM ENTERPRISE/WHOLES ALE</p>	<p><u>On 10/17/2025 7:20:00 AM at MOUNTAIN DRIVE, MOUNT POCONO BORO, MONROE PAWC</u> disagreed. The 2 violations 4(3) and 4(4.1) were withdrawn based on Pencore/Blueridge did not acknowledge any facilities during the design phase, but they did respond to the Complex project meeting as planning to attend.</p> <p>PPL Disagreed. On 3/05/2026 email was received from PPL that they agree with the violation and penalty.  ****  The incident occurred on 10/17/2025 on Mountain Dr. in MOUNT POCONO BORO in MONROE Co.</p> <p>A Coaxial Communications line owned by PENCORE SERVICES / Blue Ridge Communications was damaged.</p> <p>R L E ENTERPRISES stated in their Alleged Violation Report (AVR) that “While Digging for a new water main installation, our crew struck a mismarked cable wire 9 feet from the mark at 20 Mountain Drive. Blue Ridge Communications was contacted about the damage”. Pictures were provided. On 1/16/2026 DPI reached out for more information about the line damage and requested the part of the design which would show the communications line and name. R L E ENTERPRISES</p>	<p><b>PENCORE SERVICES / Blue Ridge Communications:</b>  <b>\$2,500.00</b>  Section 2(5)(v.2) 1st Offense \$250.00</p> <p>Section 2(5)(v.2) 1st Offense \$250.00</p> <p>Section 2(10) 1st Offense \$1,000.00</p> <p>Section 2(11) 1st Offense \$500.00</p> <p>Section 2(5)(i) 1st Offense \$500.00</p> <p><b>PENNSYLVANIA AMERICAN WATER (PAWC): \$0.00</b></p> <p><b>COOLBAUGH TOWNSHIP: \$1,000.00</b>  Section 2(5)(vii) 1st</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>responded in an email that “No one reached out to us about paying for this damage. To my best knowledge Blue ridge owns all the communication lines in this area but I dont have access to there maps to see where they exactly own”. An email received on 1/21/2025 stated that “They were onsite for other damages and we asked for a direct contact number but they would not provide us with one. So we just called in the damage ticket to PA 1 Call.”</p> <p>* As of 1/21/2026 Blue Ridge listed online as the 99.61% Cable Internet Service Provider in Mount Pocono.</p> <p>PENNSYLVANIA AMERICAN WATER (PAWC) stated in their AVR that ““While Digging for a new water main installation, RLE struck a mis marked cable wire 9 feet from the mark at 20 Mountain Drive. Blue Ridge Communications was contacted about the damage". Report was provided. project is listed as &gt;\$400,000. and over 4000'. On 1/16/2026 DPI reached out for more information about the line damage and requested the part of the design which would show the communications line and name. PA American responded that "I have attached the design sketch for reference, but Blue Ridge does not provide drawings typically".</p> <p>PENCORE SERVICES / Blue Ridge Communications were sent an AVR request letter on 12/18/2025. On 1/16/2026 an email was received stating that “we have no record of incident at the stated address on or near the dates provided. I'm not sure what else you would need from Blue Ridge CATV Technologies at this time?”. Please note that Emergency ticket 20252872250 PENCOR SERVICES/BLUE RIDGE COMMUNICATION responded “PT-INSUFF INFO. DO NOT DIG” on10/14/2025 at 14:56. Verizon responded clear.</p> <p>Emergency ticket 2025900229 was submitted by R L E ENTERPRISES on 10/17/2025 at 07:48. Verizon responded “clear”. Pencore Services / Blue Ridge gave an response of “Insuff Info”.</p> <p>Emergency ticket 20252872250 was submitted by R L E ENTERPRISES on 10/14/2025 with a response due by 10/14/2025. Electric line was damaged. PPL Electric, WINDSTREAM ENTERPRISE/WHOLESALE, and PENCOR SERVICES/BLUE RIDGE COMMUNICATION responded “PT-INSUFF INFO. DO NOT DIG” on10/14/2025 at 14:56. Verizon responded clear.</p> <p>Case is related by tickets to Case 59317 (electric line strike ticket 20252872250) and Case 59761 still in progress as of completion of this case.</p> <p><b>VIOLATIONS</b> R L E ENTERPRISES is in violation of: Section 5(3.1) – Scope of project exceeds the maximum area of a routine ticket. Mountain Dr is a looped Road which is in Coolbough Township and Mt. Pocono</p>	<p>Offense \$1,000.00</p> <p><b>PPL: \$500.00</b> Section 2(5)(v.2) 2nd Offense \$500.00</p> <p><b>WINDSTREAM ENTERPRISE/WHOLE SALE: \$250.00</b> Section 2(5)(v.2) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Borough. There are also multiple roads that intersect it. The entire road is &gt; 4000' in length. The two emergency tickets 20252872250 and 20252872249 have both: an intersecting road and a different political subdivision. Recommendation: The penalty is applied. PUC compliance education is required for the excavators working onsite of this excavation or their replacements.</p> <p>PENNSYLVANIA AMERICAN WATER (PAWC) is in violation of:  Section 4(3) – Designer’s drawing does not show the position and type of each facility owner’s line, and the name of the facility. Please see the design that was provided. No communications lines are noted in the design.  Recommendation: The penalty is applied. PUC compliance education is required for the designer(s) who worked on this project or their replacement(s).</p> <p>Section 4(4.1) - Failed to depict lines or facilities with the appropriate quality levels based on the complexity of the design and construction activities obtained through the SUE process in the planning and design phases in accordance with the American Society of Civil Engineers (ASCE) most recently published standard CI/ASCE 38. Best practices 21.1 chapter 2-2 and 2-3 specifies the steps needed for gathering Information for deign purposes including contacting the operators directly. 2-3 reads that During the design phase of the project, underground facility information from the planning phase is shown on the plans, If information was gathered from field-located facilities, potholing, underground facility surveys, or subsurface Utiliyt Engineering, (SUE) this is noted on the plans...In the event that confirmation is unavailable regarding the physical location of an existing public or private underground facility, a process to identify these facilities is noted on the plan And in bid/contract documents as applicable.  Recommendation: The penalty is applied. PUC compliance education is required for the designer(s) who worked on this project or their replacement(s).</p> <p>COOLBAUGH TOWNSHIP is in violation of:  Section 2(5)(vii) – Failed to respond to emergency notification 20252872250 as soon as practicable following notification. Ticket 20252872250 was submitted by  R L E Enterprises on 10/14/2025 at 12:14.  COOLBAUGH TOWNSHIP did not respond until 10/16/2025 at 14:59.  Recommendation: The penalty is applied. The Required PUC compliance training was recently completed.</p> <p>PENCORE SERVICES / Blue Ridge Communications is in violation of:  Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Emergency ticket 20252872250: “INSUFF INFO. DO NOT DIG” was the response given.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Emergency ticket 2025900229: “INSUFF INFO. DO NOT DIG” was the response given.</p> <p>Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. Please note that R L E Enterprises stated that Pencore / Blue Ridge was at the site after the damage and that DPI Maki sent an AVR request letter to PENCOR SERVICES/BLUE RIDGE COMMUNICATION contact.</p> <p>Section 2(11) – Facility Owner failed to comply with all requests for information by the Commission relation to the Commission’s enforcement authority under this act within thirty days of the receipt of the request. Questions in the AVR letter were not answered.</p> <p>Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendations: The penalties are applied. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p> <p>WINDSTREAM ENTERPRISE/WHOLESALE is in violation of:  Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Emergency ticket 20252872250 response was “INSUFF INFO. DO NOT DIG”.  Recommendation: The penalty is applied. The PUC required facility owner training was recently completed.</p> <p>PPL is in violation of:  Section 2(5)(v.2) - Failed to timely enter a final response to all locate requests. Emergency ticket 20252872250 response was “INSUFF INFO. DO NOT DIG”. This is a second time offense.  Recommendation: The penalty is applied. The PUC required facility owner training was recently completed</p>	
59574	<p><b>Facility Owner:</b> National Fuel Gas  <b>Contractor/Excavator:</b> Alexis Building Systems  <b>Other:</b> V &amp; V Paving and Construction</p>	<p><u>On 10/17/2025 8:00:00 AM at 7266 W Market Street Lot 34, LACKAWANNOCK TWP, MERCER</u> Incident occurred on October 17th, 2025, at 8am on 7266 West Market Street, Lot 34, Lackawannock Township, Mercer County.</p> <p>A gas line was damaged.</p> <p>National Fuel Gas' Alleged Violation Report (AVR) states, "Excavator struck a properly marked natural gas distribution service. Excavator did not have a valid PA One Call ticket request and worked off of another contractor's ticket (POCS Ticket Number 20252801590)"  NFG's AVR does not note if 911 was notified.</p>	<p><b>Alexis Building Systems:</b>  <b>\$2,500.00</b>  Section 5(2.1) 1st Offense  \$1,000.00</p> <p>Section 5(4) 1st Offense  \$500.00</p> <p>Section 5(16) 1st Offense  \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>PA1 call commented: Alexis Building Systems has placed one call notifications in the past.</p> <p>Violations:</p> <p>Alexis Building Systems  Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. PUC compliance education is required.  Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. PUC compliance education is required.  Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required.</p>	
59578	<p><b>Facility Owner:</b> Comcast  <b>Contractor/Excavator:</b> VEOLIA WATER  <b>Project Owner:</b> VEOLIA WATER (Placeholder)</p>	<p><u>On 10/22/2025 8:55:00 AM at 22 MALL RD, NEWBERRY TWP, YORK</u> Comcast accepts.  *****</p> <p>The incident occurred on October 22nd, 2025, at approximately 8:55 AM, at 22 Mall Road, in Newberry Township, York County.</p> <p>A telecom line owned by Comcast was damaged.</p> <p>Comcast, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR did not include a detailed summary of events and stated they, “Followed PA1 Tickets to fill this [AVR] out. FIBER OPTIC LINE CREW ON SITE. FACILITY TYPE: TELECOM-UNKNOWN EXCAVATION EQUIPMENT: BACKHOE”</p> <p>Veolia Water, the excavator and project owner, submitted an AVR. Their AVR did not include a summary of the event but did indicate that the damaged line was marked inaccurately and mismarked by almost 4 feet. Photos were submitted.</p> <p>The submitted photos show the damaged line was more than 18 inches away from the orange paint that was used to mark the line. Damage did not occur within the tolerance zone of the orange marking.</p> <p>Violations:</p> <p>Comcast-  - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.  Recommendation: The penalty is applied. PUC compliance training education is required.</p>	<p><b>Comcast: \$500.00</b>  Section 2(5)(i) 1st Offense  \$500.00</p>
59617	<p><b>Facility Owner:</b> Peoples Natural Gas  <b>Contractor/Excavator:</b> KUZNESKI CONTRACTING  <b>Project Owner:</b> Homeowner  <b>Other:</b> Comcast</p>	<p><u>On 10/22/2025 12:02:00 PM at 209 EAGLE AVE, WHITE TWP, INDIANA</u> Kuzneski provided additional information - reduced violation 5(16) from \$1000 to a warning of \$0, and a reduction on the 5(20) from \$250 to a warning of \$0. They are disputing 5(8) but indicated on their AVR that 911 was not contacted.  Peoples Natural Gas provided documentation of communication between excavator and PNG for the</p>	<p><b>Peoples Natural Gas: \$0.00</b></p> <p><b>KUZNESKI CONTRACTING: \$1,500.00</b>  Section 5(4) 1st Offense  \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>mark out to be completed later than the response due date. Violation removed. *****</p> <p>The incident occurred on 10/22/2025, at 12:02 PM, on 209 Eagle Ave, in White Twp, Indiana County.</p> <p>A gas line owned by Peoples Natural Gas was damaged.</p> <p>Peoples Natural Gas is the facility owner. Their Alleged Violation Report (AVR) states, “KUZNESKI CONTRACTING hit a 2" plastic main at 209 Villa on the grn in Indiana. The marks were on. PNG crews fixed the line. Emergency came in on 10/21 but was due to 10/22. PNG locator scheduled date and time to locate the main. PNG crew dug the main to install a locate box. After it was located contractor hit the line. MARKED CORRECTLY.” PNG lists excavation equipment as “Backhoe/trackhoe”, and the ticket for this excavation lists “Power equip”.</p> <p>Kuzneski Contracting is the excavator. An AVR has not been filed as of 11/18/2025 and an AVR request was sent the same day. They submitted an AVR on 11/25/2025 that states, “10/22/25 Kuzneski Contracting was digging to locate leaking water line break at 209 Eagle ave, Ind PA 15701, line was marked by utility locator but the area we began digging the gas line ran on top of the water line so there was not a flag in that specific area where the gas line was hit.” No images or documents were submitted by the excavator.</p> <p>Homeowner is the project owner. An AVR has not been filed as of 11/18/2025.</p> <p>Images submitted show the site both pre and post excavation/damage. The post-excavation damaged line is shown, and the excavation and damage occurred in the tolerance zone of the yellow marks shown in the pre-excavation images.</p> <p>Ticket #20252943177 New – Excavation– Emergency was entered on 10/21/25 at 1:43 PM with a start date of 10/22/2025 at 7:00AM. Comcast responded “Clear” on 10/26/2025.</p> <p>Peoples natural Gas responded, “SCHEDULED DATE &amp; TIME LINES WILL BE MARKED BY: 22 Oct 2025 1639” on 10/21/2025 and then Field Marked on 10/22/2025 at 9:36 AM. No documentation showing the excavator approved a 4:39PM mark out time.</p> <p>Upon arrival at the worksite the excavator, if they checked the ticket response, would have noticed that Comcast did not respond to the ticket. No renotify was called in.</p> <p>Act 127 of 2024 requires the excavator, “To renotify the One Call System of an unmarked or incorrectly marked facility, if an original, proper locate request has been made to the One Call System and, upon initial arrival at the proposed work site, it is apparent to the excavator that there is an unmarked or incorrectly marked facility.”</p>	<p>Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$0.00</p> <p>Section 5(20) 1st Offense \$0.00</p> <p><b>Comcast: \$1,000.00</b> Section 2(5)(vii) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Violations:</p> <p>Excavator - Kuzneski Contracting:  Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.  Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property.  Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.  PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement.  Section 5(20) – Excavator failed to renotify One Call of an unmarked or incorrectly marked facility upon arrival at a work site.  PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements.</p> <p>Facility - Peoples Natural Gas:  Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification.  Ticket #20252943177  PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).</p> <p>Facility(other) – Comcast:  Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification.  PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).</p>	
59661	<p><b>Facility Owner:</b> Verizon  <b>Contractor/Excavator:</b> FITZ &amp; SMITH INC  <b>Other:</b> COMCAST</p>	<p><u>On 10/24/2025 12:30:00 PM at 3155 LEWISBERRY RD, MANCHESTER TWP, YORK</u> The Non-Damage violation occurred on Friday, October 24, 2025, on Lewisberry Road, in Manchester Township, York County.</p> <p>A Contractor reported a Non-Damage facility owner issue, involving Verizon PA LLC.</p> <p>Fitz and Smith Inc, the excavator, stated in their Alleged Violation Report (AVR), Verizon responded clear no facilities. We showed up and there is a Verizon box onsite. We did two re-notifies and called Verizon directly. We were supposed to start work today and are now delayed.  One photo provided showing the Verizon box.</p> <p>On Tuesday, December 30, 2025, an email and letter were sent to Verizon PA LLC requesting an AVR. There was no response to the request and no AVR was submitted.</p>	<p><b>Verizon: \$2,500.00</b>  Section 2(5)(i) 1st Offense \$500.00</p> <p>Section 2(5)(v.1) 2nd Offense \$1,000.00</p> <p>Section 2(5)(v.1) 2nd Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>20252910276- Routine ticket placed on 10/18/2025 at 4:19pm, with a response due date of 10/22/25. Verizon PA LLC responded as “Clear No Facilities”.</p> <p>20252910276-001- Renotify Excavation Insufficient ticket placed on 10/24/2025 at 10:18am. Remark- ATTN: VERIZON YOU RESPONDED CLEAR. CALLER STATES THERE IS A VERIZON BOX AT THE SITE. PLEASE GO TO SITE TO MARK ALL INVOLVED LINES ASAP AS WELL AS UPDATE YOUR RESPONSE. DIRECT CONTACT WITH EXCAVATOR REQUIRED WITHIN TWO HOURS--[Y] No Response from Verizon PA LLC</p> <p>20252910276-002- Renotify Excavation Insufficient ticket placed on 10/24/2025 at 1:47pm. Remark: THERE IS VERIZON BOX ON SITE. PLEASE MARK LINES ASAP. WORK IS BEING HELD UP. CREW IS WAITING ON SITE. DIRECT CONTACT WITH EXCAVATOR REQUIRED WITHIN TWO HOURS--[Y] No Response from Verizon PA LLC</p> <p>Verizon PA LLC responded on 10/25/2025 as “Field Marked”.</p> <p>Violations:</p> <p>*Verizon PA LLC is in violation of sections: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. 20252910276-001 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. 20252910276-002 Recommendation: Penalties Applied</p>	
59735	<p><b>Facility Owner:</b> Verizon <b>Contractor/Excavator:</b> SIGNARAMA MONTCO <b>Other:</b> AT&amp;T <b>Other:</b> Lumen <b>Other:</b> Pennsylvania American Water (PAWC)</p>	<p><u>On 10/27/2025 12:00:00 PM at E Main St, MULTIPLE, MONTGOMERY</u> This non-damage incident occurred on October 27th, 2025, at 12pm along East Main Street, Multiple Municipalities, Montgomery County.</p> <p>This is a non-damage incident. Case is related to 60850.</p> <p>Signarama MONTCO's Alleged Violation Report (AVR) states, "Verizon has not been responding in a timely manner. They just responded to the following jobs, days after the last legal work date, asking us not to dig. 20252804294 20252804371 20252803263 20252803181 Additionally, they have not responded to our two open dig requests, first lawful start date already passed, 20252892207, 20252944089."</p> <p>Multiple routine tickets have KARL responses that Verizon gave no response or final response within the legal time frame of Act 127. The tickets were followed up with a late-interim response of Insufficient do not dig on 12/3/25.</p>	<p><b>Verizon: \$15,500.00</b> Section 2(4) Subsequent \$1,500.00</p> <p>Section 2(5)(v) Subsequent \$2,000.00</p> <p>Section 2(5)(v) Subsequent \$2,000.00</p> <p>Section 2(5)(v) Subsequent \$2,000.00</p> <p>Section 2(5)(viii) Subsequent \$2,000.00</p> <p>Section 2(5)(viii) Subsequent \$2,000.00</p> <p>Section 2(5)(viii) Subsequent \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Violations:</p> <p>Verizon  Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20252804133.  Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20252803181.  Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20252944089.  Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20252892207.  Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20252804294.  Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20252863418.  Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20252871137.  Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20252863411.  PUC compliance education is required for the individual(s) responsible to perform the locate for these tickets or their replacement(s).</p> <p>Lumen  Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20252804294.  Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20252863411.  PUC compliance education is required for the individual(s) responsible to perform the locate for these tickets or their replacement(s).</p> <p>AT&amp;T  Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20252804294.  Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20252863418.  Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20252863411.  PUC compliance education is required for the individual(s) responsible to perform the locate for these tickets or their replacement(s).</p> <p>PAWC  Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20252804294.  Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20252863418.</p>	<p>Section 2(5)(viii)  Subsequent \$2,000.00</p> <p><b>AT&amp;T: \$1,500.00</b>  Section 2(5)(viii) 1st  Offense \$500.00</p> <p>Section 2(5)(viii) 1st  Offense \$500.00</p> <p>Section 2(5)(viii) 1st  Offense \$500.00</p> <p><b>Lumen: \$1,000.00</b>  Section 2(5)(viii) 1st  Offense \$500.00</p> <p>Section 2(5)(viii) 1st  Offense \$500.00</p> <p><b>Pennsylvania American  Water (PAWC):  \$2,000.00</b>  Section 2(5)(viii) 1st  Offense \$500.00</p> <p>Section 2(5)(viii) 1st  Offense \$500.00</p> <p>Section 2(5)(viii) 1st  Offense \$500.00</p> <p>Section 2(5)(viii) 1st  Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20252871137.</p> <p>Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20252863411.</p> <p>PUC compliance education is required for the individual(s) responsible to perform the locate for these tickets or their replacement(s).</p>	
59761	<p><b>Facility Owner:</b> PPL Electric</p> <p><b>Contractor/Excavator:</b> RLE Enterprises</p> <p><b>Project Owner:</b> PENNSYLVANIA AMERICAN WATER</p> <p><b>Other:</b> Coolbaugh Township</p> <p><b>Other:</b> PENCOR SERVICES/BLUE RIDGE COMMUNICATION</p>	<p><u>On 10/28/2025 9:45:00 AM at MOUNTAIN DRIVE, MOUNT POCONO BORO, MONROE</u> Blue Ridge provided additional information - 2(v)(vii) reduced from \$1000 to a warning of \$0.</p> <p>PPL provided more information, 2(v)(vii) and 2(10) reduced from \$1000 to warnings of \$0.</p> <p>*****</p> <p>The incident occurred on 10/28/2025, at 9:45 AM, on Mountain Drive, in Mount Pocono Boro, Monroe County.</p> <p>An electric line was damaged.</p> <p>PPL is the facility owner. An Alleged Violation Report (AVR) has not been filed as of 11/18/2025 and an AVR request was sent the same day. No AVR has been received as of 1/27/2026 for this damage, even though an Emergency Ticket was input for this damage indicating PPL in the ticket, and an AVR request letter was sent. In the Coordinate PA document for this complex project there are 6 different damage tickets for this project and 4 of them are for an electric line damage. PPL did submit one AVR for damage on Mountain Drive that occurred on 10/14/25.</p> <p>R L E Enterprises is the excavator. Their AVR states, “While digging for a new water main Installation on Mountain Dr. our crew struck an unmarked power cable at House # 57. PPL Electric was contacted about the damaged cable.”</p> <p>Pennsylvania American Water is the project owner. Their AVR states the same information as RLE’s AVR.</p> <p>Due to PPL not submitting an AVR, nor responding to the emergency ticket, the owner of the damaged line cannot be accurately determined.</p> <p>Ticket #20253011480 was the emergency ticket which was entered on 10/28/25 at 10:29 AM. Coolbaugh Township responded “Clear” on 10/30/2025. PPL and PENCOR SERVICES/BLUE RIDGE COMMUNICATION responded “Insufficient Information” as their only response.</p> <p>Ticket # 20252753436 had a response due date of 10/6/2025. Verizon responded “Field Marked” on 10/10/2025. PPL and PENCOR SERVICES/BLUE RIDGE COMMUNICATION responded, “SCHEDULED DATE &amp; TIME LINES WILL BE MARKED BY: 08 Oct 2025 1548” and then “Clear” on</p>	<p><b>PPL Electric: \$500.00</b> Section 2(5)(vii) 1st Offense \$0.00</p> <p>Section 2(10) 1st Offense \$0.00</p> <p>Section 2(11) 1st Offense \$500.00</p> <p><b>Coolbaugh Township: \$1,000.00</b> Section 2(5)(vii) 1st Offense \$1,000.00</p> <p><b>PENCOR SERVICES/BLUE RIDGE COMMUNICATION: \$0.00</b> Section 2(5)(vii) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>10/17/2025. UGI responded “Conflict” on 10/3/2025 and “Field Marked” on 10/22/2025. NOTE: These responses will be addressed on Case#059317</p> <p>This case is related to cases 059317 and 059435 by tickets.</p> <p>Violations:  Facility(other) – PPL:  Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket #20253011480  PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).  Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work.  Section 2(11) – Facility Owner failed to comply with all requests for information by the Commission relation to the Commission’s enforcement authority under this act within thirty days of the receipt of the request.  PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement.</p> <p>Facility(other) - PENCOR SERVICES/BLUE RIDGE COMMUNICATION:  Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket #20253011480  PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).</p> <p>Facility(other) – Coolbaugh Township: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket #20253011480  PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).</p>	
60047	<p><b>Facility Owner:</b> National Fuel Gas  <b>Contractor/Excavator:</b> Konzel Construction  <b>Project Owner:</b> ERIE WATER WORKS  <b>Designer:</b> KLH ENGINEERS INC</p>	<p><u>On 10/28/2025 11:33:00 AM at ELIOT ROAD, ERIE CITY, ERIE</u> The incident occurred on 10/28/2025 on Eliot Rd., in Erie City in Erie Co.</p> <p>A gas line owned by National Fuel Gas was damaged.</p> <p>NATIONAL FUEL GAS stated in their Alleged Violation Report (AVR) that “Contractor failed to fully expose NFG main line while pulling in a new water service, the service was pulled along the bottom of the plastic gas main causing it to leak”. Picture and report were provided.</p>	<p><b>Konzel Construction:</b>  <b>\$1,500.00</b>  Section 5(4) 2nd Offense \$1,000.00</p> <p>Section 5(6)(ii) 1st Offense \$500.00</p> <p><b>ERIE WATER WORKS:</b>  <b>\$500.00</b>  Section 6.1(3) 1st Offense \$500.00</p> <p><b>KLH ENGINEERS INC:</b></p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>KONZEL CONSTRUCTION stated in their AVR that “While new water service was being installed, the old water line was being pulled out. While the old line was being pulled out it rubbed the exposed gas line causing a leak in the line. NFG was notified and fixed the issue”. Report was provided. On 3/26/2026 Konzel disagreed and provided more information with an attachment showing that the 911 call was made. This information was provided after the stakeholder review time period was completed. On 3/26/2026 DPI sent an email to Konzel letting him know that the violation for section 5(8) failing to notify 911 was withdrawn. DPI also let Konzel know that the time to dispute has passed and that after the Damage Prevention Committee vote, they will receive another letter and to follow the instructions in that letter if they still disagree. Konzel added that this specific utility crossing was performed utilizing trenchless technology methods. Please see attachment named "Konzel disagrees late - sends info" for complete information.</p> <p>ERIE WATER WORKS did not give a summary in their AVR. They did note that the project was &gt;\$400,000. And that above ground survey was used as the Subsurface Utility Engineering Level (SUE). This is considered level “C” SUE&gt; Reports were provided.</p> <p>KLH ENGINEERS INC gave no summary in their AVR. They provided no project information. There were no attachments.</p> <p>*OTHER AVR’S RELATED TO TICKETS but not to this incident.</p> <p>LUMEN FORMERLY LEVEL 3 stated in their AVR that “Lumen does not have buried facilities on Eliot Rd. The provided Serial Number(s): 20240580518, 20252901995. 20240580518 was for the entire city of Erie...WATER SERVICES WILL BE ABNADONED AND RENEWED THROUGHOUT THE CITY OF ERIW. and 20252901995 Lumen did not receive the ticket”. Report was provided.</p> <p><b>VIOLATIONS</b></p> <p>KONZEL CONSTRUCTION is in violation of:  Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. This is a second offense.  Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid. This is a second offense.  Section 5(6)(ii) – Excavator failed to provide support and mechanical protection for known facility owner’s lines at the construction work site.  Recommendations: The penalties are applied. PUC compliance education is required for the excavators working onsite of this excavation or their replacements.</p>	<p><b>\$500.00</b>  Section 4(2) 1st Offense  \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>ERIE WATER WORKS is in violation of: Section 6.1(3) – Released a project to bid or construction before final design was complete. Recommendation: The penalty is applied. PUC project owner compliance education is required for the person responsible for submitting AVR or their replacement.</p> <p>KLH ENGINEERS INC is in violation of: Section 4(2) – Designer failed to request the line and facility information prescribed by section 2(4) from the One Call System not less than ten nor more than ninety business days before final design is to be completed. Recommendation: The penalty is applied. PUC compliance education is required for the designer(s) who worked on this project or their replacement(s). KLH is delinquent on all education ordered by the DPC in the past. Cases 23801, 22713, 22371. KLH is years delinquent on these cases and has never taken DPC ordered education.</p>	
59874	<p><b>Facility Owner:</b> Peoples Natural Gas <b>Contractor/Excavator:</b> CRYSTAL CLEAR PLUMBING LLC <b>Project Owner:</b> Homeowner</p>	<p><u>On 10/28/2025 2:45:00 PM at 4111 TUXEY AVE, BRENTWOOD BORO, ALLEGHENY</u> The incident occurred on 10/28/2025, at 2:45 PM, on 4111 Tuxey Ave, in Brentwood Boro, Allegheny County.</p> <p>A gas line owned by Peoples Natural Gas was damaged.</p> <p>Peoples Natural Gas is the facility owner. Their Alleged Violation Report (AVR) states, “Crystal Clear Plumbing struck and damaged the customer side gas service line using mechanized equipment in the tolerance zone. Peoples Gas responded as soon as practical and within two hours. Upon arrival, the Peoples Gas locator noticed that excavation had already begun and that the customers gas service line had been severed by the Crystal Clear Plumbing crew on site. The damage occurred just after the curb box. Crystal Clear Plumbing then turned the gas curb box off and never notified 911, 811, or Peoples Gas that they had damaged the line. Also attached in the pictures are the locators notes.”</p> <p>Crystal Clear Plumbing is the excavator. An AVR has not been filed as of 11/20/2025 and an AVR request was sent the same day. No AVR was submitted, or contact made, by Crystal Clear Plumbing as of 1/9/2026.</p> <p>Homeowner is the project owner.</p> <p>Images provided show the site, excavation, mechanized equipment, and the damaged line. The exact time that damage occurred cannot be determined but it is stated that damage occurred before Peoples Gas arrived to mark for the emergency excavation ticket. Therefore, the excavator did not have a valid PA One Call prior to starting excavation. The excavator did not contact 911, 811, or the facility after damage occurred. The excavator did not submit an AVR within the required 30 days from the incident date. They also did not reply to a request that was sent on 11/20/2025 from the Public Utility Commission to provide information on the incident and submit an AVR.</p>	<p><b>CRYSTAL CLEAR PLUMBING LLC:</b> <b>\$4,750.00</b> Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(7) 1st Offense \$1,000.00</p> <p>Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>Section 5(17) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Violations:</p> <p>Excavator - Crystal Clear Plumbing:</p> <p>Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe.</p> <p>Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area.</p> <p>Section 5(7) – Failed to immediately report to the facility owner any break or leak in its lines, or any dent, gouge, groove, or other damage to such lines or to their coating or cathodic protection.</p> <p>Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property.</p> <p>Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.</p> <p>Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request.</p> <p>It is the recommendation of the Damage Prevention Investigator that PUC online Compliance Training is required for all of Crystal Clear Plumbing’s employees.</p>	
60537	<p><b>Facility Owner:</b> Service Electric Cable TV Inc.</p> <p><b>Contractor/Excavator:</b> PLUG UTILITIES</p> <p><b>Project Owner:</b> Verizon</p> <p><b>Designer:</b> Verizon - Placeholder</p>	<p><u>On 10/28/2025 4:02:00 PM at TEE CT, LOWER MACUNGIE TWP, LEHIGH</u> The incident occurred on 10/29/2025, at 12:00 PM, on Tee Ct, in Lower Macungie Twp, Lehigh County.</p> <p>A communications line owned by Service Electric Cable Tv Inc was damaged. Damage occurred due to hand tools.</p> <p>Service Electric Cable Tv Inc is the facility owner. Their Alleged Violation Report (AVR) states, “Reporting 3 more damages cause by Plug Utilities, bringing total to 8 damages in 6 months. On 10/29/2025, Plug Utilities damaged accurately marked coax cable facilities at 1192 Tee Ct, Wescosville, PA 18106. On 10/29/2025, Plug Utilities damaged accurately marked coax cable facilities at 5618 Wedge Ln, Wescosville, PA 18106. On 11/08/2025, Plug Utilities damaged accurately marked coax cable facilities at 5608 Wedge Ln, Wescosville, PA 18106. Attached are the damage investigations for each damage.” This investigation is only for the 10/29/2025 damage. In the Damage Details report submitted by SECTv is the following statement, “While digging with a shovel, they severed coax service drop near 1192 Tee Court.”</p> <p>Plug Utilities is the excavator. An AVR was not filed as of 12/17/2025 and an AVR Request was sent the same day and Plug submitted an AVR the same day that states, “We are in receipt of the Alleged Violation Report assigned for investigation by the PA Public Utility</p>	<p><b>Service Electric Cable TV Inc.: \$1,000.00</b> Section 2(5)(vii) 1st Offense \$1,000.00</p> <p><b>Verizon: \$1,000.00</b> Section 6.1(3) 1st Offense \$500.00</p> <p>Section 6.1(8) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Commission regarding the affected operation Telecom at Tee Ct, Lower Macungie Township, Lehigh County, with an incident date of October 29, 2025. After reviewing our records, we are not aware of any damage occurring at this location. While our company did perform work in the general area around the date referenced, we did not receive any complaints, damage reports, or notifications related to Tee Ct, nor were any issues observed by our crew during or after our operations.”</p> <p>Verizon is the project owner and designer. An AVR was not filed as of 12/17/2025 and an AVR Request was sent the same day. No AVR was submitted as of 1/27/2026.</p> <p>There are designs with Verizon’s name on them in the Coordinate PA Project report, but no final design ticket was located by PA One Call for this incident.</p> <p>Ticket #20253013733 New – Damage – Emergency was entered on 10/28/25 at 4:02 PM. Service Electric Cable responded “Insufficient Information” on 10/29/2025 at 9:07 AM as their only response.</p> <p>This case is related to Case # 059283 by tickets.</p> <p>Violations:  Facility - Service Electric Cable:  Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification.  Ticket #20253013733  PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).</p> <p>Project Owner– Verizon:  Section 6.1(3) – Released a project to bid or construction before final design was complete.  PUC online Compliance Training is required for the designer(s) who worked on this project, or their replacement(s).  Section 6.1(8) - Project Owner failed to comply with all requests for information by the commission relating to the commission's enforcement authority under this act within 30 days of receipt of written request.  PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement.</p>	
60197	<b>Facility Owner:</b> Verizon <b>Contractor/Excavator:</b> MELE AND MELE AND SONS INC <b>Project Owner:</b> PITTSBURGH WATER <b>Designer:</b> J M T <b>Other:</b> Comcast	<p><u>On 10/29/2025 9:00:00 AM at 1300 SQUIRREL HILL AVE, PITTSBURGH CITY, ALLEGHENY</u> Case is related to 056640, 056926, 056929, 057058, 059523, and 060339.  **  Incident occurred on October 29th, 2025, at 9am on 1300 Squirrel Hill Avenue, Pittsburgh City, Allegheny County.</p> <p>A telecom line was damaged.</p>	<p><b>Verizon: \$4,500.00</b>  Section 2(10) Subsequent \$2,500.00</p> <p>Section 2(5)(i) Subsequent \$2,000.00</p> <p><b>Comcast: \$250.00</b>  Section 2(5)(v.2) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Mele and Mele &amp; Sons' Alleged Violation Report (AVR) states, "Line was unmarked. At approximately 9am, during mainline excavation contractor struck unmarked conduit approximately 3 ft deep in trench. Foreman called 811 and Verizon. At approximately 10:30am Allegheny Electric responded to 811 call and did not claim line. At approximately 11am Verizon arrived on site, claiming line and calling for repair crew. Zottola repair crew arrived on site at 11:30am and began repairing line, by running new conduit and new fiber line. Repair was completed by 1:30pm"</p> <p>Pittsburgh Water's AVR states, "Line was unmarked. At approximately 9am, during mainline excavation contractor struck unmarked conduit approximately 3 ft deep in trench. Foreman called 811 and Verizon. At approximately 10:30am Allegheny Electric responded to 811 call and did not claim line. At approximately 11am Verizon arrived on site, claiming line and calling for repair crew. Zottola repair crew arrived on site at 11:30am and began repairing line, by running new conduit and new fiber line. Repair was completed by 1:30pm"</p> <p>JMT's AVR states, "Line was unmarked. At approximately 9am, during mainline excavation contractor struck unmarked conduit approximately 3 ft deep in trench. Foreman called 811 and Verizon. At approximately 10:30am Allegheny Electric responded to 811 call and did not claim line. At approximately 11am Verizon arrived on site, claiming line and calling for repair crew. Zottola repair crew arrived on site at 11:30am and began repairing line, by running new conduit and new fiber line. Repair was completed by 1:30pm. Underground electric and telecom lines are shown on the bid documents as per QLB survey designation provided to JMT."</p> <p>Comcast submitted and AVR stating, "FACILITY TYPE: UNKNOWN-OWNER NOT GIVEN EXCAVATION EQUIPMENT: EXCAVATOR HAZARDOUS RELEASE: NO UNMARKED LINE HIT IN THE STREET. PLASTIC PIPE, POSSIBLY A COMCAST OR VERIZON."</p> <p>The Verizon line is unmarked in the post damage images. No AVR has been submitted by Verizon as of 1/23/26.</p> <p>Violations:</p> <p>Verizon  Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. 20251633854. This specific line was in front of 1300 Squirrel Hill Ave. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).  Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work.</p> <p>Comcast Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. 20251633854. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p>	
60601	<p><b>Facility Owner:</b> Columbia Gas of PA <b>Contractor/Excavator:</b> T Byers Contracting <b>Project Owner:</b> Greencastle Borough <b>Other:</b> INSTANT BRANDS LLC</p>	<p><u>On 10/29/2025 9:30:00 AM at 646 S WASHINGTON ST, GREENCASTLE BORO, FRANKLIN</u> The incident occurred on 10/29/2025, at 9:30 AM, on 646 S Washington St, in Greencastle Boro, Franklin County.</p> <p>A gas line owned by Columbia Gas was damaged.</p> <p>Columbia Gas is the facility owner. Their Alleged Violation Report (AVR) states, “T Byers Contracting Crew was installing new water main, when they exposed small section of the CPA gas mainline, the crew was attempting to dig around the gas main when they struck and damaged a verification installed on the mainline while excavating within the tolerance zone. They immediately contacted 911, and Columbia Gas. Columbia Gas responded to make the area safe and make repairs. Damage prevention completed additional follow up on site, reviewed the tolerance zone and clear expectations of prudent digging.”</p> <p>T Byers Contracting is the excavator. An AVR was not filed as of 01/08/2026 and an AVR request was sent the same day. An AVR was submitted on 1/15/2026 with no summary or documentation.</p> <p>Greencastle Boro is the project owner. An AVR was not filed as of 01/08/2026 and an AVR request was sent the same day. They submitted and AVR on January 14th, 2026 that states, “The Greencastle Area, Franklin County, Water Authority contracted T. Byers Contracting to complete a water main replacement project on S. Washington Street, Greencastle, PA. The project generally consisted of furnishing and installing approximately 640 LF of 8-inch water main. On October 29, 2025, the contractor was excavating around a marked gas transmission line and although the main line was visibly exposed, during excavation the contractor hit a ‘finger’ on the gas main.”</p> <p>Ticket #20252861688 and #20252861689 Update – Excavation – Routine had a response due date of 10/16/2025 and Instant Brands LLC did not respond to either ticket.</p> <p>Ticket #20253021429 and #20253021431 were emergency tickets. Instant Brands LLC did not respond to either ticket.</p>	<p><b>T Byers Contracting:</b> <b>\$1,500.00</b> Section 5(4) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p><b>Greencastle Borough:</b> <b>\$1,000.00</b> Section 6.1(7) 1st Offense \$1,000.00</p> <p><b>INSTANT BRANDS LLC: \$3,000.00</b> Section 2(5)(v) 1st Offense \$500.00</p> <p>Section 2(5)(v) 1st Offense \$500.00</p> <p>Section 2(5)(vii) 1st Offense \$1,000.00</p> <p>Section 2(5)(vii) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Violations:</p> <p>Excavator - T Byers Contracting:  Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.  Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.  PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements.  PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement</p> <p>Project Owner - Greencastle Borough:  Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike.  PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement</p> <p>Facility(other) - Instant Brands LLC:  Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket #20252861688  Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket #20252861689  Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket #20253021429  Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket #20253021431  PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).</p>	
59869	<p><b>Facility Owner:</b>  NATIONAL FUEL GAS  DIST RC 350</p> <p><b>Contractor/Excavator:</b>  All Sweep Inc</p>	<p><u>On 10/29/2025 12:45:00 PM at 9135 W Ridge Rd, GIRARD BORO, ERIE</u> The Non-Damage violation occurred on Wednesday, October 29, 2025, at 9135 W. Ridge Road, in Girard Borough, Erie County.</p> <p>National Fuel Gas (NFG) reported a Near Miss. There are no tickets associated with this case. Photos were provided showing excavation.</p> <p>NFG stated in their Alleged Violation Report (AVR), Excavator installing a catch basin without PA One Call ticket submission. Field personnel advised workers of the PA One Call, and to submit a ticket. No ticket request was found.</p> <p>PA One Call Compliance commented, I found no record of All Sweep Inc having placed one call notifications in the past.</p> <p>On Tuesday, 1/6/2026, an email and letter were sent to, All Sweep Inc requesting an AVR. They submitted their AVR on 1/8/2026.</p>	<p><b>All Sweep Inc: \$1,000.00</b>  Section 5(2.1) 1st Offense  \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>All Sweep Inc stated in their AVR, we were doing maintenance work on a catch basin at 9135 West Ridge Road in Girard when someone pulled up and asked what we were doing. My crew explained that we were doing maintenance work on the catch basin. He was concerned about a gas line in the area. My crew discussed everything with him, and he marked the gas line which you can see in the attached photos. He did not leave any identification nor were we aware that this report was required to be filled out. We did not damage or disrupt anything or excavate any deeper than 8", so I did not see the need to call this in for marking on private property. We received a letter on 1/5/26 stating that this report was overdue. Please feel free to contact me if any more information is needed.</p> <p>Violation:            *All Sweep Inc is in violation of section:            5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe.            Recommendation: Penalty Applied, and PUC Online Compliance Training is required for the Excavator(s) working onsite at this excavation, or their replacements.</p>	
59938	<p><b>Facility Owner:</b> Verizon  <b>Contractor/Excavator:</b> B R KREIDER AND SON INC  <b>Project Owner:</b> Warfel Construction Company  <b>Designer:</b> R G S ASSOCIATES  <b>Other:</b> TEL HAI RETIREMENT COMMUNITY</p>	<p><u>On 10/29/2025 1:15:00 PM at 1200 TEL HAI CIR, HONEY BROOK TWP, CHESTER</u> The incident occurred on 10/29/2025 at 1200 TEL HAI CIR in HONEY BROOK TWP in CHESTER County.</p> <p>A communications line was damaged.</p> <p>B R KREIDER AND SON INC the excavator stated in their Alleged Violation Report (AVR) that While excavating for conduit installation under Serial Number 20252812906, the backhoe operator contacted an unmarked Verizon communication wire. Pictures were provided. On 1/09/2025 Damage Prevention Investigator (DPI) Maki sent an email asking for any other information that you could provide that confirms that this was a Verizon line that was damaged? Did they come out and fix the li On 1/09/2025 DPI Maki sent an email asking for any other information that you could provide that confirms that this was a Verizon line that was damaged? Did they come out and fix the line? Did someone report power loss? Are there any other communication cables that serve this Community? On 1/9/2026 email stated that Warfel Construction was the general contractor. DPI responded with an email asking who hired BR Kreider and if there is any other underground communications company serving that area. Did someone report power loss? Are there any other communication cables that serve this Community? See R G S ASSOCIATES design showing Verizon detailed.</p> <p>TEL HAI RETIREMENT COMMUNITY the project owner stated in their AVR that “While excavating for new site lighting an unmarked Verizon cable was hit and broke”. Reports were provided. On 1/09/2025 DPI Maki sent an email asking for any other information that you could provide that confirms that this was a Verizon line</p>	<p><b>Verizon: \$2,000.00</b>            Section 2(5)(i) 1st Offense \$500.00</p> <p>Section 2(11) 1st Offense \$500.00</p> <p>Section 2(10) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>that was damaged? Did they come out and fix the line? Did someone report power loss? Are there any other communication cables that serve this Community? ON 1/09/2025 an email was received stating that “The Verizon line was definitely damaged in an area that was unmarked. They did come out and repair the line”. I have copied other project representatives that were closer to the issue to provide additional information regarding the incident.</p> <p>Verizon was sent an AVR request letter on 12/30/2025. On 1/08/2026 Verizon sent an email stating that “I’ve researched this incident and can’t find any record of Verizon being involved at all. It appears that Comcast was affected on the most recent emergency damage ticket that was issued by Pa 1 call system, and the letter was written to Verizon that we were the affected facility. DPI Responded back with an email “I am not seeing what you are seeing about Comcast. Could you please share? Is there a ticket that I do not have? I have 2 Alleged Violation Reports that state a Verizon line was damaged. Verizon responded to design ticket 20250101930 with Engineering completed. Comcast is “clear”. Emergency ticket 20253023266 Verizon responded, “filed marked” . Comcast responded “clear”. For Ticket 20252812906 Verizon responded “clear” late. Comcast responded clear. Does Verizon serve TEL HAI RETIREMENT COMMUNITY?”. Can you please assist me in understanding what I need to do with these? On 1/09/2026 DPI Maki emailed Verizon the information about the Verizon line repair was reported on 10/31/2026. An email received on 1/15/2026 stated that Verizon had no pictures and has instructed the manager of the locates to follow proper procedure. Verizon stated in their AVR that “On 10/29/2025, B R KREIDER AND SON INC, allegedly hit a utility owned by Verizon at 1200 TEL HAI CIR, HONEY BROOK TWP, CHESTER. PA1Call Ticket Number: 20252812906, 20253023266, 20240883152, 20250793000, 20250101930”. Verizon added that “Locator states he marked line in white, i asked him for pictures of line marked before the hit and he could not provide me that, he now states he will take pictures moving forward”.</p> <p>An email was received on 1/07/2026 from R G S ASSOCIATES stating that “We received your letter attached regarding a utility line that was stuck during construction at Tel Hai Retirement Community. Your letter that we received via email on Jan. 5 (dated December 30) was the first we heard that a line was hit during construction. I’ve attached our design OneCall information as well as the email we received from Verizon One Call process – stating that Verizon does not do mark-outs on Design Notification Tickets. I’ve also attached the cover sheets from our Plan set with the One Call Information. We are not onsite during construction, but I have also included the information we received from Warfel Construction documenting the Verizon</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Utility Strike that we received today upon inquiring the contractor about the underground utility hit". My understanding is that Warfel Construction received this verification form and has submitted all information needed including the excavator's, BR Kreider, documentation. R G S ASSOCIATES provided the design showing Verizon detailed.</p> <p>R G S ASSOCIATES stated in their AVR that "While excavating for new site lighting an unmarked Verizon cable was hit and broke". Project is listed at &gt;\$400,000. And the length is 300'. They add that this was a facility owner issue. Reports and designs were provided. On 1/08/2026 DPI Maki sent an email asking how Warfel Construction is connected to this excavation and that RGS is still required to submit an AVR.</p> <p>Warfel Construction sent an email on 1/09/2025 stating that Verizon came out to fix line on Friday Oct 31, 2025. DPI responded to multiple emails. Warfel hired BR Kreider, thus are defined by ACT 127-2024 as the project owner. Warfel is obliged to submit an AVR. WARFEL CONSTRUCTION COMPANY stated in their AVR that "While excavating for new site lighting conduit an unmarked Verizon line was struck and broke".</p> <p><b>VIOLATIONS</b> Verizon is in violation of: Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner's lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. Someone working for Verizon was aware that the line was damaged. Verizon was observed fixing their line and 2-10 customers lost their service. Procedures need to be in place to submit AVR's when damage occurs, as per ACT 127-2024. Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Section 2(11) – Facility Owner failed to comply with all requests for information by the Commission relation to the Commission's enforcement authority under this act within thirty days of the receipt of the request. Verizon at first responded that they did not have any damage. This caused other people to research more in depth to find out whose communication line was hit. After more information was received, Verizon did acknowledge line damage and did provide an AVR. Recommendation: The penalties are applied. The required PUC compliance education has recently been completed.</p>	
60092	<p><b>Facility Owner:</b> Peoples Natural Gas <b>Contractor/Excavator:</b> DRB BORING AND DRILLING <b>Project Owner:</b> THE</p>	<p><u>On 11/5/2025 9:38:00 AM at 760 ATLANTIC AVE, ELIZABETH TWP. ALLEGHENY DRB CONSTRUCTION "REQUESTING A HEARING ON CASE 060092" No additional information was provided. ***/*</u></p>	<p><b>DRB BORING AND DRILLING: \$3,500.00</b> Section 5(4) 1st Offense \$500.00  Section 5(8) 1st Offense</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	ISBIR FAMILY OF COMPANIES	<p>The incident occurred on 11/5/2025, at 9:38 AM, on 760 Atlantic Ave, in Elizabeth Twp, Allegheny County.</p> <p>A gas line owned by Peoples Natural Gas was damaged. 911 was not contacted.</p> <p>Peoples Natural Gas is the facility owner. Their Alleged Violation Report (AVR) states, “ON 11/5/25 DRB BORING AND DRILLING WORKING NEAR 760 ATLANTIC AVE, ELIZABETH WERE DIGGING HOLE TO SET BORING MACHINE AND STRUCK PNG 4 INCH PLASTIC MAIN LINE. DRB BORING AND DRILLING HAD PNG MAIN LINE EXPOSED ON ONSIDE OF THE HOLE ALREADY. WHILE EXCAVATING THE OTHER SIDE CONTACT WAS MADE BETWEEN THE EXCAVATOR BUCKET AND PLASTIC MAIN LINE. DRB BORING AND DRILLING NOTIFIED PNG. PNG CREWS ARRIVED ONSITE AND MADE REPAIRS.”</p> <p>DRB Boring And Drilling is the excavator. An AVR was not filed as of 12/29/2025 and an AVR request was sent the same day. No AVR has been filed as of the date this investigation was submitted.</p> <p>The Isbir Family Of Companies is the project owner. An AVR was not filed as of 12/29/2025 and an AVR request was sent the same day. An AVR was filed on 1/9/2026 that states, “DRB Boring hit a gas line”</p> <p>Images submitted with AVRs show the site, excavation, and damaged line. The line is within the tolerance zone of the yellow marks.</p> <p>Ticket # 20253041315 and # 20253041317 were entered on 10/31/2025 and were New-Insufficient tickets with a start date prior to the lawful dig date.</p> <p>Violations:  Excavator – DRB Boring And Drilling:  Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.  Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property.  Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Ticket # 20253041315 and # 20253041317  PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements.  Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.  PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement.</p>	<p>\$1,000.00</p> <p>Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
62217	<p><b>Facility Owner:</b> Pennsylvania American Water (PAWC)</p> <p><b>Contractor/Excavator:</b> First Energy - West Penn Power</p> <p><b>Project Owner:</b> First Energy - West Penn Power Placeholder</p>	<p><u>On 11/5/2025 9:58:00 AM at 681 1ST AVE, SOUTH FAYETTE TWP, ALLEGHENY</u> First Energy is disputing that their ticket was to replace the pole at 681 1st Street. The damaged occurred across the alley at 677 1st Street. Please see attachment at the bottom of the First Energy dispute document compared to damage photos.</p> <p>***</p> <p>DPI asked if PAWC believed a violation of the act had occurred when they responded to the emergency ticket and took photos of the damaged water line.</p> <p>2 (10) To submit a report of alleged violation to the commission through the One Call System not more than thirty business days after receipt of notice that the facility owner's lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. The report of alleged violation shall be in a form and manner as required by the commission.</p> <p>***</p> <p>Incident occurred on November 5th, 2025, 9:58am on 681 1st Avenue, South Fayette Township, Allegheny County.</p> <p>A water line was damaged. Damage site provided on AVR was 681, but site is on the corner of 677 1st Avenue just off the road surface in the dirt.</p> <p>First Energy - West Penn Power's Alleged Violation Report (AVR) submitted on February 4th, 2026 states, "On October 23, 2025, West Penn Power (WPP), "Excavator," submitted POCS Routine Ticket 20252963018 to replace a pole at 681 1st Avenue, Bridgeville, Allegheny County, South Fayette Township, Pennsylvania. On November 5, 2025, WPP submitted a Damage Emergency Ticket 20253091323 due to the WPP auger striking and damaging the water service that was not marked. The root cause of the dig in was that the water line was not marked."</p> <p>AVR was due 30 days after the line strike. First Energy - WPP's AVR was submitted 91 days after the line strike.</p> <p>Ticket 20252963018: Work is Being Done For WESTPENN POWER Type REPLACE POLE/S 0 WE PENNSYLVANIA AMERICAN WATER WE-CLEAR. NO FACILITIES OR FACIL NOT INVOLVED "CLEAR AT POLE" 10/27/25, 4:24 PM SOP-WEBSVC N/A</p> <p>Excavator's ticket stated to replace pole/s, but Google Streetview and images provided show that a new pole was added at a new location where no previous pole was at. Excavator's ticket does say marked in white for new excavation. PAWC's response comment states "Clear at pole." Google Streetview and damage image show a fire hydrant, sewer grate, and four curb stops (two in the</p>	<p><b>Pennsylvania American Water (PAWC):</b>  <b>\$1,000.00</b>  Section 2(10) 1st Offense  \$1,000.00</p> <p><b>First Energy - West Penn Power: \$2,000.00</b>  Section 5(16) 2nd Offense  \$1,500.00</p> <p>Section 5(19) 1st Offense  \$250.00</p> <p>Section 5(20) 1st Offense  \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>grass and two in the asphalt.) No renotification was sent by WPP despite the unmarked lines and ticket responses.</p> <p>Emergency Damage Ticket 20253091323 was placed on 11/5/25: WE PENNSYLVANIA AMERICAN WATER FIELD MARKED. 11/5/2025 11:35:13 AM NIC-WEBSVC</p> <p>PAWC Field Mark, but no AVR has been submitted as of 2/10/26.</p> <p>Recommended violations, penalties, and education:</p> <p>PAWC Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. 20253091323. PUC compliance education is required for the person responsible for submitting AVR or their replacement.</p> <p>First Energy - West Penn Power Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. 20253091323. PUC compliance education is required for the person responsible for submitting AVR or their replacement. Section 5(19) – Excavator failed to provide accurate information to the One Call System. 20252963018. PUC compliance education is required for the excavators working onsite of this excavation or their replacements. Section 5(20) – Excavator failed to renotify One Call of an unmarked or incorrectly marked facility upon arrival at a work site. 20252963018. PUC compliance education is required for the excavators working onsite of this excavation or their replacements.</p>	
60364	<p><b>Facility Owner:</b> UGI <b>Contractor/Excavator:</b> KIELY CIVIL <b>Project Owner:</b> UGI (Placeholder) <b>Other:</b> Canton Township Bradford County <b>Other:</b> Zito Media</p>	<p><u>On 11/7/2025 9:00:00 AM at 31 MCFADDEN RD, CANTON TWP, BRADFORD</u> Canton Township Bradford County accepts.</p> <p>*****</p> <p>The incident occurred on November 7th, 2025, at approximately 9:00 AM, at 31 McFadden Road, in Canton Township, Bradford County.</p> <p>A gas line owned by UGI was damaged. 911 was called.</p> <p>UGI, the facility and project owner, submitted an Alleged Violation Report (AVR). Their AVR states, “Contractor struck and damaged a correctly marked gas main while installing a gas service.” Photos were submitted.</p> <p>Kiely Civil, the excavator, submitted an AVR. Their AVR states, “Crew damaged a gas main with an excavator at 31 McFadden Rd”.</p>	<p><b>KIELY CIVIL: \$500.00</b> Section 5(4) 1st Offense \$500.00</p> <p><b>Canton Township Bradford County: \$1,000.00</b> Section 2(5)(vii) 1st Offense \$1,000.00</p> <p><b>Zito Media: \$1,000.00</b> Section 2(5)(vii) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>The submitted photos show the gas line was marked out using yellow paint and flags. The damage occurred within the tolerance zone.</p> <p>Emergency ticket 20253110788 was requested 11/07/2025  - Zito Media did not respond until 11/9/25.  - Canton Township Bradford County did not respond until 11/10/25.</p> <p>Violations:</p> <p>Kiely Civil-  - Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.  Recommendation: The penalty is applied. PUC compliance training education has been satisfied.</p> <p>Canton Township Bradford County-  - Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Emergency ticket 20253110788.  Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Zito Media-  - Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Emergency ticket 20253110788.  Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
60946	<p><b>Facility Owner:</b> PECO  <b>Contractor/Excavator:</b> UTILITY LINE SERVICES INC  <b>Project Owner:</b> AQUA PENNSYLVANIA INC  <b>Designer:</b> TOTAL ENGINEERING AND CONSULTING SERVICES LLC  <b>Other:</b> COMCAST</p>	<p><u>On 11/10/2025 12:40:00 PM at AIRDALE RD, LOWER MERION TWP, MONTGOMERY</u> The incident occurred on 11/10/2025 on AIRDALE RD in LOWER MERION TWP in MONTGOMERY Co.</p> <p>A 1” plastic gas line was damaged.</p> <p>UTILITY LINE SERVICES stated in their Alleged Violation Report (AVR) that “While the crew was trenching in the area of 305 Airdale Road to install a water main they damaged an unmarked 1" plastic gas line to 305 Airdale. 911 was called and PA One Call was notified”. Report was provided.</p> <p>PECO AN EXELON COMPANY stated in their AVR that “USIC failed to mark service in complex project resulting in it being struck by ULS while Trenching for new water main”. Pictures and reports were provided.</p> <p>AQUA PENNSYLVANIA INC stated in their AVR that “Aqua Contractor Utility Line Services while the crew was trenching in the area of 305 Airdale Rd to install a water main they damaged an unmarked 1" plastic gas line to 305 Airdale. 911 was called and PA One Call notified”. Reports were provided. On 3/03/2026 Aqua sent over the answers to the questions about the project.</p> <p>TOTAL ENGINEERING AND CONSULTING SERVICES LLC stated in their AVR that “Aqua</p>	<p><b>PECO: \$2,000.00</b>  Section 2(5)(i) 3rd Offense \$1,500.00</p> <p>Section 2(5)(v) 2nd offense \$500.00</p> <p><b>TOTAL ENGINEERING AND CONSULTING SERVICES LLC: \$250.00</b>  Section 9 1st Offense \$250.00</p> <p><b>COMCAST: \$500.00</b>  Section 2(5)(v) 2nd offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Contractor Utility Line Services while the crew was trenching in the area of 305 AIRDALE RD to install a water main they damaged an unmarked 1" plastic gas line to 305 AIRDALE. 911 was called and PA One Call notified". Reports were provided. Total project on Complex Ticket is 4484' by 2' for an Aqua water main replacement.</p> <p><b>VIOLATIONS</b> PECO is in violation of: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20253070108 was requested by UTILITY LINE SERVICES INC on 11/03/2025 with a response due by 11/05/2025. PECO did not respond until 11/7/2025. This is a second time violation. Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. This is a third time offence. Recommendation: The penalty is applied. The PUC compliance education training was recently completed.</p> <p>COMCAST is in violation of: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20252740161 was requested by UTILITY LINE SERVICES INC on 10/01/2025 with a response due by 10/03/2025. Comcast did not respond until 10/06/2025. This is a second time violation. Recommendation: The penalty is applied. The PUC compliance education training was recently completed.</p> <p>TOTAL ENGINEERING AND CONSULTING SERVICES LLC is in violation of: Section 9 CGA - Chapter 2-2 The designer uses all reasonable means of obtaining information about underground facilities in the area of the planned excavation. During the planning phase of te project, all available information is gathered from facility owners/operators. This includes maps of existing, abandoned and out of service facilities; cathodic protection and grounding systems; as-builts of facilities in the area if the maps are not current; proposed project designs; and schedules of other work in the area. Recommendation: The penalty is applied. PUC compliance education is required for the designer(s) who worked on this project or their replacement(s).</p>	
60949	<p><b>Facility Owner:</b> Verizon <b>Contractor/Excavator:</b> MS Ebenezer Construction LLC. <b>Project Owner:</b> Shentel Communications LLC. <b>Other:</b> UGI</p>	<p><u>On 11/11/2025 12:00:00 AM at SCARBOROUGH LN, MANOR TWP, LANCASTER</u> The incident occurred on 11/11/2025, at 12:00 AM, on Scarborough Ln, in Manor Twp, Lancaster County.</p> <p>A communication line owned by Verizon was damaged. The facility was not notified of the damage by the excavator, but was later notified 4 days after the damage by the project owner.</p> <p>Verizon is the facility owner. An Alleged Violation Report (AVR) was not filed as of 01/16/2026 and an AVR request letter was sent the same day. An AVR was</p>	<p><b>Verizon: \$2,000.00</b> Section 2(5)(i) 1st Offense \$500.00</p> <p>Section 2(10) 1st Offense \$1,000.00</p> <p>Section 2(5)(viii) 1st Offense \$500.00</p> <p><b>MS Ebenezer Construction LLC.: \$2,000.00</b></p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>submitted on 1/23/2026 that states, “Unused drop hit by excavator”.</p> <p>Ms Ebenezer Construction LLC is the excavator. An AVR was not filed as of 01/16/2026 and an AVR request letter was sent the same day. An AVR was due by 12/11/2025 and none was submitted as of the date this report was submitted.</p> <p>Shentel Glo Fiber is the project owner. Their AVR states, “The damage occurred due to the Verizon locator not locating the service drop, they did locate the mainline. It is assumed the excavator while digging a missile pit / gas test pit @ damage #1 and a missile pit @ damage #2, struck and damaged the same service drop feeding 101 Scarborough Lane in two locations. The excavator did not report this to Glo Fiber and did not call in a damage ticket to PA811. It is assumed the excavator made two separate repairs not knowing the ownership due to Verizon not locating their drop. 4 days later the homeowner called Glo Fiber and reported the Verizon service was not working. At that point Verizon was notified of the outage. While Verizon was investigating the reported outage, they found the two repairs that the contractor MS Ebenezer made and reported this back to Bart Kelly. Pio Pauulu with Ledcor witnessed damage #2 being dug up by the Verizon contractor.”</p> <p>Shentel Glo Fiber provided all documentation of the damage and incident details. The images show the damage that was repaired and covered up. Verizon was not notified by the excavator of the damages but was later notified of the damages by Shentel Glo Fiber. Verizon’s lines were live lines as indicated by the homeowner indicating their Verizon service was interrupted. No marks are visible, that would indicate the lines that were damaged by the excavator.</p> <p>Ticket # 20252833087 had a response due date of 10/26/2025. UGI responded “SCHEDULED DATE &amp; TIME LINES WILL BE MARKED BY:28 Oct 2025 1431” but did not enter “Field Marked” until 10/31/2025.</p> <p>Complex Project ticket 20251671401 – Verizon responded “Clear” and did not attend the meeting. Act 127 of 2024, under section 2(5)(viii) requires facilities “To participate in preconstruction meetings for a complex project”. Verizon did not participate in the Complex Project meeting even though they had lines in the area, as indicated in the circumstances of this investigation.</p> <p>Violations: Facility – Verizon: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.</p>	<p>Section 5(7) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p><b>UGI: \$250.00</b> Section 2(5)(v.2) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). Ticket #20251671401  PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).</p> <p>Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work.  PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement.</p> <p>Excavator – Ms Ebenezer Construction:  Section 5(7) – Failed to immediately report to the facility owner any break or leak in its lines, or any dent, gouge, groove, or other damage to such lines or to their coating or cathodic protection.  PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements.</p> <p>Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.  PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement.</p> <p>Facility (other) – UGI:  Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket # 20252833087  PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).</p>	
60500	<p><b>Facility Owner:</b> PECO AN EXELON COMPANY  <b>Contractor/Excavator:</b> Warminster Municipal Authority  <b>Project Owner:</b> Warminster Municipal Authority  <b>Designer:</b> CKS ENGINEERS INC ARRO CONSULTING  <b>Other:</b> LUMEN FORMERLY LEVEL 3  <b>Other:</b> VERIZON PENNSYLVANIA LLC</p>	<p><u>On 11/12/2025 8:35:00 AM at 577 MAPLE STREET, WARMINSTER TWP, BUCKS</u> The incident occurred on Wednesday, November 12, 2025, at 577 Maple Street, in Warminster Township, Bucks County.</p> <p>A gas line owned by PECO An Exelon Company was damaged.</p> <p>PECO stated in their Alleged Violation Report (AVR), The damage occurred on 11/12/2025, at 577 Maple Street, while contractor Warminster Municipality was excavating to install a new water mainline, when they struck and damaged a 2-inch plastic gas main using a mini excavator; obligated ticket 20252900371. Damaged gas main was not marked. Locator did not mark the gas main crossing Maple Street, at the intersection of Maple Street and Evergreen. Locator failed to look at all the available prints for the scope of work on the obligated ticket.</p>	<p><b>PECO AN EXELON COMPANY: \$500.00</b>  Section 2(5)(i) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>CKS Engineers Inc Arro Consulting is representing Warminster Township Municipal Authority, as the excavator and project owner.</p> <p>CKS Engineers stated in their AVR, Warminster Municipal Authority was excavating at Maple Street and Evergreen Ave installing 6" water main. During the excavation an unmarked 2" steel gas main was damaged by the track hoe. 911 was called followed by an 811 call, and there was 3.5 hours of down time occurred for WMA.</p> <p>Violation: *PECO is in violation of section: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: Penalty Applied</p>	
60505	<p><b>Facility Owner:</b> PEOPLES NATURAL GAS COMPANY LLC</p> <p><b>Contractor/Excavator:</b> M. O'HERRON COMPANY</p> <p><b>Project Owner:</b> PEOPLES NATURAL GAS COMPANY LLC</p>	<p><u>On 11/13/2025 10:45:00 AM at PHILANDER ST, PITTSBURGH CITY, ALLEGHENY</u> The incident occurred on Thursday, November 13, 2025, on Philander Street, in Pittsburgh City, Allegheny County.</p> <p>A gas line owned by Peoples Natural Gas Company (PNG) was damaged. Photos were provided showing the damaged line.</p> <p>PNG, the project and facility owner, reported an Excavator issue as, failed to use prudent techniques in the tolerance zone. PNG stated in their Alleged Violation Report (AVR), M. O'Herron working for Peoples Gas struck and damaged a properly marked Peoples Gas service line.</p> <p>M. O'Herron Company reported an Excavator issue as, failing to plan the excavation or demolition work to avoid damage or minimize interference with a facility owner's facilities in a construction area. M. O'Herron Company stated in their AVR, breaking up hard surface concrete road with asphalt overlay for vac locate prior to new gas main install, put kink in existing service line that was to be spotted. Service was less than 12" deep and repaired by Peoples Gas crew.</p> <p>Violation: *M. O'Herron Company is in violation of section: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: Penalty Applied and PUC Online Compliance Training is required for the Excavator(s) working onsite at this excavation, or their replacements.</p>	<p><b>M. O'HERRON COMPANY: \$500.00</b> Section 5(4) 1st Offense \$500.00</p>
60512	<p><b>Facility Owner:</b> Municipal Authority of Westmoreland County</p> <p><b>Contractor/Excavator:</b> Sikora Plumbing and Excavating</p> <p><b>Project Owner:</b> NORTH APOLLO BOROUGH</p>	<p><u>On 11/17/2025 1:30:00 PM at ACHESON AVE, NORTH APOLLO BORO, ARMSTRONG</u> Sikora 5(16) violation is reduced from \$1000 to a warning of \$0. *****</p> <p>The incident occurred on 11/17/2025, at 1:30 PM, on Acheson Ave, in North Apollo Boro, Armstrong County.</p> <p>A water line owned by Westmoreland Co Muni Auth was damaged. 2 residential properties were flooded as a result of the damaged water main.</p>	<p><b>Sikora Plumbing and Excavating: \$1,250.00</b> Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(16) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Westmoreland Co Muni Auth is the facility owner. Their Alleged Violation Report (AVR) states, "Excavator, Sikora Plumbing and Excavating working for Project Owner North Apollo Boro, placed routine POCS ticket #20253211658 on 11/17/2025 to replace catch basins. On 11/17/2025 Sikora began its work prior to the lawful start date of November 20, 2025. Sikora struck an 8" Municipal Authority of Westmoreland County (MAWC) water main. Water from this leak entered two properties as a result of this incident. MAWC responded and made necessary repairs. MAWC advised the affected property owners to contact Sikora Plumbing and Excavating related to property damages that occurred due to the excavator digging prior to his lawful start date and prior to the utility mark outs."</p> <p>Sikora Plumbing And Excavating is the excavator. An AVR was not filed as of 01/06/2026 and an AVR request was sent the same day. An AVR was submitted on 1/15/2026 that states, "Utility line was struck at Acheson Avenue in North Apollo, PA. on 11/17/2025. Total cost of project was \$6500 for 3 days. One Call ticket was placed. 911 was notified, police and fire department were called and responded. Please let me know if you require further information. Never had to submit this report before."</p> <p>North Apollo Borough is the project owner. Their AVR states, "we had a contractor come in to replace catch basins and they did not call in the pa 811 call system before they started digging and hit a water main line on acheson ave on november 17 2025".</p> <p>Ticket # 20253211658 had a start date of 11/20/2025. The damage occurred on 11/17/2025. There was no valid PA One Call ticket for this site and excavator.</p> <p>Violations:  Excavator - Sikora Plumbing And Excavating:  Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe.  Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area.  PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements.  Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.  PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement.</p>	
60492	<b>Facility Owner:</b> UGI UTILITIES INC <b>Contractor/Excavator:</b> LANCASTER CITY OF	<u>On 11/18/2025 8:13:00 AM at 525 E. CHESTNUT ST, LANCASTER CITY, LANCASTER</u> The incident occurred on Tuesday, November 18, 2025, at 525 E. Chestnut Street, in Lancaster City, Lancaster County.	<b>UGI UTILITIES INC:</b> <b>\$500.00</b> Section 2(5)(i) 1st Offense \$500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>WATER- LU  <b>Project Owner:</b>  LANCASTER CITY OF WATER</p>	<p>A gas line owned by UGI Utilities was damaged.</p> <p>UGI reported a facility owner issue as marked incorrectly. UGI stated in their Alleged Violation Report (AVR), the Excavator utilizing mechanized equipment, struck an incorrectly marked gas service. Lancaster City of Water stated in their AVR, City of Lancaster Construction Crew hit an unmarked gas service at 525 E. Chestnut Street. It was later determined that the service for 525 E. Chestnut, that was marked 8.5 feet away, was the abandon service lateral and the new service line was never marked, which is the line that was damaged during excavation for a new water mainline installation project for the City of Lancaster. Photos provided showing the mismarked line.</p> <p>Violation:  *UGI Utilities is in violation of section:  2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.  Recommendation: Penalty Applied</p>	
60638	<p><b>Facility Owner:</b> PPL  <b>Contractor/Excavator:</b> Kauffman Gas  <b>Project Owner:</b> Homeowner</p>	<p><u>On 11/20/2025 9:00:00 AM at 5496 HIGHVIEW DR, SALISBURY TWP, LANCASTER</u> The incident occurred on 11/20/2025, at 9:00 AM, on 5496 Highview Dr, in Salisbury Twp, Lancaster County.</p> <p>An electric line owned by PPL Electric was damaged.</p> <p>PPL Electric is the facility owner. Their Alleged Violation Report (AVR) states, “On Thursday November 20, 2025, at 9:57am a non-PPL Contractor (Kauffman Gas) was installing gas when they hit an unmarked electric service going to the home. No one was hurt or injured but power was lost to the home. PPL was notified and sent a crew. When the crew arrived, they were able to make the area safe and begin repairs, the crew was able to repair the line and get the customer back in service no follow up is needed. USIC will be held liable for this damage and repair. USIC will be billed in accordance with our contract.”</p> <p>Kauffman Gas is the excavator. Their AVR states, “OUR EXCAVATION TEAM WAS EXCAVATING FOR A PROPANE TANK INSTALLATION, THEY WERE DIGGING 10 FT AWAY FROM THE FIELD MARK WHEN THEY HIT THE BURIED ELECTRIC LINE. THE HOMEOWNER STATED THAT WHEN THE LOCATOR WAS THERE TO FIELD MARK THE UTILIITIES HE WAS TALKING ON HIS PHONE WILL LOCATING AND MARKING THE LINES.” The excavator did not submit any images or documents with their AVR.</p> <p>Homeowner is the project owner. An AVR was not filed as of 01/09/2026.</p> <p>Images submitted show the site, damage, and marks. The damage is not within the tolerance zone of the red marks.</p>	<p><b>PPL: \$500.00</b>  Section 2(5)(i) 1st Offense  \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Violations:            Facility – PPL:            Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).</p>	
60548	<p><b>Facility Owner:</b>            Maisonette Homeowners Association - placeholder  <b>Contractor/Excavator:</b>            Maisonette Homeowners Association  <b>Project Owner:</b>            Maisonette Homeowners Association - placeholder  <b>Other:</b> KEITH GABAGE  <b>Other:</b> Radley Run Mews Association INC  <b>Other:</b> Radley Run Mews Sewer Association  <b>Other:</b> Verizon</p>	<p><u>On 11/20/2025 10:28:00 AM at 607 Plum Run Drive, EAST BRADFORD TWP, CHESTER</u> Maisonette Owners Association - 5(2.1) violation is reduced from \$1000 to a warning of \$0. Maisonette Owners Association accepts.            *****            The incident occurred on 11/20/2025, at 10:28 AM, on 607 Plum Run Drive, in East Bradford Twp, Chester County.</p> <p>Excavation occurred without an active PA One Call ticket. No damage was reported.</p> <p>Maisonette Homeowners Association is the excavator and project owner. An AVR has not been filed as of 12/11/2025 and an AVR request was sent the same day. An AVR was filed on 12/15/2025 that states, “The private roadway was being cored for samples (+/- 6 inch depth) in order to identify how much wearing course was present in the road. The community plans to mill the roadway and install a new wearing course. The coring was necessary in order to determine how much paving will be removed. A resident (at 607 Plum Run Dr.) called in a violation without an understanding of the nature of the work. The work was stopped (and no core was completed) once PaOneCall was contacted. It was advised by the inspector to place an application since he was unable to locate his supervisor and he was new to his job. No violation was committed since no coring was done. The work was performed on Dec. 1st within the application work window. PLEASE NOTE THE PICTURE BELOW WAS TAKEN ON DEC. 1ST WHEN THE WORK WAS PERFORMED not when the violation was called in by homeowner on Nov. 20th.”</p> <p>An AVR was submitted by Keith Gabage, a resident and member of the HOA, that states, “Homeowners Association is member and commenced boring operations to determine current road construction as their intention is to mill and overlay. Work commenced prior to calling OneCall. Joe Liberato is the lead for the HOA. This individual was advised of need to call and conveyed he would take it under advisement. I called PaOne call to report same and now completing this report.”</p> <p>Keith submitted 2 images showing that Maisonette Owners Association conducted coring using mechanized equipment on 11/20/2025. No valid one call ticket was found for this site, excavator, and timeframe during when excavation occurred.</p> <p>Keith Gabage entered a No One Call ticket on 11/20/2025 at 11:06AM. Maisonette Owners</p>	<p><b>Maisonette Homeowners Association: \$500.00</b>            Section 5(2.1) 1st Offense \$0.00</p> <p>Section 2(5)(v.2) 1st Offense \$250.00</p> <p>Section 2(5)(v.2) 1st Offense \$250.00</p> <p><b>Radley Run Mews Association INC: \$250.00</b>            Section 2(5)(v.2) 1st Offense \$250.00</p> <p><b>Verizon: \$1,000.00</b>            Section 2(5)(v) 1st Offense \$500.00</p> <p>Section 2(5)(v) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Association then entered 2 Routine ticket at 12:27PM and 12:35PM with a due date of 11/24/2025.  On Ticket #20253241915 - Maisonette Homeowners Association, Radley Run Mews Sewer Association, and Radley Run Mews Association INC did not enter a response by the due date, but responded "Clear" on 11/25/2025. Verizon responded "Clear" on 12/10/2025.  On Ticket# 20253241942 Maisonette Owners Association did not enter a response by the due date, but responded "Clear" on 11/25/2025. Verizon responded "Clear" on 12/10/2025.</p> <p>Radley Run Mews Association INC and Radley Run Mews Sewer Association are operated by the same organization.</p> <p>Violations:</p> <p>Facility and Excavator - Maisonette Homeowners Association:  Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe.  PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements.  Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket #20253241915  Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket# 20253241942  PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).  Facility(other) – Verizon:  Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket# 20253241942  Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket #20253241915  PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).  Facility(other)- Radley Run Mews Association:  Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket #20253241915  PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).</p>	
60727	<p><b>Facility Owner:</b> PECO  <b>Contractor/Excavator:</b> DELMONT UTILITIES COMPANY  <b>Other:</b> AQUA PENNSYLVANIA INC  <b>Other:</b> BRANDYWINE CAD DESIGN  <b>Other:</b> COMCAST  <b>Other:</b> JAMES J GREENHALGH JR PLUMBING  <b>Other:</b> VERIZON</p>	<p><u>On 11/20/2025 10:30:00 AM at RUSHLEY WAY, MIDDLETOWN TWP, DELAWARE</u> The incident occurred on 11/20/2025 at 241 RUSHLEY WAY in MIDDLETOWN TWP in DELAWARE Co.</p> <p>An electric conduit and cable owned by PECO were damaged.</p> <p>DELMONT UTILITIES COMPANY stated in their Alleged Violation Report (AVR) that "WORKING AT 241 RUSHLEY WAY. DIGGING TO INSTALL WATER MAIN WITH A TRACK HOE. THE BUCVKEY PULLED A 3" CONDUIT THAT WAS NOT MARKED. PECO SAID IT BELONGS TO</p>	<p><b>PECO: \$1,000.00</b>  Section 2(5)(i) 2nd  Offense \$1,000.00</p> <p><b>COMCAST: \$500.00</b>  Section 2(5)(v) 2nd  offense \$500.00</p> <p><b>VERIZON: \$1,000.00</b>  Section 2(5)(viii) 2nd  Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>THEM. IT WAS A CONDUIT PIPE WITH A DEAD WIRE IN IT FOR FUTURE. 3 FT 4 INCHES DEEP. THE PIPE DID NOT BREAK”. They added that this line was marked incorrectly.</p> <p>PECO AN EXELON COMPANY stated in their AVR that “DELMONT UTILITES WORKING FOR AQUA INSTALLING WATER MAIN HIT THE BRAND NEW CONDUIT AND CABLE”. Reports were provided.</p> <p>AQUA PENNSYLVANIA INC stated in their AVR that “ Aqua Contractor Delmont Utilities working at 241 Rushley Way. Digging to install water main with a track hoe. The bucvky pulled a 3" conduit that was not marked. PECO said it belongs to them. It was a conduit pipe with a dead wire in it for future. 3ft 4 inches deep. The pipe did not break. Reports were provided.</p> <p>BRANDYWINE CAD DESIGN INC stated in their AVR that “AQUA CONTRACTOR DELMONT UTILITIES WORKING AT 241 RUSHLEY WAY. DIGGING TO INSTALL A WATER MAIN WITH A TRACK HOE. THE BUCKET PULLED A 3" CONDUIT THAT WAS NOT MARKED. PECO SAID IT BELONGS TO THEM. IT WAS A CONDUIT PIPE WITH A DEAD WIRE IN IT FOR THE FUTURE. 3 FT 4 INCHES DEEP. THE PIPE DID NOT BREAK”. Project cost &gt;\$400,000. Length of project is 4850’. Tickets and reports were included.</p> <p><b>VIOLATIONS</b>  PECO is in violation of:  Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. This is a second offense.  Recommendation: The penalty is applied. The required education was recently completed.</p> <p>COMCAST is in violation of:  Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. This is a second time offense.  Ticket 20253190311 was submitted by DELMONT UTILITIES COMPANY on 11/15/2025 with a response due by 11/19/2025. Comcast did not respond “Field Marked” until 11/20/2025.  Recommendation: The penalty is applied. The required education was recently completed.</p> <p>VERIZON is in violation of:  Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). This is a second offense. Complex Project ticket 20252952524 was submitted by DELMONT UTILITIES COMPANY on 10/22/2025 with a response due by 10/28/2025. CP meeting to be held on 10/29/2025 at 10:00 a.m. Verizon responded “Conflict” and did not attend the meeting.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Recommendation: The penalty is applied. The required education was recently completed.</p>	
60850	<p><b>Facility Owner:</b> AT&amp;T  <b>Facility Owner:</b> PECO  <b>Facility Owner:</b> Verizon  <b>Contractor/Excavator:</b> SIGNARAMA MONTCO</p>	<p><u>On 12/3/2025 9:00:00 AM at E Main St, NORRISTOWN BORO, MONTGOMERY</u> This non-damage incident was reported on December 3rd, 2025 at 9am, East Main Street, Norristown Boro, Montgomery County.</p> <p>Non-damage violation.</p> <p>Signarama Montco's Alleged Violation Reports state:</p> <p>"20253302853 -- This ticket was reported clear, but was later reported as CONFLICT. LINES NEARBY. DIRECT CONTACT TO FOLLOW BY FACILITY OWNER. Facility owner note: ESCALATED TO DPI-- After the legal start date already passed."</p> <p>"PICO did not mark locations in time for lawful start date of tickets 20253302882, 20253302863. However, they did respond via PA1call and make me aware that they were not able to mark in time."</p> <p>"Verizon PA LLC did not respond to the following PA1Call tickets by their lawful start date: 20253302852, 20253302853, 20253302862, 20253302863, 20253302881, 20253302882"</p> <p>Verizon gave No Response to routine tickets ending in 2852, 2881, 2853, 2862, and 2863. Verizon did not give a final response to design ticket ending in 4134 within 10 business days.</p> <p>PECO gave no final response to tickets ending in 2882 and 2863.</p> <p>AT&amp;T did not give a final response to design ticket ending in 4134 within 10 business days.</p> <p>Violations:</p> <p>Verizon  Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20253302852.  Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20253302881.  Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20253302853.  Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20253302862.  Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20253302863.  Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20252804134.  PUC compliance education is required for the individual(s) responsible to respond to these tickets or their replacement(s).  PECO  Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. 20253302882.</p>	<p><b>AT&amp;T: \$250.00</b>  Section 2(4) 1st Offense \$250.00</p> <p><b>PECO: \$1,000.00</b>  Section 2(5)(v.2) 2nd Offense \$500.00</p> <p>Section 2(5)(v.2) 2nd Offense \$500.00</p> <p><b>Verizon: \$11,500.00</b>  Section 2(4) Subsequent \$1,500.00</p> <p>Section 2(5)(v)  Subsequent \$2,000.00</p> <p>Section 2(5)(v)  Subsequent \$2,000.00</p> <p>Section 2(5)(v)  Subsequent \$2,000.00</p> <p>Section 2(5)(v)  Subsequent \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. 20253302863. PUC compliance education is required for the individual(s) responsible to respond to these tickets or their replacement(s). AT&amp;T</p> <p>Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20252804134. PUC compliance education is required for the individual(s) responsible to respond to these tickets or their replacement(s).</p>	
60880	<p><b>Facility Owner:</b> Peoples Natural Gas Company <b>Contractor/Excavator:</b> Hampton Shaler Water Authority <b>Project Owner:</b> Hampton Shaler Water Authority - Placeholder</p>	<p><u>On 12/3/2025 10:09:00 AM at PERRY ST, SHALER TWP, ALLEGHENY</u> The incident occurred on 12/3/2025, at 10:09 AM, on Perry St, in Shaler Twp, Allegheny County.</p> <p>A gas line owned by Peoples Natural Gas was damaged.</p> <p>Peoples Natural Gas is the facility owner. Their Alleged Violation Report (AVR) states, “On 12/3/2025, Hampton Shaler Water was working to replace a water main when they struck an accurately marked PNG SL (main to curb). 1 customer affected. PNG crews were called and repairs were made.”</p> <p>Hampton Shaler Water Auth is the excavator and project owner. Their AVR states, “On December 3, 2025 at 25 Perry St, Hampton Shaler Water Authority was digging to replace the old water main and install a new water main. Hampton Shaler Water Authority was in the process of swapping the old service lines over from the old main to the new water main”.</p> <p>Images submitted show the site, excavation, marks, and damaged line. The damage occurred within the tolerance zone of the yellow mark as indicated using a hit kit. The excavator contacted 911.</p> <p>Violations: Excavator - Hampton Shaler Water Auth: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements.</p>	<p><b>Hampton Shaler Water Authority: \$500.00</b> Section 5(4) 1st Offense \$500.00</p>
60921	<p><b>Facility Owner:</b> Peoples Gas Company <b>Contractor/Excavator:</b> R C C BUILDING CONTRACTORS INC <b>Project Owner:</b> WEST VIEW WATER AUTHORITY <b>Other:</b> Comcast <b>Other:</b> Verizon</p>	<p><u>On 12/3/2025 3:16:00 PM at DUFF RD, OHIO TWP, ALLEGHENY</u> Peoples Accepts. Spoke to RCC on 5/8/26 on how to reject after DPC omnibus vote. Also sent an email with links for AVR, Education, and 811 Liaisons. *** Incident occurred on December 3rd, 2025, at 3:16pm along Duff Road, Ohio Township, Allegheny County.</p> <p>A gas line was damaged.</p> <p>Peoples Gas Company's Alleged Violation Report (AVR) states, "On 12/3/2025, RCC Building contactors was digging to replace a water main when they struck a mismarked PNG SL main to curb. PNG crews were</p>	<p><b>Peoples Gas Company: \$1,000.00</b> Section 2(5)(i) 2nd Offense \$1,000.00</p> <p><b>R C C BUILDING CONTRACTORS INC: \$1,250.00</b> Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(3) 1st Offense \$250.00</p> <p><b>Comcast: \$500.00</b></p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>called and repairs were made. PNG SL was mismarked by 3 feet."</p> <p>RCC Building Contractors, Inc's AVR states, "Gas line was out of lines at 335 Duff Road." AVR list 911 as not being notified.</p> <p>West View Water Authority's AVR has a blank summary report.</p> <p>Images show that the gas line was severed and marked outside of the tolerance zone. Project was over 2,000ft and no complex meeting ticket was found.</p> <p>Violations:</p> <p>Peoples Gas Company Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.</p> <p>RCC Building Contractors, Inc. Section 5(3) – Excavator failed to hold a preconstruction meeting prior to beginning a complex project. Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid. PUC compliance education is required for the excavators working onsite of this excavation or their replacements.</p> <p>Verizon Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20252044153. PUC compliance education is required for the excavators working onsite of this excavation or their replacements. Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. 20252972955. PUC compliance education is required for the excavators working onsite of this excavation or their replacements. Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. 20252972944. PUC compliance education is required for the excavators working onsite of this excavation or their replacements.</p> <p>Comcast Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20252972955. PUC compliance education is required for the excavators working onsite of this excavation or their replacements.</p>	<p>Section 2(5)(v) 1st Offense \$500.00</p> <p><b>Verizon: \$3,500.00</b> Section 2(4) Subsequent \$1,500.00</p> <p>Section 2(5)(v) Subsequent \$1,000.00</p> <p>Section 2(5)(v) Subsequent \$1,000.00</p>
61352	<p><b>Facility Owner:</b> UGI <b>Contractor/Excavator:</b> LEHIGH COUNTY AUTHORITY <b>Project Owner:</b> LEHIGH COUNTY AUTHORITY - spacesaver</p>	<p><u>On 12/22/2025 6:00:00 PM at N 4TH ST, ALLENTOWN CITY, LEHIGH</u> UGI disagreed. They stated that "The damaged facility was abandoned and not active. This was a service line and UGI has no obligation to mark abandoned service lines in section 2(13)". DPI responded with an email which stated that, "violation of section 2(5)(i) the last sentence, in bold letters, states that Facility owners shall make reasonable efforts during the excavation phase to locate or notify excavators of the existence of any known lines and abandoned lines. Violation section 2(13) was not cited and refers to main</p>	<p><b>UGI: \$0.00</b></p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>lines. A notice will be sent when case 61352 is scheduled for a Damage Prevention Committee (DPC) meeting. Please let me know if there is any other information to consider by 3/6/2026." DPI responded to UGI that, "Emergency ticket 20253563664 reads that there was an odor of gas and that 911 was notified. This conflicts with UGI's AVR that reads that the line was determined to be a retired line. An abandoned line would mean that it is disconnected from the gas line". On 3/03/2026 UGI sent an email with information that stated: "Order Comments - line was retired,, no readings or odor here,,no svc records on file for pipe ,,cut into with 4 wheel cutter no gas in pipe ,,ok water dept to proceed with job and move pipe out of the way,,made ramrods on both sides pf the street all clear." Violation of section 2(5)(i) is withdrawn to UGI.</p> <p>****</p> <p>The incident occurred on 12/22/2025 on N 4TH ST in ALLENTOWN CITY in LEHIGH County.</p> <p>A gas line was damaged.</p> <p>LEHIGH COUNTY AUTHORITY stated in their AVR that "While excavating for water main break, a unmarked gas line was pulled. 811, 911, and gas company was notified". Pictures were provided.</p> <p>UGI was sent an AVR request letter on 1/12/2026. On 1/12/2026 an AVR and email were received. UGI stated that "UGI did not submit an initial AVR because there was no damage to any active gas facilities. This was a retired line of unknown age. UGI confirmed it was retired on site and all active lines were marked". UGI UTILITIES INC stated in their AVR that "UGI was called to a potential damaged gas line. Upon arrival it was determined that this was a retired line and not an active gas line. No damage occurred to any live gas lines. Our first responder spoke with the excavator on site who let us know that no additional mark outs would be needed. All active gas lines were marked and were marked by the date required on the ticket. AVR being filed due to request from DPI. UGI would have no knowledge of the scope or cost of this work as it was not being done by or for UGI". DPI responded that "We need AVR's on retired and inactive lines. An excavator needs to know what is underground and should never assume something is inactive".</p> <p>VIOLATIONS UGI is in violation of: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: The penalty is applied. The PUC required education has been completed recently.</p>	
62004	<b>Facility Owner:</b> Peoples Gas <b>Contractor/Excavator:</b>	<u>On 1/17/2026 3:00:00 PM at 1126 BRABEC ST, PITTSBURGH CITY, ALLEGHENY</u> The incident	<b>PITTSBURGH WATER:</b> <b>\$500.00</b> Section 5(13) 1st Offense

Case Number	Stakeholders	Summary	Violations & Recommendation
	PITTSBURGH WATER <b>Project Owner:</b> PITTSBURGH WATER - Spacesaver	<p>occurred on 1/18/20026 at 1110 BRABEC ST in PITTSBURGH CITY in ALLEGHENY Co.</p> <p>A gas service line owned by Peoples Gas was damaged.</p> <p>PITTSBURGH WATER the excavator and project owner stated in their Alleged Violation Report (AVR) that “PWSA digging and hit unmarked gas service line. Peoples gas and 911 notified. Peoples Gas made repairs”. Pictures were provided.</p> <p>Peoples Gas the facility owner stated in their AVR that “Pittsburgh Water working on an emergency locate request struck and damaged a Peoples Gas service line to 1110 Brabec. The One call request that PWSA places was for 1126. The area near 1126 was marked in white. The damage occurred to 1110; there were faded yellow marks for a previous locate near 1110. The emergency request was placed on 1/17 at 1400 hours for an immediate dig. The damage occurred over 24 hours later”. 911 was notified. Pictures were provided. Peoples AVR lists the damage occurring on 1/18/2026 at 16:30. Emergency Ticket 20260170124 was submitted by Pittsburgh Water on 1/17/2026 at 13:58 to repair a water main break at 1126 Brabec St. and specifies that the site is marked in white. Pictures show that the damage is at 1110 Brabec St.</p> <p>VIOLATIONS PITTSBURGH WATER is in violation of: Section 5(13) – Excavator changed the location, scope, or duration of a proposed excavation without notifying the One call System. Section 5(2.2) – Excavator failed to provide exact information to identify the worksite. Recommendation: The penalties are applied. PUC compliance education was recently completed.</p>	<p>\$250.00</p> <p>Section 5(2.2) 1st Offense \$250.00</p>

**Full Session**

Case Number	Stakeholders	Summary	Violations & Recommendation
58912	<p><b>Facility Owner:</b> PPL Electric Utilities <b>Contractor/Excavator:</b> East Penn Foundations <b>Project Owner:</b> Property Owner</p>	<p><u>On 9/3/2025 11:47:00 AM at 1348 HIGHLAND CT, LOWER MACUNGIE TWP, LEHIGH</u> On 5/12/26 the DPC voted to accept the case as updated.</p> <p>*****</p> <p>On 04/14/2026, the DPC voted to table this case until the case is updated to reflect East Penn Foundations as the excavator.</p> <p>*****</p> <p>Garloff Carpentry is disputing.</p> <p>*****</p> <p>The incident occurred on September 3rd, 2025, at 11:47 AM, at 1348 Highland Court, in Lower Macungie Township, Lehigh County.</p>	<p><b>East Penn Foundations:</b> <b>\$2,750.00</b></p> <p>Section 5(23) 1st Offense \$500.00</p> <p>Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>An electrical line owned by PPL was damaged.</p> <p>PPL, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, "On Wednesday 9/3/2025 at approximately 11:47 AM Garloff Carpentry contacted an underground service while installing concrete footers for a pavilion at 1348 Highland Ct. Garloff Carpentry did not have a PA One Call ticket for this work. The homeowner did have a PA One Call ticket that was out of date that I will reference in the AVR." A photo was submitted.</p> <p>Garloff Carpentry is the excavator. An AVR has not been filed as of 12/08/2025.</p> <p>The property owner was the project owner. An AVR has not been filed as of 12/08/2025. AVR request letter sent 2/25/2026.</p> <p>Routine ticket 20251563154 was requested by the homeowner in June of 2025. No Pa One Call tickets were requested by Garloff Carpentry.</p> <p>In the submitted photo, there is evidence of multiple underground utilities in the immediate area. An electrical meter, as well as multiple utility boxes are attached to the side of the house, directly next to where the excavator was auguring. The augur is attached to a Kubota.</p> <p>Pa One Call noted in their research that there was no record of Garloff Carpentry placing one call notifications in the past.</p> <p>Violations:</p> <p>Garloff Carpentry-</p> <ul style="list-style-type: none"> <li>- Section 5(23) – Excavator may not delegate their duty to submit a locate request to the One Call System to another person. The excavator shall have sole responsibility to submit each locate request to the One Call System.</li> <li>- Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe.</li> <li>- Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area.</li> <li>- Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.</li> <li>- Section 5(21) – Excavator failed to pay the annual fee for service provided by the One Call System.</li> </ul> <p>(withdrawn)</p> <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
58953	<p><b>Facility Owner:</b> Peoples Gas  <b>Contractor/Excavator:</b> J S Bova Excavating  <b>Project Owner:</b> FORD CITY BOROUGH  <b>Designer:</b> Stiffler McGraw</p>	<p><u>On 9/29/2025 10:01:00 AM at 8TH STREET, FORD CITY BORO, ARMSTRONG</u> On Tuesday 5/12/2026, at the DPC meeting, disputing was Peoples Natural Gas and it was voted to accept the DPI's recommendations.  *****  Peoples Gas is disputing.  *****  The incident occurred on September 29th, 2025, at 10:01 AM, on 8th Street, in Ford City Borough, Armstrong County.</p> <p>A gas line owned by Peoples Gas was damaged. 911 was called.</p> <p>Peoples Gas, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, "Originally not located because of bad maps and records but Bova found it and did not call in a renotify ticket. Then they cut the live service with a saw instead of going under it." Photos were submitted.</p> <p>J S Bova Excavating, the excavator, submitted an AVR. Their AVR states, "Hit an unmarked gas line at the intersection of 8th Street &amp; Ash Ave."</p> <p>Ford City Borough, the project owner, submitted an AVR. Their AVR states, "Contractor cut 1 inch steel line believed to be out of service. It was inserted with 3/4 inch plastic service line. The service line was not marked from Peoples Gas. 801 8th Ave at 9:10am. Contractor called 911, 811 and gas company. Gas company repaired service."</p> <p>Stiffler McGraw, the designer, submitted an AVR. Their AVR states, "Contractor cut 1 inch steel line believed to be out of service. It was inserted with 3/4 inch plastic service line. The service line was not marked from Peoples Gas. 801 8th Ave at 9:10am. Contractor called 911, 811 and gas company. Gas company repaired service." Photos were submitted.</p> <p>This case is related to the following cases: 051368, 051438, 056687, 058755.</p> <p>The submitted photos show no visible mark outs for the gas line.</p> <p>Violations:</p> <p>Peoples Gas-  - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.  Recommendation: The penalty is applied. PUC compliance training education is required.</p>	<p><b>Peoples Gas: \$1,000.00</b>  Section 2(5)(i) 2nd  Offense \$1,000.00</p>
58985	<p><b>Facility Owner:</b> UGI Utilities, Inc  <b>Contractor/Excavator:</b> Peiffer Property Management LLC</p>	<p><u>TABLED</u></p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
	<b>Project Owner:</b> HERMAN PROPERTIES LLC - Property Owner		
59870	<b>Facility Owner:</b> PECO <b>Contractor/Excavator:</b> CHRIS NATALINI MASONRY INC <b>Project Owner:</b> Neal's Tire and Service Center	<p><u>On 10/1/2025 12:00:00 AM at 6019 Baltimore Ave, PHILADELPHIA CITY, PHILADELPHIA</u> On 5/12/26 the DPC voted to accept DPIs Rec and add \$250 for No Show for Natalini Masonry.  5(2.1) Added \$250 for now show. \$1,000 + \$250 is \$1,250.  ****  Natalini Masonry is disputing Section 5(2.1) only. Already agreed to education and 5(16) being reduced.</p> <p>DPI emailed to offer:  Natalini Masonry  Keep - \$1,000 Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. PUC compliance education is required.  Reduce by 50% from \$1,000 to \$500 - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required.</p> <p>****  Incident occurred October 1st, 2025, at 12am on 6019 Baltimore Ave, Philadelphia City, Philadelphia County.</p> <p>An electric line was damaged.</p> <p>PECO's Alleged Violation Report (AVR) states, "CONTRACTOR PERFORMING CONCRETE WORK FOR PROPERTY OWNER, WITHOUT A PA ONE CALL, DAMAGED THE SECONDARY MAIN WITH AN EXCAVATOR WHILE REMOVING CONCRETE DRIVE AND SIDEWALK."</p> <p>Damage Prevention Investigator reached out to PECO for pictures and more information. PECO email states, "Peco showed up onsite Masonry Inc was still onsite removing concrete on Edgewood Ave, spoke with Chris Natalini who stated that he was advised that the building owner had called in a One Call as there were marks onsite, no ticket was located for either Masonry Inc or the property owner."</p> <p>811 Compliance commented, "There was no record for Masonry Inc.; however the phone number and address are listed for Chris Nataline Masonry Inc. in our system."</p> <p>Natalini Masonry's AVR submitted on 1/12/2026 states, "We removed a concrete sidewalk to pour new. When excavating our bucket hit the PECO power line. It was 5” underground and 18” off the mark. When PECO dug up the line to fix it, they couldn’t find it on the mark. They were 3’ deep and 18” over. They finally found it 5” below the surface and 18” from the mark. Since that was the case they worked with me on the cost of the repair.</p>	<b>CHRIS NATALINI MASONRY INC:</b> <b>\$1,750.00</b> Section 5(2.1) 1st Offense \$1,250.00  Section 5(16) 1st Offense \$500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Email from Natalini Masonry mentions that the property owner, Firefighters Investments LLC, made a pa1 call. Natalini Masonry failed to make their own PA1 call ticket prior to digging.</p> <p>Violations:</p> <p>Natalini Masonry  Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. PUC compliance education is required.  Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required. Penalty for 5(16) reduced by 50% from \$1,000 to \$500 due to AVR being past due but submitted late.</p>	
59122	<p><b>Facility Owner:</b> Peoples Gas Company  <b>Contractor/Excavator:</b> ARMSTRONG</p>	<p><u>On 10/1/2025 4:00:00 PM at WILLOW WOOD DR, BUTLER TWP, BUTLER</u> On 5/12/26 the DPC voted to accept DPIs recommendation for Peoples Gas Company.  ****</p> <p>Peoples Gas Company is disputing.</p> <p>****</p> <p>Incident occurred on October 1st, 2025, at 4pm along Willow Wood Drive, Butler Township, Butler County.</p> <p>A gas line was damaged.</p> <p>Peoples Gas Company's Alleged Violation Report (AVR) states, "On 10/1/2025, Armstrong was working to install fiber optic cable when they struck a mismarked PNG SL curb to meter. PNG locator hooked to wire and located curb to meter facility off of tone. PNG locator tone put the marks 24 inches off."</p> <p>Armstrong's AVR states, "On Oct 1st, 2025, Armstrong Utilities was horizontal directional boring along 108 Willow Wood Dr in Butler, PA working under PA One Call ticket #20252590514. While in the process of boring the team smelled gas and immediately stopped drilling. The team called 911 and also contacted People Gas. Upon investigation, Peoples Gas acknowledged that the gas line was missed marked as can be seen in the attached photos."</p> <p>Images show that the line was not marked within the tolerance zone.</p> <p>Case is related to 059122 &amp; 060091.</p> <p>Violations:</p> <p>Peoples Gas Company  Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. 20252590514. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p>	<p><b>Peoples Gas Company:</b>  <b>\$1,000.00</b>  Section 2(5)(i) 2nd  Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
59185	<p><b>Facility Owner:</b> Peoples Natural Gas  <b>Contractor/Excavator:</b> BRIAN SCHMUCKER GENERAL CONTRACTOR  <b>Project Owner:</b> WEST PENN POWER  <b>Other:</b> COMCAST  <b>Other:</b> Windstream and Windstream Enterprise</p>	<p><u>On 10/9/2025 11:07:00 AM at 1 HONES RD, PENN TWP, WESTMORELAND</u> On 5/12/2026 The Damage Prevention Committee (DPC) voted to remove the violation of 5(2.2) to BRIAN SCHMUCKER GENERAL CONTRACTOR and to maintain the violations of 5(9) and 5(8).  *  BRIAN SCHMUCKER GENERAL CONTRACTOR disagrees. On 3/26/2025 an email was received from Brian asking for more considerations. DPI Maki provided guidance of things that could be provided. No other information was provided as of 5/07/2026.  *****  The incident occurred on 10/09/2025 at 1 Hones rd. in Penn Township in Westmoreland Co.</p> <p>A plastic gas service line was damaged. 911 was not notified.</p> <p>PEOPLES NATURAL GAS COMPANY LLC stated in their Alleged Violation Report (AVR) that “BRIAN SCHMUCKER GENERAL CONTRACTOR placed an one-call to replace the electric line at 1 Hones rd export. Contractor placed this as an emergency and only had white paint at the address provided. Contractor dug outside the scope of his one-call and bored through a 1" plastic service line that was marked for a previous one-call for electric. Previous one-call number is 20252034459 from a different contractor where they had white paint on the road. Brian Schmucker did pot hole on the curb to meter side of the gas line since it was marked but did not find it, he assumed it was deeper so they bored through the gas line. 1" plastic gas line was hit curb to meter at 6906 Mellon Rd export. Locator tried to call the contractor 3 times to make sure that was the only place he was digging because we had previous one-calls going up to 6910 mellon rd, his one-call would not cover that distance. Locator marked it anyway. No answer, no call back. One-calls states working only 160ft which is over 250ft where he was digging. Line was hit on customer side, contractor will get a plumber to make repairs”. Used directional drilling technique. 911 was not notified. Pictures were provided.</p> <p>BRIAN SCHMUCKER GENERAL CONTRACTOR AVR request letter sent on 12/18/2025. No AVR has been received as of 1/23/2026. On 1/15/2026 DPI Maki returned a call to Tyler SCHMUCKER from BRIAN SCHMUCKER GENERAL CONTRACTOR who had lots of questions about 2 other cases that they are involved with. He had lots of questions about the education and about submitting AVR's, violations, issues they have had in the past and talked for 40 minutes. DPI explained everything and why it is needed and how the process works. DPI looked up his education letter and stated the date of the letter and that the education needs to be done within 60 days.</p> <p>WEST PENN POWER AVR the project owner and a facility owner, request letter sent on 12/18/2025. West</p>	<p><b>BRIAN SCHMUCKER GENERAL CONTRACTOR: \$4,500.00</b>  Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>Section 5(17) 1st Offense \$500.00</p> <p>Section 5(11.2) 1st Offense \$500.00</p> <p>Section 5(9) 2nd Offense \$1,500.00</p> <p><b>COMCAST: \$3,000.00</b>  Section 2(5)(vii) 2nd Offense \$1,500.00</p> <p>Section 2(5)(vii) 2nd Offense \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Penn Power stated in their AVR that “On October 3, 2025, Brian Schmucker General Contractor, Excavator, submitted PA One Call Ticket 20252762025, to install a new electric line for West Penn Power (WPP). On October 9, 2025, the Excavator submitted Emergency POCS Ticket 20252821918 to repair a gas line. WPP was not aware that an AVR was needed until notified by the PAPUC. WPP has communicated to Excavators that notifying WPP is a requirement any time there is a dig in. WPP’s Operation Supervisor has reached out to Brian Schmucker to reinforce the policy to contact WPP when a dig in occurs. 911 was not notified.</p> <p><b>VIOLATIONS</b>  <b>BRIAN SCHMUCKER GENERAL CONTRACTOR</b> is in violation of:</p> <p>Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or damaging a facility owner’s line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.</p> <p>Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within 30 days of the receipt of the request.</p> <p>Section 5(11.2) – When using trenchless technology, Excavator failed to utilize at a minimum, the best practices published by the Common Ground Alliance. 9) 5-29 The excavator requests the location of underground facilities at the entrance pit, trenchless excavation path and the exit pit by notifying the facility owner/operator through the 811 center. The trenchless equipment operator performs a site inspection, walking the trenchless excavation path prior to commencing work, and has a good understanding of the job. The trenchless excavation operator confirms and maintains the path and minimum clearances established by the project owner and design engineer by tracking and recording the path of the trenchless excavation until complete. Means of trenchless excavation include electronic locating/guidance devices, pipe lasers, water levels, visual inspection, ect.</p> <p>Section 5(2.2) – Excavator failed to provide exact information to identify the worksite. Pictures show that the excavation is taking place away from the pole and on the side of 6906 Mellon Rd. This customer was affected.</p> <p>Section 5(9) – Emergency notification does not meet the requirements of “emergency” as defined in Section 1 – Emergency Ticket 20252762025 was submitted by BRIAN SCHMUCKER GENERAL CONTRACTOR on 10/03/2025 at 12:21 and is for a 2 week work project for West Penn Power to install a new electric line using a EXCAVATOR DIRECTIONAL DRILL. This is a second time offense.</p> <p>Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Recommendation: The penalties are applied. PUC compliance education is required for the excavators working onsite of this excavation or their replacements.</p> <p>COMCAST is in violation of:  Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Emergency Ticket 20252762025 was submitted by BRIAN SCHMUCKER GENERAL CONTRACTOR on 10/09/2025 at 11:57 for a gas line repair. Comcast did not respond “clear” until 10/17/2025. Historically the Damage Prevention Committee has considered this late response as no response. This is a second offense.  Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Emergency Ticket 20252821918 was submitted by BRIAN SCHMUCKER GENERAL CONTRACTOR on 10/09/2025 at 11:57 for a gas line repair. Comcast did not respond “clear” until 10/17/2025. Historically the Damage Prevention Committee has considered this late response as no response. This is a second offense.  Recommendation: The penalties are applied. PUC required education was recently completed.</p>	
61200	<p><b>Facility Owner:</b> Zayo Bandwidth  <b>Contractor/Excavator:</b> EK Services  <b>Project Owner:</b> Veolia Water  <b>Designer:</b> GANNETT FLEMING WATER RESOURCES  <b>Other:</b> Comcast  <b>Other:</b> Frontier  <b>Other:</b> H2Q ENERGY LLC  <b>Other:</b> Lumen  <b>Other:</b> PPL Electric  <b>Other:</b> UGI Utilities</p>	<p><u>On 10/14/2025 10:45:00 AM at 3930 CHAMBERS HILL RD, SWATARA TWP, DAUPHIN</u> On 5/12/26 the DPC voted to accept the recommendations for Veolia.</p> <p>***  Veolia is disputing.</p> <p>****  Incident occurred on October 14th, 2025, at 10:45am on 3930 Chambers Hill Road, Swatara Township Dauphin County.</p> <p>EK Services' Alleged Violation Report (AVR) states, "Hit unmarked communication line. LINE WAS UNMARKED. LINE IS A COMMUNICATIONS LINE THAT IS LABELED AS OPTICAL CABLE. LINE MAY BELONG TO ZAYO BUT IDENTITY IS UNKNOWN. LINE IS IN A BLACK CONDUIT."</p> <p>Veolia Water's AVR states, "Hit unmarked communication line. LINE WAS UNMARKED. LINE IS A COMMUNICATIONS LINE THAT IS LABELED AS OPTICAL CABLE. LINE MAY BELONG TO ZAYO BUT IDENTITY IS UNKNOWN. LINE IS IN A BLACK CONDUIT."</p> <p>Gannett Fleming's AVR states, "Contractor was excavating for water main for Veolia Water and struck a communications line believed to belong to Zayo. Gannett Fleming only became aware of this incident on 11/11/25 as we did not have field representation."</p> <p>Emails have been sent out to Zayo, and they are looking into the status and ownership of the line. Location is near a demolished building. AVR was requested from Zayo. Zayo's Email response states, "With the current</p>	<p><b>Veolia Water: \$250.00</b>  Section 2(5)(v) 1st Offense \$250.00</p> <p><b>Comcast: \$250.00</b>  Section 2(5)(v) 1st Offense \$250.00</p> <p><b>Frontier: \$1,250.00</b>  Section 2(5)(vii) 1st Offense \$1,000.00</p> <p>Section 2(5)(v) 1st Offense \$250.00</p> <p><b>H2Q ENERGY LLC: \$1,500.00</b>  Section 2(5)(v) 1st Offense \$500.00</p> <p>Section 2(5)(vii) 1st Offense \$1,000.00</p> <p><b>Lumen: \$500.00</b>  Section 2(5)(viii) 1st Offense \$500.00</p> <p><b>PPL Electric: \$250.00</b>  Section 2(5)(v) 1st Offense \$250.00</p> <p><b>UGI Utilities: \$250.00</b>  Section 2(5)(v) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>information I have, if this is the line, I believe it was probably abandoned before we bought the facilities as there is no record of us having anything there buried." No violation for abandoned/unknown owner of line.</p> <p>Recommended violations, penalties, and education:</p> <p><b>Veolia Water</b> Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. 20252682622. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p> <p><b>Lumen</b> Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20251213848. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p> <p><b>Frontier</b> Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. 20252682622. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20252812712. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p> <p><b>PPL</b> Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. 20252682622. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p> <p><b>UGI</b> Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. 20252682622. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p> <p><b>H2Q Energy</b> Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20252682622. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20252871553. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p> <p><b>Comcast</b></p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. 20252682622. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p>	
59544	<p><b>Facility Owner:</b> WALLACE TOWNSHIP <b>Contractor/Excavator:</b> TAYLOR SUMAN CONSTRUCTION <b>Project Owner:</b> C.Jacobsen Construction Co.</p>	<p><u>On 10/21/2025 1:00:00 PM at 21 PARK LN, WALLACE TWP, CHESTER</u> On 5/12/26 the DPC voted to accept DPis Rec and add \$250 for No Show for Taylor Suman Construction.</p> <p>5(22) Added \$250 for now show. \$500 + \$250 is \$750.</p> <p>****</p> <p>Taylor Suman Construction is disputing.</p> <p>****</p> <p>This non-damage incident occurred on October 21st, 2025, at 1pm on 21 Park Lane, Wallace Township, Chester County.</p> <p>An emergency ticket was placed for a non-emergency situation, as described in Act 127 of 2024.</p> <p>Wallace Township's Alleged Violation Report (AVR) states, "Excavator put in an emergency ticket for a house basement and has just been issued a permit for construction the day before."</p> <p>Emergency ticket 20252940129: Type of Work--[EXCAV FOUNDATION] Depth--[8FT] Extent of Excavation--[15FT X 40FT] Method of Excavation--[POWER EQUIP] Equip Type--[EXCAVATOR]</p> <p>Violation:</p> <p>Taylor Suman Construction Section 5(22) – Excavator provided a misrepresentation of an emergency excavation, subject to an administrative penalty imposed under section 7(10). 20252940129. PUC compliance education is required.</p>	<p><b>TAYLOR SUMAN CONSTRUCTION:</b> <b>\$750.00</b> Section 5(22) 1st Offense \$750.00</p>
60298	<p><b>Facility Owner:</b> Veolia Water PA <b>Project Owner:</b> PA Fixer Upper, LLC <b>Designer:</b> ELSA ASSOCIATES LLC <b>Other:</b> Comcast <b>Other:</b> LUMEN FORMERLY LEVEL 3 <b>Other:</b> Verizon</p>	<p><u>On 10/22/2025 4:14:00 PM at KOKOMO AVE, HUMMELSTOWN BORO, DAUPHIN</u> On 5/12/26 the DPC voted to remove the violation and penalty for Elsa Associates.</p> <p>***</p> <p>Elsa Associates are disputing.</p> <p>***</p> <p>This non damage incident occurred on October 22nd, 2026, at 4:14pm along Kokomo Avenue, Hummelstown Boro, Dauphin County.</p> <p>This a non-damage incident.</p> <p>Designer, Elsa Associates LLC's Alleged Violation Reports (AVRs) state, "Veolia will not provide information regarding their facilities as required by the</p>	<p><b>Veolia Water PA:</b> <b>\$500.00</b> Section 2(4) 1st Offense \$250.00</p> <p>Section 2(5)(v.2) 1st Offense \$250.00</p> <p><b>ELSA ASSOCIATES LLC: \$0.00</b></p> <p><b>Comcast: \$500.00</b> Section 2(4) 1st Offense \$250.00</p> <p>Section 2(5)(v.2) 1st</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>PA One Call Law. See attached email from them. Veolia will not mark out their facilities as required by the PA One Call Law. They claim insufficient information was provided, however Hummelstown Borough was able to mark out their (sewer) facilities."</p> <p>Facility Owner, Veolia's AVR states, "This is an AVR in regards to case #60298, contractor failed to properly communicate with Veolia utility locator when attempting to understand the specific location of the worksite. Area was not marked in white besides two white arrows pointing East on Circle Dr. and Kokomo Ave. Locator attempted to contact contractor to coordinate an on site meeting due to the length of excavation being approximately 1500'. Ticket did not specify where the work was expected to take place. Contractor failed to return phone calls and respond to voicemails left by locator and Veolia management. Ticket was marked insufficient."</p> <p>Facility Owner, Lumen's AVR states, "New home construction work-Lumen telecommunications no work/and in the railroad row. Serial Number(s): Received: 20252860492, 20253070849."</p> <p>Preliminary Design Ticket 202528604922: AQ1 COMCAST ENGINEERING COMPLETED. A PDF FILE OR MARKED UP PLANS WERE SENT TO THE REQUESTOR. 11/11/2025 3:19:17 PM AAA-WEBSVC DID NOT RESPOND THROUGH PA ONE CALL. 10/29/2025 12:03:32 AM</p> <p>DH VEOLIA WATER PENNSYLVANIA INC DESIGN CONFLICT. PLEASE EMAIL OR SEND PLANS TO: CHRISTOPHER BRIDE VEOLIA WATER PENNSYLVANIA INC 6310 ALLENTOWN BOULEVARD HARRISBURG PA 17112 CHRISTOPHER.BRIDE@VEOLIA.COM 10/28/2025 8:48:20 PM CBR-WEBSVC</p> <p>HC VERIZON PENNSYLVANIA LLC DID NOT RESPOND THROUGH PA ONE CALL. 10/29/2025 12:03:32 AM</p> <p>Routine Ticket 20253070849: 0 DH VEOLIA WATER PENNSYLVANIA INC DH-INSUFF INFO. DO NOT DIG 11/3/2025 11:14:22 AM HCa-WEBSVC 0 AQ1 COMCAST AQ1-NO RESPONSE 11/6/2025 12:03:23 AM Auto-KARL 0 AQ1 COMCAST AQ1-CLEAR. NO FACILITIES OR FACIL NOT INVOLVED 11/12/2025 1:51:57 PM AAA-WEBSVC</p> <p>Veolia provided an NDA along with the reasoning for the NDA before they provide designs. The designer then placed a routine ticket to obtain mark outs since Veolia</p>	<p>Offense \$250.00</p> <p><b>Verizon: \$250.00</b> Section 2(4) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>claims they do not require the NDA for PA1 call markouts.</p> <p>Designers routine ticket was ~1,490 feet. No complex ticket was placed.</p> <p>Violations:</p> <p>Veolia Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20252860492. PUC compliance education is required for the individual(s) responsible to respond to this ticket or their replacement(s).Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests.20253070849. PUC compliance education is required for the individual(s) responsible to respond to this ticket or their replacement(s).</p> <p>Elsa Associates LLC Section 5(3) – Excavator failed to hold a preconstruction meeting prior to beginning a complex project. 20253070849.</p> <p>Comcast Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20252860492. PUC compliance education is required for the individual(s) responsible to respond to this ticket or their replacement(s).Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests.20253070849. PUC compliance education is required for the individual(s) responsible to respond to this ticket or their replacement(s).</p> <p>Verizon Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20252860492. PUC compliance education is required for the individual(s) responsible to respond to this ticket or their replacement(s).</p>	
60830	<p><b>Facility Owner:</b> Comcast</p> <p><b>Contractor/Excavator:</b> ROGELE INC</p> <p><b>Project Owner:</b> Derry Township Municipal Authority of Derry Township</p> <p><b>Other:</b> Buckley Cable Construction</p> <p><b>Other:</b> Conewago Township - Dauphin County</p> <p><b>Other:</b> First Energy - Met-Ed</p> <p><b>Other:</b> HOMEOWNER</p> <p><b>Other:</b> PPL Electric</p> <p><b>Other:</b> Verizon</p>	<p><u>On 10/23/2025 1:00:00 PM at adjacent to 352 Laurel Drive, CONEWAGO TWP, DAUPHIN</u> On 5/12/26 the DPC voted to remove the violation and penalty for First Energy - Met ed.</p> <p>****</p> <p>First Energy is disputing the violation for response on ticket 20253240264.</p> <p>****</p> <p>Incident occurred on October, 23rd 2025, at 1pm on 352 Laurel Drive, Conewago Township, Dauphin County.</p> <p>A communications line was damaged.</p> <p>Comcast's Alleged Violation Report (AVR) states, "Excavator cut marked feeder line."</p> <p>Homeowner's AVR states, "Verizon/Comcast failed to properly mark cables/lines which resulted in loss of service. There are two people in the home that require</p>	<p><b>Comcast: \$2,500.00</b> Section 2(5)(v.2) 1st Offense \$250.00</p> <p>Section 2(5)(v.2) 1st Offense \$250.00</p> <p>Section 2(5)(vii) 1st Offense \$1,000.00</p> <p>Section 2(5)(vii) 1st Offense \$1,000.00</p> <p><b>ROGELE INC: \$1,250.00</b> Section 5(16) 1st Offense \$1,000.00</p> <p>Section 5(20) 1st Offense</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>internet service; one who works from home and the other is a college student. The person that works from home was required to take vacation time to account for her time at no fault of her own."</p> <p>Homeowner's follow up email: Just to clarify this issue was with Comcast/Xfinity not Verizon. While preparing the work site next door to our residence Roegle Inc cut our line while digging and were unaware they had done so until informed by me due to our loss of internet service which negatively impacted my employment with patient care as I work remotely as well as my daughter's ability to participate in her online college courses. Per the DTMA representative on site (Scott Winters) the lines were never marked by Comcast who shared that in his experience is a constant issue as "it is cheaper for Comcast to pay the fines than to send anyone out to mark their lines" and this incident was then reported as they are required to do. Mr Winters informed me that by law Comcast is required to respond within 3 hours which never happened. Comcast never came to the work site or took any initiative with this incident: it was because of my endless hours of time, numerous repeated phone calls, and insistence on a prompt repair/response for resolution that this issue was even addressed. Comcast arrived at the site the next day only to cause even more problems as the tech that arrived questioned why there was work order which I was told was placed on 10/23/25 by 2 different people I spoke with at Comcast (Nichil at 1347 and then Mark in Manilla at 1634). In addition he was not the correct person to be at the work site and had to request for the appropriate person come to the site for the actual repair. All of this this information should be recorded on my account if Comcast follows the proper business procedures for these services. Attached are pictures of the severed line and the sealed work site where the line was located which are the most telling. We also have additional pictures of the surrounding work site area if those would be helpful. I suspect this is not an isolated incident: swift action definitely needs to be taken with Comcast to stop their bad behavior and poor business practices that likely negatively impact many of their customers.</p> <p>DPI confirmed with the homeowner that it was a Comcast line.</p> <p>Rogele Inc's AVR submitted on 1/12/26 states, "Rogele was excavating to install new 6" sewer lateral. Crew hand dug and uncovered the marked facilities. Then while digging with a trackhoe to get to require grade, a bucket tooth hooked the unmarked cable that was along the curblin approx. 30"deep. There were no markings (paint or flags) in the area for this line. Shortly after, the neighbor informed our crew their Comcast service was knocked out. We called PA1Call for Emergency (hit line). Crew waited for 2hrs and no one showed up. Onsite representative from Derry Twp Mun Auth (owner) instructed Rogele to complete the job and backfill the excavation. It's Rogele's understanding that</p>	<p>\$250.00</p> <p><b>Derry Township Municipal Authority of Derry Township:</b>  <b>\$1,000.00</b>  Section 6.1(7) 1st Offense  \$1,000.00</p> <p><b>Conewago Township - Dauphin County:</b>  <b>\$500.00</b>  Section 2(5)(v) 1st Offense  \$500.00</p> <p><b>First Energy - Met-Ed:</b>  <b>\$0.00</b></p> <p><b>PPL Electric: \$250.00</b>  Section 2(5)(v.2) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Comcast/Xfinity (not Verizon) did not arrive on site until the next day. ***Please note, the hit line was owned by Comcast and not Verizon."</p> <p>Derry Township Municipal Authority's AVR submitted on 1/13/26 states, "On 10/23/2025 our contractor, Rogele Inc., was digging to install a 6" sanitary sewer service lateral to a new home. They hand dug around all marked utilities to locate them. When all marked utilities were located, they began using the backhoe/tracker to continue their excavation. Upon doing so, around 12:30pm, they hit a Comcast line that was not marked. Rogele immediately placed an Emergency One Call (20252962622) for the hit. After waiting over two hours for all utilities to respond, Rogele continued their work connecting the sewer line. We directed Rogele to complete the work and backfill the trench since they were calling for bad weather. The excavation was on the edge of the road so it would have been a hazard to leave it open. We (and Rogele) received no call or site visit from Comcast from the Emergency One Call. We learned that Comcast did not show up until the following day."</p> <p>Images from Rogele are from a grassy area. The damage images from the homeowner and Comcast are the wooded area with leaves between 352 Laurel Lane and their neighbor. Homeowner's file, IMG_6080 Homeowner, is date stamped 10/23/25 at 4:06pm with two telecom flags in the ground along the roadway. Comcast did not respond to the routine dig tickets ending in 1068 and 1070 until 11/8/2025, and the response was due by 10/17/25.</p> <p>Rogele and Derry Township submitted their AVRs after 30 days from the incident date. Derry Township is listed as the project owner and field marked both emergency damage tickets. Comcast failed to respond to both emergency tickets.</p> <p>Ticket 20253240264 had response due date of Response Due Date of 11/24/25.  2(5)(v) To respond to all notices through the One Call System, provided the request is made in the time frame set forth under this act. The response shall be made not later than the end of the second business day.  PPL and Met-Ed responded Scheduled Mark on 11/24/25 for ticket ending in 0264.  PPL and Met-Ed responded Scheduled Mark on 11/28/25 for ticket ending in 0264.  PPL and Met-Ed responded Scheduled Mark on 12/1/25 for ticket ending in 0264.</p> <p>Responses were given on ticket 20253240264 but no Final Response of clear or field marked was completed until 12/3/25 which is 10 days after the Response Due Date of 11/24/25. Excavator had a legal start date of 11/25/25. Ticket 20253240264 was provided by Comcast on their Alleged Violation Report.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>2(5)(v.2) To timely enter a final response to all locate requests.  PPL and Met-Ed gave the following Final Responses.  PPL responded Clear No Facilities on 12/3/25 for ticket ending in 0264.  Met-Ed responded Field Marked on 12/3/25 for ticket ending in 0264.</p> <p>Conewago Township responded with No Response on 10/18/25 then a Clear No Facilities on 10/20/25 for ticket ending in 1068.  Comcast failed to give a final response on ticket ending in 1070.  Verizon gave no response then clear on 10/21 to ticket ending in 1070.</p> <p>Investigator emailed Rogele to confirm if the images submitted correlated to incident at 352 Laurel Drive.</p> <p>Violations:</p> <p>Comcast  Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. 20252881070. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).  Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. 20252881068. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).  Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20252962622. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).  Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20252962621. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p> <p>Rogel Inc.  Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. 20252962621. PUC compliance education is required for the person responsible for submitting AVR or their replacement.  Section 5(20) – Excavator failed to renotify One Call of an unmarked or incorrectly marked facility upon arrival at a work site. 20252881070. PUC compliance education is required for the excavators working onsite of this excavation or their replacements.</p> <p>Derry Township Dauphin County  Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. 20252962621. PUC compliance education is required for</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>the person responsible for submitting AVR or their replacement.</p> <p>First Energy Met-Ed Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. 20253240264. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p> <p>PPL Electric Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. 20253240264. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p> <p>Conewago Township Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20252881068. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p>	
60081	<p><b>Facility Owner:</b> CHESTER WATER AUTHORITY</p> <p><b>Contractor/Excavator:</b> GENERAL ASPHALT PAVING</p> <p><b>Project Owner:</b> PECO Energy</p> <p><b>Designer:</b> PECO - SPACESAVER</p> <p><b>Other:</b> UPPER CHICHESTER TOWNSHIP</p>	<p><u>On 11/3/2025 8:05:00 AM at BETHEL AVE, UPPER CHICHESTER TWP, DELAWARE</u> On 5/12/2026 the Damage Prevention Committee (DPC) voted to keep the violation and remove the penalty to Upper Chichester Township.</p> <p>*</p> <p>Upper Chichester Township disagrees. *****</p> <p>The incident occurred on 11/03/2025 on Bethel Ave in UPPER CHICHESTER TWP in Delaware Co.</p> <p>A water Service line owned by Chester Water Authority was damaged.</p> <p>GENERAL ASPHALT PAVING stated in their Alleged Violation Report (AVR) that “Crew damaged a 3/4" copper water service to 828 Bethel Ave., Upper Chichester, PA during excavation for new 12" steel gas main. Damaged water service was not marked. There was a marked water service meter box, to 828 Bethel Ave, located over 18 feet away from damaged copper line. There was no water service meter box or any indication of the unmarked service that was damaged”. The project is listed as &gt;\$400,000. 1000LF and Test Hole/Pot Holing is the Subsurface Utility Engineering (SUE) that was completed.</p> <p>PECO AN EXELON COMPANY stated in their AVR that “ON 11/3/2025, GAP WORKING FOR PECO WAS EXCAVATING WHEN THEY STRUCK A WATER SERVICE”.</p> <p>Chester Water Authority the facility owner was sent an AVR request letter on 1/05/2025. On 1/06/2025 an email was received from Chester Water Authority stating that the foreman of this project will be in tomorrow and will submit an AVR.</p>	<p><b>CHESTER WATER AUTHORITY: \$1,500.00</b> Section 2(5)(i) 1st Offense \$500.00</p> <p>Section 2(10) 1st Offense \$1,000.00</p> <p><b>UPPER CHICHESTER TOWNSHIP: \$0.00</b> Section 2(5)(vii) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>CHESTER WATER AUTHORITY stated in their AVR that “Subcontractor ( General Asphalt ) for PECO struck Chester Water Authority mismarked water service”. They note that the line was marked inaccurately. Chester Water Authority send an email stating that they are working on improving thier process and actively working with their foremen to reinforce the importance of before and after photos as part of the documentation.</p> <p>Emergency ticket 20253070941 was submitted on Monday, 11/03/2025 at 9:00 am. UPPER CHICHESTER TOWNSHIP did not respond until on Wednesday, 11/05/2025 at 9:44 am. they responded “clear”.</p> <p><b>VIOLATIONS</b> CHESTER WATER AUTHORITY is in violation of: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: The penalties are applied. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p> <p>UPPER CHICHESTER TOWNSHIP is in violation of: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Recommendation: The penalty is applied. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p>	
60313	<p><b>Facility Owner:</b> Verizon North <b>Contractor/Excavator:</b> S AND C PIPELINE <b>Project Owner:</b> Peoples Gas Company <b>Designer:</b> EADS GROUP</p>	<p><u>On 11/10/2025 8:40:00 AM at BARRON AVE, JOHNSTOWN CITY, CAMBRIA</u> On 5/12/26 the DPC voted to remove the violation and penalty for S&amp;C Pipeline.</p> <p>*** S&amp;C Pipeline mailed in a dispute.</p> <p>*** Incident occurred on November 10th, 2025, at 8:40am along Barron Avenue, Johnstown City, Cambria County.</p> <p>A telecom line was damaged.</p> <p>S &amp; C Pipeline's Alleged Violation Report (AVR) states, "Work was taking place at the intersection of Barron Ave and Virginia Ave when we hit an unmarked Verizon line. The operator and ditch digger saw zero indication of any type of line in the ground. Before every job we as a company review facility owners responses and Verizon responded with Clear no facilities. Upon damage we</p>	<p><b>Verizon North: \$2,250.00</b> Section 2(4) 1st Offense \$250.00</p> <p>Section 2(5)(i) 1st Offense \$500.00</p> <p>Section 2(10) 1st Offense \$1,000.00</p> <p>Section 2(11) 1st Offense \$500.00</p> <p><b>S AND C PIPELINE: \$0.00</b></p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>notified pa 1 call. This is an ongoing problem with Verizon not responding to tickets in this region."</p> <p>Peoples Gas Company's AVR states, "S&amp;C was digging to install new plastic gas mains and services when they struck an unmarked Verizon line. Contractor damaged the fiberline at the intersection of Barron Ave and Virginia ave while trenching . Verizon responded and had lambert cable splicing repair the line."</p> <p>The EADS Group's AVR states, "S&amp;C was digging to install new plastic gas mains and services when they struck an unmarked verizon line. The contractor damaged the fiberline at the intersection of Barron Ave and Virginia Ave while trenching. Verizon responded and had lambert cable splicing repair the line."</p> <p>An AVR request letter was sent to Verizon on 1/9/2026. No AVR has been received to date. No markouts were made by Verizon North. Verizon North responded clear no facilities to 20252873107, 20251142781, 20222540201, 20232880151, and 20232880152.</p> <p>Verizon North responded clear no facilities followed up by field marked to emergency damage ticket 20253141033. 0 TF VERIZON NORTH TF-CLEAR. NO FACILITIES OR FACIL NOT INVOLVED 11/10/2025 9:26:52 AM PRA-WEBSVC 0 TF VERIZON NORTH TF-FIELD MARKED 11/10/2025 12:41:42 PM AAA-WEBSVC</p> <p>Verizon failed to respond to design ticket 20252734120: 0 TF VERIZON NORTH TF-NO RESPONSE 10/16/2025 12:04:21 AM Auto-KARL</p> <p>No complex project ticket was located by PA1 call for S&amp;C Pipeline.</p> <p>Recommended violations, penalties, and education:</p> <p>Verizon North Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20252734120. -PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. 20252873107. -PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>-PUC compliance education is required for the person responsible for submitting AVR or their replacement. Section 2(11) – Facility Owner failed to comply with all requests for information by the Commission relation to the Commission’s enforcement authority under this act within thirty days of the receipt of the request.</p> <p>S&amp;C Pipeline Section 5(3) – Excavator failed to hold a preconstruction meeting prior to beginning a complex project. -PUC compliance education is required for the excavators working onsite of this excavation or their replacements.</p>	
60250	<p><b>Contractor/Excavator:</b> CITY SIGN SERVICE INC <b>Other:</b> EAST PIKELAND TOWNSHIP</p>	<p><u>On 11/11/2025 1:03:00 PM at 283 SCHUYLKILL RD, EAST PIKELAND TWP, CHESTER</u> Disputing- City Sign Service Inc and they stated their reason why in an email: DLZ hired Clayco to install the signs - DLZ is a consultant for USPS in the form of architects/engineering and so forth. DLZ was under pressure from the local Postmaster from USPS and the office of the inspector general to install the signage. The original install location had a road / solid concrete 14" below grade and 30'x20' that was still intact from the previous construction. We had to pivot to a new location quickly that was farther away from the road and was not covered in the original scope of the first one call City Sign has been working with PA One Call for many years and hasn't had any violations or issues. We have worked with local utilities and municipalities that were unable to meet the deadlines specified in our requests as well as communicating with them exact locations to make the process more efficient. I will gladly go online and re-do the training to brush up on the details, it was my understanding that the emergency designation dictated something that needed to be done in a tighter timeline than routine. I didn't receive any notice that we needed to provide any additional information or what information would be required as when we were on site there were no issues, the dig went according to plan. Please let me know if I can provide any further information, although I feel that this should serve as a comprehensive detail of what happened. Thank you and have a nice day. Liz Liz Jones City Sign Service, Inc. 424 Caredean Drive Horsham PA 19044 Office – 215-442-1323 lhill@citysign.net</p> <p>***** The Non-Damage violation occurred on Wednesday, November 11, 2025, at 283 Schuylkill Road, in East Pikeland Township, Chester County.</p>	<p><b>CITY SIGN SERVICE INC: \$1,500.00</b> Section 5(17) 1st Offense \$500.00</p> <p>Section 5(9) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Non-Damage violation was reported by East Pikeland Township, the locator.</p> <p>East Pikeland Township stated in their Alleged Violation Report (AVR), I received an emergency one call for a sign footer install at a construction site and I don't consider this an emergency. Poor planning on their part shouldn't be an emergency on my part. 20253151970- Excavation Emergency ticket placed on 11/11/2025 at 1:03pm, by City Sign Service Inc, and Type of Work--[SIGN FOOTER].</p> <p>The Underground Utility Line Protection Law (UULPL) aka PA One Call Law, ACT 127, definition: "Emergency" means a sudden or unforeseen occurrence involving a clear and immediate danger to life, property and the environment, including, but not limited to, serious breaks or defects in a facility owner's lines.</p> <p>On Friday, 1/9/2026, letter and an email were sent requesting an AVR from City Sign Service Inc. There was no response to the request and no AVR was submitted.</p> <p>Violations: *City Sign Service, Inc. is in violation of sections: 5(9) – Emergency notification does not meet the requirements of “emergency” as defined in Section 1 – Excavator Ticket. 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. Recommendation: Penalties Applied and PUC Online Compliance Training is required for the Excavator(s) working onsite at this excavation, or their replacements.</p>	
60338	<p><b>Facility Owner:</b> Comcast <b>Contractor/Excavator:</b> PLUG UTILITIES <b>Project Owner:</b> Verizon <b>Other:</b> First Energy - Met-Ed <b>Other:</b> Texas Eastern Transmission, LP</p>	<p><u>On 11/13/2025 9:45:00 AM at CAROL ANN DR, NORTH LEBANON TWP, LEBANON</u> On 5/12/26 the DPC voted to keep 2(5)(vii) but remove 2(5)(v.2) for First Energy Met-Ed.</p> <p>*** First Energy is disputing.</p> <p>See complex meeting sign in sheet with notes of a no show by USIC. *** Texas Eastern Transmission's violation was removed after showing Enbridge signed in on the complex project meeting notes. ****</p> <p>Incident occurred on November 13th, 2025, at 9:45am along Carol Ann Drive, North Lebanon Township, Lebanon County.</p> <p>A telecom line was damaged.</p> <p>Comcast was the facility owner and they submitted three AVRs for this incident. Comcast's Alleged Violation</p>	<p><b>Comcast: \$1,000.00</b> Section 2(5)(i) 1st Offense \$500.00</p> <p>Section 2(5)(viii) 1st Offense \$500.00</p> <p><b>Verizon: \$6,500.00</b> Section 4(2) 1st Offense \$500.00</p> <p>Section 4(2.2) 1st Offense \$250.00</p> <p>Section 4(3) 1st Offense \$250.00</p> <p>Section 4(4) 1st Offense \$250.00</p> <p>Section 4(4.1) 1st Offense \$500.00</p> <p>Section 4(5) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Reports (AVR) state, "WORKING IN THE EASEMENT BTWN 12 AND 13 CAROL ANN DR. USING A MISSLE AND HAND TOOLS. FACILITY TYPE: CABLE TV-COMCAST. Filled out based on PA One Call tickets and PUC email. Comcast has not been receiving AVRs."</p> <p>Plug Utilities' AVR states, "While installing conduit on CAROL ANN DR, the crew struck an unmarked cable line belonging to COMCAST. All corresponding utilities are required to mark their lines by the project's LEGAL START DATE OF FRI 11/07/2025. However on start date the site was MARKED BY ALL EXCEPT COMCAST. Renotifications were sent to COMCAST on 11-10-2025 and were also notified the crew was on site ready to proceed. However, they did not respond, and consequently the crew interrupted crossed an unmarked COMCAST cable at address 12 &amp; 13 CAROL ANN DR. LEBANON COUNTY, N LEBANON TWP."</p> <p>Comcast was sent an AVR request letter asking, "Why did Comcast respond "Clear No Facilities" to the tickets on this case despite having underground utilities in the excavation area?"</p> <p>Verizon was mailed an emailed an AVR request letter asking, "Did Verizon do designs to plan ahead and protect other underground utilities in accordance with Act 127 of 2024?" Coordinate PA includes Verizon's design documents, file 1A6P1RP. Verizon failed to complete a Final Design ticket within 10-90 days, failed to place a final design ticket after designs were completed, failed to depict lines, failed to make reasonable effort to avoid damage, failed to use the appropriate level of SUE, and failed to use the PA1 call number and serial number for design ticket on designs. Designer's names are listed on the design documents.</p> <p>Complex sign-in sheet shows that Met-Ed, Verizon, and Texas Eastern did not attend. Comcast responded clear to the complex ticket despite having underground lines.</p> <p>Met-Ed responded scheduled mark to ticket 20253072918 which had a due date of 11/6/25. On 11/7/25 Met-Ed responded clear no facilities.</p> <p>Recommended violations, penalties, and education:</p> <p>Comcast  Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. 20253072918.  - PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).  Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20252973360.</p>	<p>Section 6.1(7) 1st Offense \$1,000.00</p> <p>Section 6.1(8) 1st Offense \$500.00</p> <p>Section 6.1(3) 1st Offense \$500.00</p> <p>Section 6.1(4) 1st Offense \$500.00</p> <p>Section 2(5)(viii) Subsequent \$2,000.00</p> <p><b>First Energy - Met-Ed: \$500.00</b></p> <p>Section 2(5)(viii) 1st Offense \$500.00</p> <p><b>Texas Eastern Transmission, LP: \$0.00</b></p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>- PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p> <p>Verizon Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20252973360.</p> <p>- PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p> <p>Section 4(2) – Designer failed to request the line and facility information prescribed by section 2(4) from the One Call System not less than ten nor more than ninety business days before final design is to be completed.</p> <p>-PUC compliance education is required for the designer(s) who worked on this project or their replacement(s).</p> <p>Section 4(2.2) – Failed to submit a design notification through the One Call System when a design drawing is completed.</p> <p>-PUC compliance education is required for the designer(s) who worked on this project or their replacement(s).</p> <p>Section 4(3) – Designer’s drawing does not show the position and type of each facility owner’s line, and the name of the facility.</p> <p>-PUC compliance education is required for the designer(s) who worked on this project or their replacement(s).</p> <p>Section 4(4) – Failed to prepare construction drawings to avoid damage to and minimize interference with facilities in the construction area.</p> <p>-PUC compliance education is required for the designer(s) who worked on this project or their replacement(s).</p> <p>Section 4(4.1) - Failed to depict lines or facilities with the appropriate quality levels based on the complexity of the design and construction activities obtained through the SUE process in the planning and design phases in accordance with the American Society of Civil Engineers (ASCE) most recently published standard CI/ASCE 38.</p> <p>-PUC compliance education is required for the designer(s) who worked on this project or their replacement(s).</p> <p>Section 4(5) – Designer’s drawing does not include One Call’s toll-free number and the serial number of the ticket.</p> <p>-PUC compliance education is required for the designer(s) who worked on this project or their replacement(s).</p> <p>Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike.</p> <p>Section 6.1(8) - Project Owner failed to comply with all requests for information by the commission relating to the commission's enforcement authority under this act within 30 days of receipt of written request.</p> <p>Section 6.1(3) – Released a project to bid or construction before final design was complete.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 6.1(4) – Failed to participate in design and preconstruction meetings.</p> <p>First Energy's Met-Ed Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. 20253072918. - PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20252973360. - PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p> <p>Texas Eastern Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20252973360. - PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p>	
60553	<p><b>Facility Owner:</b> UGI UTILITIES INC <b>Contractor/Excavator:</b> CM WEAVER CONSTRUCTION <b>Project Owner:</b> Homeowner <b>Other:</b> LANCASTER TOWNSHIP</p>	<p><u>On 11/17/2025 1:13:00 PM at 1296 MEADOWBROOK ROAD, LANCASTER TWP, LANCASTER</u> On Tuesday 5/12/2026, at the DPC meeting, disputing was Lancaster Twp and they were a NO SHOW, but it was voted to remove the penalties and violations. ***** Disputing is UGI Utilities, they stated, "UGI respectfully rejects the violations applied in this case. Our line was not marked straight, and the excavator stripped the soil and destroyed almost all markings on site. The attached picture shows our line as marked with a curve like described by the excavator in their AVR." UGI presented additional photos showing the line was likely marked within 18 inches. Violation and penalty withdrawn before case went to DPC for dispute. ***** Disputing is Lancaster Township the violation and penalty (see attachments), stating, "Finally, the two sections from the most recent updated user guide stating that ALL responses are final with the exception of 007 voice message and 999 did not respond." From the 1/28/2026 PA811 Users Guide, Disclaimer of Liability- "...the Guide is meant to clarify and explain the law according to POCS' understanding of how it affects interaction with POCS. This Guide is not a substitute for the Act and it does not relieve anyone from discharging their responsibilities as set forth in the Act or as otherwise required by law..." ***** The incident occurred on Monday, November 17, 2025, at 1296 Meadowbrook Road, in Lancaster Township, Lancaster County.  A gas line owned by UGI Utilities was damaged.</p>	<p><b>UGI UTILITIES INC:</b> <b>\$0.00</b></p> <p><b>CM WEAVER CONSTRUCTION:</b> <b>\$500.00</b> Section 5(16) 1st Offense \$500.00</p> <p><b>LANCASTER TOWNSHIP: \$0.00</b></p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>UGI stated in their Alleged Violation Report (AVR), "Excavator utilizing mechanized equipment, struck a correctly marked gas service."</p> <p>UGI provided pictures of the damaged line and locate marks. The photos showing the damaged gas service line was not straight, as indicated by the straight locate marks in the photos.</p> <p>CM Weaver Construction stated in their AVR, "The gas line had a 6-foot-long sweeping curve instead of a straight line, requiring us to adjust the location of the addition. The gas line was punctured while attempting to locate the gas line to position the addition properly."</p> <p>CM Weaver Construction AVR was submitted on 12/23/2025, not submitted within 30 days of the 11/17/2025 incident.</p> <p>20253152901- Routine ticket placed on 11/11/2025 at 3:14pm. Lancaster Township Lancaster County responded with Scheduled Marked by 11/12/25, but they did not follow-up with Field Marked or Clear No Facilities.</p> <p>Violations:</p> <p>*UGI Utilities is in violation of section: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: Penalty Applied</p> <p>*CM Weaver Construction is in violation of section: 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: Penalty Applied with 50% reduction (\$1,000 to \$500), and PUC Online Compliance Training is required for the Excavator(s) working onsite at this excavation, or their replacements.</p> <p>*Lancaster Township is in violation of section: 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. 20253152901 Recommendation: Penalty Applied and PUC Online Compliance Training is required for the Individual(s) responsible to perform the locate for this ticket, or their replacement(s).</p>	
60731	<p><b>Facility Owner:</b> PECO <b>Contractor/Excavator:</b> N ABBONIZIO CONTRACTORS INC <b>Project Owner:</b> Tredyffrin Township <b>Designer:</b> Princeton Hydro</p>	<p><u>On 11/18/2025 10:00:00 AM at WILLIS LN, TREDYFFRIN TWP, CHESTER</u> On 5/12/26 the DPC voted to reduce the penalty to \$250 and keep education for Princeton Hydro.</p> <p>*** Princeton Hydro's dispute states, "Princeton Hydro knew about the gas line strike and the responses from PA One Call and the emergency responders to secure the site and repair the service. It is Princeton Hydro's understanding that it was the contractor's responsibility to notify all parties which they did. We were not aware of the change</p>	<p><b>N ABBONIZIO CONTRACTORS INC:</b> <b>\$500.00</b> Section 5(4) 1st Offense \$500.00</p> <p><b>Tredyffrin Township:</b> <b>\$500.00</b> Section 6.1(7) 1st Offense \$500.00</p> <p><b>Princeton Hydro:</b></p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>in regulations which required the design to report this incident to the PUC."</p> <p>Princeton Hydro submitted an AVR on 4/07/2026 that states, "The contractor was digging to locate a water service and hit a gas service for 558 Willis Lane."</p> <p>DPI mailed and emailed Princeton Hydro a request for an AVR with multiple questions on 1/12/2026. ***</p> <p>Tredyffrin Township Accepts after providing design contracts.</p> <p>Removed Section 6.1(1) – Failed to utilize sufficient quality levels of subsurface utility engineering or other similar techniques to properly determine the existence and positions of underground facilities when designing known complex projects having an estimated cost of (\$400,000) or more.</p> <p>Removed Section 6.1(3) – Released a project to bid or construction before final design was complete. Reduced to \$500. Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Reduced by 50% from \$1,000 to \$500 for promptly submitting after PUC request. -PUC compliance education is required for the person responsible for submitting AVR or their replacement.</p> <p>***</p> <p>Incident occurred on November 18th, 2025, at 10am along Willis Lane, Tredyffrin Township, Chester County.</p> <p>A gas line was damaged.</p> <p>PECO's Alleged Violation Report (AVR) states, "CONTRACTOR N ABBONIZIO CONTRACTORS INC ADMITTED TO HITTING THE ACCURATELY MARKED 1.25" GAS SERVICE WITH THE TOOTH OF THE EXCAVATOR BUCKET."</p> <p>Images from PECO show that the line was snapped and pulled vertically above the road surface.</p> <p>N. Abbonizio Contractors' AVR states, "We were hand digging to locate a water service and hit a gas service for 558 Willis Lane."</p> <p>Tredyffrin Township's AVR submitted on 1/14/26 states, "Tredyffrin Township contractor (N. Abbonizio) who was working on the Twp. Willis/Woodcrest/Upper Weadley Rd Stormwater Management and Drainage Improvement Project was digging in the cul-de-sac of Willis Lane (Twp. roadway) and was attempting to locate the water service near where the stormwater pipe was being installed, and N. Abbonizio hit a PECO gas service for 558 Willis Lane (a residential property). Contractor (N. Abbonizio Contracting, LLC.) submitted an AVR Report for this Gas Line Incident on 12/18/2025 (see attached AVR). Tredyffrin Twp. was only received notification from PA PUC with letter dated 1/12/26.</p>	<p><b>\$250.00</b> Section 4(8) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Photos provided by the Twp. inspector (Princeton-Hydro) are included as attached."</p> <p>Tredyffrin Township was notified of the damage on emergency damage ticket 20253221091. Emergency Damage Ticket 20253221091 noted "Work is Being Done For: TREDYFFRIN TOWNSHIP" and was responded with "TREDYFFRIN TOWNSHIP XK1-FIELD MARKED on 11/14/25 at 10:04 AM."</p> <p>AVR for Tredyffrin listed the project as over 1,500 ft and over \$400,000 with SUE D. No complex ticket or final design ticket was located by PA1call. Design documents do not include a final design serial number.</p> <p>Princeton Hydro was mailed and emailed a request for an AVR with additional information on 1/12/26. No AVR has been received.</p> <p>Recommended violations, penalties, and education:</p> <p>N. Abbonizio Contractors Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. -PUC compliance education is required for the excavators working onsite of this excavation or their replacements.</p> <p>Tredyffrin Township Section 6.1(1) – Failed to utilize sufficient quality levels of subsurface utility engineering or other similar techniques to properly determine the existence and positions of underground facilities when designing known complex projects having an estimated cost of (\$400,000) or more. Section 6.1(3) – Released a project to bid or construction before final design was complete. Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. -PUC compliance education is required for the person responsible for submitting AVR or their replacement.</p> <p>Princeton Hydro Section 4(2) – Designer failed to request the line and facility information prescribed by section 2(4) from the One Call System not less than ten nor more than ninety business days before final design is to be completed. Section 4(2.5) – Failed to comply with all requests for information by the commission relating to the commission's enforcement authority under this act within 30 days of receipt of request. Section 4(8) – Designer failed to submit an Alleged Violation Report through the One Call System within 30 business days of being notified or aware that a violation of this act may have been committed. -PUC compliance education is required for the designer(s) who worked on this project or their replacement(s).</p>	
60470	<b>Facility Owner:</b> FRANKLIN TOWNSHIP	<u>On 11/18/2025 12:36:00 PM at 101 CAROUSEL DR, MURRYSVILLE MUNIC, WESTMORELAND</u> On	<b>Beaver Jack Tree Service: \$750.00</b>

Case Number	Stakeholders	Summary	Violations & Recommendation
	MUNI SANITARY AUTH <b>Contractor/Excavator:</b> Beaver Jack Tree Service	<p>5/12/26 the DPC voted to accept DPIs recommendation and add \$250 for No Show for Beaver Jack Tree Service. 5(22) Added \$250 for now show. \$500 + \$250 is \$750. *****</p> <p>This non-damage incident occurred on November 18th, 2025, at 12:36pm on 101 Carousel Drive, Murrys ville Municipality, Westmoreland County.</p> <p>An emergency ticket was placed for a non-emergency situation, as described in Act 127 of 2024.</p> <p>Franklin Township Municipal Sanitation Authority's Alleged Violation Report states, "Tree trimming contractor filed an emergency one call for stump grinding. The work to be performed does not meet the requirements for an emergency (no threat to life, equipment or the environment). I called the contractor to educate them to the rule."</p> <p>Emergency ticket 20253221869: Location Information EXISTING MAPLE TREE IN FRONT YARD. Equip Type--[STUMP GRINDER].</p> <p>Google streetview shows multiple trees in the front yard.</p> <p>Violation:</p> <p>Beaver Jack Tree Service  Section 5(22) – Excavator provided a misrepresentation of an emergency excavation, subject to an administrative penalty imposed under section 7(10). 20253221869. PUC compliance education is required for the excavators working onsite of this excavation or their replacements.</p>	Section 5(22) 1st Offense \$750.00
60528	<b>Facility Owner:</b> Columbia Gas <b>Contractor/Excavator:</b> Graziani Construction <b>Project Owner:</b> Pennsylvania American Water (PAWC)	<p><u>On 11/19/2025 12:00:00 PM at 908 OAK ST, NEW CASTLE CITY, LAWRENCE</u> On May 12th, 2026 the Damage Prevention Committee voted on Columbia Gas' violations to keep all violations but remove the penalty for 2(10) and 2(11). Education was also removed. *****</p> <p>Graziani Construction provided additional information - violation removed.  Columbia Gas disputing.  *****</p> <p>The incident occurred on 11/19/2025, at 12:00 PM, on 908 Oak St, in New Castle City, Lawrence County.</p> <p>A gas line was damaged. Columbia Gas did not mark the lateral connection to the main, and did not submit an AVR, even after a request was sent.</p> <p>Columbia Gas is the facility owner. An Alleged Violation Report (AVR) was not filed as of 01/06/2026 and an AVR request was sent the same day. Additional information was requested on their attendance to the complex project meeting. Columbia did email on this case stating it was a customer owned line that was damaged, but never provided any additional information to verify that statement, and did not enter an AVR. Images show they marked their main and lateral connection 20+ feet away from the damage. No lateral</p>	<p><b>Columbia Gas: \$250.00</b>  Section 2(5)(i.1) 1st Offense \$250.00</p> <p>Section 2(10) 2nd Offense \$0.00</p> <p>Section 2(11) 1st Offense \$0.00</p> <p><b>Graziani Construction: \$0.00</b></p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>mark is shown to indicate the connection to Columbia Gas' main where the damage occurred, and Columbia was asked to provide their markout images showing this lateral was marked, which they did not provide. A wire appears beside the damaged gas line in the images but no confirmation if it is a tracer wire or not.</p> <p>Graziani Construction is the excavator. Their AVR states, "EXCAVATOR STRUCK GAS SERVICE LINE @ 908 OAK STREET THAT WAS MISMARKED BY 23.5FT. I ADDED 3 PICTURES OF THE EVENT TO THIS AVR REPORT."</p> <p>Pennsylvania American Water is the project owner and designer. Their AVR states, "Graziani Construction struck a gas service line @ 908 Oak St that was mismarked by 23.5ft". Graziani damaged a gas line while using mechanized equipment.</p> <p>Violations:  Columbia Gas -  Section 2(5)(i.1) – Failed to locate an actually known facility's point of connection to its facilities.  PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).  Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner's lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work.  Section 2(11) – Facility Owner failed to comply with all requests for information by the Commission relation to the Commission's enforcement authority under this act within thirty days of the receipt of the request.  PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement.</p> <p>Excavator - Graziani Construction:  Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner's facilities in the construction area.  PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements.</p>	
61332	<b>Facility Owner:</b> PECO <b>Contractor/Excavator:</b> DANELLA <b>Project Owner:</b> PECO Placeholder <b>Other:</b> Radnor Township <b>Other:</b> Verizon	<u>On 11/25/2025 11:20:00 AM at 208 SAINT DAVIDS CT, RADNOR TWP, DELAWARE</u> On 5/12/26 the DPC voted to accept DPIs recommendations for Radnor Township. **** Radnor Township is disputing with the township ordinance. ***	<b>PECO: \$500.00</b> Section 2(5)(i) 1st Offense \$500.00  <b>DANELLA: \$1,000.00</b> Section 1.1 1st Offense \$1,000.00  <b>Radnor Township: \$250.00</b> Section 2(5)(i.1) 1st

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Incident occurred on November 25th, 2025, at 11:20am on 208 Saint Davids Court, Radnor Township, Delaware County.</p> <p>A gas line was damaged.</p> <p>PECO's Alleged Violation Report (AVR) states, "On November 25th, 2025, Danella was working for PECO to install a new service when they struck an existing 1-inch gas service. The damaged service was approximately 24 ft off the marks. The foreman had spotted the existing service at the riser and assumed from the direction the service looked to be headed, it was on the mark and would not be in conflict with the installation of the new service. Danella also started before the lawful start date of 11/26/2025." AVR noted 911 as being notified.</p> <p>Danella's AVR states, "November 25th. 2025 at 12:00 PM on 208 Saint Davids Court in Wayne, Pa - a Danella gas crew was plowing in an upgrade gas service from 1" plastic to 1 ¼". The crew had 1- Call responses and all utilities were marked out. While plowing in the service the crew made contact with a mismarked 1-inch plastic gas service. The path for the new service installation had been established by the onsite PECO Inspector. The Danella crew had previously contacted the PECO inspector to confirm the location of the service and were instructed to follow the path where the damage resulted."</p> <p>Ticket 20253251849 had a lawful start date of 11/26/25, and the damage occurred on 11/25/25. Verizon did not respond, and Radnor Township indicated that they did not mark the point of connection to sewer laterals. Please see ticket responses for Radnor Township.</p> <p>Recommended violations, penalties, and education:</p> <p>Danella Section 1.1 – Excavator did not begin within legal timeframe. PUC compliance education is required for the excavators working onsite of this excavation or their replacements.</p> <p>Verizon Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20253251849. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p> <p>Radnor Township Section 2(5)(i.1) – Failed to locate an actually known facility's point of connection to its facilities. 20253251849. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p> <p>PECO Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.</p>	<p>Offense \$250.00</p> <p><b>Verizon: \$2,000.00</b> Section 2(5)(v) Subsequent \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		20253251849. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).	
61067	<p><b>Facility Owner:</b> Peoples Gas Company  <b>Contractor/Excavator:</b> M OHERRON COMPANY  <b>Project Owner:</b> PEOPLES PLACEHOLDER  <b>Designer:</b> PEOPLES PLACEHOLDER  <b>Other:</b> Wilkinsburg Borough</p>	<p><u>On 12/4/2025 11:45:00 AM at GAYWOOD DR, WILKINSBURG BORO, ALLEGHENY</u> On 5/12/26 the DPC voted to accept the violations but drop the penalties by 50% each.  2(4) - \$250 with 50% reduction is \$125.  2(5)(v) - \$500 with 50% reduction is \$250.  2(5)(v) - \$500 with 50% reduction is \$250.  2(5)(viii) - \$500 with 50% reduction is \$250.</p> <p>***  Wilkinsburg Boro is disputing.</p> <p>Please see Gaywood complex sign in sheet.</p> <p>****  Incident occurred on December 4th, 2025, at 11:45am, along Gaywood Drive, Wilkinsburg Boro, Allegheny County.</p> <p>A gas line was damaged while saw cutting.</p> <p>Peoples Gas Company's Alleged Violation Report (AVR) states, "M O'Herron working for Peoples Gas struck and damaged a Peoples Gas service line. The line was 4 inches deep and M O'Herron was removing the hard surface with a backhoe."</p> <p>M. O'herron's AVR states, "M. O'Herron Co sawcutting pavement on Gaywood Dr. to install new gas main for Peoples Gas Co. Saw cut through shallow gas service line crossing in asphalt running across road to 2500 Gaywood. Sawcut service line was 3' from marked crossing point on road."</p> <p>Images show that the line was not marked within the tolerance zone. AVR notes that 911 was notified.</p> <p>Violations:</p> <p>Peoples Gas Company  Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. 20253212957.</p> <p>Wilkinsburg Boro  Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20252370728.  PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).  Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20253212972. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).  Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20253212957. PUC compliance education is</p>	<p><b>Peoples Gas Company:</b>  <b>\$1,000.00</b>  Section 2(5)(i) 2nd Offense \$1,000.00</p> <p><b>Wilkinsburg Borough:</b>  <b>\$875.00</b>  Section 2(4) 1st Offense \$125.00</p> <p>Section 2(5)(v) 1st Offense \$250.00</p> <p>Section 2(5)(v) 1st Offense \$250.00</p> <p>Section 2(5)(viii) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).            Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20253111077. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).</p>	
61391	<p><b>Facility Owner:</b> Columbia Gas  <b>Contractor/Excavator:</b> Barrasso Excavation  <b>Project Owner:</b> Abbottstown Paradise JSA  <b>Other:</b> CS DAVIDSON INC  <b>Other:</b> Hamilton Township Adams County  <b>Other:</b> Met-ed / Firstenergy</p>	<p><u>On 12/11/2025 2:05:00 PM at 6895 York Road, BERWICK TWP, ADAMS</u> Violations for Met Ed, Columbia Gas, and Barrasso Excavating were removed by the Damage Prevention Committee on 5/12/2026.        *****        Met Ed is disputing - no documentation provided that the excavator approved late mark out.        Columbia Gas is disputing.        Barrasso Excavating is disputing - no additional information was provided.        *****        The incident occurred on 12/11/2025, on 6895 York Rd, in Berwick Twp, Adams County.</p> <p>A gas line owned by Columbia Gas was damaged. The facility and 911 were contacted by the excavator.</p> <p>Columbia Gas is the facility owner. Their Alleged Violation Report (AVR) states, “Barrasso Excavation Inc was performing a sewer replacement project, and was working to remove the hard surface when they detected a gas odor. A crew member immediately contacted 911 and Columbia Gas. Columbia Gas responded promptly, investigated the situation, and upon exposing the gas main, discovered a gouge in a 2-inch main that caused a leak. The area was made safe, and repairs were completed. Damage Prevention met onsite with Barrasso to review the steps leading up to the damage. The investigation determined that the damage occurred when the crew removed the old sewer pipe, the broken sewer pipe had impacted and damaged the unexposed gas main.”</p> <p>Barrasso Excavation is the excavator. Their AVR states, “We were digging in the shoulder of Lincoln Hwy. near Bridgeview Dr. removing 4" Ductile iron pipe for replacement of 6" HDPE pipe in same trench as we were digging and removing the existing 4" sewer pipe it went out of our ditch and lost visual on the pipe, we thought it continued out of trench following the marks provided on the ground by the sewer department. As we were digging further per installation design and plans with track hoe, approximately 14 feet under and behind our machine in unexcavated material we came in contact with the existing 4 " , 8' off sewer marks, pipe broke later to be determined the existing force main, and it resulted in damage to an existing 2" gas main owned by Columbia Gas. We were approximately 14 Feet from gas line marks on road and hadn't removed the blacktop within tolerance zone of gas main. Columbia gas was negligent of pipe separation. (less than 2") during their installation of NEW gas main installed in year of 2024. We called</p>	<p><b>Columbia Gas: \$0.00</b></p> <p><b>Barrasso Excavation: \$0.00</b></p> <p><b>Hamilton Township Adams County: \$1,500.00</b>        Section 2(5)(vii) 1st Offense \$1,000.00</p> <p>Section 2(5)(v) 1st Offense \$500.00</p> <p><b>Met-ed / Firstenergy: \$0.00</b></p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>911 and Notified Columbia gas of incident. We believe if the sewer department locate lines would have been correct the incident may have been prevented. Barrasso in not responsible for the damage to the gas line due to incorrect marking of existing 4" sewer line.”</p> <p>Abbottstown Paradise Joint Sewer Auth is the project owner. Their AVR states, “During excavation replacing APJSA sewer force main, Barrasso encountered an unmarked gas service. Bill Shupe, Columbia Gas was notified. Gas service repaired.”</p> <p>CS Davidson Inc is the designer. Their AVR has no summary.</p> <p>Images submitted show the sewer and gas marks prior to excavation. The gas marks are accurate and the line is within the tolerance zone of the marks. The sewer marks are not visible in the damage images, but in the mark out images it shows the manhole cover and marks indicating the direction of the line. The sewer line that damaged the gas line was marked, but it’s exact distance from the marks to the damage cannot be determined based on images submitted. Barrasso Excavation did not locate the marked gas line, that run perpendicular to the marked sewer line, prior to removing the sewer line, which is what caused the damage to the gas line.</p> <p>Ticket #20253452338 New – Excavation– Emergency was entered on 12/11/25 at 3:03 PM. Hamilton Township Adams County did not respond.</p> <p>Ticket # 20253000356 New – Excavation – Routine had a response due date of 10/31/2025. Columbia Gas responded “Conflict” on 10/28/2025, and “Field Marked” on 11/6/2025. Metropolitan Edison Co/Firstenergy responded “Scheduled Date” on 10/31/2025 and “Field Marked” on 11/3/2025. No documentation was provided that the excavator approved the late markouts. Hamilton Township Adams County did not respond to the ticket.</p> <p>Violations:  Excavator - Barrasso Excavation:  Section 5(6)(ii) – Excavator failed to provide support and mechanical protection for known facility owner’s lines at the construction work site.  Section 5(3) – Excavator failed to preserve mark-outs or request a remark.  PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements.</p> <p>Facility - Columbia Gas:  Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket # 20253000356  PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).  Facility (Other) - Metropolitan Edison Co/Firstenergy</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket # 20253000356 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).</p> <p>Facility (Other) - Hamilton Township Adams County Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket #20253452338</p> <p>Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket # 20253000356 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).</p>	
61333	<p><b>Facility Owner:</b> First Energy - PENNSYLVANIA ELECTRIC CO  <b>Contractor/Excavator:</b> PLUG UTILITIES  <b>Project Owner:</b> VERIZON  <b>Other:</b> BREEZELINE  <b>Other:</b> PAINT TOWNSHIP CLARION COUNTY  <b>Other:</b> WINDSTREAM</p>	<p>On 12/16/2025 12:00:00 PM at B Lane, PAINT TWP, CLARION Paint Township Clarion County did not attend the Damage Prevention Committee meeting on 5/12/2026. The DPC voted to keep their violation and add \$250 for not attending the meeting.  *****  Paint Township disputing  *****  The incident occurred on 12/16/2025, at 12:00 PM, on B Lane, in Paint Twp, Clarion County.</p> <p>An electrical line owned by Pennsylvania Electric Co was damaged. A damage emergency ticket was placed by Plug Utilities.</p> <p>Pennsylvania Electric Co is the facility owner. Their Alleged Violation Report (AVR) states, “On November 4, 2025, Plug Utilities, “Excavator,” submitted POCs Routine Ticket 20253080472 to install conduit at 13 B Lane, Paint Township, Clarion County, Pennsylvania. On December 16, 2025, Penelec was notified of an outage at this location. USIC, Penelec’s Contract Locator, investigated and determined that the Excavator damaged an accurately marked secondary service line. The root cause of the damage was the Excavator failed to use prudent techniques within the tolerance zone.”</p> <p>Plug Utilities is the excavator. Their AVR states, “While installing conduit on B LN, the crew struck an unmarked power cable line (unknown utility owner). The crew was digging about 30in deep when line was hit. Site of damage and loss of power was at 13 B LN. CLARION COUNTY, PAINT TWP.”</p> <p>Verizon is the project owner and listed as the project owner on the 2 damage tickets for this incident. An AVR was not filed as of 02/03/2026 and an AVR request was sent the same day.</p> <p>Ticket # 20253432095 was an [UPDATE][EXCAVATION][ROUTINE] ticket placed on 12-9-2025, and renotified on 12-18-2025 at 6:29PM. On the original update ticket Pennsylvania Electric Co requested a meeting on 12-11-2025. All other responses</p>	<p><b>First Energy - PENNSYLVANIA ELECTRIC CO: \$750.00</b>  Section 2(5)(v.2) 1st Offense \$250.00</p> <p>Section 2(5)(v.1) 1st Offense \$500.00</p> <p><b>PLUG UTILITIES: \$750.00</b>  Section 5(20) 2nd Offense \$500.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p><b>VERIZON: \$1,000.00</b>  Section 6.1(7) 1st Offense \$1,000.00</p> <p><b>BREEZELINE: \$2,750.00</b>  Section 2(5)(v.2) 1st Offense \$250.00</p> <p>Section 2(5)(v.1) 1st Offense \$500.00</p> <p>Section 2(5)(vii) 1st Offense \$1,000.00</p> <p>Section 2(5)(vii) 1st Offense \$1,000.00</p> <p><b>PAINT TOWNSHIP CLARION COUNTY: \$500.00</b>  Section 2(5)(v.2) 1st Offense \$500.00</p> <p><b>WINDSTREAM: \$750.00</b>  Section 2(5)(v.2) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>occurred after the damage, which would indicate that the lines were not marked.  The renotify information states, “ATTN BREEZELINE WINDSTREAM AND PENELEC CALLER HAS REQUESTED MARKINGS MULTIPLE TIMES FOR THIS SITE AND THE SITE IS STILL UNMARKED. YOUR UG LINES ARE BEHIND THE UNITS. THERE IS SNOW ON THE GROUND SO CALLER HAS USED FLAGS TO OUTLINE THE WORK AREA. OTHER UTILITIES HAVE MARKED THEIR LINES BUT CREW IS STILL WAITING ON YOUR MARKINGS. PLEASE VERIFY INVOLVEMENT GO TO THE SITE TO MARK LINES AND UPDATE YOUR RESPONSE ASAP SO THAT THE WORK CAN BEGIN. THANK YOU.”</p> <p>BREEZELINE – Did not respond to the renotify until 12/19/2025 at 9:10 AM with “Field Marked”  WINDSTREAM - Did not respond to the renotify until 12/19/2025 at 2:07 PM with “Clear”  PENELEC - Did not respond to the renotify until 12/19/2025 at 2:06 PM with “Field Marked”  PAINT TOWNSHIP CLARION COUNTY – Did not respond to Ticket #20253432095-000</p> <p>Ticket # 20253501484 New – Damage – Emergency was entered on 12/16/25 at 12:21 PM. Breezeline’s only response was entered on 1/14/2026.</p> <p>Ticket #20253501955 New – Damage – Emergency was entered on 12/16/25 at 2:27 PM. Breezeline’s only response was entered on 1/14/2026.</p> <p>The damage occurred on 12-16-2025. The first damage ticket was called in at 12:21PM. At that time there were 3 facilities that indicated on the routine ticket that was valid for the time and location, based on their responses, that they did not mark yet. No renotification was called in until 12-18-2025. The excavator proceeded to excavate after the locator for Pennsylvania Electric Co informed them the area was not fully marked via text message, as shown in provided documents.</p> <p>Violations:  Excavator - Plug Utilities :  Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area.  Section 5(20) – Excavator failed to renotify One Call of an unmarked or incorrectly marked facility upon arrival at a work site.  PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements.</p> <p>Facility – First Energy - Pennsylvania Electric Co –  Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket #20253432095-000</p>	<p>Section 2(5)(v.1) 1st  Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Ticket #20253432095-001  PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).  Project Owner – Verizon-  Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement.</p> <p>Facility(other) - BREEZELINE –  Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket #20253432095-000  Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Ticket #20253432095-001  Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket # 20253501484  Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket #20253501955  PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).  Facility(other) - WINDSTREAM –  Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket #20253432095-000  Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Ticket #20253432095-001  PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).  Facility(other) - PAINT TOWNSHIP CLARION COUNTY – Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Did not respond timely to Ticket #20253432095-000  PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).</p>	