



March 13, 2026

VIA E-FILING

Jonathan P. Nase

Direct Phone 717-773-4191

Direct Fax 215-372-2340

jnase@cozen.com

Matthew L. Homsher, Secretary
Pennsylvania Public Utility Commission
Commonwealth Keystone Building
400 North Street
Harrisburg, PA 17120

Re: McCloskey v. Hidden Valley Utility Services, L.P. (Water and Wastewater Divisions) and Pennsylvania Public Utility Commission v. Hidden Valley Utility Services, L.P. (Water and Wastewater Divisions); Docket Nos. C-2014-2447138, C-2014-2447169, R-2018-3001306 and R-2018-3001307

Report of Compliance Pursuant to 52 Pa. Code § 5.591 – Required Reports for 2025

Dear Secretary Homsher:

In compliance with the Settlement Agreement approved by the Pennsylvania Public Utility Commission by Order entered on December 21, 2023 at the above-referenced dockets, enclosed please find:

1. The Company's customer complaint logs, as required by Paragraph 52 of the Joint Petition for Settlement filed on May 25, 2023 (the "Settlement").
2. A report regarding operation and maintenance activities for 2025, as required by Paragraph 55 of the Settlement.

Additionally, Paragraph 56 of the Settlement Agreement provides:

If requested by the Hidden Valley Foundation's Board of Directors, HVUS will meet with representatives of the Hidden Valley Foundation's Board of Directors, virtually or in-person, at least once per calendar year, from 2023 through December 31, 2023.

The President of HVUS met with the Hidden Valley Foundation's Board of Directors, as well as the homeowners in Hidden Valley, on January 24, 2025.

Copies of this filing have been served as shown on the enclosed Certificate of Service.

Matthew L. Homsher, Secretary
March 13, 2026
Page 2

Respectfully submitted,

COZEN O'CONNOR



By: Jonathan P. Nase
Counsel for *Hidden Valley Utility Services, L.P.*

JPN
Enclosures
cc: Per Certificate of Service

**BEFORE THE
PENNSYLVANIA PUBLIC UTILITY COMMISSION**

Tanya J. McCloskey, Acting Consumer Advocate	:	
	:	
	:	Docket Nos. C-2014-2447138
v.	:	and C-2014-2447169
	:	
Hidden Valley Utility Services, L.P. (Water and Wastewater Divisions)	:	
	:	
and	:	
	:	
Pennsylvania Public Utility Commission	:	
	:	
	:	
v.	:	Docket Nos. R-2018-3001306
	:	and R-2018-3001307
	:	
Hidden Valley Utility Services, L.P. (Water and Wastewater Divisions)	:	
	:	

CERTIFICATE OF SERVICE

I hereby certify that I have this day served a true copy of the foregoing **Report of Compliance** upon the parties, listed below, in accordance with the requirements of 52 Pa. Code § 1.54 (relating to service by a party).

VIA E-MAIL AND FIRST CLASS MAIL:

Darryl A. Lawrence, Esq.
Consumer Advocate
555 Walnut Street
Forum Place, 5th Floor
Harrisburg, PA 17101-1923
ra-OCA@paoca.org
Counsel for *Office of Consumer Advocate*

Scott Granger, Esq.
Joanna Toft-Funk, Esq.
Bureau of Investigation and Enforcement
Pennsylvania Public Utility Commission
400 North Street
Harrisburg, PA 17120
sgranger@pa.gov
jtoftfunk@pa.gov
Counsel for *Bureau of Investigation and Enforcement*

Sharon Howard-Frieri
P.O. Box 4126
1174 Gristmill Court
Hidden Valley PA 15502
sharonhoward.frieri@yahoo.com

Robert J. Kollar, CPA and
Kellie A. Kuhleman
1374 Langport Dr.
Pittsburgh, PA 15241
bob@kkacpas.com

DATED: March 13, 2026



Jonathan P. Nase, Esquire
Counsel for *Hidden Valley Utility Services, L.P.*

Hidden Valley Utility Services LP

2025

Customer Complaints – Water & Sewage

1/11/25	OHV209	No water. Customers service line froze. No leaks. Curb stop operates.
1/21/25	SW2314	No water. Customers service line froze. No leaks. Curb stop operates.
1/27/25	SV5046	Answering service called. E-1 pump station breaker kicked. New breaker and pump plug replaced.
5/19/25	SF1617	Dirty water. Investigation found leak at 1627 curb stop.
6/10/25	SV5322	Dirty water. Two leak repairs 6/8/25 & 6/9/25. Flushed inside bldg.

HIDDEN VALLEY UTILITY SERVICES

MONTHLY REPORT 2025

JANUARY

Pressure reducing stations checked

Pump stations checked

Ski Lodge PRS installed new CRD on 2" PRV

Phone dailer battery replaced.

Leak repair 1735 main tap.

Leak repair 1737 curb and main tap.

Installed new 3 phase heater #1 in water bldg.

Frozen line OHV 209. Curb stop turns, frozen to house.

4 seasons PRS rebuilt CRD

SW 2314 frozen, curb stop turns, frozen in house.

Ski Lodge PRS replaced line on 2" PRV

LKV191 leak inside, cannot find curb stop. Under deck?

Leak repair 1722 curb stop.

New breaker install North Summit pump station Pump #2

Replaced plug Pump #2 North Summit pump station

Added float in North Summit pump station drywell for alarm of water in drywell.

FEBRUARY

Leak Repair HTS 504 main tap, added curb stop.

Pump stations checked.

4 seasons PRS checked for blockage in 3" PRV.

Pressure reducing stations checked

Leak repair HC 1150 at curb stop.

Leak repair SR 1926 insert at saddle.

New stators installed both pumps north summit E-1 station.

Leak repair ER 1855 and ER 1825 inserts at saddles.

Installed new hour meters north summit pump #2 and Hightop station.

Nighttime leak dection 1am – 6am

Leak repair ER 1816 insert at saddle.

Leak repair ER 1859 insert at saddle.

MARCH

Nighttime Leak Detection. 11pm – 6am

Leak repair SF 1601 insert at saddle.

SR 1927 added curb stop on main.

Replaced fittings main to service line SC 2010.

Installed meter pit HC 1240.

Repaired leak FW 1754 at curb stop buried under driveway.

New orifice installed 4 seasons PRS.

Sewerline on Beginers Slope jetted out.

Meter reads - 3 days.

Checked pumps stations.

APRIL

Checked pressure reducing stations

Pump stations checked

Leak repair HL 1555 insert at saddle

Replaced plug ends north summit pump station.

Yard repairs.

Leak repair HC 1165 insert ot saddle.

Leak repair HC 1176 curb stop.

Leak repair OHV 319 insert at saddle.

8" valve installed on main at post office.

Paving repairs.

Westridge pump station installed new lead float.

MAY

Installed new on/off float effluent pumps Plant #1

System Pressure survey.

System flushing 4 days.

Restore yards from water repairs

Leak repair SF1627 and SF 1926 curb stop inserts.

Plant 2 trimming

Unclogged service line SF 1626 caused by repairs.

Lagoon trimming, unclog fountain

Leak repair WR 1325, our service line.

Install wall fan EQ blower room

Leak detection

Pressure reducing station checks

Pump stations checked

JUNE

Leak Detection

ER 1809 off at curb, leak inside.

Yard repairs.

Leak repair SV 5008 main line split 5'.

Sprayfield samples

Meter reads

Pressure reducing station checks

Pump stations checked

Leak repair SV 5119 insert on main.

Leak inside SW 2322.

Leak repair HL 1572 insert on main.

JULY

Pressure reducing station checks

Pump stations checked

Leak inside SC 2105 off at curb.

Leak inside HL 1461 off at curb.

Leak inside HL 1572 off at curb.

Trimmed trees at water tank.

SR 1925 replaced main insert.

New discharge pipe and check valve installed Hightop pump station pump #2.

Yard repairs.

Installed aerator in lagoon.

Flow meter calibration at both Wastewater Plants

Raised manhole in North Summit bridge entrance.

EQ tank #2 air leak outside tank repaired.

Installed curb stop on main SR 1928.

AUGUST

Leak repair SV 5018 insert on saddle.

Leak detection

Leak repair SV 5010 curb stop.

Leak repair SR 1931 insert on main.

Pressure reducing station checks

Pump stations checked

Leak repair HL 1503 curb stop.

Plant #1 effluent pump #1 rebuilt and reinstalled.

Yard repairs.

Sprayfield samples.

Leak inside SV 5025 off at curb.

SEPTEMBER

New motor installed Plant #2 effluent pump #1.

Leak repair OHV 271 blow off curb stop.

Leak under slab HL 1534 shut off at curb. Homeowner notified to repair.

Meter reads.

Replaced 6" valve on sludge tank #2.

Pump stations checked.

Leak repair SR 1940 curb stop.

Leak repair SR 1911 insert on main.

Nighttime leak detection two nights 9/29 and 9/30.

OCTOBER

Repair sewerline LKV 20. Raised due to settling at clean out.

Leak repair SW 2330 insert on main.

New flywheel on ranger 500.

New teeth on excavator bucket.

Leak under slab VV 60 shut off at curb. Notified homeowner.

Installed new curb stops Gebhart 1456, 1457, 1458, 1459, and 1460.

Leak inside 1249 shut off at curb.

Leak repair SW 2301 curb stop.

Yard repairs.

Pumps stations checked.

Installed meter pit GT 106.

NOVEMBER

Contractor hit service line OHV 548. Found and shut off at curb.

Repaired leak on OHV PRS ¾" line.

Installed Plant 2 new chorine line.

Repaired leak HC 1155 curb stop.

Repaired leak ER 1801 main saddle.

Repaired leak HL 1484 curb stop.

Installed new gauges Westview PRS.

Repaired leak HVW 504 curb stop.

Pressure reducing stations checked.

Repaired leak FW 1752 curb stop.

Old blower room lights replaced with LED.

Pump stations checked.

DECEMBER

Well #2 new pump and 15hp motor installed.

Air release lines installed Filters 1 & 2.

Meter reads.

Leak repair SF 1610 curb stop.

Pump stations checked.

Leak repair PR 2703 main insert.

Leak repair SV 5038 main insert.

Leak repair SR 1915 curb stop.

Chlorine line replaced filter plant chlorine pump #2.

Pressure reducing stations checked.