

Notice to Plead
Reply to New Matter

CARMAN GEE

v.

FIRST ENERGY PENNSYLVANIA ELECTRIC COMPANY

Docket No. C-2026-3062017

Section 4 statement is inaccurate.

1. Electric power was disconnected to the service entrance before repairs were made. Work was performed by a licensed Electrician.
2. The power surge did not occur while the new panel box or the new service entrance was being installed. It occurred after power was restored to the new service entrance and panel box completion.
3. No further work was done to the home owners repairs after power surge occurred. Only the field work to the utility supply was performed.
4. There WAS a quality issue that the Penelec technician repaired and explained to the licensed electrician.
5. No further brownouts or surges occurred after utility field work was completed.

Carman D. Gee