



Pennsylvania Public Utility Commission

**Damage Prevention Committee Meeting Case List
March 11, 2025**

Omnibus Session

Case Number	Stakeholders	Summary	Violations & Recommendation
45000	<p>Facility Owner: Lancaster Airport Authority Contractor/Excavator: I B Abel Project Owner: PPL Electric Utilities Designer: ROUSSEY COMPANIES</p>	<p><u>On 2/20/2024 1:13:00 PM at AIRPORT RD. MANHEIM TWP. LANCASTER</u> On 1/13/2025 it was discovered that the Lancaster Airport Authority (LAA) stakeholder review notice was not sent. This was brought to the attention of the DPS, who notified MIS. The notice and an email to LAA was sent letting them know they have 30 days to dispute. ***** The incident occurred on 2/20/2024, at 1:13pm, at Airport Road, in Manheim Township, Lancaster County</p> <p>A Lancaster Airport Authority sewer and water line was damaged.</p> <p>PPL's alleged violation report (AVR) states "On Tuesday, 2/20/2024 at approximately 1308 a non-PPL contractor from I B Abel contacted an unmarked sewer lateral while digging with an auger to install a utility pole near PPL grid 40496S28911 at the Lancaster Airport, 500 Airport Road, Lititz, PA 17543 At approximately 1323, the same I B Able crew struck an unmarked water line with an auger while digging with an auger to install a utility pole near PPL grid 40513S28879. There were no reported injuries. It was unknow how many water or sewer customers were affected. The excavator had placed an Update Ticket earlier in the day and therefore was no longer working with a valid one call. As a result, I B Abel is in violation of digging before the legal start date on their most recent Update ticket. PPL Public Safety investigation determined that the damaged water and sewer lines were owned by the Lancaster Airport Authority, who were not listed on the tickets as a member of the PA One Call system as a facility owner. As a result, the damaged lines had not been marked. There was no physical sign of there being buried water and sewer lines in the vicinity of the excavation area. PPL Public Safety contacted the regional PA One Call liaison and requested they contact the Lancaster Airport to educate them on their obligation of being a member of the One Call system as a facility owner to prevent future incidents."</p> <p>On 5/6/2024 an AVR Request Letter was mailed and e-mailed to Lancaster Airport and I B Abel</p> <p>I B Abel's alleged violation report (AVR) states "An I.B. Abel distribution crew was tasked with digging and setting poles for a project on the Lancaster Airport. At approximately 12:00 pm on Tuesday February 20, 2024, an I.B. Abel crew was utilizing their boom mounted auger to excavate for a new pole at location</p>	<p>Lancaster Airport Authority: \$1,000.00 Section 2(1) 1st Offense \$250.00</p> <p>Section 2(1)(ii)(A) 1st Offense \$250.00</p> <p>Section 2(10) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>404595S28908, location 110 on the approved plans. The AP was operating the auger when it struck an active 4” PVC sanitary sewer line. The crew noticed plastic when they pulled the auger out of the hole. The closest sanitary sewer utility mark was approximately 6 feet to the east of the strike. There were two green dots painted on the driveway. The auger hole was approximately 10’ south of the driveway. The two green dots were marked approximately 6’ east of the sanitary sewer line strike. The crew notified their foreman immediately. The I.B. Abel foreman notified his General Foreman and then contacted PA 1 Call. The foreman reached out to the Safety Manager to inform him of the dig in. The crew performed a Stop/Time out and discussed the next steps. The foreman was in contact with PA 1 call and instructed the crew to move location 40513S28879, location 70 on the approved plans. The crew mobilized to this location and began auger excavation for a new pole. At approximately 1:00 pm, the AP, operating the auger truck, struck an unmarked 12” DI waterline. Water immediately flooded the hole and began running toward an existing swale. The closest waterline utility marker was approximately 100’ north of the strike. The utility flagging stopped north of the dig location and was not marked from that point to Airport Road, 500’+ to the south. PA One Call No. 20240390541 was completed. UGI was the only visible utility that was marked from Airport Road though the entire site. A private locating company was contracted to complete a private locate for the remainder of the utilities on site. In addition, the Lancaster Airport maintenance crew located their own sanitary sewer lines. A wire was inserted into the pipe for detection. Morgan-Keller, Inc. completed an emergency dig one call to complete both sewer and water repairs. The repairs began at approximately 7:45 am on Wednesday February 21, 2024."</p> <p>Lancaster Airport Authority is in violation of sections: Section 2(1) – Facility owner is not a member of One Call. Section 2(1)(ii)(A) – Failed to provide the One Call System with the counties, municipalities, and wards in which it lines are located. Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: Education Required; penalties applied</p>	
45535	<p>Facility Owner: PECO Contractor/Excavator: Utility Line Services Project Owner: Aqua Designer: TOTAL ENGINEERING AND CONSULTING LLC Other: DOWNINGTOWN</p>	<p><u>On 3/13/2024 10:00:00 AM at 137 S LLOYD AVE, DOWNINGTOWN BORO, CHESTER</u> The incident occurred on 3/13/2024, at 10:00am, at 137 S Lloyd Ave., Downingtown Boro., Chester County</p> <p>A PECO gas line was damaged. 911 was called.</p> <p>PECO's alleged violation report (AVR) states "On 3/13/2024 ULS was working for Aqua when they</p>	<p>Utility Line Services: \$1,000.00 Section 5(4) 2nd Offense \$1,000.00</p> <p>DOWNINGTOWN MUNICIPAL WATER AUTHORITY: \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	MUNICIPAL WATER AUTHORITY	<p>damaged a ½” Gas service with a powered excavator. The Gas Service was properly marked and ULS was digging using powered tools within the tolerance zone."</p> <p>Utility Line Services alleged violation report (AVR) states "While the crew was working in the area of 137 S. Lloyd Avenue to install a water main they damaged a marked gas service." Photos were submitted.</p> <p>Aqua's alleged violation report (AVR) states "Aqua Contractor Utility Line Services, while the crew was working in the area of 137 S Lloyd Avenue to install a water main they damaged a marked gas service."</p> <p>On 6/5/2024 an AVR Request Letter was mailed and e-mailed to Total Engineering and Consulting LLC.</p> <p>Total Engineering and Consulting LLC's alleged violation report (AVR) states "AQUA CONTRACTOR, UTILITY LINE SERVICES, WHILE THE CREW WAS WORKING IN THE AREA OF 137 LLOYD AVE TO INSTALL A WATER MAIN THEY DAMAGED A MARKED GAS SERVICE."</p> <p>Utility Line Services is in violation of sections: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: Penalties applied. (Excavator education was completed and passed by Utility Line Services on 07/08/2024.) Utility Line Services has prior violations of 5(4).</p> <p>DOWNINGTOWN MUNICIPAL WATER AUTHORITY is in violation of section: Section 2(4) – Failed to respond to designer’s request for information within 10 business days for Ticket 20231240352. Response was due 5/18/23. Responded "Field Marked" on 5/24/23. Recommendation: Education Required; penalties applied No prior violations found for DOWNINGTOWN MUNICIPAL WATER AUTHORITY.</p>	Section 2(4) 1st Offense \$250.00
47052	<p>Facility Owner: Columbia Gas of PA - North</p> <p>Contractor/Excavator: DJ Hannon and Sons</p> <p>Other: Buddy Services, LLC</p>	<p><u>On 5/7/2024 3:00:00 PM at 2229 BERGER ST, SHENANGO TWP, LAWRENCE</u> Incident occurred on May 7th, 2024, at 2229 Berger Street, Shenango Township, Lawrence County.</p> <p>A gas line was damaged.</p> <p>Columbia Gas Company's Alleged Violation Report (AVR) states, "DJ Hannon and Sons damaged a service tee at the gas main, lifting it off the gas main. They notified 911 and Columbia Gas when the damage occurred. Columbia Gas responded immediately to make the area safe and complete repairs. Marks were on the ground from a previous locate; ticket # 20241134018 for Buddy Services LLC. While DJ Hannon and Sons did not have their own valid PA One Call ticket, marks were accurate and visible at the job site."</p> <p>Columbia Gas submitted photos.</p>	<p>DJ Hannon and Sons: \$2,250.00</p> <p>Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(4) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$500.00</p> <p>Section 5(17) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>811 comments indicate D J Hannon and Son Plumbing and Heating has placed notifications with PA One Call in the past.</p> <p>DJ Hannon and Sons were mailed and emailed a request for an AVR on 8/16/24. No AVR has been received to date.</p> <p>Violations:</p> <p>DJ Hannon and Sons Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Education is required.</p> <p>Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Education is required.</p> <p>Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. Education is required.</p> <p>Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. Education is required.</p>	
47263	<p>Facility Owner: PECO An Exelon Company Contractor/Excavator: Diantonio and Bongiovanni Builders Project Owner: Triangle Property Group</p>	<p><u>On 5/9/2024 10:00:00 AM at 720 W 5TH STREET, CHESTER CITY, DELAWARE</u> Incident occurred on 5/9/2024 at 10am at 718 West 5th Street, Chester City, Delaware County.</p> <p>A gas line was damaged. No PA1 call.</p> <p>First AVR had Chester County, but google maps, property records, and pictures show that the house is in Delaware County.</p> <p>PECO's Alleged Violation Report (AVR) states, "On 05/09/2024 PECO received notification through the customer service line of a gas damage at 718 W. 5th Street. When PECO arrived Contractor, DiAntonio & Bongiovanni, was on site and admitted to being the General Contractor but denied that they were performing excavation work and indicated an unknown Contractor / Plumber had caused the damage and left the location. Investigation indicates that the Contractor was excavating to install a water line to the residence, without a PA One Call, and caused the damage while excavating with a backhoe. USIC inspected the location on 05/10/2024 and the same General Contractor, DiAntonio & Bongiovanni was on site. This damage occurred because the contractor failed to make a PA One Call." USIC report has the property as 720 W. 5th Street which correlates with the photos.</p> <p>Contractor has placed One Call notifications with PA One Call in the past. There are no tickets associated with this incident. Pictures from PECO show that the line was damaged.</p> <p>DiAntonio & Bongiovanni was mailed a request for an AVR on 9/24/2024. No AVR has been received to date.</p>	<p>Diantonio and Bongiovanni Builders: \$2,750.00 Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$500.00</p> <p>Section 5(17) 1st Offense \$250.00</p> <p>Triangle Property Group: \$500.00 Section 6.1(7) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Triangle Property Group, LLC was located as the property owner through county records. They were mailed a request for an AVR on 10/10/2024. No AVR has been received to date.</p> <p>Violations:</p> <p>DiAntonio & Bongiovanni Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Education is required. Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. Education is required. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. Education is required. Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. Education is required.</p> <p>Triangle Property Group, LLC Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 10 Business Days of a line strike. Education is required.</p>	
47346	<p>Facility Owner: PENNSYLVANIA AMERICAN WATER Contractor/Excavator: UGI Utilities</p>	<p><u>On 5/24/2024 7:00:00 AM at 3267 GREENWOOD AVE, SCRANTON CITY, LACKAWANNA</u> Incident occurred on May 24th, 2024 at 3267 Greenwood Avenue, Scranton City, Lackawanna County.</p> <p>A sewer line was damaged.</p> <p>Pennsylvania American Water Company's Alleged Violation Report (AVR) states, "U.G.I was doing a routine service renewal to 3267 Greenwood Ave on 5/24/2024 we received several complaints of homes backing up with raw sewage in their basements. We dispatched a CCTV crew & a Vactor crew to this area, upon inspection with the CCTV we had found out that a section of our main was collapsed causing the backups into these homes (3261, 3262, 3267 Greenwood Ave) We got damage control to do the remediation to these homes & a private sewer service to open their sewer service connections from inside the homes to the main line. We also had to get a contractor to repair the damage to the main line. U.G.I. hit our main sewer line causing a backup to the customers' homes."</p> <p>UGI's AVR states, "UGI is filing in response to a request from Investigator Cooper. UGI has no knowledge of any damage that was done to the PA America Waste Water facility in question. A photo sent to out claims department (attached) clearly shows fresh green paint in a PA American Waste Water contractor's patch which was put there several weeks after we worked in the area. The far left side of PAWW's photo shows faded green marks on the opposite side of the street. These older marks were the marks that were there when UGI did it's</p>	<p>PENNSYLVANIA AMERICAN WATER: \$500.00 Section 2(5)(i) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>work in the area. UGI would not have known of any sewer main in our area of excavation as it was not marked as being in our area of excavation. UGI also did not uncover any sewer mains while performing our work as the sewer main was deeper than our facility and unmarked."</p> <p>Picture from UGI supports their summary of events. Only sewer mark outs are on the opposite side of the street. A fresh sewer mark was placed on the new patch of asphalt after work was completed.</p> <p>Violation:</p> <p>PAWC Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.</p>	
47562	<p>Facility Owner: Windstream</p> <p>Contractor/Excavator: LINDY PAVING INC</p> <p>Project Owner: EQT Production</p> <p>Other: Jefferson Township Greene County</p>	<p><u>On 6/7/2024 11:00:00 AM at SHARPNACK HOLLOW RD, JEFFERSON TWP, GREENE</u> Incident occurred on June 7th, 2024, at 11am along Sharpnack Hollow Road, Jefferson Township, Greene County.</p> <p>A telecom line was damaged.</p> <p>Lindy Paving's Alleged Violation Report (AVR) states, "At 11:30am, Lindy Paving was excavating on Sharpknack Hollow Rd for shoulder stabilization. The operator was digging at approximately 18 inches deep when the spotter noticed a line had been severed. Work was stopped immediately and the foreman was notified. The foreman inspected the line and identified it as a telecom line. The line was unmarked and there were no flags or paint marks at least 100 feet in either direction. The foreman called to notify the 811 system and EQT. 811 was notified and a damage ticket was created. EQT safety department rep Nate Keppler arrived onsite and discussed the incident with the crew. Nate asked for a copy of the line strike AVR. USIC then later arrived and stated there was a "mix up" and as a result the line was unmarked. Lindy contacted Windstream and they stated a Work Order had been created. As of 1:30PM, the line was still not repaired. An excavation log and JSA for the day was completed before any work started for the day. The line was later repaired by Windstream at 4:30PM."</p> <p>Lindy's AVR was also submitted on behalf of EQT Production.</p> <p>Windstream and EQT Production were mailed and emailed a request for an AVR on 10/3/24.</p> <p>Violation:</p> <p>Windstream Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. 20241413087. Education is required.</p> <p>Jefferson Township Greene County</p>	<p>Windstream: \$1,000.00 Section 2(5)(i) 2nd Offense \$1,000.00</p> <p>Jefferson Township Greene County: \$1,500.00 Section 2(5)(v) 1st Offense \$500.00</p> <p>Section 2(5)(vii) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20241413087. Education is required.</p> <p>Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20241591619. Education is required.</p>	
47994	<p>Facility Owner: AQUA PENNSYLVANIA INC</p> <p>Contractor/Excavator: GENERAL ASPHALT AND PAVING</p> <p>Project Owner: PECO</p> <p>Other: Verizon</p>	<p><u>On 6/19/2024 12:00:00 PM at STATE RD, BRISTOL TWP, BUCKS</u> Incident occurred on June 19th, 2024, at 12pm along State Road, Bristol Township, Bucks County.</p> <p>A water line was damaged.</p> <p>Aqua's Alleged Violation Report (AVR) states, "STRAY CURRENT WAS AN ISSUE, WORKER SHOCKED WHILE TOUGHING COPPER LINE. WORKER WAS EMPLOYEE OF GENERAL ASPHALT. PECO CUT POWER TO HOME."</p> <p>No water mark outs are visible in the pictures.</p> <p>Email from Aqua confirms that the worker was shocked but did not receive medical treatment.</p> <p>PECO's AVR states, "General asphalt working for PECO was digging for a nat. gas service line when they struck the mismarked water service. GAP identified the water service, and the existing marks were not in conflict with their gas service, so they started to excavate."</p> <p>General Asphalt and Paving states, "Water service was not marked."</p> <p>Violation:</p> <p>Aqua Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.</p> <p>Verizon Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20241712425 Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20241712454 Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20241650225</p>	<p>AQUA PENNSYLVANIA INC: \$500.00 Section 2(5)(i) 1st Offense \$500.00</p> <p>Verizon: \$6,000.00 Section 2(5)(vii) 3rd Offense \$2,000.00</p> <p>Section 2(5)(vii) 3rd Offense \$2,000.00</p> <p>Section 2(5)(v) Subsequent \$2,000.00</p>
48005	<p>Facility Owner: Peoples Gas Company</p> <p>Contractor/Excavator: PATINO CONSTRUCTION</p> <p>Project Owner: Comcast</p> <p>Other: Armstrong Communications</p> <p>Other: Consolidated Communications</p> <p>Other: First Energy Penn Power</p>	<p><u>On 6/19/2024 2:34:00 PM at 152 Tanglewood Dr, PINE TWP, ALLEGHENY</u> Penn Power accepted resolution. *****</p> <p>Incident occurred on June 19th, 2024, at 152 Tanglewood Drive, Pine Township Allegheny County.</p> <p>A gas line was damaged.</p> <p>Patino Construction's Alleged Violation Report (AVR) states, "Drill trainee was pulling back pipe and lifted too high and it caught the bottom of the gas line. 911 was called, peoples gas was called."</p>	<p>PATINO CONSTRUCTION: \$1,000.00 Section 5(4) 1st Offense \$500.00</p> <p>Section 5(11.2) 1st Offense \$500.00</p> <p>Comcast: \$12,500.00 Section 4(2) 2nd Offense \$2,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Comcast's AVR states, "Drill trainee was pulling back pipe and lifted too high and it caught the bottom of the gas line. 911 was called, peoples gas was called."</p> <p>Peoples Gas Company's AVR states, "On 6/19/2024, Patino Construction was working for Comcast to install Conduit along Tanglewood Drive in Wexford. Patino struck an accurately marked PNG 2" PL ML."</p> <p>Pictures show that the gas line was marked within the tolerance zone.</p> <p>No design tickets were placed by Comcast or a designer on behalf of Comcast.</p> <p>Violations:</p> <p>Patino Construction Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Education is required. Section 5(11.2) – When using Horizontal Directional Drilling (HDD), Excavator failed to utilize the best practices published by the HDD Consortium. Education is required.</p> <p>Comcast Section 4(2) – Designer failed to request the line and facility information prescribed by section 2(4) from the One Call System not less than ten nor more than ninety business days before final design is to be completed. Section 4(4) – Failed to prepare construction drawings to avoid damage to and minimize interference with facilities in the construction area. Section 6.1(3) – Released a project to bid or construction before final design was complete. Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20241364367 Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20241701263 All fines have been raised to \$2500.00. Comcast has failed to show good faith by being delinquent on 9 invoices for DPC ordered fines despite having been sent notices for 6 of them. 0364624-007723 - \$500.00- Dunning notice sent 9/4/2024. 037738-007955 - \$1000.00 -Dunning notice sent 9/4/2024. 038284-007078 - \$1000.00 -Notice to be sent. 039698-007985 - \$4000.00 - Notice to be sent. 040354-007382 - \$750.00 - Dunning notice sent 9/4/2024. 043990-007863 - \$1500.00 - Dunning notice to be sent. 034870-006507 - \$500.00 - Dunning notice sent 7/2/2024 036682-007835 - \$1000.00 - Dunning notice sent 7/2/2024 041863-007102 - \$2250- Dunning notice sent 7/2/2024.</p> <p>Penn Power - First Energy Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20241364367 Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20241701263</p>	<p>Section 4(4) 2nd Offense \$2,500.00</p> <p>Section 2(5)(v) Subsequent \$2,500.00</p> <p>Section 2(5)(v) Subsequent \$2,500.00</p> <p>Section 6.1(3) Subsequent \$2,500.00</p> <p>Armstrong Communications: \$2,000.00 Section 2(5)(v) 2nd Offense \$1,000.00</p> <p>Section 2(5)(v) 2nd Offense \$1,000.00</p> <p>Consolidated Communications: \$5,000.00 Section 2(5)(v) 2nd Offense \$2,500.00</p> <p>Section 2(5)(v) 2nd Offense \$2,500.00</p> <p>First Energy Penn Power: \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Consolidated Communications Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20241364367 Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20241701263 All fines raised to \$2500. Consolidated is delinquent on DPC ordered fines for 6 invoices. 040354-007381 - \$1000.00 - Invoice created 4/19/24 - Dunning notice sent on 9/4/24. 040356-007405 - \$1000.00 - Invoice created 4/19/24 - Dunning notice sent on 9/4/24. 040461-007756 - \$1000.00 - Invoice created 4/19/24 - Dunning notice sent on 9/4/24. 042134-007629 - \$1000.00 - Invoice created 4/19/24 - Dunning notice sent on 9/4/24. 043627-007817 - \$500.00 - Invoice Created 6/18/24 - Dunning notice still to be sent on the date this case was approved. 006412-001520 Invoice created 8/5/2019 - Dunning notice sent on 10/24/2023.</p> <p>Armstrong Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20241364367. Education is required. Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20241701263. Education is required.</p>	
48118	<p>Facility Owner: Verizon PA LLC Contractor/Excavator: Kinsley Construction Project Owner: Columbia Gas</p>	<p><u>On 6/21/2024 9:00:00 AM at MOUNT OLIVET RD, HOPEWELL TWP, YORK</u> This occurred on 06/21/2024 at 9:00 AM, Mount Olivet Road, Hopewell Township, York County.</p> <p>Near miss of communication line owned by Verizon.</p> <p>Verizon - An AVR request letter was mailed and emailed on 07/09/2024. An AVR was received and states, "Verizon has contracted Stake Center to complete locates for this region. The POC tickets were updated by Stake Center "All Clear No Facilities" Verizon is aware of two cables in Felton that have been cut at the same place at 12030 Mt. Olivet Rd, between Apple St and Swamp Rd. There is a 100 pair cable with CZ1 prs 101-200 and a 300 pair cable with CZ1 prs 201-500. The excavator says he called PA1 and Verizon never marked, and that he called after the cable was hit and we never came out to check, so it's been buried. The 100 pair runs from L8011p6 to L8011p7, and the 300 goes from L8011p2 to L8011p7. I have two tickets today for elderly medical customers on Mont Rd with little to no cellular reception. Did you speak to the excavator, as the facility owner? I had no interaction with the excavator. My technician Dan Garber first reported to me that the cable was severed due to a locate that came back cleared no facilities Was the line marked within the tolerance zone? Lines were not marked. My tech did go out and mark an X where the excavator made the cut. That picture is attached Was the line marked within the required time frame? Lines were not marked because it was cleared no facilities Has this excavator hit two or more of your lines in a 6-month period? YES ALL CLEARED NO FACILITIES".</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Columbia Gas of PA submitted an AVR. Their AVR states, "Kinsley Construction, working on behalf of Columbia Gas for an infrastructure replacement project, encountered an unmarked pedestal within the scope of ticket # 20241630248. The ticket responses noted that all Verizon North facilities were clear, despite a visible pedestal that appeared operational. The foreman issued the first renotification to 811 on 06/20/2024, but Stake Center failed to respond within the allotted time. Consequently, work was halted to prevent potential damage. When Stake Center finally arrived the next day (06/21), markings were placed across our entire Right of Way (ROW) (see attached images for 06/21), obstructing the proposed gas main location. The Kinsley locator had proper equipment to locate the telecom lines, so she hooked up to verify their location, as the original markings seemed unreliable based on the pedestal's placement and the size of the 2" cable line. The Kinsley locator identified the telecom line 4 feet past the ROW stake. A subsequent renotification sent back to Verizon on 06/21/2024 also went unanswered. The scheduled date and time were pushed back from 06/21 to 06/22, and final field marks were completed on 06/24. Unfortunately, on 06/25, despite multiple re-notifications, Kinsley damaged an unmarked 2-inch telecom line (AVR2024JUL010007) on Mount Olivet. Verizon responded 'Clear: No Facilities' to Final Design Ticket # 20240222312." Photos were submitted.</p> <p>Kinsley Construction submitted an AVR. Their AVR states, "Kinsley Construction working on behalf of Columbia Gas came across and unmarked pedestal within the area of ticket 20241630248. The ticket response for that ticket stated that all Verizon north facilities were clear, despite the visible pedestal that appeared to be operational. The foreman issued the first renotification to 811 on June 20, 2024, but Stake Center failed to respond within the allotted time. Consequently, work was halted to prevent potential damage. When Stake Center finally arrived the next day (6/21), markings were placed across our entire Right of Way (ROW) (see attached images for June 21st), obstructing our proposed gas main location. We engaged an independent locator to verify the telecom lines, as the original markings seemed unreliable based on the pedestal's placement and the size of the 2" cable line. The independent locator identified the telecom line 4 feet beyond our designated Pink LOD Stakes outside of the current marks. Subsequent renotification went back to Verizon on June 21, 2024, also went unanswered. The scheduled date and time were pushed back from June 21 to June 22, and final field marks were completed on June 24. Unfortunately, on June 25th, despite multiple notifications, Kinsley accidentally damaged an unmarked 2-inch telecom line (Ticket 20241771005) on Mount Olivet."</p> <p>No violations assigned on this case. Violations and penalties for non/ late response to tickets are on case 048175.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
48084	<p>Facility Owner: National Fuel Gas Contractor/Excavator: D and T Concrete Project Owner: Homeowner</p>	<p><u>On 6/25/2024 8:00:00 AM at 401 COLLEGE ST, YOUNGSVILLE BORO, WARREN</u> The incident occurred on Tuesday, June 25, 2024, at 401 College Street, in Youngsville Borough, Warren County.</p> <p>A National Fuel Gas (NFG) line was damaged.</p> <p>NFG reported that D and T Concrete failed to use prudent techniques within the tolerance zone, and stated that the excavator hit a properly marked gas service line. D and T stated, hand dug a test hole to find the pipe, two spotters on bucket, and while digging, 2 teeth on the bucket stuck out further, and I clipped the line when pulling spoils away from area. I heard gas, shut the excavator off, called 911 and informed the Homeowners of what happened.</p> <p>On Tuesday, September 17, 2024, letters were mailed requesting Alleged Violation Report's (AVR) from D and T Concrete and from the Homeowner. D and T submitted an AVR on 9/21/2024. The Homeowner called on 9/24/2024, and said they don't have information, and they weren't home at the time.</p> <p>*D and T Concrete is in violation of sections: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. Recommendation: Education Required and Penalties Applied. For 5(16), penalty reduced by 50% from \$500.00 to \$250.00</p>	<p>D and T Concrete: \$750.00 Section 5(4) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$250.00</p>
48098	<p>Facility Owner: AQUA PENNSYLVANIA INC Contractor/Excavator: INFRA SOURCE Project Owner: PECO AN EXELON COMPANY</p>	<p><u>On 6/26/2024 11:00:00 AM at 2936 CASTLE DR, BENSALEM TWP, BUCKS</u> The incident occurred on Wednesday, June 26, 2024, at 2936 Castle Drive, in Bensalem Township, Bucks County.</p> <p>A water line was damaged.</p> <p>Aqua PA stated that their line was hit and damaged by InfraSource, and explained that the excavator never exposed the water mainline and shot a gopher causing a leak. The water main was flagged and offset marks were used. Aqua provide photos. PECO An Exelon Company, the project owner stated that the excavator never exposed the water mainline and shot a gopher causing a leak.</p> <p>On Wednesday, October 2, 2024, emails were sent to InfraSource; the contractor and to PECO An Exelon Company; the project owner, requesting Alleged Violation Report's (AVR). PECO submitted their AVR on 10/3/2024. InfraSource did not respond to the request and no AVR was submitted.</p> <p>*InfraSource is in violation of sections: 5(11.2) – When using horizontal directional drilling (HDD), Excavator failed to utilize the best practices.</p>	<p>INFRA SOURCE: \$1,000.00 Section 5(11.2) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. Recommendation: Education Required and Penalties Applied.</p>	
48656	<p>Facility Owner: UGI Utilities Contractor/Excavator: JF Kiely Construction Project Owner: UGI Utilities - Placeholder Other: AT&T Other: Comcast Cablevision Other: HARRISBURG CITY Other: PPL</p>	<p><u>On 7/22/2024 10:00:00 AM at 642 RADNOR ST, HARRISBURG CITY, DAUPHIN</u> AT&T had disputed due to a system issue. The penalty was reduced to zero and the violation was reduced from a second offense to a warning.</p> <p>PPL will be accepting the fine and violation.</p> <p>*****</p> <p>The incident occurred on 07/22/2024 at 10:00, at 642 Radnor Street, Harrisburg City, Dauphin County.</p> <p>A marked gas line that is owned by UGI Utilities, was damaged. 911 was called.</p> <p>UGI Utilities submitted an Alleged Violation Report (AVR). Their AVR states, "While digging to install a new gas service, contractor struck and damaged a correctly marked service tee." Photos were submitted.</p> <p>JF Kiely Construction submitted an AVR. Their AVR states, "Crew damaged a marked gas line with an excavator in front of 642 Radnor st."</p> <p>Violations:</p> <p>JF Kiely Construction - - Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: The penalty is applied. Education is required. JF Kiely Construction had 1 prior violation for 5(4).</p> <p>HARRISBURG CITY - - Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Emergency ticket 20242041441 had a response due date of 07/22/2024. HARRISBURG CITY OF responded 'CLEAR' on 08/05/2024. Recommendation: The penalty is applied. (Harrisburg City completed and passed the facility owner/ locator education on 07/29/2024.) Harrisburg City has 2 prior violations of 2 (5)(vii) from incidents in 2022.</p> <p>AT&T - - Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). Complex Project ticket 20240873492 had a response due date of 04/02/2024. AT&T did not respond. A copy of the sign in sheet was also submitted, which verified AT&T did not attend the meeting. Recommendation: Warning, no penalty. AT&T has had multiple prior violations of 2(5)(viii).</p>	<p>JF Kiely Construction: \$500.00 Section 5(4) 1st Offense \$500.00</p> <p>AT&T: \$0.00 Section 2(5)(viii) 1st Offense \$0.00</p> <p>Comcast Cablevision: \$250.00 Section 2(4) 1st Offense \$250.00</p> <p>HARRISBURG CITY: \$1,000.00 Section 2(5)(vii) 1st Offense \$1,000.00</p> <p>PPL: \$250.00 Section 2(4) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>PPL - - Section 2(4) – Failed to respond to designer’s request for information within 10 business days. Final Design ticket 20233470660 had a response due date of 12/28/2023. PPL responded 'CLEAR' on 01/04/2024. Recommendation: The penalty is applied. PPL has 1 prior violation of 2(4) for an incident in 2019.</p> <p>Comcast - - Section 2(4) – Failed to respond to designer’s request for information within 10 business days. Final Design ticket 20233470660 had a response due date of 12/28/2023. Comcast responded 'CLEAR' on 01/04/2024. Recommendation: The penalty is applied. (Comcast completed and passed the facility owner/ locator education on 07/25/2024.) Comcast has had multiple prior violations of 2(4).</p>	
50225	<p>Facility Owner: UGI Contractor/Excavator: Haugland Energy Group LLC Project Owner: PPL Designer: KATAPULT ENGINEERING</p>	<p>On 9/12/2024 12:00:00 AM at 1099 THROOP STREET, <u>DICKSON CITY BORO, LACKAWANNA</u> UGI disagrees and states that "The CGA language to does not require the use of the word ‘off’, it is used as an example in the visual portion of the Best Practices guide. UGI believes use of the word ‘to’ rather than ‘off’ fulfills the purpose of the marking as the arrows and lines were done to the visual standard. The violation has been withdrawn. ***** The incident occurred on 9/12/2024 at 1099 THROOP STREET, in DICKSON CITY Borough, Lackawanna County.</p> <p>A gas line was hit and damaged.</p> <p>UGI UTILITIES INC stated in their Alleged Violation Report (AVR) that “Excavator struck and damaged a correctly marked gas main while using an auger in the tolerance zone”. 911 was notified. 1 customer was affected. Pictures were provided.</p> <p>Haugland Energy Group LLC was emailed and mailed an AVR request letter on 11/01/2024, but investigation found that AVR2024SEP180011 was submitted. The dates did not match, but the incident was verified to be the same by PPL. Haugland stated in their AVR that “line crew was digging hole for new pole set using Auger truck, misread offset markings in yellow for UGI gas line, hand dug to approx. 24", felt area was safe to dig with Auger, began auguring. Shortly afterward, the line crew heard a hissing sound, called an All/Stop, removed auger from hole and noticed hit gas line. If more space is needed, attach additional pages or document”. Project cost was listed as <\$400,000. And level “C”” Subsurface Utility Engineering (SUE) was utilized. 911 was notified. Haugland Energy also submitted AVR2024NOV030001 and stated that “Crew did not understand offset markings. Believed markings showed gas line to be in the street. Hit 2" gas line with auger. Crew called 911, 811 then me. When I arrived UGI was on site had shut</p>	<p>UGI: \$0.00</p> <p>Haugland Energy Group LLC: \$1,000.00 Section 5(3) 1st Offense \$500.00 Section 5(4) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>the gas line off, first responders had returned to service. Pictures were provided.</p> <p>PPL was emailed and mailed an AVR request letter on 11/01/2024. On 11/01/2024 PPL sent an email stating they will investigate and submit an AVR. AVR was submitted with a date of 10/12/2024, but an email received on 11/08/2024 verified that the only incident they are aware of is the one on 9/12/2024. PPL stated in their AVR that “Haugland line crew was digging hole for new pole set using Auger truck, misread offset markings in yellow for UGI gas line, hand dug to approx. 24", felt area was safe to dig with Auger, began auguring. Shortly afterward, the line crew heard a hissing sound, called an All/Stop, removed auger from hole and noticed hit gas line. No pictures were provided.</p> <p>KATAPULT ENGINEERING was emailed and mailed an AVR request letter on 11/01/2024. AVR request letter was mailed with the incident date that PPL provided. On 11/09/2024 DPI sent an email to Katapult with the correction.</p> <p>Katapult Engineering sent an AVR which listed no project information. They summarized that “On 11/1/24 Katapult engineering was notified of an alleged PA 1Call violation that occurred. We completed and submitted the design 1call 20240590510 WR# 146220240228 on 2/28/2024. the design number and information were included on the construction prints for the crew. Pictures were provided.</p> <p>On 11/15/2024 DPI sent an email asking for the project information that was missed and if any below groundwork was detailed. An email received on 12/03/2024 read that "There were no Underground plans drawn out as the pole was to be replaced at its current location. Project Cost: \$10,391.15, Project Length: 25 ft radius from the pole location, Project Scope: Replace existing 40 ft pole with 45 ft pole.</p> <p>No SUE was used, as the construction contractor submits construction tickets prior to commencing the work.</p> <p>*****</p> <p>*Final Design ticket 20240590510 was requested by Katapult Engineering on 2/28/2024 to replace poles for new PPL facilities along Throop St., with a response due by 3/13/2024. All facility owners responded timely.</p> <p>*Ticket 20242423828 was requested by Haugland Energy on 8/29/2024, to replace poles for PPL with a response due by 9/03/2024. All facility owners responded timely.</p> <p>*Update Ticket 20242544666 was requested by Haugland Energy on 9/10/2024 stating that work had not yet started. No additional Mark outs are needed. The response was due by 9/12/2024. All facility owners responded timely.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>*Emergency Ticket 20242561774 was requested by Haugland Energy on 9/12/2024 at 12:07. All facility owners responded timely. *****</p> <p>Haugland Energy Group LLC is in violation of Section: Section 5(3) – Excavator failed to preserve mark-outs or request a remark. AVR from Haugland states that the crew misread the offset markings. The markings were not clearly / correctly annotated.</p> <p>5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Besides calling UGI or OneCall to clarify the offset markings, the UGI line was not daylighted and the excavator proceeded to dig. Recommendation: The penalty is applied. Education is required.</p>	
49990	<p>Facility Owner: PECO Contractor/Excavator: CONCRETE CUTTING SYSTEMS Project Owner: PECO Designer: ENTRUST Solutions Group Other: CARR AND DUFF Other: Lansdowne Borough Other: Upper Darby Township Other: Verizon, PA LLC</p>	<p><u>On 9/22/2024 9:00:00 PM at MARSHALL RD, UPPER DARBY TWP, DELAWARE</u> Incident occurred on September 22nd, 2024, at 9am along Marshall Roady, Upper Darby Township, Delaware County.</p> <p>A gas line was damaged.</p> <p>Carr and Duff's Alleged Violation Report submitted on behalf of Concrete Cutting Systems (AVR) states, "Tonight at 9:39PM 9/22/2024 concrete cutting services where saw cutting a trench for us along Marshall rd. Job # 240330. WO# 18037309. When the struck a gas service. The service line was touching the bottom of the concrete road base at 14" in depth. There was a service mark but it was 6' off of where they hit it. Peco Gas came out and opened the trench up and told us that is was put in at a improper depth to shallow and not our fault. Prior to Peco coming out the steps that were taken was I call 911 we Evacuated the businesses near the strike. Then called PA on call, I then called Karen K my Peco CM, Dan V my boss, then finally my safety department. The Hit number from PA One call is 20242660288. Peco Gas repair # is 19718057. Our one call number that we have for this job is 20242610536. And finally the one call number that the concrete cutting services where using is 20242602520."</p> <p>PECO's AVR states, "On 9/22/2024 Concrete Cutting Systems was cutting the roadway in the 7300 Block of Marshall Ln in Upper Darby for Carr and Duff to replace electrical conduit for PECO, when they cut through a 1" insert renew steel service to the above address. The marks were accurate to the prints but in reality, the service runs on a angle and the T is about 50' from that intersection. This print issue does not change the fact that the gas service was at a depth of about 15" in direct contact with the underside of the concrete roadway. This damage occurred because the service was installed too shallow underneath the road surface. 0 injuries, 1 Cust interrupted."</p> <p>Entrust Solutions Group's AVR states, "A PECO gas service was struck by excavator crew. The Contractor bid event was from approximately February to April 2024. Approximately \$2M is total of the project."</p>	<p>PECO: \$1,500.00 Section 2(5)(i) 3rd Offense \$1,500.00</p> <p>Lansdowne Borough: \$2,500.00 Section 2(4) 1st Offense \$2,500.00</p> <p>Upper Darby Township: \$7,500.00 Section 2(4) 1st Offense \$2,500.00</p> <p>Section 2(4) 1st Offense \$2,500.00</p> <p>Section 2(4) 1st Offense \$2,500.00</p> <p>Verizon, PA LLC: \$3,000.00 Section 2(4) Subsequent \$1,500.00</p> <p>Section 2(4) Subsequent \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Pictures show that the line was mismarked.</p> <p>Violations:</p> <p>PECO Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.</p> <p>Upper Darby Township Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20230612946. Education was due by 11/6/23. Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20230190753. Education was due by 11/6/23. Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20233472878. Education was due by 11/6/23. Upper Darby Township's was ordered to attend education by the DPC Augustu 9, 2023 for case 31076. Upper Darby was notified they had 60 days to attend. All violations raised to \$2500.00 for failure to comply with all DPC requirements.</p> <p>Lansdowne Borough Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20230190752. Education is required.</p> <p>Verizon Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20230190752. Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20230612946.</p>	
50166	<p>Facility Owner: PECO Contractor/Excavator: PACT CONSTRUCTION INC Project Owner: POTTSTOWN BORO/POTTSTOWN BORO MUNI AUTH Designer: HRG INC Other: Verizon</p>	<p><u>On 9/23/2024 8:00:00 AM at N HANOVER ST, POTTSTOWN BORO, MONTGOMERY</u> PECO submitted additional documentation. Violations withdrawn.</p> <p>*****</p> <p>The incident occurred on 9/23/2024 at 8:00 AM, on North Hanover Street, in Pottstown Borough, Montgomery County. The nearest intersection is East High Street.</p> <p>A gas line owned by PECO was damaged. 911 was called.</p> <p>PECO submitted an Alleged Violation Report (AVR). Their AVR states, "On 9/23/2024 Pact Construction was excavating for new water service at the above location when they struck and severed a 1/2" plastic gas service within the tolerance zone of the marks for the PA One Call Locate Request. 0 injuries, 1 Cust interrupted."</p> <p>PACT ONE LLC submitted an AVR. Their AVR states, "PACT One, LLC (PACT) while in the course of excavating for lead water service line replacements came into contact with and severed a mismarked PECO gas</p>	<p>PECO: \$0.00</p> <p>POTTSTOWN BORO/POTTSTOWN BORO MUNI AUTH: \$10,000.00 Section 2(5)(v) 1st Offense \$2,500.00 Section 2(5)(v) 1st Offense \$2,500.00 Section 2(5)(vii) 1st Offense \$2,500.00 Section 2(5)(vii) 1st Offense \$2,500.00 Verizon: \$1,000.00 Section 2(5)(v) Subsequent \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>service (photo attached). Service markings were crossed-out (x) and markings as painted were perpendicular to the sidewalk/roadway-service was actually in parallel with sidewalk/roadway.” Photos were submitted.</p> <p>POTTSTOWN BORO/POTTSTOWN BORO MUNI AUTH submitted an AVR. Their AVR did not include a summary.</p> <p>HRG INC submitted an AVR. Their AVR states, "While in the process of excavating for new water service line installation/lead service replacement at house #418 Lincoln Avenue, PACT One, LLC (PACT) pipe crews came into contact with and severed an "unmarked" PECO gas service. (photos attached)."</p> <p>Routine ticket 20242472916 with the work site of N HANOVER ST. Nearest Intersection--[EAST HIGH ST] Second Intersection--[KING STREET], had a response due date of 09/08/2024. The scheduled excavation date was 09/09/2024. PECO replied 'Scheduled Mark' on 09/06/2024, stating the lines would be marked by 09/10/2024 at 23:30. PECO responded 'Field Marked' on 09/24/2024 at 9:23 AM. (Damage to the line occurred on 09/23/2024.)</p> <p>The submitted photos show the service marking had an 'x' on it. The marking, as painted, did not match the direction of the gas line. Additionally, the damage occurred on 09/23/2024 at 8:00 AM and PECO had not yet marked their line in response to the two routine ticket requests.</p> <p>Violations:</p> <p>POTTSTOWN BORO/POTTSTOWN BORO MUNI AUTH –</p> <ul style="list-style-type: none"> - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Routine ticket 20242472781 had a response due date of 09/05/2024. POTTSTOWN BORO/POTTSTOWN BORO MUNI AUTH responded 'Field Marked' on 09/25/2024. - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Routine ticket 20242472916 had a response due date of 09/08/2024. POTTSTOWN BORO/POTTSTOWN BORO MUNI AUTH responded 'Field Marked' on 09/25/2024. - Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Emergency ticket 20242670648 had a response due date of 09/23/2024. POTTSTOWN BORO/POTTSTOWN BORO MUNI AUTH responded 'FIELD MARKED' on 09/25/2024. - Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Emergency ticket 20242670748 had a response due date of 09/23/2024. POTTSTOWN BORO/POTTSTOWN BORO MUNI AUTH responded 'FIELD MARKED' on 09/25/2024. 	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Recommendation: The penalty is applied. Education is required. Pottstown was ordered by the DPC to attend education on July 9, 2024, for case 34642. As of November 27, 2024, they failed to comply with all DPC instructions and have not attended the class. All fines raised to \$2500 for failure to comply with all DPC orders.</p> <p>Verizon – - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Routine ticket 20242472916 had a response due date of 09/08/2024. VERIZON PENNSYLVANIA LLC responded 'Field Marked' on 09/09/2024. Recommendation: The penalty is applied. Education is required.</p> <p>PECO –(withdrawn) - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Routine ticket 20242472916 had a response due date of 09/08/2024. PECO had responded scheduled mark by 09/10/2024, but the line was not 'Field Marked' until 09/24/2024. - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: The penalty is applied. Education is required.</p>	
50067	<p>Facility Owner: Peoples Gas Company Contractor/Excavator: FRANK J ZOTTOLA CONSTRUCTION INC Project Owner: Pittsburgh Water and Sewer (PWSA)</p>	<p><u>On 9/23/2024 9:00:00 AM at 1129 PENNSYLVANIA AVE, PITTSBURGH CITY, ALLEGHENY</u> Peoples provided additional pictures during the dispute phase that show the line was hit first within the tolerance zone. Violation and penalty are removed.</p> <p>****</p> <p>Incident occurred on September 23rd, 2024, at 9am at 1129 Pennsylvania Avenue, Pittsburgh City, Allegheny County.</p> <p>A gas line was damaged.</p> <p>Peoples Gas Company's Alleged Violation Report (AVR) states, "Frank J Zottola Construction working for Pittsburgh Water and Sewer doing lead line replacements struck and damaged a properly marked Peoples Gas service line."</p> <p>FRANK J ZOTTOLA CONSTRUCTION's AVR states, "While excavating for water service line work at 1129 Pennsylvania Ave, a gas line was struck. We located what was believed to be the marked gas service for 1129 Pennsylvania Ave. While excavating beside that gas service line, an unmarked gas service line was struck outside of the tolerance zone. 911, 811, and the gas company were contacted. The gas company repaired the line within an hour. No injuries."</p> <p>PWSA's AVR states, "While excavating for water service line work at 1129 Pennsylvania Ave, a gas line was struck. We located what was believed to be the marked gas service for 1129 Pennsylvania Ave. While excavating beside that gas service line, an unmarked gas</p>	<p>Peoples Gas Company: \$0.00</p> <p>Pittsburgh Water and Sewer (PWSA): \$1,000.00 Section 2(5)(v) 2nd Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>service line was struck outside of the tolerance zone. 911, 811, and the gas company were contacted. The gas company repaired the line within an hour. No injuries."</p> <p>Peoples' damage photo "1129 Pennsylvania 1" show that the line was mismarked.</p> <p>Violations:</p> <p>Peoples Gas Company Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.</p> <p>PWSA Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20242432161.</p>	
50254	<p>Facility Owner: Columbia Gas</p> <p>Contractor/Excavator: MICHAEL A FACCHIANO CONTRACTING INC</p> <p>Project Owner: Columbia Gas of PA - Central</p> <p>Designer: Columbia Gas of PA -</p> <p>Designer: TRC Companies</p> <p>Other: Dormont Borough</p> <p>Other: Northern Pipeline Company</p> <p>Other: Pittsburgh Water and Sewer (PWSA)</p> <p>Other: Verizon</p> <p>Other: Verizon Business</p>	<p><u>On 9/23/2024 11:00:00 AM at CROSBY, DORMONT BORO, ALLEGHENY PWSA</u> agrees to resolution. *****</p> <p>Incident occurred on 9/23/2024 at 11am along Crosby Avenue, Dormont Boro, Allegheny County.</p> <p>A gas line was damaged.</p> <p>Columbia Gas Company's Alleged Violation Report (AVR) states, "Michael Facchiano Contracting, Inc., completing restoration work on behalf of Columbia Gas after an infrastructure replacement project, was digging an 18" trench for the base of the concrete curb when the operator struck an accurately marked, 1" plastic gas service. The operator had already removed the hard service and proceeded to use the equipment within the tolerance zone, striking the gas facility. They notified 911 and Columbia Gas when the damage occurred. Columbia Gas responded immediately to make the area safe and capped the gas service, as it was set to be abandoned at the completion of the project. A root cause meeting was held on 09/24/2024 to review the events leading up to the damage. An after-action plan was created, which includes speaking to every crew on the job site, as well as an all-employee meeting with the local PA One Call Liaison and Columbia Gas Damage Prevention. The operator involved has been terminated."</p> <p>Michael A Facchiano Contracting's AVR states, "On Monday, September 23, 2024, Michael Facchiano Contracting, Inc. (MFC) was pouring concrete curb and sidewalk on Crosby Ave., in Dormont Borough. Also onsite, was a hydraulic excavator digging an 18" trench for the base of the concrete curb. The excavator operator was digging ahead of the concrete crew. While the crew was pouring the concrete curb and sidewalk, the on-site foreman was present and helping at the pour. Without direction or guidance, unbeknownst to the foreman, the excavator operator dug through the marked tolerance zone, striking the marked, active, low pressure, 1" orange PE gas line that formerly served 2958 Crosby Ave. Immediately after the gas line strike, the operator told a laborer that a gas line was struck and leaking. The laborer then went and told the on-site foreman that a gas</p>	<p>MICHAEL A FACCHIANO CONTRACTING INC: \$1,000.00 Section 5(4) 2nd Offense \$1,000.00</p> <p>Dormont Borough: \$500.00 Section 2(4) 1st Offense \$250.00</p> <p>Section 2(4) 1st Offense \$250.00</p> <p>Pittsburgh Water and Sewer (PWSA): \$0.00 Section 2(4) 3rd Offense \$0.00</p> <p>Section 2(5)(v) 2nd Offense \$0.00</p> <p>Verizon: \$3,000.00 Section 2(4) Subsequent \$1,500.00</p> <p>Section 2(4) Subsequent \$1,500.00</p> <p>Verizon Business: \$6,000.00 Section 2(4) Subsequent \$1,500.00</p> <p>Section 2(4) Subsequent \$1,500.00</p> <p>Section 2(4) Subsequent \$1,500.00</p> <p>Section 2(4) Subsequent \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>line was struck. The foreman immediately called 911. While the foreman was on the phone with 911, the operator took it upon himself to grab an adjacent form pin, cloth rag, vise grips and proceeded to plug the leaking gas line. ****Please note, the operator did this action with no direction from any MFC supervisor or employees.**** After the 911 Call was placed, the area was made safe. Columbia Gas representatives capped the gas line. Follow Up After Line Strike: The operator that dug through the gas line and plugged the gas line has been terminated by MFC. On Tuesday, September 24, 2024, MFC developed a Tool Box Talk concerning digging in tolerance zones and NOT stopping the flow of escaping natural gas. Starting Wednesday, September 25, 2024, all MFC project managers, field supervision and field employees are being presented with the Tool Box Talk/Safety Stand Down. I have attached our Tool Box Talk to the submitted AVR."</p> <p>Violations:</p> <p>Michael A Facchiano Contracting Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.</p> <p>PWSA Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20242503480 Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20242393546</p> <p>Verizon Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20231231065 Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20231231067</p> <p>Verizon Business Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20232722876. Education is required. Education was due on 9/10/24. Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20231231065. Education is required. Education was due on 9/10/24. Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20231231067. Education is required. Education was due on 9/10/24. Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20232722878. Education is required. Education was due on 9/10/24.</p> <p>Dormont Borough Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20232722876 Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20231231065</p>	
50140	Facility Owner: Pittsburgh Water and Sewer (PWSA)	<u>On 9/23/2024 12:00:00 PM at DEVONSHIRE ST, PITTSBURGH CITY, ALLEGHENY</u> PWSA accepts resolution.	Pittsburgh Water and Sewer (PWSA): \$500.00 Section 2(5)(i) 1st Offense

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>Contractor/Excavator: WILSON EXCAVATING AND UTILITY CONSTRUCTION LLC</p> <p>Project Owner: Peoples Gas Company</p> <p>Other: AT&T</p> <p>Other: Verizon PA LLC</p>	<p>*****</p> <p>Peoples gas provided the communication notes with the excavator. Violations and penalty have been removed.</p> <p>****</p> <p>Incident occurred on September 23rd, 2024, at 12pm along Devonshire Street, Pittsburgh City, Allegheny County.</p> <p>A water line was damaged.</p> <p>Peoples Gas Company's Alleged Violation Report (AVR) states, "Wilson Excavating was performing work for Peoples Gas on Devonshire Street in Pittsburgh when a mismarked PWSA water line was struck and damaged. The crew was excavating for main line when they struck a water line that was 3+ feet from the marks. PWSA was notified and sent a crew to make the repairs."</p> <p>Wilson's Excavating's AVR states, "Wilson Excavating was performing work for Peoples Gas on Devonshire Street in Pittsburgh when a mismarked PWSA water line was struck and damaged. The crew was excavating for main line when they struck a water line that was 3+ feet from the marks. PWSA was notified and sent a crew to make the repairs."</p> <p>Pictures show that the line was mismarked.</p> <p>PWSA Submitted their AVR on 10/29/2024.</p> <p>PWSA's AVR states, "Wilson excavation digging and hit mismarked copper active service line. PWSA responded and made repairs."</p> <p>Violations:</p> <p>PWSA Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20243204375 Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20243204376 Education is required</p> <p>Peoples Gas Company Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. 20243204375 Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. 20243204376</p> <p>Verizon Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20241933411</p> <p>AT&T Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20241933411</p>	<p>\$500.00</p> <p>Peoples Gas Company: \$0.00</p> <p>AT&T: \$2,000.00 Section 2(5)(viii) Subsequent \$2,000.00</p> <p>Verizon PA LLC: \$2,000.00 Section 2(5)(viii) Subsequent \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
50274	<p>Facility Owner: NATIONAL FUEL GAS</p> <p>Contractor/Excavator: PRO GOMEZ COMMUNICATIONS INC</p> <p>Project Owner: VELOCITY NET COMMUNICATIONS INC</p> <p>Other: Empire Telephone Corp / North Penn Telephone Company</p>	<p><u>On 9/23/2024 6:00:00 PM at 721 MINEO DR, MILLCREEK TWP, ERIE</u> NFG's violation and penalty have been removed. They were able to provide information during stakeholder review.</p> <p>On 1/29/2025 the DPI returned a call to Dave from Empire Accessor North Bend Telephone and left a detailed message letting him know that if they want to dispute the findings, they need to put something in writing. They can then provide additional information that will be considered.</p> <p>*****</p> <p>The incident occurred on 9/23/2024 at 721 Mineo Dr. in Millcreek Township in Erie County.</p> <p>A gas distribution line was hit and damaged. 911 was not notified.</p> <p>NATIONAL FUEL GAS the facility owner, stated in their AVR that "Excavator performing directional drilling struck natural gas distribution service. Please see attachments". 911 was not notified. Pictures were provided. On 11/30/2024 the Damage prevention Investigator (DPI) sent an email asking for confirmation if 911 was notified and when NFG placed the markings, since ticket 20242481256 did not have a final response. The DPI also asked for any verification that contact was made with the excavator since for ticket 20242481256, NFG responded Conflict. DCTF on 9/11/2024. No response has been received to date.</p> <p>Pro Gomez the excavator was emailed and mailed an AVR request letter on 11/12/2024. No AVR has been received to date.</p> <p>VELOCITY NET COMMUNICATIONS INC the Project Owner was mailed and emailed an AVR request letter on 11/12/2024.</p> <p>Velocity Net Communications the Project owner stated in their AVR that "A gas line was hit by the contractors hired by Velocity Network. I was not make aware of the situation until the next day or so. Thus I do not have a lot of information for this break". A Pneumatic Missile was being used. None of the questions asked in the AVR request letter were answered. On 12/06/2024 the DPI sent an email asking for the questions in the AVR request letter to be answered. Most of the questions that the project owner would know are left blank in the AVR. No information about the project was provided. On 12/06/2024 Velocity asked what was missing. DPI responded to the email 12/06/2024 and sent the AVR request letter with the questions highlighted.</p> <p>*****</p> <p>*Ticket 20242481256 was requested by Pro Gomez Communications Inc working at 739 and 645 Mineo Rd. for Velicity using boring missiles. The response was due by 9/11/2024.</p> <p>National Fuel Gas responded with a conflict on 9/11/2024 and field marked by 9/24/2024 at 10:05.</p>	<p>NATIONAL FUEL GAS: \$0.00</p> <p>PRO GOMEZ COMMUNICATIONS INC: \$2,750.00 Section 5(11.2) 1st Offense \$500.00</p> <p>Section 5(4) 1st Offense \$500.00</p> <p>Section 5(17) 1st Offense \$250.00</p> <p>Section 5(16) 1st Offense \$500.00</p> <p>Section 5(8) 1st Offense \$1,000.00</p> <p>VELOCITY NET COMMUNICATIONS INC: \$500.00 Section 6.1(7) 1st Offense \$500.00</p> <p>Empire Telephone Corp / North Penn Telephone Company: \$2,500.00 Section 2(5)(vii) 1st Offense \$2,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>*Emergency Ticket 20242674272 was requested by Pro Gomez Communications Inc on 9/23/2024 at 18:36. Crew is on site and state that they can smell gas - but state there is no hazardous release. They also stated that they were hand digging.</p> <p>North Penn Telephone Company never responded. Velocity Net Communications Inc never responded. National Fuel Gas responded with a conflict until they responded “field marked” on 9/24/2024 at 12:27 am. *****</p> <p>NATIONAL FUEL GAS is in violation of Sections: Section 9 - Failed to make best efforts to comply with the Common Ground Alliance Best Practices Chapter (5-8) The owner /operator notifies the excavator/contractor of the status of the ticketed by providing an electronic positive response through the 811 center. National Fuel Gas responded with a conflict for ticket 20242481256 on 9/11/2024 and field marked by 9/24/2024 at 10:05. *Please see ticket details above. The incident occurred on 9/23/2024. Recommendation: The penalty is applied.</p> <p>PRO GOMEZ COMMUNICATIONS INC is in violation of Sections: Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. Recommendation: The penalty is applied. Education is required. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property Section 5(11.2) When using horizontal Drilling (HDD) Excavator failed to utilize the best practices published by the HDD Consortium. Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: The penalty is applied. Education is required.</p> <p>VELOCITY NET COMMUNICATIONS INC is in violation of Sections: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 10 Business Days of a line strike. Velocity stated in their AVR that “I was not make aware of the situation until the next day or so”. Velocity did not submit an AVR until after a courtesy request for an AVR was sent and then they did not answer any questions that the damage Prevention Investigator asked. The incident occurred on 9/23/2024 and the AVR is dated 12/03/2024 and is well past the 10 business days required by law for an AVR to be submitted by a project owner. Velocity also did not answer the questions in the AVR about this project, so there is no project cost or design information.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Recommendation: The penalty is applied. Education is required. *****</p> <p>Listed below are facility owners in violation of Act 50, Section 2(5)(vii) Failed to respond to an emergency One Call ticket as soon as practicable.</p> <p>NORTH PENN TELEPHONE COMPANY is in violation of Sections: Section 2(5)(vii) – Failed to respond to an emergency notification 20242674272 as soon as practicable following notification. The education that was due by 1/10/2024 is not completed. Recommendation: The penalty is applied. Education is required. North Penn telephone was ordered to attend education within 60 days by the DPC on 10/11/23 for case 30645. North Penn has not complied with all DPC orders, so fines are raised to \$2500.0</p>	
50335	<p>Facility Owner: Peoples Gas Contractor/Excavator: W.A. Petrakis Contracting LLC Project Owner: New Wilmington Borough Designer: HERBERT ROWLAND AND GRUBIC INC</p>	<p><u>On 9/24/2024 8:00:00 AM at NORTH MARKET STREET, NEW WILMINGTON BORO, LAWRENCE</u> Peoples Gas submitted additional information. Violation withdrawn. *****</p> <p>The incident occurred on 09/24/2024, at 8:00 AM, on North Market Street, in New Wilmington Borough, Lawrence County. The nearest intersection is State Route 208.</p> <p>A gas line owned by Peoples Gas was damaged. 911 was called.</p> <p>Peoples Gas submitted an Alleged Violation Report (AVR). Their AVR states, "On 9/24/2024, W A Petrakis struck an unmarked, unidentified PNG ML crossing. Petrakis was doing sewer work for New Wilmington Borough." Photos were submitted.</p> <p>W.A. Petrakis Contracting LLC submitted an AVR. Their AVR states, "Crew was excavating trench for new sanitary sewer in North Market Street. Operator struck unmarked 2" steel line. Gas marks ended at line marker and curb line, they did not extend into the roadway where the excavation was taking place resulting in the damage. 911 was contacted with release of gas, first responders and Peoples repair crew dispatched to fix break. Line was repaired and remarked across the road correctly." Photos were submitted.</p> <p>New Wilmington Borough submitted an AVR. Their AVR states, "Crew was excavating trench for new sanitary sewer in North Market Street. Operator struck unmarked 2" steel line. Gas marks ended at line marker and curb line, they did not extend into the roadway where the excavation was taking place resulting in the damage. 911 was contacted with release of gas, first responders and Peoples repair crew dispatched to fix break. Line was repaired and remarked across the road correctly." Photos were submitted.</p>	<p>Peoples Gas: \$0.00</p> <p>New Wilmington Borough: \$500.00 Section 6.1(3) 1st Offense \$500.00</p> <p>HERBERT ROWLAND AND GRUBIC INC: \$1,000.00 Section 4(2) 2nd Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>HERBERT ROWLAND AND GRUBIC INC - An AVR request letter was emailed and mailed on 10/28/2024. An AVR was submitted and states, “Herbert, Rowland, & Grubic (HRG) was notified via email on October 8, 2024 by the W.A. Petrakis Contracting project manager, Nate Stolarski, that an unmarked gas line was struck by W.A. Petrakis Contracting on September 24, 2024 at 8:00 AM. The gas line was struck during the installation of a sanitary sewer main located in North Market Street, State Route 158. A representative of HRG was not present at the site on September 24, 2024. The information received in the October 8, 2024 email indicated that the gas line marking did not extend beyond an adjacent parking lot into the roadway where the excavation was occurring. HRG prepared construction plans for the replacement of an existing sanitary sewer line located in North Market Street for New Wilmington Borough. The final design was completed and the project was released for bidding on April 10, 2024. In the area that the gas line was struck, gas lines are located on the east and west sides of North Market Street with a connecting gas line crossing North Market Street. The gas line crossing North Market Street was shown on the construction drawing, but the line was not shown across the full width of the roadway where the sanitary sewer main was located. A copy of the construction drawing with the location noted is attached.”</p> <p>No Final Design tickets were located.</p> <p>Violations:</p> <p>HERBERT ROWLAND AND GRUBIC INC – - Section 4(2) – Designer failed to request the line and facility information prescribed by section 2(4) from the One Call System not less than ten nor more than ninety business days before final design is to be completed. Recommendation: The penalty is applied. Education is required.HERBERT ROWLAND AND GRUBIC INC has prior violations of 4(2).</p> <p>New Wilmington Borough – - Section 6.1(3) – Released a project to bid or construction before final design was complete. Recommendation: The penalty is applied. Education is required.New Wilmington Borough has no prior violations.</p> <p>Peoples Gas – (Withdrawn) - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: The penalty is applied. Education is required.</p>	
50198	Facility Owner: National Fuel Gas Contractor/Excavator: PASSAUER EXCAVATION	<u>On 9/24/2024 11:00:00 AM at 3279 Loleta Rd., JENKS TWP, FOREST</u> Incident occurred on September 24th, 2024, at 11am, at 3279 Loleta Road, Jenks Township, Forest County.	PASSAUER EXCAVATION: \$2,500.00 Section 5(2.1) 1st Offense \$1,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>A gas line was damaged. No PA one call.</p> <p>National Fuel Gas' Alleged Violation Report states, "Excavator struck a natural gas distribution main line. Excavator failed to submit POCS ticket request. Please see attachments."</p> <p>Pictures from NFG show the excavator along with the damaged gas line with no visible mark outs.</p> <p>Passauer Excavation was mailed a request for an AVR 10/30/24. AVR was submitted on 11/12/2024.</p> <p>Passauer Excavation's AVR states, "Passauer Excavation Inc was contacted by the property owner, Barrett Graham. Mr. Graham had been installing an illegal leach field for sewage, gray water and was turned in by the township. Mr. Graham asked if we could install a holding tank and clean up his excavation in his yard. We agreed to do this as his yard was already dug up and visible gas line markers were on the opposite side of the highway. We started to clean up the previous excavation in this process we did nick the plastic gas line, and we did not do a 1 call. After nicking the line the excavator bucket was set on the line, and the gas company was called. 1 call was notified."</p> <p>Violations:</p> <p>Passauer Excavation Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. PUC compliance training education is required. Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. PUC compliance training education is required. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. PUC compliance training education is required.</p>	<p>Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$500.00</p>
50269	<p>Facility Owner: Columbia Gas of PA - Central</p> <p>Contractor/Excavator: A. Folino Construction</p> <p>Project Owner: Pittsburgh Water and Sewer (PWSA)</p> <p>Designer: JOHNSON MIRMIRAN AND THOMPSON J M T</p> <p>Other: Crown Castle</p> <p>Other: Verizon</p> <p>Other: Verizon Business</p>	<p>On 9/24/2024 11:47:00 AM at S 19TH ST, PITTSBURGH CITY, ALLEGHENY Removed Verizon Local violations for 2(5)v on ticket 20223271708. Verizon is no longer disputing. *****</p> <p>Incident occurred on September 24th, 2024, at 11:47am at the corner of S 19th Street and 1901 Sidney Street, Pittsburgh City, Allegheny County.</p> <p>A gas line was damaged.</p> <p>Columbia Gas Company's Alleged Violation Report (AVR) states, "A Folino Construction struck a 1" plastic, medium pressure, gas service with their backhoe. They notified Columbia Gas directly when the damage occurred. Columbia Gas responded immediately to make the area safe and complete repairs. A Folino Construction was digging on routine tickets placed in June of 2024, and the marks were no longer visible.</p>	<p>A. Folino Construction: \$2,000.00 Section 5(4) 2nd Offense \$1,000.00</p> <p>Section 5(3) 2nd Offense \$1,000.00</p> <p>Crown Castle: \$5,000.00 Section 2(4) 2nd Offense \$2,500.00</p> <p>Section 2(4) 2nd Offense \$2,500.00</p> <p>Verizon: \$9,000.00 Section 2(4) Subsequent \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>There have been no update tickets placed. The gas service was accurately marked back in June 2024. Additional document attachment left off that needs added to AVR 10/14/24 cag."</p> <p>A. Folino Construction's AVR states, "A. Folino Construction was digging on S 19 St to install new main sewage line when we hit an unmarked gas service line that went to 1901 Sidney St. 911 was called and a damage ticket was made through 811. Peoples Gas responded and claimed the line as theirs. Peoples Gas had a crew come out and make the repairs."</p> <p>PWSA's AVR states, "A Folino digging to install sewer main and hit an unmarked gas line. 911 was called, Peoples Gas responded and made repairs."</p> <p>JMT's AVR states, "A. Folino Construction was digging on S 19 St to install new main sewage line when we hit an unmarked gas service line that went to 1901 Sidney St. 911 was called and a damage ticket was made through 811. Peoples Gas responded and claimed the line as theirs. Peoples Gas had a crew come out and make the repairs. Lines were shown on the bid documents."</p> <p>Pictures of mark outs show that the line was accurately marked.</p> <p>Violations:</p> <p>A. Folino Construction Section 5(3) – Excavator failed to preserve mark-outs or request a remark. Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.</p> <p>Verizon Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20223271708 Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20232292322 Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20230120489 Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20220200496 Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20220201070 Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20223272664 Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20220201094</p> <p>Verizon Business Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20232292322. Verizon Business is delinquent on education due by 9/10/2024. Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20230120489. Verizon Business is delinquent on education due by 9/10/2024.</p>	<p>Section 2(4) Subsequent \$1,500.00</p> <p>Verizon Business: \$10,000.00</p> <p>Section 2(4) 1st Offense \$2,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20220201070. Verizon Business is delinquent on education due by 9/10/2024.</p> <p>Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20223272664. Verizon Business is delinquent on education due by 9/10/2024.</p> <p>All fines raised to \$2500 because Verizon Business failed to attend DPC ordered education for 2 cases in 2024. Case 36553 the DPC ordered Verizon Business to education on 6/11/24, and case 39785 the DPC ordered education on 7/19/24. Verizon business is delinquent on these and on payment for invoice 039785-008156 from 7/19/24.</p> <p>Crown Castle</p> <p>Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20232292322. Education is required. Crown Castle is delinquent on education due by 9/10/2024.</p> <p>Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20230120489. Education is required. Crown Castle is delinquent on education due by 9/10/2024.</p> <p>Fines raised to \$2500 because Crown Castle is delinquent on DPC ordered education for case 42290 which was ordered by the DPC on 6/11/24 Crown Castle last attended education on 6/16/2023, however that education would not apply to case 42290 because that incident took place on 10/3/2023, after the last education was taken.</p> <p>Crown Castle is also delinquent in invoice 034674-005926 from 6/28/2023 and 029887-005966 from 9/27/2023.</p>	
50266	<p>Facility Owner: UGI Contractor/Excavator: REIFF BROTHERS EXCAVATING Project Owner: HOMEOWNER</p>	<p><u>On 9/24/2024 2:10:00 PM at 489 Montdale Road, SCOTT TWP, LACKAWANNA</u> The incident occurred on 9/24/2024 at 489 Montdale Road in Scott Township in Lackawanna County.</p> <p>A Gas meter riser was damaged during a demolition.</p> <p>UGI UTILITIES INC stated in their Alleged Violation Report (AVR) that Excavator caused an uncontrolled release of gas when during demolition they removed a meter installation and pulled the gas riser out of the ground with an excavator. Excavator did not have a demolition OC ticket. Cost of repair was \$1688.00. verified by UGI in an email received on 10/24/2024. see attachment named UGI cost of damage. Pictures were provided.</p> <p>Reiff Brothers Construction was mailed, emailed and emailed, through their online site, an AVR request letter on 10/23/2024. Project owner information was specifically asked for. Reiff Brothers was hired by owner to dismantle and salvage the wooden portion of the structure - not including removal of the foundation or any excavation. Owner arranged for disconnection of electric. Owner called UGI regarding the gas service which had not been used for at least several years. Owner states that he called UGI multiple times and was told that the gas service had been cut in the street several years before. During the process of dismantling some</p>	<p>REIFF BROTHERS EXCAVATING: \$1,000.00 Section 5(2.1) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>wood debris fell against the meters causing a leak. Work was immediately halted and fire company and UGI called.</p> <p>Project Owner Johnathan Lewis was mailed an AVR request on 11/15/2024. ***</p> <p>Ticket 20242683516 was submitted by REIFF BROTHERS EXCAVATING for a demolition on 9/24/2024 at 15:30. Incident occurred on 9/24/2024 at 14:10. Stakeholders did not have an opportunity to respond to this ticket prior to demolition. Ticket states that Reiff Brothers has contacted the utilities directly for disconnects / meter removal. ****</p> <p>REIFF BROTHERS EXCAVATING is in violation of Section: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Recommendation: The penalty is applied. Education is required.</p>	
50123	<p>Facility Owner: PECO Contractor/Excavator: BORO CONSTRUCTION Project Owner: UPPER DUBLIN TOWNSHIP Designer: CHA Consulting</p>	<p><u>On 9/25/2024 9:00:00 AM at 801 LOCH ALSH AVE, UPPER DUBLIN TWP, MONTGOMERY CHA</u> Solutions provided documentation that they were not the designer for this particular project. Both violations and penalties are removed for CHA. *****</p> <p>Incident occurred on September 21st, 2024, at 9am at 801 Loch Alsh Avenue, Upper Dublin Township, Montgomery Township.</p> <p>A gas line was damaged.</p> <p>PECO's Alleged Violation Report (AVR) states, "On 9/25/2024 Boro Construction was trenching with a trackhoe, when they dug through a properly marked 2" high pressure gas main. Prior to striking the gas main the Contractor severed streetlight conduit, PVC drainpipe and a telecommunications conduit. Bill Boro Construction. 0 injuries, 1 Cust interrupted."</p> <p>PECO Damage report pdf shows that the 2" line was damaged at 18 inches with a hit kit.</p> <p>Boro Construction was mailed and emailed a request for an AVR on 10/30/24. AVR was received 10/30/24. Incident occurred 9/25/24.</p> <p>Boro Construction's AVR states, "a Gas line was marked and flagged south of the sidewalk on Loch Alsh Avenue. It was located, found, and cleared by hand digging at the One call markings provided. After clearing away the debris the excavation resumed, and an unmarked gas line was hit located approximately 30 inches south of the one call marking. Please see attached pictures." 911 was notified.</p> <p>Returned a missed call to Boro Construction and provided the information on how to file an AVR on 10/30/24.</p>	<p>BORO CONSTRUCTION: \$1,000.00 Section 5(4) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$500.00</p> <p>UPPER DUBLIN TOWNSHIP: \$1,000.00 Section 6.1(3) 1st Offense \$500.00</p> <p>Section 6.1(7) 1st Offense \$500.00</p> <p>CHA Consulting: \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Upper Dublin Township was mailed and emailed with a request for an AVR on 10/30/24. AVR received on 11/24/24. Incident date of 9/25/24.</p> <p>Upper Dublin notified CHA Solutions of the AVR email. No AVR received to date. Please see email attachments.</p> <p>Upper Dublin Township's AVR states, "We were notified after the gas main was hit by the Construction Manager. We had no other involvement."</p> <p>No design tickets were located by 811 on the AVRs received.</p> <p>Violations:</p> <p>Boro Construction Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Education is required.</p> <p>Upper Dublin Township Section 6.1(3) – Released a project to bid or construction before final design was complete. Education is required. Previous education was due 3/13/23. Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 10 Business Days of a line strike. Education is required. Previous education was due 3/13/23.</p> <p>CHA Solutions Section 4(4) – Failed to prepare construction drawings to avoid damage to and minimize interference with facilities in the construction area. Education is required. Section 4(8) – Designer failed to submit an Alleged Violation Report through the One Call System within 30 business days of being notified or aware that a violation of this act may have been committed. Education is required.</p>	
50184	<p>Facility Owner: National Fuel Contractor/Excavator: All Green Landscaping</p>	<p><u>On 9/26/2024 11:00:00 AM at 238 Oil Valley Rd., Duke Center, MCKEAN</u> The incident occurred on 09/26/2024, at 11:00 AM, at 238 Oil Valley Road, Duke Center, in Mckean County.</p> <p>A gas line owned by National Fuel was damaged. No PA One Call ticket. 911 was called.</p> <p>National Fuel submitted an Alleged Violation Report (AVR). Their AVR states, "Excavator struck and damaged natural gas distribution service. Excavator did not submit a POCS Ticket Request. Please see attachments. Damage occurred at 238 Oil Valley Rd. Duke Center, PA 16729. Unable to find Duke Center under municipalities." Photos were submitted.</p> <p>All Green Landscaping - An AVR request letter was mailed 11/12/2024. An AVR was submitted, but did not include a summary or any details about the incident. AVR indicates that 911 was called.</p>	<p>All Green Landscaping: \$1,250.00 Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>The project owner is unknown.</p> <p>The gas meter shown in the photos is an indicator that gas lines are present in the area.</p> <p>Violations:</p> <p>All Green Landscaping –</p> <ul style="list-style-type: none"> - Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. - Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
50396	<p>Facility Owner: Columbia Gas of PA - Central</p> <p>Contractor/Excavator: Concrete Cutting Systems Pittsburgh, Inc</p> <p>Project Owner: Columbia Gas</p> <p>Designer: Columbia</p> <p>Other: DeSoto</p> <p>Other: Verizon</p>	<p><u>On 9/27/2024 9:00:00 AM at 453 2ND ST, WASHINGTON CITY, WASHINGTON</u> Incident occurred on September 27th, 2024, at 9am at 453 2nd Street, Washington City, Washington County.</p> <p>A gas line was damaged.</p> <p>Columbia Gas Company's Alleged Violation Report (AVR) states, "DeSoto Line Services, working on behalf of Columbia Gas for an infrastructure replacement project, subcontracted their saw cutting work to Concrete Cutting Systems. Concrete Cutting Systems saw cut the ditch line on Monday, 09/23/2024. After completing the saw cutting, the Concrete Cutting Systems crew, DeSoto crew, and Columbia Gas walked the area for footage numbers. At that time, there was no indication that a line had been cut. On Friday 09/27/2024, DeSoto was removing the hard surface in the vicinity of 453 2nd St., Washington, when they had an odor of gas. DeSoto immediately contacted 911, 811, and Columbia Gas. Columbia Gas responded immediately to make the area safe and found the gas service to 453 2nd St., had been saw cut. Repairs were made. A root cause investigation was conducted on 10/03/2024 to review the events leading up to the damage. Concrete Cutting Systems uses a saw to cut the road and follows with a vac truck to clean up dust and debris from the saw, ensuring the area is clean. During this process, there were no indications of bubbling slurry to identify that a gas service had been damaged. Due to the shallow depth of this gas service at only 10" deep, the root cause was determined to be Poor Records. During the root cause, it was determined that all proper protocols were followed. One of the key takeaways was to use soap water on gas services after saw cutting to identify any possible leaks."</p> <p>Concrete Cutting System's Alleged Violation Report (AVR) states, "Excavator: Concrete Cutting Systems Working for: DeSoto, working for Columbia Gas Root Cause: Poor Records, improper installation Concrete Cutting Systems working on behalf of DeSoto, saw cut the ditch line on Monday. After completing the saw cutting, saw cut crew and DeSoto along with Columbia</p>	<p>Concrete Cutting Systems Pittsburgh, Inc: \$500.00 Section 5(4) 1st Offense \$500.00</p> <p>Verizon: \$2,750.00 Section 2(5)(v) 3rd offense \$750.00</p> <p>Section 2(5)(viii) Subsequent \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Gas walked the area for footage numbers. On Friday 09/27/2024, DeSoto was removing the hard surface and got an odor of gas. DeSoto contacted 911 and Columbia Gas Construction Coordinator. The Columbia Gas Coordinator called for a service tech to respond. Columbia Gas Service Tech responded and found that the service line had been cut while saw cutting. Area was made safe and repairs were completed. Root Cause was held on 10/03/2024, involving Concrete Cutting Systems, DeSoto and Columbia Gas. Concrete Cutting Systems uses a saw to cut the road and follows up with a vac truck to clean up dust and debris from the saw, leaving the area clean. During this process there were no signs of bubbling slurry to identify that a service line had been damaged. During this meeting it was found that all protocol was followed. One take away that was discussed was using soaping water on service lines after saw cutting was completed to identify and possible leaks."</p> <p>Pictures show that the line was marked within the tolerance zone.</p> <p>Violation:</p> <p>Concrete Cutting Systems Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.</p> <p>Verizon Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. 20242562126 Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20241372571</p>	
50154	<p>Facility Owner: Peoples Gas Company LLC Contractor/Excavator: LINDY PAVING INC Contractor/Excavator: SWANK CONSTRUCTION Contractor/Excavator: WILSON EXCAVATING AND UTILITY CONSTRUCTION LLC Project Owner: PENNSYLVANIA AMERICAN WATER</p>	<p><u>On 9/27/2024 11:30:00 AM at ROSWIN DR, PITTSBURGH CITY, ALLEGHENY</u> The incidents occurred on Friday, September 27, 2024, on Roswin Drive, in Pittsburgh City, Allegheny County.</p> <p>Two Peoples Natural Gas (PNG) lines were damaged.</p> <p>PNG explained, the initial damage came in as 120 Roswin Drive from the 911 operator. Both Swank Construction and Crews Control had placed tickets to saw-cut on Roswin Drive, for Lindy Paving for the same day. Upon arrival at the 1st damage, 114 Roswin Drive, PNG first responder noticed the Crews Control vehicles onsite and documented that, and the supervisor located the ticket for Crews Control and listed them as the damaging party. PNG first responder was informed of the 2nd damage and called into the Ops Center, which was 152 Roswin Drive. Both damages were caused by Swank Construction, Crews Control was only flagging. PNG stated that Swank Construction saw-cut through 2 properly marked PNG service lines on the same project on the same day, at 114 and 152 Roswin Drive. They failed to use prudent digging techniques around marked facilities</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Wilson Excavating explained that they were working for PA American Water Company (PAWC) to install new utilities at 114 and 152 Roswin Drive. Wilson Excavating had completed the installation of pipes and hired Lindy Paving to do the restoration portion of the project. Lindy Paving hired Swank Construction to saw-cut the hard surface in preparation for paving and restoration activities. Swank Construction struck a marked PNG line with the saw.</p> <p>Swank Construction stated they were saw-cutting at a depth of 8-inches and cut 2 gas service lines. The cut at 114 Roswin Drive was approximately 1-foot off the identifying paint mark by PNG.</p> <p>PAWC stated that Swank Construction damaged a shallow PNG service line, and explained that the same service line at 114 Roswin Drive was damaged on 1/10/2024, for the same reason, the shallow depth. When PNG fixed the service line in January, they failed to lower the service line to the federal minimum depth of 18-inches. For both 114 and 152 Roswin Drive, Swank Construction was following best practices to break the hard surface, which allows for mechanized equipment in the tolerance zone.</p> <p>No Violation because of the shallow depth of the lines</p>	
50200	<p>Facility Owner: PEOPLES GAS COMPANY LLC Contractor/Excavator: HAND-D-MAN Contractor/Excavator: HAND-D-MAN Project Owner: HOMEOWNER</p>	<p><u>On 9/27/2024 3:45:00 PM at 448 HERSHEY RD, PENN HILLS MUNIC, ALLEGHENY</u> The incident occurred on 9/27/2024, at 448 Hersey Rd, in Penn Hills Municipal, Allegheny County.</p> <p>A gas line was hit and damaged. Four hours later the same contractor again hit and damaged a gas line. 911 was not notified by the excavator..</p> <p>PEOPLES GAS COMPANY LLC stated in their Alleged Violation Report (AVR) on 9/27/2024 “JAMES MCFADDEN struck and damaged a Peoples Gas service line while using mechanized equipment in the tolerance zone with clear evidence of underground facilities in the area”. 1 customer was affected. 911 was not checked as being notified. Pictures were provided.</p> <p>Peoples Gas the facility owner sent in another AVR that stated “JAMES MCFADDEN struck and damaged a Peoples Gas service line while using mechanized equipment in the tolerance zone with clear evidence of underground facilities in the area. This was the second time within 4 hours that the same person hit this same service line”. Pictures were provided.</p> <p>On 11/20/2024 and email was received from Peoples gas confirming that 911 was not notified. Peoples send an email on 11/21/2024 stating that they billed the homeowner for this damage, because the homeowner never mentioned a contractor.</p> <p>James McFadden the homeowner was mailed and emailed an AVR request letter on 10/25/2024. DPI returned a call to Homeowner James McFadden, who</p>	<p>HAND-D-MAN: \$3,750.00 Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(4) 1st Offense \$500.00</p> <p>Section 5(4) 1st Offense \$500.00</p> <p>Section 5(17) 1st Offense \$250.00</p> <p>Section 5(16) 1st Offense \$500.00</p> <p>Section 5(8) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>stated that he was not outside when the incident occurred. He had a friend that was excavating. He also said that the friend works for a gas company and was doing some work on the side. James stated that he put it all in the AVR and looked up his email to give me AVR2024OCT250036. As of this moment, the AVR is not in my system. James said that his friend was digging a trench and that he hit his service line, between the service and the shut off. He said that 911 was not called, but the gas company was called immediately He asked what to expect and DPI went over the process and what to expect. I explained about the notice that will be sent with the violations and mentioned a for example 911 was not called, so I will be putting that as a violation. He started telling me that he is not sure if 911 was called. He did not call 911. WE also spoke about the responsibility that professional have to call in their own OneCall tickets. They were trying to save money he said. He added that now he has a bill from the gas company too. DPI let him know that if he did not hit the line, it is the excavator's responsibility. James said he is just going to pay it because the odd issue of the friend doing him a favor. DPI also let him know that excavators doing "favors" has led to some bad things that have occurred. James McFadden AVR stated that "Excavator was hired to help with this project. See above My gas service was affected. Just my residence was affected. My Gas line service was damaged at the gas main. My service line was damaged near gas meter Peoples Gas Co was contacted and repaired service line at the main. Plumber repaired service line near the gas meter. There are no pictures available, all work has been completed.</p> <p>Hand-D-Man was emailed and mailed an AVR request letter on 10/25/2024 to the address provided on routine ticket 20242682131. Another AVR letter was emailed and mailed to the address provided by Compliance Specialist on 11/18/2024.</p> <p>*Professional Hand-D-Man Contracting Services has placed one call notifications with PA One Call in the past. Last Contact Info: 3898 Old William Penn Hwy Suite 101, Penn Hills PA, 15235, 412-512-3117 Ticket 20242682131 was requested by James McFadden on 9/24/2024 to install a French drain at 448 Hershey Rd with a response due by 9/26/2024. All facility owners responded timely. This address matches James McFadden's address. *****</p> <p>Hand-D-Man is in violation of: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. On 9/27/2024 the same gas line was hit 2 times. Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. Both hits of the gas line could have been reported on 1 AVR.</p> <p>Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request.</p> <p>Recommendation: The penalty is applied. Education is required.</p>	
50295	<p>Facility Owner: UGI Utilities</p> <p>Contractor/Excavator: Linde Corporation</p> <p>Project Owner: UGI Utilities - Place holder</p> <p>Other: ADAMS CABLE TV</p> <p>Other: LACKAWANNA RIVER BASIN SEWER AUTHORITY</p>	<p><u>On 9/30/2024 10:30:00 AM at 12 LACKAWANNA ST, JERMYN BORO, LACKAWANNA</u> LACKAWANNA RIVER BASIN SEWER AUTHORITY accepted the violation and submitted payment.</p> <p>*****</p> <p>The incident occurred on 09/30/2024 at 10:30 AM, at 12 Lackawanna Street, in Jermyn Borough, Lackawanna County.</p> <p>A UGI Utilities gas line was damaged. 911 was called.</p> <p>UGI Utilities submitted an Alleged Violation Report (AVR). Their AVR states, "Excavator struck and damaged a 2" plastic gas main while digging in the tolerance zone." Photos were submitted.</p> <p>Linde Corporation submitted an AVR. Their AVR states, "As crew was excavating for install of gas service the struck a marked 2" gas main. This main was exposed via vac excavation approx. 40" away from damage. See attachments." Photos were submitted.</p> <p>Violations:</p> <p>LACKAWANNA RIVER BASIN SEWER AUTHORITY –</p> <p>- Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Routine ticket 20242681205 had a response due date of 09/26/2024. LACKAWANNA RIVER BASIN SEWER AUTHORITY responded 'Field Marked' on 09/30/2024. Recommendation: The penalty is applied. Education is required.</p> <p>LACKAWANNA RIVER BASIN SEWER AUTHORITY has no prior violation of 2(5)(v).</p> <p>ADAMS CABLE TV –</p> <p>- Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Emergency ticket 20242741920 had a response due date of 09/30/2024. ADAMS CABLE TV did not respond to the ticket.</p> <p>Recommendation: The penalty is applied. Education is required.</p> <p>ADAMS CABLE TV has overdue education for case 022992, that was due 02/06/2023.</p> <p>ADAMS CABLE TV has multiple violations of 2(5)(vii) on a prior case - 022992.</p> <p>Linde Corporation –</p>	<p>Linde Corporation: \$500.00 Section 5(4) 1st Offense \$500.00</p> <p>ADAMS CABLE TV: \$1,000.00 Section 2(5)(vii) 1st Offense \$1,000.00</p> <p>LACKAWANNA RIVER BASIN SEWER AUTHORITY: \$250.00 Section 2(5)(v) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>- Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: The penalty is applied. Education is required. Linde Corporation has two prior violations of 5(4) for incidents in 2023.</p>	
50370	<p>Facility Owner: PENNECO PIPELINE CORPORATION Contractor/Excavator: W A PETRAKIS CONTRACTING COMPANY Project Owner: PLUM BOROUGH MUNICIPAL AUTHORITY</p>	<p><u>On 10/1/2024 9:00:00 AM at SARDIS ROAD, PLUM BORO, ALLEGHENY</u> The incident occurred on Tuesday, October 1, 2024, on Sardis Road, in Plum Borough, Allegheny County.</p> <p>Penneco Pipeline Corporation line was damaged.</p> <p>W. A. Petrakis Contracting Company stated that their crew was excavating a trench for new water mainline replacement. The Operator dug through a mismarked Penneco gas line perpendicular to our trench that was 5-feet off the mark. W. A. Petrakis Contracting called 911, the Fire Department responded and Penneco completed repairs.</p> <p>Penneco Pipeline Corporation submitted an AVR and emailed a letter explaining, “Penneco is a voluntary enrollee in the PA 1-Call System as an operator of production flow lines form stripper wells and is not a “facility owner” as defined in Act 50.” See the attached letter</p> <p>On Thursday, October 31, 2024, an email was sent requesting an Alleged Violation Report (AVR) from the facility owner, Penneco Pipeline Corporation. On 11/1/2024, a letter was mailed to the facility owner requesting an AVR. Penneco submitted an AVR and email with an attached letter on 11/5/2024.</p> <p>No Violations</p>	
50338	<p>Facility Owner: Peoples Gas Contractor/Excavator: A. Liberoni, Inc. Project Owner: PENNDOT Designer: Designer's name was not provided</p>	<p><u>On 10/1/2024 9:00:00 AM at SYLVAN AVE, PITTSBURGH CITY, ALLEGHENY</u> PennDOT disagreed and provided the verification that they were not the project owner. The AVR from Peoples and the tickets listed PennDOT. The 2 violations to PennDOT are withdrawn. *****</p> <p>The incident occurred on 10/01/2024 at Sylvan Ave in Pittsburgh City in Allegheny County.</p> <p>A gas line was hit and damaged.</p> <p>A LIBERONI Inc stated in their Alleged Violation Report (AVR) that “Liberoni removed a piece of sandstone curb at 4711 Sylvan Ave. Upon removal, the service gas line came out with the curb. It appeared as the curb gas line for 4711 Sylvan Ave had been run through the curb instead of under the curb”. The project is listed as >\$400,000. 2300 LF and a Level “C” Subsurface Utility Engineering (SUE). 911 was notified. 1 customer was affected.</p> <p>PEOPLES GAS COMPANY LLC stated in their AVR that “A Liberoni working for PennDOT struck and damaged a properly marked Peoples Gas service while</p>	<p>A. Liberoni, Inc.: \$500.00 Section 5(4) 1st Offense \$500.00</p> <p>PENNDOT: \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>using mechanized equipment in the tolerance zone”. Pictures were provided. 1 customer was affected.</p> <p>PENNDOT the project owner was mailed and emailed an AVR request letter on 11/03/2024. No AVR has been received to date.</p> <p>Designer was not provided. ***** This case is connected to case 50338. ***** *Ticket 20241200987 was requested by A Liberoni Inc on 4/29/2024 with a response due by 5/01/2024. Pittsburgh Water and Sewer Authority never responded.</p> <p>*Ticket 20242253774 was requested on 8/12/2024 by A Liberoni with a response due by 8/14/2024. The Pittsburgh Water and Sewer Authority never responded.</p> <p>***** A Liberoni, Inc. is in violation of: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: The penalty is applied. Education is required.</p> <p>PENNDOT is in violation of: Section 6.1(1) – Failed to utilize sufficient quality levels of subsurface utility engineering or other similar techniques to properly determine the existence and positions of underground facilities when designing known complex projects having an estimated cost of (\$400,000) or more. This is a second offense. Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 10 Business Days of a line strike. This is a second offense. Recommendation: The penalty is applied. The required Project Owner education was completed by 11/13/2024.</p>	
50413	<p>Facility Owner: CITIZENS ELECTRIC COMPANY OF LEWISBURG</p> <p>Contractor/Excavator: ML Yoder Enterprise</p> <p>Project Owner: CLASSIC QUALITY HOMES</p>	<p><u>On 10/1/2024 11:30:00 AM at 96 DOGWOOD LN, EAST BUFFALO TWP, UNION</u> The incident occurred on Tuesday, October 1, 2024, at 96 Dogwood Lane, in East Buffalo Township, Union County.</p> <p>An electric line was damaged.</p> <p>Citizens Electric Company of Lewisburg stated that ML Yoder Enterprise failed to exercise due care and take all reasonable steps necessary to avoid damaging the line. Citizens Electric explained that ML Yoder Enterprise began trenching on Dogwood Lane near the end of the cul-de-sac for a new electric service. Beginning the work using a mini excavator near 97 Dogwood Lane, the excavator caught the single electric service conduit and damaged the wire pulling some of the internal components of the pad-mount transformer. Citizens’ Electric was notified of the damaged, and employees arrived at the worksite and made temporary repairs to the service cable, until permanent repairs could be made at a later time. The facilities were clearly marked, and the</p>	<p>ML Yoder Enterprise: \$500.00 Section 5(4) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>trench was dug within the 18-inch tolerance zone. There was no interruption to the electrical service, but the underground cable was damaged enough that it needed to be replaced.</p> <p>ML Yoder Enterprise stated that they failed to exercise due care and take all reasonable steps necessary to avoid damaging the line, and explained, dug open the line at the transformer and saw that it curved to the right and started digging to the left of the line, but not far enough and caught the tube, but did not damage the wire enough to cause a power outage.</p> <p>Classic Quality Homes, the project owner, stated in their AVR an excavator issue and was unable to provide detailed information because they did not witness the incident.</p> <p>Photos were provided of the damage and locate marks.</p> <p>On Thursday, October 31, 2024, emails were sent requesting Alleged Violation Reports (AVR) from the excavator; ML Yoder Enterprise, and the project owner; Classic Quality Homes.</p> <p>ML Yoder Enterprise submitted their AVR on 11/8/2024, and Classic Quality Homes submitted their AVR on 11/7/2024.</p> <p>*ML Yoder Enterprise is in violation of section: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: Education Required and Penalty Applied</p>	
50459	<p>Facility Owner: Columbia Gas</p> <p>Contractor/Excavator: Wilson Excavating and Utility</p> <p>Project Owner: Michael Baker International</p> <p>Designer: KCI Technologies Inc.</p>	<p><u>On 10/2/2024 5:00:00 PM at POWELL ROAD, CRANBERRY TWP, BUTLER</u> Columbia Gas violation and penalty withdrawn.</p> <p>*****</p> <p>The incident occurred on 10/02/2024, at 5:00 PM, on Powell Road, in Cranberry Township, Butler County. The nearest intersection was Freedom Road.</p> <p>A gas line owned by Columbia Gas was damaged. 911 was called.</p> <p>Columbia Gas submitted an Alleged Violation Report (AVR). Their AVR states, "Wilson Excavating was digging to install water services on Powell Rd., when they struck and damaged an unmarked 8' stub of 6" plastic gas main. They notified 911, and 911 notified Columbia Gas when the damage occurred. Columbia Gas responded immediately to make the area safe and complete repairs. The local Columbia Gas Damage Prevention Specialist met with Wilson Excavating to review the One Call law regarding the upkeep of marks or calling a new ticket. Wilson did call in a new ticket for the area but did not wait for the locate to be completed. They damaged the line the day before the response due date." Photos were submitted.</p>	Columbia Gas: \$0.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Wilson Excavating and Utility submitted an AVR. Their AVR states, "Wilson Excavating was performing work for PennDOT on Powell Rd near the intersection of Freedom Road in Cranberry Township. The project was to install 10" water main. As the crew was excavating a mismarked 6" gas main that was capped off was struck and damaged. The line belongs to Columbia gas. 911 was called and the facility owner was notified. There was concern of an odor of gas in the office of Barkley Manor Apts so it was evacuated of 2-3 people. But it was determined there was no gas leaking/escaping inside the building. Columbia gas crew arrived and shut off the gas line and performed repairs." Photos were submitted.</p> <p>Michael Baker International submitted an AVR. Their AVR states, "During excavation for installation of planned 10" Water Main the subcontractor encountered and damaged an existing 8" Gas line damaging it causing gas to escape. Cranberry Township inspector notified 911 with Fire and Police response. Columbia Gas called to site to shut off the line and perform repairs." Photos were submitted.</p> <p>KCI Technologies Inc. submitted an AVR. Their AVR states, "During excavation, subcontractor (Wilson) encountered and damaged an existing 8" gas line causing gas to escape. Inspector notified 911, and fire and police responded. Columbia Gas was called to shut off line and do repairs."</p> <p>Routine ticket 20242482934 was requested on 09/04/2024. Columbia Gas responded 'Field Marked' on 09/06/2024. The mapping for this ticket matches the emergency ticket (20242764387) and both are for Powell Road. The submitted photos show visible line markings when the damage occurred. Routine ticket 20242753767 was for markings on Freedom Road and requested 10/01/2024. (This is ticket referenced in Colombia Gas AVR response.)</p> <p>Violations:</p> <p>Columbia Gas – **Withdrawn. Additional information was submitted.** - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: The penalty is applied. Education is required.</p>	
50376	Facility Owner: Lancaster City Water - LU Contractor/Excavator: JVI Group Inc. Project Owner: Lancaster City Water - LU - Placeholder Other: LAND GRANT SURVEYORS LLC	<p><u>On 10/3/2024 9:45:00 AM at 545 PERSHING AVE, LANCASTER CITY, LANCASTER</u> The incident occurred on 10/03/2024, at 9:45 AM, at 545 Pershing Ave., in Lancaster City, Lancaster County.</p> <p>A water line owned by Lancaster City Water was damaged.</p> <p>Lancaster City Water submitted an Alleged Violation Report (AVR). Their AVR states, "JVI Group is working for Lancaster City on a contract to repair curbs and sidewalks. JVI was repairing a sewer lateral that was</p>	Lancaster City Water - LU: \$500.00 Section 2(5)(i) 1st Offense \$500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>damaged during last years contract work. The serial number for the PA 1 Call that was used for the repair work is 20242502746. JVI hit an unmarked water service line for 545 Pershing Avenue during excavation. Lancaster City Water responded to make necessary repairs. JVI avr number is Avr2024oct030016." Photos were submitted.</p> <p>JVI Group Inc. submitted an AVR. Their AVR states, "Started digging knowing a gas service was to the left of the trench. needed to dig down to fit the trench box in then expose the sewer service to see what for fittings are needed to finish the repair. as we were digging down we hit a 2" water service to the building. Lancaster city was on site when the hit happened and as a group effort we were able to shut down water and Lancaster city showed up with vac truck and made the repair."</p> <p>Violations:</p> <p>Lancaster City Water - - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: The penalty is applied. Education is required.</p>	
50268	<p>Facility Owner: WILLISTOWN TWP Contractor/Excavator: PECO Project Owner: PECO Designer: PECO Other: Everstream Other: Verizon</p>	<p><u>On 10/3/2024 4:30:00 PM at ANDREWS RD, WILLISTOWN TWP, CHESTER</u> Everstream updated their mapping solutions since 2022. Violation and penalty removed. ***** Incident occurred on October 3rd, 2024 along Andrews Road, Willistown Township, Chester County.</p> <p>A sewer line was damaged.</p> <p>Willistown Township's Alleged Violation Report (AVR) states, "PECO Gas bored through the low pressure sewer lateral on Andrews in front of 22 Andrews. The line was correctly marked. PECO's contracted spot service had it measured at 24 Inch depth. They bored 34 inches down and hit the line."</p> <p>PECO's AVR states, "on 10/03/2024, USIC locators had marked the sewer pipes accurately. PECO excavators pulled a large rock into the sewer pipe. All Calls were made to repair and remediate the scene. 0 injured, 1 affected."</p> <p>No complex ticket was located by 811. Final Design was placed on 7/13/2022 and the next ticket, routine, placed on 7/31/2024. Tickets placed stated the project was 1 x 2,500.</p> <p>Violations:</p> <p>PECO Section 4(2) – Designer failed to request the line and facility information prescribed by section 2(4) from the One Call System not less than ten nor more than ninety business days before final design is to be completed.</p>	<p>PECO: \$1,500.00 Section 4(2) 1st Offense \$500.00</p> <p>Section 5(3) 1st Offense \$250.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(16) 1st Offense \$500.00</p> <p>Everstream: \$0.00</p> <p>Verizon: \$2,500.00 Section 2(4) Subsequent \$1,500.00</p> <p>Section 2(5)(v) 1st Offense \$500.00</p> <p>Section 2(5)(v) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 5(3) – Excavator failed to hold a preconstruction meeting prior to beginning a complex project. Education is required.</p> <p>Section 5(6)(ii) – Excavator failed to provide support and mechanical protection for known facility owner’s lines at the construction work site. Education is required.</p> <p>Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. Education is required.</p> <p>Verizon Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20242134557 Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20242531451 Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20221942138Education is required. Verizon last attended on 6/6/24 and this incident took place after attending.</p> <p>Everstream Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20221942138</p>	
50310	<p>Facility Owner: UGI Utilities Inc Contractor/Excavator: H&K GROUP INC. LEHIGH VALLEY DIVISION</p>	<p><u>On 10/4/2024 11:06:00 AM at 5887 HAMILTON BLVD, LOWER MACUNGIE TWP, LEHIGH</u> The incident occurred on Friday, October 4, 2024, at 5887 Hamilton Blvd, in Lower Macungie Township, Lehigh County.</p> <p>A UGI Utilities gas line was damaged by H&K Group Inc./Lehigh Valley Division (The Lehigh Valley Division).</p> <p>UGI stated that The Lehigh Valley Division was grading and when doing so an unmarked and unrecorded gas service stub was hit and damaged, creating a gas leak. The gas pipe that was damaged was not on UGI’s mapping or records.</p> <p>The Lehigh Valley Division did not give a summary of the event, but provided locating information and commented that a one call ticket was completed, and no gas line markings were in the area, and UGI was on site and did not know the line existed.</p> <p>Photos were provided by UGI and The Lehigh Valley Division showing the damaged line.</p> <p>*UGI Utilities is in violation of section: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: Penalty Applied</p> <p>*H&K Group Inc./Lehigh Valley Division is in violation of section: 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. Recommendation: Education Required. Zero Penalty but keep the violation because the AVR did not include a summary.</p>	<p>UGI Utilities Inc: \$1,000.00 Section 2(5)(i) 2nd Offense \$1,000.00</p> <p>H&K GROUP INC. LEHIGH VALLEY DIVISION: \$0.00 Section 5(16) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
50419	<p>Facility Owner: PECO Contractor/Excavator: HYBAR CONSTRUCTION Designer: Morrissey Architects Other: Blue Marsh Associates, INC</p>	<p><u>On 10/4/2024 3:00:00 PM at 1152 MORRIS RD, LOWER MERION TWP, MONTGOMERY</u> Incident occurred on October 4th, 2024 at 3pm, at 1152 Morris Road, Lower Merion Township, Montgomery County.</p> <p>A gas line was damaged. No PA1 call.</p> <p>PECO's Alleged Violation Report (AVR) states, "On 10/04/2024 was excavating without a locate request and damaged the gas service for this location. No marks present and no locate request made by contractor. 0 Injuries, 1 Cust interrupted."</p> <p>Hybar Construction was sent a request for an AVR on 11/4/2024. AVR was submitted on 11/11/2024.</p> <p>Hybar Construction's AVR states, "The operator was digging a trench to put under ground storm water piping in from the down spout at the corner of the house, and he hit the line. PECO was called immediately, they came out and fixed it."</p> <p>Hybar placed a ticket on 1/24/24 and the damage occurred on 10/4/24. Google Streetview from August 2024 shows that the excavator did not keep the marks up to date or request a remark. January ticket was also for demolition and not for unground installation.</p> <p>20233211815 is a preliminary design ticket by Blue Marsh Associates. No final design was found and the ticket indicates that the work was test pits for Morrissey Architects. No final design ticket was located.</p> <p>Violations:</p> <p>Hybar Construction Section 5(3) – Excavator failed to preserve mark-outs or request a remark. Education is required. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. Education is required.</p> <p>Morrissey Architects Section 4(2) – Designer failed to request the line and facility information prescribed by section 2(4) from the One Call System not less than ten nor more than ninety business days before final design is to be completed. Education is required.</p>	<p>HYBAR CONSTRUCTION: \$1,000.00 Section 5(3) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$500.00</p> <p>Morrissey Architects: \$500.00 Section 4(2) 1st Offense \$500.00</p>
50431	<p>Facility Owner: PECO Contractor/Excavator: FULL TILT GRADING Project Owner: HOMEOWNER</p>	<p><u>On 10/7/2024 1:00:00 PM at 6012 W MILL RD, WHITEMARSH TWP, MONTGOMERY</u> Full Tilt Accepts Violation with Education. *** Incident occurred on October 7th, 2024, at 1pm, at 6012 West Mill Road, Whitmarsh Township, Montgomery County.</p> <p>An electric line was damaged.</p> <p>PECO's Alleged Violation Report (AVR) states, "On 10/7/24 Full Tilt Grading Damaged a mis marked</p>	<p>PECO: \$1,000.00 Section 2(5)(i) 2nd Offense \$1,000.00</p> <p>FULL TILT GRADING: \$0.00 Section 5(16) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>underground secondary cable. The locator mis marked the cable by approximately 4.5 ft. It is unknown how or why the cable was mismarked. 0 Injuries, 1 Cust interrupted." AVR notes that 911 was called.</p> <p>PECO pictures show that the line was mismarked.</p> <p>Full Tilt Grading was mailed and emailed a request for an AVR on 11/4/24. No AVR has been received to date. Delivery receipt is attached.</p> <p>Violations</p> <p>PECO Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Education is required</p> <p>Full Tilt Grading Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. Education is required.</p>	
50442	<p>Facility Owner: COMCAST CABLEVISION Contractor/Excavator: Henkels & McCoy Project Owner: UGI Other: VERIZON PA LLC</p>	<p><u>On 10/8/2024 12:00:00 AM at 504 ARROWHEAD TRL, SPRING TWP, BERKS</u> The incident occurred on 10/08/2024, at 504 Arrowhead Trl, in Spring Township, Berks County.</p> <p>A communications line was hit and damaged. >51 Customers were affected.</p> <p>HENKELS AND MCCOY stated in their Alleged Violation Report (AVR) that While trenching to install a new gas service a mismarked comcast line was struck and damaged with a trencher. Utility was 4ft away from the marks. No pictures were provided.</p> <p>UGI UTILITIES INC stated in their AVR that “Contractor states that the Crew was trenching to install a gas service with they struck and damaged an unmarked comcast line”. No pictures were provided.</p> <p>COMCAST stated in their AVR that their lines were marked incorrectly. They note that over 51 people were affected. Pictures were provided. On 11/07/2024 Damage Prevention Investigator (DPI) sent an email asking for confirmation of the number of people that were affected. ***** *Ticket 20242691943 was requested by Henkels and McCoy to install a gas service with a response due by 9/27/2024. Verizon never responded. ***** Comcast is in violation of Section: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. This is a subsequent offense. A fine factor of .5 has been calculated as per the .59 Bureau of Investigation and Enforcement Damage Prevention Section Fine Factor Determination Sheet.</p>	<p>COMCAST CABLEVISION: \$3,000.00 Section 2(5)(i) Subsequent \$3,000.00</p> <p>VERIZON PA LLC: \$2,000.00 Section 2(5)(v) Subsequent \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Recommendation: The penalty is applied. Education is required. Education was completed by 7/09/2024. The incident occurred on 10/08/2024.</p> <p>Listed below are facility owners in violation of Act 50, Section 2(5)(v) Failed to respond to a routine One Call ticket</p> <p>Verizon is in violation of: Section 2(5)(v) – Failed to respond to a routine One Call ticket. This is a subsequent offense.</p> <p>Recommendation: The penalty is applied. Education is required. Facility owner education was completed by 8/13/2024.</p>	
50397	<p>Facility Owner: UGI Utilities Contractor/Excavator: DOLI Construction Project Owner: Boyertown Borough</p>	<p><u>On 10/8/2024 7:00:00 AM at MADISON STREET, BOYERTOWN BORO, BERKS</u> Doli Construction violation and penalty withdrawn.</p> <p>*****</p> <p>The incident occurred on 10/08/2024, at 7:00 AM, on Madison Street, in Boyertown Borough, Berks County. The closest intersection was 4Th Street.</p> <p>A gas line owned by UGI Utilities was damaged. 911 was called.</p> <p>UGI Utilities submitted an Alleged Violation Report (AVR). Their AVR states, "Excavator utilizing mechanized equipment, struck a correctly marked gas service." Photo was submitted.</p> <p>DOLI Construction submitted an AVR. Their AVR states, "Crew hit unmarked gas service for 600 E Highland St. We have a video but its too large to upload." Photo was submitted.</p> <p>Photo submitted by UGI shows the line was marked and damage occurred within the tolerance zone. A hit kit was used to show the distance from the line marking to the damage.</p> <p>Violations:</p> <p>DOLI Construction – (Withdrawn) - Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: The penalty is applied. Education is required.</p>	<p>DOLI Construction: \$0.00</p>
50462	<p>Facility Owner: COLUMBIA GAS OF PA INC Contractor/Excavator: NIANDO CONSTRUCTION, INC. Project Owner: MUNICIPALITY OF MT LEBANON Designer: GATEWAY ENGINEERS INC Other: VERIZON BUSINESS</p>	<p><u>On 10/8/2024 9:00:00 AM at MAPLETON AVENUE, MT LEBANON TWP, ALLEGHENY</u> The incident occurred on 10/08/2024 at MAPLETON AVENUE between Bower Hill Rd and Rae Ave in Mt. Lebanon Township in Allegheny County.</p> <p>A 2” medium pressure gas main was hit and damaged.</p> <p>NIANDO CONSTRUCTION INC stated in their Alleged Violation Report (AVR) that GAS LINE NOT MARKED AND REPAIR MAP PROVIDED INDICATES GAS LINE ON THE OTHER SIDE OF</p>	<p>NIANDO CONSTRUCTION, INC.: \$500.00 Section 5(3) 1st Offense \$500.00</p> <p>VERIZON BUSINESS: \$250.00 Section 9 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>THE STREET. 911 was notified. They added that the line was not marked correctly. Reports were provided.</p> <p>Columbia Gas of PA stated in their AVR that “Niando Construction was completing road reconstruction when they struck and damaged an accurately marked 2” medium pressure gas main with their backhoe. They notified 911 and Columbia Gas when the damage occurred. Columbia Gas responded immediately to make the area safe and complete repairs. Niando Construction had removed all hard surface for their road reconstruction, resulting in no visible marks. They did not call to have marks redone after this removal. No project information provided. Pictures and reports provided.</p> <p>MOUNT LEBANON PUBLIC WORKS DEPARTMENT gave no summary, but stated that the project was <\$400,000. And level “C” Subsurface Utility Engineering (SUE) was used. Reports were provided.</p> <p>GATEWAY ENGINEERS INC stated in their AVR that “Contractor was excavating within the middle of the roadway for the purposes of replacing an existing storm sewer and a 2" unmarked gas line was hit. They stated that the project was <\$400,000. And level “C” Subsurface Utility Engineering (SUE) was used. Reports were provided. *****</p> <p>Complex Project ticket 20241084206 was requested by Niando Construction Inc. on 4/17/2024 with the meeting held on 4/25/2024 at 9a.m. and the response due by 4/24/2024 VERIZON BUSINESS never responded. *****</p> <p>Connected to case 47500 *****</p> <p>NIANDO CONSTRUCTION, INC. is in violation of: Section 5(3) – Excavator failed to preserve mark-outs or request a remark. Recommendation: The penalty is applied. Education is required.</p> <p>Listed below are facility owners in violation of Act 50, Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project as described in section 5(3).</p> <p>VERIZON BUSINESS is in violation of: Section 9 – Failed to make the best efforts to comply with the Common Ground Alliance Best Practices – CGA 5-16 Federal and State Regulations for required training and Failed to make best efforts to comply with the Common Ground Alliance Best Practices Chapter 7(1)(B) Mandatory Education is considered as an alternative or supplement to penalties for offenders of the damage prevention laws and regulations. Recommendation: The penalty is applied. Education is required. The required education was not completed. Education was due by 7/09/2024 and by 9/10/2024.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Note *Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). Complex Project meeting ticket 20241084206 was never responded to. This violation is listed as a subsequent offense in Case 47500</p>	
50387	<p>Facility Owner: PEOPLES GAS COMPANY LLC</p> <p>Contractor/Excavator: BAIANO CONSTRUCTION INC</p> <p>Project Owner: Pittsburgh City Dept. of Mobility & Infrastructure</p>	<p><u>On 10/8/2024 9:45:00 AM at ONE WILD PL, PITTSBURGH CITY, ALLEGHENY</u> The incident occurred on Tuesday, October 8, 2024, at One Wild Place, in Pittsburgh City, Allegheny County.</p> <p>A gas line was damaged.</p> <p>Peoples Natural Gas (PNG) stated that Baiano Construction Inc failed to use prudent techniques within the tolerance zone, and explained while the contractor was doing sidewalk and curb restoration for the City of Pittsburgh, a correctly marked PNG service line was struck, creating damage; the line services the Pittsburgh Zoo. Baiano Construction was using mechanized equipment within the tolerance zone with clear indications of underground utilities, and they attempted to preserve markings by adding their own in orange paint but still struck the gas line.</p> <p>Baiano Construction stated that they failed to use prudent techniques within the tolerance zone and failed to preserve the markings, and explained that the mark was intact, as removing the old sandstone cubing block it was found to be set directly on said line. The bottom of the curbing measured at 21.5-inches from grade as did the top of the line damaged. The Baiano Construction crew called PNG immediately to report the damage, nobody was in danger, and no emergency response was needed.</p> <p>On Friday, November 8, 2024, emails and letters were sent requesting Alleged Violation Report's (AVR) from Baiano Construction Inc, and from Pittsburgh City Department of Mobility and Infrastructure, the project owner. There was no response from Pittsburgh City Department of Mobility and Infrastructure and no AVR was submitted. Baiano Construction submitted their AVR on 11/12/2024.</p> <p>*Baiano Construction Inc is in violation of section: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: Education Required and Penalty Applied</p> <p>*Pittsburgh City Department of Mobility and Infrastructure is in violation of section: 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 10 Business Days of a line strike. Recommendation: Education Required and Penalty Applied</p>	<p>BAIANO CONSTRUCTION INC: \$500.00 Section 5(4) 1st Offense \$500.00</p> <p>Pittsburgh City Dept. of Mobility & Infrastructure: \$500.00 Section 6.1(7) 1st Offense \$500.00</p>
50461	<p>Facility Owner: Columbia Gas of PA - South</p>	<p><u>On 10/8/2024 9:52:00 AM at 221 WHITNEY CHASE DR, NORTH HUNTINGDON TWP, WESTMORELAND</u> Incident occurred on October 8th,</p>	<p>North Huntingdon Township: \$7,500.00 Section 5(4) 3rd Offense</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>Contractor/Excavator: North Huntingdon Township</p> <p>Project Owner: NHTwp</p>	<p>2024, at 9:52am, at 221 Whitney Chase Drive, North Huntingdon Township, Westmoreland County.</p> <p>A gas line was damaged.</p> <p>Columbia Gas Company's AVR states, "North Huntingdon Township was digging to replace a catch basin and repair some soft spots in the roadway when they struck and damaged an accurately marked 1" plastic, company-side gas service. They notified 911 and Columbia Gas when the damage occurred. Columbia Gas responded immediately to make the area safe and complete repairs. Earlier that morning, the Columbia Gas locator met with Vern Mardis onsite to review the locate marks and make sure North Huntingdon Township understood them. They acknowledged they did but proceeded to dig directly on the marks with mechanized equipment."</p> <p>North Huntingdon Township was mailed and emailed a request for an AVR on 11/8/2024. Email read receipt is attached. No AVR has been received to date.</p> <p>Pictures from Columbia Gas Company show that the line was marked within the tolerance zone.</p> <p>The DPC voted to send Huntingdon Township to required education on 8/13/2024 & 10/8/2024. Huntingdon Township has not completed the required education.</p> <p>Violations:</p> <p>North Huntingdon Township Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Education is required. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. Education is required. Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. Education is required. North Huntingdon Township was ordered by the DPC to attend the following education within 60 days and failed to do so. All fines raised to \$2500.00 for failure to comply with all DPC ordered remedies. 39675 8/13/2024 Excavator and Project Owner. 40394 10/8/24 Designer, Excavator, and Project Owner.</p>	<p>\$2,500.00</p> <p>Section 5(16) 3rd Offense \$2,500.00</p> <p>Section 5(17) 3rd Offense \$2,500.00</p>
50505	<p>Facility Owner: AQUA PENNSYLVANIA INC</p> <p>Contractor/Excavator: UTILITY LINE SERVICES</p> <p>Project Owner: PECO</p> <p>Other: BUCKS COUNTY WATER AND SEWER AUTHORITY</p> <p>Other: SPRINGFIELD TOWNSHIP OF</p>	<p><u>On 10/8/2024 10:30:00 AM at AVONDALE RD, SPRINGFIELD TWP, MONTGOMERY</u> Springfield Township accepts.</p> <p>***</p> <p>BCWSA now accepts.</p> <p>Bucks County Water Sewer Authority is disputing their Violations for 2(4) with the Conflict DCTF responses made. BCWSA claims they had direct communication with the designer via email, but were unable to provide copies of the emails.</p> <p>*****</p>	<p>AQUA PENNSYLVANIA INC: \$500.00 Section 2(5)(i) 1st Offense \$500.00</p> <p>PECO: \$5,000.00 Section 2(5)(v) Subsequent \$2,000.00</p> <p>Section 2(5)(v)</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>MONTGOMERY COUNTY Other: Verizon</p>	<p>Incident occurred on October 8th, 2024, at 10:30am along Avondale Road, Springfield Township, Montgomery County.</p> <p>A water line was damaged.</p> <p>Aqua's Alleged Violation Report (AVR) states, "SERVICE LINE WAS MISMARKED. 216 GLENDALOUGH RD"</p> <p>Utility Line Services' AVR states, "While the crew was working in the area of 216 Glendalough Road to install a gas main they damaged a water service 9' off the mark."</p> <p>PECO's AVR states, "ULS hit a mismarked water service 6 feet off of the mark, Aqua had to shut down the water main to the development the service was pulled out of the main, Aqua mark out arrived and said they mismarked the service. ULS was not at fault."</p> <p>Final Design was placed on 10/31/2022 and the complex project meeting ticket was placed on 9/10/2024. Incident occurred on 10/8/2024 and PECO submitted their AVR on 11/18/2024.</p> <p>Violations:</p> <p>Aqua Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.</p> <p>PECO Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20242744013 Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20242744017 Section 4(2) – Designer failed to request the line and facility information prescribed by section 2(4) from the One Call System not less than ten nor more than ninety business days before final design is to be completed. Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 10 Business Days of a line strike.</p> <p>Verizon Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20223042897 Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20223041483 Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20242543239</p> <p>Bucks County Water and Sewer Authority Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20242744013 Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20242744017 Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20223042897</p>	<p>Subsequent \$2,000.00</p> <p>Section 4(2) 1st Offense \$500.00</p> <p>Section 6.1(7) 1st Offense \$500.00</p> <p>BUCKS COUNTY WATER AND SEWER AUTHORITY: \$1,500.00</p> <p>Section 2(5)(v) 1st Offense \$500.00</p> <p>Section 2(4) 1st Offense \$250.00</p> <p>Section 2(4) 1st Offense \$250.00</p> <p>Section 2(5)(v) 1st Offense \$500.00</p> <p>SPRINGFIELD TOWNSHIP OF MONTGOMERY COUNTY: \$0.00</p> <p>Section 2(5)(vii) 1st Offense \$0.00</p> <p>Section 2(5)(viii) 1st Offense \$0.00</p> <p>Section 2(5)(v) 1st Offense \$0.00</p> <p>Section 2(5)(v) 1st Offense \$0.00</p> <p>Verizon: \$5,000.00</p> <p>Section 2(4) Subsequent \$1,500.00</p> <p>Section 2(4) Subsequent \$1,500.00</p> <p>Section 2(5)(viii) Subsequent \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20223041483</p> <p>Springfield Township of Montgomery County Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20242744013. Education is required. Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20242744017. Education is required. Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20242821237. Education is required. Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20242821918. Education is required.</p>	
50394	<p>Facility Owner: NATIONAL FUEL GAS Contractor/Excavator: E E Austin & Son Inc Project Owner: ERIE INSURANCE - O'DONNELL HOUSE Other: AT&T LOCAL SERVICES Other: DWYER PLUMBING Other: VERIZON PA LLC</p>	<p><u>On 10/8/2024 12:00:00 PM at 410 French Street, ERIE CITY, ERIE</u> Verizon disagreed and provided documentation. The violation of 2(5)(v) is withdrawn. * AT&T disputed. The violation was applied for not answering the ticket when it should have said they were late because they answered 1 day late. Violation and penalty have been removed. ***** The incident occurred on 10/08/2024 at 410 French St in Erie City in Erie County. *No Damage Near miss with a gas line while excavating. No One call ticket was submitted for this excavation. NATIONAL FUEL GAS stated in their Alleged Violation Report (AVR) that Excavator working over top of natural gas facilities without POCS ticket submission. Please see attached. Pictures were provided. E E Austin & Son Inc was mailed an AVR request letter on 11/12/2024. On 11/12/2024 DPI returned a call to David Passmore from EE Auston who stated that they work almost exclusively with Dwyer Plumbing. They hire Dwyer Plumbing and Dwyer uses some of EE Auston's guys to spot while they are digging. DPI explained the process and why we are requesting an AVR from them. DPI asked them to submit the AVR in the OneCall system. DPI clarified that she is not working for OneCall but is with the PUC. David said that they put in a OneCall ticket because they were told to do so by PNG. He also said that PNG told them it was marked and OK to dig. E E Austin & Son Inc stated in their AVR that “First of all I could not change county or Municipality in this report. County-Erie Munic-Erie. Dwyer Excavating called in one call for this property and area was CLEARLY marked. Dwyer does 98% of our excavation and was working in another area on Erie Insurance Campus and occupied. Due to meeting schedules for Erie Insurance noise could not be made and we had a 2 day window to complete this excavation so EE Austin started to demo sidewalks and dig. NOTHING was DAMAGED because area was clearly marked. National fuel showed up and stopped us.He told us we could not</p>	<p>E E Austin & Son Inc: \$1,000.00 Section 5(2.1) 1st Offense \$1,000.00</p> <p>ERIE INSURANCE - O'DONNELL HOUSE: \$500.00 Section 6.1(7) 1st Offense \$500.00</p> <p>AT&T LOCAL SERVICES: \$0.00</p> <p>VERIZON PA LLC: \$500.00 Section 2(5)(i) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>be digging under Dwyer ticket even though the area was clearly marked and Dwyer was on campus working for us. I was under the assumption since there was a ticket and area was clearly marked we could proceed. I ask how we could proceed and he said call a ticket in under our company so I immediately did and explained how we had our 2 day window to make noise. He received the request within minutes after my call and since area was already marked he said he was good. Also a gentleman from USIC was on site and after he received the ticket he said he was good for us to go as well because the area was already clearly marked. In all honesty I did not think we were doing anything wrong as one call was contacted, the area was clearly marked and we were not trying to pull any fast ones. I now know the rule 811 prior to excavating has to be called in by the actor of the operation and not called in by just anyone. Project is listed as <&400,000. 14 ft length and Level "C" Subsurface Utility Engineering (SUE)</p> <p>Note *Ticket 20232511382 was provided with AVR2024NOV150018, but this ticket is not connected to this area. Excavator E E AUSTIN AND SON INC stated that he mistakenly entered the incorrect county and municipality in the AVR that was submitted and he could not change it.</p> <p>Compliance Research results: E E Austin has placed notifications with PA One Call in the past.</p> <p>Erie Insurance was mailed an AVR request letter on 11/12/2024. On 11/26/2024 the Representative from Erie Insurance left a message. DPI returned a call to Erie Insurance and explained why an AVR request letter was sent to them. DPI also told them that we do need an AVR filled out and if they have any issue with that, they can reach out to OneCall and left the telephone number to OneCall. No AVR has been received to date.</p> <p>*****</p> <p>*Ticket 20242572150 was requested by Dwyer Plumbing on 9/13/2024 to replace steps and sidewalk. Ticket responses were due by 9/17/2024. Project was expected to last 3 weeks. All facility owners responded promptly.</p> <p>*Update ticket Ticket 20242572150 was requested by Dwyer Plumbing on 9/13/2024 to replace steps and sidewalk. Ticket responses were due by 9/27/2024. Project was expected to last 3 weeks. All facility owners responded promptly. Work in progress. Remark requested.</p> <p>AT&T did not respond "clear" until 9/29/2024.</p> <p>*Insufficient Ticket 20242821391 was requested by E E Auston and Sons Inc on 10/08/2024 with a response due by 10/10/2024 and a lawful start date of 10/11/2024 to replace steps and sidewalk. Excavation is scheduled to begin on 10/08/2024.</p> <p>Verizon did not respond "Field Marked" until 10/14/2024. Please note the "No facilities involved" and the "Filed marked" responses for the same exact project and address on the two separate tickets.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>E E Austin & Son Inc is in violation of: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Recommendation: The penalty is applied. Education is required.</p> <p>ERIE INSURANCE - O'DONNELL HOUSE is in violation of: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 10 Business Days of a line strike. Recommendation: The penalty is applied. Education is required. *****</p> <p>Listed below are facility owners in violation of Act 50, Section 2(5)(v) Failed to respond to a routine One Call ticket and 2(5)(v) Failed to respond to a routine One Call ticket within the required amount of time.</p> <p>AT&T LOCAL SERVICES is in violation of: Section 2(5)(v) – Failed to respond to routine One Call ticket 20242572150. This is a third offense. Recommendation: The penalty is applied. The required education was completed by 10/07/2024.</p> <p>VERIZON PA LLC is in violation of: Section 2(5)(v) Failed to respond to a routine One Call ticket within the required amount of time. This is a subsequent offense. Ticket 20242690682 was due by 9/27/2024. On 10/09/2024 the response was “Scheduled Mark”.</p> <p>Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Verizon did not respond “Scheduled mark” to ticket 20242690682 until 10/09/2024. On 10/10/2024 the response became “clear no facilities”. Ticket 20242690682 conflicts with responses to tickets 20242821391 and 20242572150, which were requested for the same exact area and “field Marked”.</p> <p>Recommendation: The penalties are applied. The required education was compiled by 9/10/2024. Education is required. Tickets and incident are after this date.</p>	
50513	<p>Facility Owner: National Fuel Gas Contractor/Excavator: Terra Works Inc Project Owner: Summit Township Sewer Authority Designer: GREENMAN PEDERSEN INC Other: Velocity Net Communications</p>	<p><u>On 10/8/2024 3:00:00 PM at OLIVER RD, SUMMIT TWP, ERIE STSA</u> accepts resolution. *****</p> <p>Incident occurred on October 8, 2024, at 3pm, Oliver Road, Summit Township, Erie County.</p> <p>A gas line was damaged. 911 was notified.</p> <p>National Fuel Gas' Alleged Violation Report (AVR) states, "Excavator failed to use prudent digging techniques within tolerance zone and struck natural gas service. Please see attachments."</p> <p>Greenman Pedersen's AVR states, "Contractor was hand digging down 8-10” at a time in the middle of their ditch 2’ each side of the one call markings. Would then peel</p>	<p>Terra Works Inc: \$1,000.00 Section 5(4) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$500.00</p> <p>Summit Township Sewer Authority: \$0.00 Section 6.1(7) 1st Offense \$0.00</p> <p>Velocity Net Communications: \$12,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>away 6-8” with excavator bucket to get down near hand dug depth. Continued this until service line was hit. In the excavation for the sewer, the gas line made a vertical bend making it shallower than the area that was hand dug."</p> <p>Terra Works and Summit Township Sewer Authority were mailed and emailed requests for AVRs on 11/17/2024.</p> <p>Terra Works' AVR states, "Line was located by hand shoveling. after line was exposed our operator hit the line while trying to move a trench box." AVR was submitted on 11/18/24.</p> <p>Summit Township Sewer Authority's AVR states, "Contractor was hand digging down 8-10” at a time in the middle of their ditch 2’ each side of the one call markings. Would then peel away 6-8” with excavator bucket to get down near hand dug depth. Continued this until service line was hit. In the excavation for the sewer, the gas line made a vertical bend making it shallower than the area that was hand dug." AVR was submitted on 11/17/24.</p> <p>Violations:</p> <p>Terra Works Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Education is required. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. Education is required.</p> <p>Summit Township Sewer Authority Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 10 Business Days of a line strike. Education is required.</p> <p>Velocity Net Communications Velocity Net Communications is delinquent on education that was due 9/10/2024 Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20212654024. Education is required. Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20212653651. Education is required. Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20212653410. Education is required. Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20212011425. Education is required. Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20221664210. Education is required.</p>	<p>Section 2(4) 1st Offense \$2,500.00</p> <p>Section 2(4) 2nd Offense \$2,500.00</p> <p>Section 2(4) 2nd Offense \$2,500.00</p> <p>Section 2(4) 2nd Offense \$2,500.00</p> <p>Section 2(5)(viii) 2nd Offense \$2,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
50377	<p>Facility Owner: PECO Contractor/Excavator: GasTec Enterprises Other: Comcast Cablevision Other: Verizon</p>	<p><u>On 10/8/2024 11:00:00 PM at LINCOLN DR E, UPPER DUBLIN TWP, MONTGOMERY</u> Comcast accepts and is submitting a payment.</p> <p>****</p> <p>The incident occurred on 10/09/2024, at 11:00 AM, on Lincoln Drive East, in Upper Dublin Township, Montgomery County. The closest intersection is Lincoln Drive.</p> <p>An electric line owned by PECO was damaged.</p> <p>PECO submitted an Alleged Violation Report (AVR). Their AVR states, "CONTRACTOR WORKING AT THIS LOCATION TO REPLACE A LEAKING PROPANE TANK AND PROPANE LINES STRUCK AN UNMARKED SECONDARY WHILE EXCAVATING WITH A MINI EXCAVATOR. THE LOCATION WAS NOT MARKED. CONTRACTOR WAS AWARE OF THE UNDERGROUND FACILITIES AT THIS LOCATION AND HAD CIRCLED THE UNDERGROUND TRANSFORMER IN WHITE. PADMOUNT TRANSFORMER WAS VISIBLE. CONTRACTOR UPON ARRIVING SHOULD HAVE PERFORMED A VISUAL INSPECTION OF THE LOCATION, AT WHICH TIME HE WOULD HAVE BEEN AWARE THAT THE LOCATION HAD NOT BEEN MARKED. CONTRACTOR VIOLATED PA ACT 50, 5(20), WHICH REQUIRES AN EXCAVATOR TO RENOTIFY THE ONE CALL SYSTEM OF AN UNMARKED OR INCORRECTLY MARKED FACILITY, IF AN ORIGINAL, PROPER, NONEMERGENCY LOCATE REQUEST HAS BEEN MADE TO THE ONE CALL SYSTEM AND, UPON ARRIVAL AT THE PROPOSED WORK SITE, IT IS APPARENT TO THE EXCAVATOR THAT THERE IS AN UNMARKED OR INCORRECTLY MARKED FACILITY. AN EXCAVATOR MAY NOT BEGIN EXCAVATING IN THE AFFECTED AREA OF THE WORK SITE UNTIL AFTER RECEIVING SUFFICIENT INFORMATION FROM THE FACILITY OWNER TO SAFELY EXCAVATE."</p> <p>GasTec Enterprises submitted an AVR. Their AVR states, "One call tickets 20242712977 and 20242712961 were submitted on 9/27/24 for work to begin 10/9. Response ticket stated that utilities at address were marked. No markings were placed at dig area - excavators expected dig area clear. On morning of 10/9, excavation begin to install a UG propane line. around 830am a live electric supply line was struck. work halted immediately. OneCall and PECO notified. Attached images show no utility markings." Photos were submitted.</p> <p>The project owner is unknown.</p> <p>PECO did not respond to the routine ticket, until after the emergency ticket was requested. Lines were not marked prior to the damage occurring.</p>	<p>PECO: \$2,500.00 Section 2(5)(v) 2nd offense \$500.00</p> <p>Section 2(5)(vii) 1st Offense \$1,000.00</p> <p>Section 2(5)(i) 2nd Offense \$1,000.00</p> <p>Comcast Cablevision: \$1,000.00 Section 2(5)(v) 2nd Offense \$1,000.00</p> <p>Verizon: \$1,000.00 Section 2(5)(v) Subsequent \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Routine ticket 20242712961 had a response due date of 10/08/2024. PECO responded on 10/8/2024 4:36:37 "SCHEDULED DATE & TIME LINES WILL BE MARKED BY: 08 Oct 2024 2359". PECO replied 'FIELD MARKED' on 10/9/2024 11:43:13.AM. The line was entered as 'marked' after the initial emergency ticket (20242831983) was requested. Initial emergency ticket was requested on 10/09/2024 at 11:29 AM.</p> <p>Violations:</p> <p>Verizon – - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Routine ticket 20242712961 had a response due date of 10/08/2024. Verizon responded 'INSUFFICIENT INFORMATION. DO NOT DIG' on 10/17/2024. Recommendation: The penalty is applied. Education is required.</p> <p>PECO – - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Routine ticket 20242712961 had a response due date of 10/08/2024. PECO responded on 10/8/2024 4:36:37 "SCHEDULED DATE & TIME LINES WILL BE MARKED BY: 08 Oct 2024 2359". PECO replied 'FIELD MARKED' on 10/9/2024 11:43:13.AM. - Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Emergency ticket 20242831983-000. A renotify ticket was requested due to lack of response. - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: The penalty is applied. Education is required.</p> <p>Comcast – - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Routine ticket 20242712961 had a response due date of 10/08/2024. Comcast responded 'FIELD MARKED' on 10/16/2024. Recommendation: The penalty is applied. Education is required.</p>	
50436	Facility Owner: PECO Contractor/Excavator: ELITE ELECTRICAL	<p><u>On 10/9/2024 9:00:00 AM at 1775 MACDADE BLVD, RIDLEY TWP, DELAWARE</u> Incident occurred on October 9th, 2024, at 9am at 1775 MacDade Boulevard, Ridley Township, Delaware County.</p> <p>A gas line was damaged. No PA1 call.</p> <p>PECO's Alleged Violation Report (AVR) states, "CONTRACTOR VIOLATED PA ACT 50, Contractor Elite Electric was digging with out a Pa One Call onsite to run electrical conduit when they hit the 1.25" gas service. 0 injured, 1 affected." AVR notes that 911 was not notified.</p> <p>Elite Electrical Contractor, LLC was mailed and emailed on 11/20/24</p>	<p>ELITE ELECTRICAL: \$2,750.00 Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$500.00</p> <p>Section 5(17) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>DPI called project manager who sent the correct Elite Electrical and their contact information.</p> <p>Violations:</p> <p>Elite Electrical Contractor, LLC Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Education is required. Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. Education is required. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. Education is required. Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. Education is required.</p>	
50602	<p>Facility Owner: UGI - Spacesaver Contractor/Excavator: KINSLEY CONSTRUCTION Project Owner: UGI Designer: UGI _ Spacesaver Other: PPL Other: RETTEW ASSOCIATES INC</p>	<p><u>On 10/9/2024 11:00:00 AM at FOUNTAIN AVE, MANHEIM TWP, LANCASTER</u> The incident occurred on 10/09/2024 on Fountain Ave in Manheim Township in Lancaster County.</p> <p>A gas line was hit and damaged. 911 was not notified.</p> <p>KINSLEY CONSTRUCTION stated in their Alleged Violation Report (AVR) that “Operator removed 12in of blacktop and encountered another 10in large of ballast. Crew was unable to prudently dig due to the compacted ballast. The operator used the trackhoe to loosen up the ballast so crew could hand dig to spot the gas service. When loosening up the rock, the gas service was damaged and UGI was notified. The gas service had a EFV that prevented gas from escaping. The gas service was .5" PE line inserted in 1" HDPE. Crew was given UGI permission to make repairs and customer was back in service within an hour. The UGI gas service was approx. 18inches below road surface”. No 911 call was made. 1 customer was affected. Reports and pictures were provided.</p> <p>UGI the facility owner, designer and the project owner was mailed and emailed an AVR request on 11/18/2024. UGI AVR stated that “Excavator Utilizing mechanized equipment, struck a correctly marked gas service. Contractor did not call 911 and did not notify 811 of the facility damage. Project is listed to be >\$400,000. Pictures and report were provided. On 12/09/2024 an email was sent asking about the UGI line repair, how UGI was notified and why UGI responded conflict to design tickets and did not update to a final response. ***** *Final Design ticket 20240330379 was submitted by UGI on 2/02/2024 with a response due by 2/16/2024. PPL had no response until 2/21/2024.</p>	<p>KINSLEY CONSTRUCTION: \$1,500.00 Section 5(4) 1st Offense \$500.00</p> <p>Section 5(8) 1st Offense \$1,000.00</p> <p>UGI: \$0.00</p> <p>PPL: \$500.00 Section 2(4) 1st Offense \$250.00</p> <p>Section 2(4) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>*Final Design ticket 20240330380 was submitted by UGI on 2/02/2024 with a response due by 2/16/2024. PPL had no response until 2/21/2024. *****</p> <p>KINSLEY CONSTRUCTION is in violation of: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. Recommendation: The penalty is applied. Education is required. ****</p> <p>Listed below are facility owners in violation of Act 50, Section 2(4) – Failed to respond to Designer’s request for information within 10 Business days. Violation 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project as described in section 5(3).</p> <p>PPL is in violation of: Section 2(4) – Failed to respond to designer’s request for information within 10 business days. Tickets 20240330379 and 20240330380 were not responded to until 2/21/2024. *See ticket information above. Recommendation: The penalty is applied.</p>	
50610	<p>Facility Owner: PECO AN EXELON COMPANY Contractor/Excavator: A J C CONSTRUCTION</p>	<p><u>On 10/9/2024 11:00:00 AM at 1012 PLYMOUTH RD, PLYMOUTH TWP, MONTGOMERY</u> Incident occurred on October 9th, 2024, at 11am at 1012 Plymouth Road, Plymouth Township, Montgomery County.</p> <p>A gas line was damaged.</p> <p>PECO's Alleged Violation Report (AVR) states, "On 10/9/24 AJC Construction was digging a drainage ditch with a backhoe and severed the ½” Gas service feeding the above location. No locate request was made by AJC and there are no marks indicating the location of underground utilities. 0 Injuries, 1 Cust interrupted." AVR notes that 911 was notified.</p> <p>DPI emailed PECO for their USIC damage report.</p> <p>AJC Construction's AVR is blank, except for they claim to have hit a sewer line, but 811 provided the emergency damage ticket. No PA1 call ticket was made prior to the excavation. 811 notes that AJC Construction has placed one calls in the past.</p> <p>Please see PECO damage report with photos.</p> <p>Violations:</p> <p>AJC Construction Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Education is required.</p>	<p>A J C CONSTRUCTION: \$1,000.00 Section 5(2.1) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
50456	<p>Facility Owner: Peoples Gas Contractor/Excavator: PITTSBURGH WATER & SEWER AUTHORITY Project Owner: PITTSBURGH WATER & SEWER AUTHORITY - Placeholder</p>	<p><u>On 10/9/2024 12:38:00 PM at 3224 BRIGHTON RD, PITTSBURGH CITY, ALLEGHENY</u> The incident occurred on 10/09/2024, at 12:38 PM, at 3224 Brighton Road, in Pittsburgh City, Allegheny County.</p> <p>A gas line owned by Peoples Gas was damaged. 911 was called.</p> <p>Peoples Gas submitted an Alleged Violation Report (AVR). Their AVR states, "On 10/9/2024, PWSA was digging on an emergency one call to repair a water main break. PWSA struck an accurately marked PNG 1.25" PL SL. PNG crews reported to site and repaired." Photos were submitted.</p> <p>PITTSBURGH WATER & SEWER AUTHORITY submitted an AVR. Their AVR states, "PWSA digging and hit an accurate marked gas service line. Peoples gas responded and made repairs."</p> <p>Violations:</p> <p>PITTSBURGH WATER & SEWER AUTHORITY – - Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: The penalty is applied. Education is required.</p>	<p>PITTSBURGH WATER & SEWER AUTHORITY: \$1,000.00 Section 5(4) 2nd Offense \$1,000.00</p>
50597	<p>Facility Owner: LITITZ BOROUGH Contractor/Excavator: KINSLEY CONSTRUCTION Project Owner: UGI Designer: UGI _ Spacesaver</p>	<p><u>On 10/10/2024 9:00:00 AM at FRONT ST, LITITZ BORO, LANCASTER</u> Incident occurred on 10/10/2024 at 35 Front St in Lititz Borough in Lancaster County.</p> <p>A water lateral was hit and damaged.</p> <p>KINSLEY CONSTRUCTION INC (KCI) stated in their Alleged Violation Report (AVR) that “Crew damaged copper water lateral to 35 Front ST while excavating to install UGI gas main. Marks were approx. 42" off from the actual location of the service. Lititz Borough was notified and they arrived onsite to make repairs. Repairs took approx. 4hrs to complete”. No project information was provided. Picture and Reports were provided.</p> <p>Lititz Borough was emailed and mailed an AVR request letter on 11/15/2024. They stated that “We attended the complex project meeting, the damage was outside the tolerance zone. The line was not marked within the tolerance zone. The excavator has hit 2 of Lititz Borough's utility lines within the last 6 months. One sewer line and one water line. No pictures were provided.</p> <p>UGI was emailed and mailed an AVR request letter on 11/15/2024. They stated in their AVR that “Contractor states that the Crew damaged copper water lateral to 35 Front ST while excavating to install UGI gas main. Marks were approx. 42" off from the actual location of the service. Lititz Borough was notified and they arrived onsite to make repairs. Repairs took approx. 4hrs to complete. No pictures were provided. No Project information was provided. The AVR request letter</p>	<p>LITITZ BOROUGH: \$750.00 Section 2(10) 1st Offense \$0.00</p> <p>Section 2(4) 1st Offense \$250.00</p> <p>Section 2(5)(i) 1st Offense \$500.00</p> <p>UGI: \$500.00 Section 4(2) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>specifically asks for the cost and SUE information about the project. The Final Design Ticket was requested on 10/06/2023. AVR2024NOV270004 states that the excavation began on 10/10/2024. That is 253 business days from Final Design to Construction. On 11/27/2024 an email was received stating that there was a miscommunication with their excavator for this case, and that is why the AVR was not submitted when the damage occurred. AVR was submitted when requested and they may not have been notified about the damage when it occurred.</p> <p>Final Design Ticket 20232792725 was requested by UGI on 10/06/2023 with a response due by 10/23/2023. Lititz Borough did not respond until 10/27/2024.</p> <p>*Complex Project Ticket 20242431177 was requested by Kingsley Construction Inc on 8/30/2024 with the meeting to be held on 9/05/2024 and the response due by 9/04/2024. UGI responded late on 9/05/2024 with field marked. Lititz Borough, Windstream and Comcast responded that they will attend the meeting, but never updated this information. They stated that they did attend the meeting on the AVR they submitted.</p> <p>*Ticket 20242633106 was requested by Kingsley Construction Inc on 9/19/2024 with a response due by 9/23/2024. UGI had a conflict on 9/19/2024, scheduled mark on 9/23/2024, had no access on 9/27/2024 and rescheduled the marking, and on 10/02/2024 UGI was field marked.</p> <p>*Ticket 20242753088 was requested by Kingsley Construction Inc on 10/01/2024 with a response due by 10/03/2024. All facility owners responded timely. *****</p> <p>LITITZ BOROUGH is in violation of: Section 2(4) – Failed to respond to designer’s request for information within 10 business days. Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. This is a first-time violation and an AVR was submitted after the AVR request letter was sent. The penalty of \$500 is reduced to a warning. Recommendation: The penalties are applied. Education is required.</p> <p>UGI is in violation of: Section 4(2) – Designer failed to request the line and facility information prescribed by section 2(4) from the One Call System not less than ten nor more than ninety business days before final design is to be completed.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
50533	Facility Owner: UGI UTILITIES INC Contractor/Excavator: G & R CHARLES EXCAVATING Project Owner: SUNBURY CITY Designer: CES ENGINEERING LLC	<p>Recommendation: The penalty is applied.</p> <p><u>On 10/10/2024 11:11:00 AM at 9 Packer Street, SUNBURY CITY, NORTHUMBERLAND</u> The incident occurred on Thursday, October 10, 2024, at 9 Packer Street, in Sunbury City, Northumberland County.</p> <p>A UGI Utilities Gas line was damaged.</p> <p>UGI stated that G and R Charles Excavating was working for Sunbury City, installing a sewer line, when a 1-inch PE service line that was exposed crossing open trench, was hit with hydraulic tamper on an excavator. G & R Charles Excavating, had squeezed off the gas line before UGI had arrived.</p> <p>G and R Charles Excavating stated, while they were installing an 8-inch sewer line, a gas line was located and while compacting the backfill in the trench the gas line was hit and damage.</p> <p>On Thursday, November 21, 2024, an email and letter was sent to G & R Charles Excavating, requesting an Alleged Violation Report (AVR). They submitted their AVR on 11/27/2024.</p> <p>On Monday, December 2, 2024, an email and letter was sent to the project owner, Sunbury Municipal Authority requesting an AVR. They submitted an AVR on 12/6/2024</p> <p>*G and R Charles Excavating is in violation of section: 5(6)(ii) – Excavator failed to provide support and mechanical protection for known facility owner’s lines at the construction work site. 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. Recommendation: Education Required. Penalty Applied to 5(6)(ii). For 5(16) zero penalty but keep the violation, AVR was submitted late</p>	<p>G & R CHARLES EXCAVATING: \$500.00 Section 5(16) 1st Offense \$0.00</p> <p>Section 5(6)(ii) 1st Offense \$500.00</p>
50464	Facility Owner: Peoples Gas Contractor/Excavator: Pennsylvania American Water (PAWC) Project Owner: Pennsylvania American Water (PAWC) - Placeholder	<p><u>On 10/13/2024 12:35:00 PM at 5727 KINGS SCHOOL RD, BETHEL PARK BORO, ALLEGHENY</u> Peoples Gas violation withdrawn.</p> <p>*****</p> <p>The incident occurred on 10/13/2024 at 12:35 PM, at 5727 Kings School Road, in Bethel Park Borough, Allegheny County.</p> <p>A gas line owned by Peoples Gas was damaged. 911 was called.</p> <p>Peoples Gas submitted an Alleged Violation Report (AVR). Their AVR states, "ON 10-13/24 PA AMERICAN WATER DIGGING TO REPAIR WATER ELAK STRUCK PNG 3IN PE M/L AT 5727 KINGS SCHOOL RD. NO SURFACE ACCESS TO TRACER WIRE FOR PE PIPE. WTR CO STRUCK 3 IN PE RD CROSSING. CROSSING WAS MARKED BY WIRE IN NEAR BY TEST STATION THAT GAVE LOCATOR A SIGNAL. MARKS WERE OFF BY 36 INCHES." Photos were submitted.</p>	<p>Peoples Gas: \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Pennsylvania American Water (PAWC) submitted an AVR. Their AVR states, "PA American Water while digging to repair a leak hit and damaged a Peoples Gas main that was off the marks by 3'. The main was marked as coming straight across King School from Willow Terrace and "T'd" into another main running down King School. Where the line was hit in our excavation it was offset with 90's which were not identified with markings. It was 18" below grade on top of (crossing) a large diameter concrete storm drain. Because the way the repair was made it is probably less than 18" below the surface, which does not meet federal minimum. The Peoples Service driver did state that it was mis-marked, and my photos were taken after he placed his hit kit. The gas was a plastic line and was laid on top of our main along with the storm drain and other old steel gas lines (abandoned). The gas main was medium pressure."</p> <p>Violations:</p> <p>Peoples Gas – (Withdrawn) - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: The penalty is applied. Education is required.</p>	
50733	<p>Facility Owner: PECO Contractor/Excavator: FS LANDSCAPING CONTRACTORS INC Contractor/Excavator: FS LANDSCAPING CONTRACTORS INC Project Owner: HOMEOWNER Other: SCOTT PAYNE OUTDOOR POOLS</p>	<p><u>On 10/14/2024 10:00:00 AM at 814 W CUB HUNT LN, WEST WHITELAND TWP, CHESTER</u> The incident occurred on 10/14/2024 at 814 W CUB HUNT LN in WEST WHITELAND TWP in Chester County.</p> <p>A gas line was hit and damaged.</p> <p>PECO stated in their Alleged Violation Report (AVR) that “FS LANDSCAPING CONTRACTORS INC was working for the homeowner installing fencing in the back yard of residence, without a POC, when they struck the gas line for the residence. Edgar Melendres was the onsite foreman for the contractor. 0 Injured, 1 affected”. On 11/07/2024 Damage Prevention Investigator sent an email to PECO asking for pictures, bills, and the homeowner name. On 11/07/2024 email was received with the property owners name and pictures. None of the pictures showed mechanized equipment. One of the pictures in the USIC report showed a post digger that was not mechanized.</p> <p>Compliance Research Results state that: Contractor has placed One Call notifications with PA One Call in the past. FS LANDSCAPING CONTRACTORS INC. 215-491-1116. 4950 MOYER RD, DOYLESTOWN, PA 18902.</p> <p>FS LANDSCAPING CONTRACTORS INC. was mailed and emailed an AVR request on 11/07/2024. On 11/14/2024 an email was received which included two pictures of the yard where the incident occurred. FS Landscaping stated that “Attached are the answers for the PAPUC. We have pictures of the site before and after the damage but we do not have any pictures of the accident. Pictures and form attached. From what I am</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>told from the crew onsite is that they were digging holes for the aluminum fence being installed around the pool. The fence needed to be installed further towards the front of the house due to AC units and pool equipment. They were digging by hand with post hole diggers and shale bars. Due to how hard the soil was from lack of rain a laborer struck the underground gas line with the digging bar. I was immediately called and then I called the homeowner and PECO about the incident. The damage was done to the line behind the meter. Scott Payne Custom Pool originally called 811 on 5/16/24 and a start date of 5/23/24. Please let me know if you need additional information” DPI responded with an email on 11/14/2024 and highlighted that an AVR is submitted through the OneCall site. DPI also asked that the missed questions be answered.</p> <p>Homeowner was mailed an AVR request on 11/07/2024. An email was received on 11/18/2024 stating that FS Landscaping was digging by hand with post hole digger and a shale bar, no auger. FS was hired directly by the homeowner. Did the excavator call 811 before digging? - Yes, Scott Payne Custom Pools had a call in on 5/16/24, start date 5/23/24. DPI asked if the excavator call 911 when the accident happened? - No, PECO was the first emergency call when the person digging noticed the damaged line. The homeowner was notified.</p> <p>Ticket 20241413036 was requested by Scott Payne Custom Pools on 5/20/2024 with a response due by 5/22/2024. This was for digging an inground pool. All facility owners responded “clear, no facilities”. Site was listed as marked in white. Area is listed as 20X40 ft.</p> <p>No violations were found. There is no evidence that mechanized equipment was being used by FS LANDSCAPING CONTRACTORS INC. Both the excavator and the homeowner agree that no mechanized equipment was used by FS LANDSCAPING CONTRACTORS INC.</p>	
50490	<p>Facility Owner: National Fuel Gas Contractor/Excavator: GREEN ACRES CONTRACTING Project Owner: PENNDOT</p>	<p><u>On 10/14/2024 4:10:00 PM at SR 0219, RIDGWAY TWP, ELK</u> The incident occurred on Monday, October 14, 2024, on SR 219, in Ridgway Township, Elk County.</p> <p>A National Fuel Gas (NFG) line was damaged.</p> <p>NFG stated, Green Acres Contracting struck and damaged an unmarked service line.</p> <p>Green Acres stated that their crew was installing rail alone SR 219, in Ridgway Township, and a crew member got done pounding a MSKT, when he and his post setter noticed and smelled gas. The crew member reached out to their company contact to come look because there were no line marked in the area, and NFG was notified. NFG arrived at the worksite and verified it was a service line, and they rerouted the service line. Green Acres provide photos of the unmarked worksite.</p>	<p>National Fuel Gas: \$500.00 Section 2(5)(i) 1st Offense \$500.00</p> <p>GREEN ACRES CONTRACTING: \$1,000.00 Section 5(8) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>PennDOT, the project owner stated that Green Acres Contracting used a post pounding truck to drive guide rail post into location. Multiple areas throughout the site were marked but this section was not marked with any indication a gas line was present. A gas line was hit and the crew stopped driving the post once the smell of gas became noticeable. Green Acres notified NFG and moved their crew to a different location to continue working.</p> <p>On Thursday, November 21, 2024, an email was sent to the facility owner, National Fuel Gas requesting an Alleged Violation Report. Their report was submitted on 11/25/2024.</p> <p>*National Fuel Gas is in violation of section: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: Penalty Applied</p> <p>*Green Acres Contracting is in violation of section: 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. Recommendation: Education Required and Penalty Applied</p>	
50637	<p>Facility Owner: Peoples Gas Contractor/Excavator: Independent Enterprises Inc. Project Owner: PITTSBURGH WATER AND SEWER AUTHORITY Designer: G A I CONSULTANTS INC Other: COLUMBIA GAS OF PA INC Other: COMCAST Other: VERIZON PA LLC</p>	<p><u>On 10/15/2024 10:00:00 AM at TERMON AVE, PITTSBURGH CITY, ALLEGHENY PWSA</u> accepted resolution. Documents showed they attended the complex meeting and communicated with the designer to complete designs. ***** Peoples disagreed and sent in more pictures with explanations. Picture 1 is the original picture most likely submitted by Independent Enterprises. That marking for the “T” for the main and service near the damage in the top right corner of the picture and the service line marking for the service line being marked properly was marked after the damage. Violation 2(5)(iii) to Peoples Gas has been withdrawn. Picture 2 shows the new markings on the right in yellow for the damaged plastic service line. To the left of those markings, you can see fainting pink markings applied by Independent Enterprises with a “G” to maintain the original yellow markings for the long plastic service line for. And if you look closely at the bottom middle of the picture, you can still see the original yellow paint applied by the Peoples Gas Locator in line with the pink paint. This picture is marked up later. The “mark placard” is lined up with the marks for the short service line, not the long service line, and that is the confusing part here. Those were the most prevailing marks at the time. Picture 3 is another view showing how Independent Enterprises was applying pink paint in the street with a “G” in line with the yellow paint to maintain the markings for the gas facilities. Picture 4 is a locate photo showing the offset of the short and long service lines, and the main line. The work area</p>	<p>Peoples Gas: \$0.00</p> <p>PITTSBURGH WATER AND SEWER AUTHORITY: \$0.00</p> <p>COLUMBIA GAS OF PA INC: \$0.00</p> <p>COMCAST: \$500.00 Section 2(4) 2nd Offense \$500.00</p> <p>VERIZON PA LLC: \$3,500.00 Section 2(5)(viii) Subsequent \$2,000.00</p> <p>Section 2(4) Subsequent \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>was only involving the long plastic service line at this time, per the Locator and agreement in place at the complex project meeting.</p> <p>Picture 5 is picture 2 with the markings labeled by the supervisor pointing out the most important details to show where the “mark placard” should actually be placed to get the correct distance in inches for the damage from the markings.</p> <p>Picture 6 is picture 1 marked up to give you a better view of where the “mark placard” should have been placed and where the distance should have starting to begin. This shows the damage occurred within the 18” tolerance zone, once you count the distance manually on the ruler.</p> <p>Picture 7 is a bigger view of the pink markings for the damaged plastic service line applied by Independent Enterprises making the damage within the tolerance zone. And the letter “G” is noticeable as well.</p> <p>With the attached photos, and information, explaining in detail how Independent Enterprises used pink paint to maintain the yellow original markings applied by Peoples Gas’ Locator, that made the damage occur within the permissible tolerance zone allowed by law, we ask that the violation and penalty for section 2(5)(i) be removed.</p> <p>*</p> <p>Verizon disagreed and stated that they did respond timely to ticket 20240370940. Verification was provided and the Damage Prevention Investigator (DPI) has withdrawn the 2(4) violation for ticket 20240370940 to Verizon.</p> <p>*</p> <p>Columbia Gas disagreed and stated that "Columbia would like to respectfully request an appeal of the 2(5)(viii) violation in this case. Columbia Gas was in attendance at the complex meeting. I was unable to find the sign in sheet uploaded to the project in CoordinatePA, but our Damage Prevention Specialists (DPS) complete a task for all complex meetings they attend. I have attached that task documenting the attendance and what was discussed (it will be on the last page). I am also attaching the ticket with the locator’s response of Attended Meeting. The investigator’s report indicates the meeting date was 08/07/2024, but that was actually the lawful start date. The meeting was held on 07/31/2024. The DPI withdrew the violation. Columbia Gas provided documentation of attending the meeting. Ticket response was late but was a final response. The violation of 2(5)(viii) to Columbia Gas has been withdrawn.</p> <p>*****</p> <p>The incident occurred on 10/15/2024 at 1233 Termon Ave in Pittsburgh City in Allegheny County.</p> <p>A gas line was hit and damaged.</p> <p>INDEPENDENT ENTERPRISES the excavator stated in their Alleged Violation Report (AVR) that “One Call Mark was approximately 2' off from service line (see hit kit photos). Contractors found a plastic line inserted into</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>steel line and assumed this to be the live service, while they continued digging mainline trench the struck the yellow poly service line was hit and broke. Contractors ripped out the service line completely with the bucket of the 138 excavator, stopped work and IEI Foreman called 911. 911 call center was notified of the incident who informed People's Gas Co. of the broken line. 911 was called to Termon Ave by IEI Foreman at 10:00AM and gas line was crimped off at that time. Gas service line is going to a condemned address (1233 Termon Ave). Stop work was called on all machines and were turned off. Pittsburgh Fire Dept. showed up at 10:06 AM and Peoples Gas Co. on site 10:15AM. Peoples Gas Crew repaired line later at 12:15PM and remarked the line at correct location. 911 was notified. 1 person was affected. Pictures were provided.</p> <p>PEOPLES GAS COMPANY the facility owner stated in their AVR that “On 10/15/2024, Independent Enterprises struck a mismarked PNG service line. PNG crews were called onsite and repairs were made. Pictures were provided.</p> <p>Pittsburg Water and Sewer Authority (PWSA) the project owner was mailed and emailed an AVR request letter on 11/19/2024.</p> <p>PWSA stated in their AVR that “One Call Mark was approximately 2' off from service line (see hit kit photos). Contractors found a plastic line inserted into steel line and assumed this to be the live service, while they continued digging mainline trench the struck the yellow poly service line was hit and broke. Contractors ripped out the service line completely with the bucket of the 138 excavator, stopped work and IEI Foreman called 911. 911 call center was notified of the incident who informed People's Gas Co. of the broken line. 911 was called to Termon Ave by IEI Foreman at 10:00AM and gas line was crimped off at that time. Gas service line is going to a condemned address (1233 Termon Ave). Stop work was called on all machines and were turned off. Pittsburgh Fire Dept. showed up at 10:06 AM and Peoples Gas Co. on site 10:15AM. Peoples Gas Crew repaired line later at 12:15PM and remarked the line at correct location”. They listed the project as <\$400,000 but PWSA later verified that this project is >\$400,000. The project expected to be completed in 3 months. 1 customer was affected. 911 was called. Pictures and tickets were provided.</p> <p>G A I CONSULTANTS INC the designer was mailed and emailed an AVR request letter on 11/19/2024.</p> <p>GAI stated in their AVR that “Paint marking was approximately 2' off from service line (see photos). Contractor found a plastic line inserted into steel line and assumed this to be the live service, while they continued digging mainline trench they struck the yellow plastic gas service line. Contractor stopped work and Foreman called 911. 911 call center was notified of the incident who informed Peoples Gas of the broken line. 911 was called to Termon Ave by Foreman at 10:00AM and gas</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>line was crimped off at that time. Gas service line is going to a condemned address (1233 Termon Ave). Stop work was called and all machines were turned off. Pittsburgh Fire Department arrived at 10:06 AM and Peoples Gas Company arrived at 10:15AM. Peoples Gas Crew repaired line at 12:15PM and remarked the line at correct location. SUE up to Quality Level A was performed as part of this project since overall project cost is greater than \$400,000. Final Design One Call was placed within the required 10-90 day window prior to the end of final design. Training was previously assigned to GAI for Case 17347 (training completed on Friday 6.10.2022) and Case 030748 (training completed on Friday 3.17.2023)". On 12/03/2024 DPI asked GAI about the document that shows the bid date and design date differentials. GAI sent a design page, a final design ticket 20240370940 and the bid date of 3/28/2024. They also described the process they used for SUE.</p> <p>*****</p> <p>*Complex Project Ticket 20242062014 was requested by Independent Enterprises on 7/24/2024 with a response due by 7/30/2024. The meeting to be held on 8/07/2024 at 10:00 a.m. Columbia Gas had no response until the "attended meeting" on 7/31/2024. Note that the meeting is on 8/07/2024. Pittsburgh Water and Sewer Authority never responded. Verizon did not respond until they "field marked" on 7/31/2024. Peoples Gas responded that they "will attend" the meeting, but this was never updated.</p> <p>*Final Design ticket 20230660649 was requested on 3/07/2023, by GAI Consultants with a response due by 3/21/2023. Verizon did not respond "Conflict" until 5/5/2023. Pittsburgh Water and Sewer Authority had no response until they responded "Engineering Completed" on 3/28/2023</p> <p>*Final Design Ticket 20232570690 was requested on 9/14/2023, by GAI Consultants with a response due by 9/28/2023. Comments: Project > \$400,000. This is a portion of a series of calls. All facility owners responded timely. Comcast Communication had no response until 3/28/2024, when they completed Engineering.</p> <p>*Emergency ticket 20242814737 was requested by Independent Enterprises on 10/15/2024 at 1 6:17. Remarks-- [PER CALLER THE LINE WAS MISMARKED 911 WAS CALLED AND PEOPLES GAS HAS ALREADY RESPONDED AND REPAIRED THE LINE. CREW IS STILL ON SITE IF NEEDED FACILITY TYPE: NATURAL GAS-PEOPLES GAS EXCAVATION EQUIPMENT: TRACKHOE HAZARDOUS RELEASE: YES CALLER HAS NOTIFIED 911.] All facility owners responded timely.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>*Emergency ticket 20242893888 was requested by Independent Enterprises on 10/15/2024 at 1 6:17. Remarks-- [PER CALLER THE LINE WAS MISMARKED 911 WAS CALLED AND PEOPLES GAS HAS ALREADY RESPONDED AND REPAIRED THE LINE. CREW IS STILL ON SITE IF NEEDED FACILITY TYPE: NATURAL GAS-PEOPLES GAS EXCAVATION EQUIPMENT: TRACKHOE HAZARDOUS RELEASE: YES CALLER HAS NOTIFIED 911.] All facility owners responded timely.</p> <p>Final Design ticket 20240370940 was requested by GAI Consultants on 2/06/2024 with a response due by 2/21/2024. Comcast did not respond until 2/23/2024. *****</p> <p>Listed below are facility owners in violation of Act 50, Violation Section 2(4) – Failed to respond to Designer’s request for information within 10 Business days. Violation 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project as described in section 5(3). VERIZON PA LLC is in violation of: Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). *Ticket 20242062014 This is a subsequent offense. Section 2(4) – Failed to respond to designer’s request for information within 10 business days. *Tickets *20230660649 See detailed ticket information above. This is a subsequent offense. Recommendation: The penalties are applied. The required facility owner education was completed by 8/13/2024.</p> <p>Comcast is in violation of: Section 2(4) – Failed to respond to designer’s request for information within 10 business days. *Ticket 20240370940 was not responded to until 2/23/2024. * See ticket details. This is a second offense. Recommendation: The penalty is applied. Education is required. The required education that was due by 9/10/2024 was completed. Incident occurred on 10/15/2024.</p>	
50635	<p>Facility Owner: PECO AN EXELON COMPANY Contractor/Excavator: MOR CONSTRUCTION</p>	<p><u>On 10/16/2024 9:14:00 AM at 214 CEDAR AVE, RIDLEY TWP, DELAWARE</u> The incident occurred Wednesday, October 16, 2024, on 214 Cedar Avenue, in Ridley Township, Delaware County.</p> <p>A PECO An Exelon Company’s gas line was damaged.</p> <p>PECO stated, MOR Construction was excavating for sanitary sewer mainline and service line install when they severed the mis-marked .75 plastic gas service line, 10' from the gas mark outs. It was found that all access points were not utilized at the time of the locate resulting in the .75" plastic service line being damaged and in need of repair.</p>	<p>PECO AN EXELON COMPANY: \$1,000.00 Section 2(5)(i) 2nd Offense \$1,000.00</p> <p>MOR CONSTRUCTION: \$1,000.00 Section 5(8) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>MOR Construction stated that upon arriving at the worksite, there were no gas service markings within the limits of the excavation site, only public water marks. MOR excavated with the excavator to approximately 2-feet of depth, and at that point was going to start vacuum excavating, but at 2-feet depth, MOR hit the existing gas service with the bucket of the excavator and broke the 1-inch plastic gas service. MOR was able to crimp the gas line to keep the gas from continuing to escape, and called the office and let someone know of the situation. Mike called One Call and PECO to alert them of the mismarked/unmarked gas service. The nearest gas service mark was located approximately 9-feet away. When the PECO representative arrived at the worksite they hooked onto the locating tape and was able to correctly identify the location of the gas service. The previous mark out went directly out to the street and gas main, not cutting across the yard as it actually does. MOR Construction placed a damage emergency ticket, 20242900859.</p> <p>20242900859- Damage Emergency ticket placed on 10/16/2024, at 9:05am. Remarks- caller states they hit an unmarked gas line. caller states it is crimped off.</p> <p>20242641900- Routine ticket placed on 9/20/2024.</p> <p>20242702048- Update Routine ticket placed on 9/26/2024. Remarks- work in progress no additional mark outs needed.</p> <p>20242813253- Update Routine ticket placed on 10/7/2024. Remarks- work in progress no additional mark outs needed.</p> <p>*PECO An Exelon Company is in violation of section: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: Penalty Applied</p> <p>*MOR Construction is in violation of sections: 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. Recommendation: Education Required and Penalty Applied</p>	
51257	<p>Facility Owner: Comcast Cablevision Contractor/Excavator: PITTSBURGH WATER & SEWER AUTHORITY Project Owner: PITTSBURGH WATER & SEWER AUTHORITY - Placeholder</p>	<p><u>On 10/16/2024 10:25:00 AM at 519 E GENERAL ROBINSON ST. PITTSBURGH CITY, ALLEGHENY</u> The incident occurred on 10/16/2024 at 10:25 AM on 519 E. General Robinson Street, Pittsburgh City, Allegheny County.</p> <p>A cable tv line owned by Comcast was damaged.</p> <p>Comcast Cablevision submitted an Alleged Violation Report (AVR). Their AVR states, "HIT AN ACCURATELY MARKED LINE - ORANGE PAINT</p>	<p>PITTSBURGH WATER & SEWER AUTHORITY: \$1,000.00 Section 5(4) 2nd Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>WAS CLEARLY ABOVE OUR LINES ON THE ROAD.” Photos were submitted.</p> <p>PITTSBURGH WATER & SEWER AUTHORITY submitted an AVR. Their AVR states, "C.O. 10/16/24 - BACKHOE HIT/PULLED PERFECTLY MARKED COMCAST CABLE LINES. CREW WAS SPOTTING FOR DIG, THOUGHT DIG WAS DONE, TURNED FOR TOOLS TO CUT OUT VALVE AND BACKHOE DECIDED (1) MORE. COMCAST ON SITE FOR REPAIR, PWSA REPAIR DONE FOR THE DAY, COMCAST PLATED WITH PWSA PLATE AND PWSA CREW RETURNED ON FRI. 10/18 TO REPLACE 8” VALVE.”</p> <p>Violations:</p> <p>PITTSBURGH WATER & SEWER AUTHORITY – - Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: The penalty is applied. Education is required.</p>	
50553	<p>Facility Owner: PECO Contractor/Excavator: BLOOMING GLEN WASTE WATER CONSTRUCTION / H&K GROUP Project Owner: Willistown Township Designer: CARROLL ENGINEERING CORPORATION Other: Verizon</p>	<p><u>On 10/16/2024 11:00:00 AM at 123 PAOLI PIKE, WILLISTOWN TWP, CHESTER</u> The incident happened on 10/16/2024, at 11:00 AM, at 123 Paoli Pike, in Willistown, Township, Chester County.</p> <p>A gas line owned by PECO was damaged. 911 was called.</p> <p>PECO submitted an Alleged Violation Report (AVR). Their AVR states, "Contractor Blooming Glen Waste water construction, and a sister company H&K Group, working for the township to install sewer mains/man-holes with an active POC. The mark out was incorrect due to print issues. 0 injured, 1 affected.”</p> <p>BLOOMING GLEN WASTE WATER CONSTRUCTION / H&K GROUP submitted an AVR. Their AVR states, "While digging a trench on Paoli Pike for sewer main, backhoe struck an active natural gas line servicing 102 Fairview rd. The crew was using an air knife to search for gas line. When using the backhoe for clearing the soil disrupted by air knife, backhoe bucket with grade plate over teeth caught the service line. PA1 call markings were off by 32 inches.” Photos were submitted.</p> <p>Willistown Township submitted an AVR. Their AVR states, "While digging a trench on Paoli Pike for sewer main, backhoe struck an active natural gas line servicing 102 Fairview rd. The crew was using an air knife to search for gas line. When using the backhoe for clearing the soil disrupted by air knife, backhoe bucket with grade plate over teeth caught the service line. PA1 call markings were off by 32 inches.”</p> <p>CARROLL ENGINEERING CORPORATION submitted an AVR. Their AVR states, "An active gas service was struck by a backhoe while excavating for a</p>	<p>PECO: \$1,000.00 Section 2(5)(i) 2nd Offense \$1,000.00</p> <p>BLOOMING GLEN WASTE WATER CONSTRUCTION / H&K GROUP: \$500.00 Section 5(4) 1st Offense \$500.00</p> <p>Verizon: \$1,000.00 Section 2(5)(v) Subsequent \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>sanitary sewer replacement project. The crew was using an air knife to search for the service line. The backhoe hit the service when clearing the soil disrupted by the air knife. The service was 32 inches from where it was marked.” Photos were submitted.</p> <p>Violations:</p> <p>Verizon – - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Routine ticket 20242133197 had a response due date of 08/02/2024. Verizon responded ‘Field Marked’ on 08/08/2024. Recommendation: The penalty is applied. Education is required.</p> <p>PECO – - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: The penalty is applied. Education is required.</p> <p>BLOOMING GLEN WASTE WATER CONSTRUCTION / H&K GROUP – - Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: The penalty is applied. Education is required.</p>	
50886	<p>Facility Owner: PECO AN EXELON COMPANY Contractor/Excavator: MILLER BROTHERS Project Owner: PECO AN EXELON COMPANY Other: HAVERFORD TOWNSHIP</p>	<p><u>On 10/17/2024 11:00:00 AM at HARVARD RD, HAVERFORD TWP, DELAWARE</u> The incident occurred on Thursday, October 17, 2024, on Harvard Road, in Haverford Township, Delaware County.</p> <p>A gas line was damaged.</p> <p>PECO An Exelon Company stated that Miller Brother was replacing a 4-inch cast iron gas mainline, when they hit and ripped out 2 1-inch gas service lines that ran to the same location due to inaccurate prints.</p> <p>Miller Brothers stated that their crew spotted and found the marked 1 ¼” steel service per the GFR, sketch and gas quad, and they continued to install the 6-inch gas mainline in the utility cleared trench, and the backhoe hit an unmarked steel gas service line in front of 26 Harvard Road. Upon review, it was confirmed there were 2 fully unmarked steel service lines. The PECO crew arrived and made repairs to the service and made the job safe. On Friday, December 6, 2024, an email was sent to the contractor, Miller Brothers, requesting an Alleged Violation Report (AVR). They submitted their AVR on 12/6/2024.</p> <p>20242911949- Damage Emergency ticket placed on 10/17/2024. No Response from- Haverford Township, they responded late on 10/21/2024 as Field Marked.</p> <p>*PECO An Exelon Company is in violation of section: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: Penalty Applied</p>	<p>PECO AN EXELON COMPANY: \$1,000.00 Section 2(5)(i) 2nd Offense \$1,000.00</p> <p>HAVERFORD TOWNSHIP: \$1,500.00 Section 2(5)(vii) 2nd Offense \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>*Haverford Township is in violation of section: 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20242911949</p> <p>Recommendation: Education Required and Penalty Applied</p>	
50684	<p>Facility Owner: Wilkinsburg-Penn Joint Water Authority</p> <p>Contractor/Excavator: Peoples Gas</p> <p>Project Owner: Peoples Gas - Placeholder</p>	<p><u>On 10/17/2024 11:20:00 AM at 931 JEFFERSON ROAD, PENN HILLS MUNIC, ALLEGHENY</u> Peoples Gas violations and penalties were withdrawn.</p> <p>*****</p> <p>The incident occurred on 10/17/2024 at 11:20 AM, at 931 Jefferson Road, in Penn Hills Munic., Allegheny County.</p> <p>A water line owned by Wilkinsburg-Penn Joint Water Authority was damaged.</p> <p>Wilkinsburg-Penn Joint Water Authority submitted an Alleged Violation Report (AVR). Their AVR states, "Peoples Gas pulled WPJWA 3/4" copper water service line at 931 Jefferson Road from 8" cast iron main, causing disruption to water distribution system. Most recent Ticket No 20242041874 7/22/2024 for work taking place in front of 1003 Jefferson Road. Ticket was field marked on 7/23/2024. Damage 90' North of most recent Ticket." Photos were submitted.</p> <p>Peoples Gas - A courtesy letter, requesting an AVR to be completed was sent by email and mail on 11/20/2024. Peoples Gas submitted an AVR. Their AVR states, "While digging to repair a natural gas line, PEOPLES GAS crews struck an unmarked Wilkinsburg Penn Joint Water Authority service line."</p> <p>Routine ticket 20242711869 states: Work Site--[1003 JEFFERSON RD] Site Marked in White--[Y] Location Information-- [WOR WILL TAKE PLACE IN FRONT OF AND NEAR THIS ADDRESS] Street--[X] Sidewalk--[X] Pub Prop--[X]</p> <p>WILKINSBURG PENN JOINT WATER AUTH responded to the routine ticket 20242711869 on 09/27/2024 as 'Field Marked'.</p> <p>The mapping for the routine ticket 20242711869 is for the street address of 1003 only. No additional properties are within mapped area for the ticket. Additionally, there is another property between the address listed on the ticket and where the damage occurred.</p> <p>Violations:</p> <p>Peoples Gas – (Withdrawn.) - Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area.</p>	Peoples Gas: \$0.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>- Section 5(13) – Excavator changed the location, scope, or duration of a proposed excavation without notifying the One call System.</p> <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
50672	<p>Facility Owner: ALTOONA WATER AUTHORITY WATER DIVISION</p> <p>Contractor/Excavator: Mingle Contracting</p> <p>Project Owner: Peoples Gas Company</p> <p>Designer: PEOPLES</p>	<p><u>On 10/21/2024 9:00:00 AM at 1005 N 3RD ST - H ALLEY, ALTOONA CITY, BLAIR</u> Incident occurred on October 21st, 2024, at 9am at 100 North 3rd Street - H Alley, Altoona City, Blair County.</p> <p>A water line was damaged.</p> <p>Altoona Water Authority's Alleged Violation Report (AVR) states, "AWA was called to location by Mingles Contracting a subcontractor of Peoples Gas Company. Mingles had torn out the water service line corporation for the indicated address. AWA responded within one hour of call. Upon AWA arrival, AWA assessed the damage, Mingles had the area already open and proceeded to repair the water lines after draining of ditch. Mingles had dug down farther than they expected. Per the Gas company inspector, the AWA lines were marked correctly. PHOTOS ATTACHED."</p> <p>Mingle Contracting's AVR states, "Excavator operator for our company (Mingle Contracting) struck a water line in a dirt alley owned by Altoona Water Authority which required repair. The facility was marked by Altoona Water Authority (properly)."</p> <p>Peoples Gas Company's AVR states, "Mingle Contracting struck a water line in the alley which required a repair. The facility was marked correctly by Altoona water authority. I do not know the physical address. Hit 1" copper off of the main line"</p> <p>Pictures show that the curb stop was marked out near the damaged line.</p> <p>Violation:</p> <p>Mingle Contracting Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.</p>	<p>Mingle Contracting: \$1,000.00 Section 5(4) 2nd Offense \$1,000.00</p>
50691	<p>Facility Owner: UGI UTILITIES INC</p> <p>Contractor/Excavator: UGI UTILITIES INC</p> <p>Project Owner: UGI UTILITIES INC</p>	<p><u>On 10/21/2024 11:04:00 AM at N HOBSON ST, WHITEHALL TWP, LEHIGH</u> The incident occurred on Monday, October 21, 2024, on N. Habson Street, in Whitehall Township, Lehigh County.</p> <p>UGI Utilities gas stub was damaged.</p> <p>UGI stated, they were digging to install a new gas mainline and when doing so the UGI crew hit an unmarked main stub, creating damage and a leak. The main stub that was damage was not marked, but the locate was correct on the rest of the project. UGI provided photos of the unmarked damaged main stub.</p> <p>*UGI Utilities is in violation of section:</p>	<p>UGI UTILITIES INC: \$2,000.00 Section 2(5)(i) Subsequent \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: Penalty Applied</p>	
51475	<p>Facility Owner: AQUA PA - SPACESAVER Contractor/Excavator: MORTIMER'S EXCAVATING INC Project Owner: AQUA PA Designer: WallacePancher Group, a division of The Mannik & Smith Group, Inc.</p>	<p><u>On 10/22/2024 12:13:00 PM at 444 LAYFAYETTE AVE, SHARON CITY, MERCER</u> Removed violation and penalty for Aqua. **** The incident occurred on 10/22/2024 at 444 Lafayette Ave in Sharon City in Mercer County.</p> <p>An old, abandoned water service line was hit and damaged.</p> <p>AQUA PENNSYLVANIA INC the Project owner and facility owner stated in their Alleged Violation Report (AVR) that Aqua contractor Mortimer Excavating Inc, hit old abandoned service corporation stop at 444 Lafayette Ave. No records exist for this. On 12/01/2024 DPI sent an email asking who the final designer is for this project. One customer was affected. There was a short shutdown of the water main for the crew to install a repair clamp. They also verified that WallacePancher Group, a division of The Mannik & Smith Group, Inc is the final designer for this project. Project is listed as >\$400,000. And 4,045 LF. They state that level “A” Test Hole /Pot Hole was utilized for this project.</p> <p>Wallace Pancher Group prepared the design for Aqua. The One Call logo and Design ticket number is on the design. Wallace Pancher Group prepared the design for Aqua. The One Call logo and Design ticket number is on the design. On 12/03/2024 an email was received asking about AVR submission. DPI responded immediately and confirmed that an AVR needs to be submitted and explained some of our process. On 12/04/2024 email was received including the final design map and a pending AVR attached. WallacePancher Group stated in their AVR that “was made aware of this event on 12/01/2024. After conversations with the Contractor (Mortimer's Excavating) and the Project Owner (Aqua PA) it was determined that an unmarked abandoned lead service lateral was struck by the excavator that caused a leak on the main service line. Water service was temporarily interrupted while repairs were made. Aqua PA indicated that they do not have historic records of this service lateral. A survey for the entire site was completed by Sheffler & Company Inc. dated 07/21/23”. They answered the questions in the AVR request letter. They stated that the abandoned line was not located by the survey work that was done.</p> <p>WallacePancher Group stated that they had to submit their AVR by phone. They added that “WallacePancher was made aware of this event on 12/1/24. After conversations with the contractor (Mortimers Excavating) and the project owner Aqua PA it was determined that unmarked abandoned lead service lateral was struck by the excavator that caused a leak on the main service line. Water service was temporarily interrupted while repairs were made. Aqua indicated that</p>	AQUA PA: \$0.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>they do not have historic records of this service lateral. A survey for the entire site was completed by Sheffler and Company Incorporated dated 7/21/23". The project is >\$400,000. The length is 4045 LF. Email was received on 12/04/2024 stating that the project was authorized to begin construction on 7/22/2024. Final Design Drawings PDF created on 8/16/2024. Final Design ticket 20242201968 was requested on 8/07/2024.</p> <p>MORTIMER'S EXCAVATING INC stated in their AVR that "Before excavation to renew the service lateral for 444 Lafayette Ave, we observed the utility completed line locates. We then used our own electronic utility line locator and traced out the service lateral to almost the exact markings from Aqua's locator. We excavated to 2 feet below grade level and started hand shoveling to find the service tie in to the main. Once we found the service line and corporation stop that ties into the watermain, we needed to provide ourselves with sufficient room to work to allow access to turn off and cut the existing service to be able to renew with new service materials. While being spotted, the excavator operator was directed to remove material from next to the existing service to allow said room that was needed. upon doing so, the excavator bucket encountered an unknown, unmarked abandoned service corporation stop, tapped on the watermain at 12 o'clock and roughly 3 inches of old lead service line that had been cut off. The foreman directed the crew to shutdown the watermain to slow the water to allow access to make the repair needed. within the hour, the parts needed to make the repair were on site and the repair was made". The contractor added that "The KNOWN current service lateral was marked accurately. Contractor found and exposed said current service. The hit line was unknown/unmarked" Project is listed to be >\$400,000. And expected to take 9 months to complete. Report and Pictures were provided. DPI asked for the BID documents from Mortimer's Excavating. An email was received on 12/6/2024 that the information about the bid will be forwarded when received.</p> <p>WallacePancher Group, stated that "This project was authorized to begin construction on 7/22/2024". On 12/05/2024 DPI sent an email to MORTIMER'S EXCAVATING INC asking for documentation of when the bid went out for this project, since the construction date is before the Final Design ticket 20242201968 which was requested on 8/07/2024.</p> <p>AQUA Report that was run on 11/05/2024 and shows the status as in progress, shows the construction date of 8/19/2024 for installing a water line. Complex Project ticket was requested on 7/30/2024.</p> <p>*****</p> <p>AQUA is in violation of: Section 6.1(3) – Released a project to bid or construction before final design was complete. email from designer states that the project was authorized for construction on 7/22/2024. The 7738911 report shows a date of 8/19/2024.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Recommendation: The penalty is applied. Project Owner Training was completed by 11/11/2024. This is after the final design ticket was submitted.</p>	
50678	<p>Facility Owner: COLUMBIA GAS Contractor/Excavator: West Penn Utilities (WPU) Project Owner: BRIGHTSPEED Designer: BRIGHTSPEED - SPACESAVER Other: CROWN CASTLE Other: PALNIES Other: PARKSIDE UTILITY CONSTRUCTION LLC</p>	<p><u>On 10/22/2024 2:39:00 PM at 108 PINEHURST DR, CRANBERRY TWP, BUTLER</u> The incident occurred on 10/22/2024 at 108 Pinehurst Dr. in Cranberry Township in Butler Co.</p> <p>PARKSIDE UTILITY CONSTRUCTION LLC representing Brightspeed, the project owner and designer stated in their Alleged Violation Report (AVR) that “Parkside Utility Construction is the prime contractor for this Brightspeed project. West Penn Utilities was drilling in conduit and hit the gas service line at the above address. Service line was 14 feet, 10 inches from the locates. Photos were provided. No project owner information was given.</p> <p>AVR letters were mailed and emailed to COLUMBIA GAS OF PA INC the facility owner, West Penn Utilities (WPU) the excavator, and PALNIES the submitter of the design ticket on 11/21/2024. On 12/02/2024 Palnies responded with an email that stated that they are not the designer, but the permit submitter for Brightspeed who they stated is the final design of the project.</p> <p>Columbia Gas the facility owner stated in their AVR that West Penn Utilities, working on behalf of Brightspeed, was installing fiber conduit when their directional drill struck and damaged the inaccurately marked 1" plastic, customer-side, gas service feeding 108 Pinehurst Dr., Cranberry Twp. They notified 911, 811, and Columbia Gas when the damage occurred. Columbia Gas responded immediately to make the area safe. An onsite investigation was conducted to determine why the customer-side gas service was inaccurately marked. It was determined that this property actually had two curb valves; the second one being found after the damage occurred and not documented in any company records. The portion of the customer-side gas service between the two curb valves was not locatable. The damage took place to the service line 12" inches into the customer side. Per Section 2(5)(i.1), "The identification shall not be deemed to impose any liability upon the facility owner for the accuracy of the other facility's identification." The add that 1 customer was affected. Pictures were provided.</p> <p>WEST PENN UTILITIES the excavator stated in their AVR that “at approximately 1:15 pm on Oct 22, a miss marked service line was damaged. The marked service gas line for 108 pinehurst dr was approximately 15 ft off from the actual gas service for 108 pinehurst dr. This address had two curb boxes on their property and the abandoned curb box was the one located with print. A second curb box was located 15 ft away in the middle of the home buried under the sod and was the active gas line for the customer. The struck line was on the customer side of the correct curb box and Columbia gas made the repairs to get the customer up in service”. They</p>	<p>West Penn Utilities (WPU): \$500.00 Section 5(16) 1st Offense \$500.00</p> <p>BRIGHTSPEED: \$2,750.00 Section 4(2) 1st Offense \$500.00</p> <p>Section 6.1(4) 1st Offense \$500.00</p> <p>Section 6.1(3) 2nd Offense \$1,000.00</p> <p>Section 2(5)(viii) 1st Offense \$500.00</p> <p>Section 2(5)(v) 1st Offense \$250.00</p> <p>CROWN CASTLE: \$2,500.00 Section 2(5)(v) 1st Offense \$2,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>state the project was <\$400,000. The length was 10,000. 911 was called. Pictures were provided. Please note that this excavator was aware of the damage when the incident occurred.</p> <p>**Final Design and Bid date are both on 9/02/2024. On 12/03/2024 Damage Prevention Investigator (DPI) sent an email to Brightspeed and PARKSIDE UTILITY CONSTRUCTION LLC representatives asking about the design and cost of this project. *****</p> <p>*Final Design ticket 20242331511 was requested by Palnies on 8/20/2024 with a response due by 9/04/2024. All facility owners responded timely.</p> <p>*Complex Project ticket 20242393920- was requested by PARKSIDE UTILITY CONSTRUCTION LLC on 8/26/2024 with a response due by 8/29/2024. The meeting was scheduled for 8/30/2024 at 10:00. On 12/03/2024 DPI sent an email asking for the CPM sign-in sheet. Brightspeed had no response until 9/03/2024. Parkside Utility Construction provided the Complex Project Sign sheet attendees: PA 811, Columbia Gas, and CPA.</p> <p>*Ticket 20242882964 was requested by West Penn Utilities on 10/14/2024 with a response due by 10/17/2024. Worksite is for 109 to 103 Pinehurst Dr. About 500 ft of road. Crown Castle did not respond "Clear" until 10/19/2024. Brightspeed field marked on 10/19/2024.</p> <p>*Emergency ticket 20242962573 was requested by West Penn Utilities on 10/22/2024 at 13:14 for a Columbia Gas gas line hit and damage. 911 was notified.</p> <p>Emergency ticket 20242962973 was requested by Columbia Gas on 10/22/2024 at 14:12. All facility owners responded timely. *****</p> <p>West Penn Utilities (WPU) is in violation of: Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. Recommendation: The penalty is applied.</p> <p>BRIGHTSPEED is in violation of: Section 6.1(3) – Released a project to bid or construction before final design was complete. This is a second offense. Section 6.1(4) – Failed to participate in design and preconstruction meetings. Section 4(2) – Designer failed to request the line and facility information prescribed by section 2(4) from the One Call System not less than ten nor more than ninety business days before final design is to be completed. Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3).</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(v) Failed to respond to a routine One Call ticket within the required amount of time. Recommendation: The penalty is applied. Project Owner education is required. Project Owner education is due by 2/12/2025 from case 40715 and has not been taken to date.</p> <p>CROWN CASTLE is in violation of: Section 2(5)(v) Failed to respond to a routine One Call ticket within the required amount of time. Recommendation: The penalty is applied. Facility owner education was due by 9/10/2024 and has not been taken to date for case 42290. Fines raised to \$2500 for failure to comply with the DPC's orders within 60 days.</p>	
50776	<p>Facility Owner: UGI Contractor/Excavator: Living Landesign Inc</p>	<p><u>On 10/23/2024 10:30:00 AM at 3126 Walnut St. PENBROOK BORO, DAUPHIN</u> The incident occurred on 10/23/2024 at 3126 Walnut St in Penbrook Boro in Dauphin County.</p> <p>A gas line was hit. 911 was called by the gas company. No One Call ticket was submitted prior to excavation. 31 customers were affected. 2 were evacuated.</p> <p>UGI UTILITIES INC stated in their Alleged Violation Report (AVR) that “While digging in the yard on a landscaping project, contractor struck and damaged a steel gas service. The service was pulled from the tee on the gas main. The One Call system was not notified prior to excavation”. Pictures were provided. 31 people were affected. 2 were evacuated.</p> <p>Living Landesign Inc and homeowner were mailed and emailed an AVR request letter on 11/21/2024. On 11/25/2024 an email was received providing some information. DPI responded with an email sent on 11/26/2024 that an AVR is still needed.</p> <p>Living Landesign Inc stated in their AVR that “Upon realized damage to gas line- operator contacted homeowner who then contacted UGI. UGI dispatched a technician to site who called 911 upon realizing the extent of damage. UGI then proceeded to turn off gas line to site and fixed damaged gas line connecting to the residence. Operator did not realize the extent of damage at the time the line was hit, and was also not aware 911 had to be called immediately”. On 11/30/2024 DPI asked for the name of the Project Owner.</p> <p>Contractor has placed One Call notifications with PA One Call in the past. Listed contact info is most recent info on file for this contractor.</p> <p>Living Landesign provided all the information that this DPI requested. AVR letter was sent to the project owner at the incident address. On 12/02/2024 an email was received with the name of the project owner, who lives at a different address.</p> <p>On 2/25/2025 Living Landesign left a voice mail message asking about the case. DPI sent an email stating that the stakeholder review notice went out and if the contact information could be verified.</p>	<p>Living Landesign Inc: \$3,000.00 Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(7) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$0.00</p> <p>Section 5(2.1) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>On 12/16/2024 a return letter was received from 3126 Walnut St stating “vacant” Unable to forward” DPI did not send a letter out to the contact that was provided by the excavator, since the information needed was already in the case. *****</p> <p>Living Landesign Inc is in violation of Sections: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Section 5(7) – Failed to immediately report to the facility owner any break or leak in its lines, or any dent, gouge, groove, or other damage to such lines or to their coating or cathodic protection. Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. This is a first-time offense. The \$500. penalty is reduced to a warning. Recommendation: The penalties are applied. Education is required. Fine factor was not added in because although 31 folks were affected, 2 were evacuated.</p>	
50810	<p>Facility Owner: Columbia Gas of PA - North</p> <p>Contractor/Excavator: INDEPENDENT ENTERPRISES</p> <p>Project Owner: Pittsburgh Water and Sewer (PWSA)</p> <p>Designer: GAI Consultants</p> <p>Other: Verizon</p>	<p><u>On 10/23/2024 12:40:00 PM at 1107 TERMON AVE, PITTSBURGH CITY, ALLEGHENY</u> Incident occurred on October 23rd, 2024, at 12:40pm at 1107 Termon Avenue, Pittsburgh City, Allegheny County.</p> <p>A gas line was damaged.</p> <p>Columbia Gas Company's Alleged Violation Report (AVR) states, "Independent Enterprises, working on behalf of PWSA, was digging to install water main and laterals when they struck and damaged an accurately marked 1" plastic gas service. They notified 911 and 811 when the damage occurred. Columbia Gas responded immediately to make the area safe and complete repairs. When the crew arrived, the gas service was bent back and taped. This was the third line hit in two days. A discussion was held onsite with the foreman and crew to discuss damage prevention best practices. They were also told to not tape back lines when a damage occurs."</p> <p>Independent Enterprise Inc's AVR states, "While digging out mainline trench operator struck service line going to 1107. Gas main crossed roadway just prior to this location. Stop work was called and all machinery was shut down. 911 was called and an IEI laborer crimped off the line and tapped it shut. Columbia Gas Rep on site to inspect damages at 1:00 pm."</p> <p>PWSA's AVR states, "While digging out mainline trench operator struck service line going to 1107. Gas main crossed roadway just prior to this location. Stop work was called and all machinery was shut down. 911 was called and an IEI laborer crimped off the line and tapped it shut. Columbia Gas Rep on site to inspect damages at 1:00 pm."</p>	<p>INDEPENDENT ENTERPRISES: \$1,000.00 Section 5(4) 2nd Offense \$1,000.00</p> <p>Verizon: \$1,500.00 Section 2(4) Subsequent \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>GAI Consultant's AVR states, "While digging out water main line trench operator struck service line going to 1107 Termon Ave. Gas main crossed roadway just prior to this location. Stop work was called and all machinery was shut down. 911 was called and Contractor crimped off the line and tapped it shut. Columbia Gas Rep on site to inspect damages at 1:00 pm. Final Design One Call was run by GAI Consultants on Thurs 2.6.2024, which was within the required 10 to 90-day window prior to the end of final design. Final Design ended on Tues 3.18.2024. The bid date was Thurs 3.28.2024. The total project value is over \$400,000 and during design SUE up to Quality Level (QL) A was performed. Record Drawing Research (QL-D) was done by the whole project team as the project moved through design. The surface expressions of utilities such as manholes, curb boxes, and valve boxes were surveyed (QL-C). The project owner had GAI include the cost to hire a utility locator as a subcontractor. That was Lexis Group. They connected to the locate wires and metallic pipes to use mark utility locations across the job (QL-B). The surveyor surveyed the paint markings. GAI identified places where the QL-B needed clarification and had Lexis do Test Pits (QL-A) there. Training was previously assigned to GAI for Case 17347 (training completed on Fri 6.10.2022) and Case 030748 (training completed on Fri 3.17.2023)."</p> <p>Pictures show that line was marked within the tolerance zone.</p> <p>Case is related to 50637.</p> <p>Violations:</p> <p>Independent Enterprise Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.</p> <p>Verizon Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20222360768</p>	
50844	<p>Facility Owner: PEOPLES GAS COMPANY LLC</p> <p>Contractor/Excavator: INDEPENDENT ENTERPRISES INC</p> <p>Project Owner: PITTSBURGH WATER & SEWER AUTHORITY</p> <p>Designer: G A I CONSULTANTS</p>	<p><u>On 10/25/2024 7:00:00 AM at HOBART ST, PITTSBURGH CITY, ALLEGHENY</u> Removed penalty and violation of Peoples Gas Company based on the information they provided. *****</p> <p>The incident occurred on Friday, October 25, 2024, on Hobart Street, in Pittsburgh City, Allegheny County.</p> <p>Peoples Gas Company’s line was damaged.</p> <p>Peoples Gas stated that Independent Enterprises Inc working for Pittsburgh Water and Sewer Authority (PWSA) to install new water lines, saw cut through a clearly marked Peoples Gas service line on Friday 10/25/2024, and did not report the damage to Peoples Gas, 811 or 911. Peoples Gas found the damaged line on Monday 10/28/2024, at 9:00am. Independent Enterprises</p>	<p>PEOPLES GAS COMPANY LLC: \$0.00</p> <p>INDEPENDENT ENTERPRISES INC: \$3,500.00 Section 5(7) 2nd Offense \$1,500.00</p> <p>Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(8) 1st Offense \$1,000.00</p> <p>PITTSBURGH WATER & SEWER</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>failed to notify the facility owner of the damage and left the site with gas blowing in a highly travelled public street in front of 5427 Hobart Street. Peoples Gas provided a photos showing the line mark.</p> <p>Independent Enterprises and PWSA stated that they were saw-cutting road at 15-inches deep for a water line installation. The gas line was shallow and in the road base. On 10/29/2024, the Construction Inspector was informed by Peoples Gas that an unmarked gas service to 5423 Hobart Street was cut by Independent Enterprises saw cutter. On Friday 10/25/2024, the saw cutter was on the road in front of 5423 Hobart Street cutting the road, at 15-inch in depth. The saw cutter did not smell gas and was unaware of a gas strike. In the morning of Monday 10/28/2024, the resident at 5423 Hobart Street called Peoples Gas to report a gas smell. The Peoples Gas crew repaired the line and determined that the line was cut by the saw. The Peoples Gas rep informed the Construction Inspector that line was unmarked when cut. After the line was repaired Peoples Gas marked the service line.</p> <p>GAI Consultants, the designer, stated that the contractor was saw-cutting road 15" deep for water line installation. The gas line was shallow and in road base. On 10/29/24, the Construction Inspector was informed by Peoples Gas rep, that a unmarked gas service to 5423 Hobart Street was cut by the contractor. The saw-cutter was on the road in front of house 5423 Hobart Street on Friday 10/25/24, cutting road 15" in depth. The saw-cutter noticed no gas smell and was unaware of a gas strike. The resident at 5423 Hobart Street called Peoples Gas on Monday 10/28/24, in the morning to report a gas smell. The Peoples Gas crew repaired line and determined line was cut by a saw. The Peoples Gas rep informed CI that line was unmarked when cut, after the line was repaired Peoples Gas marked the service line.</p> <p>The Final Design One Call was run by GAI Consultants on Thurs 2/6/2024, which was within the required 10 to 90-day window prior to the end of final design. The Final Design ended on Tues 3/18/2024. The bid date was Thurs 3/28/2024. The total project value is over \$400,000. During the design, SUE up to Quality Level (QL) A was performed. The Record Drawing Research (QL-D) was done by the whole project team as the project moved through the design stage. The surface expressions of utilities such as manholes, curb boxes, and valve boxes were surveyed (QL-C). The project owner had GAI include the cost to hire a utility locator as a subcontractor. That was Lexis Group, LLC (Lexis). Lexis connected to the locate wires and metallic pipes to use mark utility locations across the job (QL-B). The surveyor surveyed the paint markings. GAI identified places where the QL-B needed clarification and had Lexis do Test Pits (QL-A) there. Training was previously assigned to GAI for Case 17347 (training completed on Fri 6/10/2022) and Case 030748 (training completed on Fri 3/17/2023).</p>	<p>AUTHORITY: \$2,000.00 Section 2(5)(v) Subsequent \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>20242603952- Routine ticket placed on 9/16/2024, with response due date of 9/18/2024, No Response from - PWSA. Late response from- Peoples Gas on 9/26/2024, as Field Marked.</p> <p>*Independent Enterprises Inc is in violation of sections: 5(7) – Failed to immediately report to the facility owner any break or leak in its lines, or any dent, gouge, groove, or other damage to such lines or to their coating or cathodic protection. 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. 5(8) – Excavator vacated worksite after causing damage that resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. Recommendation: Penalties Applied</p> <p>*Peoples Gas Company is in violation of section: 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. 20242603952 Recommendation: Penalty Applied</p> <p>*Pittsburgh Water and Sewer Authority is in violation of section: 2(5)(v) – Failed to respond to a routine One Call ticket. 20242603952 Recommendation: Penalty Applied</p>	
50959	<p>Facility Owner: Columbia Gas of PA - North</p> <p>Contractor/Excavator: WILSON EXCAVATING AND UTILITY CONSTRUCTION LLC</p> <p>Project Owner: PEOPLES GAS COMPANY</p>	<p><u>On 10/26/2024 10:00:00 AM at 3636 FLEMING AVE, PITTSBURGH CITY, ALLEGHENY</u> The incident occurred on Saturday, October 26, 2024, at 3636 Fleming Avenue, in Pittsburgh City, Allegheny County.</p> <p>Columbia Gas’ line was damaged by Wilson Excavating and Utility Construction, LLC.</p> <p>Columbia Gas stated that Wilson Excavating, working on behalf of Peoples Gas Company, was digging to install new gas main and service lines, when they struck and damaged an unmarked 1-inch plastic gas service line with their backhoe, company-side line. An onsite investigation was conducted to determine why the gas service line was not marked. The locator was able to produce locate pictures showing the gas facility was previously marked accurately. Wilson Excavating failed to preserve the markings and had covered the marks with their backfill and sand piles. Therefore, the root cause of this damage was deemed to be excavator negligence. Wilson Excavating and Peoples Gas stated, while digging a trench to install a 4-inch gas mainline, a marked gas line, owned by Columbia Gas, was hit and damaged. The crew stopped excavating and called 911 and Columbia Gas. There was some confusion because the curb box was marked with a question mark, but further investigation determined there were marks on the road to indicate a long service crossing the road. Columbia Gas responded immediately to make the area safe and complete repairs.</p>	<p>WILSON EXCAVATING AND UTILITY CONSTRUCTION LLC: \$1,000.00 Section 5(3) 1st Offense \$500.00</p> <p>Section 5(4) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>*Wilson Excavating and Utility Construction, LLC is in violation of sections: 5(3) – Excavator ailed to protect and preserve the markings after beginning excavation, or request a remark through the One Call System to request the facilities be marked again. 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: Education Required and Penalties Applied</p>	
50857	<p>Facility Owner: PEOPLES GAS COMPANY LLC Contractor/Excavator: INDEPENDENT ENTERPRISES INC Project Owner: PITTSBURGH WATER & SEWER AUTHORITY Designer: G A I CONSULTANTS</p>	<p><u>On 10/28/2024 11:00:00 AM at HOBART ST, PITTSBURGH CITY, ALLEGHENY</u> Peoples Gas-Removed penalty and violation, 2(5)(v), Routine ticket 20242603944, because related Case 50844, penalty and violation was removed for 2(5)(v), Routine Ticket-20242603952. Both Routine tickets were placed for the same location, on the same day, 2 minutes apart, and for the same job.</p> <p>*****</p> <p>The incident occurred on Monday, October 28, 2024, on Hobart Street, in Pittsburgh City, Allegheny County.</p> <p>Peoples Gas Company’s line was damaged.</p> <p>Peoples Gas stated that Independent Enterprises Inc, working for Pittsburgh Water and Sewer Authority (PWSA), struck and damaged a properly marked Peoples Gas service line. Independent Enterprises was using mechanized equipment in the tolerance zone causing the line strike. Peoples Gas provided photos showing that the line was damaged within the tolerance zone.</p> <p>Independent Enterprises and PWSA stated that during the excavation they hit a 1.25-inch plastic gas service line, on the public side, damaging the line. The line was mismarked. Independent Enterprises called 911 and Peoples Gas. The Pittsburgh Fire Department arrived on site at 12:10pm with Peoples Gas representatives arriving on site at 12:20pm. Peoples Gas Rep. called for a repair crew who arrived on site at 1:20pm and repaired the line.</p> <p>GAI Consultants Inc, the designer stated, during excavation the contractor encountered a 1.25" plastic gas service line on the public side, damaging line. The line was mismarked, and the contractor called 911 and Peoples Gas. The Pittsburgh Fire Department arrived on-site at 12:10pm with Peoples Gas representatives arriving on-site at 12:20pm. Peoples Gas called for a repair crew who arrived on site at 1:20pm and repaired the line.</p> <p>The Final Design One Call was run by GAI Consultants on Thurs 2/6/2024, which was within the required 10 to 90-day window prior to the end of final design. The Final Design ended on Tues 3/18/2024. The bid date was Thurs 3/28/2024. The total project value is over \$400,000. During design, SUE up to Quality Level (QL) A was performed. The Record Drawing Research (QL-</p>	<p>PEOPLES GAS COMPANY LLC: \$0.00</p> <p>INDEPENDENT ENTERPRISES INC: \$1,000.00 Section 5(4) 2nd Offense \$1,000.00</p> <p>PITTSBURGH WATER & SEWER AUTHORITY: \$0.00 Section 2(5)(v) 2nd Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>D) was done by the whole project team as the project moved through the design stage. The surface expressions of utilities such as manholes, curb boxes, and valve boxes were surveyed (QL-C). The project owner had GAI include the cost to hire a utility locator as a subcontractor. That was Lexis Group, LLC (Lexis). Lexis connected to the locate wires and metallic pipes to use mark utility locations across the job (QL-B). The surveyor surveyed the paint markings. GAI identified places where the QL-B needed clarification and had Lexis do Test Pits (QL-A) there. Training was previously assigned to GAI for Case 17347 (training completed on Fri 6/10/2022) and Case 030748 (training completed on Fri 3/17/2023).</p> <p>20242603944- Routine ticket placed on 9/16/2024, at 3:50pm, with response due date of 9/18/2024, No Response from - PWSA. Late response from- Peoples Gas on 9/26/2024, as Field Marked.</p> <p>*Independent Enterprises Inc is in violation of sections: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: Penalty Applied, education required.</p> <p>*Peoples Gas Company is in violation of section: 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. 20242603944 Recommendation: Zero penalty but keep the violation because violation and penalty applied to Case 50844, to Routine Ticket- 20242603952, placed on 9/16/2024, at 3:52pm, with response due date of 9/18/2024. Both tickets placed on the same day, for the same street.</p> <p>*Pittsburgh Water and Sewer Authority is in violation of section: 2(5)(v) – Failed to respond to a routine One Call ticket. 20242603944 Recommendation: Zero penalty but keep the violation because violation and penalty applied to Case 50844, to Routine Ticket- 20242603952, placed on 9/16/2024, at 3:52pm, with response due date of 9/18/2024. Both tickets placed on the same day, for the same street.</p>	
50863	<p>Facility Owner: PEOPLES GAS COMPANY LLC Contractor/Excavator: INDEPENDENT ENTERPRISES Project Owner: PITTSBURGH WATER & SEWER AUTHORITY Designer: G A I CONSULTANTS</p>	<p><u>On 10/29/2024 10:00:00 AM at HOBART ST, PITTSBURGH CITY, ALLEGHENY</u> Removed Peoples Gas penalty and violation. After reviewing the rejection from PNG by email and their attachments, section 2(5)(i) penalty and violation has been removed. *****</p> <p>The incident occurred on Tuesday, October 29, 2024, on Hobart Street, in Pittsburgh City, Allegheny County.</p> <p>Peoples Gas Company’s line was damaged.</p> <p>Peoples Gas stated that Independent Enterprises Inc, working for Pittsburgh Water and Sewer Authority (PWSA), struck and damaged an improperly marked Peoples Gas service line at 5521 Hobart Street. Peoples Gas had this mark as a trouble locate and was unable to complete work to find this line prior to the damage.</p>	<p>PEOPLES GAS COMPANY LLC: \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Independent Enterprises and PWSA stated that Peoples Gas service line was unmarked. During excavation Independent Enterprises struck an unmarked gas service line to 5515 Hobart Street; the line had no mark outs and no visible curb box, and the line was hit on public side in the street. Independent Enterprises foreman called 911 and Peoples Gas, the Pittsburgh Fire department arrived on site at 9:20am, and the Peoples Gas Representative arrived on site at 9:30am. The Peoples Gas Representative called for a repair crew which arrived on site at 10am, and the line was repaired by 10:30am. Independent Enterprises and PWSA provided photos of the unmarked damaged line.</p> <p>GAI Consultants Inc, the designer stated that Peoples Gas service line was unmarked, and during the excavation the contractor struck unmarked gas service line to 5515 Hobart Street. The line had no mark outs and no visible curb box, and the line was hit on the public side in the street. The IEI foreman called 911 and Peoples Gas, and the Pittsburgh Fire department arrived on site at 9:20am, Peoples Gas Rep arrived on site at 9:30am. The Peoples Gas Rep called for a repair crew which arrived on site at 10am, and the line was repaired by 10:30am.</p> <p>The Final Design One Call was run by GAI Consultants on Thurs 2/6/2024, which was within the required 10 to 90-day window prior to the end of final design. The Final Design ended on Tues 3/18/2024. The bid date was Thurs 3/28/2024. The total project value is over \$400,000. During design, SUE up to Quality Level (QL) A was performed. The Record Drawing Research (QL-D) was done by the whole project team as the project moved through the design stage. The surface expressions of utilities such as manholes, curb boxes, and valve boxes were surveyed (QL-C). The project owner had GAI include the cost to hire a utility locator as a subcontractor. That was Lexis Group, LLC (Lexis). Lexis connected to the locate wires and metallic pipes to use mark utility locations across the job (QL-B). The surveyor surveyed the paint markings. GAI identified places where the QL-B needed clarification and had Lexis do Test Pits (QL-A) there. Training was previously assigned to GAI for Case 17347 (training completed on Fri 6/10/2022) and Case 030748 (training completed on Fri 3/17/2023).</p> <p>*Peoples Gas Company is in violation of section: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: Penalty Applied</p>	
50822	<p>Facility Owner: Peoples Gas Co Contractor/Excavator: M. O'Herron Co. Project Owner: Penn Township - WESTMORELAND Designer: GIBSON</p>	<p><u>On 10/29/2024 11:33:00 AM at 25 Penntown Dr., PENN TWP, WESTMORELAND</u> West Penn (First Energy) and Penn Township Sewage Authority's violations were removed. ***** Verizon disagreed and stated that they did mark their lines and provided documentation. The DPI has withdrawn the violation of 2(5)(i) to Verizon.</p>	<p>M. O'Herron Co.: \$1,000.00 Section 5(2.1) 1st Offense \$1,000.00</p> <p>COMCAST CABLEVISION: \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>THOMAS ENGINEERING CO INC Other: COMCAST CABLEVISION Other: PENN TOWNSHIP SEWAGE AUTHORITY Other: VERIZON PA LLC Other: West Penn Power / First Energy</p>	<p>* Penn Township Sewage Authority disagreed and stated that "This email is to inform you as you requested that we are in total disagreement with this fine. PTSA responded to each, and every PA 1 call as required by law. In reference to ticket #20242840178: Work site Thomas Jefferson Ct. It was marked by PTSA on 10/24/24 and the response to the ticket was as follows: PTSA will have ALL THE LINES MARKED BY 10/31/2024.It appears to me that the line struck was at 25 Penntown Dr on 10/29/2024.PTSA marked our line at this location for ticket # 20243033511 on 10/29/2024 and called it in on 10/30/2024. I believe that it is very clear that the actions of Penn Township Sewage Authority had absolutely nothing to do with the line strike and therefore we will not be pay the fine .In fact if Penn Township Sewage Authority would have not responded to any of the Pa 1 calls the line would have still been struck.</p> <p>Violatoins have been removed. ***** The incident occurred on 10/29/2024, at 25 Penntown Drive, in Penn Township, Westmoreland County.</p> <p>A gas line was hit and damaged.</p> <p>PENN TOWNSHIP – Westmoreland stated in their Alleged Violation Report (AVR) that “Contractor was saw cutting road @ 6" deep and cut thru service line to residence. PA one Call Ticket #20243020617”. Project length is 10,000’ no other project information was provided. On 11/05/2024 Damage Prevention Investigator (DPI) sent an email asking who the final designer for the project was. Reports were provided. No pictures were provided. On 11/06/2024 Penn Township’s response was they will forward to the Engineer. Gibson Thomas was included in the email. DPI asked Penn Township to verify the contact information. This was never addressed. 2-10 customers were listed as affected by this incident.</p> <p>PEOPLES NATURAL GAS COMPANY stated in their AVR that “One-call LAWFUL START DATE IS 10/31/2024. M O’HERRON company was saw cutting and hit a 1" plastic service 2 days prior of the lawful start date. Site was not marked yet by any utilities”. Pictures were provided. 911 was notified.</p> <p>M OHERRON COMPANY stated in their AVR that “M. O’Herron Co saw cutting pavement in preparation for storm drain replacement in Penntowne housing development for Penn Township. Foreman mistakenly referenced New Excavation (complex) 1call ticket# 20242880962 with lawful start date of Oct 29 instead of New Excavation (routine) 1call ticket#20243020617 with lawful start date of Oct 31. saw cut through shallow gas s/l approximately 6" below pavement grade. Peoples Gas responded to dig out and repair damaged service. On 11/05/2024 Damage Prevention Investigator (DPI)</p>	<p>Section 2(5)(v) Subsequent \$2,000.00</p> <p>PENN TOWNSHIP SEWAGE AUTHORITY: \$0.00</p> <p>VERIZON PA LLC: \$2,000.00 Section 2(5)(viii) Subsequent \$2,000.00</p> <p>West Penn Power / First Energy: \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>requested the Complex Project meeting sign in sheet on 11/05/2024 in an email. On 11/07/2024 a list of attendees was emailed stating that they need to pull a file for this sheet.</p> <p>GIBSON THOMAS ENGINEERING CO INC (GTE), the designer was mailed and emailed AVR request letters on 11/06/2024. They responded quickly that they will submit an AVR.</p> <p>GTE stated that “CONTRACTOR WAS SAW CUTTING ROAD @ 6" DEEP AND CUT THROUGH SERVICE LINE TO RESIDENCE. PA ONECALL TICKET #20233020617”. They listed the project to be >\$400,000. The length of the project as 6000 FT and that level “B” SUE was utilized. There was no information about if this level was used during the design phase of the excavating phase. Pictures of the damage were included. No design work was included. None of the questions in the AVR request letter were answered. On 11/18/2024 DPI sent an email asking for a copy of the first page of the design stating that the questions that were written in the AVR request letter provide information of what is needed. On 11/19/2024 DPI sent an email with the questions that were asked in the AVR about the design.</p> <p>GIBSON THOMAS ENGINEERING CO INC *****</p> <p>Final Design Ticket 20242000770 was requested by Gibson Thomas Engineering Co Inc. on 7/18/2024 with a response due by 8/01/2024. Remarks-- [PROJECT MAPPING HAS BEEN UPLOADED TO THE PA ONE CALL DRAWING PORTAL FOR PROJECT LIMITS AND MARK UP PURPOSES. MAPPING CAN BE MAILED OUT BY REQUEST. PLEASE PROVIDE FACILITY MAPPING AND FIELD MARK UTILITIES IF POSSIBLE. PLEASE CONTACT OUR OFFICE WHEN FIELD MARKING SO THAT WE MAY SCHEDULE A SURVEY OF THE MARKED UTILITIES.]</p> <p>*Complex Project Meeting Ticket 20242880962 was requested by M Oherron Company on 10/14/2024 with a response due by 10/17/2024 and the meeting to be held on 10/18/2024 at 14:15. On 11/07/2024 an email was received with a list of the Penntowne Storm Sewer Preconstruction Meeting Attendees: M.O’Herron- PJ Adamson, Penn Township Road Department -Tom Lamacz, Municipal Authority of Westmoreland County- Mark Sikora, Penn Township Sewage Authority- Mike Sicce, Peoples Gas- Joe Tamburrino.</p> <p>Peoples Gas Company and Penn Township of Westmoreland County responded that they will attend the meeting, but this was never updated in the KARL System.</p> <p>Verizon had no response until 10/24/2024, when they responded with ” Insufficient info conflict”.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>*Ticket 20243020617- was requested by M Oherron Company on 10/28/2024 with a response due by 10/30/2024. Lawful dig date is OCT 31. Extent of excavation is 10,000FT.</p> <p>*Renotify ticket 20243020617-001 was requested by M Oherron Company on 10/30/2024 at 10:12 noting that the 2 hour response is required. Project is the entire Penn Town Estates Neighborhood. 10,000LF and expecting 160 days of excavation. RNO Remarks-- [ATTN WEST PENN POWER, COMCAST AND VERIZON YOU HAVE NOT RESPONDED. CALLER ADVISED WORK WILL BEGIN AT 0700 TOMORROW MORNING. SITE NEEDS TO BE MARKED IN TIME FOR START OF DIG. PLEASE REPORT TO SITE AND MARK LINES ASAP.]</p> <p>West Penn Power and Comcast scheduled mark on 10/30/2024. This was not by mutual agreement. Verizon responded on 10/30/2024 that they field marked, but are also listed by M O'Herron for not marking. * Note that the renotify ticket was placed on the day prior to the legal dig date and Verizon marked their lines on this date and within the legal timeline.</p> <p>Penn Township Sewage Authority field marked late on 10/31/2024.</p> <p>Westmoreland County Municipal Authority responded on 10/30/ 2024 that they are working with PJ on Markings. They were not mentioned to mark/respond in the renotify ticket.</p> <p>*Ticket 202430333511000 was requested by Peoples Gas on 10/29/2024 at 15:32 with a response due by 10/31/2024. Location Information-- [WORKING IN FRONT OF HOUSES 24 AND 25 PENNTOWNE DR TO RENEW LONG SIDE GAS SERVICE. GAS MAIN IS IN THE FRONT YARD OF HOUSE 25 SO WE WILL BE DIGGING THERE AND THE WHOLE WAY ACROSS TO THE PROPERTY OF HOUSE 24 ACROSS THE STREET.]</p> <p>All facility owners responded timely.</p> <p>*Final Design ticket 20242840178 was requested by M O'Herron Co. on 10/10/2024 with a response due by 10/25/2024. Work was for storm sewer installation. All facility owners responded timely.</p> <p>*Final Design 20240032926 was requested by Gibson Thomas Engineering Co Inc. on 1/03/2024 with a response due by 1/18/2024. All facility owners responded timely.</p> <p>*****</p> <p>M. O'Herron Co. is in violation of: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Ticket 20243020617 was requested on 10/28/2024 with a dig date of 10/01/2024. Recommendation: The penalty is applied. Education is required. The required Excavator education was</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>completed by 10/07/2024, but the incident occurred on 10/29/2024</p> <p>VERIZON PA LLC is in violation of: Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). *Please see the details of CPM ticket 20242880962 above. This is a subsequent offense. Recommendation: The penalty is applied. Education is required. Facility owner education was completed b 8/13/2024 but the incident occurred on 10/29/2024.</p> <p>West Penn Power / First Energy is in violation of: Section 2(5)(v) Failed to respond to a routine One Call ticket within the required amount of time. This is a subsequent offense. Recommendation: The penalty is applied. Required Education was completed by 1/07/2025.</p> <p>COMCAST CABLEVISION is in violation of: Section 2(5)(v) Failed to respond to a routine One Call ticket within the required amount of time. This is a subsequent offense. Recommendation: The penalty is applied. Education is required. Facility Owner education was completed by 9/10/2024. The incident occurred on 10/29/2024.</p> <p>PENN TOWNSHIP SEWAGE AUTHORITY is in violation of: Section 2(5)(v) Failed to respond to a routine One Call ticket within the required amount of time. Recommendation: The penalty is applied. Facility Owner education is required.</p>	
51001	<p>Facility Owner: PECO Contractor/Excavator: Joao & Bradley Construction Company Project Owner: Bucks County Water & Sewer Authority Other: AMBLER BOROUGH OF SERVICES Other: AT&T LOCAL SERVICES Other: CROWN CASTLE Other: GILMORE & ASSOCIATES INC Other: VERIZON BUSINESS Other: VERIZON PA LLC Other: ZAYO BANDWIDTH</p>	<p><u>On 11/4/2024 8:00:00 AM at 411S MAIN ST AND RANDOLPH AVE, BETWEEN STATIONS 11+60 TO 18+84, AMBLER BORO, MONTGOMERY AT&T</u> disagreed and asked to have a discussion with the Damage Prevention Committee (DPC). DPI reduced the \$2000. penalty to \$0. but kept the violation because the ticket was never responded to. On 2/07/2025 an email was received stating that AT&T accepted this violation with no penalty. ***** The incident occurred on 11/04/2024 at 411S MAIN ST AND RANDOLPH AVE, BETWEEN STATIONS 11+60 TO 18+84 in Ambler Borough in Montgomery County. A Gas line was hit and damaged. 911 was notified. JOAO AND BRADLEY CONSTRUCTION CO INC stated in their Alleged Violation Report (AVR) that “Hit off the mark a ½” plastic gas service, had to stop digging till 9:30am when peco came to fix the line”. 911 was called. 1 customer was affected. Pictures and reports were provided. An email was received on 12/06/2024 providing the CPM sign-in sheet. JOAO also stated that "Drawings were handed out at the meeting".</p>	<p>PECO: \$2,000.00 Section 2(5)(i) Subsequent \$2,000.00</p> <p>AMBLER BOROUGH OF: \$500.00 Section 2(5)(viii) 1st Offense \$500.00</p> <p>AT&T LOCAL SERVICES: \$0.00 Section 2(5)(viii) Subsequent \$0.00</p> <p>CROWN CASTLE: \$1,000.00 Section 2(5)(viii) 2nd Offense \$1,000.00</p> <p>GILMORE & ASSOCIATES INC: \$500.00 Section 4(5) 2nd Offense \$500.00</p> <p>VERIZON BUSINESS: \$2,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>GILMORE ASSOCIATES the designer and representing the project owner; Bucks County Water and Sewer Authority, stated in their AVR that “Utility Contractor damaged an unmarked gas service. See attached picture”. The project is listed as >\$400,000. The length is 4000ft and no Subsurface Utility Engineering (SUE) is provided. Picture and report were provided.</p> <p>On 12/06/2024 an email was received explaining that “The pre-construction meeting was held on September 25, 2024, where it was discussed with JOAO that revisions to plans were needed due to finalization of easements. Revised plans were provided to JOAO at the meeting due to the easements and the updated one call number. A notice to proceed was issued to JOAO for 10.01.2024 and the construction start was 10.28.2024”.</p> <p>On 12/13/2024 DPI returned a call to Gilmore and Associates who stated they had submitted 2 AVRs but just now realized there was a third incident with damage on the same day. They submitted some of the incorrect information on the AVR, since the three damages got grouped together. They asked how they can remedy this. DPI gave them the telephone number of OneCall to submit an AVR by phone.</p> <p>PECO the facility owner stated in their AVR that “On 11/04/2024 Joao Bradley was trenching at the above location when they struck a mismarked gas service. The service was mismarked due to inaccurate measurements. 0 Injuries, 1 Cust interrupted.</p> <p>Bucks County Water and Sewer Authority, the Project owner is represented by Gilmore Associates for their AVR. *****</p> <p>Complex Project ticket 20242432393 was requested on 8/30/2024 by Joao & Bradley Construction Company with the meeting to be held on 9/05/2024 and a response due by 9/04/2024. Complex Project Sign-in Sheet participants: AT&T, PA1Call, Aqua, NWWA, and G&A designer and representing BCWSA.</p> <p>Verizon never responded. Zayo Bandwidth never responded. Verizon Business never responded. Ambler Borough never responded. AT&T never responded, but they are on the sign-in sheet. Crown Castle responded with insf. info. do not dig and never updated this response to be a final response. *****</p> <p>GILMORE & ASSOCIATES INC is in violation of: Section 4(5) – Designer’s drawing does not include One Call’s toll-free number and the serial number of the ticket. This is a second offense. *See attachment DPI to G&A comparing page 2 of 31. Recommendation: The penalty is applied. The required Education was completed by 12/10/2024.</p> <p>PECO is in violation of: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.</p>	<p>Section 2(5)(viii) Subsequent \$2,500.00</p> <p>VERIZON PA LLC: \$2,000.00 Section 2(5)(viii) Subsequent \$2,000.00</p> <p>ZAYO BANDWIDTH: \$2,500.00 Section 2(5)(viii) Subsequent \$2,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>This is a subsequent offense. The required education was completed by 9/10/2024. This incident occurred on 11/04/2024.</p> <p>Recommendation: The penalty is applied. Facility owner education is required.</p> <p>*****</p> <p>Listed below are facility owners in violation of Act 50, Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project as described in section 5(3).</p> <p>Verizon is in violation of: Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). Ticket 20242432393 was never responded to. This is a subsequent offense. Recommendation: The penalty is applied. Facility Owner education is required. The required education was completed by 8/13/2024. This incident occurred on 11/04/2024.</p> <p>Zayo Bandwidth is in violation of: Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). Ticket 20242432393 was never responded to. This is a subsequent offense. Recommendation: The penalty is applied. Education is required. The DPC has required facility owner education 6 times in the past - all of which Zayo has failed to attend: 4/12/2022 - 26321, 2/14/2023 - 23787, 3/14/2023 - 29504. 5/9/2023 - 32009, 6/12/2024 - 34700, and 7/9/24 - 42978.</p> <p>Verizon Business is in violation of: Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). Ticket 20242432393 was never responded to. Verizon Business is delinquent on DPC ordered education for 6/11/24 - 36553, and 4/9/24 - 36201. Verizon Business is also delinquent on invoice 039785-008156 for \$750.00. They were reminded on 10/10/24 and sent a dunning notice on 11/19/24 and have not paid. All fines raised to \$2500</p> <p>Ambler Borough is in violation of: Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). Ticket 20242432393 was never responded to. Recommendation: The penalty is applied. Facility owner education is required. Project Owner education was completed by 12/10/2024.</p> <p>AT&T never responded is in violation of: Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). Ticket 20242432393 was never responded to. This is a subsequent offense.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Recommendation: The penalty is applied. Education is required. Education was completed by 10/07/2024. This incident occurred on 11/04/2024.</p> <p>Crown Castle is in violation of: Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). Ticket 20242432393 was responded with insf info do not dig and never updated this response to be a final response. This is a second offense.</p> <p>Recommendation: The penalty is applied. Education is required. The required Facility owner education was due by 9/10/2024. This has not been completed to date.</p>	
51245	<p>Facility Owner: Columbia Gas of PA - South</p> <p>Contractor/Excavator: Municipal Authority of Westmoreland County</p> <p>Project Owner: Municipal Authority of Westmoreland County - spacesaver</p>	<p><u>On 11/7/2024 11:08:00 AM at 901 RIDGE AVE, JEANNETTE CITY, WESTMORELAND</u> The incident occurred on 11/07/2024 at 901 RIDGE AVE in Jeanette City in Westmoreland County.</p> <p>A gas line was hit and damaged.</p> <p>Columbia Gas the facility owner stated in their Alleged violation Report (AVR) that "The Municipal Authority of Westmoreland County (MAWC) was digging on an emergency ticket to repair a sewer line when they struck and damaged an unmarked 4" plastic gas main. They immediately notified Columbia Gas when the damage occurred. Columbia is unsure if 911 was notified. Columbia Gas responded immediately to make the area safe and complete repairs. Columbia Gas was unable to locate some underground facilities in the vicinity of this emergency ticket. The Facchiano locator, locating on behalf of Columbia Gas, had very thorough communications with MAWC on where the facilities were unlocatable. The ticket was also thoroughly documented and is attached. MAWC had a vac onsite and agreed to vac in those areas. However, they did not vac to find the gas main and damaged the facility. The notes stating, "1020 Whiteman St. (apartment building) wire at meter locates service does not locate main. Searched intersection for Marker balls did not locate any, did not locate any other tracer wire point," are the notes specific to where the damage occurred. Miller Pipeline has since assisted Columbia Gas with vac'ing these problem locate areas to make them locatable. Those notes from 11/12/2024 are also visible on the attached ticket". Pictures and reports were provided.</p> <p>WESTMORELAND CO MUNI AUTH stated in their AVR that "Project Owner and Excavator, Municipal Authority of Westmoreland County (MAWC) was working under emergency ticket 20243102277 to repair a collapsed sewer line along Ridge Avenue. MAWC placed this ticket on 11/5/2024. On 11/6/2024 MAWC began its saw cutting of the proposed area of excavation. There were no marks for any gas lines in the area. On 11/7/2024 MAWC discovered a potential gas line, MAWC contacted Columbia gas and offered to pothole this gas line to help Columbia gas mark its unmarked facilities. Columbia attempted to mark its lines. on</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>11/7/2024 MAWC struck an unmarked gas line. Prior to beginning work on 11/6/2024 MAWC conducted a site evaluation and relied on the existing utility markings. There was no clear indication of the presence of the gas line in the area where the excavation was to occur. After the gas line was hit MAWC immediately halted work. Emergency protocols were taken, and the area was secured to ensure safety. MAWC called 911 to notify local emergency services of the escape of gas. Columbia Gas was contacted and promptly dispatched to assess the situation. Columbia made necessary repairs to the gas line, MAWC stayed on-site to assist Columbia as needed during the repair of the gas line. Once Columbia completed their repair and testing, MAWC resumed work, and successfully tied in the sewer line, and backfilled the area. Pictures were provided.</p> <p>***** No violations found</p>	

Full Session

Case Number	Stakeholders	Summary	Violations & Recommendation
47056	<p>Facility Owner: Columbia Gas of PA - South</p> <p>Contractor/Excavator: WRIGHT ASPHALT AND CONCRETE</p> <p>Project Owner: City of Jeannette</p> <p>Designer: Antonacci Design Associates, INC</p> <p>Other: Comcast</p> <p>Other: Verizon PA LLC</p>	<p>On 5/8/2024 8:44:00 AM at 907 WYLIE AVE, JEANNETTE CITY, WESTMORELAND On 3/11/25 the Ditty motioned to remove both violations and penalties for Antonacci Design Associates.</p> <p>*****</p> <p>Antonacci Design Assoc. is disputing.</p> <p>*****</p> <p>City of Jeannette accepted resolution.</p> <p>*****</p> <p>Columbia Gas violation and penalty were removed after reviewing new pictures and emergency damage site.</p> <p>*****</p> <p>Incident occurred on May 8th, 2024, at 8:44am at 907 Wylie Avenue, Jeannette City, Westmoreland County.</p> <p>A gas line was damaged.</p> <p>Columbia Gas Company's Alleged Violation Report (AVR) states, "W.D. Wright Asphalt and Concrete struck an unmarked 1" plastic gas service feeding 907 Wylie Ave., Jeannette, while milling at 12" deep. They notified 911 and Columbia Gas when the damage occurred. Columbia Gas responded immediately to make the area safe and complete repairs, which consisted of lowering the gas facility to prevent a future incident due to shallow depth. Additionally, local operations installed a marker ball and updated the Service Line Record. A review of events leading up to the damage was conducted to determine why the gas service was not marked. W.D. Wright did not accurately describe the work location, or the work being performed on the routine ticket. This work should have been a Complex Project, as it spans multiple streets and intersections. The ticket describes work taking place as replacing handicap ramps at intersections from Baughman Avenue to the dead end of Wylie Ave. There was no existing handicap ramp at the location of the damage."</p>	<p>Columbia Gas of PA - South: \$0.00</p> <p>WRIGHT ASPHALT AND CONCRETE: \$1,000.00 Section 5(3) 1st Offense \$250.00</p> <p>Section 5(16) 1st Offense \$500.00</p> <p>Section 5(20) 1st Offense \$250.00</p> <p>City of Jeannette: \$1,500.00 Section 6.1(3) 1st Offense \$500.00</p> <p>Section 6.1(7) 1st Offense \$1,000.00</p> <p>Antonacci Design Associates, INC: \$0.00</p> <p>Comcast: \$500.00 Section 2(4) 2nd Offense \$500.00</p> <p>Verizon PA LLC: \$1,000.00 Section 2(4) 3rd Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Wright Asphalt & Concrete, Antonacci Design, and Jeanette Borough were mailed and emailed requests to submit AVRs. No AVR has been received to date from Jeannette Borough. Wright Asphalt & Concrete submitted their AVR four months after the line strike.</p> <p>WRIGHT ASPHALT AND CONCRETE's AVR was blank, but noted 911 was called.</p> <p>Antonacci Design Associates' AVR states, "While doing excavation work for street base repair, a gas service lateral was struck. The service lateral had a measured depth of 9 inches below grade to the damaged section. The same service lateral had other measurements below grade that averaged 13 inches. The damaged service lateral had a change in elevation due to concrete being present in the roadway subbase. City of Jeannette Fire Department was first on the scene and plug the service line. Columbia Gas representatives arrived on the scene and repaired and lowered the service line. Roadway base repair was than completed."</p> <p>Antonacci Design group failed to submit a final design ticket. Paperwork for bids include PennDOT specifications.</p> <p>Design tickets show that this was part of a larger project as well as multiple intersections over 1,000ft.</p> <p>Violations:</p> <p>Columbia Gas Company Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.</p> <p>Wright Asphalt Section 5(3) – Excavator failed to hold a preconstruction meeting prior to beginning a complex project. Education is required. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. Education is required. Section 5(20) – Excavator failed to renotify One Call of an unmarked or incorrectly marked facility upon arrival at a work site. Education is required.</p> <p>City of Jeannette Section 6.1(3) – Released a project to bid or construction before final design was complete. Education is required. Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 10 Business Days of a line strike. Education is required. (City of Jeannette has yet to complete training that was due on 12/31/2023. DPC ordered the City to attend on September 12, 2023. All penalties raised to \$2500.00 for failure to comply with all DPC orders.</p> <p>Antonacci Design Associates</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 4(2) – Designer failed to request the line and facility information prescribed by section 2(4) from the One Call System not less than ten nor more than ninety business days before final design is to be completed. Education is required.</p> <p>Section 4(5) – Designer’s drawing does not include One Call’s toll-free number and the serial number of the ticket. Education is required.</p> <p>Verizon PA LLC Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20232132841</p> <p>Comcast Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20232132841</p>	
47270	<p>Facility Owner: Columbia Gas of PA - Central</p> <p>Contractor/Excavator: Watson Excavating Inc</p> <p>Project Owner: GORDON TERMINAL SERVICE</p> <p>Other: McKees Rocks Borough</p>	<p><u>On 5/14/2024 11:47:00 AM at ELLA ST, MCKEES ROCKS BORO, ALLEGHENY</u> On 3/11/25 the DPC voted to accept DPI’s recommendation. *****</p> <p>Watson Excavating of Prosperity, PA disputed. DPI was provided with the incorrect excavator's contact information by the original submitter. When the DPI reached out to the Watson Excavating, we were told was at the site by asking for an AVR they failed to make a response and the DPI had no way of knowing we had the wrong Watson until they disputed during stakeholder review. Violations and penalties have been removed.</p> <p>Correct Excavator is: Jim Watson Watson Excavating 3662 Frew Mill Rd New Castle, PA 16101</p> <p>*****</p> <p>McKees Rocks Boro is disputing their no response to a routine ticket placed within the boro. See dispute email *****</p> <p>Incident occurred on May 14th, 2024 at 11:47am along Ella Street, McKees Rocks Boro, Allegheny County.</p> <p>An idle gas stub was damaged.</p> <p>Columbia Gas Company's Alleged Violation Report (AVR) states, "Watson Excavating was digging without a One Call when they struck and damaged an idle stub. Watson Excavating notified 911. According to Columbia's call records, a passerby named Karen called in the line strike to Columbia Gas. Columbia Gas responded immediately to make the area safe and complete repairs."</p> <p>Watson Excavating has placed notifications with PA One Call in the past. Pictures show Watson Excavating equipment on site.</p> <p>Gordon Terminal Service's AVR states, "April 25, 2024 8:47 am PA-1 call made for Excavation of 3 pads 3' W x 5' L x 3' D. The pads were marked with white paint. Ticket confirmation received April 25, 2024 8:47 am.</p>	<p>Watson Excavating Inc: \$0.00</p> <p>McKees Rocks Borough: \$500.00 Section 2(5)(v) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>#20241160713. Ticket confirmation received April 30, 2024 2:09 #20241160714. Columbia and Peoples gas marked field. May 14, 2024 9:00 am during excavation an unmarked 1" low gas pressure line was punctured. 911 call made and gas companies called to repair. Either company had any knowledge of this 1" line and did NOT know who it belonged to. Finally, Columbia gas took ownership and repaired it."</p> <p>Gordon Terminal Service filed their AVR as the Project Owner and not as the excavator.</p> <p>Watson Excavating was mailed a request for an AVR on 9/16/2024. No AVR was submitted to date.</p> <p>Violations:</p> <p>Watson Excavating Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Education is required. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. Education is required. Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. Education is required.</p> <p>McKees Rocks Borough Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20241160714. Education is required.</p>	
48445	<p>Facility Owner: PENNSYLVANIA AMERICAN WATER Contractor/Excavator: Mosites Construction Company Project Owner: PENNDOT Designer: ALFRED BENESCH AND COMPANY Other: CITY OF CONNELLSVILLE Other: VERIZON BUSINESS Other: VERIZON PA LLC</p>	<p><u>On 5/29/2024 2:00:00 PM at N ARCH ST, CONNELLSVILLE CITY, FAYETTE</u> On 3/11/2025 the Damage Prevention Committee voted to Remove the violation and penalties to PennDOT. Alfred Benesch Company was a no show. The DPC voted to keep all the violations and penalties to Alfred Benesch Company. ***** PennDOT disagreed and stated that Robert Epley will be representing the district challenge and can provide details in the near future. DPI responded that "I have listed case 48445 disputed by PennDOT. Please provide any information that you would like considered prior to 1/17/2025. The Damage Prevention Committee will not consider any new information that is presented at the meeting. PennDOT sent in A Subsurface Utility Engineering (SUE) Evaluation Form that was not dated or signed, but showed the results that Based on the answers in the impact analysis the recommended SUE Quality Level is "A", the Designer suggested that Sue quality level recommendation is "C", and the Project Manager decision is that level "B" will suffice for the current SUE level needed. See attachment SUE Evaluation. An email was received on 1/23/2025 stating that PennDOT is not sure who filled this form out. I have received the bid date and design information from Alfred Benesch and Company and have withdrawn the violation of Section 6.1(3) Released a project to bid or construction before the final design was complete.</p>	<p>PENNSYLVANIA AMERICAN WATER: \$1,500.00 Section 2(5)(i) 3rd Offense \$1,500.00</p> <p>Mosites Construction Company: \$0.00</p> <p>PENNDOT: \$0.00</p> <p>ALFRED BENESCH AND COMPANY: \$250.00 Section 4(4) 1st Offense \$250.00</p> <p>CITY OF CONNELLSVILLE: \$250.00 Section 2(4) 1st Offense \$250.00</p> <p>VERIZON BUSINESS: \$5,250.00 Section 2(4) 3rd Offense \$2,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>I have maintained the violation of 6.1(1) Failed to use sufficient levels of Subsurface Utility Engineering. Benesch provided notes that were prepared during the Complex Project meetings that described Columbia Gas facilities and PAWC stating that ...Columbia's facilities should be deep enough. Another note for PAWC reads that ...the waterlines appear to not be impacted by the proposed construction as the full depth of reconstruction limits are minimal, and the water lines should be deep enough...SUE is mentioned as a possibility to be done. I am looking for documentation of the SUE that was done to avoid damage, specifically noting distance of underground utility lines to each other".</p> <p>*</p> <p>Benesch disagreed and sent a letter stating that they requested a "final design on 3/01/2023 and the project was let on 5/11/2023". They also stated that this particular area has service lines that are close to 100 years old whose locations are unknown to both the provider and the customer". Please see Benesch letter - disagreement for more information.</p> <p>DPI sent an email asking about the final design ticket and compared the routine ticket 20241303574 and 20241303688 area that the excavator submitted. The final design did not include the intersections, and the excavation tickets provided are clearly on N Arch St. where the incident occurred. Violation Section 4(2) is withdrawn because information was provided about the bid and when the work began. 1/7/2025 DPI sent an email stating that violation 4(4) Failed to prepare construction drawings to avoid damage and minimize interference with facilities in the area. See attachment titled Not SUE with notes describing Columbia Gas facilities and PAWC read ...Columbia's facilities should be deep enough. Another note for PAWC reads that ...the waterlines appear to not be impacted by the proposed construction as the full depth of reconstruction limits are minimal, and the water lines should be deep enough...SUE is mentioned as a possibility to be done. a detailed explanation of why.</p> <p>*Please see attachment DPI responds to Benesch.</p> <p>*</p> <p>Mosites Construction Company disagrees and sent a letter stating that they performed the needed OneCalls prior to construction, met with the appropriate facility owners and maintained markings. Please see Mosites disagrees and Responds attachment for full letter. After reviewing the information, both violations section 5(3)n are withdrawn.</p> <p>*****</p> <p>The incident occurred on 5/29/2024 on N Arch St in Connellsville City in Fayette County.</p> <p>A water line was hit.</p> <p>MOSITES CONSTRUCTION COMPANY the excavator stated in their Alleged Violation Report (AVR) that the project cost over \$400,000, the length was 850'. Comments stated that "During excavation of</p>	<p>Section 2(4) 3rd Offense \$2,500.00</p> <p>Section 9 1st Offense \$250.00</p> <p>VERIZON PA LLC: \$250.00</p> <p>Section 2(4) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>new stormwater management a 3/4" service water line was struck and damaged. This line was unmarked. PA American Water was notified which followed with a site visit, and a repair performed".</p> <p>PENNSYLVANIA AMERICAN WATER stated in their AVR that "Mosites Excavation was installing a storm drain and hit a unmarked service line".- They also noted that there was a meter pit indicating that there were facilities in the area.</p> <p>PENNDOT stated in their AVR that "Mosites Construction Company was excavating for new storm sewer installation and dug through an existing 3/4 inch water service line that was not marked. This service line runs perpendicular to an existing water main that was marked. Pennsylvania American Water was notified, came out, and installed a repair. They also listed the project cost over \$400,000, the length was 850' On 11/22/2024 PennDOT sent an email with more pictures of the damage.</p> <p>ALFRED BENCH AND COMPANY stated in their AVR that "Mosites Construction Company was excavating for new storm sewer installation and dug through an existing 3/4 inch water service line that was not marked. This service line runs perpendicular to an existing water main that was marked. Pennsylvania American Water was notified, came out, and installed a repair".</p> <p>Preliminary Design ticket 20202532047 was requested by ALFRED BENESCH AND COMPANY on 9/09/2020 with a response due by 9/23/2020. Verizon Business never responded. City of Connellsville never responded.</p> <p>Final Design ticket 20230602677 Was requested by ALFRED BENESCH AND COMPANY on 3/01/2023 with a response due by 3/15/2023. Remarks-- [FINAL DESIGN PA ONE CALL FOR AN UPDATED SERIAL NUMBER. NO ADDITIONAL MARKINGS OR PLANS ARE NEEDED AT THIS TIME.] *This is 2.5 YEARS after THE PRELIMINARY DESIGN WAS SUBMITTED. Verizon Business never responded. Connellsville Municipal Authority requests a meeting. DCTF by FO. Verizon never responds.</p> <p>Ticket 20241303574 was requested by MOSITES CONSTRUCTION COMPANY on 5/09/2024 with a response due by 5/13/2024. {WORKING FROM THE INTERSECTION OF W CRAWFORD AVENUE ON NORTH ARCH STREET APPROXIMATELY 80 LF. WORK IS IN THE ROADWAY AND SIDEWALK AREAS] All facility owners responded timely.</p> <p>Ticket 20241303688 was requested by MOSITES CONSTRUCTION COMPANY on 5/09/2024 with a</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>response due by 5/13/2024. [WORKING IN THE DEAN STREET ROADWAY AND SIDEWALKS FROM THE INTERSECTION OF WATER STREET TO NORTH ARCH STREET.] All facility owners responded timely.</p> <p>*Please note that all the tickets give a single linear length but note where the incident occurred. This area needs to be considered in length calculations. *****</p> <p>PENNSYLVANIA AMERICAN WATER is in violation of: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. This is a third offense. Recommendation: The penalty is applied. The required education was completed by 9/10/2024.</p> <p>Mosites Construction Company Section 5(3) – Excavator failed to preserve mark-outs or request a remark. PAWC stated that here was a meter pit indicating that there were facilities in the area. Section 5(3) – Excavator failed to hold a preconstruction meeting prior to beginning a complex project. Please see Preliminary Design ticket 20202532047 image of the scope of the project. See also attachment named "the work done is not a single road over 1000" Recommendation: The penalty is applied. Education is required.</p> <p>PENNDOT is in violation of: Section 6.1(1) – Failed to utilize sufficient quality levels of subsurface utility engineering or other similar techniques to properly determine the existence and positions of underground facilities when designing known complex projects having an estimated cost of (\$400,000) or more. See attachment titled Not SUE with notes describing Columbia Gas facilities and PAWC read ...Columbia's facilities should be deep enough. Another note for PAWC reads that ...the waterlines appear to not be impacted by the proposed construction as the full depth of reconstruction limits are minimal, and the water lines should be deep enough...SUE is mentioned as a possibility to be done. Recommendation: The penalty is applied. The required education was completed by 11/13/2024.</p> <p>ALFRED BENESCH AND COMPANY is in violation of: Section 4(4) – Failed to prepare construction drawings to avoid damage to and minimize interference with facilities in the construction area. See attachment titled Not SUE with notes describing Columbia Gas facilities and PAWC read ...Columbia's facilities should be deep enough. Another note for PAWC reads that ...the waterlines appear to not be impacted by the proposed construction as the full depth of reconstruction limits are minimal, and the water lines should be deep enough...SUE is mentioned as a possibility to be done. Recommendation: The penalty is applied. Education is required.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>CITY OF CONNELLSVILLE is in violation of: Section 2(4) – Failed to respond to designer’s request for information within 10 business days. City of Connellsville never responded to Design ticket 20202532047. Then for Final Design ticket 20230602677 City of Connellsville requested a meeting. Recommendation: The penalty is applied. Education is required.</p> <p>VERIZON BUSINESS is in violation of: Section 2(4) – Failed to respond to designer’s request for information within 10 business days. Design ticket 20202532047 and ticket 20230602677 were never responded to. These are third offense violations. The required education has never been completed. The \$1000 penalty for each offense is raised to \$2500. Section 9 – Failed to make the best efforts to comply with the Common Ground Alliance Best Practices – CGA 5-16 Federal and State Regulations for required training. Recommendation: The penalty is applied, and Education is required. The required education has not been completed to date.</p> <p>VERIZON PA LLC is in violation of: Section 2(4) – Failed to respond to designer’s request for information within 10 business days. Design ticket 20230602677 was never responded to. Recommendation: The penalty is applied. The required education was completed by 8/13/2024.</p>	
47473	<p>Facility Owner: Peoples Gas Contractor/Excavator: Armstrong Utilities Project Owner: Armstrong Utilities - Placeholder Designer: Armstrong Utilities - Placeholder Other: Evans City Water and Sewer Authority</p>	<p><u>On 6/4/2024 10:30:00 AM at 1655 -1661 CHAPEL RIDGE LN, ADAMS TWP, BUTLER</u> On 03/11/2025: The DPC voted to accept DPI’s recommendation. No changes in the violation or penalty for EVANS CITY WATER AND SEWER AUTHORITY.</p> <p>***** EVANS CITY WATER AND SEWER AUTHORITY is disputing. ***** The incident occurred on 06/04/2024 at 10:30 AM, at 1655 -1661 Chapel Ridge Lane, Adams Township, Butler County.</p> <p>A properly marked gas line owned by Peoples Gas, was damaged. 911 was called.</p> <p>Peoples Gas submitted an Alleged Violation Report (AVR). Their AVR states, "On 6/4/2024, Armstrong was boring to install cable along chapel hill court when they hit an accurately marked 2" PNG mainline. PNG was notified and made the necessary repairs." Photos were submitted.</p> <p>Armstrong Utilities submitted an AVR. Their AVR states, "Armstrong’s underground construction crew was directional boring under a valid dig ticket 20241480043. The bore path was going around a turn in the road and</p>	<p>Armstrong Utilities: \$500.00 Section 5(4) 1st Offense \$500.00</p> <p>Evans City Water and Sewer Authority: \$500.00 Section 2(5)(viii) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>the employee locating failed to accurately check the drill head to ensure it was tracking properly remaining out of the tolerance zone for the gas line. Armstrong will provide additional training to the crew to help ensure drilling best practices are followed in the future." Photos were submitted.</p> <p>File ARMSTRONG 6933786_report includes a sign in sheet for the complex project meeting, ticket 20241220547. EVANS CITY WATER AND SEWER AUTHORITY is not listed as attending the meeting. The meeting was held virtually and not in person.</p> <p>Violations:</p> <p>EVANS CITY WATER AND SEWER AUTHORITY - - Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). Complex Project ticket 20241220547 had a response due date of 05/05/2024. EVANS CITY WATER AND SEWER AUTHORITY responded "CLEAR. WILL NOT ATTEND MEETING" on 5/24/2024. Recommendation: The penalty is applied. Education is required. No prior violations.</p> <p>Armstrong Utilities - Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: The penalty is applied. Education is required. No prior violation of 5(4).</p>	
47702	<p>Facility Owner: North Fayette County Municipal Authority Contractor/Excavator: Precision Pipeline Solutions Project Owner: Columbia Gas of PA Designer: Columbia Gas - Spacesaver Other: ARMSTRONG GROUP OF COMPANIES Other: BREEZELINE Other: PERRY TOWNSHIP FAYETTE CO Other: PERRY TOWNSHIP MUNICIPAL AUTHORITY Other: PERRYBOROUGH OF Other: VERIZON BUSINESS Other: VERIZON PA LLC</p>	<p>On 6/10/2024 11:00:00 AM at RIVER RD, PERRYOPOLIS BORO, FAYETTE On 3/11/2025 the Damage Prevention Committee voted to accept the Damage Prevention Investigators recommendations as presented for Perryopolis Borough and Perry Township who was a no show. Remove education to Perry Township. ***** Perryopolis Borough disagreed and sent a letter stating that the identified line strike on River Road is not an area that is situated in the Borough of Perryopolis. Please see Perryopolis letter for more information. * Perry Township Fayette Co. disagreed and stated that "Perry Township is responding to the above case 047702 to disagree with the findings and the penalties. We are a small municipality with some overlapping responsibilities with our personnel. It is ultimately my responsibility to ensure compliance. Understanding the need for this system is critical for the safety of the public. The design ticket that we are sighted for not responding to in a timely manner was due to my not understanding the need to do so. We ask for your cooperation in alleviating the need for a monetary penalty in this matter". DPS Locke offered them a warning on both violations in exchange for attending education by March 1. Perry Township attended and</p>	<p>North Fayette County Municipal Authority: \$0.00</p> <p>Columbia Gas of PA: \$2,000.00 Section 4(2) 1st Offense \$500.00 Section 4(3) 1st Offense \$250.00 Section 4(4) 1st Offense \$250.00 Section 6.1(3) 1st Offense \$500.00 Section 6.1(1) 1st Offense \$500.00</p> <p>ARMSTRONG GROUP OF COMPANIES: \$2,500.00 Section 2(4) 1st Offense \$2,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>passed on February 18, 2025. Violations reduced to a warning.</p> <p>North Fayette County Municipal Authority is disagreeing. They stated that "I just read the report on this case 047702 and it is totally wrong. We did have our line marked correctly, and the original design was the gas was suppose to be on the other side of the road. They moved it in the field, and put it next to our line. The reason they sent the camera with marking equipment up our line was they wanted to see how close they could get to our line, so they did not have to move their cut too far. When I arrived onsite, it was not told to me prior that they were next to our line until they broke it. The pictures are attached. Our markings was on the road about 1' from the side. We would of asked for a 5' distance between pipes". No new documents were provided.</p> <p>DPI sent an email on 12/24/24 stating that "I have marked your disagreement in case 47702 and attached the pictures. The report is based on the information received from all of the parties. I If there is any other information that you would like to have considered, please provide that by 12/27/2024. I would like to see some more information about this change. The tickets that i am seeing state to mark the entire road. I see that a meeting was requested by North Fayette County Municipal Authority on ticket 20241081540. Was this meeting ever held? Is there any information that you can provide about this. Were you provided any maps of their designs? Was this information provided with the AVR? Do you have anything showing what side of the road they will be working on? Do you have any date /time stamped pictures showing the line was marked completely. How did you know how far to mark?" No new information has been received to date.</p> <p>On 12/27/2024 an email was received from NFCMA stating that the DPS had withdrawn all of the 3 violations.</p> <p>Violations to NFCMA are withdrawn. *****</p> <p>The incident occurred on 6/10/2024 on River Rd in Perryopolis Borough in Fayette County.</p> <p>A water line was hit and damaged. Up to 50 customers were affected.</p> <p>PRECISION PIPELINE SOLUTIONS the excavator stated in their Alleged Violation Report (AVR) that "North Fayette Water Authority indicated that they had transite water line running along river road but were unable to accurately locate the main. They had indicated to us that the line was in the grass along the edge of the road. No marks were placed, occasionally, they would place 6" TRAN along the edge of the road, but no specific marks were placed. Again, we were told that their best estimate was it was in the grass along the road. The water line came out into road into our run line and was damaged. After the damage, we offered to run a Jamison tool up the water line to allow the water</p>	<p>BREEZELINE: \$500.00 Section 2(4) 2nd Offense \$500.00</p> <p>PERRY TOWNSHIP FAYETTE CO: \$0.00 Section 2(4) 1st Offense \$0.00</p> <p>Section 2(5)(viii) 1st Offense \$0.00</p> <p>PERRYOPOLIS BOROUGH OF: \$750.00 Section 2(4) 1st Offense \$250.00</p> <p>Section 2(5)(viii) 1st Offense \$500.00</p> <p>VERIZON BUSINESS: \$5,000.00 Section 2(4) Subsequent \$2,500.00</p> <p>Section 2(4) Subsequent \$2,500.00</p> <p>VERIZON PA LLC: \$3,000.00 Section 2(4) Subsequent \$1,500.00</p> <p>Section 2(4) Subsequent \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>company to accurately mark their facility. The water company placed accurate marks after this effort was made. Pictures River Road 1,2,3 are prior to the Jamison Tool use and Pictures River Road 4,5 are after.</p> <p>Columbia Gas of PA the project owner and designer stated in their AVR that “Precision Pipeline Solutions, working on behalf of Columbia Gas for an infrastructure replacement project, struck an incompletely marked 6" transite water main while digging to install a new gas line. Upon striking this line, they contacted North Fayette to make repairs. When North Fayette arrived and were able to shut off the water, PPS suggested pushing their Jameson up the line from the break for them to get accurate markings. There were no paint lines prior to this. North Fayette expressed to PPS that they did not know exactly where the line was, nor did they have a way to locate it due to it being transite without wire. North Fayette made the necessary repairs prior to restoring service to the affected customers”.</p> <p>NORTH FAYETTE COUNTY MUNICIPAL AUTHORITY the facility owner stated in their AVR that 11-50 customers were affected. There was no summary provided. On 10/07/2024 Damage Prevention Investigator (DPI) sent an email asking for the amount of customers that were affected and the cost of the damage. No information has been received to date.</p> <p>Complex Project Meeting attendees: Precision Pipeline Solutions, MAWC, Verizon, Perry Township, North Fayette Township Water, North Fayette, and South Huntington Township. *****</p> <p>*Preliminary Design ticket 20223041405 was submitted by Columbia Gas on 10/31/2022 with a response due by 11/15/2022. Perryopolis Borough never responded. Breezeline has no response until 11/16/2022 Verizon never responded.</p> <p>*Preliminary Design ticket 20223041406 was requested by Columbia Gas on 10/31/2022 with a response due by 11/15/2022. Perry Township Fayette Co responded Insf info. Do not dig and never updated this information. Armstrong did not respond until 11/16/2022. Verizon Business never responded. Verizon never responded.</p> <p>*Preliminary Design ticket 20223041406 was requested by Columbia Gas on 10/31/2022 with a response due by 11/15/2022. Verizon Business never responded.</p> <p>*Complex Project ticket 20240781564 was requested by Columbia Gas on 3/18/2024 with the meeting to be held on 3/21/2024 at 11:00 and a response due by 3/20/2024. Perryopolis Borough never responded. They are not on the Complex meeting sign-in sheet.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Perry Township Municipal Authority never responded. They are on the Complex Meeting Sign-in sheet.</p> <p>*Complex Project ticket 20240781565 was requested by Columbia Gas on 3/18/2024 with the meeting to be held on 3/21/2024 at 11:00 and a response due by 3/20/2024. South Huntington Township responded that they will attend the meeting. They are on the CP meeting sign in sheet.</p> <p>The Westmoreland County Municipal Authority responded that they will attend the meeting. They are on the CP meeting sign in sheet.</p> <p>*Ticket 20241081487 was requested by precision Pipeline solutions on 4/17/2024 with a response due by 4/23/2024. All facility owners responded timely. North Fayette County Municipal Authority is not a facility owner on this ticket.</p> <p>*Ticket 20241081488 was requested by precision Pipeline solutions on 4/17/2024 with a response due by 4/23/2024. North Fayette County Municipal Authority Requested a meeting. DCTF on 4/23/2024 and filed marked on 5/03/2024.</p> <p>*Ticket 20241081538 was requested by precision Pipeline solutions on 4/17/2024 with a response due by 4/23/2024. Mark out for 3' X 6600'. River Rd. in Fayette Co. North Fayette County requests a meeting. DCTF by FO. Field marked by 5/03/20245.</p> <p>*Ticket 20241081539 was requested by precision Pipeline solutions on 4/17/2024 with a response due by 4/23/2024. Mark out for 3' X 6600'. River Rd. in Westmoreland Co. All facility owners responded timely.</p> <p>*Ticket 20241081540 was requested by precision Pipeline solutions on 4/17/2024 with a response due by 4/23/2024. Mark out for 3' X 6600'. River Rd. in Fayette Co. North Fayette County Municipal Authority requested a meeting. Field marked by 5/03/20245.</p> <p>*****</p> <p>North Fayette Municipal Authority (NFMA) is in violation of:</p> <p>Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.</p> <p>Section 2(5)(iii.1) – Facility owner failed to propose a mutually agreeable scheduling by which the excavator, facility owner or designer may locate the facilities.</p> <p>Section 2(11) – Facility Owner failed to comply with all requests for information by the Commission relation to the Commission’s enforcement authority under this act within thirty days of the receipt of the request. An email was sent on 10-07-2024 asking how many people were affected and the cost of the damage. No response was ever received.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Columbia Gas is in violation of Sections: Section 6.1(1) – Failed to utilize sufficient quality levels of subsurface utility engineering or other similar techniques to properly determine the existence and positions of underground facilities when designing known complex projects having an estimated cost of (\$400,000) or more. Section 6.1(3) – Released a project to bid or construction before final design was complete. Section 4(2) – Designer failed to request the line and facility information prescribed by section 2(4) from the One Call System not less than ten nor more than ninety business days before final design is to be completed. Section 4(3) – Designer’s drawing does not show the position and type of each facility owner’s line, and the name of the facility. Section 4(4) – Failed to prepare construction drawings to avoid damage to and minimize interference with facilities in the construction area ***** Listed below are facility owners in violation of Act 50, Section 2(5)(v) Failed to respond to a routine One Call ticket and 2(5)(v) Failed to respond to a routine One Call ticket within the required amount of time. Violation Section 2(4) – Failed to respond to Designer’s request for information within 10 Business days. Violation 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project as described in section 5(3).</p> <p>Verizon Business is in violation of: Section 2(4) – Failed to respond to designer’s request for information within 10 business days. Ticket 20223041407 and ticket 20223041406 were never responded to. This is a subsequent offense. Recommendation: The subsequent offense penalty of \$1500 has been raised to \$2500. because the required education has not been taken to date. The DPC sent Verizon Business to Facility Owner education on 4/9/24 for case 036201 and 6/11/24 for case 036553. Verizon has not attended. Education is required.</p> <p>PERRYOPOLIS BOROUGH OF is in violation of: Section 2(4) – Failed to respond to designer’s request for information within 10 business days. Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). They never responded to CP Meeting ticket 20240781564 and are not on the sign-in sheet. Design ticket 20223041405 was never responded to. Recommendation: The penalty is applied. Education is required.</p> <p>BREEZELINE is in violation of: Section 2(4) – Failed to respond to designer’s request for information within 10 business days. Design ticket 20223041405 was not responded to until 11/16/2022. This is a second offense.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Recommendation: The penalty is applied. The training required is due by 12/10/2024.</p> <p>VERIZON PA LLC is in violation of: Section 2(4) – Failed to respond to designer’s request for information within 10 business days. Design tickets- 20223041405 and 20223041406 were never responded to. These are subsequent violations. Recommendation: The penalties are applied. The required education was taken by 8/13/2024.</p> <p>ARMSTRONG TELEPHONE COMPANY PA is in violation of: Section 2(4) – Failed to respond to designer’s request for information within 10 business days. Design ticket 20223041406 was not responded to until 11/16/2022. This is a second-time offense. Recommendation: The \$500. Second offense penalty is raised to \$2500. for not completing the required education by the due date. The required education was due by 10/07/2024 for cases 040354 and 040356 Education is required.</p> <p>PERRY TOWNSHIP FAYETTE CO is in violation of: Section 2(4) – Failed to respond to designer’s request for information within 10 business days. Design ticket 20223041406 information was insufficient info. Do not dig. This was never updated. Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). CP Meeting ticket 20240781564 was responded to that they will attend the CP meeting. This was never updated. They are on the CP meeting sign in sheet. The \$500. Penalty is reduced to a warning. Recommendation: The penalty is applied. Education is required.</p> <p>PERRY TOWNSHIP Municipal Authority (PTMA) is in violation of: Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). CP Meeting ticket 20240781564 was never responded to. They are listed on the CP sign-in sheet. Recommendation: The penalty is applied. The required facility owner education was completed by 7/09/2024.</p>	
48018	<p>Facility Owner: Columbia Gas of PA - South</p> <p>Contractor/Excavator: West Brownsville Borough</p> <p>Project Owner: West Brownsville Borough</p>	<p><u>On 6/13/2024 9:09:00 AM at 401 MONROE AVE, WEST BROWNSVILLE BORO, WASHINGTON</u> Tuesday, March 11, 2025, at the DPC meeting, disputing was West Brownsville Borough, and it was voted to Keep/Accept DPI’s Recommendations for sections 5(4) and 5(16). Remove the penalties but keep violations and education for sections 5(8), 2(5)(v), 2(5)(vii). ***** Dispute- West Brownsville Borough wants to dispute all penalties and violations and their reason is "After review of the above referenced report, West Brownsville Borough and Street Commissioner Todd King, would like to reject the DPI Report. The Borough and Street</p>	<p>Columbia Gas of PA - South: \$500.00 Section 2(5)(v) 1st Offense \$500.00</p> <p>West Brownsville Borough: \$1,000.00 Section 2(5)(v) 1st Offense \$0.00</p> <p>Section 2(5)(vii) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Commissioner King feel that the reported incident was correctly responded to, and all proper procedures were followed. Furthermore, we feel that the initial reporting from Columbia Gas is false, therefore the violations are unfounded."</p> <p>*****</p> <p>The incident occurred on Thursday, June 13, 2024, at 401 Monroe Avenue, in West Brownsville Borough, Washington County.</p> <p>A Columbia Gas line was damaged.</p> <p>Columbia Gas reported that West Brownsville Borough failed to use prudent techniques within the tolerance zone and explained while the borough was repairing a storm drain when they struck and damaged the accurately marked 2-inch plastic, low pressure gas mainline with their excavator, resulting in a 14 customer outage. They notified Columbia Gas directly when the damage occurred.</p> <p>On Wednesday, September 4, 2024, an email and letter was sent requesting an Alleged Violation Report (AVR) from the excavator West Brownsville Borough. On 9/5/2024, I talked to Todd from West Brownsville Borough. He explained what happened and I told him to submit an AVR and he said he would. He said Columbia Gas marked the line the next day, but line was shallow, and marking was off; they used an Ohio company. West Brownsville Borough did not submit an AVR.</p> <p>~20241571150- Routine was placed on 6/5/2024, to replace pipe crossing. No Response from: West Brownsville Borough, and Columbia Gas responded Conflict DCTF By FO but did not close ticket with a final response.</p> <p>~20241651180- Excavation Emergency ticket placed on 3/13/2024 at 10:04 am, by Columbia Gas to repair the gas line. No Response from- West Brownsville Borough.</p> <p>*West Brownsville Borough is in violation of sections: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. 2(5)(v) – Failed to respond to a routine One Call ticket. 20241571150 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20241651180 Recommendation: Education Required and Penalties Applied *Columbia Gas is in violation of section:</p>	<p>Section 5(4) 1st Offense \$500.00</p> <p>Section 5(8) 1st Offense \$0.00</p> <p>Section 5(16) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>2(5)(v) – Failed to respond to a routine One Call ticket. 20241571150 Recommendation: Education Required and Penalties Applied</p>	
48029	<p>Facility Owner: UGI Utilities Inc Contractor/Excavator: CANTON BOROUGH Project Owner: CANTON BOROUGH</p>	<p><u>On 6/19/2024 9:32:00 AM at 267 WEST UNION ST, CANTON BORO, BRADFORD</u> Tuesday, March 11, 2025, at the DPC meeting, disputing was Canton Borough [they did not dispute sections 5(16), 5(17)]. It was voted to Remove the penalties and violations for sections 5(3), 5(4). Accept section 5(8) as recommended by the DPI. ***** Dispute- Canton Borough would like to dispute the following violations: 5(3) Excavator failed to preserve mark-outs or request a remark - There were no markings of gas line where we were digging. After hitting the gas line, the gas company was called and they came out and marked it then. 5(4) Excavator failed to exercise due care and employ prudent excavation techniques - We followed the main line and never touched it. The 3/4 gas line that was hit was never marked. 5(8) Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of gas or liquid which may endanger life, health or property - We are not disputing the fact we did not call 911 we understand we were wrong there but we did contact UGI the facility owner. Canton Borough attached a few pictures: 1st picture is the main gas line that was never hit 2nd picture is of flags on the opposite side for the road yellow and blue 3rd picture is the side where the line was hit and there are no flags - it is hard to see but there are no blue flags in that area on the other side of the orange fence where the line was hit. ***** The incident occurred on Wednesday, June 19, 2024, at 267 West Union Street, in Canton Borough, Bradford County. A gas line was damaged. UGI Utilities reported that Canton Borough failed to use prudent techniques within the tolerance zone, failed to preserve the markings, and failed to call 911. UGI stated that the gas line was marked but most of the marks were gone by the contractor, Canton Borough, not maintaining them. UGI attempted to hook up to remark the line, but the Canton Borough employee had stated that they had cut the tracing wire in multiple places, and it would be impossible to trace out the gas facilities. UGI provided photos of the damaged line and tracing wire. On Friday, September 13, 2024, an email and letter were sent to Canton Borough requesting an Alleged Violation Report (AVR). There was no response to the request and no AVR was submitted as of 10/1/2024.</p>	<p>CANTON BOROUGH: \$1,750.00 Section 5(8) 1st Offense \$1,000.00 Section 5(16) 1st Offense \$500.00 Section 5(17) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>On 10/23/2024, David of Canton Borough called and he explained what happened and said the gas line was not marked. Canton Borough does not have pictures. I told him to submit the AVR with the information they do have, and he said yes he will. No AVR was submitted.</p> <p>*Canton Borough is in violation of sections: 5(3) – Excavator failed to preserve mark-outs or request a remark. 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. 5(17) - Excavator failed to respond to PUC requests for information. Recommendation: Education Required and Penalties Applied</p>	
48040	<p>Facility Owner: MUNI AUTH OF WESTMORELAND COUNTY Contractor/Excavator: Excavator- Mr. Greg Ward Project Owner: Homeowner</p>	<p>On 6/19/2024 2:00:00 PM at 305 Wallace Ave, <u>TRAFFORD BORO, WESTMORELAND</u> Tuesday, March 11, 2025, at the DPC meeting, disputing was Greg Ward, and it was voted to Reduce all penalties by 50% and keep education. ***** Dispute- The Excavator, Mr. Greg Ward wants dispute, see attached letter. ***** The incident occurred on Wednesday, June 19, 2024, at 305 Wallace Avenue, in Trafford Borough, Westmoreland County.</p> <p>A water line was damaged.</p> <p>Municipal Authority of Westmoreland County (MAWC) reported that contractor, Greg Ward, was excavating without a one call ticket. MAWC explained that Mr. Ward contacted them requesting that the water be shut off at 305 Wallace Avenue. When the MAWC crew arrived on site they observed a new modular home had been set up and Mr. Ward was excavating for new utility connections without an exaction ticket. MAWC made the necessary repairs and submitted an invoice to Mr. Ward for the damaged MAWC facilities. MAWC provided pictures of the damaged line. PA One Call Compliance commented, Greg Ward has not placed notifications with PA One Call in the past. There are no tickets associated with this incident. On Friday, September 13, 2024, letters were mailed requesting Alleged Violation Reports (AVR) from the Excavator, Greg Ward and the Homeowner. There were no responses to the request and no AVR's submitted. The letter requesting an AVR from the Homeowner was returned, return mail date is 10/8/2024, attempted not known unable to forward.</p> <p>*Excavator, Mr. Greg Ward is in violation of sections:</p>	<p>Excavator- Mr. Greg Ward: \$875.00 Section 5(2.1) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$250.00</p> <p>Section 5(17) 1st Offense \$125.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe.</p> <p>5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line.</p> <p>5(17) Excavator failed to comply with all PUC requests for information.</p> <p>Recommendation: Education Required and Penalties Applied</p>	
48509	<p>Facility Owner: PECO AN EXELON COMPANY</p> <p>Contractor/Excavator: UTILITY LINE SERVICES</p> <p>Project Owner: AQUA PENNSYLVANIA INC</p> <p>Other: LOWER MERION TOWNSHIP</p> <p>Other: PENNDOT</p> <p>Other: Verizon PA LLC</p>	<p><u>On 7/17/2024 9:50:00 AM at ROCK HILL RD, LOWER MERION TWP, MONTGOMERY</u> Tuesday, March 11, 2025, at the DPC meeting, disputing was Lower Merion Township and it was voted to Accept the DPI's Recommendations.</p> <p>*****</p> <p>Lower Merion Township wants to dispute the penalty and violation, they gave no reason for the dispute.</p> <p>*****</p> <p>The incident occurred on Wednesday, July 17, 2024, on Rock Hill Road, in Lower Merion Township, Montgomery County.</p> <p>PECO an Exelon Company, gas line was damaged.</p> <p>Aqua PA contractor, Utility Line Services stated, was working to install a water mainline when a mismarked gas mainline was hit and damaged, it was approximately 6-feet off the mark. ULS provided photos.</p> <p>PECO stated, it appeared that the roadway's path was altered to allow for the installation of a roadside retention basin/drainage system. PECO's prints were based off measurements from the curb line, which is what USIC used to mark out the mainline. When the roadwork moved the curb-line it caused our prints to be inaccurate. Also, in an email PECO stated that their records were updated after the damage. Not sure on when the installation of the roadside basin/drainage system was, within the last 5 years.</p> <p>Google Street View photos shows that the road has not widen and the basin/drainage system does not appear to have been altered.</p> <p>On Friday, September 13, 2024, an email was sent requesting an Alleged Violation Report (AVR) from PECO an Exelon Company. PECO submitted their AVR on 9/17/2024.</p> <p>~20241900439- Routine ticket placed on 7/8/2024, with response due date as 7/10/2024. No Response from- Verizon PA LLC. Late Response from- PECO on 7/12/24 as Field Marked.</p> <p>~20241990967- Update Routine ticket placed on 7/17/2024 at 9:19am. No Response from- Verizon PA LLC, and PennDOT responded as Scheduled Mark but did not close ticket with Field Marked or Clear No Facilities.</p>	<p>PECO AN EXELON COMPANY: \$1,750.00 Section 2(5)(i) 2nd Offense \$1,000.00</p> <p>Section 2(5)(v) 3rd offense \$750.00</p> <p>LOWER MERION TOWNSHIP: \$1,000.00 Section 2(5)(vii) 1st Offense \$1,000.00</p> <p>PENNDOT: \$500.00 Section 2(5)(v) 1st Offense \$500.00</p> <p>Verizon PA LLC: \$6,000.00 Section 2(5)(v) Subsequent \$2,000.00</p> <p>Section 2(5)(v) Subsequent \$2,000.00</p> <p>Section 2(5)(viii) Subsequent \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>~20241991373- Damage Emergency ticket placed on 7/17/2024, at 10:04am. Late Response from- Lower Merion Township on 7/29/2024 as Field Marked.</p> <p>~20241240041- Complex Project Meeting ticket placed on 5/3/2024. No Response from- Verizon PA LLC responded on 5/16/2024 as Conflict DCTF.</p> <p>*PECO an Exelon Company is in violation of sections: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. 20241900439 Recommendation: Penalties Applied</p> <p>*Verizon PA LLC is in violation of sections: 2(5)(v) – Failed to respond to a routine One Call ticket. 20241900439 2(5)(v) – Failed to respond to a routine One Call ticket. 20241990967 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project. 20241240041 Recommendation: Penalties Applied</p> <p>*PennDOT is in violation of section: 2(5)(v) – Failed to respond to a routine One Call ticket. 20241990967 Recommendation: Education Required and Penalty Applied</p> <p>*Lower Merion Township is in violation of section: 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20241991373 Recommendation: Education Required and Penalty Applied</p>	
49997	<p>Facility Owner: PECO Contractor/Excavator: JD ECKMAN INC Project Owner: PennDOT Designer: Susquehanna Civil Other: AQUA PENNSYLVANIA Other: Bucks County Water and Sewer Authority Other: Comcast Other: Johnson Mirmiran and Thompson (JMT) Other: Verizon</p>	<p>On 9/20/2024 8:00:00 AM at <u>ROCKHILL DRIVE, BENSALEM TWP, BUCKS</u> On 3/11/25 the DPC voted to accept DPI’s recommendation. ***** PECO is disputing. ***** Incident occurred on September 20th, 2024 at 8am, Rockhill Drive, Bensalem Township, Bucks County.</p> <p>An electric line was damaged.</p> <p>PECO's Alleged Violation Report (AVR) states, "ON 09/20/2024 CONTRACTOR, JD ECKMAN, WORKING FOR PENNDOT, PERFORMING ROAD WIDENING AND DRAINAGE WORK, STRUCK AN UNMARKED PRIMARY CABLE. FOR UNKNOWN REASONS THE LOCATOR FAILED TO MARK THE CHANGE IN DIRECTION OF THE CABLE. CONTRACTOR VIOLATED PA ACT 50, 5(20), WHICH REQUIRES AN EXCAVATOR TO RENOTIFY THE ONE CALL SYSTEM OF AN UNMARKED OR INCORRECTLY MARKED FACILITY, IF AN ORIGINAL, PROPER, NONEMERGENCY LOCATE REQUEST HAS BEEN MADE TO THE ONE CALL SYSTEM AND, UPON</p>	<p>PECO: \$2,000.00 Section 2(5)(i) Subsequent \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>ARRIVAL AT THE PROPOSED WORK SITE, IT IS APPARENT TO THE EXCAVATOR THAT THERE IS AN UNMARKED OR INCORRECTLY MARKED FACILITY. AN EXCAVATOR MAY NOT BEGIN EXCAVATING IN THE AFFECTED AREA OF THE WORK SITE UNTIL AFTER RECEIVING SUFFICIENT INFORMATION FROM THE FACILITY OWNER TO SAFELY EXCAVATE."</p> <p>JD Eckman's AVR states, "Utility was located 8 feet off the markings. PECO made a claim that the mark was dug up but a previous photo showing the area prior to excavating shows no mark existed."</p> <p>PennDOT's AVR states, "Utility was located 8 feet off the markings. PECO made a claim that the mark was dug up but a previous photo showing the area prior to excavating shows no mark existed."</p> <p>JD Eckman's pictures show that the line was mismarked.</p> <p>Case is related to 39502.</p> <p>Violations:</p> <p>PECO Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.</p>	
50119	<p>Facility Owner: PECO an Exelon Company Contractor/Excavator: BLANKS QUALITY BUILDERS Project Owner: HOMEOWNER</p>	<p><u>On 9/24/2024 10:00:00 AM at 266 Brookhaven Rd, BROOKHAVEN BORO, DELAWARE</u> Tuesday, March 11, 2025, at the DPC meeting, disputing was Blanks Quality Builders [they're not disputing 5(2.1)] and they were NO SHOW. It was voted to Accept the DPI's Recommendations. *****</p> <p>Blanks Quality Builders LLC is disputing the violations of 5(16) and 5(17). [They did not dispute 5(2.1).] The incident took place on September 24, so the AVR was due on October 24. The DPI asked for an AVR on October 24, and no AVR was filed until November 17, so still more than 30 days beyond the request and more than 60 days after the incident. *****</p> <p>The incident occurred on Tuesday, September 24, 2024, at 266 Brookhaven Road, in Brookhaven Borough, Delaware County.</p> <p>A gas line was damaged.</p> <p>PECO an Exelon Company stated that contractor Blanks Quality Builders was working for the Homeowner to install a deck on the front of the house, without an excavation ticket. Blanks Quality Builders was using a Dingo Excavator with an auger attachment at the time of the damage, a 1/2" plastic gas service line was damaged. PECO provide photos of the damaged line, The PA One Call Compliance commented that the contractor has placed notifications with PA One Call. There are no tickets associated with this incident.</p>	<p>BLANKS QUALITY BUILDERS: \$1,750.00 Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$500.00</p> <p>Section 5(17) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Mr. Blank of Quality Builders stated that work was to be hand dug only but was using an auger when the gas line was hit.</p> <p>On Thursday, October 24, 2024, letters were mailed requesting Alleged Violation Report's (AVR) from Blanks Quality Builders LLC and the Homeowner. There were no responses to the request and no AVR's were submitted. On 11/6/2024, returned mail- letter requesting an AVR from the homeowner, No Such Number and Unable to Forward. On 11/21/2024, Mr. Blank of Quality Builders called. He said he's Amish and never used a computer and said he's going to ask a friend to help him. I ask him to submit an AVR asap. Mr. Blank submitted an AVR on 11/27/2024.</p> <p>*Blanks Quality Builders LLC is in violation of sections: 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. 5(17) Excavator failed to comply with requests for information from PUC Staff Recommendation: Education Required and Penalties Applied</p>	
50142	<p>Facility Owner: Columbia Gas of PA - North</p> <p>Contractor/Excavator: A FOLINO CONSTRUCTION INC</p> <p>Project Owner: PENNDOT</p>	<p><u>On 9/26/2024 9:45:00 AM at 418 LAWRENCE AVE (SR 351), ELLWOOD CITY BORO, LAWRENCE</u> Tuesday, March 11, 2025, at the DPC meeting, disputing was A. Folino and they were NO SHOW. It was voted to Accept the DPI's Recommendations. *****</p> <p>Dispute- A. Folino Construction wants to dispute all penalties and violations. They gave no reason why. *****</p> <p>The incident occurred on Thursday, September 26, 2024, at 418 Lawrence Avenue/SR 351, in Ellwood City Borough, Lawrence County.</p> <p>Columbia Gas line was damaged.</p> <p>Columbia Gas stated that A. Folino Construction struck and damaged an accurately marked 1-inch plastic, company-side gas service line feeding 418 Lawrence Avenue, while doing road reconstruction for PennDOT. The marks were faded but still visible and accurate. Columbia Gas explained, as for the ticket, Folino Construction was digging on, Routine ticket-20241662499 was placed on 6/14/2024 and was cancelled on 8/23/2024. Folino Construction did not space out their locate tickets, which is why the ticket never had a final response until it was cancelled. However, the locator notated the ticket throughout the project with updates after communicating with Folino Construction. The local Columbia Gas Damage Prevention Specialist (DPS) was told by Folino Construction that they were leaving the work area to work on a different job. The DPS advised them at that time they would need to place new tickets when they returned. The locator was working directly with Folino Construction on these complex tickets and notated the</p>	<p>A FOLINO CONSTRUCTION INC: \$2,250.00 Section 5(3) 2nd Offense \$1,000.00</p> <p>Section 5(4) 2nd Offense \$1,000.00</p> <p>Section 5(14) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>tickets accordingly. Folino Construction was not adhering to the meeting agreement established at the time of the complex meeting.</p> <p>Folino Construction stated they were excavating on Lawrence Avenue installing a new inlet, when a mismarked gas service line was hit. Folino Construction called 911, 811 and Columbia Gas when the damage occurred. Columbia Gas responded and claimed the gas line as theirs and made the repairs.</p> <p>PennDOT stated, while Folino Construction was excavating to remove the existing cast in place inlet at station 76+12 LT, they struck the gas line. All operations were halted immediately, and 911 emergency services were contacted by Folino Construction.</p> <p>Photos were provided showing the damaged gas line and locate marks.</p> <p>*A. Folino Construction is in violation of sections: 5(3) – Excavator failed to preserve mark-outs or request a remark. 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. 5(14) – Excavator failed to renotify the One Call System after vacating a work site for more than two business days. Recommendation: Penalties Applied. Education required.</p>	
50138	<p>Facility Owner: UGI Utilities Inc Contractor/Excavator: Mountain Top Contracting, LLC Project Owner: Homeowner</p>	<p><u>On 9/26/2024 4:44:00 PM at 850 WYNNEWOOD RD, CAMP HILL BORO. CUMBERLAND</u> Tuesday, March 11, 2025, at the DPC meeting, disputing was Mountain Top Contracting and it was voted to Accept the DPI's Recommendations. ***** Dispute- Mountain Top Contracting LLC is disputing all penalties and violations, and the reasons: 5(3) – Excavator failed to preserve mark-outs or request a remark: We DID preserve the original markouts. There were no markings in the area. The closest mark was at the street and that was still visible. As our report noted, the line was also shallow, did not have any stone dust, caution tape or locator wire per code to notify us. 5(8) – Excavator failed to immediately notify 911: We DID notify the facility owner (UGI) immediately to ensure a solution could be started ASAP. UGI called 911 right away. There was no need for 2 people to call 911. 5(16): The foreman on duty submitted a report onsite to UGI who was submitting the AVR within 10 days. It was our understanding that UGI was submitting for both of us. ***** The incident occurred on Thursday, September 26, 2024, at 850 Wynnewood Drive, in Camp Hill Borough, Cumberland County.</p>	<p>Mountain Top Contracting, LLC: \$1,750.00 Section 5(3) 1st Offense \$500.00 Section 5(8) 1st Offense \$1,000.00 Section 5(16) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>A gas line was damaged.</p> <p>UGI Utilities stated that Mountain Top Contracting LLC hit and damaged a gas service line while excavating a trench for utilities running to a pool. Excavation routine ticket, 20241972529 was placed on 7/15/2024 and work began in July, but stopped and did not resume until September. Mountain Top failed to place an update routine ticket, so utility markings were not visible within the scope of their excavation/worksites, but only UGI markings were visible on curb and street. UGI provided photos of the damage line and the locate marks on the curb and street. UGI received a call from the Mountain Top Contracting crew about the damaged line, and UGI called 911 after arriving to the worksite.</p> <p>The Homeowner stated that they were not involved in the incident. Our swimming pool contractor, Mountain Top Contracting, notified UGI immediately, and it was fixed the same day. Both the excavator and the UGI submitted reports with all the details.</p> <p>Mountain Top Contracting stated that the crew was finishing the trenching and conduit tie-in to the house up through the side yard. There was one person watching outside of the mini-excavator as they were getting closer to the house. The crew had just turned the corner and was finishing up outside of the flower bed and more than 3-feet from the gas and electric meters. As the crew was making the last pass in the trench, they heard the sound of air blowing and the smell of gas. The crew stopped working immediately and uncovered some loose dirt to find a gas line laying in the ground, the tooth of the mini-excavator caught the top of the line. There were no locate markings, no caution tape, no locator wire, no dust, and the line was buried about 12 – 14-inches in depth. The crew called UGI's emergency services and the Homeowner, and the worksite was closed for the rest of the day. When UGI arrived, they called 911 and repaired the gas line.</p> <p>Also, Mountain Top Contracting explained, the Routine ticket, 20241972529 placed on 7/15/2024, they did a pre-site visit to make sure nothing was going to be in the way. We were waiting on permission from the township to start with some questions about storm-water, and started shortly after that.</p> <p>The process of Concrete pools have multiple phases which have certain cure times in between phases where no one is working there while the pool shell cures. Once the shell cured, our crew jumped back into the job. We were unaware that if the job stops for more than 3 days, you need to submit another PA1 call ticket. All Mountain Top job's schedules vary, depending on what's getting installed, but between items getting done, weather delays, and waiting for specialty subs like granite, steel, and plaster, there are always going to be periods throughout the job that there are gaps when no one is working there. If Mountain Top Contracting had to call a PA1 call ticket for each time throughout the job, we would have probably 10-20 calls throughout a project</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>and then must keep pausing everyone for 3 days until they are done each time. Our job timelines and schedules are within industry standards and how other companies plan and schedule their jobs as well. They're not out of the ordinary or something missed. We always try to take all the steps to be safe so something like this does not happen: submit the PA1 call ticket, do a site inspection prior to start, and note anything in the way so we know what to avoid or add remarks to caution throughout the project. The gas line that was hit was not marked, not very deep, no stone on top, no caution tape, and no trace wire.</p> <p>Mountain Top Contracting provided photos of worksite and gas meter on the side of the house.</p> <p>On Monday, October 28, 2024, letters were mailed to Mountain Top Contracting and to the Homeowner, and an email sent to the excavator requesting Alleged Violation Report's (AVR).</p> <p>Mountain Top Contracting submitted their AVR on 10/30/2024. The Homeowner submitted their AVR on 11/6/2024.</p> <p>*Mountain Top Contracting LLC is in violation of sections: 5(3) – Excavator failed to preserve mark-outs or request a remark. 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. Recommendation: Education Required and Penalties Applied, with 50% penalty reduction for 5(16) from \$500 to \$250.</p>	
50208	<p>Facility Owner: PEOPLES NATURAL GAS</p> <p>Contractor/Excavator: PLAVCHAK CONSTRUCTION CO INC</p> <p>Project Owner: WEST MIFFLIN AREA HIGHSCHOOL</p>	<p><u>On 9/30/2024 11:00:00 AM at 91 COMMONWEALTH AVE, WEST MIFFLIN BORO, ALLEGHENY</u> On 3/11/2025 the Damage Prevention Committee (DPC) voted to accept the recommendations presented by the Damage Prevention Investigator (DPI), except to keep the violation but remove the penalty for section 5(8) to Plavchak.</p> <p>*****</p> <p>Plavchak sent an email stating that "I would like to reject the attached DPI Report and request a hearing". DPI responded with an email and asked for any other documents to be considered sent by 1/31/2025. On 1/31/2025 an email was received that stated that "The only information I would like to be considered is we were told by the contractor we were working for that there was a One Call requested and there was no damage to any Peoples Gas line. The line was privately owned by West Mifflin School District".</p> <p>*****</p> <p>The incident occurred on 9/30/2024 at 91 Commonwealth in West Mifflin Borough in Allegheny County.</p>	<p>PLAVCHAK CONSTRUCTION CO INC: \$2,250.00 Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(17) 2nd Offense \$500.00</p> <p>Section 5(16) 2nd Offense \$750.00</p> <p>Section 5(8) 2nd Offense \$0.00</p> <p>WEST MIFFLIN AREA HIGHSCHOOL: \$500.00 Section 6.1(7) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>A gas line was struck. No One Call ticket was requested for this excavation. 911 was not notified.</p> <p>PEOPLES GAS COMPANY LLC the facility owner state in their Alleged Violation Report (AVR) that “PLAVCHAK CONSTRUCTION struck and damaged a gas service line on the West Mifflin School District property while working without a One Call”. Pictures are provided. On 11/15/2024 DPI asked for more information. On 11/20/2024. Peoples sent an attachment of the bill that was paid by Plavchak for this incident.</p> <p>WEST MIFFLIN AREA HIGHSCHOOL the project owner was emailed and mailed an AVR request letter on 11/01/2024. No AVR has been received to date.</p> <p>PLAVCHAK CONSTRUCTION CO INC the excavator was emailed and mailed an AVR request letter on 11/01/2024. On 11/15/2024, an email was found when searching for prior offenses. The AVR request letter was emailed. No AVR has been received to date. On 11/15/2024 Plavchak sent an email stating that they did not hit a Peoples Gas line, but a private line and to advise. DPI advised that they fill out an AVR and asked if there were 2 line strikes and who notified 911. ON 11/15/2024 Plavchak sent an email stating that “I will get you this information. Only one line was hit and it was a private line on their property. I verified with Peoples Gas this week that it was not their line”. On 11/16/2024 DPI send an email back stating that an AVR must be filed and explained in detail why. OneCall liaisons contact information was attached.</p> <p>Compliance update information: Contractor has placed One Call notifications with PA One Call in the past. Listed contact information is the most recent contact info on file for Plavchak Construction *****</p> <p>PLAVCHAK CONSTRUCTION CO INC is in violation of:</p> <p>Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. This is a second offense violation. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. This is a second offense violation. Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. This is a second time offense.</p> <p>Recommendation: The penalties are applied. Education is required. The required education was completed on 6/11/2024. The incident occurred on 9/30/2024.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>WEST MIFFLIN AREA HIGHSCHOOL is in violation of: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 10 Business Days of a line strike. Recommendation: The penalties are applied. Education is required.</p>	
50248	<p>Facility Owner: Westover Company Contractor/Excavator: Henkels and McCoy Project Owner: PECO Designer: HBK Engineering Other: Darby Creek Joint Authority Other: Upper Darby Township Other: Verizon</p>	<p><u>On 10/1/2024 9:00:00 AM at W PROVIDENCE RD, YEADON BORO, DELAWARE</u> On 3/11/25 the DPC voted to keep the violation but remove the penalty. ***** The Westover Companies is disputing. Westover completed education on 1/10/25. ***** Incident occurred on October 1st, 2024 at 9am at 784 West Providence Road, Delaware County. A gas line was damaged. 911 was notified. Henkels and McCoy's Alleged Violation Report (AVR) states, "On Tuesday Oct 1, 2024, at approximately 0900 hours a Henkels & McCoy Directional drill crew was using a Mini x to dig a trench to get conduit to a transformer when they hit an unmarked private gas service, stopped all work, called 911. Gas line was 25 inched deep. All proper notifications were made. Gas line repair complete by 15:00. No injuries One call number 20242641456" PECO's AVR states, "ON TUESDAY OCT 1, 2024, AT APPROXIMATELY 0900 HOURS A HENKELS & MCCOY DIRECTIONAL DRILL CREW WAS USING A MINI AX TO DIG A TRENCH TO GET CONDUIT TO A TRANSFORMER WHEN THEY HIT An UNMARKED PRIVATE GAS SERVICE, STOPPED ALL WORK, CALLED 911. GAS LINE WAS 25 INCHED DEEP.ALL PROPER NOTIFICATIONS WERE MADE. GAS LINE REPAIR COMPLETE BY15:00. NO INJURIES" No AVR was found for the Westover Company who owns the Hillcrest Apartments. Hillcrest Apartments responded filed marked on ticket 20242641455. Picture shows that the line was not marked. Email form PECO states: H&M has been working with this property owner to identify their underground facilities The owner was not able to supply any documentation of their private underground gas or water line locations related to our work area H&M hired a GPR outfit, property owner supported this H&M states they have a valid PA1 ticket (The first initial complex ticket was 4/23, and they had tickets that were updated before any 10-day expiration, 2 of those attached) They confirmed with property owner on September 17th that they would be starting work</p>	<p>Westover Company: \$0.00 Section 2(5)(i) 1st Offense \$0.00</p> <p>Darby Creek Joint Authority: \$500.00 Section 2(4) 1st Offense \$250.00</p> <p>Section 2(4) 1st Offense \$250.00</p> <p>Upper Darby Township: \$500.00 Section 2(4) 1st Offense \$250.00</p> <p>Section 2(4) 1st Offense \$250.00</p> <p>Verizon: \$4,500.00 Section 2(4) Subsequent \$1,500.00</p> <p>Section 2(4) Subsequent \$1,500.00</p> <p>Section 2(4) Subsequent \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>The morning of October 1st a private gas line was struck, no marks present at this location from the GPR or others 911 and OCC were called (fire truck did show up)</p> <p>Violations:</p> <p>Westover Company - Hillcrest Apartments Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.</p> <p>Verizon Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20202870441 Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20202870442 Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20202870443</p> <p>Upper Darby Township Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20202870441. Education is required. Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20241001045. Education is required.</p> <p>Darby Creek Joint Authority Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20202870441. Education is required. Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20241001045. Education is required.</p>	
50455	<p>Facility Owner: Columbia Gas of PA Contractor/Excavator: A Team Trenching Project Owner: OMNI FIBER Designer: FERGUSON CONSTRUCTION LLC Other: ADB Other: FUTURE COMMUNICATIONS Other: NORTH FAYETTE COUNTY MUNICIPAL AUTHORITY (NFCMA) Other: PA AMERICAN WATER Other: SOUTH UNION TOWNSHIP Other: Uniontown City Other: VERIZON PA LLC</p>	<p><u>On 10/1/2024 5:35:00 PM at 1 WILLIAMS ST EXT, SOUTH UNION TWP, FAYETTE</u> On 3/11/2025 the Damage Prevention Committee (DPC) voted to Remove the penalty and violation to Uniontown City. ***** South Union Township disagreed. They stated that they took the required education. DPI offered to reduce their penalty to \$0, but keep the violation, and to send documentation of the required education. South Union Township agreed to this, on 2/06/2025. They send an email with education, but no the required education. DPI sent an email responding that this was not the required education with instructions of how to take the required education. On 2/28/2025 DPI sent an email asking if the required education has been taken to date? * PA American disagreed and stated that their representative did attend in person. PA American is on the CPM sheet. The violation has been withdrawn. * City of Union Town disagreed and requested to be notified for the Damage Prevention Committee meeting. On 2/06/2025, a telephone message was received. DPI returned a call to Uniontown City. The person did not leave a name or an extension. The answering service did not have an option to leave a message or talk to</p>	<p>Columbia Gas of PA: \$0.00</p> <p>A Team Trenching: \$750.00 Section 5(17) 1st Offense \$250.00</p> <p>Section 5(16) 1st Offense \$500.00</p> <p>OMNI FIBER: \$3,000.00 Section 2(5)(vii) 1st Offense \$1,000.00</p> <p>Section 2(5)(vii) 1st Offense \$1,000.00</p> <p>Section 6.1(3) 1st Offense \$500.00</p> <p>Section 2(5)(viii) 1st Offense \$500.00</p> <p>NORTH FAYETTE</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>someone. DPI sent an email correspondence to the contact we have on file. DPI verified that City of Uniontown is marked a disputing party and requested that any considerations for the case be in writing. *</p> <p>North Fayette County Municipal Authority (NFCMA) disagreed and stated that they did attend the meeting but could not come up with an agreement for marking, but on 2/04/2025 and email was received stating that NFCMA found that they did not attend the meeting due to an emergency. NFCMA is not listed on the CPM sign in sheet. DPI sent an email back asking if they are still wanting to discuss this with the DPC. ON 2/05/2025 email was received stating that NFCMA is not disagreeing. *</p> <p>Columbia Gas disagreed and stated that "The Columbia Gas locator used the existing records, mapping, and lengths of nearby services to complete this locate. The equipment's tone was not questionable and aligned with the mapping and measurements. Therefore, the locate was completed using standard locating techniques and available records. Unfortunately, there was an unknown/undocumented bend in the mainline, but the tone from the locator did not indicate any deviation in the line. Marker balls have since been placed in this location and have been mapped to assist with future locates". Columbia Gas provided the notes from attending the meeting and also stated that they have added into their training to close out the tickets with a final response. All 3 violations to Columbia Gas are withdrawn. *****</p> <p>The incident occurred on 10/01/2024 at WILLIAMS ST EXT in SOUTH UNION TWP in Fayette County.</p> <p>A Gas main was hit and damaged.</p> <p>Columbia Gas the facility owner stated in their Alleged Violation Report (AVR) that "A Team Trenching was installing fiber optics on Williams St Ext., when they struck and damaged an inaccurately marked 2" plastic gas main. They notified 911, 811, and Columbia Gas when the damage occurred. Columbia Gas responded immediately to make the area safe and complete repairs. An onsite investigation was conducted to determine what led to the inaccurate locate. A Team Trenching was using the existing yellow paint marks to dig parallel to the marked gas main safely. Unfortunately, there was a bend in the gas main that was not documented. The locator did not lose tone in this area. During the repairs of the gas main, two marker balls were placed on the line and mapped. In addition to the marker balls, Columbia added a line marker with wire for the gas main on Williams St Ext. The gas main is accurately locatable at this time". Pictures were provided.</p> <p>A Team Trenching the excavator, was mailed and emailed an AVR request letter on 11/04/2024. No AVR has been received to date.</p>	<p>COUNTY MUNICIPAL AUTHORITY (NFCMA): \$500.00 Section 2(5)(viii) 1st Offense \$500.00</p> <p>PA AMERICAN WATER: \$0.00</p> <p>SOUTH UNION TOWNSHIP: \$0.00 Section 2(5)(viii) 1st Offense \$0.00</p> <p>Uniontown City: \$0.00</p> <p>VERIZON PA LLC: \$2,000.00 Section 2(5)(viii) Subsequent \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>ADB the contractor who hired the excavator stated in their AVR that “While directional drilling my subcontractor crew hit gas utility line that was not marked (drilling was being done 5ft off the marked utility) Project report was provided which listed the project Final design completed on 10/22/2024. The construction start date was 9/25/2024. Lots of pictures were provided. The excavator who was said to have hit the line, was not named. The information provided by ADB only gave “my subcontractor” as information about who hit the line. On 12/01/2024 DPI sent an email asking for the Complex Project sign in sheet. ON 12/04/2024 an email was received stating that the CPMSign-in sheet will be provided soon. On 12/09/2024 notes from the Complex project meeting were attached in an email. DPI requested the Complex Project attendance sheet.</p> <p>Omni Fiber the project owner was mailed and emailed an AVR request letter on 11/04/2024. Omni Fiber stated in their AVR that ”While directional drilling a subcontractor crew hit a gas utility line that was not marked correctly. They were drilling 5ft off the marked utility. The excavator was not named. Ono 12/01/2024 DPI sent an email asking for the size and coast of the project, the final design ticket and the final designer information. *****</p> <p>* Complex Project meeting ticket 20232781535 was requested by Future Communications with a response due by 10/10/2023 and the meeting to be held on 10/11/2023 at 10:00a.m. South Union TS/South Union TWP never responded. Columbia Gas had no response until 10/11/2023. North Fayette County Municipal Authority (NFCMA) responded that they will attend the meeting. This was never updated to a final response.</p> <p>*Complex Project meeting ticket 20242642492 was requested by ADB on 9/20/2024 with a response due by 9/24/2024. The meeting to be held at 10:30. Columbia Gas did not respond until 9/25/2024. Verizon responded that they will attend the meeting. This was never updated to a final response. Uniontown City had no response until 10/07/2024, when they responded “filed marked” OMNI Fiber never responded. PA American water responded that they will attend the meeting. This was never updated to a final response.</p> <p>*Ticket 20242554431 was requested by A Team Trenching on 9/11/2024 with a response due by 9/13/2024. All facility owners responded timely.</p> <p>*Ticket 20242554432 was requested by A Team Trenching on 9/11/2024 with a response due by 9/13/2024. All facility owners responded timely.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>*Emergency Ticket 20242754011 was requested by Columbia Gas on 10/01/2024 at 18:17. OMNI FIBER LLC never responded.</p> <p>*Emergency Ticket 20242754050 was requested by A Team Trenching on 10/01/2024 at 18:40. [DAMAGED LINE IS A 2IN PLASTIC LINE. A DIRECTIONAL DRILL WAS IN USE WHEN THE LINE WAS DAMAGED. 911 HAS BEEN NOTIFIED. FIRE DEPARTMENT AND COLUMBIA GAS ARE ON SITE. FACILITY TYPE: NATURAL GAS- COLUMBIA GAS EXCAVATION EQUIPMENT: DIRECTIONAL DRILLING HAZARDOUS RELEASE: YES CALLER HAS NOTIFIED 911.] OMNI FIBER LLC never responded.</p> <p>*Final Design ticket 20242964474 was requested by Furguson Construction LLC on 10/22/2024 with a response due by 11/05/2024. *****</p> <p>Columbia Gas of PA is in violation of Sections: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). CPM ticket 20242642492 Columbia Gas did not respond until 9/25/2024. CPM ticket 20232781535 Columbia Gas had no response until 10/11/2023. *See ticket details above. Recommendation: Education is required.</p> <p>A Team Trenching is in violation of Sections: Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. Recommendations: Excavator education is required.</p> <p>OMNI Fiber is in violation of Sections: Section 2(5)(vii) – Failed to respond to an emergency notification 20242754050 and 20242754011 as soon as practicable following notification. OMNI FIBER LLC never responded to either ticket. Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20242642492 OMNI Fiber never responded. Section 6.1(3) – Released a project to bid or construction before final design was complete. The only final design tickets were submitted after the date of this incident. *See ticket details above. Recommendation: The penalties are applied. Facility owner, project owner education is required.</p> <p>South Union Township is in violation of Sections: Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). South Union TS/South Union</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>TWP never responded to Complex project meeting ticket 20232781535. They stated that the required education was completed by 8/13/2024. But when Union Township sent the verification, it was for another OneCall training, not the required PUC education. DPI sent an email on 2/20/2025 explaining what education needs to be taken and provided the OneCall liaison contact list. No information has been received to date about taking the required education. Recommendation: The penalty is applied.</p> <p>North Fayette County Municipal Authority (NFCMA) is in violation of Sections: Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). North Fayette County Municipal Authority (NFCMA) responded that they will attend the meeting for CPM ticket 20232781535. This was never updated to a final response. Recommendation: The penalty is applied. Education is required.</p> <p>Verizon PA LLC is in violation of Sections: Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). In CPM ticket 20242642492, Verizon responded that they will attend the meeting. This was never updated to a final response. This is a subsequent offense. Required Facility owner education was completed by 8/13/2024. This incident occurred on 10/01/2024. Recommendation: The penalty is applied.</p> <p>PA American Water is in violation of Sections: Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). For CPM ticket 20242642492, PA American water responded that they will attend the meeting. This was never updated to a final response. Recommendation: The penalty is applied. Facility Owner education is required. The DPC ordered PA American to attend and pass education within 60 days on 7/9/24 for case 42178. PA American failed to comply and all violations are raised to \$2500.</p> <p>Union City is in violation of Sections: Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). CPM ticket 20242642492 - Uniontown City had no response until 10/07/2024, when they responded, “filed marked”. On 2/25/2025 Uniontown sent confirmation of their just completed required education. Recommendation: The penalty is applied. Education is required. The DPC ordered Union City to attend and pass education within 60 days on 11/14/23 for case 34933 and on 12/12/23 for case 33050. Union City has failed to attend education and all violations are raised to \$2500.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
50283	<p>Facility Owner: ADAMS TOWNSHIP MUNICIPAL WATER AUTHORITY (MWAAT) Contractor/Excavator: A FOLINO CONSTRUCTION Project Owner: BLUE BIRD BUS Other: SAXONBURG AREA AUTHORITY</p>	<p><u>On 10/3/2024 2:30:00 PM at 1365 SR 8, MIDDLESEX TWP, BUTLER</u> On 3/11/2025 the Damage Prevention Committee (DPC) voted to Keep the violations and reduce both penalties to \$500 each for MWAAT. ***** MWAAT is disputing. ***** Saxonburg Area Authority Accepts ***** The incident occurred on 10/03/2024 at 1365 SR 8 in Middlesex Township in Butler County.</p> <p>Water box lids were hit and damaged.</p> <p>A Folino Construction the excavator stated in their Alleged Violation Report (AVR) that “ A. Folino Construction was milling to prep to pave a new parking lot when we hit buried under 6 inches of stone, unmarked water box lids. A damage ticket was made through 811. Adams Township responded and claimed them as theirs. Adams Township claimed they didn't know the water box lids were there that’s why they didn't mark them. Adams Township made the repairs. One picture was provided.</p> <p>ADAMS TOWNSHIP MUNICIPAL WATER AUTHORITY (MWAAT) the facility owner was mailed and emailed an AVR request letter on 11/03/2024. MWAAT stated in their AVR that "the contractor damaged the water valve boxes only with the milling machine that was digging at a depth of 6 inches. The valve boxes were marked however they were covered with stones from the milling, therefore they were not visible". No pictures were provided.</p> <p>BLUE BIRD BUS was mailed an AVR request letter on 11/03/2024. No AVR has been received to date. No mail has been returned. This is considered delivered by the USPS. ***** *Ticket 20242703923 was requested by A Folino Construction on 9/26/2024 with a response due date of 9/30/2024. Blue Bird Bus is named as the Project Owner. All facility owners responded timely.</p> <p>*Emergency Ticket 20242772827 was requested by A. Folino on 10/03/2024 at 14:32. Blue Bird Bus is named as the Project Owner. Remarks-- [CALLER STATES THEY WERE MILLING AND AND EXPOSED 2 WTR VALVES THAT WERE NOT MARKED FACILITY TYPE: WATER-OWNER NOT GIVEN EXCAVATION EQUIPMENT: MILLING EQUIPMENT HAZARDOUS RELEASE: NO] Saxonburg Area Authority / Saxonburg Boro never responded. ***** BLUE BIRD BUS Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 10 Business Days of a line strike.</p>	<p>ADAMS TOWNSHIP MUNICIPAL WATER AUTHORITY (MWAAT): \$1,000.00 Section 2(5)(i) 1st Offense \$500.00</p> <p>Section 9 1st Offense \$500.00</p> <p>BLUE BIRD BUS: \$500.00 Section 6.1(7) 1st Offense \$500.00</p> <p>SAXONBURG AREA AUTHORITY: \$500.00 Section 2(5)(vii) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Recommendation: The penalty is applied. Education is required.</p> <p>ADAMS TOWNSHIP MUNICIPAL WATER AUTHORITY (MWAAT) Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Section 9 – Failed to make the best efforts to comply with the Common Ground Alliance Best Practices – CGA 5-16 Federal and State Regulations for required training.</p> <p>Recommendation: The penalty is applied. Education is required. The required education that was due on 3/12/2024, 5/15/2024, 7/09/2024, and 10/07/2024 has not been completed to date. Both penalties are increased to \$2500. ***** Listed below are facility owners in violation of Act 50, Section 2(5)(vii) Failed to respond to an emergency One Call ticket as soon as practicable.</p> <p>SAXONBURG AREA AUTHORITY Section 2(5)(vii) – Failed to respond to emergency notification 20242772827 as soon as practicable following notification. Recommendation: The penalty is applied. Education is required.</p>	
50458	<p>Facility Owner: Columbia Gas of PA - North</p> <p>Contractor/Excavator: Osmoste Utilities Services Inc</p> <p>Project Owner: Verizon</p> <p>Other: AT&T</p> <p>Other: BELLEVUE BOROUGH</p> <p>Other: COMMUNITY COLLEGE OF ALLEGHENY COUNTY</p> <p>Other: Peoples Gas Company</p> <p>Other: Pittsburgh Water and Sewer (PWSA)</p> <p>Other: West View Water Authority</p>	<p><u>On 10/4/2024 2:30:00 PM at 3297 WINSHIRE ST, PITTSBURGH CITY, ALLEGHENY</u> On 3/11/2025 the DPC voted to:</p> <p>Bellevue Borough: Not in attendance. 2(5)(viii)- Accept the DPI’s recommendations.</p> <p>Community College of Allegheny County: 2(5)(viii)- Accept the DPI’s recommendations. 2(5)(viii)- Accept the DPI’s recommendations. 2(5)(viii)- Accept the DPI’s recommendations.</p> <p>AT&T: 2(5)(viii)- Accept the DPI’s recommendations. 2(5)(viii)- Accept the DPI’s recommendations.</p> <p>***** AT&T is disputing claiming that an 811 software update for complex tickets was done and they were not notified of the change. ***** Community College of Allegheny County is disputing their violations for Section 2(5)(viii). No response was provided to KARL. Dispute states that they were never notified of the complex meetings. DPI asked if they have a locator to mark CCAC's facilities. Please see the attached email with CCAC's response. *****</p>	<p>Osmoste Utilities Services Inc: \$4,000.00 Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(4) 1st Offense \$500.00</p> <p>Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$500.00</p> <p>Verizon: \$3,000.00 Section 6.1(7) 3rd Offense \$1,000.00</p> <p>Section 2(5)(viii) Subsequent \$2,000.00</p> <p>AT&T: \$17,500.00 Section 2(5)(viii) Subsequent \$2,500.00</p> <p>Section 2(5)(viii) Subsequent \$2,500.00</p> <p>Section 2(5)(viii) Subsequent \$2,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Peoples provided their mark out agreements with Osmosis. Violation and penalty are removed. *****</p> <p>Bellevue Borough is disputing their violation to not responding to the complex meeting ticket from 2023. Bellevue Borough stated that this is a mapping issue, and they have not met with 811 after having their previous violation on case 32111 reduced by the DPC back in 2023.</p> <p>"My public works superintendent has been trying to get together with pa one call to have the maps corrected. I am not sure why responding was missed however we were having some issues with having tickets faxed to us. Our concern continues to be this particular project is not anywhere in Bellevue's area."</p> <p>*****</p> <p>Incident occurred on October 4th, 2024, at 2:30pm at 3297 Winshire Street, Pittsburgh City, Allegheny County.</p> <p>A gas line was damaged.</p> <p>Columbia Gas Company's Alleged Violation Report (AVR) states, "Osmose Utilities Services Inc., working on behalf of Verizon, was removing and installing a telephone pole without a valid PA One Call when they struck and damaged an accurately marked 1" plastic, company-side gas service. They notified Columbia Gas when the damage occurred. 911 was not notified. Columbia Gas responded immediately to make the area safe and complete repairs. The Columbia Gas crew immediately noticed that Osmose had backed filled the hole where the damage occurred and covered with concrete. Jack Titus was the crew leader for Osmose. They provided a 2023 ticket number when asked for their active ticket. Columbia Gas advised that ticket was no longer valid. Columbia Gas also advised that 911 needs to be called anytime there is a release of gas. The Osmose crew provided their boss's name and number and then left the scene."</p> <p>Osmose and Verizon were mailed and emailed requests for AVRs on 11/5/2024. Line was damaged on 10/4/24. Osmose submitted an AVR on 11/14/24. No AVR was submitted by Verizon for this incident.</p> <p>Osmose's AVR states, "As we were excavating this pole, the crew was aware of a gas markout within our tolerance zone and were excavating carefully. The crew did not see the line but as they were moving dirt, they started smelling gas."</p> <p>Pictures show that the gas line was gouged twice then buried. Osmose claims 911 was called on their AVR, but Columbia gas states 911 was not called on top of the excavating crew leaving after they showed up. Osmose's AVR also states hand tools. Original ticket placed in</p>	<p>Section 2(5)(viii) Subsequent \$2,500.00</p> <p>Section 2(5)(viii) Subsequent \$2,500.00</p> <p>Section 2(5)(viii) Subsequent \$2,500.00</p> <p>Section 2(5)(viii) Subsequent \$2,500.00</p> <p>BELLEVUE BOROUGH: \$500.00 Section 2(5)(viii) 1st Offense \$500.00</p> <p>COMMUNITY COLLEGE OF ALLEGHENY COUNTY: \$1,500.00 Section 2(5)(viii) 1st Offense \$500.00</p> <p>Section 2(5)(viii) 1st Offense \$500.00</p> <p>Section 2(5)(viii) 1st Offense \$500.00</p> <p>Peoples Gas Company: \$0.00</p> <p>Pittsburgh Water and Sewer (PWSA): \$2,000.00 Section 2(5)(viii) 2nd Offense \$1,000.00</p> <p>Section 2(5)(v) 2nd Offense \$1,000.00</p> <p>West View Water Authority: \$500.00 Section 2(5)(viii) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>2023 states Equip Type--[JACKHAMMER]. Osmose pictures show pneumatic lines for pneumatic powered tools.</p> <p>Violations:</p> <p>Osmose Utilities Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Education is required. Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Education is required. Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. Education is required. Section 5(8) – Excavator vacated worksite after causing damage that resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. Education is required. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 10 business days of striking a line. Education is required.</p> <p>Verizon Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 10 Business Days of a line strike. Section 5(3) – In a complex project, Excavator failed to meet with facility owner upon facility owner’s request. 20233322289</p> <p>PWSA Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20241061796 Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20233381045</p> <p>AT&T Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20241061796 Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20232992653 Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20233072743 Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20233190951 Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20233322289 Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20233390752</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20233072537 AT&T is delinquent on invoices 043679-007843 - Created 6/18/2024 - \$1500.00. AT&T is also delinquent on Invoice 039674-006792 Created 12/21/2023 - \$2500.00 All fines raised to \$2500 (originally they were \$2500 for subsequent violations) for failure to pay invoices within 30 days.</p> <p>Peoples Natural Gas Company Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20233381045</p> <p>West View Water Authority Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20233072537. Education is required.</p> <p>Community College of Allegheny County Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20233072743. Education is required. Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20233072537. Education is required. Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20232992653. Education is required.</p> <p>Bellevue Borough Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20232992653. Education is required.</p>	
50496	<p>Facility Owner: Columbia Gas of PA - North</p> <p>Contractor/Excavator: Team Fishel</p> <p>Project Owner: Columbia GAS</p> <p>Other: AT&T</p> <p>Other: AVALON BOROUGH</p> <p>Other: Lumen</p> <p>Other: Verizon</p>	<p><u>On 10/8/2024 9:30:00 AM at 513 SPRUCE ST, AVALON BORO, ALLEGHENY</u> On 3/11/25 the DPC voted to accept the DPI's recommendations</p> <p>*****</p> <p>AT&T is disputing with the response made on 2/6/2024. Proposed Meeting Date and Time--[30-Jan-24][1030] Response Due Date--[29-Jan-24]</p> <p>*****</p> <p>Incident occurred on October 8th, 2024 at 9:30am at 513 Spruce Street, Avalon Boro, Allegheny County.</p> <p>A gas line was damaged.</p> <p>Columbia Gas Company's Alleged Violation Report (AVR) states, "Team Fishel, working on behalf of Columbia Gas for an infrastructure replacement project, was excavating to install a new gas service at 513 Spruce St., Avalon, when they damaged the existing gas service. They notified 911, 811, and Columbia Gas when the</p>	<p>Team Fishel: \$500.00 Section 5(4) 1st Offense \$500.00</p> <p>AT&T: \$2,000.00 Section 2(5)(viii) Subsequent \$2,000.00</p> <p>AVALON BOROUGH: \$250.00 Section 2(4) 1st Offense \$250.00</p> <p>Lumen: \$0.00 Section 2(4) 1st Offense \$0.00</p> <p>Verizon: \$1,500.00 Section 2(4) Subsequent \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>damage occurred, in addition to making the area safe. Columbia Gas responded immediately to complete repairs. A root cause investigation was conducted on 10/09/2024 to review the events leading up to the damage. The existing gas service at 513 Spruce St., Avalon, was identified as unlocatable due to piano wire not having tone. However, the Team Fishel locator did mark the T and curb box, giving a rough estimate of where the gas service should be. The Team Fishel crew then used mechanized equipment in the tolerance zone, resulting in the gas line damage."</p> <p>Team Fishel's AVR states, "Team Fishel was excavating to install a service line when they damaged a service line. They were using mechanized equipment in the tolerance zone. Team Fishel was brought in for a root cause analysis to discuss the damage and admitted they should have been more careful and avoid using mechanized equipment in the tolerance zone."</p> <p>Violations:</p> <p>Team Fishel Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Education is required.</p> <p>Verizon Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20231152426</p> <p>Avalon Borough Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20231152426. Education is required.</p> <p>AT&T Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20240252254</p> <p>Lumen Section 2(4) – Failed to respond to designer’s request for information within 10 business days. 20231152426. IT issues fixed after May 2023. Reduced penalty to \$0.</p>	
50651	<p>Facility Owner: Columbia Gas of PA - North</p> <p>Contractor/Excavator: MEALY EXCAVATING AND CONSTRUCTION INC</p> <p>Project Owner: PENNSYLVANIA AMERICAN WATER</p> <p>Designer: GWIN DOBSON AND FOREMAN ENGINEERS</p> <p>Other: BREEZELINE</p> <p>Other: PAPCO INC</p>	<p><u>On 10/17/2024 9:00:00 AM at 264 and 266 PLEASANT DR, PLEASANT TWP, WARREN</u> Tuesday, March 11, 2025, at the DPC meeting, disputing parties were PAPCo Inc, Pennhills Resources LLC, Valley View Coop and SLT Production LLC Frmly Sheffield Land. NO SHOW from PAPCo Inc, and SLT Production LLC Frmly Sheffield Land. It was voted, for all disputing parties, to Accept the DPI’s Recommendations. ***** PAPCO is disputing. ***** Valley View Co-op is disputing. *****</p>	<p>MEALY EXCAVATING AND CONSTRUCTION INC: \$500.00 Section 5(4) 1st Offense \$500.00</p> <p>BREEZELINE: \$500.00 Section 2(5)(v) 1st Offense \$500.00</p> <p>PAPCO INC: \$1,500.00 Section 2(5)(v) 1st Offense \$500.00</p> <p>Section 2(5)(v) 1st Offense</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>Other: Pennhills Resources LLC Other: SLT PRODUCTION LLC FRMLY SHEFFIELD LAND Other: Valley View Coop Other: Verizon PA LLC</p>	<p>SLT Production is disputing. All violations and penalties withdrawn as SLT is not a facility owner as described in the law. ***** Pennhills Resources LLC is disputing. ***** The incident occurred on Thursday, October 17, 2024, at 264 and 266 Pleasant Drive, in Pleasant Township, Warren County.</p> <p>Columbia Gas line was damaged.</p> <p>Mealy Excavating and Construction Inc stated that their crew hit and damaged a gas service line to 264 Pleasant Drive while installing water mainline for Pennsylvania American Water Company. The gas mark was missed by our crew and resulted in a severed poly gas service line. PA American Water stated that Mealy Excavating hit and damaged a correctly marked gas service line while installing a water mainline. Columbia Gas stated that Mealy Excavating was digging to install a new water mainline when they hit and damaged an accurately marked 1-inch plastic, company-side, gas service line that fed 264 and 266 Pleasant Drive, with their excavator. Mealy Excavating notified 911 and Columbia Gas when the damage occurred. Photos were provided by Mealy Excavating and Columbia Gas.</p> <p>~20242624592- Routine ticket placed on 9/18/2024, with a duration of 8 months. No Response from- Valley View Coop, SLT Production LLC FRMLY Sheffield Land, and Breezeline.</p> <p>~20242631295- Update Routine ticket placed on 9/19/2024, with a duration of 8 months. No Response from- Valley View Coop, and SLT Production LLC FRMLY Sheffield Land.</p> <p>~20242753557- Routine ticket placed on 10/1/2024, with a duration of 8 months and response due date of 10/3/2024. No Response from- Valley View Coop, SLT Production LLC FRMLY Sheffield Land, and PAPCO INC. Late Response from- Pennhills Resources LLC responded on 10/21/2024 as Clear No Facilities.</p> <p>~20242830611- Update Routine ticket placed on 10/9/2024, with a duration of 8 months and response due date of 10/11/2024. No Response from- Valley View Coop, SLT Production LLC FRMLY Sheffield Land, and PAPCO INC. Late Response from- Pennhills Resources LLC responded on 10/21/2024 as Clear No Facilities.</p> <p>~20242560523- Complex Project Meeting ticket placed on 9/12/2024. No Response from- Valley View Coop, SLT Production LLC FRMLY Sheffield Land, PAPCO INC, and Verizon PA LLC.</p>	<p>\$500.00 Section 2(5)(viii) 1st Offense \$500.00</p> <p>Pennhills Resources LLC: \$500.00 Section 2(5)(v) 1st Offense \$250.00</p> <p>Section 2(5)(v) 1st Offense \$250.00</p> <p>SLT PRODUCTION LLC FRMLY SHEFFIELD LAND: \$0.00</p> <p>Valley View Coop: \$2,500.00 Section 2(5)(v) 1st Offense \$500.00</p> <p>Section 2(5)(viii) 1st Offense \$500.00</p> <p>Verizon PA LLC: \$2,000.00 Section 2(5)(viii) Subsequent \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>*Mealy Excavating and Construction Inc is in violation of section: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: Education Required and Penalty Applied</p> <p>*Valley View Coop is in violation of sections: 2(5)(v) – Failed to respond to a routine One Call ticket. 20242624592 2(5)(v) – Failed to respond to a routine One Call ticket. 20242631295 2(5)(v) – Failed to respond to a routine One Call ticket. 20242753557 2(5)(v) – Failed to respond to a routine One Call ticket. 20242830611 Recommendation: Education Required and Penalties Applied</p> <p>*SLT Production LLC FRMLY Sheffield Land is in violation of sections: 2(5)(v) – Failed to respond to a routine One Call ticket. 20242624592 2(5)(v) – Failed to respond to a routine One Call ticket. 20242631295 2(5)(v) – Failed to respond to a routine One Call ticket. 20242753557 2(5)(v) – Failed to respond to a routine One Call ticket. 20242830611 Recommendation: Education Required and Penalties Applied</p> <p>*Breezeline is in violation of section: 2(5)(v) – Failed to respond to a routine One Call ticket. 20242624592 Recommendation: Education Required and Penalty Applied</p> <p>*PAPCO INC is in violation of sections: 2(5)(v) – Failed to respond to a routine One Call ticket. 20242753557 2(5)(v) – Failed to respond to a routine One Call ticket. 20242830611 Recommendation: Education Required and Penalties Applied</p> <p>*Pennhills Resources LLC is in violation of sections: 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. 20242753557 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. 20242830611 Recommendation: Education Required and Penalties Applied</p> <p>*Verizon PA LLC is in violation of section: 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project. 20242560523 Recommendation: Penalty Applied</p>	

Committee Review

No cases scheduled.