



**Pennsylvania Public Utility Commission**

**Damage Prevention Committee Meeting Case List  
October 15, 2025**

**Omnibus Session**

Case Number	Stakeholders	Summary	Violations & Recommendation
54693	<p><b>Facility Owner:</b> Penelec / First Energy  <b>Contractor/Excavator:</b> Meyers Excavating  <b>Project Owner:</b> Homeowner  <b>Other:</b> Portage Township Cambria County</p>	<p><u>On 3/21/2025 1:00:00 PM at 266 PLANE RD, PORTAGE TWP, CAMBRIA</u> The incident occurred on 3/21/2025 at 1:00 PM, at 266 Plane Road, in Portage Township, Cambria County.</p> <p>An electrical line owned by Penelec was damaged.</p> <p>Penelec, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, "PLEASE NOTE: Access to the One Call System on 5-2-25 was denied. On March 20, 2025, Meyers Excavating, "Excavator", submitted POCS Emergency Ticket 20250791681 for 266 Plane Rd in Portage Township, Pennsylvania. The Excavator was working to repair a broken water line when they dug into an electric line, blowing a transformer fuse on a pole. On March 20, 2025, Penelec was notified and repaired. USIC's damage investigation found that the Excavator had failed to expose marked facilities while digging within the tolerance zone." Photos were submitted.</p> <p>Meyers Excavating is the excavator. An AVR has not been filed as of 06/24/2025.</p> <p>The homeowner is the project owner. An AVR was not filed as of 06/24/2025.</p> <p>The submitted photos show the electrical line marked out in red paint. The damage occurred within the tolerance zone.</p> <p>Emergency ticket 20250801892 had a response due date of 03/21/2025. Portage Township Cambria County did not respond to this ticket until 03/24/2025.</p> <p>Violations:</p> <p>Meyers Excavating-</p> <ul style="list-style-type: none"> <li>- Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.</li> <li>- Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.</li> </ul> <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Portage Township Cambria County-</p>	<p><b>Meyers Excavating:</b>  <b>\$1,500.00</b>            Section 5(16) 1st Offense            \$1,000.00</p> <p>Section 5(4) 1st Offense            \$500.00</p> <p><b>Portage Township Cambria County:</b>  <b>\$1,000.00</b>            Section 2(5)(vii) 1st Offense            \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>- Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket 20250801892.</p> <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Portage Township is delinquent on DPC ordered education from 3/12/2024 for case 41043.</p>	
54550	<p><b>Facility Owner:</b> Met Ed / First Energy  <b>Contractor/Excavator:</b> POTTEIGER FARMS  <b>Project Owner:</b> Homeowner</p>	<p><u>On 4/9/2025 11:00:00 AM at 20 WOODLAND DR, ROCKLAND TWP, BERKS</u> The incident occurred on 04/09/2025 at 11:00 AM, at 20 Woodland Drive, in Rockland Township, Berks County.</p> <p>An electrical line owned by Met Ed / First Energy was damaged.</p> <p>Met Ed, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “On March 25, 2025, Potteiger Farms, Excavator, submitted POCS Routine Ticket 20250841628 to repair a wall near 20 Woodland Drive, Fleetwood, Berks County, PA. USIC, Met-Ed’s contract locator, responded “field marked” on April 1, 2025. On April 9, 2025, Excavator damaged a marked secondary service while excavating. The root cause of the damage is that the Excavator failed to dig prudently within the Tolerance Zone.” Photos were submitted.</p> <p>Potteiger Farms was the excavator. An AVR has not been filed as of 06/25/2025.</p> <p>The homeowner was the project owner. An AVR was not requested. An AVR has not been filed as of 06/25/2025.</p> <p>The submitted photos show the electrical line was damaged within the tolerance zone.</p> <p>Violations:  Potteiger Farms-  - Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.  - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.  Recommendation: The penalty is applied. PUC compliance training education is required.</p>	<p><b>POTTEIGER FARMS: \$1,500.00</b>  Section 5(4) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>
54730	<p><b>Facility Owner:</b> COLUMBIA GAS OF PA INC_Central  <b>Contractor/Excavator:</b> ESCAJEDA MASONRY &amp; CHIMNEY  <b>Project Owner:</b> UPPER ST CLAIR TOWNSHIP  <b>Designer:</b> THE GATEWAY ENGINEERS INC</p>	<p><u>On 4/16/2025 12:30:00 PM at 1766 MEADOWCREST DR, UPPER ST CLAIR TWP, ALLEGHENY</u> The incident occurred on Wednesday, April 16, 2025, at 1766 Meadowcrest Drive, in Upper St. Clair Township, Allegheny County.</p> <p>A gas line was damaged</p> <p>Columbia Gas stated in their Alleged Violation Report (AVR), Escajeda Masonry working on behalf of Upper St. Clair Township damaged an accurately marked</p>	<p><b>ESCAJEDA MASONRY &amp; CHIMNEY: \$1,500.00</b>  Section 5(4) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>service line with a backhoe, while installing french drains and sidewalk. 911 and Columbia Gas were notified and responded. Service tech and plant crew completed safety checks and repairs were completed. Damage Prevention Specialist spoke with crew and foreman about hand digging in the tolerance zone. Advised foreman that an AVR would need to be completed on this damage. DPS offered assistance if needed.</p> <p>Columbia Gas provided photos.</p> <p>Upper St. Clair Township and the designer, The Gateway Engineers stated in their AVR's, Contractor, Escajeda Masonry was excavating at the provided location and came into contact with gas line.</p> <p>Escajeda Masonry &amp; Chimney did not submit an AVR within 30 days of striking the gas line.</p> <p>Violations:</p> <p>*Escajeda Masonry &amp; Chimney is in violation of sections:</p> <p>5(4) – Excavator failed to exercise due care and employ prudent excavation techniques</p> <p>5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line.</p> <p>Recommendation: PUC Compliance Education Required and Penalties Applied.</p>	
55199	<p><b>Facility Owner:</b> WEST PENN POWER / FIRSTENERGY</p> <p><b>Contractor/Excavator:</b> S &amp; E Utility Contracting</p> <p><b>Project Owner:</b> PENN TOWNSHIP OF WESTMORELAND COUNTY</p> <p><b>Designer:</b> GIBSON THOMAS ENGINEERING CO INC</p>	<p><u>On 4/17/2025 11:00:00 AM at 5 HAWTHORNE LN, PENN TWP, WESTMORELAND</u> The incident occurred on Thursday, April 17, 2025, at 5 Hawthorne Lane, in Penn Township, Westmoreland County.</p> <p>An underground electric line was damaged.</p> <p>West Penn Power / FirstEnergy (WPP) stated in their Alleged Violation Report (AVR), that S &amp; E Utility Contracting submitted a PA One Call Routine Ticket, 20250941734, on 4/4/2025, to install a storm sewer. On April 17, 2025, the customer at 5 Hawthorne Ln reported no power. WPP investigated and located a damaged underground primary cable. WPP's Contract Locator, USIC, investigated and determined that the Excavator failed to dig prudently within the tolerance zone and damaged an accurately marked underground primary cable.</p> <p>WPP provided a detailed report with photos.</p> <p>Penn Township of Westmoreland County, the project owner, submitted their AVR indicating an Excavator issue as, failed to use prudent techniques in the tolerance zone. No summary was provided. They commented in the Locating Information section, Excavator hit marked utility line.</p> <p>Gibson Thomas Engineering stated in their AVR, contractor, S &amp; E Utility Contracting, broke an electric line. According to our inspector, it was marked correctly.</p>	<p><b>S &amp; E Utility Contracting: \$2,000.00</b></p> <p>Section 5(3) 1st Offense \$500.00</p> <p>Section 5(4) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>S &amp; E Utility Contracting did not submit an AVR within 30 days of striking the line.</p> <p>On Tuesday, June 10, 2025, an email was sent to the excavator requesting an AVR. S &amp; E Utility Contracting did not respond to the request and their AVR was not submitted.</p> <p>Violations:</p> <p>*S &amp; E Utility Contracting is in violation of sections:  5(3) – Excavator failed to preserve mark-outs or request a remark.  5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.  5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line.  Recommendation: PUC Compliance Education Required and Penalties Applied.</p>	
54691	<p><b>Facility Owner:</b> Columbia Gas</p> <p><b>Contractor/Excavator:</b> Scott Zurin Plumbing</p> <p><b>Project Owner:</b> Homeowner</p>	<p>On 4/17/2025 12:07:00 PM at 108 Thomas Ave, YORK TWP, YORK The incident occurred on 04/17/2025 at 108 Thomas Avenue, in York Township, York County.</p> <p>A gas line owned by Columbia Gas was damaged by an excavator and 911 was called. There was not a PA One Call ticket.</p> <p>Columbia Gas, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “Scott Zurin Plumbing was installing a new septic tank at the property located at 108 Thomas Ave, when the crew damaged our 1-inch plastic gas service line. Mr. Scott Zurin stated that when the Service Tech and Plant Crew arrived on site, a rock from the top of the dirt pile rolled off and damaged the gas service, causing gas to blow. Upon examining the piece after it was cut out and replaced, there were visible scrapes along the service line and teeth marks in the dirt wall that were not consistent with damage caused by a rock hitting the service. The section where the break occurred was at the end of the scrape marks and was pulled up, which is consistent with the tooth of an excavator bucket coming into contact with the pipe. There was no valid One Call ticket for Scott Zurin Plumbing. An emergency ticket was placed for The Septic Doctor by Anthony Zurin on April 1st to install a septic tank. Crews squeezed off the service, making the area safe, as the curb valve was buried under the dirt from digging out for the septic tank. We spoke with Mr. Zurin about our investigation and emphasized the importance of using hand tools to expose gas facilities, not just directly above them, and to avoid using an excavator, even with the bucket flat, to skim off the top layer of dirt directly on top of the facilities. Additionally, we identified the hazard of burying our curb valves, which could pose a risk in the event we need to use them for emergencies.” Additionally, they noted on their AVR, ‘Locate marks were painted out under an emergency ticket from another excavator on April 1st. Excavation and damage occurred on April 17th, no one call ticket was placed.’ Photos were submitted.</p>	<p><b>Scott Zurin Plumbing:</b>  <b>\$2,250.00</b>  Section 5(2.1) 1st Offense  \$1,000.00</p> <p>Section 5(6)(i) 1st Offense  \$250.00</p> <p>Section 5(16) 1st Offense  \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Scott Zurin Plumbing is the excavator. An AVR has not been filed as of 07/09/2025.</p> <p>The homeowner is the project owner.</p> <p>New Excavation Emergency ticket 20250903067 for this location was requested by a different excavator, The Septic Doctor, on 03/31/2025 (note the damage did not occur until 04/17/2025). There was not a Pa One Call ticket for Scott Zurin Plumbing.</p> <p>The yellow mark outs seen in photos are from Emergency ticket 20250903067.</p> <p>PA One Call noted in their research, “There is no record of company name Scott Zurin Plumbing but there is one for The Septic Doctor and Scott Zurin at same phone # and email provided on the AVR. Past tickets have been placed under these company names.”</p> <p>Violations:</p> <p>Scott Zurin Plumbing-</p> <ul style="list-style-type: none"> <li>- Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe.</li> <li>- Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area.</li> <li>- Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.</li> </ul> <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
54513	<p><b>Facility Owner:</b> PECO  <b>Contractor/Excavator:</b> Teva Landscaping  <b>Project Owner:</b> Homeowner</p>	<p><u>On 4/20/2025 1:00:00 PM at 8369 FISHER RD, CHELTENHAM TWP, MONTGOMERY</u> The incident occurred on 04/20/2025 at 1:00 PM, at 8369 Fisher Road, in Cheltenham Township, Montgomery County.</p> <p>A gas line owned by PECO was damaged. 911 was called. There was no Pa One Call ticket.</p> <p>PECO, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “TEVA LANDSCAPING was excavating with unknown equipment to install a fence when they severed the unmarked 1.25 Plastic gas service, it was found that TEVA LANDSCAPING did not have a locate request prior to excavating resulting in the unmarked gas service being severed and in need of repair.” Photos were submitted.</p> <p>Teva Landscaping is the excavator. An AVR has not been filed as of 06/25/2025.</p> <p>The Property Owner is the project owner. An AVR has not been filed as of 06/25/2025.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>The excavator did not have a PA One Call ticket. The submitted photos show there were no utility mark outs.</p> <p>No Violations were applied.</p> <ul style="list-style-type: none"> <li>- PECO's AVR noted that Teva Landscaping was excavating with unknown equipment. - Unable to verify if damage was caused by mechanized equipment or hand tools.</li> <li>- If hand tools were used a Pa One Call ticket would not be required.</li> <li>- No photos of the actual line damage were submitted or photos showing Teva Landscaping was on site.</li> </ul>	
54360	<p><b>Facility Owner:</b> UGI  <b>Contractor/Excavator:</b> Grace Industries  <b>Project Owner:</b> PennDOT  <b>Designer:</b> ALFRED BENESCH AND COMPANY</p>	<p><u>On 4/22/2025 8:30:00 AM at RACE ST, CATASAUQUA BORO, LEHIGH</u> The incident occurred on 4/22/2025 at 8:30 AM, on Race St, in Catasauqua Boro, Lehigh County.</p> <p>A gas line owned by UGI Utilities Inc was damaged. The facility was notified of the damage. 911 was contacted.  Duration of Service Interruption 1 - &lt; 6 hrs  Approximate Number of Customers Affected 1</p> <p>UGI Utilities Inc is the facility owner. Their Alleged Violation Report (AVR) states, "GRACE INDUSTRIES WAS DIGGING TO WORK ON STORM SEWER AND WHEN DOING SO THEY STRUCK A CORRECTLY MARKED GAS SERVICE FACILITY CREATING A DAMAGE. DIGGING IN THE TOLERANCE ZONE."</p> <p>Grace Industries Inc is the excavator. Their AVR states, "PennDOT project SR 1004 Catasauqua Borough ECMS project # 57433. Broke UGI utility lateral, utility was marked. Notified UGI - Line repaired by 4 pm same day."</p> <p>PennDOT is the project owner. Their AVR states, "PennDOT project SR 1004 Catasauqua Borough ECMS project #57433. Broke UGI utility lateral, utility was marked. Notified UGI -Line repaired by 4 pm same day."</p> <p>Alfred Benesch And Company is the designer.</p> <p>Violations:  Excavator - Grace Industries Inc:  Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.  Recommendation: PUC compliance training education is required.</p>	<p><b>Grace Industries:</b>  <b>\$500.00</b>  Section 5(4) 1st Offense  \$500.00</p>
54518	<p><b>Facility Owner:</b> ALTOONA WATER AUTHORITY  <b>Contractor/Excavator:</b> RIVERSIDE POINT APARTMENTS  <b>Project Owner:</b></p>	<p><u>On 4/24/2025 9:00:00 AM at 1916 15TH AVE, ALTOONA CITY, BLAIR</u> RIVERSIDE POINT APARTMENTS - Discussed relevant laws, procedures, and issues with the facility. They are responsive and have taken steps to correct prior issues.5(7) and 5(16) reduced by 50% from \$1000 to \$500 on both violations, and 5(17) reduced to a warning.</p>	<p><b>RIVERSIDE POINT APARTMENTS:</b>  <b>\$1,750.00</b>  Section 5(3) 1st Offense  \$500.00   Section 5(6)(i) 1st Offense  \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	Beauchamp Plumbing & Heating	<p>Beauchamp Plumbing &amp; Heating - Reduced violations to a warning of \$0. Education is required. *****</p> <p>The incident occurred on 4/24/2025 at 9:00 AM, on 1916 15Th Ave, in Altoona City, Blair County.</p> <p>A water line owned by Altoona Water Authority Water Division was damaged.</p> <p>Altoona Water Authority Water Division is the facility owner. Their Alleged Violation Report (AVR) states, "AWA GOT CALL FOR MEN DIGGING WITH OUT ONE CALL MADE - CONTRACTOR HIT AWA WATER LINE. AWA RESPONDED AND REPAIRED LINE TO PROPERTY SEE ATTACHED PHOTOS".</p> <p>Riverside Apartments is the excavator. An AVR has not been filed as of 06-30-2025.</p> <p>Beauchamp Plumbing And Heating is the project owner. An AVR has not been filed as of 6-30-2025.</p> <p>Ticket#20250762626, submitted by Riverside Apartments on 3/17/2025 for 1916 15TH AVE with a start date of 3/20/2025 and a duration of 1-2.5 day, indicates that Beauchamp Plumbing And Heating is the project owner. The application to the City of Altoona for a building permit was completed by Riverside Point Apartments.</p> <p>An AVR request letter was sent, via mail and email, to both Riverside Apartments and Beauchamp Plumbing And Heating. Riverside Apartments did not respond. Beauchamp Plumbing And Heating emailed stating, "We have nothing in on this, I am not filling out the form." And "This is not one of our properties. This belongs to Riverside Apartments. My husband pulled the permit on behalf of Beauchamp Plumbing and Heating for a water line, but we did not do the digging."</p> <p>The only Ticket for this location has Beauchamp Plumbing and Heating as the Project Owner, and Riverside Apartments as the Excavator, and had a start date of 3/20/2025. The damage occurred on 4/24/2025. No visible markings can be seen from the original mark out in the photos provided, and Altoona Water Authority also states, "NO ONE CALL MARKS OR ONE CALL AREA INDICATED ON AREA SURFACE".</p> <p>Violations: Excavator-Riverside Apartments: Section 5(3) – Excavator failed to preserve mark-outs or request a remark. Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. Section 5(7) – Failed to immediately report to the facility owner any break or leak in its lines, or any dent, gouge,</p>	<p>Section 5(7) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$500.00</p> <p>Section 5(17) 1st Offense \$0.00</p> <p><b>Beauchamp Plumbing &amp; Heating: \$0.00</b></p> <p>Section 6.1(7) 1st Offense \$0.00</p> <p>Section 6.1(8) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>groove, or other damage to such lines or to their coating or cathodic protection.</p> <p>Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.</p> <p>Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request.</p> <p>Recommendation: PUC compliance training education is required.</p> <p>Project Owner -Beauchamp Plumbing And Heating: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Section 6.1(8) - Project Owner failed to comply with all requests for information by the commission relating to the commission's enforcement authority under this act within 30 days of receipt of written request. Recommendation: PUC compliance training education is required.</p>	
54522	<p><b>Facility Owner:</b> PECO <b>Contractor/Excavator:</b> ANRICH INC <b>Project Owner:</b> PENNSYLVANIA AMERICAN WATER <b>Other:</b> Verizon</p>	<p><u>On 4/24/2025 10:00:00 AM at OLD LINCOLN HWY, VALLEY TWP, CHESTER</u> Incident occurred on April 24th, 2025, at 10am on Old Lincoln Highway, Valley Township, Chester County.</p> <p>A gas line was damaged.</p> <p>PECO's Alleged Violation Report (AVR) states, "Anrich Inc was excavating with a trachoe to remove the blacktop to install a sewer main when they severed the marked 1" plastic gas service, it was found that ANRICH INC damaged the marked gas service within the tolerance zone of 18" it was found the damage occurred 7" from the gas mark out."</p> <p>PECO's pictures an excavator and the damaged line marked within the tolerance zone.</p> <p>PAWC's AVR states, "ANRICH WAS DIGGING WITH A TRACKHOE ABOUT 10:20 AM TO INSTALL NEW WATER MAIN AND WAS PULLING UP BLACKTOP AND THE GAS SERVICE WAS IN THE BLACKTOP AND PULLED THE SERVICE UP WITH THE BLACKTOP.PECO INSTALLED THE GAS SERVICE LINE TO SHALLOW."</p> <p>No AVR has been submitted by Anrich Inc for this line strike as of 6/25/25. Emergency ticket states that 911 was notified by the excavator.</p> <p>Violations:</p> <p>Anrich Inc. Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. PUC compliance education is required. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required.</p>	<p><b>ANRICH INC: \$2,000.00</b> Section 5(4) 2nd Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p><b>Verizon: \$1,000.00</b> Section 2(5)(viii) 2nd Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Verizon Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). Meeting was held on 3/17/25 and Verizon did not respond until 4/14/25 with "Did not attend meeting. DCTF by FO.</p>	
54581	<p><b>Facility Owner:</b> Peoples Gas Company <b>Contractor/Excavator:</b> LYNN PLUMBING AND CONCRETE <b>Project Owner:</b> LEGENDS CAPITOL HOLDINGS</p>	<p><u>On 4/24/2025 11:18:00 AM at 552 RYDER CT, LIBERTY TWP, MERCER</u> Incident occurred on April 24th, 2025, at 11:18am on 552 Ryder Court, Liberty Township, Mercer County.</p> <p>A gas line was damaged.</p> <p>Peoples Gas Company's Alleged Violation Report (AVR) states, "On 4/24/2025, Lynn Plumbing and Concrete struck an accurately marked PNG 4" PL ML. PNG crews were called and repairs were made." Pictures from Peoples show the line was marked within the tolerance zone along with excavator bucket teeth marks in the dirt.</p> <p>Lynn Plumbing &amp; Concrete's emergency ticket states they notified 911.</p> <p>No AVRs have been submitted by Lynn Plumbing &amp; Concrete or Legends Capitol Holdings.</p> <p>Violations:</p> <p>Lynn Plumbing &amp; Concrete Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. PUC compliance education is required. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required.</p> <p>Legends Capitol Holdings. Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. PUC compliance education is required.</p>	<p><b>LYNN PLUMBING AND CONCRETE: \$1,500.00</b> Section 5(4) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p><b>LEGENDS CAPITOL HOLDINGS: \$1,000.00</b> Section 6.1(7) 1st Offense \$1,000.00</p>
55216	<p><b>Facility Owner:</b> PEOPLES GAS COMPANY LLC <b>Contractor/Excavator:</b> N&amp;N LANDSCAPING <b>Project Owner:</b> Oakmont Borough</p>	<p><u>On 4/24/2025 6:00:00 PM at 503 8TH STREET, OAKMONT BORO, ALLEGHENY</u> The incident occurred on Thursday, April 24, 2025, at 503 8th Street, in Oakmont Borough, Allegheny County.</p> <p>A gas line was damaged.</p> <p>Peoples Gas Company stated in their Alleged Violation Report (AVR), N&amp;N Landscaping working for Oakmont Borough to do brick road restoration struck and damaged a properly marked Peoples Gas service line. N&amp;N Landscaping did not call in to 811, 911 or the facility owner to report the damage. The gas was off by a flow limiter after the damage and Peoples Gas crews found the damage when responding to the customer calling in to report they had no gas. The mark in the picture named</p>	<p><b>N&amp;N LANDSCAPING: \$3,500.00</b> Section 5(4) 1st Offense \$500.00</p> <p>Section 5(7) 1st Offense \$1,000.00</p> <p>Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p><b>Oakmont Borough: \$1,000.00</b></p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Repaired with the bricks removed was placed by the crew who repaired the line.</p> <p>Additional information sent by Peoples Gas, "The O&amp;M (Operations &amp; Maintenance) Crew was called to respond to a no gas call notified by the homeowner, and is not typically the first responder when there's a damage; therefore, the pictures taken was not the best pictures because the O&amp;M Crew is not used to taking the pictures needed for a damage report caused by a 3rd party contractor. It was not until they dug the plastic service line, in the newly backfilled area of the plastic service line as shown in the attached damaged pictures, that the O&amp;M Crew found the damaged plastic gas service line, then they notified the Ops Center of the damage, and took pictures. There was no sand or warning tape visible and the gas company will never place slag directly covering plastic pipe due to the potential of the rocks causing a leak when compacting the backfill and just over the years. The gas lines has a 25#MAOP on the street, making it almost impossible for the homeowner to be without gas, unless there was a malfunction with the EFV, the curb valve, the punch tee separated from the main line, or there was a damage to the plastic service line with a large enough hole in the line causing the EFV to work and stop the flow of gas, and this is what was discovered by the O&amp;M Crew once they dug and exposed the plastic service line. N and N Landscaping failed to report this damage to 811, 911, and Peoples Gas. N and N Landscaping was not on site when the O&amp;M Crew responded to the homeowner's no gas call. And moving forward, the locator was informed to mark more marks outside the white marks applied by the Excavator due to all the markings being excavated by N and N Landscaping."</p> <p>N&amp;N Landscaping did not submit an AVR within 30 days of striking the gas line.</p> <p>Oakmont Borough did not submit an AVR within 30 days of the gas line strike.</p> <p>Violations:</p> <p>*N&amp;N Landscaping is in violation of sections:  5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.  5(7) – Failed to immediately report to the facility owner any break or leak in its lines, or any dent, gouge, groove, or other damage to such lines or to their coating or cathodic protection.  5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid.  5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line.</p> <p>Recommendation: PUC Compliance Education Required and Penalties Applied.</p> <p>*Oakmont Borough is in violation of section:  6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike.</p>	<p>Section 6.1(7) 1st Offense  \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		Recommendation: PUC Compliance Education Required and Penalty Applied.	
54596	<p><b>Facility Owner:</b> VERIZON PA LLC</p> <p><b>Contractor/Excavator:</b> WILSON EXCAVATING AND UTILITY CONSTRUCTION LLC</p> <p><b>Project Owner:</b> Peoples Natural Gas</p> <p><b>Other:</b> WEST VIEW BOROUGH OF</p>	<p><u>On 4/28/2025 10:00:00 AM at 41 CENTER AVE, WEST VIEW BORO, ALLEGHENY</u> The incident occurred on 4/28/2025 on Center Ave. in West View Borough in Allegheny County.</p> <p>A telecommunication line owned by Verizon was damaged.</p> <p>WILSON EXCAVATING AND UTILITY CONSTRUCTION LLC stated in their Alleged Violation Report (AVR) that “Wilson Excavating was performing work for Peoples Gas on Center Ave in Pittsburgh when an unmarked Verizon line was struck and damaged. The crew was digging a trench to install as gas mainline. There were no marks on the road for any utilities so they began to dig with the excavator and they encountered a grey conduit. The conduit was damaged and the fiber line inside was damaged as well. Verizon was notified and they came to the site to make the repair”. Pictures were provided.</p> <p>PEOPLES GAS COMPANY stated in their AVR that “Wilson Excavating was performing work for Peoples Gas on CenterAve in Pittsburgh when an unmarked Verizon line was struck anddamaged. The crew was digging a trench to install as gas mainline. There were no marks on the road for any utilities so they began to dig with the excavator and they encountered a grey conduit. The conduit was damaged and the fiber line inside was damaged aswell. Verizon was notified and they came to the site to make the repair. Picture and report was provided.</p> <p>Verizon’s AVR was due by 6/10/2025. No AVR has been received as of 6/26/2025.</p> <p><b>VIOLATIONS</b> VERIZON PA LLC Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). Complex project ticket 20250913055 was submitted on 4/01/2025 with a response due by 4/03/2025. Verizon never responded. Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: The penalty is applied. Compliance education has recently been completed.</p> <p>WEST VIEW BOROUGH OF is in violation of:</p>	<p><b>VERIZON PA LLC:</b> <b>\$4,500.00</b> Section 2(10) 3rd Offense \$2,000.00</p> <p>Section 2(5)(i) 1st Offense \$500.00</p> <p>Section 2(5)(viii) Subsequent \$2,000.00</p> <p><b>WEST VIEW BOROUGH OF: \$250.00</b> Section 2(5)(v) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20250992824 was submitted on 4/09/2025 with a response due by 4/14/2025. West View Borough did not respond until 4/16/2025.</p> <p>Recommendation: The penalty is applied. Compliance Education is required.</p>	
54502	<p><b>Facility Owner:</b> National Fuel Gas  <b>Contractor/Excavator:</b> WEISSEARLEY LANDSCAPE  <b>Project Owner:</b> Homeowner</p>	<p><u>On 4/28/2025 11:00:00 AM at 5146 ANNENDALE DR, MILLCREEK TWP, ERIE</u> This non-damage incident occurred on 5146 Annendale Dive, Millcreek Township, Erie County.</p> <p>National Fuel Gas' Alleged Violation Report (AVR) states, "Excavator working before lawful start date and near National Fuel facilities. Please see attachments."</p> <p>Weissearley Landscape's insufficient ticket 20251181162 stated, "Crew on site." Pictures from National Fuel Gas' mark outs show that excavation had begun and are dated 4/28/25. The legal start date for ticket 20251181162 was 4/30/25.</p> <p>Violations:</p> <p>Weissearley Lanscape  Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. 20251181162. PUC compliance education is required.</p>	<p><b>WEISSEARLEY LANDSCAPE: \$1,000.00</b>  Section 5(2.1) 1st Offense \$1,000.00</p>
54595	<p><b>Facility Owner:</b> National Fuel Gas  <b>Contractor/Excavator:</b> Oakland Beach Golf Course  <b>Project Owner:</b> Oakland Beach Golf Course Placeholder</p>	<p><u>On 4/28/2025 1:00:00 PM at 11866 Oakland Beach Rd., CONNEAUT LAKE BORO, CRAWFORD</u> Incident occurred on April 28th, 2025, at 1pm on 11866 Oakland Beach Road, Conneaut Lake Boro, Crawford County.</p> <p>A gas line was damaged.</p> <p>National Fuel Gas' Alleged Violation Report (AVR) states, "Excavator was using a ditch witch to run an electric line and hit national fuel distribution service. Excavator did not have a POCS Ticket submission. Please see attachments." AVR does not note if 911 was notified.</p> <p>Pictures show a gas meter next to the damaged gas line from a ditch witch.</p> <p>811 commented, "Contractor has placed One Call notifications with PA One Call in the past. Listed contact info is most recent contact info on file for Oakland Beach Golf Course."</p> <p>No AVR has been submitted by Oakland Beach Golf Course as of 6/26/25.</p> <p>Violations:</p> <p>Oakland Beach Golf Course  Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. PUC compliance education is required.</p>	<p><b>Oakland Beach Golf Course: \$2,000.00</b>  Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
54940	<p><b>Facility Owner:</b> PEOPLES GAS COMPANY</p> <p><b>Contractor/Excavator:</b> WESTMORELAND CO MUNI AUTH</p> <p><b>Project Owner:</b> WESTMORELAND CO MUNI AUTH</p>	<p>Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required.</p> <p><u>On 4/28/2025 2:00:00 PM at 607 LYNDA LN, NORTH VERSAILLES TWP, ALLEGHENY</u> The incident occurred on Monday, April 28, 2025, at 607 Lynda Lane, in North Versailles Township, Allegheny County.</p> <p>A gas line was damaged.</p> <p>Municipal Authority of Westmoreland County (MAWC), the project owner and excavator, stated in their Alleged Violation Report (AVR), they were working to repair a leaking water facility at 607 Lynda Lane in North Versailles MAWC was using a saw to cut out a section of its leaking water main. While performing this cut MAWC struck a Peoples Gas plastic main. This gas main is located inches away from the water main, making any maintenance to the water main difficult. MAWC contacted 911, and 811 to report the escape of gas and damaged gas main. Peoples Gas responded and made the necessary repair.</p> <p>Peoples Gas Company stated in their AVR, on 4/28/25 MAWC saw cut into PNG main line, MAWC was attempting to saw cut their main to remove a piece when saw cut into PNG plastic main line. PNG mainline was exposed. MAWC notified 811 and PNG. PNG crews arrived onsite and made safe. PNG crews are making final repairs.</p> <p>Photos are provided showing the damaged gas line.</p> <p>Violation:</p> <p>*Municipal Authority of Westmoreland County is in violation of section: 5(6)(ii) – Excavator failed to provide support and mechanical protection for known facility owner’s lines at the construction work site. Recommendation: Penalty Applied.</p>	<p><b>WESTMORELAND CO MUNI AUTH: \$500.00</b> Section 5(6)(ii) 1st Offense \$500.00</p>
56014	<p><b>Facility Owner:</b> Met Ed / First Energy</p> <p><b>Contractor/Excavator:</b> Keystone Custom Decks</p> <p><b>Project Owner:</b> Homeowner</p>	<p><u>On 4/29/2025 7:00:00 AM at 2 SYLVAN LN, CUMRU TWP, BERKS</u> Met- Ed - Penalty reduced by 50% from \$1000 to \$500. *****</p> <p>The incident occurred on 4/29/2025 at 7:00 AM, on 2 Sylvan Ln, in Cumru Twp, Berks County.</p> <p>An electric line owned by Metropolitan Edison Co was damaged. The facility was not notified of the damage by the excavator.</p> <p>Metropolitan Edison Co/Firstenergy is the facility owner. Their Alleged Violation Report (AVR) states, “On April 22, 2025, Keystone Custom Decks, Excavator, submitted PA One Call Routine ticket 20251120486 to install a new patio at 2 Sylvan Lane, Cumru Township, Berks County, PA. On April 29, 2025, the customer at the location reported no power. Met-Ed's crew investigated and located a damaged underground</p>	<p><b>Met Ed / First Energy: \$500.00</b> Section 2(10) 1st Offense \$500.00</p> <p><b>Keystone Custom Decks: \$2,500.00</b> Section 5(16) 1st Offense \$1,000.00</p> <p>Section 5(4) 1st Offense \$500.00</p> <p>Section 5(7) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>secondary cable. Met-Ed’s Contract Locator, USIC, investigated and determined that the Excavator failed to take due care while digging in the tolerance zone and damaged Met-Ed’s underground secondary cable.”</p> <p>Keystone Custom Decks is the excavator. An AVR has not been filed as of 7/1/2025.</p> <p>Cheryl Rowe is the homeowner.</p> <p>Multiple photos were submitted of the site from before and after the damage. There is newly dug dirt shown in the damage photos, as well as a support post for the new deck that is installed within the tolerance zone of the marks shown in the pre-damage photos. Ticket# 20251120486 indicates that power equipment/auger was method of excavation.</p> <p>Violations:  Facility – Met-Ed:  Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work.  Recommendation: PUC Online Compliance Training is required.</p> <p>Excavator – Keystone Custom Decks:  Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.  Section 5(7) – Failed to immediately report to the facility owner any break or leak in its lines, or any dent, gouge, groove, or other damage to such lines or to their coating or cathodic protection.  Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.  Recommendation: PUC Online Compliance Training is required.</p>	
54572	<p><b>Facility Owner:</b> UGI Utilities Inc.  <b>Contractor/Excavator:</b> Monarch Concrete &amp; Construction LLC  <b>Project Owner:</b> SPRINGGATE VINEYARD  <b>Other:</b> VERIZON PA LLC</p>	<p>On 4/29/2025 10:43:00 AM at 5790 Devonshire Rd, LOWER PAXTON TWP, DAUPHIN Springate Vinyard disagreed. DPI Maki withdrew the penalty for this first-time offender but maintained the education.  *****  The incident occurred on 4/29/2025 at 5790 Devonshire Rd in Lower Paxton Township in Dauphin County.</p> <p>A customer owned gas line was damaged. No OneCall ticket was placed prior to excavation.</p> <p>UGI Utilities Inc. the facility owner stated in their AVR that “UGI was called to 5790 Devonshire Rd in Harrisburg to a struck gas line. It was determined the excavator struck and damaged a customer owned fuel line. UGI facilities exist on the property but were not damaged. UGI employee determined that excavator was</p>	<p><b>Monarch Concrete &amp; Construction LLC:</b>  <b>\$2,000.00</b>  Section 5(2.1) 1st Offense  \$1,000.00</p> <p>Section 5(16) 1st Offense  \$1,000.00</p> <p><b>SPRINGGATE VINEYARD: \$0.00</b>  Section 6.1(7) 1st Offense  \$0.00</p> <p><b>VERIZON PA LLC:</b>  <b>\$250.00</b></p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>digging without a PA One Call ticket, stopped the work and asked them to submit a ticket". 911 was notified. Pictures were provided. Compliance Research Results: Contractor has placed One Call notifications with PA One Call in the past.</p> <p>Monarch Concrete &amp; Construction LLC the excavator AVR was due by 5/29/2025. No AVR has been received as of 6/26/2025.</p> <p>SPRINGGATE VINEYARD the project owner was due by 5/29/2025. No AVR has been received as of 6/26/2025.</p> <p><b>VIOLATIONS:</b> Monarch Concrete &amp; Construction LLC is in violation of: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe.</p> <p>Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or damaging a facility owner’s line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: The penalties are applied. Compliance education is required.</p> <p>SPRINGGATE VINEYARD is in violation of: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike or damaging a facility owner’s line during excavation or demolition work activities or if a project owner believes a violation of this act has been committed in association or demolition. Recommendation: The \$1000. Penalty is reduced to a warning. Compliance education is required.</p> <p>VERIZON PA LLC is in violation of: Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Emergency ticket 20251191827 was requested by UGI on 4/29/2025 at 10:43. Verizon responded “Conflict” DCTF by FO on 4/29/2025 at 10:49 but never gave a final response. Recommendation: The penalty is applied. Compliance education was recently completed and another is due by 8/10/2025. See case 51649.</p>	<p>Section 2(5)(v.2) 1st Offense \$250.00</p>
54950	<p><b>Facility Owner:</b> UGI Utilities <b>Contractor/Excavator:</b> Pennsylvania American Water Company (PAWC) <b>Project Owner:</b> PA American Water Co.</p>	<p><u>On 4/29/2025 11:35:00 AM at 1008 HILL ST, MAYFIELD BORO, LACKAWANNA</u> Incident occurred on April 29th, 2025, at 11:35am on 1008 Hill Street, Mayfield Boro, Lackawanna County.</p> <p>A gas line was damaged.</p> <p>UGI's Alleged Violation Report (AVR) states, "Excavator was digging to repair water leak when a ditch collapse damaged and broke an exposed gas service. An uncontrolled release of gas occurred." 911 was notified.</p>	<p><b>Pennsylvania American Water Company (PAWC): \$1,500.00</b> Section 5(6)(ii) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>UGi's pictures show a small excavation site with collapsed walls.</p> <p>PAWC's AVR states, "the existing gas line was completely uncovered by vac truck. while in the process of getting shoring off crew truck the ditch wall caved in severing the service line to the house."</p> <p>PAWC's AVR was submitted on 7/1/25 as the excavator. This is 63 calendar days and 43 business days after the line was damaged. PAWC was both the excavator and project owner. DPI is only giving a violation for no AVR with in 30 days as an excavator.</p> <p>Violations:</p> <p>PAWC Section 5(6)(ii) – Excavator failed to provide support and mechanical protection for known facility owner’s lines at the construction work site. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation.</p>	
54630	<p><b>Facility Owner:</b> Old Forge Crossing Condo Assoc <b>Contractor/Excavator:</b> Empower Construction <b>Project Owner:</b> PECO <b>Designer:</b> MCGINLEY CONSULTING GROUP <b>Other:</b> Comcast <b>Other:</b> Verizon, PA LLC</p>	<p><u>On 4/30/2025 9:00:00 AM at OLD FORGE CROSSING, TREDYFFRIN TWP, CHESTER</u> The incident occurred on 4/30/2025 at 9:00 AM, on Old Forge Crossing, in Tredyffrin Twp, Chester County.</p> <p>An irrigation line owned by Old Forge Crossing Condo Assoc was damaged.</p> <p>Old Forge Crossing Condo Assoc is the facility owner. An Alleged Violation Report (AVR) request letter was sent to them on 5/30/2025. Email received on 6/23/2025 stating they would submit an AVR that week. No AVR has not been filed as of 7/1/2025.</p> <p>Empower Construction is the excavator. Their AVR states, “On Wednesday, April 30th, 2025, an Empower Construction civil crew was tasked with installing new conduit on Upper Drive in Devon, PA on the Upper Merion-142 project WO#18152243. The crew began their day with conducting a job briefing and walking the project down for mark outs. As crew was in the process of utilizing mechanical means to trench, the crew came in contact with an unmarked sprinkler water line 5 inches below grade. HOA arrived onsite to make repairs. The crew immediately stopped work, notified PECO Construction Management, PA One Call, and Empower Construction Management. Original PA1 Call Ticket #20251130371. Damage PA1 call ticket #20251201326.”</p> <p>Peco Energy is the project owner. An AVR Request letter was mailed on 5/30/2025. Their AVR was submitted on 6/13/2025 and states, “On Wednesday, April 30th, 2025, an Empower Construction civil crew was tasked with installing new conduit on Upper Drive in Devon, PA on the Upper Merion-142 project</p>	<p><b>Old Forge Crossing Condo Assoc: \$4,000.00</b> Section 2(10) 1st Offense \$1,000.00</p> <p>Section 2(11) 1st Offense \$500.00</p> <p>Section 2(5)(i) 1st Offense \$500.00</p> <p>Section 2(5)(v) 1st Offense \$500.00</p> <p>Section 2(5)(v.1) 1st Offense \$500.00</p> <p>Section 2(5)(vii) 1st Offense \$1,000.00</p> <p><b>PECO: \$250.00</b> Section 2(5)(iii.1) 1st Offense \$250.00</p> <p>Section 6.1(7) 3rd Offense \$0.00</p> <p><b>Comcast: \$2,000.00</b> Section 2(5)(v.1) 1st Offense \$500.00</p> <p>Section 2(5)(v) 3rd Offense \$1,500.00</p> <p><b>Verizon, PA LLC: \$5,500.00</b></p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>WO#18152243. The crew began their day with conducting a job briefing and walking the project down for mark outs. As crew was in the process of utilizing mechanical means to trench, the crew came in contact with an unmarked sprinkler water line 5 inches below grade. HOA arrived onsite to make repairs. The crew immediately stopped work, notified PECO Construction Management, PA One Call, and Empower Construction Management.”</p> <p>Mcginley Consulting Group is the designer. Their AVR states, “McGinley Consulting Group was not made aware of the event occurring or has any knowledge regarding the event. Empower Construction is the Contractor of Choice (COC) for PECO Electric. McGinley Consulting Group is Engineer of Choice (EOC) for PECO Electric. McGinley Consulting Group has no responsibility for COC's work, nor has a contractual relationship with the COC.”</p> <p>No photos of the damage or location were submitted.</p> <p>Ticket #20251130371-00 New – Excavation – Routine - Comcast did not respond. Old Forge Crossing Condo Assoc did not respond. Verizon did not respond.</p> <p>Ticket #20251130371-01 (Renotify – Excavation – Insufficient) was prepared on 4/28/2025 at 12:16 PM. The Ticket notes, “ATTN COMCAST, OLD FORGE CROSSING CONDO ASSOC AND VERIZON YOU HAVE NOT RESPONDED. PLEASE MARK OR CLEAR THE LINES ASAP. ATTN PECO YOU POSTED A SCHEDULED TO MARK 4/28 BY 1615. PLEASE MARK ASAP.” Old Forge Crossing Condo Assoc (OFC) did not respond. Verizon did not respond. Comcast responded “Clear.” On 4/30/2025.</p> <p>Ticket #20251201326 New – Damage – Emergency – Old Forge Crossing Condo Assoc did not respond. Verizon did not respond.</p> <p>Violations:  Facility - Old Forge Crossing Condo Assoc  Section 2(5)(v) – Failed to respond to a routine One Call ticket. #20251130371-00  Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. #20251130371-01  Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. #20251201326  Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.  Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work.</p>	<p>Section 2(5)(vii) Subsequent \$2,500.00</p> <p>Section 2(5)(v) Subsequent \$2,000.00</p> <p>Section 2(5)(v.1) 2nd Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 2(11) – Facility Owner failed to comply with all requests for information by the Commission relation to the Commission’s enforcement authority under this act within thirty days of the receipt of the request.  Recommendation: PUC compliance training education is required.</p> <p>Facility (other) – Comcast:  Section 2(5)(v) – Failed to respond to a routine One Call ticket. #20251130371-00  Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. #20251130371-01  Recommendation: PUC compliance training education is required.</p> <p>Facility (other) - Verizon  Section 2(5)(v) – Failed to respond to a routine One Call ticket. #20251130371-00  Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. #20251130371-01  Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. . #20251201326  Recommendation: PUC compliance training education is required.</p> <p>Facility (other) – PECO:  Section 2(5)(iii.1) – Facility owner failed to propose a mutually agreeable scheduling by which the excavator, facility owner or designer may locate the facilities. Ticket #20251130371-00  Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike.  Recommendation: PUC compliance training education is required.</p>	
54621	<p><b>Facility Owner:</b>  PEOPLES NATURAL GAS</p> <p><b>Contractor/Excavator:</b> A MERANTE CONTRACTING INC</p> <p><b>Project Owner:</b> UPPER ST CLAIR TWP</p> <p><b>Other:</b> GATEWAY ENGINEERS INC</p> <p><b>Other:</b> PA AMERICAN WATER (PAWC)</p>	<p><u>On 4/30/2025 4:42:00 PM at 747 THORNWICK DR, UPPER ST CLAIR TWP, ALLEGHENY PA</u> American disagreed. Violations were withdrawn.</p> <p>Upper St Claire Township is disagreeing. AVR has been located and added to case 54621. The violation section-6.17 has been withdrawn.</p> <p>A Merante is disputing. DPI asked for more information from both A Merante and PNG. PNG responded that A. Merante stayed for only one damage. The second damage call was made by the PNG first responder who was returning to the site to complete the work. A. Merante had left the site after completing the backfilling. The O&amp;M operator did not notify A. Merante of the gas damage. Peoples Gas sent another email explaining that A Merante had been told before to only backfill with only sand, but A Merante used 2A slag backfill material. A Merante responded with an email on 8/25/2025 that they were never told and he would like to see documentation of when Peoples notified them of only backfilling with sand. On 8/15/2025 DPI Maki sent an email to Peoples asking about this. In short Peoples stated that using sand has always been conveyed to the crews in the field. They do not document this information since the excavators should be trained to</p>	<p><b>A MERANTE CONTRACTING INC: \$1,250.00</b>  Section 5(16) 1st Offense \$1,000.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p><b>UPPER ST CLAIR TWP: \$0.00</b></p> <p><b>PA AMERICAN WATER (PAWC): \$0.00</b></p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>know the proper backfill for this situation. Please also note that the larger bill was paid by A Mercantile. Please see attachment named Peoples explains - backfill material. DPI withdrew the violation section 5(8) since A Merante was not notified of the damage. They may not have known about the leak when they left the site. On 9/10/2025 A Merante accepted the 2 violations of 5(16) and 5(6)(i). *****</p> <p>The incident occurred on 4/30/2025 at 747 Thornwick Dr.</p> <p>A gas service line owned by Peoples Gas was damaged.</p> <p>PEOPLES GAS COMPANY LLC the facility owner stated in their Alleged Violation Report (AVR) that “ON 4/29/25 A MERANTE CONTRACTING STRUCK PNG COMPANY SIDE SERVICE LINE, PNG CREWS ARRIVED ONSITE AND MADE REPAIRS. A MERANTE CONTRACTING WAS TO BACK FILL DITCH. WHEN BACK FILLING A MERANTE CONTRACTING SPLIT PNG COMPANY SIDE SERVICE AT END OF CASING. A MERANTE CONTRACTING CALLED PNG FOR ODOR OF GAS AND LEFT SITE ON 4/30/25 AT 1642. WHEN PNG REP ARRIVED ONSITE THEY FOUND GAS IN BACKFILLED DITCH IN AREA OF PREVIOUS DAMAGE. PNG CREWS CALLED TO SITE AND SERVICE WAS RENEWED. 911 was notified per E ticket20251192377. Pictures were provided.</p> <p>Peoples Gas sent another AVR which stated that “ON 4/29/25 AT 1200 A. MERANTE CONTRACTING WORKING FOR UPPER ST CLAIR TWP INSTALLING/REPAIRING SANITARY SEWER STRUCK PNG SERVICE LINE PULLING IT FROM TAP AT THE MAIN. EXCAVATION WAS WITH IN TOLERANCE ZONE OF MAIN AND SERVICE LINE. A MERANTED NOTFIED 911 AND 811, PNG CREWS ARRIVED ONSITE AND MADE REPAIRS.</p> <p>UPPER ST CLAIR TOWNSHIP AVR was located after the stakeholder review went out. They stated in their AVR that “Performing Consent Order repairs on Twp sanitary sewer lines when gas line was struck”. Pictures attached.</p> <p>A MERANTE CONTRACTING the excavator did not submit an AVR as of 6/30/2025.</p> <p>GATEWAY ENGINEERS INC submitted a final design ticket for this project.</p> <p>*EMERGENCY TICKET 20251204760 was submitted by Peoples Gas Company LLC on 4/30/2025 at 18:44. Pennsylvania American Water responded on 4/30/2025 with “Conflict” but, never gave a final response.</p> <p>VIOLATIONS A MERANTE CONTRACTING is in violation of:</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or damaging a facility owner’s line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.</p> <p>Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area.</p> <p>Section 5(8) – Excavator vacated worksite after causing damage that resulted in the escape of any flammable, toxic or corrosive gas or liquid.</p> <p>Recommendations: The penalties are applied. Compliance Education is required.</p> <p>PA AMERICAN WATER (PAWC) Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests</p> <p>Section 9 – Failed to make best efforts to comply with the Common Ground Alliance Best Practices Chapter 7(1)(B) Mandatory Education is considered as an alternative or supplement to penalties for offenders of the damage prevention laws and regulations. Project Owner Compliance Education was due by 10/07/2024 and has not been completed as of 6/30/2025.</p> <p>Recommendations: The penalty is applied. Compliance Education is required.</p>	
54825	<p><b>Facility Owner:</b> PECO <b>Contractor/Excavator:</b> PENNSYLVANIA TREE SERVICE <b>Project Owner:</b> Homeowner</p>	<p><u>On 5/1/2025 12:00:00 AM at 324 KELLER RD, TREDYFFRIN TWP, CHESTER</u> The incident occurred on 5/1/2025 at 12:00 AM, on 324 Keller Rd, in Tredyffrin Twp, Chester County.</p> <p>A gas line owned by PECO was damaged. The facility was not notified of the damage. 911 was contacted.</p> <p>PECO is the facility owner. Their Alleged Violation Report (AVR) states, “PENNSYLVANIA TREE SERVICE was excavating with unknown equipment at 324 Keller Rd for stump removal when they severed the unmarked 1/2" plastic gas service, it was found that PENNSYLVANIA TREE SERVICE did not have a locate request for 324 Keller rd., Resulting in the unmarked gas line being severed and needing repair. No One Call.”</p> <p>Pennsylvania Tree Service is the excavator. Their AVR includes the following information on the incident, “On March 24, 2025, Pennsylvania Tree Service, Inc. was contracted with Pat O’Brien of 330 Keller Road in Berwyn. The work consisted of several larger tree removals. We began this work on May 1, 2025. The trees were approximately 100 feet to 140 feet in height. We dismantled the trees to reduce the danger of damage to the neighbor's house driveway or grounds. We had designated and prepared an area around the grounds of the home where the tops of the trees and logs could be felled into safely. At approximately 1:00 the logs or trunk section was felled to the ground. This section measured about 60 to 75 feet in length, and had a</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>diameter of four feet at the base, and two feet at the top. The weight of this trunk section I would estimate to have been 16,000 lbs. total. We set down 12-foot cross sections of timber on the ground in order to fell the large sections onto. This was intended to lessen the impact on the ground. The drop was successful, and we began cutting the trunk into 12-foot sections. Using a skid loader, we removed the wood for the logger to pick up in front of the property. After we had removed the wood from the site, we raked and picked up the smaller debris around the work zone. During this time, we detected a gas odor. We stopped working and immediately searched for the source. We found the source to be in the area where the large tree was felled. Right away, I called for PECO emergency services. This was around 2:15 PM. A PECO technician arrived by 3:15 PM. He surveyed the area and told me that the pipe utility was only inches buried underground. I asked if he needed me to stay on site, and he replied no, and that there shouldn't be any issues. Because of that, I left at about 3:40 PM.”</p> <p>Pat O'Brien, is the Home Owner and Project Owner.</p> <p>The images submitted by PECO show the site, and damage as indicated by a hit kit marker. There is substantial bare dirt that looks recently disturbed in the area surrounding the damage marker. No excavator, or mechanized equipment is seen. No photos of the area prior to the incident, or during the repair could be obtained. Our findings cannot determine how the damage occurred and there is no evidence of a violation.</p>	
54668	<p><b>Facility Owner:</b> MILFORD BOROUGH MUNICIPAL AUTHORITY / Milford Boro</p> <p><b>Contractor/Excavator:</b> Harlan Electric Company</p> <p><b>Project Owner:</b> PIKE COUNTY LIGHT AND POWER (PCLP)</p> <p><b>Other:</b> PIKE COUNTY OF</p>	<p><u>On 5/1/2025 11:00:00 AM at SR 0209, MILFORD Boro.</u> PIKE Pike County disagrees. In an email sent on 8/26/2025 DPI Maki offered to lower their \$1000. to \$500. and keep education. An email was received from Pike County on 8/27/2025 stating that they will make changes and twill complete education. They are asking for a full reduction of the penalty to \$0. DPI emailed links for the required education. On 8/29/2025 an email was received stating that Pike County did take education and also reached out to One Call and added another person who will cover responding to tickets, when the main person is out. The penalty is reduced again from \$500. to \$250. The education requirement was completed on 8/29/2025. On an email was received that Pike County accepts the violation of Section 2(5)(v) for \$250. and wants to withdraw their dispute.</p> <p>Milford Water Authority is not the facility owner, and they responded to the emergency tickets within 24 hours. DPI removed violations and penalties.</p> <p>Pike County Light and Electric disagreed, but then accepted the following: Keep - Section 2(5)(v) – Failed to respond to routine One Call ticket 20251184964. Keep - Section 2(5)(v) – Failed to respond to routine One Call ticket 20251184965. Keep, but reduce penalty to \$0 - Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report</p>	<p><b>MILFORD BOROUGH MUNICIPAL AUTHORITY / Milford Boro: \$0.00</b></p> <p><b>PIKE COUNTY LIGHT AND POWER (PCLP): \$500.00</b> Section 6.1(7) 1st Offense \$0.00</p> <p>Section 2(5)(v) 1st Offense \$250.00</p> <p>Section 2(5)(v) 1st Offense \$250.00</p> <p><b>PIKE COUNTY OF: \$250.00</b> Section 2(5)(vii) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>within 30 Days of a line strike or damaging a facility owner's line during excavation or demolition work activities or if a project owner believes a violation of this act has been committed in association or demolition. Recommendation: Project owner education complete. PCLE completed education and submitted an AVR. *****</p> <p>The incident occurred on 5/01/2025 at SR 0209 in Milford Township in Pike County.</p> <p>A sewer line owned by MILFORD BORO MUNI AUTHORITY - MILFORD BORO was damaged.</p> <p>HARLAN ELECTRIC COMPANY (HEC) stated in their Alleged Violation Report (AVR) that "On Thursday 05-01-2025 a Harlan crew was digging for a pole installation. A valid PA 1 call was in effect. At approximately 11:00 the crew dug into an unmarked drainage pipe approximately 3'6" below grade. PA 1 call was notified of the dig in. It was determined that the drainage pipe belonged to Milford Twp. PA 1 Call notified Harlan excavator that Milford Twp was not a registered member of PA 1 call. Milford Twp made repairs to their facilities on the same day of dig in". They added that "Milford Twp is not a registered member of PA 1 Call, therefore no notification was received by them". DPI Maki sent an email to HARLAN ELECTRIC COMPANY asking if they received a bill from anyone for the damage and asking if they could confirm who owned the sewer line that was damage. On 7/01/2025 HEC responded that the "line is owned by Milford Township and that Milford Township is not a OneCall member".</p> <p>On 7/02/2025 OneCall verified with an email that Milford Township is a OneCall member. Milford Township does not have any facilities in this area and is not listed on the tickets.</p> <p>MILFORD BOROUGH MUNICIPAL AUTHORITY / Milford Boro AVR was due by 6/13/2025. No AVR has been received as of 7/02/2025.</p> <p>PIKE COUNTY LIGHT AND POWER (PCLP) the project owner did not submit an AVR as of 7/02/2025. *****</p> <p>*Ticket 20251184964 was submitted by Harlan Electric Company on 4/28/2025 with a response due by 4/30/2025. Work was expected to last 8 hours to replace a pole. SITE IS AT POLE 37262/48366. Pike County Light and Power Co (PCLP) did not respond until 5/01/2025.</p> <p>Milford Borough Municipal Authority / Milford Borough responded "clear. No facilities or facilities not involved" on 5/01/20025.</p> <p>*Ticket 20251184965 was submitted by Harlan Electric Company on 4/28/2025 with a response due by 4/30/2025.</p> <p>Pike County Light and Power Co (PCLP) did not respond until 5/01/2025.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Milford Borough Municipal Authority / Milford Borough responded “clear. No facilities or facilities not involved” on 5/01/20025.</p> <p>*Emergency ticket 20251212556 was submitted on 5/01/2025 at 12:44. The remarks state that damage is to a black culvert pipe and that the facility owner is not known.</p> <p>Pike County never responded.</p> <p>VIOLATIONS</p> <p>PIKE COUNTY LIGHT AND POWER (PCLP) is in violation of:</p> <p>2X Section 2(5)(v) – Failed to respond to routine One Call ticket 20251184964 and 20251184965 within the required amount of time. Please see ticket details above.</p> <p>Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike or damaging a facility owner’s line during excavation or demolition work activities or if a project owner believes a violation of this act has been committed in association or demolition.</p> <p>Recommendation: The penalties are applied. Project Owner Compliance Education is required. Facility owner Education was recently completed.</p> <p>MILFORD BOROUGH MUNICIPAL AUTHORITY / Milford Boro is in violation of:</p> <p>Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.</p> <p>Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work.</p> <p>2X Section 2(5)(v) – Failed to respond to routine One Call ticket 20251184964 and 20251184965 within the required amount of time. Please see ticket details above.</p> <p>Recommendation: The penalties are applied. Compliance Education is required.</p> <p>PIKE COUNTY is in violation of:</p> <p>Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification.</p> <p>Recommendation: The penalty is applied. Compliance Education is required.</p>	
54663	<p><b>Facility Owner:</b> UGI Utilities, Inc.</p> <p><b>Contractor/Excavator:</b> Selsyn Electric</p> <p><b>Project Owner:</b> South Williamsport Borough</p>	<p><u>On 5/1/2025 2:31:00 PM at 545 E Central Ave, SOUTH WILLIAMSPORT BORO, LYCOMING</u> The incident occurred on 05/01/2025 at 2:31 PM, at 545 East Central Avenue, in South Williamsport Borough, Lycoming County.</p> <p>A gas line owned by UGI was damaged. 911 was called. There was not a PA One Call ticket.</p> <p>UGI, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “Excavator digging without notifying PA One Call struck and damaged a gas service. There was clear evidence of gas facilities in the</p>	<p><b>Selsyn Electric: \$2,250.00</b></p> <p>Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p><b>South Williamsport Borough: \$0.00</b></p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>area. There was an old yellow mark on a nearby concrete sidewalk from a previous locate and gas meter directly in front of excavation.” Photos were submitted.</p> <p>Selsyn Electric is the excavator. An AVR has not been filed as of 06/25/2025.</p> <p>South Williamsport Borough is the project owner. An AVR has not been filed as of 06/25/2025.</p> <p>PA One Call noted that Selsyn Electric has placed one call notifications in the past.</p> <p>No PA One Call ticket. Photos show no utility mark outs. A gas meter is visible in the submitted photos which is an indication that there is gas line in the immediate area.</p> <p>Violations:</p> <p>Selsyn Electric –</p> <ul style="list-style-type: none"> <li>- Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe.</li> <li>- Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area.</li> <li>- Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.</li> </ul> <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>South Williamsport Borough –</p> <ul style="list-style-type: none"> <li>- Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike.</li> <li>- This is a warning. No penalty applied.</li> </ul> <p>Recommendation: PUC compliance training education is required.</p>	<p>Section 6.1(7) 1st Offense \$0.00</p>
54790	<p><b>Facility Owner:</b> Columbia Gas</p> <p><b>Contractor/Excavator:</b> W.A. Petrakis Contracting</p> <p><b>Project Owner:</b> Pennsylvania American Water</p> <p><b>Designer:</b> Pennsylvania American Water - Placeholder</p>	<p><u>On 5/5/2025 9:00:00 AM at PARY STREET, BRENTWOOD BORO, ALLEGHENY</u> The incident occurred on 5/5/2025 at 9:00 AM, on Pary Street, in Brentwood Boro, Allegheny County.</p> <p>A gas line owned by Columbia Gas Of Pa was damaged. 911 was called. The facility was notified of the damage.</p> <p>Columbia Gas Of PA is the facility owner. Their Alleged Violation Report (AVR) states, “WA Petrakis Contracting, working on behalf of PA Water, damaged a 1" company-side plastic gas service line while excavating for a water line installation project. Emergency services, including 911 and Columbia Gas, were promptly notified and responded to the scene. Upon investigation, it was determined that the duplex property had two gas services located in close proximity. During excavation, WA Petrakis exposed an abandoned</p>	<p><b>W.A. Petrakis Contracting: \$500.00</b> Section 5(4) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>steel gas line within the tolerance zone of the locate marks. Believing this to be the only service, excavation continued. However, a live plastic gas service line—located outside the tolerance zone of the original locate marks—was subsequently damaged. The locate marks had indicated a plastic service line, and upon exposing a steel line instead, WA Petrakis failed to renotify Columbia Gas as required. A renotification should have been initiated at the time the steel line was exposed, given the discrepancy between the marked material and the field conditions.”</p> <p>W A Petrakis is the excavator. Their AVR has no summary.</p> <p>Pennsylvania American Water is the project owner and designer. Their AVR states, “Petrakis while digging to lay new water main hit and damaged a 1" plastic service line belonging to Columbia Gas. Petrakis vacuum excavated and located to steel service lines but the markings on the ground appear to indicate plastic. Petrakis failed to re-notify for additional information and failed to vac 18" on both sides of the marks.”</p> <p>Images submitted by all stakeholders show the damage was within the tolerance zone of the yellow marks for 1” plastic using a hit kit with pylons.</p> <p>Violations: Excavator - W A Petrakis: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation:PUC Online Compliance Training is required.</p>	
54824	<p><b>Facility Owner:</b> PECO <b>Contractor/Excavator:</b> Green Tree Group Contracting LLC <b>Project Owner:</b> Green Tree Group Contracting LLC - placeholder</p>	<p><u>On 5/5/2025 9:00:00 AM at VINCENT RD, TREDYFFRIN TWP, CHESTER</u> The incident occurred on 5/5/2025 at 12:00 AM, on 115 Vincent Rd, in Tredyffrin Twp, Chester County.</p> <p>An electric line owned by Peco was damaged. The facility was not notified of the damage.</p> <p>PECO is the facility owner. Their Alleged Violation Report (AVR) states, “Contractor Green Tree Group Contracting LLC was working without a PA One Call and damaged the underground primary.”</p> <p>Green Tree Group Contracting LLC is the excavator and project owner, according to their AVR. Their AVR states, “Contractor was installing a mail box post and didn't expect to be at the depth of the electric line”. Their AVR indicates the excavation method was hand-tools.</p> <p>Green Tree Group included Ticket#20243410703 on their AVR, but this Ticket is not relevant to the incident as it was entered by excavator JOSEPH W DAVIS INC on 12/6/24 and states, “INSTALLING FOUNDATIONS FOR NEW HOMES”.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>There is a damage report submitted by PECO, as well as 2 photos submitted by Green Tree Group. No evidence is provided to show what method of excavation was used which caused damage. The images provided do not indicate that mechanized equipment was used.</p>	
54792	<p><b>Facility Owner:</b> UGI  <b>Contractor/Excavator:</b> Peachey Landscape, Inc.</p>	<p><u>On 5/5/2025 12:24:00 PM at 110 Rodney Ln, HAMPDEN TWP, CUMBERLAND</u> The incident occurred on 5/05/2025 at 110 Rodney Ln. in Hampden Township in Cumberland County.</p> <p>A gas line was damaged. No One Call ticket was submitted for this work.</p> <p>UGI UTILITIES INC stated in their Alleged Violation Report (AVR) that “Peachey Landscaping, Inc. was digging to replace a sidewalk without a PA One Call ticket. They struck and damaged an unmarked gas service with mini excavator”. 911 was notified. Pictures were provided.</p> <p>Compliance Research Results: Contractor has placed One Call notifications with PA One Call in the past.</p> <p>Peachey Landscaping, Inc. AVR was due by 6/05/2025. No AVR has been received as of 6/25/2025.</p> <p>Project owner was not provided.</p> <p><b>VIOLATIONS</b>  Peachey Landscaping, Inc. is in violation of:  Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe.  Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or damaging a facility owner’s line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.  Recommendation: The penalties are applied.  Compliance Education has not been taken as of 6/25/2025 but is due by 8/10/2025.</p>	<p><b>Peachey Landscape, Inc.:</b>  <b>\$2,000.00</b>  Section 5(2.1) 1st Offense  \$1,000.00</p> <p>Section 5(16) 1st Offense  \$1,000.00</p>
54779	<p><b>Facility Owner:</b> PPL ELECTRIC UTILITIES CORPORATION  <b>Contractor/Excavator:</b> European Builders  <b>Project Owner:</b> European Builders  Placeholder20250430653</p>	<p><u>On 5/5/2025 6:04:00 PM at 2829 WIMBLEDON LN, EAST HEMPFIELD TWP, LANCASTER</u> Incident occurred May 5th, 2025, at 6:04pm, 2829 Wimbledon Lane, East Hempfield Township, Lancaster County.</p> <p>An electric line was damaged.</p> <p>PPL Electric's Alleged Violation Report (AVR) states, "On Monday May 6th, 2025, at 6:04 pm a non-PPL contractor (European Builders) we're installing in-law's quarters when they struck and damaged a marked electric service going to the home. No one was hurt or injured but the home at 2829 Wimbledon Lane did lose power, PPL was called and when our first responders arrived at the site, they were able to make the area safe and begin their repair. Contractor European builders did have a PA 1 call, but it was from February. PPL we're able to splice the service and restore power to the home no follow up work will need to be done. European</p>	<p><b>European Builders:</b>  <b>\$2,000.00</b>  Section 5(3) 1st Offense  \$500.00</p> <p>Section 5(4) 1st Offense  \$500.00</p> <p>Section 5(16) 1st Offense  \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>builders will be held liable for the damage and repair of this line."</p> <p>Pictures from PPL show that the line was marked within the tolerance zone in February on ticket 20250430653.</p> <p>No AVR has been submitted by European Builders as of 6/27/25.</p> <p>Violations:</p> <p>European Builders  Section 5(3) – Excavator failed to preserve mark-outs or request a remark.  Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.  Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation.</p>	
54811	<p><b>Facility Owner:</b> West Penn Power / First Energy  <b>Contractor/Excavator:</b> JR CONTRACTING, LLC  <b>Project Owner:</b> PENNSYLVANIA AMERICAN WATER  <b>Designer:</b> PENNSYLVANIA AMERICAN WATER - SPACESAVER  <b>Other:</b> COMCAST</p>	<p><u>On 5/6/2025 8:43:00 AM at 6516 QUAKER DRIVE, SOUTH PARK TWP, ALLEGHENY</u> The incident occurred on 5/06/2025 at 6516 Quaker Dr., in South Park Township in Allegheny County.</p> <p>An Electric line was damaged.</p> <p>J R CONTRACTING the excavator stated in their Alleged Violation Report (AVR) that “JR CONTRACTING, LLC COMPLETED AND EXERCISED DUE CARE AND EMPLOYED PRUDENT EXCAVATION TECHNIQUES. WHILE EXCAVATING IN THE PUBLIC STREET IN FRONT OF 6516 QUAKER DRIVE, JR CONTRACTING STRUCK AND DAMAGED AN UNMARKED ELECTRIC CABLE INSIDE OF 3 INCH BLACK POLY CASING. THERE WERE NO MARKINGS MADE BY USIC IN THE AREA INDICATING AN ELECTRIC FACILITY WAS CROSSING THE ROAD IN THIS AREA. USIC LOCATOR ERIC HASIS ARRIVED ONSITE AND CONFIRMED THAT THE UTILITY WAS NOT MARKED. THE DAMAGED FACILITY WAS LOCATED AT A DEPTH OF 21 INCHES FROM THE SURFACE. WEST PENN POWER TECHNICIAN NATHAN TARR ARRIVED ONSITE APPROXIMATELY 9:30AM AND CONFIRMED THE DAMAGED LINE WAS A WEST PENN POWER FACILITY. NATHAN TARR WAS ABLE TO RESTORE POWER TO THE AFFECTED CUSTOMERS BY BYPASSING THE DAMAGED AREA. A THIRD PARTY REPAIR CREW ARRIVED ONSITE AT APPROXIMATELY 12:00PM TO BEGIN REPAIRING THE CONDUIT/CASING. THE REPAIR CREW LEFT SITE AT 2:00PM AFTER REPAIRING THE CONDUIT/CASING AND STATED A NEW WIRE WOULD BE PULLED WITHIN THE NEXT 2 DAYS. JRC SUPERVISOR SEAN DOUGLAS NOTIFIED PA ONE CALL AND WAS ISSUED DAMAGE TICKET NUMBER 20251262089. NOTE: March 25, 2025 USIC-ERIC HASIS STATED TO LEE COOPER-JR CONTRACTING ALL LINES ARE</p>	<p><b>West Penn Power / First Energy: \$3,500.00</b>  Section 2(10) 2nd Offense \$1,500.00</p> <p>Section 2(5)(viii) 2nd Offense \$1,000.00</p> <p>Section 2(5)(i) 1st Offense \$500.00</p> <p>Section 2(5)(i.1) 1st Offense \$250.00</p> <p>Section 2(5)(i.2) 1st Offense \$250.00</p> <p><b>COMCAST: \$500.00</b>  Section 2(5)(viii) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>LOCATED ON QUAKER”. Pictures were provided. On 6/25/2025 DPI Maki sent an email to J R CONTRACTING asking about the complex Project attendees. J R CONTRACTING responded quickly that Comcast, West Penn Power/First Energy were not in attendance.</p> <p>PENNSYLVANIA AMERICAN WATER the project owner stated in their AVR that “JR Contracting while digging to install water main hit and damaged conduit and wire belonging to West Penn Power. USIC locates for West Penn and had marked other areas where there was underground but this was not one of those areas. On 3/25/25 the USIC locator told JR Contracting that all lines were marked”. Project is &lt;\$400,000. And 2200 feet in length. Subsurface Utility Engineering (SUE) Level “A” is listed stating “test hole/pothole”. Pictures and report were provided.</p> <p>West Penn Power the facility owner did not submit an AVR. Their AVR was due by 6/18/2025. *****</p> <p>Complex Project ticket 20250450303 meeting attendees: JR Contracting, Peoples Gas, PHA, PAWC, Verizon, South Park Township.</p> <p>Not at the meeting: West Penn Power / First Energy and Comcast. *****</p> <p>*Emergency ticket 20251232089 was submitted by J R Contracting on 5/06/2025 at 11:12. West Penn Power responded “Clear” and that they have no facilities in the area.</p> <p>*Ticket 20250830354 was submitted by J R Contracting on 3/24/2025 with a response due by 3/26/2025. Requesting house numbers 6520 to the end of the cul-de-sac.</p> <p>West Penn Power scheduled marked on 3/26/2025 and field marked on 3/27/2025.</p> <p><b>VIOLATIONS</b></p> <p>West Penn Power / First Energy is in violation of:</p> <p>Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. This is a second offense.</p> <p>Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). This is a second offense.</p> <p>Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.</p> <p>Section 2(5)(i.1) – Failed to locate an actually known facility’s point of connection to its facilities.</p> <p>Section 2(5)(i.2) – Failed to document Communications between a Facility Owner and Excavator to ensure the</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>excavator is aware of a facility owner’s inability to locate it’s facilities.  Recommendation: The penalties are applied. PUC Compliance education is required.</p> <p>COMCAST is in violation of:  Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3).  Recommendation: The penalty is applied. PUC Compliance education was recently completed.</p>	
54986	<p><b>Facility Owner:</b> Greater Johnstown Water Auth - RDM Johnstown LLC  <b>Contractor/Excavator:</b> Peoples Natural Gas  <b>Project Owner:</b> Peoples Natural Gas (Placeholder)</p>	<p><u>On 5/6/2025 1:00:00 PM at 306 WARREN ST, UPPER YODER TWP, CAMBRIA</u> Peoples Gas accepts.  *****</p> <p>The incident occurred on 05/06/2025 at 1:00 PM, at 306 Warren Street, in Upper Yoder Township, Cambria County.</p> <p>A water line owned by Greater Johnstown Water Authority was damaged.</p> <p>RDM JOHNSTOWN LLC represents Greater Johnstown Water Authority, the facility owner. An Alleged Violation Report (AVR) was submitted. Their AVR states, “Peoples Natural Gas was installing a new gas service line for 304 &amp; 306 Warren St when they hit and damaged a lead service line. The line was accurately marked. From the main to the valve box shown in one of the photos. From the time of the damage notification from Peoples to the time of the repair lasted approximately 1.75 hours. GJWA will be directly billing PNG for the material and labor to repair the line. No customer was without water as the structure is currently not-occupied.” It was noted on the AVR that the service line was marked using an electronic locating tool that was connected to the curb stop and transmitted signal along service line. Photos were submitted.</p> <p>Peoples Natural Gas was the excavator and project owner. An AVR has not been filed as of 06/26/2025.</p> <p>The submitted photos show the water line marked out in blue paint. The line was damaged within the tolerance zone.</p> <p>Final Design ticket 20250792366 had a response due date of 04/03/2025.  - Greater Johnstown Water Authority did not respond to this ticket.</p> <p>Violations:</p> <p>Peoples Natural Gas-  - Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.  - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been</p>	<p><b>Greater Johnstown Water Auth - RDM Johnstown LLC: \$250.00</b>  Section 2(4) 1st Offense \$250.00</p> <p><b>Peoples Natural Gas: \$2,000.00</b>  Section 5(4) 2nd Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>committed in association with excavation or demolition work.  Recommendation: The penalty is applied. PUC compliance training education was recently completed.</p> <p>Greater Johnstown Water Authority -  - Section 2(4) – Failed to respond to designer’s request for information within 10 business days. Ticket 20250792366.  Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
54822	<p><b>Facility Owner:</b> PECO AN EXELON COMPANY  <b>Contractor/Excavator:</b> KBC CONSTRUCTION LLC  <b>Project Owner:</b> HATFIELD BORO  <b>Designer:</b> BURSICH ASSOCIATES INC  <b>Other:</b> Verizon PA, LLC</p>	<p><u>On 5/8/2025 9:00:00 AM at 56 E BROAD ST, HATFIELD BORO, MONTGOMERY</u> The incident occurred on Thursday, May 8, 2025, at 56 E. Broad Street, in Hatfield Borough, Montgomery County.</p> <p>A gas line was damaged.</p> <p>PECO an Exelon Company, stated in their Alleged Violation Report (AVR), KBC Construction LLC was excavating with an excavator to install Storm Sewer when they severed the 1/2" plastic gas service 8' from the gas mark out, it was found that at the time of the locate the locator did not use all available measurements that are provided on the Gas services cards and the GFR sketch resulting in the gas being mis marked by 8'. PECO provided photos of the mis-marked gas line.</p> <p>Hatfield Borough, the project owner stated in their AVR, KBC Construction damaged a 3/4" gas service line that was not marked correctly while they were excavating to install new storm sewer pipe. The mark that was there was close to 8' away from where the line was hit. KBC Construction LLC submitted an AVR, but no summary provided. The AVR Mentioned a Facility Owner issue as, Marked Incorrectly.</p> <p>20251041060- Routine ticket placed on 4/14/2025, with a response due date of 4/16/2025, a Late Response from Verizon PA LLC on 4/21/2025, as Field Marked.</p> <p>Violations:</p> <p>*PECO An Exelon Company is in violation of section: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.  Recommendation: Penalty Applied</p> <p>*Verizon PA LLC is in violation of section: 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. 20251041060  Recommendation: Penalty Applied</p>	<p><b>PECO AN EXELON COMPANY: \$1,000.00</b>  Section 2(5)(i) 2nd Offense \$1,000.00</p> <p><b>Verizon PA, LLC: \$1,000.00</b>  Section 2(5)(v) Subsequent \$1,000.00</p>
54840	<p><b>Facility Owner:</b> Peoples Gas Company  <b>Contractor/Excavator:</b> Municipal Authority of Westmoreland County  <b>Project Owner:</b> MAWC Placeholder</p>	<p><u>On 5/8/2025 10:00:00 AM at 4002 WELLINGTON CT, PENN TWP, WESTMORELAND</u> Incident occurred on May 8th, 2025, at 10am on 4002 Wellington Court, Penn Township, Westmoreland County.</p> <p>A gas line was damaged.</p> <p>Peoples Gas Company's Alleged Violation Report (AVR) states, "ON 5/8/25 AT 10:24 MAWC</p>	<p><b>Municipal Authority of Westmoreland County: \$500.00</b>  Section 5(4) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>WORKING TO INSTALL TAP, STRUCK A MARKED PNG 4INCH PLASTIC MAIN LINE. MAWC FAILED TO DIG PRUDENTLY IN THE TOLERANCE ZONE. MAWC NOTFIED 911 AND PNG OR DAMAGE. PNG CREWS ARRIVED ONSITE AND SQUEEZED OFF PLASTIC MAIN LINE PUTTING 28 CUSTOMERS OUT OF GAS TO MAKE SITE SAFE. PNG MAKING REPAIRS AND RELIGHTING CUSTOMERS."</p> <p>Municipal Authority of Westmoreland County's AVR states, "Project Owner and Excavator, Municipal Authority of Westmoreland County was excavating to install a new water service at 3001 Wellington Ct. MAWC backhoe hit an accurately marked Peoples Gas main. MAWC called 911, and Peoples gas to make the necessary repair."</p> <p>Pictures show that the line was marked within the tolerance zone.</p> <p>Violation:</p> <p>Municipal Authority of Westmoreland County Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. PUC compliance education is required.</p>	
54909	<p><b>Facility Owner:</b> WESTMORELAND CO MUNI AUTH  <b>Contractor/Excavator:</b> S &amp; E Utility Contracting  <b>Project Owner:</b> PENN TOWNSHIP OF WESTMORELAND COUNTY  <b>Designer:</b> GIBSON THOMAS ENGINEERING CO INC</p>	<p><u>On 5/8/2025 11:00:00 AM at 12 Arbor Ct., PENN TWP, WESTMORELAND</u> The incident occurred on Thursday, May 8, 2025, at 12 Arbor Court, in Penn Township, Westmoreland County.</p> <p>A water line was damaged.</p> <p>Penn Township of Westmoreland County, the project owner, indicated in their Alleged Violation Report (AVR), an Excavator issue as, failed to use prudent techniques in the tolerance zone, and stated, the Contractor, S &amp; E Utility Contracting failed to hand dig after being told multiple times to stop the excavation and hand dig.</p> <p>Municipal Authority of Westmoreland County (MAWC) stated in their AVR, Excavator, S&amp;E Utility Contracting was working for Project Owner, Penn Township Municipal Authority, to install a new storm sewer line along Arbor Court, in Penn Township. S&amp;E struck a MAWC water service line in the vicinity of 12 Arbor Court. S&amp;E contacted MAWC directly to report the damage. The MAWC Foreman for this area was working to shut down 3 water main breaks at the time of this hit. The Foreman sent a utilityman to Arbor Court to mitigate the hit. When the utilityman arrived he cut out the damaged area of the service line and installed two fittings and 6' of new service line in the trench that S&amp;E had opened. The repair took approximately 20 mins and cost less than \$50.00. Due to the 3 emergencies that were ongoing at the time of this hit the MAWC Foreman, failed to follow MAWC internal protocol to document this incident. Further, had S&amp;E called 811 to</p>	<p><b>S &amp; E Utility Contracting: \$1,000.00</b>  Section 5(16) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>report this hit MAWC would have had proper notice and documentation of the incident. MAWC provided photos of locate marks but no damage.</p> <p>S &amp; E Utility Contracting did not submit an AVR within 30 days of striking the line. Westmoreland County Municipal Authority, the facility owner, had not submitted their AVR yet. They have 30 business days to submit an AVR. On Tuesday, June 10, 2025, emails were sent to the excavator and facility owner requesting AVR's. S &amp; E Utility Contracting did not respond to the request and their AVR was not submitted. MAWC submitted their AVR.</p> <p>Violations:</p> <p>*S &amp; E Utility Contracting is in violation of sections: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: PUC Compliance Education Required and Penalty Applied for 5(16). No penalty or violation for 5(4) because the photos provided by MAWC do not indicate the excavator failed in using prudent techniques.</p>	
54856	<p><b>Facility Owner:</b> Philadelphia Gas Works <b>Contractor/Excavator:</b> JOHN J DOUGHERTY AND SONS INC <b>Project Owner:</b> CITY OF PHILADELPHIA</p>	<p><u>On 5/8/2025 3:30:00 PM at UMBRIA ST, PHILADELPHIA CITY, PHILADELPHIA</u> The incident occurred on 5/8/2025 at 3:30 PM, on Umbria St, in Philadelphia City, Philadelphia County.</p> <p>-No Damage-</p> <p>Philadelphia Gas Works is the facility owner. Their Alleged Violation Report (AVR) states, “This is an ongoing job that did not have a pa one call for installing these curbs and sidewalks. the city of philadelphia reached out to a pgw employee looking to have someone locate the gas main. PGW has a high pressure gas man they were using power equipment over and not hand excavation. You can see from the attached photo it is dated and shows they were digging yesterday without a one call. TODAY they put in these emergency tickets. this doesn't fall under what constitutes an emergency ticket and should have not been accpeted as a ticket.” One photo was submitted of the site showing excavation at the site on 5/8/2025. No marks are visible, and no one call ticket was located for this site.</p> <p>John J Dougherty And Sons Inc is the excavator. An AVR has not been filed as of 06-27-2025.</p> <p>City Of Philadelphia is the project owner. An AVR has not been filed as of 06-27-2025.</p> <p>The (2) New – Excavation– Emergency tickets submitted on 5/9/2025 for this site indicate the following information, “CONSTRUCTION FOR NEW CURB AND SIDEWALK - WORKING APPX 400FT W ON UMBRIA ST AND APPX 300FT N ON DOMINO LN”.</p>	<p><b>JOHN J DOUGHERTY AND SONS INC:</b> <b>\$2,000.00</b> Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(22) 1st Offense \$500.00</p> <p>Section 5(22) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Act 127 of 2024 defines Emergency as, “a sudden or unforeseen occurrence involving a clear and immediate danger to life, property or the environment, including, but not limited to, serious breaks or defects in a facility owner's lines.”</p> <p>Violations:  Excavator - John J Dougherty And Sons Inc:  Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe.  Section 5(22) – Excavator provided a misrepresentation of an emergency excavation, subject to an administrative penalty imposed under section 7(10). Ticket # 20251290441  Section 5(22) – Excavator provided a misrepresentation of an emergency excavation, subject to an administrative penalty imposed under section 7(10). Ticket # 20251290456  Recommendation: PUC Online Compliance Training is required.</p>	
54870	<p><b>Facility Owner:</b> Peoples Gas Company  <b>Contractor/Excavator:</b> Cuccaro Plumbing</p>	<p><u>On 5/9/2025 9:01:00 AM at 100 BAIR BLVD, NEW STANTON BORO, WESTMORELAND</u> Incident occurred on May 9th, 2025, at 9:01am on 100 Blair Boulevard, New Stanton Boro, Westmoreland County.</p> <p>A gas line was damaged.</p> <p>Peoples Gas Company's Alleged Violation Report (AVR) states, "ON 5/9/25 AT 0901 CUCCARO PLUMBING WORKING AT 100 BAIR BLVD STRUCK CUSTOMER SIDE SERVICE LINE SEVERAL FEET FROM EXISTING METER BAR AND RISER. CUCCARO PLUMBING WAS UNABLE TO PROVIDE VALID ONECALL FOR THIS ADDRESS. SEARCHES FOR TICKETS GAVE NO RESULTS. GAS IS OFF AT CURB AND CUSTOMER SERVICE LINE WILL NEED REPAIRED/REPLACED." AVR notes that 911 was not notified.</p> <p>PA1Call commented, "Contractor has placed One Call notifications with PA One Call in the past."</p> <p>Pictures show a damaged gas line between a gas meter and backhoe.</p> <p>No AVR has been submitted by Cuccaro Plumbing as of 6/30/25.</p> <p>Violations:  Cuccaro Plumbing  Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. PUC compliance education is required.  Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid. PUC compliance education is required.</p>	<p><b>Cuccaro Plumbing:</b>  <b>\$3,000.00</b>  Section 5(2.1) 1st Offense  \$1,000.00</p> <p>Section 5(8) 1st Offense  \$1,000.00</p> <p>Section 5(16) 1st Offense  \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
54872	<p><b>Facility Owner:</b> Peoples Natural Gas  <b>Contractor/Excavator:</b> Mark Allen Plumbing  <b>Project Owner:</b> Homeowner</p>	<p>Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required.</p> <p><u>On 5/9/2025 10:26:00 AM at 396 SABBATH DR, PLEASANT HILLS BORO, ALLEGHENY</u> The incident occurred on 05/09/2025 at 10:26 AM, on 396 Sabbath Drive, In Pleasant Hills Borough, Allegheny County.</p> <p>A gas line owned by Peoples Natural Gas was damaged. 911 was not called.</p> <p>Peoples Natural Gas, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “On 5/9/25 at 10:26 Mark Allen Plumbing working to replace customer side gas service line struck PNG curb stop while jack hammering causing damage. Mark Allen Plumbing called PNG, PNG arrived onsite and made repairs.” Photos were submitted.</p> <p>Mark Allen Plumbing is the excavator. An AVR has not been filed as of 06/25/2025.</p> <p>The homeowner is the project owner. An AVR has not been filed as of 06/25/2025.</p> <p>The submitted photos show the gas line was correctly marked using yellow paint. The curb stop is visible and aligns with the yellow markings. The gas line was damaged within the tolerance zone.</p> <p>Peoples Natural Gas AVR did not indicate that 911 was called. The submitted photos show no indication that 911 was called. Act 127 of 2024 states that it is the excavator’s responsibility to immediately notify 911 and the facility owner if the damage results in the escape of any flammable, toxic or corrosive gas or liquid.</p> <p>Violations:</p> <p>Mark Allen Plumbing –</p> <ul style="list-style-type: none"> <li>- Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.</li> <li>- Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property.</li> <li>- Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.</li> </ul> <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p>	<p><b>Mark Allen Plumbing:</b>  <b>\$2,500.00</b>  Section 5(4) 1st Offense  \$500.00</p> <p>Section 5(8) 1st Offense  \$1,000.00</p> <p>Section 5(16) 1st Offense  \$1,000.00</p>
54937	<p><b>Facility Owner:</b> PECO AN EXELON COMPANY  <b>Contractor/Excavator:</b> ROTO ROOTER</p>	<p><u>On 5/12/2025 12:00:00 AM at 515 SABINE CIR, LOWER MERION TWP, MONTGOMERY</u> The incident occurred on Monday, May 12, 2025, at 515 Sabine Circle, in Lower Merion Township, Montgomery County.</p>	<p><b>ROTO ROOTER SERVICE CORPORATION:</b>  <b>\$1,500.00</b>  Section 5(4) 1st Offense</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	SERVICE CORPORATION	<p>A gas line was damaged</p> <p>PECO An Exelon Company stated in their Alleged Violation Report (AVR), Roto Rooter Service Corp was excavating with a Mini excavator to make repairs to the drainage under ticket number 20251320035 when they severed the correctly marked 1" plastic gas service, it was found that Roto Rooter Service Corp did not expose the correctly marked gas service prior to crossing over it with the excavator, resulting in the 1" plastic gas service being damage and in need of repair. PECO provided photos.</p> <p>Roto Rooter Service Corp. did not submit an AVR within 30 days of the line strike.</p> <p>Violations:</p> <p>*Roto Rooter Service Corporation is in violation of sections:  5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.  5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line.  Recommendation: PUC Compliance Education Required and Penalties Applied.</p>	<p>\$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>
54952	<p><b>Facility Owner:</b> Peoples Gas Company  <b>Contractor/Excavator:</b> PIONEER CONSTRUCTION CO INC  <b>Project Owner:</b> Pennsylvania American Water Company (PAWC)</p>	<p><u>On 5/12/2025 10:00:00 AM at 830 N WEBSTER AVE, SCRANTON CITY, LACKAWANNA</u> Incident occurred on May 12th, 2025, at 10am on 830 North Webster Avenue, Scranton City, Lackawanna County.</p> <p>Damage Prevention Investigator's findings:  An accurately marked gas line was damaged while digging with powered machinery within the tolerance zone. Both related cases, 55414 &amp; 55843, have AVRs from Pioneer that state rocks damaged the gas lines while utilizing an excavator.</p> <p>UGI's Alleged Violation Report (AVR) states, "Excavator struck and damaged a correctly marked gas facility while digging in the tolerance zone."</p> <p>Pioneer Construction Co Inc's AVR states:  • Pioneer Operator was removing blacktop to install a new 8'' watermain when the blacktop fell and struck the exposed gas service, damaging it. Work was immediately stopped and 911 and UGI called.  • The ½'' Gas service was for house #830 N Webster Ave Scranton, PA 18510. It was approximately 18'' deep and was previously potholed by Pioneer Vac Truck.  • This incident happened at approximately 9:57 am.  • Witnesses included operators, laborers, and Supervision.</p> <p>PAWC's AVR states, "While excavating for water main replacement project on N Webster Ave, Scranton the contractor removed a piece of blacktop from the trench. While doing so the operator caught the 1" inserted with 1/2" plastic gas service for #830 N Webster Ave</p>	<p><b>PIONEER CONSTRUCTION CO INC: \$1,000.00</b>  Section 5(4) 1st Offense \$500.00</p> <p>Section 5(6)(ii) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>breaking the service. 911 was called by the foreman on site and both emergency services and UGI responded in a timely manner to repair the gas service."</p> <p>Pictures show that the excavator was digging in the tolerance zone of the accurately marked gas line.</p> <p>Violations:</p> <p>Pioneer Construction Co Inc. Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. PUC compliance education is required. Section 5(6)(ii) – Excavator failed to provide support and mechanical protection for known facility owner’s lines at the construction work site. PUC compliance education is required.</p>	
55015	<p><b>Facility Owner:</b> Peoples Natural Gas <b>Contractor/Excavator:</b> WILSON EXCAVATING AND UTILITY CONSTRUCTION LLC <b>Project Owner:</b> Pennsylvania American Water (PAWC) <b>Designer:</b> Pennsylvania American Water (PAWC) - Placeholder</p>	<p><u>On 5/14/2025 10:00:00 AM at 9TH STREET, GLASSPORT BORO, ALLEGHENY</u> Peoples Gas - Reduced 2(5)(v) from \$250 to \$0. Education required. Wilson Excavating - Withdraw Violation - Section 5(19) – Excavator failed to provide accurate information to the One Call System. ***** The incident occurred on 5/14/2025 at 10:00 AM, 9th Street in Glassport, PA Allegheny.</p> <p>A gas line owned by Peoples Gas was damaged.</p> <p>Peoples Gas is the facility owner. Their Alleged Violation Report (AVR) states, “ON 5/14/25 WILSON WORKING FOR PA AMERICAN WATER STRUCK UNMARKED PNG GAS SERVICE LINE TO 210 9TH ST IN GLASSPORT. PNG SERVICE LINE WAS ABANDONED AT THE CURB AND WAS DAMAGED BETWEEN MAIN AND CURB. WILSON CONTACTED PNG AND PNG ARRIVED ONSITE AND CUT OFF SERVICE NEAR THE MAIN.”</p> <p>Wilson Excavating And Utility Construction LLC is the excavator. Their AVR states, “Wilson Excavating was performing work for PAWC near 210 9th Street in Glassport, PA when an unmarked Peoples Gas line was struck and damaged. The crew was excavating for water main installation when the line was struck with the excavator. The line was not marked. 911 was called and the facility owner was notified.” Wilson Excavating indicated an incorrect address and county in their AVR. Wilson Excavating was contacted to update their AVR and provide valid and correct information. The AVR was not updated, nor was a response received back from Wilson Excavating.</p> <p>PA American Water Company is the project owner and designer. Their AVR states, “Wilson Excavating was performing work for PA American Water Company near 210 9th St when they struck an unmarked gas service. 911 was called”</p>	<p><b>Peoples Natural Gas:</b> <b>\$500.00</b> Section 2(5)(i) 1st Offense \$500.00 Section 2(5)(v) 1st Offense \$0.00</p> <p><b>WILSON EXCAVATING AND UTILITY CONSTRUCTION LLC:</b> <b>\$0.00</b></p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Multiple photos of the site, location, and damage were submitted. There are no marks within the area of the excavation where the damage occurred.</p> <p>Ticket # 20251222003 had a response due date of 5/7/2025. Peoples Gas Company responded “Field Marked” on 5/8/2025.</p> <p>Ticket #20251222000 was included on Wilson Excavating’s AVR but is not relevant to this case, nor is it a Ticket that Wilson Excavating, or any other stakeholder on this case created.</p> <p>Violations:  Facility – Peoples Gas  Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.  Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time.  Ticket # 20251222003  Recommendation: PUC Online Compliance Training was recently completed.</p> <p>Excavator – Wilson Excavating:  Section 5(19) – Excavator failed to provide accurate information to the One Call System.  Recommendation: PUC Online Compliance Training is required.</p>	
55414	<p><b>Facility Owner:</b> UGI UTILITIES INC  <b>Contractor/Excavator:</b> PIONEER CONSTRUCTION CO INC  <b>Project Owner:</b> PENNSYLVANIA AMERICAN WATER  <b>Other:</b> Dunmore Borough</p>	<p><u>On 5/15/2025 9:50:00 AM at 936 N WEBSTER AVE, SCRANTON CITY, LACKAWANNA</u> The incident occurred on Thursday, May 15, 2025, at 936 N. Webster Avenue, in Scranton City, Lackawanna County.</p> <p>A gas line was damaged.</p> <p>UGI Utilities stated in their Alleged Violation Report (AVR), Excavator, Pioneer Construction, struck and damaged a correctly marked gas facility while digging within the tolerance zone.</p> <p>Pioneer Construction stated in their AVR, the operator was removing rock with a buster to install a new 8-inch watermain when the buster caught a rock and struck the gas service, damaging it. The crew had hand dug as much as possible to limit the damage, unfortunately the rock could not be removed without the use of heavy equipment. This line was put in place by a “bullet”, meaning it was installed using directional drilling, so the service line was completely incased in rock. The ½” Gas service was for 936 N. Webster Avenue. It was approximately 18-inches deep and was previously potholed by Pioneer Vac Truck. Unfortunately, there is no other way for the removal of rock in a trench line. The crew worked very slowly and with due care but that still didn’t stop them from catching the service with a rock.</p>	<p><b>PIONEER CONSTRUCTION CO INC: \$500.00</b>  Section 5(4) 1st Offense \$500.00</p> <p><b>Dunmore Borough: \$1,000.00</b>  Section 2(5)(viii) 2nd Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>PA American Water Company (PAWC) stated in their AVR, on 5-15-25 Pioneer struck a 1/2-inch plastic gas service to 936 N. Webster Avenue while busting rock to install new water main under gas service at proper depth. While busting rock underneath service, rock popped upwards and broke the plastic gas service. UGI came to repair service. No evacuations were necessary.</p> <p>20250771474- Complex Project Meeting ticket was placed on 3/18/2025. No Response from- Dunmore Borough.</p> <p>Violations:</p> <p>*Pioneer Construction is in violation of section: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: PUC Compliance Education Required and Penalty Applied.</p> <p>*Dunmore Borough is in violation of section: 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project. 20250771474 Recommendation: Penalty Applied</p>	
55115	<p><b>Facility Owner:</b> Armstrong</p> <p><b>Contractor/Excavator:</b> National Fuel Gas Distribution</p> <p><b>Project Owner:</b> National Fuel Gas Distribution - Placeholder</p>	<p><u>On 5/15/2025 10:00:00 AM at 23547 STATE HIGHWAY 77, EAST MEAD TWP, CRAWFORD</u> The incident occurred on 5/15/2025 at 10:00 AM, on 23547 State Highway 77, in East Mead Twp, Crawford County.</p> <p>A communication line owned by Armstrong was damaged.</p> <p>Armstrong is the facility owner. An Alleged Violation Report (AVR) has not been filed as of 7-10-2025</p> <p>National Fuel is the excavator, and project owner. Their AVR states, “National Fuel struck an unmarked Armstrong Communications service while renewing a natural gas distribution service. There was no indication that there was a communications line prior to the commencement of the excavation. Armstrong advised that they were not notified of the original POCS ticket. Please see attachment.” One image submitted with the AVR shows the damage and no marks visible.</p> <p>Ticket# 20251353964 states, “CALLER STATES AN UNMARKED COMMUNICATIONS LINE WAS DAMAGED WITH MINI EXCAVATOR. IN A 2FT WIDE HOLE. SPECIAL ATTN ARMSTRONG CUSTOMER IS WITHOUT SERVICE. FACILITY TYPE: TELECOM-ARMSTRONG EXCAVATION EQUIPMENT:”</p> <p>On both Tickets placed for this site, Armstrong was not listed as a Facility for notifications. Armstrong was aware of this damage as indicated in National Fuel's AVR, as well as Ticket#20251353964 which states an Armstrong customer lost service after damage occurred.</p> <p>Violations:</p>	<p><b>Armstrong: \$1,750.00</b> Section 2(1)(ii)(A) 1st Offense \$250.00</p> <p>Section 2(10) 2nd Offense \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Facility – Armstrong</p> <p>Section 2(1)(ii)(A) – Failed to provide the One Call System with the counties, municipalities, and wards in which it lines are located.</p> <p>Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work.</p> <p>Recommendation: PUC Online Compliance Training was recently completed.</p>	
55540	<p><b>Facility Owner:</b> UGI Utilities Inc</p> <p><b>Contractor/Excavator:</b> WESTYS PROPERTY SERVICES</p> <p><b>Project Owner:</b> WESTYS PROPERTY SERVICES - SPACESAVER</p> <p><b>Other:</b> FIRSTLIGHT FIBER LLC</p> <p><b>Other:</b> PPL ELECTRIC UTILITIES CORPORATION</p>	<p><u>On 5/19/2025 12:38:00 PM at GREGG STREET, SHILLINGTON BORO, BERKS</u> PPL disagreed. PPL accepted the 2(5)(v) violation but asked that the 2(5)(v.2) violation be given as a warning. The \$250. penalty has been reduced to a warning.</p> <p>*****</p> <p>The incident occurred on 5/19/2025 on Gregg St in SHILLINGTON BORO I Berks County.</p> <p>A gas line owned by UGI was damaged.</p> <p>UGI UTILITIES INC the facility owner stated in their Alleged Violation Report (AVR) that Excavator utilizing mechanized equipment struck a correctly marked gas service. Pictures and reports were provided.</p> <p>WESTYS PROPERTY SERVICES the excavator and the property owner did not submit an AVR as of 7/03/2025. AVR was due by 6/18/2025.</p> <p><b>VIOLATIONS</b></p> <p>WESTYS PROPERTY SERVICES is in violation of:</p> <p>Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.</p> <p>Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or damaging a facility owner’s line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.</p> <p>Recommendation: The penalties are applied. Compliance Education is required.</p> <p>PPL ELECTRIC UTILITIES CORPORATION is in violation of:</p> <p>Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket 20251263598 was submitted by WESTYS PROPERTY SERVICES on 5/06/2025 with a response due by 5/11/2025. PPL did not respond until on 5/12/2025 when they responded with Not-Marked. No Access, which is not a final response.</p> <p>Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20251263598 was submitted by WESTYS PROPERTY SERVICES on 5/06/2025 with a response due by 5/11/2025. PPL did not respond until on 5/12/2025 they responded with Not-Marked. No Access.</p>	<p><b>WESTYS PROPERTY SERVICES: \$1,500.00</b></p> <p>Section 5(4) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p><b>FIRSTLIGHT FIBER LLC: \$750.00</b></p> <p>Section 2(5)(v) 2nd offense \$500.00</p> <p>Section 9 1st Offense \$250.00</p> <p><b>PPL ELECTRIC UTILITIES CORPORATION: \$500.00</b></p> <p>Section 2(5)(v) 2nd offense \$500.00</p> <p>Section 2(5)(v.2) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Recommendation: The penalties are applied. Compliance Education was recently completed.</p> <p>FIRSTLIGHT FIBER LLC is in violation of:            Section 2(5)(v) – Failed to respond to a routine One Call ticket 20251263598 within the required amount of time. Ticket 20251263598 was submitted by WESTYS PROPERTY SERVICES on 5/06/2025 with a response due by 5/11/2025. Firstlight Fiber had no response until they responded “Clear” on 5/12/2025.            This is a second offense violation.            Section 9 – Failed to make best efforts to comply with the Common Ground Alliance Best Practices Chapter 7(1)(B) Mandatory Education is considered as an alternative or supplement to penalties for offenders of the damage prevention laws and regulations. Firstlight Fiber has not completed the education requirement since 8/07/2023.            Recommendation: The penalties are applied. Compliance Education is required.</p>	
55288	<p><b>Facility Owner:</b> Peoples Gas  <b>Contractor/Excavator:</b> A. Liberoni, Inc.  <b>Project Owner:</b> Pittsburgh Department of Mobility and Infrastructure  <b>Designer:</b> MICHAEL BAKER CORPORATION INC</p>	<p><u>On 5/19/2025 1:00:00 PM at SYLVAN AVE, PITTSBURGH CITY, ALLEGHENY</u> The incident occurred on 5/19/2025 at 1:00 PM, on Sylvan Ave, in Pittsburgh City, Allegheny County.</p> <p>A gas line owned by Peoples Gas Company LLC was damaged. 911 was contacted.</p> <p>Peoples Gas Company LLC is the facility owner. Their Alleged Violation Report (AVR) states, “A Liberoni was using mechanized equipment for roadway reconstruction and struck and damaged a 2 inch blow off on an 8 inch steel pressured gas line causing a damage. This project was field walked with a Peoples Gas Damage Prevention supervisor, the on site foreman for A Liberoni, Pittsburgh Department of Mobility and Infrastructure, and the engineering firm for the job approximately 3 weeks prior to the damage. This particular area has multiple Peoples Gas valves, blow offs and locate wire boxes within the planned excavation area. When this damage was reported, it was called that same Damage Prevention supervisor at Peoples. The damage was reported as damage to a gate box, not a damage to a line with gas blowing with approximately 45 PSIG. 911 was on scene, but the caller is not known. As shown in the pictures, Peoples Gas marked all the lines within the area and the exposed facilities. According to the Peoples Gas first responders to this incident, A Liberoni has also painted the exposed facilities in pink as a warning to their on site crews.”</p> <p>A. Liberoni is the excavator. Their AVR states, “Damaged gas square valve box was an unmarked gas box that was buried 3 inches under the asphalt. This gas valve box had been buried since at least 2007 according to google maps. A utility meeting was held on site with Peoples Gas before work began.”</p> <p>City of Pittsburgh is the project owner. Their AVR, which was submitted by Mackin Engineering states,</p>	<p><b>A. Liberoni, Inc.:</b>  <b>\$1,500.00</b>            Section 5(3) 1st Offense            \$500.00</p> <p>Section 5(4) 2nd Offense            \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>“The contractor's crew was working in the area of the gas line leak. They were not excavating in that area at the time but doing roadwork. No one from our inspection team witnessed the damage occur but we assume a valve box was hit at ground level during their work operations.”</p> <p>Michael Baker Corporation Inc is the designer. Their AVR states, “It is assumed that the contractor's crew hit a valve box at ground level during roadway work operations.”</p> <p>PGC and A.Liberoni submitted multiple photos of the location. PGC provided an image of when they marked out on 4/24/2025 under Ticket#20251120710. No update to Ticket#20251120710 was located by PA One Call, and no other Tickets include this area to be marked. The photos of when the damage occurred do not show marks on the road surface, though marks are still visible on the sidewalks. The damage is located within the tolerance zone of the marks that are shown in the PGC photos from 4/24/2025.</p> <p>Case#055288 is related to Case#050570 by Ticket#20232013477</p> <p>Violations:</p> <p>Excavator - A Liberoni:  Section 5(3) – Excavator failed to preserve mark-outs or request a remark.  Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.  Recommendation: PUC Online Compliance Training is required.</p>	
55230	<p><b>Facility Owner:</b> PEOPLES GAS COMPANY LLC</p> <p><b>Contractor/Excavator:</b> N &amp; N LANDSCAPING</p> <p><b>Project Owner:</b> Oakmont Borough</p>	<p><u>On 5/19/2025 1:30:00 PM at 510 8TH ST, OAKMONT BORO, ALLEGHENY</u> The incident occurred on Monday, May 19, 2025, at 510 8th Street, in Oakmont Borough, Allegheny County.</p> <p>A gas line was damaged.</p> <p>Peoples Gas Company stated in their Alleged Violation Report (AVR), N &amp; N Landscaping working for Oakmont Borough struck and damaged a Peoples Gas service line. This project was last called in for an update on 4-17-2025. This is the second Peoples Gas service line that the contractor has hit on this project, the first being on 4-24-2025. N &amp; N Landscaping working for Oakmont Borough to do brick road restoration struck and damaged a properly marked Peoples Gas service line. N &amp; N Landscaping did not call in to 811, or 911 to report the damage. The gas was off by a flow limiter after the damage.</p> <p>Peoples Gas provided photos of the damaged line  Additional information sent from Peoples Gas:  "After speaking with the local Damage Prevention Supervisor, N and N Landscaping failed to place a complex project meeting for the multiple tickets placed for street repair in Oakmont since starting the project in</p>	<p><b>N &amp; N LANDSCAPING:</b>  <b>\$3,500.00</b>  Section 5(7) 1st Offense  \$1,000.00</p> <p>Section 5(8) 1st Offense  \$1,000.00</p> <p>Section 5(16) 1st Offense  \$1,000.00</p> <p>Section 5(4) 1st Offense  \$500.00</p> <p><b>Oakmont Borough:</b>  <b>\$1,000.00</b>  Section 6.1(7) 1st Offense  \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>2024. The first responder could not locate the PA One Call placed by N and N Landscaping, and had root caused the damage as no current one call because all he could see was the two bricks with a partial yellow marking. The Supervisor had to try and determine the distance from the damage and the marking because the first responder did not actually place the "damage" placard where the damage occurred. He had placed it where there was solid ground thinking N and N Landscaping did not have a legal PA One Call. His supervisor has retrained him on setting the damage and marker placard exactly where each is regardless if he locates an active PA One Call Ticket. N and N Landscaping failed to notify 811 and 911 when this damage occurred. There was a release of gas when the initial damage occurred, and then the EFV worked and shut the gas off."</p> <p>N &amp; N Landscaping did not submit an AVR within 30 days of striking the gas line. Oakmont Borough did not submit an AVR within 30 days of the gas line strike.</p> <p>20251074352- Routine update ticket placed on 4/17/2025, with Scheduled Excavation date as 4/22/25, and Lawful Start Dates as 4/22/25 - 5/1/25. Remark- REASON FOR UPDATE: WORK NOT STARTED, REMARK LINES. The duration of the excavation was expected to be 1 month which includes May 19, 2025.</p> <p>Violations:</p> <p>*N &amp; N Landscaping is in violation of sections: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. 5(7) – Failed to immediately report to the facility owner any break or leak in its lines, or any dent, gouge, groove, or other damage to such lines or to their coating or cathodic protection. 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: PUC Compliance Education Required and Penalties Applied.</p> <p>*Oakmont Borough is in violation of section: 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Recommendation: PUC Compliance Education Required and Penalty Applied.</p>	
55224	<p><b>Facility Owner:</b> PECO <b>Contractor/Excavator:</b> Twining Construction Co., Inc. <b>Project Owner:</b> Pancoast &amp; Clifford</p>	<p><u>On 5/21/2025 10:00:00 AM at 23 BRIDGE AVE, EASTTOWN TWP, CHESTER</u> The incident occurred on 5/21/2025 at 10:00 AM, on Woodbine Ave, in Easttown Twp, Chester County.</p> <p>A gas line owned by PECO was damaged. Duration of Service Interruption 1 - &lt; 6 hrs</p>	<p><b>Twining Construction Co., Inc.: \$500.00</b> Section 5(2.2) 1st Offense \$250.00</p> <p>Section 5(6) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>PECO is the facility owner. Their Alleged Violation Report (AVR) states, "TWINING CONSTRUCTION was excavating with a Hydraulic Excavator under ticket number 20251352340 when they severed the unmarked 1" plastic gas service, after reviewing locate requests for TWINING CONSTRUCTION and 23 Bridge Ave it was found that TWINING CONSTRUCTION has a locate request for the front of the building to remove the curb and sidewalk it was found that this damage occurred in the rear of the new building at 23 Bridge Ave, it was found that the contractor was out of the scope of work that they defined on the locate request resulting in the 1" plastic gas service being severed and in need of repair".</p> <p>Twining Construction is the excavator. Their AVR states, "Twining was digging with a 305 Excavator in the rear lot of 23 Bridge Ave. where it meets Woodbine Ave., where our Woodbine Ave. PA1CALL was located SN 20250860389. Twining's Operator hit a new service gas line which was newly installed (approx. 1 mo) and 18" down from grade and unmarked. We were digging around the sewer cleanouts when the unmarked gas line was hit at 10:00AM on 5/21/25, the Foreman, Joe Smolinsky, immediately called 911. Twining's office called in a damage ticket to PA1CALL at 10:05AM, and following the damage ticket Twining called PECO Gas Emergency line to notify PECO. Peco showed up on-site by 10:30 to shut off the gas valve and fix the damaged gas line. The damaged gas line is a newly installed gas service line and Twining has been on site with their equipment since December 2024 with multiple active 1Calls. We are completing work for Pancoast &amp; Clifford, who also has active 1Calls for the site. The gas leak was repaired by Peco within 1 hour."</p> <p>Pancoast &amp; Clifford is the project owner. An AVR has not been filed as of 06-24-2025.</p> <p>Ticket #20251352340 New – Excavation – Routine location information, "OUT FRONT BERWYN FIRE HOUSE PLEASE MARK WHOLE SIDEWALK &amp; ROAD. REMOVING OLD CURB &amp; ROADWAY TO INSTALL NEW."</p> <p>Ticket# 20250860389 "MARK ALL UTILITIES WITHIN ROAD AND GRASS ON ALL OF WOODBINE AVE TO KNOX AVE. WORKING FROM BACK OF FIRESTATION SITE DOWN WOODBINE THEN TURNING RIGHT ONTO KNOX AVE INSTALLING STORM UTILITIES"</p> <p>No Tickets found by PA One Call have locating information that includes the area where the damage occurred as indicated by the photos submitted with the AVRs, and the locating information of the Damage Ticket.</p> <p>Ticket #20251411263 New – Damage – Emergency, locating information, "REAR OF BERWYN FIRE HOUSE".</p> <p>Violations: Excavator - Twining Construction:</p>	<p><b>Pancoast &amp; Clifford:</b> <b>\$1,000.00</b> Section 6.1(7) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 5(2.2) – Excavator failed to provide exact information to identify the worksite.</p> <p>Section 5(6) – Excavator failed to inform each operator employed by the excavator at the work site of the information obtained.</p> <p>Recommendation: PUC Online Compliance Training is required.</p> <p>Project Owner - Pancoast &amp; Clifford:</p> <p>Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike.</p> <p>Recommendation: PUC Online Compliance Training is required.</p>	
55417	<p><b>Facility Owner:</b> EAST STROUDSBURG BOROUGH</p> <p><b>Contractor/Excavator:</b> HENKELS AND MCCOY</p> <p><b>Project Owner:</b> UGI</p> <p><b>Other:</b> Verizon</p>	<p><u>On 5/28/2025 11:00:00 AM at S COURTLAND ST, EAST STROUDSBURG BORO, MONROE</u> The incident occurred on 5/28/2025 at 11:00 AM, on S Courtland St, in East Stroudsburg Borough, Monroe County.</p> <p>A sewer line owned by East Stroudsburg Borough was damaged.</p> <p>East Stroudsburg Borough is the facility owner. Their Alleged Violation Report (AVR) states, “The clay lateral was cracked from the near miss of the bucket. Once exposed the area around the pipe was excavated by hand so the damaged pipe could be cut out and Guy Brink from the WWTP repaired it with SDR 35 sewer pipe. The borough office bathrooms were out of service for less than an hour.” East Stroudsburg Borough provided 3 photos showing the site, damage, and marks. The damage occurred outside of the tolerance zone of the marks. Their AVR states the damage occurred on 5/27/2025, though the photos are dated for 5/28/2025 and all other AVRs show the damage occurring on 5/28/2025.</p> <p>Henkels And Mccoy is the excavator. Their AVR states, “While excavating/trenching for 6" HDPE main; 8" sewer later/main was struck via backhoe 5 feet from locate marks. Rhino kit was used for post-strike pictures. Municipality was contacted; they fixed pipe after we hand dug more out for them to repair safely.”</p> <p>UGI is the project owner. Their AVR states, “Contractor stated: While excavating/trenching for 6" HDPE main; 8" sewer later/main was struck via backhoe 5 feet from locate marks. Rhino kit was used for post-strike pictures. Municipality was contacted; they fixed pipe after we hand dug more out for them to repair safely.” UGI did not provide photos.</p> <p>Ticket #20251483567 New – Damage – Emergency was created on 5/28/25 at 2:24 PM. VERIZON PENNSYLVANIA LLC responded “Clear” on 6/16/2025.</p> <p>Ticket # 20251252998 had a response due date of 5/7/2025. VERIZON PENNSYLVANIA LLC responded “Clear” on 5/23/2025.</p>	<p><b>EAST STROUDSBURG BOROUGH: \$500.00</b> Section 2(5)(i) 1st Offense \$500.00</p> <p><b>Verizon: \$3,500.00</b> Section 2(5)(v) Subsequent \$1,000.00</p> <p>Section 2(5)(vii) Subsequent \$2,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Violations:            Facility - East Stroudsburg Borough:            Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.            Recommendation: PUC Online Compliance Training is required.</p> <p>Facility (other) – Verizon:            Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification.            Ticket #20251483567            Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time.            Ticket # 20251252998            Recommendation: PUC Online Compliance Training was recently completed.</p>	
55379	<p><b>Facility Owner:</b> PPL  <b>Contractor/Excavator:</b> Everhart and Hoover  <b>Project Owner:</b> PPL - Placeholder</p>	<p><u>On 5/28/2025 11:30:00 AM at NICHOLSON SQUARE DR, MANHEIM TWP, LANCASTER</u> The incident occurred on 5/28/2025 at 11:30 AM, on Nicholson Square Dr, in Manheim Twp, Lancaster County.</p> <p>An electric line owned by PPL was damaged.</p> <p>PPL is the facility owner, and project owner. Their Alleged Violation Report (AVR) states, “On Wednesday 5/28/2025 at approximately 12:23 PM, PPL contractor Everhart and Hoover contacted and underground service to 370 Delp Rd while directional boring to replace an underground electric line along Nicholson Square Dr, Manheim Twp.”</p> <p>Everhart And Hoover is the excavator. Their AVR states, “Crew was boring to replace failed primary cable frol pole 39811S27807 on Delp Road approximately 1200 feet to PMT 39792S27750 on Nicholson Square Road. Bore went past PMT 39805S27784. Crew damaged house service to 366 Delp Road at road crossing on Nicholas Square Road. SERVICE WAS NOT MARKED. Road crossing was only electric service wire to 366 Delp road. No other utilities crossed at that location.”</p> <p>Multiple photos of the site and damage were included with the AVRs. No marks are visible within the area of the damage. PPL responded “Field Marked” to the Routine Ticket for this excavation on 5/23/2025.</p> <p>Violations:            Facility – PPL :            Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.            Recommendation: PUC Online Compliance Training is required.</p>	<p><b>PPL: \$1,000.00</b>            Section 2(5)(i) 2nd            Offense \$1,000.00</p>
55412	<p><b>Facility Owner:</b> UGI  <b>Contractor/Excavator:</b> Pioneer Construction Co Inc  <b>Project Owner:</b></p>	<p><u>On 5/29/2025 7:35:00 AM at BOWERS RD, SALEM TWP, LUZERNE</u> The incident occurred on 5/29/2025 at 7:35 AM, on Bowers Rd, in Salem Twp, Luzerne County.</p>	<p><b>Pioneer Construction Co Inc: \$500.00</b>            Section 5(6)(ii) 1st            Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>Pennsylvania American Water (PAWC)  <b>Designer:</b> HERBERT ROWLAND &amp; GRUBIC INC</p>	<p>A gas line owned by UGI Utilities, Inc was damaged. UGI indicates 911 was contacted.</p> <p>UGI Utilities, Inc is the facility owner. Their Alleged Violation Report (AVR) states, “Contractor struck and damaged a correctly marked gas service. Track hoe was digging in the tolerance zone.”</p> <p>Pioneer Construction Co is the excavator. Their AVR has no Summary but includes an attachment with information and pictures, “Pioneer Operator was heeling the trench line to install 8” water main. Operator caught the already exposed gas service, damaging it.”</p> <p>Pennsylvania American Water is the project owner. An AVR has not been filed as of 06-26-2025.</p> <p>Ticket # 20251483023 Damage – Emergency was created on 5/28/25. UGI responded “Clear” to this Ticket on 5/28/2025. A comparison of the photos submitted by UGI on their AVR, and the location of Ticket # 20251483023 show they are for the same location. The Routine Ticket for this location had an excavation start date of 3/2/2025. The yellow mark on the road surface in the images submitted by UGI is very faded. The damage is within the tolerance zone of the mark. There are no new marks visible on the images as would be expected if UGI responded to the locating request Ticket # 20251483023 Damage – Emergency on 5/28/2025.</p> <p>Pioneer provided this additional information on the damage Ticket, “This damage ticket was the day before at the same site. We had to call it in bc it was unknown. To this day no one has claimed ownership of the line. We had the gas exposed that day but had to backfill due to waiting for over 2hrs for utilities to clear the ticket.”</p> <p>Violations:  Excavator - Pioneer Construction Co:  Section 5(6)(ii) – Excavator failed to provide support and mechanical protection for known facility owner’s lines at the construction work site.  Recommendation: PUC Online Compliance Training is required.  Project Owner - Pennsylvania American Water:  Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike.  Recommendation: PUC Online Compliance Training is required.</p>	<p><b>Pennsylvania American Water (PAWC):</b>  <b>\$1,000.00</b>  Section 6.1(7) 1st Offense  \$1,000.00</p>
55843	<p><b>Facility Owner:</b> UGI  <b>Contractor/Excavator:</b> Pioneer Construction Co  <b>Project Owner:</b> Pennsylvania American Water (PAWC)  <b>Designer:</b> Pennsylvania American Water (PAWC) - Placeholder</p>	<p><u>On 5/29/2025 8:20:00 AM at 948 N WEBSTER AVE., SCRANTON CITY, LACKAWANNA</u> The incident occurred on 5/29/2025 at 10:00 AM, on 948 N Webster Ave, in Scranton City, Lackawanna County.</p> <p>A gas line owned by UGI was damaged.</p> <p>UGI is the facility owner. Their Alleged Violation Report (AVR) states, “Excavator struck and damaged a correctly marked gas facility while digging in the tolerance zone.”</p>	<p><b>Pioneer Construction Co: \$500.00</b>  Section 5(6)(ii) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Pioneer Construction Co is the excavator. Their AVR states, "Pioneer Operator was removing rock with a buster to install a new 8" watermain when the buster caught a rock and struck the gas service, damaging it. The crew had hand dug as much as possible to limit the damage, unfortunately the rock can't be removed without the use of heavy equipment. This line was put in place by a "bullet", meaning it was installed using directional drilling, so the service line was completely incased in rock."</p> <p>Pennsylvania American Water is the project owner and designer. Their AVR states, "On 5-29-25 Pioneer struck a 1/2 inch plastic gas service while digging with excavator to #948 N Webster Ave. service was about 2ft off of the mark but very close to the tolerance zone. . UGI came to repair service. No evacuations were necessary."</p> <p>Multiple photos of the site, damage, and marks were provided. The damage is within the tolerance zone of the yellow marks. A hit kit is shown indicating damage location and distance.</p> <p>Violations: Excavator – Pioneer: Section 5(6)(ii) – Excavator failed to provide support and mechanical protection for known facility owner's lines at the construction work site. Recommendation: PUC Online Compliance Training is required.</p>	
55428	<p><b>Facility Owner:</b> PEOPLES GAS COMPANY <b>Contractor/Excavator:</b> K &amp; M Construction <b>Project Owner:</b> Homeowner</p>	<p><u>On 5/31/2025 12:10:00 PM at 3 Short Street, OHARA TWP, ALLEGHENY</u> The incident occurred on Sunday, May 31, 2025, at 3 Short Street, in Ohara Township, Allegheny County.</p> <p>A gas line was damaged. No tickets associated with is case.</p> <p>Peoples Gas indicated in their Alleged Violation Report (AVR), K &amp; M Construction failed to place an routine ticket before excavating and explained, the homeowner at hired a plumber, K &amp; M Construction to work on their sewer lateral. K &amp; M exposed a 4-inch steel line and thought it was the sewer lateral. K &amp; M used a Sawzall to cut the 4-inch steel line, and it turned out to be PNG's encased 2-inch PL ML. PNG crews were called, and repairs were made. Additional information from Peoples Gas, "Michael [of K &amp; M Construction] tried to state he hired a subcontractor he only knew as "Matt" to dig and cut the pipe. No one else was onsite except Michael. The homeowner stated they had hired K&amp;M to complete the work. Michael could not produce any information for Matt. Michael claims he was returning to the site and found the pipe damaged???? PNG did not believe the story, so we decided to bill Michael of K&amp;M Construction, that the homeowner hired, who was onsite upon our arrival at the time of the damage." Peoples Gas provided photos of the damaged line.</p>	<p><b>K &amp; M Construction:</b> <b>\$2,000.00</b> Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>The Fire and Police Departments respond to the 911 call, 2 – 10 customers affected, service interrupted for 1 - &lt; 6 hours, 2 evacuated.</p> <p>K &amp; M Construction did not submit an AVR within 30 days of striking the gas line.</p> <p>Violations:</p> <p>*K &amp; M Construction is in violation of sections:            5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe.            5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line.            Recommendation: PUC Compliance Education Required and Penalties Applied.</p>	
55516	<p><b>Facility Owner:</b> Peoples Natural Gas  <b>Contractor/Excavator:</b> B Q BASEMENT SYSTEMS  <b>Project Owner:</b> HOME OWNER  <b>Other:</b> West Homestead Borough</p>	<p><u>On 6/2/2025 11:34:00 AM at 3449 PINWOOD DR, WEST HOMESTEAD BORO, ALLEGHENY</u> The incident occurred on 6/2/2025 at 11:34 AM, on 3449 Pinewood Dr, in West Homestead Boro, Allegheny County.</p> <p>A gas line owned by Peoples Gas Company was damaged.            1 customer 48+ Hours</p> <p>Peoples Gas Company is the facility owner. Their Alleged Violation Report (AVR) states, “ON 6/2/25 AT 11:34 AM BAKERS WATER PROOFING/B Q BASEMENT SYSTEMS INSTALLING DRAINAGE FOR PROPERTY OWNER AT 3449 PINWOOD DR, STRUCK THE CUSTOMERS SIDE GAS SERVICE LINE. BAKERS WATER PROOFING/B Q BASEMENT SYSTEMS DID NOT PLACE A ONE CALL. BAKERS WATER PROOFING/B Q BASEMENT SYSTEMS CALLED 911 AND PNG WAS NOTIFIED. PNG CREWS ARRIVED ONSITE AND SHUT GAS OFF. BAKERS WATER PROOFING/B Q BASEMENT SYSTEMS WAS ADVISED THE SERVICE LINE WITH NEED REPAIRED/REPLACED. AFTER DAMAGE BAKERS WATER PROOFING/B Q BASEMENT SYSTEMS PLACED EMERGENCY ONE CALL FOR FOUNDATION REPAIRS 20251532467.” Photos submitted show the site location, and damage. A trench is seen which was dug using mechanized equipment, which is where the damage occurred.</p> <p>B Q Basement Systems is the excavator. An AVR has not been filed as of 7-10-2025.</p> <p>Homeowner is the project owner. An AVR has not been filed as of 7-10-2025.</p> <p>Ticket #20251532467 New – Excavation– Emergency was prepared on 6/2/2025 at 12:27. West Homestead Borough did not respond clear until 6/6/2025.</p> <p>Violations:</p>	<p><b>B Q BASEMENT SYSTEMS: \$2,250.00</b>            Section 5(16) 1st Offense \$1,000.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(2.1) 1st Offense \$1,000.00</p> <p><b>West Homestead Borough: \$1,000.00</b>            Section 2(5)(vii) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Excavator - B Q Basement Systems:  Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe.  Section 5(7) – Failed to immediately report to the facility owner any break or leak in its lines, or any dent, gouge, groove, or other damage to such lines or to their coating or cathodic protection.  Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area.  Recommendation: PUC Online Compliance Training is required.</p> <p>Facility (Other) - West Homestead Borough:  Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. #20251532467  Recommendation: PUC Online Compliance Training is required.</p>	
55463	<p><b>Contractor/Excavator:</b>  YORK TRENCHING AND BORING, LLC  <b>Project Owner:</b> Service Electric Cablevision Inc.  <b>Other:</b> Met Ed  <b>Other:</b> Verizon</p>	<p><u>On 6/3/2025 7:00:00 AM at SADOWSKI DR, EXETER TWP, BERKS</u> The incident occurred on 6/3/2025 at 7:00 AM, on Sadowski Dr, in Exeter Twp, Berks County.</p> <p>This is a non-damage incident.</p> <p>York Trenching And Boring is the excavator. Their AVR states, “Had complex meeting on Thursday 5/22/25 . York Trenching and Boring, LLC started calling in tickets 5/27/25 per agreement will all facility owners who attend the complex meeting. Charlie Pineta with USIC is not holding up USIC’S end of what was discussed and agreed to. USIC is coming on the project that has not yet been marked stating their boss is telling them to leave and mark another project. This issue with USIC is only in the Berks County Region. We have been working with many utility companies and have very little to no issues.”</p> <p>Service Electric Cablevision is the project owner, as indicated on the Tickets and AVR submitted by York Trenching and Boring.</p> <p>Ticket # 20251483186-00 had a response due date of 5-30-2025. Met-Ed, and Service Electric Cablevision responded that they would mark by 6/6/2025, and then changed it to 6/4/2025. Verizon did not respond through PA One Call.</p> <p>Ticket # 20251483186-01, which is a renotify, states, “ATTENTION MET ED, AND SERVICE ELECTRIC, RESPONSE WAS SCHEDULED FOR 6/4/2025. THE LAWFUL START STATE IS 06/02/2025. PLEASE GO TO SITE ASAP FOR MARKINGS THAT ARE DUE ASAP. ATTENTION VERIZON, NO RESPONSE WAS GIVEN, PLEASE GO TO SITE TO MARK ASAP AS THE LAWFUL START DATE WAS 6/2/2025.” This Ticket was entered on 6/3/2025 at 7:45 AM. Met-Ed, Service Electric Cablevision and Verizon did not respond within 2 hours.</p>	<p><b>Service Electric Cablevision Inc.:</b>  <b>\$1,000.00</b>  Section 2(5)(v) 2nd offense \$500.00</p> <p>Section 2(5)(v.1) 1st Offense \$500.00</p> <p><b>Met Ed: \$750.00</b>  Section 2(5)(v.1) 1st Offense \$500.00</p> <p>Section 2(5)(v) 1st Offense \$250.00</p> <p><b>Verizon: \$3,000.00</b>  Section 2(5)(v) Subsequent \$1,000.00</p> <p>Section 2(5)(v.1) 2nd Offense \$1,000.00</p> <p>Section 2(5)(viii) 2nd Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Ticket # 20251392520 – Complex Project – had a due date of 5/21/2025. Verizon responded “Clear” on 6/2/2025. On future tickets for the same location, they respond “Field Marked”.</p> <p>Violations:            Facility (other) - METROPOLITAN EDISON CO:            Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time.            Ticket #20251483186 -00            Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Ticket #20251483186 -01            Recommendation: PUC Online Compliance Training is required.</p> <p>Facility (other) - SERVICE ELECTRIC CABLEVISION            Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time.            Ticket #20251483186 -00            Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Ticket #20251483186 -01            Recommendation: PUC Online Compliance Training is required.</p> <p>Facility (other) – VERIZON            Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time.            Ticket #20251483186 -00            Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Ticket #20251483186 -01            Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3).            Ticket # 20251392520            Recommendation: PUC Online Compliance Training is required.</p>	

**Full Session**

Case Number	Stakeholders	Summary	Violations & Recommendation
53648	<p><b>Facility Owner:</b> Columbia Gas of PA  <b>Contractor/Excavator:</b> Zokaites Contracting  <b>Project Owner:</b> Zokaites Contracting (Place holder)</p>	<p><u>On 3/19/2025 10:44:00 AM at CLAIRE VALLEY CT, JEFFERSON HILLS BORO, ALLEGHENY</u> On 10/15/2025: The Damage Prevention Committee (DPC) voted for Zokaites Contracting to:            5(4)- Keep violation and penalty.            5(16)- Keep violation and penalty.</p> <p>*****            Zokaites Contracting is disputing.</p> <p>*****            The incident occurred on 03/19/2025 at 10:44 AM, on Claire Valley Court, in Jefferson Hills Borough, Allegheny County.</p> <p>A gas line owned by Columbia Gas of PA was damaged. 911 was called.</p>	<p><b>Zokaites Contracting:</b>  <b>\$2,500.00</b>            Section 5(4) 2nd Offense            \$1,000.00</p> <p>Section 5(16) 2nd Offense            \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Columbia Gas of PA, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “Zokaites Contracting was working on their private well to repair a gas leak when they struck a saddle and ripped it off the gas main with a backhoe. Mr. Zokaites notified Columbia Gas directly when the damage occurred. Columbia Gas responded immediately to make the area safe and complete repairs. The local Damage Prevention Specialist (DPS) and Columbia Gas crew advised Mr. Zokaites that 911 needs to be notified anytime there is a damage resulting in the release of gas. The DPS further advised that an Alleged Violation Report would need to be completed for this damage.”</p> <p>Zokaites Contracting is the excavator and project owner. An AVR has not been filed as of 06/06/2025.</p> <p>The submitted photos yellow paint and flags, indicating where the gas line was located. The gas line was damaged within the tolerance zone.</p> <p>Violations:</p> <p>Zokaites Contracting –</p> <ul style="list-style-type: none"> <li>- Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.</li> <li>- Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.</li> </ul> <p>Recommendation: The penalty is applied. PUC online compliance training/education is required.</p>	
53933	<p><b>Facility Owner:</b> UGI Utilities Inc.  <b>Contractor/Excavator:</b> City Of Reading Public Works- Sign Department  <b>Other:</b> VERIZON</p>	<p><u>On 3/28/2025 12:00:00 AM at 116 1/2 ORANGE ST, READING CITY, BERKS</u> On 10/15/2025 the Damage Prevention Committee (DPC) voted to Keep the violation and penalty for section 5(4) and 5(17) and to Remove both of the violations for section 5(8). and to remove the education, since this was recently completed.  **  City of Reading disagrees. They state that the employee was unaware that a gas line was hit and that no heavy equipment was being used at this site. Please note powered hand tools were used. AVR summary states that the City of Reading was drilling a hole for a traffic sign installation. On 9/02/2025 The City of Reading answered the questions that the DPI asked about the picture that was sent. DPI withdrew the penalty but maintained the violation for section 5(17) not complying with information.  *****  The incident occurred on 3/27/2025 on Orange St in Reading City in Berks County.</p> <p>A UGI gas line was damaged. The damage was discovered the next day.</p>	<p><b>City Of Reading Public Works- Sign Department: \$500.00</b>  Section 5(17) 1st Offense \$0.00</p> <p>Section 5(4) 1st Offense \$500.00</p> <p><b>VERIZON: \$2,000.00</b>  Section 2(5)(v) 1st Offense \$500.00</p> <p>Section 2(5)(vii) 2nd Offense \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>UGI stated in their Alleged Violation Report (AVR) that “Excavator utilizing mechanized equipment, struck a correctly marked gas service while driving in a street sign”. Pictures were provided. On 5/08/2025 DPI Maki sent an email asking if Reading Public Works was billed for this damage and if this was paid. On 5/08/2025 UGI responded that they did bill Reading Public Works, but that Reading Public Works did not pay yet. UGI also noticed that the date was incorrectly listed in the AVR and updated this information to be 3/28/2025. DPI also requested a copy of the bill. On 5/15/2025 UGI provided a confidential document (do not share with the public) showing the invoice that was sent to the City of Reading and due by 5/24/2025. Note that AVR2025APR040018 report states that the incident occurred on 3/27/2025, but the emergency ticket was placed on 3/28/2025, by UGI to repair the gas leak. On 5/27/2025 DPI Maki asked UGI how they knew of the gas leak. 911 was checked “not notified”. On 5/28/2025 UGI responded that “We received an odor complaint call from a resident. When our first responder arrived, they made the determination that the leak was caused by sign placement. We were not informed by City of Reading Public Works. The damage was not discovered until the day after they installed the sign when the resident made the odor complaint”. On 5/29/2025 DPI asked UGI if it was possible to not smell gas after drilling into a gas pipe. UGI responded immediately with an email that "Well, it had what’s called an ‘excess flow valve’ which prevents large amounts of gas from escaping in the event a service line is struck. When it is initially severed however, there is a release of gas before the excess flow limiter trips. So, I would say it’s not impossible they didn’t smell gas, but it is very unlikely they didn’t smell gas".</p> <p>City Of Reading Public Works- Sign Department AVR was due by 4/27/2025. DPI Maki emailed and mailed an AVR request letter on 5/08/2025. On 5/28/2025 READING CITY AVR was received and stated that “Was drilling a hole for a traffic sign installation and hit a gas line. was close to the mark”. Picture was submitted. On 5/29/2025 DPI asked City of Reading about the picture that they submitted to get more information about what they were trying to explain with the picture. DPI Maki sent a reminder email on 6/11/2025. DPI Maki waited until 6-28-2025 and no response has been received as of 6/28/2025.</p> <p><b>VIOLATION</b>  City Of Reading Public Works- Sign Department is in violation of:  Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid.  Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.  Section 5(8) – Excavator vacated worksite after causing damage that resulted in the escape of any flammable, toxic or corrosive gas or liquid.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within 30 days of the receipt of the request. After the stakeholder review was sent, The City of Reading Public Works responded to my inquiry of why they had a highlight and arrow pointing to the gas cover on the ground. DPI Maki did not understand what they were trying to convey by adding this to the picture. An email response was received after the stakeholder review was sent out. The City of Reading was just pointing out where the cover was. This information did not affect the case findings. The violation was maintained, since they did not respond to the question in a timely manner.  Recommendation: The penalties are applied. Compliance Education is required.</p> <p>Verizon is in violation of:  Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Emergency ticket 20250873635 was submitted on 3/28/2025 at 20:09. Verizon did not respond “field marked” until 3/31/2025. This is a second offense.  Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket 20250800270 was submitted by the City of Reading on 3/21/2025 with a response due by 3/25/2025. Verizon did not respond until 3/31/2025, when they “field marked”  Recommendation: The penalty is applied. Compliance education was recently completed.</p>	
55024	<p><b>Facility Owner:</b> COMCAST</p> <p><b>Contractor/Excavator:</b> WARWICK TOWNSHIP LANCASTER COUNTY</p> <p><b>Project Owner:</b> WARWICK TOWNSHIP LANCASTER COUNTY</p>	<p><u>On 4/1/2025 11:00:00 AM at 390 CARDINAL RD, WARWICK TWP, LANCASTER</u> On Wednesday, October 15, 2025, at the DPC meeting, disputing party was Warwick Twp. It was voted to Remove the penalty but keep the violation and education.  *****  Dispute- Warwick Township is disputing.  *****  The incident occurred on Tuesday, April 1, 2025, at 390 Cardinal Road, in Warwick Township, Lancaster County.</p> <p>A communications line was damaged.</p> <p>Comcast stated in their Alleged Violation Report (AVR), excavator, Warwick Township hit an unmarked line. Approximate Number of Customers Affected- 51 + and Comcast provided photos of the damaged line. 20250783513- Routine ticket placed on 3/19/2025. Comcast responded as Clear No Facilities. Warwick Township did not submit an AVR within 30 days of striking the line.</p> <p>Violations:</p> <p>*Comcast is in violation of section:  (5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.  20250783513  Recommendation: Penalty Applied.</p>	<p><b>COMCAST: \$1,000.00</b>  Section 2(5)(i) 2nd Offense \$1,000.00</p> <p><b>WARWICK TOWNSHIP LANCASTER COUNTY: \$0.00</b>  Section 5(16) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>*Warwick Township is in violation of section: 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line.  Recommendation: PUC Compliance Education Required and Penalty Applied.</p>	
54013	<p><b>Facility Owner:</b> UGI UTILITIES INC  <b>Contractor/Excavator:</b> DOMINANT POWER  <b>Project Owner:</b> Lamberts Cable Splicing  <b>Project Owner:</b> Verizon PA LLC</p>	<p><u>On 4/7/2025 9:00:00 AM at 1130 PRESTON PL, SCRANTON CITY, LACKAWANNA</u> On Wednesday, October 15, 2025, at the DPC meeting, disputing party was Dominant Power. It was voted to Remove All their Penalties and Violations.  *****  Dispute- Dominant Power is disputing penalties and violations. See attached email  *****  The incident occurred on Monday, April 7, 2025, at 1130 Preston Place, in Scranton City, Lackawanna County.   A gas line was damaged.   UGI stated in their Alleged Violation Report (AVR), “Excavator [Dominant Power] struck and damaged a correctly marked gas facility. We believe the excavator installed the pole on 4-7-25. We were notified on 4-8-25 at 11:00 AM of an odor of gas in the area from the homeowner. 911 was notified of the gas odor. Upon investigation a UGI Tech found 100% gas readings at the newly installed pole. Upon further investigation the gas service was found to be completely severed in a manner indicative of mechanized equipment damage. The severed gas service was within inches of the newly installed pole. The excavator denied smelling gas and also denied damaging the facility. The excavator stated the hole was dug by hand. Pictures are attached. 3 pictures were provided to me by the excavator labeled excavator pic 1,2,3.”   Dominant Power stated in their AVR, “Dominant Power received a call from Mike at UGI on 4/8/25 at approximately 12:20pm stating that our company damaged a gas service in the process of placing pole number 103. Dominant Power provided the documentation (pictures) from the job showing where the crew had hand dug the hole before placing the pole and to show that there were no damages to their lines during the process. Regardless of the documentation, Mike continued to accuse Dominant Power and said that Dominant Power is inherently responsible for the damages because we were the last known contractor working at this location. Mike was very unprofessional, and there were a lot of discrepancies in the information Mike was providing for us. For example, Mike claimed the damages occurred on 4/7/25, and Dominant Power completed this job on 3/31/25. Dominant Power explained to Mike that if we would've struck a gas line, we would've evacuated the area immediately and called 911. Dominant Power also explained that there was never any smell of gas or indications of a gas line being struck. Dominant Power keeps a gas monitor on scene when digging this close to utilities, however Mike</p>	<p><b>DOMINANT POWER:</b>  <b>\$0.00</b></p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>continued accusing Dominant Power of the damages. Dominant Power will attach our internal pictures of the job as well as the pictures sent to us from Mike of the damages afterwards, and you will see that if the line Mike is accusing us of damaging was struck during our operation, it would have been easily visible as we still hand dug an additional 5ft below the depth of the line.”</p> <p>Verizon PA LLC, the project owner, stated in their AVR, this is “the information Verizon received from our contractor Lambert Cable Splicing: Lamberts was contacted 4/8/25 by both the gas company and Verizon about an alleged gas line hit at the address in question. After researching this was identified as pole 103 under EWO 1A6GC4X. No injuries or property damage were reported aside from the gas line. Information from the gas company was that a homeowner smelled gas and called on 4/8/25 stating that a crew setting a pole in front of his property on 4/7/25 had damaged the facility. Researching further and checking one calls; Pole 103 has been set on EWO 1A6GC4X on 3/31/25 which was disclosed to the gas company rep. Pre dig pictures were taken and reviewed as well as dig in flight pictures that showed no facilities in the hole or sidewall of the hole. Crew was questioned and stated that they did not smell gas on 3/31 during or after the dig and had no reason to believe that any facility was damaged during the dig. Due to marked gas lines in the area crew reported that they hand dug the hole to a depth of 4.5 feet and no utilities were found. Digger Derrick with grounding hardware was then used to set the pole in power. Crew then backfilled and tamped around the pole. Reviewing the pictures supplied by the gas company, the plastic gas service line is next to the new pole set and has catastrophic damage at the break point that is not consistent with side damage done by an auger or hand tools. There is also an intact tracer line running underneath and next to the damaged gas line that looks to be intact and undamaged. An AVR was completed by the contract, Dominant Power LLC, through the PA One Call System once notified of the alleged damage and site pictures are attached for reference.”</p> <p>Photos were provided showing a 3-foot off set- 1-inch PL, showing the severed gas line, showing pole installed within the tolerance zone, showing gas reading at 100%, and showing the hole prior to the pole installation. 20250844876- Routine ticket placed on 3/25/2025, with Lawful start dates of 3/28/2025 - 4/8/2025, duration of 8 hours, type of work was replacing a pole, method of excavation was Augering, and Remarks--[MARK 10FT RADIUS AROUND THE OLD POLE].</p> <p>Violations:</p> <p>*Dominant Power is in violation of sections: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid.</p> <p>5(8) – Excavator vacated worksite after causing damage that resulted in the escape of any flammable, toxic or corrosive gas or liquid.</p> <p>Recommendation: PUC Compliance Education Required and Penalties Applied.</p>	
54291	<p><b>Facility Owner:</b> Peoples Gas Company  <b>Contractor/Excavator:</b> PROTOCOL LLC  <b>Project Owner:</b> ROSTRAVER TOWNSHIP  <b>Designer:</b> KLH ENGINEERS INC</p>	<p><u>On 4/17/2025 8:53:00 AM at 1128 WILLOWBROOK RD, ROSTRAVER TWP, WESTMORELAND</u> On 10/15/2025 the DPC voted to:  Protocol  5(4)- accept the violation and penalty.  5(8)- accept the violation and penalty.  5(16)- accept the violation but remove the penalty. Keep the education requirement.</p> <p>*****  Protocol is disputing.  *****</p> <p>Incident occurred on April 17th, 2025, at 8:53am on 1128 Willowbrook Road, Rostraver Township, Westmoreland County.</p> <p>A gas line was damaged.</p> <p>Peoples Gas Company's Alleged Violation Report (AVR) states, "ON 4/17/25 AT 08:53 PROTOCOL LLC WORKING FOR ROSTRAVER TWP INSTALLING STORM SEWER, STRUCK A MARKED PNG COMPANY SIDE SERVICE LINE. PNG SERVICE LINE WAS MARKED VIA SNAKE DUE TO WIRE ACCESS. MARKS WERE GOOD. PROTOCOL STRUCK SERVICE LINE WHILE ATTEMPTING TO REMOVE LARGE ROCK ABOVE THE SERVICE. PNG CREWS WERE CALLED TO SITE AND REPAIRS MADE." AVR notes that 911 was not notified.</p> <p>Pictures show that the line was marked out within the tolerance zone along with bucket teeth marks. No complex ticket was placed, and the final design states the project was 3,300 LF.</p> <p>Protocol, LLC and Rostraver Township have not submitted an AVR as of 6/5/2025.</p> <p>Violations:</p> <p>Protocol, LLC  Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. PUC compliance education is required. PUC compliance education is required.  Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid. PUC compliance education is required.</p>	<p><b>PROTOCOL LLC:</b>  <b>\$1,500.00</b>  Section 5(4) 1st Offense  \$500.00</p> <p>Section 5(8) 1st Offense  \$1,000.00</p> <p>Section 5(16) 1st Offense  \$0.00</p> <p><b>ROSTRAVER TOWNSHIP: \$1,000.00</b>  Section 6.1(7) 1st Offense  \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required.</p> <p>Rostraver Township Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. PUC compliance education is required.</p>	
54752	<p><b>Facility Owner:</b> UGI UTILITIES INC <b>Contractor/Excavator:</b> TIMOTHY LEBIAK <b>Project Owner:</b> TIMOTHY LEBIAK <b>Other:</b> Comcast</p>	<p>On 4/17/2025 1:52:00 PM at 514 PARK ST, TAYLOR BORO, LACKAWANNA On Wednesday, October 15, 2025, at the DPC meeting, disputing party was Timothy Lebiak. It was voted to Remove the penalty but keep the violation and education. *****</p> <p>Dispute- excavator, TIMOTHY LEBIAK is disputing stated, I am contacting you about anyway to reduce or remove this fine within this case. As you can see from the other reports the gas lines were mismarked so hitting them was not my fault. I understand I did not file the Alleged Violation Report but im young homeowner that was just trying to improve his home and just didnt know this was something that was needed. *****</p> <p>The incident occurred on Thursday, April 17, 2025, at 514 Park Street, in Taylor Borough, Lackawanna County.</p> <p>A gas line was damaged.</p> <p>UGI Utilities stated in their Alleged Violation Report (AVR), excavator struck and damaged an incorrectly marked gas service. UGI and the Fire Department responded to the 911 call, placed by the excavator. UGI provided photos of the damaged line.</p> <p>Timothy Lebiak, the excavator and project owner, did not submit an AVR within 30 days of striking the gas line.</p> <p>20250844205- Routine ticket placed on 3/25/2025. No Response from Comcast.</p> <p>Violations:</p> <p>*UGI Utilities is in violation of section: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: Penalty Applied.</p> <p>*Timothy Lebiak is in violation of section: 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: PUC Compliance Education Required and Penalty Applied.</p> <p>*Comcast is in violation of section: 2(5)(v) – Failed to respond to a routine One Call ticket. 20250844205 Recommendation: Penalty Applied.</p>	<p><b>UGI UTILITIES INC:</b> <b>\$1,000.00</b> Section 2(5)(i) 2nd Offense \$1,000.00</p> <p><b>TIMOTHY LEBIAK:</b> <b>\$0.00</b> Section 5(16) 1st Offense \$0.00</p> <p><b>Comcast: \$500.00</b> Section 2(5)(v) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
54312	<p><b>Facility Owner:</b> Peoples Gas  <b>Contractor/Excavator:</b> Craig Rupinski  <b>Project Owner:</b> Chantal Mitchell</p>	<p><u>On 4/17/2025 5:00:00 PM at 1400 Grant St. BRADDOCK BORO, ALLEGHENY</u> Craig Rupinski did not attend the Damage Prevention Committee (DPC) on 10/15/2025. The DPC voted to:</p> <p>5(2.1) Accept the violation and penalty  5(6)(i) Accept the violation and penalty  5(16) Accept the violation and penalty  5(17) Accept the violation and increase the penalty to \$1000 for wasting DPC time.</p> <p>*****  Craig Rupinski - Disputing  Homeowner : 6.1(7) Penalty reduced from \$1000 to a warning of \$0. 6.1(8)Penalty reduced by 50% from \$500 to \$250.  *****  The incident occurred on 4/17/2025 at 5:00 PM on 1400 Grant St, in Braddock Borough, Allegheny County.</p> <p>A gas line owned by Peoples Gas was damaged. 911 was contacted.  Duration of Service Interruption 1 - &lt; 6 hrs  Approximate Number of Customers Affected 1</p> <p>Peoples Gas, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, "Craig Rupinski was working for his neighbor at 1500 Grant St in Braddock without a locate request and struck and damaged a plastic customer side plastic gas line between the curb valve and meter." Peoples Gas submitted 2 photos with their AVR showing the site and damage. A curb stop and meter base are visible at the site. The area is mostly disturbed dirt, and the side of the hill towards the home is excavated. There is a skid steer on site, and retaining wall blocks were starting to be placed around the excavated hill towards the home where the damage occurred.</p> <p>Craig Rupinski, the excavator, was mailed an AVR request letter on 5/19/2025. Craig sent a hand written letter in stating, "Your information is incorrect. There was absolutley no digging underground at any time. A gas line was sandwiched between a fallen wall I was only the one who reported it, I'm a neibor." Additional contact with Craig via phone to discuss submitting the AVR occurred on 6/23/2025. Craig stated, "I won't be submitting an AVR" but the phone conversation ended with Craig understanding an AVR needed submitted. No AVR has been received.</p> <p>Chantal Mitchell , the project owner and homeowner, was mailed an AVR request letter on 5/19/2025. Nothing has been received from Chantal as of 6/25/2025.</p> <p>Violations:  Excavator – Craig Rupinski  Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe.  Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize</p>	<p><b>Craig Rupinski:</b>  <b>\$3,250.00</b>  Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p>Section 5(17) 1st Offense \$1,000.00</p> <p><b>Chantal Mitchell:</b>  <b>\$250.00</b>  Section 6.1(7) 1st Offense \$0.00</p> <p>Section 6.1(8) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>interference with a facility owner’s facilities in the construction area.</p> <p>Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.</p> <p>Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request.</p> <p>Recommendation: PUC compliance training education is required.</p> <p>Project Owner - Chantal Mitchell</p> <p>Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike.</p> <p>Section 6.1(8) - Project Owner failed to comply with all requests for information by the commission relating to the commission's enforcement authority under this act within 30 days of receipt of written request.</p> <p>Recommendation: PUC compliance training education is required.</p>	
54580	<p><b>Facility Owner:</b> UGI Utilities, Inc.</p> <p><b>Contractor/Excavator:</b> J F Kiely Construction</p> <p><b>Project Owner:</b> UGI - Placeholder</p>	<p><u>On 4/21/2025 12:00:00 AM at UNIVERSITY AVE, PENN TWP, SNYDER</u> On 10/15/2025: The Damage Prevention Committee (DPC) voted: UGI - 2(5)(i) -No changes to violation and penalty. ***** UGI Disputing - 2(5)(i)</p> <p>The incident occurred on 4/21/2025, at 9:15 AM, on University Ave, in Penn Twp, Snyder County.</p> <p>A gas line owned by UGI was damaged. 911 was contacted. Repair Cost - \$1,001-\$5,000</p> <p>UGI is the facility and project owner. Their Alleged Violation Report (AVR) states, “UGI facility records location matched instrument signal tone. Actual location of gas main was outside of the established tolerance zone. There was no hazardous release of gas. Damage was done to casing pipe only.” UGI submitted 2 photos of the site with their AVR.</p> <p>J F Kiely Construction Co is the excavator. Their AVR states, “Affected gas line was 7.5 feet away from marks. crew caught line with an excavator.”</p> <p>The photos, and AVRs, submitted indicate the damage was outside of the tolerance zone.</p> <p>Violations: UGI: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: The penalty is applied. PUC compliance training education is required.</p>	<p><b>UGI Utilities, Inc.:</b> <b>\$2,000.00</b> Section 2(5)(i) Subsequent \$2,000.00</p>
54434	<p><b>Contractor/Excavator:</b> GRAY LAND MANAGEMENT</p> <p><b>Project Owner:</b></p>	<p><u>On 4/23/2025 11:45:00 AM at 5117 Rosecrest Dr, PITTSBURGH CITY, ALLEGHENY</u> On 10/15/2025 the DPC voted to: Gray Land Management</p>	<p><b>GRAY LAND MANAGEMENT:</b> <b>\$3,000.00</b> Section 5(2.1) 1st Offense</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>homeowner <b>Other:</b> Peoples Gas Company</p>	<p>5(2.1)- accept the DPI's recommendation. 5(8)- accept the DPI's recommendation. 5(16)- accept the DPI's recommendation. *****</p> <p>Gray Land Management is disputing.</p> <p>DPI followed up with Peoples Gas Company who stated no 911 notification was received and no emergency services were on sight of the incident. Gray Land Management submitted an AVR during stakeholder review that states, "While working on a driveway replacement project, a homeowner gas line was scratched enough to cause a leak. The line was directly under the driveway surface. A one call was not made prior to the start of the project being that we were working on private property and private property is not marked when one call is made. We knew exactly where the gas line ran as we could clearly see the meter and the curb box. It was a straight shot. Line just happened to be right under the surface rather than being buried at an appropriate depth. When it happened, the foreman on site called both 911 and the gas company to ensure that the leak was taken care of quickly. Crew on site did make sure to pinch off line quickly after the leak happened. Gas company showed up and shut curb box and then we had a registered dot plumber come out to complete the repair." Completed Education.</p> <p>****</p> <p>Incident occurred on April 23rd, 2025, at 11:45am on 5117 Rosecrest Drive, Pittsburgh City, Allegheny County.</p> <p>A gas line was damaged.</p> <p>Peoples Gas Company's Alleged Violation Report (AVR) states, "GRAY LAND MANAGEMENT Failed to place a locate request prior to excavation and struck and damaged a customer side plastic service line." AVR notes that 911 was not notified.</p> <p>811 Commented, "Gray Land Management has placed notifications with PA One Call in the past."</p> <p>Violations: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. PUC compliance education is required. Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid. PUC compliance education is required. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required.</p>	<p>\$1,000.00</p> <p>Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p>
54829	<p><b>Facility Owner:</b> UPPER MERION TOWNSHIP <b>Contractor/Excavator:</b> UTILITY LINE</p>	<p><u>On 4/29/2025 10:20:00 AM at JONES RD, UPPER MERION TWP, MONTGOMERY</u> On 10/15/2025 Upper Merion Township did not attend the meeting. The Damage Prevention Committee (DPC) voted to Accept</p>	<p><b>UPPER MERION TOWNSHIP: \$2,500.00</b> Section 2(5)(i) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>SERVICES  <b>Project Owner:</b> PECO  <b>Other:</b> CROWN CASTLE  <b>Other:</b> VERIZON PA LLC</p>	<p>all of the recommendations and add a \$500. penalty to 2(5)(i) violation.  Upper Merion Township is disputing.  *****</p> <p>The incident occurred on 4/29/2025 on Jones Rd. in Upper Merion Township in Montgomery County.</p> <p>A traffic light sensor wire and box owned by Upper Merion Township was damaged.</p> <p>UTILITY LINE SERVICES the excavator, stated in their Alleged Violation Report (AVR) that “While the crew was working i in the area of Swedeland Road to install a gas main they damaged an unmarked traffic light sensor wire and box”. Pictures were provided. No project information was provided.  On 6/02/2025 DPI Maki sent an email asking ULS about the final design and if Merion Township did come out to fix the line. ULS responded with an email on 6/03/2025. They sent the responses to CP ticket 20243590710 and said that PECO would have the design. DPI responded back with an email on 6/03/2025 that I am looking for the Complex Project sign-in sheet. ULS responded that they did not have a CP sign-in sheet.</p> <p>PECO stated in their AVR that “ULS was working i in the area of Swedeland Road to install a gas main they damaged an unmarked traffic light sensor wire and box”. No project information was provided. Report was provided. No project information was provided.</p> <p>UPPER MERION TOWNSHIP AVR was due on 6/11/2025. No AVR has been received as of 6/27/2025.  *****</p> <p>*Complex project ticket 20243590710 was submitted by Utility Line Services (ULS) on 12/24/2025 with a response due by 12/30/2025. The CP meeting was held on 12/31/2024 at 10:00 a.m. New Gas main is being installed. This is a 12 mo project.  Verizon Responded late with “Insuff Info. Do not dig”. on 1/24/2025.  Crown Castle did not respond “clear” until 1/02/2025.</p> <p>*Ticket 20251012988 was submitted by Utility Line Services on 4/11/2025 with a response due by 4/15/2025. PECO Scheduled a mark by 4/15/2025, but did not respond “field marked” until 4/17/2025.</p> <p>Verizon did not respond “clear” until 4/28/2025.  Upper Merion Township responded “scheduled mark on 4/15/2025, but did not respond “clear” until 4/17/2025.  Upper Merion Sanitary and stormwater Authority did not respond “clear” until 4/17/2025.</p> <p>*Ticket 20251073843 was submitted by ULS on 4/17/2025 with a response due by 4/21/2025.  Verizon responded “clear” late, on 5/02/2025.</p>	<p>Section 2(10) 1st Offense \$1,000.00</p> <p>Section 2(5)(v.2) 1st Offense \$250.00</p> <p>Section 2(5)(v.2) 1st Offense \$250.00</p> <p><b>CROWN CASTLE:</b>  <b>\$1,500.00</b>  Section 2(5)(viii) 3rd Offense \$1,500.00</p> <p><b>VERIZON PA LLC:</b>  <b>\$5,000.00</b>  Section 2(5)(v) Subsequent \$1,000.00</p> <p>Section 2(5)(v) Subsequent \$2,000.00</p> <p>Section 2(5)(viii) Subsequent \$2,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>PECO and Upper Merion Township scheduled mark on 4/21/2025, but did not give a final response until 4/24/2025.</p> <p>Upper Merian Sanitary and Stormwater Authority scheduled mark on 4/21/2025, but did not give a final response “clear” until 4/24/2025.</p> <p><b>VIOLATIONS</b></p> <p>Upper MERION Township is in violation of:</p> <p>Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.</p> <p>Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work.</p> <p>Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests Ticket 20251012988 was submitted by Utility Line Services on 4/11/2025 with a response due by 4/15/2025. Upper Merion Township responded “scheduled Mark” on 4/15/2025 and responded “clear” on 4/17/2025. This was not a final response, since they did have facilities within the ticket area. This late response was also not in mutual agreement with the excavator.</p> <p>Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests Ticket 20251073843 was submitted by Utility Line Services on 4/17/2025 with a response due by 4/21/2025. Upper Merion Township responded “scheduled Mark” on 4/21/2025 and responded “clear” on 4/24/2025. This was not a final response, since they did have facilities within the ticket area. This late response was also not in mutual agreement with the excavator.</p> <p>Recommendation: The penalties are applied. Compliance Education is required.</p> <p>Verizon is in violation of:</p> <p>Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). This is a subsequent violation.</p> <p>Section 2(5)(v) – Failed to respond to a routine One Call ticket. This is a subsequent violation.</p> <p>Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. This is a subsequent violation.</p> <p>Please see ticket 20243590710, 20251073843, and 20251012988 details above.</p> <p>Recommendation: The penalties are applied. Compliance education was recently completed.</p> <p>Crown Castle is in violation of:</p> <p>Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). This is a third time violation. Please see ticket 20243590710 details above.</p> <p>Recommendation: The penalties are applied. Compliance education was recently completed.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
54599	<p><b>Facility Owner:</b> AQUA PA</p> <p><b>Contractor/Excavator:</b> J M C CONTRACTORS INC</p> <p><b>Project Owner:</b> UPPER PROVIDENCE TOWNSHIP</p> <p><b>Other:</b> PECO</p> <p><b>Other:</b> UPPER PROVIDENCE TSA DELAWARE CO</p>	<p><u>On 4/29/2025 1:45:00 PM at MEDIA STATION RD, UPPER PROVIDENCE TWP, DELAWARE</u> Upper Providence Township did not attend the 10/15/2025 Damage Prevention Committee (DPC) meeting. The vote for Upper Providence Township:</p> <p>2(5)(v) - Keep the violation and increase fine by \$250 per violation</p> <p>6.1(7) -Keep the violation and increase fine by \$250 per violation</p> <p>*****</p> <p>Upper Providence Township - dispute - 2(5)(v) and 6.1(7)</p> <p>*****</p> <p>The incident occurred on 4/29/2025 at 1:45 PM, on Media Station Rd, in Upper Providence Twp, Delaware County.</p> <p>A water line owned by Aqua Pennsylvania Inc was damaged.</p> <p>Aqua Pennsylvania Inc is the facility owner. Their Alleged Violation Report (AVR) states, "EXCAVATOR HIT &amp; PULLED A MARKED WATER SERVICE. EXCAVATOR HAD BEEN WARNED EARLIER ABOUT GETTING CLOSE TO THE MARKED WATER SERVICE WHEN LOCATOR RESPONDED TO AN EMERGENCY GAS LEAK TICKET 20251192708, WHICH THE SAME EXCAVATOR DAMAGED THE GAS LINE. 316 MEDIA STATION RD". 2 photos were submitted that show a blue mark with the damage within the tolerance zone, as well as an excavator bucket in the pit where the damage occurred. Aqua was contacted by JMC Contractors when the damaged occurred.</p> <p>J M C Contractors Inc is the excavator. An AVR has not been filed as of 06-11-2025.</p> <p>Upper Providence Twp is the project owner. An AVR has not been filed as of 06-11-2025.</p> <p>Ticket # 20250931341 had a response due date of 4/7/2025: PECO and UPPER PROVIDENCE TSA DELAWARE CO responded, "SCHEDULED DATE &amp; TIME LINES WILL BE MARKED BY: 07 Apr 2025 2359" on 4/7/2025, and responded, "FIELD MARKED." on 4/22/2025. UPPER PROVIDENCE TOWNSHIP DELAWARE COUNTY responded "FIELD MARKED." On 4/9/2025. AQUA PENNSYLVANIA INC responded "FIELD MARKED." on 4/16/2025 with a note "2025/04/07 23:59 CONTRACTORS DIDNT ANSWER LEFT A VOICE MESSAGE 2025/04/07 23:59 RESCHEDULE APPROVED BY: JOE COSTANTINI 6103611850." No interim response was recorded.</p> <p>This Case is related to Case #054610 by Ticket # 20250931341.</p>	<p><b>AQUA PA: \$250.00</b> Section 2(5)(v) 1st Offense \$250.00</p> <p><b>J M C CONTRACTORS INC: \$1,500.00</b> Section 5(4) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p><b>UPPER PROVIDENCE TOWNSHIP: \$1,750.00</b> Section 6.1(7) 1st Offense \$1,250.00</p> <p>Section 2(5)(v) 1st Offense \$500.00</p> <p><b>PECO: \$1,000.00</b> Section 2(5)(v) Subsequent \$1,000.00</p> <p><b>UPPER PROVIDENCE TSA DELAWARE CO: \$250.00</b> Section 2(5)(v) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Violations:  Excavator - J M C Contractors Inc:  Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.  Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.  Recommendation: PUC compliance training education is required.</p> <p>Project Owner - Upper Providence Twp:  Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike.  Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time.  Ticket#20250931341  Recommendation: PUC compliance training education is required.</p> <p>Facility (other) – PECO:  Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time.  Ticket#20250931341  Recommendation: PUC compliance training was recently completed.</p> <p>Facility (other) - UPPER PROVIDENCE TSA DELAWARE CO:  Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time.  Ticket#20250931341  Recommendation: PUC compliance training education is required.</p> <p>Facility (other) - AQUA PENNSYLVANIA INC:  Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time.  Ticket#20250931341  Recommendation: PUC compliance training was recently completed.</p>	
54808	<p><b>Facility Owner:</b>  PEOPLES GAS COMPANY</p> <p><b>Contractor/Excavator:</b>  RICHLAND TOWNSHIP MUNICIPAL AUTHORITY OF ALLEGHENY COUNTY</p> <p><b>Project Owner:</b>  RICHLAND TOWNSHIP MUNICIPAL AUTHORITY OF ALLEGHENY COUNTY</p>	<p><u>On 5/1/2025 10:53:00 AM at 3606 OAKCREST DR, RICHLAND TWP, ALLEGHENY</u> On Wednesday, October 15, 2025, at the DPC meeting, disputing party was Richland Township MA of Allegheny County. It was voted to Accept sections 4(2.2) and 5(4). Remove the penalty but keep the violation for section 5(16) and education. Remove the penalty and violation for section 5(8).  *****  Dispute- Richland Township Municipal Authority of Allegheny County is disputing all penalties and violations.  *****  The incident occurred on Thursday, May 1, 2025, at 3606 Oakcrest Drive, in Richland Township, Allegheny County.</p>	<p><b>RICHLAND TOWNSHIP MUNICIPAL AUTHORITY OF ALLEGHENY COUNTY: \$750.00</b>  Section 4(2.2) 1st Offense \$250.00</p> <p>Section 5(4) 1st Offense \$500.00</p> <p>Section 5(16) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>A gas line was damaged.</p> <p>Peoples Gas Company stated in their Alleged Violation Report (AVR), Richland Township Water was working along Oakcrest Drive when they struck an accurately marked PNG service line. Main to Curb. Peoples Gas provided photos of the damaged, served line. AVR does not mention a call to 911 was placed.</p> <p>Richland Township Municipal Authority, the excavator and project owner, did not submit an AVR within 30 days of striking the gas line.</p> <p>20250431657- Preliminary Design ticket was placed on 2/12/25, by Richland Township Municipal Authority. A Final Design ticket was not placed.</p> <p>Violations:</p> <p>*Richland Township Municipal Authority is in violation of sections:  4(2.2) – Failed to submit a design notification through the One Call System when a design drawing is completed.  5(4) – Excavator failed to exercise due care and employ prudent excavation techniques.  5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid.  5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line.  Recommendation: PUC Compliance Education Required and Penalties Applied.</p>	
54710	<p><b>Facility Owner:</b> UGI UTILITIES INC.  <b>Contractor/Excavator:</b> Z &amp; S CONSTRUCTION LLC  <b>Project Owner:</b> Homeowner</p>	<p><u>On 5/2/2025 1:15:00 PM at 138 JOHNS AVE, HAZLETON CITY, LUZERNE</u> On 10/15/2025: The Damage Prevention Committee (DPC) voted:</p> <p>Z&amp;S Construction LLC - Not in attendance  5(2.1)- Accept the DPI’s recommendation and add \$500.00 penalty for not attending DPC meeting. Penalty for this violation increased from \$1000.00 to \$1500.00.  5(6)(i)- Accept the DPI’s recommendation.  5(16)- Accept the DPI’s recommendation.</p> <p>*****  Z &amp; S CONSTRUCTION LLC is disputing.</p> <p>*****  The incident occurred on 05/02/2025 at 1:15 PM, at 138 Johns Avenue, in Hazleton City, Luzerne County.</p> <p>A gas line owned by UGI was damaged. 911 was called. There was not a Pa One Call ticket.</p> <p>UGI, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “Z &amp; S Construction was digging to landscape and when doing so they struck a correctly marked gas service facility creating a damage and a leak. Digging in the tolerance zone.” Photos were submitted.</p>	<p><b>Z &amp; S CONSTRUCTION LLC:</b>  <b>\$2,750.00</b>  Section 5(2.1) 1st Offense \$1,500.00   Section 5(6)(i) 1st Offense \$250.00   Section 5(16) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Z &amp; S Construction LLC is the excavator. An AVR has not been filed as of 06/26/2025.</p> <p>The homeowner is the project owner. An AVR has not been filed as of 06/26/2025.</p> <p>Routine ticket 20241710082 was requested in June of 2024 and the damage occurred in May of 2025, almost 1 year later. No utility mark outs seen in the submitted photos. A gas meter was in the area where the excavation occurred, and UGI had re responded "Field Marked" to the June 2024 ticket (for the same excavator), indicating there was underground gas lines in the area.</p> <p>Violations:</p> <p>Z &amp; S Construction LLC –</p> <ul style="list-style-type: none"> <li>- Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe.</li> <li>- Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area.</li> <li>- Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work.</li> </ul> <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
54965	<p><b>Facility Owner:</b> Danville Borough Municipal Authority Sewer</p> <p><b>Contractor/Excavator:</b> UGI Utilities, Inc</p> <p><b>Project Owner:</b> UGI Utilities, Inc - PLACEHOLDER</p>	<p><u>On 5/7/2025 11:11:00 AM at 749 GRAND ST, DANVILLE BORO, MONTOUR</u> On 10/15/2025 the Damage Prevention Committee (DPC) voted to keep the violation and education requirements, but to reduce the penalties to a warning for Danville Borough Sewer Department.</p> <p>Danville Borough Sewer Department disagrees. On 9/18/2025 Danville sent an email with 3 pictures that stated they want to share at the DPC meeting. On 9/19/2025 DPI Maki sent an email asking if there was any other information that should be added for the 3 violations. The pictures provided by Danville Borough show that the facility mark is over 18" away from the facility. which show the facility more than 18" away from the mark. On 9/22/2025 Danville Borough responded with an email that stated "That the work was boring not digging. it was boring perpendicular so crossing regardless measurement is not taken from center of pipe. We were on site and repaired the work communicating with contractor in person the entire time a lateral was struck which we cannot mark and the contractor is aware of that as they just struck a lateral last week. We work continuously with this contractor, and we have always been in contact with them seamlessly. Zero investigators spoke with our team on site". On 9/22/2025 DPI Maki sent an email providing</p>	<p><b>Danville Borough Municipal Authority Sewer: \$0.00</b></p> <p>Section 2(10) 1st Offense \$0.00</p> <p>Section 2(5)(i) 1st Offense \$0.00</p> <p>Section 2(5)(i.2) 1st Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>specific information asking for documentation to consider withdrawing any of the violations. Please see attachment named "DPI asks Danville Boro MAS about communication". On 9/24/2025 Danville sent an email with an attachment of a Verizon call log. This shows that calls were received from the same number ending in 4611 on May 7. The name Shawn Holdings is written by hand on the side of the highlighted 3 calls. On 10/02/2025 DPI Maki asked specifically what Danville Borough Municipal Authority Sewer is disagreeing with for the violations that were cited.</p> <p>*****</p> <p>The incident occurred on 5/07/2025 at 749 Grand St. in Danville Borough in Montour County.</p> <p>A sewer line owned by Danville Borough Municipal Authority Sewer was damaged.</p> <p>UGI the excavator and the project owner stated in their Alleged Violation Report (AVR) that “While digging to install a gas service, UGI crew struck and damaged an incorrectly marked sewer main. Sewer main was mis-marked by 32inches”. Pictures are provided.</p> <p>Danville Borough Municipal Authority Sewer the facility owner did not submit an AVR as of 9/22/2025.</p> <p><b>VIOLATIONS</b>  Danville Borough Municipal Authority Sewer is in violation of:  Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work.  Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.  Section 2(5)(i.2) – Failed to document Communications between a Facility Owner and Excavator to ensure the excavator is aware of a facility owner’s inability to locate it’s facilities.  Recommendation: The penalties are applied.  Compliance education is required.</p>	
54985	<p><b>Facility Owner:</b> Columbia Gas</p> <p><b>Contractor/Excavator:</b> Golden Triangle Construction Company, Inc.</p> <p><b>Project Owner:</b> Pennsylvania American Water (PAWC)</p> <p><b>Designer:</b> Bankson Engineers Inc</p> <p><b>Other:</b> Pittsburgh Department of Mobility</p>	<p><u>On 5/9/2025 10:45:00 AM at MINOOKA STREET, PITTSBURGH CITY, ALLEGHENY</u> On 10/15/2025 the Damage Prevention Committee (DPC) voted:  Golden Triangle Construction Co. 5(6)(ii) Accept the violation remove the penalty. Education is required.  Pittsburgh Water 2(5)(v) Accept violation and remove the penalty. Education is required.  *****  Pittsburgh Water - Dispute 2(5)(v)  Golden Triangle - Dispute 5(6)(ii)  ****</p>	<p><b>Golden Triangle Construction Company, Inc.: \$0.00</b>  Section 5(6)(ii) 1st Offense \$0.00</p> <p><b>Pittsburgh Department of Mobility and Infrastructure: \$500.00</b>  Section 2(5)(v) 1st Offense \$500.00</p> <p><b>Pittsburgh Water: \$0.00</b></p>

Case Number	Stakeholders	Summary	Violations & Recommendation
	<p>and Infrastructure  <b>Other:</b> Pittsburgh Water</p>	<p>The incident occurred on 5/9/2025 at 10:45 AM, on 116 Minooka Street, in Pittsburgh City, Allegheny County.</p> <p>A gas line owned by Columbia Gas Of Pa was damaged. 911 was contacted.</p> <p>Columbia Gas Of Pa is the facility owner. Their Alleged Violation Report (AVR) states, “Golden Triangle, working on behalf of PA American Water, was performing excavation work for a water main installation. Although prudent excavation techniques were used to uncover Columbia Gas’s 1" plastic gas service line, the crew failed to provide adequate trench support in the area of the exposed facility. This resulted in a trench wall collapse, which subsequently damaged the gas service. Emergency services, including 911 and Columbia Gas, were promptly notified. Columbia Gas responded to the scene, secured the area, and completed the necessary repairs.”</p> <p>Golden Triangle Construction is the excavator. Their AVR states, “Crew was working on installing 42” waterline along Minooka Street. A 1” gas service was located in front of trench box and had been exposed and safely dug around to make room for next section of pipe to be installed. In order to install pipe, crew needed to remove trench box from ditch and jump ahead of gas service line. As crew was removing the trench box from the ditch, the side of the ditch sloughed off into the ditch, contacting the 1” service line and causing damage requiring repair. 911 was called and Columbia Gas was contacted and sent a crew to repair the damaged service line within an hour.”</p> <p>Pennsylvania American Water is the project owner. Their AVR states, “The trench box was being removed from the trench in preparation to backfill and move the box along to the next portion. The trench collapsed as the box was being removed, resulting in damage to the exposed gas service line for 116 Minooka Street.”</p> <p>Bankson Engineers INC is the designer. An AVR has not been filed as of 06-13-2025.</p> <p>Multiple photos showing the site, excavation, trench box, and damage were submitted with the AVRs.</p> <p>Ticket # 20250692610 New – Excavation – Routine had a response due date of 3/12/25. Pittsburgh Water &amp; Sewer Authority did not respond to the Ticket.</p> <p>Ticket # 20251291900 New – Damage – Emergency was entered at 5/9/25, 11:21 AM. Pittsburgh Department of Mobility and Infrastructure did not respond to the Ticket.</p> <p>Violations:</p>	<p>Section 2(5)(v) 3rd  Offense \$0.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Excavator – Golden Triangle Construction: Section 5(6)(ii) – Excavator failed to provide support and mechanical protection for known facility owner’s lines at the construction work site. Recommendation: PUC Online Compliance Training is required.</p> <p>Facility(Other)- Pittsburgh Department of Mobility and Infrastructure- Ticket # 20251291900 Section 2(5)(v) – Failed to respond to a routine One Call ticket. Recommendation: PUC Online Compliance Training is required.</p> <p>Facility(Other)-Pittsburgh Water - Ticket # 20250692610 Section 2(5)(v) – Failed to respond to a routine One Call ticket. Recommendation: PUC Online Compliance Training was recently completed.</p>	
55054	<p><b>Facility Owner:</b> National Fuel GAS <b>Contractor/Excavator:</b> FRANKLIN CIITY GENERAL AUTHORITY / FRANKLIN CITY <b>Project Owner:</b> FRANKLIN CITY GENERAL AUTHORITY / FRANKLIN CITY - spacesaver</p>	<p><u>On 5/12/2025 11:00:00 AM at PARKER AVE, SUGARCREEK BORO, VENANGO</u> The General Authority of the City of Franklin is disagreeing. DPI reduced the \$1000. penalty to \$500 for violation section 5(16) for not submitting an AVR. This is a first-time offense. On 9/04/2025 an email was received asking for a reduction to the penalty. On 9/11/2025 DPI reduced the 5(4) violations from \$500. to \$250. and asked if 911 was notified. On 9/11/2025 an email response noted that General Authority of the City of Franklin did not notify 911. They also stated that they would like to have case 55054 discussed. On 9/15/2025 DPI emailed Franklin City General Authority / Franklin City asking if they still want to disagree despite the reduced penalties and to confirm that they want to attend the meeting. On 9/17/2025 an email received from Franklin City General Authority / Franklin City stated that "has agreed to the reduced fines and we are requesting to withdraw our appeal to the DPC".</p> <p>On 10/15/2025 the Damage Prevention Committee (DPC) voted to Remove the violation to National Fuel Gas (NFG). NFG is disputing. **** The incident occurred on 5/12/2025 at 11 Parker Ave in Sugarcreek Borough in Venango County.</p> <p>A gas line owned by National Fuel Gas was damaged.</p> <p>National Fuel stated in their Alleged Violation Report (AVR) that “Excavator struck natural gas distribution service line while installing a new water line. Excavator stated that they forgot about the service to 11 Parker Ave. Marks were not maintained. Please see the attachments”. Pictures were provided. 911 was not checked as being notified.</p>	<p><b>National Fuel GAS: \$0.00</b></p> <p><b>FRANKLIN CIITY GENERAL AUTHORITY / FRANKLIN CITY: \$1,750.00</b> Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(4) 1st Offense \$250.00</p> <p>Section 5(16) 1st Offense \$500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>FRANKLIN CIITY GENERAL AUTHORITY / FRANKLIN CITY the project owner and excavator did not submit an AVR until 7/08/2025. AVR was due by 6/12/2025. They stated that “ Water Dept Back hoe operator mistakenly hit a marked abandoned gas line service while installing new water main along Parker avenue in Rocky Grove”. They state that the cost was &lt;\$400,000. No pictures were provided.</p> <p>VIOLATIONS National Fuel GAS is in violation of: Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests.Ticket 20251040146 was submitted on 4/14/2025 by FRANKLIN CITY GENERAL AUTH/FRANKLIN CITY with a response due by 4/16/2025. National Fuel Gas responded on 4/15/2025 with Conflict. DCTF. This is not a final response. Recommendation: The penalty is applied. Compliance education was recently completed.</p> <p>FRANKLIN CIITY GENERAL AUTHORITY / FRANKLIN CITY is in violation of: Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid. Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or damaging a facility owner’s line during excavation or demolition or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: The penalty is applied. Compliance education is required</p>	
55112	<p><b>Contractor/Excavator:</b> Smucker Landscapes <b>Project Owner:</b> Homeowner <b>Other:</b> ELIZABETHVILLE AREA AUTHORITY <b>Other:</b> Pennsylvania Public Utility Commission <b>Other:</b> UPPER DAUPHIN AREA SCHOOL DISTRICT <b>Other:</b> WASHINGTON TOWNSHIP DAUPHIN CO</p>	<p><u>On 5/16/2025 1:30:00 PM at 154 JAMES ST, WASHINGTON TWP, DAUPHIN</u> On 10/15/2025: The Damage Prevention Committee (DPC) voted:</p> <p>Smucker Landscapes- 5(2.1)- Accept the DPI’s recommendation.</p> <p>Elizabethville Area Authority- Not in attendance at DPC meeting. 2(5)(vii)- Accept the DPI’s recommendation and increase the penalty by \$250.00 for not attending the DPC meeting. Penalty increased from \$1000.00 to \$1250.00.</p> <p>***** Smucker Landscapes is disputing the violation of 5(2.1). The violation of 5(5) was withdrawn.</p> <p>ELIZABETHVILLE AREA AUTHORITY is disputing. *****</p>	<p><b>Smucker Landscapes:</b> <b>\$1,000.00</b> Section 5(2.1) 1st Offense \$1,000.00</p> <p><b>ELIZABETHVILLE AREA AUTHORITY:</b> <b>\$1,250.00</b> Section 2(5)(vii) 1st Offense \$1,250.00</p> <p><b>UPPER DAUPHIN AREA SCHOOL DISTRICT: \$0.00</b> Section 2(5)(vii) 1st Offense \$0.00</p> <p><b>WASHINGTON TOWNSHIP DAUPHIN CO: \$1,000.00</b> Section 2(5)(vii) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>The incident occurred on 05/16/2025 at 1:30 PM, at 154 James Street, in Washington Township, Dauphin County.</p> <p>Non-damage event. Excavation without a PA One Call ticket.</p> <p>Smucker Landscapes, the excavator, submitted an AVR. Their AVR states, “We are a landscape company and we normally do a PA 1 call if we are digging with our machine. On this job we were using a wide flat bucket to prepare to reseed yard and not actually digging down,, just skimming of the existing decorative gravel to prepare for topsoil and yard reseeding. We had no idea you need to do a PA 1 call for that. Nothing was hit or damaged on this project.”</p> <p>Pennsylvania Public Utility Commission (PUC), the enforcement agency, submitted an AVR. Their AVR states, “Excavator was digging along the house with a backhoe with the DPI stopped the excavator to ask for an 811 ticket after seeing no mark outs. The excavator stated he didn’t have one and was only scraping the top layer. DPI told him to place a ticket and wait three days to dig. He stopped to call his office then began digging deeper with the excavator again. Photos are time and date stamped to show stoppage and restarting. Two more workers showed up and began using shovels while the excavator continued to dig with the backhoe. Videos of excavator digging with the backhoe are also available.” Photos were submitted.</p> <p>The homeowner is the project owner. An AVR has not been filed as of 06/25/2025.</p> <p>Photos were submitted by PPL from when their lines were marked.</p> <p>The excavator, Smucker Landscapes, was excavating without a PA One Call ticket. On 05/16/2025, a PUC Damage Prevention Investigator (DPI) stopped the excavator and asked if they had a PA One Call ticket, after noticing there were no utility mark outs in the area. The excavator advised they did not have a PA One Call ticket. The DPI advised the excavator to stop digging, request a PA One Call ticket and wait three days to dig. A ticket was not placed by Smucker Landscapes after this encounter, they continued to excavate. As seen in photos, an excavator with a backhoe was being used. DPI contacted PA One Call and placed a request for an Emergency No One Call ticket (20251362623) on 05/16/2025 at 1:44 PM. From the emergency ticket, electrical and telecom lines were located and marked out. Photos show the excavator with a backhoe digging within the tolerance zone of these marked lines. There were no arial lines in the area and there is a green electrical transformer located in the neighbor's front yard, indicating there are unground electrical lines in the area.</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Act 127 of 2024, Section 5(1) states it is the responsibility of the excavator to submit a locate request to identify the location and type of facility owner lines at each work site by notifying the facility owner through the One Call System. Notification shall be not less than three nor more than ten business days in advance of beginning excavation or demolition work. No work shall begin earlier than the lawful start date which shall be on or after the third business day after notification. The lawful start date shall exclude the date upon which notification was received by the One Call System and notification received on a Saturday, Sunday or holiday, which shall be processed on the following business day. In the case of a complex project, notification shall not be less than ten business days in advance of the beginning of excavation or demolition work.</p> <p>Act 127 of 2024 states: "Excavation work" means the use of powered equipment or explosives in the movement of earth, rock or other material, and includes, but is not limited to, anchoring, auguring, backfilling, blasting, boring, digging, ditching, dredging, drilling, driving-in, grading, plowing-in, pulling-in, ripping, scraping, trenching and tunneling.</p> <p>Emergency ticket 20251362623 had a response due date of 05/16/2025.  - Elizabethville Area Authority did not respond until 05/19/2025.  - Upper Dauphin Area School District did not respond to this ticket.  - Washington Township Dauphin CO did not respond until 05/27/2025.</p> <p>Violations:</p> <p>Smucker Landscapes –  -Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe.  -Section 5(5) – Excavator failed to exercise due care when facility owner is unable to mark within a mutually agreeable time frame. - Withdrawn.  Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Elizabethville Area Authority -  -Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket 20251362623.  Recommendation: The penalty is applied. PUC compliance training education is required.</p> <p>Upper Dauphin Area School District –  -Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket 20251362623.  Recommendation: PUC compliance training education is required. This is a warning no penalty assigned.</p> <p>Washington Township Dauphin CO –</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>-Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket 20251362623.</p> <p>Recommendation: The penalty is applied. PUC compliance training education is required.</p>	
55409	<p><b>Facility Owner:</b> Peoples Gas  <b>Contractor/Excavator:</b> Independent Enterprises  <b>Project Owner:</b> Pittsburgh Water  <b>Designer:</b> JOHNSON MIRMIRAN AND THOMPSON J M T</p>	<p><u>On 5/17/2025 10:30:00 AM at UVILLA ST, PITTSBURGH CITY, ALLEGHENY</u> On 10/15/2025: The Damage Prevention Committee (DPC) voted to remove the 2(5)(i) violation and penalty for Peoples Natural Gas.  *****  Peoples Gas Disputing 2(5)(i)  *****</p> <p>The incident occurred on 5/17/2025 at 10:30 AM, on Uvilla St, in Pittsburgh City, Allegheny County.</p> <p>A gas line owned by Peoples Gas Company was damaged.</p> <p>Peoples Gas Company is the facility owner. Their Alleged Violation Report (AVR) states, “Independent Enterprises struck and damaged a Peoples Gas service line. Peoples Gas marked the line via measurements due to no surface tracer wire. The road was completely torn up with no visible markings on the street. With that said, there do appear to be orange and pink markings denoting the contractor was aware of facilities. As shown in pictures 3 and 4, there were these markings, including an orange mark above the damaged gas service line.”</p> <p>Independent Enterprises is the excavator. Their AVR states, “Gas service line was marked outside of the 18” tolerance zone. It was approximately 30” off of where the actual service line was located. While installing the 4” underdrain on the lower part of Uvilla, contractors struck the plastic gas service line at 1020 Uvilla St. Their operator caught the tooth of his bucket against the service line, causing for it to rip into two pieces. The line was marked approximately 30” from where the service was actually located. Stop work was called immediately. Contractors were able to crimp off the service line with vise grips. 911 was called by Randy (IEI). Hit kit was deployed by CI. Pittsburgh Fire arrived on site at 10:40 am. No signs of gas leaking, they deemed the area safe and notified People’s Gas that a repair was needed at this time. People's Gas supervisor arrived on site at 12:15 pm. He was able to install a blunt cap over the supply side of the service. He let us know that another crew would be out to make the full repair. We also notified the homeowner of the broken gas line to their residence. Inspector and foreman remained on site til 5:00 pm but no repair crew showed up by this time.”</p> <p>Pittsburgh Water is the project owner. Their AVR states, “Gas service line was marked outside of the 18” tolerance zone. It was approximately 30” off of where the actual service line was located.”</p> <p>Johnson Mirmiran And Thompson J M T is the designer. Their AVR states, “Gas service line was marked outside</p>	<p><b>Peoples Gas: \$0.00</b></p> <p><b>Independent Enterprises: \$1,000.00</b>  Section 5(7) 1st Offense  \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>of the 18" tolerance zone. It was approximately 30" off of where the actual service line was located. Lines were shown on the bid documents.”</p> <p>Multiple photos of the site were submitted. A comparison of the locate image versus the damage image show the damage is not within the tolerance zone of the yellow marks. 2 additional marks appear in images after the original PCG locate image. It is undetermined who added these marks, one is pink and one is orange. All responses to Ticket 20251000420 are “Clear” except for Peoples Gas who responded “Field Marked”.</p> <p>This Case is related to Case 044579, 55492, and 045089 by design and complex project tickets.</p> <p>Violations:</p> <p>Facility – PGC: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: PUC Online Compliance Training was recently completed.</p> <p>Excavator - Independent Enterprises: Section 5(7) – Failed to immediately report to the facility owner any break or leak in its lines, or any dent, gouge, groove, or other damage to such lines or to their coating or cathodic protection. Recommendation: PUC Online Compliance Training is required.</p>	
55273	<p><b>Facility Owner:</b> PEOPLES GAS COMPANY LLC</p> <p><b>Contractor/Excavator:</b> JL EDWARDS</p> <p><b>Project Owner:</b> RYAN HOMES</p> <p><b>Other:</b> North Huntingdon Township</p> <p><b>Other:</b> North Huntingdon Township Municipal Auth</p> <p><b>Other:</b> Peoples Gas Company</p> <p><b>Other:</b> Verizon PA LLC</p>	<p><u>On 5/26/2025 12:31:00 PM at 6837 KATE CT, NORTH HUNTINGDON TWP, WESTMORELAND</u> On Wednesday, October 15, 2025, at the DPC meeting, disputing party is North Huntingdon Twp. It was voted to Accept the DPIs recommendations. *****</p> <p>Dispute- North Huntingdon Township rejects the report and requests to present our case before the DPC at a future meeting. *****</p> <p>Peoples Gas violation and penalty REMOVED because they placed the Excavation Emergency ticket to repair their gas line. *****</p> <p>The incident occurred on Monday, May 26, 2025, at 6837 Kate Court, in North Huntingdon Township, Westmoreland County.</p> <p>A gas line was damaged.</p> <p>Peoples Gas Company stated in their Alleged Violation Report (AVR), JL Edwards working for Ryan Homes installing sidewalks in new housing plan struck 1-inch PNG company side service line at the curb stop. Homeowner in area called 911 for odor of gas. PNG crews arrived onsite and found JL Edwards did not place a one call and struck S/L with skid steer while attempting to grade for sidewalk install. PNG supervisor and FCS squeezed the line to make it safe until PNG</p>	<p><b>JL EDWARDS:</b> <b>\$4,000.00</b> Section 5(2.1) 1st Offense \$1,000.00</p> <p>Section 5(7) 1st Offense \$1,000.00</p> <p>Section 5(8) 1st Offense \$1,000.00</p> <p>Section 5(16) 1st Offense \$1,000.00</p> <p><b>North Huntingdon Township: \$1,000.00</b> Section 2(5)(vii) 1st Offense \$1,000.00</p> <p><b>North Huntingdon Township Municipal Auth: \$1,000.00</b> Section 2(5)(vii) 1st Offense \$1,000.00</p> <p><b>Peoples Gas Company: \$0.00</b></p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>crew could arrive for repairs. JL Edwards was advised of the PA Law and 811 needed to be notified. After the damage was done JL Edwards placed 2 routine tickets 20251460248 and 20251460251 for the area. Peoples Gas provided photos of the damaged line.</p> <p>JL Edwards did not submit an AVR within 30 days of striking the gas line.</p> <p>20251460223- Excavation Emergency ticket was placed on 5/26/2025, by Peoples Gas to repair the gas line. No Response from: Verizon PA LLC Late Responses from: North Huntingdon Township responded on 5/27/25 as Clear No Facilities. North Huntingdon Township Municipal Auth responded on 5/27/25 as Clear No facilities. Peoples Gas Company responded on 5/27/25 as Field Marked.</p> <p>Violations:</p> <p>*JL Edwards Enterprises is in violation of sections: 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. 5(7) – Failed to immediately report to the facility owner any break or leak in its lines, or any dent, gouge, groove, or other damage to such lines or to their coating or cathodic protection. 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: PUC Compliance Education Required and Penalties Applied</p> <p>*Verizon PA LLC is in violation of section: 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20251460223 Recommendation: Penalty Applied</p> <p>*North Huntingdon Township is in violation of section: 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20251460223 Recommendation: PUC Compliance Education Required and Penalty Applied.</p> <p>*North Huntingdon Township Municipal Auth is in violation of section: 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20251460223 Recommendation: PUC Compliance Education Required and Penalties Applied.</p> <p>*Peoples Gas Company is in violation of section:</p>	<p><b>Verizon PA LLC:</b> <b>\$1,500.00</b> Section 2(5)(vii) 2nd Offense \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20251460223</p> <p>Recommendation: Penalty Applied</p>	
55397	<p><b>Facility Owner:</b> Westmoreland County Municipal Authority</p> <p><b>Contractor/Excavator:</b> W. A. PETRAKIS CONTRACTING COMPANY</p> <p><b>Project Owner:</b> Peoples Gas Company</p>	<p><u>On 5/27/2025 8:00:00 AM at MARILOU AVE, PENN TWP, WESTMORELAND</u> On Wednesday, October 15, 2025, at the DPC meeting, disputing party was MAWC, and their only disputing section 2(10). It was voted to Remove the Penalty but Keep the Violation and Education.</p> <p>*****</p> <p>Dispute- MAWC is disputing the \$1,000 penalty for failing to submit an AVR, and the education requirement. See their attached dispute email. They're not disputing 2(5)(i). See the attached email, MAWC Education Completed- They, MAWC last completed facility owner education on 2/13/2025. For case 055397, I would require education because the violation date 5/27/2025, was after they most recent completed education, completed on 2/13/2025: Compliance Test - Facility Owner &amp; Locator Municipal Authority of Westmoreland County Karl Shellgren 92 46171</p> <p>*****</p> <p>The incident occurred on Tuesday, May 27, 2025, on Marilou Avenue, in Penn Township, Westmoreland County.</p> <p>A water line was damaged.</p> <p>W. A. Petrakis Contracting Company stated in their Alleged Violation Report (AVR), while digging a trench for installation of natural gas main, the excavator encountered a water service that was off mark by 10 feet, therefore, 8.5 feet out of the tolerance zone. The line was damaged by digging with track-hoe machine. Westmoreland County Municipal Authority was contacted directly, and they sent a crew to repair their line. W. A. Petrakis Contracting is accepting no liability for the miss-marked line being damaged as we were digging far outside the tolerance zone. W. A. Petrakis Contracting provided photos of the miss-marked water line.</p> <p>Westmoreland County Municipal Authority did not submit an AVR within 30 business days of the line strike.</p> <p>Peoples Gas Company did not submit an AVR within 30 days of the line strike.</p> <p>Violations:</p> <p>*Westmoreland County Municipal Authority is in violation of sections:</p> <p>2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line.</p> <p>2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or</p>	<p><b>Westmoreland County Municipal Authority:</b> <b>\$500.00</b></p> <p>Section 2(5)(i) 1st Offense \$500.00</p> <p>Section 2(10) 1st Offense \$0.00</p> <p><b>Peoples Gas Company:</b> <b>\$1,000.00</b></p> <p>Section 6.1(7) 1st Offense \$1,000.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work.  Recommendation: PUC Compliance Education Required and Penalties Applied.</p> <p>*Peoples Gas Company is in violation of section: 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike.  Recommendation: Penalty Applied.</p>	
55492	<p><b>Facility Owner:</b> Peoples Natural Gas  <b>Contractor/Excavator:</b> INDEPENDENT ENTERPRISES  <b>Project Owner:</b> Pittsburgh Water  <b>Designer:</b> JMT Johnson, Mirmiran and Thompson</p>	<p><u>On 5/27/2025 2:00:00 PM at MARENA ST, PITTSBURGH CITY, ALLEGHENY</u> On 10/15/2025: The Damage Prevention Committee (DPC) voted to remove the 2(5)(i) violation and penalty for Peoples Natural Gas.  ****  Peoples Natural Gas - Disputing 2(5)(i)  *****  The incident occurred on 5/27/2025 at 2:00 PM, on Marena St, in Pittsburgh City, Allegheny County.</p> <p>A gas line owned by Peoples Gas was damaged. 911 was contacted. The facility was not notified by the excavator of the damage.</p> <p>Peoples Gas is the facility owner. Their Alleged Violation Report (AVR) states, “INDEPENDENT ENTERPRISES working for Pittsburgh Water and Sewer Authority was doing road reconstruction after a water line installation struck and damaged an improperly marked Peoples Gas owned service line. Peoples Gas marked the line via measurements due to no surface access to tracer wire. INDEPENDENT ENTERPRISES previously exposed this service line last year while doing this water line project and never alerted Peoples Gas to the fact that the markings on the line were off. This damage could have been prevented had INDEPENDENT ENTERPRISES renotified Peoples Gas. The attached pictures show that the line was marked last year for the water line, again this year for the road work and then the damage.”</p> <p>Independent Enterprises is the excavator. Their AVR states, “Gas service one call mark was approximately 44" off of where the actual service line was located at. Service line was only 13" from top of road. At approximately 2:00 pm, operator was digging out existing cobblestone block and road base at the 1000 block of Marena St. A gas odor was observed at 2:40 pm coming from what appeared to be the gas service line going to 1039 Marena St. Upon further investigation this was confirmed, there was a small pinhole in the plastic gas service line. Stop work was called at this time. 911 was notified of the situation at 2:47 pm, who then notified Pittsburgh Fire and People's Natural Gas. Inspector deployed hit kit and documented the damaged line. Pittsburgh Fire crew arrived on site at 2:53 pm. IEI was able to seal off the gas line from leaking any further prior to the fire company arriving. People's Gas supervisor on site at 3:30 pm. He was able to install a</p>	<p><b>Peoples Natural Gas:</b>  <b>\$0.00</b></p> <p><b>INDEPENDENT ENTERPRISES:</b>  <b>\$1,500.00</b>  Section 5(7) 2nd Offense  \$1,500.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>cap on the supply end of the service line. A repair crew from People's showed up at 4:00 pm and were able to reconnect the lines back together by 4:26 pm.”</p> <p>Pittsburgh Water is the project owner. Their AVR states, “Gas service one call mark was approximately 44" off of where the actual service line was located at. Service line was only 13" from top of road. At approximately 2:00 pm, operator was digging out existing cobblestone block and road base at the 1000 block of Marena St. A gas odor was observed at 2:40 pm coming from what appeared to be the gas service line going to 1039 Marena St. Upon further investigation this was confirmed, there was a small pinhole in the plastic gas service line. Stop work was called at this time. 911 was notified of the situation at 2:47 pm, who then notified Pittsburgh Fire and People's Natural Gas. Inspector deployed hit kit and documented the damaged line. Pittsburgh Fire crew arrived on site at 2:53 pm. IEI was able to seal off the gas line from leaking any further prior to the fire company arriving. People's Gas supervisor on site at 3:30 pm. He was able to install a cap on the supply end of the service line. A repair crew from People's showed up at 4:00 pm and were able to reconnect the lines back together by 4:26 pm. Lines were shown on the bid documents. No service line for 1039 was located and no information on service line locations provided by PNG.”</p> <p>Johnson Mirmiran And Thompson J M T is the designer. Their AVR states, “Gas service one call mark was approximately 44" off of where the actual service line was located at. Service line was only 13" from top of road. At approximately 2:00 pm, operator was digging out existing cobblestone block and road base at the 1000 block of Marena St. A gas odor was observed at 2:40 pm coming from what appeared to be the gas service line going to 1039 Marena St. Upon further investigation this was confirmed, there was a small pinhole in the plastic gas service line. Stop work was called at this time. 911 was notified of the situation at 2:47 pm, who then notified Pittsburgh Fire and People's Natural Gas. Inspector deployed hit kit and documented the damaged line. Pittsburgh Fire crew arrived on site at 2:53 pm. IEI was able to seal off the gas line from leaking any further prior to the fire company arriving. People's Gas supervisor on site at 3:30 pm. He was able to install a cap on the supply end of the service line. A repair crew from People's showed up at 4:00 pm and were able to reconnect the lines back together by 4:26 pm. Lines were shown on the bid documents. No service line for 1039 was located and no information on service line locations provided by PNG.”</p> <p>All images submitted with the AVRs show the yellow mark was not within 18 inches of the damaged gas line.</p> <p>This case is related to 044579, 045089, and 055409 by Ticket # 20233050371- Complex Project</p> <p>Violations:</p>	

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Facility – Peoples Gas: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: PUC Online Compliance Training was recently completed.</p> <p>Excavator - Independent Enterprises: Section 5(7) – Failed to immediately report to the facility owner any break or leak in its lines, or any dent, gouge, groove, or other damage to such lines or to their coating or cathodic protection. Recommendation: PUC Online Compliance Training is required.</p>	
55440	<p><b>Facility Owner:</b> Peoples Gas <b>Contractor/Excavator:</b> Kukurin Contracting, Inc. <b>Project Owner:</b> Frankstown Township <b>Designer:</b> STIFFLER MCGRAW AND ASSOCIATES</p>	<p><u>On 5/30/2025 7:55:00 AM at FIORE LN, FRANKSTOWN TWP, BLAIR</u> On 10/15/2025: The Damage Prevention Committee (DPC) voted on Kukurin Contracting Inc alleged violations: 5(3) Accept violation and penalty 5(6)(i) Accept violation and penalty ***** Kukurin Contracting Inc - Disputing ***** The incident occurred on 5/30/2025 at 7:55 AM, on Fiore Ln, in Frankstown Twp, Blair County.</p> <p>A gas line owned by Peoples Gas was damaged. 911 was contacted, 6 evacuated, according to Kukurin Contracting. Peoples Gas - 1 Customer ; 1-6 hours</p> <p>Peoples Gas is the facility owner. Their Alleged Violation Report (AVR) states, “THE CONTRACTOR HIT A MARKED SERVICE LINE”. Additional information provided by Peoples Gas, “I have attached pictures from the damage as well as pictures from two separate locates of the area showing the line was marked prior to the damage. Kukurin Contracting failed to maintain the markings crossing the road while working of Fiore Lane in Frankstown Twp. Kukurin Contracting failed to dig prudently within 18” of the tolerance zone of the gas markings of the facility. As you can see in both locate ticket requests pictures, the damaged facility was located properly with yellow paint. The three pictures labeled Fiore lane locate is for ticket 20251272818. The damage pictures shows the damage occurred approximately 6” from the remaining flag in the grass for this facility. “</p> <p>Kukurin Contracting Inc is the excavator. Their AVR states, “At 7:55am on May 30, Kukurin struck an unmarked 1" gas service near #206 Fiore Lane while excavating to install a sanitary sewer main for Frankstown Township. The gas line was struck near the west berm of Fiore Lane where there were no gas marks. The closest marks were only along the east berm. The struck line was crossing Fiore perpendicularly and there were not any marks for a gas crossing at this location.”</p>	<p><b>Kukurin Contracting, Inc.: \$750.00</b> Section 5(3) 1st Offense \$500.00</p> <p>Section 5(6)(i) 1st Offense \$250.00</p> <p><b>Frankstown Township: \$250.00</b> Section 2(5)(v.2) 1st Offense \$250.00</p>

Case Number	Stakeholders	Summary	Violations & Recommendation
		<p>Frankstown Township is the project owner. Their AVR states, "KUKURIN STRUCK AN UNMARKED NATURAL GAS LINE."</p> <p>Stiffler Mcgraw And Associates is the designer. Their AVR states, "Kukurin Contractor struck an unmarked 1" gas service line at 7:55 am on May 30, 2025, while installing a sanitary sewer main. Gas service line was providing service to a building at #206 Fiore Lane. The paint marks on the main gas line were marked, however the service line did not appear to be marked."</p> <p>Multiple photos were submitted of the site, damage, marks, and location. The area where the damage occurred is shown as being marked in pre-excavation photos with yellow paint marks, and yellow flags. When damage is seen, the road has been excavated in sections with stone and dirt across the areas that haven't been excavated, and the flags have been removed that were seen in the lawn on the same side of the street as the damage location. No Renotify or Update Tickets were located for this site.</p> <p>Ticket #20251272818 - FRANKSTOWN TOWNSHIP responded "SCHEDULED DATE &amp; TIME LINES WILL BE MARKED BY: 09 May 2025 1030" and did not enter a final response.</p> <p>This case is related to 052828, and 054221 by Ticket # 20242843085</p> <p>Violations:</p> <p>Excavator- Kukurin Contracting:  Section 5(3) – Excavator failed to preserve mark-outs or request a remark.  Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area.  Recommendation: PUC Online Compliance Training is required.</p> <p>Facility (other): FRANKSTOWN TOWNSHIP  Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests.  Recommendation: PUC Online Compliance Training is required.</p>	