

8 December 2016

To: The Pa Public Utility Commission Secretary
400 North Street
Harrisburg, PA 17120

From: Ross E. Schell
203 Knollwood Drive
Harrisburg, PA 17109-5515
PH# 717-651-0824
Fax# same but call First.

C-2016 - 2552834

To Whom this may Concern:

Notice of Exceptions to Initial Decision by judge Watson November 22 2016 received
12/08/2016

1. My electricity has gone out at least 10 times since PPL went crazy and hacked up trees all over the place. It went out August 23 2016 at least 3 times for at least 3-6

minutes this was after they cut the vegetation as you stated. This on and off has been going on for at least the last 17 years we have lived here. Since none of my neighbors are home most of the day they do not complain about it. Most do not even know their power went off during the morning or evening or afternoon.

2. They have summited proof that my power was going on and off over the year.
3. It has gone off since they cut the trees. When trying to file complaints since July regarding my power going off and on the secretary Reject it as a duplicate even though the dates are different. They will admit that it has gone off in the past yet not currently. It went off and on 4 times since July. Recently it has not gone off and on lately but winter is not quite here yet and it will start again.
4. Now I did ask for the incorrect relief on this complaint but they proved it was going off and on for the last 17 years. A monetary on off still violates the Law.

Ross E. Schell

Certificate Of Service

I do Herby Certify That I have This Day 08 December 2016 I Have Served a true And correct copy of the Exceptions 08 December 2016 upon The person's and manner Set Forth Below.

Via Fax Exceptions

Kimberly G. Krupka
33 S Seventh Street

P.O. box 4060

Allentown, PA 18105-4060

The Honorable Jeffery A. Watson

Piatt Place

Suite 220

301 5th Avenue

Pittsburg, Pa 15222 undeliverable

Ross E. Schell

Schell; 09010-71010

Wednesday, June 29, 2016
2:18:44 PM

OMS Outage History

Trouble Date & Time	Restored Date & Time	Job Number	Duration	Order Description	Cause	Weather Type	Comments
6/24/2007 7:00:00 AM	6/24/2007 7:00:00 AM	130870-1	0	NL Order	Unknown	Unknown	
8/2/2007 10:27:21 PM	8/3/2007 1:40:05 AM	148048-1	160	NL Order	Equipment Failures	Not a Factor	Received from SCADA: 22:27 08/02/2007 UG 3 phase cable failed SC-27715s35327 to SC-27502s35278. Problems with Bakelight Insulators between switches of GOLB-9526 at SC-27502s35278 caused approx. a 45 minute delay to restoring last 1339 customers. SC needs permanent repairs.
9/6/2007 8:54:21 AM	9/6/2007 8:54:21 AM	162232-1	0	NL Order	Unknown	Unknown	
11/2/2007 10:02:00 AM	11/2/2007 10:02:00 AM	180420-1	0	NL Order	Unknown	Unknown	
12/16/2007 5:06:00 AM	12/16/2007 5:06:00 AM	205962-1	0	NL Order	Unknown	Unknown	
12/16/2007 5:24:48 AM	12/19/2007 12:00:19 PM	208534-1	4716	NL Order	Trees-Not Trimming Related	Ice/Sleet/Snow	A & C phase S side loops opened at pole 26404s35107 for downed conductors pole 26404s35080 to pole 26403s35060. switch order H-462 WR 35449. Back in service at this time.
12/17/2007 12:45:00 PM	12/17/2007 12:45:00 PM	207559-1	0	NL Order	Unknown	Unknown	
4/30/2008 8:13:20 AM	4/30/2008 10:00:00 AM	253789-1	107	NL Order	Scheduled Outage	Not a Factor	tree trimming crew removed trees
6/16/2008 11:25:00 PM	6/16/2008 11:25:00 PM	277099-1	0	NL Order	Unknown	Unknown	
11/6/2008 8:34:00 AM	11/6/2008 8:34:00 AM	335897-1	0	NL Order	Unknown	Unknown	
5/5/2009 8:48:00 PM	5/5/2009 8:48:00 PM	387901-1	0	NL Order	Unknown	Unknown	
7/14/2009 8:12:00 AM	7/14/2009 8:12:00 AM	411445-1	0	NL Order	Unknown	Unknown	
4/28/2010 7:38:00 AM	4/28/2010 7:38:00 AM	507820-1	0	NL Order	Unknown	Unknown	
5/16/2010 6:19:00 AM	5/16/2010 6:19:00 AM	516918-1	0	NL Order	Unknown	Unknown	
5/29/2010 8:23:00 AM	5/29/2010 8:23:00 AM	521110-1	0	NL Order	Unknown	Unknown	
7/12/2010 4:47:00 PM	7/12/2010 4:47:00 PM	539134-1	0	NL Order	Unknown	Unknown	
7/18/2010 6:24:29 AM	7/18/2010 6:24:29 AM	542366-1	0	NL Order	Unknown	Unknown	
12/15/2010 6:07:00 PM	12/15/2010 6:07:00 PM	604022-1	0	NL Order	Unknown	Unknown	
2/21/2011 8:45:00 AM	2/21/2011 8:45:00 AM	627748-1	0	NL Order	Unknown	Unknown	
5/19/2011 3:45:00 AM	5/19/2011 3:45:00 AM	658805-1	0	NL Order	Unknown	Unknown	
7/29/2011 4:20:00 PM	7/29/2011 4:20:00 PM	699695-1	0	NL Order	Unknown	Unknown	
8/28/2011 6:28:00 AM	8/28/2011 1:15:55 PM	714514-1	407	NL Order	Trees-Not Trimming Related	Wind	::MDT ::SO audit complete per W1814**DMH
9/14/2011 7:49:00 PM	9/14/2011 7:49:00 PM	747643-1	0	NL Order	Unknown	Unknown	
9/14/2011 7:52:46 PM	9/15/2011 12:05:47 AM	747377-1	253	NL Order	Trees-Not Trimming Related	Rain	::MDT ::Tree Removed from conductors and conductors repaired (sleeved) at pole 26986s35029**SO audit complete per W0947**DMH
9/14/2011 9:21:00 PM	9/14/2011 9:21:00 PM	747655-1	0	NL Order	Unknown	Unknown	
9/15/2011 1:47:00 AM	9/15/2011 1:47:00 AM	747708-1	0	NL Order	Unknown	Unknown	
9/15/2011 2:27:00 AM	9/15/2011 2:27:00 AM	747710-1	0	NL Order	Unknown	Unknown	
9/15/2011 3:03:00 AM	9/15/2011 3:03:00 AM	747717-1	0	NL Order	Unknown	Unknown	
10/29/2011 3:07:00 PM	10/29/2011 3:07:00 PM	791317-1	0	NL Order	Unknown	Unknown	
10/4/2012 8:57:00 AM	10/4/2012 8:57:00 AM	915136-1	0	NL Order	Unknown	Unknown	
8/9/2013 5:15:00 AM	8/9/2013 5:15:00 AM	1046036-1	0	NL Order	Unknown	Unknown	
12/1/2013 8:38:00 AM	12/1/2013 9:50:31 AM	1082969-1	72	NL Order	Nothing Found (Explain)	Not a Factor	callout for sub repairman per SO.. rich dorman will work derek shearer will work. CB failure, did not cycle according to reclosing schedule.
1/13/2014	1/13/2014	1094600-1	0	NL Order	Unknown	Unknown	

9:39:29 AM	9:39:29 AM	1							
5/21/2014 9:41:06 AM	5/21/2014 10:37:00 AM	1285646-1	56	NL Order	Equipment Failures	Rain	Per Andy Pattison, failed fiber glass bracket at pole 26964s35049, will lift in the clear. H-0730		
6/5/2014 4:33:25 PM	6/5/2014 4:33:25 PM	1316439-1	0	NL Order	Unknown	Unknown			
7/11/2014 6:34:37 AM	7/11/2014 8:30:00 AM	1337880-1	116	NL Order	Equipment Failures	Not a Factor	::MDT No Required Permit per e60096 ::@1900-FM OFarrell sd I.Moyer taking call.Tman Welsko in enola. H-1005		
7/19/2014 10:22:59 AM	7/19/2014 10:22:59 AM	1341360-1	0	NL Order	Unknown	Unknown			
7/27/2014 6:23:21 PM	7/27/2014 6:23:21 PM	1344311-1	0	NL Order	Unknown	Unknown			
10/29/2014 9:02:01 AM	10/29/2014 9:02:01 AM	1374407-1	0	NL Order	Unknown	Unknown			
3/31/2015 12:00:16 PM	3/31/2015 12:00:16 PM	1418184-1	0	NL Order	Unknown	Unknown			
5/7/2015 11:47:53 AM	5/7/2015 11:50:00 AM	1429278-1	3	NL Order	Scheduled Outage	Not a Factor	balancing the load		
6/14/2015 5:35:40 PM	6/14/2015 5:35:40 PM	1764832-1	0	NL Order	Unknown	Unknown			
6/23/2015 4:17:45 PM	6/23/2015 4:17:45 PM	1915433-1	0	NL Order	Unknown	Unknown			
6/29/2015 11:40:18 AM	6/29/2015 11:40:18 AM	2065179-1	0	NL Order	Unknown	Unknown			
8/12/2015 1:07:00 PM	8/12/2015 1:09:00 PM	2134873-1	2	NL Order	Equipment Failures	Not a Factor	while performing switching for ABB relay upgrade jobs at Devonshire sub, the 22-2 CB was carrying the 22-4 12kV line, and then the 22-2 CB unexpectedly operated.		
9/1/2015 7:22:50 AM	9/1/2015 7:22:50 AM	2142440-1	0	NL Order	Unknown	Unknown			
9/1/2015 7:22:56 AM	9/1/2015 7:22:56 AM	2142441-1	0	NL Order	Unknown	Unknown			
9/22/2015 6:05:49 PM	9/22/2015 6:05:49 PM	2150585-1	0	NL Order	Unknown	Unknown			
9/22/2015 6:05:50 PM	9/22/2015 6:05:50 PM	2150586-1	0	NL Order	Unknown	Unknown			
9/25/2015 10:48:35 PM	9/25/2015 10:48:35 PM	2151771-1	0	NL Order	Unknown	Unknown			
2/7/2016 8:17:33 AM	2/7/2016 8:17:33 AM	3177278-1	0	NL Order	Unknown	Unknown			
5/10/2016 6:11:40 AM	5/10/2016 6:11:40 AM	3276230-1	0	NL Order	Unknown	Unknown			
5/31/2016 7:22:40 PM	5/31/2016 7:22:40 PM	3283767-1	0	NL Order	Unknown	Unknown			
6/16/2016 12:15:36 PM	6/16/2016 12:15:36 PM	3291388-1	0	NL Order	Unknown	Unknown			
6/27/2016 4:02:07 AM	6/27/2016 4:02:07 AM	3295165-1	0	NL Order	Unknown	Unknown			
7/4/2016 3:59:10 PM	7/4/2016 3:59:10 PM	3298511-1	0	NL Order	Unknown	Unknown			
9/4/2016 6:40:31 AM	9/4/2016 6:40:31 AM	3330281-1	0	NL Order	Unknown	Unknown			
9/7/2016 4:04:40 PM	9/7/2016 4:04:40 PM	3331302-1	0	NL Order	Unknown	Unknown			
9/23/2016 7:11:53 AM	9/23/2016 7:11:53 AM	3337500-1	0	NL Order	Unknown	Unknown			
9/23/2016 7:11:56 AM	9/23/2016 7:11:56 AM	3337501-1	0	NL Order	Unknown	Unknown			

Trouble Calls

1082969-1	12/1/2013 8:40:25 AM	No Lights	0901071010
1082969-1	12/1/2013 8:55:04 AM	No Lights	0901071010
1082969-1	12/1/2013 9:30:35 AM	Outbound ERT Call	0901071010
1285646-1	5/21/2014 9:44:24 AM	No Lights	0901071010
1285646-1	5/21/2014 10:28:33 AM	Outbound ERT Call	0901071010
148049-1	7/11/2014 6:49:15 AM	No Lights	0901071010
148049-1	8/2/2007 10:30:55 PM	No Lights	0901071010
148048-1	8/2/2007 10:46:28 PM	No Lights	0901071010
202533-1	12/16/2007 3:41:41 PM	No Lights/Wire Down	0901071010
714514-1	8/28/2011 8:02:13 AM	No Lights	0901071010
739358-1	9/6/2011 5:53:21 PM	No Lights	0901071010
747377-1	9/14/2011 7:53:29 PM	No Lights	0901071010
747377-1	9/14/2011 8:00:56 PM	No Lights	0901071010
747377-1	9/14/2011 10:18:06 PM	No Lights	0901071010

747377-1	9/15/2011 12:03:31 AM	No Lights	0901071010
768299-1	10/29/2011 3:23:47 PM	No Lights	0901071010
771509-1	10/29/2011 7:36:55 PM	No Lights	0901071010

Transformer Outage History (Pre-OMS History for Customer's Current Transformer)

Effected Grid	Trouble Time	Restore Time	Job Number	Duration	Cause	Weather
26482S35254	7/1/1998 2:54:00 AM	7/1/1998 3:02:00 AM	58982101	8	Vehicles	Not a Factor
26482S35254	6/22/2001 4:52:00 PM	6/22/2001 5:57:00 PM	58122201	65	Trees - Not Trimming Related	Lightning
26482S35254	1/31/2002 9:46:00 PM	1/31/2002 9:56:00 PM	58219201	10	Other - Non-Controllable	Rain
26482S35254	1/31/2002 9:46:00 PM	1/31/2002 10:50:00 PM	58219202	64	Other - Non-Controllable	Rain
26482S35254	12/15/2003 7:33:00 PM	12/16/2003 12:23:00 AM	58630801	290	Equipment Failure	Not a Factor
26482S35254	8/4/2004 4:42:00 AM	8/4/2004 5:04:00 AM	58728401	22	Nothing Found	Lightning
26482S35254	5/2/2006 3:06:00 PM	5/2/2006 4:22:00 PM	58382001	76	Animals	Not a Factor
26482S35254	2/1/2007 10:20:00 AM	2/1/2007 11:51:00 AM	58625901	91	Forced Prearranged	Not a Factor