



March 28, 2024

VIA E-FILING

Jonathan P. Nase

Direct Phone 717-773-4191

Direct Fax 215-372-2340

jnase@cozen.com

Rosemary Chiavetta, Secretary
Pennsylvania Public Utility Commission
Commonwealth Keystone Building
400 North Street
Harrisburg, PA 17120

Re: McCloskey v. Hidden Valley Utility Services, L.P. (Water and Wastewater Divisions) and Pennsylvania Public Utility Commission v. Hidden Valley Utility Services, L.P. (Water and Wastewater Divisions); Docket Nos. C-2014-2447138, C-2014-2447169, R-2018-3001306 and R-2018-3001307

Correspondence Filing Annual Reports for 2023

Dear Secretary Chiavetta:

In compliance with the Settlement Agreement approved by the Pennsylvania Public Utility Commission by Order entered on December 21, 2023 at the above-referenced dockets, enclosed please find:

1. The Company's customer complaint logs, as required by Paragraph 52 of the Joint Petition for Settlement filed on May 25, 2023 (the "Settlement").
2. A report regarding operation and maintenance activities for 2023, as required by Paragraph 55 of the Settlement.

Additionally, Paragraph 56 of the Settlement Agreement provides:

If requested by the Hidden Valley Foundation's Board of Directors, HVUS will meet with representatives of the Hidden Valley Foundation's Board of Directors, virtually or in-person, at least once per calendar year, from 2023 through December 31, 2023.

The President of HVUS is scheduled to meet with the Hidden Valley Foundation's Board of Directors in April, 2024.

Copies of this filing have been served as shown on the enclosed Certificate of Service.

Rosemary Chiavetta, Secretary
March 28, 2024
Page 2

Respectfully submitted,

COZEN O'CONNOR



By: Jonathan P. Nase
Counsel for *Hidden Valley Utility Services, L.P.*

JPN

Enclosures

cc: Honorable Katrina L. Dunderdale
Per Certificate of Service

**BEFORE THE
PENNSYLVANIA PUBLIC UTILITY COMMISSION**

Tanya J. McCloskey, Acting Consumer Advocate	:	
	:	
	:	Docket Nos. C-2014-2447138
v.	:	and C-2014-2447169
	:	
Hidden Valley Utility Services, L.P. (Water and Wastewater Divisions)	:	
	:	
and	:	
	:	
Pennsylvania Public Utility Commission	:	
	:	
	:	
v.	:	Docket Nos. R-2018-3001306
	:	and R-2018-3001307
	:	
Hidden Valley Utility Services, L.P. (Water and Wastewater Divisions)	:	
	:	

CERTIFICATE OF SERVICE

I hereby certify that I have this day served a true copy of the foregoing **Correspondence Filing Annual Reports for 2023** upon the parties, listed below, in accordance with the requirements of 52 Pa. Code § 1.54 (relating to service by a party).

VIA E-MAIL AND FIRST CLASS MAIL:

Christine Maloni Hoover, Esq.
Erin L. Gannon, Esq.
Office of Consumer Advocate
555 Walnut Street
Forum Place, 5th Floor
Harrisburg, PA 17101-1923
CHoover@paoca.org
EGannon@paoca.org
Counsel for *Office of Consumer Advocate*

Allison Kaster, Esq.
Pennsylvania Public Utility Commission
Bureau of Investigation and Enforcement
Commonwealth Keystone Building
400 North Street, 2nd Floor West
Harrisburg, PA 17120
akaster@pa.gov
Counsel for *Bureau of Investigation and Enforcement*

Sharon Howard-Frieri
P.O. Box 4126
1174 Gristmill Court
Hidden Valley PA 15502
sharonhoward.frieri@yahoo.com

Robert J. Kollar, CPA and
Kellie A. Kuhleman
1374 Langport Dr.
Pittsburgh, PA 15241
bob@kkacpas.com

Terry L. Fought
780 Cardinal Drive
Harrisburg, PA 17111
foughtbusiness@gmail.com
Consultant for
Office of Consumer Advocate

DATED: March 28, 2024



Jonathan P. Nase, Esquire
Counsel for *Hidden Valley Utility Services, L.P.*

Hidden Valley Utility Services LP

2023

Customer Complaints – Water & Sewage

1/5/23	HL1587	Water leak in back yard. Repaired leak, tap on main for 1588.
1/9/23	SR1901	High usage. Due to leak in unit. 0.3 gpm while water is on.
1/22/23	Summit	Air in lines. Due to leak survey and repair on 1/18/23
2/21/23	AW4534	Sewer backup. Dug line found wye broken and had roots. Replaced.
3/16/23	P3B156	Dirty water. Due to water leak at P3B698. Line blew apart for P3B021 after repairs. Installed new taps for 698, 021 and 157.
3/17/23	P3B156	Low pressure. Due to continued flushing of Ridgeview Road.
5/29/23	PR2740	Low pressure. Booster pump in unit kicked out on ground fault breaker.
7/7/23	HL1456	Black particles floating in water. Flushed at Blow off. Blow off not operating, broken wire to timer.
7/20/23	HTS551	Hot water smells. Advised h/o to flush their hot water tank.
8/7/23	SV5143	Dirty water. Flushed at golf course hydrant. Valve off in summit that should have been open. Ran auto blowoff two times.
8/25/23	SV5143	Dirty water upon arriving. Flushed at golf hydrant. Valved everything through North Summit.
10/16/23	SV5143	Dirty water upon arriving. Flushed h/o hot water tank 474 gallons.
11/15/23	FW1747	Dirty water. H/O says steam unit on shower is corroding and toilets have a yellow ring in them. Flushed Hightop Circle and took Fe, Mn, and TDS sample to Geochemical from outside and inside laundry tub. Spoke to Tony at Specialty Water who maintains home water softener unit, booster pump is for shower that uses 31 gpm.
12/24/23	HVW423	Low pressure. Adjusted PRS valves. 30psi to 45psi.

HIDDEN VALLEY UTILITY SERVICES

MONTHLY REPORT 2023

JANUARY

Pressure reducing stations checked

Pump stations checked

Leak repair 1914 @ curb stop

Installed 3" valve behind 1914

Leak repair 1588 galv. Fitting on main

Leak inside 1723 shut off

Leak 5031 shut off

Clearwell pump #1 fault on Sunday 1/29/23

FEBRUARY

Opened filter 3 no mudballs, smooth, media looked good.

Clearwell pump #1 pulled and replaced motor

Pressure reducing stations checked

Pump stations checked

Sewer wye replaced 4534

MARCH

Raw water pump #4 check valve replaced

Leak 3b706 curb stop broke

Replaced curb stops 706, 698, 157

Flushed ridgeview road

Meter reads - 3 days

Leak repair 1579 curb inserts

Leak repair 1576 main insert

Leak repair 2315 curb insert to lot

Leak repair 1843 main insert

APRIL

Installed Well #2 VFD

Installed clearwell pump #1 check valve

Installed water filter bldg. trim

Checked pressure reducing stations

Pump stations checked

Dug and replaced fittings 1575, 1576, 1572, 1573, 1574, 1580, 1577, 1578

Pulled westridge pump station #1 Pump #1 unclogged flushable wipe and installed new start capacitor

Ski maint garage leak shut off

MAY

Installed Lagoon pump #2

Singles installed on Well #8 pump building

Installed water bldg. trim

Restore yards from water repairs

Shut off 1161 leak inside

Plant 2 trimming

Sludge removal from Plant 1

Lagoon trimming, unclog fountain

EQ tank trimming

EQ tank painting

Install wall fan EQ blower room

Leak detection

Water system flushing

Pressure reducing station checks

Pump stations checked

JUNE

Leak Detection – Ski Lodge PRS

Dug for Lagoon valve replacement

Clearwell Pump #1 Check valve replacement with spool piece

Cleaned and patched Chlorine contact tanks

Leak repair 1165

Sprayfield samples

Meter reads

Pressure reducing station checks

Pump stations checked

Dug water line and installed curb stop HVW426

Replaced truck vacuum pump

Clear cattails from Lagoon

Patched Chlorine contact tank #1

Patched Clearwell

JULY

Pressure reducing station checks

Pump stations checked

Meter rechecks one pulled for testing

Pulled Influent pump #1 Plant 1 clogged

Flushed lines at Gebhart

Fixed yard 2315

Leak found at 5031 shut off at curb for condo assoc.

Valve exercise for 3 days

Installed air release valves on Filters 3 & 4

Flow meter calibration at both Wastewater Plants

Installed 4" D.I. valve at ski lodge

Sprayfield samples

AUGUST

Meter pit installed at HVW426

Leak detection

Leak repair 1498 curb stop & fitting replaced

Well #1 off radio circuit

Pressure reducing station checks

Pump stations checked

Leak repair VV59 tee on main replaced with saddle

Leak repair 3" main to Ridgeview, glue coupling replaced.

Air drop repair EQ Tank #2

Blower 3 belts replaced, broken check valve in discharge valve removed.

Replaced chlorine tubing at Plant 2

Yard repairs 1914 & 1587

SEPTEMBER

Leak repair P3B 157 curb stop.

Flushed Ridgeview Road.

Leak repair SR1967 curb stop.

Meter reads.

North Summit Blow off new diaphragm.

Pump stations checked.

OCTOBER

Leak repair SF1613 curb stop.

Installed 3" valve in main to South Ridge Terrace Lots.

SR1959 water off for leak at inside filter unit.

Leak repair at Heights Blow off.

Nighttime leak detection two nights 9/9 and 9/10.

Remount floats in wet well Plant 2.

Leak repair HTS 564 service line.

New slide rails in wet well Plant 2 for both pumps.

Yard repair HTS 564

Pumps stations checked.

NOVEMBER

Removed Plant 2 Effluent pump 1 discharge check valve and piping.

Lowered New pump into basement.

Installed Plant 2 new influent pump 2. Flight 5hp.

Installed Plant 2 new influent pump 1. Flight 5hp.

Pump stations checked.

Ski lodge PRS 2" in valve broke. Replumbed w/brass fittings and new 2" valve.

CRD replaced on 6" PRV at ski lodge PRS.

New injection fitting on caustic feed.

New belts installed on Plant 1 Blower #4.

Cleaned strainer on Conf. Center 2" meter.

Leak repair HL1515 curb stop.

Leak repair PN2403 main saddle insert. Thanksgiving Day.

Leak repair HL 1493 curb stop. Thanksgiving Day.

DECEMBER

New snowmaking main meter installed.

FW1713 off for plumber.

Leak repair HL1475. 3" main split.

Meter reads.

Line flushing 3 days.

Pump stations checked.