

On the date and at the time described on page one of this Complaint, the following violations were disclosed:

52 Pa. Code §29.306 - Failed to have consumer info decal on vehicle. (Scheduled Route) \$50

52 Pa. Code §29.314(b)(7) - Inoperative meter in taxi. \$1,000

 ORIGINAL

RECEIVED

NOV 21 2013

PA PUBLIC UTILITY COMMISSION
SECRETARY'S BUREAU

Inspection Information:

100 Mine Street, Hazleton, Luzerne County, PA, 18201
June 3, 2013, 9:15 AM

Vehicle Information:

Taxi #6, 2006 Dodge Caravan
PA, TX47217, 1D8GP45R16B599658

DVCR # 004313 1045

Authorized Officer Performing Inspection: Steven E. Watkins, #43


On the date and at the time described above, the following violations were disclosed:

67 Pa. Code Ref §175.65 – Left front wheel had 1 stud and nut totally missing. \$100

67 Pa. Code Ref §175.65 - Left Steering tire had no measurable tread. \$100

WHEREFORE, the Bureau of Investigation and Enforcement hereby requests that the Commission fine respondent the sum of **\$1,250.00** for the illegal activity described in this Complaint and order any other remedy as the Commission may deem appropriate.

Respectfully submitted,



David W. Loueks, Chief
Motor Carrier Enforcement
Bureau of Investigation and Enforcement
P.O. Box 3265
Harrisburg, PA 17105-3265

La Union Tax LLC
1126 Market St
Berwick PA 18605


CERTIFIED MAIL™



7013 1090 0002 3919 8403



UNITED STATES
POSTAL SERVICE



17105

1000

U.S. POSTAGE
PAID
HAZLETON, PA
18201
NOV 21 2013
AMOUNT

\$3.56
00045655-03

Rosemary Chivetta Secretary
Pennsylvania Public Utility Commission

P.O. Box 3225

Harrisburg PA - 17105-3225

171053225

