

August 26, 2014

Via Electronic Filing

Rosemary Chiavetta, Esquire
Secretary
PA Public Utility Commission
Commonwealth Keystone Building, 2 North
P.O. Box 3265
Harrisburg, PA 17105-3265

**Re: Docket No. C-2014-2417835
E. McCauley v. Pennsylvania Electric Company
Motion of Penelec for Admission of Exhibits**

Dear Secretary Chiavetta:

Attached for filing, please find the Motion of Pennsylvania Electric Company ("Penelec") for Admission of Exhibits into Evidence in the above-captioned proceeding.

As indicated on the Certificate of Service, a copy of the Motion has been provided to the Complainant in the manner indicated.

If there are any questions, please do not hesitate to contact me.

Very truly yours,

Reger Rizzo & Darnall LLP



Margaret A. Morris

MAM/jmm
Enclosures

cc: The Honorable Katrina L. Dunderdale, PA PUC, via email w/encls.]
Lauren Lepkoski, Esquire, FirstEnergy Service Company [w/encls.]
E. McCauley [w/encls.]

**Re: Docket No. C-2014-2417835
E. McCauley v. Pennsylvania Electric Company
Motion of Penelec for Admission of Exhibits**


CERTIFICATE OF SERVICE

I hereby certify that a true and correct copy of the foregoing document has been served upon the following persons, in the manner indicated, in accordance with the requirements of § 1.54 (relating to service by a participant).

Via First Class Mail

E. McCauley
2550 State Route 49
Westfield, PA 16950

Dated: August 26, 2014


Margaret A. Morris, Esquire

**BEFORE THE
PENNSYLVANIA PUBLIC UTILITY COMMISSION**

E. MCCAULEY

v.

PENNSYLVANIA ELECTRIC COMPANY

:
:
:
:
:

Docket No. C-2014-2417835

NOTICE TO PLEAD

Pursuant to 52 Pa.Code § 5.103, you are hereby notified that if you do not file a written response answering the enclosed Motion of Pennsylvania Electric Company within ten (10) days from service of this Notice, the facts set forth by Pennsylvania Electric Company in the Motion may be deemed to be true, whereby requiring no other proof. All pleadings, such as a Reply to Motion, must be filed with the Secretary of the Pennsylvania Public Utility Commission, with a copy served to counsel for Pennsylvania Electric Company, Margaret A. Morris, Esq., and to the presiding Administrative Law Judge, the Honorable Katrina L. Dunderdale.

File with:


Rosemary Chiavetta, Esq.
Secretary
Pennsylvania Public Utility Commission
Commonwealth Keystone Building – 2 North
P.O. Box 3265
Harrisburg, PA 17105

With a copy to:

The Honorable Katrina L. Dunderdale
PA Public Utility Commission
Piatt Place, Suite 220
301 Fifth Avenue
Pittsburgh, PA 15222

Margaret A. Morris, Esquire
Reger Rizzo & Darnall LLP
Cira Centre, 13th Floor
2929 Arch Street
Philadelphia, PA 19104

Date: August 26, 2014



Margaret A. Morris, Esq.
Reger Rizzo & Darnall LLP
Cira Centre, 13th Floor
2929 Arch Street
Philadelphia, PA 19104
(215) 495-6524 tel.
(215) 495-6600 fax
mmorris@regerlaw.com

Counsel for Pennsylvania Electric
Company

4. By Hearing Notice dated August 19, 2014, this matter was reassigned to the Honorable Katrina L. Dunderdale at the above noted date and time.

5. Penelec Exhibits 1 through 6 were sponsored at the time of hearing by Penelec witness Kurt Durland, Supervisor of Distribution Planning, Protection & Reliability.

6. The August 20, 2014 hearing was concluded before Penelec moved Exhibits 1 through 6 into evidence.

7. The evidentiary record in this proceeding remains open.

8. Penelec Exhibits 1 through 6 are relevant to the issues in this proceeding and will assist Judge Dunderdale and the Commission in its disposition of the issues raised by both parties.

9. The Complainant was consulted after the hearing and does not object to the admission of Penelec Exhibits 1 through 6 into evidence.

10. The Complainant will not be unfairly disadvantaged by admitting Penelec Exhibits 1 through 6 into evidence.


11. Penelec witness, Kurt Durland, was available at the time of hearing to address any questions or issues in regard to Exhibits 1 through 6; no questions or issues were raised at the hearing.

12. It is in the public interest to admit Penelec's Exhibits 1 through 6 into evidence in these proceedings.

WHEREFORE, for the foregoing reasons, Pennsylvania Electric Company, respectfully requests that its Motion for Admission of Exhibits be granted and its Exhibits 1 through 6 be admitted into evidence.

Respectfully submitted,

Date: August 26, 2014



Margaret A. Morris, Esq.
Attorney ID No. 75048
Reger Rizzo & Darnall LLP
Cira Centre, 13th Floor
2929 Arch Street
Philadelphia, PA 19104
(215) 495-6524 tel.
(215) 495-6600 fax
mmorris@regerlaw.com

Counsel for Pennsylvania Electric Company

Docket No. C-2014-2417835
E. McCauley v. Pennsylvania Electric Company

Attachment 1

Previously Submitted Exhibits 1-6

CUSTOMER CALL NOTIFICATION

WORK TYPE: Voltage Problem - On/Off Lights

Notification: 330355970 **Type:** CC
Work Request:

SM Order:

Short Text:

Malfunction Start: 12/20/2013 @ 19:53:44

Work Complete: /
(Malfunct. End) Date / Time

Reported by: E MCCAULEY

Phone: (814)334-5527

BUSINESS PARTNER

Business Partner No.: 800494529

Contract Acct. No.: 100008649921

PREMISE INFORMATION

Premise No.: 3083921
2550 SR 49
WESTFIELD PA 16950

Phone: (814)334-5527

TECHNICAL INFORMATION

Pole Key: SEH-9863
Maintenance Group: 327 (Westfield)
Tax District: 00001104
Tax Location: HARRISON - PA
Tax County: POTTER

Meter: A87666825 1 Phase
Main Wrk Ctr: DMC-PA
MRU-Seq: P706357-0024

Long Text:

* sw E MCCAULEY has just experined 3 reclosers within the last 2 hours

Comments:

Complete in: PRD(010)

Name (Please Print)



PRD /

PROVED

Order #: 8689062-1 Type: Outage

Status: Archived

Priority: 5

Special:

Time Off: 12/21/13 02:29 PM
Created: 12/21/13 02:45 PM
Assigned:
Patched:
In Route:
Arrived:

Last Restoration: 12/21/13 02:50 PM
Field Complete: 12/21/13 06:20 PM
Closed: 12/21/13 06:20 PM
ETR: 12/21/13 04:45 PM
Number of Calls: 16
Customers Affected: 298

Crew:
Crew Area: WESTFIELD CA
Duration (Min): 21
Total CMI: 6258
Work Desc: No Lights

Current Org: Dispatch
Owner: McDaniel, Thomas

Substation: HARRISON VALLEY
Circuit: 00738-63

Dispatch Center: Mansfield PA District
Dispatch Area: Towanda Oper Area

ID: Circuit HARRISON VALLEY-0

Type: Circuit Lockout

Voltage: 1247 V / 7.2 kV

Event Details


Cause: Equipment Failure
Cause Pole: Pole SEH-6363
Failed Comp: Arrester
Facility Location: HARRISON VALLEY
Action Taken: Isolated

Outage Type: Subtransmission
Weather: Raining
Follow Up:
Related Events:
Follow Ups Sent:

Comments:

Arrester tracking on pole SEH-63 caused RCL on pole 1D342 to lock open at 14:29 causing loss of supply at Harrison Valley. Switching on PN-13-25867-SC. Restored at 14:50. Related PO#'s 8689053, 8689061, 8689062, 8689105, 8689109, %2526 8689110.

Order Instructions:



Order Details [8689110-1]

PROVED

Order #:	8689110-1	Type:	Outage	Status:	Archived	Priority:	5	Special:	
Time Off:	12/21/13 05:19 PM	Last Restoration:	12/21/13 05:23 PM	Crew:		Crew Area:	WESTFIELD CA	Duration (Min):	4
Created:	12/21/13 05:27 PM	Field Complete:	12/21/13 06:29 PM	Total CMI:	1192	Work Desc:	No Lights		
Assigned:		Closed:	12/21/13 06:29 PM						
Patched:		ETR:	12/21/13 07:27 PM						
Number of Calls:	8	Customers Affected:	298						

Current Org:	Dispatch	Substation:	HARRISON VALLEY	Dispatch Center:	Mansfield PA District
Owner:	Gavio, John A	Circuit:	00738-63	Dispatch Area:	Towanda Oper Area

ID:	Circuit HARRISON VALLEY-4	Type:	Circuit Lockout	Device Info		Voltage:	1247 V / 7.2 kV
-----	---------------------------	-------	-----------------	-------------	--	----------	-----------------

Cause:	Forced Outage	Outage Type:	Subtransmission
Cause Pole:	Pole SEH-6363	Weather:	Raining
Failed Comp:	Arrester	Follow Up:	Auto generate of SAP followup d
Facility Location:	HARRISON VALLEY	Related Events:	
Action Taken:	Isolated	Follow Ups Sent:	Line

Comments:
 Forced outage to isolate arrester on pole SEH-63.
 Opened RCL on pole SEH-1 at 17:19. Restored at 17:23. Switching on PN-13-25867-SC. Related PO#s 8689063, 8689061, 8689062, 8689105, 8689109, % 2526 8689110.

Order Instructions:

Page 2 of 2

Order Details [8688791-1]

Order #: [8688791-1] Type: [Outage]

Status: [Archived]

Priority: [5]

Special: []

Time Off: [12/20/13 09:31 PM]
 If Created: [12/20/13 09:42 PM]
 Assigned: [12/20/13 10:12 PM]
 Patched: [12/20/13 10:12 PM]
 On Route: [12/20/13 10:12 PM]
 Arrived: [12/21/13 12:44 AM]

Last Restoration: []
 Field Complete: [12/21/13 12:44 AM]
 Closed: [12/21/13 12:44 AM]
 ETR: [12/21/13 02:42 AM]
 Number of Calls: [7]
 Customers Affected: [0]

Crew: [Chappell, Steven]
 Crew Area: [WESTFIELD CA]
 Duration (Min): [0]
 Total CMI: [0]
 Work Desc: [No Lights]

Current Org: [Dispatch]

Owner: [Musselman, Thomas]

Substation: [HARRISON VALLEY]

Circuit: [00738-63]

Organization

Dispatch Center: [Mansfield PA Distinct]

Dispatch Area: [Towanda Oper Area]

ID: [Customer 0001102484]

Type: [Customer]

Device Info

Voltage: [1247 Y / 7.2 kV]

Event Details

Cause: [Call Error]
 Cause Pole: []
 Failed Comp: []
 Facility Location: [103 W MAIN ST]
 Action Taken: []

Outage Type: [No Outage]
 Weather: []
 Follow Up: []
 Related Events: []
 Follow Ups Sent: []

Comments:

Multiple trips on 34KV Cowanessque RCL @ Knoxville. Fl's fit on center phase at pole SEH-40. Tony F saw nothing obvious from road. Problem likely between SEH-40 and SEH-66.

Order Instructions:

[]



Page 1 of 2

Order Details [8688787-1]

Order #: [8688787-1] Type: [Trouble]

Status: [Archived]

Priority: [6]

Special: []

Time Off: [12/20/13 09:34 PM]
Order Create: [12/20/13 09:35 PM]
Assigned: []
Dispatched: []
En Route: []
Arrived: []

Last Restoration: []
Field Complete: [12/21/13 01:45 AM]
Closed: [12/21/13 01:46 AM]
ETR: []
Number of Calls: [2]
Customers Affected: [0]

Crew: []
Crew Area: [WESTFIELD CA]
Duration (Min): [0]
Total CMI: [0]
Work Desc: [Voltage Problem - On/Off Li

Current Org: [Dispatch]
Owner: [Musselman, Thomas]

Substation: [SABINSVILLE TRANS]
Circuit: [00563-63]

Dispatch Center: [Mansfield PA District]
Dispatch Area: [Towanda Oper Area]

ID: [Electric Service Point]

Type: [Unknown]

Voltage: [34.5 V / 19.9 kV]

Event Details

Cause: [Unknown]
Cause Pole: [Unknown]
Failed Comp: []
Facility Location: [KRUSEN ST, 205, WESTFIELD, PA]
Action Taken: []

Outage Type: [No Outage]
Weather: []
Follow Up: [F/U to line to replace line arrester]
Related Events: []
Follow Ups Sent: [Line]

Comments:

F/U to line to replace line arresters on pole SEH-63

Order Instructions:

[]

Page 2 of 2

FirstEnergy

Line Recloser Annual Inspection

Work Request: Q55603488 SAP Order #: 13388178
 Functional Loc: PNDNP9690662, D Pole UNK WESTFIELD-ULYSSES
 On St. / X St.: UNK / See circuit map
 Station Number: 6H4963 Sub: HARRISON VALLEY Ckt: 00738-63

GENERAL INFORMATION

Line Shop: PWLWF Pole #: 191081, 6H4963

Remarks: _____

Mark the appropriate columns to designate: Pass = (no problem), WR = Work Required, C = Work completed during inspection											
Pole Condition (EDD/POLE)	Pass	WR	C		Pass	WR	C		Pass	WR	C
Pole damaged / deteriorated [223]	X			Conductor damaged / problem [235]	X						
Crossarm broken / damaged [227]	X			Primary clearance problem [239]	X						
Crossarm brace broken / damaged [228]	X			Mounting rack problem [211]	X						
Pins or hardware damaged / loose [230]	X			Ground broken / needed [210]	X						
Guy broken or problem [232]	N/A			Other - include text in Remarks [213]	N/A						
Recloser Control (EDD/RECL)	Pass	WR	C		Pass	WR	C		Pass	WR	C
Control problem [216] <i>HYD.</i>	X			Control lock needed [218]	X						
Counter problem [217]	X			Power source / battery problem [219]	N/A						
Recloser Equipment Records By Phase From SAP (Not required)											
Equipment Number	191081			191082							
Phase	A			C							
Assignment Code											
Company Number											
Manufacturer	KY			KY							
Mfr. Serial number	CP571012081			CP571012076							
Recloser Type	L			L							
Current Rating	50			50							
Interrupt Ability	0			0							
Fault Current											
Last Counter Read Date	01/18/2012			01/18/2012							
Last Counter Reading (Total/Last)	51 / 0			38 / 0							
Current Counter Reading	52			38							
Recloser Condition (EDD/RECL)	Pass	WR	C	Pass	WR	C	Pass	WR	C		
Cutout / switch damaged [205]	X			X			N/A				
Arrester damaged / blown [206]	X			X			N/A				
Device failed [200]	X			X			N/A				
Tank damaged [201]	X			X			N/A				
Device leaking [203]	X			X			N/A				
Equipment riser broken / damaged [207]	X			X			N/A				
Bushing damaged / chipped / flashed [208]	X			X			N/A				
Other - include text in Remarks [213]	N/A			N/A			N/A				
Inspection Completed By: <i>Robert Kimball</i>	Emp. SAP #: <i>4999</i>			Date: <i>7-10-12</i>							
Inspection Approved By: <i>Russ Hull</i>	Emp. SAP #: <i>43884</i>			Date: <i>8-14-12</i>							
Priority Hazard: Call In											
Condition:				PowerOn or WR #:							
Repairs Needed After Inspection											
Repair Notification: DX or M3 #:				WR #:							

RESPONDENT'S EXHIBIT
 4
 RECEIVED

11/27/12
 Page 1 of 2
 AUG 20 2012

Line Recloser Annual Inspection

Work Request: 055603488 SAP Order #: 13388178
 Functional Loc: PNDNP9984924, D Pole SOUTH WATER ST, SABINSVILLE - ELKLAND
 On St. / X St.: SOUTH WATER ST. / UNKNOWN
 Station Number: 1D34263 Sub: OSCEOLA Ckt: 00562-63

GENERAL INFORMATION

Line Shop: PWLWP Pole #: 299473, 1D34263

Remarks: _____

Mark the appropriate columns to designate Pass (no problem), WR - Work Required, or C - Work completed during inspection.									
Pole Condition (EED: POLE)	Pass	WR	C	Pass	WR	C	Pass	WR	C
Pole damaged / deteriorated [223]	X			Conductor damaged / problem [235]	X				
Crossarm broken / damaged [227]	X			Primary clearance problem [239]	X				
Crossarm brace broken / damaged [228]	X			Mounting rack problem [211]	X				
Pins or hardware damaged / loose [230]	X			Ground broken / needed [210]	X				
Guy broken or problem [232]	NA			Other - include text in Remarks [213]	NA				
Recloser Control (EED: RECL)	Pass	WR	C	Pass	WR	C	Pass	WR	C
Control problem [216]	X			Control lock needed [218]	X				
Counter problem [217]	X			Power source / battery problem [219]	X				
Recloser Equipment Records By Phase from SAP (Not required)									
Equipment Number	299473								
Phase	3								
Assignment Code									
Company Number									
Manufacturer	CP								
Mfr. Serial number	CP571140389								
Recloser Type	VWVE								
Current Rating	560								
Interrupt Ability	0								
Fault Current									
Last Counter Read Date	01/18/2012								
Last Counter Reading (Total/Last)	30 / 1								
Current Counter Reading	32								
Recloser Condition (EED: RECL)	Pass	WR	C	Pass	WR	C	Pass	WR	C
Cutout / switch damaged [205]	X			NA			NA		
Arrester damaged / blown [206]	X			NA			NA		
Device failed [200]	X			NA			NA		
Tank damaged [201]	X			NA			NA		
Device leaking [203]	X			NA			NA		
Equipment riser broken / damaged [207]	X			NA			NA		
Bushing damaged / chipped / flashed [208]	X			NA			NA		
Other - include text in Remarks [213]	NA			NA			NA		
Inspection Completed By: <i>Robert Kimball</i>	Emp. SAP #: 4499			Date: 7-2-12					
Inspection Approved By: <i>Paul Hogg</i>	Emp. SAP #: 13541			Date: 8-11-12					
Priority Hazard Call In									
Condition:	PowerOn or WR #:								
Repairs Needed After Inspection									
Repair Notification: DX or M3 #:	WR #: RECEIVED								

AUG 20 2012
 #68 11/27/12
 Page 2 of 2

FirstEnergy

Line Recloser Annual Inspection

Work Request: 056248460 SAP Order #: 13764725
 Functional Loc: PNDNP9690662, D Pole UNK WESTFIELD-ULYSSES
 On St. / X St.: UNK / See circuit map
 Station Number: 6H4963 Sub: HARRISON VALLEY Ckt: 00738-63

GENERAL INFORMATION

Line Shop: PWLWF Pole #: 6H4963

Remarks: _____

Mark the appropriate columns to designate: Pass = (no problem) WR = Work Required, or C = Work completed during inspection							
Pole Condition (DDD-POLE)	Pass	WR	C		Pass	WR	C
Pole damaged / deteriorated [223]	X			Conductor damaged / problem [235]	X		
Crossarm broken / damaged [227]	X			Primary clearance problem [239]	X		
Crossarm brace broken / damaged [228]	X			Mounting rack problem [211]	X		
Pins or hardware damaged / loose [230]	X			Ground broken / needed [210]	X		
Guy broken or problem [232]	X			Other - include text in Remarks [213]	NA		
Recloser Control (DDD-RECL)	Pass	WR	C		Pass	WR	C
Control problem [216]	NA			Control lock needed [218]	NA		
Counter problem [217]	NA			Power source / battery problem [219]	NA		

Recloser Equipment Records By Phase From SAP (Not required)		
Equipment Number	191081	191082
Phase	A	C
Assignment Code		
Company Number		
Manufacturer	KY	KY
Mfr. Serial number	CP571012081	CP571012076
Recloser Type	L	L
Current Rating	50	50
Interrupt Ability	0	0
Fault Current		
Last Counter Read Date	07/10/2012	07/10/2012
Last Counter Reading	52	38
Operations Counter Reading	52	38

Recloser Condition (DDD-RECL)	Pass	WR	C	Pass	WR	C	Pass	WR	C
Cutout / switch damaged [205]	X			X			NA		
Arrester damaged / blown [206]	X			X			NA		
Device failed [200]	X			X			NA		
Tank damaged [201]	X			X			NA		
Device leaking [203]	X			X			NA		
Equipment riser broken / damaged [207]	X			X			NA		
Bushing damaged / chipped / flashed [208]	X			X			NA		
Other - include text in Remarks [213]	NA			NA			NA		

Inspection Completed By: Robert Kimball Emp. SAP #: 44799 Date: 7-12-13
 Inspection Approved By: Russell Hull Emp. SAP #: 43884 Date: 7-23-13

Priority Hazard Call In
 Condition: _____ PowerOn or WR #: _____
 Repairs Needed After Inspection
 Repair Notification: DX or M3 #: _____ WR #: _____

RESPONDENT'S EXHIBIT
 5

FirstEnergy

Line Recloser Annual Inspection

Work Request: 056248460 SAP Order #: 13764725
 Functional Loc: PNDNP9984924, D Pole SOUTH WATER ST. SABINSVILLE - ELKLAND
 On St. / X St.: SOUTH WATER ST. / UNKNOWN
 Station Number: 1D34263 Sub: OSCEOLA Ckt: 00562-63

GENERAL INFORMATION

Line Shop: PWLWP Pole #: 1D34263

Remarks: Recloser has been yellow tagged
Y26063

Mark the appropriate columns to designate Pass (no problem), WR (Work Required), or C (Work completed during inspection)						
Pole Condition (EDD/POLE)	Pass	WR	C	Pass	WR	C
Pole damaged / deteriorated [223]	X			Conductor damaged / problem [235]	X	
Crossarm broken / damaged [227]	X			Primary clearance problem [239]	X	
Crossarm brace broken / damaged [228]	X			Mounting rack problem [211]	X	
Pins or hardware damaged / loose [230]	X			Ground broken / needed [210]	X	
Guy broken or problem [232]	NA			Other - include text in Remarks [213]	NA	
Recloser Control (EDD/REC)	Pass	WR	C	Pass	WR	C
Control problem [216]	X			Control lock needed [218]	X	
Counter problem [217]	X			Power source / battery problem [219]	X	

Recloser Equipment Records By Phase (Not required)	
Equipment Number	299473
Phase	3
Assignment Code	
Company Number	
Manufacturer	CP
Mfr. Serial number	CP571140389
Recloser Type	VWVE
Current Rating	560
Interrupt Ability	0
Fault Current	
Last Counter Read Date	07/02/2012
Last Counter Reading	32
Operations Counter Reading	46

Recloser Condition (EDD/REC)	Pass	WR	C	Pass	WR	C	Pass	WR	C
Cutout / switch damaged [205]	X			NA			NA		
Arrester damaged / blown [206]	X			NA			NA		
Device failed [200]	X			NA			NA		
Tank damaged [201]	X			NA			NA		
Device leaking [203]	X			NA			NA		
Equipment riser broken / damaged [207]	X			NA			NA		
Bushing damaged / chipped / flashed [208]	X			NA			NA		
Other - include text in Remarks [213]	NA			NA			NA		

Inspection Completed By: P. Kimball Emp. SAP #: 4499 Date: 8-19-13
 Inspection Approved By: Sherrill Hull Emp. SAP #: 4388 Date: 7-23-13

Priority Hazard Call In
 Condition: _____ Power On or WR #: _____

Repairs Needed After Inspection
 Repair Notification: DX or M3 #: _____ WR #: _____

Page 2 of 2 RECEIVED
 AUG 26 2013

Date Time: 06/18/2014 08:00:52

Page: 13 of 23.

FirstEnergy

Line Recloser Annual Inspection

Work Request: 056881296 SAP Order #: 14173387
 Functional Loc: PNDNP9690662, D Pole UNK WESTFIELD-ULYSSES
 On St. / X St.: UNK / See circuit map
 Station Number: 6H4963 Sub: HARRISON VALLEY Ckt: 00738-63

GENERAL INFORMATION

Line Shop: PWLWP Pole #: 6H4963

Remarks: _____

Mark the appropriate columns to diagnosis (Pass - no problem) WR - Work Required or C - Work completed during inspection	
Pole Condition (EED:POLE)	Pass WR C
Pole damaged / deteriorated [223]	X
Crossarm broken / damaged [227]	X
Crossarm brace broken / damaged [228]	X
Pins or hardware damaged / loose [230]	X
Guy broken or problem [232]	NA
Conductor damaged / problem [235]	X
Primary clearance problem [239]	X
Mounting rack problem [211]	X
Ground broken / needed [210]	X
Other - include text in Remarks [213]	NA
Recloser Control (EED:RECL)	Pass WR C
Control problem [216]	NA
Counter problem [217]	NA
Control lock needed [218]	NA
Power source / battery problem [219]	NA

Recloser Equipment Record By: Phase from SAP (Not required)		
Equipment Number	191081	191082
Phase	A	C
Assignment Code		
Company Number		
Manufacturer	KY	KY
Mfr. Serial number	CP571012081	CP571012076
Recloser Type	L	L
Current Rating	50	50
Interrupt Ability	0	0
Fault Current		
Last Counter Read Date	07/12/2013	07/12/2013
Last Counter Reading	52	38
Operations Counter Reading	52	39

Recloser Condition (EED:RECL)	Pass	WR	C
Cutout / switch damaged [205]	NA		
Arrester damaged / blown [206]	X		
Device failed [200]	X		
Tank damaged [201]	X		
Device leaking [203]	X		
Equipment riser broken / damaged [207]	X		
Bushing damaged / chipped / flashed [208]	X		
Other - include text in Remarks [213]	NA		

Inspection Completed By: Robert Kimball Emp. SAP #: 4499 Date: 7-13-14
 Inspection Approved By: Russell Hull Emp. SAP #: 413884 Date: 7-23-14

Priority Hazard Call In Condition: _____ PowerOn or WR #: _____

Repairs Needed After Inspection Repair Notification: DX or M3 #: _____ WR #: _____



Date Time: 06/18/2014 08:00:52

Page: 20 of 23.

FirstEnergy

Line Recloser Annual Inspection

Work Request: 056881296 SAP Order #: 14173387
 Functional Loc: PNDNP9984924, D Pole SOUTH WATER ST, SABINSVILLE - BLKLAND
 On St. / X St.: SOUTH WATER ST. / UNKNOWN
 Station Number: 1D34263 Sub: OSCEOLA Ckt: 00562-63

GENERAL INFORMATION

Line Shop: PWLWF Pole #: 1D34263

Remarks: _____

Mark the appropriate column to designate Pass (no problem), WR (Work Required) or C (Work completed during inspection)			
Pole Condition (EDD/POLE)	Pass	WR	C
Pole damaged / deteriorated [223]	X		
Crossarm broken / damaged [227]	X		
Crossarm brace broken / damaged [228]	X		
Pins or hardware damaged / loose [230]	X		
Guy broken or problem [232]	NA		
Recloser Control (EDD/REC)	Pass	WR	C
Control problem [216]	X		
Counter problem [217]	X		

Recloser Equipment Record: By/Place from SAP (Not required)	
Equipment Number	299473
Phase	3
Assignment Code	
Company Number	
Manufacturer	CP
Mfr. Serial number	CP571140389
Recloser Type	VWVE
Current Rating	560
Interrupt Ability	0
Fault Current	
Last Counter Read Date	08/19/2013
Last Counter Reading	46
Operations Counter Reading	68

Recloser Condition (EDD/REC)									
	Pass	WR	C	Pass	WR	C	Pass	WR	C
Cutout / switch damaged [205]	X			NA			NA		
Arrester damaged / blown [206]	X			NA			NA		
Device failed [200]	X			NA			NA		
Tank damaged [201]	X			NA			NA		
Device leaking [203]	X			NA			NA		
Equipment riser broken / damaged [207]	X			NA			NA		
Bushing damaged / chipped / flashed [208]	X			NA			NA		
Other - include text in Remarks [213]	NA			NA			NA		

Inspection Completed By: Robert Kimball Emp. SAP #: 4499 Date: 7-13-14
 Inspection Approved By: Russell Hull Emp. SAP #: 43884 Date: 7-23-14

Priority Hazard Call In
 Condition: _____ Power On or WR #: _____

Repairs Needed After Inspection
 Repair Notification: DX or M3 #: _____ WR #: _____

RECEIVED