

Complaint E, # A

C-2018-3005382

3/27/19

Handy
WJH

(A) Damages to the siding on the west side of the home from the wire being ripped off.



Complaint Ex B & C

C-2018-3005382

3/27/19

Handy
WJH

(B) Shows the remnants of shredded wires hanging from the sagging main wire, to the left, in front of the man in the bucket. Damaged wire is lying on the ground.



(C) When the wire was replaced it was connected at the top of the pole on the right.



Complaint Ex D

C-2018-3005382

3/27/19

Hendry
wfh

(D) New wire being attached at the peak of the home approximately 12 feet higher, than the original location at the lower right corner of the window, which is 4 ft. from the ground.

