



COMMONWEALTH OF PENNSYLVANIA  
PENNSYLVANIA PUBLIC UTILITY COMMISSION  
COMMONWEALTH KEYSTONE BUILDING  
400 NORTH STREET, HARRISBURG, PA 17120

BUREAU OF  
INVESTIGATION  
&  
ENFORCEMENT

April 1, 2021

**Via Electronic Filing**

Rosemary Chiavetta, Secretary  
Pennsylvania Public Utility Commission  
Commonwealth Keystone Building  
400 North Street  
Harrisburg, PA 17120

Re: Pennsylvania Public Utility Commission,  
Bureau of Investigation and Enforcement v.  
TSE, Inc.  
Docket No. C-2021-  
**Formal Complaint**

Dear Secretary Chiavetta:

Enclosed for electronic filing please find the Complaint in the above referenced case on behalf of the Bureau of Investigation and Enforcement of the Pennsylvania Public Utility Commission. Copies have been served on the parties of record in accordance with the Certificate of Service.

Should you have any questions, please do not hesitate to contact me.

Sincerely,

A handwritten signature in black ink, appearing to read 'K. Myers', written over a white background.

Kourtney L. Myers  
Prosecutor  
PA Attorney ID No. 316494  
(717) 705-4366  
[komyers@pa.gov](mailto:komyers@pa.gov)

KLM/jfm  
Enclosure

cc: Per Certificate of Service

## NOTICE

**A. You must file an Answer within 20 days of the date of service of this Complaint.**

The date of service is the date as indicated at the top of the Secretarial Letter. *See* 52 Pa. Code §1.56(a). The Answer must raise all factual and legal arguments that you wish to claim in your defense, include the docket number of this Complaint, and be verified. You may file your

Answer by mailing an original to: Rosemary Chiavetta, Secretary  
Pennsylvania Public Utility Commission  
400 North Street  
Harrisburg, PA 17120

Or, you may eFile your Answer using the Commission's website at [www.puc.pa.gov](http://www.puc.pa.gov). The link to eFiling is located under the Filing & Resources tab on the homepage. If your Answer is 250 pages or less, you are not required to file a paper copy. If your Answer exceeds 250 pages, you must file a paper copy with the Secretary's Bureau.

**Additionally, please serve a copy on:**

Kourtney L. Myers, Prosecutor  
Pennsylvania Public Utility Commission  
Bureau of Investigation and Enforcement  
400 North Street  
Harrisburg, PA 17210  
[komyers@pa.gov](mailto:komyers@pa.gov)

B. If you fail to answer this Complaint within 20 days, the Bureau of Investigation and Enforcement will request that the Commission issue an Order imposing the requested relief.

C. You may elect not to contest this Complaint by paying the administrative penalty within 20 days. Send only a certified check or money order made payable to the "Commonwealth of Pennsylvania," with the docket number indicated, and mail to:

Rosemary Chiavetta, Secretary  
Pennsylvania Public Utility Commission  
400 North Street  
Harrisburg, PA 17120

D. If you file an Answer which either admits or fails to deny the allegations of the Complaint, the Bureau of Investigation and Enforcement will request that the Commission to issue an Order imposing the requested relief set forth in this Complaint.

E. If you file an Answer which contests the Complaint, the matter will be assigned to an Administrative Law Judge for hearing and decision. The Judge is not bound by the penalty set forth in the Complaint and may impose additional and/or alternative penalties as appropriate.

F. If you are a corporation, you must be represented by legal counsel. 52 Pa. Code § 1.21.

G. Alternative formats of this material are available for persons with disabilities by contacting the Commission's ADA Coordinator at 717-787-8714.

**BEFORE THE  
PENNSYLVANIA PUBLIC UTILITY COMMISSION**

Pennsylvania Public Utility Commission	:	
Bureau of Investigation and Enforcement	:	
	:	
v.	:	Docket No. C-2021-
	:	
TSE, Inc.	:	

---

**FORMAL COMPLAINT**

---

NOW COMES the Bureau of Investigation and Enforcement (“I&E”) of the Pennsylvania Public Utility Commission (“Commission”), by its prosecuting attorneys, and files this Formal Complaint (“Complaint”) against TSE, Inc. (“TSE” or “Respondent”), pursuant to Sections 182.8(d) and 182.10 of the Underground Utility Line Protection Law, Act of October 30, 2017, P.L.806, No. 50 (hereinafter referred to as the “PA One Call Law”), 73 P.S. §§ 182.8(d) and 182.10.<sup>1</sup> In support of its Complaint, I&E respectfully represents the following:

**I. Commission Jurisdiction and Authority**

1. The Pennsylvania Public Utility Commission, with a mailing address of 400 North Street, Harrisburg, PA 17120, is a duly constituted agency of the Commonwealth of Pennsylvania empowered to, *inter alia*, enforce compliance by excavators and other stakeholders pursuant to Section 182.10 of the PA One Call Law, 73 P.S. § 182.10.

---

<sup>1</sup> The purpose of the PA One Call Law is to protect the public health and safety by preventing excavation or demolition work from damaging underground lines used in providing electricity, communication, gas, propane, oil delivery, oil product delivery, sewage, water or other service; imposing duties upon the providers of such service and persons and other entities preparing drawings or performing excavation or demolition work; and prescribing penalties.

2. Complainant is the Commission's Bureau of Investigation and Enforcement, which is the bureau established to take enforcement actions against public utilities and other entities subject to the Commission's jurisdiction pursuant to 66 Pa.C.S. § 308.2(a)(11); *See also Implementation of Act 129 of 2008; Organization of Bureaus and Offices*, Docket No. M-2008-2071852 (Order entered August 11, 2011) (delegating authority to initiate proceedings that are prosecutory in nature to I&E), including actions to enforce compliance of the PA One Call Law.

3. Complainant is represented by:

Kourtney L. Myers  
Prosecutor  
Pennsylvania Public Utility Commission  
Bureau of Investigation and Enforcement  
400 North Street  
Harrisburg, PA 17120  
(717) 705-4366  
[komyers@pa.gov](mailto:komyers@pa.gov)

Michael L. Swindler  
Deputy Chief Prosecutor  
Pennsylvania Public Utility Commission  
Bureau of Investigation and Enforcement  
400 North Street  
Harrisburg, PA 17120

4. Respondent is TSE, Inc. and maintains its principal place of business at 1302 Dunham Drive, Dunmore, PA 18512.

5. Respondent is an “excavator” as that term is defined at 73 P.S. § 176 as it “performs excavation or demolition work for [itself] or for another person.”

6. “Excavation work” is defined as “the use of powered equipment or explosives in the movement of earth, rock or other material, and includes, but is not limited to,

anchoring, augering, backfilling, blasting, boring, digging, ditching, drilling, driving-in, grading, plowing-in, pulling-in, ripping, scraping, trenching and tunneling.” 73 P.S. § 176.

7. “Powered equipment” is defined as “any equipment energized by an engine or motor and used in excavation or demolition work.” 73 P.S. § 176.

8. Respondent, as an excavator, is subject to the power and authority of this Commission pursuant to Section 182.10 of the PA One Call Law, 73 P.S. § 182.10, which requires excavators to comply with the PA One Call Law.

9. Sections 182.8(d) and 182.10 of the PA One Call Law, 73 P.S. §§ 182.8(d) and 182.10, authorize the Commission to, *inter alia*, hear and determine complaints against excavators for violations of the PA One Call Law and enforce the provisions of the PA One Call Law.

10. Section 182.10(a) of the PA One Call Law, 73 P.S. § 182.10(a), authorizes the Commission to impose administrative penalties on excavators who violate the PA One Call Law. Section 182.10(b)(1)(i)-(ii) allows for the imposition of an administrative penalty not to exceed \$2,500 for each violation or if the violation results in injury, death, or property damage of \$25,000 or more, an administrative penalty not to exceed \$50,000.

11. Pursuant to the provisions of the applicable Commonwealth statutes, the Commission has jurisdiction over the subject matter of this complaint and the actions of Respondent related thereto.

## **II. Factual Background**

12. On April 24, 2018, TSE placed an excavation routine ticket (“routine ticket”) with the Pennsylvania One Call System (“POCS”) at POCS Serial No. 20181143788 to

conduct an excavation with powered equipment. The routine ticket and responses thereto are attached as I&E Exhibit 1A and 1B, respectively.

13. The purpose of the excavation was to install a water main for Pennsylvania-American Water Company.

14. The routine ticket identified the work site as Butler Street between the Butler Street intersections with Wheeler Avenue and Sixth Street in Dunmore, Pennsylvania 18512.

15. UGI Utilities, Inc. (“UGI”) is the facility owner of gas lines and facilities that run underground in the vicinity of the work site.

16. An underground gas line is a “line” or “facility” as defined in 73 P.S. § 176.

17. On April 26, 2018, UGI responded “FIELD MARKED” to TSE’s routine ticket through the POCS indicating that UGI had located and marked its underground lines at the work site.

18. At all material times hereto, Respondent was an “excavator” as defined in Section 73 P.S. § 176.

19. Respondent located and exposed UGI’s line at the work site.

20. On May 14, 2018, TSE damaged UGI’s exposed line at the work site with a backhoe during backfilling. A photograph of the work site, including the damaged UGI line is attached as I&E Exhibit 2.

21. After damaging UGI’s line, TSE submitted an alleged violation report (“AVR”) with the POCS, pursuant to 73 P.S. § 180(16). Respondent’s AVR is attached as I&E Exhibit 3.

22. The purpose of an AVR is to report to the Commission through the POCS an alleged violation of the PA One Call Law that has been committed in association with excavation or demolition work. *See* 73 P.S. §§ 176 and 180(16).

23. In its AVR, TSE describes the type of alleged violation as an “Excavator Issue” and admits that the reason for the AVR is that TSE “[f]ailed to plan the excavation or demolition work to avoid damage or minimize interference with a facility owner’s facilities in a construction area §5(6)(i).”

24. Respondent further admits in its AVR that while it was “performing [its] compaction of [the] trench for the day a rock pushed against the gas line” and that there was “[r]eally nothing [TSE] could of [sic] done to prevent this matter.”

25. “Compaction of trench” is a part of the backfilling process.

26. After damaging UGI’s line, Respondent did not submit a damage emergency notification with the POCS.

### **III. Violations**

#### **COUNT 1**

27. All allegations set forth above are incorporated as if fully set forth herein. TSE failed to plan the excavation to avoid damage to or minimize interference with UGI’s facilities at the work site in that after exposing UGI’s line at the work site, Respondent damaged the line.

If proven, this is a violation of Section 180(6)(i) of the PA One Call Law, 73 P.S. § 180(6)(i) (requiring an excavator to “[p]lan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area”).

The Bureau of Investigation and Enforcement’s proposed administrative penalty for this violation is \$1,000.

### **COUNT 2**

28. All allegations set forth above are incorporated as if fully set forth herein. TSE failed to provide support and mechanical protection for known UGI’s lines at the work site during excavation, including during backfilling operations, as was reasonably necessary for the protection of such lines in that after exposing UGI’s line at the work site, TSE damaged the line during backfilling.

If proven, this is a violation of Section 180(6)(ii) of the PA One Call Law, 73 P.S. § 180(6)(ii) (requiring an excavator to “provide such support and mechanical protection for known facility owner’s lines at the construction work site during the excavation . . . including during backfilling operations, as may be reasonably necessary for the protection of such lines”).

The Bureau of Investigation and Enforcement’s proposed administrative penalty for this violation is \$1,000.

### **COUNT 3**

29. All allegations set forth above are incorporated as if fully set forth herein. TSE failed to use its best efforts to comply with Common Ground Alliance Best Practice 5.15 (requiring an excavator to use “reasonable care to avoid damaging underground facilities”) in that TSE damaged the exposed, UGI line.

If proven, this is a violation of Section 184 of the PA One Call Law, 73 P.S. § 184 (requiring an excavator to “use [its] best efforts to comply with the Common Ground Alliance Best Practices”).

The Bureau of Investigation and Enforcement’s proposed administrative penalty for this violation is \$500.

**COUNT 4**

30. All allegations set forth above are incorporated as if fully set forth herein. TSE failed to use its best efforts to comply with Common Ground Alliance Best Practice 5.22 (requiring an excavator to “support and protect exposed underground lines and facilities from damage”) in that TSE damaged and failed to support and protect the exposed, UGI line.

If proven, this is a violation of Section 184 of the PA One Call Law, 73 P.S. § 184 (requiring an excavator to “use [its] best efforts to comply with the Common Ground Alliance Best Practices”).

The Bureau of Investigation and Enforcement’s proposed administrative penalty for this violation is \$500.

**COUNT 5**

31. All allegations set forth above are incorporated as if fully set forth herein. TSE failed to use its best efforts to comply with Common Ground Alliance Best Practice 5.24 (requiring an excavator “causing damage to underground facilities . . . [to notify] the facility owner/operator and the one call center”) in that after damaging UGI’s line, TSE did not notify the POCS by submitting a damage emergency notification with the POCS.

If proven, this is a violation of Section 184 of the PA One Call Law, 73 P.S. § 184 (requiring an excavator to “use [its] best efforts to comply with the Common Ground Alliance Best Practices”).

The Bureau of Investigation and Enforcement’s proposed administrative penalty for this violation is \$500.

## COUNT 6

32. All allegations set forth above are incorporated as if fully set forth herein. TSE failed to use its best efforts to comply with Common Ground Alliance Best Practice 5.27 (requiring an excavator to “[protect] all facilities from damage when backfilling an excavation”) in that after exposing UGI’s line at the work site, TSE damaged and failed to protect the line during backfilling.

If proven, this is a violation of Section 184 of the PA One Call Law, 73 P.S. § 184 (requiring an excavator to “use [its] best efforts to comply with the Common Ground Alliance Best Practices”).

The Bureau of Investigation and Enforcement’s proposed administrative penalty for this violation is \$500.

#### **IV. Requested Relief**

33. Due to the failure of TSE to plan the excavation to avoid damage to or minimize interference with UGI’s facilities at the work site, provide support and mechanical protection for known UGI’s lines at the work site during excavation, including during backfilling operations, as was reasonably necessary for the protection of such lines, and use its best efforts to comply with Common Ground Alliance Best Practices, which resulted in damage to the exposed line, I&E proposes that TSE pay a total administrative penalty of Four Thousand Dollars (\$4,000).

34. In addition to payment of the administrative penalty, I&E proposes that TSE be ordered by the Commission to:

- (a) Plan excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area as required by 73 P.S. § 180(6)(i);

- (b) Provide support and mechanical protection for known facility owner's lines at the construction work site during excavation, including during backfilling operations, as may be reasonably necessary for the protection of such lines as required by 73 P.S. § 180(6)(ii);
- (c) Use its best efforts to comply with the Common Ground Alliance Best Practices as required by 73 P.S. § 184;
- (d) Require its employees to attend annual, third-party training on excavation and trenching safety for a minimum of three (3) years; and
- (e) Any other remedies as the Commission may deem appropriate.

Respectfully submitted,



Kourtney L. Myers  
Prosecutor  
PA Attorney ID No. 316494

Pennsylvania Public Utility Commission  
Bureau of Investigation and Enforcement  
400 North Street  
Harrisburg, PA 17120  
(717) 705-4366  
[komyers@pa.gov](mailto:komyers@pa.gov)

Date: April 1, 2021


**BEFORE THE  
PENNSYLVANIA PUBLIC UTILITY COMMISSION**

Pennsylvania Public Utility Commission	:	
Bureau of Investigation and Enforcement	:	
	:	
v.	:	Docket No. C-2021-
	:	
TSE, Inc.	:	

**VERIFICATION**

I, Sara Andrade-Locke, Damage Prevention Supervisor, Damage Prevention Section, Bureau of Investigation and Enforcement, hereby state that the facts above set forth are true and correct to the best of my knowledge, information, and belief and that I expect the Bureau will be able to prove the same at any hearing held in this matter. I understand that the statements herein are made subject to the penalties of 18 Pa.C.S. § 4904 relating to unsworn falsification to authorities.

Date: April 1, 2021



---

Sara Andrade-Locke  
Damage Prevention Supervisor  
Damage Prevention Section  
Bureau of Investigation and Enforcement  
Pennsylvania Public Utility Commission  
400 North Street  
Harrisburg, PA 17120

# **Exhibit**

## **1A**

CDC 00000 POCs MM/DD/YY TT:TT:TT 20181143788-000 NEW XCAV RTN

=====PENNSYLVANIA UNDERGROUND UTILITY LINE PROTECTION REQUEST=====

Serial Number--[20181143788]-[000] Channel#--[1629A004][0262]  
Message Type--[NEW][EXCAVATION][ROUTINE]

County--[LACKAWANNA] Municipality--[DUNMORE BORO]  
Work Site--[BUTLER ST]  
Nearest Intersection--[WHEELER AVE]  
Second Intersection--[6TH ST]  
At Intersection--[N] Between Intersections--[Y] Site Marked in White--[Y]  
Subdivision--[ ]

Location Information--  
[ ]  
Caller Lat/Lon--[ ]  
Mapped Type--[P] Mapped Lat/Lon--  
[41.415065/-75.634987,41.414161/-75.635665,41.412592/-75.632468,  
41.413483/-75.631749]

Attachments--[http://www.pa811.org/attachments/20181143788]  
Type of Work--[WTR MAIN PROJECT] Depth--[ ]  
Extent of Excavation--[ ] Method of Excavation--[TRENCHING]  
Equip Type--[EXCAVATOR]  
Street--[X] Sidewalk--[X] Pub Prop--[X] Pvt Prop--[X] Other--[ ]  
Private Front--[X] Rear--[X] Left--[X] Right--[X]

Lawful Start Dates--[27-Apr-18] thru [08-May-18] Response Due Date--[26-Apr-18]  
Scheduled Excavation Date--[27-Apr-18] Dig Time--[0700] Duration--[ ]

Caller--[JEFFREY HESSMILLER]  
Caller Phone--[570-341-7557] Caller Ext--[ ]  
Excavator--[T S E INC]  
Address--[1302 DUNHAM DR]  
City--[DUNMORE] State--[PA] Zip--[18512]  
FAX--[ ] Caller Type--[B]  
Email--[paonecallstseinc@gmail.com]  
Work For--[PAWC]  
Person to Contact--[JEFFREY HESSMILLER]  
Contact Phone--[570-903-3127] Contact Ext--[ ]  
Best Time to Call--[0800-1600]

Prepared--[24-Apr-18] at [1633] by [KATELYNN HORVATH]  
Remarks--  
[ ]

AQ10 AQ1=COMCAST GN 0 GN =UGI PNG HI 0 HI =VERIZON WB STN  
PT 0 PT =PPL ELEC SRTN SSA0 SSA=PAWC SCRANTON WW 0 WW =PAWC WILKES-BAR

Serial Number--[20181143788]-[000]  
===== Copyright (c) 2018 by Pennsylvania One Call System, Inc. =====

# **Exhibit 1B**

RESPONSES FOR 20181143788:

Ver	CDC	Name	Response	Time	Respondent
0	AQ1	COMCAST	1-CLEAR NO FACIL	04/26/2018 09:37:18	CLS-WEBSVC
0	GN	UGI PENN NATURAL GAS-ARCH	3-FIELD MARKED	04/26/2018 09:52:34	PGN-WEBSVC
0	HI	VERIZON PENNSYLVANIA LLC	1-CLEAR NO FACIL	04/24/2018 16:37:59	PRA-WEBSVC
0	PT	PPL ELECTRIC UTILITIES CO	3-FIELD MARKED	04/26/2018 09:37:19	CLS-WEBSVC
0	SSA	PENNSYLVANIA AMERICAN WAT	3-FIELD MARKED	04/26/2018 13:17:53	GAY-WEBSVC
0	WW	PENNSYLVANIA AMERICAN WAT	3-FIELD MARKED	04/26/2018 17:20:57	JON-WEBSVC

# **Exhibit**

**2**



# **Exhibit**

## **3**



## Alleged Violation Report

PA Act 287, as amended 73 P. S. § 176 et. seq.  
Powered by Pennsylvania One Call System, Inc.

**First Name** JEFFREY **Last Name** HESSMILLER  
**Company Name** T S E INC  
**Address** 1302 DUNHAM DR  
**City** DUNMORE **State** PA **Zip Code** 18512  
**Email** paonecallstseinc@gmail.com **Phone** 5703417557  
om

### Role

**Submitter Role(s) \*** (?)

- |   |   |
|---|---|
| <input type="checkbox"/> Facility Owner       | <input type="checkbox"/> Designer           |
| <input checked="" type="checkbox"/> Excavator | <input type="checkbox"/> Project Owner      |
| <input type="checkbox"/> Locator              | <input type="checkbox"/> Enforcement Agency |
| <input type="checkbox"/> Other                |   |

**Are you representing a company other than your own?**  Yes  No

### Alleged Violation Information

**Type of Alleged Violation \*** (?)

Excavator Issue

**Reason \***

Failed to plan the excavation or demolition work to avoid damage or minimize interference with a facility owner's facilities in a construction area §5(6)(i)

**When did the alleged violation occur?** 2018-05-14

(?)

07:00:00 AM

**Was the One Call System notified? \***  Yes  No

**Original Serial Number (?)** 20181143788

**Related Damage Serial Number, if applicable**

**Other Related Serial Numbers (?)**

**Was the excavation exempt from One Call notification?**  Yes  No  Unknown

### Event Information

County LACKAWANNA  
 Municipality DUNMORE BORO  
 Ward 0  
 Work Site BUTLER ST  
 Nearest Intersection WHEELER AVE  
 Geolocation (?)

### Affected Facility Information

Primary Right of Way Type Public  
 Public Right of Way Type City Street  
 Affected Operation Gas  
 Facility Subtype Affected Service/Drop/Lateral  
 Joint Trench?  Yes  No  Unknown  
 Involve Cross Bore?  Yes  No  Unknown  
 Measured Depth from Grade Embedded in concrete/asphalt pavement

### Work Information

Start Date of Excavation (?) 04/24/2018  
 07:00:00 AM  
 Excavation Activity MAIN  
 Marked in White  Yes  No  Unknown  
 Method of Excavation TRENCHING  
 Equipment Used What Equipment was used for excavation or demolition when the event occurred?  
 BACKHOE/TRACKHOE  
 Type of Excavator What is the type of excavator for whom the work was being done when the event occurred?  
 Property Owner/Occupant (individual)  
 Did Excavator incur down time?  Yes  No  Unknown  
 Was a response posted to the One Call System?  Yes  No  Unknown

### Event Impact

Did Violation result in underground damage or near miss event? Damage  
 OSHA Report Filed?  Yes  No

Was 911 called?  Yes  No

Name of 911 Caller

Fire Response  Yes  No

Police Response  Yes  No

Number of Injuries (?) 0

Number of Fatalities 0

Was there an evacuation?  Yes  No

Traffic Stopped?  Yes  No

Service Interrupted?  Yes  No

Duration of Service Interruption? < 1 hr

Number of Customers Affected? 1

Cost of Damaged Line Repair? Unknown

Was other property damaged?  Yes  No

### Locator/Locate Information

Who was the facility line locator?

Locator Company

Locator Contact Name

Locator Address

Street Address

Address Line 2

City

State

Zip Code

Locator Email

Locator Company Phone

Locator Cell Phone

Locator Fax

Was the line marked?  Yes  No  Unknown

Was the excavation within the tolerance zone? (?)  Yes  No  Unknown

Was there an indication of underground facilities (clear evidence) in the excavation area?  Yes  No  Unknown

What method(s) were used to locate the facility?  Electronic  Visual

Records

Exposed

Did the excavator request payment  Yes  No  
under PennDOT Form 408  
specifications for extra work  
performed on a force account  
basis?

**Additional Locate Comments**

If this incident involved any locating/markings errors, please include all records related to the locator's training and qualification (including training to meet UULPL standards as well as Operator Qualification).

## Summary and Attachments

---

**Provide a summary of the event**

While TSE Inc. was performing their compaction of trench for the day a rock pushed against the gas line. In this particular area of the project as well as the other streets in the area of this project are known for a fact of the heavy rock being underground . Really nothing we could of done to prevent this matter.

THANK YOU

If more space is needed, attach additional pages or documents.

**Attachments**

**BEFORE THE  
PENNSYLVANIA PUBLIC UTILITY COMMISSION**


Pennsylvania Public Utility Commission	:	
Bureau of Investigation and Enforcement	:	
	:	
v.	:	Docket No. C-2021-
	:	
TSE, Inc.	:	

**CERTIFICATE OF SERVICE**

I hereby certify that I have this day served a true copy of the foregoing **Formal Complaint** in the manner and upon the parties listed below, in accordance with the requirements of 52 Pa. Code §§ 1.54 (relating to service by a party).

**Served via Electronic Mail**

Jeffrey Hessmiller  
TSE, Inc.  
1302 Dunham Drive  
Dunmore, PA 18512  
[paonecallstseinc@gmail.com](mailto:paonecallstseinc@gmail.com)  
[tseinc1@verizon.net](mailto:tseinc1@verizon.net)



Kourtney L. Myers  
Prosecutor  
PA Attorney ID No. 316494

Bureau of Investigation and Enforcement  
Pennsylvania Public Utility Commission  
Commonwealth Keystone Building  
400 North Street  
Harrisburg, PA 17120  
(717) 705-4366  
[komyers@pa.gov](mailto:komyers@pa.gov)

Date: April 1, 2021