ECKERT SEAMANS
ATTORNEYS AT LAW

Eckert Seamans Cherin & Mellott, LLC
213 Market Street
8th Floor
Harrisburg, PA 17101

TEL 717 237 6000
FAX 717 237 6019
www.eckertseamans.com

Deanne M. O'Dell
717.255.3744
dodell@eckertseamans.com

April 8, 2022

Via Electronic Filing
Rosemary Chiavetta, Secretary
PA Public Utility Commission
P.O. Box 3265
Harrisburg, PA 17105-3265

Re: Pittsburgh Water and Sewer Authority 2021 Rate Filing;
Docket Nos. R-2021-3024773 (water), R-2021-3024774 (wastewater);
R-2021-3024779 (stormwater)

Dear Secretary Chiavetta:

In accordance with Section III.9.E.1.a.iv of the Joint Petition for Settlement that was filed on September 7, 2021 and approved by Commission Order on November 18, 2021, the Pittsburgh Water and Sewer Authority ("PWSA") agreed to file a report for calendar year 2021 identifying each valve that it attempted to exercise and whether it was broken or operable. **Enclosed please find the report consistent with this settlement term.**

The report includes the condition of the valve if known and reported at the time the valve was exercised. In 2021, PWSA did not record this information for each valve exercised and, therefore, the information is unavailable for some of the valves. PWSA is in the process of ensuring the condition of the valve at the time it is exercised is recorded for all work orders in 2022.

Please note that while PWSA committed to filing the report by January 31, 2022, PWSA was delayed in gathering the necessary information as a result of both staffing shortages and the on-going amount of time required by existing staff as part of the multi-phased implementation of an Enterprise Resource Planning ("ERP") system.

Copies to be served in accordance with the attached Certificate of Service.

Sincerely,

Deanne M. O'Dell

Deanne M. O'Dell

DMO/lww

cc: Hon. Eranda Vero w/enc.
Cert. of Service w/enc.

#102915771v1

CERTIFICATE OF SERVICE

I hereby certify that this day I served a copy of PWSA's 2021 Valve Exercise Report upon the persons listed below in the manner indicated in accordance with the requirements of 52 Pa. Code Section 1.54.

Via Email Only

Christine Maloni Hoover, Esq.
Erin L. Gannon, Esq.
Lauren E. Guerra, Esq.
Office of Consumer Advocate
555 Walnut St., 5th Fl., Forum Place
Harrisburg, PA 17101-1923
choover@paoca.org
egannon@paoca.org
lguerra@paoca.org

Gina L. Miller, Esq.
Bureau of Investigation & Enforcement
Commonwealth Keystone Building
400 North St., 2nd Floor West
Harrisburg, PA 17120
ginmiller@pa.gov

Elizabeth R. Marx, Esq.
John W. Sweet, Esq.
Ria M. Pereira, Esq.
Lauren N. Berman, Esq.
The Pennsylvania Utility Law Project
118 Locust St.
Harrisburg, PA 17101
pulp@pautilitylawproject.org

Jared Thompson, Esq.
Peter DeMarco, Esq.
Natural Resources Defense Council
1152 15th St., NW, Suite 300
Washington, DC 20005
Jared.thompson@nrdc.org
pdemarco@nrdc.org

Erin K. Fure, Esq.
Office of Small Business Advocate
Forum Place Building
555 Walnut Street, 1st Floor
Harrisburg, PA 17101
efure@pa.gov

Brian Kalcic
Excel Consulting
225 S. Meramec Ave., Suite 720T
St. Louis, MO 63105
Excel.consulting@sbcglobal.net

Thomas J. Sniscak, Esq.
Kevin J. McKeon, Esq.
Whitney E. Snyder, Esq.
Hawke McKeon & Sniscak, LLP
100 North Tenth Street
Harrisburg, PA 17101
kjmckeon@hmslegal.com
tjsniscak@hmslegal.com
wesnyder@hmslegal.com

John F. Doherty
Lawrence H. Baumiller
City of Pittsburgh Department of Law
City-County Building, Suite 313
414 Grant Street
Pittsburgh, PA 15219
john.doherty@pittsburghpa.gov
lawrence.baumiller@pittsburghpa.gov

April 8, 2022

Deanne M. O'Dell

Deanne M. O'Dell, Esq.

#6606361v1

PWSA Report Valves Exercised 2021
Per Section III.9.E.1.a.iv of the Joint Petition for Settlement at Docket No. R-2021-3024773

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-59519	1	Completed	October 5, 2021, 10:35 AM	October 5, 2021, 12:00 AM	Valve Maintenance Report	October 5, 2021, 10:42 AM	V-001BV011	Valve Condition	
WO-57517	43	Completed	September 15, 2021, 10:24 AM	September 16, 2021, 12:00 AM	Test shut		V-001CV036	Valve Condition	
WO-58870	41	Completed	September 28, 2021, 10:27 AM	October 8, 2021, 12:00 AM	PGH2O Creww shut request		V-001CV040	Valve Condition	
WO-57517	43	Completed	September 15, 2021, 10:24 AM	September 16, 2021, 12:00 AM	Test shut		V-001CV041	Valve Condition	
WO-34146	1	Completed	January 21, 2021, 10:13 AM	January 21, 2021, 12:00 AM	Valve Maintenance Report	January 21, 2021, 11:57 AM	V-001CV071	Valve Condition	
WO-60668	1	Completed	October 14, 2021, 12:20 PM	October 14, 2021, 12:00 AM	Valve Maintenance Report	October 14, 2021, 12:26 PM	V-001CV075	Valve Condition	
WO-33677	84	Completed	January 15, 2021, 9:53 AM	January 15, 2021, 12:00 AM	Main or service line leak investigation/survey WATER GOING INTO COMMERCISL PROPERTY. COULD BE ON OWNER, BUT IT DOES LOOK LIKE WE HAVE A SIDEWALK MAIN HERE.	January 15, 2021, 10:07 AM	V-001CV081	Valve Condition	Fair
WO-58327	1	Completed	September 22, 2021, 2:17 PM	September 22, 2021, 12:00 AM	Valve Maintenance Report	September 22, 2021, 2:32 PM	V-001DV016	Valve Condition	
WO-58327	1	Completed	September 22, 2021, 2:17 PM	September 22, 2021, 12:00 AM	Valve Maintenance Report	September 22, 2021, 2:32 PM	V-001DV018	Valve Condition	
WO-58125	1	Completed	September 21, 2021, 10:51 AM	September 24, 2021, 12:00 AM	Valve Maintenance Report	September 24, 2021, 10:52 AM	V-001DV019	Valve Condition	
WO-58320	1	Completed	September 22, 2021, 1:51 PM	September 22, 2021, 12:00 AM	Valve Maintenance Report	September 22, 2021, 1:52 PM	V-001DV020	Valve Condition	Fair
WO-58327	1	Completed	September 22, 2021, 2:17 PM	September 22, 2021, 12:00 AM	Valve Maintenance Report	September 22, 2021, 2:32 PM	V-001DV021	Valve Condition	
WO-58327	1	Completed	September 22, 2021, 2:17 PM	September 22, 2021, 12:00 AM	Valve Maintenance Report	September 22, 2021, 2:32 PM	V-001DV022	Valve Condition	Fair
WO-41744	43	Completed	April 15, 2021, 11:32 AM	April 15, 2021, 12:00 AM	Test shut	April 15, 2021, 11:38 AM	V-001DV097	Valve Condition	
WO-38160	1	Completed	March 4, 2021, 10:56 AM	March 4, 2021, 12:00 AM	Valve Maintenance Report	March 4, 2021, 11:00 AM	V-001DV104	Valve Condition	Fair
WO-41744	43	Completed	April 15, 2021, 11:32 AM	April 15, 2021, 12:00 AM	Test shut	April 15, 2021, 11:38 AM	V-001DV105	Valve Condition	Good
WO-38155	43	Completed	March 4, 2021, 10:40 AM	March 4, 2021, 12:00 AM	Test shut,Independent doing a private tie in	March 4, 2021, 11:08 AM	V-001DV109	Valve Condition	
WO-46026	41	Completed	May 24, 2021, 6:20 PM	May 24, 2021, 12:00 AM	Contractor shut request	May 25, 2021, 1:01 AM	V-001DV110	Valve Condition	Good
WO-41744	43	Completed	April 15, 2021, 11:32 AM	April 15, 2021, 12:00 AM	Test shut	April 15, 2021, 11:38 AM	V-001DV113	Valve Condition	
WO-41744	43	Completed	April 15, 2021, 11:32 AM	April 15, 2021, 12:00 AM	Test shut	April 15, 2021, 11:38 AM	V-001DV143	Valve Condition	Good
WO-45444	43	Completed	May 20, 2021, 1:19 AM	May 20, 2021, 12:00 AM	Test shut	May 20, 2021, 5:01 AM	V-001DV144	Valve Condition	Good
WO-45444	43	Completed	May 20, 2021, 1:19 AM	May 20, 2021, 12:00 AM	Test shut	May 20, 2021, 5:01 AM	V-001DV148	Valve Condition	Good
WO-43356	41	Completed	April 30, 2021, 2:38 PM	May 1, 2021, 12:00 AM	Contractor shut request		V-001DV151	Valve Condition	Good
WO-55762	41	Completed	August 26, 2021, 11:15 AM	August 26, 2021, 12:00 AM	Contractor shut request	August 26, 2021, 11:19 AM	V-001DV205	Valve Condition	
WO-55759	41	Completed	August 26, 2021, 11:05 AM	August 26, 2021, 12:00 AM	Contractor shut request	August 26, 2021, 11:13 AM	V-001DV251	Valve Condition	
WO-34362	41	Completed	January 23, 2021, 10:57 PM	January 24, 2021, 12:00 AM	Contractor shut request.	January 24, 2021, 7:43 AM	V-001GV007	Valve Condition	
WO-34362	41	Completed	January 23, 2021, 10:57 PM	January 24, 2021, 12:00 AM	Contractor shut request.	January 24, 2021, 7:43 AM	V-001GV011	Valve Condition	
WO-56057	1	Completed	August 30, 2021, 2:48 PM	August 30, 2021, 12:00 AM	Valve Maintenance Report	August 30, 2021, 2:54 PM	V-001GV096	Valve Condition	
WO-56057	1	Completed	August 30, 2021, 2:48 PM	August 30, 2021, 12:00 AM	Valve Maintenance Report	August 30, 2021, 2:54 PM	V-001GV101	Valve Condition	
WO-54784	84	Completed	August 15, 2021, 11:07 PM	August 16, 2021, 12:00 AM	INVESTIGATE WATER LEAKING IN THE STREET		V-001GV106	Valve Condition	
WO-34362	41	Completed	January 23, 2021, 10:57 PM	January 24, 2021, 12:00 AM	Contractor shut request.	January 24, 2021, 7:43 AM	V-001HV028	Valve Condition	
WO-44850	1	Completed	May 14, 2021, 12:44 PM	May 14, 2021, 12:00 AM	Valve Maintenance Report	May 14, 2021, 12:51 PM	V-001JV001	Valve Condition	
WO-44850	1	Completed	May 14, 2021, 12:44 PM	May 14, 2021, 12:00 AM	Valve Maintenance Report	May 14, 2021, 12:51 PM	V-001JV002	Valve Condition	
WO-44852	41	Completed	May 14, 2021, 1:05 PM	May 26, 2021, 8:00 AM	Contractor shut request	May 26, 2021, 1:27 PM	V-001JV003	Valve Condition	Good
WO-44850	1	Completed	May 14, 2021, 12:44 PM	May 14, 2021, 12:00 AM	Valve Maintenance Report	May 14, 2021, 12:51 PM	V-001JV005	Valve Condition	
WO-44852	41	Completed	May 14, 2021, 1:05 PM	May 26, 2021, 8:00 AM	Contractor shut request	May 26, 2021, 1:27 PM	V-001JV007	Valve Condition	
WO-44842	21	Completed	May 14, 2021, 12:02 PM	May 26, 2021, 12:00 AM	Valve requires replacement	May 26, 2021, 2:30 PM	V-001JV008	Valve Condition	
WO-64059	1	Completed	November 22, 2021, 8:43 AM	November 24, 2021, 12:00 AM	Repair water main		V-001JV009	Valve Condition	
WO-54784	84	Completed	August 15, 2021, 11:07 PM	August 16, 2021, 12:00 AM	INVESTIGATE WATER LEAKING IN THE STREET		V-001LV002	Valve Condition	
WO-44769	1	Completed	May 14, 2021, 7:06 AM	May 17, 2021, 12:00 AM	Repair water main		V-001MV066	Valve Condition	
WO-44847	1	Completed	May 14, 2021, 12:38 PM	May 14, 2021, 12:00 AM	Valve Maintenance Report	May 14, 2021, 12:39 PM	V-001NV002	Valve Condition	Fair
WO-44852	41	Completed	May 14, 2021, 1:05 PM	May 26, 2021, 8:00 AM	Contractor shut request	May 26, 2021, 1:27 PM	V-001NV003	Valve Condition	Fair
WO-44852	41	Completed	May 14, 2021, 1:05 PM	May 26, 2021, 8:00 AM	Contractor shut request	May 26, 2021, 1:27 PM	V-001NV006	Valve Condition	Fair
WO-37245	1	Completed	February 23, 2021, 9:15 AM	February 24, 2021, 12:00 AM	Repair water main		V-001NV012	Valve Condition	
WO-43921	1	Completed	May 6, 2021, 10:44 AM	May 6, 2021, 12:00 AM	Valve Maintenance Report	May 6, 2021, 10:56 AM	V-001NV027	Valve Condition	
WO-43926	1	Completed	May 6, 2021, 11:05 AM	May 6, 2021, 12:00 AM	Valve Maintenance Report	May 6, 2021, 11:07 AM	V-001NV028	Valve Condition	Good
WO-43929	1	Completed	May 6, 2021, 11:08 AM	May 6, 2021, 12:00 AM	Valve Maintenance Report	May 6, 2021, 11:11 AM	V-001NV029	Valve Condition	Good
WO-43931	1	Completed	May 6, 2021, 11:12 AM	May 6, 2021, 12:00 AM	Valve Maintenance Report	May 6, 2021, 11:25 AM	V-001NV030	Valve Condition	Good
WO-43942	1	Completed	May 6, 2021, 12:11 PM	May 6, 2021, 12:00 AM	Valve Maintenance Report	May 6, 2021, 12:32 PM	V-001NV031	Valve Condition	Good
WO-43973	1	Completed	May 6, 2021, 2:02 PM	May 6, 2021, 12:00 AM	Valve Maintenance Report	May 6, 2021, 2:04 PM	V-001NV032	Valve Condition	
WO-44840	1	Completed	May 14, 2021, 12:33 PM	May 14, 2021, 12:00 AM	Valve Maintenance Report	May 14, 2021, 12:37 PM	V-001NV035	Valve Condition	
WO-56353	1	Completed	September 1, 2021, 12:52 PM	March 18, 2021, 12:00 AM	Valve Maintenance Report		V-001PV003	Valve Condition	
WO-39444	21	Completed	March 18, 2021, 2:55 PM	March 18, 2021, 12:00 AM	Valve is inoperable and requires replacement	March 18, 2021, 3:08 PM	V-001PV005	Valve Condition	
WO-62438	1	Completed	November 3, 2021, 9:07 AM	November 4, 2021, 12:00 AM	Valve Maintenance Report	November 4, 2021, 11:17 AM	V-001RV021	Valve Condition	Good
WO-58389	1	Completed	September 23, 2021, 9:03 AM	September 23, 2021, 12:00 AM	Valve Maintenance Report	September 23, 2021, 9:05 AM	V-002AV076	Valve Condition	
WO-56997	1	Completed	September 9, 2021, 9:28 AM	September 17, 2021, 12:00 AM	Valve Maintenance Report		V-002AV094	Valve Condition	
WO-65164	1	Completed	December 6, 2021, 3:14 PM	December 14, 2021, 12:00 AM	Valve Maintenance Report	December 14, 2021, 7:32 AM	V-002AV173	Valve Condition	Good
WO-58389	1	Completed	September 23, 2021, 9:03 AM	September 23, 2021, 12:00 AM	Valve Maintenance Report	September 23, 2021, 9:05 AM	V-002AV219	Valve Condition	
WO-58391	1	Completed	September 23, 2021, 9:07 AM	September 23, 2021, 12:00 AM	Valve Maintenance Report	September 23, 2021, 9:08 AM	V-002BV005	Valve Condition	
WO-64338	1	Completed	November 24, 2021, 8:44 AM	November 24, 2021, 12:00 AM	Valve Maintenance Report	November 24, 2021, 8:53 AM	V-002BV016	Valve Condition	
WO-39572	84	Completed	March 19, 2021, 9:26 PM	April 6, 2021, 12:00 AM	Main or service line leak investigation/survey , leak in street in front of Double Tree hotel Clarence 412-281-5800, states they have no water		V-002BV021	Valve Condition	
WO-39572	84	Completed	March 19, 2021, 9:26 PM	April 6, 2021, 12:00 AM	Main or service line leak investigation/survey , leak in street in front of Double Tree hotel Clarence 412-281-5800, states they have no water		V-002BV025	Valve Condition	
WO-39572	84	Completed	March 19, 2021, 9:26 PM	April 6, 2021, 12:00 AM	Main or service line leak investigation/survey , leak in street in front of Double Tree hotel Clarence 412-281-5800, states they have no water		V-002BV029	Valve Condition	
WO-63826	41	Completed	November 18, 2021, 8:50 AM	November 19, 2021, 12:00 AM	Contractor shut request. Folino tie in	November 19, 2021, 1:40 PM	V-002DV013	Valve Condition	
WO-34136	1	Completed	January 21, 2021, 9:45 AM	August 27, 2021, 9:45 AM	Repair water main		V-002DV043	Valve Condition	
WO-63826	41	Completed	November 18, 2021, 8:50 AM	November 19, 2021, 12:00 AM	Contractor shut request. Folino tie in	November 19, 2021, 1:40 PM	V-002DV115	Valve Condition	
WO-34226	1	Completed	January 22, 2021, 6:54 AM	August 30, 2021, 6:54 AM	Repair water main		V-002EV022	Valve Condition	
WO-65164	1	Completed	December 6, 2021, 3:14 PM	December 14, 2021, 12:00 AM	Valve Maintenance Report	December 14, 2021, 7:32 AM	V-002EV061	Valve Condition	Good
WO-65164	1	Completed	December 6, 2021, 3:14 PM	December 14, 2021, 12:00 AM	Valve Maintenance Report	December 14, 2021, 7:32 AM	V-002EV063	Valve Condition	Good
WO-64594	84	Completed	November 30, 2021, 1:02 AM	November 30, 2021, 12:00 AM	INVESTIGATE WATER LEAKING IN THE STREET. STREET IS BEGINNING TO BUCKLE	November 30, 2021, 2:10 AM	V-002EV077	Valve Condition	
WO-65164	1	Completed	December 6, 2021, 3:14 PM	December 14, 2021, 12:00 AM	Valve Maintenance Report	December 14, 2021, 7:32 AM	V-002EV084	Valve Condition	Good
WO-65164	1	Completed	December 6, 2021, 3:14 PM	December 14, 2021, 12:00 AM	Valve Maintenance Report	December 14, 2021, 7:32 AM	V-002EV103	Valve Condition	Good
WO-65164	1	Completed	December 6, 2021, 3:14 PM	December 14, 2021, 12:00 AM	Valve Maintenance Report	December 14, 2021, 7:32 AM	V-002EV104	Valve Condition	Good
WO-65164	1	Completed	December 6, 2021, 3:14 PM	December 14, 2021, 12:00 AM	Valve Maintenance Report	December 14, 2021, 7:32 AM	V-002EV106	Valve Condition	Good
WO-65164	1	Completed	December 6, 2021, 3:14 PM	December 14, 2021, 12:00 AM	Valve Maintenance Report	December 14, 2021, 7:32 AM	V-002EV110	Valve Condition	Good
WO-65164	1	Completed	December 6, 2021, 3:14 PM	December 14, 2021, 12:00 AM	Valve Maintenance Report	December 14, 2021, 7:32 AM	V-002EV113	Valve Condition	Good
WO-65164	1	Completed	December 6, 2021, 3:14 PM	December 14, 2021, 12:00 AM	Valve Maintenance Report	December 14, 2021, 7:32 AM	V-002EV151	Valve Condition	Good
WO-65164	1	Completed	December 6, 2021, 3:14 PM	December 14, 2021, 12:00 AM	Valve Maintenance Report	December 14, 2021, 7:32 AM	V-002EV153	Valve Condition	Good
WO-65558	1	Completed	December 10, 2021, 7:59 AM	December 9, 2021, 12:00 AM	Valve Maintenance Report		V-002FV057	Valve Condition	Good
WO-65558	1	Completed	December 10, 2021, 7:59 AM	December 9, 2021, 12:00 AM	Valve Maintenance Report		V-002FV078	Valve Condition	Good
WO-54316	464	Completed	August 10, 2021, 2:47 PM	August 26, 2021, 12:00 AM	Contractor damage to sewer main	August 26, 2021, 7:33 AM	V-002GV007	Valve Condition	
WO-32386	85	Completed	January 5, 2021, 12:38 AM	January 5, 2021, 12:00 AM	Repair water main	January 5, 2021, 1:25 AM	V-002GV022	Valve Condition	
WO-66423	464	Completed	December 21, 2021, 9:54 AM	December 21, 2021, 12:00 AM	Contractor damage to service line	December 21, 2021, 2:07 PM	V-002GV037	Valve Condition	
WO-32386	85	Completed	January 5, 2021, 12:38 AM	January 5, 2021, 12:00 AM	Repair water main	January 5, 2021, 1:25 AM	V-002GV042	Valve Condition	
WO-61389	43	Completed	October 22, 2021, 11:16 AM	November 4, 2021, 12:00 AM	Test shut		V-002GV045	Valve Condition	
WO-41217	401	Completed	April 9, 2021, 12:09 PM	April 9, 2021, 12:00 AM	Dividing Pressure Valve Maintenance Report	April 9, 2021, 12:19 PM	V-002GV048	Valve Condition	
WO-40085	85	Completed	March 26, 2021, 9:37 AM	April 6, 2021, 12:00 AM	Repair water main 6" main. Water infiltration sewer. ENERGY CENTER NEEDS NOTIFIED. THEY SUPPLY STEAM TO THE HOSPITAL. 1 call valid 3/31/21. NO WATER SURFACING. SEE PICTURES BELOW and SEE SEWER VIDEO IN ATTACHED W.O. Have LD on site when digging	April 6, 2021, 2:40 PM	V-002GV049	Valve Condition	Broke
WO-54316	464	Completed	August 10, 2021, 2:47 PM	August 26, 2021, 12:00 AM	Contractor damage to sewer main	August 26, 2021, 7:33 AM	V-002GV062	Valve Condition	
WO-57283	1	Completed	September 13, 2021, 1:27 PM	September 13, 2021, 12:00 AM	Valve Maintenance Report	September 13, 2021, 1:29 PM	V-002GV075	Valve Condition	
WO-54316	464	Completed	August 10, 2021, 2:47 PM	August 26, 2021, 12:00 AM	Contractor damage to sewer main	August 26, 2021, 7:33 AM	V-002GV086	Valve Condition	
WO-41214	1	Completed	April 9, 2021, 11:20 AM	April 9, 2021, 12:00 AM	Valve Maintenance Report	April 9, 2021, 11:22 AM	V-002HV004	Valve Condition	Good
WO-41193	1	Completed	April 9, 2021, 9:17 AM	April 9, 2021, 12:00 AM	Valve Maintenance Report	April 9, 2021, 9:19 AM	V-002HV005	Valve Condition	
WO-40925	85	Completed	April 6, 2021, 12:26 PM	April 13, 2021, 12:00 AM	Repair water main	April 13, 2021, 3:21 PM	V-002HV006	Valve Condition	Good
WO-41183	1	Completed	April 9, 2021, 8:50 AM	April 9, 2021, 12:00 AM	Valve Maintenance Report	April 9, 2021, 8:51 AM	V-002HV008	Valve Condition	
WO-41187	1	Completed	April 9, 2021, 8:53 AM	April 9, 2021, 12:00 AM	Valve Maintenance Report	April 9, 2021, 8:54 AM	V-002HV009	Valve Condition	
WO-41218	401	Completed	April 9, 2021, 12:21 PM	April 9, 2021, 12:00 AM	Dividing Pressure Valve Maintenance Report	April 9, 2021, 12:22 PM	V-002HV010	Valve Condition	Marginal
WO-61389	43	Completed	October 22, 2021, 11:16 AM	November 4, 2021, 12:00 AM	Test shut		V-002HV011	Valve Condition	
WO-34136	1	Completed	January 21, 2021, 9:45 AM	August 27, 2021, 9:45 AM	Repair water main		V-002HV016	Valve Condition	
WO-41207	1	Completed	April 9, 2021, 10:41 AM	April 9, 2021, 12:00 AM	Valve Maintenance Report	April 9, 2021, 10:44 AM	V-002HV017	Valve Condition	Good
WO-42379	1	Completed	April 21, 2021, 3:31 PM	May 13, 2021, 12:00 AM	Valve Maintenance Report	May 13, 2021, 10:45 AM	V-002HV021	Valve Condition	Good
WO-62690	41	Completed	November 4, 2021, 9:40 AM	November 5, 2021, 12:00 AM	Perform hydrant inspection and flushing	November 5, 2021, 10:04 AM	V-002HV031	Valve Condition	
WO-41200	1	Completed	April 9, 2021, 10:17 AM	April 9, 2021, 12:00 AM	Valve Maintenance Report	April 9, 2021, 10:28 AM	V-002HV032	Valve Condition	
WO-41219	401	Completed	April 9, 2021, 12:24 PM	April 9, 2021, 12:00 AM	Dividing Pressure Valve Maintenance Report	April 9, 2021, 12:27 PM	V-002HV033	Valve Condition	
WO-42379	1	Completed	April 21, 2021, 3:31 PM	May 13, 2021, 12:00 AM	Valve Maintenance Report	May 13, 2021, 10:45 AM	V-002HV037	Valve Condition	Good
WO-42379	1	Completed	April 21, 2021, 3:31 PM	May 13, 2021, 12:00 AM	Valve Maintenance Report	May 13, 2021, 10:45 AM	V-002HV038	Valve Condition	Good
WO-51954	1	Completed	July 14, 2021, 8:14 AM	July 14, 2021, 12:00 AM	Valve Maintenance Report	July 14, 2021, 8:33 AM	V-002HV041	Valve Condition	
WO-63704	41	Completed	November 17, 2021, 9:26 AM	November 17, 2021, 12:00 AM	Contractor shut request	November 17, 2021, 2:56 PM	V-002HV042	Valve Condition	
WO-48152	1	Completed	June 10, 2021, 1:29 PM	June 10, 2021, 12:00 AM	Valve Maintenance Report	June 10, 2021, 1:33 PM	V-002HV048	Valve Condition	
WO-48152	1	Completed	June 10, 2021, 1:29 PM	June 10, 2021, 12:00 AM	Valve Maintenance Report	June 10, 2021, 1:33 PM	V-002HV050	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-63826	41	Completed	November 18, 2021, 8:50 AM	November 19, 2021, 12:00 AM	Contractor shut request. Folino tie in	November 19, 2021, 1:40 PM	V-002HV055	Valve Condition	
WO-63704	41	Completed	November 17, 2021, 9:26 AM	November 17, 2021, 12:00 AM	Contractor shut request	November 17, 2021, 2:56 PM	V-002HV058	Valve Condition	
WO-41213	1	Completed	April 9, 2021, 11:18 AM	April 9, 2021, 12:00 AM	Valve Maintenance Report	April 9, 2021, 11:19 AM	V-002HV066	Valve Condition	Good
WO-44914	41	Completed	May 15, 2021, 8:09 AM	May 15, 2021, 12:00 AM	Contractor shut request, TJ. 21-0139	May 15, 2021, 3:35 PM	V-002JV064	Valve Condition	
WO-43394	41	Completed	May 1, 2021, 9:40 AM	May 2, 2021, 12:00 AM	Contractor shut request- zottola hit main water line. water shooting 100ft into the air.	May 2, 2021, 2:11 PM	V-002JV075	Valve Condition	Good
WO-44717	1	Completed	May 13, 2021, 1:45 PM	May 13, 2021, 12:00 AM	Valve Maintenance Report	May 13, 2021, 1:47 PM	V-002JV077	Valve Condition	
WO-43394	41	Completed	May 1, 2021, 9:40 AM	May 2, 2021, 12:00 AM	Contractor shut request- zottola hit main water line. water shooting 100ft into the air.	May 2, 2021, 2:11 PM	V-002JV088	Valve Condition	Good
WO-43394	41	Completed	May 1, 2021, 9:40 AM	May 2, 2021, 12:00 AM	Contractor shut request- zottola hit main water line. water shooting 100ft into the air.	May 2, 2021, 2:11 PM	V-002JV090	Valve Condition	Good
WO-43394	41	Completed	May 1, 2021, 9:40 AM	May 2, 2021, 12:00 AM	Contractor shut request- zottola hit main water line. water shooting 100ft into the air.	May 2, 2021, 2:11 PM	V-002JV091	Valve Condition	Good
WO-43394	41	Completed	May 1, 2021, 9:40 AM	May 2, 2021, 12:00 AM	Contractor shut request- zottola hit main water line. water shooting 100ft into the air.	May 2, 2021, 2:11 PM	V-002JV092	Valve Condition	Good
WO-43394	41	Completed	May 1, 2021, 9:40 AM	May 2, 2021, 12:00 AM	Contractor shut request- zottola hit main water line. water shooting 100ft into the air.	May 2, 2021, 2:11 PM	V-002JV094	Valve Condition	Good
WO-44704	1	Completed	May 13, 2021, 1:12 PM	May 13, 2021, 12:00 AM	Valve Maintenance Report	May 13, 2021, 1:37 PM	V-002JV129	Valve Condition	
WO-61374	1	Completed	October 22, 2021, 7:42 AM	October 27, 2021, 12:00 AM	Repair water main		V-002KV002	Valve Condition	Good
WO-36127	1	Completed	February 9, 2021, 1:56 PM	February 9, 2021, 12:00 AM	Valve Maintenance Report	February 9, 2021, 2:08 PM	V-002KV006	Valve Condition	Good
WO-66837	41	Completed	December 30, 2021, 8:12 PM	December 30, 2021, 12:00 AM	Contractor shut request Carl 724-259-0226, with NORELCO CORP , PULLED SERCIVE LINE THAT THEY ARE DEAD CAPPING AND THEY NEED SHUT TO MAKE REPAIRS	December 30, 2021, 10:42 PM	V-002KV020	Valve Condition	
WO-43647	85	Completed	May 4, 2021, 2:37 PM	May 4, 2021, 12:00 AM	Repair water main	May 5, 2021, 10:00 AM	V-002KV034	Valve Condition	
WO-36191	41	Completed	February 10, 2021, 10:17 AM	February 10, 2021, 12:00 AM	Contractor shut request	February 10, 2021, 2:01 PM	V-002LV002	Valve Condition	Good
WO-36193	41	Completed	February 10, 2021, 10:20 AM	February 10, 2021, 12:00 AM	Contractor shut request	February 10, 2021, 1:52 PM	V-002LV006	Valve Condition	
WO-56806	464	Completed	September 7, 2021, 3:03 PM	September 7, 2021, 12:00 AM	Contractor damage to sewer main	September 7, 2021, 3:43 PM	V-002LV029	Valve Condition	
WO-36190	41	Completed	February 10, 2021, 10:14 AM	February 10, 2021, 12:00 AM	Contractor shut request	February 10, 2021, 1:51 PM	V-002LV030	Valve Condition	Fair
WO-36187	41	Completed	February 10, 2021, 10:11 AM	February 10, 2021, 12:00 AM	Contractor shut request	February 10, 2021, 1:50 PM	V-002LV031	Valve Condition	Good
WO-55463	41	Completed	August 23, 2021, 11:24 AM	August 23, 2021, 12:00 AM	Contractor shut request	August 23, 2021, 11:29 AM	V-002LV033	Valve Condition	
WO-36186	41	Completed	February 10, 2021, 10:04 AM	February 10, 2021, 12:00 AM	Contractor shut request	February 10, 2021, 2:01 PM	V-002LV037	Valve Condition	
WO-36195	41	Completed	February 10, 2021, 10:23 AM	February 10, 2021, 12:00 AM	Contractor shut request	February 10, 2021, 1:59 PM	V-002LV049	Valve Condition	
WO-36011	1	Completed	February 8, 2021, 10:27 AM	February 8, 2021, 12:00 AM	Valve Maintenance Report	February 8, 2021, 10:28 AM	V-002MV002	Valve Condition	
WO-61389	43	Completed	October 22, 2021, 11:16 AM	November 4, 2021, 12:00 AM	Test shut		V-002MV003	Valve Condition	
WO-48653	41	Completed	June 15, 2021, 10:30 AM	June 15, 2021, 12:00 AM	Contractor shut request, MASCARO CONSTRUCTION	September 2, 2021, 9:04 AM	V-002MV006	Valve Condition	
WO-40386	85	Completed	March 30, 2021, 10:22 AM	March 30, 2021, 12:00 AM	Repair water main	March 30, 2021, 4:49 PM	V-002MV009	Valve Condition	Fair
WO-40386	85	Completed	March 30, 2021, 10:22 AM	March 30, 2021, 12:00 AM	Repair water main	March 30, 2021, 4:49 PM	V-002MV013	Valve Condition	Fair
WO-56459	41	Completed	September 2, 2021, 7:43 AM	February 17, 2021, 12:00 AM	Contractor shut request		V-002MV017	Valve Condition	Good
WO-55396	41	Completed	August 21, 2021, 5:23 PM	August 21, 2021, 12:00 AM	Contractor shut request		V-002MV019	Valve Condition	
WO-61374	1	Completed	October 22, 2021, 7:42 AM	October 27, 2021, 12:00 AM	Repair water main		V-002MV020	Valve Condition	
WO-63704	41	Completed	November 17, 2021, 9:26 AM	November 17, 2021, 12:00 AM	Contractor shut request	November 17, 2021, 2:56 PM	V-002MV022	Valve Condition	
WO-63704	41	Completed	November 17, 2021, 9:26 AM	November 17, 2021, 12:00 AM	Contractor shut request	November 17, 2021, 2:56 PM	V-002MV023	Valve Condition	
WO-62690	41	Completed	November 4, 2021, 9:40 AM	November 5, 2021, 12:00 AM	Perform hydrant inspection and flushing	November 5, 2021, 10:04 AM	V-002MV024	Valve Condition	
WO-55396	41	Completed	August 21, 2021, 5:23 PM	August 21, 2021, 12:00 AM	Contractor shut request		V-002MV030	Valve Condition	
WO-45818	84	Completed	May 24, 2021, 6:09 AM	May 25, 2021, 12:00 AM	INVESTIGATE WATER LEAKING IN STREET	May 25, 2021, 6:35 AM	V-002MV031	Valve Condition	Good
WO-59488	1	Completed	October 5, 2021, 9:41 AM	October 5, 2021, 12:00 AM	Valve Maintenance Report	October 5, 2021, 9:43 AM	V-002MV032	Valve Condition	Good
WO-64125	41	Completed	November 22, 2021, 12:40 PM	November 22, 2021, 12:00 AM	Contractor shut request	November 22, 2021, 2:40 PM	V-002MV033	Valve Condition	
WO-64125	41	Completed	November 22, 2021, 12:40 PM	November 22, 2021, 12:00 AM	Contractor shut request	November 22, 2021, 2:40 PM	V-002MV034	Valve Condition	
WO-64125	41	Completed	November 22, 2021, 12:40 PM	November 22, 2021, 12:00 AM	Contractor shut request	November 22, 2021, 2:40 PM	V-002MV035	Valve Condition	
WO-48149	1	Completed	June 10, 2021, 1:23 PM	June 10, 2021, 12:00 AM	Valve Maintenance Report	June 10, 2021, 1:28 PM	V-002MV038	Valve Condition	
WO-48149	1	Completed	June 10, 2021, 1:23 PM	June 10, 2021, 12:00 AM	Valve Maintenance Report	June 10, 2021, 1:28 PM	V-002MV039	Valve Condition	
WO-64098	41	Completed	November 22, 2021, 10:43 AM	November 22, 2021, 12:00 AM	Contractor shut request	November 22, 2021, 11:57 AM	V-002MV040	Valve Condition	
WO-56459	41	Completed	September 2, 2021, 7:43 AM	February 17, 2021, 12:00 AM	Contractor shut request		V-002MV041	Valve Condition	Good
WO-56459	41	Completed	September 2, 2021, 7:43 AM	February 17, 2021, 12:00 AM	Contractor shut request		V-002MV043	Valve Condition	Good
WO-45818	84	Completed	May 24, 2021, 6:09 AM	May 25, 2021, 12:00 AM	INVESTIGATE WATER LEAKING IN STREET	May 25, 2021, 6:35 AM	V-002MV051	Valve Condition	Good
WO-51312	41	Completed	July 7, 2021, 11:51 AM	July 8, 2021, 12:00 AM	Contractor shut request	July 8, 2021, 10:52 AM	V-002MV052	Valve Condition	
WO-63813	41	Completed	November 17, 2021, 8:45 PM	November 17, 2021, 12:00 AM	Contractor shut request	November 17, 2021, 10:53 PM	V-002MV053	Valve Condition	
WO-59493	1	Completed	October 5, 2021, 9:46 AM	October 5, 2021, 12:00 AM	Valve Maintenance Report	October 5, 2021, 9:49 AM	V-002MV057	Valve Condition	
WO-59493	1	Completed	October 5, 2021, 9:46 AM	October 5, 2021, 12:00 AM	Valve Maintenance Report	October 5, 2021, 9:49 AM	V-002MV058	Valve Condition	
WO-51312	41	Completed	July 7, 2021, 11:51 AM	July 8, 2021, 12:00 AM	Contractor shut request	July 8, 2021, 10:52 AM	V-002MV059	Valve Condition	
WO-65615	41	Completed	December 10, 2021, 12:11 PM	December 10, 2021, 12:00 AM	Contractor shut request	December 10, 2021, 1:46 PM	V-002MV063	Valve Condition	
WO-65615	41	Completed	December 10, 2021, 12:11 PM	December 10, 2021, 12:00 AM	Contractor shut request	December 10, 2021, 1:46 PM	V-002MV065	Valve Condition	
WO-63813	41	Completed	November 17, 2021, 8:45 PM	November 17, 2021, 12:00 AM	Contractor shut request	November 17, 2021, 10:53 PM	V-002MV068	Valve Condition	
WO-42269	84	Completed	April 20, 2021, 9:33 PM	April 21, 2021, 12:00 AM	Main or service line leak investigation/survey/COMPANY WORKING WATER LEAK POSSIBLY HIT LINE WHILE WORKING....JOSEPHINE FAY COMPANY HEATH COPE 412 715 9074 SEE NOTES BELOW	April 21, 2021, 2:41 AM	V-002MV074	Valve Condition	
WO-40386	85	Completed	March 30, 2021, 10:22 AM	March 30, 2021, 12:00 AM	Repair water main	March 30, 2021, 4:49 PM	V-002MV099	Valve Condition	Fair
WO-48653	41	Completed	June 15, 2021, 10:30 AM	June 15, 2021, 12:00 AM	Contractor shut request, MASCARO CONSTRUCTION	September 2, 2021, 9:04 AM	V-002MV101	Valve Condition	
WO-42989	41	Completed	April 28, 2021, 7:25 AM	April 28, 2021, 12:00 AM	Contractor shut request	April 28, 2021, 11:20 AM	V-002MV103	Valve Condition	
WO-42989	41	Completed	April 28, 2021, 7:25 AM	April 28, 2021, 12:00 AM	Contractor shut request	April 28, 2021, 11:20 AM	V-002MV104	Valve Condition	
WO-66837	41	Completed	December 30, 2021, 8:12 PM	December 30, 2021, 12:00 AM	Contractor shut request Carl 724-259-0226, with NORELCO CORP , PULLED SERCIVE LINE THAT THEY ARE DEAD CAPPING AND THEY NEED SHUT TO MAKE REPAIRS	December 30, 2021, 10:42 PM	V-002PV006	Valve Condition	
WO-43647	85	Completed	May 4, 2021, 2:37 PM	May 4, 2021, 12:00 AM	Repair water main	May 5, 2021, 10:00 AM	V-002PV009	Valve Condition	
WO-42989	41	Completed	April 28, 2021, 7:25 AM	April 28, 2021, 12:00 AM	Contractor shut request	April 28, 2021, 11:20 AM	V-002SV009	Valve Condition	
WO-64853	1	Completed	December 2, 2021, 11:40 AM	December 2, 2021, 12:00 AM	Valve Maintenance Report	December 2, 2021, 11:55 AM	V-002SV015	Valve Condition	
WO-64853	1	Completed	December 2, 2021, 11:40 AM	December 2, 2021, 12:00 AM	Valve Maintenance Report	December 2, 2021, 11:55 AM	V-002SV024	Valve Condition	
WO-62438	1	Completed	November 3, 2021, 9:07 AM	November 4, 2021, 12:00 AM	Valve Maintenance Report	November 4, 2021, 11:17 AM	V-003EV028	Valve Condition	Good
WO-64387	563	Completed	November 24, 2021, 11:38 AM	December 1, 2021, 12:00 AM	Water main repair		V-003FV008	Valve Condition	
WO-62438	1	Completed	November 3, 2021, 9:07 AM	November 4, 2021, 12:00 AM	Valve Maintenance Report	November 4, 2021, 11:17 AM	V-003FV023	Valve Condition	Good
WO-64387	563	Completed	November 24, 2021, 11:38 AM	December 1, 2021, 12:00 AM	Water main repair		V-003FV025	Valve Condition	
WO-64387	563	Completed	November 24, 2021, 11:38 AM	December 1, 2021, 12:00 AM	Water main repair		V-003FV038	Valve Condition	
WO-36783	41	Completed	February 17, 2021, 8:45 AM	February 17, 2021, 12:00 AM	Contractor shut request	February 17, 2021, 4:10 PM	V-003GV016	Valve Condition	Good
WO-36784	41	Completed	February 17, 2021, 8:48 AM	February 17, 2021, 12:00 AM	Contractor shut request	February 17, 2021, 4:11 PM	V-003GV017	Valve Condition	
WO-36785	41	Completed	February 17, 2021, 8:51 AM	February 17, 2021, 12:00 AM	Contractor shut request	February 17, 2021, 4:12 PM	V-003GV022	Valve Condition	
WO-64568	1	Completed	November 29, 2021, 2:03 PM	November 29, 2021, 12:00 AM	Valve Maintenance Report	November 29, 2021, 2:07 PM	V-003GV030	Valve Condition	
WO-64768	1	Completed	December 1, 2021, 2:25 PM	December 2, 2021, 12:00 AM	Repair water main 8" MLL Water is off 1 person out of water. Mission crew has a mark. View attached W.O.	December 3, 2021, 9:06 AM	V-003GV031	Valve Condition	
WO-64568	1	Completed	November 29, 2021, 2:03 PM	November 29, 2021, 12:00 AM	Valve Maintenance Report	November 29, 2021, 2:07 PM	V-003GV032	Valve Condition	
WO-34688	43	Completed	January 27, 2021, 9:21 AM	January 27, 2021, 12:00 AM	Test shut	January 27, 2021, 10:45 AM	V-003GV039	Valve Condition	
WO-64387	563	Completed	November 24, 2021, 11:38 AM	December 1, 2021, 12:00 AM	Water main repair		V-003GV049	Valve Condition	
WO-34688	43	Completed	January 27, 2021, 9:21 AM	January 27, 2021, 12:00 AM	Test shut	January 27, 2021, 10:45 AM	V-003GV059	Valve Condition	
WO-34688	43	Completed	January 27, 2021, 9:21 AM	January 27, 2021, 12:00 AM	Test shut	January 27, 2021, 10:45 AM	V-003GV074	Valve Condition	
WO-64387	563	Completed	November 24, 2021, 11:38 AM	December 1, 2021, 12:00 AM	Water main repair		V-003GV081	Valve Condition	
WO-64768	1	Completed	December 1, 2021, 2:25 PM	December 2, 2021, 12:00 AM	Repair water main 8" MLL Water is off 1 person out of water. Mission crew has a mark. View attached W.O.	December 3, 2021, 9:06 AM	V-003GV084	Valve Condition	
WO-64566	1	Completed	November 29, 2021, 1:59 PM	November 29, 2021, 12:00 AM	Valve Maintenance Report	November 29, 2021, 2:02 PM	V-003GV092	Valve Condition	
WO-41405	41	Completed	April 12, 2021, 2:11 PM	April 12, 2021, 12:00 AM	Contractor shut request	April 12, 2021, 2:57 PM	V-003HV032	Valve Condition	
WO-41405	41	Completed	April 12, 2021, 2:11 PM	April 12, 2021, 12:00 AM	Contractor shut request	April 12, 2021, 2:57 PM	V-003HV033	Valve Condition	
WO-41405	41	Completed	April 12, 2021, 2:11 PM	April 12, 2021, 12:00 AM	Contractor shut request	April 12, 2021, 2:57 PM	V-003HV034	Valve Condition	
WO-37313	1	Completed	February 23, 2021, 6:55 PM	February 24, 2021, 12:00 AM	Repair water main		V-003HV038	Valve Condition	
WO-37313	1	Completed	February 23, 2021, 6:55 PM	February 24, 2021, 12:00 AM	Repair water main		V-003HV041	Valve Condition	
WO-37313	1	Completed	February 23, 2021, 6:55 PM	February 24, 2021, 12:00 AM	Repair water main		V-003HV042	Valve Condition	
WO-37313	1	Completed	February 23, 2021, 6:55 PM	February 24, 2021, 12:00 AM	Repair water main		V-003HV046	Valve Condition	
WO-34355	84	Completed	January 23, 2021, 3:40 PM	March 2, 2021, 12:00 AM	Main or service line leak investigation/survey- REPORTS OF A LARGE BREAK AT THIS LOCATION.		V-003HV060	Valve Condition	
WO-59105	41	Completed	September 30, 2021, 9:22 AM	September 30, 2021, 12:00 AM	PGH2O crew shut	September 30, 2021, 2:54 PM	V-003HV067	Valve Condition	
WO-58691	43	Completed	September 27, 2021, 9:08 AM	September 27, 2021, 12:00 AM	Test shut	September 27, 2021, 10:05 AM	V-003HV068	Valve Condition	
WO-60558	43	Completed	October 13, 2021, 2:24 PM	October 26, 2021, 12:00 AM	Test shut	October 26, 2021, 11:46 AM	V-003HV071	Valve Condition	Good
WO-60558	43	Completed	October 13, 2021, 2:24 PM	October 26, 2021, 12:00 AM	Test shut	October 26, 2021, 11:46 AM	V-003HV072	Valve Condition	Good
WO-37313	1	Completed	February 23, 2021, 6:55 PM	February 24, 2021, 12:00 AM	Repair water main		V-003HV080	Valve Condition	
WO-34688	43	Completed	January 27, 2021, 9:21 AM	January 27, 2021, 12:00 AM	Test shut	January 27, 2021, 10:45 AM	V-003LV011	Valve Condition	
WO-41405	41	Completed	April 12, 2021, 2:11 PM	April 12, 2021, 12:00 AM	Contractor shut request	April 12, 2021, 2:57 PM	V-003MV001	Valve Condition	
WO-37945	1	Completed	March 2, 2021, 1:20 PM	August 30, 2021, 12:00 AM	Repair water main		V-003MV005	Valve Condition	Good
WO-37821	88	Completed	March 1, 2021, 3:30 PM	March 23, 2021, 12:00 AM	Repair service line..... Private side was changed to copper. Public Service line leaking, sounded and operated. Site needs marked up and 1 call needs placed. this is a residental account. Jason, if you check out this site call me and i will bring you up to speed. Per Luke	March 23, 2021, 3:54 PM	V-003MV007	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-63870	1	Completed	November 18, 2021, 1:41 PM	November 19, 2021, 12:00 AM	Repair water main		V-003MV014	Valve Condition	
WO-63870	1	Completed	November 18, 2021, 1:41 PM	November 19, 2021, 12:00 AM	Repair water main		V-003MV015	Valve Condition	
WO-34355	84	Completed	January 23, 2021, 3:40 PM	March 2, 2021, 12:00 AM	Main or service line leak investigation/survey- REPORTS OF A LARGE BREAK AT THIS LOCATION.		V-003MV016	Valve Condition	
WO-37528	43	Completed	February 25, 2021, 10:20 AM	February 25, 2021, 12:00 AM	Test shut	February 25, 2021, 10:30 AM	V-003MV020	Valve Condition	
WO-37528	43	Completed	February 25, 2021, 10:20 AM	February 25, 2021, 12:00 AM	Test shut	February 25, 2021, 10:30 AM	V-003MV037	Valve Condition	
WO-37821	88	Completed	March 1, 2021, 3:30 PM	March 23, 2021, 12:00 AM	Repair service line..... Private side was changed to copper. Public Service line leaking, sounded and operated. Site needs marked up and 1 call needs placed. this is a residental account. Jason, if you check out this site call me and i will bring you up to speed. Per Luke	March 23, 2021, 3:54 PM	V-003MV042	Valve Condition	
WO-37945	1	Completed	March 2, 2021, 1:20 PM	August 30, 2021, 12:00 AM	Repair water main		V-003MV043	Valve Condition	Good
WO-61022	1	Completed	October 19, 2021, 5:51 AM	October 19, 2021, 12:00 AM	Valve Maintenance Report	October 19, 2021, 6:06 AM	V-003MV059	Valve Condition	
WO-37821	88	Completed	March 1, 2021, 3:30 PM	March 23, 2021, 12:00 AM	Repair service line..... Private side was changed to copper. Public Service line leaking, sounded and operated. Site needs marked up and 1 call needs placed. this is a residental account. Jason, if you check out this site call me and i will bring you up to speed. Per Luke	March 23, 2021, 3:54 PM	V-003MV061	Valve Condition	
WO-42683	88	Completed	April 25, 2021, 3:24 PM	May 5, 2021, 12:00 AM	Repair service line	May 7, 2021, 7:18 AM	V-003NV023	Valve Condition	
WO-52802	84	Completed	July 22, 2021, 11:49 AM	July 24, 2021, 12:00 AM	Main or service line leak investigation/survey	July 24, 2021, 3:19 PM	V-003PV021	Valve Condition	
WO-52802	84	Completed	July 22, 2021, 11:49 AM	July 24, 2021, 12:00 AM	Main or service line leak investigation/survey	July 24, 2021, 3:19 PM	V-003PV022	Valve Condition	
WO-63018	1	Completed	November 8, 2021, 10:41 AM	November 9, 2021, 12:00 AM	Repair water main		V-003RV003	Valve Condition	
WO-52802	84	Completed	July 22, 2021, 11:49 AM	July 24, 2021, 12:00 AM	Main or service line leak investigation/survey	July 24, 2021, 3:19 PM	V-003RV018	Valve Condition	
WO-52802	84	Completed	July 22, 2021, 11:49 AM	July 24, 2021, 12:00 AM	Main or service line leak investigation/survey	July 24, 2021, 3:19 PM	V-003RV024	Valve Condition	
WO-52802	84	Completed	July 22, 2021, 11:49 AM	July 24, 2021, 12:00 AM	Main or service line leak investigation/survey	July 24, 2021, 3:19 PM	V-003RV025	Valve Condition	
WO-44917	1	Completed	May 15, 2021, 6:38 PM	May 17, 2021, 12:00 AM	Repair water main		V-003SV006	Valve Condition	
WO-34273	1	Completed	January 22, 2021, 10:24 AM	January 22, 2021, 12:00 AM	Valve Maintenance Report	January 22, 2021, 10:30 AM	V-003SV017	Valve Condition	
WO-37598	1	Completed	February 26, 2021, 8:27 AM	August 30, 2021, 12:00 AM	Repair water main		V-003SV018	Valve Condition	
WO-39839	88	Completed	March 24, 2021, 1:13 PM	April 5, 2021, 12:00 AM	Repair service line 3 Day one Call placed 3/24/21 service is 1"copper both sides.	June 17, 2021, 12:31 PM	V-003SV070	Valve Condition	
WO-37245	1	Completed	February 23, 2021, 9:15 AM	February 24, 2021, 12:00 AM	Repair water main		V-004AV007	Valve Condition	
WO-44938	1	Completed	May 17, 2021, 6:25 AM	August 31, 2021, 12:00 AM	Repair water main		V-004AV063	Valve Condition	Good
WO-56353	1	Completed	September 1, 2021, 12:52 PM	March 18, 2021, 12:00 AM	Valve Maintenance Report		V-004AV073	Valve Condition	
WO-58244	1	Completed	September 22, 2021, 7:56 AM	September 22, 2021, 12:00 AM	Valve Maintenance Report	September 22, 2021, 8:17 AM	V-004AV076	Valve Condition	Good
WO-51863	1	Completed	July 13, 2021, 12:55 PM	August 31, 2021, 12:00 AM	Repair water main		V-004BV021	Valve Condition	
WO-53491	41	Completed	August 2, 2021, 9:12 AM	August 2, 2021, 12:00 AM	Contractor shut request	August 2, 2021, 3:18 PM	V-004BV023	Valve Condition	
WO-44344	1	Completed	May 11, 2021, 8:29 AM	May 11, 2021, 12:00 AM	Valve Maintenance Report	May 11, 2021, 8:32 AM	V-004BV024	Valve Condition	
WO-44335	1	Completed	May 11, 2021, 8:14 AM	May 11, 2021, 12:00 AM	Valve Maintenance Report	May 11, 2021, 8:27 AM	V-004BV025	Valve Condition	Good
WO-44938	1	Completed	May 17, 2021, 6:25 AM	August 31, 2021, 12:00 AM	Repair water main		V-004BV026	Valve Condition	Good
WO-44216	1	Completed	May 10, 2021, 9:44 AM	May 10, 2021, 12:00 AM	Valve Maintenance Report	May 10, 2021, 9:54 AM	V-004BV028	Valve Condition	
WO-44248	1	Completed	May 10, 2021, 10:58 AM	May 11, 2021, 12:00 AM	Valve Maintenance Report	May 11, 2021, 7:51 AM	V-004BV029	Valve Condition	
WO-44248	1	Completed	May 10, 2021, 10:58 AM	May 11, 2021, 12:00 AM	Valve Maintenance Report	May 11, 2021, 7:51 AM	V-004BV030	Valve Condition	Fair
WO-44248	1	Completed	May 10, 2021, 10:58 AM	May 11, 2021, 12:00 AM	Valve Maintenance Report	May 11, 2021, 7:51 AM	V-004BV031	Valve Condition	Good
WO-44248	1	Completed	May 10, 2021, 10:58 AM	May 11, 2021, 12:00 AM	Valve Maintenance Report	May 11, 2021, 7:51 AM	V-004BV033	Valve Condition	
WO-44216	1	Completed	May 10, 2021, 9:44 AM	May 10, 2021, 12:00 AM	Valve Maintenance Report	May 10, 2021, 9:54 AM	V-004BV036	Valve Condition	Good
WO-53491	41	Completed	August 2, 2021, 9:12 AM	August 2, 2021, 12:00 AM	Contractor shut request	August 2, 2021, 3:18 PM	V-004BV040	Valve Condition	Good
WO-42917	1	Completed	April 27, 2021, 1:16 PM	April 27, 2021, 12:00 AM	Valve Maintenance Report	April 27, 2021, 2:20 PM	V-004BV044	Valve Condition	Good
WO-53491	41	Completed	August 2, 2021, 9:12 AM	August 2, 2021, 12:00 AM	Contractor shut request	August 2, 2021, 3:18 PM	V-004BV045	Valve Condition	Good
WO-59935	1	Completed	October 7, 2021, 12:43 PM	October 8, 2021, 12:00 AM	Repair water main		V-004BV055	Valve Condition	
WO-44344	1	Completed	May 11, 2021, 8:29 AM	May 11, 2021, 12:00 AM	Valve Maintenance Report	May 11, 2021, 8:32 AM	V-004BV058	Valve Condition	
WO-44534	1	Completed	May 12, 2021, 11:06 AM	May 12, 2021, 12:00 AM	Valve Maintenance Report	May 12, 2021, 11:15 AM	V-004BV064	Valve Condition	Good
WO-58857	1	Completed	September 28, 2021, 9:30 AM	September 28, 2021, 12:00 AM	Valve Maintenance Report	September 28, 2021, 9:36 AM	V-004CV005	Valve Condition	
WO-51863	1	Completed	July 13, 2021, 12:55 PM	August 31, 2021, 12:00 AM	Repair water main		V-004CV010	Valve Condition	
WO-51863	1	Completed	July 13, 2021, 12:55 PM	August 31, 2021, 12:00 AM	Repair water main		V-004CV011	Valve Condition	
WO-44938	1	Completed	May 17, 2021, 6:25 AM	August 31, 2021, 12:00 AM	Repair water main		V-004CV015	Valve Condition	
WO-63736	41	Completed	November 17, 2021, 10:35 AM	December 2, 2021, 12:00 AM	Contractor shut request	December 2, 2021, 11:17 AM	V-004DV012	Valve Condition	
WO-44938	1	Completed	May 17, 2021, 6:25 AM	August 31, 2021, 12:00 AM	Repair water main		V-004EV010	Valve Condition	
WO-44423	85	Completed	May 11, 2021, 1:19 PM	May 12, 2021, 12:00 AM	Repair water main, DOMI-OP-2021-05567	May 12, 2021, 2:45 PM	V-004EV012	Valve Condition	Good
WO-44938	1	Completed	May 17, 2021, 6:25 AM	August 31, 2021, 12:00 AM	Repair water main		V-004EV013	Valve Condition	
WO-44700	1	Completed	May 13, 2021, 12:50 PM	May 13, 2021, 12:00 AM	Valve Maintenance Report	May 13, 2021, 12:55 PM	V-004EV015	Valve Condition	Good
WO-57384	1	Completed	September 14, 2021, 10:08 AM	September 14, 2021, 12:00 AM	Valve Maintenance Report	September 14, 2021, 4:25 PM	V-004EV017	Valve Condition	
WO-54103	1	Completed	August 7, 2021, 6:57 AM	August 9, 2021, 12:00 AM	Repair water main		V-004EV018	Valve Condition	Fair
WO-57384	1	Completed	September 14, 2021, 10:08 AM	September 14, 2021, 12:00 AM	Valve Maintenance Report	September 14, 2021, 4:25 PM	V-004EV019	Valve Condition	
WO-57384	1	Completed	September 14, 2021, 10:08 AM	September 14, 2021, 12:00 AM	Valve Maintenance Report	September 14, 2021, 4:25 PM	V-004EV020	Valve Condition	
WO-43810	21	Completed	May 5, 2021, 2:19 PM	May 7, 2021, 12:00 AM	Valve requires replacement	May 10, 2021, 11:49 AM	V-004EV021	Valve Condition	
WO-44423	85	Completed	May 11, 2021, 1:19 PM	May 12, 2021, 12:00 AM	Repair water main, DOMI-OP-2021-05567	May 12, 2021, 2:45 PM	V-004EV022	Valve Condition	
WO-54103	1	Completed	August 7, 2021, 6:57 AM	August 9, 2021, 12:00 AM	Repair water main		V-004FV001	Valve Condition	Fair
WO-44346	1	Completed	May 11, 2021, 8:48 AM	May 11, 2021, 12:00 AM	Valve Maintenance Report	May 11, 2021, 10:08 AM	V-004FV002	Valve Condition	
WO-44938	1	Completed	May 17, 2021, 6:25 AM	August 31, 2021, 12:00 AM	Repair water main		V-004FV003	Valve Condition	
WO-53491	41	Completed	August 2, 2021, 9:12 AM	August 2, 2021, 12:00 AM	Contractor shut request	August 2, 2021, 3:18 PM	V-004FV008	Valve Condition	
WO-53634	1	Completed	August 3, 2021, 10:25 AM	August 3, 2021, 12:00 AM	Valve Maintenance Report	August 3, 2021, 10:30 AM	V-004FV013	Valve Condition	Fair
WO-53634	1	Completed	August 3, 2021, 10:25 AM	August 3, 2021, 12:00 AM	Valve Maintenance Report	August 3, 2021, 10:30 AM	V-004FV014	Valve Condition	Fair
WO-44341	1	Completed	May 11, 2021, 8:11 AM	May 11, 2021, 12:00 AM	Valve Maintenance Report	May 11, 2021, 8:14 AM	V-004FV016	Valve Condition	Poor
WO-57384	1	Completed	September 14, 2021, 10:08 AM	September 14, 2021, 12:00 AM	Valve Maintenance Report	September 14, 2021, 4:25 PM	V-004FV018	Valve Condition	
WO-45407	1	Completed	May 19, 2021, 12:56 PM	May 19, 2021, 12:00 AM	Valve Maintenance Report	May 19, 2021, 1:13 PM	V-004FV019	Valve Condition	
WO-45561	1	Completed	May 20, 2021, 11:15 AM	May 21, 2021, 12:00 AM	Valve Maintenance Report	May 21, 2021, 10:50 AM	V-004FV020	Valve Condition	
WO-57384	1	Completed	September 14, 2021, 10:08 AM	September 14, 2021, 12:00 AM	Valve Maintenance Report	September 14, 2021, 4:25 PM	V-004FV021	Valve Condition	Poor
WO-45995	1	Completed	May 24, 2021, 2:09 PM	May 24, 2021, 12:00 AM	Valve Maintenance Report	May 24, 2021, 2:12 PM	V-004FV022	Valve Condition	Poor
WO-45546	1	Completed	May 20, 2021, 10:48 AM	May 20, 2021, 12:00 AM	Valve Maintenance Report	May 20, 2021, 10:50 AM	V-004FV028	Valve Condition	Good
WO-45546	1	Completed	May 20, 2021, 10:48 AM	May 20, 2021, 12:00 AM	Valve Maintenance Report	May 20, 2021, 10:50 AM	V-004FV031	Valve Condition	Good
WO-53634	1	Completed	August 3, 2021, 10:25 AM	August 3, 2021, 12:00 AM	Valve Maintenance Report	August 3, 2021, 10:30 AM	V-004FV032	Valve Condition	Fair
WO-43100	41	Completed	April 28, 2021, 1:37 PM	April 29, 2021, 12:00 AM	Contractor shut request/PER FOLINO HIT A LINE NOT SURE IF SERVICE LINE REQUEST A SHUT	April 29, 2021, 10:50 AM	V-004FV033	Valve Condition	Poor
WO-45895	1	Completed	May 24, 2021, 10:22 AM	May 24, 2021, 12:00 AM	Valve Maintenance Report	May 24, 2021, 10:25 AM	V-004GV007	Valve Condition	Good
WO-45895	1	Completed	May 24, 2021, 10:22 AM	May 24, 2021, 12:00 AM	Valve Maintenance Report	May 24, 2021, 10:25 AM	V-004GV008	Valve Condition	Good
WO-46236	84	Completed	May 25, 2021, 9:11 PM	May 26, 2021, 12:00 AM	Main or service line leak investigation/survey, MAIN BREAK , Hello - I received a report of a main break on Shiloh St in front of the Subway shop. , IT ENDED UP BEING A PACKING LEAK FROM FOLINO TYING INTO WATER MAIN	May 26, 2021, 1:32 PM	V-004GV010	Valve Condition	
WO-45905	1	Completed	May 24, 2021, 10:49 AM	May 24, 2021, 12:00 AM	Valve Maintenance Report	May 24, 2021, 10:53 AM	V-004GV011	Valve Condition	Good
WO-45905	1	Completed	May 24, 2021, 10:49 AM	May 24, 2021, 12:00 AM	Valve Maintenance Report	May 24, 2021, 10:53 AM	V-004GV013	Valve Condition	Good
WO-47258	41	Completed	June 3, 2021, 7:07 AM	June 3, 2021, 12:00 AM	Contractor shut request	June 3, 2021, 3:07 PM	V-004GV014	Valve Condition	
WO-45213	1	Completed	May 18, 2021, 9:34 AM	May 18, 2021, 12:00 AM	Valve Maintenance Report	May 18, 2021, 9:59 AM	V-004GV015	Valve Condition	Good
WO-44473	1	Completed	May 12, 2021, 8:01 AM	May 12, 2021, 12:00 AM	Valve Maintenance Report	May 12, 2021, 8:03 AM	V-004GV020	Valve Condition	Good
WO-44474	1	Completed	May 12, 2021, 8:05 AM	May 12, 2021, 12:00 AM	Valve Maintenance Report	May 12, 2021, 8:07 AM	V-004GV021	Valve Condition	
WO-44470	1	Completed	May 12, 2021, 7:58 AM	May 12, 2021, 12:00 AM	Valve Maintenance Report	May 12, 2021, 8:04 AM	V-004GV023	Valve Condition	
WO-32264	1	Completed	January 2, 2021, 10:36 PM	January 11, 2021, 10:36 PM	Repair water main	January 21, 2021, 11:30 AM	V-004GV053	Valve Condition	
WO-62438	1	Completed	November 3, 2021, 9:07 AM	November 4, 2021, 12:00 AM	Valve Maintenance Report	November 4, 2021, 11:17 AM	V-004HV016	Valve Condition	Good
WO-62438	1	Completed	November 3, 2021, 9:07 AM	November 4, 2021, 12:00 AM	Valve Maintenance Report	November 4, 2021, 11:17 AM	V-004HV017	Valve Condition	Good
WO-61171	21	Completed	October 20, 2021, 8:14 AM	October 20, 2021, 12:00 AM	Valve requires replacement- If the valve is unmapped, use Install New Valve work order	October 20, 2021, 8:17 AM	V-004HV018	Valve Condition	
WO-63736	41	Completed	November 17, 2021, 10:35 AM	December 2, 2021, 12:00 AM	Contractor shut request	December 2, 2021, 11:17 AM	V-004HV020	Valve Condition	
WO-63736	41	Completed	November 17, 2021, 10:35 AM	December 2, 2021, 12:00 AM	Contractor shut request	December 2, 2021, 11:17 AM	V-004HV021	Valve Condition	
WO-43810	21	Completed	May 5, 2021, 2:19 PM	May 7, 2021, 12:00 AM	Valve requires replacement	May 10, 2021, 11:49 AM	V-004JV003	Valve Condition	
WO-43709	41	Completed	May 5, 2021, 8:58 AM	May 5, 2021, 12:00 AM	Contractor shut request	May 5, 2021, 1:51 PM	V-004JV004	Valve Condition	Good
WO-54026	43	Completed	August 6, 2021, 8:45 AM	August 6, 2021, 12:00 AM	Test shut	August 6, 2021, 12:43 PM	V-004JV006	Valve Condition	
WO-43810	21	Completed	May 5, 2021, 2:19 PM	May 7, 2021, 12:00 AM	Valve requires replacement	May 10, 2021, 11:49 AM	V-004JV007	Valve Condition	
WO-54433	41	Completed	August 11, 2021, 11:14 AM	August 11, 2021, 12:00 AM	Contractor shut request	August 11, 2021, 2:27 PM	V-004JV008	Valve Condition	
WO-44404	41	Completed	May 11, 2021, 12:14 PM	May 12, 2021, 12:00 AM	Contractor shut request, Folino working for PGH2O	May 12, 2021, 8:22 AM	V-004JV010	Valve Condition	
WO-56294	1	Completed	September 1, 2021, 10:43 AM	May 7, 2021, 12:00 AM	Valve Maintenance Report		V-004JV011	Valve Condition	Good
WO-54026	43	Completed	August 6, 2021, 8:45 AM	August 6, 2021, 12:00 AM	Test shut	August 6, 2021, 12:43 PM	V-004JV012	Valve Condition	
WO-54026	43	Completed	August 6, 2021, 8:45 AM	August 6, 2021, 12:00 AM	Test shut	August 6, 2021, 12:43 PM	V-004JV013	Valve Condition	Good
WO-56294	1	Completed	September 1, 2021, 10:43 AM	May 7, 2021, 12:00 AM	Valve Maintenance Report		V-004JV014	Valve Condition	Good
WO-43810	21	Completed	May 5, 2021, 2:19 PM	May 7, 2021, 12:00 AM	Valve requires replacement	May 10, 2021, 11:49 AM	V-004JV015	Valve Condition	
WO-44206	1	Completed	May 10, 2021, 9:23 AM	May 10, 2021, 12:00 AM	Valve Maintenance Report	May 10, 2021, 9:37 AM	V-004JV016	Valve Condition	
WO-45600	1	Completed	May 20, 2021, 1:43 PM	May 21, 2021, 12:00 AM	Valve Maintenance Report	May 21, 2021, 9:47 AM	V-004JV017	Valve Condition	
WO-45600	1	Completed	May 20, 2021, 1:43 PM	May 21, 2021, 12:00 AM	Valve Maintenance Report	May 21, 2021, 9:47 AM	V-004JV018	Valve Condition	
WO-45600	1	Completed	May 20, 2021, 1:43 PM	May 21, 2021, 12:00 AM	Valve Maintenance Report	May 21, 2021, 9:47 AM	V-004JV020	Valve Condition	
WO-45600	1	Completed	May 20, 2021, 1:43 PM	May 21, 2021, 12:00 AM	Valve Maintenance Report	May 21, 2021, 9:47 AM	V-004JV021	Valve Condition	
WO-43709	41	Completed	May 5, 2021, 8:58 AM	May 5, 2021, 12:00 AM	Contractor shut request	May 5, 2021, 1:51 PM	V-004JV022	Valve Condition	Good
WO-47366	1	Completed	June 3, 2021, 10:53 AM	June 3, 2021, 12:00 AM	Valve Maintenance Report	June 3, 2021, 11:50 AM	V-004JV024	Valve Condition	Good
WO-47366	1	Completed	June 3, 2021, 10:53 AM	June 3, 2021, 12:00 AM	Valve Maintenance Report	June 3, 2021, 11:50 AM	V-004JV025	Valve Condition	Good
WO-45933	1	Completed	May 24, 2021, 11:56 AM	May 24, 2021, 12:00 AM	Valve Maintenance Report	May 24, 2021, 12:19 PM	V-004JV026	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-45933	1	Completed	May 24, 2021, 11:56 AM	May 24, 2021, 12:00 AM	Valve Maintenance Report	May 24, 2021, 12:19 PM	V-004JV027	Valve Condition	
WO-45933	1	Completed	May 24, 2021, 11:56 AM	May 24, 2021, 12:00 AM	Valve Maintenance Report	May 24, 2021, 12:19 PM	V-004JV028	Valve Condition	
WO-45941	1	Completed	May 24, 2021, 12:21 PM	May 24, 2021, 12:00 AM	Valve Maintenance Report	May 24, 2021, 12:22 PM	V-004JV029	Valve Condition	
WO-45992	1	Completed	May 24, 2021, 2:04 PM	May 24, 2021, 12:00 AM	Valve Maintenance Report	May 24, 2021, 2:07 PM	V-004KV001	Valve Condition	
WO-45992	1	Completed	May 24, 2021, 2:04 PM	May 24, 2021, 12:00 AM	Valve Maintenance Report	May 24, 2021, 2:07 PM	V-004KV002	Valve Condition	
WO-45975	1	Completed	May 24, 2021, 1:26 PM	May 24, 2021, 12:00 AM	Valve Maintenance Report	May 24, 2021, 2:03 PM	V-004KV003	Valve Condition	Good
WO-45958	1	Completed	May 24, 2021, 12:58 PM	May 24, 2021, 12:00 AM	Valve Maintenance Report	May 24, 2021, 1:16 PM	V-004KV004	Valve Condition	Good
WO-45958	1	Completed	May 24, 2021, 12:58 PM	May 24, 2021, 12:00 AM	Valve Maintenance Report	May 24, 2021, 1:16 PM	V-004KV005	Valve Condition	Good
WO-45958	1	Completed	May 24, 2021, 12:58 PM	May 24, 2021, 12:00 AM	Valve Maintenance Report	May 24, 2021, 1:16 PM	V-004KV006	Valve Condition	Good
WO-32459	1	Completed	January 5, 2021, 1:09 PM	January 5, 2021, 12:00 AM	Valve Maintenance Report	January 5, 2021, 1:11 PM	V-004KV021	Valve Condition	
WO-32059	1	Completed	December 30, 2020, 10:58 AM	January 5, 2021, 10:58 AM	Repair water main	January 21, 2021, 10:34 AM	V-004KV024	Valve Condition	
WO-32458	43	Completed	January 5, 2021, 1:03 PM	January 5, 2021, 12:00 AM	Test shut	January 5, 2021, 1:07 PM	V-004KV026	Valve Condition	
WO-46510	1	Completed	May 27, 2021, 11:36 AM	May 27, 2021, 12:00 AM	Valve Maintenance Report	May 27, 2021, 11:37 AM	V-004KV030	Valve Condition	
WO-46512	1	Completed	May 27, 2021, 11:48 AM	May 27, 2021, 12:00 AM	Valve Maintenance Report	May 27, 2021, 11:51 AM	V-004KV031	Valve Condition	
WO-46512	1	Completed	May 27, 2021, 11:48 AM	May 27, 2021, 12:00 AM	Valve Maintenance Report	May 27, 2021, 11:51 AM	V-004KV032	Valve Condition	
WO-46517	1	Completed	May 27, 2021, 11:53 AM	May 28, 2021, 12:00 AM	Valve Maintenance Report	May 28, 2021, 12:00 PM	V-004KV033	Valve Condition	Good
WO-46517	1	Completed	May 27, 2021, 11:53 AM	May 28, 2021, 12:00 AM	Valve Maintenance Report	May 28, 2021, 12:00 PM	V-004KV034	Valve Condition	Good
WO-46517	1	Completed	May 27, 2021, 11:53 AM	May 28, 2021, 12:00 AM	Valve Maintenance Report	May 28, 2021, 12:00 PM	V-004KV035	Valve Condition	Good
WO-46062	1	Completed	May 25, 2021, 8:50 AM	May 25, 2021, 12:00 AM	Valve Maintenance Report	May 25, 2021, 12:31 PM	V-004KV047	Valve Condition	
WO-46062	1	Completed	May 25, 2021, 8:50 AM	May 25, 2021, 12:00 AM	Valve Maintenance Report	May 25, 2021, 12:31 PM	V-004KV048	Valve Condition	
WO-46062	1	Completed	May 25, 2021, 8:50 AM	May 25, 2021, 12:00 AM	Valve Maintenance Report	May 25, 2021, 12:31 PM	V-004KV049	Valve Condition	
WO-44482	1	Completed	May 12, 2021, 10:20 AM	August 31, 2021, 12:00 AM	Valve Maintenance Report		V-004LV006	Valve Condition	Good
WO-44482	1	Completed	May 12, 2021, 10:20 AM	August 31, 2021, 12:00 AM	Valve Maintenance Report		V-004LV007	Valve Condition	Good
WO-44222	1	Completed	May 10, 2021, 10:13 AM	May 10, 2021, 12:00 AM	Valve Maintenance Report	May 10, 2021, 10:26 AM	V-004LV009	Valve Condition	
WO-44482	1	Completed	May 12, 2021, 10:20 AM	August 31, 2021, 12:00 AM	Valve Maintenance Report		V-004LV012	Valve Condition	Good
WO-44482	1	Completed	May 12, 2021, 10:20 AM	August 31, 2021, 12:00 AM	Valve Maintenance Report		V-004LV024	Valve Condition	Good
WO-44482	1	Completed	May 12, 2021, 10:20 AM	August 31, 2021, 12:00 AM	Valve Maintenance Report		V-004LV041	Valve Condition	Good
WO-38134	1	Completed	March 4, 2021, 8:31 AM	August 30, 2021, 12:00 AM	Repair water main		V-004LV044	Valve Condition	
WO-44996	1	Completed	May 17, 2021, 10:00 AM	May 17, 2021, 12:00 AM	Valve Maintenance Report	May 17, 2021, 10:02 AM	V-004MV005	Valve Condition	Fair
WO-44997	1	Completed	May 17, 2021, 10:04 AM	May 17, 2021, 12:00 AM	Valve Maintenance Report	May 17, 2021, 10:08 AM	V-004MV013	Valve Condition	Good
WO-44997	1	Completed	May 17, 2021, 10:04 AM	May 17, 2021, 12:00 AM	Valve Maintenance Report	May 17, 2021, 10:08 AM	V-004MV017	Valve Condition	Good
WO-47367	1	Completed	June 3, 2021, 11:02 AM	June 3, 2021, 12:00 AM	Valve Maintenance Report	June 3, 2021, 11:51 AM	V-004NV002	Valve Condition	Good
WO-47360	1	Completed	June 3, 2021, 10:44 AM	June 3, 2021, 12:00 AM	Valve Maintenance Report	June 3, 2021, 10:49 AM	V-004NV003	Valve Condition	Good
WO-47360	1	Completed	June 3, 2021, 10:44 AM	June 3, 2021, 12:00 AM	Valve Maintenance Report	June 3, 2021, 10:49 AM	V-004NV004	Valve Condition	Good
WO-45948	1	Completed	May 24, 2021, 12:39 PM	May 24, 2021, 12:00 AM	Valve Maintenance Report	May 24, 2021, 12:51 PM	V-004NV005	Valve Condition	
WO-45948	1	Completed	May 24, 2021, 12:39 PM	May 24, 2021, 12:00 AM	Valve Maintenance Report	May 24, 2021, 12:51 PM	V-004NV006	Valve Condition	
WO-45948	1	Completed	May 24, 2021, 12:39 PM	May 24, 2021, 12:00 AM	Valve Maintenance Report	May 24, 2021, 12:51 PM	V-004NV007	Valve Condition	
WO-47349	1	Completed	June 3, 2021, 9:59 AM	June 3, 2021, 12:00 AM	Valve Maintenance Report	June 3, 2021, 10:06 AM	V-004NV008	Valve Condition	Poor
WO-47349	1	Completed	June 3, 2021, 9:59 AM	June 3, 2021, 12:00 AM	Valve Maintenance Report	June 3, 2021, 10:06 AM	V-004NV009	Valve Condition	Poor
WO-47349	1	Completed	June 3, 2021, 9:59 AM	June 3, 2021, 12:00 AM	Valve Maintenance Report	June 3, 2021, 10:06 AM	V-004NV010	Valve Condition	Poor
WO-65065	84	Completed	December 4, 2021, 7:16 PM	December 8, 2021, 12:00 AM	Main or service line leak investigation/survey- LEAK IN STREET.	December 8, 2021, 11:57 PM	V-004NV015	Valve Condition	
WO-48435	683	Completed	June 14, 2021, 8:18 AM	June 13, 2021, 12:00 AM	Work site details for reporting		V-004NV016	Valve Condition	
WO-47360	1	Completed	June 3, 2021, 10:44 AM	June 3, 2021, 12:00 AM	Valve Maintenance Report	June 3, 2021, 10:49 AM	V-004NV017	Valve Condition	Good
WO-47360	1	Completed	June 3, 2021, 10:44 AM	June 3, 2021, 12:00 AM	Valve Maintenance Report	June 3, 2021, 10:49 AM	V-004NV018	Valve Condition	Good
WO-47367	1	Completed	June 3, 2021, 11:02 AM	June 3, 2021, 12:00 AM	Valve Maintenance Report	June 3, 2021, 11:51 AM	V-004NV019	Valve Condition	Good
WO-46858	1	Completed	June 1, 2021, 1:35 PM	June 1, 2021, 12:00 AM	Valve Maintenance Report	June 1, 2021, 1:44 PM	V-004PV001	Valve Condition	Fair
WO-46858	1	Completed	June 1, 2021, 1:35 PM	June 1, 2021, 12:00 AM	Valve Maintenance Report	June 1, 2021, 1:44 PM	V-004PV002	Valve Condition	Fair
WO-46858	1	Completed	June 1, 2021, 1:35 PM	June 1, 2021, 12:00 AM	Valve Maintenance Report	June 1, 2021, 1:44 PM	V-004PV003	Valve Condition	Fair
WO-46858	1	Completed	June 1, 2021, 1:35 PM	June 1, 2021, 12:00 AM	Valve Maintenance Report	June 1, 2021, 1:44 PM	V-004PV005	Valve Condition	Fair
WO-65243	1	Completed	December 7, 2021, 10:06 AM	December 7, 2021, 12:00 AM	Repair water main		V-004PV006	Valve Condition	
WO-65243	1	Completed	December 7, 2021, 10:06 AM	December 7, 2021, 12:00 AM	Repair water main		V-004PV015	Valve Condition	
WO-33159	85	Completed	January 12, 2021, 10:19 AM	June 2, 2021, 12:00 AM	Repair water main	June 2, 2021, 12:10 PM	V-004PV018	Valve Condition	
WO-51268	85	Completed	July 7, 2021, 7:17 AM	July 7, 2021, 12:00 AM	Repair water main	July 7, 2021, 3:13 PM	V-004PV023	Valve Condition	
WO-66100	1	Completed	December 16, 2021, 11:38 AM	December 16, 2021, 12:00 AM	Valve Maintenance Report	December 16, 2021, 12:28 PM	V-004PV034	Valve Condition	
WO-66100	1	Completed	December 16, 2021, 11:38 AM	December 16, 2021, 12:00 AM	Valve Maintenance Report	December 16, 2021, 12:28 PM	V-004PV035	Valve Condition	
WO-48296	43	Completed	June 11, 2021, 1:46 PM	June 11, 2021, 12:00 AM	Test shut	June 11, 2021, 1:58 PM	V-004PV036	Valve Condition	
WO-48296	43	Completed	June 11, 2021, 1:46 PM	June 11, 2021, 12:00 AM	Test shut	June 11, 2021, 1:58 PM	V-004PV037	Valve Condition	
WO-50626	1	Completed	June 30, 2021, 10:08 AM	June 30, 2021, 12:00 AM	Valve Maintenance Report	June 30, 2021, 11:07 AM	V-004PV038	Valve Condition	Good
WO-66100	1	Completed	December 16, 2021, 11:38 AM	December 16, 2021, 12:00 AM	Valve Maintenance Report	December 16, 2021, 12:28 PM	V-004PV039	Valve Condition	
WO-33159	85	Completed	January 12, 2021, 10:19 AM	June 2, 2021, 12:00 AM	Repair water main	June 2, 2021, 12:10 PM	V-004PV040	Valve Condition	
WO-39936	1	Completed	March 25, 2021, 9:11 AM	March 26, 2021, 12:00 AM	Valve Maintenance Report. Shut for crew	March 26, 2021, 9:38 AM	V-004RV004	Valve Condition	Good
WO-39936	1	Completed	March 25, 2021, 9:11 AM	March 26, 2021, 12:00 AM	Valve Maintenance Report. Shut for crew	March 26, 2021, 9:38 AM	V-004RV016	Valve Condition	
WO-46399	1	Completed	May 26, 2021, 2:13 PM	June 2, 2021, 12:00 AM	Valve Maintenance Report	May 26, 2021, 2:16 PM	V-004RV035	Valve Condition	Good
WO-39936	1	Completed	March 25, 2021, 9:11 AM	March 26, 2021, 12:00 AM	Valve Maintenance Report. Shut for crew	March 26, 2021, 9:38 AM	V-004RV036	Valve Condition	Good
WO-46399	1	Completed	May 26, 2021, 2:13 PM	June 2, 2021, 12:00 AM	Valve Maintenance Report	May 26, 2021, 2:16 PM	V-004RV037	Valve Condition	Good
WO-45703	1	Completed	May 21, 2021, 11:01 AM	May 21, 2021, 12:00 AM	Valve Maintenance Report	May 21, 2021, 11:25 AM	V-004SV001	Valve Condition	
WO-45703	1	Completed	May 21, 2021, 11:01 AM	May 21, 2021, 12:00 AM	Valve Maintenance Report	May 21, 2021, 11:25 AM	V-004SV002	Valve Condition	
WO-45690	1	Completed	May 21, 2021, 10:21 AM	May 21, 2021, 12:00 AM	Valve Maintenance Report	May 21, 2021, 10:47 AM	V-004SV003	Valve Condition	
WO-45690	1	Completed	May 21, 2021, 10:21 AM	May 21, 2021, 12:00 AM	Valve Maintenance Report	May 21, 2021, 10:47 AM	V-004SV004	Valve Condition	
WO-45690	1	Completed	May 21, 2021, 10:21 AM	May 21, 2021, 12:00 AM	Valve Maintenance Report	May 21, 2021, 10:47 AM	V-004SV005	Valve Condition	
WO-45735	1	Completed	May 21, 2021, 1:08 PM	May 21, 2021, 12:00 AM	Valve Maintenance Report	May 21, 2021, 1:12 PM	V-004SV010	Valve Condition	Good
WO-45735	1	Completed	May 21, 2021, 1:08 PM	May 21, 2021, 12:00 AM	Valve Maintenance Report	May 21, 2021, 1:12 PM	V-004SV012	Valve Condition	Good
WO-45689	1	Completed	May 21, 2021, 10:18 AM	May 21, 2021, 12:00 AM	Valve Maintenance Report	May 21, 2021, 10:20 AM	V-004SV016	Valve Condition	
WO-45746	1	Completed	May 21, 2021, 1:42 PM	May 21, 2021, 12:00 AM	Valve Maintenance Report	May 21, 2021, 2:05 PM	V-004SV017	Valve Condition	
WO-35748	1	Completed	February 4, 2021, 11:16 PM	February 5, 2021, 12:00 AM	Valve Maintenance Report	February 5, 2021, 2:22 AM	V-004SV020	Valve Condition	
WO-35778	1	Completed	February 5, 2021, 7:00 AM	February 8, 2021, 7:00 AM	Repair water main		V-004SV021	Valve Condition	
WO-64679	1	Completed	December 1, 2021, 1:08 AM	December 2, 2021, 12:00 AM	Repair water main		V-004SV023	Valve Condition	Good
WO-64679	1	Completed	December 1, 2021, 1:08 AM	December 2, 2021, 12:00 AM	Repair water main		V-004SV027	Valve Condition	Good
WO-64679	1	Completed	December 1, 2021, 1:08 AM	December 2, 2021, 12:00 AM	Repair water main		V-004SV028	Valve Condition	Good
WO-64679	1	Completed	December 1, 2021, 1:08 AM	December 2, 2021, 12:00 AM	Repair water main		V-004SV029	Valve Condition	Good
WO-64679	1	Completed	December 1, 2021, 1:08 AM	December 2, 2021, 12:00 AM	Repair water main		V-004SV030	Valve Condition	Good
WO-45703	1	Completed	May 21, 2021, 11:01 AM	May 21, 2021, 12:00 AM	Valve Maintenance Report	May 21, 2021, 11:25 AM	V-004SV035	Valve Condition	
WO-64967	1	Completed	December 3, 2021, 10:51 AM	December 3, 2021, 12:00 AM	Valve Maintenance Report	December 3, 2021, 10:53 AM	V-005AV001	Valve Condition	
WO-64968	1	Completed	December 3, 2021, 10:54 AM	December 3, 2021, 12:00 AM	Valve Maintenance Report	December 3, 2021, 10:57 AM	V-005AV002	Valve Condition	
WO-64556	1	Completed	November 29, 2021, 1:22 PM	November 29, 2021, 12:00 AM	Valve Maintenance Report	November 29, 2021, 1:25 PM	V-005AV003	Valve Condition	
WO-64971	1	Completed	December 3, 2021, 11:00 AM	December 3, 2021, 12:00 AM	Valve Maintenance Report	December 3, 2021, 11:04 AM	V-005AV004	Valve Condition	
WO-64974	1	Completed	December 3, 2021, 11:09 AM	December 3, 2021, 12:00 AM	Valve Maintenance Report	December 3, 2021, 11:15 AM	V-005AV005	Valve Condition	Good
WO-64999	1	Completed	December 3, 2021, 12:47 PM	December 3, 2021, 12:00 AM	Valve Maintenance Report	December 3, 2021, 12:49 PM	V-005AV006	Valve Condition	
WO-65000	1	Completed	December 3, 2021, 12:51 PM	December 3, 2021, 12:00 AM	Valve Maintenance Report	December 3, 2021, 12:53 PM	V-005AV007	Valve Condition	
WO-64562	1	Completed	November 29, 2021, 1:48 PM	November 29, 2021, 12:00 AM	Valve Maintenance Report	November 29, 2021, 1:51 PM	V-005AV009	Valve Condition	
WO-64246	1	Completed	November 23, 2021, 10:26 AM	November 23, 2021, 12:00 AM	Valve Maintenance Report	November 23, 2021, 12:04 PM	V-005AV010	Valve Condition	
WO-58897	563	Completed	September 28, 2021, 12:17 PM	October 6, 2021, 12:00 AM	Water main repair PGH2O Crews doing repairs	October 6, 2021, 1:29 PM	V-005AV011	Valve Condition	Good
WO-64240	1	Completed	November 23, 2021, 10:16 AM	November 23, 2021, 12:00 AM	Valve Maintenance Report	November 23, 2021, 12:04 PM	V-005AV012	Valve Condition	
WO-64244	1	Completed	November 23, 2021, 10:22 AM	November 23, 2021, 12:00 AM	Valve Maintenance Report	November 23, 2021, 12:04 PM	V-005AV013	Valve Condition	Good
WO-64978	1	Completed	December 3, 2021, 11:16 AM	December 3, 2021, 12:00 AM	Valve Maintenance Report	December 3, 2021, 12:46 PM	V-005AV016	Valve Condition	
WO-65003	1	Completed	December 3, 2021, 12:54 PM	December 3, 2021, 12:00 AM	Valve Maintenance Report	December 3, 2021, 12:58 PM	V-005AV017	Valve Condition	
WO-64242	1	Completed	November 23, 2021, 10:19 AM	November 23, 2021, 12:00 AM	Valve Maintenance Report	November 23, 2021, 12:04 PM	V-005AV019	Valve Condition	
WO-65381	1	Completed	December 8, 2021, 5:44 PM	December 10, 2021, 12:00 AM	Repair water main		V-005AV020	Valve Condition	Good
WO-64561	1	Completed	November 29, 2021, 1:43 PM	November 29, 2021, 12:00 AM	Valve Maintenance Report	November 29, 2021, 1:47 PM	V-005AV021	Valve Condition	
WO-58897	563	Completed	September 28, 2021, 12:17 PM	October 6, 2021, 12:00 AM	Water main repair PGH2O Crews doing repairs	October 6, 2021, 1:29 PM	V-005AV022	Valve Condition	Good
WO-64860	1	Completed	December 2, 2021, 12:17 PM	December 2, 2021, 12:00 AM	Valve Maintenance Report	December 2, 2021, 3:16 PM	V-005BV001	Valve Condition	
WO-51619	1	Completed	July 10, 2021, 7:04 AM	July 13, 2021, 12:00 AM	Repair water main	July 13, 2021, 1:34 PM	V-005BV012	Valve Condition	
WO-64848	1	Completed	December 2, 2021, 10:55 AM	December 2, 2021, 12:00 AM	Valve Maintenance Report	December 2, 2021, 10:58 AM	V-005BV013	Valve Condition	
WO-64852	1	Completed	December 2, 2021, 11:32 AM	December 2, 2021, 12:00 AM	Valve Maintenance Report	December 2, 2021, 3:17 PM	V-005BV014	Valve Condition	
WO-64852	1	Completed	December 2, 2021, 11:32 AM	December 2, 2021, 12:00 AM	Valve Maintenance Report	December 2, 2021, 3:17 PM	V-005BV015	Valve Condition	
WO-65109	1	Completed	December 6, 2021, 8:13 AM	December 20, 2021, 12:00 AM	Valve Maintenance Report	December 20, 2021, 2:15 PM	V-005CV001	Valve Condition	
WO-65112	1	Completed	December 6, 2021, 8:17 AM	December 20, 2021, 12:00 AM	Valve Maintenance Report	December 20, 2021, 2:15 PM	V-005CV004	Valve Condition	
WO-65009	1	Completed	December 3, 2021, 1:23 PM	December 3, 2021, 12:00 AM	Valve Maintenance Report	December 3, 2021, 2:30 PM	V-005CV005	Valve Condition	
WO-65008	1	Completed	December 3, 2021, 1:18 PM	December 3, 2021, 12:00 AM	Valve Maintenance Report	December 3, 2021, 2:30 PM	V-005CV006	Valve Condition	
WO-65010	1	Completed	December 3, 2021, 1:26 PM	December 3, 2021, 12:00 AM	Valve Maintenance Report	December 3, 2021, 2:30 PM	V-005CV007	Valve Condition	
WO-65107	1	Completed	December 6, 2021, 8:10 AM	December 6, 2021, 12:00 AM	Valve Maintenance Report	December 6, 2021, 8:12 AM	V-005CV008	Valve Condition	
WO-66762	1	Completed	December 29, 2021, 11:25 AM	December 29, 2021, 12:00 AM	Valve Maintenance Report	December 29, 2021, 12:17 PM	V-005CV010	Valve Condition	
WO-50356	1	Completed	June 28, 2021, 10:57 AM	October 13, 2021, 12:00 AM	Valve Maintenance Report		V-005CV013	Valve Condition	
WO-66772	1	Completed	December 29, 2021, 12:38 PM	December 29, 2021, 12:00 AM	Valve Maintenance Report	December 29, 2021, 12:40 PM	V-005CV014	Valve Condition	
WO-66770	1	Completed	December 29, 2021, 12:30 PM	December 29, 2021, 12:00 AM	Valve Maintenance Report	December 29, 2021, 12:34 PM	V-005CV015	Valve Condition	
WO-54494	1	Completed	August 12, 2021, 8:29 AM	August 12, 2021, 12:00 AM	Valve Maintenance Report	August 12, 2021, 8:35 AM	V-005CV017	Valve Condition	
WO-41723	41	Completed	April 15, 2021, 9:10 AM	April 15, 2021, 12:00 AM	Contractor shut request	April 15, 2021, 5:33 PM	V-005CV018	Valve Condition	Good
WO-40380	464	Completed	March 30, 2021, 9:36 AM	March 30, 2021, 12:00 AM	Contractor damage to 6"water main	March 30, 2021, 10:55 AM	V-005CV019	Valve Condition	Fair
WO-54974	1	Completed	August 17, 2021, 12:01 PM	August 17, 2021, 12:00 AM	Valve Maintenance Report	August 17, 2021, 12:03 PM	V-005CV021	Valve Condition	
WO-66705	1	Completed	December 28, 2021, 12:25 PM	December 28, 2021, 12:00 AM	Valve Maintenance Report	December 28, 2021, 2:06 PM	V-005CV026	Valve Condition	
WO-66706	1	Completed	December 28, 2021, 12:28 PM	December 28, 2021, 12:00 AM	Valve Maintenance Report	December 28, 2021, 2:06 PM	V-005CV027	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-66720	1	Completed	December 28, 2021, 2:24 PM	December 28, 2021, 12:00 AM	Valve Maintenance Report	December 28, 2021, 2:28 PM	V-005CV028	Valve Condition	
WO-66720	1	Completed	December 28, 2021, 2:24 PM	December 28, 2021, 12:00 AM	Valve Maintenance Report	December 28, 2021, 2:28 PM	V-005CV029	Valve Condition	
WO-66700	1	Completed	December 28, 2021, 11:22 AM	December 28, 2021, 12:00 AM	Valve Maintenance Report	December 28, 2021, 12:24 PM	V-005CV030	Valve Condition	
WO-54494	1	Completed	August 12, 2021, 8:29 AM	August 12, 2021, 12:00 AM	Valve Maintenance Report	August 12, 2021, 8:35 AM	V-005CV032	Valve Condition	Good
WO-66691	1	Completed	December 28, 2021, 10:25 AM	December 28, 2021, 12:00 AM	Valve Maintenance Report	December 28, 2021, 11:10 AM	V-005CV033	Valve Condition	
WO-66695	1	Completed	December 28, 2021, 10:58 AM	December 28, 2021, 12:00 AM	Valve Maintenance Report	December 28, 2021, 11:04 AM	V-005CV034	Valve Condition	
WO-66699	1	Completed	December 28, 2021, 11:19 AM	December 28, 2021, 12:00 AM	Valve Maintenance Report	December 28, 2021, 11:45 AM	V-005CV035	Valve Condition	
WO-66690	1	Completed	December 28, 2021, 10:19 AM	December 28, 2021, 12:00 AM	Valve Maintenance Report	December 28, 2021, 10:57 AM	V-005CV036	Valve Condition	
WO-50471	1	Completed	June 29, 2021, 12:40 PM	June 29, 2021, 12:00 AM	Valve Maintenance Report	June 29, 2021, 12:43 PM	V-005CV037	Valve Condition	
WO-44971	41	Completed	May 17, 2021, 9:21 AM	May 18, 2021, 12:00 AM	Contractor shut request, Meta st	May 19, 2021, 1:15 AM	V-005DV003	Valve Condition	Poor
WO-54494	1	Completed	August 12, 2021, 8:29 AM	August 12, 2021, 12:00 AM	Valve Maintenance Report	August 12, 2021, 8:35 AM	V-005DV006	Valve Condition	Good
WO-40224	41	Completed	March 29, 2021, 8:36 AM	March 30, 2021, 12:00 AM	Contractor shut request. Folino tie	March 30, 2021, 6:57 AM	V-005DV008	Valve Condition	
WO-41723	41	Completed	April 15, 2021, 9:10 AM	April 15, 2021, 12:00 AM	Contractor shut request	April 15, 2021, 5:33 PM	V-005DV009	Valve Condition	Good
WO-54494	1	Completed	August 12, 2021, 8:29 AM	August 12, 2021, 12:00 AM	Valve Maintenance Report	August 12, 2021, 8:35 AM	V-005DV010	Valve Condition	Good
WO-38762	43	Completed	March 11, 2021, 10:44 AM	March 11, 2021, 12:00 AM	Test shut On 12"" and 6" mains	March 11, 2021, 12:19 PM	V-005DV011	Valve Condition	Good
WO-57238	1	Completed	September 13, 2021, 9:11 AM	September 24, 2021, 12:00 AM	Repair water main 8" main. Water showed chlorine immediately on field sample. Dig where the water is. 3 day 1 call placed and valid on 9/16/21		V-005DV023	Valve Condition	Good
WO-58244	1	Completed	September 22, 2021, 7:56 AM	September 22, 2021, 12:00 AM	Valve Maintenance Report	September 22, 2021, 8:17 AM	V-005DV024	Valve Condition	
WO-58244	1	Completed	September 22, 2021, 7:56 AM	September 22, 2021, 12:00 AM	Valve Maintenance Report	September 22, 2021, 8:17 AM	V-005DV025	Valve Condition	
WO-51619	1	Completed	July 10, 2021, 7:04 AM	July 13, 2021, 12:00 AM	Repair water main	July 13, 2021, 1:34 PM	V-005FV004	Valve Condition	
WO-35940	85	Completed	February 7, 2021, 2:59 PM	February 7, 2021, 12:00 AM	Repair water main	February 7, 2021, 8:31 PM	V-005FV010	Valve Condition	
WO-59097	85	Completed	September 30, 2021, 9:06 AM	October 1, 2021, 12:00 AM	Repair water main	October 18, 2021, 12:57 PM	V-005GV002	Valve Condition	
WO-44668	1	Completed	May 13, 2021, 11:06 AM	May 13, 2021, 12:00 AM	Valve Maintenance Report	May 13, 2021, 11:13 AM	V-005GV003	Valve Condition	Good
WO-44971	41	Completed	May 17, 2021, 9:21 AM	May 18, 2021, 12:00 AM	Contractor shut request, Meta st	May 19, 2021, 1:15 AM	V-005GV004	Valve Condition	Poor
WO-59098	1	Completed	September 30, 2021, 9:06 AM	October 1, 2021, 12:00 AM	Repair water main		V-005GV006	Valve Condition	
WO-35940	85	Completed	February 7, 2021, 2:59 PM	February 7, 2021, 12:00 AM	Repair water main	February 7, 2021, 8:31 PM	V-005GV008	Valve Condition	
WO-44668	1	Completed	May 13, 2021, 11:06 AM	May 13, 2021, 12:00 AM	Valve Maintenance Report	May 13, 2021, 11:13 AM	V-005GV010	Valve Condition	Poor
WO-54494	1	Completed	August 12, 2021, 8:29 AM	August 12, 2021, 12:00 AM	Valve Maintenance Report	August 12, 2021, 8:35 AM	V-005HV003	Valve Condition	Poor
WO-35940	85	Completed	February 7, 2021, 2:59 PM	February 7, 2021, 12:00 AM	Repair water main	February 7, 2021, 8:31 PM	V-005LV002	Valve Condition	
WO-44345	1	Completed	May 11, 2021, 8:32 AM	May 11, 2021, 12:00 AM	Valve Maintenance Report	May 11, 2021, 8:34 AM	V-005MV009	Valve Condition	
WO-49426	1	Completed	June 21, 2021, 11:01 AM	September 9, 2021, 12:00 AM	Repair water main		V-006AV009	Valve Condition	
WO-49424	85	Completed	June 21, 2021, 11:01 AM	September 7, 2021, 12:00 AM	Repair water main 6" MLL or on the service at the ferrell. See pictures below. 3 day 1 call placed 8/12/21 Water is not surfacing but its getting into a storm drain and dumping into the creek behind guard rail. Maps are showing a 2 valve shut.	September 7, 2021, 2:58 PM	V-006AV010	Valve Condition	
WO-49426	1	Completed	June 21, 2021, 11:01 AM	September 9, 2021, 12:00 AM	Repair water main		V-006AV011	Valve Condition	
WO-35210	1	Completed	February 1, 2021, 9:23 AM	February 1, 2021, 12:00 AM	Valve Maintenance Report		V-006CV001	Valve Condition	Good
WO-48688	1	Completed	June 15, 2021, 1:07 PM	August 31, 2021, 12:00 AM	Repair water main		V-006FV019	Valve Condition	
WO-42324	1	Completed	April 21, 2021, 10:23 AM	April 21, 2021, 12:00 AM	Valve Maintenance Report	April 21, 2021, 10:44 AM	V-006GV002	Valve Condition	Fair
WO-42324	1	Completed	April 21, 2021, 10:23 AM	April 21, 2021, 12:00 AM	Valve Maintenance Report	April 21, 2021, 10:44 AM	V-006GV003	Valve Condition	Fair
WO-42324	1	Completed	April 21, 2021, 10:23 AM	April 21, 2021, 12:00 AM	Valve Maintenance Report	April 21, 2021, 10:44 AM	V-006GV004	Valve Condition	Fair
WO-53957	1	Completed	August 5, 2021, 1:45 PM	August 5, 2021, 12:00 AM	Valve Maintenance Report	August 5, 2021, 1:55 PM	V-006GV014	Valve Condition	
WO-53957	1	Completed	August 5, 2021, 1:45 PM	August 5, 2021, 12:00 AM	Valve Maintenance Report	August 5, 2021, 1:55 PM	V-006GV015	Valve Condition	
WO-48688	1	Completed	June 15, 2021, 1:07 PM	August 31, 2021, 12:00 AM	Repair water main		V-006GV025	Valve Condition	
WO-42353	1	Completed	April 21, 2021, 1:47 PM	April 21, 2021, 12:00 AM	Valve Maintenance Report	April 21, 2021, 1:49 PM	V-006GV026	Valve Condition	
WO-53957	1	Completed	August 5, 2021, 1:45 PM	August 5, 2021, 12:00 AM	Valve Maintenance Report	August 5, 2021, 1:55 PM	V-006GV043	Valve Condition	
WO-42332	1	Completed	April 21, 2021, 10:45 AM	April 21, 2021, 12:00 AM	Valve Maintenance Report	April 21, 2021, 12:42 PM	V-006GV046	Valve Condition	
WO-42332	1	Completed	April 21, 2021, 10:45 AM	April 21, 2021, 12:00 AM	Valve Maintenance Report	April 21, 2021, 12:42 PM	V-006GV047	Valve Condition	
WO-42332	1	Completed	April 21, 2021, 10:45 AM	April 21, 2021, 12:00 AM	Valve Maintenance Report	April 21, 2021, 12:42 PM	V-006GV050	Valve Condition	
WO-42361	1	Completed	April 21, 2021, 2:08 PM	April 21, 2021, 12:00 AM	Valve Maintenance Report	April 21, 2021, 2:29 PM	V-006KV001	Valve Condition	
WO-42361	1	Completed	April 21, 2021, 2:08 PM	April 21, 2021, 12:00 AM	Valve Maintenance Report	April 21, 2021, 2:29 PM	V-006KV002	Valve Condition	
WO-42361	1	Completed	April 21, 2021, 2:08 PM	April 21, 2021, 12:00 AM	Valve Maintenance Report	April 21, 2021, 2:29 PM	V-006KV003	Valve Condition	
WO-42361	1	Completed	April 21, 2021, 2:08 PM	April 21, 2021, 12:00 AM	Valve Maintenance Report	April 21, 2021, 2:29 PM	V-006KV005	Valve Condition	
WO-42639	1	Completed	April 23, 2021, 1:54 PM	April 23, 2021, 12:00 AM	Valve Maintenance Report	April 23, 2021, 2:21 PM	V-006KV009	Valve Condition	
WO-53645	1	Completed	August 3, 2021, 11:09 AM	August 3, 2021, 12:00 AM	Valve Maintenance Report	August 3, 2021, 11:44 AM	V-006KV012	Valve Condition	Fair
WO-42639	1	Completed	April 23, 2021, 1:54 PM	April 23, 2021, 12:00 AM	Valve Maintenance Report	April 23, 2021, 2:21 PM	V-006KV016	Valve Condition	
WO-53400	43	Completed	July 30, 2021, 1:23 PM	July 30, 2021, 12:00 AM	Test shut	July 30, 2021, 1:33 PM	V-006KV018	Valve Condition	
WO-47681	41	Completed	June 7, 2021, 9:18 AM	June 7, 2021, 12:00 AM	Contractor shut request	June 7, 2021, 2:12 PM	V-006KV020	Valve Condition	
WO-38079	41	Completed	March 3, 2021, 1:39 PM	March 9, 2021, 12:00 AM	Contractor shut request		V-006KV021	Valve Condition	
WO-53645	1	Completed	August 3, 2021, 11:09 AM	August 3, 2021, 12:00 AM	Valve Maintenance Report	August 3, 2021, 11:44 AM	V-006KV023	Valve Condition	Good
WO-53400	43	Completed	July 30, 2021, 1:23 PM	July 30, 2021, 12:00 AM	Test shut	July 30, 2021, 1:33 PM	V-006KV025	Valve Condition	Good
WO-53645	1	Completed	August 3, 2021, 11:09 AM	August 3, 2021, 12:00 AM	Valve Maintenance Report	August 3, 2021, 11:44 AM	V-006KV026	Valve Condition	
WO-47681	41	Completed	June 7, 2021, 9:18 AM	June 7, 2021, 12:00 AM	Contractor shut request	June 7, 2021, 2:12 PM	V-006KV027	Valve Condition	Good
WO-34193	1	Completed	January 21, 2021, 4:08 PM	January 22, 2021, 4:08 PM	Repair water main		V-006LV012	Valve Condition	
WO-34193	1	Completed	January 21, 2021, 4:08 PM	January 22, 2021, 4:08 PM	Repair water main		V-006LV013	Valve Condition	
WO-53400	43	Completed	July 30, 2021, 1:23 PM	July 30, 2021, 12:00 AM	Test shut	July 30, 2021, 1:33 PM	V-006LV023	Valve Condition	Good
WO-35587	1	Completed	February 4, 2021, 2:52 AM	February 5, 2021, 2:52 AM	Repair water main		V-006MV028	Valve Condition	Good
WO-35587	1	Completed	February 4, 2021, 2:52 AM	February 5, 2021, 2:52 AM	Repair water main		V-006MV036	Valve Condition	Good
WO-51994	43	Completed	July 14, 2021, 10:38 AM	July 14, 2021, 12:00 AM	Test shut	July 14, 2021, 10:45 AM	V-006RV007	Valve Condition	Good
WO-51994	43	Completed	July 14, 2021, 10:38 AM	July 14, 2021, 12:00 AM	Test shut	July 14, 2021, 10:45 AM	V-006RV029	Valve Condition	Good
WO-41759	1	Completed	April 15, 2021, 2:06 PM	April 15, 2021, 12:00 AM	Valve Maintenance Report	April 15, 2021, 2:07 PM	V-006SV012	Valve Condition	
WO-41723	41	Completed	April 15, 2021, 9:10 AM	April 15, 2021, 12:00 AM	Contractor shut request	April 15, 2021, 5:33 PM	V-006SV015	Valve Condition	Good
WO-43975	1	Completed	May 6, 2021, 2:06 PM	May 6, 2021, 12:00 AM	Valve Maintenance Report	May 6, 2021, 2:07 PM	V-006SV059	Valve Condition	Good
WO-32267	1	Completed	January 3, 2021, 2:47 AM	January 5, 2021, 2:47 AM	Repair water main	January 21, 2021, 9:25 AM	V-007BV019	Valve Condition	
WO-32267	1	Completed	January 3, 2021, 2:47 AM	January 5, 2021, 2:47 AM	Repair water main	January 21, 2021, 9:25 AM	V-007BV021	Valve Condition	
WO-32267	1	Completed	January 3, 2021, 2:47 AM	January 5, 2021, 2:47 AM	Repair water main	January 21, 2021, 9:25 AM	V-007BV023	Valve Condition	
WO-32267	1	Completed	January 3, 2021, 2:47 AM	January 5, 2021, 2:47 AM	Repair water main	January 21, 2021, 9:25 AM	V-007BV028	Valve Condition	
WO-51854	1	Completed	July 13, 2021, 12:16 PM	July 13, 2021, 12:00 AM	Valve Maintenance Report	July 13, 2021, 12:30 PM	V-007BV036	Valve Condition	Good
WO-51854	1	Completed	July 13, 2021, 12:16 PM	July 13, 2021, 12:00 AM	Valve Maintenance Report	July 13, 2021, 12:30 PM	V-007BV037	Valve Condition	Good
WO-51854	1	Completed	July 13, 2021, 12:16 PM	July 13, 2021, 12:00 AM	Valve Maintenance Report	July 13, 2021, 12:30 PM	V-007BV038	Valve Condition	Good
WO-50658	1	Completed	June 30, 2021, 11:53 AM	August 31, 2021, 12:00 AM	Repair water main		V-007BV039	Valve Condition	
WO-64381	1	Completed	November 24, 2021, 10:36 AM	November 24, 2021, 12:00 AM	Valve Maintenance Report	November 24, 2021, 10:45 AM	V-007BV041	Valve Condition	
WO-51854	1	Completed	July 13, 2021, 12:16 PM	July 13, 2021, 12:00 AM	Valve Maintenance Report	July 13, 2021, 12:30 PM	V-007BV046	Valve Condition	Good
WO-51854	1	Completed	July 13, 2021, 12:16 PM	July 13, 2021, 12:00 AM	Valve Maintenance Report	July 13, 2021, 12:30 PM	V-007BV047	Valve Condition	Good
WO-51854	1	Completed	July 13, 2021, 12:16 PM	July 13, 2021, 12:00 AM	Valve Maintenance Report	July 13, 2021, 12:30 PM	V-007BV049	Valve Condition	Good
WO-32267	1	Completed	January 3, 2021, 2:47 AM	January 5, 2021, 2:47 AM	Repair water main	January 21, 2021, 9:25 AM	V-007CV005	Valve Condition	
WO-51121	182	Completed	July 6, 2021, 8:46 AM	July 7, 2021, 12:00 AM	Information sheet for connection		V-007CV008	Valve Condition	Good
WO-51121	182	Completed	July 6, 2021, 8:46 AM	July 7, 2021, 12:00 AM	Information sheet for connection		V-007CV015	Valve Condition	Good
WO-32267	1	Completed	January 3, 2021, 2:47 AM	January 5, 2021, 2:47 AM	Repair water main	January 21, 2021, 9:25 AM	V-007CV039	Valve Condition	
WO-54053	1	Completed	August 6, 2021, 1:29 PM	August 6, 2021, 12:00 AM	Valve Maintenance Report	August 6, 2021, 3:10 PM	V-007DV031	Valve Condition	
WO-54053	1	Completed	August 6, 2021, 1:29 PM	August 6, 2021, 12:00 AM	Valve Maintenance Report	August 6, 2021, 3:10 PM	V-007DV032	Valve Condition	
WO-54053	1	Completed	August 6, 2021, 1:29 PM	August 6, 2021, 12:00 AM	Valve Maintenance Report	August 6, 2021, 3:10 PM	V-007DV033	Valve Condition	
WO-54046	1	Completed	August 6, 2021, 12:46 PM	August 6, 2021, 12:00 AM	Valve Maintenance Report	August 6, 2021, 1:27 PM	V-007DV037	Valve Condition	
WO-54046	1	Completed	August 6, 2021, 12:46 PM	August 6, 2021, 12:00 AM	Valve Maintenance Report	August 6, 2021, 1:27 PM	V-007DV038	Valve Condition	
WO-54046	1	Completed	August 6, 2021, 12:46 PM	August 6, 2021, 12:00 AM	Valve Maintenance Report	August 6, 2021, 1:27 PM	V-007DV040	Valve Condition	
WO-48139	41	Completed	June 10, 2021, 12:39 PM	June 14, 2021, 12:00 AM	Contractor shut request	June 14, 2021, 12:53 PM	V-007LV006	Valve Condition	
WO-48139	41	Completed	June 10, 2021, 12:39 PM	June 14, 2021, 12:00 AM	Contractor shut request	June 14, 2021, 12:53 PM	V-007MV027	Valve Condition	
WO-36956	84	Completed	February 18, 2021, 8:52 PM	February 20, 2021, 12:00 AM	Main or service line leak investigation/survey/PER EOC-911/ CHECK FOR A WATER LEAK COMING FROM UNDER MANHOLE COVER WATER RUNNING STEADY INTO MIDDLE OF THE STREET POOLING ON THE OUTBOUND LANE/W CARSON ST TO W END BRDG TOWARD W END CIRCLE	February 20, 2021, 7:11 PM	V-007NV003	Valve Condition	Good
WO-35210	1	Completed	February 1, 2021, 9:23 AM	February 1, 2021, 12:00 AM	Valve Maintenance Report		V-007PV008	Valve Condition	Good
WO-54046	1	Completed	August 6, 2021, 12:46 PM	August 6, 2021, 12:00 AM	Valve Maintenance Report	August 6, 2021, 1:27 PM	V-008AV012	Valve Condition	
WO-55162	1	Completed	August 19, 2021, 8:36 AM	August 19, 2021, 12:00 AM	Valve Maintenance Report	August 19, 2021, 1:29 PM	V-008BV001	Valve Condition	Good
WO-55162	1	Completed	August 19, 2021, 8:36 AM	August 19, 2021, 12:00 AM	Valve Maintenance Report	August 19, 2021, 1:29 PM	V-008BV003	Valve Condition	Good
WO-55162	1	Completed	August 19, 2021, 8:36 AM	August 19, 2021, 12:00 AM	Valve Maintenance Report	August 19, 2021, 1:29 PM	V-008BV006	Valve Condition	Good
WO-43301	1	Completed	April 30, 2021, 10:22 AM	April 30, 2021, 12:00 AM	Valve Maintenance Report	April 30, 2021, 10:23 AM	V-008BV010	Valve Condition	Good
WO-55162	1	Completed	August 19, 2021, 8:36 AM	August 19, 2021, 12:00 AM	Valve Maintenance Report	August 19, 2021, 1:29 PM	V-008BV011	Valve Condition	Good
WO-55162	1	Completed	August 19, 2021, 8:36 AM	August 19, 2021, 12:00 AM	Valve Maintenance Report	August 19, 2021, 1:29 PM	V-008BV012	Valve Condition	Good
WO-55162	1	Completed	August 19, 2021, 8:36 AM	August 19, 2021, 12:00 AM	Valve Maintenance Report	August 19, 2021, 1:29 PM	V-008CV003	Valve Condition	Good
WO-55162	1	Completed	August 19, 2021, 8:36 AM	August 19, 2021, 12:00 AM	Valve Maintenance Report	August 19, 2021, 1:29 PM	V-008CV013	Valve Condition	Good
WO-57425	1	Completed	September 14, 2021, 1:17 PM	September 14, 2021, 12:00 AM	Valve Maintenance Report	September 14, 2021, 1:19 PM	V-008CV020	Valve Condition	
WO-50140	1	Completed	June 25, 2021, 1:06 PM	June 25, 2021, 12:00 AM	Valve Maintenance Report	June 25, 2021, 1:08 PM	V-008DV018	Valve Condition	
WO-58377	1	Completed	September 23, 2021, 7:49 AM	September 23, 2021, 12:00 AM	Valve Maintenance Report	September 23, 2021, 7:54 AM	V-008DV027	Valve Condition	
WO-52736	683	Completed	July 21, 2021, 4:23 PM	July 21, 2021, 12:00 AM	Work site details for reporting VANTAGE CORP PULLED SERVICE	July 23, 2021, 7:09 AM	V-008DV029	Valve Condition	
WO-52736	683	Completed	July 21, 2021, 4:23 PM	July 21, 2021, 12:00 AM	Work site details for reporting VANTAGE CORP PULLED SERVICE	July 23, 2021, 7:09 AM	V-008DV035	Valve Condition	
WO-50706	1	Completed	June 30, 2021, 6:49 PM	August 31, 2021, 12:00 AM	Repair water main. Leak on hydrant branch		V-008GV002	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-57220	1	Completed	September 13, 2021, 1:45 AM	September 16, 2021, 12:00 AM	Valve Maintenance Report		V-008GV005	Valve Condition	Fair
WO-58354	21	Completed	September 23, 2021, 12:02 AM	September 22, 2021, 12:00 AM	Valve requires replacement	September 23, 2021, 12:31 AM	V-008GV006	Valve Condition	Good
WO-57220	1	Completed	September 13, 2021, 1:45 AM	September 16, 2021, 12:00 AM	Valve Maintenance Report		V-008GV007	Valve Condition	Fair
WO-57220	1	Completed	September 13, 2021, 1:45 AM	September 16, 2021, 12:00 AM	Valve Maintenance Report		V-008GV009	Valve Condition	Fair
WO-58377	1	Completed	September 23, 2021, 7:49 AM	September 23, 2021, 12:00 AM	Valve Maintenance Report	September 23, 2021, 7:54 AM	V-008GV023	Valve Condition	
WO-50588	1	Completed	June 30, 2021, 9:25 AM	June 30, 2021, 12:00 AM	Valve Maintenance Report	June 30, 2021, 9:28 AM	V-008GV026	Valve Condition	Good
WO-52418	85	Completed	July 19, 2021, 9:57 AM	July 21, 2021, 12:00 AM	Repair water main (LEAK ON HYDRANT BRANCH)3 day one call placed 7/19/21	July 21, 2021, 1:26 PM	V-008GV049	Valve Condition	
WO-57426	1	Completed	September 14, 2021, 1:20 PM	September 14, 2021, 12:00 AM	Valve Maintenance Report	September 14, 2021, 1:21 PM	V-008GV054	Valve Condition	Good
WO-58377	1	Completed	September 23, 2021, 7:49 AM	September 23, 2021, 12:00 AM	Valve Maintenance Report	September 23, 2021, 7:54 AM	V-008HV002	Valve Condition	
WO-45661	85	Completed	May 21, 2021, 8:49 AM	July 1, 2021, 12:00 AM	Repair water main	July 1, 2021, 2:26 AM	V-008HV010	Valve Condition	Good
WO-45661	85	Completed	May 21, 2021, 8:49 AM	July 1, 2021, 12:00 AM	Repair water main	July 1, 2021, 2:26 AM	V-008HV025	Valve Condition	Good
WO-45661	85	Completed	May 21, 2021, 8:49 AM	July 1, 2021, 12:00 AM	Repair water main	July 1, 2021, 2:26 AM	V-008HV028	Valve Condition	Good
WO-50141	1	Completed	June 25, 2021, 1:16 PM	June 25, 2021, 12:00 AM	Valve Maintenance Report	June 25, 2021, 1:45 PM	V-008KV015	Valve Condition	
WO-50141	1	Completed	June 25, 2021, 1:16 PM	June 25, 2021, 12:00 AM	Valve Maintenance Report	June 25, 2021, 1:45 PM	V-008KV019	Valve Condition	
WO-50141	1	Completed	June 25, 2021, 1:16 PM	June 25, 2021, 12:00 AM	Valve Maintenance Report	June 25, 2021, 1:45 PM	V-008KV031	Valve Condition	
WO-38702	85	Completed	March 11, 2021, 6:13 AM	March 12, 2021, 12:00 AM	Repair water main	March 12, 2021, 2:54 PM	V-008LV043	Valve Condition	
WO-61983	84	Completed	October 28, 2021, 3:34 PM	October 28, 2021, 12:00 AM	Main or service line leak investigation/survey/PER PLUMBER WORKING AT COMMERCIAL SITE 41 ISABELLA ST CANNOT SHUT OFF WATER FOR FIREL LINE REQUEST IT BE SHUT IN STREET 6 INCH VALVE OFF MAIN WATER IN GUSHING INTO TRANSFORMER BOX ASKING FOR HELP ASAP		V-008MV009	Valve Condition	
WO-60662	1	Completed	October 14, 2021, 11:59 AM	October 14, 2021, 12:00 AM	Valve Maintenance Report	October 14, 2021, 12:15 PM	V-008RV029	Valve Condition	
WO-58329	1	Completed	September 22, 2021, 2:28 PM	September 22, 2021, 12:00 AM	Valve Maintenance Report	September 22, 2021, 2:30 PM	V-008SV020	Valve Condition	
WO-58330	1	Completed	September 22, 2021, 2:31 PM	September 22, 2021, 12:00 AM	Valve Maintenance Report	September 22, 2021, 2:34 PM	V-008SV024	Valve Condition	
WO-58125	1	Completed	September 21, 2021, 10:51 AM	September 24, 2021, 12:00 AM	Valve Maintenance Report	September 24, 2021, 10:52 AM	V-008SV025	Valve Condition	
WO-58125	1	Completed	September 21, 2021, 10:51 AM	September 24, 2021, 12:00 AM	Valve Maintenance Report	September 24, 2021, 10:52 AM	V-008SV027	Valve Condition	
WO-58125	1	Completed	September 21, 2021, 10:51 AM	September 24, 2021, 12:00 AM	Valve Maintenance Report	September 24, 2021, 10:52 AM	V-008SV029	Valve Condition	
WO-58330	1	Completed	September 22, 2021, 2:31 PM	September 22, 2021, 12:00 AM	Valve Maintenance Report	September 22, 2021, 2:34 PM	V-008SV040	Valve Condition	
WO-58125	1	Completed	September 21, 2021, 10:51 AM	September 24, 2021, 12:00 AM	Valve Maintenance Report	September 24, 2021, 10:52 AM	V-008SV044	Valve Condition	
WO-58125	1	Completed	September 21, 2021, 10:51 AM	September 24, 2021, 12:00 AM	Valve Maintenance Report	September 24, 2021, 10:52 AM	V-008SV065	Valve Condition	
WO-58125	1	Completed	September 21, 2021, 10:51 AM	September 24, 2021, 12:00 AM	Valve Maintenance Report	September 24, 2021, 10:52 AM	V-008SV067	Valve Condition	
WO-58312	1	Completed	September 22, 2021, 1:21 PM	September 22, 2021, 12:00 AM	Valve Maintenance Report	September 22, 2021, 1:22 PM	V-008SV077	Valve Condition	
WO-58313	1	Completed	September 22, 2021, 1:23 PM	September 22, 2021, 12:00 AM	Valve Maintenance Report	September 22, 2021, 1:25 PM	V-008SV085	Valve Condition	
WO-58125	1	Completed	September 21, 2021, 10:51 AM	September 24, 2021, 12:00 AM	Valve Maintenance Report	September 24, 2021, 10:52 AM	V-008SV111	Valve Condition	
WO-42272	43	Completed	April 20, 2021, 10:45 PM	April 21, 2021, 12:00 AM	Test shut	April 21, 2021, 2:47 PM	V-009AV013	Valve Condition	
WO-42272	43	Completed	April 20, 2021, 10:45 PM	April 21, 2021, 12:00 AM	Test shut	April 21, 2021, 2:47 PM	V-009AV014	Valve Condition	
WO-37179	85	Completed	February 22, 2021, 1:12 PM	April 21, 2021, 12:00 AM	Repair water main	April 21, 2021, 2:28 PM	V-009AV019	Valve Condition	Good
WO-65504	85	Completed	December 9, 2021, 2:35 PM	December 15, 2021, 12:00 AM	Repair water main	December 15, 2021, 7:04 AM	V-009BV003	Valve Condition	
WO-62822	1	Completed	November 5, 2021, 11:37 AM	November 8, 2021, 12:00 AM	Repair water main		V-009BV021	Valve Condition	
WO-36635	84	Completed	February 16, 2021, 8:02 AM	February 16, 2021, 12:00 AM	eoc called to report water main break that is buckling the street	February 16, 2021, 2:08 PM	V-009DV041	Valve Condition	Good
WO-42015	1	Completed	April 19, 2021, 9:38 AM	May 12, 2021, 12:00 AM	Valve Maintenance Report, liberty ave	May 12, 2021, 2:21 PM	V-009DV044	Valve Condition	
WO-37179	85	Completed	February 22, 2021, 1:12 PM	April 21, 2021, 12:00 AM	Repair water main	April 21, 2021, 2:28 PM	V-009EV016	Valve Condition	Good
WO-37179	85	Completed	February 22, 2021, 1:12 PM	April 21, 2021, 12:00 AM	Repair water main	April 21, 2021, 2:28 PM	V-009EV032	Valve Condition	Good
WO-37179	85	Completed	February 22, 2021, 1:12 PM	April 21, 2021, 12:00 AM	Repair water main	April 21, 2021, 2:28 PM	V-009EV033	Valve Condition	Good
WO-37179	85	Completed	February 22, 2021, 1:12 PM	April 21, 2021, 12:00 AM	Repair water main	April 21, 2021, 2:28 PM	V-009EV034	Valve Condition	Good
WO-39413	43	Completed	March 18, 2021, 10:18 AM	March 18, 2021, 12:00 AM	Test shut, for INDEPENDENT CONTRACTOR	March 18, 2021, 10:38 AM	V-009FV002	Valve Condition	
WO-39534	41	Completed	March 19, 2021, 1:25 PM	March 20, 2021, 12:00 AM	Contractor shut request	March 20, 2021, 7:27 PM	V-009FV003	Valve Condition	
WO-57674	1	Completed	September 16, 2021, 9:32 AM	September 16, 2021, 12:00 AM	Valve Maintenance Report	September 16, 2021, 9:34 AM	V-009GV002	Valve Condition	
WO-61683	1	Completed	October 26, 2021, 9:25 AM	October 28, 2021, 12:00 AM	Repair water main		V-009GV024	Valve Condition	
WO-61683	1	Completed	October 26, 2021, 9:25 AM	October 28, 2021, 12:00 AM	Repair water main		V-009GV026	Valve Condition	Fair
WO-39413	43	Completed	March 18, 2021, 10:18 AM	March 18, 2021, 12:00 AM	Test shut, for INDEPENDENT CONTRACTOR	March 18, 2021, 10:38 AM	V-009GV041	Valve Condition	
WO-56321	1	Completed	September 1, 2021, 11:27 AM	March 23, 2021, 12:00 AM	Valve Maintenance Report		V-009HV016	Valve Condition	
WO-56321	1	Completed	September 1, 2021, 11:27 AM	March 23, 2021, 12:00 AM	Valve Maintenance Report		V-009HV018	Valve Condition	
WO-36635	84	Completed	February 16, 2021, 8:02 AM	February 16, 2021, 12:00 AM	eoc called to report water main break that is buckling the street	February 16, 2021, 2:08 PM	V-009HV019	Valve Condition	Good
WO-42015	1	Completed	April 19, 2021, 9:38 AM	May 12, 2021, 12:00 AM	Valve Maintenance Report, liberty ave	May 12, 2021, 2:21 PM	V-009HV020	Valve Condition	
WO-41253	85	Completed	April 10, 2021, 2:27 AM	April 11, 2021, 12:00 AM	Repair water main	April 11, 2021, 3:21 PM	V-009HV022	Valve Condition	
WO-41253	85	Completed	April 10, 2021, 2:27 AM	April 11, 2021, 12:00 AM	Repair water main	April 11, 2021, 3:21 PM	V-009HV024	Valve Condition	
WO-49857	1	Completed	June 23, 2021, 6:22 PM	August 31, 2021, 12:00 AM	Repair water main		V-009KV022	Valve Condition	
WO-49857	1	Completed	June 23, 2021, 6:22 PM	August 31, 2021, 12:00 AM	Repair water main		V-009KV026	Valve Condition	
WO-49857	1	Completed	June 23, 2021, 6:22 PM	August 31, 2021, 12:00 AM	Repair water main		V-009KV029	Valve Condition	
WO-57674	1	Completed	September 16, 2021, 9:32 AM	September 16, 2021, 12:00 AM	Valve Maintenance Report	September 16, 2021, 9:34 AM	V-009LV002	Valve Condition	
WO-63319	85	Completed	November 10, 2021, 9:49 AM	December 27, 2021, 12:00 AM	Repair water main	December 27, 2021, 1:29 PM	V-009LV017	Valve Condition	Fair
WO-41571	85	Completed	April 14, 2021, 8:53 AM	April 18, 2021, 12:00 AM	Repair water main	April 20, 2021, 2:57 PM	V-009MV011	Valve Condition	
WO-41571	85	Completed	April 14, 2021, 8:53 AM	April 18, 2021, 12:00 AM	Repair water main	April 20, 2021, 2:57 PM	V-009MV013	Valve Condition	
WO-36278	1	Completed	February 11, 2021, 6:49 AM	August 30, 2021, 6:49 AM	Repair water main		V-009MV022	Valve Condition	Good
WO-36278	1	Completed	February 11, 2021, 6:49 AM	August 30, 2021, 6:49 AM	Repair water main		V-009MV025	Valve Condition	Good
WO-56773	41	Completed	September 7, 2021, 11:45 AM	September 7, 2021, 12:00 AM	Contractor shut request	September 7, 2021, 2:02 PM	V-009NV061	Valve Condition	
WO-55219	1	Completed	August 19, 2021, 12:33 PM	August 19, 2021, 12:00 AM	Valve Maintenance Report	August 19, 2021, 12:36 PM	V-009NV068	Valve Condition	
WO-55219	1	Completed	August 19, 2021, 12:33 PM	August 19, 2021, 12:00 AM	Valve Maintenance Report	August 19, 2021, 12:36 PM	V-009NV072	Valve Condition	
WO-55219	1	Completed	August 19, 2021, 12:33 PM	August 19, 2021, 12:00 AM	Valve Maintenance Report	August 19, 2021, 12:36 PM	V-009NV083	Valve Condition	
WO-55219	1	Completed	August 19, 2021, 12:33 PM	August 19, 2021, 12:00 AM	Valve Maintenance Report	August 19, 2021, 12:36 PM	V-009NV089	Valve Condition	
WO-49823	41	Completed	June 23, 2021, 12:59 PM	June 23, 2021, 12:00 AM	Contractor shut request	June 23, 2021, 1:02 PM	V-009SV019	Valve Condition	
WO-47972	1	Completed	June 9, 2021, 2:50 PM	July 12, 2021, 12:00 AM	Repair water main 1st Picture from shooting on Granville from Webster to Enoch —- out at the Tee going down Enoch , 2nd pic shooting on Enoch from Granville to Hydrant A709 on Enoch, leak marked over 8" main 113ft Down from Enoch , Standard 3 day one call placed, post no parking, see this is how you give proper information , you can make the notification	July 12, 2021, 2:59 PM	V-009SV030	Valve Condition	
WO-65524	1	Completed	December 9, 2021, 5:41 PM	December 10, 2021, 12:00 AM	Repair water main		V-009SV033	Valve Condition	
WO-50793	1	Completed	July 1, 2021, 11:40 AM	July 6, 2021, 12:00 AM	Valve Maintenance Report	July 6, 2021, 10:31 AM	V-009SV035	Valve Condition	
WO-49752	1	Completed	June 23, 2021, 1:49 AM	July 1, 2021, 12:00 AM	Repair water main		V-009SV036	Valve Condition	Good
WO-50793	1	Completed	July 1, 2021, 11:40 AM	July 6, 2021, 12:00 AM	Valve Maintenance Report	July 6, 2021, 10:31 AM	V-009SV037	Valve Condition	
WO-49752	1	Completed	June 23, 2021, 1:49 AM	July 1, 2021, 12:00 AM	Repair water main		V-009SV042	Valve Condition	Good
WO-47972	1	Completed	June 9, 2021, 2:50 PM	July 12, 2021, 12:00 AM	Repair water main 1st Picture from shooting on Granville from Webster to Enoch —- out at the Tee going down Enoch , 2nd pic shooting on Enoch from Granville to Hydrant A709 on Enoch, leak marked over 8" main 113ft Down from Enoch , Standard 3 day one call placed, post no parking, see this is how you give proper information , you can make the notification	July 12, 2021, 2:59 PM	V-009SV043	Valve Condition	Poor
WO-49817	41	Completed	June 23, 2021, 12:46 PM	June 23, 2021, 12:00 AM	Contractor shut request	June 23, 2021, 12:50 PM	V-009SV045	Valve Condition	
WO-49821	41	Completed	June 23, 2021, 12:52 PM	June 23, 2021, 12:00 AM	Contractor shut request	June 23, 2021, 12:57 PM	V-009SV046	Valve Condition	
WO-65884	88	Completed	December 14, 2021, 1:12 PM	December 21, 2021, 12:00 AM	Repair service line- if drilled, Drill Sheet work order MUST be completed Stop is broke shut lead on private side needs internal repairs. 12/15/21 Dug at C/B PWSA had copper. Plumber installed a new stop. Left hole opened and plywood and crew notified Dispatch to notify Lead Team that customer has Lead.	January 24, 2022, 10:40 AM	V-009SV057	Valve Condition	
WO-65884	88	Completed	December 14, 2021, 1:12 PM	December 21, 2021, 12:00 AM	Repair service line- if drilled, Drill Sheet work order MUST be completed Stop is broke shut lead on private side needs internal repairs. 12/15/21 Dug at C/B PWSA had copper. Plumber installed a new stop. Left hole opened and plywood and crew notified Dispatch to notify Lead Team that customer has Lead.	January 24, 2022, 10:40 AM	V-009SV066	Valve Condition	
WO-65524	1	Completed	December 9, 2021, 5:41 PM	December 10, 2021, 12:00 AM	Repair water main		V-009SV083	Valve Condition	
WO-49832	41	Completed	June 23, 2021, 1:32 PM	June 23, 2021, 12:00 AM	Contractor shut request	June 23, 2021, 1:34 PM	V-009SV084	Valve Condition	
WO-42015	1	Completed	April 19, 2021, 9:38 AM	May 12, 2021, 12:00 AM	Valve Maintenance Report, liberty ave	May 12, 2021, 2:21 PM	V-010AV020	Valve Condition	
WO-42015	1	Completed	April 19, 2021, 9:38 AM	May 12, 2021, 12:00 AM	Valve Maintenance Report, liberty ave	May 12, 2021, 2:21 PM	V-010AV021	Valve Condition	
WO-42015	1	Completed	April 19, 2021, 9:38 AM	May 12, 2021, 12:00 AM	Valve Maintenance Report, liberty ave	May 12, 2021, 2:21 PM	V-010AV023	Valve Condition	
WO-42015	1	Completed	April 19, 2021, 9:38 AM	May 12, 2021, 12:00 AM	Valve Maintenance Report, liberty ave	May 12, 2021, 2:21 PM	V-010AV026	Valve Condition	
WO-42015	1	Completed	April 19, 2021, 9:38 AM	May 12, 2021, 12:00 AM	Valve Maintenance Report, liberty ave	May 12, 2021, 2:21 PM	V-010AV027	Valve Condition	
WO-63284	1	Completed	November 9, 2021, 7:30 PM	November 10, 2021, 12:00 AM	Repair water main - 8" main , not 6" main noted on I.O.S.		V-010BV015	Valve Condition	Good
WO-53610	1	Completed	August 3, 2021, 8:32 AM	August 31, 2021, 12:00 AM	Repair water main 6". Emergency 1 call placed. Stakes are in the ground for 1 call location. Dig where leak created the hole. Valve crew shut down and no one is out of water. SEE PICTURES BELOW		V-010BV019	Valve Condition	Good
WO-53610	1	Completed	August 3, 2021, 8:32 AM	August 31, 2021, 12:00 AM	Repair water main 6". Emergency 1 call placed. Stakes are in the ground for 1 call location. Dig where leak created the hole. Valve crew shut down and no one is out of water. SEE PICTURES BELOW		V-010BV025	Valve Condition	
WO-36471	85	Completed	February 12, 2021, 2:42 PM	February 12, 2021, 12:00 AM	Repair water main	February 12, 2021, 11:04 PM	V-010BV026	Valve Condition	Fair
WO-35537	1	Completed	February 3, 2021, 1:53 PM	February 22, 2021, 12:00 AM	Valve Maintenance Report	February 22, 2021, 10:00 AM	V-010CV012	Valve Condition	
WO-35537	1	Completed	February 3, 2021, 1:53 PM	February 22, 2021, 12:00 AM	Valve Maintenance Report	February 22, 2021, 10:00 AM	V-010CV016	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-43037	1	Completed	April 28, 2021, 10:17 AM	April 28, 2021, 12:00 AM	Valve Maintenance Report	April 28, 2021, 2:49 PM	V-010CV023	Valve Condition	Good
WO-35537	1	Completed	February 3, 2021, 1:53 PM	February 22, 2021, 12:00 AM	Valve Maintenance Report	February 22, 2021, 10:00 AM	V-010CV025	Valve Condition	
WO-43037	1	Completed	April 28, 2021, 10:17 AM	April 28, 2021, 12:00 AM	Valve Maintenance Report	April 28, 2021, 2:49 PM	V-010CV029	Valve Condition	Good
WO-43037	1	Completed	April 28, 2021, 10:17 AM	April 28, 2021, 12:00 AM	Valve Maintenance Report	April 28, 2021, 2:49 PM	V-010DV004	Valve Condition	Good
WO-43037	1	Completed	April 28, 2021, 10:17 AM	April 28, 2021, 12:00 AM	Valve Maintenance Report	April 28, 2021, 2:49 PM	V-010DV007	Valve Condition	Good
WO-47827	1	Completed	June 8, 2021, 9:26 AM	June 15, 2021, 12:00 AM	Valve Maintenance Report	June 15, 2021, 1:37 PM	V-010DV008	Valve Condition	Good
WO-63696	1	Completed	November 17, 2021, 8:13 AM	November 22, 2021, 12:00 AM	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-010DV009	Valve Condition	
WO-33444	1	Completed	January 14, 2021, 1:59 AM	January 22, 2021, 1:59 AM	Repair water main		V-010DV016	Valve Condition	
WO-33444	1	Completed	January 14, 2021, 1:59 AM	January 22, 2021, 1:59 AM	Repair water main		V-010DV017	Valve Condition	
WO-35517	1	Completed	February 3, 2021, 10:45 AM	August 27, 2021, 10:45 AM	Repair water main		V-010DV026	Valve Condition	
WO-35517	1	Completed	February 3, 2021, 10:45 AM	August 27, 2021, 10:45 AM	Repair water main		V-010DV030	Valve Condition	
WO-43037	1	Completed	April 28, 2021, 10:17 AM	April 28, 2021, 12:00 AM	Valve Maintenance Report	April 28, 2021, 2:49 PM	V-010DV054	Valve Condition	Good
WO-34032	1	Completed	January 20, 2021, 11:12 AM	January 20, 2021, 12:00 AM	Valve Maintenance Report	January 20, 2021, 11:18 AM	V-010DV057	Valve Condition	
WO-47827	1	Completed	June 8, 2021, 9:26 AM	June 15, 2021, 12:00 AM	Valve Maintenance Report	June 15, 2021, 1:37 PM	V-010DV058	Valve Condition	Good
WO-63696	1	Completed	November 17, 2021, 8:13 AM	November 22, 2021, 12:00 AM	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-010DV059	Valve Condition	
WO-43037	1	Completed	April 28, 2021, 10:17 AM	April 28, 2021, 12:00 AM	Valve Maintenance Report	April 28, 2021, 2:49 PM	V-010DV062	Valve Condition	Good
WO-35537	1	Completed	February 3, 2021, 1:53 PM	February 22, 2021, 12:00 AM	Valve Maintenance Report	February 22, 2021, 10:00 AM	V-010FV004	Valve Condition	
WO-43037	1	Completed	April 28, 2021, 10:17 AM	April 28, 2021, 12:00 AM	Valve Maintenance Report	April 28, 2021, 2:49 PM	V-010FV014	Valve Condition	Good
WO-52695	643	Completed	July 21, 2021, 10:45 AM	August 17, 2021, 12:00 AM	Repair service line- Shut and cut service	August 17, 2021, 11:17 AM	V-010FV015	Valve Condition	Good
WO-35537	1	Completed	February 3, 2021, 1:53 PM	February 22, 2021, 12:00 AM	Valve Maintenance Report	February 22, 2021, 10:00 AM	V-010FV019	Valve Condition	
WO-54290	643	Completed	August 10, 2021, 12:07 PM	August 10, 2021, 12:00 AM	DIG& REPAIR 6"LEAK	August 11, 2021, 2:29 PM	V-010FV022	Valve Condition	Good
WO-32708	85	Completed	January 7, 2021, 11:28 AM	April 28, 2021, 12:00 AM	Repair water main. 1 call valid 1/12/21. Leak is either on the left or right side of valve. Water surfacing. 6". Post no parking.	April 30, 2021, 7:49 AM	V-010FV023	Valve Condition	Good
WO-52695	643	Completed	July 21, 2021, 10:45 AM	August 17, 2021, 12:00 AM	Repair service line- Shut and cut service	August 17, 2021, 11:17 AM	V-010FV024	Valve Condition	Good
WO-35537	1	Completed	February 3, 2021, 1:53 PM	February 22, 2021, 12:00 AM	Valve Maintenance Report	February 22, 2021, 10:00 AM	V-010FV025	Valve Condition	
WO-52695	643	Completed	July 21, 2021, 10:45 AM	August 17, 2021, 12:00 AM	Repair service line- Shut and cut service	August 17, 2021, 11:17 AM	V-010FV027	Valve Condition	Good
WO-43037	1	Completed	April 28, 2021, 10:17 AM	April 28, 2021, 12:00 AM	Valve Maintenance Report	April 28, 2021, 2:49 PM	V-010FV033	Valve Condition	Good
WO-63522	1	Completed	November 15, 2021, 9:23 AM	November 17, 2021, 12:00 AM	Repair water main		V-010FV035	Valve Condition	
WO-43037	1	Completed	April 28, 2021, 10:17 AM	April 28, 2021, 12:00 AM	Valve Maintenance Report	April 28, 2021, 2:49 PM	V-010FV044	Valve Condition	Good
WO-35537	1	Completed	February 3, 2021, 1:53 PM	February 22, 2021, 12:00 AM	Valve Maintenance Report	February 22, 2021, 10:00 AM	V-010FV046	Valve Condition	
WO-43037	1	Completed	April 28, 2021, 10:17 AM	April 28, 2021, 12:00 AM	Valve Maintenance Report	April 28, 2021, 2:49 PM	V-010GV003	Valve Condition	Good
WO-33444	1	Completed	January 14, 2021, 1:59 AM	January 22, 2021, 1:59 AM	Repair water main		V-010GV027	Valve Condition	
WO-55559	84	Completed	August 24, 2021, 12:47 PM	August 25, 2021, 12:00 AM	dpw called to report a leak	August 25, 2021, 10:00 PM	V-010GV035	Valve Condition	
WO-55559	84	Completed	August 24, 2021, 12:47 PM	August 25, 2021, 12:00 AM	dpw called to report a leak	August 25, 2021, 10:00 PM	V-010GV055	Valve Condition	
WO-53966	1	Completed	August 5, 2021, 2:54 PM	August 31, 2021, 12:00 AM	Repair water main		V-010JV018	Valve Condition	
WO-35537	1	Completed	February 3, 2021, 1:53 PM	February 22, 2021, 12:00 AM	Valve Maintenance Report	February 22, 2021, 10:00 AM	V-010JV030	Valve Condition	
WO-53966	1	Completed	August 5, 2021, 2:54 PM	August 31, 2021, 12:00 AM	Repair water main		V-010JV035	Valve Condition	
WO-53966	1	Completed	August 5, 2021, 2:54 PM	August 31, 2021, 12:00 AM	Repair water main		V-010JV039	Valve Condition	
WO-45802	1	Completed	May 22, 2021, 4:41 AM	May 24, 2021, 12:00 AM	Repair water main		V-010JV046	Valve Condition	Good
WO-45802	1	Completed	May 22, 2021, 4:41 AM	May 24, 2021, 12:00 AM	Repair water main		V-010JV052	Valve Condition	Good
WO-45802	1	Completed	May 22, 2021, 4:41 AM	May 24, 2021, 12:00 AM	Repair water main		V-010JV053	Valve Condition	Good
WO-49837	21	Completed	June 23, 2021, 1:49 PM	July 1, 2021, 12:00 AM	Valve requires replacement. 8" broke shut	July 2, 2021, 9:56 AM	V-010JV089	Valve Condition	
WO-50793	1	Completed	July 1, 2021, 11:40 AM	July 6, 2021, 12:00 AM	Valve Maintenance Report	July 6, 2021, 10:31 AM	V-010JV093	Valve Condition	
WO-50793	1	Completed	July 1, 2021, 11:40 AM	July 6, 2021, 12:00 AM	Valve Maintenance Report	July 6, 2021, 10:31 AM	V-010JV095	Valve Condition	
WO-45802	1	Completed	May 22, 2021, 4:41 AM	May 24, 2021, 12:00 AM	Repair water main		V-010JV098	Valve Condition	Good
WO-35537	1	Completed	February 3, 2021, 1:53 PM	February 22, 2021, 12:00 AM	Valve Maintenance Report	February 22, 2021, 10:00 AM	V-010JV100	Valve Condition	
WO-45802	1	Completed	May 22, 2021, 4:41 AM	May 24, 2021, 12:00 AM	Repair water main		V-010KV004	Valve Condition	Good
WO-49860	84	Completed	June 23, 2021, 8:09 PM	June 26, 2021, 12:00 AM	Main or service line leak investigation/survey/PER CUSTOMER MAJOR LEAK IN MIDDKE OF STREET RUNNING LIKE A RIVER CALLER HAS WATER BUT LOW PRESSURE NO KNOWN DAMAGE NO FURTHER INFO	June 26, 2021, 8:26 AM	V-010KV005	Valve Condition	Good
WO-59454	1	Completed	October 5, 2021, 8:33 AM	October 5, 2021, 12:00 AM	Repair water main		V-010KV006	Valve Condition	
WO-59454	1	Completed	October 5, 2021, 8:33 AM	October 5, 2021, 12:00 AM	Repair water main		V-010KV007	Valve Condition	
WO-63522	1	Completed	November 15, 2021, 9:23 AM	November 17, 2021, 12:00 AM	Repair water main		V-010KV009	Valve Condition	
WO-63522	1	Completed	November 15, 2021, 9:23 AM	November 17, 2021, 12:00 AM	Repair water main		V-010KV012	Valve Condition	
WO-49860	84	Completed	June 23, 2021, 8:09 PM	June 26, 2021, 12:00 AM	Main or service line leak investigation/survey/PER CUSTOMER MAJOR LEAK IN MIDDKE OF STREET RUNNING LIKE A RIVER CALLER HAS WATER BUT LOW PRESSURE NO KNOWN DAMAGE NO FURTHER INFO	June 26, 2021, 8:26 AM	V-010KV041	Valve Condition	Good
WO-54879	84	Completed	August 16, 2021, 4:24 PM	August 17, 2021, 12:00 AM	Main or service line leak investigation/survey/PLUMBER ON SCENE MISTER PLUMBER JT STATES LUKE TOLD THEM TO CALL NEED SHUT AT STREET CURB BOX WAS DUGGED TECH CANNOT SHUT OFF WATER CHURCH FLOODING		V-010KV046	Valve Condition	
WO-60282	84	Completed	October 11, 2021, 11:39 PM	October 26, 2021, 12:00 AM	INVESTIGATE WATER LEAKING IN THE STREET	October 27, 2021, 1:03 PM	V-010KV054	Valve Condition	
WO-43363	1	Completed	April 30, 2021, 6:25 PM	May 1, 2021, 12:00 AM	Repair water main	May 1, 2021, 1:28 AM	V-010LV018	Valve Condition	Good
WO-43363	1	Completed	April 30, 2021, 6:25 PM	May 1, 2021, 12:00 AM	Repair water main	May 1, 2021, 1:28 AM	V-010LV021	Valve Condition	Good
WO-59006	1	Completed	September 29, 2021, 9:40 AM	September 29, 2021, 12:00 AM	Valve Maintenance Report	September 29, 2021, 10:00 AM	V-010LV049	Valve Condition	
WO-59006	1	Completed	September 29, 2021, 9:40 AM	September 29, 2021, 12:00 AM	Valve Maintenance Report	September 29, 2021, 10:00 AM	V-010MV063	Valve Condition	
WO-65884	88	Completed	December 14, 2021, 1:12 PM	December 21, 2021, 12:00 AM	Repair service line- if drilled, Drill Sheet work order MUST be completed Stop is broke shut lead on private side needs internal repairs. 12/15/21 Dug at C/B PWSA had copper. Plumber installed a new stop. Left hole opened and plywood and crew notified Dispatch to notify Lead Team that customer has Lead.	January 24, 2022, 10:40 AM	V-010NV063	Valve Condition	
WO-65884	88	Completed	December 14, 2021, 1:12 PM	December 21, 2021, 12:00 AM	Repair service line- if drilled, Drill Sheet work order MUST be completed Stop is broke shut lead on private side needs internal repairs. 12/15/21 Dug at C/B PWSA had copper. Plumber installed a new stop. Left hole opened and plywood and crew notified Dispatch to notify Lead Team that customer has Lead.	January 24, 2022, 10:40 AM	V-010NV064	Valve Condition	
WO-35434	1	Completed	February 2, 2021, 5:12 PM	February 3, 2021, 5:12 PM	Repair water main		V-010PV012	Valve Condition	Good
WO-60557	1	Completed	October 13, 2021, 2:10 PM	October 13, 2021, 12:00 AM	Valve Maintenance Report	October 13, 2021, 2:14 PM	V-010PV018	Valve Condition	
WO-54879	84	Completed	August 16, 2021, 4:24 PM	August 17, 2021, 12:00 AM	Main or service line leak investigation/survey/PLUMBER ON SCENE MISTER PLUMBER JT STATES LUKE TOLD THEM TO CALL NEED SHUT AT STREET CURB BOX WAS DUGGED TECH CANNOT SHUT OFF WATER CHURCH FLOODING		V-010PV020	Valve Condition	
WO-35434	1	Completed	February 2, 2021, 5:12 PM	February 3, 2021, 5:12 PM	Repair water main		V-010PV026	Valve Condition	Good
WO-49248	85	Completed	June 18, 2021, 5:40 PM	June 18, 2021, 12:00 AM	Repair water main	June 18, 2021, 11:24 PM	V-010PV062	Valve Condition	Good
WO-49248	85	Completed	June 18, 2021, 5:40 PM	June 18, 2021, 12:00 AM	Repair water main	June 18, 2021, 11:24 PM	V-010PV063	Valve Condition	Good
WO-37730	1	Completed	March 1, 2021, 8:23 AM	March 1, 2021, 12:00 AM	Valve Maintenance Report	March 1, 2021, 8:26 AM	V-010SV029	Valve Condition	
WO-34789	85	Completed	January 27, 2021, 8:39 PM	January 27, 2021, 12:00 AM	Repair water main	January 27, 2021, 11:22 PM	V-011AV041	Valve Condition	
WO-34789	85	Completed	January 27, 2021, 8:39 PM	January 27, 2021, 12:00 AM	Repair water main	January 27, 2021, 11:22 PM	V-011AV044	Valve Condition	
WO-34789	85	Completed	January 27, 2021, 8:39 PM	January 27, 2021, 12:00 AM	Repair water main	January 27, 2021, 11:22 PM	V-011AV050	Valve Condition	
WO-34789	85	Completed	January 27, 2021, 8:39 PM	January 27, 2021, 12:00 AM	Repair water main	January 27, 2021, 11:22 PM	V-011AV052	Valve Condition	
WO-34789	85	Completed	January 27, 2021, 8:39 PM	January 27, 2021, 12:00 AM	Repair water main	January 27, 2021, 11:22 PM	V-011AV065	Valve Condition	
WO-49248	85	Completed	June 18, 2021, 5:40 PM	June 18, 2021, 12:00 AM	Repair water main	June 18, 2021, 11:24 PM	V-011CV001	Valve Condition	Good
WO-50366	1	Completed	June 28, 2021, 12:28 PM	October 20, 2021, 12:00 AM	Valve Maintenance Report		V-011EV003	Valve Condition	
WO-34789	85	Completed	January 27, 2021, 8:39 PM	January 27, 2021, 12:00 AM	Repair water main	January 27, 2021, 11:22 PM	V-011EV005	Valve Condition	
WO-53295	41	Completed	July 29, 2021, 9:27 AM	July 28, 2021, 12:00 AM	Contractor shut request	July 29, 2021, 2:20 PM	V-011EV007	Valve Condition	
WO-62690	41	Completed	November 4, 2021, 9:40 AM	November 5, 2021, 12:00 AM	Perform hydrant inspection and flushing	November 5, 2021, 10:04 AM	V-011EV011	Valve Condition	
WO-53607	41	Completed	August 3, 2021, 8:29 AM	August 3, 2021, 12:00 AM	Contractor shut request	August 3, 2021, 2:24 PM	V-011EV012	Valve Condition	Good
WO-53607	41	Completed	August 3, 2021, 8:29 AM	August 3, 2021, 12:00 AM	Contractor shut request	August 3, 2021, 2:24 PM	V-011EV013	Valve Condition	Good
WO-35349	41	Completed	February 2, 2021, 11:14 AM	February 2, 2021, 12:00 AM	Contractor shut request	February 2, 2021, 1:40 PM	V-011EV014	Valve Condition	
WO-57093	1	Completed	September 10, 2021, 6:20 AM	September 15, 2021, 12:00 AM	Repair water main		V-011EV018	Valve Condition	
WO-51954	1	Completed	July 14, 2021, 8:14 AM	July 14, 2021, 12:00 AM	Valve Maintenance Report	July 14, 2021, 8:33 AM	V-011EV023	Valve Condition	
WO-56245	43	Completed	September 1, 2021, 8:45 AM	September 1, 2021, 12:00 AM	Test shut	September 1, 2021, 9:55 AM	V-011EV033	Valve Condition	Good
WO-65983	41	Completed	December 15, 2021, 9:38 AM	December 16, 2021, 12:00 AM	Contractor shut request	December 16, 2021, 7:43 AM	V-011EV039	Valve Condition	
WO-65983	41	Completed	December 15, 2021, 9:38 AM	December 16, 2021, 12:00 AM	Contractor shut request	December 16, 2021, 7:43 AM	V-011EV040	Valve Condition	
WO-34789	85	Completed	January 27, 2021, 8:39 PM	January 27, 2021, 12:00 AM	Repair water main	January 27, 2021, 11:22 PM	V-011EV041	Valve Condition	
WO-61389	43	Completed	October 22, 2021, 11:16 AM	November 4, 2021, 12:00 AM	Test shut		V-011FV013	Valve Condition	
WO-63847	1	Completed	November 18, 2021, 11:25 AM	December 6, 2021, 12:00 AM	Valve Maintenance Report		V-011FV014	Valve Condition	Good
WO-64013	41	Completed	November 20, 2021, 10:37 AM	November 20, 2021, 12:00 AM	Contractor shut request	November 20, 2021, 4:01 PM	V-011FV022	Valve Condition	Good
WO-64013	41	Completed	November 20, 2021, 10:37 AM	November 20, 2021, 12:00 AM	Contractor shut request	November 20, 2021, 4:01 PM	V-011FV023	Valve Condition	Good
WO-62963	41	Completed	November 8, 2021, 8:25 AM	November 8, 2021, 12:00 AM	Contractor shut request	November 8, 2021, 1:27 PM	V-011FV027	Valve Condition	
WO-45799	563	Completed	May 21, 2021, 11:22 PM	October 12, 2021, 12:00 AM	Water main repair given to contractor		V-011FV028	Valve Condition	Good
WO-65777	41	Completed	December 13, 2021, 2:05 PM	December 14, 2021, 12:00 AM		December 14, 2021, 4:10 PM	V-011FV029	Valve Condition	
WO-55648	41	Completed	August 25, 2021, 11:59 AM	August 25, 2021, 12:00 AM	Contractor shut request	August 25, 2021, 12:46 PM	V-011HV006	Valve Condition	
WO-55648	41	Completed	August 25, 2021, 11:59 AM	August 25, 2021, 12:00 AM	Contractor shut request	August 25, 2021, 12:46 PM	V-011HV007	Valve Condition	
WO-55648	41	Completed	August 25, 2021, 11:59 AM	August 25, 2021, 12:00 AM	Contractor shut request	August 25, 2021, 12:46 PM	V-011HV027	Valve Condition	
WO-47896	1	Completed	June 9, 2021, 8:40 AM	June 9, 2021, 12:00 AM	Valve Maintenance Report	June 9, 2021, 8:43 AM	V-011JV001	Valve Condition	Good
WO-53607	41	Completed	August 3, 2021, 8:29 AM	August 3, 2021, 12:00 AM	Contractor shut request	August 3, 2021, 2:24 PM	V-011JV003	Valve Condition	Good
WO-53295	41	Completed	July 29, 2021, 9:27 AM	July 28, 2021, 12:00 AM	Contractor shut request	July 29, 2021, 2:20 PM	V-011JV004	Valve Condition	
WO-62690	41	Completed	November 4, 2021, 9:40 AM	November 5, 2021, 12:00 AM	Perform hydrant inspection and flushing	November 5, 2021, 10:04 AM	V-011JV005	Valve Condition	
WO-51302	41	Completed	July 7, 2021, 11:40 AM	July 7, 2021, 12:00 AM	Contractor shut request	July 7, 2021, 3:29 PM	V-011JV007	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-51302	41	Completed	July 7, 2021, 11:40 AM	July 7, 2021, 12:00 AM	Contractor shut request	July 7, 2021, 3:29 PM	V-011JV008	Valve Condition	
WO-42269	84	Completed	April 20, 2021, 9:33 PM	April 21, 2021, 12:00 AM	Main or service line leak investigation/survey/COMPANY WORKING WATER LEAK POSSIBLY HIT LINE WHILE WORKING...JOSEPHINE FAY COMPANY HEATH COPE 412 715 9074 SEE NOTES BELOW	April 21, 2021, 2:41 AM	V-011JV009	Valve Condition	
WO-47893	1	Completed	June 9, 2021, 8:28 AM	June 9, 2021, 12:00 AM	Valve Maintenance Report	June 9, 2021, 8:30 AM	V-011JV013	Valve Condition	Good
WO-53607	41	Completed	August 3, 2021, 8:29 AM	August 3, 2021, 12:00 AM	Contractor shut request	August 3, 2021, 2:24 PM	V-011JV014	Valve Condition	Good
WO-42269	84	Completed	April 20, 2021, 9:33 PM	April 21, 2021, 12:00 AM	Main or service line leak investigation/survey/COMPANY WORKING WATER LEAK POSSIBLY HIT LINE WHILE WORKING...JOSEPHINE FAY COMPANY HEATH COPE 412 715 9074 SEE NOTES BELOW	April 21, 2021, 2:41 AM	V-011JV017	Valve Condition	
WO-42269	84	Completed	April 20, 2021, 9:33 PM	April 21, 2021, 12:00 AM	Main or service line leak investigation/survey/COMPANY WORKING WATER LEAK POSSIBLY HIT LINE WHILE WORKING...JOSEPHINE FAY COMPANY HEATH COPE 412 715 9074 SEE NOTES BELOW	April 21, 2021, 2:41 AM	V-011JV018	Valve Condition	
WO-53607	41	Completed	August 3, 2021, 8:29 AM	August 3, 2021, 12:00 AM	Contractor shut request	August 3, 2021, 2:24 PM	V-011JV021	Valve Condition	Good
WO-49350	1	Completed	June 21, 2021, 8:45 AM	August 31, 2021, 12:00 AM	Repair water main		V-011JV022	Valve Condition	Good
WO-49350	1	Completed	June 21, 2021, 8:45 AM	August 31, 2021, 12:00 AM	Repair water main		V-011JV023	Valve Condition	Good
WO-59486	1	Completed	October 5, 2021, 9:38 AM	October 5, 2021, 12:00 AM	Valve Maintenance Report	October 5, 2021, 9:40 AM	V-011JV024	Valve Condition	
WO-49350	1	Completed	June 21, 2021, 8:45 AM	August 31, 2021, 12:00 AM	Repair water main		V-011JV025	Valve Condition	
WO-64822	41	Completed	December 2, 2021, 9:30 AM	December 2, 2021, 12:00 AM	Contractor shut request	December 2, 2021, 3:18 PM	V-011JV027	Valve Condition	Good
WO-56271	1	Completed	September 1, 2021, 9:59 AM	June 28, 2021, 12:00 AM	Valve Maintenance Report		V-011JV036	Valve Condition	
WO-56271	1	Completed	September 1, 2021, 9:59 AM	June 28, 2021, 12:00 AM	Valve Maintenance Report		V-011JV037	Valve Condition	
WO-56271	1	Completed	September 1, 2021, 9:59 AM	June 28, 2021, 12:00 AM	Valve Maintenance Report		V-011JV038	Valve Condition	
WO-56271	1	Completed	September 1, 2021, 9:59 AM	June 28, 2021, 12:00 AM	Valve Maintenance Report		V-011JV040	Valve Condition	Good
WO-56245	43	Completed	September 1, 2021, 8:45 AM	September 1, 2021, 12:00 AM	Test shut	September 1, 2021, 9:55 AM	V-011JV044	Valve Condition	Good
WO-48749	464	Completed	June 15, 2021, 4:03 PM	June 15, 2021, 12:00 AM	Contractor damage to sewer main, MIKE FROM FOLINO 412-475-4597, WORKING ON WATER LINES AND HIT OUR MAIN	June 15, 2021, 11:04 PM	V-011JV051	Valve Condition	
WO-56245	43	Completed	September 1, 2021, 8:45 AM	September 1, 2021, 12:00 AM	Test shut	September 1, 2021, 9:55 AM	V-011JV052	Valve Condition	Good
WO-56264	41	Completed	September 1, 2021, 9:51 AM	September 2, 2021, 12:00 AM	Shut for contractor Folino	September 2, 2021, 12:35 PM	V-011JV054	Valve Condition	
WO-56264	41	Completed	September 1, 2021, 9:51 AM	September 2, 2021, 12:00 AM	Shut for contractor Folino	September 2, 2021, 12:35 PM	V-011JV055	Valve Condition	
WO-56245	43	Completed	September 1, 2021, 8:45 AM	September 1, 2021, 12:00 AM	Test shut	September 1, 2021, 9:55 AM	V-011JV056	Valve Condition	Good
WO-56264	41	Completed	September 1, 2021, 9:51 AM	September 2, 2021, 12:00 AM	Shut for contractor Folino	September 2, 2021, 12:35 PM	V-011JV065	Valve Condition	
WO-56245	43	Completed	September 1, 2021, 8:45 AM	September 1, 2021, 12:00 AM	Test shut	September 1, 2021, 9:55 AM	V-011JV067	Valve Condition	Good
WO-56264	41	Completed	September 1, 2021, 9:51 AM	September 2, 2021, 12:00 AM	Shut for contractor Folino	September 2, 2021, 12:35 PM	V-011JV072	Valve Condition	
WO-53173	43	Completed	July 27, 2021, 12:16 PM	July 27, 2021, 12:00 AM	Test shut	July 27, 2021, 12:19 PM	V-011JV080	Valve Condition	
WO-47585	1	Completed	June 4, 2021, 11:39 AM	June 4, 2021, 12:00 AM	Valve Maintenance Report	June 4, 2021, 11:46 AM	V-011KV001	Valve Condition	
WO-47584	1	Completed	June 4, 2021, 11:34 AM	June 4, 2021, 12:00 AM	Valve Maintenance Report	June 4, 2021, 11:36 AM	V-011KV002	Valve Condition	Good
WO-62491	41	Completed	November 3, 2021, 1:01 PM	November 4, 2021, 12:00 AM	Contractor shut request Folino tie in	November 4, 2021, 12:57 PM	V-011KV003	Valve Condition	
WO-32812	1	Completed	January 7, 2021, 8:29 PM	January 13, 2021, 8:29 PM	Repair water main	January 13, 2021, 8:57 PM	V-011KV004	Valve Condition	
WO-63333	43	Completed	November 10, 2021, 10:10 AM	November 10, 2021, 12:00 AM	Test shut	November 10, 2021, 10:51 AM	V-011KV007	Valve Condition	
WO-53173	43	Completed	July 27, 2021, 12:16 PM	July 27, 2021, 12:00 AM	Test shut	July 27, 2021, 12:19 PM	V-011KV009	Valve Condition	
WO-64820	41	Completed	December 2, 2021, 9:12 AM	December 3, 2021, 12:00 AM	Contractor shut request	December 3, 2021, 10:17 AM	V-011KV010	Valve Condition	
WO-55164	41	Completed	August 19, 2021, 8:50 AM	August 20, 2021, 12:00 AM	Contractor shut request	August 20, 2021, 9:20 AM	V-011KV011	Valve Condition	
WO-55164	41	Completed	August 19, 2021, 8:50 AM	August 20, 2021, 12:00 AM	Contractor shut request	August 20, 2021, 9:20 AM	V-011KV015	Valve Condition	Good
WO-55164	41	Completed	August 19, 2021, 8:50 AM	August 20, 2021, 12:00 AM	Contractor shut request	August 20, 2021, 9:20 AM	V-011KV016	Valve Condition	Good
WO-64820	41	Completed	December 2, 2021, 9:12 AM	December 3, 2021, 12:00 AM	Contractor shut request	December 3, 2021, 10:17 AM	V-011KV021	Valve Condition	
WO-44249	88	Completed	May 10, 2021, 10:59 AM	May 11, 2021, 12:00 AM	Repair service line. Sinkhole forming. Gene is setting a plate. No parking is posted. Emergency 1 call placed. 6" main. Service is leaking that feeds the play ground. SEE PICTURES BELOW.	May 12, 2021, 2:41 PM	V-011KV022	Valve Condition	
WO-57404	41	Completed	September 14, 2021, 11:27 AM	September 15, 2021, 8:00 AM	Contractor shut request	September 15, 2021, 3:11 PM	V-011KV025	Valve Condition	
WO-57404	41	Completed	September 14, 2021, 11:27 AM	September 15, 2021, 8:00 AM	Contractor shut request	September 15, 2021, 3:11 PM	V-011KV026	Valve Condition	
WO-47566	1	Completed	June 4, 2021, 10:28 AM	June 4, 2021, 12:00 AM	Valve Maintenance Report	June 4, 2021, 10:52 AM	V-011KV027	Valve Condition	
WO-47573	1	Completed	June 4, 2021, 10:51 AM	June 4, 2021, 12:00 AM	Valve Maintenance Report	June 4, 2021, 10:57 AM	V-011KV032	Valve Condition	
WO-57404	41	Completed	September 14, 2021, 11:27 AM	September 15, 2021, 8:00 AM	Contractor shut request	September 15, 2021, 3:11 PM	V-011KV033	Valve Condition	
WO-57404	41	Completed	September 14, 2021, 11:27 AM	September 15, 2021, 8:00 AM	Contractor shut request	September 15, 2021, 3:11 PM	V-011KV034	Valve Condition	
WO-60431	1	Completed	October 13, 2021, 6:42 AM	October 14, 2021, 12:00 AM	Repair water main		V-011KV035	Valve Condition	
WO-46629	1	Completed	May 28, 2021, 10:47 AM	May 28, 2021, 12:00 AM	Valve Maintenance Report	May 28, 2021, 11:55 AM	V-011KV037	Valve Condition	Good
WO-61389	43	Completed	October 22, 2021, 11:16 AM	November 4, 2021, 12:00 AM	Test shut		V-011KV039	Valve Condition	
WO-60431	1	Completed	October 13, 2021, 6:42 AM	October 14, 2021, 12:00 AM	Repair water main		V-011KV041	Valve Condition	
WO-60431	1	Completed	October 13, 2021, 6:42 AM	October 14, 2021, 12:00 AM	Repair water main		V-011KV042	Valve Condition	
WO-55164	41	Completed	August 19, 2021, 8:50 AM	August 20, 2021, 12:00 AM	Contractor shut request	August 20, 2021, 9:20 AM	V-011KV043	Valve Condition	
WO-44249	88	Completed	May 10, 2021, 10:59 AM	May 11, 2021, 12:00 AM	Repair service line. Sinkhole forming. Gene is setting a plate. No parking is posted. Emergency 1 call placed. 6" main. Service is leaking that feeds the play ground. SEE PICTURES BELOW.	May 12, 2021, 2:41 PM	V-011KV044	Valve Condition	
WO-57163	1	Completed	September 10, 2021, 4:27 PM	September 13, 2021, 12:00 AM	Repair water main		V-011KV046	Valve Condition	
WO-46632	1	Completed	May 28, 2021, 11:07 AM	May 28, 2021, 12:00 AM	Valve Maintenance Report	May 28, 2021, 11:10 AM	V-011KV048	Valve Condition	Good
WO-53902	41	Completed	August 5, 2021, 8:56 AM	August 5, 2021, 12:00 AM	Contractor shut request	August 5, 2021, 12:05 PM	V-011KV050	Valve Condition	Good
WO-57163	1	Completed	September 10, 2021, 4:27 PM	September 13, 2021, 12:00 AM	Repair water main		V-011KV056	Valve Condition	
WO-55164	41	Completed	August 19, 2021, 8:50 AM	August 20, 2021, 12:00 AM	Contractor shut request	August 20, 2021, 9:20 AM	V-011KV062	Valve Condition	Good
WO-39753	1	Completed	March 23, 2021, 1:41 PM	March 24, 2021, 12:00 AM	DUD & REPAIR 6" LEAK		V-011KV063	Valve Condition	Good
WO-44860	41	Completed	May 14, 2021, 1:35 PM	May 20, 2021, 12:00 AM	Contractor shut request	May 20, 2021, 6:09 AM	V-011LV004	Valve Condition	
WO-51161	41	Completed	July 6, 2021, 10:36 AM	July 6, 2021, 12:00 AM	Contractor shut request	July 6, 2021, 1:33 PM	V-011LV009	Valve Condition	
WO-55164	41	Completed	August 19, 2021, 8:50 AM	August 20, 2021, 12:00 AM	Contractor shut request	August 20, 2021, 9:20 AM	V-011LV016	Valve Condition	
WO-65777	41	Completed	December 13, 2021, 2:05 PM	December 14, 2021, 12:00 AM		December 14, 2021, 4:10 PM	V-011LV018	Valve Condition	
WO-49176	1	Completed	June 18, 2021, 7:51 AM	June 18, 2021, 12:00 AM	Valve Maintenance Report	June 18, 2021, 8:33 AM	V-011LV020	Valve Condition	Good
WO-55164	41	Completed	August 19, 2021, 8:50 AM	August 20, 2021, 12:00 AM	Contractor shut request	August 20, 2021, 9:20 AM	V-011LV026	Valve Condition	
WO-44860	41	Completed	May 14, 2021, 1:35 PM	May 20, 2021, 12:00 AM	Contractor shut request	May 20, 2021, 6:09 AM	V-011LV032	Valve Condition	
WO-55164	41	Completed	August 19, 2021, 8:50 AM	August 20, 2021, 12:00 AM	Contractor shut request	August 20, 2021, 9:20 AM	V-011LV039	Valve Condition	
WO-47558	1	Completed	June 4, 2021, 9:58 AM	June 4, 2021, 12:00 AM	Valve Maintenance Report	June 4, 2021, 10:00 AM	V-011LV048	Valve Condition	
WO-64013	41	Completed	November 20, 2021, 10:37 AM	November 20, 2021, 12:00 AM	Contractor shut request	November 20, 2021, 4:01 PM	V-011LV049	Valve Condition	
WO-65222	43	Completed	December 7, 2021, 9:05 AM	December 8, 2021, 12:00 AM	Test shut	December 8, 2021, 11:35 AM	V-011LV050	Valve Condition	Good
WO-64013	41	Completed	November 20, 2021, 10:37 AM	November 20, 2021, 12:00 AM	Contractor shut request	November 20, 2021, 4:01 PM	V-011LV066	Valve Condition	
WO-65287	1	Completed	December 7, 2021, 2:15 PM	December 7, 2021, 12:00 AM	Valve Maintenance Report	December 7, 2021, 2:17 PM	V-011MV025	Valve Condition	
WO-64853	1	Completed	December 2, 2021, 11:40 AM	December 2, 2021, 12:00 AM	Valve Maintenance Report	December 2, 2021, 11:55 AM	V-011NV005	Valve Condition	
WO-44860	41	Completed	May 14, 2021, 1:35 PM	May 20, 2021, 12:00 AM	Contractor shut request	May 20, 2021, 6:09 AM	V-011NV006	Valve Condition	
WO-64959	41	Completed	December 3, 2021, 9:23 AM	December 8, 2021, 12:00 AM	Contractor shut request	December 8, 2021, 11:46 AM	V-011NV007	Valve Condition	
WO-64959	41	Completed	December 3, 2021, 9:23 AM	December 8, 2021, 12:00 AM	Contractor shut request	December 8, 2021, 11:46 AM	V-011NV008	Valve Condition	
WO-63523	1	Completed	November 15, 2021, 9:25 AM	November 16, 2021, 12:00 AM	Valve Maintenance Report	November 16, 2021, 7:58 AM	V-011NV010	Valve Condition	
WO-64853	1	Completed	December 2, 2021, 11:40 AM	December 2, 2021, 12:00 AM	Valve Maintenance Report	December 2, 2021, 11:55 AM	V-011PV002	Valve Condition	
WO-44860	41	Completed	May 14, 2021, 1:35 PM	May 20, 2021, 12:00 AM	Contractor shut request	May 20, 2021, 6:09 AM	V-011PV003	Valve Condition	
WO-64959	41	Completed	December 3, 2021, 9:23 AM	December 8, 2021, 12:00 AM	Contractor shut request	December 8, 2021, 11:46 AM	V-011SV015	Valve Condition	
WO-65353	1	Completed	December 8, 2021, 11:06 AM	December 8, 2021, 12:00 AM	Valve Maintenance Report	December 8, 2021, 11:08 AM	V-012AV002	Valve Condition	
WO-65353	1	Completed	December 8, 2021, 11:06 AM	December 8, 2021, 12:00 AM	Valve Maintenance Report	December 8, 2021, 11:08 AM	V-012AV024	Valve Condition	
WO-65353	1	Completed	December 8, 2021, 11:06 AM	December 8, 2021, 12:00 AM	Valve Maintenance Report	December 8, 2021, 11:08 AM	V-012AV025	Valve Condition	
WO-34493	85	Completed	January 25, 2021, 2:24 PM	January 25, 2021, 12:00 AM	Repair water main	January 26, 2021, 6:55 AM	V-012EV020	Valve Condition	
WO-34493	85	Completed	January 25, 2021, 2:24 PM	January 25, 2021, 12:00 AM	Repair water main	January 26, 2021, 6:55 AM	V-012EV021	Valve Condition	
WO-60558	43	Completed	October 13, 2021, 2:24 PM	October 26, 2021, 12:00 AM	Test shut	October 26, 2021, 11:46 AM	V-012EV053	Valve Condition	Good
WO-35761	1	Completed	February 5, 2021, 3:23 AM	February 5, 2021, 12:00 AM	Valve Maintenance Report	February 5, 2021, 3:37 AM	V-012EV064	Valve Condition	
WO-60558	43	Completed	October 13, 2021, 2:24 PM	October 26, 2021, 12:00 AM	Test shut	October 26, 2021, 11:46 AM	V-012EV074	Valve Condition	Good
WO-60558	43	Completed	October 13, 2021, 2:24 PM	October 26, 2021, 12:00 AM	Test shut	October 26, 2021, 11:46 AM	V-012EV075	Valve Condition	Good
WO-60558	43	Completed	October 13, 2021, 2:24 PM	October 26, 2021, 12:00 AM	Test shut	October 26, 2021, 11:46 AM	V-012EV077	Valve Condition	Good
WO-56595	41	Completed	September 3, 2021, 8:17 AM	September 3, 2021, 12:00 AM	Contractor shut request	September 3, 2021, 12:33 PM	V-012EV090	Valve Condition	
WO-46022	1	Completed	May 24, 2021, 4:35 PM	May 24, 2021, 12:00 AM	Valve Maintenance Report	May 24, 2021, 4:48 PM	V-012FV029	Valve Condition	
WO-46022	1	Completed	May 24, 2021, 4:35 PM	May 24, 2021, 12:00 AM	Valve Maintenance Report	May 24, 2021, 4:48 PM	V-012FV030	Valve Condition	
WO-46022	1	Completed	May 24, 2021, 4:35 PM	May 24, 2021, 12:00 AM	Valve Maintenance Report	May 24, 2021, 4:48 PM	V-012FV031	Valve Condition	
WO-46022	1	Completed	May 24, 2021, 4:35 PM	May 24, 2021, 12:00 AM	Valve Maintenance Report	May 24, 2021, 4:48 PM	V-012FV032	Valve Condition	
WO-42383	84	Completed	April 21, 2021, 5:41 PM	April 21, 2021, 12:00 AM	Main or service line leak investigation/survey/PER EOC-911/CHECK FOR A WATER MAIN BREAK STREET BUCKLING NO FURTHER INFO	April 21, 2021, 10:50 PM	V-012FV049	Valve Condition	
WO-35761	1	Completed	February 5, 2021, 3:23 AM	February 5, 2021, 12:00 AM	Valve Maintenance Report	February 5, 2021, 3:37 AM	V-012FV063	Valve Condition	
WO-59105	41	Completed	September 30, 2021, 9:22 AM	September 30, 2021, 12:00 AM	PGH2O crew shut	September 30, 2021, 2:54 PM	V-012FV065	Valve Condition	
WO-42383	84	Completed	April 21, 2021, 5:41 PM	April 21, 2021, 12:00 AM	Main or service line leak investigation/survey/PER EOC-911/CHECK FOR A WATER MAIN BREAK STREET BUCKLING NO FURTHER INFO	April 21, 2021, 10:50 PM	V-012FV089	Valve Condition	
WO-54981	1	Completed	August 17, 2021, 12:46 PM	August 17, 2021, 12:00 AM	Valve Maintenance Report	August 17, 2021, 1:24 PM	V-012GV007	Valve Condition	
WO-54979	1	Completed	August 17, 2021, 12:33 PM	August 17, 2021, 12:00 AM	Valve Maintenance Report	August 17, 2021, 12:37 PM	V-012GV008	Valve Condition	
WO-54981	1	Completed	August 17, 2021, 12:46 PM	August 17, 2021, 12:00 AM	Valve Maintenance Report	August 17, 2021, 1:24 PM	V-012GV015	Valve Condition	
WO-34714	1	Completed	January 27, 2021, 1:21 PM	January 27, 2021, 12:00 AM	Valve Maintenance Report	January 27, 2021, 1:25 PM	V-012GV016	Valve Condition	
WO-34884	1	Completed	January 28, 2021, 11:43 AM	January 28, 2021, 12:00 AM	Valve Maintenance Report	January 28, 2021, 11:45 AM	V-012GV018	Valve Condition	
WO-34719	1	Completed	January 27, 2021, 1:44 PM	January 27, 2021, 12:00 AM	Valve Maintenance Report	January 27, 2021, 1:57 PM	V-012GV019	Valve Condition	
WO-34752	1	Completed	January 27, 2021, 2:01 PM	January 27, 2021, 12:00 AM	Valve Maintenance Report	January 27, 2021, 2:06 PM	V-012GV020	Valve Condition	
WO-34753	1	Completed	January 27, 2021, 2:07 PM	January 27, 2021, 12:00 AM	Valve Maintenance Report	January 27, 2021, 2:18 PM	V-012GV022	Valve Condition	
WO-34886	1	Completed	January 28, 2021, 11:48 AM	January 28, 2021, 12:00 AM	Valve Maintenance Report	January 28, 2021, 11:51 AM	V-012GV024	Valve Condition	
WO-34887	1	Completed	January 28, 2021, 11:52 AM	January 28, 2021, 12:00 AM	Valve Maintenance Report	January 28, 2021, 12:03 PM	V-012GV025	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-34717	1	Completed	January 27, 2021, 1:27 PM	January 27, 2021, 12:00 AM	Valve Maintenance Report	January 27, 2021, 1:40 PM	V-012GV026	Valve Condition	
WO-54979	1	Completed	August 17, 2021, 12:33 PM	August 17, 2021, 12:00 AM	Valve Maintenance Report	August 17, 2021, 12:37 PM	V-012GV027	Valve Condition	
WO-54981	1	Completed	August 17, 2021, 12:46 PM	August 17, 2021, 12:00 AM	Valve Maintenance Report	August 17, 2021, 1:24 PM	V-012GV028	Valve Condition	
WO-34933	1	Completed	January 28, 2021, 2:26 PM	January 28, 2021, 12:00 AM	Valve Maintenance Report	January 28, 2021, 2:28 PM	V-012HV003	Valve Condition	Fair
WO-34906	1	Completed	January 28, 2021, 1:37 PM	January 28, 2021, 12:00 AM	Valve Maintenance Report	January 28, 2021, 1:38 PM	V-012HV005	Valve Condition	
WO-32350	1	Completed	January 4, 2021, 1:49 PM	January 4, 2021, 12:00 AM	Valve Maintenance Report	January 4, 2021, 1:54 PM	V-012JV014	Valve Condition	
WO-55357	88	Completed	August 20, 2021, 2:25 PM	August 23, 2021, 12:00 AM	Repair service line	August 24, 2021, 9:54 AM	V-012JV029	Valve Condition	Good
WO-48659	1	Completed	June 15, 2021, 11:13 AM	June 15, 2021, 12:00 AM	Valve Maintenance Report	June 15, 2021, 11:15 AM	V-012JV046	Valve Condition	
WO-44607	1	Completed	May 12, 2021, 11:24 PM	May 13, 2021, 12:00 AM	Repair water main	May 13, 2021, 3:02 PM	V-012JV047	Valve Condition	Good
WO-61022	1	Completed	October 19, 2021, 5:51 AM	October 19, 2021, 12:00 AM	Valve Maintenance Report	October 19, 2021, 6:06 AM	V-012JV053	Valve Condition	
WO-44607	1	Completed	May 12, 2021, 11:24 PM	May 13, 2021, 12:00 AM	Repair water main	May 13, 2021, 3:02 PM	V-012JV069	Valve Condition	Good
WO-49009	41	Completed	June 17, 2021, 7:13 AM	June 17, 2021, 8:00 AM	Contractor shut request, S ND T PLUMBING	June 17, 2021, 12:03 PM	V-012JV070	Valve Condition	Good
WO-55357	88	Completed	August 20, 2021, 2:25 PM	August 23, 2021, 12:00 AM	Repair service line	August 24, 2021, 9:54 AM	V-012JV071	Valve Condition	Good
WO-55357	88	Completed	August 20, 2021, 2:25 PM	August 23, 2021, 12:00 AM	Repair service line	August 24, 2021, 9:54 AM	V-012JV083	Valve Condition	Good
WO-49009	41	Completed	June 17, 2021, 7:13 AM	June 17, 2021, 8:00 AM	Contractor shut request, S ND T PLUMBING	June 17, 2021, 12:03 PM	V-012KV019	Valve Condition	Good
WO-48659	1	Completed	June 15, 2021, 11:13 AM	June 15, 2021, 12:00 AM	Valve Maintenance Report	June 15, 2021, 11:15 AM	V-012KV034	Valve Condition	
WO-50455	1	Completed	June 29, 2021, 11:22 AM	June 30, 2021, 12:00 AM	Valve Maintenance Report	June 30, 2021, 9:51 AM	V-012KV045	Valve Condition	
WO-50134	1	Completed	June 25, 2021, 12:35 PM	June 25, 2021, 12:00 AM	Valve Maintenance Report	June 25, 2021, 12:41 PM	V-012KV048	Valve Condition	
WO-50134	1	Completed	June 25, 2021, 12:35 PM	June 25, 2021, 12:00 AM	Valve Maintenance Report	June 25, 2021, 12:41 PM	V-012KV050	Valve Condition	
WO-50455	1	Completed	June 29, 2021, 11:22 AM	June 30, 2021, 12:00 AM	Valve Maintenance Report	June 30, 2021, 9:51 AM	V-012KV070	Valve Condition	
WO-47962	1	Completed	June 9, 2021, 1:50 PM	June 14, 2021, 12:00 AM	Repair water main		V-012LV017	Valve Condition	
WO-47962	1	Completed	June 9, 2021, 1:50 PM	June 14, 2021, 12:00 AM	Repair water main		V-012LV024	Valve Condition	
WO-47962	1	Completed	June 9, 2021, 1:50 PM	June 14, 2021, 12:00 AM	Repair water main		V-012LV025	Valve Condition	
WO-47962	1	Completed	June 9, 2021, 1:50 PM	June 14, 2021, 12:00 AM	Repair water main		V-012LV032	Valve Condition	
WO-60907	1	Completed	October 18, 2021, 9:27 AM	October 14, 2021, 12:00 AM	Valve Maintenance Report		V-012LV071	Valve Condition	
WO-60907	1	Completed	October 18, 2021, 9:27 AM	October 14, 2021, 12:00 AM	Valve Maintenance Report		V-012LV072	Valve Condition	
WO-37003	1	Completed	February 19, 2021, 1:40 PM	February 19, 2021, 12:00 AM	Valve Maintenance Report	February 19, 2021, 1:41 PM	V-012MV019	Valve Condition	Fair
WO-36993	1	Completed	February 19, 2021, 11:30 AM	February 19, 2021, 12:00 AM	Valve Maintenance Report	February 19, 2021, 11:32 AM	V-012MV051	Valve Condition	
WO-37001	1	Completed	February 19, 2021, 1:24 PM	February 19, 2021, 12:00 AM	Valve Maintenance Report	February 19, 2021, 1:25 PM	V-012MV054	Valve Condition	Fair
WO-36992	1	Completed	February 19, 2021, 11:27 AM	February 19, 2021, 12:00 AM	Valve Maintenance Report	February 19, 2021, 11:28 AM	V-012MV057	Valve Condition	
WO-37000	1	Completed	February 19, 2021, 1:10 PM	February 19, 2021, 12:00 AM	Valve Maintenance Report	February 19, 2021, 1:11 PM	V-012MV058	Valve Condition	
WO-39839	88	Completed	March 24, 2021, 1:13 PM	April 5, 2021, 12:00 AM	Repair service line 3 Day one Call placed 3/24/21 service is 1"copper both sides.	June 17, 2021, 12:31 PM	V-012NV056	Valve Condition	
WO-39839	88	Completed	March 24, 2021, 1:13 PM	April 5, 2021, 12:00 AM	Repair service line 3 Day one Call placed 3/24/21 service is 1"copper both sides.	June 17, 2021, 12:31 PM	V-012NV066	Valve Condition	
WO-56969	1	Completed	September 9, 2021, 8:19 AM	September 15, 2021, 12:00 AM	Valve Maintenance Report		V-012PV023	Valve Condition	Good
WO-56969	1	Completed	September 9, 2021, 8:19 AM	September 15, 2021, 12:00 AM	Valve Maintenance Report		V-012PV027	Valve Condition	Good
WO-60534	1	Completed	October 13, 2021, 12:30 PM	October 27, 2021, 12:00 AM	Repair water main. 6 in main water surfacing NO PARKING SIGNS BOTH SIDES OF STREET also need and request flaggers high traffic area and bus route 1 call placed 10/13/21 leak on or near sline 1920 curb box full of rocks tried blowing out no good there fore couldn't sound cb SEE PICTURES BELOW		V-012PV028	Valve Condition	
WO-50455	1	Completed	June 29, 2021, 11:22 AM	June 30, 2021, 12:00 AM	Valve Maintenance Report	June 30, 2021, 9:51 AM	V-012PV040	Valve Condition	
WO-56969	1	Completed	September 9, 2021, 8:19 AM	September 15, 2021, 12:00 AM	Valve Maintenance Report		V-012RV003	Valve Condition	Good
WO-44429	21	Completed	May 11, 2021, 1:30 PM	September 10, 2021, 12:00 AM	Valve requires replacement	September 10, 2021, 7:59 AM	V-012RV004	Valve Condition	
WO-56969	1	Completed	September 9, 2021, 8:19 AM	September 15, 2021, 12:00 AM	Valve Maintenance Report		V-012RV005	Valve Condition	Good
WO-65685	1	Completed	December 13, 2021, 7:53 AM	December 21, 2021, 12:00 AM	Repair water main		V-012RV009	Valve Condition	
WO-56969	1	Completed	September 9, 2021, 8:19 AM	September 15, 2021, 12:00 AM	Valve Maintenance Report		V-012RV011	Valve Condition	
WO-61464	84	Completed	October 24, 2021, 4:22 PM	October 24, 2021, 12:00 AM	INVESTIGATE WATER LEAKING IN THE STREET. THE ADDRESSES AT 2235 MARY ST AND 2225 MARY ST ARE BOTH GETTING FLOODED WITH WATER GOING INTO THEIR HOMES.		V-012RV016	Valve Condition	Good
WO-65685	1	Completed	December 13, 2021, 7:53 AM	December 21, 2021, 12:00 AM	Repair water main		V-012RV017	Valve Condition	
WO-33038	1	Completed	January 11, 2021, 9:12 AM	August 27, 2021, 9:12 AM	Repair water main		V-012RV018	Valve Condition	
WO-51636	1	Completed	July 11, 2021, 12:15 AM	July 12, 2021, 12:00 AM	Repair water main		V-012RV027	Valve Condition	Good
WO-51636	1	Completed	July 11, 2021, 12:15 AM	July 12, 2021, 12:00 AM	Repair water main		V-012RV028	Valve Condition	
WO-51763	1	Completed	July 12, 2021, 11:41 PM	July 13, 2021, 12:00 AM	Repair water main-6"		V-012RV032	Valve Condition	Good
WO-51763	1	Completed	July 12, 2021, 11:41 PM	July 13, 2021, 12:00 AM	Repair water main-6"		V-012RV033	Valve Condition	Good
WO-51763	1	Completed	July 12, 2021, 11:41 PM	July 13, 2021, 12:00 AM	Repair water main-6"		V-012RV034	Valve Condition	Good
WO-54628	1	Completed	August 13, 2021, 5:49 AM	August 16, 2021, 12:00 AM	Repair water main	August 16, 2021, 2:30 PM	V-012RV042	Valve Condition	Good
WO-61949	1	Completed	October 28, 2021, 11:44 AM	October 28, 2021, 12:00 AM	Repair water main		V-012SV029	Valve Condition	
WO-61949	1	Completed	October 28, 2021, 11:44 AM	October 28, 2021, 12:00 AM	Repair water main		V-012SV030	Valve Condition	
WO-61949	1	Completed	October 28, 2021, 11:44 AM	October 28, 2021, 12:00 AM	Repair water main		V-012SV049	Valve Condition	
WO-60957	85	Completed	October 18, 2021, 1:22 PM	October 18, 2021, 12:00 AM	Repair water main 6" repair MLL. McCarthy put in a robo call and had Nick alert the customers to move their vehicles. I call still valid..... C.O. 10/17/21 called by dispatch, arrived on site, water surfacing at bend and city steps before yard Way. Big puddle and running across street to catch basin. Sounded street at 6" main with strong sound on Yard Way side of crack where water is surfacing. Problem is all roads dead end behind leak, all cars have to exit over leak from Saint Paul/ Yard Way / Shamokin.	October 18, 2021, 11:13 PM	V-013AV005	Valve Condition	
WO-31752	84	Completed	December 27, 2020, 9:49 AM	January 4, 2021, 12:00 AM	Main or service line leak investigation/survey		V-013AV008	Valve Condition	
WO-51664	1	Completed	July 12, 2021, 7:46 AM	July 12, 2021, 12:00 AM	Repair water main		V-013AV009	Valve Condition	Good
WO-60957	85	Completed	October 18, 2021, 1:22 PM	October 18, 2021, 12:00 AM	Repair water main 6" repair MLL. McCarthy put in a robo call and had Nick alert the customers to move their vehicles. I call still valid..... C.O. 10/17/21 called by dispatch, arrived on site, water surfacing at bend and city steps before yard Way. Big puddle and running across street to catch basin. Sounded street at 6" main with strong sound on Yard Way side of crack where water is surfacing. Problem is all roads dead end behind leak, all cars have to exit over leak from Saint Paul/ Yard Way / Shamokin.	October 18, 2021, 11:13 PM	V-013AV010	Valve Condition	
WO-60878	85	Completed	October 17, 2021, 3:03 PM	October 18, 2021, 12:00 AM	Repair water main	October 18, 2021, 11:11 PM	V-013AV012	Valve Condition	
WO-51664	1	Completed	July 12, 2021, 7:46 AM	July 12, 2021, 12:00 AM	Repair water main		V-013AV026	Valve Condition	Good
WO-46540	1	Completed	May 27, 2021, 1:26 PM	May 27, 2021, 12:00 AM	Valve Maintenance Report	May 27, 2021, 1:29 PM	V-013CV013	Valve Condition	
WO-61953	41	Completed	October 28, 2021, 12:16 PM	October 28, 2021, 12:00 AM	Contractor shut request	October 28, 2021, 7:16 PM	V-013CV015	Valve Condition	
WO-60052	41	Completed	October 8, 2021, 9:31 AM	October 8, 2021, 12:00 AM	Contractor shut request	October 8, 2021, 3:17 PM	V-013CV016	Valve Condition	
WO-55460	43	Completed	August 23, 2021, 10:58 AM	August 23, 2021, 12:00 AM	Test shut	August 23, 2021, 12:38 PM	V-013CV017	Valve Condition	
WO-55460	43	Completed	August 23, 2021, 10:58 AM	August 23, 2021, 12:00 AM	Test shut	August 23, 2021, 12:38 PM	V-013CV023	Valve Condition	
WO-55460	43	Completed	August 23, 2021, 10:58 AM	August 23, 2021, 12:00 AM	Test shut	August 23, 2021, 12:38 PM	V-013CV024	Valve Condition	
WO-52543	43	Completed	July 20, 2021, 9:20 AM	July 20, 2021, 12:00 AM	Test shut Eleanor @ Cobden	July 20, 2021, 2:21 PM	V-013CV028	Valve Condition	
WO-52543	43	Completed	July 20, 2021, 9:20 AM	July 20, 2021, 12:00 AM	Test shut Eleanor @ Cobden	July 20, 2021, 2:21 PM	V-013CV029	Valve Condition	
WO-52543	43	Completed	July 20, 2021, 9:20 AM	July 20, 2021, 12:00 AM	Test shut Eleanor @ Cobden	July 20, 2021, 2:21 PM	V-013CV031	Valve Condition	
WO-59579	41	Completed	October 5, 2021, 2:19 PM	October 7, 2021, 12:00 AM	Water main repair given to contractor. Shut scheduled for Friday10-8	October 7, 2021, 12:49 PM	V-013CV034	Valve Condition	Good
WO-59579	41	Completed	October 5, 2021, 2:19 PM	October 7, 2021, 12:00 AM	Water main repair given to contractor. Shut scheduled for Friday10-8	October 7, 2021, 12:49 PM	V-013CV037	Valve Condition	Good
WO-52828	43	Completed	July 22, 2021, 2:13 PM	July 22, 2021, 12:00 AM	Test shut	July 22, 2021, 2:17 PM	V-013DV002	Valve Condition	Good
WO-52828	43	Completed	July 22, 2021, 2:13 PM	July 22, 2021, 12:00 AM	Test shut	July 22, 2021, 2:17 PM	V-013DV003	Valve Condition	Good
WO-50919	84	Completed	July 2, 2021, 11:54 AM	August 26, 2021, 12:00 AM	7/3/2021- CUSTOMER CALLED IN FOR AN UPDATE ON THE ISSUE, STATED WATER IS STILL LEAKING. CUSTOMER HAS A SMALL SERVICE LINE LEAK , NOT CAUSING DAMAGE		V-013DV004	Valve Condition	Fair
WO-50919	84	Completed	July 2, 2021, 11:54 AM	August 26, 2021, 12:00 AM	7/3/2021- CUSTOMER CALLED IN FOR AN UPDATE ON THE ISSUE, STATED WATER IS STILL LEAKING. CUSTOMER HAS A SMALL SERVICE LINE LEAK , NOT CAUSING DAMAGE		V-013DV007	Valve Condition	Good
WO-63824	41	Completed	November 18, 2021, 8:23 AM	November 19, 2021, 12:00 AM	Contractor shut request	November 19, 2021, 7:59 AM	V-013DV009	Valve Condition	
WO-59579	41	Completed	October 5, 2021, 2:19 PM	October 7, 2021, 12:00 AM	Water main repair given to contractor. Shut scheduled for Friday10-8	October 7, 2021, 12:49 PM	V-013DV010	Valve Condition	
WO-62836	1	Completed	November 5, 2021, 12:51 PM	November 5, 2021, 12:00 AM	Valve Maintenance Report	November 5, 2021, 12:54 PM	V-013DV011	Valve Condition	
WO-54664	1	Completed	August 13, 2021, 8:42 AM	August 13, 2021, 12:00 AM	Valve Maintenance Report	August 13, 2021, 9:06 AM	V-013DV016	Valve Condition	Good
WO-56092	41	Completed	August 31, 2021, 8:46 AM	August 31, 2021, 12:00 AM	Contractor shut request	August 31, 2021, 3:37 PM	V-013DV032	Valve Condition	
WO-59579	41	Completed	October 5, 2021, 2:19 PM	October 7, 2021, 12:00 AM	Water main repair given to contractor. Shut scheduled for Friday10-8	October 7, 2021, 12:49 PM	V-013DV033	Valve Condition	Good
WO-50919	84	Completed	July 2, 2021, 11:54 AM	August 26, 2021, 12:00 AM	7/3/2021- CUSTOMER CALLED IN FOR AN UPDATE ON THE ISSUE, STATED WATER IS STILL LEAKING. CUSTOMER HAS A SMALL SERVICE LINE LEAK , NOT CAUSING DAMAGE		V-013DV038	Valve Condition	Fair
WO-53899	41	Completed	August 5, 2021, 8:28 AM	August 5, 2021, 12:00 AM	Contractor shut request	August 5, 2021, 2:49 PM	V-013FV001	Valve Condition	Good
WO-53899	41	Completed	August 5, 2021, 8:28 AM	August 5, 2021, 12:00 AM	Contractor shut request	August 5, 2021, 2:49 PM	V-013FV002	Valve Condition	Good
WO-52805	1	Completed	July 22, 2021, 12:36 PM	July 23, 2021, 12:00 AM	Valve Maintenance Report		V-013FV003	Valve Condition	Good

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-46543	1	Completed	May 27, 2021, 1:32 PM	May 27, 2021, 12:00 AM	Valve Maintenance Report	May 27, 2021, 1:51 PM	V-013FV004	Valve Condition	
WO-53899	41	Completed	August 5, 2021, 8:28 AM	August 5, 2021, 12:00 AM	Contractor shut request	August 5, 2021, 2:49 PM	V-013FV005	Valve Condition	Good
WO-44861	1	Completed	May 14, 2021, 1:46 PM	May 14, 2021, 12:00 AM	Valve Maintenance Report	May 14, 2021, 2:18 PM	V-013FV006	Valve Condition	
WO-53899	41	Completed	August 5, 2021, 8:28 AM	August 5, 2021, 12:00 AM	Contractor shut request	August 5, 2021, 2:49 PM	V-013FV007	Valve Condition	Good
WO-44861	1	Completed	May 14, 2021, 1:46 PM	May 14, 2021, 12:00 AM	Valve Maintenance Report	May 14, 2021, 2:18 PM	V-013FV008	Valve Condition	
WO-52543	43	Completed	July 20, 2021, 9:20 AM	July 20, 2021, 12:00 AM	Test shut Eleanor @ Cobden	July 20, 2021, 2:21 PM	V-013GV003	Valve Condition	
WO-52543	43	Completed	July 20, 2021, 9:20 AM	July 20, 2021, 12:00 AM	Test shut Eleanor @ Cobden	July 20, 2021, 2:21 PM	V-013GV004	Valve Condition	
WO-52638	41	Completed	July 21, 2021, 8:04 AM	July 21, 2021, 12:00 AM	Contractor shut request	July 21, 2021, 4:28 PM	V-013GV006	Valve Condition	
WO-52638	41	Completed	July 21, 2021, 8:04 AM	July 21, 2021, 12:00 AM	Contractor shut request	July 21, 2021, 4:28 PM	V-013GV008	Valve Condition	
WO-53374	41	Completed	July 30, 2021, 9:19 AM	July 30, 2021, 12:00 AM	Contractor shut request, MELE SHUT	July 30, 2021, 2:18 PM	V-013GV010	Valve Condition	Good
WO-53601	41	Completed	August 3, 2021, 7:53 AM	August 3, 2021, 12:00 AM	Contractor shut request	August 3, 2021, 2:18 PM	V-013GV015	Valve Condition	
WO-53716	43	Completed	August 4, 2021, 8:43 AM	August 4, 2021, 12:00 AM	Test shut MELE Contracting	August 4, 2021, 9:34 AM	V-013GV016	Valve Condition	
WO-53038	41	Completed	July 26, 2021, 9:17 AM	July 26, 2021, 12:00 AM	Contractor shut request	July 26, 2021, 2:56 PM	V-013GV017	Valve Condition	Good
WO-52924	43	Completed	July 23, 2021, 9:59 AM	July 23, 2021, 12:00 AM	Test shut Eleanor @ Patterson	July 23, 2021, 11:39 AM	V-013GV018	Valve Condition	
WO-52543	43	Completed	July 20, 2021, 9:20 AM	July 20, 2021, 12:00 AM	Test shut Eleanor @ Cobden	July 20, 2021, 2:21 PM	V-013GV019	Valve Condition	Good
WO-53601	41	Completed	August 3, 2021, 7:53 AM	August 3, 2021, 12:00 AM	Contractor shut request	August 3, 2021, 2:18 PM	V-013GV022	Valve Condition	Fair
WO-53601	41	Completed	August 3, 2021, 7:53 AM	August 3, 2021, 12:00 AM	Contractor shut request	August 3, 2021, 2:18 PM	V-013GV023	Valve Condition	Good
WO-53716	43	Completed	August 4, 2021, 8:43 AM	August 4, 2021, 12:00 AM	Test shut MELE Contracting	August 4, 2021, 9:34 AM	V-013GV026	Valve Condition	
WO-44650	1	Completed	May 13, 2021, 9:48 AM	May 13, 2021, 12:00 AM	Valve Maintenance Report	May 13, 2021, 9:51 AM	V-013GV030	Valve Condition	
WO-53601	41	Completed	August 3, 2021, 7:53 AM	August 3, 2021, 12:00 AM	Contractor shut request	August 3, 2021, 2:18 PM	V-013GV032	Valve Condition	Fair
WO-53601	41	Completed	August 3, 2021, 7:53 AM	August 3, 2021, 12:00 AM	Contractor shut request	August 3, 2021, 2:18 PM	V-013GV033	Valve Condition	Fair
WO-51665	85	Completed	July 12, 2021, 7:48 AM	September 3, 2021, 12:00 AM	Repair water main Leak on hydrant branch. Leak is isolated until repairs are made. Hydrant was called out of service.	September 3, 2021, 1:02 PM	V-013GV035	Valve Condition	
WO-52924	43	Completed	July 23, 2021, 9:59 AM	July 23, 2021, 12:00 AM	Test shut Eleanor @ Patterson	July 23, 2021, 11:39 AM	V-013GV036	Valve Condition	Good
WO-54058	43	Completed	August 6, 2021, 2:08 PM	August 6, 2021, 12:00 AM	Test shut	August 6, 2021, 2:27 PM	V-013GV038	Valve Condition	Marginal
WO-54858	43	Completed	August 16, 2021, 12:24 PM	August 16, 2021, 12:00 AM	Test shut	August 16, 2021, 12:33 PM	V-013GV039	Valve Condition	Good
WO-53601	41	Completed	August 3, 2021, 7:53 AM	August 3, 2021, 12:00 AM	Contractor shut request	August 3, 2021, 2:18 PM	V-013GV040	Valve Condition	Good
WO-53601	41	Completed	August 3, 2021, 7:53 AM	August 3, 2021, 12:00 AM	Contractor shut request	August 3, 2021, 2:18 PM	V-013GV041	Valve Condition	Good
WO-54858	43	Completed	August 16, 2021, 12:24 PM	August 16, 2021, 12:00 AM	Test shut	August 16, 2021, 12:33 PM	V-013GV043	Valve Condition	Good
WO-54447	43	Completed	August 11, 2021, 12:57 PM	August 11, 2021, 12:00 AM	Test shut	August 11, 2021, 1:04 PM	V-013HV001	Valve Condition	Good
WO-55529	41	Completed	August 24, 2021, 8:29 AM	August 24, 2021, 12:00 AM	Contractor shut request	August 24, 2021, 12:34 PM	V-013HV003	Valve Condition	
WO-53508	43	Completed	August 2, 2021, 11:07 AM	August 2, 2021, 12:00 AM	Test shut	August 2, 2021, 11:17 AM	V-013HV004	Valve Condition	Fair
WO-55529	41	Completed	August 24, 2021, 8:29 AM	August 24, 2021, 12:00 AM	Contractor shut request	August 24, 2021, 12:34 PM	V-013HV005	Valve Condition	
WO-54656	1	Completed	August 13, 2021, 7:55 AM	September 1, 2021, 12:00 AM	Valve Maintenance Report		V-013HV006	Valve Condition	Good
WO-53601	41	Completed	August 3, 2021, 7:53 AM	August 3, 2021, 12:00 AM	Contractor shut request	August 3, 2021, 2:18 PM	V-013HV007	Valve Condition	Good
WO-53508	43	Completed	August 2, 2021, 11:07 AM	August 2, 2021, 12:00 AM	Test shut	August 2, 2021, 11:17 AM	V-013HV008	Valve Condition	Fair
WO-56036	43	Completed	August 30, 2021, 12:06 PM	August 30, 2021, 12:00 AM	Test shut	August 30, 2021, 12:14 PM	V-013HV009	Valve Condition	
WO-56036	43	Completed	August 30, 2021, 12:06 PM	August 30, 2021, 12:00 AM	Test shut	August 30, 2021, 12:14 PM	V-013HV010	Valve Condition	
WO-50147	1	Completed	June 25, 2021, 1:37 PM	August 31, 2021, 12:00 AM	Repair water main		V-013HV011	Valve Condition	
WO-53601	41	Completed	August 3, 2021, 7:53 AM	August 3, 2021, 12:00 AM	Contractor shut request	August 3, 2021, 2:18 PM	V-013HV014	Valve Condition	
WO-53622	41	Completed	August 3, 2021, 9:17 AM	August 3, 2021, 12:00 AM	Contractor shut request	August 3, 2021, 1:40 PM	V-013HV015	Valve Condition	Fair
WO-53625	1	Completed	August 3, 2021, 9:22 AM	August 3, 2021, 12:00 AM	Valve Maintenance Report	August 3, 2021, 9:28 AM	V-013HV016	Valve Condition	
WO-54656	1	Completed	August 13, 2021, 7:55 AM	September 1, 2021, 12:00 AM	Valve Maintenance Report		V-013HV017	Valve Condition	
WO-53601	41	Completed	August 3, 2021, 7:53 AM	August 3, 2021, 12:00 AM	Contractor shut request	August 3, 2021, 2:18 PM	V-013HV022	Valve Condition	Fair
WO-54284	41	Completed	August 10, 2021, 10:10 AM	August 10, 2021, 12:00 AM	Contractor shut request	August 10, 2021, 3:39 PM	V-013HV023	Valve Condition	Fair
WO-53331	43	Completed	July 29, 2021, 1:16 PM	July 29, 2021, 12:00 AM	Test shut	July 29, 2021, 1:22 PM	V-013HV024	Valve Condition	
WO-53331	43	Completed	July 29, 2021, 1:16 PM	July 29, 2021, 12:00 AM	Test shut	July 29, 2021, 1:22 PM	V-013HV026	Valve Condition	
WO-54447	43	Completed	August 11, 2021, 12:57 PM	August 11, 2021, 12:00 AM	Test shut	August 11, 2021, 1:04 PM	V-013HV031	Valve Condition	Good
WO-54664	1	Completed	August 13, 2021, 8:42 AM	August 13, 2021, 12:00 AM	Valve Maintenance Report	August 13, 2021, 9:06 AM	V-013HV033	Valve Condition	
WO-52805	1	Completed	July 22, 2021, 12:36 PM	July 23, 2021, 12:00 AM	Valve Maintenance Report		V-013KV001	Valve Condition	
WO-46553	1	Completed	May 27, 2021, 1:53 PM	May 27, 2021, 12:00 AM	Valve Maintenance Report	May 27, 2021, 2:05 PM	V-013KV005	Valve Condition	Good
WO-52805	1	Completed	July 22, 2021, 12:36 PM	July 23, 2021, 12:00 AM	Valve Maintenance Report		V-013KV006	Valve Condition	
WO-46559	1	Completed	May 27, 2021, 2:19 PM	June 2, 2021, 12:00 AM	Valve Maintenance Report	May 27, 2021, 2:25 PM	V-013KV009	Valve Condition	
WO-52805	1	Completed	July 22, 2021, 12:36 PM	July 23, 2021, 12:00 AM	Valve Maintenance Report		V-013KV011	Valve Condition	
WO-52805	1	Completed	July 22, 2021, 12:36 PM	July 23, 2021, 12:00 AM	Valve Maintenance Report		V-013KV012	Valve Condition	Good
WO-51878	1	Completed	July 13, 2021, 2:09 PM	July 13, 2021, 12:00 AM	Valve Maintenance Report	July 13, 2021, 2:21 PM	V-013KV013	Valve Condition	Good
WO-52063	88	Completed	July 14, 2021, 2:50 PM	July 16, 2021, 12:00 AM	Repair service line	July 16, 2021, 2:57 PM	V-013KV014	Valve Condition	
WO-52063	88	Completed	July 14, 2021, 2:50 PM	July 16, 2021, 12:00 AM	Repair service line	July 16, 2021, 2:57 PM	V-013KV015	Valve Condition	
WO-52805	1	Completed	July 22, 2021, 12:36 PM	July 23, 2021, 12:00 AM	Valve Maintenance Report		V-013KV016	Valve Condition	
WO-56586	41	Completed	September 3, 2021, 6:58 AM	September 8, 2021, 8:00 AM	Contractor shut request, MELE Arlington ave @ Eleanor	September 8, 2021, 2:39 PM	V-013KV018	Valve Condition	
WO-51878	1	Completed	July 13, 2021, 2:09 PM	July 13, 2021, 12:00 AM	Valve Maintenance Report	July 13, 2021, 2:21 PM	V-013KV019	Valve Condition	Good
WO-46559	1	Completed	May 27, 2021, 2:19 PM	June 2, 2021, 12:00 AM	Valve Maintenance Report	May 27, 2021, 2:25 PM	V-013KV020	Valve Condition	
WO-53716	43	Completed	August 4, 2021, 8:43 AM	August 4, 2021, 12:00 AM	Test shut MELE Contracting	August 4, 2021, 9:34 AM	V-013LV001	Valve Condition	
WO-66633	1	Completed	December 27, 2021, 11:48 AM	December 27, 2021, 12:00 AM	Valve Maintenance Report	December 27, 2021, 11:52 AM	V-013LV003	Valve Condition	
WO-54058	43	Completed	August 6, 2021, 2:08 PM	August 6, 2021, 12:00 AM	Test shut	August 6, 2021, 2:27 PM	V-013LV006	Valve Condition	
WO-36086	1	Completed	February 9, 2021, 7:31 AM	August 30, 2021, 7:31 AM	Repair water main		V-013LV007	Valve Condition	Marginal
WO-49673	1	Completed	June 22, 2021, 1:53 PM	June 22, 2021, 12:00 AM	Valve Maintenance Report	June 22, 2021, 1:57 PM	V-013LV008	Valve Condition	
WO-54058	43	Completed	August 6, 2021, 2:08 PM	August 6, 2021, 12:00 AM	Test shut	August 6, 2021, 2:27 PM	V-013LV010	Valve Condition	
WO-36003	1	Completed	February 8, 2021, 10:14 AM	August 30, 2021, 12:00 AM	Valve Maintenance Report, Eleanor street		V-013LV011	Valve Condition	Fair
WO-36086	1	Completed	February 9, 2021, 7:31 AM	August 30, 2021, 7:31 AM	Repair water main		V-013LV012	Valve Condition	Marginal
WO-47872	1	Completed	June 8, 2021, 1:48 PM	June 8, 2021, 12:00 AM	Valve Maintenance Report	June 8, 2021, 1:49 PM	V-013LV013	Valve Condition	
WO-49673	1	Completed	June 22, 2021, 1:53 PM	June 22, 2021, 12:00 AM	Valve Maintenance Report	June 22, 2021, 1:57 PM	V-013LV014	Valve Condition	
WO-56586	41	Completed	September 3, 2021, 6:58 AM	September 8, 2021, 8:00 AM	Contractor shut request, MELE Arlington ave @ Eleanor	September 8, 2021, 2:39 PM	V-013LV015	Valve Condition	
WO-47820	41	Completed	June 8, 2021, 9:13 AM	June 8, 2021, 12:00 AM	Contractor shut request	June 8, 2021, 2:44 PM	V-013LV016	Valve Condition	
WO-36003	1	Completed	February 8, 2021, 10:14 AM	August 30, 2021, 12:00 AM	Valve Maintenance Report, Eleanor street		V-013LV017	Valve Condition	Good
WO-54936	41	Completed	August 17, 2021, 8:53 AM	August 17, 2021, 12:00 AM	Contractor shut request	August 17, 2021, 2:36 PM	V-013LV018	Valve Condition	Good
WO-54858	43	Completed	August 16, 2021, 12:24 PM	August 16, 2021, 12:00 AM	Test shut	August 16, 2021, 12:33 PM	V-013LV019	Valve Condition	
WO-47820	41	Completed	June 8, 2021, 9:13 AM	June 8, 2021, 12:00 AM	Contractor shut request	June 8, 2021, 2:44 PM	V-013LV023	Valve Condition	
WO-36003	1	Completed	February 8, 2021, 10:14 AM	August 30, 2021, 12:00 AM	Valve Maintenance Report, Eleanor street		V-013LV026	Valve Condition	Fair
WO-36086	1	Completed	February 9, 2021, 7:31 AM	August 30, 2021, 7:31 AM	Repair water main		V-013LV027	Valve Condition	Marginal
WO-53716	43	Completed	August 4, 2021, 8:43 AM	August 4, 2021, 12:00 AM	Test shut MELE Contracting	August 4, 2021, 9:34 AM	V-013LV028	Valve Condition	
WO-54281	41	Completed	August 10, 2021, 9:59 AM	August 10, 2021, 12:00 AM	Contractor shut request	August 10, 2021, 3:37 PM	V-013MV002	Valve Condition	
WO-54936	41	Completed	August 17, 2021, 8:53 AM	August 17, 2021, 12:00 AM	Contractor shut request	August 17, 2021, 2:36 PM	V-013MV003	Valve Condition	Good
WO-54727	43	Completed	August 13, 2021, 2:27 PM	August 13, 2021, 12:00 AM	Test shut	August 13, 2021, 2:31 PM	V-013MV004	Valve Condition	
WO-35817	85	Completed	February 5, 2021, 9:50 AM	February 11, 2021, 12:00 AM	Repair water main. Some one was there and painted and put in a 1 call. Sidewalk main. No parking needs posted. View picture below	February 11, 2021, 3:18 PM	V-013MV005	Valve Condition	Fair
WO-54058	43	Completed	August 6, 2021, 2:08 PM	August 6, 2021, 12:00 AM	Test shut	August 6, 2021, 2:27 PM	V-013MV006	Valve Condition	Good
WO-49673	1	Completed	June 22, 2021, 1:53 PM	June 22, 2021, 12:00 AM	Valve Maintenance Report	June 22, 2021, 1:57 PM	V-013MV011	Valve Condition	
WO-50726	1	Completed	July 1, 2021, 6:29 AM	July 19, 2021, 12:00 AM	Repair water main		V-013MV012	Valve Condition	
WO-35817	85	Completed	February 5, 2021, 9:50 AM	February 11, 2021, 12:00 AM	Repair water main. Some one was there and painted and put in a 1 call. Sidewalk main. No parking needs posted. View picture below	February 11, 2021, 3:18 PM	V-013MV016	Valve Condition	Fair
WO-40014	1	Completed	March 25, 2021, 2:31 PM	March 25, 2021, 12:00 AM	Repair water main	March 25, 2021, 11:26 PM	V-013MV020	Valve Condition	
WO-35817	85	Completed	February 5, 2021, 9:50 AM	February 11, 2021, 12:00 AM	Repair water main. Some one was there and painted and put in a 1 call. Sidewalk main. No parking needs posted. View picture below	February 11, 2021, 3:18 PM	V-013MV021	Valve Condition	Fair
WO-35817	85	Completed	February 5, 2021, 9:50 AM	February 11, 2021, 12:00 AM	Repair water main. Some one was there and painted and put in a 1 call. Sidewalk main. No parking needs posted. View picture below	February 11, 2021, 3:18 PM	V-013MV024	Valve Condition	Fair
WO-54858	43	Completed	August 16, 2021, 12:24 PM	August 16, 2021, 12:00 AM	Test shut	August 16, 2021, 12:33 PM	V-013MV029	Valve Condition	
WO-50726	1	Completed	July 1, 2021, 6:29 AM	July 19, 2021, 12:00 AM	Repair water main		V-013MV030	Valve Condition	
WO-50720	1	Completed	July 1, 2021, 2:20 AM	August 31, 2021, 12:00 AM	Repair water main		V-014AV004	Valve Condition	
WO-42683	88	Completed	April 25, 2021, 3:24 PM	May 5, 2021, 12:00 AM	Repair service line	May 7, 2021, 7:18 AM	V-014AV006	Valve Condition	
WO-63806	1	Completed	November 17, 2021, 3:16 PM	November 18, 2021, 12:00 AM	Repair water main		V-014BV008	Valve Condition	
WO-63806	1	Completed	November 17, 2021, 3:16 PM	November 18, 2021, 12:00 AM	Repair water main		V-014BV013	Valve Condition	
WO-56177	1	Completed	August 31, 2021, 2:45 PM	September 7, 2021, 12:00 AM	Repair water main		V-014CV007	Valve Condition	
WO-56311	1	Completed	September 1, 2021, 11:02 AM	April 15, 2021, 12:00 AM	Valve Maintenance Report		V-014DV005	Valve Condition	
WO-56311	1	Completed	September 1, 2021, 11:02 AM	April 15, 2021, 12:00 AM	Valve Maintenance Report		V-014DV011	Valve Condition	
WO-56311	1	Completed	September 1, 2021, 11:02 AM	April 15, 2021, 12:00 AM	Valve Maintenance Report		V-014DV012	Valve Condition	
WO-56311	1	Completed	September 1, 2021, 11:02 AM	April 15, 2021, 12:00 AM	Valve Maintenance Report		V-014DV014	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-56311	1	Completed	September 1, 2021, 11:02 AM	April 15, 2021, 12:00 AM	Valve Maintenance Report		V-014DV015	Valve Condition	
WO-60878	85	Completed	October 17, 2021, 3:03 PM	October 18, 2021, 12:00 AM	Repair water main	October 18, 2021, 11:11 PM	V-014DV038	Valve Condition	
WO-43337	88	Completed	April 30, 2021, 12:56 PM	April 30, 2021, 12:00 AM	Repair service line customer out of water stop is broken.posted 8am -6pm 4/30/21	July 23, 2021, 3:19 PM	V-014EV014	Valve Condition	Good
WO-43337	88	Completed	April 30, 2021, 12:56 PM	April 30, 2021, 12:00 AM	Repair service line customer out of water stop is broken.posted 8am -6pm 4/30/21	July 23, 2021, 3:19 PM	V-014EV015	Valve Condition	Good
WO-64645	1	Completed	November 30, 2021, 10:59 AM	December 1, 2021, 12:00 AM	Valve Maintenance Report		V-014FV018	Valve Condition	Good
WO-43913	84	Completed	May 6, 2021, 10:28 AM	May 7, 2021, 12:00 AM	Main or service line leak investigation/survey		V-014FV025	Valve Condition	Poor
WO-64645	1	Completed	November 30, 2021, 10:59 AM	December 1, 2021, 12:00 AM	Valve Maintenance Report		V-014FV030	Valve Condition	Good
WO-64645	1	Completed	November 30, 2021, 10:59 AM	December 1, 2021, 12:00 AM	Valve Maintenance Report		V-014FV036	Valve Condition	Good
WO-43913	84	Completed	May 6, 2021, 10:28 AM	May 7, 2021, 12:00 AM	Main or service line leak investigation/survey		V-014FV041	Valve Condition	Poor
WO-43913	84	Completed	May 6, 2021, 10:28 AM	May 7, 2021, 12:00 AM	Main or service line leak investigation/survey		V-014FV050	Valve Condition	Poor
WO-60770	1	Completed	October 15, 2021, 9:54 AM	October 29, 2021, 12:00 AM	Repair water main		V-014GV002	Valve Condition	
WO-60770	1	Completed	October 15, 2021, 9:54 AM	October 29, 2021, 12:00 AM	Repair water main		V-014GV003	Valve Condition	
WO-50620	1	Completed	June 30, 2021, 10:01 AM	June 30, 2021, 12:00 AM	Valve Maintenance Report	June 30, 2021, 10:35 AM	V-015AV001	Valve Condition	
WO-50381	1	Completed	June 28, 2021, 2:08 PM	June 28, 2021, 12:00 AM	Valve Maintenance Report	June 28, 2021, 2:12 PM	V-015AV002	Valve Condition	
WO-48717	1	Completed	June 15, 2021, 2:40 PM	June 15, 2021, 12:00 AM	Valve Maintenance Report	June 15, 2021, 2:45 PM	V-015AV004	Valve Condition	
WO-38778	464	Completed	March 11, 2021, 12:23 PM	March 11, 2021, 12:00 AM	Contractor damage to water 6" main / service line	March 11, 2021, 6:07 PM	V-015AV005	Valve Condition	
WO-53620	1	Completed	August 3, 2021, 9:15 AM	August 4, 2021, 12:00 AM	Repair water main		V-015AV006	Valve Condition	Fair
WO-50370	1	Completed	June 28, 2021, 1:25 PM	June 28, 2021, 12:00 AM	Valve Maintenance Report	June 28, 2021, 1:33 PM	V-015AV007	Valve Condition	
WO-50370	1	Completed	June 28, 2021, 1:25 PM	June 28, 2021, 12:00 AM	Valve Maintenance Report	June 28, 2021, 1:33 PM	V-015AV008	Valve Condition	
WO-48708	1	Completed	June 15, 2021, 2:05 PM	June 15, 2021, 12:00 AM	Valve Maintenance Report	June 15, 2021, 2:10 PM	V-015AV009	Valve Condition	
WO-48708	1	Completed	June 15, 2021, 2:05 PM	June 15, 2021, 12:00 AM	Valve Maintenance Report	June 15, 2021, 2:10 PM	V-015AV010	Valve Condition	
WO-48708	1	Completed	June 15, 2021, 2:05 PM	June 15, 2021, 12:00 AM	Valve Maintenance Report	June 15, 2021, 2:10 PM	V-015AV011	Valve Condition	
WO-48708	1	Completed	June 15, 2021, 2:05 PM	June 15, 2021, 12:00 AM	Valve Maintenance Report	June 15, 2021, 2:10 PM	V-015AV012	Valve Condition	
WO-48717	1	Completed	June 15, 2021, 2:40 PM	June 15, 2021, 12:00 AM	Valve Maintenance Report	June 15, 2021, 2:45 PM	V-015AV013	Valve Condition	
WO-48716	1	Completed	June 15, 2021, 2:19 PM	June 15, 2021, 12:00 AM	Valve Maintenance Report	June 15, 2021, 2:23 PM	V-015AV014	Valve Condition	
WO-48716	1	Completed	June 15, 2021, 2:19 PM	June 15, 2021, 12:00 AM	Valve Maintenance Report	June 15, 2021, 2:23 PM	V-015AV015	Valve Condition	
WO-55102	1	Completed	August 18, 2021, 12:12 PM	August 18, 2021, 12:00 AM	Valve Maintenance Report	August 18, 2021, 12:15 PM	V-015BV002	Valve Condition	Good
WO-55038	1	Completed	August 18, 2021, 9:55 AM	August 18, 2021, 12:00 AM	Valve Maintenance Report	August 18, 2021, 10:05 AM	V-015BV003	Valve Condition	
WO-55038	1	Completed	August 18, 2021, 9:55 AM	August 18, 2021, 12:00 AM	Valve Maintenance Report	August 18, 2021, 10:05 AM	V-015BV004	Valve Condition	
WO-55038	1	Completed	August 18, 2021, 9:55 AM	August 18, 2021, 12:00 AM	Valve Maintenance Report	August 18, 2021, 10:05 AM	V-015BV005	Valve Condition	
WO-55038	1	Completed	August 18, 2021, 9:55 AM	August 18, 2021, 12:00 AM	Valve Maintenance Report	August 18, 2021, 10:05 AM	V-015BV007	Valve Condition	
WO-50644	1	Completed	June 30, 2021, 10:46 AM	June 30, 2021, 12:00 AM	Valve Maintenance Report	June 30, 2021, 10:48 AM	V-015BV008	Valve Condition	
WO-50647	1	Completed	June 30, 2021, 11:01 AM	June 30, 2021, 12:00 AM	Valve Maintenance Report	June 30, 2021, 11:06 AM	V-015BV010	Valve Condition	
WO-50647	1	Completed	June 30, 2021, 11:01 AM	June 30, 2021, 12:00 AM	Valve Maintenance Report	June 30, 2021, 11:06 AM	V-015BV011	Valve Condition	
WO-50647	1	Completed	June 30, 2021, 11:01 AM	June 30, 2021, 12:00 AM	Valve Maintenance Report	June 30, 2021, 11:06 AM	V-015BV012	Valve Condition	
WO-50654	1	Completed	June 30, 2021, 11:32 AM	June 30, 2021, 12:00 AM	Valve Maintenance Report	June 30, 2021, 2:59 PM	V-015BV014	Valve Condition	Good
WO-50654	1	Completed	June 30, 2021, 11:32 AM	June 30, 2021, 12:00 AM	Valve Maintenance Report	June 30, 2021, 2:59 PM	V-015BV015	Valve Condition	Good
WO-50654	1	Completed	June 30, 2021, 11:32 AM	June 30, 2021, 12:00 AM	Valve Maintenance Report	June 30, 2021, 2:59 PM	V-015BV016	Valve Condition	Good
WO-50654	1	Completed	June 30, 2021, 11:32 AM	June 30, 2021, 12:00 AM	Valve Maintenance Report	June 30, 2021, 2:59 PM	V-015BV017	Valve Condition	Good
WO-52364	1	Completed	July 19, 2021, 4:16 AM	July 19, 2021, 12:00 AM	Valve Maintenance Report	July 19, 2021, 4:18 AM	V-015BV022	Valve Condition	
WO-52364	1	Completed	July 19, 2021, 4:16 AM	July 19, 2021, 12:00 AM	Valve Maintenance Report	July 19, 2021, 4:18 AM	V-015BV023	Valve Condition	
WO-50654	1	Completed	June 30, 2021, 11:32 AM	June 30, 2021, 12:00 AM	Valve Maintenance Report	June 30, 2021, 2:59 PM	V-015BV024	Valve Condition	Good
WO-50761	1	Completed	July 1, 2021, 9:15 AM	July 1, 2021, 12:00 AM	Valve Maintenance Report	July 1, 2021, 9:18 AM	V-015BV026	Valve Condition	
WO-54492	1	Completed	August 12, 2021, 8:19 AM	August 16, 2021, 12:00 AM	Repair water main		V-015BV027	Valve Condition	Good
WO-52363	1	Completed	July 19, 2021, 4:12 AM	July 19, 2021, 12:00 AM	Valve Maintenance Report	July 19, 2021, 4:14 AM	V-015BV029	Valve Condition	
WO-50651	1	Completed	June 30, 2021, 11:17 AM	June 30, 2021, 12:00 AM	Valve Maintenance Report	June 30, 2021, 11:26 AM	V-015BV030	Valve Condition	
WO-50644	1	Completed	June 30, 2021, 10:46 AM	June 30, 2021, 12:00 AM	Valve Maintenance Report	June 30, 2021, 10:48 AM	V-015BV031	Valve Condition	
WO-55100	1	Completed	August 18, 2021, 12:08 PM	August 18, 2021, 12:00 AM	Valve Maintenance Report	August 18, 2021, 12:12 PM	V-015CV001	Valve Condition	Good
WO-55100	1	Completed	August 18, 2021, 12:08 PM	August 18, 2021, 12:00 AM	Valve Maintenance Report	August 18, 2021, 12:12 PM	V-015CV002	Valve Condition	Good
WO-55090	1	Completed	August 18, 2021, 10:57 AM	August 18, 2021, 12:00 AM	Valve Maintenance Report	August 18, 2021, 11:02 AM	V-015CV003	Valve Condition	Fair
WO-55123	1	Completed	August 18, 2021, 2:15 PM	August 18, 2021, 12:00 AM	Valve Maintenance Report	August 18, 2021, 2:25 PM	V-015CV005	Valve Condition	
WO-55123	1	Completed	August 18, 2021, 2:15 PM	August 18, 2021, 12:00 AM	Valve Maintenance Report	August 18, 2021, 2:25 PM	V-015CV006	Valve Condition	Good
WO-55030	1	Completed	August 18, 2021, 8:43 AM	August 18, 2021, 12:00 AM	Valve Maintenance Report	August 18, 2021, 8:45 AM	V-015CV007	Valve Condition	
WO-55035	1	Completed	August 18, 2021, 9:01 AM	August 18, 2021, 12:00 AM	Valve Maintenance Report	August 18, 2021, 9:05 AM	V-015CV008	Valve Condition	
WO-55035	1	Completed	August 18, 2021, 9:01 AM	August 18, 2021, 12:00 AM	Valve Maintenance Report	August 18, 2021, 9:05 AM	V-015CV009	Valve Condition	
WO-54968	1	Completed	August 17, 2021, 11:13 AM	August 17, 2021, 12:00 AM	Valve Maintenance Report	August 17, 2021, 11:22 AM	V-015CV010	Valve Condition	
WO-54968	1	Completed	August 17, 2021, 11:13 AM	August 17, 2021, 12:00 AM	Valve Maintenance Report	August 17, 2021, 11:22 AM	V-015CV011	Valve Condition	
WO-54968	1	Completed	August 17, 2021, 11:13 AM	August 17, 2021, 12:00 AM	Valve Maintenance Report	August 17, 2021, 11:22 AM	V-015CV012	Valve Condition	
WO-54958	1	Completed	August 17, 2021, 10:18 AM	August 17, 2021, 12:00 AM	Valve Maintenance Report	August 17, 2021, 10:22 AM	V-015CV013	Valve Condition	
WO-54959	1	Completed	August 17, 2021, 10:23 AM	August 17, 2021, 12:00 AM	Valve Maintenance Report	August 17, 2021, 2:37 PM	V-015CV014	Valve Condition	
WO-54959	1	Completed	August 17, 2021, 10:23 AM	August 17, 2021, 12:00 AM	Valve Maintenance Report	August 17, 2021, 2:37 PM	V-015CV016	Valve Condition	
WO-55117	1	Completed	August 18, 2021, 1:22 PM	August 18, 2021, 12:00 AM	Valve Maintenance Report	August 18, 2021, 1:28 PM	V-015CV017	Valve Condition	
WO-55123	1	Completed	August 18, 2021, 2:15 PM	August 18, 2021, 12:00 AM	Valve Maintenance Report	August 18, 2021, 2:25 PM	V-015CV018	Valve Condition	
WO-55123	1	Completed	August 18, 2021, 2:15 PM	August 18, 2021, 12:00 AM	Valve Maintenance Report	August 18, 2021, 2:25 PM	V-015CV019	Valve Condition	
WO-55120	1	Completed	August 18, 2021, 1:48 PM	August 18, 2021, 12:00 AM	Valve Maintenance Report	August 18, 2021, 1:51 PM	V-015CV020	Valve Condition	
WO-45753	1	Completed	May 21, 2021, 2:07 PM	May 21, 2021, 12:00 AM	Valve Maintenance Report	May 21, 2021, 2:24 PM	V-015CV021	Valve Condition	
WO-45753	1	Completed	May 21, 2021, 2:07 PM	May 21, 2021, 12:00 AM	Valve Maintenance Report	May 21, 2021, 2:24 PM	V-015CV022	Valve Condition	
WO-55117	1	Completed	August 18, 2021, 1:22 PM	August 18, 2021, 12:00 AM	Valve Maintenance Report	August 18, 2021, 1:28 PM	V-015CV023	Valve Condition	
WO-45739	1	Completed	May 21, 2021, 1:24 PM	May 21, 2021, 12:00 AM	Valve Maintenance Report	May 21, 2021, 1:40 PM	V-015DV001	Valve Condition	
WO-45739	1	Completed	May 21, 2021, 1:24 PM	May 21, 2021, 12:00 AM	Valve Maintenance Report	May 21, 2021, 1:40 PM	V-015DV002	Valve Condition	
WO-55355	1	Completed	August 20, 2021, 2:20 PM	August 20, 2021, 12:00 AM	Valve Maintenance Report	August 20, 2021, 2:33 PM	V-015DV003	Valve Condition	
WO-55355	1	Completed	August 20, 2021, 2:20 PM	August 20, 2021, 12:00 AM	Valve Maintenance Report	August 20, 2021, 2:33 PM	V-015DV005	Valve Condition	
WO-55355	1	Completed	August 20, 2021, 2:20 PM	August 20, 2021, 12:00 AM	Valve Maintenance Report	August 20, 2021, 2:33 PM	V-015DV006	Valve Condition	
WO-55473	1	Completed	August 23, 2021, 12:40 PM	August 23, 2021, 12:00 AM	Valve Maintenance Report	August 23, 2021, 12:52 PM	V-015DV007	Valve Condition	
WO-55473	1	Completed	August 23, 2021, 12:40 PM	August 23, 2021, 12:00 AM	Valve Maintenance Report	August 23, 2021, 12:52 PM	V-015DV008	Valve Condition	
WO-56044	1	Completed	August 30, 2021, 1:06 PM	August 30, 2021, 12:00 AM	Valve Maintenance Report	August 30, 2021, 1:11 PM	V-015DV009	Valve Condition	
WO-56044	1	Completed	August 30, 2021, 1:06 PM	August 30, 2021, 12:00 AM	Valve Maintenance Report	August 30, 2021, 1:11 PM	V-015DV010	Valve Condition	
WO-55498	1	Completed	August 23, 2021, 2:15 PM	August 23, 2021, 12:00 AM	Valve Maintenance Report	August 23, 2021, 2:20 PM	V-015DV011	Valve Condition	
WO-50720	1	Completed	July 1, 2021, 2:20 AM	August 31, 2021, 12:00 AM	Repair water main		V-015DV012	Valve Condition	
WO-55498	1	Completed	August 23, 2021, 2:15 PM	August 23, 2021, 12:00 AM	Valve Maintenance Report	August 23, 2021, 2:20 PM	V-015DV013	Valve Condition	
WO-55493	1	Completed	August 23, 2021, 1:42 PM	August 23, 2021, 12:00 AM	Valve Maintenance Report	August 23, 2021, 1:47 PM	V-015DV014	Valve Condition	
WO-56044	1	Completed	August 30, 2021, 1:06 PM	August 30, 2021, 12:00 AM	Valve Maintenance Report	August 30, 2021, 1:11 PM	V-015DV016	Valve Condition	
WO-55493	1	Completed	August 23, 2021, 1:42 PM	August 23, 2021, 12:00 AM	Valve Maintenance Report	August 23, 2021, 1:47 PM	V-015DV017	Valve Condition	
WO-55473	1	Completed	August 23, 2021, 12:40 PM	August 23, 2021, 12:00 AM	Valve Maintenance Report	August 23, 2021, 12:52 PM	V-015DV020	Valve Condition	
WO-55475	1	Completed	August 23, 2021, 12:54 PM	August 23, 2021, 12:00 AM	Valve Maintenance Report	August 23, 2021, 12:57 PM	V-015DV021	Valve Condition	
WO-55470	1	Completed	August 23, 2021, 12:13 PM	August 23, 2021, 12:00 AM	Valve Maintenance Report	August 23, 2021, 12:16 PM	V-015DV022	Valve Condition	
WO-56377	1	Completed	September 1, 2021, 1:27 PM	September 1, 2021, 12:00 AM	Valve Maintenance Report	September 1, 2021, 2:23 PM	V-015EV001	Valve Condition	
WO-56394	1	Completed	September 1, 2021, 1:56 PM	September 1, 2021, 12:00 AM	Valve Maintenance Report	September 1, 2021, 2:20 PM	V-015EV002	Valve Condition	
WO-56394	1	Completed	September 1, 2021, 1:56 PM	September 1, 2021, 12:00 AM	Valve Maintenance Report	September 1, 2021, 2:20 PM	V-015EV003	Valve Condition	
WO-56384	1	Completed	September 1, 2021, 1:36 PM	September 1, 2021, 12:00 AM	Valve Maintenance Report	September 1, 2021, 1:39 PM	V-015EV007	Valve Condition	
WO-56495	1	Completed	September 2, 2021, 9:33 AM	September 2, 2021, 12:00 AM	Valve Maintenance Report	September 2, 2021, 10:19 AM	V-015EV008	Valve Condition	
WO-49796	84	Completed	June 23, 2021, 11:07 AM	June 24, 2021, 12:00 AM	Main or service line leak investigation/survey, CUSTOMER SAYS SHE CAN HEAR WATER RUNNING. NO WATER IS SURFACING, HER HUSBAND WAS IN THE BACKROUND SAYING IT WAS UNDER THE HOUSE ON THE SERVICE LINE. NO REPORT OF LOW WATER PRESSURE		V-015EV009	Valve Condition	
WO-56495	1	Completed	September 2, 2021, 9:33 AM	September 2, 2021, 12:00 AM	Valve Maintenance Report	September 2, 2021, 10:19 AM	V-015EV011	Valve Condition	
WO-56495	1	Completed	September 2, 2021, 9:33 AM	September 2, 2021, 12:00 AM	Valve Maintenance Report	September 2, 2021, 10:19 AM	V-015EV012	Valve Condition	
WO-56388	1	Completed	September 1, 2021, 1:40 PM	September 1, 2021, 12:00 AM	Valve Maintenance Report	September 1, 2021, 1:55 PM	V-015EV013	Valve Condition	Good
WO-45564	1	Completed	May 20, 2021, 11:25 AM	May 20, 2021, 12:00 AM	Valve Maintenance Report	May 20, 2021, 11:56 AM	V-015EV014	Valve Condition	
WO-45564	1	Completed	May 20, 2021, 11:25 AM	May 20, 2021, 12:00 AM	Valve Maintenance Report	May 20, 2021, 11:56 AM	V-015EV015	Valve Condition	
WO-45564	1	Completed	May 20, 2021, 11:25 AM	May 20, 2021, 12:00 AM	Valve Maintenance Report	May 20, 2021, 11:56 AM	V-015EV016	Valve Condition	
WO-56388	1	Completed	September 1, 2021, 1:40 PM	September 1, 2021, 12:00 AM	Valve Maintenance Report	September 1, 2021, 1:55 PM	V-015EV020	Valve Condition	Good
WO-56758	1	Completed	September 7, 2021, 10:32 AM	September 7, 2021, 12:00 AM	Valve Maintenance Report	September 7, 2021, 10:36 AM	V-015FV002	Valve Condition	
WO-56745	1	Completed	September 7, 2021, 8:56 AM	September 7, 2021, 12:00 AM	Valve Maintenance Report	September 7, 2021, 9:06 AM	V-015FV004	Valve Condition	
WO-56745	1	Completed	September 7, 2021, 8:56 AM	September 7, 2021, 12:00 AM	Valve Maintenance Report	September 7, 2021, 9:06 AM	V-015FV005	Valve Condition	
WO-53662	1	Completed	August 3, 2021, 12:33 PM	August 4, 2021, 12:00 AM	Repair water main		V-015FV006	Valve Condition	
WO-50763	1	Completed	July 1, 2021, 9:24 AM	July 1, 2021, 12:00 AM	Valve Maintenance Report	July 1, 2021, 9:26 AM	V-015FV008	Valve Condition	
WO-56745	1	Completed	September 7, 2021, 8:56 AM	September 7, 2021, 12:00 AM	Valve Maintenance Report	September 7, 2021, 9:06 AM	V-015FV010	Valve Condition	
WO-56799	1	Completed	September 7, 2021, 2:09 PM	September 7, 2021, 12:00 AM	Valve Maintenance Report	September 15, 2021, 7:02 AM	V-015HV020	Valve Condition	
WO-56515	1	Completed	September 2, 2021, 10:58 AM	September 2, 2021, 12:00 AM	Valve Maintenance Report	September 2, 2021, 11:00 AM	V-015JV001	Valve Condition	
WO-56924	1	Completed	September 8, 2021, 12:45 PM	September 15, 2021, 12:00 AM	Valve Maintenance Report	September 15, 2021, 1:43 PM	V-015JV002	Valve Condition	
WO-56924	1	Completed	September 8, 2021, 12:45 PM	September 15, 2021, 12:00 AM	Valve Maintenance Report	September 15, 2021, 1:43 PM	V-015JV003	Valve Condition	
WO-56924	1	Completed	September 8, 2021, 12:45 PM	September 15, 2021, 12:00 AM	Valve Maintenance Report	September 15, 2021, 1:43 PM	V-015JV004	Valve Condition	
WO-56924	1	Completed	September 8, 2021, 12:45 PM	September 15, 2021, 12:00 AM	Valve Maintenance Report	September 15, 2021, 1:43 PM	V-015JV005	Valve Condition	
WO-56781	1	Completed	September 7, 2021, 12:33 PM	September 7, 2021, 12:00 AM	Valve Maintenance Report	September 7, 2021, 12:41 PM	V-015JV006	Valve Condition	
WO-53662	1	Completed	August 3, 2021, 12:33 PM	August 4, 2021, 12:00 AM	Repair water main		V-015JV007	Valve Condition	
WO-56781	1	Completed	September 7, 2021, 12:33 PM	September 7, 2021, 12:00 AM	Valve Maintenance Report	September 7, 2021, 12:41 PM	V-015JV008	Valve Condition	
WO-56781	1	Completed	September 7, 2021, 12:33 PM	September 7, 2021, 12:00 AM	Valve Maintenance Report	September 7, 2021, 12:41 PM	V-015JV009	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-56921	1	Completed	September 8, 2021, 12:34 PM	September 8, 2021, 12:00 AM	Valve Maintenance Report	September 8, 2021, 12:37 PM	V-015JV014	Valve Condition	
WO-56515	1	Completed	September 2, 2021, 10:58 AM	September 2, 2021, 12:00 AM	Valve Maintenance Report	September 2, 2021, 11:00 AM	V-015JV015	Valve Condition	
WO-58429	1	Completed	September 23, 2021, 10:36 AM	September 23, 2021, 12:00 AM	Valve Maintenance Report	September 23, 2021, 10:43 AM	V-018BV003	Valve Condition	Good
WO-58385	1	Completed	September 23, 2021, 8:46 AM	September 23, 2021, 12:00 AM	Valve Maintenance Report	September 23, 2021, 8:58 AM	V-018BV005	Valve Condition	
WO-58385	1	Completed	September 23, 2021, 8:46 AM	September 23, 2021, 12:00 AM	Valve Maintenance Report	September 23, 2021, 8:58 AM	V-018BV006	Valve Condition	
WO-58385	1	Completed	September 23, 2021, 8:46 AM	September 23, 2021, 12:00 AM	Valve Maintenance Report	September 23, 2021, 8:58 AM	V-018BV007	Valve Condition	
WO-58396	1	Completed	September 23, 2021, 9:24 AM	September 23, 2021, 12:00 AM	Valve Maintenance Report	September 23, 2021, 9:28 AM	V-018BV009	Valve Condition	
WO-58386	1	Completed	September 23, 2021, 9:12 AM	September 23, 2021, 12:00 AM	Valve Maintenance Report	September 23, 2021, 9:14 AM	V-018BV010	Valve Condition	
WO-60955	1	Completed	October 18, 2021, 1:13 PM	October 18, 2021, 12:00 AM	Valve Maintenance Report	October 18, 2021, 1:40 PM	V-018BV011	Valve Condition	Good
WO-60924	1	Completed	October 18, 2021, 10:14 AM	October 18, 2021, 12:00 AM	Valve Maintenance Report	October 18, 2021, 10:41 AM	V-018BV013	Valve Condition	
WO-60969	1	Completed	October 18, 2021, 1:47 PM	October 19, 2021, 12:00 AM	Valve Maintenance Report	October 19, 2021, 10:43 AM	V-018BV014	Valve Condition	
WO-60969	1	Completed	October 18, 2021, 1:47 PM	October 19, 2021, 12:00 AM	Valve Maintenance Report	October 19, 2021, 10:43 AM	V-018BV015	Valve Condition	
WO-60969	1	Completed	October 18, 2021, 1:47 PM	October 19, 2021, 12:00 AM	Valve Maintenance Report	October 19, 2021, 10:43 AM	V-018BV016	Valve Condition	
WO-58429	1	Completed	September 23, 2021, 10:36 AM	September 23, 2021, 12:00 AM	Valve Maintenance Report	September 23, 2021, 10:43 AM	V-018BV017	Valve Condition	Good
WO-58429	1	Completed	September 23, 2021, 10:36 AM	September 23, 2021, 12:00 AM	Valve Maintenance Report	September 23, 2021, 10:43 AM	V-018BV018	Valve Condition	Good
WO-61334	1	Completed	October 21, 2021, 12:45 PM	October 21, 2021, 12:00 AM	Valve Maintenance Report	October 21, 2021, 12:48 PM	V-018CV001	Valve Condition	
WO-61342	1	Completed	October 21, 2021, 1:07 PM	October 21, 2021, 12:00 AM	Valve Maintenance Report	October 21, 2021, 1:11 PM	V-018CV002	Valve Condition	
WO-61213	1	Completed	October 20, 2021, 12:40 PM	October 20, 2021, 12:00 AM	Valve Maintenance Report	October 20, 2021, 12:54 PM	V-018CV003	Valve Condition	
WO-61212	1	Completed	October 20, 2021, 12:34 PM	October 20, 2021, 12:00 AM	Valve Maintenance Report	October 20, 2021, 12:35 PM	V-018CV004	Valve Condition	Good
WO-61336	1	Completed	October 21, 2021, 1:08 PM	October 21, 2021, 12:00 AM	Valve Maintenance Report	October 21, 2021, 1:54 PM	V-018CV005	Valve Condition	
WO-61336	1	Completed	October 21, 2021, 1:08 PM	October 21, 2021, 12:00 AM	Valve Maintenance Report	October 21, 2021, 1:54 PM	V-018CV006	Valve Condition	
WO-61216	1	Completed	October 20, 2021, 12:56 PM	October 20, 2021, 12:00 AM	Valve Maintenance Report	October 20, 2021, 1:27 PM	V-018CV008	Valve Condition	
WO-61216	1	Completed	October 20, 2021, 12:56 PM	October 20, 2021, 12:00 AM	Valve Maintenance Report	October 20, 2021, 1:27 PM	V-018CV009	Valve Condition	
WO-61213	1	Completed	October 20, 2021, 12:40 PM	October 20, 2021, 12:00 AM	Valve Maintenance Report	October 20, 2021, 12:54 PM	V-018CV010	Valve Condition	
WO-61334	1	Completed	October 21, 2021, 12:45 PM	October 21, 2021, 12:00 AM	Valve Maintenance Report	October 21, 2021, 12:48 PM	V-018CV011	Valve Condition	
WO-60266	1	Completed	October 11, 2021, 1:31 PM	October 11, 2021, 12:00 AM	Valve Maintenance Report	November 3, 2021, 12:55 PM	V-018DV001	Valve Condition	
WO-60948	1	Completed	October 18, 2021, 11:50 AM	October 19, 2021, 12:00 AM	Repair water main		V-018DV002	Valve Condition	
WO-60266	1	Completed	October 11, 2021, 1:31 PM	October 11, 2021, 12:00 AM	Valve Maintenance Report	November 3, 2021, 12:55 PM	V-018DV003	Valve Condition	
WO-60266	1	Completed	October 11, 2021, 1:31 PM	October 11, 2021, 12:00 AM	Valve Maintenance Report	November 3, 2021, 12:55 PM	V-018DV004	Valve Condition	
WO-60266	1	Completed	October 11, 2021, 1:31 PM	October 11, 2021, 12:00 AM	Valve Maintenance Report	November 3, 2021, 12:55 PM	V-018DV005	Valve Condition	
WO-60264	1	Completed	October 11, 2021, 1:21 PM	October 11, 2021, 12:00 AM	Valve Maintenance Report	October 15, 2021, 11:32 AM	V-018DV006	Valve Condition	
WO-60258	1	Completed	October 11, 2021, 12:48 PM	October 11, 2021, 12:00 AM	Valve Maintenance Report	October 11, 2021, 1:06 PM	V-018DV007	Valve Condition	
WO-60258	1	Completed	October 11, 2021, 12:48 PM	October 11, 2021, 12:00 AM	Valve Maintenance Report	October 11, 2021, 1:06 PM	V-018DV008	Valve Condition	
WO-60198	1	Completed	October 11, 2021, 10:16 AM	October 11, 2021, 12:00 AM	Valve Maintenance Report	October 11, 2021, 10:40 AM	V-018DV009	Valve Condition	
WO-60198	1	Completed	October 11, 2021, 10:16 AM	October 11, 2021, 12:00 AM	Valve Maintenance Report	October 11, 2021, 10:40 AM	V-018DV010	Valve Condition	
WO-60239	1	Completed	October 11, 2021, 11:47 AM	October 11, 2021, 12:00 AM	Valve Maintenance Report	October 11, 2021, 11:50 AM	V-018DV011	Valve Condition	
WO-60242	1	Completed	October 11, 2021, 11:52 AM	October 11, 2021, 12:00 AM	Valve Maintenance Report	October 11, 2021, 11:55 AM	V-018DV012	Valve Condition	
WO-60198	1	Completed	October 11, 2021, 10:16 AM	October 11, 2021, 12:00 AM	Valve Maintenance Report	October 11, 2021, 10:40 AM	V-018DV013	Valve Condition	
WO-60211	1	Completed	October 11, 2021, 10:50 AM	October 11, 2021, 12:00 AM	Valve Maintenance Report	October 11, 2021, 11:24 AM	V-018DV014	Valve Condition	
WO-60211	1	Completed	October 11, 2021, 10:50 AM	October 11, 2021, 12:00 AM	Valve Maintenance Report	October 11, 2021, 11:24 AM	V-018DV015	Valve Condition	
WO-60913	1	Completed	October 18, 2021, 9:38 AM	October 18, 2021, 12:00 AM	Valve Maintenance Report	October 18, 2021, 10:10 AM	V-018GV003	Valve Condition	
WO-60913	1	Completed	October 18, 2021, 9:38 AM	October 18, 2021, 12:00 AM	Valve Maintenance Report	October 18, 2021, 10:10 AM	V-018GV004	Valve Condition	
WO-60789	1	Completed	October 15, 2021, 12:01 PM	October 15, 2021, 12:00 AM	Valve Maintenance Report	October 15, 2021, 12:50 PM	V-018GV005	Valve Condition	
WO-60905	1	Completed	October 18, 2021, 9:17 AM	October 18, 2021, 12:00 AM	Valve Maintenance Report	October 18, 2021, 9:36 AM	V-018GV006	Valve Condition	
WO-60905	1	Completed	October 18, 2021, 9:17 AM	October 18, 2021, 12:00 AM	Valve Maintenance Report	October 18, 2021, 9:36 AM	V-018GV007	Valve Condition	
WO-60905	1	Completed	October 18, 2021, 9:17 AM	October 18, 2021, 12:00 AM	Valve Maintenance Report	October 18, 2021, 9:36 AM	V-018GV008	Valve Condition	
WO-60789	1	Completed	October 15, 2021, 12:01 PM	October 15, 2021, 12:00 AM	Valve Maintenance Report	October 15, 2021, 12:50 PM	V-018GV012	Valve Condition	
WO-60789	1	Completed	October 15, 2021, 12:01 PM	October 15, 2021, 12:00 AM	Valve Maintenance Report	October 15, 2021, 12:50 PM	V-018GV013	Valve Condition	
WO-60789	1	Completed	October 15, 2021, 12:01 PM	October 15, 2021, 12:00 AM	Valve Maintenance Report	October 15, 2021, 12:50 PM	V-018GV014	Valve Condition	
WO-60789	1	Completed	October 15, 2021, 12:01 PM	October 15, 2021, 12:00 AM	Valve Maintenance Report	October 15, 2021, 12:50 PM	V-018GV015	Valve Condition	
WO-60789	1	Completed	October 15, 2021, 12:01 PM	October 15, 2021, 12:00 AM	Valve Maintenance Report	October 15, 2021, 12:50 PM	V-018GV016	Valve Condition	
WO-57945	1	Completed	September 20, 2021, 10:07 AM	September 20, 2021, 12:00 AM	Valve Maintenance Report	September 20, 2021, 12:11 PM	V-018GV019	Valve Condition	
WO-57943	1	Completed	September 20, 2021, 10:04 AM	September 20, 2021, 12:00 AM	Valve Maintenance Report	September 20, 2021, 12:10 PM	V-018GV020	Valve Condition	
WO-60789	1	Completed	October 15, 2021, 12:01 PM	October 15, 2021, 12:00 AM	Valve Maintenance Report	October 15, 2021, 12:50 PM	V-018GV021	Valve Condition	
WO-60892	1	Completed	October 18, 2021, 8:30 AM	October 18, 2021, 12:00 AM	Valve Maintenance Report	October 18, 2021, 9:01 AM	V-018GV022	Valve Condition	
WO-60892	1	Completed	October 18, 2021, 8:30 AM	October 18, 2021, 12:00 AM	Valve Maintenance Report	October 18, 2021, 9:01 AM	V-018GV023	Valve Condition	
WO-60892	1	Completed	October 18, 2021, 8:30 AM	October 18, 2021, 12:00 AM	Valve Maintenance Report	October 18, 2021, 9:01 AM	V-018GV024	Valve Condition	
WO-60892	1	Completed	October 18, 2021, 8:30 AM	October 18, 2021, 12:00 AM	Valve Maintenance Report	October 18, 2021, 9:01 AM	V-018GV025	Valve Condition	
WO-60789	1	Completed	October 15, 2021, 12:01 PM	October 15, 2021, 12:00 AM	Valve Maintenance Report	October 15, 2021, 12:50 PM	V-018GV026	Valve Condition	
WO-61219	1	Completed	October 20, 2021, 1:07 PM	October 20, 2021, 12:00 AM	Valve Maintenance Report	October 20, 2021, 1:42 PM	V-018GV027	Valve Condition	Good
WO-60175	1	Completed	October 11, 2021, 9:23 AM	October 11, 2021, 12:00 AM	Valve Maintenance Report	October 11, 2021, 9:40 AM	V-018HV001	Valve Condition	
WO-60175	1	Completed	October 11, 2021, 9:23 AM	October 11, 2021, 12:00 AM	Valve Maintenance Report	October 11, 2021, 9:40 AM	V-018HV002	Valve Condition	
WO-59764	1	Completed	October 6, 2021, 1:48 PM	October 6, 2021, 12:00 AM	Valve Maintenance Report	October 6, 2021, 2:44 PM	V-018HV003	Valve Condition	
WO-59764	1	Completed	October 6, 2021, 1:48 PM	October 6, 2021, 12:00 AM	Valve Maintenance Report	October 6, 2021, 2:44 PM	V-018HV004	Valve Condition	
WO-59764	1	Completed	October 6, 2021, 1:48 PM	October 6, 2021, 12:00 AM	Valve Maintenance Report	October 6, 2021, 2:44 PM	V-018HV005	Valve Condition	
WO-58142	1	Completed	September 21, 2021, 11:59 AM	September 21, 2021, 12:00 AM	Valve Maintenance Report	September 21, 2021, 12:08 PM	V-018HV006	Valve Condition	
WO-59764	1	Completed	October 6, 2021, 1:48 PM	October 6, 2021, 12:00 AM	Valve Maintenance Report	October 6, 2021, 2:44 PM	V-018HV007	Valve Condition	
WO-57973	1	Completed	September 20, 2021, 12:03 PM	September 20, 2021, 12:00 AM	Valve Maintenance Report	September 20, 2021, 12:12 PM	V-018HV008	Valve Condition	
WO-60181	1	Completed	October 11, 2021, 9:38 AM	October 11, 2021, 12:00 AM	Valve Maintenance Report	October 11, 2021, 9:52 AM	V-018HV009	Valve Condition	
WO-57973	1	Completed	September 20, 2021, 12:03 PM	September 20, 2021, 12:00 AM	Valve Maintenance Report	September 20, 2021, 12:12 PM	V-018HV010	Valve Condition	
WO-60175	1	Completed	October 11, 2021, 9:23 AM	October 11, 2021, 12:00 AM	Valve Maintenance Report	October 11, 2021, 9:40 AM	V-018HV011	Valve Condition	
WO-57973	1	Completed	September 20, 2021, 12:03 PM	September 20, 2021, 12:00 AM	Valve Maintenance Report	September 20, 2021, 12:12 PM	V-018HV012	Valve Condition	
WO-57221	1	Completed	September 13, 2021, 6:11 AM	September 13, 2021, 12:00 AM	Valve Maintenance Report	September 13, 2021, 6:20 AM	V-018LV001	Valve Condition	
WO-57221	1	Completed	September 13, 2021, 6:11 AM	September 13, 2021, 12:00 AM	Valve Maintenance Report	September 13, 2021, 6:20 AM	V-018LV002	Valve Condition	
WO-57221	1	Completed	September 13, 2021, 6:11 AM	September 13, 2021, 12:00 AM	Valve Maintenance Report	September 13, 2021, 6:20 AM	V-018LV003	Valve Condition	
WO-57221	1	Completed	September 13, 2021, 6:11 AM	September 13, 2021, 12:00 AM	Valve Maintenance Report	September 13, 2021, 6:20 AM	V-018LV004	Valve Condition	
WO-57934	1	Completed	September 20, 2021, 9:31 AM	September 20, 2021, 12:00 AM	Valve Maintenance Report	September 20, 2021, 12:10 PM	V-018LV005	Valve Condition	
WO-57934	1	Completed	September 20, 2021, 9:31 AM	September 20, 2021, 12:00 AM	Valve Maintenance Report	September 20, 2021, 12:10 PM	V-018LV006	Valve Condition	
WO-57934	1	Completed	September 20, 2021, 9:31 AM	September 20, 2021, 12:00 AM	Valve Maintenance Report	September 20, 2021, 12:10 PM	V-018LV007	Valve Condition	
WO-57934	1	Completed	September 20, 2021, 9:31 AM	September 20, 2021, 12:00 AM	Valve Maintenance Report	September 20, 2021, 12:10 PM	V-018LV008	Valve Condition	
WO-46389	1	Completed	May 26, 2021, 1:49 PM	June 2, 2021, 12:00 AM	Valve Maintenance Report	May 26, 2021, 1:51 PM	V-019BV028	Valve Condition	Good
WO-46374	1	Completed	May 26, 2021, 1:20 PM	June 2, 2021, 12:00 AM	Valve Maintenance Report	May 26, 2021, 1:31 PM	V-019BV037	Valve Condition	Fair
WO-46372	1	Completed	May 26, 2021, 1:17 PM	June 2, 2021, 12:00 AM	Valve Maintenance Report	May 26, 2021, 1:19 PM	V-019BV038	Valve Condition	Fair
WO-56729	1	Completed	September 7, 2021, 6:36 AM	September 8, 2021, 12:00 AM	Repair water main	September 13, 2021, 8:03 AM	V-019BV046	Valve Condition	
WO-56729	1	Completed	September 7, 2021, 6:36 AM	September 8, 2021, 12:00 AM	Repair water main	September 13, 2021, 8:03 AM	V-019BV047	Valve Condition	
WO-48008	85	Completed	June 9, 2021, 9:39 PM	June 10, 2021, 12:00 AM	Repair water main - 8"	June 10, 2021, 3:53 AM	V-019BV050	Valve Condition	
WO-46383	1	Completed	May 26, 2021, 1:32 PM	June 2, 2021, 12:00 AM	Valve Maintenance Report	May 26, 2021, 1:47 PM	V-019BV051	Valve Condition	Good
WO-46374	1	Completed	May 26, 2021, 1:20 PM	June 2, 2021, 12:00 AM	Valve Maintenance Report	May 26, 2021, 1:31 PM	V-019BV052	Valve Condition	Fair
WO-56729	1	Completed	September 7, 2021, 6:36 AM	September 8, 2021, 12:00 AM	Repair water main	September 13, 2021, 8:03 AM	V-019BV055	Valve Condition	
WO-58523	85	Completed	September 24, 2021, 9:08 AM	September 21, 2021, 12:00 AM	Repair water main		V-019DV027	Valve Condition	Good
WO-58523	85	Completed	September 24, 2021, 9:08 AM	September 21, 2021, 12:00 AM	Repair water main		V-019DV036	Valve Condition	Good
WO-58523	85	Completed	September 24, 2021, 9:08 AM	September 21, 2021, 12:00 AM	Repair water main		V-019DV068	Valve Condition	Good
WO-46392	1	Completed	May 26, 2021, 1:53 PM	June 2, 2021, 12:00 AM	Valve Maintenance Report	May 26, 2021, 2:34 PM	V-019FV002	Valve Condition	Marginal
WO-46392	1	Completed	May 26, 2021, 1:53 PM	June 2, 2021, 12:00 AM	Valve Maintenance Report	May 26, 2021, 2:34 PM	V-019FV003	Valve Condition	Marginal
WO-46392	1	Completed	May 26, 2021, 1:53 PM	June 2, 2021, 12:00 AM	Valve Maintenance Report	May 26, 2021, 2:34 PM	V-019FV004	Valve Condition	Marginal
WO-52332	1	Completed	July 17, 2021, 10:39 PM	July 19, 2021, 12:00 AM	Repair water main		V-019GV002	Valve Condition	
WO-52332	1	Completed	July 17, 2021, 10:39 PM	July 19, 2021, 12:00 AM	Repair water main		V-019GV003	Valve Condition	
WO-52332	1	Completed	July 17, 2021, 10:39 PM	July 19, 2021, 12:00 AM	Repair water main		V-019GV004	Valve Condition	
WO-43395	84	Completed	May 1, 2021, 11:34 AM	May 1, 2021, 12:00 AM	Main or service line leak investigation/survey- CALLER REPORTED WATER GUSHING FROM CURB OF PROPERTY. WATER IS RUNNING AND STARTING TO FLOODING THE INTERSECTION.	May 1, 2021, 3:27 PM	V-019GV012	Valve Condition	Poor
WO-52332	1	Completed	July 17, 2021, 10:39 PM	July 19, 2021, 12:00 AM	Repair water main		V-019GV031	Valve Condition	
WO-49424	85	Completed	June 21, 2021, 11:01 AM	September 7, 2021, 12:00 AM	Repair water main 6" MLL or on the service at the ferrell. See pictures below. 3 day 1 call placed 8/12/21 Water is not surfacing but its getting into a storm drain and dumping into the creek behind guard rail. Maps are showing a 2 valve shut.	September 7, 2021, 2:58 PM	V-019HV006	Valve Condition	
WO-43395	84	Completed	May 1, 2021, 11:34 AM	May 1, 2021, 12:00 AM	Main or service line leak investigation/survey- CALLER REPORTED WATER GUSHING FROM CURB OF PROPERTY. WATER IS RUNNING AND STARTING TO FLOODING THE INTERSECTION.	May 1, 2021, 3:27 PM	V-019HV015	Valve Condition	Poor
WO-32179	41	Completed	December 31, 2020, 11:55 AM	January 6, 2021, 12:00 AM	Contractor shut request, PWSA crew	January 6, 2021, 9:58 AM	V-019JV001	Valve Condition	
WO-32179	41	Completed	December 31, 2020, 11:55 AM	January 6, 2021, 12:00 AM	Contractor shut request, PWSA crew	January 6, 2021, 9:58 AM	V-019JV007	Valve Condition	
WO-32179	41	Completed	December 31, 2020, 11:55 AM	January 6, 2021, 12:00 AM	Contractor shut request, PWSA crew	January 6, 2021, 9:58 AM	V-019LV017	Valve Condition	
WO-47240	1	Completed	June 2, 2021, 10:15 PM	August 31, 2021, 12:00 AM	Repair water main -8"		V-019LV018	Valve Condition	Good
WO-47240	1	Completed	June 2, 2021, 10:15 PM	August 31, 2021, 12:00 AM	Repair water main -8"		V-019LV019	Valve Condition	Good
WO-47240	1	Completed	June 2, 2021, 10:15 PM	August 31, 2021, 12:00 AM	Repair water main -8"		V-019LV027	Valve Condition	Good
WO-39269	1	Completed	March 17, 2021, 10:11 AM	August 30, 2021, 12:00 AM	Repair water main 8". See pictures below. 1 call was placed		V-019MV019	Valve Condition	
WO-39269	1	Completed	March 17, 2021, 10:11 AM	August 30, 2021, 12:00 AM	Repair water main 8". See pictures below. 1 call was placed		V-019MV020	Valve Condition	
WO-39269	1	Completed	March 17, 2021, 10:11 AM	August 30, 2021, 12:00 AM	Repair water main 8". See pictures below. 1 call was placed		V-019MV024	Valve Condition	
WO-40088	1	Completed	March 26, 2021, 9:40 AM	March 26, 2021, 12:00 AM	Valve Maintenance Report	March 26, 2021, 9:44 AM	V-019SV021	Valve Condition	Good
WO-47240	1	Completed	June 2, 2021, 10:15 PM	August 31, 2021, 12:00 AM	Repair water main -8"		V-019SV030	Valve Condition	Good
WO-40099	1	Completed	March 26, 2021, 10:49 AM	March 26, 2021, 12:00 AM	Valve Maintenance Report	March 26, 2021, 10:51 AM	V-019SV032	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-36956	84	Completed	February 18, 2021, 8:52 PM	February 20, 2021, 12:00 AM	Main or service line leak investigation/survey/PER EOC-911/ CHECK FOR A WATER LEAK COMING FROM UNDER MANHOLE COVER WATER RUNNING STEADY INTO MIDDLE OF THE STREET POOLING ON THE OUTBOUND LANE/W CARSON ST TO W END BRDG TOWARD W END CIRCLE	February 20, 2021, 7:11 PM	V-020CV006	Valve Condition	Good
WO-42242	1	Completed	April 20, 2021, 1:35 PM	April 23, 2021, 12:00 AM	Repair water main		V-020GV003	Valve Condition	
WO-42242	1	Completed	April 20, 2021, 1:35 PM	April 23, 2021, 12:00 AM	Repair water main		V-020LV001	Valve Condition	
WO-42242	1	Completed	April 20, 2021, 1:35 PM	April 23, 2021, 12:00 AM	Repair water main		V-020LV005	Valve Condition	
WO-55643	1	Completed	August 25, 2021, 10:42 AM	August 25, 2021, 12:00 AM	Valve Maintenance Report	August 25, 2021, 10:56 AM	V-020LV014	Valve Condition	
WO-55643	1	Completed	August 25, 2021, 10:42 AM	August 25, 2021, 12:00 AM	Valve Maintenance Report	August 25, 2021, 10:56 AM	V-020LV015	Valve Condition	
WO-55643	1	Completed	August 25, 2021, 10:42 AM	August 25, 2021, 12:00 AM	Valve Maintenance Report	August 25, 2021, 10:56 AM	V-020LV016	Valve Condition	
WO-57640	1	Completed	September 16, 2021, 7:16 AM	September 15, 2021, 12:00 AM	Valve Maintenance Report		V-020MV011	Valve Condition	Good
WO-57640	1	Completed	September 16, 2021, 7:16 AM	September 15, 2021, 12:00 AM	Valve Maintenance Report		V-020MV015	Valve Condition	Good
WO-57640	1	Completed	September 16, 2021, 7:16 AM	September 15, 2021, 12:00 AM	Valve Maintenance Report		V-020MV016	Valve Condition	Good
WO-57640	1	Completed	September 16, 2021, 7:16 AM	September 15, 2021, 12:00 AM	Valve Maintenance Report		V-020MV019	Valve Condition	Good
WO-56729	1	Completed	September 7, 2021, 6:36 AM	September 8, 2021, 12:00 AM	Repair water main	September 13, 2021, 8:03 AM	V-020PV014	Valve Condition	
WO-55643	1	Completed	August 25, 2021, 10:42 AM	August 25, 2021, 12:00 AM	Valve Maintenance Report	August 25, 2021, 10:56 AM	V-020RV012	Valve Condition	
WO-33502	1	Completed	January 14, 2021, 9:56 AM	January 15, 2021, 12:00 AM	Valve Maintenance Report	January 15, 2021, 8:44 AM	V-021AV001	Valve Condition	
WO-33502	1	Completed	January 14, 2021, 9:56 AM	January 15, 2021, 12:00 AM	Valve Maintenance Report	January 15, 2021, 8:44 AM	V-021EV019	Valve Condition	
WO-34496	1	Completed	January 25, 2021, 2:24 PM	January 26, 2021, 2:24 PM	Repair water main		V-021EV020	Valve Condition	
WO-47614	1	Completed	June 4, 2021, 3:04 PM	August 31, 2021, 12:00 AM	Repair water main		V-021HV013	Valve Condition	Good
WO-47614	1	Completed	June 4, 2021, 3:04 PM	August 31, 2021, 12:00 AM	Repair water main		V-021HV014	Valve Condition	Good
WO-66549	85	Completed	December 23, 2021, 11:39 AM	December 27, 2021, 12:00 AM	Repair water main	January 4, 2022, 12:19 PM	V-021PV012	Valve Condition	
WO-46797	1	Completed	June 1, 2021, 9:39 AM	June 1, 2021, 12:00 AM	Valve Maintenance Report	June 1, 2021, 12:10 PM	V-021RV019	Valve Condition	Good
WO-59142	1	Completed	September 30, 2021, 11:13 AM	September 30, 2021, 12:00 AM	Valve Maintenance Report	September 30, 2021, 11:20 AM	V-021SV001	Valve Condition	
WO-48908	41	Completed	June 16, 2021, 1:44 PM	June 16, 2021, 12:00 AM	Contractor shut request	June 16, 2021, 1:48 PM	V-022DV010	Valve Condition	Good
WO-40377	21	Completed	March 30, 2021, 9:30 AM	April 19, 2021, 12:00 AM	Valve requires replacement V-022DV028	April 19, 2021, 3:02 PM	V-022DV026	Valve Condition	Good
WO-40377	21	Completed	March 30, 2021, 9:30 AM	April 19, 2021, 12:00 AM	Valve requires replacement V-022DV028	April 19, 2021, 3:02 PM	V-022DV028	Valve Condition	Good
WO-48908	41	Completed	June 16, 2021, 1:44 PM	June 16, 2021, 12:00 AM	Contractor shut request	June 16, 2021, 1:48 PM	V-022DV048	Valve Condition	Good
WO-32353	85	Completed	January 4, 2021, 3:13 PM	January 5, 2021, 12:00 AM	Repair water main	January 5, 2021, 3:18 PM	V-022EV018	Valve Condition	
WO-32353	85	Completed	January 4, 2021, 3:13 PM	January 5, 2021, 12:00 AM	Repair water main	January 5, 2021, 3:18 PM	V-022FV003	Valve Condition	
WO-60885	85	Completed	October 18, 2021, 6:54 AM	October 18, 2021, 12:00 AM	Repair water main	October 19, 2021, 8:49 AM	V-022FV006	Valve Condition	
WO-60885	85	Completed	October 18, 2021, 6:54 AM	October 18, 2021, 12:00 AM	Repair water main	October 19, 2021, 8:49 AM	V-022FV017	Valve Condition	
WO-40584	88	Completed	March 31, 2021, 1:34 PM	June 3, 2021, 12:00 AM	Repair service line Customer Brought Out New Service Line 1" copper. 3 Day 1 Call placed 5/25/21 Call Doug the day before the Job.	June 3, 2021, 7:32 AM	V-022KV002	Valve Condition	
WO-40584	88	Completed	March 31, 2021, 1:34 PM	June 3, 2021, 12:00 AM	Repair service line Customer Brought Out New Service Line 1" copper. 3 Day 1 Call placed 5/25/21 Call Doug the day before the Job.	June 3, 2021, 7:32 AM	V-022KV003	Valve Condition	
WO-54143	88	Completed	August 9, 2021, 7:14 AM	August 2, 2021, 12:00 AM	Repair service line		V-022KV042	Valve Condition	
WO-32958	1	Completed	January 9, 2021, 4:09 PM	January 21, 2021, 4:09 PM	Repair water main	January 21, 2021, 11:37 AM	V-022LV024	Valve Condition	
WO-32958	1	Completed	January 9, 2021, 4:09 PM	January 21, 2021, 4:09 PM	Repair water main	January 21, 2021, 11:37 AM	V-022LV025	Valve Condition	
WO-54143	88	Completed	August 9, 2021, 7:14 AM	August 2, 2021, 12:00 AM	Repair service line		V-022LV032	Valve Condition	
WO-32958	1	Completed	January 9, 2021, 4:09 PM	January 21, 2021, 4:09 PM	Repair water main	January 21, 2021, 11:37 AM	V-022LV047	Valve Condition	
WO-32958	1	Completed	January 9, 2021, 4:09 PM	January 21, 2021, 4:09 PM	Repair water main	January 21, 2021, 11:37 AM	V-022LV049	Valve Condition	
WO-32958	1	Completed	January 9, 2021, 4:09 PM	January 21, 2021, 4:09 PM	Repair water main	January 21, 2021, 11:37 AM	V-022MV013	Valve Condition	
WO-61235	84	Completed	October 20, 2021, 3:03 PM	October 21, 2021, 12:00 AM	Main or service line leak investigation/survey Constant dirty water at buildings on Riversea Road 15212 for over a week flushing hydrants is not helping with water quality. Contact at WW Patterson Jenny Unis 724-510-1831 & 412-291-8070	October 21, 2021, 9:54 AM	V-022MV023	Valve Condition	Good
WO-61235	84	Completed	October 20, 2021, 3:03 PM	October 21, 2021, 12:00 AM	Main or service line leak investigation/survey Constant dirty water at buildings on Riversea Road 15212 for over a week flushing hydrants is not helping with water quality. Contact at WW Patterson Jenny Unis 724-510-1831 & 412-291-8070	October 21, 2021, 9:54 AM	V-022MV025	Valve Condition	Good
WO-61235	84	Completed	October 20, 2021, 3:03 PM	October 21, 2021, 12:00 AM	Main or service line leak investigation/survey Constant dirty water at buildings on Riversea Road 15212 for over a week flushing hydrants is not helping with water quality. Contact at WW Patterson Jenny Unis 724-510-1831 & 412-291-8070	October 21, 2021, 9:54 AM	V-022MV026	Valve Condition	Good
WO-61235	84	Completed	October 20, 2021, 3:03 PM	October 21, 2021, 12:00 AM	Main or service line leak investigation/survey Constant dirty water at buildings on Riversea Road 15212 for over a week flushing hydrants is not helping with water quality. Contact at WW Patterson Jenny Unis 724-510-1831 & 412-291-8070	October 21, 2021, 9:54 AM	V-022MV028	Valve Condition	Good
WO-61235	84	Completed	October 20, 2021, 3:03 PM	October 21, 2021, 12:00 AM	Main or service line leak investigation/survey Constant dirty water at buildings on Riversea Road 15212 for over a week flushing hydrants is not helping with water quality. Contact at WW Patterson Jenny Unis 724-510-1831 & 412-291-8070	October 21, 2021, 9:54 AM	V-022MV029	Valve Condition	Good
WO-61235	84	Completed	October 20, 2021, 3:03 PM	October 21, 2021, 12:00 AM	Main or service line leak investigation/survey Constant dirty water at buildings on Riversea Road 15212 for over a week flushing hydrants is not helping with water quality. Contact at WW Patterson Jenny Unis 724-510-1831 & 412-291-8070	October 21, 2021, 9:54 AM	V-022MV030	Valve Condition	Good
WO-61235	84	Completed	October 20, 2021, 3:03 PM	October 21, 2021, 12:00 AM	Main or service line leak investigation/survey Constant dirty water at buildings on Riversea Road 15212 for over a week flushing hydrants is not helping with water quality. Contact at WW Patterson Jenny Unis 724-510-1831 & 412-291-8070	October 21, 2021, 9:54 AM	V-022MV032	Valve Condition	Good
WO-61235	84	Completed	October 20, 2021, 3:03 PM	October 21, 2021, 12:00 AM	Main or service line leak investigation/survey Constant dirty water at buildings on Riversea Road 15212 for over a week flushing hydrants is not helping with water quality. Contact at WW Patterson Jenny Unis 724-510-1831 & 412-291-8070	October 21, 2021, 9:54 AM	V-022MV037	Valve Condition	Good
WO-61324	1	Completed	October 21, 2021, 10:38 AM	October 21, 2021, 12:00 AM	Valve Maintenance Report	October 21, 2021, 11:51 AM	V-022NV005	Valve Condition	Good
WO-61324	1	Completed	October 21, 2021, 10:38 AM	October 21, 2021, 12:00 AM	Valve Maintenance Report	October 21, 2021, 11:51 AM	V-022NV006	Valve Condition	Good
WO-65433	41	Completed	December 9, 2021, 10:53 AM	December 10, 2021, 12:00 AM	Contractor shut request	December 10, 2021, 1:25 PM	V-022NV018	Valve Condition	
WO-65433	41	Completed	December 9, 2021, 10:53 AM	December 10, 2021, 12:00 AM	Contractor shut request	December 10, 2021, 1:25 PM	V-022NV022	Valve Condition	
WO-61324	1	Completed	October 21, 2021, 10:38 AM	October 21, 2021, 12:00 AM	Valve Maintenance Report	October 21, 2021, 11:51 AM	V-022NV023	Valve Condition	Good
WO-64714	182	Completed	December 1, 2021, 9:27 AM	December 14, 2021, 12:00 AM	Information sheet for connection		V-022NV024	Valve Condition	
WO-61324	1	Completed	October 21, 2021, 10:38 AM	October 21, 2021, 12:00 AM	Valve Maintenance Report	October 21, 2021, 11:51 AM	V-022NV025	Valve Condition	Good
WO-64965	1	Completed	December 3, 2021, 10:18 AM	December 3, 2021, 12:00 AM	Valve Maintenance Report	December 3, 2021, 11:19 AM	V-022NV026	Valve Condition	Good
WO-65433	41	Completed	December 9, 2021, 10:53 AM	December 10, 2021, 12:00 AM	Contractor shut request	December 10, 2021, 1:25 PM	V-022NV040	Valve Condition	
WO-64714	182	Completed	December 1, 2021, 9:27 AM	December 14, 2021, 12:00 AM	Information sheet for connection		V-022NV045	Valve Condition	
WO-60754	1	Completed	October 15, 2021, 8:12 AM	October 15, 2021, 12:00 AM	Valve Maintenance Report		V-022PV003	Valve Condition	
WO-60754	1	Completed	October 15, 2021, 8:12 AM	October 15, 2021, 12:00 AM	Valve Maintenance Report		V-022PV009	Valve Condition	
WO-32267	1	Completed	January 3, 2021, 2:47 AM	January 5, 2021, 2:47 AM	Repair water main	January 21, 2021, 9:25 AM	V-022RV075	Valve Condition	
WO-61235	84	Completed	October 20, 2021, 3:03 PM	October 21, 2021, 12:00 AM	Main or service line leak investigation/survey Constant dirty water at buildings on Riversea Road 15212 for over a week flushing hydrants is not helping with water quality. Contact at WW Patterson Jenny Unis 724-510-1831 & 412-291-8070	October 21, 2021, 9:54 AM	V-022SV001	Valve Condition	Good
WO-47434	85	Completed	June 3, 2021, 3:13 PM	June 4, 2021, 12:00 AM	Repair water main	June 4, 2021, 2:54 PM	V-022SV002	Valve Condition	Good
WO-61235	84	Completed	October 20, 2021, 3:03 PM	October 21, 2021, 12:00 AM	Main or service line leak investigation/survey Constant dirty water at buildings on Riversea Road 15212 for over a week flushing hydrants is not helping with water quality. Contact at WW Patterson Jenny Unis 724-510-1831 & 412-291-8070	October 21, 2021, 9:54 AM	V-022SV003	Valve Condition	Good
WO-55635	1	Completed	August 25, 2021, 10:05 AM	August 25, 2021, 12:00 AM	Valve Maintenance Report	August 25, 2021, 10:10 AM	V-022SV029	Valve Condition	Good
WO-55635	1	Completed	August 25, 2021, 10:05 AM	August 25, 2021, 12:00 AM	Valve Maintenance Report	August 25, 2021, 10:10 AM	V-022SV034	Valve Condition	
WO-55635	1	Completed	August 25, 2021, 10:05 AM	August 25, 2021, 12:00 AM	Valve Maintenance Report	August 25, 2021, 10:10 AM	V-022SV040	Valve Condition	
WO-55635	1	Completed	August 25, 2021, 10:05 AM	August 25, 2021, 12:00 AM	Valve Maintenance Report	August 25, 2021, 10:10 AM	V-022SV041	Valve Condition	
WO-58347	1	Completed	September 22, 2021, 4:28 PM	September 22, 2021, 12:00 AM	Repair water main	September 22, 2021, 9:55 PM	V-022SV042	Valve Condition	
WO-59211	1	Completed	October 1, 2021, 8:33 AM	October 1, 2021, 12:00 AM	Valve Maintenance Report	October 1, 2021, 9:17 AM	V-022SV050	Valve Condition	
WO-57815	85	Completed	September 17, 2021, 1:22 PM	October 1, 2021, 12:00 AM	Repair water main	October 1, 2021, 7:47 AM	V-023AV030	Valve Condition	
WO-57748	1	Completed	September 17, 2021, 7:20 AM	September 20, 2021, 12:00 AM	Repair water main		V-023BV021	Valve Condition	Fair
WO-34048	1	Completed	January 20, 2021, 2:02 PM	January 20, 2021, 12:00 AM	Valve Maintenance Report	January 20, 2021, 2:11 PM	V-023DV005	Valve Condition	
WO-34048	1	Completed	January 20, 2021, 2:02 PM	January 20, 2021, 12:00 AM	Valve Maintenance Report	January 20, 2021, 2:11 PM	V-023DV006	Valve Condition	
WO-34048	1	Completed	January 20, 2021, 2:02 PM	January 20, 2021, 12:00 AM	Valve Maintenance Report	January 20, 2021, 2:11 PM	V-023DV007	Valve Condition	
WO-34048	1	Completed	January 20, 2021, 2:02 PM	January 20, 2021, 12:00 AM	Valve Maintenance Report	January 20, 2021, 2:11 PM	V-023DV012	Valve Condition	
WO-35980	41	Completed	February 8, 2021, 6:59 AM	February 23, 2021, 12:00 AM	Contractor shut request	February 23, 2021, 5:50 PM	V-023DV013	Valve Condition	
WO-58658	1	Completed	September 25, 2021, 3:39 PM	October 4, 2021, 12:00 AM	Repair water main		V-023DV019	Valve Condition	
WO-58658	1	Completed	September 25, 2021, 3:39 PM	October 4, 2021, 12:00 AM	Repair water main		V-023DV030	Valve Condition	
WO-43488	41	Completed	May 3, 2021, 11:23 AM	May 3, 2021, 12:00 AM	Contractor shut request	May 3, 2021, 2:45 PM	V-023DV031	Valve Condition	Poor
WO-55729	1	Completed	August 26, 2021, 7:04 AM	August 27, 2021, 12:00 AM	Repair water main		V-023EV017	Valve Condition	
WO-55729	1	Completed	August 26, 2021, 7:04 AM	August 27, 2021, 12:00 AM	Repair water main		V-023EV020	Valve Condition	
WO-31917	84	Completed	December 29, 2020, 5:53 AM	January 4, 2021, 12:00 AM	Main or service line leak investigation/survey SEVERAL CALLS OF NO WATER ON GARFIELD AND ARMANDALE. NEAREST ADDRESS OF LEAK IS 1533 GARFIELD	January 4, 2021, 6:51 AM	V-023EV022	Valve Condition	
WO-57815	85	Completed	September 17, 2021, 1:22 PM	October 1, 2021, 12:00 AM	Repair water main	October 1, 2021, 7:47 AM	V-023FV002	Valve Condition	Fair
WO-51649	84	Completed	July 12, 2021, 6:06 AM	July 12, 2021, 12:00 AM	INVESTIGATE WATER LEAKING IN THE STREET		V-023FV012	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-51649	84	Completed	July 12, 2021, 6:06 AM	July 12, 2021, 12:00 AM	INVESTIGATE WATER LEAKING IN THE STREET		V-023FV016	Valve Condition	
WO-51649	84	Completed	July 12, 2021, 6:06 AM	July 12, 2021, 12:00 AM	INVESTIGATE WATER LEAKING IN THE STREET		V-023FV018	Valve Condition	
WO-51649	84	Completed	July 12, 2021, 6:06 AM	July 12, 2021, 12:00 AM	INVESTIGATE WATER LEAKING IN THE STREET		V-023FV019	Valve Condition	
WO-51649	84	Completed	July 12, 2021, 6:06 AM	July 12, 2021, 12:00 AM	INVESTIGATE WATER LEAKING IN THE STREET		V-023FV020	Valve Condition	
WO-58513	1	Completed	September 24, 2021, 8:45 AM	September 22, 2021, 12:00 AM	Valve Maintenance Report		V-023FV030	Valve Condition	
WO-58513	1	Completed	September 24, 2021, 8:45 AM	September 22, 2021, 12:00 AM	Valve Maintenance Report		V-023FV038	Valve Condition	
WO-58513	1	Completed	September 24, 2021, 8:45 AM	September 22, 2021, 12:00 AM	Valve Maintenance Report		V-023FV039	Valve Condition	
WO-58513	1	Completed	September 24, 2021, 8:45 AM	September 22, 2021, 12:00 AM	Valve Maintenance Report		V-023FV041	Valve Condition	
WO-37656	88	Completed	February 26, 2021, 2:26 PM	March 4, 2021, 12:00 AM	run new service to curb Posted 3/4/21-3/11/21 8Am-6pm VEHICLES/CREW: 248 CIMINO, GRAY/ 127 WHIGHAM/ 673 WILSON JOB: NEW SERVICE THE CREW DUG OVER THE 12" MAIN AND TRENCHED TO THE CURB. THE SIDEWALK WAS DUG BY THE HOMEOWNER. THEY RAN 1" COPPER OUT. WE DRILLED A NEW 1" FERRULE AND RAN 15' OF 1" PEX TO A NEW C/S. THE STOP WAS LEFT OFF. THERE IS NO INTERNAL PLUMBING IN THE HOUSE. THE NEW C/B WAS SET AND THE SITE WAS BACKFILED, COLD PATCHED AND TAMPED. STREET: 16' X 4' ASPHALT OVER CONCRETE SIDEWALK: 5' X 6'	March 4, 2021, 3:20 PM	V-023FV044	Valve Condition	Poor
WO-58513	1	Completed	September 24, 2021, 8:45 AM	September 22, 2021, 12:00 AM	Valve Maintenance Report		V-023FV046	Valve Condition	
WO-37116	1	Completed	February 22, 2021, 7:11 AM	August 30, 2021, 12:00 AM	Repair water main		V-023FV047	Valve Condition	Good
WO-37656	88	Completed	February 26, 2021, 2:26 PM	March 4, 2021, 12:00 AM	run new service to curb Posted 3/4/21-3/11/21 8Am-6pm VEHICLES/CREW: 248 CIMINO, GRAY/ 127 WHIGHAM/ 673 WILSON JOB: NEW SERVICE THE CREW DUG OVER THE 12" MAIN AND TRENCHED TO THE CURB. THE SIDEWALK WAS DUG BY THE HOMEOWNER. THEY RAN 1" COPPER OUT. WE DRILLED A NEW 1" FERRULE AND RAN 15' OF 1" PEX TO A NEW C/S. THE STOP WAS LEFT OFF. THERE IS NO INTERNAL PLUMBING IN THE HOUSE. THE NEW C/B WAS SET AND THE SITE WAS BACKFILED, COLD PATCHED AND TAMPED. STREET: 16' X 4' ASPHALT OVER CONCRETE SIDEWALK: 5' X 6'!!	March 4, 2021, 3:20 PM	V-023FV048	Valve Condition	Poor
WO-37116	1	Completed	February 22, 2021, 7:11 AM	August 30, 2021, 12:00 AM	Repair water main		V-023FV050	Valve Condition	Good
WO-35164	84	Completed	January 31, 2021, 9:38 AM	February 22, 2021, 12:00 AM	Main or service line leak investigation/survey- CUSTOMER REPORTED SMALL LEAK IN STREET. DUE TO COLD WEATHER, WATER HAS STARTED TO FREEZE LEAVING A SHEET OF ICE.		V-023FV051	Valve Condition	
WO-37116	1	Completed	February 22, 2021, 7:11 AM	August 30, 2021, 12:00 AM	Repair water main		V-023FV052	Valve Condition	Good
WO-48819	85	Completed	June 16, 2021, 8:01 AM	June 16, 2021, 12:00 AM	DIG AND 6" LEAK	June 22, 2021, 10:32 AM	V-023GV026	Valve Condition	Good
WO-49236	85	Completed	June 18, 2021, 2:01 PM	June 24, 2021, 12:00 AM	Repair water main	June 24, 2021, 3:23 PM	V-023GV029	Valve Condition	Good
WO-37656	88	Completed	February 26, 2021, 2:26 PM	March 4, 2021, 12:00 AM	run new service to curb Posted 3/4/21-3/11/21 8Am-6pm VEHICLES/CREW: 248 CIMINO, GRAY/ 127 WHIGHAM/ 673 WILSON JOB: NEW SERVICE THE CREW DUG OVER THE 12" MAIN AND TRENCHED TO THE CURB. THE SIDEWALK WAS DUG BY THE HOMEOWNER. THEY RAN 1" COPPER OUT. WE DRILLED A NEW 1" FERRULE AND RAN 15' OF 1" PEX TO A NEW C/S. THE STOP WAS LEFT OFF. THERE IS NO INTERNAL PLUMBING IN THE HOUSE. THE NEW C/B WAS SET AND THE SITE WAS BACKFILED, COLD PATCHED AND TAMPED. STREET: 16' X 4' ASPHALT OVER CONCRETE SIDEWALK: 5' X 6'	March 4, 2021, 3:20 PM	V-023GV033	Valve Condition	Poor
WO-46194	1	Completed	May 25, 2021, 1:12 PM	August 31, 2021, 12:00 AM	Repair water main		V-023GV037	Valve Condition	Good
WO-46193	85	Completed	May 25, 2021, 1:12 PM	May 27, 2021, 12:00 AM	Repair water main	May 27, 2021, 2:06 PM	V-023GV051	Valve Condition	
WO-46194	1	Completed	May 25, 2021, 1:12 PM	August 31, 2021, 12:00 AM	Repair water main		V-023GV052	Valve Condition	Good
WO-47185	85	Completed	June 2, 2021, 2:11 PM	June 4, 2021, 12:00 AM	Repair water main	June 4, 2021, 7:47 AM	V-023GV053	Valve Condition	Good
WO-58658	1	Completed	September 25, 2021, 3:39 PM	October 4, 2021, 12:00 AM	Repair water main		V-023HV008	Valve Condition	
WO-53250	88	Completed	July 29, 2021, 1:23 AM	August 2, 2021, 12:00 AM	Repair water main	August 4, 2021, 12:27 PM	V-023HV015	Valve Condition	Good
WO-48819	85	Completed	June 16, 2021, 8:01 AM	June 16, 2021, 12:00 AM	DIG AND 6" LEAK	June 22, 2021, 10:32 AM	V-023HV017	Valve Condition	Good
WO-48819	85	Completed	June 16, 2021, 8:01 AM	June 16, 2021, 12:00 AM	DIG AND 6" LEAK	June 22, 2021, 10:32 AM	V-023HV025	Valve Condition	Good
WO-53250	88	Completed	July 29, 2021, 1:23 AM	August 2, 2021, 12:00 AM	Repair water main	August 4, 2021, 12:27 PM	V-023HV036	Valve Condition	Good
WO-46639	41	Completed	May 28, 2021, 11:54 AM	June 2, 2021, 12:00 AM	Contractor shut request	June 2, 2021, 1:21 PM	V-023JV019	Valve Condition	
WO-61235	84	Completed	October 20, 2021, 3:03 PM	October 21, 2021, 12:00 AM	Main or service line leak investigation/survey Constant dirty water at buildings on Riversea Road 15212 for over a week flushing hydrants is not helping with water quality. Contact at WW Patterson Jenny Unis 724-510-1831 & 412-291-8070	October 21, 2021, 9:54 AM	V-023JV027	Valve Condition	Good
WO-46765	1	Completed	June 1, 2021, 8:38 AM	June 1, 2021, 12:00 AM	Valve Maintenance Report	June 1, 2021, 12:05 PM	V-023JV049	Valve Condition	Good
WO-37116	1	Completed	February 22, 2021, 7:11 AM	August 30, 2021, 12:00 AM	Repair water main		V-023KV002	Valve Condition	Good
WO-46639	41	Completed	May 28, 2021, 11:54 AM	June 2, 2021, 12:00 AM	Contractor shut request	June 2, 2021, 1:21 PM	V-023KV010	Valve Condition	
WO-36833	85	Completed	February 17, 2021, 8:03 PM	February 19, 2021, 12:00 AM	Main Repair	February 19, 2021, 1:18 PM	V-023KV014	Valve Condition	
WO-36833	85	Completed	February 17, 2021, 8:03 PM	February 19, 2021, 12:00 AM	Main Repair	February 19, 2021, 1:18 PM	V-023KV030	Valve Condition	
WO-36833	85	Completed	February 17, 2021, 8:03 PM	February 19, 2021, 12:00 AM	Main Repair	February 19, 2021, 1:18 PM	V-023KV047	Valve Condition	
WO-36833	85	Completed	February 17, 2021, 8:03 PM	February 19, 2021, 12:00 AM	Main Repair	February 19, 2021, 1:18 PM	V-023KV061	Valve Condition	
WO-66212	43	Completed	December 17, 2021, 12:58 PM	December 17, 2021, 12:00 AM	Test shut	December 17, 2021, 1:54 PM	V-023LV039	Valve Condition	
WO-66212	43	Completed	December 17, 2021, 12:58 PM	December 17, 2021, 12:00 AM	Test shut	December 17, 2021, 1:54 PM	V-023LV041	Valve Condition	
WO-66212	43	Completed	December 17, 2021, 12:58 PM	December 17, 2021, 12:00 AM	Test shut	December 17, 2021, 1:54 PM	V-023LV042	Valve Condition	
WO-66212	43	Completed	December 17, 2021, 12:58 PM	December 17, 2021, 12:00 AM	Test shut	December 17, 2021, 1:54 PM	V-023LV057	Valve Condition	
WO-66703	1	Completed	December 28, 2021, 12:18 PM	December 30, 2021, 12:00 AM	Repair water main		V-023MV045	Valve Condition	
WO-66703	1	Completed	December 28, 2021, 12:18 PM	December 30, 2021, 12:00 AM	Repair water main		V-023MV046	Valve Condition	
WO-66702	85	Completed	December 28, 2021, 12:18 PM	December 28, 2021, 12:00 AM	Repair water main	January 4, 2022, 12:40 PM	V-023MV047	Valve Condition	
WO-55229	88	Completed	August 19, 2021, 1:38 PM	August 23, 2021, 12:00 AM	Repair service line	September 2, 2021, 2:11 PM	V-023MV058	Valve Condition	
WO-66212	43	Completed	December 17, 2021, 12:58 PM	December 17, 2021, 12:00 AM	Test shut	December 17, 2021, 1:54 PM	V-023NV020	Valve Condition	
WO-66212	43	Completed	December 17, 2021, 12:58 PM	December 17, 2021, 12:00 AM	Test shut	December 17, 2021, 1:54 PM	V-023NV022	Valve Condition	
WO-55635	1	Completed	August 25, 2021, 10:05 AM	August 25, 2021, 12:00 AM	Valve Maintenance Report	August 25, 2021, 10:10 AM	V-023NV032	Valve Condition	Good
WO-55635	1	Completed	August 25, 2021, 10:05 AM	August 25, 2021, 12:00 AM	Valve Maintenance Report	August 25, 2021, 10:10 AM	V-023NV035	Valve Condition	
WO-58347	1	Completed	September 22, 2021, 4:28 PM	September 22, 2021, 12:00 AM	Repair water main	September 22, 2021, 9:55 PM	V-023NV040	Valve Condition	
WO-66212	43	Completed	December 17, 2021, 12:58 PM	December 17, 2021, 12:00 AM	Test shut	December 17, 2021, 1:54 PM	V-023PV006	Valve Condition	
WO-66212	43	Completed	December 17, 2021, 12:58 PM	December 17, 2021, 12:00 AM	Test shut	December 17, 2021, 1:54 PM	V-023PV008	Valve Condition	
WO-66212	43	Completed	December 17, 2021, 12:58 PM	December 17, 2021, 12:00 AM	Test shut	December 17, 2021, 1:54 PM	V-023PV010	Valve Condition	
WO-66212	43	Completed	December 17, 2021, 12:58 PM	December 17, 2021, 12:00 AM	Test shut	December 17, 2021, 1:54 PM	V-023PV012	Valve Condition	
WO-66212	43	Completed	December 17, 2021, 12:58 PM	December 17, 2021, 12:00 AM	Test shut	December 17, 2021, 1:54 PM	V-023PV013	Valve Condition	
WO-45550	41	Completed	May 20, 2021, 10:52 AM	May 20, 2021, 12:00 AM	Contractor shut request	May 20, 2021, 1:41 PM	V-023PV024	Valve Condition	
WO-45550	41	Completed	May 20, 2021, 10:52 AM	May 20, 2021, 12:00 AM	Contractor shut request	May 20, 2021, 1:41 PM	V-023PV034	Valve Condition	
WO-63510	41	Completed	November 15, 2021, 8:24 AM	November 15, 2021, 12:00 AM	Contractor shut request	November 15, 2021, 3:00 PM	V-023SV008	Valve Condition	
WO-63510	41	Completed	November 15, 2021, 8:24 AM	November 15, 2021, 12:00 AM	Contractor shut request	November 15, 2021, 3:00 PM	V-023SV015	Valve Condition	
WO-63919	1	Completed	November 19, 2021, 8:51 AM	November 19, 2021, 12:00 AM	Valve Maintenance Report	November 19, 2021, 9:18 AM	V-023SV023	Valve Condition	
WO-63919	1	Completed	November 19, 2021, 8:51 AM	November 19, 2021, 12:00 AM	Valve Maintenance Report	November 19, 2021, 9:18 AM	V-023SV026	Valve Condition	
WO-63919	1	Completed	November 19, 2021, 8:51 AM	November 19, 2021, 12:00 AM	Valve Maintenance Report	November 19, 2021, 9:18 AM	V-023SV027	Valve Condition	
WO-63919	1	Completed	November 19, 2021, 8:51 AM	November 19, 2021, 12:00 AM	Valve Maintenance Report	November 19, 2021, 9:18 AM	V-023SV058	Valve Condition	
WO-48687	1	Completed	June 15, 2021, 1:07 PM	June 15, 2021, 12:00 AM	Valve Maintenance Report	June 15, 2021, 1:08 PM	V-024AV001	Valve Condition	
WO-53749	1	Completed	August 4, 2021, 10:06 AM	August 4, 2021, 12:00 AM	Valve Maintenance Report	August 4, 2021, 10:23 AM	V-024AV006	Valve Condition	Fair
WO-48690	1	Completed	June 15, 2021, 1:11 PM	June 15, 2021, 12:00 AM	Valve Maintenance Report	June 15, 2021, 1:12 PM	V-024AV008	Valve Condition	Good
WO-48693	1	Completed	June 15, 2021, 1:14 PM	June 15, 2021, 12:00 AM	Valve Maintenance Report	June 15, 2021, 1:16 PM	V-024AV009	Valve Condition	
WO-53770	1	Completed	August 4, 2021, 10:53 AM	August 4, 2021, 12:00 AM	Valve Maintenance Report	August 4, 2021, 10:55 AM	V-024AV017	Valve Condition	
WO-53773	1	Completed	August 4, 2021, 10:56 AM	August 4, 2021, 12:00 AM	Valve Maintenance Report	August 4, 2021, 10:59 AM	V-024AV018	Valve Condition	Good
WO-48704	1	Completed	June 15, 2021, 1:55 PM	June 15, 2021, 12:00 AM	Valve Maintenance Report	June 15, 2021, 1:57 PM	V-024AV019	Valve Condition	
WO-48706	1	Completed	June 15, 2021, 1:59 PM	June 15, 2021, 12:00 AM	Valve Maintenance Report	June 15, 2021, 2:23 PM	V-024AV020	Valve Condition	
WO-53758	1	Completed	August 4, 2021, 10:24 AM	August 4, 2021, 12:00 AM	Valve Maintenance Report	August 4, 2021, 10:30 AM	V-024AV021	Valve Condition	
WO-48694	1	Completed	June 15, 2021, 1:27 PM	June 15, 2021, 12:00 AM	Valve Maintenance Report	June 15, 2021, 1:29 PM	V-024AV022	Valve Condition	
WO-48697	1	Completed	June 15, 2021, 1:31 PM	June 15, 2021, 12:00 AM	Valve Maintenance Report	June 15, 2021, 1:39 PM	V-024AV023	Valve Condition	
WO-53942	1	Completed	August 5, 2021, 12:09 PM	August 5, 2021, 12:00 AM	Valve Maintenance Report	August 5, 2021, 12:17 PM	V-024BV002	Valve Condition	
WO-53942	1	Completed	August 5, 2021, 12:09 PM	August 5, 2021, 12:00 AM	Valve Maintenance Report	August 5, 2021, 12:17 PM	V-024BV003	Valve Condition	
WO-53942	1	Completed	August 5, 2021, 12:09 PM	August 5, 2021, 12:00 AM	Valve Maintenance Report	August 5, 2021, 12:17 PM	V-024BV004	Valve Condition	
WO-53942	1	Completed	August 5, 2021, 12:09 PM	August 5, 2021, 12:00 AM	Valve Maintenance Report	August 5, 2021, 12:17 PM	V-024BV005	Valve Condition	
WO-49107	1	Completed	June 17, 2021, 1:47 PM	June 17, 2021, 12:00 AM	Valve Maintenance Report	June 17, 2021, 1:49 PM	V-024BV024	Valve Condition	
WO-49108	1	Completed	June 17, 2021, 1:50 PM	June 17, 2021, 12:00 AM	Valve Maintenance Report	June 17, 2021, 2:16 PM	V-024BV027	Valve Condition	
WO-49108	1	Completed	June 17, 2021, 1:50 PM	June 17, 2021, 12:00 AM	Valve Maintenance Report	June 17, 2021, 2:16 PM	V-024BV029	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-58442	1	Completed	September 23, 2021, 11:18 AM	September 23, 2021, 12:00 AM	Valve Maintenance Report	September 23, 2021, 11:21 AM	V-024BV032	Valve Condition	
WO-49087	1	Completed	June 17, 2021, 11:42 AM	June 17, 2021, 12:00 AM	Valve Maintenance Report	June 17, 2021, 12:14 PM	V-024CV007	Valve Condition	
WO-38693	88	Completed	March 10, 2021, 3:18 PM	March 18, 2021, 12:00 AM	Repair service line	July 23, 2021, 3:28 PM	V-024CV010	Valve Condition	
WO-49665	1	Completed	June 22, 2021, 1:19 PM	June 22, 2021, 12:00 AM	Valve Maintenance Report	June 22, 2021, 1:20 PM	V-024CV012	Valve Condition	Good
WO-49084	1	Completed	June 17, 2021, 11:40 AM	June 17, 2021, 12:00 AM	Valve Maintenance Report	June 17, 2021, 11:45 AM	V-024CV019	Valve Condition	
WO-49081	1	Completed	June 17, 2021, 11:37 AM	June 17, 2021, 12:00 AM	Valve Maintenance Report	June 17, 2021, 11:39 AM	V-024CV022	Valve Condition	Good
WO-49505	1	Completed	June 21, 2021, 1:51 PM	June 21, 2021, 12:00 AM	Valve Maintenance Report	June 21, 2021, 2:26 PM	V-024CV023	Valve Condition	Fair
WO-49505	1	Completed	June 21, 2021, 1:51 PM	June 21, 2021, 12:00 AM	Valve Maintenance Report	June 21, 2021, 2:26 PM	V-024CV024	Valve Condition	Fair
WO-49505	1	Completed	June 21, 2021, 1:51 PM	June 21, 2021, 12:00 AM	Valve Maintenance Report	June 21, 2021, 2:26 PM	V-024CV025	Valve Condition	Fair
WO-55477	1	Completed	August 23, 2021, 1:01 PM	August 23, 2021, 12:00 AM	Valve Maintenance Report	August 23, 2021, 1:36 PM	V-024CV027	Valve Condition	
WO-49671	1	Completed	June 22, 2021, 1:49 PM	June 22, 2021, 12:00 AM	Valve Maintenance Report	June 22, 2021, 1:50 PM	V-024CV028	Valve Condition	
WO-63317	1	Completed	November 10, 2021, 9:44 AM	November 17, 2021, 12:00 AM	Repair water main		V-024CV031	Valve Condition	
WO-48907	1	Completed	June 16, 2021, 1:37 PM	June 16, 2021, 12:00 AM	Valve Maintenance Report	June 16, 2021, 1:39 PM	V-024CV034	Valve Condition	Good
WO-48907	1	Completed	June 16, 2021, 1:37 PM	June 16, 2021, 12:00 AM	Valve Maintenance Report	June 16, 2021, 1:39 PM	V-024CV037	Valve Condition	Good
WO-54992	1	Completed	August 17, 2021, 2:00 PM	September 1, 2021, 12:00 AM	Valve Maintenance Report		V-024CV039	Valve Condition	
WO-54984	1	Completed	August 17, 2021, 12:57 PM	August 17, 2021, 12:00 AM	Valve Maintenance Report	August 17, 2021, 1:06 PM	V-024CV040	Valve Condition	Good
WO-49226	1	Completed	June 18, 2021, 1:07 PM	June 18, 2021, 12:00 AM	Valve Maintenance Report	June 18, 2021, 1:19 PM	V-024CV042	Valve Condition	Good
WO-49223	1	Completed	June 18, 2021, 12:53 PM	June 18, 2021, 12:00 AM	Valve Maintenance Report	June 18, 2021, 1:05 PM	V-024CV043	Valve Condition	Good
WO-54960	1	Completed	August 17, 2021, 10:27 AM	August 17, 2021, 12:00 AM	Valve Maintenance Report	August 17, 2021, 10:41 AM	V-024CV044	Valve Condition	
WO-54955	1	Completed	August 17, 2021, 10:07 AM	August 17, 2021, 12:00 AM	Valve Maintenance Report	August 17, 2021, 10:22 AM	V-024CV045	Valve Condition	
WO-51925	88	Completed	July 14, 2021, 6:54 AM	July 14, 2021, 12:00 AM	Repair service line	July 14, 2021, 2:27 PM	V-024CV047	Valve Condition	
WO-51925	88	Completed	July 14, 2021, 6:54 AM	July 14, 2021, 12:00 AM	Repair service line	July 14, 2021, 2:27 PM	V-024CV048	Valve Condition	
WO-49666	1	Completed	June 22, 2021, 1:22 PM	June 22, 2021, 12:00 AM	Valve Maintenance Report	June 22, 2021, 1:24 PM	V-024CV051	Valve Condition	Good
WO-49668	1	Completed	June 22, 2021, 1:43 PM	June 22, 2021, 12:00 AM	Valve Maintenance Report	June 22, 2021, 1:45 PM	V-024CV052	Valve Condition	
WO-49669	1	Completed	June 22, 2021, 1:46 PM	June 22, 2021, 12:00 AM	Valve Maintenance Report	June 22, 2021, 1:48 PM	V-024CV054	Valve Condition	
WO-54965	1	Completed	August 17, 2021, 10:48 AM	August 17, 2021, 12:00 AM	Valve Maintenance Report	August 17, 2021, 10:59 AM	V-024CV058	Valve Condition	
WO-60201	1	Completed	October 11, 2021, 10:20 AM	October 11, 2021, 12:00 AM	Valve Maintenance Report	October 11, 2021, 11:06 AM	V-024CV059	Valve Condition	
WO-58444	1	Completed	September 23, 2021, 11:33 AM	September 23, 2021, 12:00 AM	Valve Maintenance Report	September 23, 2021, 11:57 AM	V-024CV060	Valve Condition	
WO-58444	1	Completed	September 23, 2021, 11:33 AM	September 23, 2021, 12:00 AM	Valve Maintenance Report	September 23, 2021, 11:57 AM	V-024CV061	Valve Condition	
WO-54990	1	Completed	August 17, 2021, 1:46 PM	August 17, 2021, 12:00 AM	Valve Maintenance Report	August 17, 2021, 1:50 PM	V-024CV062	Valve Condition	
WO-58444	1	Completed	September 23, 2021, 11:33 AM	September 23, 2021, 12:00 AM	Valve Maintenance Report	September 23, 2021, 11:57 AM	V-024CV065	Valve Condition	
WO-36867	84	Completed	February 18, 2021, 9:03 AM	February 18, 2021, 12:00 AM	Main or service line leak investigation/survey		V-024DV008	Valve Condition	
WO-50290	1	Completed	June 28, 2021, 9:02 AM	June 28, 2021, 12:00 AM	Valve Maintenance Report	June 28, 2021, 9:07 AM	V-024DV009	Valve Condition	
WO-50278	1	Completed	June 28, 2021, 8:42 AM	June 28, 2021, 12:00 AM	Valve Maintenance Report	June 28, 2021, 8:45 AM	V-024DV010	Valve Condition	Fair
WO-52509	1	Completed	July 20, 2021, 5:24 AM	July 20, 2021, 12:00 AM	Valve Maintenance Report	July 20, 2021, 5:26 AM	V-024DV011	Valve Condition	Good
WO-51925	88	Completed	July 14, 2021, 6:54 AM	July 14, 2021, 12:00 AM	Repair service line	July 14, 2021, 2:27 PM	V-024DV012	Valve Condition	
WO-50348	1	Completed	June 28, 2021, 10:31 AM	June 28, 2021, 12:00 AM	Valve Maintenance Report	June 28, 2021, 11:02 AM	V-024DV014	Valve Condition	
WO-50300	1	Completed	June 28, 2021, 9:34 AM	June 28, 2021, 12:00 AM	Valve Maintenance Report	June 28, 2021, 10:29 AM	V-024DV016	Valve Condition	
WO-50300	1	Completed	June 28, 2021, 9:34 AM	June 28, 2021, 12:00 AM	Valve Maintenance Report	June 28, 2021, 10:29 AM	V-024DV017	Valve Condition	
WO-50371	1	Completed	June 28, 2021, 1:28 PM	June 28, 2021, 12:00 AM	Valve Maintenance Report	June 28, 2021, 2:02 PM	V-024DV019	Valve Condition	
WO-50371	1	Completed	June 28, 2021, 1:28 PM	June 28, 2021, 12:00 AM	Valve Maintenance Report	June 28, 2021, 2:02 PM	V-024DV020	Valve Condition	
WO-50371	1	Completed	June 28, 2021, 1:28 PM	June 28, 2021, 12:00 AM	Valve Maintenance Report	June 28, 2021, 2:02 PM	V-024DV021	Valve Condition	
WO-52504	1	Completed	July 20, 2021, 2:21 AM	July 20, 2021, 12:00 AM	Valve Maintenance Report	July 20, 2021, 2:24 AM	V-024DV024	Valve Condition	Good
WO-52505	1	Completed	July 20, 2021, 3:02 AM	July 20, 2021, 12:00 AM	Valve Maintenance Report	July 20, 2021, 3:04 AM	V-024DV027	Valve Condition	Fair
WO-52507	1	Completed	July 20, 2021, 3:49 AM	July 20, 2021, 12:00 AM	Valve Maintenance Report	July 20, 2021, 3:50 AM	V-024DV028	Valve Condition	Fair
WO-52504	1	Completed	July 20, 2021, 2:21 AM	July 20, 2021, 12:00 AM	Valve Maintenance Report	July 20, 2021, 2:24 AM	V-024DV029	Valve Condition	Good
WO-52508	1	Completed	July 20, 2021, 4:28 AM	July 20, 2021, 12:00 AM	Valve Maintenance Report	July 20, 2021, 4:29 AM	V-024DV030	Valve Condition	Good
WO-52506	1	Completed	July 20, 2021, 3:31 AM	July 20, 2021, 12:00 AM	Valve Maintenance Report	July 20, 2021, 3:33 AM	V-024DV031	Valve Condition	Fair
WO-55888	1	Completed	August 27, 2021, 11:10 AM	August 27, 2021, 12:00 AM	Valve Maintenance Report	August 27, 2021, 12:07 PM	V-024EV001	Valve Condition	
WO-55787	1	Completed	August 26, 2021, 1:28 PM	August 26, 2021, 12:00 AM	Valve Maintenance Report	August 26, 2021, 1:30 PM	V-024EV005	Valve Condition	
WO-55790	1	Completed	August 26, 2021, 1:33 PM	August 26, 2021, 12:00 AM	Valve Maintenance Report	August 26, 2021, 1:35 PM	V-024EV006	Valve Condition	
WO-55789	1	Completed	August 26, 2021, 1:31 PM	August 26, 2021, 12:00 AM	Valve Maintenance Report	August 26, 2021, 1:32 PM	V-024EV007	Valve Condition	
WO-55791	1	Completed	August 26, 2021, 1:33 PM	August 26, 2021, 12:00 AM	Valve Maintenance Report	August 26, 2021, 2:06 PM	V-024EV008	Valve Condition	
WO-55791	1	Completed	August 26, 2021, 1:33 PM	August 26, 2021, 12:00 AM	Valve Maintenance Report	August 26, 2021, 2:06 PM	V-024EV009	Valve Condition	
WO-58466	1	Completed	September 23, 2021, 1:51 PM	September 23, 2021, 12:00 AM	Valve Maintenance Report	September 23, 2021, 2:19 PM	V-024EV010	Valve Condition	
WO-34447	464	Completed	January 25, 2021, 10:44 AM	January 26, 2021, 12:00 AM	Contractor damage to WATER main	January 26, 2021, 9:50 PM	V-024EV013	Valve Condition	Good
WO-34447	464	Completed	January 25, 2021, 10:44 AM	January 26, 2021, 12:00 AM	Contractor damage to WATER main	January 26, 2021, 9:50 PM	V-024EV016	Valve Condition	
WO-55866	1	Completed	August 27, 2021, 9:16 AM	August 27, 2021, 12:00 AM	Valve Maintenance Report	August 27, 2021, 9:18 AM	V-024EV017	Valve Condition	
WO-55863	1	Completed	August 27, 2021, 9:09 AM	August 27, 2021, 12:00 AM	Valve Maintenance Report	August 27, 2021, 9:11 AM	V-024EV018	Valve Condition	
WO-55864	1	Completed	August 27, 2021, 9:12 AM	August 27, 2021, 12:00 AM	Valve Maintenance Report	August 27, 2021, 9:15 AM	V-024EV019	Valve Condition	
WO-55864	1	Completed	August 27, 2021, 9:12 AM	August 27, 2021, 12:00 AM	Valve Maintenance Report	August 27, 2021, 9:15 AM	V-024EV020	Valve Condition	
WO-55875	1	Completed	August 27, 2021, 9:56 AM	August 27, 2021, 12:00 AM	Valve Maintenance Report	August 27, 2021, 9:59 AM	V-024EV021	Valve Condition	
WO-41860	1	Completed	April 16, 2021, 8:16 AM	April 16, 2021, 12:00 AM	Valve Maintenance Report	April 16, 2021, 12:57 PM	V-024EV022	Valve Condition	
WO-41860	1	Completed	April 16, 2021, 8:16 AM	April 16, 2021, 12:00 AM	Valve Maintenance Report	April 16, 2021, 12:57 PM	V-024EV023	Valve Condition	
WO-41860	1	Completed	April 16, 2021, 8:16 AM	April 16, 2021, 12:00 AM	Valve Maintenance Report	April 16, 2021, 12:57 PM	V-024EV025	Valve Condition	
WO-55882	1	Completed	August 27, 2021, 10:29 AM	August 27, 2021, 12:00 AM	Valve Maintenance Report	August 27, 2021, 12:21 PM	V-024EV026	Valve Condition	
WO-58464	1	Completed	September 23, 2021, 1:31 PM	September 23, 2021, 12:00 AM	Valve Maintenance Report	September 23, 2021, 1:55 PM	V-024FV003	Valve Condition	
WO-58462	1	Completed	September 23, 2021, 1:29 PM	September 23, 2021, 12:00 AM	Valve Maintenance Report	September 23, 2021, 1:49 PM	V-024FV005	Valve Condition	
WO-58441	1	Completed	September 23, 2021, 11:11 AM	September 23, 2021, 12:00 AM	Valve Maintenance Report	September 23, 2021, 11:13 AM	V-024FV006	Valve Condition	
WO-55491	1	Completed	August 23, 2021, 1:40 PM	August 23, 2021, 12:00 AM	Valve Maintenance Report	August 23, 2021, 2:24 PM	V-024FV008	Valve Condition	
WO-55491	1	Completed	August 23, 2021, 1:40 PM	August 23, 2021, 12:00 AM	Valve Maintenance Report	August 23, 2021, 2:24 PM	V-024FV009	Valve Condition	
WO-57722	1	Completed	September 16, 2021, 2:24 PM	September 16, 2021, 12:00 AM	Valve Maintenance Report	September 16, 2021, 2:25 PM	V-024FV014	Valve Condition	
WO-58398	1	Completed	September 23, 2021, 9:26 AM	September 23, 2021, 12:00 AM	Valve Maintenance Report	September 23, 2021, 9:34 AM	V-024FV015	Valve Condition	
WO-57723	1	Completed	September 16, 2021, 2:27 PM	September 16, 2021, 12:00 AM	Valve Maintenance Report	September 16, 2021, 2:29 PM	V-024FV016	Valve Condition	
WO-58398	1	Completed	September 23, 2021, 9:26 AM	September 23, 2021, 12:00 AM	Valve Maintenance Report	September 23, 2021, 9:34 AM	V-024FV019	Valve Condition	
WO-58398	1	Completed	September 23, 2021, 9:26 AM	September 23, 2021, 12:00 AM	Valve Maintenance Report	September 23, 2021, 9:34 AM	V-024FV021	Valve Condition	
WO-55469	1	Completed	August 23, 2021, 12:01 PM	August 23, 2021, 12:00 AM	Valve Maintenance Report	August 23, 2021, 12:03 PM	V-024FV022	Valve Condition	
WO-55081	1	Completed	August 18, 2021, 10:42 AM	August 18, 2021, 12:00 AM	Valve Maintenance Report	August 18, 2021, 11:15 AM	V-024FV023	Valve Condition	Good
WO-55081	1	Completed	August 18, 2021, 10:42 AM	August 18, 2021, 12:00 AM	Valve Maintenance Report	August 18, 2021, 11:15 AM	V-024FV024	Valve Condition	Good
WO-55043	1	Completed	August 18, 2021, 9:16 AM	August 18, 2021, 12:00 AM	Valve Maintenance Report	August 18, 2021, 9:34 AM	V-024FV025	Valve Condition	
WO-55040	1	Completed	August 18, 2021, 9:08 AM	August 18, 2021, 12:00 AM	Valve Maintenance Report	August 18, 2021, 9:11 AM	V-024FV027	Valve Condition	
WO-55042	1	Completed	August 18, 2021, 9:12 AM	August 18, 2021, 12:00 AM	Valve Maintenance Report	August 18, 2021, 9:14 AM	V-024FV029	Valve Condition	
WO-55468	1	Completed	August 23, 2021, 11:59 AM	August 23, 2021, 12:00 AM	Valve Maintenance Report	August 23, 2021, 12:00 PM	V-024FV030	Valve Condition	
WO-57258	1	Completed	September 13, 2021, 10:52 AM	September 13, 2021, 12:00 AM	Valve Maintenance Report	September 13, 2021, 12:27 PM	V-024FV033	Valve Condition	
WO-52902	643	Completed	July 23, 2021, 8:32 AM	July 26, 2021, 12:00 AM	Water service line shut and cut/Sewer lateral connection removal/Stormwater connection removal	July 26, 2021, 3:28 PM	V-024FV035	Valve Condition	Good
WO-56373	1	Completed	September 1, 2021, 1:22 PM	January 22, 2021, 12:00 AM	Valve Maintenance Report		V-024FV036	Valve Condition	
WO-57249	1	Completed	September 13, 2021, 9:56 AM	September 13, 2021, 12:00 AM	Valve Maintenance Report	September 13, 2021, 10:18 AM	V-024FV037	Valve Condition	
WO-57258	1	Completed	September 13, 2021, 10:52 AM	September 13, 2021, 12:00 AM	Valve Maintenance Report	September 13, 2021, 12:27 PM	V-024FV038	Valve Condition	
WO-57249	1	Completed	September 13, 2021, 9:56 AM	September 13, 2021, 12:00 AM	Valve Maintenance Report	September 13, 2021, 10:18 AM	V-024FV042	Valve Condition	
WO-55055	1	Completed	August 18, 2021, 9:47 AM	August 18, 2021, 12:00 AM	Valve Maintenance Report	August 18, 2021, 10:14 AM	V-024FV046	Valve Condition	
WO-55055	1	Completed	August 18, 2021, 9:47 AM	August 18, 2021, 12:00 AM	Valve Maintenance Report	August 18, 2021, 10:14 AM	V-024FV047	Valve Condition	
WO-55055	1	Completed	August 18, 2021, 9:47 AM	August 18, 2021, 12:00 AM	Valve Maintenance Report	August 18, 2021, 10:14 AM	V-024FV048	Valve Condition	
WO-57248	1	Completed	September 13, 2021, 9:53 AM	September 13, 2021, 12:00 AM	Valve Maintenance Report	September 13, 2021, 9:55 AM	V-024GV001	Valve Condition	
WO-55114	1	Completed	August 18, 2021, 1:09 PM	August 23, 2021, 12:00 AM	Valve Maintenance Report	August 23, 2021, 10:50 AM	V-024GV005	Valve Condition	
WO-55477	1	Completed	August 23, 2021, 1:01 PM	August 23, 2021, 12:00 AM	Valve Maintenance Report	August 23, 2021, 1:36 PM	V-024GV008	Valve Condition	
WO-58158	1	Completed	September 21, 2021, 1:15 PM	September 21, 2021, 12:00 AM	Valve Maintenance Report	September 21, 2021, 1:58 PM	V-024GV009	Valve Condition	
WO-58136	1	Completed	September 21, 2021, 11:29 AM	September 21, 2021, 12:00 AM	Valve Maintenance Report	September 21, 2021, 11:34 AM	V-024GV011	Valve Condition	
WO-57232	1	Completed	September 13, 2021, 8:35 AM	September 13, 2021, 12:00 AM	Valve Maintenance Report	September 13, 2021, 8:42 AM	V-024GV012	Valve Condition	
WO-57233	1	Completed	September 13, 2021, 8:43 AM	September 13, 2021, 12:00 AM	Valve Maintenance Report	September 13, 2021, 8:48 AM	V-024GV013	Valve Condition	
WO-58158	1	Completed	September 21, 2021, 1:15 PM	September 21, 2021, 12:00 AM	Valve Maintenance Report	September 21, 2021, 1:58 PM	V-024GV015	Valve Condition	
WO-58158	1	Completed	September 21, 2021, 1:15 PM	September 21, 2021, 12:00 AM	Valve Maintenance Report	September 21, 2021, 1:58 PM	V-024GV016	Valve Condition	
WO-55477	1	Completed	August 23, 2021, 1:01 PM	August 23, 2021, 12:00 AM	Valve Maintenance Report	August 23, 2021, 1:36 PM	V-024GV017	Valve Condition	
WO-57236	1	Completed	September 13, 2021, 9:10 AM	September 13, 2021, 12:00 AM	Valve Maintenance Report	September 13, 2021, 9:20 AM	V-024GV019	Valve Condition	Good
WO-57236	1	Completed	September 13, 2021, 9:10 AM	September 13, 2021, 12:00 AM	Valve Maintenance Report	September 13, 2021, 9:20 AM	V-024GV020	Valve Condition	Good
WO-57236	1	Completed	September 13, 2021, 9:10 AM	September 13, 2021, 12:00 AM	Valve Maintenance Report	September 13, 2021, 9:20 AM	V-024GV021	Valve Condition	Good
WO-58159	1	Completed	September 21, 2021, 1:16 PM	September 21, 2021, 12:00 AM	Valve Maintenance Report	September 21, 2021, 1:29 PM	V-024GV039	Valve Condition	
WO-58146	1	Completed	September 21, 2021, 12:18 PM	September 21, 2021, 12:00 AM	Valve Maintenance Report	September 21, 2021, 12:19 PM	V-024GV040	Valve Condition	
WO-58159	1	Completed	September 21, 2021, 1:16 PM	September 21, 2021, 12:00 AM	Valve Maintenance Report	September 21, 2021, 1:29 PM	V-024GV041	Valve Condition	
WO-58159	1	Completed	September 21, 2021, 1:16 PM	September 21, 2021, 12:00 AM	Valve Maintenance Report	September 21, 2021, 1:29 PM	V-024GV042	Valve Condition	
WO-58598	1	Completed	September 24, 2021, 1:12 PM	September 24, 2021, 12:00 AM	Valve Maintenance Report	September 24, 2021, 1:15 PM	V-024GV043	Valve Condition	Good
WO-58598	1	Completed	September 24, 2021, 1:12 PM	September 24, 2021, 12:00 AM	Valve Maintenance Report	September 24, 2021, 1:15 PM	V-024GV045	Valve Condition	Good
WO-58596	1	Completed	September 24, 2021, 1:09 PM	September 24, 2021, 12:00 AM	Valve Maintenance Report	September 24, 2021, 1:10 PM	V-024GV046	Valve Condition	
WO-55474	1	Completed	August 23, 2021, 12:42 PM	August 23, 2021, 12:00 AM	Valve Maintenance Report	August 23, 2021, 12:45 PM	V-024GV055	Valve Condition	
WO-52902	643	Completed	July 23, 2021, 8:32 AM	July 26, 2021, 12:00 AM	Water service line shut and cut/Sewer lateral connection removal/Stormwater connection removal	July 26, 2021, 3:28 PM	V-024GV057	Valve Condition	Good
WO-55114	1	Completed	August 18, 2021, 1:09 PM	August 23, 2021, 12:00 AM	Valve Maintenance Report	August 23, 2021, 10:50 AM	V-024GV063	Valve Condition	
WO-55114	1	Completed	August 18, 2021, 1:09 PM	August 23, 2021, 12:00 AM	Valve Maintenance Report	August 23, 2021, 10:50 AM	V-024GV064	Valve Condition	
WO-55114	1	Completed	August 18, 2021, 1:09 PM	August 23, 2021, 12:00 AM	Valve Maintenance Report	August 23, 2021, 10:50 AM	V-024GV065	Valve Condition	
WO-55114	1	Completed	August 18, 2021, 1:09 PM	August 23, 2021, 12:00 AM	Valve Maintenance Report	August 23, 2021, 10:50 AM	V-024GV066	Valve Condition	
WO-58140	1	Completed	September 21, 2021, 11:51 AM	September 21, 2021, 12:00 AM	Valve Maintenance Report	September 21, 2021, 11:57 AM	V-024HV002	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-58140	1	Completed	September 21, 2021, 11:51 AM	September 21, 2021, 12:00 AM	Valve Maintenance Report	September 21, 2021, 11:57 AM	V-024HV003	Valve Condition	
WO-58581	1	Completed	September 24, 2021, 11:26 AM	September 24, 2021, 12:00 AM	Valve Maintenance Report	September 24, 2021, 11:29 AM	V-024HV004	Valve Condition	
WO-58580	1	Completed	September 24, 2021, 11:26 AM	September 24, 2021, 12:00 AM	Valve Maintenance Report	September 24, 2021, 11:52 AM	V-024HV006	Valve Condition	
WO-55647	1	Completed	August 25, 2021, 11:49 AM	August 25, 2021, 12:00 AM	Valve Maintenance Report	August 25, 2021, 11:50 AM	V-024HV014	Valve Condition	
WO-55763	1	Completed	August 26, 2021, 11:18 AM	August 26, 2021, 12:00 AM	Valve Maintenance Report	August 26, 2021, 11:19 AM	V-024HV020	Valve Condition	
WO-55760	1	Completed	August 26, 2021, 11:05 AM	August 26, 2021, 12:00 AM	Valve Maintenance Report	August 26, 2021, 11:10 AM	V-024HV024	Valve Condition	
WO-55760	1	Completed	August 26, 2021, 11:05 AM	August 26, 2021, 12:00 AM	Valve Maintenance Report	August 26, 2021, 11:10 AM	V-024HV028	Valve Condition	
WO-55774	1	Completed	August 26, 2021, 12:40 PM	August 26, 2021, 12:00 AM	Valve Maintenance Report	August 26, 2021, 12:43 PM	V-024HV031	Valve Condition	
WO-55761	1	Completed	August 26, 2021, 11:11 AM	August 26, 2021, 12:00 AM	Valve Maintenance Report	August 26, 2021, 11:14 AM	V-024HV032	Valve Condition	
WO-55761	1	Completed	August 26, 2021, 11:11 AM	August 26, 2021, 12:00 AM	Valve Maintenance Report	August 26, 2021, 11:14 AM	V-024HV033	Valve Condition	
WO-55778	1	Completed	August 26, 2021, 1:11 PM	August 26, 2021, 12:00 AM	Valve Maintenance Report	August 26, 2021, 1:12 PM	V-024HV037	Valve Condition	
WO-55774	1	Completed	August 26, 2021, 12:40 PM	August 26, 2021, 12:00 AM	Valve Maintenance Report	August 26, 2021, 12:43 PM	V-024HV039	Valve Condition	
WO-55774	1	Completed	August 26, 2021, 12:40 PM	August 26, 2021, 12:00 AM	Valve Maintenance Report	August 26, 2021, 12:43 PM	V-024HV041	Valve Condition	
WO-41860	1	Completed	April 16, 2021, 8:16 AM	April 16, 2021, 12:00 AM	Valve Maintenance Report	April 16, 2021, 12:57 PM	V-024JV009	Valve Condition	
WO-58610	1	Completed	September 24, 2021, 2:15 PM	September 24, 2021, 12:00 AM	Valve Maintenance Report	September 24, 2021, 2:21 PM	V-024JV012	Valve Condition	Good
WO-38719	41	Completed	March 11, 2021, 7:55 AM	March 11, 2021, 12:00 AM	Contractor shut request	March 11, 2021, 4:38 PM	V-024JV013	Valve Condition	Good
WO-41860	1	Completed	April 16, 2021, 8:16 AM	April 16, 2021, 12:00 AM	Valve Maintenance Report	April 16, 2021, 12:57 PM	V-024JV014	Valve Condition	Good
WO-50374	1	Completed	June 28, 2021, 1:35 PM	June 29, 2021, 12:00 AM	Repair water main		V-024JV031	Valve Condition	Fair
WO-50374	1	Completed	June 28, 2021, 1:35 PM	June 29, 2021, 12:00 AM	Repair water main		V-024JV033	Valve Condition	Fair
WO-66702	85	Completed	December 28, 2021, 12:18 PM	December 28, 2021, 12:00 AM	Repair water main	January 4, 2022, 12:40 PM	V-024JV035	Valve Condition	
WO-45988	88	Completed	May 24, 2021, 2:16 PM	June 8, 2021, 12:00 AM	Repair service line New 1" copper service has been run out to curb need to complete public side. 3 Day one Call placed 5/25/21 Call Walt the day before job	July 23, 2021, 2:58 PM	V-024JV050	Valve Condition	
WO-45988	88	Completed	May 24, 2021, 2:16 PM	June 8, 2021, 12:00 AM	Repair service line New 1" copper service has been run out to curb need to complete public side. 3 Day one Call placed 5/25/21 Call Walt the day before job	July 23, 2021, 2:58 PM	V-024KV007	Valve Condition	
WO-56273	1	Completed	September 1, 2021, 10:02 AM	June 22, 2021, 12:00 AM	Valve Maintenance Report		V-024KV042	Valve Condition	Good
WO-56273	1	Completed	September 1, 2021, 10:02 AM	June 22, 2021, 12:00 AM	Valve Maintenance Report		V-024KV044	Valve Condition	Good
WO-56273	1	Completed	September 1, 2021, 10:02 AM	June 22, 2021, 12:00 AM	Valve Maintenance Report		V-024KV045	Valve Condition	Good
WO-56273	1	Completed	September 1, 2021, 10:02 AM	June 22, 2021, 12:00 AM	Valve Maintenance Report		V-024KV046	Valve Condition	Good
WO-56273	1	Completed	September 1, 2021, 10:02 AM	June 22, 2021, 12:00 AM	Valve Maintenance Report		V-024KV065	Valve Condition	Good
WO-52902	643	Completed	July 23, 2021, 8:32 AM	July 26, 2021, 12:00 AM	Water service line shut and cut/Sewer lateral connection removal/Stormwater connection removal	July 26, 2021, 3:28 PM	V-024LV003	Valve Condition	Good
WO-52902	643	Completed	July 23, 2021, 8:32 AM	July 26, 2021, 12:00 AM	Water service line shut and cut/Sewer lateral connection removal/Stormwater connection removal	July 26, 2021, 3:28 PM	V-024LV008	Valve Condition	Good
WO-64390	88	Completed	November 24, 2021, 12:26 PM	December 9, 2021, 12:00 AM	Repair service line- if drilled, Drill Sheet work order MUST be completed	December 9, 2021, 7:21 PM	V-024PV019	Valve Condition	
WO-53183	1	Completed	July 27, 2021, 2:36 PM	July 27, 2021, 12:00 AM	Valve Maintenance Report	July 27, 2021, 2:40 PM	V-025AV036	Valve Condition	
WO-34078	41	Completed	January 20, 2021, 4:50 PM	January 20, 2021, 12:00 AM	Contractor shut request		V-025CV011	Valve Condition	
WO-33895	1	Completed	January 19, 2021, 11:50 AM	January 21, 2021, 12:00 AM	Valve Maintenance Report	January 21, 2021, 3:13 PM	V-025CV012	Valve Condition	
WO-34078	41	Completed	January 20, 2021, 4:50 PM	January 20, 2021, 12:00 AM	Contractor shut request		V-025CV014	Valve Condition	
WO-34138	1	Completed	January 21, 2021, 10:03 AM	January 21, 2021, 12:00 AM	Valve Maintenance Report		V-025CV019	Valve Condition	
WO-34078	41	Completed	January 20, 2021, 4:50 PM	January 20, 2021, 12:00 AM	Contractor shut request		V-025CV027	Valve Condition	
WO-43714	1	Completed	May 5, 2021, 9:09 AM	May 5, 2021, 12:00 AM	Valve Maintenance Report	May 5, 2021, 9:11 AM	V-025CV039	Valve Condition	Poor
WO-43720	1	Completed	May 5, 2021, 9:17 AM	May 5, 2021, 12:00 AM	Valve Maintenance Report	May 5, 2021, 9:19 AM	V-025CV046	Valve Condition	Good
WO-36041	1	Completed	February 8, 2021, 1:39 PM	February 15, 2021, 1:38 PM	Repair water main		V-025DV006	Valve Condition	
WO-43716	1	Completed	May 5, 2021, 9:12 AM	May 5, 2021, 12:00 AM	Valve Maintenance Report	May 5, 2021, 10:22 AM	V-025DV009	Valve Condition	Good
WO-39328	1	Completed	March 18, 2021, 2:17 AM	March 22, 2021, 12:00 AM	Repair water main		V-025DV010	Valve Condition	
WO-39328	1	Completed	March 18, 2021, 2:17 AM	March 22, 2021, 12:00 AM	Repair water main		V-025DV014	Valve Condition	
WO-32180	1	Completed	December 31, 2020, 12:08 PM	January 8, 2021, 12:00 AM	Valve Maintenance Report	January 8, 2021, 2:49 PM	V-025DV018	Valve Condition	
WO-32180	1	Completed	December 31, 2020, 12:08 PM	January 8, 2021, 12:00 AM	Valve Maintenance Report	January 8, 2021, 2:49 PM	V-025DV020	Valve Condition	
WO-43711	1	Completed	May 5, 2021, 9:02 AM	May 5, 2021, 12:00 AM	Valve Maintenance Report	May 5, 2021, 9:04 AM	V-025DV021	Valve Condition	
WO-32180	1	Completed	December 31, 2020, 12:08 PM	January 8, 2021, 12:00 AM	Valve Maintenance Report	January 8, 2021, 2:49 PM	V-025DV022	Valve Condition	
WO-34860	41	Completed	January 28, 2021, 10:15 AM	February 5, 2021, 12:00 AM	Contractor shut request Buncher bld	February 5, 2021, 2:04 PM	V-025DV028	Valve Condition	
WO-47768	43	Completed	June 8, 2021, 1:19 AM	June 23, 2021, 12:00 AM	Test shut	June 23, 2021, 12:06 PM	V-025DV029	Valve Condition	
WO-47768	43	Completed	June 8, 2021, 1:19 AM	June 23, 2021, 12:00 AM	Test shut	June 23, 2021, 12:06 PM	V-025DV031	Valve Condition	
WO-47768	43	Completed	June 8, 2021, 1:19 AM	June 23, 2021, 12:00 AM	Test shut	June 23, 2021, 12:06 PM	V-025DV033	Valve Condition	
WO-34860	41	Completed	January 28, 2021, 10:15 AM	February 5, 2021, 12:00 AM	Contractor shut request Buncher bld	February 5, 2021, 2:04 PM	V-025DV034	Valve Condition	
WO-34860	41	Completed	January 28, 2021, 10:15 AM	February 5, 2021, 12:00 AM	Contractor shut request Buncher bld	February 5, 2021, 2:04 PM	V-025DV035	Valve Condition	
WO-34860	41	Completed	January 28, 2021, 10:15 AM	February 5, 2021, 12:00 AM	Contractor shut request Buncher bld	February 5, 2021, 2:04 PM	V-025DV036	Valve Condition	
WO-53887	1	Completed	August 5, 2021, 7:17 AM	August 6, 2021, 12:00 AM	DIG AND REPAIR 6" LEAK		V-025DV037	Valve Condition	
WO-34860	41	Completed	January 28, 2021, 10:15 AM	February 5, 2021, 12:00 AM	Contractor shut request Buncher bld	February 5, 2021, 2:04 PM	V-025DV041	Valve Condition	
WO-47686	1	Completed	June 7, 2021, 10:04 AM	June 8, 2021, 12:00 AM	Valve Maintenance Report	June 8, 2021, 7:45 AM	V-025DV045	Valve Condition	
WO-46080	1	Completed	May 25, 2021, 9:18 AM	August 31, 2021, 12:00 AM	Repair water main		V-025DV046	Valve Condition	
WO-34860	41	Completed	January 28, 2021, 10:15 AM	February 5, 2021, 12:00 AM	Contractor shut request Buncher bld	February 5, 2021, 2:04 PM	V-025DV049	Valve Condition	
WO-32180	1	Completed	December 31, 2020, 12:08 PM	January 8, 2021, 12:00 AM	Valve Maintenance Report	January 8, 2021, 2:49 PM	V-025DV060	Valve Condition	
WO-38618	85	Completed	March 10, 2021, 6:48 AM	March 11, 2021, 12:00 AM	Repair water main	March 11, 2021, 8:29 AM	V-025DV068	Valve Condition	
WO-53638	1	Completed	August 3, 2021, 10:38 AM	August 3, 2021, 12:00 AM	Valve Maintenance Report	August 3, 2021, 1:00 PM	V-025DV069	Valve Condition	Fair
WO-32180	1	Completed	December 31, 2020, 12:08 PM	January 8, 2021, 12:00 AM	Valve Maintenance Report	January 8, 2021, 2:49 PM	V-025DV071	Valve Condition	
WO-38833	1	Completed	March 12, 2021, 7:32 AM	August 30, 2021, 12:00 AM	Repair water main		V-025FV013	Valve Condition	
WO-38833	1	Completed	March 12, 2021, 7:32 AM	August 30, 2021, 12:00 AM	Repair water main		V-025FV015	Valve Condition	
WO-39155	41	Completed	March 16, 2021, 10:16 AM	March 16, 2021, 12:00 AM	Contractor shut request	March 16, 2021, 2:26 PM	V-025FV016	Valve Condition	
WO-50915	1	Completed	July 2, 2021, 11:35 AM	August 31, 2021, 12:00 AM	Repair water main		V-025FV035	Valve Condition	
WO-66484	1	Completed	December 22, 2021, 10:20 AM	December 22, 2021, 12:00 AM	Valve Maintenance Report	December 22, 2021, 1:50 PM	V-025FV041	Valve Condition	
WO-66302	41	Completed	December 20, 2021, 8:17 AM	December 20, 2021, 12:00 AM	Contractor shut request	December 20, 2021, 11:51 PM	V-025FV053	Valve Condition	
WO-38833	1	Completed	March 12, 2021, 7:32 AM	August 30, 2021, 12:00 AM	Repair water main		V-025FV059	Valve Condition	
WO-61942	1	Completed	October 28, 2021, 11:22 AM	November 2, 2021, 12:00 AM	Repair water main		V-025GV006	Valve Condition	
WO-39008	85	Completed	March 15, 2021, 9:39 AM	March 25, 2021, 12:00 AM	Repair water main	March 25, 2021, 6:46 PM	V-025GV007	Valve Condition	
WO-50915	1	Completed	July 2, 2021, 11:35 AM	August 31, 2021, 12:00 AM	Repair water main		V-025GV008	Valve Condition	
WO-39008	85	Completed	March 15, 2021, 9:39 AM	March 25, 2021, 12:00 AM	Repair water main	March 25, 2021, 6:46 PM	V-025GV009	Valve Condition	
WO-34565	41	Completed	January 26, 2021, 10:22 AM	January 27, 2021, 12:00 AM	Contractor shut request	January 27, 2021, 10:40 AM	V-025GV026	Valve Condition	
WO-34565	41	Completed	January 26, 2021, 10:22 AM	January 27, 2021, 12:00 AM	Contractor shut request	January 27, 2021, 10:40 AM	V-025GV027	Valve Condition	
WO-60312	85	Completed	October 12, 2021, 6:35 AM	October 13, 2021, 12:00 AM	Repair water main		V-025GV029	Valve Condition	
WO-60313	1	Completed	October 12, 2021, 6:35 AM	October 14, 2021, 12:00 AM	Repair water main	October 14, 2021, 9:21 AM	V-025GV039	Valve Condition	
WO-56866	1	Completed	September 8, 2021, 8:09 AM	August 31, 2021, 12:00 AM	Valve Maintenance Report	September 8, 2021, 8:13 AM	V-025GV045	Valve Condition	
WO-32180	1	Completed	December 31, 2020, 12:08 PM	January 8, 2021, 12:00 AM	Valve Maintenance Report	January 8, 2021, 2:49 PM	V-025GV049	Valve Condition	
WO-60313	1	Completed	October 12, 2021, 6:35 AM	October 14, 2021, 12:00 AM	Repair water main	October 14, 2021, 9:21 AM	V-025GV068	Valve Condition	
WO-38833	1	Completed	March 12, 2021, 7:32 AM	August 30, 2021, 12:00 AM	Repair water main		V-025JV012	Valve Condition	
WO-39155	41	Completed	March 16, 2021, 10:16 AM	March 16, 2021, 12:00 AM	Contractor shut request	March 16, 2021, 2:26 PM	V-025JV013	Valve Condition	
WO-56523	41	Completed	September 2, 2021, 11:40 AM	September 3, 2021, 12:00 AM	Contractor shut request	September 3, 2021, 10:15 AM	V-025JV023	Valve Condition	
WO-56523	41	Completed	September 2, 2021, 11:40 AM	September 3, 2021, 12:00 AM	Contractor shut request	September 3, 2021, 10:15 AM	V-025JV029	Valve Condition	
WO-63081	1	Completed	November 8, 2021, 1:32 PM	November 8, 2021, 12:00 AM	Valve Maintenance Report	November 8, 2021, 2:18 PM	V-025JV031	Valve Condition	
WO-50092	41	Completed	June 25, 2021, 8:20 AM	June 25, 2021, 12:00 AM	Contractor shut request	June 25, 2021, 1:09 PM	V-025JV032	Valve Condition	Fair
WO-56523	41	Completed	September 2, 2021, 11:40 AM	September 3, 2021, 12:00 AM	Contractor shut request	September 3, 2021, 10:15 AM	V-025JV037	Valve Condition	
WO-56523	41	Completed	September 2, 2021, 11:40 AM	September 3, 2021, 12:00 AM	Contractor shut request	September 3, 2021, 10:15 AM	V-025JV044	Valve Condition	
WO-50092	41	Completed	June 25, 2021, 8:20 AM	June 25, 2021, 12:00 AM	Contractor shut request	June 25, 2021, 1:09 PM	V-025JV053	Valve Condition	Fair
WO-38833	1	Completed	March 12, 2021, 7:32 AM	August 30, 2021, 12:00 AM	Repair water main		V-025KV004	Valve Condition	
WO-66484	1	Completed	December 22, 2021, 10:20 AM	December 22, 2021, 12:00 AM	Valve Maintenance Report	December 22, 2021, 1:50 PM	V-025KV021	Valve Condition	
WO-34565	41	Completed	January 26, 2021, 10:22 AM	January 27, 2021, 12:00 AM	Contractor shut request	January 27, 2021, 10:40 AM	V-025KV028	Valve Condition	
WO-34565	41	Completed	January 26, 2021, 10:22 AM	January 27, 2021, 12:00 AM	Contractor shut request	January 27, 2021, 10:40 AM	V-025KV030	Valve Condition	
WO-34565	41	Completed	January 26, 2021, 10:22 AM	January 27, 2021, 12:00 AM	Contractor shut request	January 27, 2021, 10:40 AM	V-025KV031	Valve Condition	
WO-60312	85	Completed	October 12, 2021, 6:35 AM	October 13, 2021, 12:00 AM	Repair water main		V-025KV053	Valve Condition	
WO-60312	85	Completed	October 12, 2021, 6:35 AM	October 13, 2021, 12:00 AM	Repair water main		V-025KV055	Valve Condition	
WO-38833	1	Completed	March 12, 2021, 7:32 AM	August 30, 2021, 12:00 AM	Repair water main		V-025KV061	Valve Condition	
WO-60312	85	Completed	October 12, 2021, 6:35 AM	October 13, 2021, 12:00 AM	Repair water main		V-025KV063	Valve Condition	
WO-60313	1	Completed	October 12, 2021, 6:35 AM	October 14, 2021, 12:00 AM	Repair water main	October 14, 2021, 9:21 AM	V-025LV001	Valve Condition	
WO-60312	85	Completed	October 12, 2021, 6:35 AM	October 13, 2021, 12:00 AM	Repair water main		V-025LV012	Valve Condition	
WO-57531	1	Completed	September 15, 2021, 11:31 AM	October 13, 2021, 12:00 AM	Valve Maintenance Report	October 13, 2021, 7:20 AM	V-025MV032	Valve Condition	Poor
WO-35673	1	Completed	February 4, 2021, 1:49 PM	February 4, 2021, 12:00 AM	Valve Maintenance Report	February 4, 2021, 1:57 PM	V-025MV034	Valve Condition	Fair
WO-58686	1	Completed	September 27, 2021, 7:52 AM	September 28, 2021, 12:00 AM	Valve Maintenance Report	September 28, 2021, 1:49 PM	V-025MV039	Valve Condition	
WO-58686	1	Completed	September 27, 2021, 7:52 AM	September 28, 2021, 12:00 AM	Valve Maintenance Report	September 28, 2021, 1:49 PM	V-025MV042	Valve Condition	
WO-57227	1	Completed	September 13, 2021, 7:26 AM	September 14, 2021, 12:00 AM	Repair water main		V-025NV030	Valve Condition	Good
WO-57227	1	Completed	September 13, 2021, 7:26 AM	September 14, 2021, 12:00 AM	Repair water main		V-025NV031	Valve Condition	Good
WO-57227	1	Completed	September 13, 2021, 7:26 AM	September 14, 2021, 12:00 AM	Repair water main		V-025NV032	Valve Condition	Good
WO-57226	85	Completed	September 13, 2021, 7:26 AM	September 13, 2021, 12:00 AM	Repair water main	September 14, 2021, 9:43 AM	V-025NV062	Valve Condition	Good
WO-57227	1	Completed	September 13, 2021, 7:26 AM	September 14, 2021, 12:00 AM	Repair water main		V-025NV063	Valve Condition	Good
WO-57227	1	Completed	September 13, 2021, 7:26 AM	September 14, 2021, 12:00 AM	Repair water main		V-025NV065	Valve Condition	Good
WO-66774	1	Completed	December 29, 2021, 12:54 PM	December 29, 2021, 12:00 AM	Valve Maintenance Report	December 29, 2021, 12:58 PM	V-025NV079	Valve Condition	
WO-42015	1	Completed	April 19, 2021, 9:38 AM	May 12, 2021, 12:00 AM	Valve Maintenance Report, liberty ave	May 12, 2021, 2:21 PM	V-025NV081	Valve Condition	
WO-42015	1	Completed	April 19, 2021, 9:38 AM	May 12, 2021, 12:00 AM	Valve Maintenance Report, liberty ave	May 12, 2021, 2:21 PM	V-025NV083	Valve Condition	
WO-42015	1	Completed	April 19, 2021, 9:38 AM	May 12, 2021, 12:00 AM	Valve Maintenance Report, liberty ave	May 12, 2021, 2:21 PM	V-025NV085	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-42015	1	Completed	April 19, 2021, 9:38 AM	May 12, 2021, 12:00 AM	Valve Maintenance Report, liberty ave	May 12, 2021, 2:21 PM	V-025PV009	Valve Condition	
WO-42015	1	Completed	April 19, 2021, 9:38 AM	May 12, 2021, 12:00 AM	Valve Maintenance Report, liberty ave	May 12, 2021, 2:21 PM	V-025PV010	Valve Condition	
WO-42015	1	Completed	April 19, 2021, 9:38 AM	May 12, 2021, 12:00 AM	Valve Maintenance Report, liberty ave	May 12, 2021, 2:21 PM	V-025PV011	Valve Condition	
WO-34889	21	Completed	January 28, 2021, 11:57 AM	January 28, 2021, 12:00 AM	Valve is inoperable and requires replacement	January 28, 2021, 12:01 PM	V-025PV014	Valve Condition	
WO-42015	1	Completed	April 19, 2021, 9:38 AM	May 12, 2021, 12:00 AM	Valve Maintenance Report, liberty ave	May 12, 2021, 2:21 PM	V-025PV015	Valve Condition	
WO-34860	41	Completed	January 28, 2021, 10:15 AM	February 5, 2021, 12:00 AM	Contractor shut request Buncher bld	February 5, 2021, 2:04 PM	V-025PV018	Valve Condition	
WO-36471	85	Completed	February 12, 2021, 2:42 PM	February 12, 2021, 12:00 AM	Repair water main	February 12, 2021, 11:04 PM	V-025PV026	Valve Condition	
WO-36472	1	Completed	February 12, 2021, 2:42 PM	February 12, 2021, 2:42 PM	Repair water main	February 12, 2021, 11:20 PM	V-025PV027	Valve Condition	Fair
WO-57529	1	Completed	September 15, 2021, 11:25 AM	September 15, 2021, 12:00 AM	Valve Maintenance Report	September 15, 2021, 12:20 PM	V-025RV009	Valve Condition	
WO-53642	1	Completed	August 3, 2021, 10:48 AM	September 1, 2021, 12:00 AM	Repair water main		V-025RV010	Valve Condition	Fair
WO-36354	41	Completed	February 12, 2021, 5:37 AM	February 24, 2021, 12:00 AM	Contractor shut request		V-025SV001	Valve Condition	Poor
WO-36354	41	Completed	February 12, 2021, 5:37 AM	February 24, 2021, 12:00 AM	Contractor shut request		V-025SV002	Valve Condition	
WO-57529	1	Completed	September 15, 2021, 11:25 AM	September 15, 2021, 12:00 AM	Valve Maintenance Report	September 15, 2021, 12:20 PM	V-025SV005	Valve Condition	Fair
WO-57529	1	Completed	September 15, 2021, 11:25 AM	September 15, 2021, 12:00 AM	Valve Maintenance Report	September 15, 2021, 12:20 PM	V-025SV006	Valve Condition	
WO-35808	563	Completed	February 5, 2021, 9:35 AM	February 10, 2021, 12:00 AM	Water main repair given to contractor	February 10, 2021, 1:25 PM	V-025SV008	Valve Condition	
WO-52590	84	Completed	July 20, 2021, 3:20 PM	July 20, 2021, 12:00 AM	Main or service line leak investigation/survey/PER CUSTOMER JUSTRODE BY INTERSECTING STREETS WATER LEAK IN MIDDLE OF STREET AND STREET IS BUCKLING A LITTLE WATER COMING FROM UNDERNEATH POLES ON STREET GOOD AMOUNTOF WATER CALLER IS NOT HOME COULD GIVE ANY INFO IF HE HAD WATER AT HIS HOME OR PRESSURE NO OTHER PHONE CALLS AT THIS TIME	July 20, 2021, 10:40 PM	V-025SV011	Valve Condition	Good
WO-49645	1	Completed	June 22, 2021, 10:58 AM	October 21, 2021, 12:00 AM	Repair water main		V-025SV013	Valve Condition	
WO-44693	21	Completed	May 13, 2021, 12:11 PM	June 8, 2021, 12:00 AM	Valve requires replacement	June 8, 2021, 1:00 PM	V-025SV015	Valve Condition	
WO-47828	1	Completed	June 8, 2021, 9:29 AM	June 22, 2021, 12:00 AM	Valve Maintenance Report	June 22, 2021, 8:10 AM	V-026AV003	Valve Condition	Good
WO-47828	1	Completed	June 8, 2021, 9:29 AM	June 22, 2021, 12:00 AM	Valve Maintenance Report	June 22, 2021, 8:10 AM	V-026AV007	Valve Condition	Good
WO-47828	1	Completed	June 8, 2021, 9:29 AM	June 22, 2021, 12:00 AM	Valve Maintenance Report	June 22, 2021, 8:10 AM	V-026AV008	Valve Condition	Good
WO-47828	1	Completed	June 8, 2021, 9:29 AM	June 22, 2021, 12:00 AM	Valve Maintenance Report	June 22, 2021, 8:10 AM	V-026AV011	Valve Condition	Good
WO-47828	1	Completed	June 8, 2021, 9:29 AM	June 22, 2021, 12:00 AM	Valve Maintenance Report	June 22, 2021, 8:10 AM	V-026AV012	Valve Condition	Good
WO-50277	1	Completed	June 28, 2021, 8:39 AM	June 29, 2021, 12:00 AM	Valve Maintenance Report	June 29, 2021, 8:20 AM	V-026AV016	Valve Condition	
WO-50277	1	Completed	June 28, 2021, 8:39 AM	June 29, 2021, 12:00 AM	Valve Maintenance Report	June 29, 2021, 8:20 AM	V-026AV017	Valve Condition	
WO-47828	1	Completed	June 8, 2021, 9:29 AM	June 22, 2021, 12:00 AM	Valve Maintenance Report	June 22, 2021, 8:10 AM	V-026AV026	Valve Condition	Good
WO-47828	1	Completed	June 8, 2021, 9:29 AM	June 22, 2021, 12:00 AM	Valve Maintenance Report	June 22, 2021, 8:10 AM	V-026AV027	Valve Condition	Good
WO-47828	1	Completed	June 8, 2021, 9:29 AM	June 22, 2021, 12:00 AM	Valve Maintenance Report	June 22, 2021, 8:10 AM	V-026AV028	Valve Condition	Good
WO-50277	1	Completed	44375.36071	44376	Valve Maintenance Report	June 29, 2021, 8:20 AM	V-026AV029	Valve Condition	
WO-46598	1	Completed	44344.27458	44348	Repair water main		V-026BV002	Valve Condition	Good
WO-46598	1	Completed	44344.27458	44348	Repair water main		V-026BV003	Valve Condition	Good
WO-55343	1	Completed	44428.54564	44433	Valve Maintenance Report	August 25, 2021, 7:22 AM	V-026BV004	Valve Condition	Fair
WO-55343	1	Completed	44428.54564	44433	Valve Maintenance Report	August 25, 2021, 7:22 AM	V-026BV005	Valve Condition	Fair
WO-55343	1	Completed	44428.54564	44433	Valve Maintenance Report	August 25, 2021, 7:22 AM	V-026BV006	Valve Condition	Fair
WO-55343	1	Completed	44428.54564	44433	Valve Maintenance Report	August 25, 2021, 7:22 AM	V-026BV008	Valve Condition	Fair
WO-55343	1	Completed	44428.54564	44433	Valve Maintenance Report	August 25, 2021, 7:22 AM	V-026BV009	Valve Condition	Fair
WO-55343	1	Completed	44428.54564	44433	Valve Maintenance Report	August 25, 2021, 7:22 AM	V-026BV010	Valve Condition	Fair
WO-55343	1	Completed	44428.54564	44433	Valve Maintenance Report	August 25, 2021, 7:22 AM	V-026BV012	Valve Condition	Fair
WO-55343	1	Completed	44428.54564	44433	Valve Maintenance Report	August 25, 2021, 7:22 AM	V-026BV013	Valve Condition	Fair
WO-55343	1	Completed	44428.54564	44433	Valve Maintenance Report	August 25, 2021, 7:22 AM	V-026BV016	Valve Condition	Fair
WO-55343	1	Completed	44428.54564	44433	Valve Maintenance Report	August 25, 2021, 7:22 AM	V-026BV018	Valve Condition	
WO-55343	1	Completed	44428.54564	44433	Valve Maintenance Report	August 25, 2021, 7:22 AM	V-026BV020	Valve Condition	Fair
WO-64193	1	Completed	44523.2973	44522	Valve Maintenance Report		V-026BV023	Valve Condition	
WO-50375	1	Completed	44375.57156	44378	Valve Maintenance Report	July 1, 2021, 8:48 AM	V-026BV024	Valve Condition	Fair
WO-50880	1	Completed	44379.35058	44383	Valve Maintenance Report	July 6, 2021, 7:24 AM	V-026CV001	Valve Condition	
WO-50880	1	Completed	44379.35058	44383	Valve Maintenance Report	July 6, 2021, 7:24 AM	V-026CV002	Valve Condition	
WO-50880	1	Completed	44379.35058	44383	Valve Maintenance Report	July 6, 2021, 7:24 AM	V-026CV003	Valve Condition	
WO-50880	1	Completed	44379.35058	44383	Valve Maintenance Report	July 6, 2021, 7:24 AM	V-026CV006	Valve Condition	
WO-50880	1	Completed	44379.35058	44383	Valve Maintenance Report	July 6, 2021, 7:24 AM	V-026CV007	Valve Condition	
WO-50880	1	Completed	44379.35058	44383	Valve Maintenance Report	July 6, 2021, 7:24 AM	V-026CV009	Valve Condition	
WO-49620	1	Completed	44369.3608	44369	Valve Maintenance Report	June 22, 2021, 8:42 AM	V-026CV010	Valve Condition	
WO-49622	1	Completed	44369.36369	44369	Valve Maintenance Report	June 22, 2021, 8:46 AM	V-026CV011	Valve Condition	
WO-48199	41	Completed	44358.31627	44358	Contractor shut request	June 11, 2021, 10:47 AM	V-026CV012	Valve Condition	Good
WO-50880	1	Completed	44379.35058	44383	Valve Maintenance Report	July 6, 2021, 7:24 AM	V-026CV015	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV002	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV003	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV005	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV008	Valve Condition	
WO-38196	401	Completed	44259.57643	44259	Dividing Pressure Valve Maintenance Report	March 4, 2021, 1:52 PM	V-026DV009	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV010	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV011	Valve Condition	
WO-48199	41	Completed	44358.31627	44358	Contractor shut request	June 11, 2021, 10:47 AM	V-026DV014	Valve Condition	Good
WO-48199	41	Completed	44358.31627	44358	Contractor shut request	June 11, 2021, 10:47 AM	V-026DV015	Valve Condition	Good
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV017	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV018	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV019	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV020	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV021	Valve Condition	
WO-38200	401	Completed	44259.59452	44259	Dividing Pressure Valve Maintenance Report	March 4, 2021, 2:18 PM	V-026DV023	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV026	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV027	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV028	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV030	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV035	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV037	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV038	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV039	Valve Condition	
WO-37837	401	Completed	44257.07643	44257	Dividing Pressure Valve Maintenance Report	March 2, 2021, 1:52 AM	V-026DV040	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV041	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV042	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV043	Valve Condition	
WO-38669	401	Completed	44265.48668	44265	Dividing Pressure Valve Maintenance Report	March 10, 2021, 11:43 AM	V-026DV044	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV046	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV047	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV048	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV049	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV050	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV051	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV052	Valve Condition	
WO-38198	401	Completed	44259.58442	44259	Dividing Pressure Valve Maintenance Report	March 4, 2021, 2:04 PM	V-026DV053	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV054	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV055	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV056	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV057	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV058	Valve Condition	
WO-51118	1	Completed	44383.35221	44390	Valve Maintenance Report	July 13, 2021, 2:11 PM	V-026DV059	Valve Condition	
WO-52226	1	Completed	44393.39183	44427	Valve Maintenance Report	August 19, 2021, 8:37 AM	V-026EV001	Valve Condition	
WO-52226	1	Completed	44393.39183	44427	Valve Maintenance Report	August 19, 2021, 8:37 AM	V-026EV003	Valve Condition	
WO-52226	1	Completed	44393.39183	44427	Valve Maintenance Report	August 19, 2021, 8:37 AM	V-026EV004	Valve Condition	
WO-52226	1	Completed	44393.39183	44427	Valve Maintenance Report	August 19, 2021, 8:37 AM	V-026EV006	Valve Condition	
WO-52226	1	Completed	44393.39183	44427	Valve Maintenance Report	August 19, 2021, 8:37 AM	V-026EV009	Valve Condition	
WO-52226	1	Completed	44393.39183	44427	Valve Maintenance Report	August 19, 2021, 8:37 AM	V-026EV010	Valve Condition	
WO-52226	1	Completed	44393.39183	44427	Valve Maintenance Report	August 19, 2021, 8:37 AM	V-026EV011	Valve Condition	
WO-52226	1	Completed	44393.39183	44427	Valve Maintenance Report	August 19, 2021, 8:37 AM	V-026EV012	Valve Condition	
WO-52226	1	Completed	44393.39183	44427	Valve Maintenance Report	August 19, 2021, 8:37 AM	V-026EV013	Valve Condition	
WO-52226	1	Completed	44393.39183	44427	Valve Maintenance Report	August 19, 2021, 8:37 AM	V-026EV014	Valve Condition	
WO-52226	1	Completed	44393.39183	44427	Valve Maintenance Report	August 19, 2021, 8:37 AM	V-026EV015	Valve Condition	
WO-52226	1	Completed	44393.39183	44427	Valve Maintenance Report	August 19, 2021, 8:37 AM	V-026EV016	Valve Condition	
WO-52226	1	Completed	44393.39183	44427	Valve Maintenance Report	August 19, 2021, 8:37 AM	V-026EV020	Valve Condition	
WO-52226	1	Completed	44393.39183	44427	Valve Maintenance Report	August 19, 2021, 8:37 AM	V-026EV021	Valve Condition	
WO-52226	1	Completed	44393.39183	44427	Valve Maintenance Report	August 19, 2021, 8:37 AM	V-026EV022	Valve Condition	
WO-52226	1	Completed	44393.39183	44427	Valve Maintenance Report	August 19, 2021, 8:37 AM	V-026EV023	Valve Condition	
WO-52226	1	Completed	44393.39183	44427	Valve Maintenance Report	August 19, 2021, 8:37 AM	V-026EV024	Valve Condition	
WO-52226	1	Completed	44393.39183	44427	Valve Maintenance Report	August 19, 2021, 8:37 AM	V-026EV025	Valve Condition	
WO-52226	1	Completed	44393.39183	44427	Valve Maintenance Report	August 19, 2021, 8:37 AM	V-026EV026	Valve Condition	
WO-52226	1	Completed	44393.39183	44427	Valve Maintenance Report	August 19, 2021, 8:37 AM	V-026EV027	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-52226	1	Completed	44393.39183	44427	Valve Maintenance Report	August 19, 2021, 8:37 AM	V-026EV029	Valve Condition	
WO-52226	1	Completed	44393.39183	44427	Valve Maintenance Report	August 19, 2021, 8:37 AM	V-026EV033	Valve Condition	
WO-52226	1	Completed	44393.39183	44427	Valve Maintenance Report	August 19, 2021, 8:37 AM	V-026EV034	Valve Condition	
WO-52226	1	Completed	44393.39183	44427	Valve Maintenance Report	August 19, 2021, 8:37 AM	V-026EV036	Valve Condition	
WO-36049	21	Completed	44235.62111	44258	Valve locate or expose	March 3, 2021, 9:34 PM	V-026FV001	Valve Condition	
WO-55842	1	Completed	44435.34907	44441	Valve Maintenance Report	September 2, 2021, 3:34 PM	V-026FV002	Valve Condition	
WO-55842	1	Completed	44435.34907	44441	Valve Maintenance Report	September 2, 2021, 3:34 PM	V-026FV003	Valve Condition	
WO-55842	1	Completed	44435.34907	44441	Valve Maintenance Report	September 2, 2021, 3:34 PM	V-026FV004	Valve Condition	
WO-55842	1	Completed	44435.34907	44441	Valve Maintenance Report	September 2, 2021, 3:34 PM	V-026FV005	Valve Condition	
WO-55842	1	Completed	44435.34907	44441	Valve Maintenance Report	September 2, 2021, 3:34 PM	V-026FV006	Valve Condition	
WO-55842	1	Completed	44435.34907	44441	Valve Maintenance Report	September 2, 2021, 3:34 PM	V-026FV007	Valve Condition	
WO-36009	1	Completed	44235.43203	44236	Valve Maintenance Report	February 9, 2021, 6:47 AM	V-026FV008	Valve Condition	
WO-36009	1	Completed	44235.43203	44236	Valve Maintenance Report	February 9, 2021, 6:47 AM	V-026FV009	Valve Condition	
WO-36009	1	Completed	44235.43203	44236	Valve Maintenance Report	February 9, 2021, 6:47 AM	V-026FV010	Valve Condition	
WO-36009	1	Completed	44235.43203	44236	Valve Maintenance Report	February 9, 2021, 6:47 AM	V-026FV011	Valve Condition	
WO-36009	1	Completed	44235.43203	44236	Valve Maintenance Report	February 9, 2021, 6:47 AM	V-026FV012	Valve Condition	
WO-55842	1	Completed	44435.34907	44441	Valve Maintenance Report	September 2, 2021, 3:34 PM	V-026FV013	Valve Condition	
WO-55842	1	Completed	44435.34907	44441	Valve Maintenance Report	September 2, 2021, 3:34 PM	V-026FV014	Valve Condition	
WO-55842	1	Completed	44435.34907	44441	Valve Maintenance Report	September 2, 2021, 3:34 PM	V-026FV015	Valve Condition	
WO-55842	1	Completed	44435.34907	44441	Valve Maintenance Report	September 2, 2021, 3:34 PM	V-026FV019	Valve Condition	
WO-55842	1	Completed	44435.34907	44441	Valve Maintenance Report	September 2, 2021, 3:34 PM	V-026FV020	Valve Condition	
WO-55842	1	Completed	44435.34907	44441	Valve Maintenance Report	September 2, 2021, 3:34 PM	V-026FV021	Valve Condition	
WO-55842	1	Completed	44435.34907	44441	Valve Maintenance Report	September 2, 2021, 3:34 PM	V-026FV022	Valve Condition	
WO-55842	1	Completed	44435.34907	44441	Valve Maintenance Report	September 2, 2021, 3:34 PM	V-026FV025	Valve Condition	
WO-38813	1	Completed	44267.06239	44438	Repair water main		V-026FV026	Valve Condition	
WO-55842	1	Completed	44435.34907	44441	Valve Maintenance Report	September 2, 2021, 3:34 PM	V-026FV027	Valve Condition	
WO-55842	1	Completed	44435.34907	44441	Valve Maintenance Report	September 2, 2021, 3:34 PM	V-026FV028	Valve Condition	
WO-55842	1	Completed	44435.34907	44441	Valve Maintenance Report	September 2, 2021, 3:34 PM	V-026FV029	Valve Condition	
WO-55842	1	Completed	44435.34907	44441	Valve Maintenance Report	September 2, 2021, 3:34 PM	V-026FV030	Valve Condition	
WO-55842	1	Completed	44435.34907	44441	Valve Maintenance Report	September 2, 2021, 3:34 PM	V-026FV031	Valve Condition	
WO-55842	1	Completed	44435.34907	44441	Valve Maintenance Report	September 2, 2021, 3:34 PM	V-026FV033	Valve Condition	
WO-56641	1	Completed	44442.48069	44446	Valve Maintenance Report	September 7, 2021, 1:57 PM	V-026GV001	Valve Condition	
WO-32847	1	Completed	44204.36373	44204	Valve Maintenance Report	January 8, 2021, 8:47 AM	V-026GV003	Valve Condition	
WO-56641	1	Completed	44442.48069	44446	Valve Maintenance Report	September 7, 2021, 1:57 PM	V-026GV004	Valve Condition	
WO-56641	1	Completed	44442.48069	44446	Valve Maintenance Report	September 7, 2021, 1:57 PM	V-026GV005	Valve Condition	
WO-56641	1	Completed	44442.48069	44446	Valve Maintenance Report	September 7, 2021, 1:57 PM	V-026GV008	Valve Condition	
WO-56641	1	Completed	44442.48069	44446	Valve Maintenance Report	September 7, 2021, 1:57 PM	V-026GV010	Valve Condition	
WO-56641	1	Completed	44442.48069	44446	Valve Maintenance Report	September 7, 2021, 1:57 PM	V-026GV011	Valve Condition	
WO-56641	1	Completed	44442.48069	44446	Valve Maintenance Report	September 7, 2021, 1:57 PM	V-026GV012	Valve Condition	
WO-56641	1	Completed	44442.48069	44446	Valve Maintenance Report	September 7, 2021, 1:57 PM	V-026GV014	Valve Condition	
WO-56641	1	Completed	44442.48069	44446	Valve Maintenance Report	September 7, 2021, 1:57 PM	V-026GV015	Valve Condition	
WO-56641	1	Completed	44442.48069	44446	Valve Maintenance Report	September 7, 2021, 1:57 PM	V-026GV016	Valve Condition	
WO-56641	1	Completed	44442.48069	44446	Valve Maintenance Report	September 7, 2021, 1:57 PM	V-026GV017	Valve Condition	
WO-56641	1	Completed	44442.48069	44446	Valve Maintenance Report	September 7, 2021, 1:57 PM	V-026GV021	Valve Condition	
WO-56641	1	Completed	44442.48069	44446	Valve Maintenance Report	September 7, 2021, 1:57 PM	V-026GV022	Valve Condition	
WO-56641	1	Completed	44442.48069	44446	Valve Maintenance Report	September 7, 2021, 1:57 PM	V-026GV025	Valve Condition	
WO-56641	1	Completed	44442.48069	44446	Valve Maintenance Report	September 7, 2021, 1:57 PM	V-026GV026	Valve Condition	
WO-56641	1	Completed	44442.48069	44446	Valve Maintenance Report	September 7, 2021, 1:57 PM	V-026GV027	Valve Condition	
WO-56780	1	Completed	44446.52303	44460	Valve Maintenance Report	September 21, 2021, 9:00 AM	V-026HV001	Valve Condition	
WO-56780	1	Completed	44446.52303	44460	Valve Maintenance Report	September 21, 2021, 9:00 AM	V-026HV003	Valve Condition	
WO-56780	1	Completed	44446.52303	44460	Valve Maintenance Report	September 21, 2021, 9:00 AM	V-026HV004	Valve Condition	
WO-56780	1	Completed	44446.52303	44460	Valve Maintenance Report	September 21, 2021, 9:00 AM	V-026HV006	Valve Condition	
WO-56780	1	Completed	44446.52303	44460	Valve Maintenance Report	September 21, 2021, 9:00 AM	V-026HV007	Valve Condition	
WO-56780	1	Completed	44446.52303	44460	Valve Maintenance Report	September 21, 2021, 9:00 AM	V-026HV009	Valve Condition	
WO-56780	1	Completed	44446.52303	44460	Valve Maintenance Report	September 21, 2021, 9:00 AM	V-026HV010	Valve Condition	Good
WO-56780	1	Completed	44446.52303	44460	Valve Maintenance Report	September 21, 2021, 9:00 AM	V-026HV012	Valve Condition	Good
WO-56780	1	Completed	44446.52303	44460	Valve Maintenance Report	September 21, 2021, 9:00 AM	V-026HV013	Valve Condition	
WO-56780	1	Completed	44446.52303	44460	Valve Maintenance Report	September 21, 2021, 9:00 AM	V-026HV015	Valve Condition	
WO-56780	1	Completed	44446.52303	44460	Valve Maintenance Report	September 21, 2021, 9:00 AM	V-026HV016	Valve Condition	
WO-56780	1	Completed	44446.52303	44460	Valve Maintenance Report	September 21, 2021, 9:00 AM	V-026HV017	Valve Condition	
WO-56780	1	Completed	44446.52303	44460	Valve Maintenance Report	September 21, 2021, 9:00 AM	V-026HV018	Valve Condition	
WO-62971	1	Completed	44508.36331	44505	Valve Maintenance Report		V-026HV019	Valve Condition	
WO-56780	1	Completed	44446.52303	44460	Valve Maintenance Report	September 21, 2021, 9:00 AM	V-026HV020	Valve Condition	
WO-56780	1	Completed	44446.52303	44460	Valve Maintenance Report	September 21, 2021, 9:00 AM	V-026HV022	Valve Condition	
WO-56780	1	Completed	44446.52303	44460	Valve Maintenance Report	September 21, 2021, 9:00 AM	V-026HV023	Valve Condition	
WO-56780	1	Completed	44446.52303	44460	Valve Maintenance Report	September 21, 2021, 9:00 AM	V-026HV024	Valve Condition	
WO-56780	1	Completed	44446.52303	44460	Valve Maintenance Report	September 21, 2021, 9:00 AM	V-026HV025	Valve Condition	
WO-56780	1	Completed	44446.52303	44460	Valve Maintenance Report	September 21, 2021, 9:00 AM	V-026HV026	Valve Condition	
WO-56780	1	Completed	44446.52303	44460	Valve Maintenance Report	September 21, 2021, 9:00 AM	V-026HV027	Valve Condition	Good
WO-56780	1	Completed	44446.52303	44460	Valve Maintenance Report	September 21, 2021, 9:00 AM	V-026HV028	Valve Condition	
WO-56780	1	Completed	44446.52303	44460	Valve Maintenance Report	September 21, 2021, 9:00 AM	V-026HV029	Valve Condition	
WO-58457	1	Completed	44462.54549	44466	Valve Maintenance Report	September 27, 2021, 5:45 AM	V-026JV001	Valve Condition	
WO-58457	1	Completed	44462.54549	44466	Valve Maintenance Report	September 27, 2021, 5:45 AM	V-026JV003	Valve Condition	
WO-58457	1	Completed	44462.54549	44466	Valve Maintenance Report	September 27, 2021, 5:45 AM	V-026JV004	Valve Condition	
WO-58686	1	Completed	44466.32805	44467	Valve Maintenance Report	September 28, 2021, 1:49 PM	V-026JV007	Valve Condition	
WO-58686	1	Completed	44466.32805	44467	Valve Maintenance Report	September 28, 2021, 1:49 PM	V-026JV009	Valve Condition	
WO-58686	1	Completed	44466.32805	44467	Valve Maintenance Report	September 28, 2021, 1:49 PM	V-026JV010	Valve Condition	
WO-64013	41	Completed	44520.4427	44520	Contractor shut request	November 20, 2021, 4:01 PM	V-026JV012	Valve Condition	
WO-58686	1	Completed	44466.32805	44467	Valve Maintenance Report	September 28, 2021, 1:49 PM	V-026JV013	Valve Condition	
WO-58686	1	Completed	44466.32805	44467	Valve Maintenance Report	September 28, 2021, 1:49 PM	V-026JV015	Valve Condition	
WO-58686	1	Completed	44466.32805	44467	Valve Maintenance Report	September 28, 2021, 1:49 PM	V-026JV016	Valve Condition	
WO-33248	84	Completed	44208.67219	44209	Main or service line leak investigation/survey LEAK IN STREET -- PER GEORGE B	January 13, 2021, 10:32 AM	V-026JV018	Valve Condition	
WO-58686	1	Completed	44466.32805	44467	Valve Maintenance Report	September 28, 2021, 1:49 PM	V-026JV019	Valve Condition	
WO-56986	1	Completed	44448.38045	44461	Valve Maintenance Report	September 22, 2021, 7:27 AM	V-026JV020	Valve Condition	
WO-56986	1	Completed	44448.38045	44461	Valve Maintenance Report	September 22, 2021, 7:27 AM	V-026JV021	Valve Condition	
WO-38813	1	Completed	44267.06239	44438	Repair water main		V-026JV022	Valve Condition	
WO-58686	1	Completed	44466.32805	44467	Valve Maintenance Report	September 28, 2021, 1:49 PM	V-026JV023	Valve Condition	
WO-58686	1	Completed	44466.32805	44467	Valve Maintenance Report	September 28, 2021, 1:49 PM	V-026JV024	Valve Condition	
WO-53669	1	Completed	44411.5543	44411	Valve Maintenance Report	August 3, 2021, 1:23 PM	V-026JV029	Valve Condition	
WO-35161	88	Completed	44227.23424	44227	Repair service line	January 31, 2021, 5:40 AM	V-026JV031	Valve Condition	Good
WO-35161	88	Completed	44227.23424	44227	Repair service line	January 31, 2021, 5:40 AM	V-026JV032	Valve Condition	
WO-56986	1	Completed	44448.38045	44461	Valve Maintenance Report	September 22, 2021, 7:27 AM	V-026JV033	Valve Condition	
WO-56986	1	Completed	44448.38045	44461	Valve Maintenance Report	September 22, 2021, 7:27 AM	V-026JV034	Valve Condition	
WO-56986	1	Completed	44448.38045	44461	Valve Maintenance Report	September 22, 2021, 7:27 AM	V-026JV036	Valve Condition	
WO-56986	1	Completed	44448.38045	44461	Valve Maintenance Report	September 22, 2021, 7:27 AM	V-026JV037	Valve Condition	
WO-56986	1	Completed	44448.38045	44461	Valve Maintenance Report	September 22, 2021, 7:27 AM	V-026JV039	Valve Condition	
WO-56986	1	Completed	44448.38045	44461	Valve Maintenance Report	September 22, 2021, 7:27 AM	V-026JV040	Valve Condition	
WO-56986	1	Completed	44448.38045	44461	Valve Maintenance Report	September 22, 2021, 7:27 AM	V-026JV041	Valve Condition	
WO-56986	1	Completed	44448.38045	44461	Valve Maintenance Report	September 22, 2021, 7:27 AM	V-026JV042	Valve Condition	
WO-58457	1	Completed	44462.54549	44466	Valve Maintenance Report	September 27, 2021, 5:45 AM	V-026JV044	Valve Condition	
WO-58686	1	Completed	44466.32805	44467	Valve Maintenance Report	September 28, 2021, 1:49 PM	V-026JV046	Valve Condition	
WO-58686	1	Completed	44466.32805	44467	Valve Maintenance Report	September 28, 2021, 1:49 PM	V-026JV047	Valve Condition	
WO-59147	1	Completed	44469.48035	44470	Valve Maintenance Report	October 1, 2021, 2:39 PM	V-026KV003	Valve Condition	
WO-59147	1	Completed	44469.48035	44470	Valve Maintenance Report	October 1, 2021, 2:39 PM	V-026KV004	Valve Condition	
WO-59147	1	Completed	44469.48035	44470	Valve Maintenance Report	October 1, 2021, 2:39 PM	V-026KV006	Valve Condition	
WO-59147	1	Completed	44469.48035	44470	Valve Maintenance Report	October 1, 2021, 2:39 PM	V-026KV007	Valve Condition	
WO-59147	1	Completed	44469.48035	44470	Valve Maintenance Report	October 1, 2021, 2:39 PM	V-026KV008	Valve Condition	
WO-59147	1	Completed	44469.48035	44470	Valve Maintenance Report	October 1, 2021, 2:39 PM	V-026KV009	Valve Condition	
WO-59147	1	Completed	44469.48035	44470	Valve Maintenance Report	October 1, 2021, 2:39 PM	V-026KV010	Valve Condition	
WO-59147	1	Completed	44469.48035	44470	Valve Maintenance Report	October 1, 2021, 2:39 PM	V-026KV011	Valve Condition	
WO-59147	1	Completed	44469.48035	44470	Valve Maintenance Report	October 1, 2021, 2:39 PM	V-026KV012	Valve Condition	
WO-60260	1	Completed	44480.53794	44484	Valve Maintenance Report	October 15, 2021, 2:26 PM	V-026KV014	Valve Condition	
WO-60260	1	Completed	44480.53794	44484	Valve Maintenance Report	October 15, 2021, 2:26 PM	V-026KV017	Valve Condition	
WO-60260	1	Completed	44480.53794	44484	Valve Maintenance Report	October 15, 2021, 2:26 PM	V-026KV018	Valve Condition	
WO-60260	1	Completed	44480.53794	44484	Valve Maintenance Report	October 15, 2021, 2:26 PM	V-026KV019	Valve Condition	
WO-60260	1	Completed	44480.53794	44484	Valve Maintenance Report	October 15, 2021, 2:26 PM	V-026KV020	Valve Condition	
WO-60260	1	Completed	44480.53794	44484	Valve Maintenance Report	October 15, 2021, 2:26 PM	V-026KV021	Valve Condition	
WO-60260	1	Completed	44480.53794	44484	Valve Maintenance Report	October 15, 2021, 2:26 PM	V-026KV022	Valve Condition	
WO-60260	1	Completed	44480.53794	44484	Valve Maintenance Report	October 15, 2021, 2:26 PM	V-026KV023	Valve Condition	
WO-59147	1	Completed	44469.48035	44470	Valve Maintenance Report	October 1, 2021, 2:39 PM	V-026KV027	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-60771	1	Completed	44484.41778	44484	Valve Maintenance Report	October 15, 2021, 2:34 PM	V-026LV002	Valve Condition	
WO-60771	1	Completed	44484.41778	44484	Valve Maintenance Report	October 15, 2021, 2:34 PM	V-026LV003	Valve Condition	
WO-60771	1	Completed	44484.41778	44484	Valve Maintenance Report	October 15, 2021, 2:34 PM	V-026LV004	Valve Condition	
WO-60771	1	Completed	44484.41778	44484	Valve Maintenance Report	October 15, 2021, 2:34 PM	V-026LV006	Valve Condition	
WO-60771	1	Completed	44484.41778	44484	Valve Maintenance Report	October 15, 2021, 2:34 PM	V-026LV008	Valve Condition	
WO-60960	1	Completed	44487.56097	44494	Valve Maintenance Report	October 25, 2021, 7:35 AM	V-026LV009	Valve Condition	
WO-61045	1	Completed	44488.35019	44494	Valve Maintenance Report	October 25, 2021, 7:35 AM	V-026LV010	Valve Condition	
WO-61045	1	Completed	44488.35019	44494	Valve Maintenance Report	October 25, 2021, 7:35 AM	V-026LV011	Valve Condition	
WO-61045	1	Completed	44488.35019	44494	Valve Maintenance Report	October 25, 2021, 7:35 AM	V-026LV012	Valve Condition	
WO-60960	1	Completed	44487.56097	44494	Valve Maintenance Report	October 25, 2021, 7:35 AM	V-026LV013	Valve Condition	
WO-60960	1	Completed	44487.56097	44494	Valve Maintenance Report	October 25, 2021, 7:35 AM	V-026LV015	Valve Condition	
WO-60960	1	Completed	44487.56097	44494	Valve Maintenance Report	October 25, 2021, 7:35 AM	V-026LV016	Valve Condition	
WO-61045	1	Completed	44488.35019	44494	Valve Maintenance Report	October 25, 2021, 7:35 AM	V-026LV017	Valve Condition	
WO-61045	1	Completed	44488.35019	44494	Valve Maintenance Report	October 25, 2021, 7:35 AM	V-026LV018	Valve Condition	
WO-60771	1	Completed	44484.41778	44484	Valve Maintenance Report	October 15, 2021, 2:34 PM	V-026LV020	Valve Condition	
WO-60771	1	Completed	44484.41778	44484	Valve Maintenance Report	October 15, 2021, 2:34 PM	V-026LV021	Valve Condition	
WO-60771	1	Completed	44484.41778	44484	Valve Maintenance Report	October 15, 2021, 2:34 PM	V-026LV022	Valve Condition	
WO-60771	1	Completed	44484.41778	44484	Valve Maintenance Report	October 15, 2021, 2:34 PM	V-026LV023	Valve Condition	
WO-60771	1	Completed	44484.41778	44484	Valve Maintenance Report	October 15, 2021, 2:34 PM	V-026LV024	Valve Condition	
WO-45929	1	Completed	44340.48523	44340	Valve Maintenance Report	May 24, 2021, 11:47 AM	V-026LV026	Valve Condition	Good
WO-60771	1	Completed	44484.41778	44484	Valve Maintenance Report	October 15, 2021, 2:34 PM	V-026LV027	Valve Condition	
WO-61077	1	Completed	44488.42985	44494	Valve Maintenance Report	October 25, 2021, 7:35 AM	V-026MV001	Valve Condition	Good
WO-61077	1	Completed	44488.42985	44494	Valve Maintenance Report	October 25, 2021, 7:35 AM	V-026MV009	Valve Condition	Good
WO-61077	1	Completed	44488.42985	44494	Valve Maintenance Report	October 25, 2021, 7:35 AM	V-026MV010	Valve Condition	Good
WO-61077	1	Completed	44488.42985	44494	Valve Maintenance Report	October 25, 2021, 7:35 AM	V-026MV011	Valve Condition	Good
WO-53670	1	Completed	44411.55953	44411	Valve Maintenance Report	August 3, 2021, 1:28 PM	V-026NV001	Valve Condition	
WO-61088	1	Completed	44488.4617	44494	Valve Maintenance Report	October 25, 2021, 7:35 AM	V-026NV002	Valve Condition	
WO-60960	1	Completed	44487.56097	44494	Valve Maintenance Report	October 25, 2021, 7:35 AM	V-026NV005	Valve Condition	
WO-60960	1	Completed	44487.56097	44494	Valve Maintenance Report	October 25, 2021, 7:35 AM	V-026NV007	Valve Condition	
WO-61708	1	Completed	44495.53011	44498	Valve Maintenance Report	October 29, 2021, 2:58 PM	V-026NV009	Valve Condition	
WO-47827	1	Completed	44355.39359	44362	Valve Maintenance Report	June 15, 2021, 1:37 PM	V-026NV010	Valve Condition	Good
WO-34431	41	Completed	44221.35879	44221	Contractor shut request	January 25, 2021, 2:27 PM	V-026NV011	Valve Condition	
WO-61708	1	Completed	44495.53011	44498	Valve Maintenance Report	October 29, 2021, 2:58 PM	V-026NV012	Valve Condition	
WO-60960	1	Completed	44487.56097	44494	Valve Maintenance Report	October 25, 2021, 7:35 AM	V-026NV013	Valve Condition	
WO-60960	1	Completed	44487.56097	44494	Valve Maintenance Report	October 25, 2021, 7:35 AM	V-026NV014	Valve Condition	
WO-61708	1	Completed	44495.53011	44498	Valve Maintenance Report	October 29, 2021, 2:58 PM	V-026NV015	Valve Condition	
WO-61708	1	Completed	44495.53011	44498	Valve Maintenance Report	October 29, 2021, 2:58 PM	V-026NV016	Valve Condition	
WO-61708	1	Completed	44495.53011	44498	Valve Maintenance Report	October 29, 2021, 2:58 PM	V-026NV019	Valve Condition	
WO-61708	1	Completed	44495.53011	44498	Valve Maintenance Report	October 29, 2021, 2:58 PM	V-026NV020	Valve Condition	
WO-62048	1	Completed	44498.46557	44505		November 5, 2021, 3:00 PM	V-026PV001	Valve Condition	
WO-62048	1	Completed	44498.46557	44505		November 5, 2021, 3:00 PM	V-026PV002	Valve Condition	
WO-62048	1	Completed	44498.46557	44505		November 5, 2021, 3:00 PM	V-026PV003	Valve Condition	
WO-62048	1	Completed	44498.46557	44505		November 5, 2021, 3:00 PM	V-026PV004	Valve Condition	
WO-62048	1	Completed	44498.46557	44505		November 5, 2021, 3:00 PM	V-026PV006	Valve Condition	
WO-62048	1	Completed	44498.46557	44505		November 5, 2021, 3:00 PM	V-026PV007	Valve Condition	
WO-62048	1	Completed	44498.46557	44505		November 5, 2021, 3:00 PM	V-026PV008	Valve Condition	
WO-62048	1	Completed	44498.46557	44505		November 5, 2021, 3:00 PM	V-026PV009	Valve Condition	
WO-62048	1	Completed	44498.46557	44505		November 5, 2021, 3:00 PM	V-026PV010	Valve Condition	
WO-62048	1	Completed	44498.46557	44505		November 5, 2021, 3:00 PM	V-026PV032	Valve Condition	
WO-62048	1	Completed	44498.46557	44505		November 5, 2021, 3:00 PM	V-026PV034	Valve Condition	
WO-62048	1	Completed	44498.46557	44505		November 5, 2021, 3:00 PM	V-026PV035	Valve Condition	
WO-62048	1	Completed	44498.46557	44505		November 5, 2021, 3:00 PM	V-026PV036	Valve Condition	
WO-62048	1	Completed	44498.46557	44505		November 5, 2021, 3:00 PM	V-026PV037	Valve Condition	
WO-62048	1	Completed	44498.46557	44505		November 5, 2021, 3:00 PM	V-026PV038	Valve Condition	
WO-62048	1	Completed	44498.46557	44505		November 5, 2021, 3:00 PM	V-026PV039	Valve Condition	
WO-62048	1	Completed	44498.46557	44505		November 5, 2021, 3:00 PM	V-026PV040	Valve Condition	
WO-62048	1	Completed	44498.46557	44505		November 5, 2021, 3:00 PM	V-026PV041	Valve Condition	
WO-62048	1	Completed	44498.46557	44505		November 5, 2021, 3:00 PM	V-026PV042	Valve Condition	
WO-62048	1	Completed	44498.46557	44505		November 5, 2021, 3:00 PM	V-026PV043	Valve Condition	
WO-62048	1	Completed	44498.46557	44505		November 5, 2021, 3:00 PM	V-026PV045	Valve Condition	
WO-62048	1	Completed	44498.46557	44505		November 5, 2021, 3:00 PM	V-026PV047	Valve Condition	
WO-62048	1	Completed	44498.46557	44505		November 5, 2021, 3:00 PM	V-026PV048	Valve Condition	
WO-55780	1	Completed	44434.55448	44434	Valve Maintenance Report	August 26, 2021, 1:22 PM	V-026PV052	Valve Condition	
WO-62048	1	Completed	44498.46557	44505		November 5, 2021, 3:00 PM	V-026PV062	Valve Condition	
WO-55782	1	Completed	44434.55808	44434	Valve Maintenance Report	August 26, 2021, 1:26 PM	V-026PV068	Valve Condition	
WO-62799	1	Completed	44505.37942	44505	Valve Maintenance Report	November 5, 2021, 3:01 PM	V-026RV001	Valve Condition	
WO-62799	1	Completed	44505.37942	44505	Valve Maintenance Report	November 5, 2021, 3:01 PM	V-026RV002	Valve Condition	
WO-63192	1	Completed	44509.43197	44512	Valve Maintenance Report	November 12, 2021, 2:51 PM	V-026RV005	Valve Condition	
WO-63192	1	Completed	44509.43197	44512	Valve Maintenance Report	November 12, 2021, 2:51 PM	V-026RV029	Valve Condition	
WO-63192	1	Completed	44509.43197	44512	Valve Maintenance Report	November 12, 2021, 2:51 PM	V-026RV030	Valve Condition	
WO-63192	1	Completed	44509.43197	44512	Valve Maintenance Report	November 12, 2021, 2:51 PM	V-026RV031	Valve Condition	
WO-63192	1	Completed	44509.43197	44512	Valve Maintenance Report	November 12, 2021, 2:51 PM	V-026RV032	Valve Condition	
WO-62799	1	Completed	44505.37942	44505	Valve Maintenance Report	November 5, 2021, 3:01 PM	V-026RV035	Valve Condition	
WO-62799	1	Completed	44505.37942	44505	Valve Maintenance Report	November 5, 2021, 3:01 PM	V-026RV036	Valve Condition	
WO-62799	1	Completed	44505.37942	44505	Valve Maintenance Report	November 5, 2021, 3:01 PM	V-026RV037	Valve Condition	
WO-62799	1	Completed	44505.37942	44505	Valve Maintenance Report	November 5, 2021, 3:01 PM	V-026RV038	Valve Condition	
WO-63192	1	Completed	44509.43197	44512	Valve Maintenance Report	November 12, 2021, 2:51 PM	V-026RV039	Valve Condition	
WO-63192	1	Completed	44509.43197	44512	Valve Maintenance Report	November 12, 2021, 2:51 PM	V-026RV040	Valve Condition	
WO-62799	1	Completed	44505.37942	44505	Valve Maintenance Report	November 5, 2021, 3:01 PM	V-026RV070	Valve Condition	
WO-63192	1	Completed	44509.43197	44512	Valve Maintenance Report	November 12, 2021, 2:51 PM	V-026RV071	Valve Condition	
WO-63344	1	Completed	44510.46613	44512	Valve Maintenance Report	November 12, 2021, 2:52 PM	V-026SV004	Valve Condition	
WO-63344	1	Completed	44510.46613	44512	Valve Maintenance Report	November 12, 2021, 2:52 PM	V-026SV009	Valve Condition	
WO-63344	1	Completed	44510.46613	44512	Valve Maintenance Report	November 12, 2021, 2:52 PM	V-026SV010	Valve Condition	
WO-63344	1	Completed	44510.46613	44512	Valve Maintenance Report	November 12, 2021, 2:52 PM	V-026SV011	Valve Condition	
WO-63344	1	Completed	44510.46613	44512	Valve Maintenance Report	November 12, 2021, 2:52 PM	V-026SV012	Valve Condition	
WO-63344	1	Completed	44510.46613	44512	Valve Maintenance Report	November 12, 2021, 2:52 PM	V-026SV013	Valve Condition	
WO-63344	1	Completed	44510.46613	44512	Valve Maintenance Report	November 12, 2021, 2:52 PM	V-026SV020	Valve Condition	
WO-63420	1	Completed	44512.41542	44512	Valve Maintenance Report	November 12, 2021, 2:51 PM	V-027AV001	Valve Condition	Good
WO-63420	1	Completed	44512.41542	44512	Valve Maintenance Report	November 12, 2021, 2:51 PM	V-027AV002	Valve Condition	Good
WO-63420	1	Completed	44512.41542	44512	Valve Maintenance Report	November 12, 2021, 2:51 PM	V-027AV003	Valve Condition	Good
WO-63420	1	Completed	44512.41542	44512	Valve Maintenance Report	November 12, 2021, 2:51 PM	V-027AV004	Valve Condition	Good
WO-63520	1	Completed	44515.38895	44522	Valve Maintenance Report	November 22, 2021, 7:24 AM	V-027AV006	Valve Condition	
WO-63420	1	Completed	44512.41542	44512	Valve Maintenance Report	November 12, 2021, 2:51 PM	V-027AV009	Valve Condition	Good
WO-63420	1	Completed	44512.41542	44512	Valve Maintenance Report	November 12, 2021, 2:51 PM	V-027AV010	Valve Condition	Good
WO-35073	85	Completed	44225.57848	44225	Repair water main	January 29, 2021, 9:41 PM	V-027AV012	Valve Condition	
WO-63520	1	Completed	44515.38895	44522	Valve Maintenance Report	November 22, 2021, 7:24 AM	V-027AV013	Valve Condition	
WO-63520	1	Completed	44515.38895	44522	Valve Maintenance Report	November 22, 2021, 7:24 AM	V-027AV014	Valve Condition	
WO-63420	1	Completed	44512.41542	44512	Valve Maintenance Report	November 12, 2021, 2:51 PM	V-027AV015	Valve Condition	Good
WO-63420	1	Completed	44512.41542	44512	Valve Maintenance Report	November 12, 2021, 2:51 PM	V-027AV016	Valve Condition	Good
WO-63420	1	Completed	44512.41542	44512	Valve Maintenance Report	November 12, 2021, 2:51 PM	V-027AV018	Valve Condition	Good
WO-63420	1	Completed	44512.41542	44512	Valve Maintenance Report	November 12, 2021, 2:51 PM	V-027AV019	Valve Condition	Good
WO-63420	1	Completed	44512.41542	44512	Valve Maintenance Report	November 12, 2021, 2:51 PM	V-027AV020	Valve Condition	Good
WO-63420	1	Completed	44512.41542	44512	Valve Maintenance Report	November 12, 2021, 2:51 PM	V-027AV021	Valve Condition	Good
WO-33896	85	Completed	44215.5094	44216	Repair water main	January 20, 2021, 6:38 AM	V-027AV022	Valve Condition	
WO-63520	1	Completed	44515.38895	44522	Valve Maintenance Report	November 22, 2021, 7:24 AM	V-027AV023	Valve Condition	
WO-63520	1	Completed	44515.38895	44522	Valve Maintenance Report	November 22, 2021, 7:24 AM	V-027AV026	Valve Condition	
WO-35073	85	Completed	44225.57848	44225	Repair water main	January 29, 2021, 9:41 PM	V-027BV002	Valve Condition	Fair
WO-35073	85	Completed	44225.57848	44225	Repair water main	January 29, 2021, 9:41 PM	V-027BV003	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV004	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV006	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV007	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV008	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV009	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV011	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV012	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV013	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV015	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV016	Valve Condition	Fair
WO-33896	85	Completed	44215.5094	44216	Repair water main	January 20, 2021, 6:38 AM	V-027BV018	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV019	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV020	Valve Condition	Fair

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV021	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV023	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV024	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV026	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV027	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV028	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV029	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV030	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV031	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV032	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV034	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV035	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV036	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV037	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV038	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV039	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV040	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV042	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV043	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV045	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV046	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV047	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV048	Valve Condition	Fair
WO-63529	1	Completed	44515.43448	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027BV050	Valve Condition	Fair
WO-63747	1	Completed	44517.46476	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027CV002	Valve Condition	
WO-63747	1	Completed	44517.46476	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027CV003	Valve Condition	
WO-63747	1	Completed	44517.46476	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027CV004	Valve Condition	
WO-63747	1	Completed	44517.46476	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027CV005	Valve Condition	
WO-63747	1	Completed	44517.46476	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027CV007	Valve Condition	
WO-63747	1	Completed	44517.46476	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027CV008	Valve Condition	
WO-46920	1	Completed	44349.2263	44350	Repair water main-6"		V-027CV009	Valve Condition	
WO-63747	1	Completed	44517.46476	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027CV011	Valve Condition	
WO-63747	1	Completed	44517.46476	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027CV012	Valve Condition	
WO-63747	1	Completed	44517.46476	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027CV013	Valve Condition	
WO-63747	1	Completed	44517.46476	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027CV014	Valve Condition	
WO-63747	1	Completed	44517.46476	44522	Valve Maintenance Report	November 22, 2021, 7:25 AM	V-027CV015	Valve Condition	
WO-64051	1	Completed	44522.3389	44525	Valve Maintenance Report	November 29, 2021, 7:20 AM	V-027CV019	Valve Condition	
WO-64051	1	Completed	44522.3389	44525	Valve Maintenance Report	November 29, 2021, 7:20 AM	V-027CV020	Valve Condition	
WO-64051	1	Completed	44522.3389	44525	Valve Maintenance Report	November 29, 2021, 7:20 AM	V-027CV021	Valve Condition	
WO-64051	1	Completed	44522.3389	44525	Valve Maintenance Report	November 29, 2021, 7:20 AM	V-027CV024	Valve Condition	
WO-64051	1	Completed	44522.3389	44525	Valve Maintenance Report	November 29, 2021, 7:20 AM	V-027CV025	Valve Condition	
WO-64051	1	Completed	44522.3389	44525	Valve Maintenance Report	November 29, 2021, 7:20 AM	V-027CV027	Valve Condition	
WO-64051	1	Completed	44522.3389	44525	Valve Maintenance Report	November 29, 2021, 7:20 AM	V-027CV030	Valve Condition	
WO-64051	1	Completed	44522.3389	44525	Valve Maintenance Report	November 29, 2021, 7:20 AM	V-027CV031	Valve Condition	
WO-64051	1	Completed	44522.3389	44525	Valve Maintenance Report	November 29, 2021, 7:20 AM	V-027CV032	Valve Condition	
WO-64051	1	Completed	44522.3389	44525	Valve Maintenance Report	November 29, 2021, 7:20 AM	V-027CV033	Valve Condition	
WO-64051	1	Completed	44522.3389	44525	Valve Maintenance Report	November 29, 2021, 7:20 AM	V-027CV034	Valve Condition	
WO-64051	1	Completed	44522.3389	44525	Valve Maintenance Report	November 29, 2021, 7:20 AM	V-027CV037	Valve Condition	
WO-64051	1	Completed	44522.3389	44525	Valve Maintenance Report	November 29, 2021, 7:20 AM	V-027CV038	Valve Condition	
WO-64218	1	Completed	44523.37812	44525	Valve Maintenance Report	November 29, 2021, 7:23 AM	V-027DV008	Valve Condition	
WO-64218	1	Completed	44523.37812	44525	Valve Maintenance Report	November 29, 2021, 7:23 AM	V-027DV018	Valve Condition	
WO-64218	1	Completed	44523.37812	44525	Valve Maintenance Report	November 29, 2021, 7:23 AM	V-027DV019	Valve Condition	
WO-64218	1	Completed	44523.37812	44525	Valve Maintenance Report	November 29, 2021, 7:23 AM	V-027DV024	Valve Condition	
WO-64218	1	Completed	44523.37812	44525	Valve Maintenance Report	November 29, 2021, 7:23 AM	V-027DV025	Valve Condition	
WO-64218	1	Completed	44523.37812	44525	Valve Maintenance Report	November 29, 2021, 7:23 AM	V-027DV026	Valve Condition	
WO-64218	1	Completed	44523.37812	44525	Valve Maintenance Report	November 29, 2021, 7:23 AM	V-027DV027	Valve Condition	
WO-59039	1	Completed	44468.48873	44468	Valve Maintenance Report	September 29, 2021, 7:10 PM	V-027DV030	Valve Condition	
WO-64218	1	Completed	44523.37812	44525	Valve Maintenance Report	November 29, 2021, 7:23 AM	V-027DV034	Valve Condition	
WO-41548	84	Completed	44299.70589	44300	Main or service line leak investigation/survey/PER CALLER MAJOR WATER LEAK WATER POURING IN MIDDLE OF STREET NEAR A ELECTRICAL VAULT LINE NEED WATER SHUT IMMEDIATELY	April 14, 2021, 6:24 AM	V-027DV035	Valve Condition	
WO-55935	1	Completed	44436.65894	44437	Valve Maintenance Report	August 29, 2021, 4:36 PM	V-027DV039	Valve Condition	
WO-55932	84	Completed	44436.10634	44436	Main or service line leak investigation/survey. CONTRACTORS FOUND 6IN MAIN LEAKING	August 28, 2021, 7:10 AM	V-027DV040	Valve Condition	
WO-64218	1	Completed	44523.37812	44525	Valve Maintenance Report	November 29, 2021, 7:23 AM	V-027DV052	Valve Condition	
WO-64218	1	Completed	44523.37812	44525	Valve Maintenance Report	November 29, 2021, 7:23 AM	V-027DV053	Valve Condition	
WO-64518	1	Completed	44529.37472	44533	Valve Maintenance Report	December 3, 2021, 3:10 PM	V-027EV003	Valve Condition	
WO-64518	1	Completed	44529.37472	44533	Valve Maintenance Report	December 3, 2021, 3:10 PM	V-027EV004	Valve Condition	
WO-64518	1	Completed	44529.37472	44533	Valve Maintenance Report	December 3, 2021, 3:10 PM	V-027EV005	Valve Condition	
WO-53479	1	Completed	44410.36239	44411	Valve Maintenance Report	August 3, 2021, 10:37 AM	V-027EV006	Valve Condition	
WO-53479	1	Completed	44410.36239	44411	Valve Maintenance Report	August 3, 2021, 10:37 AM	V-027EV007	Valve Condition	
WO-64518	1	Completed	44529.37472	44533	Valve Maintenance Report	December 3, 2021, 3:10 PM	V-027EV010	Valve Condition	
WO-64518	1	Completed	44529.37472	44533	Valve Maintenance Report	December 3, 2021, 3:10 PM	V-027EV012	Valve Condition	
WO-64518	1	Completed	44529.37472	44533	Valve Maintenance Report	December 3, 2021, 3:10 PM	V-027EV013	Valve Condition	
WO-64518	1	Completed	44529.37472	44533	Valve Maintenance Report	December 3, 2021, 3:10 PM	V-027EV014	Valve Condition	
WO-64518	1	Completed	44529.37472	44533	Valve Maintenance Report	December 3, 2021, 3:10 PM	V-027EV017	Valve Condition	
WO-64518	1	Completed	44529.37472	44533	Valve Maintenance Report	December 3, 2021, 3:10 PM	V-027EV018	Valve Condition	
WO-54020	1	Completed	44414.3338	44439	Valve Maintenance Report		V-027EV019	Valve Condition	
WO-64650	1	Completed	44530.51683	44540	Valve Maintenance Report	December 10, 2021, 12:01 PM	V-027FV002	Valve Condition	
WO-64650	1	Completed	44530.51683	44540	Valve Maintenance Report	December 10, 2021, 12:01 PM	V-027FV003	Valve Condition	
WO-66054	1	Completed	44545.71358	44545	Repair water main	December 15, 2021, 10:19 PM	V-027FV004	Valve Condition	
WO-56985	21	Completed	44448.38065	44448	Valve requires replacement	September 9, 2021, 9:11 AM	V-027FV006	Valve Condition	
WO-64650	1	Completed	44530.51683	44540	Valve Maintenance Report	December 10, 2021, 12:01 PM	V-027FV008	Valve Condition	
WO-64650	1	Completed	44530.51683	44540	Valve Maintenance Report	December 10, 2021, 12:01 PM	V-027FV009	Valve Condition	
WO-64650	1	Completed	44530.51683	44540	Valve Maintenance Report	December 10, 2021, 12:01 PM	V-027FV010	Valve Condition	
WO-64650	1	Completed	44530.51683	44540	Valve Maintenance Report	December 10, 2021, 12:01 PM	V-027FV011	Valve Condition	
WO-64650	1	Completed	44530.51683	44540	Valve Maintenance Report	December 10, 2021, 12:01 PM	V-027FV013	Valve Condition	
WO-64650	1	Completed	44530.51683	44540	Valve Maintenance Report	December 10, 2021, 12:01 PM	V-027FV014	Valve Condition	
WO-64650	1	Completed	44530.51683	44540	Valve Maintenance Report	December 10, 2021, 12:01 PM	V-027FV015	Valve Condition	
WO-64650	1	Completed	44530.51683	44540	Valve Maintenance Report	December 10, 2021, 12:01 PM	V-027FV017	Valve Condition	
WO-56983	1	Completed	44448.3738	44448	Valve Maintenance Report	September 9, 2021, 9:12 AM	V-027FV019	Valve Condition	
WO-64650	1	Completed	44530.51683	44540	Valve Maintenance Report	December 10, 2021, 12:01 PM	V-027FV020	Valve Condition	
WO-64650	1	Completed	44530.51683	44540	Valve Maintenance Report	December 10, 2021, 12:01 PM	V-027FV021	Valve Condition	
WO-64650	1	Completed	44530.51683	44540	Valve Maintenance Report	December 10, 2021, 12:01 PM	V-027FV022	Valve Condition	
WO-65224	1	Completed	44537.38646	44540	Valve Maintenance Report	December 10, 2021, 12:04 PM	V-027GV001	Valve Condition	
WO-65224	1	Completed	44537.38646	44540	Valve Maintenance Report	December 10, 2021, 12:04 PM	V-027GV002	Valve Condition	
WO-65224	1	Completed	44537.38646	44540	Valve Maintenance Report	December 10, 2021, 12:04 PM	V-027GV006	Valve Condition	
WO-65224	1	Completed	44537.38646	44540	Valve Maintenance Report	December 10, 2021, 12:04 PM	V-027GV008	Valve Condition	
WO-65224	1	Completed	44537.38646	44540	Valve Maintenance Report	December 10, 2021, 12:04 PM	V-027GV009	Valve Condition	
WO-65224	1	Completed	44537.38646	44540	Valve Maintenance Report	December 10, 2021, 12:04 PM	V-027GV010	Valve Condition	
WO-65224	1	Completed	44537.38646	44540	Valve Maintenance Report	December 10, 2021, 12:04 PM	V-027GV011	Valve Condition	
WO-65224	1	Completed	44537.38646	44540	Valve Maintenance Report	December 10, 2021, 12:04 PM	V-027GV012	Valve Condition	
WO-65224	1	Completed	44537.38646	44540	Valve Maintenance Report	December 10, 2021, 12:04 PM	V-027GV014	Valve Condition	
WO-65224	1	Completed	44537.38646	44540	Valve Maintenance Report	December 10, 2021, 12:04 PM	V-027GV015	Valve Condition	
WO-65224	1	Completed	44537.38646	44540	Valve Maintenance Report	December 10, 2021, 12:04 PM	V-027GV016	Valve Condition	
WO-65224	1	Completed	44537.38646	44540	Valve Maintenance Report	December 10, 2021, 12:04 PM	V-027GV017	Valve Condition	
WO-65224	1	Completed	44537.38646	44540	Valve Maintenance Report	December 10, 2021, 12:04 PM	V-027GV018	Valve Condition	
WO-65224	1	Completed	44537.38646	44540	Valve Maintenance Report	December 10, 2021, 12:04 PM	V-027GV019	Valve Condition	
WO-65224	1	Completed	44537.38646	44540	Valve Maintenance Report	December 10, 2021, 12:04 PM	V-027GV020	Valve Condition	
WO-65224	1	Completed	44537.38646	44540	Valve Maintenance Report	December 10, 2021, 12:04 PM	V-027GV021	Valve Condition	
WO-65224	1	Completed	44537.38646	44540	Valve Maintenance Report	December 10, 2021, 12:04 PM	V-027GV022	Valve Condition	
WO-65224	1	Completed	44537.38646	44540	Valve Maintenance Report	December 10, 2021, 12:04 PM	V-027GV024	Valve Condition	
WO-65224	1	Completed	44537.38646	44540	Valve Maintenance Report	December 10, 2021, 12:04 PM	V-027GV025	Valve Condition	
WO-65224	1	Completed	44537.38646	44540	Valve Maintenance Report	December 10, 2021, 12:04 PM	V-027GV027	Valve Condition	
WO-65224	1	Completed	44537.38646	44540	Valve Maintenance Report	December 10, 2021, 12:04 PM	V-027GV030	Valve Condition	
WO-59039	1	Completed	44468.48873	44468	Valve Maintenance Report	September 29, 2021, 7:10 PM	V-027HV007	Valve Condition	
WO-65582	1	Completed	44540.41464	44553	Valve Maintenance Report	December 23, 2021, 10:38 AM	V-027HV013	Valve Condition	
WO-65582	1	Completed	44540.41464	44553	Valve Maintenance Report	December 23, 2021, 10:38 AM	V-027HV014	Valve Condition	
WO-65582	1	Completed	44540.41464	44553	Valve Maintenance Report	December 23, 2021, 10:38 AM	V-027HV017	Valve Condition	
WO-65582	1	Completed	44540.41464	44553	Valve Maintenance Report	December 23, 2021, 10:38 AM	V-027HV019	Valve Condition	
WO-65582	1	Completed	44540.41464	44553	Valve Maintenance Report	December 23, 2021, 10:38 AM	V-027HV021	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-65582	1	Completed	44540.41464	44553	Valve Maintenance Report	December 23, 2021, 10:38 AM	V-027HV022	Valve Condition	
WO-61106	1	Completed	44488.54857	44502	Repair water main		V-027HV023	Valve Condition	
WO-65582	1	Completed	44540.41464	44553	Valve Maintenance Report	December 23, 2021, 10:38 AM	V-027HV024	Valve Condition	
WO-58955	1	Completed	44468.09621	44469	Repair water main		V-027HV025	Valve Condition	
WO-65582	1	Completed	44540.41464	44553	Valve Maintenance Report	December 23, 2021, 10:38 AM	V-027HV027	Valve Condition	
WO-65582	1	Completed	44540.41464	44553	Valve Maintenance Report	December 23, 2021, 10:38 AM	V-027HV028	Valve Condition	
WO-65582	1	Completed	44540.41464	44553	Valve Maintenance Report	December 23, 2021, 10:38 AM	V-027HV029	Valve Condition	
WO-65582	1	Completed	44540.41464	44553	Valve Maintenance Report	December 23, 2021, 10:38 AM	V-027HV030	Valve Condition	
WO-65582	1	Completed	44540.41464	44553	Valve Maintenance Report	December 23, 2021, 10:38 AM	V-027HV031	Valve Condition	
WO-41548	84	Completed	44299.70589	44300	Main or service line leak investigation/survey/PER CALLER MAJOR WATER LEAK WATER POURING IN MIDDLE OF STREET NEAR A ELECTRICAL VAULT LINE NEED WATER SHUT IMMEDIATELY	April 14, 2021, 6:24 AM	V-027HV033	Valve Condition	
WO-65582	1	Completed	44540.41464	44553	Valve Maintenance Report	December 23, 2021, 10:38 AM	V-027HV034	Valve Condition	
WO-65582	1	Completed	44540.41464	44553	Valve Maintenance Report	December 23, 2021, 10:38 AM	V-027HV036	Valve Condition	
WO-65582	1	Completed	44540.41464	44553	Valve Maintenance Report	December 23, 2021, 10:38 AM	V-027HV043	Valve Condition	
WO-65582	1	Completed	44540.41464	44553	Valve Maintenance Report	December 23, 2021, 10:38 AM	V-027HV049	Valve Condition	
WO-65582	1	Completed	44540.41464	44553	Valve Maintenance Report	December 23, 2021, 10:38 AM	V-027HV050	Valve Condition	
WO-65582	1	Completed	44540.41464	44553	Valve Maintenance Report	December 23, 2021, 10:38 AM	V-027HV053	Valve Condition	
WO-65582	1	Completed	44540.41464	44553	Valve Maintenance Report	December 23, 2021, 10:38 AM	V-027HV061	Valve Condition	
WO-65582	1	Completed	44540.41464	44553	Valve Maintenance Report	December 23, 2021, 10:38 AM	V-027HV062	Valve Condition	
WO-65582	1	Completed	44540.41464	44553	Valve Maintenance Report	December 23, 2021, 10:38 AM	V-027HV063	Valve Condition	
WO-65582	1	Completed	44540.41464	44553	Valve Maintenance Report	December 23, 2021, 10:38 AM	V-027HV064	Valve Condition	
WO-65582	1	Completed	44540.41464	44553	Valve Maintenance Report	December 23, 2021, 10:38 AM	V-027HV070	Valve Condition	
WO-53479	1	Completed	44410.36239	44411	Valve Maintenance Report	August 3, 2021, 10:37 AM	V-027KV010	Valve Condition	
WO-53479	1	Completed	44410.36239	44411	Valve Maintenance Report	August 3, 2021, 10:37 AM	V-027KV012	Valve Condition	
WO-62531	1	Completed	44504.13186	44505	Valve Maintenance Report		V-027LV002	Valve Condition	
WO-62531	1	Completed	44504.13186	44505	Valve Maintenance Report		V-027LV008	Valve Condition	
WO-62531	1	Completed	44504.13186	44505	Valve Maintenance Report		V-027LV016	Valve Condition	
WO-62531	1	Completed	44504.13186	44505	Valve Maintenance Report		V-027LV066	Valve Condition	
WO-62531	1	Completed	44504.13186	44505	Valve Maintenance Report		V-027LV067	Valve Condition	
WO-32692	84	Completed	44203.40142	44203	Main or service line leak investigation/survey	January 7, 2021, 2:16 PM	V-027LV070	Valve Condition	
WO-61106	1	Completed	44488.54857	44502	Repair water main		V-027MV033	Valve Condition	
WO-52771	1	Completed	44399.36636	44404	Valve Maintenance Report	July 27, 2021, 5:56 AM	V-027MV045	Valve Condition	Fair
WO-58955	1	Completed	44468.09621	44469	Repair water main		V-027MV047	Valve Condition	
WO-62986	85	Completed	44508.39644	44509	Repair water main		V-027MV050	Valve Condition	
WO-62988	1	Completed	44508.39644	44510	Repair water main		V-027MV059	Valve Condition	
WO-62908	85	Completed	44506.85133	44515	Repair water main		V-027MV082	Valve Condition	Good
WO-44016	41	Completed	44323.33192	44323	Contractor shut request	May 7, 2021, 2:58 PM	V-027PV025	Valve Condition	
WO-32692	84	Completed	44203.40142	44203	Main or service line leak investigation/survey	January 7, 2021, 2:16 PM	V-027PV032	Valve Condition	
WO-55124	1	Completed	44426.58083	44427	Valve Maintenance Report	August 19, 2021, 7:03 AM	V-027PV033	Valve Condition	
WO-55124	1	Completed	44426.58083	44427	Valve Maintenance Report	August 19, 2021, 7:03 AM	V-027PV034	Valve Condition	
WO-42900	1	Completed	44313.51916	44314	Valve Maintenance Report	April 28, 2021, 7:58 AM	V-027PV035	Valve Condition	Poor
WO-55124	1	Completed	44426.58083	44427	Valve Maintenance Report	August 19, 2021, 7:03 AM	V-027PV036	Valve Condition	
WO-55523	1	Completed	44432.27988	44432	Repair water main		V-027PV041	Valve Condition	
WO-66500	1	Completed	44552.46995	44552	Valve Maintenance Report	December 22, 2021, 1:45 PM	V-027PV050	Valve Condition	
WO-55124	1	Completed	44426.58083	44427	Valve Maintenance Report	August 19, 2021, 7:03 AM	V-027RV002	Valve Condition	
WO-55124	1	Completed	44426.58083	44427	Valve Maintenance Report	August 19, 2021, 7:03 AM	V-027RV003	Valve Condition	
WO-55124	1	Completed	44426.58083	44427	Valve Maintenance Report	August 19, 2021, 7:03 AM	V-027RV007	Valve Condition	
WO-55124	1	Completed	44426.58083	44427	Valve Maintenance Report	August 19, 2021, 7:03 AM	V-027RV008	Valve Condition	
WO-55124	1	Completed	44426.58083	44427	Valve Maintenance Report	August 19, 2021, 7:03 AM	V-027RV020	Valve Condition	
WO-32536	1	Completed	44202.40957	44218	Repair water main		V-027RV024	Valve Condition	
WO-32536	1	Completed	44202.40957	44218	Repair water main		V-027RV028	Valve Condition	
WO-55124	1	Completed	44426.58083	44427	Valve Maintenance Report	August 19, 2021, 7:03 AM	V-027RV044	Valve Condition	
WO-42900	1	Completed	44313.51916	44314	Valve Maintenance Report	April 28, 2021, 7:58 AM	V-027RV046	Valve Condition	Poor
WO-55124	1	Completed	44426.58083	44427	Valve Maintenance Report	August 19, 2021, 7:03 AM	V-027RV047	Valve Condition	
WO-55535	85	Completed	44432.39254	44432	Repair water main	August 24, 2021, 6:58 PM	V-027RV050	Valve Condition	
WO-56755	1	Completed	44446.39982	44438	Valve Maintenance Report	September 9, 2021, 10:17 AM	V-027SV005	Valve Condition	
WO-50020	41	Completed	44371.73377	44372	Contractor shut request	June 25, 2021, 12:05 PM	V-027SV020	Valve Condition	
WO-50020	41	Completed	44371.73377	44372	Contractor shut request	June 25, 2021, 12:05 PM	V-027SV021	Valve Condition	
WO-53443	43	Completed	44410.02156	44410	Test shut	August 2, 2021, 2:49 AM	V-027SV022	Valve Condition	
WO-60762	1	Completed	44484.39185	44484	Valve Maintenance Report	October 15, 2021, 9:44 AM	V-027SV023	Valve Condition	
WO-56755	1	Completed	44446.39982	44438	Valve Maintenance Report	September 9, 2021, 10:17 AM	V-027SV030	Valve Condition	
WO-52824	1	Completed	44399.55834	44412	Valve Maintenance Report	August 4, 2021, 7:26 AM	V-027SV032	Valve Condition	Fair
WO-50020	41	Completed	44371.73377	44372	Contractor shut request	June 25, 2021, 12:05 PM	V-027SV037	Valve Condition	
WO-56755	1	Completed	44446.39982	44438	Valve Maintenance Report	September 9, 2021, 10:17 AM	V-027SV038	Valve Condition	
WO-50020	41	Completed	44371.73377	44372	Contractor shut request	June 25, 2021, 12:05 PM	V-027SV041	Valve Condition	
WO-59635	1	Completed	44475.23516	44477	Repair water main		V-028BV011	Valve Condition	
WO-38715	88	Completed	44266.31416	44266	Repair service line	June 17, 2021, 12:08 PM	V-028BV014	Valve Condition	Poor
WO-59635	1	Completed	44475.23516	44477	Repair water main		V-028BV070	Valve Condition	
WO-59635	1	Completed	44475.23516	44477	Repair water main		V-028BV077	Valve Condition	
WO-56916	1	Completed	44447.50026	44447	Valve Maintenance Report	September 8, 2021, 12:11 PM	V-028BV129	Valve Condition	
WO-55523	1	Completed	44432.27988	44432	Repair water main		V-028CV003	Valve Condition	
WO-55523	1	Completed	44432.27988	44432	Repair water main		V-028CV046	Valve Condition	
WO-32653	85	Completed	44203.30707	44224	Repair water main	January 28, 2021, 5:32 PM	V-028FV003	Valve Condition	
WO-60364	1	Completed	44481.50685	44484	Valve Maintenance Report	October 15, 2021, 2:29 PM	V-028FV004	Valve Condition	
WO-61856	85	Completed	44497.26048	44503	Repair water main On Forbes Ave @ Coltart Street	November 5, 2021, 9:11 AM	V-028FV015	Valve Condition	
WO-61856	85	Completed	44497.26048	44503	Repair water main On Forbes Ave @ Coltart Street	November 5, 2021, 9:11 AM	V-028FV029	Valve Condition	
WO-60364	1	Completed	44481.50685	44484	Valve Maintenance Report	October 15, 2021, 2:29 PM	V-028FV032	Valve Condition	
WO-36663	85	Completed	44243.40774	44326	Repair water main This has nothing to do with the sink hole at bottom of the hill. NO PARKING NEEDS POSTED 1 call valid 2/19/21 NO WATER SURFACING The leak may be on the service line or on the main. FIRST... Dig up shifted curb box to role out waste water. If that's not the issue, then dig on the 6" main. This is not an emergency. View pictures below	May 10, 2021, 9:35 AM	V-028FV033	Valve Condition	
WO-61857	1	Completed	44497.26048	44504	Repair water main On Forbes Ave @ Coltart Street		V-028FV037	Valve Condition	
WO-35628	85	Completed	44231.35282	44231	Repair water main	February 4, 2021, 5:45 PM	V-028FV041	Valve Condition	
WO-60364	1	Completed	44481.50685	44484	Valve Maintenance Report	October 15, 2021, 2:29 PM	V-028FV066	Valve Condition	
WO-61856	85	Completed	44497.26048	44503	Repair water main On Forbes Ave @ Coltart Street	November 5, 2021, 9:11 AM	V-028FV068	Valve Condition	
WO-32653	85	Completed	44203.30707	44224	Repair water main	January 28, 2021, 5:32 PM	V-028GV005	Valve Condition	
WO-34831	1	Completed	44224.33946	44225	Valve Maintenance Report		V-028GV009	Valve Condition	
WO-40761	85	Completed	44289.62292	44289	Repair water main	April 3, 2021, 11:01 PM	V-028GV025	Valve Condition	
WO-34419	21	Completed	44221.32103	44221	Valve is inoperable and requires replacement	January 25, 2021, 3:36 PM	V-028HV001	Valve Condition	
WO-34429	85	Completed	44221.36015	44223	Repair water main	January 27, 2021, 12:12 PM	V-028HV006	Valve Condition	
WO-34429	85	Completed	44221.36015	44223	Repair water main	January 27, 2021, 12:12 PM	V-028HV043	Valve Condition	
WO-65222	43	Completed	44537.37874	44538	Test shut	December 8, 2021, 11:35 AM	V-028JV004	Valve Condition	Good
WO-32680	1	Completed	44203.35936	44208	Valve Maintenance Report	January 12, 2021, 11:42 AM	V-028JV007	Valve Condition	
WO-65222	43	Completed	44537.37874	44538	Test shut	December 8, 2021, 11:35 AM	V-028JV011	Valve Condition	Good
WO-45850	1	Completed	44340.35525	44340	Valve Maintenance Report	May 24, 2021, 8:33 AM	V-028JV012	Valve Condition	Good
WO-64410	1	Completed	44524.96088	44529	Repair water main		V-028JV029	Valve Condition	
WO-65943	1	Completed	44545.11894	44545	Repair water main		V-028JV030	Valve Condition	
WO-65943	1	Completed	44545.11894	44545	Repair water main		V-028JV052	Valve Condition	
WO-64410	1	Completed	44524.96088	44529	Repair water main		V-028JV054	Valve Condition	
WO-45053	1	Completed	44333.55191	44334	Valve Maintenance Report	October 27, 2021, 10:45 AM	V-028JV063	Valve Condition	Good
WO-36663	85	Completed	44243.40774	44326	Repair water main This has nothing to do with the sink hole at bottom of the hill. NO PARKING NEEDS POSTED 1 call valid 2/19/21 NO WATER SURFACING The leak may be on the service line or on the main. FIRST... Dig up shifted curb box to role out waste water. If that's not the issue, then dig on the 6" main. This is not an emergency. View pictures below	May 10, 2021, 9:35 AM	V-028KV004	Valve Condition	
WO-36663	85	Completed	44243.40774	44326	Repair water main This has nothing to do with the sink hole at bottom of the hill. NO PARKING NEEDS POSTED 1 call valid 2/19/21 NO WATER SURFACING The leak may be on the service line or on the main. FIRST... Dig up shifted curb box to role out waste water. If that's not the issue, then dig on the 6" main. This is not an emergency. View pictures below	May 10, 2021, 9:35 AM	V-028KV005	Valve Condition	
WO-35628	85	Completed	44231.35282	44231	Repair water main	February 4, 2021, 5:45 PM	V-028KV012	Valve Condition	
WO-35628	85	Completed	44231.35282	44231	Repair water main	February 4, 2021, 5:45 PM	V-028KV014	Valve Condition	
WO-35628	85	Completed	44231.35282	44231	Repair water main	February 4, 2021, 5:45 PM	V-028KV019	Valve Condition	
WO-57823	1	Completed	44456.57504	44459	Repair water main		V-028LV046	Valve Condition	
WO-40761	85	Completed	44289.62292	44289	Repair water main	April 3, 2021, 11:01 PM	V-028LV054	Valve Condition	
WO-65220	1	Completed	44537.37614	44533	Valve Maintenance Report		V-028NV010	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-38715	88	Completed	44266.31416	44266	Repair service line	June 17, 2021, 12:08 PM	V-028NV014	Valve Condition	Poor
WO-65220	1	Completed	44537.37614	44533	Valve Maintenance Report		V-028PV002	Valve Condition	
WO-35628	85	Completed	44231.35282	44231	Repair water main	February 4, 2021, 5:45 PM	V-028RV007	Valve Condition	
WO-34238	43	Completed	44218.36072	44218	Test shut	January 22, 2021, 9:18 AM	V-028RV030	Valve Condition	
WO-34238	43	Completed	44218.36072	44218	Test shut	January 22, 2021, 9:18 AM	V-028SV011	Valve Condition	
WO-34065	21	Completed	44216.62595	44220	Valve is inoperable and requires replacement	January 24, 2021, 3:53 PM	V-028SV017	Valve Condition	
WO-38185	41	Completed	44259.56064	44277	Contractor shut request	March 22, 2021, 7:27 AM	V-029CV002	Valve Condition	Good
WO-33699	1	Completed	44211.49334	44211	Valve Maintenance Report	January 15, 2021, 2:33 PM	V-029CV012	Valve Condition	
WO-33699	1	Completed	44211.49334	44211	Valve Maintenance Report	January 15, 2021, 2:33 PM	V-029CV020	Valve Condition	
WO-33699	1	Completed	44211.49334	44211	Valve Maintenance Report	January 15, 2021, 2:33 PM	V-029CV021	Valve Condition	
WO-34238	43	Completed	44218.36072	44218	Test shut	January 22, 2021, 9:18 AM	V-029DV001	Valve Condition	
WO-33699	1	Completed	44211.49334	44211	Valve Maintenance Report	January 15, 2021, 2:33 PM	V-029DV002	Valve Condition	
WO-51426	1	Completed	44385.46115	44385	Valve Maintenance Report	July 8, 2021, 11:05 AM	V-029GV019	Valve Condition	Good
WO-51424	1	Completed	44385.45809	44385	Valve Maintenance Report	July 8, 2021, 11:02 AM	V-029GV023	Valve Condition	Poor
WO-47551	1	Completed	44351.39279	44351	Valve Maintenance Report	June 4, 2021, 9:28 AM	V-029LV004	Valve Condition	
WO-43578	1	Completed	44320.42746	44320	Valve Maintenance Report	May 4, 2021, 10:18 AM	V-029MV010	Valve Condition	Good
WO-38197	1	Completed	44259.58241	44257	Valve Maintenance Report	March 4, 2021, 2:01 PM	V-029MV012	Valve Condition	Good
WO-38197	1	Completed	44259.58241	44257	Valve Maintenance Report	March 4, 2021, 2:01 PM	V-029MV023	Valve Condition	Good
WO-46166	1	Completed	44341.50029	44341	Valve Maintenance Report	May 25, 2021, 12:39 PM	V-029NV013	Valve Condition	
WO-44913	41	Completed	44331.32721	44334	Contractor shut request, Golden Triangle	May 18, 2021, 6:36 AM	V-029NV015	Valve Condition	
WO-46166	1	Completed	44341.50029	44341	Valve Maintenance Report	May 25, 2021, 12:39 PM	V-029NV041	Valve Condition	
WO-46166	1	Completed	44341.50029	44341	Valve Maintenance Report	May 25, 2021, 12:39 PM	V-029NV049	Valve Condition	
WO-46166	1	Completed	44341.50029	44341	Valve Maintenance Report	May 25, 2021, 12:39 PM	V-029NV064	Valve Condition	
WO-46166	1	Completed	44341.50029	44341	Valve Maintenance Report	May 25, 2021, 12:39 PM	V-029NV065	Valve Condition	
WO-44913	41	Completed	44331.32721	44334	Contractor shut request, Golden Triangle	May 18, 2021, 6:36 AM	V-029NV070	Valve Condition	
WO-42200	41	Completed	44306.38546	44306	Contractor shut request	April 20, 2021, 2:54 PM	V-029NV077	Valve Condition	
WO-44913	41	Completed	44331.32721	44334	Contractor shut request, Golden Triangle	May 18, 2021, 6:36 AM	V-029NV078	Valve Condition	
WO-42200	41	Completed	44306.38546	44306	Contractor shut request	April 20, 2021, 2:54 PM	V-029NV079	Valve Condition	
WO-35755	1	Completed	44232.11603	44438	Repair water main		V-029NV081	Valve Condition	
WO-42200	41	Completed	44306.38546	44306	Contractor shut request	April 20, 2021, 2:54 PM	V-029NV082	Valve Condition	
WO-46603	1	Completed	44344.29944	44439	Repair water main		V-029SV002	Valve Condition	
WO-46603	1	Completed	44344.29944	44439	Repair water main		V-029SV003	Valve Condition	
WO-46603	1	Completed	44344.29944	44439	Repair water main		V-029SV004	Valve Condition	
WO-46603	1	Completed	44344.29944	44439	Repair water main		V-029SV005	Valve Condition	
WO-46603	1	Completed	44344.29944	44439	Repair water main		V-029SV006	Valve Condition	
WO-46603	1	Completed	44344.29944	44439	Repair water main		V-029SV007	Valve Condition	
WO-56875	85	Completed	44447.36797	44448	Repair water main 6". New one call was placed 9/8/21. Dig where the water is. See pictures below. Normal road closure. Send Robo call due to the detailing car wash is notified	September 10, 2021, 8:08 AM	V-029SV008	Valve Condition	Good
WO-47939	85	Completed	44356.49427	44378	Repair water main	July 2, 2021, 7:41 AM	V-029SV011	Valve Condition	Good
WO-65724	1	Completed	44543.43169	44543	Valve Maintenance Report	December 13, 2021, 10:28 AM	V-029SV012	Valve Condition	
WO-46634	1	Completed	44344.47461	44347	Valve Maintenance Report	May 31, 2021, 11:47 PM	V-029SV013	Valve Condition	
WO-65724	1	Completed	44543.43169	44543	Valve Maintenance Report	December 13, 2021, 10:28 AM	V-029SV014	Valve Condition	
WO-43558	1	Completed	44320.40161	44320	Valve Maintenance Report	May 4, 2021, 9:41 AM	V-029SV018	Valve Condition	
WO-65724	1	Completed	44543.43169	44543	Valve Maintenance Report	December 13, 2021, 10:28 AM	V-029SV033	Valve Condition	
WO-65724	1	Completed	44543.43169	44543	Valve Maintenance Report	December 13, 2021, 10:28 AM	V-029SV034	Valve Condition	
WO-65724	1	Completed	44543.43169	44543	Valve Maintenance Report	December 13, 2021, 10:28 AM	V-029SV035	Valve Condition	
WO-47939	85	Completed	44356.49427	44378	Repair water main	July 2, 2021, 7:41 AM	V-029SV039	Valve Condition	
WO-61466	84	Completed	44493.7686	44545	Main or service line leak investigation/survey SEE NOTES BELOW FROM LD1	December 15, 2021, 3:35 PM	V-030AV002	Valve Condition	Good
WO-32638	84	Completed	44203.26389	44203	Main or service line leak investigation/survey DOMI # OP-2021-00271	January 7, 2021, 4:09 PM	V-030AV005	Valve Condition	Good
WO-61466	84	Completed	44493.7686	44545	Main or service line leak investigation/survey SEE NOTES BELOW FROM LD1	December 15, 2021, 3:35 PM	V-030AV007	Valve Condition	Good
WO-61466	84	Completed	44493.7686	44545	Main or service line leak investigation/survey SEE NOTES BELOW FROM LD1	December 15, 2021, 3:35 PM	V-030AV009	Valve Condition	Good
WO-61466	84	Completed	44493.7686	44545	Main or service line leak investigation/survey SEE NOTES BELOW FROM LD1	December 15, 2021, 3:35 PM	V-030AV024	Valve Condition	Good
WO-61466	84	Completed	44493.7686	44545	Main or service line leak investigation/survey SEE NOTES BELOW FROM LD1	December 15, 2021, 3:35 PM	V-030AV026	Valve Condition	Good
WO-61466	84	Completed	44493.7686	44545	Main or service line leak investigation/survey SEE NOTES BELOW FROM LD1	December 15, 2021, 3:35 PM	V-030AV028	Valve Condition	Good
WO-44913	41	Completed	44331.32721	44334	Contractor shut request, Golden Triangle	May 18, 2021, 6:36 AM	V-030BV054	Valve Condition	
WO-33396	1	Completed	44209.6217	44211	Repair water main		V-030EV008	Valve Condition	
WO-53041	41	Completed	44403.3944	44403	Contractor shut request	July 26, 2021, 4:09 PM	V-030EV011	Valve Condition	Good
WO-53331	43	Completed	44406.55311	44406	Test shut	July 29, 2021, 1:22 PM	V-030EV013	Valve Condition	Good
WO-53370	41	Completed	44407.35279	44407	Contractor shut request	July 30, 2021, 1:09 PM	V-030EV018	Valve Condition	
WO-53328	1	Completed	44406.5482	44406	Valve Maintenance Report	July 29, 2021, 1:14 PM	V-030JV001	Valve Condition	Good
WO-35817	85	Completed	44232.41018	44238	Repair water main. Some one was there and painted and put in a 1 call. Sidewalk main. No parking needs posted. View picture below	February 11, 2021, 3:18 PM	V-030JV002	Valve Condition	Fair
WO-37106	84	Completed	44249.02025	44250	INVESTIGATE WATER LEAKING IN THE STREET.		V-030JV005	Valve Condition	
WO-37106	84	Completed	44249.02025	44250	INVESTIGATE WATER LEAKING IN THE STREET.		V-030JV006	Valve Condition	
WO-47722	1	Completed	44354.53327	44356	Repair water main		V-042CV017	Valve Condition	
WO-47722	1	Completed	44354.53327	44356	Repair water main		V-042CV022	Valve Condition	
WO-33502	1	Completed	44210.4144	44211	Valve Maintenance Report	January 15, 2021, 8:44 AM	V-042DV016	Valve Condition	
WO-33665	1	Completed	44211.36177	44211	Valve Maintenance Report	January 15, 2021, 8:42 AM	V-042DV020	Valve Condition	
WO-59288	85	Completed	44470.63537	44470	Repair water main	October 5, 2021, 10:07 AM	V-042DV021	Valve Condition	
WO-63590	1	Completed	44516.34857	44515	Valve Maintenance Report		V-042DV022	Valve Condition	
WO-33502	1	Completed	44210.4144	44211	Valve Maintenance Report	January 15, 2021, 8:44 AM	V-042DV025	Valve Condition	
WO-37793	85	Completed	44256.5633	44270	Repair water main	March 15, 2021, 2:38 PM	V-042HV003	Valve Condition	
WO-37793	85	Completed	44256.5633	44270	Repair water main	March 15, 2021, 2:38 PM	V-042HV004	Valve Condition	
WO-63590	1	Completed	44516.34857	44515	Valve Maintenance Report		V-042HV009	Valve Condition	
WO-47851	1	Completed	44355.4551	44355	Valve Maintenance Report	June 8, 2021, 12:00 PM	V-043SV022	Valve Condition	Good
WO-47851	1	Completed	44355.4551	44355	Valve Maintenance Report	June 8, 2021, 12:00 PM	V-043SV023	Valve Condition	Good
WO-47851	1	Completed	44355.4551	44355	Valve Maintenance Report	June 8, 2021, 12:00 PM	V-043SV024	Valve Condition	Good
WO-47851	1	Completed	44355.4551	44355	Valve Maintenance Report	June 8, 2021, 12:00 PM	V-043SV025	Valve Condition	Good
WO-47851	1	Completed	44355.4551	44355	Valve Maintenance Report	June 8, 2021, 12:00 PM	V-043SV026	Valve Condition	Good
WO-34105	85	Completed	44217.1779	44217	Repair water main	January 22, 2021, 7:36 AM	V-044DV017	Valve Condition	
WO-34105	85	Completed	44217.1779	44217	Repair water main	January 22, 2021, 7:36 AM	V-044DV020	Valve Condition	
WO-52356	85	Completed	44395.98153	44397	INVESTIGATE WATER LEAKING IN THE STREET	July 20, 2021, 9:44 AM	V-044DV022	Valve Condition	
WO-52356	85	Completed	44395.98153	44397	INVESTIGATE WATER LEAKING IN THE STREET	July 20, 2021, 9:44 AM	V-044DV027	Valve Condition	
WO-34105	85	Completed	44217.1779	44217	Repair water main	January 22, 2021, 7:36 AM	V-044HV002	Valve Condition	
WO-53184	683	Completed	44404.61677	44404	Service line damaged 1 call marks were miss marked		V-044HV009	Valve Condition	
WO-53184	683	Completed	44404.61677	44404	Service line damaged 1 call marks were miss marked		V-044HV011	Valve Condition	
WO-53184	683	Completed	44404.61677	44404	Service line damaged 1 call marks were miss marked		V-044HV019	Valve Condition	
WO-64846	1	Completed	44532.45437	44533	Valve Maintenance Report		V-044HV030	Valve Condition	
WO-56908	1	Completed	44447.46377	44447	Valve Maintenance Report	September 8, 2021, 11:10 AM	V-044SV003	Valve Condition	
WO-65201	1	Completed	44537.28676	44538	Repair water main		V-045AV006	Valve Condition	
WO-31450	85	Completed	44186.63646	44210	Repair water main	January 14, 2021, 2:32 PM	V-045AV008	Valve Condition	
WO-66526	1	Completed	44552.63563	44553	Repair water main		V-045AV016	Valve Condition	
WO-65201	1	Completed	44537.28676	44538	Repair water main		V-045AV034	Valve Condition	
WO-60195	88	Completed	44480.42855	44487	Repair service line- if drilled, Drill Sheet work order MUST be completed Leak on service broken stop customer still has water 3 day one call placed 10/11/21. Records show the service to be 3/4 copper needs posted.	October 18, 2021, 11:00 AM	V-045EV001	Valve Condition	
WO-60195	88	Completed	44480.42855	44487	Repair service line- if drilled, Drill Sheet work order MUST be completed Leak on service broken stop customer still has water 3 day one call placed 10/11/21. Records show the service to be 3/4 copper needs posted.	October 18, 2021, 11:00 AM	V-045EV002	Valve Condition	
WO-60195	88	Completed	44480.42855	44487	Repair service line- if drilled, Drill Sheet work order MUST be completed Leak on service broken stop customer still has water 3 day one call placed 10/11/21. Records show the service to be 3/4 copper needs posted.	October 18, 2021, 11:00 AM	V-045EV005	Valve Condition	
WO-60195	88	Completed	44480.42855	44487	Repair service line- if drilled, Drill Sheet work order MUST be completed Leak on service broken stop customer still has water 3 day one call placed 10/11/21. Records show the service to be 3/4 copper needs posted.	October 18, 2021, 11:00 AM	V-045EV009	Valve Condition	
WO-54164	21	Completed	44417.32785	44420	Valve requires replacement	August 13, 2021, 1:35 PM	V-045EV012	Valve Condition	
WO-63126	1	Completed	44508.64888	44509	Repair water main		V-045KV031	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-64660	85	Completed	44530.56963	44530	Repair water main	December 7, 2021, 9:28 AM	V-045MV018	Valve Condition	
WO-37473	41	Completed	44251.61692	44251	Contractor shut request	February 24, 2021, 2:52 PM	V-045MV042	Valve Condition	
WO-53410	683	Completed	44407.72937	44408	Work site details for reporting		V-045NV011	Valve Condition	
WO-53410	683	Completed	44407.72937	44408	Work site details for reporting		V-045NV013	Valve Condition	Good
WO-35933	84	Completed	44233.85882	44235	Main or service line leak investigation/survey WATER COMING UP IN THE STREET IN TWO SPOTS RUNNING DOWN THE STREET ALSO TURNING ICY	February 8, 2021, 10:41 PM	V-045NV018	Valve Condition	
WO-53410	683	Completed	44407.72937	44408	Work site details for reporting		V-045NV021	Valve Condition	
WO-36120	85	Completed	44236.42746	44236	Repair water main	February 9, 2021, 5:47 PM	V-045NV025	Valve Condition	
WO-54394	41	Completed	44419.34523	44419	Contractor shut request	August 11, 2021, 9:12 AM	V-045PV003	Valve Condition	Good
WO-64660	85	Completed	44530.56963	44530	Repair water main	December 7, 2021, 9:28 AM	V-045SV040	Valve Condition	
WO-49041	88	Completed	44364.38695	44417	Curb box replacement 06/14/2021 Carson VanDyke property not razed property vacant,,,, located curb box but could not shut water off due to curb stop key being broken,,, water leaking out of right side of the house,,,, curb box fills up with water as soon as it's blown out,,,, needs dug to stop the leaking inside the property VEHICLES/CREW: 233 STORMER, CIMINO/ 127 WHIGHAM/ 675 DAY JOB: BROKEN C/S THE DRILL SHEET SHOWED A LEAD S/L FOR THE ADDRESS. THE CREW DUG THE SIDEWALK AND WE FOUND ¾" COPPER ON BOTH SIDES OF THE C/S. THE CREW DUG BACK 4' TO EXPOSE MORE OF THE LINE. IT WAS COPPER THE ENTIRE LENGTH. OUR PLUMBER CRIMPED THE LINE AND REPLACED THE C/S. THE HOUSE IS ABANDONED, SO WE LEFT IT SHUT. THE NEW C/B WAS SET AND THE SIDEWALK WAS BACKFILLED AND TAMPED. THE STREET WAS BACKFILED, COLD PATCHED AND TAMPED.	August 9, 2021, 2:56 PM	V-046AV008	Valve Condition	
WO-49041	88	Completed	44364.38695	44417	Curb box replacement 06/14/2021 Carson VanDyke property not razed property vacant,,,, located curb box but could not shut water off due to curb stop key being broken,,, water leaking out of right side of the house,,,, curb box fills up with water as soon as it's blown out,,,, needs dug to stop the leaking inside the property VEHICLES/CREW: 233 STORMER, CIMINO/ 127 WHIGHAM/ 675 DAY JOB: BROKEN C/S THE DRILL SHEET SHOWED A LEAD S/L FOR THE ADDRESS. THE CREW DUG THE SIDEWALK AND WE FOUND ¾" COPPER ON BOTH SIDES OF THE C/S. THE CREW DUG BACK 4' TO EXPOSE MORE OF THE LINE. IT WAS COPPER THE ENTIRE LENGTH. OUR PLUMBER CRIMPED THE LINE AND REPLACED THE C/S. THE HOUSE IS ABANDONED, SO WE LEFT IT SHUT. THE NEW C/B WAS SET AND THE SIDEWALK WAS BACKFILLED AND TAMPED. THE STREET WAS BACKFILED, COLD PATCHED AND TAMPED.	August 9, 2021, 2:56 PM	V-046AV017	Valve Condition	
WO-48290	41	Completed	44358.56003	44358	Contractor shut request	June 11, 2021, 2:05 PM	V-046DV003	Valve Condition	Good
WO-45947	43	Completed	44340.52451	44340	Test shut	May 24, 2021, 12:39 PM	V-046DV004	Valve Condition	
WO-45443	84	Completed	44335.87816	44335	Main or service line leak investigation/survey, LEAK IN STREET - PER 911	May 20, 2021, 1:20 AM	V-046DV005	Valve Condition	Good
WO-45443	84	Completed	44335.87816	44335	Main or service line leak investigation/survey, LEAK IN STREET - PER 911	May 20, 2021, 1:20 AM	V-046DV006	Valve Condition	Good
WO-33638	1	Completed	44211.29315	44218	Repair water main		V-046GV003	Valve Condition	
WO-48290	41	Completed	44358.56003	44358	Contractor shut request	June 11, 2021, 2:05 PM	V-046HV001	Valve Condition	Good
WO-45443	84	Completed	44335.87816	44335	Main or service line leak investigation/survey, LEAK IN STREET - PER 911	May 20, 2021, 1:20 AM	V-046HV007	Valve Condition	Good
WO-45443	84	Completed	44335.87816	44335	Main or service line leak investigation/survey, LEAK IN STREET - PER 911	May 20, 2021, 1:20 AM	V-046HV012	Valve Condition	Good
WO-32754	1	Completed	44203.57584	44204	Repair water main 8". Water blowing into the sewer and collapsed customers sewer line. Leak is on the service line at the Ferrell or on the main to to Ferrell 1 call valid 1/12/21. Main in the middle of the street. Regular street closure		V-046KV009	Valve Condition	
WO-32752	85	Completed	44203.57584	44245	Repair water main 8". Water blowing into the sewer and collapsed customers sewer line. Leak is on the service line at the Ferrell or on the main next to Ferrell 1 call valid 1/12/21. Main in the middle of the street. Regular street closure	February 18, 2021, 2:50 PM	V-046KV021	Valve Condition	Good
WO-32754	1	Completed	44203.57584	44204	Repair water main 8". Water blowing into the sewer and collapsed customers sewer line. Leak is on the service line at the Ferrell or on the main to to Ferrell 1 call valid 1/12/21. Main in the middle of the street. Regular street closure		V-046KV023	Valve Condition	
WO-32752	85	Completed	44203.57584	44245	Repair water main 8". Water blowing into the sewer and collapsed customers sewer line. Leak is on the service line at the Ferrell or on the main next to Ferrell 1 call valid 1/12/21. Main in the middle of the street. Regular street closure	February 18, 2021, 2:50 PM	V-046KV025	Valve Condition	
WO-64021	1	Completed	44521.4654	44522	Repair water main		V-046LV012	Valve Condition	
WO-64021	1	Completed	44521.4654	44522	Repair water main		V-046LV015	Valve Condition	
WO-64021	1	Completed	44521.4654	44522	Repair water main		V-046LV016	Valve Condition	
WO-65765	1	Completed	44543.53383	44543	Valve Maintenance Report	December 13, 2021, 12:52 PM	V-046MV011	Valve Condition	
WO-57576	41	Completed	44454.62317	44454	Contractor shut request	September 15, 2021, 3:10 PM	V-046NV008	Valve Condition	Good
WO-57576	41	Completed	44454.62317	44454	Contractor shut request	September 15, 2021, 3:10 PM	V-046NV009	Valve Condition	Good
WO-57576	41	Completed	44454.62317	44454	Contractor shut request	September 15, 2021, 3:10 PM	V-046NV017	Valve Condition	Good
WO-57576	41	Completed	44454.62317	44454	Contractor shut request	September 15, 2021, 3:10 PM	V-046NV019	Valve Condition	Good
WO-64021	1	Completed	44521.4654	44522	Repair water main		V-046RV003	Valve Condition	
WO-64021	1	Completed	44521.4654	44522	Repair water main		V-046RV005	Valve Condition	
WO-64021	1	Completed	44521.4654	44522	Repair water main		V-046RV008	Valve Condition	
WO-64021	1	Completed	44521.4654	44522	Repair water main		V-046RV011	Valve Condition	
WO-57498	41	Completed	44454.35253	44459	Contractor shut request	September 20, 2021, 11:56 AM	V-046SV001	Valve Condition	
WO-57498	41	Completed	44454.35253	44459	Contractor shut request	September 20, 2021, 11:56 AM	V-046SV003	Valve Condition	
WO-57400	43	Completed	44453.4542	44453	Test shut	September 14, 2021, 11:02 AM	V-046SV004	Valve Condition	
WO-54842	1	Completed	44424.41873	44424	Valve Maintenance Report	August 16, 2021, 10:04 AM	V-046SV061	Valve Condition	Fair
WO-64543	1	Completed	44529.53586	44529	Valve Maintenance Report	November 29, 2021, 12:53 PM	V-047AV001	Valve Condition	
WO-64551	1	Completed	44529.54774	44529	Valve Maintenance Report	November 29, 2021, 1:12 PM	V-047AV002	Valve Condition	
WO-64551	1	Completed	44529.54774	44529	Valve Maintenance Report	November 29, 2021, 1:12 PM	V-047AV003	Valve Condition	
WO-64549	1	Completed	44529.54348	44529	Valve Maintenance Report	November 29, 2021, 1:05 PM	V-047AV004	Valve Condition	Good
WO-64550	1	Completed	44529.54598	44529	Valve Maintenance Report	November 29, 2021, 1:07 PM	V-047AV005	Valve Condition	
WO-64551	1	Completed	44529.54774	44529	Valve Maintenance Report	November 29, 2021, 1:12 PM	V-047AV006	Valve Condition	
WO-58992	1	Completed	44468.38303	44468	Valve Maintenance Report	September 29, 2021, 9:30 AM	V-047AV007	Valve Condition	
WO-58992	1	Completed	44468.38303	44468	Valve Maintenance Report	September 29, 2021, 9:30 AM	V-047AV008	Valve Condition	
WO-58988	1	Completed	44468.37912	44468	Valve Maintenance Report	September 29, 2021, 9:09 AM	V-047AV009	Valve Condition	
WO-64549	1	Completed	44529.54348	44529	Valve Maintenance Report	November 29, 2021, 1:05 PM	V-047AV010	Valve Condition	Good
WO-58992	1	Completed	44468.38303	44468	Valve Maintenance Report	September 29, 2021, 9:30 AM	V-047AV011	Valve Condition	
WO-58998	1	Completed	44468.39157	44468	Valve Maintenance Report	September 29, 2021, 9:46 AM	V-047AV014	Valve Condition	
WO-58998	1	Completed	44468.39157	44468	Valve Maintenance Report	September 29, 2021, 9:46 AM	V-047AV015	Valve Condition	
WO-59022	1	Completed	44468.42252	44468	Valve Maintenance Report	September 29, 2021, 10:13 AM	V-047AV018	Valve Condition	
WO-64545	1	Completed	44529.53769	44529	Valve Maintenance Report	November 29, 2021, 12:55 PM	V-047AV019	Valve Condition	
WO-64546	1	Completed	44529.53912	44529	Valve Maintenance Report	November 29, 2021, 12:57 PM	V-047AV020	Valve Condition	
WO-59168	1	Completed	44469.56313	44469	Valve Maintenance Report	September 30, 2021, 1:37 PM	V-047BV001	Valve Condition	
WO-59168	1	Completed	44469.56313	44469	Valve Maintenance Report	September 30, 2021, 1:37 PM	V-047BV003	Valve Condition	
WO-59022	1	Completed	44468.42252	44468	Valve Maintenance Report	September 29, 2021, 10:13 AM	V-047BV004	Valve Condition	
WO-59171	1	Completed	44469.56942	44469	Valve Maintenance Report	September 30, 2021, 1:51 PM	V-047BV006	Valve Condition	
WO-59171	1	Completed	44469.56942	44469	Valve Maintenance Report	September 30, 2021, 1:51 PM	V-047BV007	Valve Condition	
WO-64377	1	Completed	44524.43411	44524	Valve Maintenance Report	November 24, 2021, 10:27 AM	V-047CV005	Valve Condition	
WO-65115	1	Completed	44536.36733	44536	Valve Maintenance Report	December 6, 2021, 8:50 AM	V-047CV007	Valve Condition	
WO-61815	1	Completed	44496.56429	44496	Valve Maintenance Report	October 27, 2021, 1:41 PM	V-047CV008	Valve Condition	
WO-61815	1	Completed	44496.56429	44496	Valve Maintenance Report	October 27, 2021, 1:41 PM	V-047CV009	Valve Condition	
WO-65123	1	Completed	44536.39218	44536	Valve Maintenance Report	December 6, 2021, 9:31 AM	V-047DV002	Valve Condition	Fair
WO-65123	1	Completed	44536.39218	44536	Valve Maintenance Report	December 6, 2021, 9:31 AM	V-047DV003	Valve Condition	Fair
WO-65123	1	Completed	44536.39218	44536	Valve Maintenance Report	December 6, 2021, 9:31 AM	V-047DV004	Valve Condition	Fair
WO-65123	1	Completed	44536.39218	44536	Valve Maintenance Report	December 6, 2021, 9:31 AM	V-047DV007	Valve Condition	Fair
WO-62198	1	Completed	44501.49521	44501	Valve Maintenance Report	November 1, 2021, 11:55 AM	V-047EV011	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-66713	1	Completed	44558.5741	44558	Valve Maintenance Report	December 28, 2021, 1:47 PM	V-047EV019	Valve Condition	
WO-65891	1	Completed	44544.5795	44544	Valve Maintenance Report	December 14, 2021, 1:55 PM	V-047EV021	Valve Condition	
WO-66693	1	Completed	44558.43935	44558	Valve Maintenance Report	December 28, 2021, 10:34 AM	V-047EV023	Valve Condition	
WO-64372	1	Completed	44524.42254	44524	Valve Maintenance Report	November 24, 2021, 10:11 AM	V-047EV027	Valve Condition	
WO-61814	1	Completed	44496.55699	44496	Valve Maintenance Report	October 27, 2021, 1:31 PM	V-047FV002	Valve Condition	
WO-61814	1	Completed	44496.55699	44496	Valve Maintenance Report	October 27, 2021, 1:31 PM	V-047FV003	Valve Condition	
WO-61814	1	Completed	44496.55699	44496	Valve Maintenance Report	October 27, 2021, 1:31 PM	V-047FV004	Valve Condition	
WO-61815	1	Completed	44496.56429	44496	Valve Maintenance Report	October 27, 2021, 1:41 PM	V-047GV001	Valve Condition	
WO-59252	1	Completed	44470.45684	44470	Valve Maintenance Report	October 1, 2021, 11:00 AM	V-047GV003	Valve Condition	
WO-59255	1	Completed	44470.45945	44470	Valve Maintenance Report	October 1, 2021, 11:03 AM	V-047GV004	Valve Condition	
WO-64388	1	Completed	44524.51269	44524	Valve Maintenance Report	November 24, 2021, 12:24 PM	V-047GV005	Valve Condition	
WO-64388	1	Completed	44524.51269	44524	Valve Maintenance Report	November 24, 2021, 12:24 PM	V-047GV006	Valve Condition	
WO-64388	1	Completed	44524.51269	44524	Valve Maintenance Report	November 24, 2021, 12:24 PM	V-047GV007	Valve Condition	
WO-64388	1	Completed	44524.51269	44524	Valve Maintenance Report	November 24, 2021, 12:24 PM	V-047GV019	Valve Condition	
WO-64388	1	Completed	44524.51269	44524	Valve Maintenance Report	November 24, 2021, 12:24 PM	V-047GV021	Valve Condition	
WO-42539	1	Completed	44309.31507	44439	Repair water main		V-047HV009	Valve Condition	
WO-37667	85	Completed	44253.70722	44256	Repair water main 2/27/2021 CALLER REPORTED THAT LEAK IS FLOWING HEAVLY BUT STILL FLOWING INTO CATCH BASIN.	March 1, 2021, 4:30 PM	V-047JV003	Valve Condition	Good
WO-64358	1	Completed	44524.39627	44524	Valve Maintenance Report	November 24, 2021, 9:43 AM	V-047JV004	Valve Condition	
WO-64273	1	Completed	44523.568	44523	Valve Maintenance Report	November 23, 2021, 1:44 PM	V-047JV006	Valve Condition	Good
WO-64273	1	Completed	44523.568	44523	Valve Maintenance Report	November 23, 2021, 1:44 PM	V-047JV007	Valve Condition	Good
WO-64273	1	Completed	44523.568	44523	Valve Maintenance Report	November 23, 2021, 1:44 PM	V-047JV008	Valve Condition	Good
WO-64273	1	Completed	44523.568	44523	Valve Maintenance Report	November 23, 2021, 1:44 PM	V-047JV009	Valve Condition	
WO-37667	85	Completed	44253.70722	44256	Repair water main 2/27/2021 CALLER REPORTED THAT LEAK IS FLOWING HEAVLY BUT STILL FLOWING INTO CATCH BASIN.	March 1, 2021, 4:30 PM	V-047JV010	Valve Condition	Good
WO-64254	1	Completed	44523.46867	44523	Valve Maintenance Report	November 23, 2021, 11:16 AM	V-047JV013	Valve Condition	
WO-59950	1	Completed	44476.58447	44476	Valve Maintenance Report	October 7, 2021, 2:07 PM	V-047JV014	Valve Condition	Good
WO-60262	1	Completed	44480.54422	44480	Valve Maintenance Report	October 11, 2021, 1:27 PM	V-047JV020	Valve Condition	
WO-65772	1	Completed	44543.56316	44543	Valve Maintenance Report	December 13, 2021, 1:46 PM	V-047JV021	Valve Condition	
WO-62183	1	Completed	44501.44308	44501	Valve Maintenance Report	November 1, 2021, 10:50 AM	V-047JV022	Valve Condition	
WO-62183	1	Completed	44501.44308	44501	Valve Maintenance Report	November 1, 2021, 10:50 AM	V-047JV023	Valve Condition	
WO-62192	1	Completed	44501.4728	44501	Valve Maintenance Report	November 1, 2021, 11:22 AM	V-047JV024	Valve Condition	
WO-62192	1	Completed	44501.4728	44501	Valve Maintenance Report	November 1, 2021, 11:22 AM	V-047JV025	Valve Condition	
WO-37667	85	Completed	44253.70722	44256	Repair water main 2/27/2021 CALLER REPORTED THAT LEAK IS FLOWING HEAVLY BUT STILL FLOWING INTO CATCH BASIN.	March 1, 2021, 4:30 PM	V-047JV034	Valve Condition	Good
WO-59950	1	Completed	44476.58447	44476	Valve Maintenance Report	October 7, 2021, 2:07 PM	V-047KV002	Valve Condition	
WO-60207	1	Completed	44480.53025	44480	Valve Maintenance Report	October 11, 2021, 12:46 PM	V-047KV006	Valve Condition	
WO-60262	1	Completed	44480.54422	44480	Valve Maintenance Report	October 11, 2021, 1:27 PM	V-047KV007	Valve Condition	
WO-59948	401	Completed	44476.57404	44476	Dividing Pressure Valve Maintenance Report	October 7, 2021, 1:48 PM	V-047KV009	Valve Condition	
WO-59944	1	Completed	44476.56188	44476	Valve Maintenance Report	October 7, 2021, 1:34 PM	V-047KV010	Valve Condition	
WO-59944	1	Completed	44476.56188	44476	Valve Maintenance Report	October 7, 2021, 1:34 PM	V-047KV011	Valve Condition	
WO-60262	1	Completed	44480.54422	44480	Valve Maintenance Report	October 11, 2021, 1:27 PM	V-047KV017	Valve Condition	
WO-63643	1	Completed	44516.54892	44516	Valve Maintenance Report	November 16, 2021, 1:11 PM	V-047KV022	Valve Condition	
WO-63644	1	Completed	44516.55447	44516	Valve Maintenance Report	November 16, 2021, 1:20 PM	V-047KV023	Valve Condition	
WO-60262	1	Completed	44480.54422	44480	Valve Maintenance Report	October 11, 2021, 1:27 PM	V-047KV024	Valve Condition	
WO-63646	1	Completed	44516.56771	44516	Valve Maintenance Report	November 16, 2021, 1:49 PM	V-047KV025	Valve Condition	
WO-63646	1	Completed	44516.56771	44516	Valve Maintenance Report	November 16, 2021, 1:49 PM	V-047KV026	Valve Condition	
WO-63646	1	Completed	44516.56771	44516	Valve Maintenance Report	November 16, 2021, 1:49 PM	V-047KV027	Valve Condition	
WO-63649	1	Completed	44516.57565	44516	Valve Maintenance Report	November 16, 2021, 1:50 PM	V-047KV028	Valve Condition	
WO-59943	1	Completed	44476.55336	44476	Valve Maintenance Report	October 7, 2021, 1:21 PM	V-047KV029	Valve Condition	
WO-59940	1	Completed	44476.54682	44476	Valve Maintenance Report	October 7, 2021, 1:12 PM	V-047KV031	Valve Condition	
WO-59940	1	Completed	44476.54682	44476	Valve Maintenance Report	October 7, 2021, 1:12 PM	V-047KV033	Valve Condition	
WO-43732	1	Completed	44321.41839	44321	Valve Maintenance Report	May 5, 2021, 10:06 AM	V-047KV034	Valve Condition	Poor
WO-43979	1	Completed	44322.60042	44322	Valve Maintenance Report	May 6, 2021, 2:25 PM	V-047KV035	Valve Condition	
WO-63646	1	Completed	44516.56771	44516	Valve Maintenance Report	November 16, 2021, 1:49 PM	V-047KV038	Valve Condition	
WO-59262	1	Completed	44470.48675	44470	Valve Maintenance Report	October 1, 2021, 11:44 AM	V-047LV003	Valve Condition	
WO-59271	1	Completed	44470.54601	44470	Valve Maintenance Report	October 1, 2021, 1:07 PM	V-047LV004	Valve Condition	
WO-59274	1	Completed	44470.54762	44470	Valve Maintenance Report	October 1, 2021, 1:10 PM	V-047LV005	Valve Condition	
WO-59260	1	Completed	44470.46662	44470	Valve Maintenance Report	October 1, 2021, 11:29 AM	V-047LV007	Valve Condition	
WO-59260	1	Completed	44470.46662	44470	Valve Maintenance Report	October 1, 2021, 11:29 AM	V-047LV008	Valve Condition	
WO-59480	1	Completed	44474.39909	44474	Valve Maintenance Report	October 5, 2021, 9:42 AM	V-047LV009	Valve Condition	
WO-59496	1	Completed	44474.4079	44474	Valve Maintenance Report	October 5, 2021, 9:49 AM	V-047LV013	Valve Condition	
WO-59498	1	Completed	44474.40969	44474	Valve Maintenance Report	October 5, 2021, 9:59 AM	V-047LV014	Valve Condition	
WO-59498	1	Completed	44474.40969	44474	Valve Maintenance Report	October 5, 2021, 9:59 AM	V-047LV015	Valve Condition	
WO-59512	1	Completed	44474.42161	44474	Valve Maintenance Report	October 5, 2021, 10:35 AM	V-047LV019	Valve Condition	
WO-59512	1	Completed	44474.42161	44474	Valve Maintenance Report	October 5, 2021, 10:35 AM	V-047LV020	Valve Condition	
WO-59512	1	Completed	44474.42161	44474	Valve Maintenance Report	October 5, 2021, 10:35 AM	V-047LV021	Valve Condition	
WO-59528	1	Completed	44474.45424	44474	Valve Maintenance Report	October 5, 2021, 10:56 AM	V-047LV022	Valve Condition	
WO-59526	1	Completed	44474.4502	44474	Valve Maintenance Report	October 5, 2021, 10:51 AM	V-047LV023	Valve Condition	
WO-59531	1	Completed	44474.45921	44474	Valve Maintenance Report	October 5, 2021, 11:21 AM	V-047LV024	Valve Condition	
WO-59531	1	Completed	44474.45921	44474	Valve Maintenance Report	October 5, 2021, 11:21 AM	V-047LV025	Valve Condition	
WO-54138	88	Completed	44417.29147	44417	Repair service line	September 2, 2021, 11:04 AM	V-047MV001	Valve Condition	
WO-66457	1	Completed	44552.39258	44552	Valve Maintenance Report	December 22, 2021, 10:14 AM	V-047MV002	Valve Condition	
WO-66457	1	Completed	44552.39258	44552	Valve Maintenance Report	December 22, 2021, 10:14 AM	V-047MV003	Valve Condition	
WO-54105	85	Completed	44415.33348	44415	Repair water main	August 7, 2021, 6:20 PM	V-047MV014	Valve Condition	
WO-56061	643	Completed	44438.64005	44438	Water service line shut and cut/Sewer lateral connection removal/Stormwater connection removal		V-047MV015	Valve Condition	
WO-42539	1	Completed	44309.31507	44439	Repair water main		V-047MV018	Valve Condition	Fair
WO-60801	1	Completed	44484.54552	44484	Valve Maintenance Report	October 15, 2021, 1:10 PM	V-047MV020	Valve Condition	
WO-42539	1	Completed	44309.31507	44439	Repair water main		V-047MV021	Valve Condition	Fair
WO-60163	1	Completed	44480.44087	44480	Valve Maintenance Report	October 11, 2021, 10:41 AM	V-047MV022	Valve Condition	
WO-60761	1	Completed	44484.38828	44484	Valve Maintenance Report	October 15, 2021, 9:27 AM	V-047MV024	Valve Condition	
WO-60761	1	Completed	44484.38828	44484	Valve Maintenance Report	October 15, 2021, 9:27 AM	V-047MV025	Valve Condition	
WO-44158	85	Completed	44325.31501	44325	Repair water main	May 10, 2021, 11:51 AM	V-047MV026	Valve Condition	
WO-66457	1	Completed	44552.39258	44552	Valve Maintenance Report	December 22, 2021, 10:14 AM	V-047MV030	Valve Condition	
WO-42539	1	Completed	44309.31507	44439	Repair water main		V-047MV032	Valve Condition	Fair
WO-37840	85	Completed	44257.1186	44257	Repair water main	March 3, 2021, 12:11 AM	V-047NV002	Valve Condition	Good
WO-64250	1	Completed	44523.44747	44523	Valve Maintenance Report	November 23, 2021, 10:47 AM	V-047NV004	Valve Condition	
WO-64247	1	Completed	44523.43578	44523	Valve Maintenance Report	November 23, 2021, 10:40 AM	V-047NV005	Valve Condition	
WO-64337	1	Completed	44524.35776	44524	Valve Maintenance Report	November 24, 2021, 8:36 AM	V-047NV007	Valve Condition	
WO-61538	88	Completed	44494.43431	44516	Repair service line- if drilled, Drill Sheet work order MUST be completed 3 DAY 1 CALL PLACED 10/26/21. Will need posted.STREET LOCATION: 15 SOLAR ST (W.O.61538) VEHICLES & CREWS: 233 STORMER, CIMINO, 673 R WILSON, 120 HARRIS, 248 GRAY WORK DESCRIPTION: CREW MOBILIZED FOR A SERVICE LINE REPLACEMENT. SERVICE LINES ARE COPPER. OUR PLUMBER PULLED THE C/S. NO WATER. CREW WAS DIRECTED TO REPLACE THE PUBLIC SERVICE. CREW EXCAVATED, THE MAIN IIS OUTSIDE THE HOLE. THE HOLE WAS COVERED WITH SECURED ROAD PLATES AND COLD PATCH. NEED TO RETURN AND WIDEN THE HOLE TO ACCESS THE MAIN	November 16, 2021, 3:24 PM	V-047NV008	Valve Condition	
WO-37841	1	Completed	44257.1186	44258	Repair water main		V-047NV011	Valve Condition	Good
WO-64239	1	Completed	44523.42893	44523	Valve Maintenance Report	November 23, 2021, 10:22 AM	V-047NV014	Valve Condition	
WO-37840	85	Completed	44257.1186	44257	Repair water main	March 3, 2021, 12:11 AM	V-047NV015	Valve Condition	
WO-64356	1	Completed	44524.39437	44524	Valve Maintenance Report	November 24, 2021, 9:29 AM	V-047NV031	Valve Condition	
WO-64250	1	Completed	44523.44747	44523	Valve Maintenance Report	November 23, 2021, 10:47 AM	V-047NV033	Valve Condition	
WO-64247	1	Completed	44523.43578	44523	Valve Maintenance Report	November 23, 2021, 10:40 AM	V-047NV034	Valve Condition	
WO-64340	1	Completed	44524.37512	44524	Valve Maintenance Report	November 24, 2021, 9:18 AM	V-047NV035	Valve Condition	
WO-63866	1	Completed	44518.55704	44518	Valve Maintenance Report	November 18, 2021, 1:29 PM	V-047PV011	Valve Condition	
WO-63866	1	Completed	44518.55704	44518	Valve Maintenance Report	November 18, 2021, 1:29 PM	V-047PV012	Valve Condition	
WO-63866	1	Completed	44518.55704	44518	Valve Maintenance Report	November 18, 2021, 1:29 PM	V-047PV013	Valve Condition	
WO-63852	1	Completed	44518.4978	44518	Valve Maintenance Report	November 18, 2021, 11:58 AM	V-047PV016	Valve Condition	Good
WO-63853	1	Completed	44518.50642	44518	Valve Maintenance Report	November 18, 2021, 12:10 PM	V-047PV017	Valve Condition	Good
WO-62220	1	Completed	44501.58293	44501	Valve Maintenance Report	November 1, 2021, 2:16 PM	V-047PV019	Valve Condition	
WO-63650	1	Completed	44516.58839	44516	Valve Maintenance Report	November 16, 2021, 2:08 PM	V-047PV020	Valve Condition	
WO-62220	1	Completed	44501.58293	44501	Valve Maintenance Report	November 1, 2021, 2:16 PM	V-047PV021	Valve Condition	
WO-62217	1	Completed	44501.55288	44501	Valve Maintenance Report	November 1, 2021, 1:31 PM	V-047PV026	Valve Condition	
WO-62217	1	Completed	44501.55288	44501	Valve Maintenance Report	November 1, 2021, 1:31 PM	V-047PV028	Valve Condition	
WO-62217	1	Completed	44501.55288	44501	Valve Maintenance Report	November 1, 2021, 1:31 PM	V-047PV029	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-62217	1	Completed	44501.55288	44501	Valve Maintenance Report	November 1, 2021, 1:31 PM	V-047PV030	Valve Condition	
WO-63852	1	Completed	44518.4978	44518	Valve Maintenance Report	November 18, 2021, 11:58 AM	V-047PV032	Valve Condition	Good
WO-63866	1	Completed	44518.55704	44518	Valve Maintenance Report	November 18, 2021, 1:29 PM	V-047PV034	Valve Condition	
WO-66644	1	Completed	44557.55018	44557	Valve Maintenance Report	December 27, 2021, 1:36 PM	V-047RV001	Valve Condition	
WO-43672	21	Completed	44321.07811	44321	Valve requires replacement	May 5, 2021, 9:08 AM	V-047RV002	Valve Condition	
WO-66602	1	Completed	44557.37415	44557	Valve Maintenance Report	December 27, 2021, 9:01 AM	V-047RV004	Valve Condition	
WO-66601	1	Completed	44557.36725	44557	Valve Maintenance Report	December 27, 2021, 8:53 AM	V-047RV010	Valve Condition	
WO-66601	1	Completed	44557.36725	44557	Valve Maintenance Report	December 27, 2021, 8:53 AM	V-047RV011	Valve Condition	
WO-66601	1	Completed	44557.36725	44557	Valve Maintenance Report	December 27, 2021, 8:53 AM	V-047RV012	Valve Condition	
WO-63672	85	Completed	44517.29544	44517	Repair water main		V-047RV015	Valve Condition	
WO-38693	88	Completed	44265.63781	44273	Repair service line	July 23, 2021, 3:28 PM	V-047RV021	Valve Condition	
WO-60776	1	Completed	44484.43918	44484	Valve Maintenance Report	October 15, 2021, 10:55 AM	V-047SV012	Valve Condition	Good
WO-44158	85	Completed	44325.31501	44325	Repair water main	May 10, 2021, 11:51 AM	V-047SV013	Valve Condition	Good
WO-60776	1	Completed	44484.43918	44484	Valve Maintenance Report	October 15, 2021, 10:55 AM	V-047SV014	Valve Condition	
WO-60768	1	Completed	44484.41164	44484	Valve Maintenance Report	October 15, 2021, 9:56 AM	V-047SV017	Valve Condition	
WO-60768	1	Completed	44484.41164	44484	Valve Maintenance Report	October 15, 2021, 9:56 AM	V-047SV018	Valve Condition	
WO-60757	1	Completed	44484.35823	44484	Valve Maintenance Report	October 15, 2021, 9:03 AM	V-047SV019	Valve Condition	
WO-60755	1	Completed	44484.35528	44484	Valve Maintenance Report	October 15, 2021, 8:34 AM	V-047SV020	Valve Condition	
WO-60755	1	Completed	44484.35528	44484	Valve Maintenance Report	October 15, 2021, 8:34 AM	V-047SV021	Valve Condition	
WO-60757	1	Completed	44484.35823	44484	Valve Maintenance Report	October 15, 2021, 9:03 AM	V-047SV022	Valve Condition	
WO-60609	1	Completed	44483.39278	44483	Valve Maintenance Report	October 14, 2021, 9:50 AM	V-047SV025	Valve Condition	Good
WO-60609	1	Completed	44483.39278	44483	Valve Maintenance Report	October 14, 2021, 9:50 AM	V-047SV026	Valve Condition	
WO-60609	1	Completed	44483.39278	44483	Valve Maintenance Report	October 14, 2021, 9:50 AM	V-047SV027	Valve Condition	
WO-60609	1	Completed	44483.39278	44483	Valve Maintenance Report	October 14, 2021, 9:50 AM	V-047SV028	Valve Condition	
WO-60609	1	Completed	44483.39278	44483	Valve Maintenance Report	October 14, 2021, 9:50 AM	V-047SV029	Valve Condition	
WO-60681	1	Completed	44483.55287	44483	Valve Maintenance Report	October 14, 2021, 1:20 PM	V-047SV031	Valve Condition	
WO-60681	1	Completed	44483.55287	44483	Valve Maintenance Report	October 14, 2021, 1:20 PM	V-047SV032	Valve Condition	
WO-60690	1	Completed	44483.56493	44483	Valve Maintenance Report	October 14, 2021, 2:23 PM	V-047SV034	Valve Condition	
WO-60690	1	Completed	44483.56493	44483	Valve Maintenance Report	October 14, 2021, 2:23 PM	V-047SV037	Valve Condition	
WO-60690	1	Completed	44483.56493	44483	Valve Maintenance Report	October 14, 2021, 2:23 PM	V-047SV038	Valve Condition	
WO-60690	1	Completed	44483.56493	44483	Valve Maintenance Report	October 14, 2021, 2:23 PM	V-047SV039	Valve Condition	
WO-60690	1	Completed	44483.56493	44483	Valve Maintenance Report	October 14, 2021, 2:23 PM	V-047SV040	Valve Condition	
WO-60690	1	Completed	44483.56493	44483	Valve Maintenance Report	October 14, 2021, 2:23 PM	V-047SV041	Valve Condition	
WO-60757	1	Completed	44484.35823	44484	Valve Maintenance Report	October 15, 2021, 9:03 AM	V-047SV042	Valve Condition	
WO-60603	1	Completed	44483.3696	44483	Valve Maintenance Report	October 14, 2021, 8:55 AM	V-047SV043	Valve Condition	
WO-60604	1	Completed	44483.37267	44483	Valve Maintenance Report	October 14, 2021, 8:59 AM	V-047SV048	Valve Condition	
WO-60603	1	Completed	44483.3696	44483	Valve Maintenance Report	October 14, 2021, 8:55 AM	V-047SV049	Valve Condition	
WO-60605	1	Completed	44483.37534	44483	Valve Maintenance Report	October 14, 2021, 9:03 AM	V-047SV050	Valve Condition	
WO-36867	84	Completed	44245.37722	44245	Main or service line leak investigation/survey		V-047SV058	Valve Condition	
WO-59841	43	Completed	44476.35909	44475	Test shut	October 7, 2021, 8:41 AM	V-048BV006	Valve Condition	
WO-54024	43	Completed	44414.35395	44414	Test shut	August 6, 2021, 9:27 AM	V-048DV012	Valve Condition	
WO-66316	1	Completed	44550.37207	44550	Valve Maintenance Report	December 20, 2021, 9:26 AM	V-048DV013	Valve Condition	
WO-56061	643	Completed	44438.64005	44438	Water service line shut and cut/Sewer lateral connection removal/Stormwater connection removal		V-048EV003	Valve Condition	
WO-33614	1	Completed	44210.96183	44222	Repair water main		V-048EV007	Valve Condition	
WO-33614	1	Completed	44210.96183	44222	Repair water main		V-048EV015	Valve Condition	
WO-33614	1	Completed	44210.96183	44222	Repair water main		V-048EV017	Valve Condition	
WO-47637	85	Completed	44353.58796	44353	Repair water main - 8"	June 6, 2021, 11:37 PM	V-048EV021	Valve Condition	
WO-47637	85	Completed	44353.58796	44353	Repair water main - 8"	June 6, 2021, 11:37 PM	V-048EV022	Valve Condition	
WO-54194	1	Completed	44417.50601	44417	Valve Maintenance Report	August 9, 2021, 12:10 PM	V-048EV024	Valve Condition	
WO-47637	85	Completed	44353.58796	44353	Repair water main - 8"	June 6, 2021, 11:37 PM	V-048EV026	Valve Condition	
WO-37108	88	Completed	44249.05833	44250	Repair service line	February 23, 2021, 7:44 AM	V-048EV027	Valve Condition	Fair
WO-56061	643	Completed	44438.64005	44438	Water service line shut and cut/Sewer lateral connection removal/Stormwater connection removal		V-048EV039	Valve Condition	
WO-47636	1	Completed	44352.80342	44354	Repair water main		V-048FV004	Valve Condition	
WO-47635	85	Completed	44352.80342	44354	Repair water main	June 10, 2021, 1:16 PM	V-048FV008	Valve Condition	
WO-47635	85	Completed	44352.80342	44354	Repair water main	June 10, 2021, 1:16 PM	V-048FV013	Valve Condition	
WO-66316	1	Completed	44550.37207	44550	Valve Maintenance Report	December 20, 2021, 9:26 AM	V-048HV007	Valve Condition	
WO-47682	84	Completed	44354.4026	44354	CUSTOMER CALLED TO REPORT A WTER LEAK THAT IS CRACKING THE PAVEMENT AND SHOTTING IN THE AIR .	June 8, 2021, 3:56 PM	V-048JV002	Valve Condition	Good
WO-53571	88	Completed	44410.77826	44412	Repair service line. Private side repaired and replaced 8/2/21	August 4, 2021, 7:24 AM	V-048JV004	Valve Condition	
WO-53571	88	Completed	44410.77826	44412	Repair service line. Private side repaired and replaced 8/2/21	August 4, 2021, 7:24 AM	V-048JV005	Valve Condition	
WO-53571	88	Completed	44410.77826	44412	Repair service line. Private side repaired and replaced 8/2/21	August 4, 2021, 7:24 AM	V-048JV007	Valve Condition	
WO-61454	1	Completed	44492.07707	44493	Repair water main		V-048JV013	Valve Condition	
WO-61454	1	Completed	44492.07707	44493	Repair water main		V-048JV015	Valve Condition	
WO-43729	1	Completed	44321.41499	44321	Valve Maintenance Report	May 5, 2021, 10:01 AM	V-048JV016	Valve Condition	Good
WO-43727	1	Completed	44321.41128	44321	Valve Maintenance Report	May 5, 2021, 9:56 AM	V-048JV017	Valve Condition	Good
WO-61454	1	Completed	44492.07707	44493	Repair water main		V-048JV021	Valve Condition	
WO-60208	1	Completed	44480.44687	44480	Valve Maintenance Report	October 11, 2021, 10:46 AM	V-048JV023	Valve Condition	
WO-61454	1	Completed	44492.07707	44493	Repair water main		V-048JV024	Valve Condition	
WO-32843	41	Completed	44204.34999	44215	Contractor shut request	January 19, 2021, 8:23 AM	V-048JV028	Valve Condition	
WO-58889	1	Completed	44467.46854	44467	Valve Maintenance Report		V-048JV030	Valve Condition	
WO-32846	41	Completed	44204.35638	44204	Contractor shut request	January 8, 2021, 2:25 PM	V-048JV031	Valve Condition	
WO-48650	1	Completed	44362.43028	44362	Valve Maintenance Report	June 15, 2021, 10:22 AM	V-048JV034	Valve Condition	
WO-58889	1	Completed	44467.46854	44467	Valve Maintenance Report		V-048JV036	Valve Condition	
WO-57199	683	Completed	44450.98009	44451	Work site details for reporting	September 12, 2021, 5:29 PM	V-048MV008	Valve Condition	Good
WO-57199	683	Completed	44450.98009	44451	Work site details for reporting	September 12, 2021, 5:29 PM	V-048MV016	Valve Condition	Good
WO-57199	683	Completed	44450.98009	44451	Work site details for reporting	September 12, 2021, 5:29 PM	V-048MV018	Valve Condition	Good
WO-57199	683	Completed	44450.98009	44451	Work site details for reporting	September 12, 2021, 5:29 PM	V-048MV019	Valve Condition	Good
WO-36319	21	Completed	44238.44232	44467	Valve is inoperable and requires replacement	September 30, 2021, 11:21 AM	V-048NV001	Valve Condition	
WO-37092	84	Completed	44248.37943	44248	Water main break flooding the street called out to curt	February 21, 2021, 9:51 PM	V-048NV002	Valve Condition	Fair
WO-37092	84	Completed	44248.37943	44248	Water main break flooding the street called out to curt	February 21, 2021, 9:51 PM	V-048NV003	Valve Condition	Fair
WO-37092	84	Completed	44248.37943	44248	Water main break flooding the street called out to curt	February 21, 2021, 9:51 PM	V-048NV004	Valve Condition	Fair
WO-36319	21	Completed	44238.44232	44467	Valve is inoperable and requires replacement	September 30, 2021, 11:21 AM	V-048NV005	Valve Condition	
WO-37092	84	Completed	44248.37943	44248	Water main break flooding the street called out to curt	February 21, 2021, 9:51 PM	V-048NV009	Valve Condition	Fair
WO-33895	1	Completed	44215.49357	44217	Valve Maintenance Report	January 21, 2021, 3:13 PM	V-048RV008	Valve Condition	
WO-60741	1	Completed	44484.29577	44484	Valve Maintenance Report		V-048SV022	Valve Condition	
WO-34006	1	Completed	44216.34564	44218	Valve Maintenance Report	January 22, 2021, 2:55 PM	V-048SV025	Valve Condition	
WO-36041	1	Completed	44235.56875	44243	Repair water main		V-048SV029	Valve Condition	
WO-60741	1	Completed	44484.29577	44484	Valve Maintenance Report		V-048SV030	Valve Condition	
WO-34006	1	Completed	44216.34564	44218	Valve Maintenance Report	January 22, 2021, 2:55 PM	V-048SV039	Valve Condition	
WO-34006	1	Completed	44216.34564	44218	Valve Maintenance Report	January 22, 2021, 2:55 PM	V-048SV040	Valve Condition	
WO-34006	1	Completed	44216.34564	44218	Valve Maintenance Report	January 22, 2021, 2:55 PM	V-048SV053	Valve Condition	
WO-34006	1	Completed	44216.34564	44218	Valve Maintenance Report	January 22, 2021, 2:55 PM	V-048SV055	Valve Condition	
WO-34078	41	Completed	44216.70149	44216	Contractor shut request		V-048SV060	Valve Condition	
WO-41747	1	Completed	44301.50824	44301	Valve Maintenance Report	April 15, 2021, 2:02 PM	V-049AV006	Valve Condition	Good
WO-41747	1	Completed	44301.50824	44301	Valve Maintenance Report	April 15, 2021, 2:02 PM	V-049AV049	Valve Condition	Good
WO-51528	1	Completed	44386.28897	44439	Repair water main		V-049BV050	Valve Condition	
WO-51552	1	Completed	44386.37372	44389	Valve Maintenance Report	July 12, 2021, 7:53 AM	V-049BV065	Valve Condition	Poor
WO-51552	1	Completed	44386.37372	44389	Valve Maintenance Report	July 12, 2021, 7:53 AM	V-049BV076	Valve Condition	Poor
WO-35361	85	Completed	44229.54795	44230	Repair water main	February 5, 2021, 6:50 AM	V-049CV017	Valve Condition	Good
WO-35361	85	Completed	44229.54795	44230	Repair water main	February 5, 2021, 6:50 AM	V-049CV022	Valve Condition	Fair
WO-54164	21	Completed	44417.32785	44420	Valve requires replacement	August 13, 2021, 1:35 PM	V-049EV002	Valve Condition	
WO-66316	1	Completed	44550.37207	44550	Valve Maintenance Report	December 20, 2021, 9:26 AM	V-049EV004	Valve Condition	
WO-66316	1	Completed	44550.37207	44550	Valve Maintenance Report	December 20, 2021, 9:26 AM	V-049EV007	Valve Condition	
WO-54024	43	Completed	44414.35395	44414	Test shut	August 6, 2021, 9:27 AM	V-049EV009	Valve Condition	
WO-54164	21	Completed	44417.32785	44420	Valve requires replacement	August 13, 2021, 1:35 PM	V-049EV011	Valve Condition	
WO-54024	43	Completed	44414.35395	44414	Test shut	August 6, 2021, 9:27 AM	V-049EV012	Valve Condition	
WO-51550	1	Completed	44386.37422	44389	Valve Maintenance Report	July 12, 2021, 7:53 AM	V-049EV025	Valve Condition	Poor
WO-55861	1	Completed	44435.37406	44473	Repair water main		V-049EV027	Valve Condition	
WO-55861	1	Completed	44435.37406	44473	Repair water main		V-049EV028	Valve Condition	
WO-51550	1	Completed	44386.37422	44389	Valve Maintenance Report	July 12, 2021, 7:53 AM	V-049EV029	Valve Condition	Poor
WO-34006	1	Completed	44216.34564	44218	Valve Maintenance Report	January 22, 2021, 2:55 PM	V-049EV030	Valve Condition	
WO-51528	1	Completed	44386.28897	44439	Repair water main		V-049EV031	Valve Condition	
WO-51550	1	Completed	44386.37422	44389	Valve Maintenance Report	July 12, 2021, 7:53 AM	V-049EV032	Valve Condition	Poor
WO-51552	1	Completed	44386.37372	44389	Valve Maintenance Report	July 12, 2021, 7:53 AM	V-049FV001	Valve Condition	Poor
WO-51552	1	Completed	44386.37372	44389	Valve Maintenance Report	July 12, 2021, 7:53 AM	V-049FV003	Valve Condition	Poor

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-51552	1	Completed	44386.37372	44389	Valve Maintenance Report	July 12, 2021, 7:53 AM	V-049FV007	Valve Condition	Poor
WO-32736	1	Completed	44203.54148	44208	Repair water main. 6". No parking already posted. Emergency 1 call placed for tomorrow	January 21, 2021, 11:39 AM	V-049FV011	Valve Condition	
WO-60541	1	Completed	44482.54584	44482	Valve Maintenance Report	October 13, 2021, 3:01 PM	V-049FV030	Valve Condition	
WO-57481	1	Completed	44454.31078	44453	Valve Maintenance Report		V-049GV024	Valve Condition	
WO-57481	1	Completed	44454.31078	44453	Valve Maintenance Report		V-049GV025	Valve Condition	
WO-59450	1	Completed	44474.35057	44474	Valve Maintenance Report		V-049GV033	Valve Condition	
WO-32908	1	Completed	44204.59619	44208	Repair water main	January 21, 2021, 11:35 AM	V-049GV047	Valve Condition	
WO-37094	84	Completed	44248.45677	44248	customer called to report called to report water leaking into basement and all pouring in the street	February 21, 2021, 11:28 PM	V-049JV007	Valve Condition	Good
WO-33816	1	Completed	44213.82543	44216	Repair water main		V-049JV010	Valve Condition	
WO-33816	1	Completed	44213.82543	44216	Repair water main		V-049JV014	Valve Condition	
WO-34006	1	Completed	44216.34564	44218	Valve Maintenance Report	January 22, 2021, 2:55 PM	V-049JV015	Valve Condition	
WO-34006	1	Completed	44216.34564	44218	Valve Maintenance Report	January 22, 2021, 2:55 PM	V-049JV028	Valve Condition	
WO-35207	1	Completed	44228.36044	44230	Valve Maintenance Report	February 3, 2021, 3:15 PM	V-049JV034	Valve Condition	
WO-35476	21	Completed	44230.27869	44230	Valve is inoperable and requires replacement- Main line leak above valve as well	February 4, 2021, 8:36 AM	V-049JV036	Valve Condition	
WO-57357	1	Completed	44453.34677	44453	Valve Maintenance Report		V-049JV048	Valve Condition	
WO-37094	84	Completed	44248.45677	44248	customer called to report called to report water leaking into basement and all pouring in the street	February 21, 2021, 11:28 PM	V-049JV056	Valve Condition	Good
WO-60541	1	Completed	44482.54584	44482	Valve Maintenance Report	October 13, 2021, 3:01 PM	V-049KV003	Valve Condition	
WO-57481	1	Completed	44454.31078	44453	Valve Maintenance Report		V-049LV011	Valve Condition	
WO-32908	1	Completed	44204.59619	44208	Repair water main	January 21, 2021, 11:35 AM	V-049LV015	Valve Condition	
WO-38446	401	Completed	44264.01739	44264	Dividing Pressure Valve Maintenance Report	March 9, 2021, 12:28 AM	V-049LV037	Valve Condition	
WO-38448	401	Completed	44264.02938	44264	Dividing Pressure Valve Maintenance Report	March 9, 2021, 12:45 AM	V-049LV039	Valve Condition	
WO-38167	401	Completed	44259.46655	44259	Dividing Pressure Valve Maintenance Report	March 4, 2021, 11:13 AM	V-049MV040	Valve Condition	Good
WO-52456	88	Completed	44396.57568	44432	Repair service line	August 24, 2021, 9:54 AM	V-049MV046	Valve Condition	
WO-38654	401	Completed	44265.42419	44265	Dividing Pressure Valve Maintenance Report	March 10, 2021, 10:15 AM	V-049MV048	Valve Condition	Poor
WO-42678	1	Completed	44311.31321	44312	Repair water main		V-049NV002	Valve Condition	
WO-55483	41	Completed	44431.55665	44431	Contractor shut request	August 23, 2021, 1:24 PM	V-049NV004	Valve Condition	
WO-42678	1	Completed	44311.31321	44312	Repair water main		V-049NV007	Valve Condition	
WO-35207	1	Completed	44228.36044	44230	Valve Maintenance Report	February 3, 2021, 3:15 PM	V-049NV008	Valve Condition	
WO-35207	1	Completed	44228.36044	44230	Valve Maintenance Report	February 3, 2021, 3:15 PM	V-049NV010	Valve Condition	
WO-37940	683	Completed	44257.54004	44260	Work site details for reporting		V-049NV013	Valve Condition	Good
WO-34237	1	Completed	44218.3587	44218	Valve Maintenance Report	January 22, 2021, 11:20 AM	V-049NV020	Valve Condition	Good
WO-38360	85	Completed	44261.99581	44263	Repair water main		V-049NV022	Valve Condition	
WO-55454	1	Completed	44431.42009	44431	Valve Maintenance Report	August 23, 2021, 10:07 AM	V-049NV023	Valve Condition	Good
WO-62905	1	Completed	44506.66359	44508	Repair water main		V-049NV025	Valve Condition	
WO-32313	1	Completed	44200.37233	44200	Valve Maintenance Report	January 4, 2021, 2:18 PM	V-049NV029	Valve Condition	
WO-62905	1	Completed	44506.66359	44508	Repair water main		V-049NV032	Valve Condition	
WO-46232	1	Completed	44341.64301	44341	Valve Maintenance Report	May 25, 2021, 3:29 PM	V-049NV035	Valve Condition	
WO-32313	1	Completed	44200.37233	44200	Valve Maintenance Report	January 4, 2021, 2:18 PM	V-049NV036	Valve Condition	
WO-46235	88	Completed	44341.70436	44342	Repair service line / Contractor doing waste water repair , service line separated at 1" Pex PWSA side.		V-049NV037	Valve Condition	
WO-46235	88	Completed	44341.70436	44342	Repair service line / Contractor doing waste water repair , service line separated at 1" Pex PWSA side.		V-049NV038	Valve Condition	
WO-57357	1	Completed	44453.34677	44453	Valve Maintenance Report		V-049PV002	Valve Condition	
WO-62905	1	Completed	44506.66359	44508	Repair water main		V-049PV003	Valve Condition	
WO-55456	1	Completed	44431.42287	44431	Valve Maintenance Report	August 23, 2021, 10:12 AM	V-049PV004	Valve Condition	
WO-39655	84	Completed	44277.54216	44280	customer called to report water seeping at the curb box	March 26, 2021, 9:43 AM	V-049PV006	Valve Condition	
WO-39655	84	Completed	44277.54216	44280	customer called to report water seeping at the curb box	March 26, 2021, 9:43 AM	V-049PV008	Valve Condition	
WO-37520	41	Completed	44252.36524	44252	Contractor shut request	February 25, 2021, 1:37 PM	V-049PV013	Valve Condition	
WO-37520	41	Completed	44252.36524	44252	Contractor shut request	February 25, 2021, 1:37 PM	V-049PV016	Valve Condition	
WO-37520	41	Completed	44252.36524	44252	Contractor shut request	February 25, 2021, 1:37 PM	V-049PV017	Valve Condition	
WO-62905	1	Completed	44506.66359	44508	Repair water main		V-049PV042	Valve Condition	
WO-65972	84	Completed	44545.36946	44551	Main or service line leak investigation/survey		V-049PV043	Valve Condition	
WO-36159	85	Completed	44237.2961	44238	Repair water main- Dig existing patch	February 15, 2021, 2:09 PM	V-049RV002	Valve Condition	Good
WO-36387	21	Completed	44239.36894	44246	Valve is inoperable and requires replacement Replace 6" valve 049RV004 3 day 1 call was placed Friday 2/12/21 10:00am No parking needs posted.	April 21, 2021, 7:20 AM	V-049RV004	Valve Condition	
WO-36387	21	Completed	44239.36894	44246	Valve is inoperable and requires replacement Replace 6" valve 049RV004 3 day 1 call was placed Friday 2/12/21 10:00am No parking needs posted.	April 21, 2021, 7:20 AM	V-049RV008	Valve Condition	Good
WO-56465	1	Completed	44441.33873	44246	Valve Maintenance Report		V-049RV010	Valve Condition	Good
WO-56465	1	Completed	44441.33873	44246	Valve Maintenance Report		V-049RV011	Valve Condition	Good
WO-36387	21	Completed	44239.36894	44246	Valve is inoperable and requires replacement Replace 6" valve 049RV004 3 day 1 call was placed Friday 2/12/21 10:00am No parking needs posted.	April 21, 2021, 7:20 AM	V-049RV013	Valve Condition	
WO-35452	84	Completed	44229.83826	44230	INVESTIGATE WATER LEAKING IN THE STREET. THE WATER IS LEAKING INTO THE HOME OF 459 40TH ST.....SEE NOTES BELOW	February 3, 2021, 4:33 AM	V-049RV015	Valve Condition	
WO-52419	41	Completed	44396.41567	44396	Contractor shut request	July 19, 2021, 10:02 AM	V-049RV019	Valve Condition	
WO-64193	1	Completed	44523.2973	44522	Valve Maintenance Report		V-049RV022	Valve Condition	
WO-39139	85	Completed	44271.36173	44315	Repair water main.....Leak marked over 6" main for drill holes, post no parking, will need traffic control, standard 3 day one call placed 8:42 am refer to photos attached NO PICTURE DRILL HOLES, SHOWN IN PICTURES 1 call valid 3/19/21 Water surfacing	April 29, 2021, 1:38 PM	V-049RV026	Valve Condition	
WO-39139	85	Completed	44271.36173	44315	Repair water main.....Leak marked over 6" main for drill holes, post no parking, will need traffic control, standard 3 day one call placed 8:42 am refer to photos attached NO PICTURE DRILL HOLES, SHOWN IN PICTURES 1 call valid 3/19/21 Water surfacing	April 29, 2021, 1:38 PM	V-049RV035	Valve Condition	
WO-56465	1	Completed	44441.33873	44246	Valve Maintenance Report		V-049RV044	Valve Condition	Good
WO-36387	21	Completed	44239.36894	44246	Valve is inoperable and requires replacement Replace 6" valve 049RV004 3 day 1 call was placed Friday 2/12/21 10:00am No parking needs posted.	April 21, 2021, 7:20 AM	V-049RV052	Valve Condition	Good
WO-38449	401	Completed	44264.03554	44264	Dividing Pressure Valve Maintenance Report	March 9, 2021, 12:57 AM	V-049SV003	Valve Condition	
WO-64202	1	Completed	44523.32687	44525	Valve Maintenance Report	November 29, 2021, 7:23 AM	V-049SV022	Valve Condition	
WO-38452	401	Completed	44264.05428	44264	Dividing Pressure Valve Maintenance Report	March 9, 2021, 1:20 AM	V-049SV034	Valve Condition	
WO-38451	401	Completed	44264.04655	44264	Dividing Pressure Valve Maintenance Report	March 9, 2021, 1:10 AM	V-049SV060	Valve Condition	
WO-55017	1	Completed	44426.31098	44434	Repair water main		V-050BV010	Valve Condition	
WO-55017	1	Completed	44426.31098	44434	Repair water main		V-050BV012	Valve Condition	
WO-45121	85	Completed	44333.95742	44334	Repair water main	May 18, 2021, 8:09 PM	V-050BV015	Valve Condition	
WO-56708	1	Completed	44444.51839	44444	Repair water main		V-050CV003	Valve Condition	
WO-61525	1	Completed	44494.40298	44503	Repair water main 4" Water leaking over hillside. See pictures in attached W.O.		V-050DV010	Valve Condition	
WO-46451	1	Completed	44343.29099	44344	Repair water main		V-050EV001	Valve Condition	Poor
WO-56863	1	Completed	44447.32536	44448	Valve Maintenance Report	September 9, 2021, 8:02 AM	V-050EV002	Valve Condition	
WO-46451	1	Completed	44343.29099	44344	Repair water main		V-050FV002	Valve Condition	Poor
WO-45183	1	Completed	44334.37143	44334	Valve Maintenance Report	May 18, 2021, 8:58 AM	V-050GV003	Valve Condition	
WO-45208	1	Completed	44334.3905	44334	Valve Maintenance Report	May 18, 2021, 9:25 AM	V-050GV004	Valve Condition	
WO-57527	1	Completed	44454.46464	44453	Valve Maintenance Report	September 15, 2021, 1:24 PM	V-050GV008	Valve Condition	
WO-57197	1	Completed	44450.63034	44454	Repair water main		V-050GV009	Valve Condition	
WO-45211	1	Completed	44334.39512	44334	Valve Maintenance Report	May 18, 2021, 9:32 AM	V-050GV014	Valve Condition	Good
WO-57905	84	Completed	44458.93851	44459	Main or service line leak investigation/survey	September 20, 2021, 1:42 PM	V-050GV017	Valve Condition	
WO-45202	1	Completed	44334.38641	44334	Valve Maintenance Report	May 18, 2021, 9:20 AM	V-050GV018	Valve Condition	Fair
WO-57865	1	Completed	44457.59644	44463	Repair water main		V-050GV019	Valve Condition	
WO-44558	1	Completed	44328.53853	44438	Repair water main		V-050GV020	Valve Condition	
WO-45198	1	Completed	44334.38009	44334	Valve Maintenance Report	May 18, 2021, 9:10 AM	V-050GV021	Valve Condition	
WO-46861	21	Completed	44348.57085	44454	Valve requires replacement (050GV040)	September 15, 2021, 3:31 PM	V-050GV040	Valve Condition	
WO-61839	1	Completed	44496.70972	44502	Repair water main		V-050HV027	Valve Condition	
WO-61839	1	Completed	44496.70972	44502	Repair water main		V-050HV037	Valve Condition	
WO-38161	401	Completed	44259.45854	44259	Dividing Pressure Valve Maintenance Report	March 4, 2021, 11:03 AM	V-050JV009	Valve Condition	Good
WO-52456	88	Completed	44396.57568	44432	Repair service line	August 24, 2021, 9:54 AM	V-050JV011	Valve Condition	
WO-38159	401	Completed	44259.45321	44259	Dividing Pressure Valve Maintenance Report	March 4, 2021, 10:55 AM	V-050JV015	Valve Condition	Good
WO-38259	401	Completed	44260.36765	44260	Dividing Pressure Valve Maintenance Report	March 5, 2021, 8:53 AM	V-050JV018	Valve Condition	Good
WO-38661	401	Completed	44265.44646	44265	Dividing Pressure Valve Maintenance Report	March 10, 2021, 11:21 AM	V-050JV051	Valve Condition	
WO-38661	401	Completed	44265.44646	44265	Dividing Pressure Valve Maintenance Report	March 10, 2021, 11:21 AM	V-050JV052	Valve Condition	
WO-38275	401	Completed	44260.46162	44260	Dividing Pressure Valve Maintenance Report	March 5, 2021, 11:08 AM	V-050KV015	Valve Condition	
WO-66019	1	Completed	44545.56066	44545	Valve Maintenance Report	December 15, 2021, 1:43 PM	V-050KV021	Valve Condition	
WO-65358	1	Completed	44538.50896	44537	Valve Maintenance Report		V-050KV028	Valve Condition	
WO-65358	1	Completed	44538.50896	44537	Valve Maintenance Report		V-050LV001	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-65358	1	Completed	44538.50896	44537	Valve Maintenance Report		V-050LV002	Valve Condition	
WO-65358	1	Completed	44538.50896	44537	Valve Maintenance Report		V-050LV003	Valve Condition	
WO-56121	1	Completed	44439.41777	44440	Repair water main		V-050LV022	Valve Condition	
WO-57629	1	Completed	44455.29464	44455	Repair water main		V-050LV026	Valve Condition	
WO-64743	1	Completed	44531.47758	44537	Repair water main		V-050LV027	Valve Condition	
WO-56121	1	Completed	44439.41777	44440	Repair water main		V-050LV030	Valve Condition	
WO-40637	85	Completed	44287.39545	44301	Repair water main	April 30, 2021, 3:07 PM	V-050LV031	Valve Condition	Good
WO-63661	1	Completed	44517.04043	44518	Repair water main		V-050LV037	Valve Condition	
WO-65358	1	Completed	44538.50896	44537	Valve Maintenance Report		V-050LV038	Valve Condition	
WO-65358	1	Completed	44538.50896	44537	Valve Maintenance Report		V-050LV039	Valve Condition	
WO-63661	1	Completed	44517.04043	44518	Repair water main		V-050LV040	Valve Condition	
WO-63661	1	Completed	44517.04043	44518	Repair water main		V-050LV041	Valve Condition	
WO-40637	85	Completed	44287.39545	44301	Repair water main	April 30, 2021, 3:07 PM	V-050LV042	Valve Condition	
WO-40638	1	Completed	44287.39545	44438	Repair water main		V-050LV043	Valve Condition	Good
WO-57865	1	Completed	44457.59644	44463	Repair water main		V-050LV045	Valve Condition	
WO-45234	1	Completed	44334.4176	44334	Valve Maintenance Report	May 18, 2021, 10:04 AM	V-050LV051	Valve Condition	
WO-45235	1	Completed	44334.41892	44333	Valve Maintenance Report	May 18, 2021, 10:13 AM	V-050LV052	Valve Condition	
WO-45239	1	Completed	44334.42871	44334	Valve Maintenance Report	May 18, 2021, 10:20 AM	V-050LV053	Valve Condition	Good
WO-45225	1	Completed	44334.40791	44333	Valve Maintenance Report	May 18, 2021, 9:54 AM	V-050LV058	Valve Condition	
WO-64743	1	Completed	44531.47758	44537	Repair water main		V-050LV066	Valve Condition	
WO-57629	1	Completed	44455.29464	44455	Repair water main		V-050MV011	Valve Condition	
WO-55940	84	Completed	44437.15816	44437	Main or service line leak investigation/survey/PER CALLER LEAK ON SIDEWALK RUNNING INTO STREET CALLER WALKING BY STATES IT'S A STEADY FLOW IN FRONT OF ADDRESS NO FURTHER INFI IF CUSTOMERS HAS NO WATER OR LOW PRESSURE..BROAD ST & GRAHAM ST	August 29, 2021, 9:09 AM	V-050MV012	Valve Condition	
WO-55940	84	Completed	44437.15816	44437	Main or service line leak investigation/survey/PER CALLER LEAK ON SIDEWALK RUNNING INTO STREET CALLER WALKING BY STATES IT'S A STEADY FLOW IN FRONT OF ADDRESS NO FURTHER INFI IF CUSTOMERS HAS NO WATER OR LOW PRESSURE..BROAD ST & GRAHAM ST	August 29, 2021, 9:09 AM	V-050MV015	Valve Condition	
WO-62020	1	Completed	44498.32467	44497	Valve Maintenance Report		V-050MV025	Valve Condition	
WO-66930	85	Completed	44564.4715	44561	Repair water main		V-050MV028	Valve Condition	
WO-38278	401	Completed	44260.47852	44260	Dividing Pressure Valve Maintenance Report	March 5, 2021, 11:33 AM	V-050NV038	Valve Condition	Good
WO-34853	85	Completed	44224.4051	44225	Repair water main	February 1, 2021, 8:02 AM	V-050PV009	Valve Condition	Good
WO-37839	401	Completed	44257.09185	44257	Dividing Pressure Valve Maintenance Report	March 2, 2021, 2:16 AM	V-050PV012	Valve Condition	
WO-61878	1	Completed	44497.35096	44496	Valve Maintenance Report		V-050RV012	Valve Condition	
WO-33504	43	Completed	44210.43537	44210	Test shut	January 14, 2021, 11:32 AM	V-050RV037	Valve Condition	
WO-33484	21	Completed	44210.37194	44211	Valve is inoperable and requires replacement	January 15, 2021, 2:11 PM	V-050RV039	Valve Condition	
WO-33504	43	Completed	44210.43537	44210	Test shut	January 14, 2021, 11:32 AM	V-050RV040	Valve Condition	
WO-33504	43	Completed	44210.43537	44210	Test shut	January 14, 2021, 11:32 AM	V-050RV041	Valve Condition	
WO-33721	1	Completed	44211.59078	44211	Valve Maintenance Report	January 15, 2021, 2:35 PM	V-050RV042	Valve Condition	
WO-66030	1	Completed	44545.5733	44545	Valve Maintenance Report	December 15, 2021, 2:00 PM	V-050RV045	Valve Condition	
WO-33504	43	Completed	44210.43537	44210	Test shut	January 14, 2021, 11:32 AM	V-050SV001	Valve Condition	
WO-59357	1	Completed	44473.38715	44473	Valve Maintenance Report		V-050SV008	Valve Condition	
WO-59357	1	Completed	44473.38715	44473	Valve Maintenance Report		V-050SV018	Valve Condition	
WO-37833	401	Completed	44257.05734	44257	Dividing Pressure Valve Maintenance Report	March 2, 2021, 1:25 AM	V-051AV012	Valve Condition	
WO-38672	401	Completed	44265.49698	44265	Dividing Pressure Valve Maintenance Report	March 10, 2021, 11:58 AM	V-051AV016	Valve Condition	
WO-37712	401	Completed	44256.0817	44256	Dividing Pressure Valve Maintenance Report	March 1, 2021, 2:00 AM	V-051AV021	Valve Condition	
WO-37711	401	Completed	44256.07842	44256	Dividing Pressure Valve Maintenance Report	March 1, 2021, 2:02 AM	V-051AV024	Valve Condition	
WO-37713	401	Completed	44256.10164	44256	Dividing Pressure Valve Maintenance Report	March 1, 2021, 2:29 AM	V-051AV026	Valve Condition	
WO-42237	1	Completed	44306.56111	44306	Valve Maintenance Report	April 21, 2021, 8:23 AM	V-051AV027	Valve Condition	
WO-37838	401	Completed	44257.08449	44257	Dividing Pressure Valve Maintenance Report	March 2, 2021, 2:04 AM	V-051BV002	Valve Condition	Good
WO-34853	85	Completed	44224.4051	44225	Repair water main	February 1, 2021, 8:02 AM	V-051BV011	Valve Condition	Good
WO-33070	1	Completed	44207.57807	44209	Repair water main. 8" mll. Emergency 1 call placed. Ronnie posted NO PARKING.	January 21, 2021, 11:43 AM	V-051BV018	Valve Condition	
WO-61878	1	Completed	44497.35096	44496	Valve Maintenance Report		V-051CV005	Valve Condition	
WO-33721	1	Completed	44211.59078	44211	Valve Maintenance Report	January 15, 2021, 2:35 PM	V-051CV025	Valve Condition	
WO-33721	1	Completed	44211.59078	44211	Valve Maintenance Report	January 15, 2021, 2:35 PM	V-051CV026	Valve Condition	
WO-33721	1	Completed	44211.59078	44211	Valve Maintenance Report	January 15, 2021, 2:35 PM	V-051CV028	Valve Condition	
WO-33721	1	Completed	44211.59078	44211	Valve Maintenance Report	January 15, 2021, 2:35 PM	V-051CV029	Valve Condition	
WO-33987	1	Completed	44216.29131	44216	Repair water main		V-051DV004	Valve Condition	
WO-35196	85	Completed	44228.29366	44229	Repair water main	February 2, 2021, 12:40 PM	V-051DV016	Valve Condition	
WO-58904	88	Completed	44467.55455	44468	Repair service line Service line damaged while PWSA employee changing meter. Records show service line to be lead. Curb box not visible traced with line locator and marked in concrete sidewalk. emergency 1 call placed at 1130 AM	September 29, 2021, 9:43 PM	V-051DV021	Valve Condition	
WO-58904	88	Completed	44467.55455	44468	Repair service line Service line damaged while PWSA employee changing meter. Records show service line to be lead. Curb box not visible traced with line locator and marked in concrete sidewalk. emergency 1 call placed at 1130 AM	September 29, 2021, 9:43 PM	V-051DV022	Valve Condition	
WO-58904	88	Completed	44467.55455	44468	Repair service line Service line damaged while PWSA employee changing meter. Records show service line to be lead. Curb box not visible traced with line locator and marked in concrete sidewalk. emergency 1 call placed at 1130 AM	September 29, 2021, 9:43 PM	V-051DV026	Valve Condition	
WO-37835	401	Completed	44257.06757	44257	Dividing Pressure Valve Maintenance Report	March 2, 2021, 1:39 AM	V-051EV001	Valve Condition	
WO-37834	401	Completed	44257.06293	44257	Dividing Pressure Valve Maintenance Report	March 2, 2021, 1:34 AM	V-051EV002	Valve Condition	
WO-34039	41	Completed	44216.52147	44216	Contractor shut request	January 20, 2021, 12:36 PM	V-051EV004	Valve Condition	
WO-64563	1	Completed	44529.57808	44529	Valve Maintenance Report	November 29, 2021, 3:06 PM	V-051EV005	Valve Condition	Good
WO-32530	1	Completed	44202.40029	44208	Valve Maintenance Report	January 12, 2021, 10:17 AM	V-051EV008	Valve Condition	
WO-60475	1	Completed	44482.38016	44482	Valve Maintenance Report	October 13, 2021, 9:26 AM	V-051EV009	Valve Condition	
WO-34024	1	Completed	44216.43081	44216	Valve Maintenance Report	January 20, 2021, 10:24 AM	V-051EV022	Valve Condition	
WO-32598	1	Completed	44202.52748	44202	Valve Maintenance Report	January 6, 2021, 12:43 PM	V-051EV025	Valve Condition	
WO-34013	1	Completed	44216.37273	44216	Valve Maintenance Report	January 20, 2021, 9:01 AM	V-051EV026	Valve Condition	
WO-34015	1	Completed	44216.38009	44216	Valve Maintenance Report	January 20, 2021, 9:13 AM	V-051EV028	Valve Condition	
WO-32903	1	Completed	44204.58254	44204	Valve Maintenance Report	January 8, 2021, 2:03 PM	V-051EV030	Valve Condition	
WO-32678	1	Completed	44203.35542	44208	Valve Maintenance Report	January 12, 2021, 12:56 PM	V-051EV035	Valve Condition	Good
WO-64504	88	Completed	44529.00285	44530	Repair service line- if drilled, Drill Sheet work order MUST be completed	November 30, 2021, 8:45 AM	V-051EV036	Valve Condition	
WO-32611	1	Completed	44202.57319	44202	Valve Maintenance Report	January 6, 2021, 1:50 PM	V-051EV038	Valve Condition	Good
WO-34026	1	Completed	44216.44644	44216	Valve Maintenance Report	January 20, 2021, 10:47 AM	V-051EV039	Valve Condition	
WO-32618	1	Completed	44202.59268	44208	Valve Maintenance Report	January 12, 2021, 1:14 PM	V-051EV040	Valve Condition	
WO-34297	85	Completed	44218.56744	44218	Repair water main	January 23, 2021, 1:45 AM	V-051EV043	Valve Condition	
WO-37832	401	Completed	44257.04787	44257	Dividing Pressure Valve Maintenance Report	March 2, 2021, 1:11 AM	V-051EV044	Valve Condition	
WO-34031	1	Completed	44216.46392	44216	Valve Maintenance Report	January 20, 2021, 11:12 AM	V-051EV047	Valve Condition	
WO-34297	85	Completed	44218.56744	44218	Repair water main	January 23, 2021, 1:45 AM	V-051EV049	Valve Condition	
WO-32899	1	Completed	44204.55961	44204	Valve Maintenance Report	January 8, 2021, 1:31 PM	V-051EV051	Valve Condition	
WO-37714	401	Completed	44256.10537	44264	Dividing Pressure Valve Maintenance Report	March 9, 2021, 1:33 AM	V-051EV058	Valve Condition	
WO-33070	1	Completed	44207.57807	44209	Repair water main. 8" mll. Emergency 1 call placed. Ronnie posted NO PARKING.	January 21, 2021, 11:43 AM	V-051FV014	Valve Condition	
WO-36520	84	Completed	44241.32129	44242	Main or service line leak investigation/survey- REPORTS OF WATER GUSHING IN STREET. CUSTOMER THAT REPORTED LEAK, STATED THAT HE HAS LOW PRESSURE.		V-051FV034	Valve Condition	
WO-45068	1	Completed	44333.57974	44355	Valve Maintenance Report	June 8, 2021, 2:30 PM	V-051GV025	Valve Condition	
WO-62349	1	Completed	44502.5456	44504	Repair water main		V-051GV031	Valve Condition	
WO-35196	85	Completed	44228.29366	44229	Repair water main	February 2, 2021, 12:40 PM	V-051HV008	Valve Condition	
WO-40425	84	Completed	44285.65045	44285	Main or service line leak investigation/survey, SPOKE WITH JIM FROM AECOM 412-390-9816, THEY HIT WATER S/L AND NEED A SHUT	March 30, 2021, 10:42 PM	V-051HV015	Valve Condition	
WO-64512	1	Completed	44529.28816	44530	Repair water main		V-051KV002	Valve Condition	
WO-64512	1	Completed	44529.28816	44530	Repair water main		V-051KV004	Valve Condition	
WO-36520	84	Completed	44241.32129	44242	Main or service line leak investigation/survey- REPORTS OF WATER GUSHING IN STREET. CUSTOMER THAT REPORTED LEAK, STATED THAT HE HAS LOW PRESSURE.		V-051KV005	Valve Condition	
WO-36520	84	Completed	44241.32129	44242	Main or service line leak investigation/survey- REPORTS OF WATER GUSHING IN STREET. CUSTOMER THAT REPORTED LEAK, STATED THAT HE HAS LOW PRESSURE.		V-051KV008	Valve Condition	
WO-56270	1	Completed	44440.41207	44378	Valve Maintenance Report		V-051KV010	Valve Condition	
WO-56270	1	Completed	44440.41207	44378	Valve Maintenance Report		V-051KV012	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-36520	84	Completed	44241.32129	44242	Main or service line leak investigation/survey- REPORTS OF WATER GUSHING IN STREET. CUSTOMER THAT REPORTED LEAK, STATED THAT HE HAS LOW PRESSURE.		V-051KV013	Valve Condition	
WO-45068	1	Completed	44333.57974	44355	Valve Maintenance Report	June 8, 2021, 2:30 PM	V-051LV005	Valve Condition	
WO-36520	84	Completed	44241.32129	44242	Main or service line leak investigation/survey- REPORTS OF WATER GUSHING IN STREET. CUSTOMER THAT REPORTED LEAK, STATED THAT HE HAS LOW PRESSURE.		V-051LV008	Valve Condition	
WO-50772	1	Completed	44378.4272	44424	Valve Maintenance Report	August 17, 2021, 12:55 AM	V-051LV010	Valve Condition	Good
WO-50772	1	Completed	44378.4272	44424	Valve Maintenance Report	August 17, 2021, 12:55 AM	V-051LV012	Valve Condition	Good
WO-50663	1	Completed	44377.50977	44383	Valve Maintenance Report	July 6, 2021, 7:24 AM	V-051LV015	Valve Condition	
WO-62349	1	Completed	44502.5456	44504	Repair water main		V-051LV017	Valve Condition	
WO-56270	1	Completed	44440.41207	44378	Valve Maintenance Report		V-051LV019	Valve Condition	
WO-50772	1	Completed	44378.4272	44424	Valve Maintenance Report	August 17, 2021, 12:55 AM	V-051LV048	Valve Condition	Good
WO-50772	1	Completed	44378.4272	44424	Valve Maintenance Report	August 17, 2021, 12:55 AM	V-051LV049	Valve Condition	Good
WO-50772	1	Completed	44378.4272	44424	Valve Maintenance Report	August 17, 2021, 12:55 AM	V-051LV056	Valve Condition	Good
WO-40425	84	Completed	44285.65045	44285	Main or service line leak investigation/survey, SPOKE WITH JIM FROM AECOM 412-390-9816, THEY HIT WATER S/L AND NEED A SHUT	March 30, 2021, 10:42 PM	V-051MV004	Valve Condition	
WO-42308	1	Completed	44307.38893	44307	Valve Maintenance Report	April 21, 2021, 12:41 PM	V-051PV002	Valve Condition	Good
WO-42308	1	Completed	44307.38893	44307	Valve Maintenance Report	April 21, 2021, 12:41 PM	V-051PV008	Valve Condition	Good
WO-43002	21	Completed	44314.36124	44384	Valve requires replacement. See LD notes below and pictures below THIS VALVE WAS NEVER REPLACED. IT ENDED UP BEING A WASTE WATER FOR UPMC HOSPITAL		V-051RV003	Valve Condition	Good
WO-61562	1	Completed	44494.54894	44503	Valve Maintenance Report		V-051SV004	Valve Condition	
WO-59772	1	Completed	44475.58773	44475	Valve Maintenance Report	October 6, 2021, 3:12 PM	V-051SV027	Valve Condition	
WO-59772	1	Completed	44475.58773	44475	Valve Maintenance Report	October 6, 2021, 3:12 PM	V-051SV030	Valve Condition	
WO-61749	1	Completed	44496.35034	44496	Valve Maintenance Report	October 27, 2021, 8:27 AM	V-051SV044	Valve Condition	
WO-35590	1	Completed	44231.15193	44438	Repair water main		V-051SV059	Valve Condition	Good
WO-35590	1	Completed	44231.15193	44438	Repair water main		V-051SV060	Valve Condition	Good
WO-59772	1	Completed	44475.58773	44475	Valve Maintenance Report	October 6, 2021, 3:12 PM	V-051SV061	Valve Condition	
WO-35590	1	Completed	44231.15193	44438	Repair water main		V-051SV064	Valve Condition	Good
WO-55932	84	Completed	44436.10634	44436	Main or service line leak investigation/survey. CONTRACTORS FOUND 6IN MAIN LEAKING	August 28, 2021, 7:10 AM	V-052AV003	Valve Condition	
WO-55932	84	Completed	44436.10634	44436	Main or service line leak investigation/survey. CONTRACTORS FOUND 6IN MAIN LEAKING	August 28, 2021, 7:10 AM	V-052AV012	Valve Condition	
WO-55935	1	Completed	44436.65894	44437	Valve Maintenance Report	August 29, 2021, 4:36 PM	V-052AV013	Valve Condition	
WO-55935	1	Completed	44436.65894	44437	Valve Maintenance Report	August 29, 2021, 4:36 PM	V-052AV028	Valve Condition	
WO-39121	41	Completed	44271.17593	44272	Contractor shut request	March 17, 2021, 7:29 AM	V-052BV006	Valve Condition	
WO-38854	43	Completed	44267.40315	44272	Test shut	March 17, 2021, 7:31 AM	V-052BV007	Valve Condition	
WO-39002	21	Completed	44270.38381	44271	Valve is inoperable and requires replacement DOMI -OP-2021-02805	March 17, 2021, 11:00 AM	V-052BV008	Valve Condition	
WO-41698	21	Completed	44301.29094	44302	Valve requires replacement	April 16, 2021, 9:38 AM	V-052BV009	Valve Condition	
WO-41697	21	Completed	44301.28981	44301	Valve requires replacement	April 16, 2021, 9:40 AM	V-052BV013	Valve Condition	
WO-56312	1	Completed	44440.46261	44301	Valve Maintenance Report		V-052BV014	Valve Condition	
WO-56312	1	Completed	44440.46261	44301	Valve Maintenance Report		V-052BV015	Valve Condition	
WO-56312	1	Completed	44440.46261	44301	Valve Maintenance Report		V-052BV017	Valve Condition	
WO-41785	21	Completed	44301.72252	44302	DUG & REPLACED 4" VALUE	April 16, 2021, 7:08 AM	V-052BV018	Valve Condition	Good
WO-56312	1	Completed	44440.46261	44301	Valve Maintenance Report		V-052BV019	Valve Condition	
WO-38854	43	Completed	44267.40315	44272	Test shut	March 17, 2021, 7:31 AM	V-052CV007	Valve Condition	
WO-39121	41	Completed	44271.17593	44272	Contractor shut request	March 17, 2021, 7:29 AM	V-052CV017	Valve Condition	
WO-39354	1	Completed	44273.30946	44273	Valve Maintenance Report	March 18, 2021, 7:29 AM	V-052DV002	Valve Condition	
WO-38045	41	Completed	44258.47345	44258	Contractor shut request	March 3, 2021, 11:30 AM	V-052DV006	Valve Condition	Fair
WO-45325	84	Completed	44334.75393	44335	Main or service line leak investigation/survey/MAJOR WATER BREAK ON SIDEWALK ALOT OF WATER FLOWING FLOODING BASEMENT WATER RUNNING INTO STREET WATER IS ON AND PRESSURE IS FINE JUST REALIZED 20 MINTUTES AGO UNK DAMAGE INSIDE HOME NEIGHBOR CALLING NEVER SPOKE WITH OWNER/ 911 JUST CALLED FIRE DEPT ON SCENE JUSTIN 412 255 2935	May 19, 2021, 2:12 AM	V-052DV011	Valve Condition	
WO-37006	84	Completed	44246.59711	44247	Main or service line leak investigation/survey/ PER EOC-911/WATER MAIN BREAK IN MIDDLE OF THE STREET WATER BLOWING AND STREET BUCKLING IN FRONT OF EMS HEADQUARTERS NO FURTHER INFO	February 20, 2021, 7:14 PM	V-052DV013	Valve Condition	Good
WO-38998	1	Completed	44270.37433	44270	Valve Maintenance Report	March 15, 2021, 11:27 AM	V-052DV019	Valve Condition	
WO-39362	1	Completed	44273.31312	44273	Valve Maintenance Report	March 18, 2021, 7:33 AM	V-052DV020	Valve Condition	Fair
WO-38633	1	Completed	44265.35212	44278	Valve Maintenance Report	March 23, 2021, 8:15 AM	V-052DV022	Valve Condition	
WO-38028	41	Completed	44258.46749	44279	Contractor shut request	March 24, 2021, 7:12 AM	V-052DV025	Valve Condition	
WO-39500	41	Completed	44274.39897	44274	Contractor shut request	March 19, 2021, 3:19 PM	V-052DV028	Valve Condition	
WO-39500	41	Completed	44274.39897	44274	Contractor shut request	March 19, 2021, 3:19 PM	V-052DV029	Valve Condition	
WO-38054	41	Completed	44258.49159	44258	Contractor shut request	March 3, 2021, 11:51 AM	V-052DV031	Valve Condition	
WO-39500	41	Completed	44274.39897	44274	Contractor shut request	March 19, 2021, 3:19 PM	V-052DV032	Valve Condition	
WO-45325	84	Completed	44334.75393	44335	Main or service line leak investigation/survey/MAJOR WATER BREAK ON SIDEWALK ALOT OF WATER FLOWING FLOODING BASEMENT WATER RUNNING INTO STREET WATER IS ON AND PRESSURE IS FINE JUST REALIZED 20 MINTUTES AGO UNK DAMAGE INSIDE HOME NEIGHBOR CALLING NEVER SPOKE WITH OWNER/ 911 JUST CALLED FIRE DEPT ON SCENE JUSTIN 412 255 2935	May 19, 2021, 2:12 AM	V-052DV034	Valve Condition	
WO-42787	683	Completed	44312.55081	44320	Work site details for reporting		V-052DV036	Valve Condition	Good
WO-37006	84	Completed	44246.59711	44247	Main or service line leak investigation/survey/ PER EOC-911/WATER MAIN BREAK IN MIDDLE OF THE STREET WATER BLOWING AND STREET BUCKLING IN FRONT OF EMS HEADQUARTERS NO FURTHER INFO	February 20, 2021, 7:14 PM	V-052DV048	Valve Condition	Good
WO-38854	43	Completed	44267.40315	44272	Test shut	March 17, 2021, 7:31 AM	V-052EV011	Valve Condition	
WO-38854	43	Completed	44267.40315	44272	Test shut	March 17, 2021, 7:31 AM	V-052EV016	Valve Condition	
WO-39121	41	Completed	44271.17593	44272	Contractor shut request	March 17, 2021, 7:29 AM	V-052EV032	Valve Condition	
WO-61951	1	Completed	44497.50137	44497	Valve Maintenance Report	October 28, 2021, 12:36 PM	V-052FV007	Valve Condition	Good
WO-56312	1	Completed	44440.46261	44301	Valve Maintenance Report		V-052FV010	Valve Condition	Good
WO-61951	1	Completed	44497.50137	44497	Valve Maintenance Report	October 28, 2021, 12:36 PM	V-052FV011	Valve Condition	Good
WO-61951	1	Completed	44497.50137	44497	Valve Maintenance Report	October 28, 2021, 12:36 PM	V-052FV013	Valve Condition	Good
WO-53897	1	Completed	44413.34733	44413	Valve Maintenance Report	August 5, 2021, 1:14 PM	V-052FV014	Valve Condition	Good
WO-61951	1	Completed	44497.50137	44497	Valve Maintenance Report	October 28, 2021, 12:36 PM	V-052GV006	Valve Condition	Good
WO-51022	84	Completed	44382.60372	44404	Main or service line leak investigation/survey/WATER LEAK OUTSIDE IN FRONT OF DRIVEWAY NEED WATER SHUT AT CURB FOR REPAIRS		V-052GV015	Valve Condition	Fair
WO-51022	84	Completed	44382.60372	44404	Main or service line leak investigation/survey/WATER LEAK OUTSIDE IN FRONT OF DRIVEWAY NEED WATER SHUT AT CURB FOR REPAIRS		V-052HV001	Valve Condition	Good
WO-65385	1	Completed	44538.79722	44539	Valve Maintenance Report	December 9, 2021, 11:17 AM	V-052HV002	Valve Condition	Good
WO-65385	1	Completed	44538.79722	44539	Valve Maintenance Report	December 9, 2021, 11:17 AM	V-052HV006	Valve Condition	Good
WO-39364	1	Completed	44273.3158	44273	Valve Maintenance Report	March 18, 2021, 7:37 AM	V-052HV008	Valve Condition	
WO-38998	1	Completed	44270.37433	44270	Valve Maintenance Report	March 15, 2021, 11:27 AM	V-052HV010	Valve Condition	
WO-64418	1	Completed	44525.7466	44525	Valve Maintenance Report	November 25, 2021, 6:05 PM	V-052HV016	Valve Condition	
WO-63437	84	Completed	44512.75959	44512	Main or service line leak investigation/survey	November 18, 2021, 7:34 AM	V-052HV017	Valve Condition	
WO-41102	85	Completed	44294.49602	44299	Repair water main	April 13, 2021, 6:46 AM	V-052HV023	Valve Condition	Good
WO-65385	1	Completed	44538.79722	44539	Valve Maintenance Report	December 9, 2021, 11:17 AM	V-052HV030	Valve Condition	Good
WO-62988	1	Completed	44508.39644	44510	Repair water main		V-052JV019	Valve Condition	Good
WO-35117	1	Completed	44226.2209	44228	Repair water main		V-052JV033	Valve Condition	
WO-35117	1	Completed	44226.2209	44228	Repair water main		V-052JV046	Valve Condition	
WO-36858	1	Completed	44245.34415	44270	Valve Maintenance Report	March 15, 2021, 11:32 AM	V-052JV065	Valve Condition	Good
WO-56312	1	Completed	44440.46261	44301	Valve Maintenance Report		V-052KV008	Valve Condition	Good
WO-65385	1	Completed	44538.79722	44539	Valve Maintenance Report	December 9, 2021, 11:17 AM	V-052LV022	Valve Condition	Good
WO-53443	43	Completed	44410.02156	44410	Test shut	August 2, 2021, 2:49 AM	V-052NV005	Valve Condition	
WO-54229	1	Completed	44418.09496	44418	Valve Maintenance Report	August 10, 2021, 6:49 AM	V-052NV015	Valve Condition	
WO-50020	41	Completed	44371.73377	44372	Contractor shut request	June 25, 2021, 12:05 PM	V-052NV025	Valve Condition	Fair
WO-53216	1	Completed	44405.43365	44405	Valve Maintenance Report	September 15, 2021, 1:33 PM	V-052NV029	Valve Condition	
WO-53216	1	Completed	44405.43365	44405	Valve Maintenance Report	September 15, 2021, 1:33 PM	V-052NV036	Valve Condition	Fair
WO-58380	1	Completed	44462.33702	44462	Valve Maintenance Report	September 23, 2021, 11:40 AM	V-052RV020	Valve Condition	
WO-58380	1	Completed	44462.33702	44462	Valve Maintenance Report	September 23, 2021, 11:40 AM	V-052RV024	Valve Condition	
WO-36565	1	Completed	44241.94807	44244	Repair water main		V-052SV001	Valve Condition	Good
WO-36564	85	Completed	44241.94807	44242	Repair water main	February 16, 2021, 7:39 AM	V-052SV002	Valve Condition	Good
WO-62791	1	Completed	44505.33656	44504	Valve Maintenance Report		V-052SV019	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-62791	1	Completed	44505.33656	44504	Valve Maintenance Report		V-052SV025	Valve Condition	
WO-37302	1	Completed	44250.60532	44258	Repair water main		V-053BV004	Valve Condition	
WO-50480	1	Completed	44376.56364	44439	Repair water main		V-053BV008	Valve Condition	
WO-38286	21	Completed	44260.54499	44263	Valve is inoperable and requires replacement 8" Water is surfacing. See notes and pictures below..... 8" Valve 053CV005 is leaking and needs replaced, packing leak is running across sidewalk and down along the curb, standard 3 day one call placed, post no parking, refer to photos, tension wires for telephone pole will be in the dig site, suggest looking at job before scheduling crew	March 9, 2021, 7:49 AM	V-053CV005	Valve Condition	
WO-58380	1	Completed	44462.33702	44462	Valve Maintenance Report	September 23, 2021, 11:40 AM	V-053CV018	Valve Condition	
WO-58127	1	Completed	44460.45575	44463	Valve Maintenance Report	September 24, 2021, 1:34 PM	V-053CV025	Valve Condition	
WO-38751	85	Completed	44266.41913	44267	Repair water main 6" main water showing on Forbes Ave, street below	March 12, 2021, 7:47 AM	V-053CV028	Valve Condition	Good
WO-38751	85	Completed	44266.41913	44267	Repair water main 6" main water showing on Forbes Ave, street below	March 12, 2021, 7:47 AM	V-053CV032	Valve Condition	Good
WO-54970	88	Completed	44425.48419	44434	Repair service line		V-053DV006	Valve Condition	
WO-62791	1	Completed	44505.33656	44504	Valve Maintenance Report		V-053DV011	Valve Condition	
WO-54970	88	Completed	44425.48419	44434	Repair service line		V-053DV018	Valve Condition	
WO-60931	1	Completed	44487.43663	44490	Valve Maintenance Report	October 21, 2021, 1:42 PM	V-053GV003	Valve Condition	
WO-60931	1	Completed	44487.43663	44490	Valve Maintenance Report	October 21, 2021, 1:42 PM	V-053GV004	Valve Condition	
WO-58380	1	Completed	44462.33702	44462	Valve Maintenance Report	September 23, 2021, 11:40 AM	V-053HV003	Valve Condition	
WO-48474	85	Completed	44361.40851	44361	Repair water main	June 14, 2021, 9:49 AM	V-053HV005	Valve Condition	Good
WO-48474	85	Completed	44361.40851	44361	Repair water main	June 14, 2021, 9:49 AM	V-053HV010	Valve Condition	Good
WO-60931	1	Completed	44487.43663	44490	Valve Maintenance Report	October 21, 2021, 1:42 PM	V-053HV011	Valve Condition	
WO-58127	1	Completed	44460.45575	44463	Valve Maintenance Report	September 24, 2021, 1:34 PM	V-053HV013	Valve Condition	
WO-58127	1	Completed	44460.45575	44463	Valve Maintenance Report	September 24, 2021, 1:34 PM	V-053HV014	Valve Condition	
WO-62320	1	Completed	44502.43647	44505	Valve Maintenance Report	November 5, 2021, 3:01 PM	V-053HV015	Valve Condition	
WO-62320	1	Completed	44502.43647	44505	Valve Maintenance Report	November 5, 2021, 3:01 PM	V-053HV016	Valve Condition	
WO-58380	1	Completed	44462.33702	44462	Valve Maintenance Report	September 23, 2021, 11:40 AM	V-053HV018	Valve Condition	
WO-62320	1	Completed	44502.43647	44505	Valve Maintenance Report	November 5, 2021, 3:01 PM	V-053HV019	Valve Condition	
WO-58380	1	Completed	44462.33702	44462	Valve Maintenance Report	September 23, 2021, 11:40 AM	V-053HV021	Valve Condition	
WO-58380	1	Completed	44462.33702	44462	Valve Maintenance Report	September 23, 2021, 11:40 AM	V-053HV023	Valve Condition	
WO-62320	1	Completed	44502.43647	44505	Valve Maintenance Report	November 5, 2021, 3:01 PM	V-053HV024	Valve Condition	
WO-58127	1	Completed	44460.45575	44463	Valve Maintenance Report	September 24, 2021, 1:34 PM	V-053HV026	Valve Condition	
WO-58380	1	Completed	44462.33702	44462	Valve Maintenance Report	September 23, 2021, 11:40 AM	V-053HV027	Valve Condition	
WO-60931	1	Completed	44487.43663	44490	Valve Maintenance Report	October 21, 2021, 1:42 PM	V-053HV028	Valve Condition	
WO-42244	1	Completed	44306.56791	44306	Valve Maintenance Report	April 20, 2021, 1:41 PM	V-053SV010	Valve Condition	
WO-41883	1	Completed	44302.43791	44302	Valve Maintenance Report	April 16, 2021, 10:36 AM	V-053SV016	Valve Condition	
WO-41883	1	Completed	44302.43791	44302	Valve Maintenance Report	April 16, 2021, 10:36 AM	V-053SV024	Valve Condition	Fair
WO-56482	401	Completed	44441.37493	44441	Dividing Pressure Valve Maintenance Report	September 2, 2021, 9:08 AM	V-053SV027	Valve Condition	
WO-38130	1	Completed	44259.35388	44257	Valve Maintenance Report	March 4, 2021, 8:32 AM	V-054GV007	Valve Condition	
WO-38135	1	Completed	44259.35659	44257	Valve Maintenance Report	March 4, 2021, 8:35 AM	V-054GV008	Valve Condition	
WO-38127	401	Completed	44259.35042	44257	Dividing Pressure Valve Maintenance Report	March 4, 2021, 8:27 AM	V-054GV009	Valve Condition	
WO-42323	1	Completed	44307.42916	44312	Valve Maintenance Report	April 26, 2021, 7:53 AM	V-054HV006	Valve Condition	
WO-42323	1	Completed	44307.42916	44312	Valve Maintenance Report	April 26, 2021, 7:53 AM	V-054HV016	Valve Condition	
WO-49798	1	Completed	44370.46879	44370	Valve Maintenance Report	June 23, 2021, 11:17 AM	V-054JV003	Valve Condition	
WO-49795	1	Completed	44370.46039	44370	Valve Maintenance Report	June 23, 2021, 11:07 AM	V-054JV014	Valve Condition	
WO-54779	1	Completed	44423.42503	44424	DIG AND REPAIR 6" LEAK		V-054JV016	Valve Condition	
WO-49795	1	Completed	44370.46039	44370	Valve Maintenance Report	June 23, 2021, 11:07 AM	V-054JV026	Valve Condition	
WO-60464	1	Completed	44482.32029	44481	Valve Maintenance Report		V-054LV010	Valve Condition	
WO-60464	1	Completed	44482.32029	44481	Valve Maintenance Report		V-054LV013	Valve Condition	
WO-66536	1	Completed	44553.35114	44552	Valve Maintenance Report		V-054LV026	Valve Condition	
WO-60464	1	Completed	44482.32029	44481	Valve Maintenance Report		V-054LV039	Valve Condition	
WO-60464	1	Completed	44482.32029	44481	Valve Maintenance Report		V-054LV044	Valve Condition	
WO-60464	1	Completed	44482.32029	44481	Valve Maintenance Report		V-054LV045	Valve Condition	
WO-66536	1	Completed	44553.35114	44552	Valve Maintenance Report		V-054MV003	Valve Condition	
WO-66536	1	Completed	44553.35114	44552	Valve Maintenance Report		V-054MV004	Valve Condition	
WO-41845	1	Completed	44302.31764	44438	Repair water main		V-054MV005	Valve Condition	
WO-41954	1	Completed	44302.8805	44302	Valve Maintenance Report	April 16, 2021, 9:10 PM	V-054MV006	Valve Condition	
WO-42327	41	Completed	44307.43699	44454	Contractor shut request/PER A FOLINO BLEW OUT A CORPORATION OF MAIN WHEN CLEANING UP IN AREA/ BRANDON 412 427 2502		V-054MV010	Valve Condition	Good
WO-40976	1	Completed	44293.43573	44293	Valve Maintenance Report	April 7, 2021, 10:29 AM	V-054MV011	Valve Condition	
WO-45914	1	Completed	44340.46819	44342	Valve Maintenance Report	May 26, 2021, 8:52 AM	V-054MV012	Valve Condition	Marginal
WO-41955	1	Completed	44302.88522	44302	Valve Maintenance Report	April 16, 2021, 9:17 PM	V-054MV019	Valve Condition	
WO-54779	1	Completed	44423.42503	44424	DIG AND REPAIR 6" LEAK		V-054NV002	Valve Condition	
WO-56698	1	Completed	44443.41362	44449	Repair water main		V-054NV010	Valve Condition	
WO-46002	84	Completed	44340.60091	44340	Main or service line leak investigation/survey, LEAK IN THE STREET - PER 911	May 24, 2021, 7:20 PM	V-054PV003	Valve Condition	
WO-56055	85	Completed	44438.60213	44449	Repair water main	October 1, 2021, 1:32 PM	V-054PV021	Valve Condition	Good
WO-45914	1	Completed	44340.46819	44342	Valve Maintenance Report	May 26, 2021, 8:52 AM	V-054SV001	Valve Condition	Good
WO-47386	1	Completed	44350.5525	44350	Valve Maintenance Report	June 3, 2021, 5:31 PM	V-054SV002	Valve Condition	Good
WO-45914	1	Completed	44340.46819	44342	Valve Maintenance Report	May 26, 2021, 8:52 AM	V-054SV006	Valve Condition	
WO-42331	1	Completed	44307.445	44307	Valve Maintenance Report	April 21, 2021, 12:00 PM	V-054SV007	Valve Condition	Good
WO-45914	1	Completed	44340.46819	44342	Valve Maintenance Report	May 26, 2021, 8:52 AM	V-054SV008	Valve Condition	
WO-47386	1	Completed	44350.5525	44350	Valve Maintenance Report	June 3, 2021, 5:31 PM	V-054SV009	Valve Condition	Good
WO-40977	1	Completed	44293.43853	44293	Valve Maintenance Report	April 7, 2021, 10:33 AM	V-054SV010	Valve Condition	Fair
WO-47386	1	Completed	44350.5525	44350	Valve Maintenance Report	June 3, 2021, 5:31 PM	V-054SV011	Valve Condition	Good
WO-42430	41	Completed	44308.40723	44308	Contractor shut request	April 22, 2021, 12:18 PM	V-054SV013	Valve Condition	Good
WO-36989	1	Completed	44246.43329	44246	Valve Maintenance Report	February 19, 2021, 11:02 AM	V-054SV015	Valve Condition	Good
WO-36999	1	Completed	44246.53575	44248	Valve Maintenance Report	February 21, 2021, 8:08 PM	V-054SV016	Valve Condition	
WO-47386	1	Completed	44350.5525	44350	Valve Maintenance Report	June 3, 2021, 5:31 PM	V-054SV017	Valve Condition	Good
WO-42430	41	Completed	44308.40723	44308	Contractor shut request	April 22, 2021, 12:18 PM	V-054SV018	Valve Condition	Fair
WO-47386	1	Completed	44350.5525	44350	Valve Maintenance Report	June 3, 2021, 5:31 PM	V-054SV019	Valve Condition	Good
WO-47386	1	Completed	44350.5525	44350	Valve Maintenance Report	June 3, 2021, 5:31 PM	V-054SV020	Valve Condition	Good
WO-36999	1	Completed	44246.53575	44248	Valve Maintenance Report	February 21, 2021, 8:08 PM	V-054SV021	Valve Condition	
WO-36999	1	Completed	44246.53575	44248	Valve Maintenance Report	February 21, 2021, 8:08 PM	V-054SV022	Valve Condition	
WO-40975	1	Completed	44293.43264	44293	Valve Maintenance Report	April 7, 2021, 10:25 AM	V-054SV025	Valve Condition	
WO-48540	21	Completed	44361.55068	44368	Valve requires replacement	June 21, 2021, 7:15 AM	V-054SV029	Valve Condition	
WO-33323	1	Completed	44209.37492	44209	Repair water main		V-055BV012	Valve Condition	
WO-33323	1	Completed	44209.37492	44209	Repair water main		V-055BV023	Valve Condition	
WO-35538	401	Completed	44230.5941	44230	Dividing Pressure Valve Maintenance Report	February 3, 2021, 2:23 PM	V-055BV028	Valve Condition	
WO-35535	401	Completed	44230.57827	44230	Dividing Pressure Valve Maintenance Report	February 3, 2021, 2:05 PM	V-055BV030	Valve Condition	
WO-44403	1	Completed	44327.50618	44327	Valve Maintenance Report	May 11, 2021, 2:15 PM	V-055CV010	Valve Condition	
WO-44373	1	Completed	44327.4017	44328	Repair water main	May 12, 2021, 8:19 AM	V-055CV011	Valve Condition	Good
WO-44373	1	Completed	44327.4017	44328	Repair water main	May 12, 2021, 8:19 AM	V-055CV012	Valve Condition	Good
WO-45030	1	Completed	44333.50459	44351	Repair water main- remove old abandoned main		V-055CV014	Valve Condition	
WO-34878	1	Completed	44224.4616	44224	Valve Maintenance Report	January 28, 2021, 11:12 AM	V-055CV033	Valve Condition	
WO-44373	1	Completed	44327.4017	44328	Repair water main	May 12, 2021, 8:19 AM	V-055CV035	Valve Condition	
WO-48109	1	Completed	44357.48161	44358	Valve Maintenance Report	June 11, 2021, 11:07 AM	V-055DV002	Valve Condition	
WO-48541	21	Completed	44361.55106	44364	Valve requires replacement	June 17, 2021, 1:59 PM	V-055DV003	Valve Condition	Good
WO-48109	1	Completed	44357.48161	44358	Valve Maintenance Report	June 11, 2021, 11:07 AM	V-055DV004	Valve Condition	
WO-48109	1	Completed	44357.48161	44358	Valve Maintenance Report	June 11, 2021, 11:07 AM	V-055DV006	Valve Condition	
WO-45030	1	Completed	44333.50459	44351	Repair water main- remove old abandoned main		V-055DV007	Valve Condition	
WO-48109	1	Completed	44357.48161	44358	Valve Maintenance Report	June 11, 2021, 11:07 AM	V-055DV009	Valve Condition	
WO-46547	1	Completed	44343.56714	44343	Valve Maintenance Report	May 27, 2021, 1:39 PM	V-055DV020	Valve Condition	
WO-46539	1	Completed	44343.56001	44343	Valve Maintenance Report	May 27, 2021, 1:34 PM	V-055DV021	Valve Condition	
WO-49239	88	Completed	44365.61053	44369	Repair service line	July 1, 2021, 9:26 AM	V-055DV026	Valve Condition	
WO-46549	1	Completed	44343.57019	44343	Valve Maintenance Report	May 27, 2021, 1:44 PM	V-055DV028	Valve Condition	Good
WO-35848	401	Completed	44232.55345	44232	Dividing Pressure Valve Maintenance Report	February 5, 2021, 1:19 PM	V-055DV034	Valve Condition	
WO-35852	401	Completed	44232.56953	44232	Dividing Pressure Valve Maintenance Report	February 5, 2021, 1:43 PM	V-055DV037	Valve Condition	
WO-65771	1	Completed	44543.55335	44543	Valve Maintenance Report	December 13, 2021, 1:44 PM	V-055EV004	Valve Condition	
WO-63738	1	Completed	44517.44632	44519	Repair water main		V-055FV001	Valve Condition	Good
WO-63738	1	Completed	44517.44632	44519	Repair water main		V-055FV002	Valve Condition	Good
WO-63738	1	Completed	44517.44632	44519	Repair water main		V-055FV020	Valve Condition	Good
WO-63738	1	Completed	44517.44632	44519	Repair water main		V-055FV021	Valve Condition	Good
WO-63738	1	Completed	44517.44632	44519	Repair water main		V-055FV029	Valve Condition	Good
WO-37560	1	Completed	44252.60279	44252	Valve Maintenance Report	February 25, 2021, 2:33 PM	V-055FV030	Valve Condition	Good
WO-55047	1	Completed	44426.39232	44426	Valve Maintenance Report	August 18, 2021, 11:42 AM	V-055GV019	Valve Condition	
WO-55047	1	Completed	44426.39232	44426	Valve Maintenance Report	August 18, 2021, 11:42 AM	V-055GV020	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-44373	1	Completed	44327.4017	44328	Repair water main	May 12, 2021, 8:19 AM	V-055GV039	Valve Condition	Good
WO-32304	1	Completed	44200.29271	44438	Repair water main		V-055HV003	Valve Condition	
WO-45145	88	Completed	44334.30171	44333	Repair service line		V-055HV006	Valve Condition	
WO-41957	401	Completed	44302.9527	44302	Dividing Pressure Valve Maintenance Report	April 16, 2021, 10:54 PM	V-055HV007	Valve Condition	
WO-45145	88	Completed	44334.30171	44333	Repair service line		V-055HV008	Valve Condition	
WO-55047	1	Completed	44426.39232	44426	Valve Maintenance Report	August 18, 2021, 11:42 AM	V-055HV011	Valve Condition	Good
WO-55047	1	Completed	44426.39232	44426	Valve Maintenance Report	August 18, 2021, 11:42 AM	V-055HV012	Valve Condition	
WO-33507	1	Completed	44210.43522	44211	Valve Maintenance Report	January 15, 2021, 7:01 AM	V-055HV015	Valve Condition	
WO-33507	1	Completed	44210.43522	44211	Valve Maintenance Report	January 15, 2021, 7:01 AM	V-055HV020	Valve Condition	
WO-33507	1	Completed	44210.43522	44211	Valve Maintenance Report	January 15, 2021, 7:01 AM	V-055HV021	Valve Condition	
WO-33507	1	Completed	44210.43522	44211	Valve Maintenance Report	January 15, 2021, 7:01 AM	V-055HV028	Valve Condition	
WO-33507	1	Completed	44210.43522	44211	Valve Maintenance Report	January 15, 2021, 7:01 AM	V-055HV036	Valve Condition	
WO-33507	1	Completed	44210.43522	44211	Valve Maintenance Report	January 15, 2021, 7:01 AM	V-055HV038	Valve Condition	
WO-33507	1	Completed	44210.43522	44211	Valve Maintenance Report	January 15, 2021, 7:01 AM	V-055HV039	Valve Condition	
WO-65771	1	Completed	44543.55335	44543	Valve Maintenance Report	December 13, 2021, 1:44 PM	V-055JV004	Valve Condition	
WO-37628	1	Completed	44253.45827	44438	Repair water main		V-055JV022	Valve Condition	Good
WO-66428	1	Completed	44551.44123	44552	Valve Maintenance Report NO VALVES WERE OPERATED		V-055KV002	Valve Condition	
WO-66428	1	Completed	44551.44123	44552	Valve Maintenance Report NO VALVES WERE OPERATED		V-055KV003	Valve Condition	
WO-66429	1	Completed	44551.46735	44551	Valve Maintenance Report	December 21, 2021, 12:28 PM	V-055KV004	Valve Condition	
WO-66428	1	Completed	44551.44123	44552	Valve Maintenance Report NO VALVES WERE OPERATED		V-055KV008	Valve Condition	
WO-66429	1	Completed	44551.46735	44551	Valve Maintenance Report	December 21, 2021, 12:28 PM	V-055KV014	Valve Condition	
WO-66429	1	Completed	44551.46735	44551	Valve Maintenance Report	December 21, 2021, 12:28 PM	V-055LV001	Valve Condition	
WO-45389	1	Completed	44335.47759	44337	Valve Maintenance Report	May 21, 2021, 8:27 AM	V-055LV008	Valve Condition	
WO-65771	1	Completed	44543.55335	44543	Valve Maintenance Report	December 13, 2021, 1:44 PM	V-055NV004	Valve Condition	
WO-65906	84	Completed	44544.65857	44545	Main or service line leak investigation/survey/.....Ed Carney shut this throtteled this down. Water coming into basement. Emergency 1 call placed and valid. John McCarthy says that Ed has markings on leak location. 2 valve shut..... PER CALLER WATER LEAK CLOSE TO SIDEWALK IN FRONT OF ADDRESS CALLER DRIVING BY HAS NO FURTHER INFO/ANOTHER CALL 4533 CHATSWORTH ST 3 DIFFERENT PLACES SHE HAS LOW WATER PRESSURE GWEN DUNN 412 487 8784		V-055NV007	Valve Condition	
WO-65771	1	Completed	44543.55335	44543	Valve Maintenance Report	December 13, 2021, 1:44 PM	V-055NV013	Valve Condition	
WO-65771	1	Completed	44543.55335	44543	Valve Maintenance Report	December 13, 2021, 1:44 PM	V-055NV018	Valve Condition	
WO-65906	84	Completed	44544.65857	44545	Main or service line leak investigation/survey/.....Ed Carney shut this throtteled this down. Water coming into basement. Emergency 1 call placed and valid. John McCarthy says that Ed has markings on leak location. 2 valve shut..... PER CALLER WATER LEAK CLOSE TO SIDEWALK IN FRONT OF ADDRESS CALLER DRIVING BY HAS NO FURTHER INFO/ANOTHER CALL 4533 CHATSWORTH ST 3 DIFFERENT PLACES SHE HAS LOW WATER PRESSURE GWEN DUNN 412 487 8784		V-055NV019	Valve Condition	
WO-60316	1	Completed	44481.28203	44482	Repair water main		V-055PV006	Valve Condition	
WO-31852	1	Completed	44193.48683	44351	Valve Maintenance Report		V-055PV011	Valve Condition	
WO-60316	1	Completed	44481.28203	44482	Repair water main		V-055RV001	Valve Condition	
WO-60316	1	Completed	44481.28203	44482	Repair water main		V-055RV010	Valve Condition	
WO-53189	85	Completed	44404.93425	44404	Repair water main- 6"	July 27, 2021, 10:47 PM	V-055RV026	Valve Condition	
WO-65771	1	Completed	44543.55335	44543	Valve Maintenance Report	December 13, 2021, 1:44 PM	V-056BV011	Valve Condition	
WO-46740	1	Completed	44346.69859	44348	Repair water main		V-056BV030	Valve Condition	
WO-58697	1	Completed	44466.40529	44466	Valve Maintenance Report	September 27, 2021, 9:50 AM	V-056BV033	Valve Condition	
WO-37373	1	Completed	44251.38368	44438	Repair water main. Emergency 1 call placed. 8" mll		V-056CV004	Valve Condition	
WO-37373	1	Completed	44251.38368	44438	Repair water main. Emergency 1 call placed. 8" mll		V-056CV005	Valve Condition	
WO-59917	1	Completed	44476.47377	44476	Valve Maintenance Report	October 7, 2021, 1:05 PM	V-056DV003	Valve Condition	
WO-59942	1	Completed	44476.54994	44476	Valve Maintenance Report	October 7, 2021, 1:17 PM	V-056DV004	Valve Condition	
WO-59895	1	Completed	44476.42804	44476	Valve Maintenance Report	October 7, 2021, 11:08 AM	V-056DV005	Valve Condition	Good
WO-59915	1	Completed	44476.47158	44476	Valve Maintenance Report	October 7, 2021, 11:21 AM	V-056DV006	Valve Condition	
WO-59912	1	Completed	44476.46575	44476	Valve Maintenance Report	October 7, 2021, 11:17 AM	V-056DV007	Valve Condition	
WO-53189	85	Completed	44404.93425	44404	Repair water main- 6"	July 27, 2021, 10:47 PM	V-056DV008	Valve Condition	
WO-59181	1	Completed	44469.61857	44469	Valve Maintenance Report	September 30, 2021, 2:53 PM	V-056DV009	Valve Condition	
WO-59253	1	Completed	44470.4585	44470	Valve Maintenance Report	October 1, 2021, 11:05 AM	V-056DV010	Valve Condition	
WO-59135	1	Completed	44469.45052	44469	Valve Maintenance Report	September 30, 2021, 10:57 AM	V-056DV011	Valve Condition	
WO-59125	1	Completed	44469.43205	44469	Valve Maintenance Report	September 30, 2021, 10:30 AM	V-056DV012	Valve Condition	
WO-59134	1	Completed	44469.44286	44469	Valve Maintenance Report	September 30, 2021, 10:47 AM	V-056DV013	Valve Condition	
WO-58697	1	Completed	44466.40529	44466	Valve Maintenance Report	September 27, 2021, 9:50 AM	V-056FV001	Valve Condition	
WO-58544	1	Completed	44463.41978	44463	Valve Maintenance Report	September 24, 2021, 11:03 AM	V-056FV002	Valve Condition	
WO-58910	1	Completed	44467.56577	44467	Valve Maintenance Report	September 28, 2021, 1:49 PM	V-056FV003	Valve Condition	
WO-58910	1	Completed	44467.56577	44467	Valve Maintenance Report	September 28, 2021, 1:49 PM	V-056FV004	Valve Condition	
WO-58701	1	Completed	44466.4108	44466	Valve Maintenance Report	September 27, 2021, 10:02 AM	V-056FV007	Valve Condition	
WO-58701	1	Completed	44466.4108	44466	Valve Maintenance Report	September 27, 2021, 10:02 AM	V-056FV008	Valve Condition	
WO-58734	1	Completed	44466.4638	44466	Valve Maintenance Report	September 27, 2021, 11:09 AM	V-056FV009	Valve Condition	
WO-58867	1	Completed	44467.43208	44467	Valve Maintenance Report	September 28, 2021, 11:22 AM	V-056FV010	Valve Condition	
WO-58867	1	Completed	44467.43208	44467	Valve Maintenance Report	September 28, 2021, 11:22 AM	V-056FV011	Valve Condition	
WO-58867	1	Completed	44467.43208	44467	Valve Maintenance Report	September 28, 2021, 11:22 AM	V-056FV012	Valve Condition	
WO-58867	1	Completed	44467.43208	44467	Valve Maintenance Report	September 28, 2021, 11:22 AM	V-056FV013	Valve Condition	
WO-58867	1	Completed	44467.43208	44467	Valve Maintenance Report	September 28, 2021, 11:22 AM	V-056FV014	Valve Condition	
WO-65364	1	Completed	44538.55802	44538	Valve Maintenance Report	December 8, 2021, 2:04 PM	V-056FV017	Valve Condition	
WO-64854	1	Completed	44532.49007	44532	Valve Maintenance Report	December 2, 2021, 1:53 PM	V-056FV018	Valve Condition	
WO-57982	1	Completed	44459.51007	44459	Valve Maintenance Report	September 20, 2021, 12:20 PM	V-056FV019	Valve Condition	
WO-57982	1	Completed	44459.51007	44459	Valve Maintenance Report	September 20, 2021, 12:20 PM	V-056FV020	Valve Condition	
WO-57979	1	Completed	44459.51065	44459	Valve Maintenance Report	September 20, 2021, 12:43 PM	V-056FV021	Valve Condition	
WO-57985	1	Completed	44459.5147	44459	Valve Maintenance Report	September 20, 2021, 12:44 PM	V-056FV022	Valve Condition	Fair
WO-64854	1	Completed	44532.49007	44532	Valve Maintenance Report	December 2, 2021, 1:53 PM	V-056FV023	Valve Condition	Fair
WO-64854	1	Completed	44532.49007	44532	Valve Maintenance Report	December 2, 2021, 1:53 PM	V-056FV024	Valve Condition	Good
WO-57988	1	Completed	44459.56404	44459	Valve Maintenance Report	September 20, 2021, 2:28 PM	V-056FV025	Valve Condition	Good
WO-57988	1	Completed	44459.56404	44459	Valve Maintenance Report	September 20, 2021, 2:28 PM	V-056FV026	Valve Condition	Good
WO-57988	1	Completed	44459.56404	44459	Valve Maintenance Report	September 20, 2021, 2:28 PM	V-056FV027	Valve Condition	Good
WO-58144	1	Completed	44460.50642	44460	Valve Maintenance Report	September 21, 2021, 12:13 PM	V-056FV028	Valve Condition	
WO-57148	1	Completed	44449.48196	44449	Valve Maintenance Report	September 10, 2021, 12:51 PM	V-056FV032	Valve Condition	
WO-58317	1	Completed	44461.57013	44461	Valve Maintenance Report	September 22, 2021, 1:43 PM	V-056FV033	Valve Condition	
WO-58310	1	Completed	44461.55501	44461	Valve Maintenance Report	September 22, 2021, 1:30 PM	V-056FV034	Valve Condition	
WO-58315	1	Completed	44461.56478	44461	Valve Maintenance Report	September 22, 2021, 1:39 PM	V-056FV035	Valve Condition	
WO-58918	1	Completed	44467.59448	44467	Valve Maintenance Report	September 28, 2021, 2:25 PM	V-056FV036	Valve Condition	
WO-59893	1	Completed	44476.40981	44476	Valve Maintenance Report	October 7, 2021, 9:51 AM	V-056FV037	Valve Condition	Fair
WO-59892	1	Completed	44476.4085	44476	Valve Maintenance Report	October 7, 2021, 9:49 AM	V-056FV038	Valve Condition	Fair
WO-59880	1	Completed	44476.38465	44476	Valve Maintenance Report	October 7, 2021, 9:15 AM	V-056FV039	Valve Condition	
WO-59843	1	Completed	44476.3667	44476	Valve Maintenance Report	October 7, 2021, 9:06 AM	V-056FV040	Valve Condition	
WO-57988	1	Completed	44459.56404	44459	Valve Maintenance Report	September 20, 2021, 2:28 PM	V-056FV042	Valve Condition	Good
WO-58918	1	Completed	44467.59448	44467	Valve Maintenance Report	September 28, 2021, 2:25 PM	V-056FV044	Valve Condition	
WO-59878	1	Completed	44476.38309	44476	Valve Maintenance Report	October 7, 2021, 9:13 AM	V-056FV046	Valve Condition	
WO-59871	1	Completed	44476.38042	44476	Valve Maintenance Report	October 7, 2021, 9:10 AM	V-056FV047	Valve Condition	
WO-46739	85	Completed	44346.69859	44348	Repair water main	June 1, 2021, 10:49 AM	V-056FV050	Valve Condition	
WO-58594	1	Completed	44463.55448	44463	Valve Maintenance Report	September 24, 2021, 2:37 PM	V-056FV051	Valve Condition	Good
WO-46739	85	Completed	44346.69859	44348	Repair water main	June 1, 2021, 10:49 AM	V-056FV052	Valve Condition	
WO-58144	1	Completed	44460.50642	44460	Valve Maintenance Report	September 21, 2021, 12:13 PM	V-056FV053	Valve Condition	Good
WO-58594	1	Completed	44463.55448	44463	Valve Maintenance Report	September 24, 2021, 2:37 PM	V-056FV054	Valve Condition	Good
WO-58589	1	Completed	44463.52313	44463	Valve Maintenance Report	September 24, 2021, 12:56 PM	V-056FV056	Valve Condition	
WO-46740	1	Completed	44346.69859	44348	Repair water main		V-056FV057	Valve Condition	
WO-46739	85	Completed	44346.69859	44348	Repair water main	June 1, 2021, 10:49 AM	V-056FV058	Valve Condition	
WO-58594	1	Completed	44463.55448	44463	Valve Maintenance Report	September 24, 2021, 2:37 PM	V-056FV059	Valve Condition	Good
WO-46739	85	Completed	44346.69859	44348	Repair water main	June 1, 2021, 10:49 AM	V-056FV060	Valve Condition	
WO-59340	1	Completed	44473.34692	44473	Valve Maintenance Report	October 4, 2021, 8:23 AM	V-056GV002	Valve Condition	Good
WO-59382	1	Completed	44473.41338	44473	Valve Maintenance Report	October 4, 2021, 9:58 AM	V-056GV004	Valve Condition	
WO-59384	1	Completed	44473.41683	44473	Valve Maintenance Report	October 4, 2021, 10:06 AM	V-056GV005	Valve Condition	
WO-59342	1	Completed	44473.35211	44473	Valve Maintenance Report	October 4, 2021, 9:01 AM	V-056GV006	Valve Condition	
WO-60225	1	Completed	44480.47278	44480	Valve Maintenance Report	October 11, 2021, 11:22 AM	V-056GV007	Valve Condition	
WO-60199	1	Completed	44480.44919	44480	Valve Maintenance Report	October 11, 2021, 10:49 AM	V-056GV009	Valve Condition	
WO-60222	1	Completed	44480.4524	44480	Valve Maintenance Report	October 11, 2021, 10:54 AM	V-056GV010	Valve Condition	
WO-60081	1	Completed	44477.50976	44477	Valve Maintenance Report	October 8, 2021, 12:17 PM	V-056GV011	Valve Condition	
WO-60083	1	Completed	44477.51372	44477	Valve Maintenance Report	October 8, 2021, 12:22 PM	V-056GV012	Valve Condition	
WO-60083	1	Completed	44477.51372	44477	Valve Maintenance Report	October 8, 2021, 12:22 PM	V-056GV013	Valve Condition	
WO-60500	1	Completed	44482.46144	44482	Valve Maintenance Report	October 13, 2021, 11:07 AM	V-056GV016	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-60513	1	Completed	44482.46559	44482	Valve Maintenance Report	October 13, 2021, 11:13 AM	V-056GV017	Valve Condition	
WO-60546	1	Completed	44482.55559	44482	Valve Maintenance Report	October 13, 2021, 1:22 PM	V-056GV018	Valve Condition	
WO-60521	1	Completed	44482.49597	44482	Valve Maintenance Report	October 13, 2021, 11:57 AM	V-056GV019	Valve Condition	
WO-60547	1	Completed	44482.56422	44482	Valve Maintenance Report	October 13, 2021, 1:35 PM	V-056GV020	Valve Condition	Good
WO-60517	1	Completed	44482.47091	44482	Valve Maintenance Report	October 13, 2021, 11:21 AM	V-056GV021	Valve Condition	
WO-60549	1	Completed	44482.56949	44482	Valve Maintenance Report	October 13, 2021, 1:42 PM	V-056GV022	Valve Condition	
WO-60550	1	Completed	44482.57288	44482	Valve Maintenance Report	October 13, 2021, 1:48 PM	V-056GV023	Valve Condition	
WO-60551	1	Completed	44482.57614	44482	Valve Maintenance Report	October 13, 2021, 1:52 PM	V-056GV024	Valve Condition	
WO-61091	1	Completed	44488.47189	44488	Valve Maintenance Report	October 19, 2021, 11:30 AM	V-056GV025	Valve Condition	
WO-61091	1	Completed	44488.47189	44488	Valve Maintenance Report	October 19, 2021, 11:30 AM	V-056GV026	Valve Condition	
WO-61091	1	Completed	44488.47189	44488	Valve Maintenance Report	October 19, 2021, 11:30 AM	V-056GV027	Valve Condition	
WO-60194	1	Completed	44480.42254	44480	Valve Maintenance Report	October 11, 2021, 10:10 AM	V-056GV028	Valve Condition	
WO-49275	1	Completed	44365.95792	44366	Repair water main	June 19, 2021, 10:20 PM	V-056GV029	Valve Condition	Marginal
WO-60031	1	Completed	44477.34391	44488	Repair water main		V-056GV030	Valve Condition	
WO-60178	1	Completed	44480.39332	44480	Valve Maintenance Report	October 11, 2021, 9:28 AM	V-056GV031	Valve Condition	
WO-34443	41	Completed	44221.43063	44222	Contractor shut request. Mele contractor for 1-26-21	January 26, 2021, 6:23 PM	V-056JV002	Valve Condition	
WO-32803	41	Completed	44203.6997	44204	Contractor shut request. (MELE PULLED SERVICE)	January 8, 2021, 2:45 PM	V-056JV004	Valve Condition	
WO-35979	41	Completed	44235.28936	44235	Contractor shut request	February 8, 2021, 2:16 PM	V-056JV006	Valve Condition	Good
WO-34443	41	Completed	44221.43063	44222	Contractor shut request. Mele contractor for 1-26-21	January 26, 2021, 6:23 PM	V-056JV007	Valve Condition	
WO-36156	41	Completed	44237.28426	44237	Contractor shut request	February 10, 2021, 12:52 PM	V-056JV010	Valve Condition	Good
WO-36156	41	Completed	44237.28426	44237	Contractor shut request	February 10, 2021, 12:52 PM	V-056JV013	Valve Condition	Good
WO-60927	1	Completed	44487.43161	44487	Valve Maintenance Report	October 18, 2021, 10:24 AM	V-056JV016	Valve Condition	
WO-36156	41	Completed	44237.28426	44237	Contractor shut request	February 10, 2021, 12:52 PM	V-056JV017	Valve Condition	Good
WO-36156	41	Completed	44237.28426	44237	Contractor shut request	February 10, 2021, 12:52 PM	V-056JV018	Valve Condition	Good
WO-60961	1	Completed	44487.56181	44487	Valve Maintenance Report	October 18, 2021, 1:33 PM	V-056JV019	Valve Condition	
WO-36156	41	Completed	44237.28426	44237	Contractor shut request	February 10, 2021, 12:52 PM	V-056JV020	Valve Condition	Fair
WO-37367	41	Completed	44251.35677	44251	Contractor shut request. MELE tie in	February 24, 2021, 3:07 PM	V-056JV021	Valve Condition	
WO-35979	41	Completed	44235.28936	44235	Contractor shut request	February 8, 2021, 2:16 PM	V-056JV022	Valve Condition	Fair
WO-38090	41	Completed	44258.62158	44259	Contractor shut request, MELE contracting tie in	March 4, 2021, 3:30 PM	V-056JV023	Valve Condition	Fair
WO-60975	1	Completed	44487.58287	44488	Valve Maintenance Report	October 19, 2021, 11:16 AM	V-056JV028	Valve Condition	
WO-60788	1	Completed	44484.48142	44484	Valve Maintenance Report	October 15, 2021, 11:40 AM	V-056JV039	Valve Condition	
WO-60788	1	Completed	44484.48142	44484	Valve Maintenance Report	October 15, 2021, 11:40 AM	V-056JV040	Valve Condition	
WO-60788	1	Completed	44484.48142	44484	Valve Maintenance Report	October 15, 2021, 11:40 AM	V-056JV041	Valve Condition	
WO-60799	1	Completed	44484.53849	44484	Valve Maintenance Report	October 15, 2021, 1:04 PM	V-056JV042	Valve Condition	
WO-60799	1	Completed	44484.53849	44484	Valve Maintenance Report	October 15, 2021, 1:04 PM	V-056JV043	Valve Condition	
WO-60799	1	Completed	44484.53849	44484	Valve Maintenance Report	October 15, 2021, 1:04 PM	V-056JV044	Valve Condition	
WO-60802	1	Completed	44484.54618	44484	Valve Maintenance Report	October 15, 2021, 1:46 PM	V-056JV045	Valve Condition	
WO-60817	1	Completed	44484.58037	44484	Valve Maintenance Report	October 15, 2021, 2:33 PM	V-056JV046	Valve Condition	
WO-60817	1	Completed	44484.58037	44484	Valve Maintenance Report	October 15, 2021, 2:33 PM	V-056JV047	Valve Condition	
WO-60817	1	Completed	44484.58037	44484	Valve Maintenance Report	October 15, 2021, 2:33 PM	V-056JV048	Valve Condition	
WO-60899	1	Completed	44487.36195	44487	Valve Maintenance Report	October 18, 2021, 8:44 AM	V-056JV049	Valve Condition	
WO-60921	1	Completed	44487.42268	44487	Valve Maintenance Report	October 18, 2021, 10:11 AM	V-056JV050	Valve Condition	
WO-60908	1	Completed	44487.39712	44487	Valve Maintenance Report	October 18, 2021, 9:44 AM	V-056JV051	Valve Condition	
WO-60908	1	Completed	44487.39712	44487	Valve Maintenance Report	October 18, 2021, 9:44 AM	V-056JV052	Valve Condition	
WO-60908	1	Completed	44487.39712	44487	Valve Maintenance Report	October 18, 2021, 9:44 AM	V-056JV053	Valve Condition	
WO-55109	1	Completed	44426.5329	44426	Valve Maintenance Report	August 18, 2021, 1:19 PM	V-056KV001	Valve Condition	
WO-55108	1	Completed	44426.52803	44426	Valve Maintenance Report	August 18, 2021, 12:45 PM	V-056KV002	Valve Condition	
WO-56368	1	Completed	44440.56547	44440	Valve Maintenance Report	September 1, 2021, 1:38 PM	V-056KV003	Valve Condition	
WO-56365	1	Completed	44440.55214	44440	Valve Maintenance Report	September 1, 2021, 1:18 PM	V-056KV004	Valve Condition	
WO-45843	88	Completed	44340.331	44340	Repair service line	May 24, 2021, 8:01 AM	V-056KV005	Valve Condition	
WO-55453	1	Completed	44431.41999	44431	Valve Maintenance Report	August 23, 2021, 10:12 AM	V-056KV006	Valve Condition	
WO-55077	1	Completed	44426.4441	44426	Valve Maintenance Report	August 18, 2021, 10:44 AM	V-056KV007	Valve Condition	
WO-55066	1	Completed	44426.42058	44426	Valve Maintenance Report	August 18, 2021, 10:12 AM	V-056KV008	Valve Condition	
WO-55062	1	Completed	44426.41478	44426	Valve Maintenance Report	August 18, 2021, 10:03 AM	V-056KV009	Valve Condition	
WO-55072	1	Completed	44426.42865	44426	Valve Maintenance Report	August 18, 2021, 10:20 AM	V-056KV010	Valve Condition	
WO-34443	41	Completed	44221.43063	44222	Contractor shut request. Mele contractor for 1-26-21	January 26, 2021, 6:23 PM	V-056KV011	Valve Condition	
WO-64854	1	Completed	44532.49007	44532	Valve Maintenance Report	December 2, 2021, 1:53 PM	V-056KV013	Valve Condition	
WO-64854	1	Completed	44532.49007	44532	Valve Maintenance Report	December 2, 2021, 1:53 PM	V-056KV014	Valve Condition	
WO-64854	1	Completed	44532.49007	44532	Valve Maintenance Report	December 2, 2021, 1:53 PM	V-056KV015	Valve Condition	
WO-64854	1	Completed	44532.49007	44532	Valve Maintenance Report	December 2, 2021, 1:53 PM	V-056KV016	Valve Condition	
WO-64854	1	Completed	44532.49007	44532	Valve Maintenance Report	December 2, 2021, 1:53 PM	V-056KV017	Valve Condition	
WO-64854	1	Completed	44532.49007	44532	Valve Maintenance Report	December 2, 2021, 1:53 PM	V-056KV018	Valve Condition	
WO-64854	1	Completed	44532.49007	44532	Valve Maintenance Report	December 2, 2021, 1:53 PM	V-056KV019	Valve Condition	
WO-56142	1	Completed	44439.45496	44439	Valve Maintenance Report	August 31, 2021, 10:59 AM	V-056KV020	Valve Condition	
WO-56087	1	Completed	44439.43526	44439	Valve Maintenance Report	August 31, 2021, 10:30 AM	V-056KV021	Valve Condition	
WO-64854	1	Completed	44532.49007	44532	Valve Maintenance Report	December 2, 2021, 1:53 PM	V-056KV022	Valve Condition	
WO-45843	88	Completed	44340.331	44340	Repair service line	May 24, 2021, 8:01 AM	V-056KV023	Valve Condition	
WO-55880	1	Completed	44435.42894	44435	Valve Maintenance Report	August 27, 2021, 10:21 AM	V-056KV024	Valve Condition	
WO-55872	1	Completed	44435.40646	44435	Valve Maintenance Report	August 27, 2021, 9:48 AM	V-056KV026	Valve Condition	
WO-55995	1	Completed	44438.38967	44438	Valve Maintenance Report	August 30, 2021, 9:25 AM	V-056KV027	Valve Condition	Good
WO-55992	1	Completed	44438.36586	44438	Valve Maintenance Report	August 30, 2021, 8:54 AM	V-056KV028	Valve Condition	
WO-55800	1	Completed	44434.59024	44434	Valve Maintenance Report	August 26, 2021, 2:13 PM	V-056KV029	Valve Condition	
WO-55801	1	Completed	44434.59336	44434	Valve Maintenance Report	August 26, 2021, 2:16 PM	V-056KV030	Valve Condition	
WO-55798	1	Completed	44434.58553	44434	Valve Maintenance Report	August 26, 2021, 2:07 PM	V-056KV031	Valve Condition	
WO-55796	1	Completed	44434.57976	44434	Valve Maintenance Report	August 26, 2021, 1:59 PM	V-056KV032	Valve Condition	
WO-55786	1	Completed	44434.5611	44434	Valve Maintenance Report	August 26, 2021, 1:46 PM	V-056KV033	Valve Condition	Good
WO-35821	1	Completed	44232.41236	44232	Valve Maintenance Report	February 5, 2021, 9:55 AM	V-056KV034	Valve Condition	Fair
WO-55553	1	Completed	44432.46978	44432	Valve Maintenance Report	August 24, 2021, 11:22 AM	V-056KV035	Valve Condition	Good
WO-34443	41	Completed	44221.43063	44222	Contractor shut request. Mele contractor for 1-26-21	January 26, 2021, 6:23 PM	V-056KV036	Valve Condition	Fair
WO-41534	41	Completed	44299.51837	44299	Contractor shut request. MELE tie in	April 13, 2021, 5:09 PM	V-056KV038	Valve Condition	
WO-34443	41	Completed	44221.43063	44222	Contractor shut request. Mele contractor for 1-26-21	January 26, 2021, 6:23 PM	V-056KV039	Valve Condition	
WO-66106	1	Completed	44546.49942	44547	Valve Maintenance Report	December 17, 2021, 8:09 AM	V-056KV042	Valve Condition	
WO-64854	1	Completed	44532.49007	44532	Valve Maintenance Report	December 2, 2021, 1:53 PM	V-056KV043	Valve Condition	
WO-66106	1	Completed	44546.49942	44547	Valve Maintenance Report	December 17, 2021, 8:09 AM	V-056KV044	Valve Condition	
WO-64854	1	Completed	44532.49007	44532	Valve Maintenance Report	December 2, 2021, 1:53 PM	V-056KV045	Valve Condition	
WO-64854	1	Completed	44532.49007	44532	Valve Maintenance Report	December 2, 2021, 1:53 PM	V-056KV046	Valve Condition	
WO-56001	1	Completed	44438.40359	44438	Valve Maintenance Report	August 30, 2021, 9:46 AM	V-056KV048	Valve Condition	
WO-56387	1	Completed	44440.56937	44440	Valve Maintenance Report	September 1, 2021, 2:06 PM	V-056KV052	Valve Condition	
WO-55551	1	Completed	44432.45845	44432	Valve Maintenance Report	August 24, 2021, 11:03 AM	V-056KV053	Valve Condition	Good
WO-55563	1	Completed	44432.5728	44432	Valve Maintenance Report	August 24, 2021, 1:53 PM	V-056KV055	Valve Condition	Good
WO-34443	41	Completed	44221.43063	44222	Contractor shut request. Mele contractor for 1-26-21	January 26, 2021, 6:23 PM	V-056KV056	Valve Condition	
WO-34443	41	Completed	44221.43063	44222	Contractor shut request. Mele contractor for 1-26-21	January 26, 2021, 6:23 PM	V-056KV057	Valve Condition	
WO-65364	1	Completed	44538.55802	44538	Valve Maintenance Report	December 8, 2021, 2:04 PM	V-056KV060	Valve Condition	
WO-55457	1	Completed	44431.43043	44431	Valve Maintenance Report	August 23, 2021, 11:19 AM	V-056KV062	Valve Condition	
WO-55084	1	Completed	44426.45068	44426	Valve Maintenance Report	August 18, 2021, 10:52 AM	V-056KV068	Valve Condition	
WO-65566	1	Completed	44540.34002	44540	Valve Maintenance Report	December 10, 2021, 11:29 AM	V-056KV073	Valve Condition	
WO-65566	1	Completed	44540.34002	44540	Valve Maintenance Report	December 10, 2021, 11:29 AM	V-056KV074	Valve Condition	
WO-65566	1	Completed	44540.34002	44540	Valve Maintenance Report	December 10, 2021, 11:29 AM	V-056KV077	Valve Condition	
WO-61194	88	Completed	44489.46073	44490	Repair service line- if drilled, Drill Sheet work order MUST be completed	October 22, 2021, 9:14 AM	V-056LV005	Valve Condition	Good
WO-49275	1	Completed	44365.95792	44366	Repair water main	June 19, 2021, 10:20 PM	V-056LV012	Valve Condition	
WO-37124	41	Completed	44249.36451	44249	Contractor shut request,MELE , Double tie in	February 22, 2021, 3:07 PM	V-056NV001	Valve Condition	Fair
WO-44002	1	Completed	44322.86161	44438	Repair water main		V-056NV002	Valve Condition	
WO-44002	1	Completed	44322.86161	44438	Repair water main		V-056NV003	Valve Condition	
WO-37866	41	Completed	44257.32233	44257	Contractor shut request MELE tie in	March 2, 2021, 4:17 PM	V-056NV005	Valve Condition	Good
WO-38090	41	Completed	44258.62158	44259	Contractor shut request, MELE contracting tie in	March 4, 2021, 3:30 PM	V-056NV006	Valve Condition	
WO-33885	464	Completed	44215.43147	44238	Contractor damage to sewer main	February 11, 2021, 7:32 AM	V-056NV008	Valve Condition	
WO-37866	41	Completed	44257.32233	44257	Contractor shut request MELE tie in	March 2, 2021, 4:17 PM	V-056NV010	Valve Condition	Good
WO-33888	41	Completed	44215.44544	44293	Contractor shut request	April 7, 2021, 7:48 AM	V-056NV012	Valve Condition	
WO-38090	41	Completed	44258.62158	44259	Contractor shut request, MELE contracting tie in	March 4, 2021, 3:30 PM	V-056NV013	Valve Condition	Good
WO-65364	1	Completed	44538.55802	44538	Valve Maintenance Report	December 8, 2021, 2:04 PM	V-056PV001	Valve Condition	
WO-65566	1	Completed	44540.34002	44540	Valve Maintenance Report	December 10, 2021, 11:29 AM	V-056PV002	Valve Condition	
WO-66106	1	Completed	44546.49942	44547	Valve Maintenance Report	December 17, 2021, 8:09 AM	V-056PV003	Valve Condition	
WO-66106	1	Completed	44546.49942	44547	Valve Maintenance Report	December 17, 2021, 8:09 AM	V-056PV010	Valve Condition	
WO-65566	1	Completed	44540.34002	44540	Valve Maintenance Report	December 10, 2021, 11:29 AM	V-056PV016	Valve Condition	
WO-65566	1	Completed	44540.34002	44540	Valve Maintenance Report	December 10, 2021, 11:29 AM	V-056PV018	Valve Condition	
WO-65566	1	Completed	44540.34002	44540	Valve Maintenance Report	December 10, 2021, 11:29 AM	V-056PV020	Valve Condition	
WO-41509	41	Completed	44299.42182	44299	Contractor shut request. MELE tie in	April 13, 2021, 4:15 PM	V-056PV026	Valve Condition	Fair
WO-41718	41	Completed	44301.36593	44301	Contractor shut request. MELE tie in	April 15, 2021, 11:17 AM	V-056PV027	Valve Condition	
WO-38090	41	Completed	44258.62158	44259	Contractor shut request, MELE contracting tie in	March 4, 2021, 3:30 PM	V-056PV028	Valve Condition	
WO-41718	41	Completed	44301.36593	44301	Contractor shut request. MELE tie in	April 15, 2021, 11:17 AM	V-056PV029	Valve Condition	Good

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-35359	41	Completed	44229.54155	44229	Contractor shut request	February 2, 2021, 1:07 PM	V-056PV030	Valve Condition	
WO-64037	1	Completed	44522.27933	44523	Repair water main		V-056PV037	Valve Condition	
WO-64037	1	Completed	44522.27933	44523	Repair water main		V-056PV038	Valve Condition	
WO-58544	1	Completed	44463.41978	44463	Valve Maintenance Report	September 24, 2021, 11:03 AM	V-056PV049	Valve Condition	
WO-58544	1	Completed	44463.41978	44463	Valve Maintenance Report	September 24, 2021, 11:03 AM	V-056PV050	Valve Condition	
WO-58544	1	Completed	44463.41978	44463	Valve Maintenance Report	September 24, 2021, 11:03 AM	V-056PV051	Valve Condition	
WO-62964	88	Completed	44508.36944	44512	Repair service line- if drilled, Drill Sheet work order MUST be completed. New service ran out by property owner replace old lead line and tap termination of old service.(RAY 412-277-1584) one call placed 11/8/21	November 15, 2021, 11:20 AM	V-056RV025	Valve Condition	
WO-34999	43	Completed	44225.34555	44225	Test shut	January 29, 2021, 9:15 AM	V-056RV026	Valve Condition	
WO-62964	88	Completed	44508.36944	44512	Repair service line- if drilled, Drill Sheet work order MUST be completed. New service ran out by property owner replace old lead line and tap termination of old service.(RAY 412-277-1584) one call placed 11/8/21	November 15, 2021, 11:20 AM	V-056RV029	Valve Condition	
WO-62964	88	Completed	44508.36944	44512	Repair service line- if drilled, Drill Sheet work order MUST be completed. New service ran out by property owner replace old lead line and tap termination of old service.(RAY 412-277-1584) one call placed 11/8/21	November 15, 2021, 11:20 AM	V-056RV034	Valve Condition	
WO-62964	88	Completed	44508.36944	44512	Repair service line- if drilled, Drill Sheet work order MUST be completed. New service ran out by property owner replace old lead line and tap termination of old service.(RAY 412-277-1584) one call placed 11/8/21	November 15, 2021, 11:20 AM	V-056RV035	Valve Condition	
WO-62844	1	Completed	44505.57866	44505	Valve Maintenance Report	November 5, 2021, 2:02 PM	V-056SV007	Valve Condition	
WO-62844	1	Completed	44505.57866	44505	Valve Maintenance Report	November 5, 2021, 2:02 PM	V-056SV008	Valve Condition	
WO-51303	85	Completed	44384.44344	44385	Repair water main	July 8, 2021, 8:01 AM	V-056SV013	Valve Condition	Fair
WO-49138	1	Completed	44365.03336	44439	Repair water main		V-056SV014	Valve Condition	Fair
WO-51303	85	Completed	44384.44344	44385	Repair water main	July 8, 2021, 8:01 AM	V-056SV019	Valve Condition	
WO-62850	1	Completed	44505.5913	44505	Valve Maintenance Report	November 5, 2021, 2:20 PM	V-056SV024	Valve Condition	
WO-62850	1	Completed	44505.5913	44505	Valve Maintenance Report	November 5, 2021, 2:20 PM	V-056SV025	Valve Condition	
WO-62850	1	Completed	44505.5913	44505	Valve Maintenance Report	November 5, 2021, 2:20 PM	V-056SV026	Valve Condition	
WO-33888	41	Completed	44215.44544	44293	Contractor shut request	April 7, 2021, 7:48 AM	V-057AV001	Valve Condition	
WO-64037	1	Completed	44522.27933	44523	Repair water main		V-057BV017	Valve Condition	
WO-42273	85	Completed	44307.09476	44308	Repair water main	April 21, 2021, 2:30 PM	V-057BV018	Valve Condition	
WO-42273	85	Completed	44307.09476	44308	Repair water main	April 21, 2021, 2:30 PM	V-057BV020	Valve Condition	
WO-64037	1	Completed	44522.27933	44523	Repair water main		V-057BV021	Valve Condition	
WO-39695	41	Completed	44278.37244	44278	Contractor shut request Folino capping 20" main	March 23, 2021, 2:55 PM	V-057BV023	Valve Condition	Broke
WO-39695	41	Completed	44278.37244	44278	Contractor shut request Folino capping 20" main	March 23, 2021, 2:55 PM	V-057BV024	Valve Condition	Broke
WO-58787	563	Completed	44466.55902	44466	Water service hit by contractor. PWSA crew is making repair	September 27, 2021, 2:18 PM	V-057BV026	Valve Condition	Good
WO-39695	41	Completed	44278.37244	44278	Contractor shut request Folino capping 20" main	March 23, 2021, 2:55 PM	V-057BV027	Valve Condition	Broke
WO-39437	43	Completed	44273.58188	44273	Test shut, for MELE CONTRACTOR, TIE IN FOR PGH2O	March 18, 2021, 2:20 PM	V-057BV036	Valve Condition	
WO-37866	41	Completed	44257.32233	44257	Contractor shut request MELE tie in	March 2, 2021, 4:17 PM	V-057BV037	Valve Condition	Good
WO-39437	43	Completed	44273.58188	44273	Test shut, for MELE CONTRACTOR, TIE IN FOR PGH2O	March 18, 2021, 2:20 PM	V-057BV040	Valve Condition	
WO-39154	43	Completed	44271.42693	44271	Test shut	March 16, 2021, 10:35 AM	V-057BV042	Valve Condition	Broke
WO-64037	1	Completed	44522.27933	44523	Repair water main		V-057CV001	Valve Condition	
WO-58787	563	Completed	44466.55902	44466	Water service hit by contractor. PWSA crew is making repair	September 27, 2021, 2:18 PM	V-057CV006	Valve Condition	Good
WO-32119	1	Completed	44196.33688	44202	Repair water main	January 21, 2021, 10:30 AM	V-057CV011	Valve Condition	
WO-32119	1	Completed	44196.33688	44202	Repair water main	January 21, 2021, 10:30 AM	V-057CV015	Valve Condition	
WO-39642	85	Completed	44277.4917	44284	Repair water main	April 6, 2021, 8:19 AM	V-057CV021	Valve Condition	
WO-39642	85	Completed	44277.4917	44284	Repair water main	April 6, 2021, 8:19 AM	V-057DV003	Valve Condition	
WO-39073	43	Completed	44270.47498	44270	Test shut	March 15, 2021, 1:48 PM	V-057GV001	Valve Condition	Broke
WO-39165	1	Completed	44271.48162	44271	Valve Maintenance Report	March 16, 2021, 11:35 AM	V-057GV002	Valve Condition	
WO-39073	43	Completed	44270.47498	44270	Test shut	March 15, 2021, 1:48 PM	V-057GV004	Valve Condition	Broke
WO-39695	41	Completed	44278.37244	44278	Contractor shut request Folino capping 20" main	March 23, 2021, 2:55 PM	V-057GV007	Valve Condition	
WO-39073	43	Completed	44270.47498	44270	Test shut	March 15, 2021, 1:48 PM	V-057GV008	Valve Condition	Broke
WO-40500	41	Completed	44286.37961	44286	Contractor shut request	March 31, 2021, 4:45 PM	V-057GV015	Valve Condition	Broke
WO-39695	41	Completed	44278.37244	44278	Contractor shut request Folino capping 20" main	March 23, 2021, 2:55 PM	V-057GV026	Valve Condition	Broke
WO-39073	43	Completed	44270.47498	44270	Test shut	March 15, 2021, 1:48 PM	V-057GV027	Valve Condition	Broke
WO-39695	41	Completed	44278.37244	44278	Contractor shut request Folino capping 20" main	March 23, 2021, 2:55 PM	V-057GV029	Valve Condition	Broke
WO-39167	1	Completed	44271.48357	44271	Valve Maintenance Report	March 16, 2021, 11:39 AM	V-057GV035	Valve Condition	
WO-39695	41	Completed	44278.37244	44278	Contractor shut request Folino capping 20" main	March 23, 2021, 2:55 PM	V-057GV037	Valve Condition	Broke
WO-39167	1	Completed	44271.48357	44271	Valve Maintenance Report	March 16, 2021, 11:39 AM	V-057GV038	Valve Condition	
WO-59336	1	Completed	44473.32715	44473	Valve Maintenance Report		V-075CV018	Valve Condition	
WO-59336	1	Completed	44473.32715	44473	Valve Maintenance Report		V-075CV022	Valve Condition	
WO-60919	85	Completed	44487.41903	44484	Repair water main	October 18, 2021, 10:07 AM	V-075CV031	Valve Condition	
WO-61400	88	Completed	44491.46484	44508	Repair service line- if drilled, Drill Sheet work order MUST be completed Broken Stop will need repaired 3 day one call placed 9AM Monday 10/25/21 will need posted STREET LOCATION: 3433 SHADELAND AVE (W.O.61400) VEHICLES & CREWS: 233 STORMER, SANDS, 127 WHIGHAM, 675 GERMEYER WORK DESCRIPTION: CREW DUG OVER THE MAIN AND C/B IN THE S/W. NEW 1" TAP MADE REPLACED LEAD S/L. NEW C/S. CONNECTED TO H/O COPPER S/L HOLES BACKFILLED, AREA CLEANED. (STREET IS ASPHALT OVER CONCRETE, 7 FT X 7 FT) (CONCRETE S/W 10 FT X 5 FT)	November 8, 2021, 3:10 PM	V-075DV003	Valve Condition	
WO-64637	1	Completed	44530.40967	44527	Valve Maintenance Report		V-075DV010	Valve Condition	
WO-64473	88	Completed	44527.18892	44530	Repair service line- if drilled, Drill Sheet work order MUST be completed	December 3, 2021, 2:27 PM	V-075DV015	Valve Condition	Poor
WO-61400	88	Completed	44491.46484	44508	Repair service line- if drilled, Drill Sheet work order MUST be completed Broken Stop will need repaired 3 day one call placed 9AM Monday 10/25/21 will need posted STREET LOCATION: 3433 SHADELAND AVE (W.O.61400) VEHICLES & CREWS: 233 STORMER, SANDS, 127 WHIGHAM, 675 GERMEYER WORK DESCRIPTION: CREW DUG OVER THE MAIN AND C/B IN THE S/W. NEW 1" TAP MADE REPLACED LEAD S/L. NEW C/S. CONNECTED TO H/O COPPER S/L HOLES BACKFILLED, AREA CLEANED. (STREET IS ASPHALT OVER CONCRETE, 7 FT X 7 FT) (CONCRETE S/W 10 FT X 5 FT)	November 8, 2021, 3:10 PM	V-075DV016	Valve Condition	
WO-61400	88	Completed	44491.46484	44508	Repair service line- if drilled, Drill Sheet work order MUST be completed Broken Stop will need repaired 3 day one call placed 9AM Monday 10/25/21 will need posted STREET LOCATION: 3433 SHADELAND AVE (W.O.61400) VEHICLES & CREWS: 233 STORMER, SANDS, 127 WHIGHAM, 675 GERMEYER WORK DESCRIPTION: CREW DUG OVER THE MAIN AND C/B IN THE S/W. NEW 1" TAP MADE REPLACED LEAD S/L. NEW C/S. CONNECTED TO H/O COPPER S/L HOLES BACKFILLED, AREA CLEANED. (STREET IS ASPHALT OVER CONCRETE, 7 FT X 7 FT) (CONCRETE S/W 10 FT X 5 FT)	November 8, 2021, 3:10 PM	V-075DV020	Valve Condition	
WO-64637	1	Completed	44530.40967	44527	Valve Maintenance Report		V-075DV022	Valve Condition	Poor

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-61400	88	Completed	44491.46484	44508	Repair service line- if drilled, Drill Sheet work order MUST be completed Broken Stop will need repaired 3 day one call placed 9AM Monday 10/25/21 will need posted STREET LOCATION: 3433 SHADELAND AVE (W.O.61400) VEHICLES & CREWS: 233 STORMER, SANDS, 127 WHIGHAM, 675 GERMEYER WORK DESCRIPTION: CREW DUG OVER THE MAIN AND C/B IN THE S/W. NEW 1" TAP MADE REPLACED LEAD S/L. NEW C/S. CONNECTED TO H/O COPPER S/L HOLES BACKFILLED, AREA CLEANED. (STREET IS ASPHALT OVER CONCRETE, 7 FT X 7 FT) (CONCRETE S/W 10 FT X 5 FT)	November 8, 2021, 3:10 PM	V-075DV023	Valve Condition	
WO-62029	1	Completed	44498.38671	44497	Valve Maintenance Report		V-075GV016	Valve Condition	
WO-62029	1	Completed	44498.38671	44497	Valve Maintenance Report		V-075GV017	Valve Condition	
WO-43106	85	Completed	44314.59445	44315	Repair water main. 8" no parking posted. 3 day 1 call placed. Large sinkhole forming. See picture below	April 30, 2021, 3:00 PM	V-075GV019	Valve Condition	Poor
WO-62029	1	Completed	44498.38671	44497	Valve Maintenance Report		V-075GV021	Valve Condition	
WO-62029	1	Completed	44498.38671	44497	Valve Maintenance Report		V-075GV022	Valve Condition	
WO-43108	1	Completed	44314.59445	44438	Repair water main. 8" no parking posted. 3 day 1 call placed. Large sinkhole forming. See picture below		V-075GV024	Valve Condition	Poor
WO-43108	1	Completed	44314.59445	44438	Repair water main. 8" no parking posted. 3 day 1 call placed. Large sinkhole forming. See picture below		V-075GV025	Valve Condition	Poor
WO-57002	1	Completed	44448.40092	44447	Valve Maintenance Report		V-075GV035	Valve Condition	
WO-57002	1	Completed	44448.40092	44447	Valve Maintenance Report		V-075GV037	Valve Condition	
WO-43106	85	Completed	44314.59445	44315	Repair water main. 8" no parking posted. 3 day 1 call placed. Large sinkhole forming. See picture below	April 30, 2021, 3:00 PM	V-075GV042	Valve Condition	Poor
WO-65269	41	Completed	44537.47736	44537	Contractor shut request	December 7, 2021, 5:28 PM	V-075HV012	Valve Condition	
WO-61400	88	Completed	44491.46484	44508	Repair service line- if drilled, Drill Sheet work order MUST be completed Broken Stop will need repaired 3 day one call placed 9AM Monday 10/25/21 will need posted STREET LOCATION: 3433 SHADELAND AVE (W.O.61400) VEHICLES & CREWS: 233 STORMER, SANDS, 127 WHIGHAM, 675 GERMEYER WORK DESCRIPTION: CREW DUG OVER THE MAIN AND C/B IN THE S/W. NEW 1" TAP MADE REPLACED LEAD S/L. NEW C/S. CONNECTED TO H/O COPPER S/L HOLES BACKFILLED, AREA CLEANED. (STREET IS ASPHALT OVER CONCRETE, 7 FT X 7 FT) (CONCRETE S/W 10 FT X 5 FT)	November 8, 2021, 3:10 PM	V-075HV015	Valve Condition	
WO-61400	88	Completed	44491.46484	44508	Repair service line- if drilled, Drill Sheet work order MUST be completed Broken Stop will need repaired 3 day one call placed 9AM Monday 10/25/21 will need posted STREET LOCATION: 3433 SHADELAND AVE (W.O.61400) VEHICLES & CREWS: 233 STORMER, SANDS, 127 WHIGHAM, 675 GERMEYER WORK DESCRIPTION: CREW DUG OVER THE MAIN AND C/B IN THE S/W. NEW 1" TAP MADE REPLACED LEAD S/L. NEW C/S. CONNECTED TO H/O COPPER S/L HOLES BACKFILLED, AREA CLEANED. (STREET IS ASPHALT OVER CONCRETE, 7 FT X 7 FT) (CONCRETE S/W 10 FT X 5 FT)	November 8, 2021, 3:10 PM	V-075HV022	Valve Condition	
WO-61400	88	Completed	44491.46484	44508	Repair service line- if drilled, Drill Sheet work order MUST be completed Broken Stop will need repaired 3 day one call placed 9AM Monday 10/25/21 will need posted STREET LOCATION: 3433 SHADELAND AVE (W.O.61400) VEHICLES & CREWS: 233 STORMER, SANDS, 127 WHIGHAM, 675 GERMEYER WORK DESCRIPTION: CREW DUG OVER THE MAIN AND C/B IN THE S/W. NEW 1" TAP MADE REPLACED LEAD S/L. NEW C/S. CONNECTED TO H/O COPPER S/L HOLES BACKFILLED, AREA CLEANED. (STREET IS ASPHALT OVER CONCRETE, 7 FT X 7 FT) (CONCRETE S/W 10 FT X 5 FT)	November 8, 2021, 3:10 PM	V-075HV023	Valve Condition	
WO-61400	88	Completed	44491.46484	44508	Repair service line- if drilled, Drill Sheet work order MUST be completed Broken Stop will need repaired 3 day one call placed 9AM Monday 10/25/21 will need posted STREET LOCATION: 3433 SHADELAND AVE (W.O.61400) VEHICLES & CREWS: 233 STORMER, SANDS, 127 WHIGHAM, 675 GERMEYER WORK DESCRIPTION: CREW DUG OVER THE MAIN AND C/B IN THE S/W. NEW 1" TAP MADE REPLACED LEAD S/L. NEW C/S. CONNECTED TO H/O COPPER S/L HOLES BACKFILLED, AREA CLEANED. (STREET IS ASPHALT OVER CONCRETE, 7 FT X 7 FT) (CONCRETE S/W 10 FT X 5 FT)	November 8, 2021, 3:10 PM	V-075HV024	Valve Condition	
WO-61400	88	Completed	44491.46484	44508	Repair service line- if drilled, Drill Sheet work order MUST be completed Broken Stop will need repaired 3 day one call placed 9AM Monday 10/25/21 will need posted STREET LOCATION: 3433 SHADELAND AVE (W.O.61400) VEHICLES & CREWS: 233 STORMER, SANDS, 127 WHIGHAM, 675 GERMEYER WORK DESCRIPTION: CREW DUG OVER THE MAIN AND C/B IN THE S/W. NEW 1" TAP MADE REPLACED LEAD S/L. NEW C/S. CONNECTED TO H/O COPPER S/L HOLES BACKFILLED, AREA CLEANED. (STREET IS ASPHALT OVER CONCRETE, 7 FT X 7 FT) (CONCRETE S/W 10 FT X 5 FT)	November 8, 2021, 3:10 PM	V-075HV025	Valve Condition	
WO-65269	41	Completed	44537.47736	44537	Contractor shut request	December 7, 2021, 5:28 PM	V-075LV020	Valve Condition	
WO-35857	1	Completed	44232.57732	44236	Repair water main		V-075LV022	Valve Condition	Fair
WO-35662	1	Completed	44231.48984	44235	Repair water main		V-075LV023	Valve Condition	Fair
WO-66927	1	Completed	44564.4525	44558	Valve Maintenance Report		V-075LV024	Valve Condition	
WO-45474	1	Completed	44336.32603	44337	Repair water main		V-075MV005	Valve Condition	
WO-45474	1	Completed	44336.32603	44337	Repair water main		V-075MV006	Valve Condition	Fair
WO-35662	1	Completed	44231.48984	44235	Repair water main		V-075MV013	Valve Condition	
WO-44924	85	Completed	44332.39961	44332	Repair water main	May 16, 2021, 6:14 PM	V-075MV014	Valve Condition	
WO-56259	1	Completed	44440.37948	44405	Valve Maintenance Report		V-075MV017	Valve Condition	
WO-56259	1	Completed	44440.37948	44405	Valve Maintenance Report		V-075MV022	Valve Condition	
WO-56259	1	Completed	44440.37948	44405	Valve Maintenance Report		V-075MV023	Valve Condition	
WO-56259	1	Completed	44440.37948	44405	Valve Maintenance Report		V-075MV024	Valve Condition	
WO-45474	1	Completed	44336.32603	44337	Repair water main		V-075MV025	Valve Condition	
WO-56259	1	Completed	44440.37948	44405	Valve Maintenance Report		V-075MV026	Valve Condition	
WO-56259	1	Completed	44440.37948	44405	Valve Maintenance Report		V-075MV027	Valve Condition	
WO-56259	1	Completed	44440.37948	44405	Valve Maintenance Report		V-075MV033	Valve Condition	
WO-66743	1	Completed	44559.39663	44559	Valve Maintenance Report	December 29, 2021, 9:42 AM	V-075RV006	Valve Condition	
WO-66741	43	Completed	44559.3932	44559	Test shut	December 29, 2021, 9:43 AM	V-075RV017	Valve Condition	
WO-46484	1	Completed	44343.42323	44439	Repair water main		V-075RV020	Valve Condition	
WO-44924	85	Completed	44332.39961	44332	Repair water main	May 16, 2021, 6:14 PM	V-075RV022	Valve Condition	
WO-66743	1	Completed	44559.39663	44559	Valve Maintenance Report	December 29, 2021, 9:42 AM	V-075RV031	Valve Condition	
WO-66741	43	Completed	44559.3932	44559	Test shut	December 29, 2021, 9:43 AM	V-075RV032	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-59959	1	Completed	44476.62104	44476	Valve Maintenance Report		V-075SV014	Valve Condition	
WO-58518	1	Completed	44463.37464	44470	Repair water main	October 4, 2021, 7:35 AM	V-075SV015	Valve Condition	
WO-59144	21	Completed	44469.48097	44481	Valve requires replacement- 075sv023	October 12, 2021, 3:19 PM	V-075SV021	Valve Condition	
WO-59144	21	Completed	44469.48097	44481	Valve requires replacement- 075sv023	October 12, 2021, 3:19 PM	V-075SV022	Valve Condition	
WO-59144	21	Completed	44469.48097	44481	Valve requires replacement- 075sv023	October 12, 2021, 3:19 PM	V-075SV023	Valve Condition	
WO-59144	21	Completed	44469.48097	44481	Valve requires replacement- 075sv023	October 12, 2021, 3:19 PM	V-075SV024	Valve Condition	
WO-64637	1	Completed	44530.40967	44527	Valve Maintenance Report		V-076AV002	Valve Condition	
WO-64637	1	Completed	44530.40967	44527	Valve Maintenance Report		V-076AV007	Valve Condition	
WO-65221	1	Completed	44537.37933	44537	Valve Maintenance Report		V-076AV021	Valve Condition	Good
WO-65221	1	Completed	44537.37933	44537	Valve Maintenance Report		V-076AV031	Valve Condition	Good
WO-47824	41	Completed	44355.39055	44355	Contractor shut request	June 8, 2021, 9:27 AM	V-076BV008	Valve Condition	Good
WO-47824	41	Completed	44355.39055	44355	Contractor shut request	June 8, 2021, 9:27 AM	V-076BV009	Valve Condition	Good
WO-47824	41	Completed	44355.39055	44355	Contractor shut request	June 8, 2021, 9:27 AM	V-076BV013	Valve Condition	Good
WO-47824	41	Completed	44355.39055	44355	Contractor shut request	June 8, 2021, 9:27 AM	V-076BV014	Valve Condition	Good
WO-53849	182	Completed	44412.62593	44413	Information sheet for connection SEND WASTE WATER. LEAK IS SHUT OFF. SEE NOTES BELOW.		V-076FV007	Valve Condition	
WO-36674	85	Completed	44243.43915	44244	Repair water main	February 17, 2021, 3:23 PM	V-076FV008	Valve Condition	Good
WO-34299	88	Completed	44218.57928	44328	Repair service line: This Work Order is for a Non-Metered City of Pittsburgh Properties. a crock and 1-1/2" meter need installed at the curb stop. This curb box is full and I was unable to get on the curb stop	May 12, 2021, 2:15 PM	V-076GV003	Valve Condition	
WO-61579	1	Completed	44494.61582	44494	Valve Maintenance Report	October 25, 2021, 2:47 PM	V-076JV018	Valve Condition	Good
WO-36954	1	Completed	44245.82679	44246	Repair water main	February 19, 2021, 1:44 AM	V-076JV019	Valve Condition	Good
WO-45474	1	Completed	44336.32603	44337	Repair water main		V-076JV031	Valve Condition	
WO-53849	182	Completed	44412.62593	44413	Information sheet for connection SEND WASTE WATER. LEAK IS SHUT OFF. SEE NOTES BELOW.		V-076KV001	Valve Condition	
WO-36952	85	Completed	44245.82679	44245	Repair water main	February 19, 2021, 2:38 AM	V-076KV006	Valve Condition	Fair
WO-36820	84	Completed	44244.6884	44245	Main or service line leak investigation/survey/PER TECH WATER LEAK WAS ON A JOB AT 1018 ROTHPLETZ ST WATER COMING UP OUT OF SIDEWALK & CURB RECIEVED A CALL FROM A CUSTOMER AT 912 ROTHPLETZ ST NO WATER INSIDE HOME MAJOR WATER BREAK	February 18, 2021, 6:36 AM	V-076KV015	Valve Condition	Poor
WO-36954	1	Completed	44245.82679	44246	Repair water main	February 19, 2021, 1:44 AM	V-076KV033	Valve Condition	Good
WO-60327	1	Completed	44481.33934	44481	Repair water main		V-076NV010	Valve Condition	
WO-61578	1	Completed	44494.6148	44494	Valve Maintenance Report	October 25, 2021, 2:49 PM	V-076NV016	Valve Condition	Good
WO-46864	1	Completed	44348.61095	44349	Valve Maintenance Report	June 2, 2021, 10:49 AM	V-076NV026	Valve Condition	
WO-55829	85	Completed	44435.28007	44435	Repair water main	August 30, 2021, 12:52 PM	V-076NV047	Valve Condition	
WO-33921	85	Completed	44215.64488	44215	Repair water main	January 19, 2021, 10:27 PM	V-077NV002	Valve Condition	
WO-50669	683	Completed	44377.53361	44377	Contractor pulled service line	June 30, 2021, 1:54 PM	V-077NV010	Valve Condition	Fair
WO-49041	88	Completed	44364.38695	44417	Curb box replacement 06/14/2021 Carson VanDyke property not razed property vacant,,,, located curb box but could not shut water off due to curb stop key being broken,,, water leaking out of right side of the house,,,, curb box fills up with water as soon as it's blown out,,,, needs dug to stop the leaking inside the property VEHICLES/CREW: 233 STORMER, CIMINO/ 127 WHIGHAM/ 675 DAY JOB: BROKEN C/S THE DRILL SHEET SHOWED A LEAD S/L FOR THE ADDRESS. THE CREW DUG THE SIDEWALK AND WE FOUND ¾" COPPER ON BOTH SIDES OF THE C/S. THE CREW DUG BACK 4' TO EXPOSE MORE OF THE LINE. IT WAS COPPER THE ENTIRE LENGTH. OUR PLUMBER CRIMPED THE LINE AND REPLACED THE C/S. THE HOUSE IS ABANDONED, SO WE LEFT IT SHUT. THE NEW C/B WAS SET AND THE SIDEWALK WAS BACKFILLED AND TAMPED. THE STREET WAS BACKFILED, COLD PATCHED AND TAMPED.	August 9, 2021, 2:56 PM	V-077NV022	Valve Condition	
WO-35635	85	Completed	44231.37722	44231	Repair water main	February 4, 2021, 6:07 PM	V-077NV028	Valve Condition	
WO-63268	1	Completed	44509.61732	44510	Repair water main		V-077PV013	Valve Condition	
WO-63268	1	Completed	44509.61732	44510	Repair water main		V-077PV021	Valve Condition	
WO-35635	85	Completed	44231.37722	44231	Repair water main	February 4, 2021, 6:07 PM	V-077PV050	Valve Condition	
WO-65283	1	Completed	44537.57902	44537	Valve Maintenance Report	December 7, 2021, 1:55 PM	V-078FV015	Valve Condition	
WO-65274	1	Completed	44537.53352	44537	Valve Maintenance Report	December 7, 2021, 12:49 PM	V-078LV001	Valve Condition	
WO-65281	1	Completed	44537.57759	44537	Valve Maintenance Report	December 7, 2021, 1:52 PM	V-078LV002	Valve Condition	
WO-65153	1	Completed	44536.56838	44536	Valve Maintenance Report	December 6, 2021, 1:49 PM	V-078LV005	Valve Condition	
WO-65150	1	Completed	44536.54978	44536	Valve Maintenance Report	December 6, 2021, 1:13 PM	V-078RV001	Valve Condition	
WO-65152	1	Completed	44536.56138	44536	Valve Maintenance Report	December 6, 2021, 1:29 PM	V-078RV002	Valve Condition	
WO-57944	1	Completed	44459.42001	44459	Valve Maintenance Report		V-078RV004	Valve Condition	
WO-63885	84	Completed	44518.69133	44519	Main or service line leak investigation/survey		V-079AV003	Valve Condition	
WO-46316	1	Completed	44342.44427	44343	Valve Maintenance Report	May 27, 2021, 6:16 AM	V-079AV007	Valve Condition	Good
WO-63885	84	Completed	44518.69133	44519	Main or service line leak investigation/survey		V-079AV012	Valve Condition	
WO-63885	84	Completed	44518.69133	44519	Main or service line leak investigation/survey		V-079AV013	Valve Condition	
WO-63885	84	Completed	44518.69133	44519	Main or service line leak investigation/survey		V-079AV018	Valve Condition	
WO-46316	1	Completed	44342.44427	44343	Valve Maintenance Report	May 27, 2021, 6:16 AM	V-079AV019	Valve Condition	Good
WO-46316	1	Completed	44342.44427	44343	Valve Maintenance Report	May 27, 2021, 6:16 AM	V-079AV020	Valve Condition	Good
WO-54506	1	Completed	44420.38163	44482	Repair water main		V-079BV001	Valve Condition	
WO-54506	1	Completed	44420.38163	44482	Repair water main		V-079BV002	Valve Condition	
WO-45656	1	Completed	44337.35283	44340	Valve Maintenance Report	May 24, 2021, 8:14 AM	V-079BV003	Valve Condition	
WO-45656	1	Completed	44337.35283	44340	Valve Maintenance Report	May 24, 2021, 8:14 AM	V-079BV004	Valve Condition	
WO-43950	1	Completed	44322.52482	44326	Repair water main		V-079BV009	Valve Condition	Good
WO-46316	1	Completed	44342.44427	44343	Valve Maintenance Report	May 27, 2021, 6:16 AM	V-079BV015	Valve Condition	Good
WO-52016	1	Completed	44391.51966	44391	Valve Maintenance Report	July 14, 2021, 2:41 PM	V-079BV019	Valve Condition	
WO-46316	1	Completed	44342.44427	44343	Valve Maintenance Report	May 27, 2021, 6:16 AM	V-079BV023	Valve Condition	Good
WO-54506	1	Completed	44420.38163	44482	Repair water main		V-079BV025	Valve Condition	Good
WO-45656	1	Completed	44337.35283	44340	Valve Maintenance Report	May 24, 2021, 8:14 AM	V-079BV026	Valve Condition	
WO-50412	43	Completed	44376.02913	44376	Test shut	June 29, 2021, 6:53 AM	V-079BV028	Valve Condition	Good
WO-46316	1	Completed	44342.44427	44343	Valve Maintenance Report	May 27, 2021, 6:16 AM	V-079CV003	Valve Condition	Good
WO-46605	1	Completed	44344.35007	44349	Valve Maintenance Report	June 2, 2021, 9:04 AM	V-079CV004	Valve Condition	
WO-46605	1	Completed	44344.35007	44349	Valve Maintenance Report	June 2, 2021, 9:04 AM	V-079CV005	Valve Condition	
WO-46605	1	Completed	44344.35007	44349	Valve Maintenance Report	June 2, 2021, 9:04 AM	V-079CV006	Valve Condition	
WO-46760	1	Completed	44348.33441	44349	Valve Maintenance Report	June 2, 2021, 9:04 AM	V-079CV007	Valve Condition	Fair
WO-50412	43	Completed	44376.02913	44376	Test shut	June 29, 2021, 6:53 AM	V-079CV009	Valve Condition	
WO-46605	1	Completed	44344.35007	44349	Valve Maintenance Report	June 2, 2021, 9:04 AM	V-079CV010	Valve Condition	
WO-40617	1	Completed	44287.34204	44291	Valve Maintenance Report	April 5, 2021, 8:01 AM	V-079CV012	Valve Condition	Good
WO-46605	1	Completed	44344.35007	44349	Valve Maintenance Report	June 2, 2021, 9:04 AM	V-079CV013	Valve Condition	
WO-44058	41	Completed	44323.44222	44323	Contractor shut request	May 7, 2021, 11:15 AM	V-079CV014	Valve Condition	
WO-52016	1	Completed	44391.51966	44391	Valve Maintenance Report	July 14, 2021, 2:41 PM	V-079CV016	Valve Condition	Good
WO-52016	1	Completed	44391.51966	44391	Valve Maintenance Report	July 14, 2021, 2:41 PM	V-079CV017	Valve Condition	Good
WO-61121	1	Completed	44488.60703	44496	Repair water main 4" contractor hit main. Per Bob White, McCarthy sending a crew to help shut down.		V-079CV019	Valve Condition	
WO-40617	1	Completed	44287.34204	44291	Valve Maintenance Report	April 5, 2021, 8:01 AM	V-079CV024	Valve Condition	Good
WO-46466	1	Completed	44343.37154	44344	Valve Maintenance Report	May 28, 2021, 7:32 AM	V-079DV002	Valve Condition	Good
WO-39310	41	Completed	44272.6022	44272	Contractor shut request	March 17, 2021, 2:55 PM	V-079DV004	Valve Condition	
WO-46316	1	Completed	44342.44427	44343	Valve Maintenance Report	May 27, 2021, 6:16 AM	V-079GV002	Valve Condition	Good
WO-44839	464	Completed	44330.48266	44330	Contractor damage to water main	May 14, 2021, 11:48 AM	V-079GV004	Valve Condition	
WO-46144	1	Completed	44341.46465	44349	Valve Maintenance Report	May 26, 2021, 8:53 AM	V-079GV009	Valve Condition	Good
WO-46144	1	Completed	44341.46465	44349	Valve Maintenance Report	May 26, 2021, 8:53 AM	V-079HV009	Valve Condition	
WO-46144	1	Completed	44341.46465	44349	Valve Maintenance Report	May 26, 2021, 8:53 AM	V-079HV013	Valve Condition	
WO-46144	1	Completed	44341.46465	44349	Valve Maintenance Report	May 26, 2021, 8:53 AM	V-079HV014	Valve Condition	
WO-61801	41	Completed	44496.47998	44497	Contractor shut request	October 28, 2021, 1:26 PM	V-079HV015	Valve Condition	
WO-66618	1	Completed	44557.45578	44557	Valve Maintenance Report	December 27, 2021, 10:59 AM	V-079HV021	Valve Condition	
WO-46466	1	Completed	44343.37154	44344	Valve Maintenance Report	May 28, 2021, 7:32 AM	V-079HV022	Valve Condition	Good
WO-46466	1	Completed	44343.37154	44344	Valve Maintenance Report	May 28, 2021, 7:32 AM	V-079HV024	Valve Condition	Good
WO-46466	1	Completed	44343.37154	44344	Valve Maintenance Report	May 28, 2021, 7:32 AM	V-079HV025	Valve Condition	Good
WO-46525	1	Completed	44343.53023	44344	Valve Maintenance Report	May 28, 2021, 7:32 AM	V-079HV026	Valve Condition	Good
WO-46466	1	Completed	44343.37154	44344	Valve Maintenance Report	May 28, 2021, 7:32 AM	V-079HV028	Valve Condition	Good
WO-46525	1	Completed	44343.53023	44344	Valve Maintenance Report	May 28, 2021, 7:32 AM	V-079HV029	Valve Condition	Good
WO-54215	1	Completed	44417.55484	44417	Valve Maintenance Report	August 9, 2021, 1:20 PM	V-079HV049	Valve Condition	
WO-54220	1	Completed	44417.58006	44417	Valve Maintenance Report	August 9, 2021, 1:56 PM	V-079HV054	Valve Condition	
WO-46466	1	Completed	44343.37154	44344	Valve Maintenance Report	May 28, 2021, 7:32 AM	V-079HV055	Valve Condition	Good
WO-46144	1	Completed	44341.46465	44349	Valve Maintenance Report	May 26, 2021, 8:53 AM	V-079HV056	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-46466	1	Completed	44343.37154	44344	Valve Maintenance Report	May 28, 2021, 7:32 AM	V-079HV057	Valve Condition	Good
WO-46525	1	Completed	44343.53023	44344	Valve Maintenance Report	May 28, 2021, 7:32 AM	V-079HV058	Valve Condition	Good
WO-46144	1	Completed	44341.46465	44349	Valve Maintenance Report	May 26, 2021, 8:53 AM	V-079HV059	Valve Condition	
WO-46144	1	Completed	44341.46465	44349	Valve Maintenance Report	May 26, 2021, 8:53 AM	V-079HV060	Valve Condition	
WO-46144	1	Completed	44341.46465	44349	Valve Maintenance Report	May 26, 2021, 8:53 AM	V-079HV061	Valve Condition	
WO-46466	1	Completed	44343.37154	44344	Valve Maintenance Report	May 28, 2021, 7:32 AM	V-079HV062	Valve Condition	Good
WO-46466	1	Completed	44343.37154	44344	Valve Maintenance Report	May 28, 2021, 7:32 AM	V-079HV064	Valve Condition	Good
WO-46466	1	Completed	44343.37154	44344	Valve Maintenance Report	May 28, 2021, 7:32 AM	V-079HV066	Valve Condition	Good
WO-46466	1	Completed	44343.37154	44344	Valve Maintenance Report	May 28, 2021, 7:32 AM	V-079HV067	Valve Condition	Good
WO-39310	41	Completed	44272.6022	44272	Contractor shut request	March 17, 2021, 2:55 PM	V-079HV068	Valve Condition	
WO-34686	41	Completed	44223.37842	44223	Contractor shut request	January 27, 2021, 2:36 PM	V-079LV001	Valve Condition	
WO-33161	85	Completed	44208.43985	44217	Repair water main. Very little water showing on a steep hill. Causing ice. 4". Too many existing repairs to shoot entire street. Dig at abandoned service line. SHUT N CUT OR ON THE MAIN. Service line is 15' up from water showing. NO PARKING NEEDS POSTED. 1 call valid 1/15/21. IF NEEDED, LD can shoot from open hole up to RESERVE TWP meter. View pictures below MAKE SURE ROBO CALL GOES OUT AHEAD OF TIME. PEOPLE CONCERNED	January 21, 2021, 3:49 PM	V-079LV004	Valve Condition	
WO-39738	1	Completed	44278.47665	44278	Valve Maintenance Report	March 23, 2021, 11:32 AM	V-079LV009	Valve Condition	
WO-34686	41	Completed	44223.37842	44223	Contractor shut request	January 27, 2021, 2:36 PM	V-079MV002	Valve Condition	
WO-34686	41	Completed	44223.37842	44223	Contractor shut request	January 27, 2021, 2:36 PM	V-079MV003	Valve Condition	
WO-34686	41	Completed	44223.37842	44223	Contractor shut request	January 27, 2021, 2:36 PM	V-079MV004	Valve Condition	
WO-40634	1	Completed	44287.40957	44287	Valve Maintenance Report	April 1, 2021, 1:56 PM	V-080BV007	Valve Condition	
WO-40634	1	Completed	44287.40957	44287	Valve Maintenance Report	April 1, 2021, 1:56 PM	V-080BV009	Valve Condition	
WO-32472	84	Completed	44201.63177	44201	Main or service line leak investigation/survey PEOPLE'S GAS RAY 412-244-3538 , STATES THEY HIT UNMARKED WATER LINE	January 5, 2021, 9:18 PM	V-080CV014	Valve Condition	
WO-32472	84	Completed	44201.63177	44201	Main or service line leak investigation/survey PEOPLE'S GAS RAY 412-244-3538 , STATES THEY HIT UNMARKED WATER LINE	January 5, 2021, 9:18 PM	V-080CV015	Valve Condition	
WO-32472	84	Completed	44201.63177	44201	Main or service line leak investigation/survey PEOPLE'S GAS RAY 412-244-3538 , STATES THEY HIT UNMARKED WATER LINE	January 5, 2021, 9:18 PM	V-080CV016	Valve Condition	
WO-50431	1	Completed	44376.34831	44376	Valve Maintenance Report	June 29, 2021, 1:53 PM	V-080DV016	Valve Condition	
WO-51773	84	Completed	44390.05807	44391	Main or service line leak investigation/survey	July 14, 2021, 7:02 AM	V-080DV020	Valve Condition	
WO-51773	84	Completed	44390.05807	44391	Main or service line leak investigation/survey	July 14, 2021, 7:02 AM	V-080DV022	Valve Condition	
WO-51773	84	Completed	44390.05807	44391	Main or service line leak investigation/survey	July 14, 2021, 7:02 AM	V-080DV023	Valve Condition	
WO-51809	1	Completed	44390.35721	44390	Valve Maintenance Report	July 13, 2021, 9:05 AM	V-080DV039	Valve Condition	
WO-51809	1	Completed	44390.35721	44390	Valve Maintenance Report	July 13, 2021, 9:05 AM	V-080DV046	Valve Condition	
WO-51809	1	Completed	44390.35721	44390	Valve Maintenance Report	July 13, 2021, 9:05 AM	V-080DV071	Valve Condition	
WO-35737	1	Completed	44231.80186	44232	Repair water main	February 4, 2021, 10:31 PM	V-080DV072	Valve Condition	Fair
WO-50431	1	Completed	44376.34831	44376	Valve Maintenance Report	June 29, 2021, 1:53 PM	V-080DV074	Valve Condition	
WO-50431	1	Completed	44376.34831	44376	Valve Maintenance Report	June 29, 2021, 1:53 PM	V-080DV078	Valve Condition	
WO-36658	1	Completed	44243.39612	44243	Valve Maintenance Report	February 16, 2021, 2:44 PM	V-080DV079	Valve Condition	
WO-36658	1	Completed	44243.39612	44243	Valve Maintenance Report	February 16, 2021, 2:44 PM	V-080DV080	Valve Condition	
WO-36658	1	Completed	44243.39612	44243	Valve Maintenance Report	February 16, 2021, 2:44 PM	V-080DV081	Valve Condition	
WO-36658	1	Completed	44243.39612	44243	Valve Maintenance Report	February 16, 2021, 2:44 PM	V-080DV082	Valve Condition	
WO-58133	1	Completed	44460.46474	44470	Repair water main		V-080DV096	Valve Condition	
WO-50431	1	Completed	44376.34831	44376	Valve Maintenance Report	June 29, 2021, 1:53 PM	V-080DV097	Valve Condition	
WO-50431	1	Completed	44376.34831	44376	Valve Maintenance Report	June 29, 2021, 1:53 PM	V-080DV100	Valve Condition	
WO-50431	1	Completed	44376.34831	44376	Valve Maintenance Report	June 29, 2021, 1:53 PM	V-080DV102	Valve Condition	
WO-50431	1	Completed	44376.34831	44376	Valve Maintenance Report	June 29, 2021, 1:53 PM	V-080DV107	Valve Condition	
WO-64040	1	Completed	44522.29685	44521	Valve Maintenance Report		V-080GV009	Valve Condition	
WO-64040	1	Completed	44522.29685	44521	Valve Maintenance Report		V-080GV014	Valve Condition	
WO-47924	1	Completed	44356.42668	44356	Valve Maintenance Report	June 9, 2021, 10:22 AM	V-080GV026	Valve Condition	
WO-47712	1	Completed	44354.48428	44354	Valve Maintenance Report	June 7, 2021, 2:15 PM	V-080GV027	Valve Condition	
WO-39786	1	Completed	44279.33508	44280	Valve Maintenance Report	March 25, 2021, 7:35 AM	V-080GV035	Valve Condition	Good
WO-47303	1	Completed	44350.34962	44350	Valve Maintenance Report	June 3, 2021, 8:39 AM	V-080GV038	Valve Condition	Fair
WO-32472	84	Completed	44201.63177	44201	Main or service line leak investigation/survey PEOPLE'S GAS RAY 412-244-3538 , STATES THEY HIT UNMARKED WATER LINE	January 5, 2021, 9:18 PM	V-080GV043	Valve Condition	
WO-51752	85	Completed	44389.62443	44389	Repair water main	July 12, 2021, 11:55 PM	V-080GV052	Valve Condition	Good
WO-38033	85	Completed	44258.43224	44272	Repair water main	March 17, 2021, 10:48 AM	V-080GV053	Valve Condition	
WO-51752	85	Completed	44389.62443	44389	Repair water main	July 12, 2021, 11:55 PM	V-080GV054	Valve Condition	Good
WO-38033	85	Completed	44258.43224	44272	Repair water main	March 17, 2021, 10:48 AM	V-080GV055	Valve Condition	Good
WO-47924	1	Completed	44356.42668	44356	Valve Maintenance Report	June 9, 2021, 10:22 AM	V-080GV057	Valve Condition	
WO-51752	85	Completed	44389.62443	44389	Repair water main	July 12, 2021, 11:55 PM	V-080GV061	Valve Condition	Good
WO-51752	85	Completed	44389.62443	44389	Repair water main	July 12, 2021, 11:55 PM	V-080GV064	Valve Condition	Good
WO-59318	1	Completed	44470.98841	44473	Repair water main		V-080HV016	Valve Condition	
WO-41550	85	Completed	44299.78407	44299	Repair water main	April 13, 2021, 10:46 PM	V-080HV023	Valve Condition	Fair
WO-57836	1	Completed	44456.6396	44459	DIG & REPAIR 6" LEAK	September 20, 2021, 7:47 AM	V-080HV026	Valve Condition	
WO-45807	1	Completed	44339.35451	44340	Repair water main		V-080HV033	Valve Condition	
WO-37534	41	Completed	44252.47333	44252	Contractor shut request	February 25, 2021, 11:24 AM	V-080HV034	Valve Condition	
WO-45807	1	Completed	44339.35451	44340	Repair water main		V-080HV035	Valve Condition	
WO-45807	1	Completed	44339.35451	44340	Repair water main		V-080HV036	Valve Condition	
WO-51773	84	Completed	44390.05807	44391	Main or service line leak investigation/survey	July 14, 2021, 7:02 AM	V-080HV039	Valve Condition	
WO-58133	1	Completed	44460.46474	44470	Repair water main		V-080HV040	Valve Condition	
WO-59319	85	Completed	44470.99347	44471	Repair water main	October 4, 2021, 4:09 PM	V-080HV041	Valve Condition	
WO-59319	85	Completed	44470.99347	44471	Repair water main	October 4, 2021, 4:09 PM	V-080HV042	Valve Condition	
WO-59319	85	Completed	44470.99347	44471	Repair water main	October 4, 2021, 4:09 PM	V-080HV049	Valve Condition	
WO-38035	1	Completed	44258.43224	44272	Repair water main		V-080HV051	Valve Condition	Good
WO-50431	1	Completed	44376.34831	44376	Valve Maintenance Report	June 29, 2021, 1:53 PM	V-080HV052	Valve Condition	
WO-41550	85	Completed	44299.78407	44299	Repair water main	April 13, 2021, 10:46 PM	V-080HV054	Valve Condition	Fair
WO-45807	1	Completed	44339.35451	44340	Repair water main		V-080HV062	Valve Condition	
WO-57836	1	Completed	44456.6396	44459	DIG & REPAIR 6" LEAK	September 20, 2021, 7:47 AM	V-080HV064	Valve Condition	
WO-50972	85	Completed	44381.71084	44381	Repair water main	July 4, 2021, 10:15 PM	V-080KV029	Valve Condition	Good
WO-47712	1	Completed	44354.48428	44354	Valve Maintenance Report	June 7, 2021, 2:15 PM	V-080LV012	Valve Condition	
WO-56719	1	Completed	44445.52843	44446	Repair water main		V-080NV037	Valve Condition	
WO-56719	1	Completed	44445.52843	44446	Repair water main		V-080NV044	Valve Condition	
WO-51896	88	Completed	44390.76379	44391	Repair service line-Lead and leak on PWSA side, emergency 1-called 5:50pm 7/13/21, street posted both sides 7/14-7/16 7a-5p	July 14, 2021, 1:54 PM	V-080PV008	Valve Condition	Good
WO-51896	88	Completed	44390.76379	44391	Repair service line-Lead and leak on PWSA side, emergency 1-called 5:50pm 7/13/21, street posted both sides 7/14-7/16 7a-5p	July 14, 2021, 1:54 PM	V-080PV022	Valve Condition	Good
WO-50972	85	Completed	44381.71084	44381	Repair water main	July 4, 2021, 10:15 PM	V-080PV029	Valve Condition	Good
WO-60781	1	Completed	44484.45842	44484	Valve Maintenance Report	October 15, 2021, 11:03 AM	V-081AV008	Valve Condition	
WO-60785	1	Completed	44484.46821	44484	Valve Maintenance Report	October 15, 2021, 11:17 AM	V-081AV029	Valve Condition	
WO-60923	1	Completed	44487.42544	44487	Valve Maintenance Report	October 18, 2021, 10:15 AM	V-081AV035	Valve Condition	
WO-60916	1	Completed	44487.41401	44487	Valve Maintenance Report	October 18, 2021, 9:58 AM	V-081AV036	Valve Condition	
WO-60911	1	Completed	44487.39838	44487	Valve Maintenance Report	October 18, 2021, 9:37 AM	V-081AV037	Valve Condition	
WO-60906	1	Completed	44487.38842	44487	Valve Maintenance Report	October 18, 2021, 9:22 AM	V-081AV038	Valve Condition	
WO-59927	1	Completed	44476.49933	44476	Valve Maintenance Report	October 7, 2021, 12:03 PM	V-081AV040	Valve Condition	
WO-59756	1	Completed	44475.55209	44475	Valve Maintenance Report	October 6, 2021, 1:18 PM	V-081BV004	Valve Condition	Fair
WO-59755	1	Completed	44475.53607	44475	Valve Maintenance Report	October 6, 2021, 12:57 PM	V-081BV005	Valve Condition	
WO-48724	88	Completed	44362.60912	44369	Repair service line	June 22, 2021, 3:21 PM	V-081BV008	Valve Condition	
WO-59216	1	Completed	44470.36468	44470	Valve Maintenance Report	October 1, 2021, 8:48 AM	V-081BV009	Valve Condition	
WO-59212	1	Completed	44470.35796	44470	Valve Maintenance Report	October 1, 2021, 8:39 AM	V-081BV011	Valve Condition	
WO-59753	1	Completed	44475.51913	44475	Valve Maintenance Report	October 6, 2021, 12:31 PM	V-081BV012	Valve Condition	
WO-59769	1	Completed	44475.58191	44476	Valve Maintenance Report	October 6, 2021, 2:05 PM	V-081BV015	Valve Condition	
WO-59763	1	Completed	44475.57213	44475	Valve Maintenance Report	October 6, 2021, 1:50 PM	V-081BV016	Valve Condition	Fair
WO-59224	1	Completed	44470.3824	44470	Valve Maintenance Report	October 1, 2021, 2:39 PM	V-081CV006	Valve Condition	
WO-37918	84	Completed	44257.50012	44257	Customer called to report a leak at the above address, he said the that the water is running in the back of his house. He is not sure but he believes it my be going into the neighbor's house.4428 called to report water in her basement coming from woodbine st.		V-081CV008	Valve Condition	
WO-59338	1	Completed	44473.33832	44476	Valve Maintenance Report	October 7, 2021, 2:50 PM	V-081CV009	Valve Condition	
WO-65895	1	Completed	44544.59468	44544	Valve Maintenance Report	December 14, 2021, 2:19 PM	V-081CV011	Valve Condition	
WO-66240	1	Completed	44547.60261	44547	Valve Maintenance Report	December 17, 2021, 2:30 PM	V-081CV012	Valve Condition	
WO-59224	1	Completed	44470.3824	44470	Valve Maintenance Report	October 1, 2021, 2:39 PM	V-081CV013	Valve Condition	
WO-44483	1	Completed	44328.36209	44328	Valve Maintenance Report	May 12, 2021, 3:55 PM	V-081CV016	Valve Condition	
WO-66203	1	Completed	44547.57773	44547	Valve Maintenance Report	December 17, 2021, 1:55 PM	V-081CV017	Valve Condition	
WO-62188	1	Completed	44501.46586	44501	Valve Maintenance Report	November 1, 2021, 11:13 AM	V-081CV018	Valve Condition	
WO-46116	1	Completed	44341.43024	44349	Valve Maintenance Report	May 26, 2021, 8:53 AM	V-081CV019	Valve Condition	Good
WO-44483	1	Completed	44328.36209	44328	Valve Maintenance Report	May 12, 2021, 3:55 PM	V-081CV020	Valve Condition	
WO-44483	1	Completed	44328.36209	44328	Valve Maintenance Report	May 12, 2021, 3:55 PM	V-081CV021	Valve Condition	
WO-59338	1	Completed	44473.33832	44476	Valve Maintenance Report	October 7, 2021, 2:50 PM	V-081CV022	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-61695	1	Completed	44495.47478	44495		October 26, 2021, 11:26 AM	V-081CV023	Valve Condition	
WO-62509	1	Completed	44503.58872	44503	Valve Maintenance Report	November 3, 2021, 2:10 PM	V-081CV024	Valve Condition	
WO-32195	1	Completed	44196.95551	44198	Repair water main	January 21, 2021, 9:25 AM	V-081CV025	Valve Condition	
WO-61694	1	Completed	44495.46885	44495	Valve Maintenance Report	October 26, 2021, 11:21 AM	V-081CV030	Valve Condition	
WO-61712	1	Completed	44495.55065	44495	Valve Maintenance Report	October 26, 2021, 1:15 PM	V-081CV031	Valve Condition	
WO-61715	1	Completed	44495.56378	44495	Valve Maintenance Report	October 26, 2021, 1:34 PM	V-081CV032	Valve Condition	
WO-61718	1	Completed	44495.58775	44495	Valve Maintenance Report	October 26, 2021, 2:09 PM	V-081CV033	Valve Condition	
WO-66012	1	Completed	44545.54814	44545	Valve Maintenance Report	December 15, 2021, 1:13 PM	V-081CV034	Valve Condition	
WO-44483	1	Completed	44328.36209	44328	Valve Maintenance Report	May 12, 2021, 3:55 PM	V-081CV037	Valve Condition	
WO-44483	1	Completed	44328.36209	44328	Valve Maintenance Report	May 12, 2021, 3:55 PM	V-081DV001	Valve Condition	
WO-44483	1	Completed	44328.36209	44328	Valve Maintenance Report	May 12, 2021, 3:55 PM	V-081DV002	Valve Condition	
WO-59157	1	Completed	44469.49257	44469	Valve Maintenance Report	September 30, 2021, 11:53 AM	V-081DV005	Valve Condition	
WO-66147	1	Completed	44547.34495	44547	Valve Maintenance Report	December 17, 2021, 8:20 AM	V-081DV006	Valve Condition	
WO-59158	1	Completed	44469.50333	44469	Valve Maintenance Report	September 30, 2021, 12:10 PM	V-081DV007	Valve Condition	
WO-36219	43	Completed	44237.55309	44237	Test shut	February 10, 2021, 1:35 PM	V-081DV008	Valve Condition	
WO-59161	1	Completed	44469.51991	44469	Valve Maintenance Report	September 30, 2021, 12:33 PM	V-081DV009	Valve Condition	
WO-59160	1	Completed	44469.51475	44469	Valve Maintenance Report	September 30, 2021, 12:25 PM	V-081DV010	Valve Condition	
WO-44483	1	Completed	44328.36209	44328	Valve Maintenance Report	May 12, 2021, 3:55 PM	V-081DV011	Valve Condition	Fair
WO-46116	1	Completed	44341.43024	44349	Valve Maintenance Report	May 26, 2021, 8:53 AM	V-081DV012	Valve Condition	Good
WO-59242	1	Completed	44470.43298	44470	Valve Maintenance Report	October 1, 2021, 10:29 AM	V-081DV013	Valve Condition	
WO-60821	1	Completed	44484.58311	44484	Valve Maintenance Report	October 15, 2021, 2:03 PM	V-081DV015	Valve Condition	
WO-65723	1	Completed	44543.42663	44543	Valve Maintenance Report	December 13, 2021, 10:26 AM	V-081DV016	Valve Condition	
WO-46116	1	Completed	44341.43024	44349	Valve Maintenance Report	May 26, 2021, 8:53 AM	V-081DV018	Valve Condition	Good
WO-59248	1	Completed	44470.44312	44470	Valve Maintenance Report	October 1, 2021, 10:42 AM	V-081DV019	Valve Condition	
WO-46116	1	Completed	44341.43024	44349	Valve Maintenance Report	May 26, 2021, 8:53 AM	V-081DV020	Valve Condition	Good
WO-34040	88	Completed	44216.54594	44235	Repair service line Operated stop. Leak in on pwsa side service needs to be replaced curb to main. Water is not surfacing. just filling up the curb box. 1 call valid 1/22/21 No parking needs posted. SEE PICTURES BELOW	February 8, 2021, 2:23 PM	V-081EV006	Valve Condition	
WO-66373	1	Completed	44550.59152	44550	Valve Maintenance Report	December 20, 2021, 2:14 PM	V-081EV021	Valve Condition	
WO-48724	88	Completed	44362.60912	44369	Repair service line	June 22, 2021, 3:21 PM	V-081EV023	Valve Condition	
WO-59224	1	Completed	44470.3824	44470	Valve Maintenance Report	October 1, 2021, 2:39 PM	V-081FV006	Valve Condition	
WO-59224	1	Completed	44470.3824	44470	Valve Maintenance Report	October 1, 2021, 2:39 PM	V-081FV007	Valve Condition	
WO-52437	85	Completed	44396.45932	44396	Repair water main	July 19, 2021, 10:52 PM	V-081FV008	Valve Condition	
WO-59338	1	Completed	44473.33832	44476	Valve Maintenance Report	October 7, 2021, 2:50 PM	V-081FV009	Valve Condition	
WO-37918	84	Completed	44257.50012	44257	Customer called to report a leak at the above address, he said the that the water is running in the back of his house. He is not sure but he believes it my be going into the neighbor's house.4428 called to report water in her basement coming from woodbine st.		V-081FV012	Valve Condition	
WO-66086	1	Completed	44546.38935	44546	Valve Maintenance Report	December 16, 2021, 9:25 AM	V-081FV014	Valve Condition	
WO-64212	1	Completed	44523.36573	44524	Repair water main		V-081FV019	Valve Condition	
WO-59338	1	Completed	44473.33832	44476	Valve Maintenance Report	October 7, 2021, 2:50 PM	V-081FV020	Valve Condition	
WO-64212	1	Completed	44523.36573	44524	Repair water main		V-081FV022	Valve Condition	
WO-66096	1	Completed	44546.46117	44546	Valve Maintenance Report	December 16, 2021, 11:16 AM	V-081FV023	Valve Condition	
WO-52437	85	Completed	44396.45932	44396	Repair water main	July 19, 2021, 10:52 PM	V-081FV026	Valve Condition	
WO-59338	1	Completed	44473.33832	44476	Valve Maintenance Report	October 7, 2021, 2:50 PM	V-081GV001	Valve Condition	
WO-64212	1	Completed	44523.36573	44524	Repair water main		V-081GV002	Valve Condition	
WO-64212	1	Completed	44523.36573	44524	Repair water main		V-081GV003	Valve Condition	
WO-58260	1	Completed	44461.37232	44461	Valve Maintenance Report	September 22, 2021, 9:00 AM	V-081GV004	Valve Condition	
WO-58314	1	Completed	44461.55967	44461	Valve Maintenance Report	September 22, 2021, 1:29 PM	V-081GV005	Valve Condition	
WO-58308	1	Completed	44461.5499	44461	Valve Maintenance Report	September 22, 2021, 1:18 PM	V-081GV006	Valve Condition	
WO-58321	1	Completed	44461.57916	44461	Valve Maintenance Report	September 22, 2021, 1:58 PM	V-081GV007	Valve Condition	
WO-32214	43	Completed	44197.43642	44533	Test shut 081GV008 AND 081GV009 NEED OPERATED OR TURNED IN TO DIG AND REPLACE.	December 3, 2021, 3:09 PM	V-081GV008	Valve Condition	
WO-58262	1	Completed	44461.37702	44461	Valve Maintenance Report	September 22, 2021, 9:07 AM	V-081GV009	Valve Condition	
WO-58318	1	Completed	44461.57101	44461	Valve Maintenance Report	September 22, 2021, 1:47 PM	V-081GV010	Valve Condition	
WO-64212	1	Completed	44523.36573	44524	Repair water main		V-081GV011	Valve Condition	
WO-59338	1	Completed	44473.33832	44476	Valve Maintenance Report	October 7, 2021, 2:50 PM	V-081GV013	Valve Condition	Good
WO-59338	1	Completed	44473.33832	44476	Valve Maintenance Report	October 7, 2021, 2:50 PM	V-081GV014	Valve Condition	
WO-32195	1	Completed	44196.95551	44198	Repair water main	January 21, 2021, 9:25 AM	V-081GV015	Valve Condition	
WO-66023	1	Completed	44545.5644	44545	Valve Maintenance Report	December 15, 2021, 1:45 PM	V-081GV018	Valve Condition	
WO-58160	1	Completed	44460.55967	44460	Valve Maintenance Report	September 21, 2021, 1:29 PM	V-081GV021	Valve Condition	
WO-58167	1	Completed	44460.56807	44460	Valve Maintenance Report	September 21, 2021, 1:42 PM	V-081GV022	Valve Condition	
WO-58157	1	Completed	44460.54804	44460	Valve Maintenance Report	September 21, 2021, 1:12 PM	V-081GV023	Valve Condition	
WO-58153	1	Completed	44460.53782	44460	Valve Maintenance Report	September 21, 2021, 1:01 PM	V-081GV024	Valve Condition	
WO-37907	1	Completed	44257.46568	44438	Repair water main		V-081GV029	Valve Condition	
WO-59223	1	Completed	44470.38045	44470	Valve Maintenance Report	October 1, 2021, 9:12 AM	V-081HV001	Valve Condition	
WO-59226	1	Completed	44470.38992	44470	Valve Maintenance Report	October 1, 2021, 9:27 AM	V-081HV002	Valve Condition	
WO-59228	1	Completed	44470.39868	44470	Valve Maintenance Report	October 1, 2021, 9:38 AM	V-081HV004	Valve Condition	
WO-65774	1	Completed	44543.57683	44543	Valve Maintenance Report	December 13, 2021, 1:55 PM	V-081HV006	Valve Condition	
WO-61035	1	Completed	44488.33537	44488	Valve Maintenance Report	October 19, 2021, 8:06 AM	V-081HV007	Valve Condition	
WO-61047	1	Completed	44488.35145	44488	Valve Maintenance Report	October 19, 2021, 8:32 AM	V-081HV009	Valve Condition	
WO-59123	1	Completed	44469.42153	44469	Valve Maintenance Report	September 30, 2021, 10:13 AM	V-081HV010	Valve Condition	
WO-59113	1	Completed	44469.40382	44469	Valve Maintenance Report	September 30, 2021, 9:46 AM	V-081HV012	Valve Condition	
WO-59109	1	Completed	44469.39448	44469	Valve Maintenance Report	September 30, 2021, 9:32 AM	V-081HV013	Valve Condition	
WO-40172	1	Completed	44284.27576	44285	Repair water main		V-081HV015	Valve Condition	Fair
WO-59232	1	Completed	44470.41713	44470	Valve Maintenance Report	October 1, 2021, 10:04 AM	V-081HV021	Valve Condition	
WO-59136	1	Completed	44469.4511	44469	Valve Maintenance Report	September 30, 2021, 10:53 AM	V-081HV022	Valve Condition	
WO-59415	1	Completed	44473.5446	44473	Valve Maintenance Report	October 4, 2021, 1:07 PM	V-081LV001	Valve Condition	
WO-65596	1	Completed	44540.43621	44540	Valve Maintenance Report	December 10, 2021, 10:35 AM	V-081LV004	Valve Condition	
WO-59268	1	Completed	44470.54084	44470	Valve Maintenance Report	October 1, 2021, 1:03 PM	V-081LV005	Valve Condition	
WO-60803	1	Completed	44484.54817	44484	Valve Maintenance Report	October 15, 2021, 1:15 PM	V-081LV006	Valve Condition	
WO-37907	1	Completed	44257.46568	44438	Repair water main		V-081LV009	Valve Condition	
WO-59402	1	Completed	44473.46523	44473	Valve Maintenance Report	October 4, 2021, 11:12 AM	V-081LV010	Valve Condition	
WO-59401	1	Completed	44473.46226	44473	Valve Maintenance Report	October 4, 2021, 11:08 AM	V-081LV011	Valve Condition	
WO-59283	1	Completed	44470.57833	44470	Valve Maintenance Report	October 1, 2021, 1:59 PM	V-081LV012	Valve Condition	
WO-59279	1	Completed	44470.56767	44470	Valve Maintenance Report	October 1, 2021, 1:49 PM	V-081LV013	Valve Condition	
WO-59405	1	Completed	44473.48335	44473	Valve Maintenance Report	October 4, 2021, 11:41 AM	V-081LV014	Valve Condition	
WO-59394	1	Completed	44473.43805	44473	Valve Maintenance Report	October 4, 2021, 10:40 AM	V-081LV015	Valve Condition	
WO-59404	1	Completed	44473.4774	44473	Valve Maintenance Report	October 4, 2021, 11:34 AM	V-081LV016	Valve Condition	
WO-59396	1	Completed	44473.4461	44473	Valve Maintenance Report	October 4, 2021, 10:44 AM	V-081LV017	Valve Condition	
WO-40172	1	Completed	44284.27576	44285	Repair water main		V-081MV001	Valve Condition	Fair
WO-40172	1	Completed	44284.27576	44285	Repair water main		V-081MV002	Valve Condition	Fair
WO-61065	1	Completed	44488.38327	44488	Valve Maintenance Report	October 19, 2021, 9:17 AM	V-081RV003	Valve Condition	
WO-62043	1	Completed	44498.44254	44498	Valve Maintenance Report	October 29, 2021, 10:42 AM	V-081RV010	Valve Condition	
WO-58901	1	Completed	44467.52477	44467	Valve Maintenance Report	September 28, 2021, 12:39 PM	V-081SV002	Valve Condition	
WO-59045	1	Completed	44468.53053	44468	Valve Maintenance Report	September 29, 2021, 12:50 PM	V-081SV006	Valve Condition	
WO-59038	1	Completed	44468.47526	44468	Valve Maintenance Report	September 29, 2021, 11:32 AM	V-081SV008	Valve Condition	
WO-59051	1	Completed	44468.53979	44468	Valve Maintenance Report	September 29, 2021, 1:05 PM	V-081SV009	Valve Condition	
WO-35070	88	Completed	44225.5741	44228	Repair service line	February 2, 2021, 1:31 PM	V-082AV007	Valve Condition	
WO-56888	1	Completed	44447.40434	44447	Valve Maintenance Report	September 8, 2021, 9:47 AM	V-082AV009	Valve Condition	
WO-56882	1	Completed	44447.39364	44447	Valve Maintenance Report	September 8, 2021, 9:37 AM	V-082AV010	Valve Condition	
WO-56889	1	Completed	44447.40971	44447	Valve Maintenance Report	September 8, 2021, 9:54 AM	V-082AV011	Valve Condition	
WO-56982	1	Completed	44448.3715	44448	Valve Maintenance Report	September 9, 2021, 9:01 AM	V-082AV015	Valve Condition	
WO-52931	85	Completed	44400.47365	44407	Repair water main. 6" SEE PICTURES BELOW. WATER SURFACING WHERE THE CROSSOVER IS ACCORDING TO THE 1958 DRAWING. NO PARKING NEEDS POSTED. 1 call placed and valid 7/28/21.	August 2, 2021, 9:57 AM	V-082AV017	Valve Condition	Good
WO-35070	88	Completed	44225.5741	44228	Repair service line	February 2, 2021, 1:31 PM	V-082AV018	Valve Condition	
WO-57277	1	Completed	44452.54151	44452	Valve Maintenance Report	September 13, 2021, 1:05 PM	V-082AV019	Valve Condition	
WO-57952	1	Completed	44459.43509	44459	Valve Maintenance Report	September 20, 2021, 10:31 AM	V-082AV022	Valve Condition	
WO-57948	1	Completed	44459.42743	44459	Valve Maintenance Report	September 20, 2021, 10:20 AM	V-082AV023	Valve Condition	
WO-57813	1	Completed	44456.55328	44456	Valve Maintenance Report	September 17, 2021, 1:21 PM	V-082BV003	Valve Condition	Good
WO-54916	1	Completed	44425.35734	44425	Valve Maintenance Report	August 17, 2021, 8:37 AM	V-082EV004	Valve Condition	
WO-54914	1	Completed	44425.34019	44425	Valve Maintenance Report	August 17, 2021, 8:13 AM	V-082EV005	Valve Condition	Good
WO-57278	1	Completed	44452.54387	44452	Valve Maintenance Report	September 13, 2021, 2:46 PM	V-082EV006	Valve Condition	
WO-57278	1	Completed	44452.54387	44452	Valve Maintenance Report	September 13, 2021, 2:46 PM	V-082EV007	Valve Condition	
WO-57278	1	Completed	44452.54387	44452	Valve Maintenance Report	September 13, 2021, 2:46 PM	V-082EV008	Valve Condition	
WO-56462	1	Completed	44441.33662	44441	Valve Maintenance Report	September 2, 2021, 8:07 AM	V-082EV010	Valve Condition	
WO-66129	1	Completed	44546.59813	44546	Valve Maintenance Report	December 16, 2021, 2:30 PM	V-082EV012	Valve Condition	
WO-56766	1	Completed	44446.44186	44446	Valve Maintenance Report	September 7, 2021, 10:43 AM	V-082EV013	Valve Condition	
WO-56763	1	Completed	44446.43125	44446	Valve Maintenance Report	September 7, 2021, 10:26 AM	V-082EV015	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-56461	1	Completed	44441.33337	44441	Valve Maintenance Report	September 2, 2021, 8:03 AM	V-082EV018	Valve Condition	
WO-57939	1	Completed	44459.40539	44460	Valve Maintenance Report	September 20, 2021, 9:48 AM	V-082EV020	Valve Condition	Good
WO-57929	1	Completed	44459.38227	44459	Valve Maintenance Report	September 20, 2021, 9:15 AM	V-082EV021	Valve Condition	Good
WO-54951	1	Completed	44425.41337	44425	Valve Maintenance Report	August 17, 2021, 9:58 AM	V-082EV022	Valve Condition	
WO-54949	1	Completed	44425.39723	44425	Valve Maintenance Report	August 17, 2021, 9:39 AM	V-082EV023	Valve Condition	
WO-54953	1	Completed	44425.41712	44425	Valve Maintenance Report	August 17, 2021, 10:03 AM	V-082EV025	Valve Condition	
WO-54957	1	Completed	44425.42962	44425	Valve Maintenance Report	August 17, 2021, 10:23 AM	V-082EV026	Valve Condition	
WO-54967	1	Completed	44425.46306	44425	Valve Maintenance Report	August 17, 2021, 11:10 AM	V-082EV027	Valve Condition	
WO-55642	1	Completed	44433.43259	44433	Valve Maintenance Report	August 25, 2021, 10:26 AM	V-082EV028	Valve Condition	
WO-55645	1	Completed	44433.47202	44433	Valve Maintenance Report	August 25, 2021, 11:22 AM	V-082EV029	Valve Condition	
WO-55654	1	Completed	44433.56453	44433	Valve Maintenance Report	August 25, 2021, 1:35 PM	V-082EV030	Valve Condition	
WO-48548	43	Completed	44361.57121	44361	Test shut	June 14, 2021, 1:47 PM	V-082GV018	Valve Condition	Good
WO-48547	43	Completed	44361.56632	44361	Test shut	June 14, 2021, 1:40 PM	V-082GV023	Valve Condition	
WO-32764	1	Completed	44203.58724	44203	Valve Maintenance Report	January 7, 2021, 2:12 PM	V-082HV011	Valve Condition	
WO-32772	1	Completed	44203.59654	44203	Valve Maintenance Report	January 7, 2021, 2:25 PM	V-082HV019	Valve Condition	
WO-65506	1	Completed	44539.60765	44551	Repair water main		V-082HV049	Valve Condition	
WO-40886	1	Completed	44292.33437	44293	Valve Maintenance Report	April 7, 2021, 8:22 AM	V-082HV050	Valve Condition	Fair
WO-52931	85	Completed	44400.47365	44407	Repair water main. 6" SEE PICTURES BELOW. WATER SURFACING WHERE THE CROSSOVER IS ACCORDING TO THE 1958 DRAWING. NO PARKING NEEDS POSTED. 1 call placed and valid 7/28/21.	August 2, 2021, 9:57 AM	V-082JV002	Valve Condition	
WO-35293	84	Completed	44228.85867	44230	Main or service line leak investigation/survey/ multiple calls water leak in middle of street water off at ALL residence(S) 6 residence called 1123, 1100,1143, 1647,1171,1215 DUFFIELD STREET/ RECIEVED CALLS 1615, 1600 DUFFIELD STREET EXTREMELY LOW PRESSURE	February 3, 2021, 6:54 AM	V-082JV003	Valve Condition	Good
WO-55644	1	Completed	44433.45798	44433	Valve Maintenance Report	August 25, 2021, 11:02 AM	V-082JV015	Valve Condition	
WO-55650	1	Completed	44433.53531	44433	Valve Maintenance Report	August 25, 2021, 12:54 PM	V-082JV020	Valve Condition	
WO-37733	41	Completed	44256.355	44256	Contractor shut request	March 1, 2021, 2:38 PM	V-082JV030	Valve Condition	
WO-37733	41	Completed	44256.355	44256	Contractor shut request	March 1, 2021, 2:38 PM	V-082JV031	Valve Condition	
WO-37733	41	Completed	44256.355	44256	Contractor shut request	March 1, 2021, 2:38 PM	V-082KV004	Valve Condition	
WO-44199	88	Completed	44326.37971	44326	Repair service line	May 18, 2021, 2:36 PM	V-082KV007	Valve Condition	Fair
WO-59916	1	Completed	44476.47175	44476	Valve Maintenance Report	October 7, 2021, 2:07 PM	V-082KV010	Valve Condition	
WO-59408	1	Completed	44473.49429	44482	Repair water main		V-082KV011	Valve Condition	
WO-44199	88	Completed	44326.37971	44326	Repair service line	May 18, 2021, 2:36 PM	V-082KV012	Valve Condition	Fair
WO-37733	41	Completed	44256.355	44256	Contractor shut request	March 1, 2021, 2:38 PM	V-082KV013	Valve Condition	
WO-43053	1	Completed	44314.47476	44314	Valve Maintenance Report	April 28, 2021, 11:27 AM	V-082KV018	Valve Condition	Good
WO-35050	563	Completed	44225.48606	44410	Repair water main		V-082KV026	Valve Condition	
WO-40886	1	Completed	44292.33437	44293	Valve Maintenance Report	April 7, 2021, 8:22 AM	V-082MV029	Valve Condition	Fair
WO-50823	1	Completed	44378.57754	44378	Valve Maintenance Report	July 1, 2021, 1:59 PM	V-082MV030	Valve Condition	
WO-50821	1	Completed	44378.5758	44378	Valve Maintenance Report	July 1, 2021, 1:57 PM	V-082MV031	Valve Condition	Good
WO-41201	41	Completed	44295.4295	44295	Contractor shut request	April 9, 2021, 12:32 PM	V-082MV033	Valve Condition	
WO-45824	1	Completed	44340.29834	44341	Repair water main		V-082MV045	Valve Condition	
WO-35051	1	Completed	44225.48606	44435	Repair water main		V-082NV001	Valve Condition	
WO-35050	563	Completed	44225.48606	44410	Repair water main		V-082NV005	Valve Condition	
WO-35051	1	Completed	44225.48606	44435	Repair water main		V-082NV006	Valve Condition	
WO-59916	1	Completed	44476.47175	44476	Valve Maintenance Report	October 7, 2021, 2:07 PM	V-082NV018	Valve Condition	
WO-59916	1	Completed	44476.47175	44476	Valve Maintenance Report	October 7, 2021, 2:07 PM	V-082NV019	Valve Condition	
WO-59408	1	Completed	44473.49429	44482	Repair water main		V-082PV002	Valve Condition	
WO-59408	1	Completed	44473.49429	44482	Repair water main		V-082PV003	Valve Condition	
WO-59916	1	Completed	44476.47175	44476	Valve Maintenance Report	October 7, 2021, 2:07 PM	V-082PV004	Valve Condition	
WO-59408	1	Completed	44473.49429	44482	Repair water main		V-082PV005	Valve Condition	
WO-44621	1	Completed	44329.37855	44329	Valve Maintenance Report	May 13, 2021, 4:59 PM	V-082PV023	Valve Condition	
WO-44621	1	Completed	44329.37855	44329	Valve Maintenance Report	May 13, 2021, 4:59 PM	V-082PV024	Valve Condition	
WO-44621	1	Completed	44329.37855	44329	Valve Maintenance Report	May 13, 2021, 4:59 PM	V-082PV030	Valve Condition	
WO-44621	1	Completed	44329.37855	44329	Valve Maintenance Report	May 13, 2021, 4:59 PM	V-082PV031	Valve Condition	
WO-44621	1	Completed	44329.37855	44329	Valve Maintenance Report	May 13, 2021, 4:59 PM	V-082PV032	Valve Condition	
WO-44621	1	Completed	44329.37855	44329	Valve Maintenance Report	May 13, 2021, 4:59 PM	V-082PV033	Valve Condition	
WO-44621	1	Completed	44329.37855	44329	Valve Maintenance Report	May 13, 2021, 4:59 PM	V-082PV034	Valve Condition	
WO-44621	1	Completed	44329.37855	44329	Valve Maintenance Report	May 13, 2021, 4:59 PM	V-082PV035	Valve Condition	
WO-44747	1	Completed	44329.72971	44329	Valve Maintenance Report	May 13, 2021, 5:33 PM	V-082PV036	Valve Condition	
WO-44746	1	Completed	44329.72746	44329	Valve Maintenance Report	May 13, 2021, 5:33 PM	V-082PV038	Valve Condition	Fair
WO-44745	1	Completed	44329.71368	44329	Valve Maintenance Report	May 13, 2021, 5:12 PM	V-082PV040	Valve Condition	
WO-44742	1	Completed	44329.7086	44329	Valve Maintenance Report	May 13, 2021, 5:10 PM	V-082PV045	Valve Condition	
WO-44744	1	Completed	44329.71208	44329	Valve Maintenance Report	May 13, 2021, 5:11 PM	V-082PV046	Valve Condition	Good
WO-44743	1	Completed	44329.71025	44329	Valve Maintenance Report	May 13, 2021, 5:10 PM	V-082PV047	Valve Condition	Good
WO-44621	1	Completed	44329.37855	44329	Valve Maintenance Report	May 13, 2021, 4:59 PM	V-082PV048	Valve Condition	
WO-43895	1	Completed	44322.3803	44322	Valve Maintenance Report	May 6, 2021, 2:58 PM	V-082RV001	Valve Condition	
WO-43895	1	Completed	44322.3803	44322	Valve Maintenance Report	May 6, 2021, 2:58 PM	V-082RV004	Valve Condition	
WO-43895	1	Completed	44322.3803	44322	Valve Maintenance Report	May 6, 2021, 2:58 PM	V-082RV005	Valve Condition	
WO-43895	1	Completed	44322.3803	44322	Valve Maintenance Report	May 6, 2021, 2:58 PM	V-082RV006	Valve Condition	
WO-43895	1	Completed	44322.3803	44322	Valve Maintenance Report	May 6, 2021, 2:58 PM	V-082RV007	Valve Condition	
WO-43895	1	Completed	44322.3803	44322	Valve Maintenance Report	May 6, 2021, 2:58 PM	V-082RV008	Valve Condition	
WO-46844	88	Completed	44348.4757	44357	Lead Service Line Replacement: The Plumber has ran out a new 3/4" PEX water service line out to the curb in the location of the old curb box. The plumber has run a temp. water from the neighbors hose bib at 923 Mellon St.	June 10, 2021, 6:01 AM	V-082RV009	Valve Condition	
WO-44570	1	Completed	44328.56561	44329	Valve Maintenance Report	May 13, 2021, 4:46 PM	V-082RV012	Valve Condition	
WO-44375	1	Completed	44327.40475	44327	Valve Maintenance Report	May 11, 2021, 2:21 PM	V-082RV015	Valve Condition	
WO-44091	1	Completed	44323.51334	44323	Valve Maintenance Report	May 7, 2021, 2:40 PM	V-082RV019	Valve Condition	
WO-44091	1	Completed	44323.51334	44323	Valve Maintenance Report	May 7, 2021, 2:40 PM	V-082RV020	Valve Condition	
WO-44091	1	Completed	44323.51334	44323	Valve Maintenance Report	May 7, 2021, 2:40 PM	V-082RV021	Valve Condition	
WO-44091	1	Completed	44323.51334	44323	Valve Maintenance Report	May 7, 2021, 2:40 PM	V-082RV022	Valve Condition	
WO-44091	1	Completed	44323.51334	44323	Valve Maintenance Report	May 7, 2021, 2:40 PM	V-082RV024	Valve Condition	
WO-43895	1	Completed	44322.3803	44322	Valve Maintenance Report	May 6, 2021, 2:58 PM	V-082RV025	Valve Condition	
WO-43895	1	Completed	44322.3803	44322	Valve Maintenance Report	May 6, 2021, 2:58 PM	V-082RV026	Valve Condition	Fair
WO-43895	1	Completed	44322.3803	44322	Valve Maintenance Report	May 6, 2021, 2:58 PM	V-082RV027	Valve Condition	
WO-43895	1	Completed	44322.3803	44322	Valve Maintenance Report	May 6, 2021, 2:58 PM	V-082RV028	Valve Condition	
WO-43908	85	Completed	44322.41985	44351	Repair water main moving and installing valve and hydt& moving street valve	June 4, 2021, 8:34 AM	V-082RV029	Valve Condition	Good
WO-44570	1	Completed	44328.56561	44329	Valve Maintenance Report	May 13, 2021, 4:46 PM	V-082RV031	Valve Condition	
WO-44570	1	Completed	44328.56561	44329	Valve Maintenance Report	May 13, 2021, 4:46 PM	V-082RV032	Valve Condition	Fair
WO-44570	1	Completed	44328.56561	44329	Valve Maintenance Report	May 13, 2021, 4:46 PM	V-082RV034	Valve Condition	
WO-44570	1	Completed	44328.56561	44329	Valve Maintenance Report	May 13, 2021, 4:46 PM	V-082RV035	Valve Condition	
WO-44570	1	Completed	44328.56561	44329	Valve Maintenance Report	May 13, 2021, 4:46 PM	V-082RV036	Valve Condition	Fair
WO-44570	1	Completed	44328.56561	44329	Valve Maintenance Report	May 13, 2021, 4:46 PM	V-082RV038	Valve Condition	
WO-43895	1	Completed	44322.3803	44322	Valve Maintenance Report	May 6, 2021, 2:58 PM	V-082RV039	Valve Condition	Fair
WO-43895	1	Completed	44322.3803	44322	Valve Maintenance Report	May 6, 2021, 2:58 PM	V-082RV040	Valve Condition	
WO-43895	1	Completed	44322.3803	44322	Valve Maintenance Report	May 6, 2021, 2:58 PM	V-082RV041	Valve Condition	
WO-43895	1	Completed	44322.3803	44322	Valve Maintenance Report	May 6, 2021, 2:58 PM	V-082RV042	Valve Condition	
WO-43895	1	Completed	44322.3803	44322	Valve Maintenance Report	May 6, 2021, 2:58 PM	V-082RV043	Valve Condition	Fair
WO-44570	1	Completed	44328.56561	44329	Valve Maintenance Report	May 13, 2021, 4:46 PM	V-082RV046	Valve Condition	
WO-44375	1	Completed	44327.40475	44327	Valve Maintenance Report	May 11, 2021, 2:21 PM	V-082RV047	Valve Condition	
WO-44375	1	Completed	44327.40475	44327	Valve Maintenance Report	May 11, 2021, 2:21 PM	V-082RV048	Valve Condition	
WO-44375	1	Completed	44327.40475	44327	Valve Maintenance Report	May 11, 2021, 2:21 PM	V-082RV049	Valve Condition	
WO-44375	1	Completed	44327.40475	44327	Valve Maintenance Report	May 11, 2021, 2:21 PM	V-082RV050	Valve Condition	
WO-43248	1	Completed	44315.68834	44438	Repair water main. 6" miss marked hydrant branch hit by contractor. Main runs through the catch basin and pipe is severed from hoe ram. The damage is visible. Need to do some digging, cut in 4-5 section of pipe. 1 call is valid. 1 new gate to turn back on.		V-082RV051	Valve Condition	Marginal
WO-43895	1	Completed	44322.3803	44322	Valve Maintenance Report	May 6, 2021, 2:58 PM	V-082RV053	Valve Condition	
WO-43895	1	Completed	44322.3803	44322	Valve Maintenance Report	May 6, 2021, 2:58 PM	V-082RV054	Valve Condition	
WO-44375	1	Completed	44327.40475	44327	Valve Maintenance Report	May 11, 2021, 2:21 PM	V-082RV056	Valve Condition	
WO-53494	1	Completed	44410.38867	44410	Valve Maintenance Report	August 2, 2021, 9:21 AM	V-082SV016	Valve Condition	Good
WO-53489	1	Completed	44410.38204	44410	Valve Maintenance Report	August 2, 2021, 9:13 AM	V-082SV018	Valve Condition	
WO-53495	1	Completed	44410.39106	44410	Valve Maintenance Report	August 2, 2021, 9:25 AM	V-082SV019	Valve Condition	
WO-43096	1	Completed	44314.56214	44321	Repair water main		V-082SV027	Valve Condition	Fair
WO-32697	1	Completed	44203.41102	44203	Valve Maintenance Report	January 7, 2021, 4:38 PM	V-082SV029	Valve Condition	
WO-32511	41	Completed	44202.32411	44202	Contractor shut request	January 6, 2021, 3:31 PM	V-082SV033	Valve Condition	
WO-45824	1	Completed	44340.29834	44341	Repair water main		V-082SV035	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-32305	1	Completed	44200.31689	44200	Valve Maintenance Report	January 4, 2021, 3:00 PM	V-082SV037	Valve Condition	
WO-43096	1	Completed	44314.56214	44321	Repair water main		V-082SV039	Valve Condition	Fair
WO-43096	1	Completed	44314.56214	44321	Repair water main		V-082SV041	Valve Condition	Fair
WO-32305	1	Completed	44200.31689	44200	Valve Maintenance Report	January 4, 2021, 3:00 PM	V-082SV049	Valve Condition	
WO-32511	41	Completed	44202.32411	44202	Contractor shut request	January 6, 2021, 3:31 PM	V-082SV050	Valve Condition	
WO-32511	41	Completed	44202.32411	44202	Contractor shut request	January 6, 2021, 3:31 PM	V-082SV051	Valve Condition	
WO-32511	41	Completed	44202.32411	44202	Contractor shut request	January 6, 2021, 3:31 PM	V-082SV052	Valve Condition	
WO-47730	1	Completed	44354.55415	44355	Valve Maintenance Report	June 8, 2021, 7:45 AM	V-082SV054	Valve Condition	
WO-47730	1	Completed	44354.55415	44355	Valve Maintenance Report	June 8, 2021, 7:45 AM	V-082SV055	Valve Condition	
WO-47730	1	Completed	44354.55415	44355	Valve Maintenance Report	June 8, 2021, 7:45 AM	V-082SV058	Valve Condition	
WO-47730	1	Completed	44354.55415	44355	Valve Maintenance Report	June 8, 2021, 7:45 AM	V-082SV059	Valve Condition	
WO-57745	1	Completed	44456.30351	44456	Repair water main		V-083AV005	Valve Condition	Good
WO-59681	1	Completed	44475.3699	44474	Valve Maintenance Report		V-083AV044	Valve Condition	
WO-57745	1	Completed	44456.30351	44456	Repair water main		V-083BV014	Valve Condition	Good
WO-34710	1	Completed	44223.52783	44436	Repair water main		V-083CV002	Valve Condition	
WO-47148	1	Completed	44349.54612	44350	Valve Maintenance Report	June 3, 2021, 11:50 AM	V-083CV009	Valve Condition	Fair
WO-47148	1	Completed	44349.54612	44350	Valve Maintenance Report	June 3, 2021, 11:50 AM	V-083CV010	Valve Condition	Fair
WO-40757	85	Completed	44289.40842	44289	Repair water main	April 3, 2021, 2:44 PM	V-083CV030	Valve Condition	
WO-40757	85	Completed	44289.40842	44289	Repair water main	April 3, 2021, 2:44 PM	V-083CV044	Valve Condition	
WO-47148	1	Completed	44349.54612	44350	Valve Maintenance Report	June 3, 2021, 11:50 AM	V-083CV053	Valve Condition	Fair
WO-34286	41	Completed	44218.46699	44218	Contractor shut request	January 22, 2021, 1:06 PM	V-083DV008	Valve Condition	
WO-47671	1	Completed	44354.33399	44355	Valve Maintenance Report		V-083DV024	Valve Condition	Poor
WO-47671	1	Completed	44354.33399	44355	Valve Maintenance Report		V-083DV025	Valve Condition	Poor
WO-47671	1	Completed	44354.33399	44355	Valve Maintenance Report		V-083DV029	Valve Condition	
WO-39120	84	Completed	44270.97544	44287	INVESTIGATE WATERLEAKING IN THE STREET	April 1, 2021, 1:44 PM	V-083DV030	Valve Condition	Poor
WO-56275	1	Completed	44440.4239	44350	Valve Maintenance Report		V-083DV032	Valve Condition	Fair
WO-47671	1	Completed	44354.33399	44355	Valve Maintenance Report		V-083DV033	Valve Condition	
WO-46384	1	Completed	44342.56702	44349	Valve Maintenance Report	May 26, 2021, 1:48 PM	V-083DV035	Valve Condition	Good
WO-46384	1	Completed	44342.56702	44349	Valve Maintenance Report	May 26, 2021, 1:48 PM	V-083DV036	Valve Condition	Poor
WO-42135	84	Completed	44306.20979	44307	INVESTIGATE WATER LEAKING IN THE STREET.		V-083EV011	Valve Condition	Good
WO-40757	85	Completed	44289.40842	44289	Repair water main	April 3, 2021, 2:44 PM	V-083FV012	Valve Condition	
WO-38689	1	Completed	44265.60551	44270	Valve Maintenance Report	March 15, 2021, 11:34 AM	V-083GV011	Valve Condition	Good
WO-34352	84	Completed	44219.50745	44219	Main or service line leak investigation/survey LEAK IN STREET	January 23, 2021, 3:37 PM	V-083GV019	Valve Condition	Good
WO-34286	41	Completed	44218.46699	44218	Contractor shut request	January 22, 2021, 1:06 PM	V-083HV002	Valve Condition	
WO-34286	41	Completed	44218.46699	44218	Contractor shut request	January 22, 2021, 1:06 PM	V-083HV006	Valve Condition	
WO-35851	1	Completed	44232.56751	44236	Valve Maintenance Report	February 9, 2021, 7:34 AM	V-083HV007	Valve Condition	
WO-35851	1	Completed	44232.56751	44236	Valve Maintenance Report	February 9, 2021, 7:34 AM	V-083HV009	Valve Condition	
WO-35851	1	Completed	44232.56751	44236	Valve Maintenance Report	February 9, 2021, 7:34 AM	V-083HV015	Valve Condition	
WO-34352	84	Completed	44219.50745	44219	Main or service line leak investigation/survey LEAK IN STREET	January 23, 2021, 3:37 PM	V-083HV021	Valve Condition	Good
WO-42135	84	Completed	44306.20979	44307	INVESTIGATE WATER LEAKING IN THE STREET.		V-083JV002	Valve Condition	Good
WO-61837	21	Completed	44496.6914	44498	Valve requires replacement- If the valve is unmapped, use Install New Valve work order	November 2, 2021, 10:19 AM	V-083JV004	Valve Condition	Good
WO-62020	1	Completed	44498.32467	44497	Valve Maintenance Report		V-083JV005	Valve Condition	
WO-62020	1	Completed	44498.32467	44497	Valve Maintenance Report		V-083JV007	Valve Condition	
WO-51387	1	Completed	44385.36037	44389	Valve Maintenance Report	July 12, 2021, 7:35 AM	V-083JV008	Valve Condition	
WO-51387	1	Completed	44385.36037	44389	Valve Maintenance Report	July 12, 2021, 7:35 AM	V-083JV010	Valve Condition	
WO-51387	1	Completed	44385.36037	44389	Valve Maintenance Report	July 12, 2021, 7:35 AM	V-083JV011	Valve Condition	
WO-60337	84	Completed	44481.37214	44481	Main or service line leak investigation/survey 222/226 N Negley Avenue leak investigation for the service line that comes in on Rural street.	October 12, 2021, 1:15 PM	V-083JV030	Valve Condition	
WO-60337	84	Completed	44481.37214	44481	Main or service line leak investigation/survey 222/226 N Negley Avenue leak investigation for the service line that comes in on Rural street.	October 12, 2021, 1:15 PM	V-083JV031	Valve Condition	
WO-60337	84	Completed	44481.37214	44481	Main or service line leak investigation/survey 222/226 N Negley Avenue leak investigation for the service line that comes in on Rural street.	October 12, 2021, 1:15 PM	V-083JV032	Valve Condition	
WO-33874	1	Completed	44215.35833	44218	Valve Maintenance Report	January 22, 2021, 2:22 PM	V-083KV005	Valve Condition	
WO-60337	84	Completed	44481.37214	44481	Main or service line leak investigation/survey 222/226 N Negley Avenue leak investigation for the service line that comes in on Rural street.	October 12, 2021, 1:15 PM	V-083KV034	Valve Condition	
WO-38497	84	Completed	44264.35802	44264	DPW CALLED TO REPORT SMALL LEAK COMING FROM THE CURB AT THIS LOCATION.	March 12, 2021, 10:42 AM	V-083LV001	Valve Condition	Good
WO-38497	84	Completed	44264.35802	44264	DPW CALLED TO REPORT SMALL LEAK COMING FROM THE CURB AT THIS LOCATION.	March 12, 2021, 10:42 AM	V-083LV005	Valve Condition	Good
WO-44530	401	Completed	44328.45339	44328	Dividing Pressure Valve Maintenance Report	May 12, 2021, 10:56 AM	V-083NV004	Valve Condition	Fair
WO-33874	1	Completed	44215.35833	44218	Valve Maintenance Report	January 22, 2021, 2:22 PM	V-083NV025	Valve Condition	
WO-53706	1	Completed	44412.32715	44412	Valve Maintenance Report	August 4, 2021, 10:46 AM	V-083NV035	Valve Condition	Good
WO-53706	1	Completed	44412.32715	44412	Valve Maintenance Report	August 4, 2021, 10:46 AM	V-083NV036	Valve Condition	Good
WO-33874	1	Completed	44215.35833	44218	Valve Maintenance Report	January 22, 2021, 2:22 PM	V-083NV039	Valve Condition	
WO-33874	1	Completed	44215.35833	44218	Valve Maintenance Report	January 22, 2021, 2:22 PM	V-083NV042	Valve Condition	
WO-33874	1	Completed	44215.35833	44218	Valve Maintenance Report	January 22, 2021, 2:22 PM	V-083PV015	Valve Condition	
WO-40492	1	Completed	44286.35492	44287	Valve Maintenance Report	April 1, 2021, 8:06 AM	V-083PV017	Valve Condition	
WO-38677	1	Completed	44265.55195	44265	Valve Maintenance Report	March 10, 2021, 1:17 PM	V-083RV044	Valve Condition	
WO-39791	41	Completed	44279.3521	44279	Contractor shut request	March 24, 2021, 3:19 PM	V-083SV006	Valve Condition	Good
WO-39791	41	Completed	44279.3521	44279	Contractor shut request	March 24, 2021, 3:19 PM	V-083SV024	Valve Condition	Good
WO-39426	43	Completed	44273.5126	44273	Test shut	March 18, 2021, 12:46 PM	V-083SV032	Valve Condition	Fair
WO-66182	1	Completed	44547.46515	44547	Valve Maintenance Report	December 17, 2021, 11:16 AM	V-083SV035	Valve Condition	
WO-53706	1	Completed	44412.32715	44412	Valve Maintenance Report	August 4, 2021, 10:46 AM	V-084AV013	Valve Condition	Good
WO-53706	1	Completed	44412.32715	44412	Valve Maintenance Report	August 4, 2021, 10:46 AM	V-084AV014	Valve Condition	Good
WO-54163	1	Completed	44417.322	44418	Valve Maintenance Report	August 10, 2021, 10:42 AM	V-084AV023	Valve Condition	
WO-54163	1	Completed	44417.322	44418	Valve Maintenance Report	August 10, 2021, 10:42 AM	V-084AV024	Valve Condition	
WO-40492	1	Completed	44286.35492	44287	Valve Maintenance Report	April 1, 2021, 8:06 AM	V-084BV002	Valve Condition	
WO-40492	1	Completed	44286.35492	44287	Valve Maintenance Report	April 1, 2021, 8:06 AM	V-084BV046	Valve Condition	
WO-40492	1	Completed	44286.35492	44287	Valve Maintenance Report	April 1, 2021, 8:06 AM	V-084BV047	Valve Condition	Good
WO-51290	1	Completed	44384.38631	44385	Valve Maintenance Report	July 8, 2021, 8:05 AM	V-084BV048	Valve Condition	Good
WO-51290	1	Completed	44384.38631	44385	Valve Maintenance Report	July 8, 2021, 8:05 AM	V-084BV049	Valve Condition	Good
WO-51290	1	Completed	44384.38631	44385	Valve Maintenance Report	July 8, 2021, 8:05 AM	V-084BV055	Valve Condition	
WO-33874	1	Completed	44215.35833	44218	Valve Maintenance Report	January 22, 2021, 2:22 PM	V-084BV098	Valve Condition	
WO-39426	43	Completed	44273.5126	44273	Test shut	March 18, 2021, 12:46 PM	V-084DV012	Valve Condition	Fair
WO-34998	1	Completed	44225.33934	44225	Valve Maintenance Report	January 29, 2021, 8:19 AM	V-084GV065	Valve Condition	
WO-34562	88	Completed	44222.4172	44298	Repair service line WATER NOT SURFACING Leak in service line for 331 & 333 Dennison Ave Notify 6350 walnut street so they can move their cars out of the car port 1-call placed and marked (9:55am) standard 3-day Post no parking and regular street closer		V-084HV027	Valve Condition	
WO-53766	41	Completed	44412.44915	44412	Contractor shut request	August 4, 2021, 10:53 AM	V-084JV003	Valve Condition	
WO-42804	43	Completed	44312.61142	44312	Test shut	April 26, 2021, 2:44 PM	V-084JV015	Valve Condition	
WO-51871	84	Completed	44390.55246	44391	Main or service line leak investigation/survey, CONTRACTOR TIM WITH TANDARD REALTY GROUP 727-599-3595, STATES WATER IN GOING INTO THERE HOLE, THEY ARE DOING A SEWER LINE REPAIR , NOT SURE IF ITS GROUND WATER OR A LEAK		V-084JV039	Valve Condition	Good
WO-51871	84	Completed	44390.55246	44391	Main or service line leak investigation/survey, CONTRACTOR TIM WITH TANDARD REALTY GROUP 727-599-3595, STATES WATER IN GOING INTO THERE HOLE, THEY ARE DOING A SEWER LINE REPAIR , NOT SURE IF ITS GROUND WATER OR A LEAK		V-084JV040	Valve Condition	Good
WO-38255	85	Completed	44260.35662	44270	Repair water main 12". Water getting into sump pump at 5847 Ellsworth and it's not causing any damage. Correlated 294'. Good picture but no ground noise. No service lines at the mark, but it could be possible shut n cut. 3 day 1 call placed 3/5/21. NO PARKING NEEDS POSTED. DRILL HOLES ON MARK AND HAVE LD ON SITE. SEE PICTURES BELOW	March 15, 2021, 8:19 AM	V-084JV052	Valve Condition	Good
WO-38255	85	Completed	44260.35662	44270	Repair water main 12". Water getting into sump pump at 5847 Ellsworth and it's not causing any damage. Correlated 294'. Good picture but no ground noise. No service lines at the mark, but it could be possible shut n cut. 3 day 1 call placed 3/5/21. NO PARKING NEEDS POSTED. DRILL HOLES ON MARK AND HAVE LD ON SITE. SEE PICTURES BELOW	March 15, 2021, 8:19 AM	V-084JV053	Valve Condition	Good
WO-53759	41	Completed	44412.43716	44412	Contractor shut request	August 4, 2021, 10:38 AM	V-084JV054	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-53764	41	Completed	44412.44501	44412	Contractor shut request	August 4, 2021, 10:45 AM	V-084JV055	Valve Condition	
WO-35641	1	Completed	44231.38933	44231	Valve Maintenance Report	February 4, 2021, 9:43 AM	V-084KV010	Valve Condition	Fair
WO-35641	1	Completed	44231.38933	44231	Valve Maintenance Report	February 4, 2021, 9:43 AM	V-084KV012	Valve Condition	Fair
WO-35641	1	Completed	44231.38933	44231	Valve Maintenance Report	February 4, 2021, 9:43 AM	V-084KV013	Valve Condition	Fair
WO-34998	1	Completed	44225.33934	44225	Valve Maintenance Report	January 29, 2021, 8:19 AM	V-084KV016	Valve Condition	
WO-36794	1	Completed	44244.49807	44245	Valve Maintenance Report	February 18, 2021, 8:14 AM	V-084LV022	Valve Condition	
WO-34562	88	Completed	44222.4172	44298	Repair service line WATER NOT SURFACING Leak in service line for 331 & 333 Dennison Ave Notify 6350 walnut street so they can move their cars out of the car port 1-call placed and marked (9:55am) standard 3-day Post no parking and regular street closer		V-084MV004	Valve Condition	
WO-36794	1	Completed	44244.49807	44245	Valve Maintenance Report	February 18, 2021, 8:14 AM	V-084MV027	Valve Condition	
WO-34562	88	Completed	44222.4172	44298	Repair service line WATER NOT SURFACING Leak in service line for 331 & 333 Dennison Ave Notify 6350 walnut street so they can move their cars out of the car port 1-call placed and marked (9:55am) standard 3-day Post no parking and regular street closer		V-084MV035	Valve Condition	
WO-34562	88	Completed	44222.4172	44298	Repair service line WATER NOT SURFACING Leak in service line for 331 & 333 Dennison Ave Notify 6350 walnut street so they can move their cars out of the car port 1-call placed and marked (9:55am) standard 3-day Post no parking and regular street closer		V-084MV036	Valve Condition	
WO-48850	41	Completed	44363.4258	44363	Contractor shut request	June 16, 2021, 3:05 PM	V-084NV041	Valve Condition	
WO-49468	1	Completed	44368.52938	44371	Repair water main	June 24, 2021, 3:50 AM	V-084NV045	Valve Condition	
WO-49465	85	Completed	44368.52938	44371	Repair water main	June 24, 2021, 4:52 AM	V-084NV047	Valve Condition	
WO-35641	1	Completed	44231.38933	44231	Valve Maintenance Report	February 4, 2021, 9:43 AM	V-084PV007	Valve Condition	Fair
WO-35641	1	Completed	44231.38933	44231	Valve Maintenance Report	February 4, 2021, 9:43 AM	V-084PV008	Valve Condition	Fair
WO-35641	1	Completed	44231.38933	44231	Valve Maintenance Report	February 4, 2021, 9:43 AM	V-084PV010	Valve Condition	Fair
WO-62049	1	Completed	44498.47984	44497	Valve Maintenance Report		V-084RV008	Valve Condition	Poor
WO-36791	1	Completed	44244.4602	44244	Valve Maintenance Report		V-084RV015	Valve Condition	
WO-62049	1	Completed	44498.47984	44497	Valve Maintenance Report		V-084RV016	Valve Condition	Poor
WO-52491	1	Completed	44396.65456	44397	Valve Maintenance Report	July 20, 2021, 1:09 PM	V-084RV019	Valve Condition	Good
WO-52491	1	Completed	44396.65456	44397	Valve Maintenance Report	July 20, 2021, 1:09 PM	V-084RV022	Valve Condition	Good
WO-53955	1	Completed	44413.55653	44417	Valve Maintenance Report	August 9, 2021, 7:39 AM	V-084RV024	Valve Condition	
WO-53955	1	Completed	44413.55653	44417	Valve Maintenance Report	August 9, 2021, 7:39 AM	V-084RV025	Valve Condition	
WO-53128	41	Completed	44404.3675	44404	Contractor shut request	July 27, 2021, 8:52 AM	V-084RV026	Valve Condition	
WO-53955	1	Completed	44413.55653	44417	Valve Maintenance Report	August 9, 2021, 7:39 AM	V-084RV027	Valve Condition	
WO-53948	1	Completed	44413.5327	44413	Valve Maintenance Report	August 5, 2021, 1:04 PM	V-084RV032	Valve Condition	
WO-53948	1	Completed	44413.5327	44413	Valve Maintenance Report	August 5, 2021, 1:04 PM	V-084RV036	Valve Condition	
WO-53948	1	Completed	44413.5327	44413	Valve Maintenance Report	August 5, 2021, 1:04 PM	V-084RV038	Valve Condition	
WO-53948	1	Completed	44413.5327	44413	Valve Maintenance Report	August 5, 2021, 1:04 PM	V-084RV039	Valve Condition	Good
WO-32396	1	Completed	44201.31417	44202	Repair water main	March 17, 2021, 12:11 PM	V-084SV002	Valve Condition	
WO-34562	88	Completed	44222.4172	44298	Repair service line WATER NOT SURFACING Leak in service line for 331 & 333 Dennison Ave Notify 6350 walnut street so they can move their cars out of the car port 1-call placed and marked (9:55am) standard 3-day Post no parking and regular street closer		V-084SV003	Valve Condition	
WO-36791	1	Completed	44244.4602	44244	Valve Maintenance Report		V-084SV004	Valve Condition	
WO-61199	1	Completed	44489.47441	44515	Repair water main		V-084SV014	Valve Condition	Good
WO-42750	464	Completed	44312.42176	44312	conttractor hit sl gotta shut main down	April 26, 2021, 10:09 AM	V-085AV003	Valve Condition	Good
WO-42787	683	Completed	44312.55081	44320	Work site details for reporting		V-085AV005	Valve Condition	
WO-48850	41	Completed	44363.4258	44363	Contractor shut request	June 16, 2021, 3:05 PM	V-085AV008	Valve Condition	
WO-48850	41	Completed	44363.4258	44363	Contractor shut request	June 16, 2021, 3:05 PM	V-085AV009	Valve Condition	
WO-48850	41	Completed	44363.4258	44363	Contractor shut request	June 16, 2021, 3:05 PM	V-085AV012	Valve Condition	
WO-50565	1	Completed	44377.33522	44377	Valve Maintenance Report	June 30, 2021, 2:32 PM	V-085AV013	Valve Condition	
WO-48850	41	Completed	44363.4258	44363	Contractor shut request	June 16, 2021, 3:05 PM	V-085AV022	Valve Condition	
WO-63346	41	Completed	44510.4837	44509	Contractor shut request- CONTRACTOR ZOTTOLA , MAKING REPAIRS ON WATER MAIN BREAK.		V-085AV026	Valve Condition	
WO-60602	1	Completed	44483.36356	44484	Valve Maintenance Report	October 15, 2021, 2:29 PM	V-085AV033	Valve Condition	
WO-60602	1	Completed	44483.36356	44484	Valve Maintenance Report	October 15, 2021, 2:29 PM	V-085BV005	Valve Condition	
WO-63346	41	Completed	44510.4837	44509	Contractor shut request- CONTRACTOR ZOTTOLA , MAKING REPAIRS ON WATER MAIN BREAK.		V-085BV008	Valve Condition	
WO-53923	1	Completed	44413.45067	44439	Repair water main		V-085BV010	Valve Condition	
WO-53923	1	Completed	44413.45067	44439	Repair water main		V-085BV011	Valve Condition	
WO-53923	1	Completed	44413.45067	44439	Repair water main		V-085BV013	Valve Condition	
WO-53923	1	Completed	44413.45067	44439	Repair water main		V-085BV014	Valve Condition	
WO-53923	1	Completed	44413.45067	44439	Repair water main		V-085BV015	Valve Condition	
WO-60602	1	Completed	44483.36356	44484	Valve Maintenance Report	October 15, 2021, 2:29 PM	V-085BV016	Valve Condition	
WO-60602	1	Completed	44483.36356	44484	Valve Maintenance Report	October 15, 2021, 2:29 PM	V-085BV017	Valve Condition	
WO-55608	1	Completed	44433.32766	44439	Repair water main		V-085BV018	Valve Condition	
WO-55608	1	Completed	44433.32766	44439	Repair water main		V-085BV020	Valve Condition	
WO-55607	85	Completed	44433.32766	44435	Repair water main		V-085BV022	Valve Condition	
WO-63346	41	Completed	44510.4837	44509	Contractor shut request- CONTRACTOR ZOTTOLA , MAKING REPAIRS ON WATER MAIN BREAK.		V-085BV025	Valve Condition	
WO-55607	85	Completed	44433.32766	44435	Repair water main		V-085BV040	Valve Condition	
WO-55608	1	Completed	44433.32766	44439	Repair water main		V-085CV001	Valve Condition	
WO-52491	1	Completed	44396.65456	44397	Valve Maintenance Report	July 20, 2021, 1:09 PM	V-085CV002	Valve Condition	
WO-55608	1	Completed	44433.32766	44439	Repair water main		V-085CV003	Valve Condition	
WO-39522	85	Completed	44274.49252	44285	Repair water main		V-085CV034	Valve Condition	
WO-39523	1	Completed	44274.49252	44438	Repair water main		V-085DV003	Valve Condition	
WO-65264	1	Completed	44537.46152	44537	Valve Maintenance Report	December 7, 2021, 11:06 AM	V-085DV009	Valve Condition	
WO-65266	1	Completed	44537.47076	44537	Valve Maintenance Report	December 7, 2021, 11:23 AM	V-085DV012	Valve Condition	
WO-65267	1	Completed	44537.47219	44537	Valve Maintenance Report	December 7, 2021, 11:22 AM	V-085DV013	Valve Condition	
WO-65259	1	Completed	44537.45854	44537	Valve Maintenance Report	December 7, 2021, 11:03 AM	V-085DV014	Valve Condition	
WO-41102	85	Completed	44294.49602	44299	Repair water main	April 13, 2021, 6:46 AM	V-085EV004	Valve Condition	Good
WO-39522	85	Completed	44274.49252	44285	Repair water main		V-085GV006	Valve Condition	Good
WO-39523	1	Completed	44274.49252	44438	Repair water main		V-085GV009	Valve Condition	
WO-65271	1	Completed	44537.5275	44537	Valve Maintenance Report	December 7, 2021, 12:41 PM	V-085HV001	Valve Condition	
WO-65273	1	Completed	44537.53091	44537	Valve Maintenance Report	December 7, 2021, 12:47 PM	V-085HV002	Valve Condition	
WO-32198	1	Completed	44197.25636	44438	Repair water main		V-085HV012	Valve Condition	
WO-64361	1	Completed	44524.40397	44524	Valve Maintenance Report	November 24, 2021, 9:44 AM	V-085HV022	Valve Condition	
WO-64363	1	Completed	44524.40678	44524	Valve Maintenance Report	November 24, 2021, 9:48 AM	V-085HV023	Valve Condition	
WO-49614	1	Completed	44369.34161	44370	Valve Maintenance Report	June 23, 2021, 1:58 PM	V-085KV010	Valve Condition	Fair
WO-49614	1	Completed	44369.34161	44370	Valve Maintenance Report	June 23, 2021, 1:58 PM	V-085KV011	Valve Condition	Fair
WO-41023	43	Completed	44293.6114	44294	Test shut	April 8, 2021, 10:48 AM	V-085KV012	Valve Condition	Fair
WO-50075	41	Completed	44372.34076	44372	Contractor shut request	June 25, 2021, 2:25 PM	V-085KV013	Valve Condition	
WO-50075	41	Completed	44372.34076	44372	Contractor shut request	June 25, 2021, 2:25 PM	V-085KV017	Valve Condition	Fair
WO-49614	1	Completed	44369.34161	44370	Valve Maintenance Report	June 23, 2021, 1:58 PM	V-085KV018	Valve Condition	Fair
WO-37193	1	Completed	44249.57332	44438	Repair water main		V-085LV015	Valve Condition	Good
WO-66417	1	Completed	44551.38077	44551	Valve Maintenance Report	December 21, 2021, 9:14 AM	V-085LV017	Valve Condition	
WO-37193	1	Completed	44249.57332	44438	Repair water main		V-085LV020	Valve Condition	Good
WO-33767	84	Completed	44212.34102	44212	Main or service line leak investigation/survey- REPORTS OF WATER GUSHING FROM STREET.	January 16, 2021, 3:50 PM	V-085LV022	Valve Condition	Good
WO-66417	1	Completed	44551.38077	44551	Valve Maintenance Report	December 21, 2021, 9:14 AM	V-085MV001	Valve Condition	
WO-33773	21	Completed	44212.67347	44441	Valve is inoperable and requires replacement- broke open	September 3, 2021, 11:18 AM	V-085MV006	Valve Condition	
WO-33767	84	Completed	44212.34102	44212	Main or service line leak investigation/survey- REPORTS OF WATER GUSHING FROM STREET.	January 16, 2021, 3:50 PM	V-085MV007	Valve Condition	
WO-64370	1	Completed	44524.42144	44524	Valve Maintenance Report	November 24, 2021, 10:27 AM	V-085MV008	Valve Condition	
WO-33767	84	Completed	44212.34102	44212	Main or service line leak investigation/survey- REPORTS OF WATER GUSHING FROM STREET.	January 16, 2021, 3:50 PM	V-085MV009	Valve Condition	
WO-64373	1	Completed	44524.42337	44524	Valve Maintenance Report	November 24, 2021, 10:25 AM	V-085MV010	Valve Condition	
WO-65288	1	Completed	44537.59652	44537	Valve Maintenance Report	December 7, 2021, 2:41 PM	V-085MV012	Valve Condition	
WO-64557	1	Completed	44529.5614	44529	Valve Maintenance Report	November 29, 2021, 1:41 PM	V-085MV016	Valve Condition	
WO-64558	1	Completed	44529.56284	44529	Valve Maintenance Report	November 29, 2021, 1:38 PM	V-085MV017	Valve Condition	Good
WO-64552	1	Completed	44529.54874	44529	Valve Maintenance Report	November 29, 2021, 1:21 PM	V-085MV019	Valve Condition	
WO-64353	1	Completed	44524.38903	44525	Valve Maintenance Report	November 29, 2021, 7:24 AM	V-085NV001	Valve Condition	
WO-64353	1	Completed	44524.38903	44525	Valve Maintenance Report	November 29, 2021, 7:24 AM	V-085NV002	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-64353	1	Completed	44524.38903	44525	Valve Maintenance Report	November 29, 2021, 7:24 AM	V-085NV003	Valve Condition	
WO-64353	1	Completed	44524.38903	44525	Valve Maintenance Report	November 29, 2021, 7:24 AM	V-085NV004	Valve Condition	
WO-64353	1	Completed	44524.38903	44525	Valve Maintenance Report	November 29, 2021, 7:24 AM	V-085NV005	Valve Condition	
WO-64353	1	Completed	44524.38903	44525	Valve Maintenance Report	November 29, 2021, 7:24 AM	V-085NV006	Valve Condition	
WO-64353	1	Completed	44524.38903	44525	Valve Maintenance Report	November 29, 2021, 7:24 AM	V-085NV007	Valve Condition	
WO-64353	1	Completed	44524.38903	44525	Valve Maintenance Report	November 29, 2021, 7:24 AM	V-085NV008	Valve Condition	
WO-64353	1	Completed	44524.38903	44525	Valve Maintenance Report	November 29, 2021, 7:24 AM	V-085NV009	Valve Condition	
WO-64353	1	Completed	44524.38903	44525	Valve Maintenance Report	November 29, 2021, 7:24 AM	V-085NV010	Valve Condition	
WO-64353	1	Completed	44524.38903	44525	Valve Maintenance Report	November 29, 2021, 7:24 AM	V-085NV011	Valve Condition	
WO-64353	1	Completed	44524.38903	44525	Valve Maintenance Report	November 29, 2021, 7:24 AM	V-085NV015	Valve Condition	
WO-34650	85	Completed	44222.91167	44223	Repair water main DOMI # OP-2021-01045	January 27, 2021, 10:43 PM	V-085NV027	Valve Condition	
WO-48032	1	Completed	44357.36516	44357	Valve Maintenance Report	June 10, 2021, 10:47 AM	V-085PV004	Valve Condition	
WO-49614	1	Completed	44369.34161	44370	Valve Maintenance Report	June 23, 2021, 1:58 PM	V-085PV005	Valve Condition	Fair
WO-41023	43	Completed	44293.6114	44294	Test shut	April 8, 2021, 10:48 AM	V-085PV006	Valve Condition	Fair
WO-48032	1	Completed	44357.36516	44357	Valve Maintenance Report	June 10, 2021, 10:47 AM	V-085PV016	Valve Condition	Good
WO-54868	88	Completed	44424.5611	44424	Repair service line		V-085RV010	Valve Condition	Good
WO-33771	85	Completed	44212.66136	44212	Repair water main	January 16, 2021, 4:05 PM	V-085SV002	Valve Condition	
WO-66421	1	Completed	44551.39767	44551	Valve Maintenance Report	December 21, 2021, 10:02 AM	V-085SV006	Valve Condition	
WO-66421	1	Completed	44551.39767	44551	Valve Maintenance Report	December 21, 2021, 10:02 AM	V-085SV008	Valve Condition	
WO-65368	1	Completed	44538.57988	44538	Valve Maintenance Report	December 8, 2021, 2:03 PM	V-085SV011	Valve Condition	
WO-65369	1	Completed	44538.58207	44538	Valve Maintenance Report	December 8, 2021, 2:05 PM	V-085SV013	Valve Condition	
WO-65486	1	Completed	44539.57173	44539	Valve Maintenance Report	December 9, 2021, 2:11 PM	V-085SV014	Valve Condition	
WO-65488	1	Completed	44539.57353	44539	Valve Maintenance Report	December 9, 2021, 2:15 PM	V-085SV015	Valve Condition	
WO-65489	1	Completed	44539.5751	44539	Valve Maintenance Report	December 9, 2021, 2:20 PM	V-085SV017	Valve Condition	
WO-65371	1	Completed	44538.59551	44538	Valve Maintenance Report	December 8, 2021, 2:23 PM	V-085SV021	Valve Condition	
WO-65490	1	Completed	44539.57644	44539	Valve Maintenance Report	December 9, 2021, 3:03 PM	V-085SV022	Valve Condition	
WO-66434	1	Completed	44551.52717	44551	Valve Maintenance Report	December 21, 2021, 1:08 PM	V-085SV025	Valve Condition	
WO-66434	1	Completed	44551.52717	44551	Valve Maintenance Report	December 21, 2021, 1:08 PM	V-085SV026	Valve Condition	
WO-66434	1	Completed	44551.52717	44551	Valve Maintenance Report	December 21, 2021, 1:08 PM	V-085SV027	Valve Condition	
WO-66434	1	Completed	44551.52717	44551	Valve Maintenance Report	December 21, 2021, 1:08 PM	V-085SV028	Valve Condition	
WO-62791	1	Completed	44505.33656	44504	Valve Maintenance Report		V-086AV013	Valve Condition	
WO-61600	1	Completed	44494.67272	44495	Valve Maintenance Report		V-086AV016	Valve Condition	Good
WO-60530	88	Completed	44482.51392	44483	Repair service line- if drilled, Drill Sheet work order MUST be completed		V-086AV018	Valve Condition	
WO-62791	1	Completed	44505.33656	44504	Valve Maintenance Report		V-086AV021	Valve Condition	
WO-48032	1	Completed	44357.36516	44357	Valve Maintenance Report	June 10, 2021, 10:47 AM	V-086BV001	Valve Condition	
WO-48620	1	Completed	44362.03216	44362	Valve Maintenance Report	June 15, 2021, 1:31 AM	V-086BV004	Valve Condition	
WO-48032	1	Completed	44357.36516	44357	Valve Maintenance Report	June 10, 2021, 10:47 AM	V-086BV005	Valve Condition	Good
WO-48032	1	Completed	44357.36516	44357	Valve Maintenance Report	June 10, 2021, 10:47 AM	V-086BV006	Valve Condition	Good
WO-48032	1	Completed	44357.36516	44357	Valve Maintenance Report	June 10, 2021, 10:47 AM	V-086BV007	Valve Condition	Fair
WO-48032	1	Completed	44357.36516	44357	Valve Maintenance Report	June 10, 2021, 10:47 AM	V-086BV008	Valve Condition	
WO-57521	1	Completed	44454.45045	44454	Valve Maintenance Report	September 15, 2021, 10:54 AM	V-086BV009	Valve Condition	
WO-57530	1	Completed	44454.47727	44454	Valve Maintenance Report	September 15, 2021, 11:35 AM	V-086BV011	Valve Condition	
WO-57520	1	Completed	44454.44398	44454	Valve Maintenance Report	September 15, 2021, 10:45 AM	V-086BV012	Valve Condition	
WO-57526	1	Completed	44454.46283	44454	Valve Maintenance Report	September 15, 2021, 11:10 AM	V-086BV013	Valve Condition	Fair
WO-54449	21	Completed	44419.55183	44455	Valve requires replacement	September 16, 2021, 7:45 AM	V-086BV014	Valve Condition	Good
WO-57516	1	Completed	44454.43349	44454	Valve Maintenance Report	September 15, 2021, 10:31 AM	V-086BV015	Valve Condition	
WO-57522	1	Completed	44454.45829	44454	Valve Maintenance Report	September 15, 2021, 11:04 AM	V-086BV016	Valve Condition	Fair
WO-66716	1	Completed	44558.58158	44558	Valve Maintenance Report	December 28, 2021, 2:23 PM	V-086BV019	Valve Condition	
WO-66716	1	Completed	44558.58158	44558	Valve Maintenance Report	December 28, 2021, 2:23 PM	V-086BV020	Valve Condition	
WO-66683	1	Completed	44558.39754	44558	Valve Maintenance Report	December 28, 2021, 9:34 AM	V-086BV022	Valve Condition	
WO-66682	1	Completed	44558.39585	44558	Valve Maintenance Report	December 28, 2021, 9:31 AM	V-086BV027	Valve Condition	
WO-66685	1	Completed	44558.40107	44558	Valve Maintenance Report	December 28, 2021, 9:39 AM	V-086BV028	Valve Condition	
WO-48964	41	Completed	44363.8354	44363	Contractor shut request	June 16, 2021, 9:05 PM	V-086CV001	Valve Condition	Good
WO-48032	1	Completed	44357.36516	44357	Valve Maintenance Report	June 10, 2021, 10:47 AM	V-086CV002	Valve Condition	
WO-48964	41	Completed	44363.8354	44363	Contractor shut request	June 16, 2021, 9:05 PM	V-086CV003	Valve Condition	Good
WO-53664	1	Completed	44411.54323	44412	Valve Maintenance Report	August 4, 2021, 7:26 AM	V-086CV004	Valve Condition	
WO-53664	1	Completed	44411.54323	44412	Valve Maintenance Report	August 4, 2021, 7:26 AM	V-086CV005	Valve Condition	Fair
WO-53664	1	Completed	44411.54323	44412	Valve Maintenance Report	August 4, 2021, 7:26 AM	V-086CV010	Valve Condition	
WO-53664	1	Completed	44411.54323	44412	Valve Maintenance Report	August 4, 2021, 7:26 AM	V-086CV011	Valve Condition	
WO-53664	1	Completed	44411.54323	44412	Valve Maintenance Report	August 4, 2021, 7:26 AM	V-086CV012	Valve Condition	Fair
WO-53028	1	Completed	44403.35164	44404	Valve Maintenance Report	July 27, 2021, 5:56 AM	V-086CV019	Valve Condition	Poor
WO-65576	1	Completed	44540.39365	44540	Valve Maintenance Report	December 10, 2021, 9:59 AM	V-086DV005	Valve Condition	
WO-66359	1	Completed	44550.52692	44550	Valve Maintenance Report	December 20, 2021, 12:53 PM	V-086DV007	Valve Condition	
WO-65576	1	Completed	44540.39365	44540	Valve Maintenance Report	December 10, 2021, 9:59 AM	V-086DV010	Valve Condition	
WO-66359	1	Completed	44550.52692	44550	Valve Maintenance Report	December 20, 2021, 12:53 PM	V-086DV015	Valve Condition	
WO-65576	1	Completed	44540.39365	44540	Valve Maintenance Report	December 10, 2021, 9:59 AM	V-086DV016	Valve Condition	
WO-65576	1	Completed	44540.39365	44540	Valve Maintenance Report	December 10, 2021, 9:59 AM	V-086DV017	Valve Condition	
WO-65579	1	Completed	44540.4002	44540	Valve Maintenance Report	December 10, 2021, 9:55 AM	V-086DV018	Valve Condition	
WO-65594	1	Completed	44540.43086	44540	Valve Maintenance Report	December 10, 2021, 10:45 AM	V-086DV024	Valve Condition	
WO-65594	1	Completed	44540.43086	44540	Valve Maintenance Report	December 10, 2021, 10:45 AM	V-086DV025	Valve Condition	
WO-65594	1	Completed	44540.43086	44540	Valve Maintenance Report	December 10, 2021, 10:45 AM	V-086DV027	Valve Condition	
WO-66214	1	Completed	44547.55984	44547	Valve Maintenance Report	December 17, 2021, 2:03 PM	V-086DV029	Valve Condition	
WO-65883	1	Completed	44544.54617	44544	Valve Maintenance Report	December 14, 2021, 1:51 PM	V-086DV030	Valve Condition	
WO-66214	1	Completed	44547.55984	44547	Valve Maintenance Report	December 17, 2021, 2:03 PM	V-086DV031	Valve Condition	
WO-65883	1	Completed	44544.54617	44544	Valve Maintenance Report	December 14, 2021, 1:51 PM	V-086DV032	Valve Condition	
WO-66214	1	Completed	44547.55984	44547	Valve Maintenance Report	December 17, 2021, 2:03 PM	V-086DV033	Valve Condition	
WO-66214	1	Completed	44547.55984	44547	Valve Maintenance Report	December 17, 2021, 2:03 PM	V-086DV035	Valve Condition	
WO-62320	1	Completed	44502.43647	44505	Valve Maintenance Report	November 5, 2021, 3:01 PM	V-086EV003	Valve Condition	
WO-62320	1	Completed	44502.43647	44505	Valve Maintenance Report	November 5, 2021, 3:01 PM	V-086EV004	Valve Condition	
WO-62320	1	Completed	44502.43647	44505	Valve Maintenance Report	November 5, 2021, 3:01 PM	V-086EV005	Valve Condition	
WO-60530	88	Completed	44482.51392	44483	Repair service line- if drilled, Drill Sheet work order MUST be completed		V-086EV008	Valve Condition	
WO-66674	1	Completed	44558.35028	44558	Valve Maintenance Report	December 28, 2021, 8:33 AM	V-086EV011	Valve Condition	
WO-66674	1	Completed	44558.35028	44558	Valve Maintenance Report	December 28, 2021, 8:33 AM	V-086EV012	Valve Condition	
WO-61600	1	Completed	44494.67272	44495	Valve Maintenance Report		V-086EV013	Valve Condition	Good
WO-61600	1	Completed	44494.67272	44495	Valve Maintenance Report		V-086EV014	Valve Condition	Good
WO-66677	1	Completed	44558.37095	44558	Valve Maintenance Report	December 28, 2021, 8:55 AM	V-086EV015	Valve Condition	
WO-58380	1	Completed	44462.33702	44462	Valve Maintenance Report	September 23, 2021, 11:40 AM	V-086EV017	Valve Condition	
WO-66609	1	Completed	44557.40488	44557	Valve Maintenance Report	December 27, 2021, 9:55 AM	V-086FV005	Valve Condition	
WO-66603	1	Completed	44557.37677	44557	Valve Maintenance Report	December 27, 2021, 9:31 AM	V-086FV012	Valve Condition	
WO-66603	1	Completed	44557.37677	44557	Valve Maintenance Report	December 27, 2021, 9:31 AM	V-086FV013	Valve Condition	
WO-66642	1	Completed	44557.54295	44557	Valve Maintenance Report	December 27, 2021, 2:05 PM	V-086FV016	Valve Condition	
WO-66642	1	Completed	44557.54295	44557	Valve Maintenance Report	December 27, 2021, 2:05 PM	V-086FV017	Valve Condition	
WO-66642	1	Completed	44557.54295	44557	Valve Maintenance Report	December 27, 2021, 2:05 PM	V-086FV018	Valve Condition	
WO-42224	88	Completed	44306.47498	44312	4/20/2021 Repair service line: This is a Lead line replacement. The Plumber contacted the ACHD, and was given approval to make a temporary repair to the lead line for temporary water. The plumber plans on running out a water service line out to the curb tomorrow 4/21/2021 the Plumbers contact information is Brian Keach with Cross Plumbing Phone # 412.719.3000	April 26, 2021, 1:52 PM	V-086FV022	Valve Condition	
WO-53028	1	Completed	44403.35164	44404	Valve Maintenance Report	July 27, 2021, 5:56 AM	V-086GV004	Valve Condition	Poor
WO-55634	1	Completed	44433.41859	44433	Valve Maintenance Report	August 25, 2021, 10:07 AM	V-086GV005	Valve Condition	Poor
WO-53028	1	Completed	44403.35164	44404	Valve Maintenance Report	July 27, 2021, 5:56 AM	V-086GV006	Valve Condition	Poor
WO-53028	1	Completed	44403.35164	44404	Valve Maintenance Report	July 27, 2021, 5:56 AM	V-086GV007	Valve Condition	Poor
WO-53028	1	Completed	44403.35164	44404	Valve Maintenance Report	July 27, 2021, 5:56 AM	V-086GV008	Valve Condition	Poor
WO-53028	1	Completed	44403.35164	44404	Valve Maintenance Report	July 27, 2021, 5:56 AM	V-086GV009	Valve Condition	Poor
WO-53028	1	Completed	44403.35164	44404	Valve Maintenance Report	July 27, 2021, 5:56 AM	V-086GV010	Valve Condition	Poor
WO-53028	1	Completed	44403.35164	44404	Valve Maintenance Report	July 27, 2021, 5:56 AM	V-086GV015	Valve Condition	Poor
WO-66539	1	Completed	44553.36517	44553	Valve Maintenance Report	December 23, 2021, 9:10 AM	V-086GV016	Valve Condition	
WO-52460	1	Completed	44396.58188	44397	Valve Maintenance Report	July 20, 2021, 12:40 PM	V-086GV017	Valve Condition	Poor
WO-53028	1	Completed	44403.35164	44404	Valve Maintenance Report	July 27, 2021, 5:56 AM	V-086GV018	Valve Condition	Poor
WO-66539	1	Completed	44553.36517	44553	Valve Maintenance Report	December 23, 2021, 9:10 AM	V-086GV019	Valve Condition	
WO-65883	1	Completed	44544.54617	44544	Valve Maintenance Report	December 14, 2021, 1:51 PM	V-086HV002	Valve Condition	
WO-65883	1	Completed	44544.54617	44544	Valve Maintenance Report	December 14, 2021, 1:51 PM	V-086HV003	Valve Condition	
WO-66348	1	Completed	44550.44548	44550	Valve Maintenance Report	December 20, 2021, 11:11 AM	V-086HV005	Valve Condition	
WO-66348	1	Completed	44550.44548	44550	Valve Maintenance Report	December 20, 2021, 11:11 AM	V-086HV007	Valve Condition	
WO-35509	85	Completed	44230.38651	44240	Repair water main	February 13, 2021, 3:33 PM	V-086HV015	Valve Condition	Fair
WO-35509	85	Completed	44230.38651	44240	Repair water main	February 13, 2021, 3:33 PM	V-086HV032	Valve Condition	Fair

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-61017	1	Completed	44488.07488	44488	Valve Maintenance Report	October 19, 2021, 1:56 AM	V-086KV019	Valve Condition	
WO-61018	1	Completed	44488.07711	44488	Valve Maintenance Report	October 19, 2021, 1:58 AM	V-086KV022	Valve Condition	
WO-53673	85	Completed	44411.57034	44420	Repair water main 6" mll. No parking needs posted on BOTH sides of the street. WATER NOT SURFACING but getting into the sewer. 3 day 1 call valid 8/6/21. SEE PICTURES BELOW!!!! We will need to take down steel fence	August 13, 2021, 1:19 PM	V-086KV024	Valve Condition	Fair
WO-61019	1	Completed	44488.07894	44488	Valve Maintenance Report	October 19, 2021, 1:56 AM	V-086KV050	Valve Condition	
WO-56069	1	Completed	44439.03093	44439	Valve Maintenance Report	August 31, 2021, 2:04 AM	V-086LV004	Valve Condition	
WO-56069	1	Completed	44439.03093	44439	Valve Maintenance Report	August 31, 2021, 2:04 AM	V-086LV006	Valve Condition	
WO-49328	1	Completed	44368.05479	44368	Valve Maintenance Report	June 21, 2021, 1:23 AM	V-086LV008	Valve Condition	
WO-49329	1	Completed	44368.05924	44368	Valve Maintenance Report	June 22, 2021, 6:55 AM	V-086LV009	Valve Condition	
WO-61013	1	Completed	44488.04101	44488	Valve Maintenance Report	October 19, 2021, 1:06 AM	V-086LV013	Valve Condition	
WO-61014	1	Completed	44488.04317	44488	Valve Maintenance Report	October 19, 2021, 1:05 AM	V-086LV015	Valve Condition	Fair
WO-56069	1	Completed	44439.03093	44439	Valve Maintenance Report	August 31, 2021, 2:04 AM	V-086LV016	Valve Condition	
WO-53674	1	Completed	44411.57034	44439	Repair water main 6" mll. No parking needs posted. WATER NOT SURFACING but getting into the sewer. 3 day 1 call valid 8/6/21. SEE PICTURES BELOW!!!! We will probably need to talk to the owner because we are going to be digging up his landscaping. STRONGLY RECOMMEND A VACTOR TRUCK FOR MINIMAL DAMAGE.		V-086LV018	Valve Condition	
WO-61016	1	Completed	44488.05972	44488	Valve Maintenance Report	October 19, 2021, 1:30 AM	V-086LV019	Valve Condition	
WO-56069	1	Completed	44439.03093	44439	Valve Maintenance Report	August 31, 2021, 2:04 AM	V-086LV021	Valve Condition	
WO-35510	1	Completed	44230.38651	44242	Repair water main		V-086MV015	Valve Condition	
WO-53674	1	Completed	44411.57034	44439	Repair water main 6" mll. No parking needs posted. WATER NOT SURFACING but getting into the sewer. 3 day 1 call valid 8/6/21. SEE PICTURES BELOW!!!! We will probably need to talk to the owner because we are going to be digging up his landscaping. STRONGLY RECOMMEND A VACTOR TRUCK FOR MINIMAL DAMAGE.		V-086MV020	Valve Condition	
WO-42217	1	Completed	44306.45121	44307	Valve Maintenance Report	April 21, 2021, 7:48 AM	V-086MV023	Valve Condition	Good
WO-42217	1	Completed	44306.45121	44307	Valve Maintenance Report	April 21, 2021, 7:48 AM	V-086MV024	Valve Condition	Good
WO-42217	1	Completed	44306.45121	44307	Valve Maintenance Report	April 21, 2021, 7:48 AM	V-086MV036	Valve Condition	
WO-45243	1	Completed	44334.43161	44337	Valve Maintenance Report	May 21, 2021, 8:27 AM	V-086MV042	Valve Condition	Fair
WO-60422	1	Completed	44482.04515	44498	Repair water main		V-086PV004	Valve Condition	
WO-56473	401	Completed	44441.35749	44441	Dividing Pressure Valve Maintenance Report	September 2, 2021, 8:42 AM	V-086PV023	Valve Condition	Good
WO-55614	1	Completed	44433.34048	44433	Valve Maintenance Report	August 25, 2021, 8:12 AM	V-086RV004	Valve Condition	
WO-42217	1	Completed	44306.45121	44307	Valve Maintenance Report	April 21, 2021, 7:48 AM	V-086RV008	Valve Condition	
WO-56069	1	Completed	44439.03093	44439	Valve Maintenance Report	August 31, 2021, 2:04 AM	V-086RV011	Valve Condition	
WO-56069	1	Completed	44439.03093	44439	Valve Maintenance Report	August 31, 2021, 2:04 AM	V-086RV013	Valve Condition	
WO-56069	1	Completed	44439.03093	44439	Valve Maintenance Report	August 31, 2021, 2:04 AM	V-086RV015	Valve Condition	
WO-56069	1	Completed	44439.03093	44439	Valve Maintenance Report	August 31, 2021, 2:04 AM	V-086RV016	Valve Condition	
WO-56069	1	Completed	44439.03093	44439	Valve Maintenance Report	August 31, 2021, 2:04 AM	V-086RV018	Valve Condition	
WO-56069	1	Completed	44439.03093	44439	Valve Maintenance Report	August 31, 2021, 2:04 AM	V-086RV023	Valve Condition	
WO-44804	1	Completed	44330.40393	44330	Valve Maintenance Report	May 14, 2021, 9:48 AM	V-086RV030	Valve Condition	
WO-55462	1	Completed	44431.46877	44435	Valve Maintenance Report	August 27, 2021, 8:20 AM	V-086RV031	Valve Condition	
WO-55617	1	Completed	44433.3431	44433	Valve Maintenance Report	August 25, 2021, 8:16 AM	V-086SV002	Valve Condition	Marginal
WO-42217	1	Completed	44306.45121	44307	Valve Maintenance Report	April 21, 2021, 7:48 AM	V-086SV020	Valve Condition	
WO-42217	1	Completed	44306.45121	44307	Valve Maintenance Report	April 21, 2021, 7:48 AM	V-086SV032	Valve Condition	
WO-44797	1	Completed	44330.38343	44330	Valve Maintenance Report	May 14, 2021, 9:16 AM	V-086SV050	Valve Condition	
WO-42217	1	Completed	44306.45121	44307	Valve Maintenance Report	April 21, 2021, 7:48 AM	V-086SV066	Valve Condition	
WO-42217	1	Completed	44306.45121	44307	Valve Maintenance Report	April 21, 2021, 7:48 AM	V-086SV074	Valve Condition	
WO-48323	1	Completed	44358.62914	44358	Valve Maintenance Report	June 11, 2021, 5:49 PM	V-087AV015	Valve Condition	
WO-48323	1	Completed	44358.62914	44358	Valve Maintenance Report	June 11, 2021, 5:49 PM	V-087AV016	Valve Condition	
WO-42323	1	Completed	44307.42916	44312	Valve Maintenance Report	April 26, 2021, 7:53 AM	V-087AV031	Valve Condition	
WO-42323	1	Completed	44307.42916	44312	Valve Maintenance Report	April 26, 2021, 7:53 AM	V-087AV032	Valve Condition	
WO-42323	1	Completed	44307.42916	44312	Valve Maintenance Report	April 26, 2021, 7:53 AM	V-087AV033	Valve Condition	
WO-34541	1	Completed	44222.28169	44223	Repair water main		V-087BV014	Valve Condition	
WO-42323	1	Completed	44307.42916	44312	Valve Maintenance Report	April 26, 2021, 7:53 AM	V-087BV036	Valve Condition	
WO-42323	1	Completed	44307.42916	44312	Valve Maintenance Report	April 26, 2021, 7:53 AM	V-087BV039	Valve Condition	
WO-42323	1	Completed	44307.42916	44312	Valve Maintenance Report	April 26, 2021, 7:53 AM	V-087BV041	Valve Condition	
WO-42323	1	Completed	44307.42916	44312	Valve Maintenance Report	April 26, 2021, 7:53 AM	V-087BV044	Valve Condition	
WO-42323	1	Completed	44307.42916	44312	Valve Maintenance Report	April 26, 2021, 7:53 AM	V-087BV047	Valve Condition	
WO-34893	41	Completed	44224.51308	44236	Contractor shut request INDEPENDENT NEEDS A SHUT		V-087CV020	Valve Condition	
WO-42323	1	Completed	44307.42916	44312	Valve Maintenance Report	April 26, 2021, 7:53 AM	V-087CV048	Valve Condition	
WO-42323	1	Completed	44307.42916	44312	Valve Maintenance Report	April 26, 2021, 7:53 AM	V-087CV051	Valve Condition	
WO-42323	1	Completed	44307.42916	44312	Valve Maintenance Report	April 26, 2021, 7:53 AM	V-087CV053	Valve Condition	
WO-56069	1	Completed	44439.03093	44439	Valve Maintenance Report	August 31, 2021, 2:04 AM	V-087CV058	Valve Condition	
WO-55226	401	Completed	44427.55581	44427	Dividing Pressure Valve Maintenance Report	August 19, 2021, 1:26 PM	V-087DV008	Valve Condition	
WO-56021	401	Completed	44438.4582	44438	Dividing Pressure Valve Maintenance Report	August 30, 2021, 11:01 AM	V-087DV030	Valve Condition	
WO-42217	1	Completed	44306.45121	44307	Valve Maintenance Report	April 21, 2021, 7:48 AM	V-087DV033	Valve Condition	
WO-48323	1	Completed	44358.62914	44358	Valve Maintenance Report	June 11, 2021, 5:49 PM	V-087EV001	Valve Condition	
WO-48323	1	Completed	44358.62914	44358	Valve Maintenance Report	June 11, 2021, 5:49 PM	V-087EV003	Valve Condition	
WO-34893	41	Completed	44224.51308	44236	Contractor shut request INDEPENDENT NEEDS A SHUT		V-087FV002	Valve Condition	
WO-48323	1	Completed	44358.62914	44358	Valve Maintenance Report	June 11, 2021, 5:49 PM	V-087FV004	Valve Condition	
WO-48323	1	Completed	44358.62914	44358	Valve Maintenance Report	June 11, 2021, 5:49 PM	V-087FV008	Valve Condition	
WO-64726	1	Completed	44531.41096	44531	Valve Maintenance Report		V-087GV023	Valve Condition	
WO-40305	1	Completed	44284.54741	44284	Valve Maintenance Report	March 29, 2021, 1:11 PM	V-087GV028	Valve Condition	
WO-40304	1	Completed	44284.54515	44284	Valve Maintenance Report	March 29, 2021, 1:07 PM	V-087GV029	Valve Condition	
WO-56069	1	Completed	44439.03093	44439	Valve Maintenance Report	August 31, 2021, 2:04 AM	V-087GV038	Valve Condition	
WO-53578	1	Completed	44411.14642	44411	Valve Maintenance Report	August 3, 2021, 3:53 AM	V-087GV052	Valve Condition	Good
WO-43472	401	Completed	44319.40137	44319	Dividing Pressure Valve Maintenance Report	May 3, 2021, 9:42 AM	V-087GV055	Valve Condition	Fair
WO-64726	1	Completed	44531.41096	44531	Valve Maintenance Report		V-087GV058	Valve Condition	
WO-56018	401	Completed	44438.45021	44438	Dividing Pressure Valve Maintenance Report	August 30, 2021, 10:55 AM	V-087HV001	Valve Condition	
WO-46373	1	Completed	44342.5561	44342	Valve Maintenance Report	May 26, 2021, 1:31 PM	V-087HV002	Valve Condition	Fair
WO-56016	401	Completed	44438.44823	44438	Dividing Pressure Valve Maintenance Report	August 30, 2021, 10:47 AM	V-087HV004	Valve Condition	
WO-46418	1	Completed	44342.66101	44343	Repair water main	May 27, 2021, 1:38 AM	V-087HV007	Valve Condition	
WO-43438	401	Completed	44319.35196	44319	Dividing Pressure Valve Maintenance Report	May 3, 2021, 8:41 AM	V-087HV014	Valve Condition	
WO-43465	401	Completed	44319.38356	44319	Dividing Pressure Valve Maintenance Report	May 3, 2021, 9:19 AM	V-087HV024	Valve Condition	
WO-43462	401	Completed	44319.37673	44319	Dividing Pressure Valve Maintenance Report	May 3, 2021, 9:08 AM	V-087HV026	Valve Condition	
WO-43352	1	Completed	44316.5857	44316	Valve Maintenance Report	April 30, 2021, 2:12 PM	V-087HV028	Valve Condition	Good
WO-55748	1	Completed	44434.38704	44434	Repair water main		V-087JV004	Valve Condition	
WO-55622	1	Completed	44433.37014	44433	Valve Maintenance Report	August 25, 2021, 8:55 AM	V-087JV005	Valve Condition	
WO-37956	41	Completed	44257.59133	44257	Contractor shut request	March 2, 2021, 2:14 PM	V-087KV002	Valve Condition	
WO-37953	41	Completed	44257.58477	44257	Contractor shut request	March 2, 2021, 2:06 PM	V-087KV006	Valve Condition	Good
WO-37957	41	Completed	44257.59414	44257	Contractor shut request	March 2, 2021, 2:19 PM	V-087KV007	Valve Condition	Good
WO-40302	1	Completed	44284.54135	44284	Valve Maintenance Report	March 29, 2021, 1:03 PM	V-087LV005	Valve Condition	
WO-45566	41	Completed	44336.48366	44336	Contractor shut request		V-087LV011	Valve Condition	
WO-37955	41	Completed	44257.58846	44257	Contractor shut request	March 2, 2021, 2:10 PM	V-087LV015	Valve Condition	
WO-45566	41	Completed	44336.48366	44336	Contractor shut request		V-087LV017	Valve Condition	
WO-39498	1	Completed	44274.39055	44274	Valve Maintenance Report	March 19, 2021, 9:24 AM	V-087LV021	Valve Condition	
WO-45566	41	Completed	44336.48366	44336	Contractor shut request		V-087LV024	Valve Condition	
WO-56006	401	Completed	44438.42679	44438	Dividing Pressure Valve Maintenance Report	August 30, 2021, 10:17 AM	V-087MV001	Valve Condition	
WO-45214	1	Completed	44334.39872	44337	Valve Maintenance Report	May 21, 2021, 8:26 AM	V-087MV015	Valve Condition	Good
WO-45214	1	Completed	44334.39872	44337	Valve Maintenance Report	May 21, 2021, 8:26 AM	V-087MV016	Valve Condition	Good
WO-47386	1	Completed	44350.5525	44350	Valve Maintenance Report	June 3, 2021, 5:31 PM	V-087NV018	Valve Condition	Good
WO-47386	1	Completed	44350.5525	44350	Valve Maintenance Report	June 3, 2021, 5:31 PM	V-087NV019	Valve Condition	Good
WO-47386	1	Completed	44350.5525	44350	Valve Maintenance Report	June 3, 2021, 5:31 PM	V-087NV024	Valve Condition	Good
WO-47386	1	Completed	44350.5525	44350	Valve Maintenance Report	June 3, 2021, 5:31 PM	V-087NV025	Valve Condition	Good
WO-47813	41	Completed	44355.3707	44355	Contractor shut request	June 8, 2021, 8:58 AM	V-087NV028	Valve Condition	Good
WO-42593	401	Completed	44309.42031	44309	Dividing Pressure Valve Maintenance Report	April 23, 2021, 10:08 AM	V-087NV029	Valve Condition	
WO-42590	401	Completed	44309.41494	44309	Dividing Pressure Valve Maintenance Report	April 23, 2021, 10:00 AM	V-087NV035	Valve Condition	
WO-34697	1	Completed	44223.47923	44223	Valve Maintenance Report	January 27, 2021, 11:32 AM	V-087NV037	Valve Condition	
WO-55748	1	Completed	44434.38704	44434	Repair water main		V-087PV001	Valve Condition	
WO-55748	1	Completed	44434.38704	44434	Repair water main		V-087PV003	Valve Condition	Good
WO-55628	1	Completed	44433.40097	44433	Valve Maintenance Report	August 25, 2021, 9:39 AM	V-087PV004	Valve Condition	Good
WO-41956	401	Completed	44302.94944	44302	Dividing Pressure Valve Maintenance Report	April 16, 2021, 10:50 PM	V-087PV013	Valve Condition	
WO-45566	41	Completed	44336.48366	44336	Contractor shut request		V-087RV002	Valve Condition	
WO-45566	41	Completed	44336.48366	44336	Contractor shut request		V-087RV005	Valve Condition	
WO-46382	1	Completed	44342.56731	44349	Valve Maintenance Report	May 26, 2021, 1:45 PM	V-087RV007	Valve Condition	
WO-45566	41	Completed	44336.48366	44336	Contractor shut request		V-087RV009	Valve Condition	Fair
WO-45566	41	Completed	44336.48366	44336	Contractor shut request		V-087RV010	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-45566	41	Completed	44336.48366	44336	Contractor shut request		V-087RV011	Valve Condition	
WO-45566	41	Completed	44336.48366	44336	Contractor shut request		V-087RV012	Valve Condition	
WO-45566	41	Completed	44336.48366	44336	Contractor shut request		V-087RV013	Valve Condition	
WO-45566	41	Completed	44336.48366	44336	Contractor shut request		V-087RV015	Valve Condition	
WO-45440	21	Completed	44335.64373	44337	Valve requires replacement # 087RV016	May 26, 2021, 1:29 PM	V-087RV016	Valve Condition	Good
WO-32646	41	Completed	44203.28788	44203	Contractor shut request (Folino doing tie in on 12" main)	January 7, 2021, 3:54 PM	V-087RV020	Valve Condition	
WO-45214	1	Completed	44334.39872	44337	Valve Maintenance Report	May 21, 2021, 8:26 AM	V-087SV002	Valve Condition	Good
WO-32646	41	Completed	44203.28788	44203	Contractor shut request (Folino doing tie in on 12" main)	January 7, 2021, 3:54 PM	V-087SV003	Valve Condition	
WO-38262	1	Completed	44260.36688	44438	Repair water main		V-087SV004	Valve Condition	
WO-40301	1	Completed	44284.53919	44286	Valve Maintenance Report	March 31, 2021, 7:03 AM	V-087SV005	Valve Condition	
WO-40884	21	Completed	44292.32525	44300	Valve requires replacement. In sidewalk, one call placed last week	April 14, 2021, 7:20 AM	V-087SV006	Valve Condition	Good
WO-40301	1	Completed	44284.53919	44286	Valve Maintenance Report	March 31, 2021, 7:03 AM	V-087SV007	Valve Condition	
WO-41579	1	Completed	44300.37895	44306	Valve Maintenance Report	April 20, 2021, 8:44 AM	V-087SV008	Valve Condition	
WO-56318	1	Completed	44440.46938	44294	Valve Maintenance Report		V-087SV009	Valve Condition	
WO-56318	1	Completed	44440.46938	44294	Valve Maintenance Report		V-087SV012	Valve Condition	
WO-32646	41	Completed	44203.28788	44203	Contractor shut request (Folino doing tie in on 12" main)	January 7, 2021, 3:54 PM	V-087SV013	Valve Condition	
WO-32646	41	Completed	44203.28788	44203	Contractor shut request (Folino doing tie in on 12" main)	January 7, 2021, 3:54 PM	V-087SV014	Valve Condition	
WO-40301	1	Completed	44284.53919	44286	Valve Maintenance Report	March 31, 2021, 7:03 AM	V-087SV017	Valve Condition	
WO-47895	1	Completed	44356.35532	44425	Valve Maintenance Report	August 17, 2021, 1:28 PM	V-087SV025	Valve Condition	
WO-47895	1	Completed	44356.35532	44425	Valve Maintenance Report	August 17, 2021, 1:28 PM	V-087SV031	Valve Condition	
WO-46550	1	Completed	44343.57071	44343	Valve Maintenance Report	May 27, 2021, 1:45 PM	V-088AV003	Valve Condition	Good
WO-33334	1	Completed	44209.41258	44211	Valve Maintenance Report	January 15, 2021, 7:16 AM	V-088AV007	Valve Condition	
WO-47815	41	Completed	44355.3775	44355	Contractor shut request	June 8, 2021, 9:06 AM	V-088AV016	Valve Condition	Good
WO-46473	41	Completed	44343.39209	44343	Contractor shut request	May 27, 2021, 2:57 PM	V-088AV018	Valve Condition	Good
WO-45169	1	Completed	44334.35993	44334	Valve Maintenance Report	May 18, 2021, 8:40 AM	V-088AV027	Valve Condition	Fair
WO-43630	1	Completed	44320.55528	44320	Valve Maintenance Report	May 4, 2021, 1:21 PM	V-088AV028	Valve Condition	Good
WO-33334	1	Completed	44209.41258	44211	Valve Maintenance Report	January 15, 2021, 7:16 AM	V-088AV030	Valve Condition	
WO-39970	1	Completed	44280.47524	44280	Valve Maintenance Report	March 25, 2021, 11:30 AM	V-088AV034	Valve Condition	
WO-41265	21	Completed	44297.64167	44301	Valve requires replacement 088AV043 4"	April 16, 2021, 9:44 AM	V-088AV043	Valve Condition	
WO-34843	1	Completed	44224.36654	44224	Valve Maintenance Report	January 28, 2021, 8:54 AM	V-088AV051	Valve Condition	
WO-34841	1	Completed	44224.35823	44224	Valve Maintenance Report	January 28, 2021, 8:39 AM	V-088AV054	Valve Condition	Fair
WO-34877	1	Completed	44224.46086	44224	Valve Maintenance Report	January 28, 2021, 1:43 PM	V-088AV055	Valve Condition	
WO-46473	41	Completed	44343.39209	44343	Contractor shut request	May 27, 2021, 2:57 PM	V-088AV058	Valve Condition	Good
WO-34875	1	Completed	44224.45319	44224	Valve Maintenance Report	January 28, 2021, 10:58 AM	V-088AV060	Valve Condition	
WO-39970	1	Completed	44280.47524	44280	Valve Maintenance Report	March 25, 2021, 11:30 AM	V-088AV061	Valve Condition	
WO-35844	401	Completed	44232.5319	44232	Dividing Pressure Valve Maintenance Report	February 5, 2021, 12:51 PM	V-088AV063	Valve Condition	Fair
WO-34851	1	Completed	44224.4045	44224	Valve Maintenance Report	January 28, 2021, 9:51 AM	V-088AV064	Valve Condition	
WO-49239	88	Completed	44365.61053	44369	Repair service line	July 1, 2021, 9:26 AM	V-088AV066	Valve Condition	
WO-46473	41	Completed	44343.39209	44343	Contractor shut request	May 27, 2021, 2:57 PM	V-088AV072	Valve Condition	Good
WO-65279	1	Completed	44537.56353	44537	Valve Maintenance Report	December 7, 2021, 2:58 PM	V-088BV012	Valve Condition	
WO-65279	1	Completed	44537.56353	44537	Valve Maintenance Report	December 7, 2021, 2:58 PM	V-088BV013	Valve Condition	
WO-65279	1	Completed	44537.56353	44537	Valve Maintenance Report	December 7, 2021, 2:58 PM	V-088BV015	Valve Condition	
WO-38510	1	Completed	44264.41497	44264	Valve Maintenance Report	March 9, 2021, 10:01 AM	V-088BV027	Valve Condition	
WO-34883	1	Completed	44224.48225	44230	Valve Maintenance Report	February 3, 2021, 3:14 PM	V-088BV030	Valve Condition	
WO-65279	1	Completed	44537.56353	44537	Valve Maintenance Report	December 7, 2021, 2:58 PM	V-088BV031	Valve Condition	
WO-32620	1	Completed	44202.59415	44279	Repair water main		V-088CV004	Valve Condition	
WO-34554	41	Completed	44222.38908	44222	Contractor shut request	January 26, 2021, 9:25 AM	V-088CV010	Valve Condition	
WO-34551	41	Completed	44222.36302	44222	Contractor shut request	January 26, 2021, 8:46 AM	V-088CV012	Valve Condition	
WO-34552	41	Completed	44222.38125	44222	Contractor shut request	January 26, 2021, 9:15 AM	V-088CV014	Valve Condition	
WO-33386	1	Completed	44209.57337	44211	Valve Maintenance Report	January 15, 2021, 3:15 PM	V-088DV002	Valve Condition	
WO-39987	401	Completed	44280.52306	44280	Dividing Pressure Valve Maintenance Report	March 25, 2021, 12:38 PM	V-088DV006	Valve Condition	Good
WO-32646	41	Completed	44203.28788	44203	Contractor shut request (Folino doing tie in on 12" main)	January 7, 2021, 3:54 PM	V-088DV011	Valve Condition	
WO-39589	401	Completed	44277.04215	44277	Dividing Pressure Valve Maintenance Report	March 22, 2021, 1:05 AM	V-088DV012	Valve Condition	Fair
WO-33386	1	Completed	44209.57337	44211	Valve Maintenance Report	January 15, 2021, 3:15 PM	V-088DV032	Valve Condition	
WO-44348	1	Completed	44327.35937	44327	Valve Maintenance Report	May 11, 2021, 9:32 AM	V-088EV003	Valve Condition	
WO-41188	1	Completed	44295.376	44295	Valve Maintenance Report	April 9, 2021, 2:46 PM	V-088EV008	Valve Condition	
WO-64170	1	Completed	44522.62426	44523	Repair water main		V-088EV011	Valve Condition	Fair
WO-42576	401	Completed	44309.3752	44309	Dividing Pressure Valve Maintenance Report	April 23, 2021, 9:05 AM	V-088EV014	Valve Condition	
WO-41188	1	Completed	44295.376	44295	Valve Maintenance Report	April 9, 2021, 2:46 PM	V-088EV018	Valve Condition	
WO-41188	1	Completed	44295.376	44295	Valve Maintenance Report	April 9, 2021, 2:46 PM	V-088EV020	Valve Condition	Fair
WO-41188	1	Completed	44295.376	44295	Valve Maintenance Report	April 9, 2021, 2:46 PM	V-088EV025	Valve Condition	
WO-41188	1	Completed	44295.376	44295	Valve Maintenance Report	April 9, 2021, 2:46 PM	V-088EV026	Valve Condition	
WO-55527	1	Completed	44432.34166	44434	Valve Maintenance Report	August 26, 2021, 12:00 PM	V-088EV027	Valve Condition	Fair
WO-33507	1	Completed	44210.43522	44211	Valve Maintenance Report	January 15, 2021, 7:01 AM	V-088EV029	Valve Condition	
WO-35847	401	Completed	44232.54352	44232	Dividing Pressure Valve Maintenance Report	February 5, 2021, 1:06 PM	V-088EV033	Valve Condition	
WO-43589	1	Completed	44320.46178	44320	Valve Maintenance Report	May 4, 2021, 11:09 AM	V-088EV034	Valve Condition	Good
WO-34909	1	Completed	44224.58747	44224	Valve Maintenance Report	January 28, 2021, 2:09 PM	V-088EV037	Valve Condition	
WO-34932	1	Completed	44224.59963	44230	Valve Maintenance Report	February 3, 2021, 2:08 PM	V-088EV040	Valve Condition	
WO-34863	1	Completed	44224.4322	44224	Valve Maintenance Report	January 28, 2021, 10:29 AM	V-088EV041	Valve Condition	Poor
WO-54515	1	Completed	44420.43149	44424	Valve Maintenance Report	August 16, 2021, 7:12 AM	V-088FV007	Valve Condition	Fair
WO-42568	401	Completed	44309.36126	44309	Dividing Pressure Valve Maintenance Report	April 23, 2021, 8:46 AM	V-088FV009	Valve Condition	
WO-66050	85	Completed	44545.67375	44547	Repair water main	December 19, 2021, 1:35 PM	V-088FV010	Valve Condition	
WO-39682	401	Completed	44278.02594	44278	Dividing Pressure Valve Maintenance Report	March 23, 2021, 12:39 AM	V-088FV014	Valve Condition	
WO-66050	85	Completed	44545.67375	44547	Repair water main	December 19, 2021, 1:35 PM	V-088FV015	Valve Condition	
WO-66050	85	Completed	44545.67375	44547	Repair water main	December 19, 2021, 1:35 PM	V-088FV016	Valve Condition	
WO-66050	85	Completed	44545.67375	44547	Repair water main	December 19, 2021, 1:35 PM	V-088FV026	Valve Condition	
WO-39683	401	Completed	44278.0288	44278	Dividing Pressure Valve Maintenance Report	March 23, 2021, 12:44 AM	V-088FV027	Valve Condition	
WO-65131	1	Completed	44536.43478	44536	Valve Maintenance Report	December 6, 2021, 11:24 AM	V-088FV032	Valve Condition	
WO-39681	401	Completed	44278.01268	44278	Dividing Pressure Valve Maintenance Report	March 23, 2021, 12:20 AM	V-088FV033	Valve Condition	
WO-65114	1	Completed	44536.36257	44536	Valve Maintenance Report	December 6, 2021, 8:57 AM	V-088FV034	Valve Condition	
WO-65114	1	Completed	44536.36257	44536	Valve Maintenance Report	December 6, 2021, 8:57 AM	V-088FV035	Valve Condition	
WO-39590	401	Completed	44277.06187	44277	Dividing Pressure Valve Maintenance Report	March 22, 2021, 1:32 AM	V-088FV036	Valve Condition	Fair
WO-65118	1	Completed	44536.37629	44536	Valve Maintenance Report	December 6, 2021, 9:45 AM	V-088FV037	Valve Condition	
WO-65127	1	Completed	44536.408	44536	Valve Maintenance Report	December 6, 2021, 9:57 AM	V-088FV038	Valve Condition	Good
WO-65130	1	Completed	44536.41603	44536	Valve Maintenance Report	December 6, 2021, 10:13 AM	V-088FV041	Valve Condition	
WO-65131	1	Completed	44536.43478	44536	Valve Maintenance Report	December 6, 2021, 11:24 AM	V-088FV044	Valve Condition	
WO-65118	1	Completed	44536.37629	44536	Valve Maintenance Report	December 6, 2021, 9:45 AM	V-088FV047	Valve Condition	
WO-39592	401	Completed	44277.06872	44277	Dividing Pressure Valve Maintenance Report	March 22, 2021, 1:43 AM	V-088FV048	Valve Condition	Fair
WO-65114	1	Completed	44536.36257	44536	Valve Maintenance Report	December 6, 2021, 8:57 AM	V-088FV049	Valve Condition	
WO-34883	1	Completed	44224.48225	44230	Valve Maintenance Report	February 3, 2021, 3:14 PM	V-088GV002	Valve Condition	
WO-65268	1	Completed	44537.47504	44537	Valve Maintenance Report	December 7, 2021, 1:18 PM	V-088GV003	Valve Condition	
WO-65268	1	Completed	44537.47504	44537	Valve Maintenance Report	December 7, 2021, 1:18 PM	V-088GV004	Valve Condition	
WO-65227	1	Completed	44537.39686	44537	Valve Maintenance Report	December 7, 2021, 9:35 AM	V-088GV006	Valve Condition	
WO-65225	1	Completed	44537.39318	44537	Valve Maintenance Report	December 7, 2021, 9:28 AM	V-088GV007	Valve Condition	
WO-65227	1	Completed	44537.39686	44537	Valve Maintenance Report	December 7, 2021, 9:35 AM	V-088GV008	Valve Condition	
WO-65148	1	Completed	44536.52844	44536	Valve Maintenance Report	December 6, 2021, 12:44 PM	V-088GV011	Valve Condition	
WO-65148	1	Completed	44536.52844	44536	Valve Maintenance Report	December 6, 2021, 12:44 PM	V-088GV014	Valve Condition	
WO-34883	1	Completed	44224.48225	44230	Valve Maintenance Report	February 3, 2021, 3:14 PM	V-088GV015	Valve Condition	
WO-66349	1	Completed	44550.45067	44550	Valve Maintenance Report	December 20, 2021, 11:21 AM	V-088GV016	Valve Condition	
WO-34883	1	Completed	44224.48225	44230	Valve Maintenance Report	February 3, 2021, 3:14 PM	V-088GV017	Valve Condition	
WO-34883	1	Completed	44224.48225	44230	Valve Maintenance Report	February 3, 2021, 3:14 PM	V-088GV018	Valve Condition	
WO-65148	1	Completed	44536.52844	44536	Valve Maintenance Report	December 6, 2021, 12:44 PM	V-088GV019	Valve Condition	
WO-66358	1	Completed	44550.52253	44550	Valve Maintenance Report	December 20, 2021, 12:34 PM	V-088GV020	Valve Condition	
WO-65227	1	Completed	44537.39686	44537	Valve Maintenance Report	December 7, 2021, 9:35 AM	V-088GV022	Valve Condition	
WO-65244	1	Completed	44537.42629	44537	Valve Maintenance Report	December 7, 2021, 11:18 AM	V-088GV023	Valve Condition	
WO-65248	1	Completed	44537.43802	44537	Valve Maintenance Report	December 7, 2021, 10:34 AM	V-088GV024	Valve Condition	
WO-65244	1	Completed	44537.42629	44537	Valve Maintenance Report	December 7, 2021, 11:18 AM	V-088GV025	Valve Condition	
WO-66349	1	Completed	44550.45067	44550	Valve Maintenance Report	December 20, 2021, 11:21 AM	V-088GV026	Valve Condition	
WO-65011	1	Completed	44533.56684	44533	Valve Maintenance Report	December 3, 2021, 2:28 PM	V-088KV004	Valve Condition	
WO-64981	1	Completed	44533.47619	44533	Valve Maintenance Report	December 3, 2021, 11:29 AM	V-088KV005	Valve Condition	
WO-64986	1	Completed	44533.48666	44533	Valve Maintenance Report	December 3, 2021, 11:45 AM	V-088KV006	Valve Condition	
WO-51985	1	Completed	44391.43171	44439	Repair water main		V-088KV008	Valve Condition	Poor
WO-64988	1	Completed	44533.49729	44533	Valve Maintenance Report	December 3, 2021, 1:34 PM	V-088KV009	Valve Condition	
WO-65011	1	Completed	44533.56684	44533	Valve Maintenance Report	December 3, 2021, 2:28 PM	V-088KV010	Valve Condition	
WO-51988	1	Completed	44391.43519	44439	Repair water main		V-088KV011	Valve Condition	Poor
WO-55624	401	Completed	44433.38018	44433	Dividing Pressure Valve Maintenance Report	August 25, 2021, 9:10 AM	V-088LV006	Valve Condition	
WO-34988	1	Completed	44225.29273	44225	Repair water main		V-088LV007	Valve Condition	
WO-64958	1	Completed	44533.38191	44533	Valve Maintenance Report	December 3, 2021, 9:18 AM	V-088PV001	Valve Condition	
WO-64958	1	Completed	44533.38191	44533	Valve Maintenance Report	December 3, 2021, 9:18 AM	V-088PV002	Valve Condition	
WO-64958	1	Completed	44533.38191	44533	Valve Maintenance Report	December 3, 2021, 9:18 AM	V-088PV003	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-64958	1	Completed	44533.38191	44533	Valve Maintenance Report	December 3, 2021, 9:18 AM	V-088PV004	Valve Condition	
WO-64249	1	Completed	44523.44687	44523	Valve Maintenance Report	November 23, 2021, 10:47 AM	V-089AV002	Valve Condition	
WO-64249	1	Completed	44523.44687	44523	Valve Maintenance Report	November 23, 2021, 10:47 AM	V-089AV003	Valve Condition	
WO-64537	1	Completed	44529.488	44529	Valve Maintenance Report	November 29, 2021, 11:46 AM	V-089AV005	Valve Condition	
WO-64537	1	Completed	44529.488	44529	Valve Maintenance Report	November 29, 2021, 11:46 AM	V-089AV006	Valve Condition	
WO-63534	1	Completed	44515.46356	44515	Valve Maintenance Report	November 15, 2021, 11:15 AM	V-089CV004	Valve Condition	
WO-63950	1	Completed	44519.45628	44519	Valve Maintenance Report	November 19, 2021, 2:05 PM	V-089CV007	Valve Condition	
WO-63497	1	Completed	44515.376	44515	Valve Maintenance Report	November 15, 2021, 9:09 AM	V-089CV010	Valve Condition	
WO-64068	1	Completed	44522.38205	44522	Valve Maintenance Report	November 22, 2021, 9:13 AM	V-089CV017	Valve Condition	
WO-64228	1	Completed	44523.39818	44523	Valve Maintenance Report	November 23, 2021, 9:40 AM	V-089CV019	Valve Condition	
WO-63528	1	Completed	44515.42314	44515	Valve Maintenance Report	November 15, 2021, 11:04 AM	V-089CV020	Valve Condition	Poor
WO-63528	1	Completed	44515.42314	44515	Valve Maintenance Report	November 15, 2021, 11:04 AM	V-089CV021	Valve Condition	Poor
WO-63528	1	Completed	44515.42314	44515	Valve Maintenance Report	November 15, 2021, 11:04 AM	V-089CV022	Valve Condition	Poor
WO-63950	1	Completed	44519.45628	44519	Valve Maintenance Report	November 19, 2021, 2:05 PM	V-089CV024	Valve Condition	
WO-63950	1	Completed	44519.45628	44519	Valve Maintenance Report	November 19, 2021, 2:05 PM	V-089CV025	Valve Condition	
WO-63950	1	Completed	44519.45628	44519	Valve Maintenance Report	November 19, 2021, 2:05 PM	V-089CV026	Valve Condition	
WO-63950	1	Completed	44519.45628	44519	Valve Maintenance Report	November 19, 2021, 2:05 PM	V-089CV027	Valve Condition	
WO-64068	1	Completed	44522.38205	44522	Valve Maintenance Report	November 22, 2021, 9:13 AM	V-089CV028	Valve Condition	
WO-63950	1	Completed	44519.45628	44519	Valve Maintenance Report	November 19, 2021, 2:05 PM	V-089CV029	Valve Condition	
WO-64068	1	Completed	44522.38205	44522	Valve Maintenance Report	November 22, 2021, 9:13 AM	V-089CV030	Valve Condition	
WO-64228	1	Completed	44523.39818	44523	Valve Maintenance Report	November 23, 2021, 9:40 AM	V-089CV031	Valve Condition	
WO-64228	1	Completed	44523.39818	44523	Valve Maintenance Report	November 23, 2021, 9:40 AM	V-089CV032	Valve Condition	
WO-62997	1	Completed	44508.41046	44508	Valve Maintenance Report	November 8, 2021, 10:01 AM	V-089JV006	Valve Condition	
WO-62997	1	Completed	44508.41046	44508	Valve Maintenance Report	November 8, 2021, 10:01 AM	V-089JV007	Valve Condition	
WO-62997	1	Completed	44508.41046	44508	Valve Maintenance Report	November 8, 2021, 10:01 AM	V-089JV008	Valve Condition	
WO-63005	1	Completed	44508.42454	44508	Valve Maintenance Report	November 8, 2021, 10:17 AM	V-089JV009	Valve Condition	
WO-63005	1	Completed	44508.42454	44508	Valve Maintenance Report	November 8, 2021, 10:17 AM	V-089JV010	Valve Condition	
WO-62819	1	Completed	44505.47439	44505	Valve Maintenance Report	November 5, 2021, 11:41 AM	V-089KV002	Valve Condition	
WO-62819	1	Completed	44505.47439	44505	Valve Maintenance Report	November 5, 2021, 11:41 AM	V-089KV005	Valve Condition	
WO-62819	1	Completed	44505.47439	44505	Valve Maintenance Report	November 5, 2021, 11:41 AM	V-089KV006	Valve Condition	
WO-62819	1	Completed	44505.47439	44505	Valve Maintenance Report	November 5, 2021, 11:41 AM	V-089KV007	Valve Condition	
WO-62731	1	Completed	44504.56658	44504	Valve Maintenance Report	November 4, 2021, 1:44 PM	V-089KV008	Valve Condition	
WO-62731	1	Completed	44504.56658	44504	Valve Maintenance Report	November 4, 2021, 1:44 PM	V-089KV009	Valve Condition	
WO-62731	1	Completed	44504.56658	44504	Valve Maintenance Report	November 4, 2021, 1:44 PM	V-089KV010	Valve Condition	
WO-62843	1	Completed	44505.57035	44505	Valve Maintenance Report	November 5, 2021, 1:46 PM	V-089NV015	Valve Condition	
WO-62843	1	Completed	44505.57035	44505	Valve Maintenance Report	November 5, 2021, 1:46 PM	V-089NV016	Valve Condition	
WO-62734	1	Completed	44504.57452	44504	Valve Maintenance Report	November 4, 2021, 1:51 PM	V-089PV001	Valve Condition	Good
WO-61776	41	Completed	44496.39546	44496	Contractor shut request	October 27, 2021, 1:19 PM	V-114CV006	Valve Condition	
WO-52242	1	Completed	44393.46201	44393	Valve Maintenance Report	July 16, 2021, 12:47 PM	V-114FV005	Valve Condition	
WO-52242	1	Completed	44393.46201	44393	Valve Maintenance Report	July 16, 2021, 12:47 PM	V-114FV006	Valve Condition	
WO-40766	85	Completed	44289.83769	44295	Repair water main	April 9, 2021, 2:57 PM	V-114FV008	Valve Condition	
WO-40766	85	Completed	44289.83769	44295	Repair water main	April 9, 2021, 2:57 PM	V-114FV013	Valve Condition	
WO-49111	1	Completed	44364.58701	44368	Valve Maintenance Report		V-114FV023	Valve Condition	
WO-52242	1	Completed	44393.46201	44393	Valve Maintenance Report	July 16, 2021, 12:47 PM	V-114FV025	Valve Condition	
WO-49111	1	Completed	44364.58701	44368	Valve Maintenance Report		V-114GV006	Valve Condition	
WO-49111	1	Completed	44364.58701	44368	Valve Maintenance Report		V-114GV008	Valve Condition	
WO-61776	41	Completed	44496.39546	44496	Contractor shut request	October 27, 2021, 1:19 PM	V-114GV017	Valve Condition	
WO-61776	41	Completed	44496.39546	44496	Contractor shut request	October 27, 2021, 1:19 PM	V-114GV018	Valve Condition	
WO-53198	85	Completed	44405.31422	44427	Repair water main	August 19, 2021, 7:38 AM	V-114HV001	Valve Condition	Good
WO-53198	85	Completed	44405.31422	44427	Repair water main	August 19, 2021, 7:38 AM	V-114HV002	Valve Condition	Good
WO-53198	85	Completed	44405.31422	44427	Repair water main	August 19, 2021, 7:38 AM	V-114HV004	Valve Condition	Good
WO-53198	85	Completed	44405.31422	44427	Repair water main	August 19, 2021, 7:38 AM	V-114HV008	Valve Condition	Good
WO-64966	1	Completed	44533.4299	44533	Valve Maintenance Report	December 3, 2021, 10:21 AM	V-114HV014	Valve Condition	
WO-35787	1	Completed	44232.36382	44438	Repair water main		V-114KV001	Valve Condition	
WO-35787	1	Completed	44232.36382	44438	Repair water main		V-114KV005	Valve Condition	
WO-58352	683	Completed	44461.8371	44461	Work site details for reporting	September 22, 2021, 8:22 PM	V-114KV006	Valve Condition	
WO-58352	683	Completed	44461.8371	44461	Work site details for reporting	September 22, 2021, 8:22 PM	V-114KV007	Valve Condition	
WO-58352	683	Completed	44461.8371	44461	Work site details for reporting	September 22, 2021, 8:22 PM	V-114KV012	Valve Condition	
WO-58352	683	Completed	44461.8371	44461	Work site details for reporting	September 22, 2021, 8:22 PM	V-114KV027	Valve Condition	
WO-58352	683	Completed	44461.8371	44461	Work site details for reporting	September 22, 2021, 8:22 PM	V-114KV028	Valve Condition	
WO-46095	88	Completed	44341.40502	44463	Customer Brought out New Service 1" copper need to complete public side shut and cut old service	November 17, 2021, 8:12 AM	V-114LV033	Valve Condition	
WO-53199	1	Completed	44405.31422	44448	Repair water main		V-114MV001	Valve Condition	
WO-61392	88	Completed	44491.41327	44505	Repair water main	November 5, 2021, 3:29 PM	V-114MV003	Valve Condition	Good
WO-61392	88	Completed	44491.41327	44505	Repair water main	November 5, 2021, 3:29 PM	V-114MV013	Valve Condition	Good
WO-37199	84	Completed	44249.62124	44250	Main or service line leak investigation/survey LEAK AT THE CURB , -- PER EMAIL		V-114PV006	Valve Condition	Good
WO-37199	84	Completed	44249.62124	44250	Main or service line leak investigation/survey LEAK AT THE CURB , -- PER EMAIL		V-114PV007	Valve Condition	Good
WO-37199	84	Completed	44249.62124	44250	Main or service line leak investigation/survey LEAK AT THE CURB , -- PER EMAIL		V-114RV003	Valve Condition	Good
WO-36901	88	Completed	44245.55838	44253	Repair service line I dropped meter and flushed SL for 30 minutes. I left customer a lead test kit. While I was there I heard a leak on the service line and believe there is a leak on Pwsa side	July 23, 2021, 2:37 PM	V-114SV037	Valve Condition	
WO-36901	88	Completed	44245.55838	44253	Repair service line I dropped meter and flushed SL for 30 minutes. I left customer a lead test kit. While I was there I heard a leak on the service line and believe there is a leak on Pwsa side	July 23, 2021, 2:37 PM	V-114SV044	Valve Condition	
WO-32861	1	Completed	44204.42373	44204	Valve Maintenance Report	January 8, 2021, 10:10 AM	V-115AV011	Valve Condition	
WO-32757	1	Completed	44203.57814	44215	Valve Maintenance Report	January 19, 2021, 11:53 AM	V-115AV012	Valve Condition	
WO-45413	43	Completed	44335.55678	44335	Test shut	May 19, 2021, 1:45 PM	V-115AV013	Valve Condition	Good
WO-32552	1	Completed	44202.44462	44202	Valve Maintenance Report	January 6, 2021, 10:42 AM	V-115AV015	Valve Condition	
WO-32550	1	Completed	44202.44149	44202	Valve Maintenance Report	January 6, 2021, 10:38 AM	V-115AV016	Valve Condition	
WO-32528	1	Completed	44202.39823	44202	Valve Maintenance Report	January 6, 2021, 9:39 AM	V-115AV018	Valve Condition	
WO-35837	85	Completed	44232.45633	44251	Repair water main	February 26, 2021, 3:19 PM	V-115AV019	Valve Condition	
WO-32526	1	Completed	44202.39381	44202	Valve Maintenance Report	January 6, 2021, 9:31 AM	V-115AV022	Valve Condition	
WO-32738	1	Completed	44203.56174	44203	Valve Maintenance Report	January 7, 2021, 1:30 PM	V-115AV023	Valve Condition	
WO-35837	85	Completed	44232.45633	44251	Repair water main	February 26, 2021, 3:19 PM	V-115AV024	Valve Condition	
WO-35837	85	Completed	44232.45633	44251	Repair water main	February 26, 2021, 3:19 PM	V-115AV025	Valve Condition	
WO-35837	85	Completed	44232.45633	44251	Repair water main	February 26, 2021, 3:19 PM	V-115AV026	Valve Condition	
WO-34287	1	Completed	44218.47412	44218	Valve Maintenance Report	January 22, 2021, 11:25 AM	V-115AV029	Valve Condition	
WO-32553	1	Completed	44202.44804	44202	Valve Maintenance Report	January 6, 2021, 10:46 AM	V-115AV031	Valve Condition	
WO-33066	1	Completed	44207.54668	44207	Valve Maintenance Report	January 11, 2021, 1:09 PM	V-115BV003	Valve Condition	
WO-33065	1	Completed	44207.54549	44207	Valve Maintenance Report	January 11, 2021, 1:07 PM	V-115BV004	Valve Condition	
WO-33068	1	Completed	44207.54905	44207	Valve Maintenance Report	January 11, 2021, 1:13 PM	V-115BV005	Valve Condition	
WO-34028	1	Completed	44216.45552	44216	Valve Maintenance Report	January 20, 2021, 11:07 AM	V-115BV006	Valve Condition	
WO-34027	1	Completed	44216.45251	44216	Valve Maintenance Report	January 20, 2021, 10:54 AM	V-115BV007	Valve Condition	
WO-34020	1	Completed	44216.41296	44216	Valve Maintenance Report	January 20, 2021, 10:05 AM	V-115BV008	Valve Condition	
WO-34025	1	Completed	44216.43984	44216	Valve Maintenance Report	January 20, 2021, 10:36 AM	V-115BV009	Valve Condition	
WO-33110	1	Completed	44208.36894	44208	Valve Maintenance Report	January 12, 2021, 8:53 AM	V-115BV010	Valve Condition	
WO-34017	1	Completed	44216.39207	44216	Valve Maintenance Report	January 20, 2021, 9:26 AM	V-115BV012	Valve Condition	
WO-34019	1	Completed	44216.39395	44216	Valve Maintenance Report	January 20, 2021, 9:41 AM	V-115BV013	Valve Condition	
WO-34016	1	Completed	44216.38988	44216	Valve Maintenance Report	January 20, 2021, 9:23 AM	V-115BV015	Valve Condition	
WO-33124	1	Completed	44208.39117	44208	Valve Maintenance Report	January 12, 2021, 9:26 AM	V-115BV017	Valve Condition	
WO-33126	1	Completed	44208.39466	44208	Valve Maintenance Report	January 12, 2021, 9:30 AM	V-115BV018	Valve Condition	
WO-33125	1	Completed	44208.39201	44208	Valve Maintenance Report	January 12, 2021, 9:25 AM	V-115BV019	Valve Condition	
WO-33118	1	Completed	44208.39034	44208	Valve Maintenance Report	January 12, 2021, 9:23 AM	V-115BV020	Valve Condition	
WO-33313	1	Completed	44209.36363	44209	Valve Maintenance Report	January 13, 2021, 8:56 AM	V-115BV022	Valve Condition	
WO-33363	1	Completed	44209.50802	44209	Valve Maintenance Report	January 13, 2021, 12:13 PM	V-115CV010	Valve Condition	
WO-33331	1	Completed	44209.49892	44209	Valve Maintenance Report	January 13, 2021, 12:00 PM	V-115CV017	Valve Condition	
WO-33375	1	Completed	44209.53779	44209	Valve Maintenance Report	January 13, 2021, 12:57 PM	V-115CV021	Valve Condition	
WO-33367	1	Completed	44209.53117	44209	Valve Maintenance Report	January 13, 2021, 12:46 PM	V-115CV022	Valve Condition	
WO-33373	1	Completed	44209.53594	44209	Valve Maintenance Report	January 13, 2021, 12:53 PM	V-115CV024	Valve Condition	
WO-34472	1	Completed	44221.50313	44221	Valve Maintenance Report	January 25, 2021, 12:06 PM	V-115DV006	Valve Condition	
WO-34473	1	Completed	44221.505	44221	Valve Maintenance Report	January 25, 2021, 12:42 PM	V-115DV009	Valve Condition	
WO-34712	1	Completed	44223.54896	44223	Valve Maintenance Report	January 27, 2021, 1:12 PM	V-115DV011	Valve Condition	
WO-37812	1	Completed	44256.59289	44438	Repair water main 2' main		V-115DV012	Valve Condition	Good
WO-56269	1	Completed	44440.40716	44378	Valve Maintenance Report		V-115DV040	Valve Condition	
WO-56269	1	Completed	44440.40716	44378	Valve Maintenance Report		V-115DV044	Valve Condition	Good
WO-32745	1	Completed	44203.56945	44203	Valve Maintenance Report	January 7, 2021, 1:42 PM	V-115EV005	Valve Condition	
WO-32863	1	Completed	44204.44402	44204	Valve Maintenance Report	January 8, 2021, 10:42 AM	V-115EV009	Valve Condition	
WO-33042	1	Completed	44207.39317	44207	Valve Maintenance Report	January 11, 2021, 9:29 AM	V-115EV010	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-33046	1	Completed	44207.40622	44207	Valve Maintenance Report	January 11, 2021, 9:46 AM	V-115EV013	Valve Condition	
WO-33045	1	Completed	44207.40401	44207	Valve Maintenance Report	January 11, 2021, 9:43 AM	V-115EV014	Valve Condition	
WO-33049	1	Completed	44207.40917	44207	Valve Maintenance Report	January 11, 2021, 9:50 AM	V-115EV015	Valve Condition	
WO-32896	1	Completed	44204.53887	44204	Valve Maintenance Report	January 8, 2021, 1:00 PM	V-115EV016	Valve Condition	
WO-32866	1	Completed	44204.45323	44204	Valve Maintenance Report	January 8, 2021, 10:54 AM	V-115EV017	Valve Condition	
WO-32868	1	Completed	44204.45591	44204	Valve Maintenance Report	January 8, 2021, 10:59 AM	V-115EV018	Valve Condition	
WO-33029	1	Completed	44207.36003	44207	Valve Maintenance Report	January 11, 2021, 8:41 AM	V-115EV020	Valve Condition	
WO-33033	1	Completed	44207.36287	44207	Valve Maintenance Report	January 11, 2021, 8:47 AM	V-115EV021	Valve Condition	
WO-33039	1	Completed	44207.39053	44207	Valve Maintenance Report	January 11, 2021, 9:26 AM	V-115EV022	Valve Condition	
WO-33044	1	Completed	44207.39497	44207	Valve Maintenance Report	January 11, 2021, 9:32 AM	V-115EV024	Valve Condition	
WO-33327	1	Completed	44209.39755	44209	Valve Maintenance Report	January 13, 2021, 9:35 AM	V-115GV002	Valve Condition	
WO-33333	1	Completed	44209.41035	44209	Valve Maintenance Report	January 13, 2021, 10:11 AM	V-115GV004	Valve Condition	
WO-33488	1	Completed	44210.3808	44210	Valve Maintenance Report	January 14, 2021, 9:11 AM	V-115HV003	Valve Condition	
WO-33505	1	Completed	44210.43058	44210	Valve Maintenance Report	January 14, 2021, 10:22 AM	V-115HV005	Valve Condition	
WO-33482	1	Completed	44210.39455	44210	Valve Maintenance Report	January 14, 2021, 9:30 AM	V-115HV006	Valve Condition	
WO-33495	1	Completed	44210.39645	44210	Valve Maintenance Report	January 14, 2021, 9:35 AM	V-115HV013	Valve Condition	
WO-34279	1	Completed	44218.44592	44218	Valve Maintenance Report	January 22, 2021, 10:54 AM	V-115HV019	Valve Condition	
WO-34282	1	Completed	44218.45497	44218	Valve Maintenance Report	January 22, 2021, 11:02 AM	V-115HV020	Valve Condition	
WO-33683	1	Completed	44211.4503	44211	Valve Maintenance Report	January 15, 2021, 10:52 AM	V-115JV003	Valve Condition	
WO-33691	1	Completed	44211.46381	44211	Valve Maintenance Report	January 15, 2021, 11:09 AM	V-115JV004	Valve Condition	
WO-39802	85	Completed	44279.3902	44287	Repair water main	April 1, 2021, 2:56 PM	V-115JV005	Valve Condition	Good
WO-39802	85	Completed	44279.3902	44287	Repair water main	April 1, 2021, 2:56 PM	V-115JV007	Valve Condition	Good
WO-34014	1	Completed	44216.37233	44216	Valve Maintenance Report	January 20, 2021, 8:59 AM	V-115KV002	Valve Condition	
WO-33527	1	Completed	44210.52135	44210	Valve Maintenance Report	January 14, 2021, 12:34 PM	V-115NV002	Valve Condition	
WO-39802	85	Completed	44279.3902	44287	Repair water main	April 1, 2021, 2:56 PM	V-115NV003	Valve Condition	Good
WO-34173	1	Completed	44217.5493	44217	Valve Maintenance Report	January 21, 2021, 1:12 PM	V-115NV004	Valve Condition	
WO-34177	1	Completed	44217.56116	44217	Valve Maintenance Report	January 21, 2021, 1:41 PM	V-115NV005	Valve Condition	
WO-34176	1	Completed	44217.55905	44217	Valve Maintenance Report	January 21, 2021, 1:26 PM	V-115NV006	Valve Condition	
WO-33511	1	Completed	44210.44837	44210	Valve Maintenance Report	January 14, 2021, 11:11 AM	V-115NV007	Valve Condition	
WO-39802	85	Completed	44279.3902	44287	Repair water main	April 1, 2021, 2:56 PM	V-115NV008	Valve Condition	Good
WO-39802	85	Completed	44279.3902	44287	Repair water main	April 1, 2021, 2:56 PM	V-115NV009	Valve Condition	Good
WO-33526	1	Completed	44210.5265	44210	Valve Maintenance Report	January 14, 2021, 12:40 PM	V-115NV017	Valve Condition	
WO-33528	1	Completed	44210.54534	44210	Valve Maintenance Report	January 14, 2021, 1:07 PM	V-115NV018	Valve Condition	
WO-33537	1	Completed	44210.54753	44210	Valve Maintenance Report	January 14, 2021, 1:10 PM	V-115NV019	Valve Condition	
WO-33685	1	Completed	44211.43929	44211	Valve Maintenance Report	January 15, 2021, 10:36 AM	V-115NV024	Valve Condition	
WO-49746	84	Completed	44369.93403	44370	Main or service line leak investigation/survey/PER CUSTOMER WATER IN STREET SEEMS AS IF IT IS COMING FROM TOP OF THE STREET ENTIRE STREET IS WET AT 4:30 PM IS FIRST NOTICED IS WAS A NNICE SPOT BUT NOW COMING HOME ENTIRE STREET COVERED THERE IS A PGH WATER SEWER DRAIN IN STREET IN FRONT OF HOME WHICH ASPHALT LOOKS LIKE IT IS RISING AS IF WATER IS ABOUT TO BURST UP THROUGH LID	June 23, 2021, 5:10 PM	V-115NV025	Valve Condition	
WO-49757	85	Completed	44370.29198	44371	Repair water main	June 24, 2021, 9:37 AM	V-115NV026	Valve Condition	
WO-49757	85	Completed	44370.29198	44371	Repair water main	June 24, 2021, 9:37 AM	V-115NV027	Valve Condition	
WO-34182	1	Completed	44217.58429	44217	Valve Maintenance Report	January 21, 2021, 2:19 PM	V-115NV028	Valve Condition	
WO-34034	1	Completed	44216.47771	44216	Valve Maintenance Report	January 20, 2021, 11:41 AM	V-115SV001	Valve Condition	
WO-34038	1	Completed	44216.49827	44216	Valve Maintenance Report		V-115SV002	Valve Condition	
WO-34299	88	Completed	44218.57928	44328	Repair service line: This Work Order is for a Non-Metered City of Pittsburgh Properties. a crock and 1-1/2" meter need installed at the curb stop. This curb box is full and I was unable to get on the curb stop	May 12, 2021, 2:15 PM	V-115SV005	Valve Condition	
WO-34037	1	Completed	44216.48824	44216	Valve Maintenance Report	January 20, 2021, 11:55 AM	V-115SV007	Valve Condition	
WO-50003	1	Completed	44371.57585	44390	Repair water main		V-116AV006	Valve Condition	Good
WO-50002	85	Completed	44371.57585	44372	Repair water main	June 25, 2021, 2:34 PM	V-116EV001	Valve Condition	Good
WO-50003	1	Completed	44371.57585	44390	Repair water main		V-116EV003	Valve Condition	Good
WO-50859	85	Completed	44378.96588	44379	Repair water main	July 6, 2021, 12:04 PM	V-116EV017	Valve Condition	
WO-39407	85	Completed	44273.41576	44277	Repair water main	March 22, 2021, 2:13 PM	V-116KV002	Valve Condition	
WO-39407	85	Completed	44273.41576	44277	Repair water main	March 22, 2021, 2:13 PM	V-116KV003	Valve Condition	
WO-49619	182	Completed	44369.35927	44532	Information sheet for connection SEND WASTE WATER		V-116KV009	Valve Condition	Good
WO-50756	88	Completed	44378.37505	44397	268 Watson Blvd. Repair service line: This is a Lead line replacement, the customers plumber has ran out a new 1" PEX water service line out to the lead curb stop and was allowed to reconnect to the lead line for temporary use. PWSA will need to run a new line from the main to curb. the Plumber will be backfilling the ditch in the sidewalk after his plumbing inspection form Allegheny County Health Department (ACHD) so not to block the sidewalk.	July 20, 2021, 2:22 PM	V-116NV006	Valve Condition	
WO-50756	88	Completed	44378.37505	44397	268 Watson Blvd. Repair service line: This is a Lead line replacement, the customers plumber has ran out a new 1" PEX water service line out to the lead curb stop and was allowed to reconnect to the lead line for temporary use. PWSA will need to run a new line from the main to curb. the Plumber will be backfilling the ditch in the sidewalk after his plumbing inspection form Allegheny County Health Department (ACHD) so not to block the sidewalk.	July 20, 2021, 2:22 PM	V-116NV007	Valve Condition	
WO-50756	88	Completed	44378.37505	44397	268 Watson Blvd. Repair service line: This is a Lead line replacement, the customers plumber has ran out a new 1" PEX water service line out to the lead curb stop and was allowed to reconnect to the lead line for temporary use. PWSA will need to run a new line from the main to curb. the Plumber will be backfilling the ditch in the sidewalk after his plumbing inspection form Allegheny County Health Department (ACHD) so not to block the sidewalk.	July 20, 2021, 2:22 PM	V-116NV008	Valve Condition	
WO-50756	88	Completed	44378.37505	44397	268 Watson Blvd. Repair service line: This is a Lead line replacement, the customers plumber has ran out a new 1" PEX water service line out to the lead curb stop and was allowed to reconnect to the lead line for temporary use. PWSA will need to run a new line from the main to curb. the Plumber will be backfilling the ditch in the sidewalk after his plumbing inspection form Allegheny County Health Department (ACHD) so not to block the sidewalk.	July 20, 2021, 2:22 PM	V-116NV010	Valve Condition	
WO-50756	88	Completed	44378.37505	44397	268 Watson Blvd. Repair service line: This is a Lead line replacement, the customers plumber has ran out a new 1" PEX water service line out to the lead curb stop and was allowed to reconnect to the lead line for temporary use. PWSA will need to run a new line from the main to curb. the Plumber will be backfilling the ditch in the sidewalk after his plumbing inspection form Allegheny County Health Department (ACHD) so not to block the sidewalk.	July 20, 2021, 2:22 PM	V-116PV001	Valve Condition	
WO-50199	41	Completed	44374.91139	44375	Contractor shut request	June 28, 2021, 3:11 AM	V-118GV005	Valve Condition	
WO-50199	41	Completed	44374.91139	44375	Contractor shut request	June 28, 2021, 3:11 AM	V-118GV006	Valve Condition	Good
WO-47795	1	Completed	44355.33193	44355	Valve Maintenance Report	June 8, 2021, 2:28 PM	V-118LV002	Valve Condition	Good
WO-50199	41	Completed	44374.91139	44375	Contractor shut request	June 28, 2021, 3:11 AM	V-118LV011	Valve Condition	
WO-45685	1	Completed	44337.424	44340	Valve Maintenance Report	May 24, 2021, 8:14 AM	V-118LV012	Valve Condition	Good
WO-45685	1	Completed	44337.424	44340	Valve Maintenance Report	May 24, 2021, 8:14 AM	V-118LV014	Valve Condition	Good
WO-63827	21	Completed	44518.39206	44517	Valve requires replacement- If the valve is unmapped, use Install New Valve work order	November 18, 2021, 9:26 AM	V-118MV005	Valve Condition	
WO-37603	85	Completed	44253.36713	44257	Repair water main	March 2, 2021, 1:44 PM	V-118PV014	Valve Condition	
WO-61121	1	Completed	44488.60703	44496	Repair water main 4" contractor hit main. Per Bob White, McCarthy sending a crew to help shut down.		V-118RV001	Valve Condition	Good
WO-61121	1	Completed	44488.60703	44496	Repair water main 4" contractor hit main. Per Bob White, McCarthy sending a crew to help shut down.		V-118RV002	Valve Condition	Good
WO-61121	1	Completed	44488.60703	44496	Repair water main 4" contractor hit main. Per Bob White, McCarthy sending a crew to help shut down.		V-118RV006	Valve Condition	
WO-61121	1	Completed	44488.60703	44496	Repair water main 4" contractor hit main. Per Bob White, McCarthy sending a crew to help shut down.		V-118RV012	Valve Condition	
WO-43707	41	Completed	44321.36865	44321	Contractor shut request	May 5, 2021, 9:46 AM	V-118RV015	Valve Condition	
WO-61121	1	Completed	44488.60703	44496	Repair water main 4" contractor hit main. Per Bob White, McCarthy sending a crew to help shut down.		V-118RV016	Valve Condition	
WO-42195	1	Completed	44306.37279	44306	Valve Maintenance Report	April 20, 2021, 10:49 AM	V-118RV018	Valve Condition	
WO-42195	1	Completed	44306.37279	44306	Valve Maintenance Report	April 20, 2021, 10:49 AM	V-118RV019	Valve Condition	Good

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-64949	85	Completed	44533.35753	44536	Repair water main 6" main. Leak on main or on service line. Dead end street, dead end main ,1 valve shut. additional pictures in attached W.O.		V-118RV020	Valve Condition	Good
WO-41602	85	Completed	44300.43689	44309	Repair water main	April 23, 2021, 5:08 AM	V-119SV009	Valve Condition	
WO-41602	85	Completed	44300.43689	44309	Repair water main	April 23, 2021, 5:08 AM	V-119SV013	Valve Condition	
WO-47712	1	Completed	44354.48428	44354	Valve Maintenance Report	June 7, 2021, 2:15 PM	V-119SV029	Valve Condition	
WO-59790	85	Completed	44475.98512	44477	Repair water main - 6"	October 8, 2021, 11:08 AM	V-119SV032	Valve Condition	
WO-35737	1	Completed	44231.80186	44232	Repair water main	February 4, 2021, 10:31 PM	V-119SV038	Valve Condition	Fair
WO-59790	85	Completed	44475.98512	44477	Repair water main - 6"	October 8, 2021, 11:08 AM	V-119SV039	Valve Condition	
WO-59790	85	Completed	44475.98512	44477	Repair water main - 6"	October 8, 2021, 11:08 AM	V-119SV040	Valve Condition	
WO-59790	85	Completed	44475.98512	44477	Repair water main - 6"	October 8, 2021, 11:08 AM	V-119SV041	Valve Condition	
WO-59790	85	Completed	44475.98512	44477	Repair water main - 6"	October 8, 2021, 11:08 AM	V-119SV043	Valve Condition	
WO-39786	1	Completed	44279.33508	44280	Valve Maintenance Report	March 25, 2021, 7:35 AM	V-119SV048	Valve Condition	Good
WO-64140	1	Completed	44522.58041	44522	Valve Maintenance Report	November 22, 2021, 1:59 PM	V-120LV002	Valve Condition	
WO-35326	85	Completed	44229.37374	44231	Repair water main	February 4, 2021, 6:26 PM	V-120LV004	Valve Condition	
WO-35326	85	Completed	44229.37374	44231	Repair water main	February 4, 2021, 6:26 PM	V-120LV007	Valve Condition	
WO-65372	1	Completed	44538.60299	44538	Valve Maintenance Report	December 8, 2021, 2:37 PM	V-120LV008	Valve Condition	
WO-45648	88	Completed	44337.34109	44342	Repair service line- Verify Public side material	May 27, 2021, 11:49 AM	V-120MV002	Valve Condition	Fair
WO-65354	1	Completed	44538.46824	44538	Valve Maintenance Report	December 8, 2021, 11:17 AM	V-120MV003	Valve Condition	
WO-44118	1	Completed	44323.61927	44323	Repair water main	May 7, 2021, 10:21 PM	V-120MV005	Valve Condition	
WO-64204	1	Completed	44523.33639	44523	Valve Maintenance Report	November 23, 2021, 8:07 AM	V-120MV006	Valve Condition	
WO-44100	1	Completed	44323.55666	44323	Valve Maintenance Report	May 7, 2021, 11:36 PM	V-120MV007	Valve Condition	
WO-64206	1	Completed	44523.34344	44523	Valve Maintenance Report	November 23, 2021, 8:18 AM	V-120MV008	Valve Condition	
WO-63977	1	Completed	44519.5437	44519	Valve Maintenance Report	November 19, 2021, 1:06 PM	V-120MV010	Valve Condition	
WO-63978	1	Completed	44519.5563	44519	Valve Maintenance Report	November 19, 2021, 1:24 PM	V-120MV011	Valve Condition	
WO-64050	1	Completed	44522.33974	44522	Valve Maintenance Report	November 22, 2021, 8:13 AM	V-120MV013	Valve Condition	
WO-65135	1	Completed	44536.44338	44536	Valve Maintenance Report	December 6, 2021, 10:42 AM	V-120MV017	Valve Condition	
WO-65117	1	Completed	44536.44781	44536	Valve Maintenance Report	December 6, 2021, 10:54 AM	V-120MV018	Valve Condition	
WO-65137	1	Completed	44536.47057	44536	Valve Maintenance Report	December 6, 2021, 11:23 AM	V-120MV019	Valve Condition	
WO-64154	1	Completed	44522.60178	44522	Valve Maintenance Report	November 22, 2021, 2:30 PM	V-120MV022	Valve Condition	
WO-64209	1	Completed	44523.34883	44523	Valve Maintenance Report	November 23, 2021, 8:25 AM	V-120MV023	Valve Condition	
WO-45809	84	Completed	44339.443	44339	Main or service line leak investigation/survey- LEAK IN STREET.	May 23, 2021, 3:29 PM	V-120NV018	Valve Condition	
WO-66213	1	Completed	44547.54746	44547	Valve Maintenance Report	December 17, 2021, 1:27 PM	V-120PV012	Valve Condition	
WO-66370	1	Completed	44550.58191	44550	Valve Maintenance Report	December 20, 2021, 2:00 PM	V-120PV015	Valve Condition	
WO-64055	1	Completed	44522.35826	44522	Valve Maintenance Report	November 22, 2021, 8:40 AM	V-120RV001	Valve Condition	
WO-54902	1	Completed	44425.29426	44426	Repair water main		V-120RV002	Valve Condition	
WO-50858	1	Completed	44378.96135	44439	Repair water main		V-120RV003	Valve Condition	
WO-58751	1	Completed	44466.47352	44467	Valve Maintenance Report	September 28, 2021, 1:50 PM	V-120RV015	Valve Condition	
WO-59224	1	Completed	44470.3824	44470	Valve Maintenance Report	October 1, 2021, 2:39 PM	V-120RV017	Valve Condition	
WO-62535	1	Completed	44504.28126	44504	Valve Maintenance Report	November 4, 2021, 12:59 PM	V-120RV021	Valve Condition	
WO-62537	1	Completed	44504.28126	44504	Valve Maintenance Report	November 4, 2021, 1:36 PM	V-120RV022	Valve Condition	
WO-63096	1	Completed	44508.58043	44508	Valve Maintenance Report	November 8, 2021, 1:59 PM	V-120RV024	Valve Condition	
WO-63102	1	Completed	44508.58859	44508	Valve Maintenance Report	November 8, 2021, 2:11 PM	V-120RV025	Valve Condition	
WO-63927	1	Completed	44519.39365	44519	Valve Maintenance Report	November 19, 2021, 9:31 AM	V-120RV026	Valve Condition	
WO-50858	1	Completed	44378.96135	44439	Repair water main		V-120RV027	Valve Condition	
WO-62537	1	Completed	44504.28126	44504	Valve Maintenance Report	November 4, 2021, 1:36 PM	V-120RV028	Valve Condition	
WO-62537	1	Completed	44504.28126	44504	Valve Maintenance Report	November 4, 2021, 1:36 PM	V-120RV030	Valve Condition	
WO-62700	1	Completed	44504.42211	44504	Valve Maintenance Report	November 4, 2021, 10:12 AM	V-120RV031	Valve Condition	Good
WO-65285	1	Completed	44537.59305	44537	Valve Maintenance Report	December 7, 2021, 2:17 PM	V-120RV037	Valve Condition	
WO-65282	1	Completed	44537.57925	44537	Valve Maintenance Report	December 7, 2021, 1:57 PM	V-120RV038	Valve Condition	
WO-64121	1	Completed	44522.50522	44522	Valve Maintenance Report	November 22, 2021, 12:16 PM	V-120RV039	Valve Condition	
WO-54902	1	Completed	44425.29426	44426	Repair water main		V-120RV043	Valve Condition	
WO-66210	1	Completed	44547.53094	44547	Valve Maintenance Report	December 17, 2021, 12:49 PM	V-120RV044	Valve Condition	
WO-65338	1	Completed	44538.43191	44538	Valve Maintenance Report	December 8, 2021, 10:25 AM	V-120SV001	Valve Condition	
WO-65345	1	Completed	44538.43961	44538	Valve Maintenance Report	December 8, 2021, 10:36 AM	V-120SV002	Valve Condition	Good
WO-65349	1	Completed	44538.44975	44538	Valve Maintenance Report	December 8, 2021, 10:51 AM	V-120SV003	Valve Condition	
WO-65128	1	Completed	44536.41002	44536	Valve Maintenance Report	December 6, 2021, 10:00 AM	V-120SV005	Valve Condition	
WO-65126	1	Completed	44536.39975	44536	Valve Maintenance Report	December 6, 2021, 9:41 AM	V-120SV006	Valve Condition	
WO-66109	1	Completed	44546.51713	44546	Valve Maintenance Report	December 16, 2021, 12:28 PM	V-120SV009	Valve Condition	
WO-65056	1	Completed	44534.0111	44534	Repair water main	December 4, 2021, 3:38 PM	V-120SV012	Valve Condition	
WO-65056	1	Completed	44534.0111	44534	Repair water main	December 4, 2021, 3:38 PM	V-120SV014	Valve Condition	
WO-66165	1	Completed	44547.38247	44547	Valve Maintenance Report	December 17, 2021, 9:15 AM	V-120SV015	Valve Condition	
WO-66202	1	Completed	44547.51411	44547	Valve Maintenance Report	December 17, 2021, 12:25 PM	V-120SV017	Valve Condition	
WO-66040	1	Completed	44545.60594	44545	Valve Maintenance Report	December 15, 2021, 2:37 PM	V-121EV006	Valve Condition	
WO-65446	1	Completed	44539.52526	44539	Valve Maintenance Report	December 9, 2021, 12:39 PM	V-121EV009	Valve Condition	
WO-44100	1	Completed	44323.55666	44323	Valve Maintenance Report	May 7, 2021, 11:36 PM	V-121EV011	Valve Condition	
WO-44118	1	Completed	44323.61927	44323	Repair water main	May 7, 2021, 10:21 PM	V-121EV012	Valve Condition	
WO-44118	1	Completed	44323.61927	44323	Repair water main	May 7, 2021, 10:21 PM	V-121EV014	Valve Condition	
WO-44118	1	Completed	44323.61927	44323	Repair water main	May 7, 2021, 10:21 PM	V-121EV018	Valve Condition	
WO-64163	1	Completed	44522.61653	44522	Valve Maintenance Report	November 22, 2021, 2:49 PM	V-121EV020	Valve Condition	
WO-64876	1	Completed	44532.58103	44532	Valve Maintenance Report	December 2, 2021, 1:58 PM	V-121EV021	Valve Condition	
WO-65480	1	Completed	44539.5564	44539	Valve Maintenance Report	December 9, 2021, 1:26 PM	V-121EV022	Valve Condition	
WO-64879	1	Completed	44532.58412	44532	Valve Maintenance Report	December 2, 2021, 2:03 PM	V-121EV023	Valve Condition	
WO-65487	1	Completed	44539.57401	44539	Valve Maintenance Report	December 9, 2021, 1:56 PM	V-121EV024	Valve Condition	
WO-63991	1	Completed	44519.6138	44519	Valve Maintenance Report	November 19, 2021, 2:48 PM	V-121JV002	Valve Condition	
WO-63990	1	Completed	44519.60759	44519	Valve Maintenance Report	November 19, 2021, 2:38 PM	V-121JV003	Valve Condition	
WO-33188	85	Completed	44208.51553	44217	Repair water main	January 22, 2021, 9:38 AM	V-121JV004	Valve Condition	
WO-33188	85	Completed	44208.51553	44217	Repair water main	January 22, 2021, 9:38 AM	V-121JV005	Valve Condition	
WO-65265	1	Completed	44537.46271	44537	Valve Maintenance Report	December 7, 2021, 11:09 AM	V-121JV006	Valve Condition	
WO-33188	85	Completed	44208.51553	44217	Repair water main	January 22, 2021, 9:38 AM	V-121JV013	Valve Condition	
WO-64217	1	Completed	44523.37537	44523	Valve Maintenance Report	November 23, 2021, 9:05 AM	V-121JV014	Valve Condition	Good
WO-33804	85	Completed	44213.63541	44213	Repair water main	January 17, 2021, 9:28 PM	V-121JV015	Valve Condition	
WO-66126	1	Completed	44546.55118	44546	Valve Maintenance Report	December 16, 2021, 1:24 PM	V-121JV016	Valve Condition	
WO-64233	1	Completed	44523.42278	44523	Valve Maintenance Report	November 23, 2021, 10:11 AM	V-121JV017	Valve Condition	
WO-66125	1	Completed	44546.54245	44546	Valve Maintenance Report	December 16, 2021, 1:08 PM	V-121JV021	Valve Condition	
WO-45299	1	Completed	44334.58532	44439	Repair water main		V-121KV018	Valve Condition	
WO-45299	1	Completed	44334.58532	44439	Repair water main		V-121KV042	Valve Condition	
WO-33189	1	Completed	44208.51553	44219	Repair water main		V-121LV013	Valve Condition	
WO-57488	1	Completed	44454.32243	44454	Valve Maintenance Report		V-121PV002	Valve Condition	
WO-57488	1	Completed	44454.32243	44454	Valve Maintenance Report		V-121PV003	Valve Condition	
WO-57488	1	Completed	44454.32243	44454	Valve Maintenance Report		V-121PV004	Valve Condition	
WO-40508	1	Completed	44286.4192	44286	Valve Maintenance Report	March 31, 2021, 10:09 AM	V-122DV001	Valve Condition	
WO-43043	21	Completed	44314.43651	44314	Valve requires replacement	April 28, 2021, 2:45 PM	V-122NV036	Valve Condition	Good
WO-65782	1	Completed	44543.62016	44547	Valve Maintenance Report	December 17, 2021, 3:17 PM	V-123AV014	Valve Condition	
WO-42498	1	Completed	44308.60384	44438	Repair water main		V-123AV028	Valve Condition	
WO-42498	1	Completed	44308.60384	44438	Repair water main		V-123AV030	Valve Condition	
WO-38678	84	Completed	44265.56879	44295	Main or service line leak investigation/survey	April 9, 2021, 12:37 PM	V-123AV033	Valve Condition	
WO-45023	1	Completed	44333.49081	44333	Valve Maintenance Report	May 17, 2021, 11:50 AM	V-123AV034	Valve Condition	
WO-45024	1	Completed	44333.49508	44333	Valve Maintenance Report	May 17, 2021, 11:56 AM	V-123AV035	Valve Condition	Good
WO-50194	1	Completed	44373.67176	44373	Repair water main	June 26, 2021, 8:53 PM	V-123BV002	Valve Condition	
WO-65506	1	Completed	44539.60765	44551	Repair water main		V-123EV023	Valve Condition	
WO-60284	1	Completed	44480.99628	44482	Repair water main / replace tee and replace existing D.P. Valve (8")		V-123EV029	Valve Condition	Good
WO-32697	1	Completed	44203.41102	44203	Valve Maintenance Report	January 7, 2021, 4:38 PM	V-123JV006	Valve Condition	
WO-32697	1	Completed	44203.41102	44203	Valve Maintenance Report	January 7, 2021, 4:38 PM	V-123JV008	Valve Condition	
WO-60284	1	Completed	44480.99628	44482	Repair water main / replace tee and replace existing D.P. Valve (8")		V-123KV012	Valve Condition	Good
WO-32697	1	Completed	44203.41102	44203	Valve Maintenance Report	January 7, 2021, 4:38 PM	V-123NV001	Valve Condition	
WO-32511	41	Completed	44202.32411	44202	Contractor shut request	January 6, 2021, 3:31 PM	V-123NV002	Valve Condition	
WO-32511	41	Completed	44202.32411	44202	Contractor shut request	January 6, 2021, 3:31 PM	V-123NV003	Valve Condition	
WO-32697	1	Completed	44203.41102	44203	Valve Maintenance Report	January 7, 2021, 4:38 PM	V-123NV005	Valve Condition	
WO-32511	41	Completed	44202.32411	44202	Contractor shut request	January 6, 2021, 3:31 PM	V-123NV006	Valve Condition	
WO-32511	41	Completed	44202.32411	44202	Contractor shut request	January 6, 2021, 3:31 PM	V-123NV011	Valve Condition	
WO-32511	41	Completed	44202.32411	44202	Contractor shut request	January 6, 2021, 3:31 PM	V-123NV016	Valve Condition	
WO-32511	41	Completed	44202.32411	44202	Contractor shut request	January 6, 2021, 3:31 PM	V-123NV017	Valve Condition	
WO-32511	41	Completed	44202.32411	44202	Contractor shut request	January 6, 2021, 3:31 PM	V-123NV018	Valve Condition	
WO-32511	41	Completed	44202.32411	44202	Contractor shut request	January 6, 2021, 3:31 PM	V-123NV025	Valve Condition	
WO-34946	85	Completed	44224.73175	44224	Repair water main	January 28, 2021, 9:24 PM	V-123NV028	Valve Condition	Good
WO-47671	1	Completed	44354.33399	44355	Valve Maintenance Report		V-123NV031	Valve Condition	
WO-47671	1	Completed	44354.33399	44355	Valve Maintenance Report		V-123NV033	Valve Condition	
WO-57814	1	Completed	44456.55294	44455	Valve Maintenance Report		V-123NV035	Valve Condition	Fair

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-47671	1	Completed	44354.33399	44355	Valve Maintenance Report		V-123NV036	Valve Condition	
WO-47671	1	Completed	44354.33399	44355	Valve Maintenance Report		V-123NV037	Valve Condition	
WO-47671	1	Completed	44354.33399	44355	Valve Maintenance Report		V-123NV038	Valve Condition	
WO-32697	1	Completed	44203.41102	44203	Valve Maintenance Report	January 7, 2021, 4:38 PM	V-123NV041	Valve Condition	
WO-60284	1	Completed	44480.99628	44482	Repair water main / replace tee and replace existing D.P. Valve (8")		V-123NV042	Valve Condition	Good
WO-53492	1	Completed	44410.38581	44410	Valve Maintenance Report	August 2, 2021, 9:17 AM	V-123NV048	Valve Condition	Fair
WO-60284	1	Completed	44480.99628	44482	Repair water main / replace tee and replace existing D.P. Valve (8")		V-123PV001	Valve Condition	Good
WO-60284	1	Completed	44480.99628	44482	Repair water main / replace tee and replace existing D.P. Valve (8")		V-123PV003	Valve Condition	Good
WO-60396	1	Completed	44481.59993	44481	Valve Maintenance Report	October 12, 2021, 2:27 PM	V-123PV007	Valve Condition	Good
WO-32258	1	Completed	44198.8342	44200	Repair water main	January 3, 2021, 10:57 PM	V-124AV003	Valve Condition	
WO-56275	1	Completed	44440.4239	44350	Valve Maintenance Report		V-124AV011	Valve Condition	Fair
WO-34946	85	Completed	44224.73175	44224	Repair water main	January 28, 2021, 9:24 PM	V-124AV013	Valve Condition	Good
WO-56275	1	Completed	44440.4239	44350	Valve Maintenance Report		V-124AV014	Valve Condition	Fair
WO-47671	1	Completed	44354.33399	44355	Valve Maintenance Report		V-124AV015	Valve Condition	
WO-47671	1	Completed	44354.33399	44355	Valve Maintenance Report		V-124AV016	Valve Condition	
WO-65215	1	Completed	44537.3367	44536	Valve Maintenance Report		V-124AV023	Valve Condition	
WO-57814	1	Completed	44456.55294	44455	Valve Maintenance Report		V-124AV025	Valve Condition	
WO-57814	1	Completed	44456.55294	44455	Valve Maintenance Report		V-124AV026	Valve Condition	Fair
WO-65215	1	Completed	44537.3367	44536	Valve Maintenance Report		V-124AV027	Valve Condition	Fair
WO-47671	1	Completed	44354.33399	44355	Valve Maintenance Report		V-124AV028	Valve Condition	
WO-58172	464	Completed	44460.61409	44462	Contractor damage to sewer main. OHERRON HIT SERVICE LINE	September 23, 2021, 6:43 AM	V-124DV003	Valve Condition	
WO-58912	1	Completed	44467.569	44470	Repair water main		V-124DV006	Valve Condition	
WO-38636	41	Completed	44265.36113	44266	Contractor shut request	March 11, 2021, 7:50 AM	V-124FV012	Valve Condition	
WO-63532	1	Completed	44515.4568	44515	Valve Maintenance Report	November 15, 2021, 11:00 AM	V-124GV010	Valve Condition	
WO-36458	1	Completed	44239.55999	44239	Valve Maintenance Report	February 12, 2021, 2:53 PM	V-124HV011	Valve Condition	
WO-36458	1	Completed	44239.55999	44239	Valve Maintenance Report	February 12, 2021, 2:53 PM	V-124HV039	Valve Condition	
WO-56964	1	Completed	44448.31667	44448	Valve Maintenance Report		V-124JV002	Valve Condition	
WO-38068	1	Completed	44258.54964	44258	Valve Maintenance Report	March 3, 2021, 1:16 PM	V-124JV003	Valve Condition	
WO-56964	1	Completed	44448.31667	44448	Valve Maintenance Report		V-124JV007	Valve Condition	
WO-38636	41	Completed	44265.36113	44266	Contractor shut request	March 11, 2021, 7:50 AM	V-124JV015	Valve Condition	
WO-32690	1	Completed	44203.39835	44203	Valve Maintenance Report	January 7, 2021, 2:30 PM	V-124JV016	Valve Condition	
WO-32622	1	Completed	44202.61879	44203	Valve Maintenance Report	January 7, 2021, 6:44 AM	V-124JV017	Valve Condition	
WO-39259	41	Completed	44272.36978	44272	Contractor shut request	March 17, 2021, 12:01 PM	V-124JV018	Valve Condition	
WO-39259	41	Completed	44272.36978	44272	Contractor shut request	March 17, 2021, 12:01 PM	V-124JV020	Valve Condition	
WO-39244	21	Completed	44272.30812	44278	Valve is inoperable and requires replacement	March 23, 2021, 4:27 PM	V-124JV022	Valve Condition	Fair
WO-32685	1	Completed	44203.36726	44204	Repair water main	January 21, 2021, 11:07 AM	V-124JV023	Valve Condition	
WO-38636	41	Completed	44265.36113	44266	Contractor shut request	March 11, 2021, 7:50 AM	V-124JV025	Valve Condition	
WO-39259	41	Completed	44272.36978	44272	Contractor shut request	March 17, 2021, 12:01 PM	V-124JV027	Valve Condition	
WO-39402	21	Completed	44273.40353	44278	Valve is inoperable and requires replacement	March 23, 2021, 9:09 AM	V-124JV029	Valve Condition	
WO-39400	21	Completed	44273.402	44277	Valve is inoperable and requires replacement	March 23, 2021, 8:47 AM	V-124JV030	Valve Condition	
WO-39259	41	Completed	44272.36978	44272	Contractor shut request	March 17, 2021, 12:01 PM	V-124JV031	Valve Condition	
WO-39259	41	Completed	44272.36978	44272	Contractor shut request	March 17, 2021, 12:01 PM	V-124JV032	Valve Condition	
WO-43329	1	Completed	44316.5022	44322	Repair water main		V-124KV003	Valve Condition	
WO-43329	1	Completed	44316.5022	44322	Repair water main		V-124KV005	Valve Condition	
WO-38636	41	Completed	44265.36113	44266	Contractor shut request	March 11, 2021, 7:50 AM	V-124KV033	Valve Condition	
WO-63535	1	Completed	44515.46504	44515	Valve Maintenance Report	November 15, 2021, 11:16 AM	V-124LV003	Valve Condition	
WO-63791	1	Completed	44517.5575	44517	Valve Maintenance Report	November 17, 2021, 1:24 PM	V-124LV017	Valve Condition	
WO-62321	1	Completed	44502.43778	44501	Valve Maintenance Report		V-124LV018	Valve Condition	
WO-63789	1	Completed	44517.55516	44517	Valve Maintenance Report	November 17, 2021, 1:21 PM	V-124LV019	Valve Condition	
WO-63786	1	Completed	44517.54446	44517	Valve Maintenance Report	November 17, 2021, 1:06 PM	V-124LV021	Valve Condition	Good
WO-35972	84	Completed	44234.821	44238	Main or service line leak investigation/survey NEEDS A COUPLE OF DRILL HOLES. PUT ON SALT LIST. CAUSING ICE ON A STEEP INCLINE STREET. NEED THIS LEAK CONFIRMED		V-124MV001	Valve Condition	Marginal
WO-32855	1	Completed	44204.58566	44204	Valve Maintenance Report	January 8, 2021, 2:06 PM	V-124MV003	Valve Condition	
WO-55339	85	Completed	44428.54263	44430	Repair water main	August 23, 2021, 10:33 AM	V-124MV009	Valve Condition	
WO-38171	1	Completed	44259.49606	44438	Repair water main		V-124MV014	Valve Condition	
WO-55339	85	Completed	44428.54263	44430	Repair water main	August 23, 2021, 10:33 AM	V-124MV017	Valve Condition	Good
WO-55339	85	Completed	44428.54263	44430	Repair water main	August 23, 2021, 10:33 AM	V-124MV018	Valve Condition	Good
WO-36781	88	Completed	44244.34758	44251	Repair service line: Customer has ran out a new 1" copper water service line out to the curb and is wrapped in a blue bag. A new water service needs ran from the curb to the main.	February 25, 2021, 8:50 AM	V-124NV007	Valve Condition	
WO-38636	41	Completed	44265.36113	44266	Contractor shut request	March 11, 2021, 7:50 AM	V-124NV008	Valve Condition	
WO-36781	88	Completed	44244.34758	44251	Repair service line: Customer has ran out a new 1" copper water service line out to the curb and is wrapped in a blue bag. A new water service needs ran from the curb to the main.	February 25, 2021, 8:50 AM	V-124NV014	Valve Condition	
WO-32685	1	Completed	44203.36726	44204	Repair water main	January 21, 2021, 11:07 AM	V-124NV029	Valve Condition	
WO-34459	1	Completed	44221.47851	44222	Valve Maintenance Report		V-124PV001	Valve Condition	
WO-64653	1	Completed	44530.53465	44532	Repair water main		V-124PV009	Valve Condition	
WO-59536	1	Completed	44474.50853	44473	Valve Maintenance Report	October 5, 2021, 12:17 PM	V-124PV038	Valve Condition	
WO-59536	1	Completed	44474.50853	44473	Valve Maintenance Report	October 5, 2021, 12:17 PM	V-124PV040	Valve Condition	
WO-59536	1	Completed	44474.50853	44473	Valve Maintenance Report	October 5, 2021, 12:17 PM	V-124PV041	Valve Condition	
WO-63849	1	Completed	44518.48063	44518	Valve Maintenance Report	November 18, 2021, 11:35 AM	V-124RV011	Valve Condition	
WO-63861	1	Completed	44518.54873	44518	Valve Maintenance Report	November 18, 2021, 1:12 PM	V-124RV012	Valve Condition	
WO-63846	1	Completed	44518.47563	44518	Valve Maintenance Report	November 18, 2021, 11:28 AM	V-124RV013	Valve Condition	Good
WO-63841	1	Completed	44518.46537	44518	Valve Maintenance Report	November 18, 2021, 11:12 AM	V-124SV007	Valve Condition	Good
WO-34558	1	Completed	44222.39927	44222	Valve Maintenance Report	January 26, 2021, 2:49 PM	V-124SV012	Valve Condition	Good
WO-34558	1	Completed	44222.39927	44222	Valve Maintenance Report	January 26, 2021, 2:49 PM	V-124SV014	Valve Condition	Good
WO-34558	1	Completed	44222.39927	44222	Valve Maintenance Report	January 26, 2021, 2:49 PM	V-124SV015	Valve Condition	Good
WO-38171	1	Completed	44259.49606	44438	Repair water main		V-124SV016	Valve Condition	
WO-37754	1	Completed	44256.38806	44256	Valve Maintenance Report	March 1, 2021, 9:21 AM	V-124SV026	Valve Condition	
WO-36984	1	Completed	44246.38803	44246	Valve Maintenance Report	February 19, 2021, 2:47 PM	V-124SV027	Valve Condition	Good
WO-36984	1	Completed	44246.38803	44246	Valve Maintenance Report	February 19, 2021, 2:47 PM	V-124SV033	Valve Condition	Good
WO-36984	1	Completed	44246.38803	44246	Valve Maintenance Report	February 19, 2021, 2:47 PM	V-124SV036	Valve Condition	Good
WO-62468	1	Completed	44503.44127	44503	Valve Maintenance Report	November 3, 2021, 12:22 PM	V-124SV037	Valve Condition	
WO-34558	1	Completed	44222.39927	44222	Valve Maintenance Report	January 26, 2021, 2:49 PM	V-124SV040	Valve Condition	
WO-36984	1	Completed	44246.38803	44246	Valve Maintenance Report	February 19, 2021, 2:47 PM	V-124SV046	Valve Condition	Good
WO-36437	1	Completed	44239.44769	44239	Valve Maintenance Report	February 12, 2021, 10:50 AM	V-125AV002	Valve Condition	
WO-37181	1	Completed	44249.56125	44249	Valve Maintenance Report	February 22, 2021, 1:32 PM	V-125AV003	Valve Condition	
WO-36442	1	Completed	44239.45384	44239	Valve Maintenance Report	February 12, 2021, 10:58 AM	V-125AV004	Valve Condition	
WO-36433	1	Completed	44239.42164	44239	Valve Maintenance Report	February 12, 2021, 10:14 AM	V-125AV008	Valve Condition	
WO-36432	1	Completed	44239.41374	44239	Valve Maintenance Report	February 12, 2021, 9:59 AM	V-125AV018	Valve Condition	
WO-37237	1	Completed	44250.36219	44277	Valve Maintenance Report	March 22, 2021, 7:07 AM	V-125AV029	Valve Condition	Good
WO-36455	1	Completed	44239.53769	44239	Valve Maintenance Report	February 12, 2021, 12:58 PM	V-125AV030	Valve Condition	
WO-37128	1	Completed	44249.38199	44250	Valve Maintenance Report	February 23, 2021, 1:03 PM	V-125AV034	Valve Condition	
WO-37152	1	Completed	44249.40396	44249	Valve Maintenance Report	February 22, 2021, 10:24 AM	V-125AV035	Valve Condition	
WO-37175	1	Completed	44249.54532	44438	Valve Maintenance Report		V-125AV039	Valve Condition	Marginal
WO-37127	1	Completed	44249.37561	44250	Valve Maintenance Report	February 23, 2021, 1:01 PM	V-125AV049	Valve Condition	Good
WO-59536	1	Completed	44474.50853	44473	Valve Maintenance Report	October 5, 2021, 12:17 PM	V-125BV002	Valve Condition	
WO-61266	1	Completed	44490.33373	44487	Valve Maintenance Report		V-125BV014	Valve Condition	
WO-42685	85	Completed	44311.73599	44314	Repair water main		V-125BV018	Valve Condition	
WO-42685	85	Completed	44311.73599	44314	Repair water main		V-125BV027	Valve Condition	
WO-61266	1	Completed	44490.33373	44487	Valve Maintenance Report		V-125BV035	Valve Condition	
WO-61266	1	Completed	44490.33373	44487	Valve Maintenance Report		V-125BV046	Valve Condition	
WO-62468	1	Completed	44503.44127	44503	Valve Maintenance Report	November 3, 2021, 12:22 PM	V-125DV003	Valve Condition	
WO-62797	1	Completed	44505.36348	44559	Valve Maintenance Report	December 29, 2021, 1:53 PM	V-125DV016	Valve Condition	
WO-62797	1	Completed	44505.36348	44559	Valve Maintenance Report	December 29, 2021, 1:53 PM	V-125DV017	Valve Condition	
WO-62797	1	Completed	44505.36348	44559	Valve Maintenance Report	December 29, 2021, 1:53 PM	V-125DV018	Valve Condition	
WO-62487	1	Completed	44503.51789	44503	Valve Maintenance Report	November 3, 2021, 1:12 PM	V-125DV027	Valve Condition	
WO-62487	1	Completed	44503.51789	44503	Valve Maintenance Report	November 3, 2021, 1:12 PM	V-125DV029	Valve Condition	
WO-40788	1	Completed	44291.3349	44314	Valve Maintenance Report	April 28, 2021, 7:57 AM	V-125DV030	Valve Condition	
WO-40788	1	Completed	44291.3349	44314	Valve Maintenance Report	April 28, 2021, 7:57 AM	V-125DV033	Valve Condition	
WO-62710	1	Completed	44504.4648	44504	Valve Maintenance Report	November 4, 2021, 11:23 AM	V-125HV001	Valve Condition	
WO-62710	1	Completed	44504.4648	44504	Valve Maintenance Report	November 4, 2021, 11:23 AM	V-125HV002	Valve Condition	
WO-62710	1	Completed	44504.4648	44504	Valve Maintenance Report	November 4, 2021, 11:23 AM	V-125HV003	Valve Condition	
WO-62710	1	Completed	44504.4648	44504	Valve Maintenance Report	November 4, 2021, 11:23 AM	V-125HV005	Valve Condition	
WO-62677	1	Completed	44504.36247	44504	Valve Maintenance Report	November 4, 2021, 10:20 AM	V-125HV053	Valve Condition	
WO-62677	1	Completed	44504.36247	44504	Valve Maintenance Report	November 4, 2021, 10:20 AM	V-125HV054	Valve Condition	
WO-62677	1	Completed	44504.36247	44504	Valve Maintenance Report	November 4, 2021, 10:20 AM	V-125HV055	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-34521	84	Completed	44221.91804	44228	Main or service line leak investigation/survey/ 311 COMPLAINT/PARC:0125H00243000000 Leaking on to sidewalk and row, freezing	February 1, 2021, 2:35 PM	V-125HV059	Valve Condition	
WO-49839	1	Completed	44370.58311	44372	Valve Maintenance Report	June 25, 2021, 8:11 AM	V-125KV016	Valve Condition	
WO-38900	1	Completed	44267.56092	44438	Repair water main. 6". Good correlation from hydrant to valve near 5th ave. DIG WERE WATER IS SURFACING. NO PARKING NEEDS POSTED. 1 call valid 3/17/21. See pictures below		V-125NV009	Valve Condition	Good
WO-54050	1	Completed	44414.54536	44503	Repair water main		V-125NV010	Valve Condition	
WO-64865	1	Completed	44532.54488	44532	Valve Maintenance Report	December 2, 2021, 1:24 PM	V-125NV024	Valve Condition	
WO-64866	1	Completed	44532.54645	44532	Valve Maintenance Report	December 2, 2021, 1:17 PM	V-125NV025	Valve Condition	
WO-38900	1	Completed	44267.56092	44438	Repair water main. 6". Good correlation from hydrant to valve near 5th ave. DIG WERE WATER IS SURFACING. NO PARKING NEEDS POSTED. 1 call valid 3/17/21. See pictures below		V-125NV033	Valve Condition	Good
WO-49839	1	Completed	44370.58311	44372	Valve Maintenance Report	June 25, 2021, 8:11 AM	V-125PV001	Valve Condition	
WO-50144	1	Completed	44372.56291	44375	Valve Maintenance Report	June 28, 2021, 7:30 AM	V-125PV004	Valve Condition	
WO-50144	1	Completed	44372.56291	44375	Valve Maintenance Report	June 28, 2021, 7:30 AM	V-125PV005	Valve Condition	
WO-50144	1	Completed	44372.56291	44375	Valve Maintenance Report	June 28, 2021, 7:30 AM	V-125PV006	Valve Condition	
WO-48643	1	Completed	44362.3798	44439	Repair water main		V-125PV007	Valve Condition	
WO-50144	1	Completed	44372.56291	44375	Valve Maintenance Report	June 28, 2021, 7:30 AM	V-125PV008	Valve Condition	
WO-50144	1	Completed	44372.56291	44375	Valve Maintenance Report	June 28, 2021, 7:30 AM	V-125PV009	Valve Condition	
WO-50144	1	Completed	44372.56291	44375	Valve Maintenance Report	June 28, 2021, 7:30 AM	V-125PV011	Valve Condition	
WO-50144	1	Completed	44372.56291	44375	Valve Maintenance Report	June 28, 2021, 7:30 AM	V-125PV012	Valve Condition	
WO-50144	1	Completed	44372.56291	44375	Valve Maintenance Report	June 28, 2021, 7:30 AM	V-125PV013	Valve Condition	
WO-61181	1	Completed	44489.38861	44489	Repair water main		V-125PV014	Valve Condition	
WO-50144	1	Completed	44372.56291	44375	Valve Maintenance Report	June 28, 2021, 7:30 AM	V-125PV018	Valve Condition	
WO-61181	1	Completed	44489.38861	44489	Repair water main		V-125PV019	Valve Condition	
WO-61181	1	Completed	44489.38861	44489	Repair water main		V-125PV020	Valve Condition	
WO-62705	41	Completed	44504.46007	44504	ZOTTOLA PULL A LINE REQUESTING A SHUT	November 4, 2021, 3:04 PM	V-125PV024	Valve Condition	
WO-49839	1	Completed	44370.58311	44372	Valve Maintenance Report	June 25, 2021, 8:11 AM	V-125RV001	Valve Condition	
WO-49839	1	Completed	44370.58311	44372	Valve Maintenance Report	June 25, 2021, 8:11 AM	V-125RV002	Valve Condition	
WO-49839	1	Completed	44370.58311	44372	Valve Maintenance Report	June 25, 2021, 8:11 AM	V-125RV003	Valve Condition	
WO-49839	1	Completed	44370.58311	44372	Valve Maintenance Report	June 25, 2021, 8:11 AM	V-125RV009	Valve Condition	
WO-48643	1	Completed	44362.3798	44439	Repair water main		V-125RV010	Valve Condition	
WO-49839	1	Completed	44370.58311	44372	Valve Maintenance Report	June 25, 2021, 8:11 AM	V-125RV011	Valve Condition	
WO-49839	1	Completed	44370.58311	44372	Valve Maintenance Report	June 25, 2021, 8:11 AM	V-125RV012	Valve Condition	
WO-59275	1	Completed	44470.54862	44470	Valve Maintenance Report	October 1, 2021, 1:23 PM	V-125RV013	Valve Condition	
WO-59276	1	Completed	44470.55006	44470	Valve Maintenance Report	October 1, 2021, 1:22 PM	V-125RV014	Valve Condition	
WO-49839	1	Completed	44370.58311	44372	Valve Maintenance Report	June 25, 2021, 8:11 AM	V-125RV015	Valve Condition	
WO-49839	1	Completed	44370.58311	44372	Valve Maintenance Report	June 25, 2021, 8:11 AM	V-125RV016	Valve Condition	
WO-49839	1	Completed	44370.58311	44372	Valve Maintenance Report	June 25, 2021, 8:11 AM	V-125RV017	Valve Condition	
WO-59270	1	Completed	44470.54517	44470	Valve Maintenance Report	October 1, 2021, 1:25 PM	V-125RV018	Valve Condition	
WO-59273	1	Completed	44470.54702	44470	Valve Maintenance Report	October 1, 2021, 1:24 PM	V-125RV019	Valve Condition	
WO-50144	1	Completed	44372.56291	44375	Valve Maintenance Report	June 28, 2021, 7:30 AM	V-125RV020	Valve Condition	
WO-50144	1	Completed	44372.56291	44375	Valve Maintenance Report	June 28, 2021, 7:30 AM	V-125RV021	Valve Condition	
WO-61181	1	Completed	44489.38861	44489	Repair water main		V-125RV022	Valve Condition	
WO-62705	41	Completed	44504.46007	44504	ZOTTOLA PULL A LINE REQUESTING A SHUT	November 4, 2021, 3:04 PM	V-125RV024	Valve Condition	
WO-62705	41	Completed	44504.46007	44504	ZOTTOLA PULL A LINE REQUESTING A SHUT	November 4, 2021, 3:04 PM	V-125RV025	Valve Condition	
WO-59281	1	Completed	44470.5717	44470	Valve Maintenance Report	October 1, 2021, 1:47 PM	V-125SV008	Valve Condition	
WO-59284	1	Completed	44470.58247	44470	Valve Maintenance Report	October 1, 2021, 2:29 PM	V-125SV026	Valve Condition	
WO-65257	1	Completed	44537.44864	44537	Valve Maintenance Report	December 7, 2021, 10:48 AM	V-126AV002	Valve Condition	
WO-65249	1	Completed	44537.43947	44537	Valve Maintenance Report	December 7, 2021, 10:36 AM	V-126AV003	Valve Condition	
WO-65122	1	Completed	44536.39174	44536	Valve Maintenance Report	December 6, 2021, 9:54 AM	V-126AV005	Valve Condition	
WO-65124	1	Completed	44536.39338	44536	Valve Maintenance Report	December 6, 2021, 9:55 AM	V-126AV006	Valve Condition	Good
WO-65125	1	Completed	44536.39498	44536	Valve Maintenance Report	December 6, 2021, 9:53 AM	V-126AV007	Valve Condition	
WO-64881	1	Completed	44532.59445	44532	Valve Maintenance Report	December 2, 2021, 2:32 PM	V-126AV009	Valve Condition	
WO-64880	1	Completed	44532.59291	44532	Valve Maintenance Report	December 2, 2021, 2:27 PM	V-126AV010	Valve Condition	
WO-64882	1	Completed	44532.59592	44532	Valve Maintenance Report	December 2, 2021, 2:26 PM	V-126AV011	Valve Condition	
WO-64872	1	Completed	44532.56875	44532	Valve Maintenance Report	December 2, 2021, 2:03 PM	V-126AV013	Valve Condition	
WO-64870	1	Completed	44532.56562	44532	Valve Maintenance Report	December 2, 2021, 2:04 PM	V-126AV014	Valve Condition	
WO-64862	1	Completed	44532.53398	44532	Valve Maintenance Report	December 2, 2021, 12:58 PM	V-126AV015	Valve Condition	
WO-64863	1	Completed	44532.53577	44532	Valve Maintenance Report	December 2, 2021, 12:56 PM	V-126AV016	Valve Condition	
WO-38743	1	Completed	44266.40695	44270	Valve Maintenance Report	March 15, 2021, 8:56 AM	V-126AV018	Valve Condition	
WO-62322	1	Completed	44502.44226	44501	Valve Maintenance Report		V-126AV021	Valve Condition	
WO-64346	1	Completed	44524.38313	44524	Valve Maintenance Report	November 24, 2021, 9:14 AM	V-126AV023	Valve Condition	
WO-62269	1	Completed	44502.34655	44502	Valve Maintenance Report	November 2, 2021, 8:22 AM	V-126AV024	Valve Condition	Fair
WO-34067	1	Completed	44216.62913	44223	Repair water main	February 1, 2021, 9:59 AM	V-126AV026	Valve Condition	
WO-34226	1	Completed	44218.28771	44438	Repair water main		V-126BV012	Valve Condition	
WO-34226	1	Completed	44218.28771	44438	Repair water main		V-126BV013	Valve Condition	
WO-38743	1	Completed	44266.40695	44270	Valve Maintenance Report	March 15, 2021, 8:56 AM	V-126BV014	Valve Condition	
WO-44771	1	Completed	44330.30431	44333	Repair water main		V-126BV015	Valve Condition	
WO-58971	1	Completed	44468.35203	44469	Repair water main		V-126BV026	Valve Condition	
WO-59264	1	Completed	44470.5124	44470	Valve Maintenance Report	October 1, 2021, 12:44 PM	V-126CV008	Valve Condition	
WO-59257	1	Completed	44470.46176	44470	Valve Maintenance Report	October 1, 2021, 11:13 AM	V-126CV009	Valve Condition	
WO-59256	1	Completed	44470.46015	44470	Valve Maintenance Report	October 1, 2021, 11:14 AM	V-126CV010	Valve Condition	
WO-59265	1	Completed	44470.51386	44470	Valve Maintenance Report	October 1, 2021, 12:43 PM	V-126CV011	Valve Condition	
WO-59258	1	Completed	44470.46309	44470	Valve Maintenance Report	October 1, 2021, 11:12 AM	V-126CV013	Valve Condition	
WO-64842	1	Completed	44532.43828	44533	Valve Maintenance Report	December 3, 2021, 1:39 PM	V-126CV020	Valve Condition	
WO-59254	1	Completed	44470.45874	44470	Valve Maintenance Report	October 1, 2021, 11:16 AM	V-126CV030	Valve Condition	
WO-59222	1	Completed	44470.37919	44470	Valve Maintenance Report	October 1, 2021, 9:09 AM	V-126DV001	Valve Condition	
WO-59220	1	Completed	44470.37421	44470	Valve Maintenance Report	October 1, 2021, 9:10 AM	V-126DV002	Valve Condition	
WO-59237	1	Completed	44470.42477	44470	Valve Maintenance Report	October 1, 2021, 10:22 AM	V-126DV004	Valve Condition	
WO-59240	1	Completed	44470.42872	44470	Valve Maintenance Report	October 1, 2021, 10:20 AM	V-126DV005	Valve Condition	
WO-59238	1	Completed	44470.42673	44470	Valve Maintenance Report	October 1, 2021, 10:21 AM	V-126DV006	Valve Condition	
WO-59235	1	Completed	44470.42205	44470	Valve Maintenance Report	October 1, 2021, 10:23 AM	V-126DV007	Valve Condition	
WO-59247	1	Completed	44470.44188	44470	Valve Maintenance Report	October 1, 2021, 10:40 AM	V-126DV010	Valve Condition	
WO-62322	1	Completed	44502.44226	44501	Valve Maintenance Report		V-126EV002	Valve Condition	
WO-64354	1	Completed	44524.393	44524	Valve Maintenance Report	November 24, 2021, 9:28 AM	V-126EV003	Valve Condition	
WO-34226	1	Completed	44218.28771	44438	Repair water main		V-126EV011	Valve Condition	
WO-34226	1	Completed	44218.28771	44438	Repair water main		V-126EV012	Valve Condition	
WO-38599	21	Completed	44264.62958	44265	Valve is inoperable and requires replacement	March 10, 2021, 1:22 PM	V-126EV013	Valve Condition	
WO-34226	1	Completed	44218.28771	44438	Repair water main		V-126EV016	Valve Condition	
WO-34225	85	Completed	44218.28771	44218	Repair water main	January 22, 2021, 2:27 PM	V-126EV017	Valve Condition	
WO-64750	1	Completed	44531.52891	44531	Valve Maintenance Report	December 1, 2021, 12:51 PM	V-126EV021	Valve Condition	
WO-34225	85	Completed	44218.28771	44218	Repair water main	January 22, 2021, 2:27 PM	V-126EV022	Valve Condition	
WO-64752	1	Completed	44531.54297	44531	Valve Maintenance Report	December 1, 2021, 1:12 PM	V-126EV030	Valve Condition	
WO-64763	1	Completed	44531.59189	44531	Valve Maintenance Report	December 1, 2021, 2:30 PM	V-126FV003	Valve Condition	
WO-64765	1	Completed	44531.5947	44531	Valve Maintenance Report	December 1, 2021, 2:25 PM	V-126FV004	Valve Condition	
WO-64764	1	Completed	44531.59329	44531	Valve Maintenance Report	December 1, 2021, 2:26 PM	V-126FV005	Valve Condition	
WO-32784	1	Completed	44203.60726	44436	Repair water main		V-126FV009	Valve Condition	
WO-60811	1	Completed	44484.56425	44484	Valve Maintenance Report	October 15, 2021, 1:44 PM	V-126FV020	Valve Condition	
WO-32784	1	Completed	44203.60726	44436	Repair water main		V-126FV023	Valve Condition	
WO-60508	1	Completed	44482.45492	44482	Valve Maintenance Report	October 13, 2021, 11:02 AM	V-126FV024	Valve Condition	
WO-60797	1	Completed	44484.53412	44484	Valve Maintenance Report	October 15, 2021, 1:17 PM	V-126GV002	Valve Condition	
WO-60798	1	Completed	44484.53652	44484	Valve Maintenance Report	October 15, 2021, 1:16 PM	V-126GV003	Valve Condition	
WO-60554	1	Completed	44482.58366	44482	Valve Maintenance Report	October 13, 2021, 2:15 PM	V-126GV006	Valve Condition	
WO-60553	1	Completed	44482.58171	44482	Valve Maintenance Report	October 13, 2021, 2:16 PM	V-126GV007	Valve Condition	
WO-64825	1	Completed	44532.39901	44533	Repair water main		V-126GV008	Valve Condition	
WO-37642	1	Completed	44253.54744	44438	Repair water main		V-126GV009	Valve Condition	
WO-60085	1	Completed	44477.52963	44477	Valve Maintenance Report	October 8, 2021, 12:44 PM	V-126GV014	Valve Condition	
WO-60516	1	Completed	44482.47064	44482	Valve Maintenance Report	October 13, 2021, 11:24 AM	V-126GV017	Valve Condition	
WO-60518	1	Completed	44482.47211	44482	Valve Maintenance Report	October 13, 2021, 11:22 AM	V-126GV018	Valve Condition	
WO-64825	1	Completed	44532.39901	44533	Repair water main		V-126GV019	Valve Condition	
WO-60070	1	Completed	44477.46958	44477	Valve Maintenance Report	October 8, 2021, 11:29 AM	V-126GV023	Valve Condition	
WO-35652	1	Completed	44231.41781	44231	Valve Maintenance Report	February 4, 2021, 2:34 PM	V-126GV024	Valve Condition	
WO-60072	1	Completed	44477.47268	44477	Valve Maintenance Report	October 8, 2021, 11:27 AM	V-126GV025	Valve Condition	
WO-35652	1	Completed	44231.41781	44231	Valve Maintenance Report	February 4, 2021, 2:34 PM	V-126GV026	Valve Condition	
WO-60086	1	Completed	44477.53523	44477	Valve Maintenance Report	October 8, 2021, 12:57 PM	V-126GV027	Valve Condition	
WO-60087	1	Completed	44477.53733	44477	Valve Maintenance Report	October 8, 2021, 12:56 PM	V-126GV028	Valve Condition	
WO-60509	1	Completed	44482.4567	44482	Valve Maintenance Report	October 13, 2021, 11:00 AM	V-126GV029	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-60048	1	Completed	44477.38642	44477	Valve Maintenance Report	October 8, 2021, 9:19 AM	V-126GV030	Valve Condition	Fair
WO-60047	1	Completed	44477.38485	44477	Valve Maintenance Report	October 8, 2021, 9:20 AM	V-126GV031	Valve Condition	
WO-35652	1	Completed	44231.41781	44231	Valve Maintenance Report	February 4, 2021, 2:34 PM	V-126GV032	Valve Condition	
WO-59941	1	Completed	44476.54893	44476	Valve Maintenance Report	October 7, 2021, 1:26 PM	V-126GV033	Valve Condition	Good
WO-59939	1	Completed	44476.54667	44476	Valve Maintenance Report	October 7, 2021, 1:27 PM	V-126GV034	Valve Condition	
WO-59936	1	Completed	44476.54499	44476	Valve Maintenance Report	October 7, 2021, 1:29 PM	V-126GV035	Valve Condition	
WO-60800	1	Completed	44484.54148	44484	Valve Maintenance Report	October 15, 2021, 1:15 PM	V-126GV038	Valve Condition	
WO-59172	1	Completed	44469.57396	44469	Valve Maintenance Report	September 30, 2021, 2:03 PM	V-126HV004	Valve Condition	
WO-59173	1	Completed	44469.57634	44469	Valve Maintenance Report	September 30, 2021, 2:01 PM	V-126HV006	Valve Condition	
WO-59928	1	Completed	44476.50495	44476	Valve Maintenance Report	October 7, 2021, 12:28 PM	V-126HV009	Valve Condition	
WO-59111	1	Completed	44469.4005	44469	Valve Maintenance Report	September 30, 2021, 9:44 AM	V-126HV021	Valve Condition	
WO-59112	1	Completed	44469.4022	44469	Valve Maintenance Report	September 30, 2021, 9:43 AM	V-126HV023	Valve Condition	
WO-59747	1	Completed	44475.45631	44475	Valve Maintenance Report	October 6, 2021, 11:06 AM	V-126HV026	Valve Condition	
WO-59750	1	Completed	44475.45982	44475	Valve Maintenance Report	October 6, 2021, 11:04 AM	V-126HV033	Valve Condition	
WO-59748	1	Completed	44475.45816	44475	Valve Maintenance Report	October 6, 2021, 11:05 AM	V-126HV034	Valve Condition	
WO-64565	1	Completed	44529.58214	44529	Valve Maintenance Report	November 29, 2021, 2:28 PM	V-126JV002	Valve Condition	
WO-64569	1	Completed	44529.5861	44529	Valve Maintenance Report	November 29, 2021, 2:19 PM	V-126JV003	Valve Condition	Poor
WO-64658	1	Completed	44530.56293	44530	Valve Maintenance Report	November 30, 2021, 1:52 PM	V-126JV004	Valve Condition	
WO-64567	1	Completed	44529.5842	44529	Valve Maintenance Report	November 29, 2021, 2:21 PM	V-126JV005	Valve Condition	Good
WO-64659	1	Completed	44530.56464	44530	Valve Maintenance Report	November 30, 2021, 1:50 PM	V-126JV006	Valve Condition	
WO-50999	84	Completed	44382.35949	44411	Main or service line leak investigation/survey/CHECK FOR A LEAK CALLER CAN HEAR WATER FLOWING AT BOTTOM OF YARD NEAR GARAGE DOWN PUBLIC STEPS CAN HEAR WATER AT BOTTOM OF STEPS LEFT HAND SIDE THERE WAS A SMELL OF GAS AS WELL CALLER HAD GAS CO COME AND LOOK STATES IT IS NO GAS ISSUE PROBABLY BUSTED PIPE NO VISUAL WATER CALLER HAS WATER AND PRESSURE IS FINE NO DAMAGE		V-126JV013	Valve Condition	
WO-63984	1	Completed	44519.58517	44519	Valve Maintenance Report	November 19, 2021, 2:20 PM	V-126JV017	Valve Condition	
WO-63985	1	Completed	44519.58662	44519	Valve Maintenance Report	November 19, 2021, 2:23 PM	V-126JV018	Valve Condition	
WO-63867	1	Completed	44518.56459	44518	Valve Maintenance Report	November 18, 2021, 1:40 PM	V-126JV020	Valve Condition	
WO-63871	1	Completed	44518.57196	44518	Valve Maintenance Report	November 18, 2021, 2:39 PM	V-126JV021	Valve Condition	
WO-63868	1	Completed	44518.56549	44518	Valve Maintenance Report	November 18, 2021, 2:01 PM	V-126JV022	Valve Condition	Good
WO-64110	1	Completed	44522.46999	44522	Valve Maintenance Report	November 22, 2021, 11:21 AM	V-126KV001	Valve Condition	
WO-64108	1	Completed	44522.46815	44522	Valve Maintenance Report	November 22, 2021, 11:23 AM	V-126KV002	Valve Condition	
WO-60819	1	Completed	44484.58154	44484	Valve Maintenance Report	October 15, 2021, 2:10 PM	V-126KV010	Valve Condition	
WO-60820	1	Completed	44484.58234	44484	Valve Maintenance Report	October 15, 2021, 2:12 PM	V-126KV011	Valve Condition	
WO-64101	1	Completed	44522.4575	44522	Valve Maintenance Report	November 22, 2021, 11:01 AM	V-126KV016	Valve Condition	
WO-64107	1	Completed	44522.46591	44522	Valve Maintenance Report	November 22, 2021, 11:25 AM	V-126KV018	Valve Condition	
WO-64145	1	Completed	44522.58982	44522	Valve Maintenance Report	November 22, 2021, 2:12 PM	V-126KV022	Valve Condition	
WO-64151	1	Completed	44522.6008	44522	Valve Maintenance Report	November 22, 2021, 2:30 PM	V-126KV023	Valve Condition	
WO-63797	1	Completed	44517.58765	44517	Valve Maintenance Report	November 17, 2021, 2:13 PM	V-126KV031	Valve Condition	
WO-63796	1	Completed	44517.58476	44517	Valve Maintenance Report	November 17, 2021, 2:14 PM	V-126KV037	Valve Condition	
WO-60097	1	Completed	44477.60233	44477	Valve Maintenance Report	October 8, 2021, 2:31 PM	V-126LV001	Valve Condition	
WO-60094	1	Completed	44477.56423	44477	Valve Maintenance Report	October 8, 2021, 1:36 PM	V-126LV002	Valve Condition	
WO-60092	1	Completed	44477.56251	44477	Valve Maintenance Report	October 8, 2021, 1:39 PM	V-126LV003	Valve Condition	
WO-60090	1	Completed	44477.55856	44477	Valve Maintenance Report	October 8, 2021, 1:40 PM	V-126LV005	Valve Condition	
WO-60091	1	Completed	44477.56068	44477	Valve Maintenance Report	October 8, 2021, 2:14 PM	V-126LV006	Valve Condition	Good
WO-64267	1	Completed	44523.53276	44523	Valve Maintenance Report	November 23, 2021, 1:15 PM	V-126LV007	Valve Condition	
WO-64270	1	Completed	44523.53661	44523	Valve Maintenance Report	November 23, 2021, 12:54 PM	V-126LV009	Valve Condition	
WO-64268	1	Completed	44523.53428	44523	Valve Maintenance Report	November 23, 2021, 1:14 PM	V-126LV010	Valve Condition	
WO-64265	1	Completed	44523.53258	44523	Valve Maintenance Report	November 23, 2021, 12:51 PM	V-126LV011	Valve Condition	
WO-60045	1	Completed	44477.37087	44477	Valve Maintenance Report	October 8, 2021, 9:01 AM	V-126LV012	Valve Condition	
WO-60043	1	Completed	44477.3671	44477	Valve Maintenance Report	October 8, 2021, 9:04 AM	V-126LV013	Valve Condition	
WO-60038	1	Completed	44477.35739	44477	Valve Maintenance Report	October 8, 2021, 9:06 AM	V-126LV014	Valve Condition	
WO-60044	1	Completed	44477.36884	44477	Valve Maintenance Report	October 8, 2021, 9:03 AM	V-126LV015	Valve Condition	
WO-60039	1	Completed	44477.35887	44477	Valve Maintenance Report	October 8, 2021, 9:07 AM	V-126LV016	Valve Condition	
WO-59953	1	Completed	44476.58923	44476	Valve Maintenance Report	October 7, 2021, 2:24 PM	V-126LV017	Valve Condition	
WO-59954	1	Completed	44476.59101	44476	Valve Maintenance Report	October 7, 2021, 2:22 PM	V-126LV018	Valve Condition	
WO-59952	1	Completed	44476.58774	44476	Valve Maintenance Report	October 7, 2021, 2:25 PM	V-126LV019	Valve Condition	
WO-64150	1	Completed	44522.59904	44522	Valve Maintenance Report	November 22, 2021, 2:33 PM	V-126LV020	Valve Condition	
WO-64155	1	Completed	44522.60219	44522	Valve Maintenance Report	November 22, 2021, 2:29 PM	V-126LV021	Valve Condition	
WO-64216	1	Completed	44523.37313	44523	Valve Maintenance Report	November 23, 2021, 9:00 AM	V-126LV022	Valve Condition	
WO-64213	1	Completed	44523.36783	44523	Valve Maintenance Report	November 23, 2021, 8:52 AM	V-126LV023	Valve Condition	
WO-64215	1	Completed	44523.37064	44523	Valve Maintenance Report	November 23, 2021, 8:56 AM	V-126LV024	Valve Condition	
WO-64238	1	Completed	44523.42767	44523	Valve Maintenance Report	November 23, 2021, 11:01 AM	V-126LV025	Valve Condition	
WO-64237	1	Completed	44523.42556	44523	Valve Maintenance Report	November 23, 2021, 11:00 AM	V-126LV026	Valve Condition	
WO-64245	1	Completed	44523.43296	44523	Valve Maintenance Report	November 23, 2021, 11:03 AM	V-126LV027	Valve Condition	
WO-64248	1	Completed	44523.43774	44523	Valve Maintenance Report	November 23, 2021, 12:19 PM	V-126LV029	Valve Condition	
WO-64243	1	Completed	44523.43174	44523	Valve Maintenance Report	November 23, 2021, 10:24 AM	V-126LV030	Valve Condition	
WO-59933	1	Completed	44476.52466	44476	Valve Maintenance Report	October 7, 2021, 12:53 PM	V-126LV032	Valve Condition	
WO-59932	1	Completed	44476.5221	44476	Valve Maintenance Report	October 7, 2021, 12:54 PM	V-126LV034	Valve Condition	
WO-59931	1	Completed	44476.5185	44476	Valve Maintenance Report	October 7, 2021, 12:54 PM	V-126LV035	Valve Condition	
WO-59739	1	Completed	44475.43718	44475	Valve Maintenance Report	October 6, 2021, 10:42 AM	V-126MV001	Valve Condition	
WO-59734	1	Completed	44475.43388	44475	Valve Maintenance Report	October 6, 2021, 10:43 AM	V-126MV002	Valve Condition	
WO-59737	1	Completed	44475.43579	44475	Valve Maintenance Report	October 6, 2021, 10:42 AM	V-126MV003	Valve Condition	
WO-59679	1	Completed	44475.36917	44475	Valve Maintenance Report	October 6, 2021, 8:53 AM	V-126MV006	Valve Condition	
WO-59688	1	Completed	44475.37504	44475	Valve Maintenance Report	October 6, 2021, 9:02 AM	V-126MV008	Valve Condition	
WO-59714	1	Completed	44475.41848	44475	Valve Maintenance Report	October 6, 2021, 10:09 AM	V-126MV009	Valve Condition	
WO-59696	1	Completed	44475.38826	44475	Valve Maintenance Report	October 6, 2021, 9:20 AM	V-126MV011	Valve Condition	
WO-59693	1	Completed	44475.38511	44475	Valve Maintenance Report	October 6, 2021, 9:17 AM	V-126MV013	Valve Condition	
WO-59703	1	Completed	44475.40293	44475	Valve Maintenance Report	October 6, 2021, 9:42 AM	V-126MV015	Valve Condition	
WO-59699	1	Completed	44475.39952	44475	Valve Maintenance Report	October 6, 2021, 9:44 AM	V-126MV017	Valve Condition	
WO-42903	88	Completed	44313.53646	44319	Non-Metered City of Pittsburgh Properties. Install a new crock and 1" meter at this location curb box is 45' left of S. Lexington Ave. and 16' inside the curb line on Reynolds St.	May 3, 2021, 6:41 PM	V-126MV019	Valve Condition	
WO-42903	88	Completed	44313.53646	44319	Non-Metered City of Pittsburgh Properties. Install a new crock and 1" meter at this location curb box is 45' left of S. Lexington Ave. and 16' inside the curb line on Reynolds St.	May 3, 2021, 6:41 PM	V-126MV020	Valve Condition	
WO-63793	1	Completed	44517.57025	44517	Valve Maintenance Report	November 17, 2021, 1:48 PM	V-126NV004	Valve Condition	
WO-63781	1	Completed	44517.53788	44517	Valve Maintenance Report	November 17, 2021, 1:08 PM	V-126NV006	Valve Condition	
WO-63778	1	Completed	44517.5317	44517	Valve Maintenance Report	November 17, 2021, 12:49 PM	V-126NV008	Valve Condition	
WO-63776	1	Completed	44517.5297	44517	Valve Maintenance Report	November 17, 2021, 12:53 PM	V-126NV009	Valve Condition	
WO-63768	1	Completed	44517.51675	44517	Valve Maintenance Report	November 17, 2021, 12:32 PM	V-126NV013	Valve Condition	
WO-63770	1	Completed	44517.51855	44517	Valve Maintenance Report	November 17, 2021, 12:30 PM	V-126NV016	Valve Condition	
WO-64097	1	Completed	44522.44178	44522	Valve Maintenance Report	November 22, 2021, 10:39 AM	V-126NV017	Valve Condition	
WO-64095	1	Completed	44522.44045	44522	Valve Maintenance Report	November 22, 2021, 10:40 AM	V-126NV020	Valve Condition	
WO-39915	1	Completed	44280.32894	44438	Repair water main		V-126NV025	Valve Condition	
WO-63710	1	Completed	44517.40071	44517	Valve Maintenance Report	November 17, 2021, 9:42 AM	V-126NV028	Valve Condition	
WO-63714	1	Completed	44517.4024	44517	Valve Maintenance Report	November 17, 2021, 9:41 AM	V-126NV029	Valve Condition	
WO-60176	1	Completed	44480.39188	44484	Valve Maintenance Report	October 15, 2021, 2:48 PM	V-126RV001	Valve Condition	
WO-60176	1	Completed	44480.39188	44484	Valve Maintenance Report	October 15, 2021, 2:48 PM	V-126RV002	Valve Condition	
WO-60176	1	Completed	44480.39188	44484	Valve Maintenance Report	October 15, 2021, 2:48 PM	V-126RV003	Valve Condition	
WO-60176	1	Completed	44480.39188	44484	Valve Maintenance Report	October 15, 2021, 2:48 PM	V-126RV004	Valve Condition	
WO-60176	1	Completed	44480.39188	44484	Valve Maintenance Report	October 15, 2021, 2:48 PM	V-126RV005	Valve Condition	
WO-60176	1	Completed	44480.39188	44484	Valve Maintenance Report	October 15, 2021, 2:48 PM	V-126RV006	Valve Condition	
WO-60176	1	Completed	44480.39188	44484	Valve Maintenance Report	October 15, 2021, 2:48 PM	V-126RV008	Valve Condition	
WO-60176	1	Completed	44480.39188	44484	Valve Maintenance Report	October 15, 2021, 2:48 PM	V-126RV036	Valve Condition	
WO-42903	88	Completed	44313.53646	44319	Non-Metered City of Pittsburgh Properties. Install a new crock and 1" meter at this location curb box is 45' left of S. Lexington Ave. and 16' inside the curb line on Reynolds St.	May 3, 2021, 6:41 PM	V-126SV002	Valve Condition	
WO-58612	1	Completed	44463.59666	44463	Valve Maintenance Report	September 24, 2021, 2:21 PM	V-126SV003	Valve Condition	
WO-63742	1	Completed	44517.45478	44517	Valve Maintenance Report	November 17, 2021, 11:05 AM	V-127AV001	Valve Condition	
WO-63743	1	Completed	44517.45697	44517	Valve Maintenance Report	November 17, 2021, 11:04 AM	V-127AV002	Valve Condition	
WO-63744	1	Completed	44517.4586	44517	Valve Maintenance Report	November 17, 2021, 11:02 AM	V-127AV003	Valve Condition	
WO-63788	1	Completed	44517.5487	44517	Valve Maintenance Report	November 17, 2021, 1:11 PM	V-127AV006	Valve Condition	
WO-63733	1	Completed	44517.43604	44517	Valve Maintenance Report	November 17, 2021, 10:31 AM	V-127AV008	Valve Condition	
WO-63727	1	Completed	44517.43056	44517	Valve Maintenance Report	November 17, 2021, 10:22 AM	V-127AV010	Valve Condition	
WO-63732	1	Completed	44517.43395	44517	Valve Maintenance Report	November 17, 2021, 10:32 AM	V-127AV011	Valve Condition	
WO-63838	1	Completed	44518.45911	44518	Valve Maintenance Report	November 18, 2021, 11:07 AM	V-127AV015	Valve Condition	
WO-63844	1	Completed	44518.47202	44518	Valve Maintenance Report	November 18, 2021, 11:49 AM	V-127AV016	Valve Condition	
WO-63837	1	Completed	44518.45542	44518	Valve Maintenance Report	November 18, 2021, 11:04 AM	V-127AV017	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-63840	1	Completed	44518.46324	44518	Valve Maintenance Report	November 18, 2021, 11:17 AM	V-127AV018	Valve Condition	
WO-63850	1	Completed	44518.48581	44518	Valve Maintenance Report	November 18, 2021, 11:45 AM	V-127AV022	Valve Condition	
WO-63832	1	Completed	44518.42486	44518	Valve Maintenance Report	November 18, 2021, 10:26 AM	V-127AV024	Valve Condition	
WO-63851	1	Completed	44518.48781	44518	Valve Maintenance Report	November 18, 2021, 11:44 AM	V-127AV027	Valve Condition	
WO-63833	1	Completed	44518.4294	44518	Valve Maintenance Report	November 18, 2021, 10:21 AM	V-127AV029	Valve Condition	
WO-39915	1	Completed	44280.32894	44438	Repair water main		V-127AV033	Valve Condition	
WO-63857	1	Completed	44518.54045	44518	Valve Maintenance Report	November 18, 2021, 1:05 PM	V-127AV039	Valve Condition	
WO-63859	1	Completed	44518.54335	44518	Valve Maintenance Report	November 18, 2021, 1:07 PM	V-127AV040	Valve Condition	
WO-42475	1	Completed	44308.51843	44308	Valve Maintenance Report	April 22, 2021, 12:34 PM	V-127JV006	Valve Condition	Good
WO-42475	1	Completed	44308.51843	44308	Valve Maintenance Report	April 22, 2021, 12:34 PM	V-127JV008	Valve Condition	Good
WO-42475	1	Completed	44308.51843	44308	Valve Maintenance Report	April 22, 2021, 12:34 PM	V-127JV013	Valve Condition	Good
WO-42475	1	Completed	44308.51843	44308	Valve Maintenance Report	April 22, 2021, 12:34 PM	V-127JV014	Valve Condition	Good
WO-45243	1	Completed	44334.43161	44337	Valve Maintenance Report	May 21, 2021, 8:27 AM	V-127JV016	Valve Condition	Fair
WO-45243	1	Completed	44334.43161	44337	Valve Maintenance Report	May 21, 2021, 8:27 AM	V-127JV021	Valve Condition	Fair
WO-55840	1	Completed	44435.32792	44434	Valve Maintenance Report		V-127NV020	Valve Condition	
WO-55840	1	Completed	44435.32792	44434	Valve Maintenance Report		V-127NV022	Valve Condition	
WO-45243	1	Completed	44334.43161	44337	Valve Maintenance Report	May 21, 2021, 8:27 AM	V-127PV004	Valve Condition	Fair
WO-34396	1	Completed	44220.66318	44221	Repair water main	January 24, 2021, 4:03 PM	V-128AV010	Valve Condition	
WO-41579	1	Completed	44300.37895	44306	Valve Maintenance Report	April 20, 2021, 8:44 AM	V-128JV022	Valve Condition	
WO-41579	1	Completed	44300.37895	44306	Valve Maintenance Report	April 20, 2021, 8:44 AM	V-128JV027	Valve Condition	
WO-33237	1	Completed	44208.61446	44208	Valve Maintenance Report	January 12, 2021, 2:48 PM	V-128NV012	Valve Condition	
WO-33238	1	Completed	44208.62008	44208	Valve Maintenance Report	January 12, 2021, 2:56 PM	V-128NV013	Valve Condition	
WO-43785	1	Completed	44321.54348	44321	Valve Maintenance Report	May 5, 2021, 1:09 PM	V-128SV001	Valve Condition	
WO-43786	1	Completed	44321.54468	44321	Valve Maintenance Report	May 5, 2021, 1:07 PM	V-128SV002	Valve Condition	
WO-43794	1	Completed	44321.56257	44321	Valve Maintenance Report	May 5, 2021, 1:40 PM	V-128SV004	Valve Condition	
WO-43792	1	Completed	44321.56027	44321	Valve Maintenance Report	May 5, 2021, 1:28 PM	V-128SV005	Valve Condition	
WO-43777	1	Completed	44321.52214	44321	Valve Maintenance Report	May 5, 2021, 12:43 PM	V-128SV007	Valve Condition	
WO-43889	1	Completed	44322.37628	44322	Valve Maintenance Report	May 6, 2021, 9:19 AM	V-128SV008	Valve Condition	Good
WO-43891	1	Completed	44322.37743	44322	Valve Maintenance Report	May 6, 2021, 9:20 AM	V-128SV009	Valve Condition	
WO-43892	1	Completed	44322.37839	44322	Valve Maintenance Report	May 6, 2021, 9:23 AM	V-128SV010	Valve Condition	Good
WO-56621	1	Completed	44442.40624	44442	Valve Maintenance Report	September 3, 2021, 9:50 AM	V-128SV013	Valve Condition	
WO-43954	1	Completed	44322.53499	44322	Valve Maintenance Report	May 6, 2021, 1:04 PM	V-128SV015	Valve Condition	
WO-56616	1	Completed	44442.39267	44442	Valve Maintenance Report	September 3, 2021, 9:49 AM	V-128SV021	Valve Condition	
WO-43956	1	Completed	44322.53692	44322	Valve Maintenance Report	May 6, 2021, 1:07 PM	V-128SV022	Valve Condition	
WO-43955	1	Completed	44322.53594	44322	Valve Maintenance Report	May 6, 2021, 1:05 PM	V-128SV024	Valve Condition	
WO-56617	1	Completed	44442.39493	44442	Valve Maintenance Report	September 3, 2021, 9:49 AM	V-128SV025	Valve Condition	
WO-64035	1	Completed	44522.27587	44523	Repair water main		V-129AV001	Valve Condition	
WO-47353	1	Completed	44350.42438	44350	Valve Maintenance Report	June 3, 2021, 10:20 AM	V-129CV001	Valve Condition	
WO-47335	1	Completed	44350.40867	44350	Valve Maintenance Report	June 3, 2021, 9:51 AM	V-129CV005	Valve Condition	Good
WO-47350	1	Completed	44350.42016	44350	Valve Maintenance Report	June 3, 2021, 10:18 AM	V-129CV006	Valve Condition	
WO-47352	1	Completed	44350.42251	44350	Valve Maintenance Report	June 3, 2021, 10:19 AM	V-129CV007	Valve Condition	
WO-64814	1	Completed	44532.30365	44539	Repair water main		V-129DV001	Valve Condition	
WO-64814	1	Completed	44532.30365	44539	Repair water main		V-129DV004	Valve Condition	
WO-65857	1	Completed	44544.41437	44544	Valve Maintenance Report	December 14, 2021, 9:59 AM	V-129DV005	Valve Condition	
WO-47935	1	Completed	44356.47608	44356	Valve Maintenance Report	June 9, 2021, 11:29 AM	V-129DV018	Valve Condition	
WO-47396	1	Completed	44350.58657	44350	Valve Maintenance Report	June 3, 2021, 2:18 PM	V-129DV019	Valve Condition	Good
WO-47937	1	Completed	44356.48207	44356	Valve Maintenance Report	June 9, 2021, 11:36 AM	V-129DV021	Valve Condition	
WO-45492	1	Completed	44336.37124	44336	Valve Maintenance Report	May 20, 2021, 8:57 AM	V-129GV018	Valve Condition	
WO-45390	1	Completed	44335.47838	44335	Valve Maintenance Report	May 19, 2021, 2:41 PM	V-129GV019	Valve Condition	
WO-45390	1	Completed	44335.47838	44335	Valve Maintenance Report	May 19, 2021, 2:41 PM	V-129GV020	Valve Condition	
WO-45390	1	Completed	44335.47838	44335	Valve Maintenance Report	May 19, 2021, 2:41 PM	V-129GV021	Valve Condition	
WO-45390	1	Completed	44335.47838	44335	Valve Maintenance Report	May 19, 2021, 2:41 PM	V-129GV022	Valve Condition	
WO-45499	1	Completed	44336.38074	44336	Valve Maintenance Report	May 20, 2021, 9:10 AM	V-129GV025	Valve Condition	
WO-45593	1	Completed	44336.55335	44336	Valve Maintenance Report	May 20, 2021, 1:19 PM	V-129GV026	Valve Condition	
WO-46610	1	Completed	44344.35891	44344	Valve Maintenance Report	May 28, 2021, 11:20 AM	V-129GV027	Valve Condition	
WO-45528	1	Completed	44336.4247	44336	Valve Maintenance Report	May 20, 2021, 10:14 AM	V-129GV029	Valve Condition	
WO-45538	1	Completed	44336.43837	44336	Valve Maintenance Report	May 20, 2021, 10:35 AM	V-129GV030	Valve Condition	
WO-45573	1	Completed	44336.52415	44336	Valve Maintenance Report	May 20, 2021, 12:38 PM	V-129GV031	Valve Condition	
WO-45579	1	Completed	44336.53396	44336	Valve Maintenance Report	May 20, 2021, 12:53 PM	V-129GV032	Valve Condition	
WO-45525	1	Completed	44336.42159	44336	Valve Maintenance Report	May 20, 2021, 10:10 AM	V-129GV034	Valve Condition	
WO-45577	1	Completed	44336.5296	44336	Valve Maintenance Report	May 20, 2021, 12:45 PM	V-129GV035	Valve Condition	
WO-45601	1	Completed	44336.57564	44336	Valve Maintenance Report	May 20, 2021, 1:52 PM	V-129GV036	Valve Condition	Good
WO-45584	1	Completed	44336.54763	44336	Valve Maintenance Report	May 20, 2021, 1:14 PM	V-129GV037	Valve Condition	
WO-46609	1	Completed	44344.35768	44344	Valve Maintenance Report	May 28, 2021, 11:18 AM	V-129GV038	Valve Condition	
WO-45375	1	Completed	44335.44298	44335	Valve Maintenance Report	May 19, 2021, 11:29 AM	V-129GV039	Valve Condition	
WO-45375	1	Completed	44335.44298	44335	Valve Maintenance Report	May 19, 2021, 11:29 AM	V-129GV040	Valve Condition	
WO-45576	1	Completed	44336.5274	44336	Valve Maintenance Report	May 20, 2021, 12:41 PM	V-129GV041	Valve Condition	
WO-45595	1	Completed	44336.55621	44336	Valve Maintenance Report	May 20, 2021, 1:23 PM	V-129GV042	Valve Condition	
WO-47356	1	Completed	44350.44056	44350	Valve Maintenance Report	June 3, 2021, 10:59 AM	V-129HV001	Valve Condition	Good
WO-47357	1	Completed	44350.44258	44350	Valve Maintenance Report	June 3, 2021, 11:00 AM	V-129HV002	Valve Condition	Good
WO-44173	1	Completed	44326.04413	44326	Valve Maintenance Report	May 10, 2021, 6:21 AM	V-129HV004	Valve Condition	Good
WO-44169	1	Completed	44326.03941	44326	Valve Maintenance Report	May 10, 2021, 1:40 AM	V-129HV005	Valve Condition	
WO-44172	1	Completed	44326.04297	44326	Valve Maintenance Report	May 10, 2021, 6:19 AM	V-129HV006	Valve Condition	
WO-47373	1	Completed	44350.52225	44350	Valve Maintenance Report	June 3, 2021, 12:51 PM	V-129HV007	Valve Condition	Good
WO-47375	1	Completed	44350.526	44350	Valve Maintenance Report	June 3, 2021, 12:53 PM	V-129HV008	Valve Condition	
WO-47374	1	Completed	44350.52403	44350	Valve Maintenance Report	June 3, 2021, 12:53 PM	V-129HV009	Valve Condition	
WO-44713	1	Completed	44329.56565	44329	Valve Maintenance Report	May 13, 2021, 2:12 PM	V-129HV012	Valve Condition	
WO-44707	1	Completed	44329.55954	44329	Valve Maintenance Report	May 13, 2021, 2:02 PM	V-129HV013	Valve Condition	
WO-44709	1	Completed	44329.56232	44329	Valve Maintenance Report	May 13, 2021, 2:03 PM	V-129HV015	Valve Condition	
WO-44712	1	Completed	44329.56423	44329	Valve Maintenance Report	May 13, 2021, 2:12 PM	V-129HV016	Valve Condition	
WO-44313	1	Completed	44327.05936	44327	Valve Maintenance Report	May 11, 2021, 2:04 AM	V-129HV018	Valve Condition	
WO-44314	1	Completed	44327.06199	44327	Valve Maintenance Report	May 11, 2021, 2:04 AM	V-129HV020	Valve Condition	
WO-44315	1	Completed	44327.06521	44327	Valve Maintenance Report	May 11, 2021, 2:04 AM	V-129HV021	Valve Condition	Good
WO-44670	1	Completed	44329.454	44329	Valve Maintenance Report	May 13, 2021, 10:59 AM	V-129HV023	Valve Condition	
WO-44671	1	Completed	44329.45555	44329	Valve Maintenance Report	May 13, 2021, 11:09 AM	V-129HV024	Valve Condition	
WO-44666	1	Completed	44329.45227	44329	Valve Maintenance Report	May 13, 2021, 10:58 AM	V-129HV025	Valve Condition	
WO-47390	1	Completed	44350.5649	44350	Valve Maintenance Report	June 3, 2021, 1:56 PM	V-129HV034	Valve Condition	Good
WO-47388	1	Completed	44350.55999	44350	Valve Maintenance Report	June 3, 2021, 1:54 PM	V-129HV035	Valve Condition	Good
WO-45375	1	Completed	44335.44298	44335	Valve Maintenance Report	May 19, 2021, 11:29 AM	V-129LV001	Valve Condition	
WO-45375	1	Completed	44335.44298	44335	Valve Maintenance Report	May 19, 2021, 11:29 AM	V-129LV002	Valve Condition	
WO-45375	1	Completed	44335.44298	44335	Valve Maintenance Report	May 19, 2021, 11:29 AM	V-129LV003	Valve Condition	
WO-38157	43	Completed	44259.44961	44259	Test shut	March 4, 2021, 11:01 AM	V-129NV001	Valve Condition	Good
WO-59959	1	Completed	44476.62104	44476	Valve Maintenance Report		V-1350	Valve Condition	
WO-65603	1	Completed	44540.45712	44538	Valve Maintenance Report		V-162PV002	Valve Condition	
WO-65603	1	Completed	44540.45712	44538	Valve Maintenance Report		V-162PV006	Valve Condition	
WO-65603	1	Completed	44540.45712	44538	Valve Maintenance Report		V-162PV007	Valve Condition	
WO-65603	1	Completed	44540.45712	44538	Valve Maintenance Report		V-162PV008	Valve Condition	
WO-63530	1	Completed	44515.44269	44515	Valve Maintenance Report	November 15, 2021, 10:38 AM	V-162PV013	Valve Condition	
WO-34035	85	Completed	44216.47807	44217	Repair water main	January 21, 2021, 11:26 AM	V-162SV022	Valve Condition	
WO-66093	85	Completed	44546.43341	44557	Repair water main	January 4, 2022, 11:51 AM	V-163BV004	Valve Condition	
WO-33814	1	Completed	44213.81987	44218	Repair water main		V-163FV005	Valve Condition	
WO-35193	85	Completed	44228.29152	44438	Repair water main/ANOTHER CALL 2/24/2021 MT TROY RD & SCHERLING ST WATER BREAK (TOS) DISPATCH		V-163GV003	Valve Condition	
WO-35193	85	Completed	44228.29152	44438	Repair water main/ANOTHER CALL 2/24/2021 MT TROY RD & SCHERLING ST WATER BREAK (TOS) DISPATCH		V-163GV004	Valve Condition	
WO-51398	1	Completed	44385.39155	44410	Repair water main		V-163KV005	Valve Condition	Good
WO-51398	1	Completed	44385.39155	44410	Repair water main		V-163KV007	Valve Condition	Good
WO-52184	1	Completed	44392.63255	44392	Valve Maintenance Report	July 15, 2021, 3:15 PM	V-163KV009	Valve Condition	Good
WO-37513	85	Completed	44252.30441	44253	Repair water main(Replace 6" Valve at Ivory & Sherling)	February 26, 2021, 8:20 AM	V-163LV001	Valve Condition	
WO-37513	85	Completed	44252.30441	44253	Repair water main(Replace 6" Valve at Ivory & Sherling)	February 26, 2021, 8:20 AM	V-163LV004	Valve Condition	
WO-35194	1	Completed	44228.29152	44438	Repair water main		V-163LV006	Valve Condition	
WO-34484	85	Completed	44221.55397	44229	Repair water main	February 2, 2021, 8:26 AM	V-163LV010	Valve Condition	
WO-41428	85	Completed	44298.61095	44320	Repair water main	May 4, 2021, 3:15 PM	V-163NV002	Valve Condition	
WO-41428	85	Completed	44298.61095	44320	Repair water main	May 4, 2021, 3:15 PM	V-163NV003	Valve Condition	
WO-41428	85	Completed	44298.61095	44320	Repair water main	May 4, 2021, 3:15 PM	V-163NV005	Valve Condition	
WO-52184	1	Completed	44392.63255	44392	Valve Maintenance Report	July 15, 2021, 3:15 PM	V-163PV003	Valve Condition	Good
WO-35216	1	Completed	44228.40348	44228	Valve Maintenance Report	February 1, 2021, 9:43 AM	V-166PV013	Valve Condition	
WO-35217	1	Completed	44228.4065	44228	Valve Maintenance Report	February 1, 2021, 9:47 AM	V-166PV016	Valve Condition	Fair
WO-33329	1	Completed	44209.39631	44210	Valve Maintenance Report	January 14, 2021, 1:35 PM	V-171AV002	Valve Condition	
WO-64771	1	Completed	44531.61127	44533	Valve Maintenance Report	December 3, 2021, 3:10 PM	V-171AV010	Valve Condition	
WO-64771	1	Completed	44531.61127	44533	Valve Maintenance Report	December 3, 2021, 3:10 PM	V-171AV011	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-64771	1	Completed	44531.61127	44533	Valve Maintenance Report	December 3, 2021, 3:10 PM	V-171AV012	Valve Condition	
WO-33329	1	Completed	44209.39631	44210	Valve Maintenance Report	January 14, 2021, 1:35 PM	V-171EV009	Valve Condition	
WO-33059	1	Completed	44207.48403	44207	Valve Maintenance Report	January 11, 2021, 11:46 AM	V-171EV022	Valve Condition	
WO-31482	21	Completed	44187.30291	44309	Valve is inoperable and requires replacement		V-171KV002	Valve Condition	
WO-55480	1	Completed	44431.55006	44440	Repair water main		V-171KV009	Valve Condition	
WO-55489	1	Completed	44431.56525	44434	Repair water main		V-171KV013	Valve Condition	
WO-55489	1	Completed	44431.56525	44434	Repair water main		V-171LV003	Valve Condition	
WO-40721	1	Completed	44288.45096	44438	Valve Maintenance Report		V-171LV031	Valve Condition	
WO-62647	1	Completed	44504.29277	44503	Valve Maintenance Report		V-172NV006	Valve Condition	
WO-43311	88	Completed	44316.44808	44314	Repair service line	June 17, 2021, 2:01 PM	V-172RV011	Valve Condition	Fair
WO-57936	1	Completed	44459.3999	44459	Valve Maintenance Report		V-172RV020	Valve Condition	
WO-61250	88	Completed	44489.69771	44494	Curb box needs dug for leak determination DRILL SHEET SHOWS LEAD ON PUBLIC SIDE. Ronnie posted no parking for Sun and Monday on both sides.	October 26, 2021, 10:34 AM	V-173AV001	Valve Condition	Good
WO-58568	1	Completed	44463.44479	44459	Valve Maintenance Report		V-173AV003	Valve Condition	
WO-58568	1	Completed	44463.44479	44459	Valve Maintenance Report		V-173AV008	Valve Condition	
WO-58568	1	Completed	44463.44479	44459	Valve Maintenance Report		V-173AV009	Valve Condition	
WO-58568	1	Completed	44463.44479	44459	Valve Maintenance Report		V-173AV010	Valve Condition	
WO-52375	1	Completed	44396.29448	44439	Repair water main		V-173AV022	Valve Condition	
WO-62647	1	Completed	44504.29277	44503	Valve Maintenance Report		V-173AV025	Valve Condition	
WO-56360	1	Completed	44440.54222	44250	Valve Maintenance Report		V-173AV033	Valve Condition	
WO-61588	1	Completed	44494.63702	44496	Valve Maintenance Report		V-173BV002	Valve Condition	
WO-56360	1	Completed	44440.54222	44250	Valve Maintenance Report		V-173BV007	Valve Condition	
WO-39325	182	Completed	44272.94728	44314	Information sheet for connection SEND WASTE WATER SEE NOTES BELOW		V-173BV008	Valve Condition	
WO-39325	182	Completed	44272.94728	44314	Information sheet for connection SEND WASTE WATER SEE NOTES BELOW		V-173BV013	Valve Condition	
WO-56360	1	Completed	44440.54222	44250	Valve Maintenance Report		V-173BV014	Valve Condition	
WO-37369	21	Completed	44251.3681	44252	installed a NEW 12 INCH VALVE		V-173BV015	Valve Condition	Fair
WO-37369	21	Completed	44251.3681	44252	installed a NEW 12 INCH VALVE		V-173BV016	Valve Condition	Fair
WO-49327	1	Completed	44368.01933	44439	Repair water main		V-173BV017	Valve Condition	
WO-49327	1	Completed	44368.01933	44439	Repair water main		V-173BV025	Valve Condition	
WO-56262	1	Completed	44440.38733	44440	Valve Maintenance Report	September 1, 2021, 6:43 PM	V-173BV026	Valve Condition	
WO-49486	41	Completed	44368.55225	44368	Contractor shut request	June 21, 2021, 1:19 PM	V-173BV028	Valve Condition	
WO-43311	88	Completed	44316.44808	44314	Repair service line	June 17, 2021, 2:01 PM	V-173CV001	Valve Condition	Fair
WO-57936	1	Completed	44459.3999	44459	Valve Maintenance Report		V-173CV002	Valve Condition	
WO-52375	1	Completed	44396.29448	44439	Repair water main		V-173EV008	Valve Condition	
WO-32859	1	Completed	44204.4128	44222	Repair water main		V-173EV015	Valve Condition	
WO-55339	85	Completed	44428.54263	44430	Repair water main	August 23, 2021, 10:33 AM	V-173EV016	Valve Condition	Good
WO-32859	1	Completed	44204.4128	44222	Repair water main		V-173EV017	Valve Condition	
WO-32795	21	Completed	44203.63627	44203	Valve is inoperable and requires replacement	January 7, 2021, 3:19 PM	V-173EV018	Valve Condition	
WO-49490	41	Completed	44368.56047	44368	Contractor shut request	June 21, 2021, 1:33 PM	V-173EV029	Valve Condition	
WO-38409	41	Completed	44263.43699	44263	Contractor shut request	March 8, 2021, 10:34 AM	V-173EV030	Valve Condition	
WO-38408	41	Completed	44263.43092	44263	Contractor shut request	March 8, 2021, 10:24 AM	V-173EV032	Valve Condition	Good
WO-38411	41	Completed	44263.4436	44263	Contractor shut request	March 8, 2021, 10:46 AM	V-173EV033	Valve Condition	
WO-32859	1	Completed	44204.4128	44222	Repair water main		V-173EV034	Valve Condition	
WO-35340	1	Completed	44229.41489	44229	Valve Maintenance Report	February 2, 2021, 2:03 PM	V-173EV038	Valve Condition	
WO-35340	1	Completed	44229.41489	44229	Valve Maintenance Report	February 2, 2021, 2:03 PM	V-173EV039	Valve Condition	Fair
WO-35340	1	Completed	44229.41489	44229	Valve Maintenance Report	February 2, 2021, 2:03 PM	V-173EV041	Valve Condition	
WO-49327	1	Completed	44368.01933	44439	Repair water main		V-173FV001	Valve Condition	
WO-35065	1	Completed	44225.55457	44229	Valve Maintenance Report	February 2, 2021, 2:12 PM	V-173FV018	Valve Condition	Fair
WO-55339	85	Completed	44428.54263	44430	Repair water main	August 23, 2021, 10:33 AM	V-173JV001	Valve Condition	
WO-55339	85	Completed	44428.54263	44430	Repair water main	August 23, 2021, 10:33 AM	V-173JV002	Valve Condition	Good
WO-55339	85	Completed	44428.54263	44430	Repair water main	August 23, 2021, 10:33 AM	V-173JV003	Valve Condition	
WO-61460	464	Completed	44492.96461	44492	people's gas hit a water line		V-173JV016	Valve Condition	
WO-51411	1	Completed	44385.4249	44439	Repair water main- Mingo St Main termination.		V-173JV018	Valve Condition	Good
WO-50953	1	Completed	44379.86049	44385	Repair water main		V-173JV019	Valve Condition	
WO-41381	85	Completed	44298.5169	44299	Repair water main	April 13, 2021, 8:06 AM	V-173JV020	Valve Condition	Good
WO-50952	85	Completed	44379.86049	44384	Repair water main	July 7, 2021, 10:54 AM	V-173JV023	Valve Condition	
WO-50952	85	Completed	44379.86049	44384	Repair water main	July 7, 2021, 10:54 AM	V-173JV024	Valve Condition	
WO-35065	1	Completed	44225.55457	44229	Valve Maintenance Report	February 2, 2021, 2:12 PM	V-173KV001	Valve Condition	Fair
WO-35065	1	Completed	44225.55457	44229	Valve Maintenance Report	February 2, 2021, 2:12 PM	V-173KV002	Valve Condition	Fair
WO-36050	464	Completed	44235.62778	44236	Contractor damage to service line	February 9, 2021, 10:26 AM	V-173KV003	Valve Condition	Good
WO-36050	464	Completed	44235.62778	44236	Contractor damage to service line	February 9, 2021, 10:26 AM	V-173LV004	Valve Condition	Good
WO-38352	84	Completed	44260.9606	44260	Main or service line leak investigation/survey/PER EOC-911 WATER LEAK IN MIDDLE OF STREET NO FURTHER INFO CALLED IN BY A PASSERBY		V-173NV003	Valve Condition	
WO-40788	1	Completed	44291.3349	44314	Valve Maintenance Report	April 28, 2021, 7:57 AM	V-173NV010	Valve Condition	
WO-36984	1	Completed	44246.38803	44246	Valve Maintenance Report	February 19, 2021, 2:47 PM	V-173NV012	Valve Condition	Good
WO-36984	1	Completed	44246.38803	44246	Valve Maintenance Report	February 19, 2021, 2:47 PM	V-173NV020	Valve Condition	Good
WO-62448	1	Completed	44503.40884	44503	Valve Maintenance Report	November 3, 2021, 2:09 PM	V-173NV021	Valve Condition	Fair
WO-62448	1	Completed	44503.40884	44503	Valve Maintenance Report	November 3, 2021, 2:09 PM	V-173NV022	Valve Condition	Fair
WO-62448	1	Completed	44503.40884	44503	Valve Maintenance Report	November 3, 2021, 2:09 PM	V-173NV023	Valve Condition	Fair
WO-62448	1	Completed	44503.40884	44503	Valve Maintenance Report	November 3, 2021, 2:09 PM	V-173NV024	Valve Condition	Fair
WO-37871	41	Completed	44257.34604	44279	Contractor shut request	March 24, 2021, 7:12 AM	V-173NV030	Valve Condition	
WO-62803	1	Completed	44505.3933	44505	Valve Maintenance Report	November 5, 2021, 10:02 AM	V-173NV031	Valve Condition	
WO-62803	1	Completed	44505.3933	44505	Valve Maintenance Report	November 5, 2021, 10:02 AM	V-173NV032	Valve Condition	Good
WO-38389	41	Completed	44263.34358	44279	Contractor shut request	March 24, 2021, 7:13 AM	V-173NV033	Valve Condition	
WO-36984	1	Completed	44246.38803	44246	Valve Maintenance Report	February 19, 2021, 2:47 PM	V-173NV035	Valve Condition	Good
WO-62803	1	Completed	44505.3933	44505	Valve Maintenance Report	November 5, 2021, 10:02 AM	V-173NV036	Valve Condition	Good
WO-62803	1	Completed	44505.3933	44505	Valve Maintenance Report	November 5, 2021, 10:02 AM	V-173NV037	Valve Condition	
WO-36782	41	Completed	44244.36193	44244	Contractor shut request	February 17, 2021, 10:46 AM	V-173NV038	Valve Condition	
WO-38394	41	Completed	44263.35741	44279	Contractor shut request	March 24, 2021, 7:14 AM	V-173NV041	Valve Condition	Good
WO-40788	1	Completed	44291.3349	44314	Valve Maintenance Report	April 28, 2021, 7:57 AM	V-173NV042	Valve Condition	
WO-33314	41	Completed	44209.36323	44209	Contractor shut request	January 13, 2021, 3:27 PM	V-173PV008	Valve Condition	
WO-33314	41	Completed	44209.36323	44209	Contractor shut request	January 13, 2021, 3:27 PM	V-173PV009	Valve Condition	
WO-33314	41	Completed	44209.36323	44209	Contractor shut request	January 13, 2021, 3:27 PM	V-173RV001	Valve Condition	
WO-62816	1	Completed	44505.44239	44505	Valve Maintenance Report	November 5, 2021, 10:55 AM	V-174AV001	Valve Condition	
WO-35385	41	Completed	44229.59599	44235	zottola working in the area making repairs	February 8, 2021, 7:05 AM	V-174AV002	Valve Condition	
WO-62816	1	Completed	44505.44239	44505	Valve Maintenance Report	November 5, 2021, 10:55 AM	V-174AV003	Valve Condition	
WO-62816	1	Completed	44505.44239	44505	Valve Maintenance Report	November 5, 2021, 10:55 AM	V-174AV004	Valve Condition	
WO-41457	88	Completed	44298.87126	44300	Repair service line, NO WATER CALL , FYI, PER THE PLUMBER ,SHAWN C HE PUMPED 4 GALLONS OF WATER IN IT AND WHEN HE TURNED ON VALVE THE 4 GALLONS CAME OUT POSSIBLE CLOGGED SERVICE LINE . CUSTOMER NOT ABLE TO BE PUT ON TEMP , IS AN ELDERLY WOMAN , NEED DUG , PER WS 362 SHAWN C	April 14, 2021, 7:28 AM	V-174AV005	Valve Condition	Good
WO-62816	1	Completed	44505.44239	44505	Valve Maintenance Report	November 5, 2021, 10:55 AM	V-174AV006	Valve Condition	
WO-41457	88	Completed	44298.87126	44300	Repair service line, NO WATER CALL , FYI, PER THE PLUMBER ,SHAWN C HE PUMPED 4 GALLONS OF WATER IN IT AND WHEN HE TURNED ON VALVE THE 4 GALLONS CAME OUT POSSIBLE CLOGGED SERVICE LINE . CUSTOMER NOT ABLE TO BE PUT ON TEMP , IS AN ELDERLY WOMAN , NEED DUG , PER WS 362 SHAWN C	April 14, 2021, 7:28 AM	V-174AV007	Valve Condition	Good
WO-40643	41	Completed	44287.40974	44287	Contractor shut request	April 1, 2021, 5:20 PM	V-174AV008	Valve Condition	Fair
WO-39097	85	Completed	44270.58011	44279	Repair water main	March 26, 2021, 9:49 AM	V-174AV011	Valve Condition	
WO-42708	1	Completed	44312.33052	44313	Valve Maintenance Report	April 27, 2021, 10:40 AM	V-174AV013	Valve Condition	
WO-40643	41	Completed	44287.40974	44287	Contractor shut request	April 1, 2021, 5:20 PM	V-174AV014	Valve Condition	Fair
WO-40788	1	Completed	44291.3349	44314	Valve Maintenance Report	April 28, 2021, 7:57 AM	V-174AV016	Valve Condition	
WO-40788	1	Completed	44291.3349	44314	Valve Maintenance Report	April 28, 2021, 7:57 AM	V-174AV017	Valve Condition	
WO-40788	1	Completed	44291.3349	44314	Valve Maintenance Report	April 28, 2021, 7:57 AM	V-174AV018	Valve Condition	
WO-40788	1	Completed	44291.3349	44314	Valve Maintenance Report	April 28, 2021, 7:57 AM	V-174AV019	Valve Condition	
WO-40788	1	Completed	44291.3349	44314	Valve Maintenance Report	April 28, 2021, 7:57 AM	V-174AV020	Valve Condition	
WO-40788	1	Completed	44291.3349	44314	Valve Maintenance Report	April 28, 2021, 7:57 AM	V-174AV021	Valve Condition	
WO-40788	1	Completed	44291.3349	44314	Valve Maintenance Report	April 28, 2021, 7:57 AM	V-174AV024	Valve Condition	
WO-40788	1	Completed	44291.3349	44314	Valve Maintenance Report	April 28, 2021, 7:57 AM	V-174AV026	Valve Condition	
WO-39098	1	Completed	44270.58011	44438	Repair water main		V-174AV032	Valve Condition	
WO-40788	1	Completed	44291.3349	44314	Valve Maintenance Report	April 28, 2021, 7:57 AM	V-174AV036	Valve Condition	
WO-44193	41	Completed	44326.36916	44326	Contractor shut request	May 10, 2021, 2:26 PM	V-174BV009	Valve Condition	
WO-44185	41	Completed	44326.36258	44326	Contractor shut request	May 10, 2021, 2:23 PM	V-174BV010	Valve Condition	Good
WO-35385	41	Completed	44229.59599	44235	zottola working in the area making repairs	February 8, 2021, 7:05 AM	V-174BV014	Valve Condition	
WO-37749	1	Completed	44256.37711	44256	Valve Maintenance Report	March 1, 2021, 9:05 AM	V-174BV015	Valve Condition	Good
WO-40643	41	Completed	44287.40974	44287	Contractor shut request	April 1, 2021, 5:20 PM	V-174BV016	Valve Condition	Fair

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-66746	1	Completed	44559.41846	44559	Valve Maintenance Report	December 29, 2021, 10:25 AM	V-174BV020	Valve Condition	
WO-66746	1	Completed	44559.41846	44559	Valve Maintenance Report	December 29, 2021, 10:25 AM	V-174BV021	Valve Condition	
WO-37748	1	Completed	44256.37391	44256	Valve Maintenance Report	March 1, 2021, 9:17 AM	V-174BV024	Valve Condition	Good
WO-66746	1	Completed	44559.41846	44559	Valve Maintenance Report	December 29, 2021, 10:25 AM	V-174BV025	Valve Condition	
WO-40643	41	Completed	44287.40974	44287	Contractor shut request	April 1, 2021, 5:20 PM	V-174BV026	Valve Condition	Fair
WO-40643	41	Completed	44287.40974	44287	Contractor shut request	April 1, 2021, 5:20 PM	V-174BV027	Valve Condition	Fair
WO-37746	1	Completed	44256.36954	44256	Valve Maintenance Report		V-174BV030	Valve Condition	
WO-38293	563	Completed	44260.57672	44263	Water main repair given to contractor --Meter changed no water with stop open		V-174BV031	Valve Condition	
WO-40643	41	Completed	44287.40974	44287	Contractor shut request	April 1, 2021, 5:20 PM	V-174BV033	Valve Condition	Fair
WO-39724	1	Completed	44278.45169	44278	Valve Maintenance Report	March 23, 2021, 10:53 AM	V-174BV034	Valve Condition	
WO-56234	1	Completed	44440.34562	44438	Valve Maintenance Report		V-174BV037	Valve Condition	
WO-40643	41	Completed	44287.40974	44287	Contractor shut request	April 1, 2021, 5:20 PM	V-174BV043	Valve Condition	Fair
WO-66465	1	Completed	44552.38834	44552	Valve Maintenance Report	December 22, 2021, 9:29 AM	V-174BV044	Valve Condition	
WO-66464	1	Completed	44552.36648	44552	Valve Maintenance Report	December 22, 2021, 9:18 AM	V-174BV046	Valve Condition	
WO-40643	41	Completed	44287.40974	44287	Contractor shut request	April 1, 2021, 5:20 PM	V-174BV052	Valve Condition	Fair
WO-39728	1	Completed	44278.45623	44278	Valve Maintenance Report	March 23, 2021, 10:59 AM	V-174BV055	Valve Condition	
WO-39098	1	Completed	44270.58011	44438	Repair water main		V-174BV056	Valve Condition	
WO-40643	41	Completed	44287.40974	44287	Contractor shut request	April 1, 2021, 5:20 PM	V-174BV059	Valve Condition	Fair
WO-66746	1	Completed	44559.41846	44559	Valve Maintenance Report	December 29, 2021, 10:25 AM	V-174BV061	Valve Condition	
WO-56234	1	Completed	44440.34562	44438	Valve Maintenance Report		V-174CV014	Valve Condition	
WO-56263	1	Completed	44440.39096	44377	Valve Maintenance Report		V-174CV015	Valve Condition	
WO-40788	1	Completed	44291.3349	44314	Valve Maintenance Report	April 28, 2021, 7:57 AM	V-174EV001	Valve Condition	
WO-65328	1	Completed	44538.39775	44538	Valve Maintenance Report	December 8, 2021, 9:53 AM	V-174EV002	Valve Condition	
WO-40788	1	Completed	44291.3349	44314	Valve Maintenance Report	April 28, 2021, 7:57 AM	V-174EV006	Valve Condition	
WO-65337	1	Completed	44538.4175	44538	Valve Maintenance Report	December 8, 2021, 10:37 AM	V-174EV015	Valve Condition	Good
WO-65337	1	Completed	44538.4175	44538	Valve Maintenance Report	December 8, 2021, 10:37 AM	V-174EV017	Valve Condition	Good
WO-65337	1	Completed	44538.4175	44538	Valve Maintenance Report	December 8, 2021, 10:37 AM	V-174EV019	Valve Condition	Good
WO-40788	1	Completed	44291.3349	44314	Valve Maintenance Report	April 28, 2021, 7:57 AM	V-174EV025	Valve Condition	
WO-65347	1	Completed	44538.44458	44538	Valve Maintenance Report	December 8, 2021, 11:14 AM	V-174EV028	Valve Condition	
WO-65347	1	Completed	44538.44458	44538	Valve Maintenance Report	December 8, 2021, 11:14 AM	V-174EV029	Valve Condition	
WO-34521	84	Completed	44221.91804	44228	Main or service line leak investigation/survey/ 311 COMPLAINT/PARC:0125H00243000000 Leaking on to sidewalk and row, freezing	February 1, 2021, 2:35 PM	V-174EV036	Valve Condition	
WO-65361	1	Completed	44538.53031	44538	Valve Maintenance Report	December 8, 2021, 1:03 PM	V-174EV042	Valve Condition	
WO-65361	1	Completed	44538.53031	44538	Valve Maintenance Report	December 8, 2021, 1:03 PM	V-174EV043	Valve Condition	
WO-65361	1	Completed	44538.53031	44538	Valve Maintenance Report	December 8, 2021, 1:03 PM	V-174EV044	Valve Condition	
WO-54286	1	Completed	44418.44639	44424	Valve Maintenance Report	August 16, 2021, 2:43 PM	V-174FV002	Valve Condition	Fair
WO-54286	1	Completed	44418.44639	44424	Valve Maintenance Report	August 16, 2021, 2:43 PM	V-174FV003	Valve Condition	Fair
WO-54286	1	Completed	44418.44639	44424	Valve Maintenance Report	August 16, 2021, 2:43 PM	V-174FV004	Valve Condition	Fair
WO-54286	1	Completed	44418.44639	44424	Valve Maintenance Report	August 16, 2021, 2:43 PM	V-174FV005	Valve Condition	Fair
WO-65328	1	Completed	44538.39775	44538	Valve Maintenance Report	December 8, 2021, 9:53 AM	V-174FV007	Valve Condition	
WO-54286	1	Completed	44418.44639	44424	Valve Maintenance Report	August 16, 2021, 2:43 PM	V-174FV010	Valve Condition	Fair
WO-54286	1	Completed	44418.44639	44424	Valve Maintenance Report	August 16, 2021, 2:43 PM	V-174FV011	Valve Condition	Fair
WO-46923	41	Completed	44349.25727	44349	Contractor shut request	June 2, 2021, 6:28 AM	V-174FV012	Valve Condition	Fair
WO-46923	41	Completed	44349.25727	44349	Contractor shut request	June 2, 2021, 6:28 AM	V-174FV013	Valve Condition	Fair
WO-46923	41	Completed	44349.25727	44349	Contractor shut request	June 2, 2021, 6:28 AM	V-174FV014	Valve Condition	Fair
WO-54286	1	Completed	44418.44639	44424	Valve Maintenance Report	August 16, 2021, 2:43 PM	V-174FV015	Valve Condition	Fair
WO-46270	1	Completed	44342.34916	44343	Valve Maintenance Report	May 27, 2021, 6:16 AM	V-174FV016	Valve Condition	Fair
WO-46923	41	Completed	44349.25727	44349	Contractor shut request	June 2, 2021, 6:28 AM	V-174FV017	Valve Condition	Fair
WO-46923	41	Completed	44349.25727	44349	Contractor shut request	June 2, 2021, 6:28 AM	V-174FV018	Valve Condition	Fair
WO-65575	1	Completed	44540.38907	44540	Valve Maintenance Report	December 10, 2021, 9:44 AM	V-174FV020	Valve Condition	Fair
WO-65575	1	Completed	44540.38907	44540	Valve Maintenance Report	December 10, 2021, 9:44 AM	V-174FV021	Valve Condition	Fair
WO-65575	1	Completed	44540.38907	44540	Valve Maintenance Report	December 10, 2021, 9:44 AM	V-174FV022	Valve Condition	Fair
WO-65575	1	Completed	44540.38907	44540	Valve Maintenance Report	December 10, 2021, 9:44 AM	V-174FV023	Valve Condition	Fair
WO-54286	1	Completed	44418.44639	44424	Valve Maintenance Report	August 16, 2021, 2:43 PM	V-174FV031	Valve Condition	Fair
WO-54286	1	Completed	44418.44639	44424	Valve Maintenance Report	August 16, 2021, 2:43 PM	V-174FV032	Valve Condition	Fair
WO-63432	1	Completed	44512.57976	44512	Valve Maintenance Report	November 12, 2021, 2:05 PM	V-174GV005	Valve Condition	
WO-66769	1	Completed	44559.51866	44559	Valve Maintenance Report	December 29, 2021, 1:45 PM	V-174GV006	Valve Condition	
WO-56263	1	Completed	44440.39096	44377	Valve Maintenance Report		V-174GV007	Valve Condition	
WO-66769	1	Completed	44559.51866	44559	Valve Maintenance Report	December 29, 2021, 1:45 PM	V-174GV008	Valve Condition	
WO-56263	1	Completed	44440.39096	44377	Valve Maintenance Report		V-174GV023	Valve Condition	
WO-46986	1	Completed	44349.37426	44349	Valve Maintenance Report	June 2, 2021, 9:01 AM	V-174JV016	Valve Condition	
WO-46978	1	Completed	44349.36849	44349	Valve Maintenance Report	June 2, 2021, 8:53 AM	V-174JV017	Valve Condition	
WO-47132	1	Completed	44349.47718	44349	Valve Maintenance Report	June 2, 2021, 11:43 AM	V-174JV019	Valve Condition	
WO-47012	1	Completed	44349.39529	44349	Valve Maintenance Report	June 2, 2021, 9:33 AM	V-174JV040	Valve Condition	Fair
WO-47526	1	Completed	44351.34577	44351	Valve Maintenance Report	June 4, 2021, 8:22 AM	V-174JV041	Valve Condition	Good
WO-41479	1	Completed	44299.33357	44300	Valve Maintenance Report	April 14, 2021, 7:35 AM	V-174JV045	Valve Condition	
WO-54258	1	Completed	44418.34985	44418	Valve Maintenance Report	August 10, 2021, 2:40 PM	V-174JV048	Valve Condition	
WO-41479	1	Completed	44299.33357	44300	Valve Maintenance Report	April 14, 2021, 7:35 AM	V-174JV050	Valve Condition	
WO-65571	1	Completed	44540.36126	44540	Valve Maintenance Report	December 10, 2021, 9:05 AM	V-174KV007	Valve Condition	
WO-65571	1	Completed	44540.36126	44540	Valve Maintenance Report	December 10, 2021, 9:05 AM	V-174KV009	Valve Condition	
WO-63419	1	Completed	44512.4128	44512	Valve Maintenance Report	November 12, 2021, 9:57 AM	V-174KV010	Valve Condition	
WO-63418	1	Completed	44512.41108	44512	Valve Maintenance Report	November 12, 2021, 9:58 AM	V-174KV012	Valve Condition	
WO-65503	1	Completed	44539.60598	44539	Valve Maintenance Report	December 9, 2021, 2:34 PM	V-174KV019	Valve Condition	
WO-65502	1	Completed	44539.60338	44539	Valve Maintenance Report	December 9, 2021, 2:31 PM	V-174KV023	Valve Condition	
WO-54258	1	Completed	44418.34985	44418	Valve Maintenance Report	August 10, 2021, 2:40 PM	V-174KV032	Valve Condition	
WO-47134	1	Completed	44349.48684	44349	Valve Maintenance Report	June 2, 2021, 12:03 PM	V-174KV034	Valve Condition	
WO-54258	1	Completed	44418.34985	44418	Valve Maintenance Report	August 10, 2021, 2:40 PM	V-174KV036	Valve Condition	
WO-54258	1	Completed	44418.34985	44418	Valve Maintenance Report	August 10, 2021, 2:40 PM	V-174KV037	Valve Condition	
WO-47136	1	Completed	44349.49391	44349	Valve Maintenance Report	June 2, 2021, 12:01 PM	V-174KV040	Valve Condition	
WO-56347	1	Completed	44440.5291	44273	Valve Maintenance Report		V-174KV060	Valve Condition	
WO-65485	1	Completed	44539.56813	44539	Valve Maintenance Report	December 9, 2021, 1:39 PM	V-174KV061	Valve Condition	
WO-65484	1	Completed	44539.56498	44539	Valve Maintenance Report	December 9, 2021, 1:36 PM	V-174KV062	Valve Condition	
WO-32691	85	Completed	44203.40062	44209	Repair water main	January 13, 2021, 10:12 PM	V-174NV004	Valve Condition	
WO-60974	1	Completed	44487.5805	44496	Repair water main		V-174NV005	Valve Condition	
WO-61550	1	Completed	44494.48809	44496	Valve Maintenance Report	October 27, 2021, 10:48 AM	V-174NV007	Valve Condition	
WO-41479	1	Completed	44299.33357	44300	Valve Maintenance Report	April 14, 2021, 7:35 AM	V-174NV009	Valve Condition	
WO-41479	1	Completed	44299.33357	44300	Valve Maintenance Report	April 14, 2021, 7:35 AM	V-174NV012	Valve Condition	
WO-61550	1	Completed	44494.48809	44496	Valve Maintenance Report	October 27, 2021, 10:48 AM	V-174NV017	Valve Condition	
WO-32691	85	Completed	44203.40062	44209	Repair water main	January 13, 2021, 10:12 PM	V-174NV020	Valve Condition	
WO-61550	1	Completed	44494.48809	44496	Valve Maintenance Report	October 27, 2021, 10:48 AM	V-174NV021	Valve Condition	
WO-60974	1	Completed	44487.5805	44496	Repair water main		V-174NV022	Valve Condition	
WO-60974	1	Completed	44487.5805	44496	Repair water main		V-174NV025	Valve Condition	
WO-57809	1	Completed	44456.54756	44456	Valve Maintenance Report	September 17, 2021, 1:17 PM	V-174NV028	Valve Condition	
WO-57812	1	Completed	44456.55113	44456	Valve Maintenance Report	September 17, 2021, 1:16 PM	V-174NV029	Valve Condition	Good
WO-57708	1	Completed	44455.53552	44455	Valve Maintenance Report	September 16, 2021, 12:54 PM	V-174NV031	Valve Condition	
WO-65366	1	Completed	44538.57509	44538	Valve Maintenance Report	December 8, 2021, 2:32 PM	V-174NV036	Valve Condition	
WO-60974	1	Completed	44487.5805	44496	Repair water main		V-174NV044	Valve Condition	
WO-57817	1	Completed	44456.56446	44456	Valve Maintenance Report	September 17, 2021, 1:45 PM	V-174NV046	Valve Condition	Good
WO-57820	1	Completed	44456.56707	44456	Valve Maintenance Report	September 17, 2021, 1:40 PM	V-174NV047	Valve Condition	Good
WO-38972	21	Completed	44270.29608	44271	Valve is inoperable and requires replacement	March 17, 2021, 10:22 AM	V-174PV001	Valve Condition	
WO-56347	1	Completed	44440.5291	44273	Valve Maintenance Report		V-174PV002	Valve Condition	
WO-39131	21	Completed	44271.3155	44273	Valve is inoperable and requires replacement	September 1, 2021, 12:41 PM	V-174PV003	Valve Condition	Fair
WO-63421	1	Completed	44512.44444	44512	Valve Maintenance Report	November 12, 2021, 10:56 AM	V-174PV006	Valve Condition	
WO-56347	1	Completed	44440.5291	44273	Valve Maintenance Report		V-174PV007	Valve Condition	
WO-63424	1	Completed	44512.44861	44512	Valve Maintenance Report	November 12, 2021, 10:57 AM	V-174PV008	Valve Condition	
WO-63423	1	Completed	44512.44623	44512	Valve Maintenance Report	November 12, 2021, 10:56 AM	V-174PV009	Valve Condition	
WO-63426	1	Completed	44512.4624	44512	Valve Maintenance Report	November 12, 2021, 11:12 AM	V-174PV021	Valve Condition	
WO-57795	1	Completed	44456.46034	44456	Valve Maintenance Report	September 17, 2021, 11:09 AM	V-174PV028	Valve Condition	
WO-57796	1	Completed	44456.46209	44456	Valve Maintenance Report	September 17, 2021, 11:08 AM	V-174PV029	Valve Condition	
WO-65429	1	Completed	44539.40766	44539	Valve Maintenance Report	December 9, 2021, 11:31 AM	V-174PV039	Valve Condition	Good
WO-65548	1	Completed	44540.31882	44539	Valve Maintenance Report	December 10, 2021, 9:28 AM	V-174PV041	Valve Condition	
WO-65437	1	Completed	44539.48084	44539	Valve Maintenance Report	December 9, 2021, 11:33 AM	V-174PV042	Valve Condition	
WO-65548	1	Completed	44540.31882	44539	Valve Maintenance Report	December 10, 2021, 9:28 AM	V-174PV043	Valve Condition	
WO-65366	1	Completed	44538.57509	44538	Valve Maintenance Report	December 8, 2021, 2:32 PM	V-174PV045	Valve Condition	
WO-65366	1	Completed	44538.57509	44538	Valve Maintenance Report	December 8, 2021, 2:32 PM	V-174PV046	Valve Condition	
WO-65366	1	Completed	44538.57509	44538	Valve Maintenance Report	December 8, 2021, 2:32 PM	V-174PV047	Valve Condition	
WO-65366	1	Completed	44538.57509	44538	Valve Maintenance Report	December 8, 2021, 2:32 PM	V-174PV048	Valve Condition	

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-63428	1	Completed	44512.46418	44512	Valve Maintenance Report	November 12, 2021, 11:11 AM	V-174PV049	Valve Condition	
WO-63431	1	Completed	44512.54469	44512	Valve Maintenance Report	November 12, 2021, 1:08 PM	V-174PV050	Valve Condition	
WO-63430	1	Completed	44512.54318	44512	Valve Maintenance Report	November 12, 2021, 1:09 PM	V-174PV051	Valve Condition	Good
WO-57711	1	Completed	44455.54365	44455	Valve Maintenance Report	September 16, 2021, 1:08 PM	V-175AV006	Valve Condition	
WO-57712	1	Completed	44455.54559	44455	Valve Maintenance Report	September 16, 2021, 1:07 PM	V-175AV007	Valve Condition	
WO-57713	1	Completed	44455.55549	44455	Valve Maintenance Report	September 16, 2021, 1:28 PM	V-175AV011	Valve Condition	
WO-57714	1	Completed	44455.55936	44455	Valve Maintenance Report	September 16, 2021, 1:27 PM	V-175AV012	Valve Condition	
WO-57697	1	Completed	44455.47948	44455	Valve Maintenance Report	September 16, 2021, 11:43 AM	V-175AV031	Valve Condition	
WO-57790	1	Completed	44456.44526	44456	Valve Maintenance Report	September 17, 2021, 10:43 AM	V-175BV005	Valve Condition	Good
WO-57769	1	Completed	44456.37992	44456	Valve Maintenance Report	September 17, 2021, 9:15 AM	V-175BV007	Valve Condition	
WO-57771	1	Completed	44456.38176	44456	Valve Maintenance Report	September 17, 2021, 9:14 AM	V-175BV008	Valve Condition	
WO-57768	1	Completed	44456.37734	44456	Valve Maintenance Report	September 17, 2021, 9:16 AM	V-175BV011	Valve Condition	
WO-57778	1	Completed	44456.42348	44456	Valve Maintenance Report	September 17, 2021, 10:13 AM	V-175BV018	Valve Condition	
WO-57774	1	Completed	44456.3995	44456	Valve Maintenance Report	September 17, 2021, 9:37 AM	V-175BV028	Valve Condition	
WO-57782	1	Completed	44456.43374	44456	Valve Maintenance Report	September 17, 2021, 10:30 AM	V-175BV041	Valve Condition	
WO-57784	1	Completed	44456.43574	44456	Valve Maintenance Report	September 17, 2021, 10:30 AM	V-175BV042	Valve Condition	
WO-58458	1	Completed	44462.54972	44462	Valve Maintenance Report	September 23, 2021, 1:24 PM	V-175EV003	Valve Condition	Good
WO-58459	1	Completed	44462.55143	44462	Valve Maintenance Report	September 23, 2021, 1:23 PM	V-175EV004	Valve Condition	Good
WO-61310	1	Completed	44490.43559	44515	Valve Maintenance Report		V-175EV005	Valve Condition	Good
WO-58460	1	Completed	44462.55327	44462	Valve Maintenance Report	September 23, 2021, 1:22 PM	V-175EV006	Valve Condition	Good
WO-57701	1	Completed	44455.48359	44455	Valve Maintenance Report	September 16, 2021, 11:41 AM	V-175EV007	Valve Condition	
WO-33122	1	Completed	44208.38821	44210	Repair water main		V-175EV026	Valve Condition	
WO-59101	1	Completed	44469.38359	44469	Valve Maintenance Report	September 30, 2021, 9:14 AM	V-175EV027	Valve Condition	
WO-57700	1	Completed	44455.48177	44455	Valve Maintenance Report	September 16, 2021, 11:42 AM	V-175EV028	Valve Condition	
WO-35984	85	Completed	44235.32329	44236	Repair water main	February 9, 2021, 11:09 PM	V-175FV011	Valve Condition	Good
WO-35984	85	Completed	44235.32329	44236	Repair water main	February 9, 2021, 11:09 PM	V-175FV013	Valve Condition	
WO-33122	1	Completed	44208.38821	44210	Repair water main		V-175FV023	Valve Condition	
WO-59178	1	Completed	44469.59737	44469	Valve Maintenance Report	September 30, 2021, 2:40 PM	V-175FV027	Valve Condition	
WO-60108	88	Completed	44477.73727	44479	Repair service line- if drilled, Drill Sheet work order MUST be completed Broken Stop customer put on temporary service from neighbors hose bib. Standard 3 Day 1 call put in 4pm Friday 10/8/21.Please let Jason V know when job is completed so ramps can be returned to Howard street.	October 10, 2021, 9:25 PM	V-175JV013	Valve Condition	
WO-57037	1	Completed	44448.50514	44448	Valve Maintenance Report	September 9, 2021, 12:16 PM	V-175JV017	Valve Condition	
WO-57039	1	Completed	44448.50696	44448	Valve Maintenance Report	September 9, 2021, 12:15 PM	V-175JV019	Valve Condition	
WO-56942	1	Completed	44447.59718	44447	Valve Maintenance Report	September 8, 2021, 2:36 PM	V-175JV020	Valve Condition	
WO-57042	1	Completed	44448.51562	44448	Valve Maintenance Report	September 9, 2021, 12:47 PM	V-175KV005	Valve Condition	
WO-56937	1	Completed	44447.58331	44447	Valve Maintenance Report	September 8, 2021, 2:11 PM	V-175KV011	Valve Condition	
WO-56935	1	Completed	44447.58186	44447	Valve Maintenance Report	September 8, 2021, 2:12 PM	V-175KV012	Valve Condition	
WO-60108	88	Completed	44477.73727	44479	Repair service line- if drilled, Drill Sheet work order MUST be completed Broken Stop customer put on temporary service from neighbors hose bib. Standard 3 Day 1 call put in 4pm Friday 10/8/21.Please let Jason V know when job is completed so ramps can be returned to Howard street.	October 10, 2021, 9:25 PM	V-175NV003	Valve Condition	
WO-60108	88	Completed	44477.73727	44479	Repair service line- if drilled, Drill Sheet work order MUST be completed Broken Stop customer put on temporary service from neighbors hose bib. Standard 3 Day 1 call put in 4pm Friday 10/8/21.Please let Jason V know when job is completed so ramps can be returned to Howard street.	October 10, 2021, 9:25 PM	V-175NV007	Valve Condition	
WO-54455	1	Completed	44419.57476	44419	Valve Maintenance Report	August 11, 2021, 2:48 PM	V-175NV028	Valve Condition	
WO-54455	1	Completed	44419.57476	44419	Valve Maintenance Report	August 11, 2021, 2:48 PM	V-175NV029	Valve Condition	
WO-54455	1	Completed	44419.57476	44419	Valve Maintenance Report	August 11, 2021, 2:48 PM	V-175NV030	Valve Condition	
WO-54455	1	Completed	44419.57476	44419	Valve Maintenance Report	August 11, 2021, 2:48 PM	V-175NV032	Valve Condition	
WO-55347	1	Completed	44428.56823	44428	Valve Maintenance Report	August 20, 2021, 2:09 PM	V-175PV002	Valve Condition	
WO-55348	1	Completed	44428.57019	44428	Valve Maintenance Report	August 20, 2021, 2:10 PM	V-175PV003	Valve Condition	
WO-55351	1	Completed	44428.57177	44428	Valve Maintenance Report	August 20, 2021, 2:10 PM	V-175PV004	Valve Condition	
WO-55353	1	Completed	44428.57327	44428	Valve Maintenance Report	August 20, 2021, 2:11 PM	V-175PV005	Valve Condition	
WO-54711	1	Completed	44421.56853	44421	Valve Maintenance Report	August 13, 2021, 2:03 PM	V-175PV007	Valve Condition	
WO-54717	1	Completed	44421.57524	44421	Valve Maintenance Report	August 13, 2021, 2:06 PM	V-175PV008	Valve Condition	
WO-54713	1	Completed	44421.572	44421	Valve Maintenance Report	August 13, 2021, 2:04 PM	V-175PV010	Valve Condition	
WO-54716	1	Completed	44421.57359	44421	Valve Maintenance Report	August 13, 2021, 2:06 PM	V-175PV011	Valve Condition	
WO-54712	1	Completed	44421.5704	44421	Valve Maintenance Report	August 13, 2021, 2:04 PM	V-175PV012	Valve Condition	
WO-57570	1	Completed	44454.60308	44454	Valve Maintenance Report	September 15, 2021, 2:47 PM	V-175PV014	Valve Condition	
WO-54685	1	Completed	44421.4039	44421	Valve Maintenance Report	August 13, 2021, 9:59 AM	V-175PV016	Valve Condition	
WO-54684	1	Completed	44421.40229	44421	Valve Maintenance Report	August 13, 2021, 10:01 AM	V-175PV017	Valve Condition	
WO-55075	1	Completed	44426.43995	44426	Valve Maintenance Report	August 18, 2021, 11:06 AM	V-176AV001	Valve Condition	
WO-55076	1	Completed	44426.4433	44426	Valve Maintenance Report	August 18, 2021, 11:06 AM	V-176AV002	Valve Condition	Fair
WO-55080	1	Completed	44426.44507	44426	Valve Maintenance Report	August 18, 2021, 12:26 PM	V-176AV003	Valve Condition	
WO-55074	1	Completed	44426.43801	44426	Valve Maintenance Report	August 18, 2021, 11:04 AM	V-176AV004	Valve Condition	
WO-55057	1	Completed	44426.41034	44426	Valve Maintenance Report	August 18, 2021, 10:05 AM	V-176AV007	Valve Condition	Fair
WO-55056	1	Completed	44426.40866	44426	Valve Maintenance Report	August 18, 2021, 10:03 AM	V-176AV008	Valve Condition	
WO-55027	1	Completed	44426.35583	44426	Valve Maintenance Report	August 18, 2021, 8:53 AM	V-176AV014	Valve Condition	
WO-55026	1	Completed	44426.35284	44426	Valve Maintenance Report	August 18, 2021, 8:52 AM	V-176AV015	Valve Condition	
WO-54670	1	Completed	44421.38448	44421	Valve Maintenance Report	August 13, 2021, 9:19 AM	V-176AV020	Valve Condition	Good
WO-54670	1	Completed	44421.38448	44421	Valve Maintenance Report	August 13, 2021, 9:19 AM	V-176AV021	Valve Condition	Good
WO-54670	1	Completed	44421.38448	44421	Valve Maintenance Report	August 13, 2021, 9:19 AM	V-176AV022	Valve Condition	Good
WO-55115	1	Completed	44426.54818	44426	Valve Maintenance Report	August 18, 2021, 1:15 PM	V-176AV024	Valve Condition	
WO-52259	1	Completed	44393.56801	44393	Valve Maintenance Report	July 16, 2021, 1:46 PM	V-176AV027	Valve Condition	Good
WO-51591	1	Completed	44386.56272	44386	Valve Maintenance Report	July 9, 2021, 1:51 PM	V-176AV028	Valve Condition	
WO-51593	1	Completed	44386.567	44386	Valve Maintenance Report	July 9, 2021, 1:53 PM	V-176AV029	Valve Condition	Good
WO-42304	1	Completed	44307.36624	44308	Valve Maintenance Report	April 22, 2021, 7:45 AM	V-176AV030	Valve Condition	Good
WO-55037	1	Completed	44426.37825	44426	Valve Maintenance Report	August 18, 2021, 10:03 AM	V-176AV032	Valve Condition	
WO-41359	1	Completed	44298.4314	44299	Valve Maintenance Report	April 13, 2021, 7:55 AM	V-176AV033	Valve Condition	Good
WO-51573	1	Completed	44386.46657	44386	Valve Maintenance Report	July 9, 2021, 11:15 AM	V-176BV001	Valve Condition	
WO-51570	1	Completed	44386.45147	44386	Valve Maintenance Report	July 9, 2021, 11:03 AM	V-176BV002	Valve Condition	
WO-51568	1	Completed	44386.44959	44386	Valve Maintenance Report	July 9, 2021, 11:02 AM	V-176BV003	Valve Condition	
WO-41359	1	Completed	44298.4314	44299	Valve Maintenance Report	April 13, 2021, 7:55 AM	V-176BV006	Valve Condition	
WO-41359	1	Completed	44298.4314	44299	Valve Maintenance Report	April 13, 2021, 7:55 AM	V-176BV007	Valve Condition	
WO-55180	1	Completed	44427.40014	44427	Valve Maintenance Report	August 19, 2021, 10:15 AM	V-176EV002	Valve Condition	
WO-55182	1	Completed	44427.40203	44427	Valve Maintenance Report	August 19, 2021, 10:16 AM	V-176EV005	Valve Condition	
WO-55196	1	Completed	44427.44047	44427	Valve Maintenance Report	August 19, 2021, 10:49 AM	V-176EV013	Valve Condition	
WO-51460	1	Completed	44385.53137	44385	Valve Maintenance Report	July 8, 2021, 1:23 PM	V-176EV014	Valve Condition	Good
WO-51393	1	Completed	44385.38589	44385	Valve Maintenance Report	July 8, 2021, 9:27 AM	V-176EV016	Valve Condition	
WO-51462	1	Completed	44385.53508	44385	Valve Maintenance Report	July 8, 2021, 1:25 PM	V-176EV017	Valve Condition	
WO-51461	1	Completed	44385.5332	44385	Valve Maintenance Report	July 8, 2021, 1:24 PM	V-176EV018	Valve Condition	Good
WO-51394	1	Completed	44385.38719	44385	Valve Maintenance Report	July 8, 2021, 9:28 AM	V-176EV019	Valve Condition	
WO-51488	1	Completed	44385.57526	44385	Valve Maintenance Report	July 8, 2021, 1:57 PM	V-176EV022	Valve Condition	
WO-55204	1	Completed	44427.47326	44427	Valve Maintenance Report	August 19, 2021, 11:26 AM	V-176EV025	Valve Condition	
WO-51383	1	Completed	44385.35442	44385	Valve Maintenance Report	July 8, 2021, 8:51 AM	V-176EV027	Valve Condition	
WO-51382	1	Completed	44385.35278	44385	Valve Maintenance Report	July 8, 2021, 8:49 AM	V-176EV030	Valve Condition	
WO-51385	1	Completed	44385.35751	44385	Valve Maintenance Report	July 8, 2021, 8:59 AM	V-176EV032	Valve Condition	
WO-51384	1	Completed	44385.35612	44385	Valve Maintenance Report	July 8, 2021, 8:58 AM	V-176EV033	Valve Condition	Good
WO-52239	1	Completed	44393.45492	44393	Valve Maintenance Report	July 16, 2021, 11:12 AM	V-176FV001	Valve Condition	
WO-52238	1	Completed	44393.45303	44393	Valve Maintenance Report	July 16, 2021, 11:11 AM	V-176FV002	Valve Condition	
WO-52241	1	Completed	44393.45635	44393	Valve Maintenance Report	July 16, 2021, 11:13 AM	V-176FV003	Valve Condition	
WO-55627	1	Completed	44433.39984	44433	Valve Maintenance Report	August 25, 2021, 9:40 AM	V-176JV002	Valve Condition	Good
WO-55230	1	Completed	44427.57222	44427	Valve Maintenance Report	August 19, 2021, 2:08 PM	V-176JV003	Valve Condition	
WO-51308	1	Completed	44384.48211	44384	Valve Maintenance Report	July 7, 2021, 11:53 AM	V-176JV005	Valve Condition	Good
WO-51309	1	Completed	44384.4838	44384	Valve Maintenance Report	July 7, 2021, 11:53 AM	V-176JV006	Valve Condition	
WO-51310	1	Completed	44384.49056	44384	Valve Maintenance Report	July 7, 2021, 11:58 AM	V-176JV007	Valve Condition	
WO-51317	1	Completed	44384.55218	44384	Valve Maintenance Report	July 7, 2021, 1:29 PM	V-176JV008	Valve Condition	
WO-51318	1	Completed	44384.55414	44384	Valve Maintenance Report	July 7, 2021, 1:29 PM	V-176JV009	Valve Condition	
WO-51322	1	Completed	44384.56001	44384	Valve Maintenance Report	July 7, 2021, 1:40 PM	V-176JV010	Valve Condition	Good
WO-50917	1	Completed	44379.48952	44379	Valve Maintenance Report	July 2, 2021, 11:58 AM	V-176JV012	Valve Condition	
WO-55631	1	Completed	44433.40904	44433	Valve Maintenance Report	August 25, 2021, 9:52 AM	V-176JV015	Valve Condition	
WO-55633	1	Completed	44433.41682	44433	Valve Maintenance Report	August 25, 2021, 10:02 AM	V-176JV016	Valve Condition	
WO-50921	1	Completed	44379.507	44379	Valve Maintenance Report	July 2, 2021, 1:07 PM	V-176NV006	Valve Condition	Good
WO-50918	1	Completed	44379.49055	44379	Valve Maintenance Report	July 2, 2021, 11:56 AM	V-176NV012	Valve Condition	
WO-51320	1	Completed	44384.55793	44384	Valve Maintenance Report	July 7, 2021, 1:39 PM	V-176VV001	Valve Condition	
WO-49985	1	Completed	44371.54001	44371	Valve Maintenance Report	June 24, 2021, 1:17 PM	V-177AV002	Valve Condition	
WO-49982	1	Completed	44371.53839	44371	Valve Maintenance Report	June 24, 2021, 1:09 PM	V-177AV003	Valve Condition	Fair

PWSA Report Valves Exercised 2021
Per Section III.9.E.1.a.iv of the Joint Petition for Settlement at Docket No. R-2021-3024773

Work Order Number	Work Order Type ID	Work Order Status	Created Date	Scheduled Date	Description	Field Completed Date	Asset Name	Label	Valve Condition
WO-49979	1	Completed	44371.53577	44371	Valve Maintenance Report	June 24, 2021, 1:07 PM	V-177AV005	Valve Condition	Good
WO-50641	1	Completed	44377.43882	44377	Valve Maintenance Report	June 30, 2021, 11:01 AM	V-177AV007	Valve Condition	
WO-50579	1	Completed	44377.37144	44377	Valve Maintenance Report	June 30, 2021, 8:59 AM	V-177AV008	Valve Condition	Good
WO-49999	1	Completed	44371.56441	44371	Valve Maintenance Report	June 24, 2021, 2:12 PM	V-177AV009	Valve Condition	Good
WO-50007	1	Completed	44371.59358	44371	Valve Maintenance Report	June 24, 2021, 2:16 PM	V-177AV010	Valve Condition	Poor
WO-50606	1	Completed	44377.3995	44377	Valve Maintenance Report	June 30, 2021, 9:37 AM	V-177AV012	Valve Condition	Good
WO-50578	1	Completed	44377.36881	44377	Valve Maintenance Report	June 30, 2021, 8:58 AM	V-177AV014	Valve Condition	
WO-50568	1	Completed	44377.34908	44377	Valve Maintenance Report	June 30, 2021, 8:29 AM	V-177AV016	Valve Condition	Good
WO-50570	1	Completed	44377.34994	44377	Valve Maintenance Report	June 30, 2021, 8:30 AM	V-177AV017	Valve Condition	
WO-56885	1	Completed	44447.40209	44447	Valve Maintenance Report	September 8, 2021, 9:41 AM	V-177AV019	Valve Condition	
WO-50616	1	Completed	44377.41388	44377	Valve Maintenance Report	June 30, 2021, 10:05 AM	V-177EV004	Valve Condition	Good
WO-48916	1	Completed	44363.5836	44363	Valve Maintenance Report	June 16, 2021, 2:08 PM	V-177EV006	Valve Condition	Good
WO-48902	1	Completed	44363.5547	44363	Valve Maintenance Report	June 16, 2021, 1:24 PM	V-177EV007	Valve Condition	Good
WO-48898	1	Completed	44363.54621	44363	Valve Maintenance Report	June 16, 2021, 1:13 PM	V-177EV009	Valve Condition	
WO-50618	1	Completed	44377.41587	44377	Valve Maintenance Report	June 30, 2021, 10:06 AM	V-177EV010	Valve Condition	Good
WO-55240	1	Completed	44427.98082	44463	Repair water main	September 24, 2021, 10:46 AM	V-177EV011	Valve Condition	
WO-50671	1	Completed	44377.5418	44377	Valve Maintenance Report	June 30, 2021, 1:04 PM	V-177IV006	Valve Condition	
WO-56374	1	Completed	44440.55858	44440	Valve Maintenance Report	September 1, 2021, 1:28 PM	V-177NV001	Valve Condition	
WO-50681	1	Completed	44377.58227	44377	Valve Maintenance Report	June 30, 2021, 5:52 PM	V-177NV005	Valve Condition	
WO-50682	1	Completed	44377.58402	44377	Valve Maintenance Report	June 30, 2021, 5:52 PM	V-177NV006	Valve Condition	
WO-56389	1	Completed	44440.57155	44440	Valve Maintenance Report	September 1, 2021, 2:20 PM	V-177NV022	Valve Condition	Fair
WO-44021	1	Completed	44323.35144	44323	Valve Maintenance Report	May 7, 2021, 8:27 AM	V-178AV008	Valve Condition	
WO-44022	1	Completed	44323.35381	44323	Valve Maintenance Report	May 7, 2021, 8:31 AM	V-178AV011	Valve Condition	
WO-56268	1	Completed	44440.40507	44440	Valve Maintenance Report	September 1, 2021, 10:29 AM	V-178AV014	Valve Condition	
WO-56268	1	Completed	44440.40507	44440	Valve Maintenance Report	September 1, 2021, 10:29 AM	V-178AV015	Valve Condition	
WO-56268	1	Completed	44440.40507	44440	Valve Maintenance Report	September 1, 2021, 10:29 AM	V-178AV016	Valve Condition	
WO-56268	1	Completed	44440.40507	44440	Valve Maintenance Report	September 1, 2021, 10:29 AM	V-178AV018	Valve Condition	
WO-56268	1	Completed	44440.40507	44440	Valve Maintenance Report	September 1, 2021, 10:29 AM	V-178AV019	Valve Condition	
WO-44171	1	Completed	44326.04146	44326	Valve Maintenance Report	May 10, 2021, 1:41 AM	V-178EV007	Valve Condition	
WO-44675	1	Completed	44329.464	44329	Valve Maintenance Report	May 13, 2021, 11:31 AM	V-178EV008	Valve Condition	
WO-39406	683	Completed	44273.41308	44270	Work site details for reporting	March 19, 2021, 7:39 AM	V-228FV001	Valve Condition	
WO-34703	1	Completed	44223.49745	44228	Repair water main		V-228FV004	Valve Condition	
WO-63526	1	Completed	44515.41387	44510	Valve Maintenance Report		V-228FV007	Valve Condition	
WO-61292	703	Completed	44490.38557	44524	Installing unmapped valve	December 3, 2021, 2:21 PM	V293	Valve Condition	Good
WO-61292	703	Completed	44490.38557	44524	Installing unmapped valve	December 3, 2021, 2:21 PM	V294	Valve Condition	Good
WO-61292	703	Completed	44490.38557	44524	Installing unmapped valve	December 3, 2021, 2:21 PM	V295	Valve Condition	Good
WO-61292	703	Completed	44490.38557	44524	Installing unmapped valve	December 3, 2021, 2:21 PM	V296	Valve Condition	Good