



COMMONWEALTH OF PENNSYLVANIA
PENNSYLVANIA PUBLIC UTILITY COMMISSION
COMMONWEALTH KEYSTONE BUILDING
400 NORTH STREET, HARRISBURG, PA 17120

BUREAU OF
INVESTIGATION
&
ENFORCEMENT

May 20, 2025

Via Electronic Filing

Matthew L. Homsher, Secretary
Pennsylvania Public Utility Commission
Commonwealth Keystone Building
400 North Street
Harrisburg, PA 17120

Re: Pennsylvania Public Utility Commission,
Bureau of Investigation and Enforcement v.
Dalton Sewer Authority
Docket No. C-2025-
I&E Formal Complaint (Damage Prevention)

Dear Secretary Homsher:

Enclosed for electronic filing please find the Formal Complaint of the Bureau of Investigation and Enforcement of the Pennsylvania Public Utility Commission in the above-referenced matter.

Copies are being served on the parties of record in accordance with the attached Certificate of Service.

Should you have any questions, please do not hesitate to contact me.

Sincerely,

A handwritten signature in blue ink, appearing to read 'G. Rosul', is written over a light blue horizontal line.

Grant Rosul
Prosecutor
Bureau of Investigation and Enforcement
PA Attorney ID No. 318204
(717) 783-5243
grosul@pa.gov

GR/ac
Enclosures

cc: Michael L. Swindler, Deputy Chief Prosecutor, I&E-Enf (via email - mswindler@pa.gov)
Robert Horensky, Manager, Safety Division (via email - rhorensky@pa.gov)
As per Certificate of Service

NOTICE

A. You must file an Answer within twenty (20) days of the date of service of this Complaint. The date of service is the date as indicated at the top of the Secretarial Letter. *See* 52 Pa. Code § 1.56(a). The Answer must raise all factual and legal arguments that you wish to claim in your defense, include the docket number of this Complaint, and be verified. Pursuant to *Suspension of Regulatory and Statutory Deadlines; Modification to Filing and Service Requirements*, Docket No. M-2020-3019262 (Emergency Order ratified on March 20, 2020), you must eFile your Answer using the Commission’s website at www.puc.pa.gov. The link to eFiling is located under the Filing & Resources tab on the homepage.

In addition to filing your Answer with the Commission’s Secretary, please electronically serve a copy on:

Grant Rosul, Prosecutor
Pennsylvania Public Utility Commission
Bureau of Investigation and Enforcement
grosul@pa.gov

B. If you fail to answer this Complaint within twenty (20) days, the Bureau of Investigation and Enforcement will request that the Commission issue an Order imposing the administrative penalty and other requested relief.

C. You may elect not to contest this Complaint by paying the administrative penalty within twenty (20) days and performing the corrective actions, if any, set forth in the requested relief. A certified check, cashier’s check or money order should be payable to the “Commonwealth of Pennsylvania” and mailed to:

Matthew L. Homsher, Secretary
Pennsylvania Public Utility Commission
Commonwealth Keystone Building
400 North Street
Harrisburg, PA 17120

Your payment is an admission that you committed the alleged violations and an agreement to cease and desist from committing further violations. Upon receipt of your payment, the Complaint proceeding shall be closed.

D. If you file an Answer, which either admits or fails to deny the allegations of the Complaint, the Bureau of Investigation and Enforcement will request the Commission to issue an Order imposing the administrative penalty and granting the requested relief as set forth in the Complaint.

E. If you file an Answer which contests the Complaint, the matter will proceed before the assigned presiding Administrative Law Judge for hearing and decision. The Judge is not bound by the penalty set forth in the Complaint, and may impose additional and/or alternative penalties as appropriate.

F. If you are a corporation, you must be represented by legal counsel. 52 Pa. Code § 1.21.

G. Alternative formats of this material are available for persons with disabilities by contacting the Commission’s ADA Coordinator at (717) 787-8714.

**BEFORE THE
PENNSYLVANIA PUBLIC UTILITY COMMISSION**

Pennsylvania Public Utility Commission,	:	
Bureau of Investigation and Enforcement,	:	
Complainant	:	
	:	
v.	:	Docket No. C-2025-
	:	
Dalton Sewer Authority,	:	
Respondent	:	

FORMAL COMPLAINT

NOW COMES the Bureau of Investigation and Enforcement (“I&E”) of the Pennsylvania Public Utility Commission, by its prosecuting attorneys, pursuant to Section 182 of the Underground Utility Line Protection Law (“UULPL” or “PA One Call Law”), Act of Act of October 29, 2024, P.L. 1106, No. 127, 73 P.S. § 182.8(c)(2), and files this Formal Complaint (“Complaint”) against Dalton Sewer Authority (“Respondent”) alleging violations of the PA One Call Law in connection with a line strike on a PPL underground electric secondary service cable in the vicinity of 80 Old Loggers Road, LaPlume Township, Lackawanna County, Pennsylvania. The violation alleged herein relates to the Respondent’s failure to respond to routine locate requests from an excavator. In support of its Complaint, I&E respectfully avers as follows:

I. COMMISSION JURISDICTION AND AUTHORITY

1. The Pennsylvania Public Utility Commission (“Commission” or “PUC”), with a mailing address of Commonwealth Keystone Building, 400 North Street, Harrisburg, PA 17120, is a duly constituted agency of the Commonwealth of Pennsylvania empowered to regulate, *inter alia*, facility owners, within the Commonwealth pursuant to the PA One Call Law, Act of October 29, 2024, P.L. 1106, No. 127, 73 P.S. §§ 176 *et seq.*

2. Complainant is the Commission’s Bureau of Investigation and Enforcement, which is the bureau established to take enforcement actions against public utilities and other entities subject to the Commission’s jurisdiction pursuant to 66 Pa.C.S. § 308.2(a)(11). *See also Implementation of Act 129 of 2008; Organization of Bureaus and Offices*, Docket No. M-2008-2071852 (August 11, 2011) (delegating authority to initiate proceedings that are prosecutory in nature to I&E).

3. Complainant’s prosecuting attorney is as follows:

Grant Rosul
Prosecutor
grosul@pa.gov
(717) 783-5243

Pennsylvania Public Utility Commission
Bureau of Investigation and Enforcement
Commonwealth Keystone Building
400 North Street
Harrisburg, PA 17120

4. Respondent is Dalton Sewer Authority, with a main mailing address of P.O. Box 538, Dalton, PA 18414.

5. Dalton Sewer Authority is a “facility owner,” as that term is defined in Section 176 of the PA One Call Law, 73 P.S. § 176.¹

6. Section 177 of the PA One Call Law, 73 P.S. § 177, imposes duties on facility owners.

7. Section 177(5)(v) of the PA One Call Law, 73 P.S. § 177(5)(v), requires facility owners to respond to all notices through the One Call System, provided the request is made in the time frame set forth under this act. The response shall be made not later than the end of the

¹ “Facility owner” is defined as “the public utility or agency, political subdivision, municipality, **authority**, rural electric cooperative or other person or entity who or which owns or operates a line.” 73 P.S. § 176 (emphasis added).

second business day following receipt of the notification by the One Call System, excluding the business day upon which the notification is received, or not later than the day prior to the lawful start date of excavation if the excavator specifies a later date or, in the case of an emergency, to respond through the One Call System as soon as practicable following receipt of notification of the emergency by the One Call System.” 73 P.S. § 177(5)(v).

8. Respondent, as a facility owner, is subject to the authority of this Commission pursuant to Section 182.10 of the PA One Call Law, 73 P.S. § 182.10, which requires facility owners to comply with the PA One Call Law. 73 P.S. § 182.10.

9. Section 182.8(c)-(d) and Section 182.10 of the PA One Call Law, 73 P.S. §§ 182.8(c)-(d) and 182.10, authorize the Commission to, *inter alia*, hear and determine complaints against facility owners for violations of the PA One Call Law and to enforce the provisions of the PA One Call Law. 73 P.S. §§ 182.8(c)-(d) and 182.10.

10. Section 182.8(c)(2) of the PA One Call Law, 73 P.S. § 182.8(c)(2), authorizes the Commission’s prosecutorial staff to bring a formal complaint against entities subject to the PA One Call Law. 73 P.S. § 182.8(c)(2).

11. Section 182.10 of the PA One Call Law, 73 P.S. § 182.10(b)(1)(i)-(ii), authorizes the Commission to impose administrative penalties on any person or corporation, subject to the PA One Call Law, who violates any provisions of the PA One Call Law or any regulation or order issued thereunder governing underground utility lines, of up to \$2,500 per violation or if the violation results in injury, death, or property damage of \$25,000 or more an administrative penalty not to exceed \$50,000. 73 P.S. § 182.10(b)(1)(i)-(ii).

12. Pursuant to the provisions of the applicable Commonwealth statutes and regulations, the Commission has jurisdiction over the subject matter of this Complaint and the actions of Respondent related thereto.

II. FACTUAL BACKGROUND

13. On February 5, 2024, Friendly Underground Construction (“Friendly”) was excavating with a pneumatic missile while installing fiber optic cable on behalf of Frontier Communications (“Frontier”) in the vicinity of 80 Old Loggers Road, LaPlume Township, Lackawanna County, Pennsylvania, when it struck an underground electric secondary service cable belonging to PPL. I&E Exhibit 1.

14. Although there were no injuries, one PPL customer was without power for an unknown amount of time.

15. Dalton Sewer Authority is the facility owner of a wastewater line in the area where the excavation took place.

16. Friendly submitted three locations requests, known as “Tickets,” to the Pennsylvania One Call System (“POCS”) in connection with the excavation that resulted in the February 2024 line strike incident.

17. Routine Excavation Ticket 20240122488 was submitted by Friendly on January 12, 2024, with a required response due date from facility owners of January 17, 2024. Dalton Sewer Authority did not respond to this Ticket, and the Ticket was marked “NO RESPONSE” on January 18, 2024. I&E Exhibit 2.

18. Routine Excavation Ticket 20240150570 was submitted by Friendly on January 15, 2024, with a required response due date from facility owners of January 18, 2024. Dalton

Sewer Authority did not respond to this Ticket, and the Ticket was marked “NO RESPONSE” on January 19, 2024.² I&E Exhibit 3.

19. On December 9, 2024, a copy of the report prepared by the Damage Prevention Investigator (“DPI”) from the Commission’s Bureau of Investigation and Enforcement, Damage Prevention Section, was mailed to Dalton Sewer Authority informing Respondent that it was in violation of the PA One Call Law by failing to respond to a routine One Call ticket.

20. In the letter from the DPI, the Respondent was informed that it could either accept the findings and pay the assessed administrative penalty or reject the DPI report and present its case before the Damage Prevention Committee (“DPC”) by informing the DPI in writing of its rejection within thirty days of the date of the letter.

21. On December 16, 2024, Dalton Sewer Authority rejected the findings in the DPI’s report and requested to present its case before the DPC.

22. On January 6, 2025, a notice of the DPC meeting was sent to Dalton Sewer Authority, informing Respondent that it could present its case for discussion at the February 11, 2025, DPC meeting.

23. Dalton Sewer Authority failed to appear to present its case to the DPC at the February 11, 2025, meeting. Nevertheless, its case was discussed and voted upon.

24. On February 13, 2025, a copy of the DPC’s Informal Determination accepting the DPI’s report and proposed administrative penalty was mailed to Dalton Sewer Authority, informing Respondent that it could either accept the DPC’s Informal Determination or reject it in writing within thirty (30) days of the date of the notification letter, and that if the Informal

² Friendly also submitted a Routine Excavation Ticket at 20240150522 on January 15, 2024. This ticket was placed 8 minutes prior to Ticket 20240150570 for the same excavation location. Thus, I&E will treat both Tickets as functionally one locate request. Dalton Sewer Authority also did not provide a response to Ticket 20240150522.

Determination is rejected the case may be sent to I&E prosecutory staff for issuance of a formal complaint.

25. On February 24, 2025, Respondent rejected the DPC's informal determination via letter.

III. VIOLATIONS

26. Paragraphs 1-25 are incorporated herein as if stated in their entirety.

Counts 1 and 2

27. Respondent failed to respond to a routine PA One Call Ticket within the statutorily required amount of time (2 counts).

If proven, this is a violation of Section 177(5)(v) of the PA One Call Law, 73 P.S. § 177(5)(v). As a facility owner, Respondent had the duty “[t]o respond to all notices through the One Call System, provided the request is made in the time frame set forth under this act. The response shall be made not later than the end of the second business day following receipt of the notification by the One Call System, excluding the business day upon which the notification is received, or not later than the day prior to the lawful start date of excavation if the excavator specifies a later date....” 73 P.S. § 177(5)(v).

Here, Respondent was obligated to provide a response to the excavator, Friendly Underground Construction, through POCS by January 17, 2024, for Routine Excavation Ticket 20240122488 and by January 18, 2024, for Routine Excavation Ticket 20240150570. However, no response was provided by Dalton Sewer Authority to either Ticket.

While neither Dalton Sewer Authority nor its facilities were involved in the line strike incident, the failure to respond to an excavator's locate request is independently a violation of the PA One Call Law.

The Bureau of Investigation and Enforcement's proposed cumulative administrative penalty for this violation is \$2,000, or \$1,000 per count.

WHEREFORE, for all the foregoing reasons, the Pennsylvania Public Utility Commission's Bureau of Investigation and Enforcement respectfully requests that the Commission:

- (1) Find Dalton Sewer Authority to be in violation of the PA One Call Law at: §§ 177(5)(v);
- (2) Impose a cumulative administrative penalty upon Dalton Sewer Authority in the amount of \$2,000;
- (3) Order Dalton Sewer Authority to attend Online Compliance Training through the Pennsylvania One Call System for facility owners and provide proof of compliance to the Commission within thirty (30) days of the entry of a Final Commission Order;
- (4) Order such other remedies as the Commission may deem appropriate.

Respectfully submitted,



Grant Rosul
Prosecutor
PA Attorney ID No. 318204

Pennsylvania Public Utility Commission
Bureau of Investigation and Enforcement
Commonwealth Keystone Building
400 North Street
Harrisburg, PA 17120
(717) 783-5243
grosul@pa.gov

Date: May 20, 2025


**BEFORE THE
PENNSYLVANIA PUBLIC UTILITY COMMISSION**

Pennsylvania Public Utility Commission,	:	
Bureau of Investigation and Enforcement,	:	
Complainant	:	
	:	
v.	:	Docket No. C-2025-
	:	
Dalton Sewer Authority,	:	
Respondent	:	

VERIFICATION

I, Sara Andrade-Locke, Damage Prevention Supervisor, Damage Prevention Section, Bureau of Investigation and Enforcement, hereby state that the facts above set forth are true and correct to the best of my knowledge, information, and belief and that I expect that the Bureau of Investigation and Enforcement will be able to prove the same at any hearing held in this matter. I understand that the statements herein are made subject to the penalties of 18 Pa.C.S. § 4904 relating to unsworn falsification to authorities.

Date: May 20, 2025



Sara Andrade-Locke
Damage Prevention Supervisor
Damage Prevention Section
Pennsylvania Public Utility Commission
Bureau of Investigation and Enforcement
Commonwealth Keystone Building
400 North Street
Harrisburg, PA 17120

I&E Exhibit 1



Alleged Violation Report

PA Act 287, as amended 73 P. S. § 176 et. seq.
Powered by Pennsylvania One Call System, Inc.

AVR Number AVR2024FEB060009

AVR Version 1

First Name STEPHEN **Last Name** KRAUSE

Company Name PPL ELECTRIC UTILITIES CORPORATION

Address 1801 BROOKWOOD ST

City HARRISBURG

State PA

Zip Code 17104

Email STKRAUSE@PPLWEB.COM **Phone** 717-926-3357

Ext

Role

- Submitter Role(s) (?)**
- Facility Owner
 - Excavator
 - Locator
 - Other
 - Designer
 - Project Owner
 - Enforcement Agency

Are you representing a company other than your own? Yes No

What company or individual are you representing?

Alleged Violation Information

PUC Case Number (if known)

Related AVR Number (?)

Type of Alleged Violation (?) Excavator Issue

Reason Failed to use prudent techniques in the tolerance zone §5(4)

When did the alleged violation occur? (?) 02/05/2024
12:37:00 PM

Was the One Call System notified? Yes No

Original Serial Number

Please enter the 11 digit One Call Serial Number under which work was taking place, which will populate the work site information of this alleged violation.

20240122488

Related Damage Serial Number, if applicable

20240362672

Other Related Serial Numbers (?)

20240150522

Other Related Serial Numbers (?)

20240150570

Was the excavation exempt from One Call notification? Yes No Unknown

Reason for Exemption

Event Information



County

LACKAWANNA

Municipality

LAPLUME TWP

Ward

0

Work Site

OLD LOGGERS RD

Nearest Intersection

APPLE TREE RD

Second Intersection

TIMBER TRL

Geolocation (?)

Affected Facility Information



Primary Right of Way Type

Private

Public Right of Way Type

Private Right of Way Type

Land Owner

Affected Operation

Electric

Facility Subtype Affected

Service/Drop/Lateral

Facility Owner Company Name

PPL Electric Utilities

Contact First Name

Stephen

Last Name

Krause

Address

1801 Brookwood Street

City

Harrisburg

State

PA

Zip 17104

Email stkrause@pplweb.com Phone 717-926-3357

Joint Trench? Yes No Unknown

Involve Cross Bore? Yes No Unknown

Measured Depth from Grade 18" - 36" / 46 - 91 cm

Exact Measured Depth from Grade Enter the inches or centimeters with number and measurement used

Work Information

Start Date of Excavation (?)

Excavation Activity INSTALLING UTILITIES

Excavator Company Name Friendly Underground Construction, LLC

Contact First Name Merlin Last Name Serrano

Address 525 Main Street

City Dundalk

State MD

Zip 21222

Email friendlyunderground@gm ail.com Phone 443-630-1163

Marked in White Yes No Unknown

Method of Excavation HORIZONTAL DIRECTIONAL DRILLING

Equipment Used What Equipment was used for excavation or demolition when the event occurred?
UNKNOWN/OTHER

Type of Excavator What is the type of excavator for whom the work was being done when the event occurred?
Other

Did Excavator incur down time? Yes No Unknown

How much down time?

Estimated cost of down time

Was a response posted to the One Call System? Yes No Unknown

Was the design serial number on the plans/bid documents? Yes No Unknown

Were the lines shown on the plans/bid documents? Yes No Unknown

What level of subsurface utility engineering was utilized?

Estimated cost of the entire project

What was the length of the entire project?

Project Owner Company Name Frontier Communications

Contact First Name Last Name

Address

City

State

Zip

Email Phone

Event Impact



Did Violation result in underground damage or near miss event? Damage

OSHA Report Filed? Yes No

OSHA Report Number

Was 911 called? Yes No

Name of 911 Caller

Fire Response Yes No

Police Response Yes No

Did the incident cause any injuries? Yes

Number of Injuries (?)

Did the incident cause any deaths? Yes

Number of Deaths

Was there an evacuation? Yes No

Number of people evacuated?

Traffic Stopped? Yes No

Service Interrupted? Yes No

Duration of Service Interruption? 1 - < 6 hrs

Exact Value of Service Interruption

Approximately how many customers were affected? 1

Exact Number of Customers Affected

Cost of Damaged Line Repair? \$1,001-\$5,000

Exact Cost of Damaged Line Repair

Was other property damaged? Yes No

What other property was damaged?

Cost of Other Property Repair

Locator/Locate Information

Who was the facility line locator? Contract Locator

Locator Company USIC

Contact First Name Daylin Last Name Knaub

Address 1737 West Trindle Road

City Carlisle

State PA

Zip 17015

Email daylinknaub@usicllc.com Phone 717-443-5687

Was the line marked? Accurately Inaccurately/Incompletely Not Marked
 Unknown

Were facilities marked according to APWA/CGA temporary marking color code (ANSI standard Z535.1)? Yes No Unknown

What types of marks were present? Paint Flags Stakes Other

Were offset markings used? Yes No Unknown

Condition of Marks Readily Visible

Was the line marked by the response due date or within the agreed upon locate schedule? (?) Yes No Unknown

Reason for Late Locate

Was the excavation within the tolerance zone? (?) Yes No Unknown

Was there an indication of underground facilities (clear evidence) in the excavation area? Yes No Unknown

What was the evidence?
(meter/pedestal, pipeline marker, valve
box, hydrant, manhole, etc.)

What method(s) were used to locate
the facility? Electronic Records
 Visual Exposed

Did the excavator request payment
under PennDOT Form 408
specifications for extra work
performed on a force account basis? Yes No

Additional Locate Comments Locators credentials available upon request.
If this incident involved any locating/marketing errors, please include all records related to the
locator's training and qualification (including training to meet UULPL standards as well as
Operator Qualification).

Summary and Attachments

Provide a summary of the event On Monday, 2/5/2004 at approximately 1237 a non-PPL contractor
from Friendly Underground Construction contacted an underground
electric secondary / service cable with a pneumatic missile while
installing fiber optic communications lines for Frontier
Communications near 80 Old Loggers Road, Factoryville, La
Plume Township, Lackawanna County.
There were no reported injuries. One customer lost electric service.
The contractor was working with a valid PA One Call ticket.
PPL Public Safety and USIC investigations determined the
damaged service was accurately marked. The excavator is in
violation of using powered excavation equipment within the
tolerance zone of a marked facility.

If more space is needed, attach additional pages or documents.

Attachments	
80 Old Loggers Rd_Field Smart View.JPG	184.72KB
20240122488 KARL Response.pdf	61.79KB
20240122488 Locate Ticket Photo (1).jpg	157.62KB
20240122488 Locate Ticket Photo (2).jpg	172.84KB
20240122488 Locate Ticket Photo (3).jpg	168.87KB
20240122488 Locate Ticket Photo (4).jpg	209.74KB
20240122488 Locate Ticket Photo (5).jpg	176.94KB
20240122488 Locate Ticket Photo (6).jpg	187.81KB
20240122488 Locate Ticket Photo (7).jpg	178.16KB
20240122488 Locate Ticket Photo (8).jpg	167.35KB
20240122488 Locate Ticket Photo (9).jpg	172.19KB
20240122488 Locate Ticket Photo (10).jpg	179.32KB
20240122488 Locate Ticket Photo (11).jpg	185.61KB
20240122488 Locate Ticket Photo (12).jpg	185.61KB
20240122488 Locate Ticket Photo (13).jpg	157.41KB
20240122488 Locate Ticket Photo (14).jpg	160.42KB
20240122488 Locate Ticket Photo (15).jpg	197.28KB

20240122488 Locate Ticket Photo (16).jpg	192.36KB
20240122488 Locate Ticket Photo (17).jpg	188.19KB
20240122488 Locate Ticket Photo (18).jpg	173.52KB
20240122488 Locate Ticket Photo (19).jpg	173.32KB
20240122488 Locate Ticket Photo (20).jpg	152.11KB
20240122488 Locate Ticket Photo (21).jpg	161.73KB
20240122488 Locate Ticket Photo (22).jpg	159.82KB
20240122488 Locate Ticket Photo (23).jpg	167.29KB
20240122488 Locate Ticket Photo (24).jpg	151.42KB
20240122488 Locate Ticket Photo (25).jpg	149.28KB
20240122488 Locate Ticket Photo (26).jpg	140.36KB
20240122488 Locate Ticket Photo (27).jpg	168.02KB
20240122488 Locate Ticket Photo (28).jpg	152.83KB
20240122488 Locate Ticket Photo (29).jpg	174.99KB
20240122488 Locate Ticket Photo (30).jpg	169.3KB
20240122488 Locate Ticket Photo (31).jpg	90.49KB
20240122488 Locate Ticket Photo (32).jpg	153.57KB
20240122488 Locate Ticket Photo (33).jpg	122.3KB
20240122488 Locate Ticket Photo (34).jpg	148.12KB
20240122488 Locate Ticket Photo (35).jpg	167.54KB
20240122488 Locate Ticket Photo (36).jpg	177.99KB
20240122488 Locate Ticket Photo (37).jpg	128.25KB
20240122488 Locate Ticket Photo (38).jpg	145.36KB
20240122488 Locate Ticket Photo (39).jpg	140.04KB
20240122488 Locate Ticket Photo	170.60KB

(40).jpg	129.59KB
20240122488 Locate Ticket Photo	168.32KB
(41).jpg	
20240122488 Locate Ticket Photo	165.4KB
(42).jpg	
20240122488 Locate Ticket Photo	155.6KB
(43).jpg	
20240122488 Locate Ticket Photo	154.31KB
(44).jpg	
20240122488 Locate Ticket Photo	157.02KB
(45).jpg	
20240122488 Locate Ticket Photo	170.94KB
(46).jpg	
20240122488 Locate Ticket Photo	162.39KB
(47).jpg	
20240122488 Locate Ticket Photo	156.98KB
(48).jpg	
20240122488 Locate Ticket Photo	165.06KB
(49).jpg	
20240122488 Locate Ticket Photo	160.63KB
(50).jpg	
20240122488 Locate Ticket Photo	165.84KB
(51).jpg	
20240122488 Locate Ticket Photo	134.64KB
(52).jpg	
20240122488 Locate Ticket Photo	167.18KB
(53).jpg	
20240122488 Locate Ticket Photo	177.46KB
(54).jpg	
20240122488 Locate Ticket Photo	180.41KB
(55).jpg	
20240122488 Locate Ticket Photo	159.85KB
(56).jpg	
20240122488 Locate Ticket Photo	148.42KB
(57).jpg	
20240122488 Locate Ticket Photo	177.14KB
(58).jpg	
20240122488 Locate Ticket Photo	175.05KB
(59).jpg	
20240122488 Locate Ticket Photo	173.61KB
(60).jpg	
20240122488 Locate Ticket Photo	176.7KB
(61).jpg	
20240122488 Locate Ticket Photo	173.24KB
(62).jpg	
20240122488 Locate Ticket Photo	171.1KB
(63).jpg	
20240122488 Locate Ticket Photo	166.26KB
(64).jpg	

20240122488 Locate Ticket Photo (65).jpg	155.34KB
20240122488 Locate Ticket Photo (66).jpg	147.08KB
20240122488 Locate Ticket Photo (67).jpg	158.87KB
20240122488 Locate Ticket Photo (68).jpg	164.82KB
20240122488 Locate Ticket Photo (69).jpg	167.09KB
20240122488 Locate Ticket Photo (70).jpg	162.53KB
20240122488 Locate Ticket Photo (71).jpg	168.24KB
20240122488 Locate Ticket Photo (72).jpg	184.88KB
20240122488 Locate Ticket Photo (73).jpg	179.69KB
20240122488 Locate Ticket Photo (74).jpg	178.17KB
20240122488 Locate Ticket Photo (75).jpg	164.43KB
20240122488 Locate Ticket Photo (76).jpg	195.18KB
20240122488 Locate Ticket Photo (77).jpg	174.15KB
20240122488 Locate Ticket Photo (78).jpg	165.95KB
20240122488 Locate Ticket Photo (79).jpg	133.58KB
20240122488 Locate Ticket Photo (80).jpg	134.39KB
20240122488 Locate Ticket Photo (81).jpg	141.39KB
20240122488 Locate Ticket Photo (82).jpg	140.71KB
20240122488 Locate Ticket Photo (83).jpg	152.88KB
20240122488 Locate Ticket Photo (84).jpg	153.38KB
20240122488 Locate Ticket Photo (85).jpg	172.86KB
20240122488 Locate Ticket Photo (86).jpg	119.07KB
20240122488 Locate Ticket Photo (87).jpg	153.52KB
20240122488 Locate Ticket Photo (88).jpg	127.8KB
20240122488 Locate Ticket Photo	144.92KB

(89).jpg	
20240122488 Locate Ticket Photo	162.32KB
(90).jpg	
20240122488 Locate Ticket.pdf	64.75KB
20240150522 KARL Response.pdf	61.56KB
20240150522 Locate Ticket.pdf	65.26KB
20240150570 KARL Response.pdf	61.56KB
20240150570 Locate Ticket.pdf	65.58KB
20240362672 Damage Ticket Photo	
(1).jpg	129.45KB
20240362672 Damage Ticket Photo	
(2).jpg	115.7KB
20240362672 Damage Ticket Photo	
(3).jpg	130.33KB
20240362672 Damage Ticket Photo	
(4).jpg	134.6KB
20240362672 Damage Ticket Photo	
(5).jpg	122.6KB
20240362672 Damage Ticket Photo	
(6).jpg	110.54KB
20240362672 Damage Ticket Photo	
(7).jpg	129.31KB
20240362672 Damage Ticket Photo	
(8).jpg	138.92KB
20240362672 Damage Ticket Photo	
(9).jpg	143.63KB
20240362672 Damage Ticket Photo	
(10).jpg	114.76KB
20240362672 Damage Ticket Photo	
(11).jpg	122.03KB
20240362672 Damage Ticket Photo	
(12).jpg	136.79KB
20240362672 Damage Ticket Photo	
(13).jpg	104.11KB
20240362672 Damage Ticket Photo	
(14).jpg	122.29KB
20240362672 Damage Ticket Photo	
(15).jpg	104.72KB
20240362672 Damage Ticket Photo	
(16).jpg	140.22KB
20240362672 Damage Ticket Photo	
(17).jpg	133.2KB
20240362672 Damage Ticket Photo	
(18).jpg	133.65KB
20240362672 Damage Ticket Photo	
(19).jpg	132.51KB
20240362672 Damage Ticket Photo	
(20).jpg	135.75KB
20240362672 Damage Ticket Photo	
(21).jpg	113.04KB

(21).jpg	
20240362672 Damage Ticket Photo	91.45KB
(22).jpg	
20240362672 Damage Ticket Photo	103.72KB
(23).jpg	
20240362672 Damage Ticket Photo	123.08KB
(24).jpg	
20240362672 Damage Ticket.pdf	65.5KB
USIC Damage Comparison.png	3.04MB
Attach pictures and additional documents	

Submit Date 02/06/2024

Compliance Update

Research Result

- Listed tickets found
- Additional tickets found
- No tickets found

Additional Tickets Found

Additional Serial Numbers

Ticket Attachment

Comments Frontier Communications has placed notifications with PA One Call in the past. 17 Main St, Towanda PA 18848. 570-362-1945

I&E Exhibit 2

CDC 00000 POCS MM/DD/YY TT:TT:TT 20240122488-000 NEW XCAV RTN

=====
Serial Number--[20240122488]-[000] Channel#--[1952A999][0303][2019-08]
Message Type--[NEW][EXCAVATION][ROUTINE]

County--[LACKAWANNA] Municipality--[LAPLUME TWP]
Work Site--[OLD LOGGERS RD]
Nearest Intersection--[APPLE TREE RD]
Second Intersection--[TIMBER TRL]
At Intersection--[N] Between Intersections--[N] Site Marked in White--[Y]
Subdivision--[]
Location Information--
[WORKING AT 62 THROUGH 51 OLD LOGGERS RD. WORKING ON BOTH SIDES OF THE
ROAD.]
Caller Lat/Lon--[]
Mapped Type--[P] Mapped Lat/Lon--
[41.567481/-75.767294,41.567593/-75.763957,41.566084/-75.761876,
41.563175/-75.764006,41.563440/-75.769639]
Attachments--[http://www.pa811.org/attachments/20240122488]
Type of Work--[INSTALL TELECOM LINES] Depth--[24IN]
Extent of Excavation--[5FT X 2FT] Method of Excavation--[BORING]
Equip Type--[MISSILE AND DITCH WITCH]
Street--[X] Sidewalk--[X] Pub Prop--[X] Pvt Prop--[X] Other--[]
Private Front--[X] Rear--[] Left--[X] Right--[X]

Lawful Start Dates--[18-Jan-24] thru [29-Jan-24] Response Due Date--[17-Jan-24]
Scheduled Excavation Date--[18-Jan-24] Dig Time--[0700] Duration--[2-3 WEEKS]

Caller--[VALERIE RIVERA]
Caller Phone--[443-630-1163]
Excavator--[FRIENDLY UNDERGROUND CONSTRUCTION LLC]
Address--[525 MAIN ST]
City--[DUNDALK] State--[MD] Zip--[21222]
FAX--[] Caller Type--[B]
Email--[friendlyunderground@gmail.com]
Work For--[FRONTIER]
Onsite Contact--[MERLIN SERRANO]
Onsite Contact Phone--[443-630-1163]
Best Time to Call--[ANYTIME]
Onsite Contact Email--[friendlyunderground@gmail.com]
Job Number--[2511294]

Prepared--[12-Jan-24] at [1957] by [JASON ZUBER]
Remarks--
[]

AQ10 AQ1=COMCAST DSA0 DSA=DALTON SWR AUTH ET 0 ET =FRONTIER COMM
GN 0 GN =UGI ARCHBALD LAP0 LAP=LA PLUME TWP PT 0 PT =PPL ELEC SRTN

Serial Number--[20240122488]-[000]
=====
Copyright (c) 2024 by Pennsylvania One Call System, Inc. =====


RESPONSES for S/N: 20240122488:

Ver	CDC	Name	Response	Time	Respondent
0	PT	PPL ELECTRIC UTILITIES CORPORATION	PT-SCHEDULED MARK	1/17/2024 5:49:32 PM	CLS-WEBSVC
0	PT	PPL ELECTRIC UTILITIES CORPORATION	PT-FIELD MARKED	1/29/2024 2:27:08 PM	CLS-WEBSVC
0	LAP	LA PLUME TOWNSHIP	LAP-NO RESPONSE	1/18/2024 12:02:19 AM	Auto-KARL
0	GN	UGI UTL ARCHBALD	GN-CLEAR. NO FACILITIES OR FACIL NOT INVOLVED	1/15/2024 9:57:24 AM	AAA-WEBSVC
0	DSA	DALTON SEWER AUTHORITY	DSA-NO RESPONSE	1/18/2024 12:02:19 AM	Auto-KARL
0	AQ1	COMCAST	AQ1-SCHEDULED MARK	1/17/2024 5:49:30 PM	CLS-WEBSVC
0	AQ1	COMCAST	AQ1-FIELD MARKED	1/29/2024 2:27:11 PM	CLS-WEBSVC
0	ET	FRONTIER COMMUNICATIONS OF PA INC	ET-SCHEDULED MARK	1/17/2024 5:49:30 PM	CLS-WEBSVC
0	ET	FRONTIER COMMUNICATIONS OF PA INC	ET-FIELD MARKED	1/29/2024 2:27:11 PM	CLS-WEBSVC

DELIVERIES for S/N: 20240122488:

Ver	CDC	Name	To	Time	Seq	Type
0	PT	PPL ELECTRIC UTILITIES CORPORATION	PT	1/12/2024 7:57:27 PM	52	MAIL
0	LAP	LA PLUME TOWNSHIP	LAP	1/12/2024 7:57:28 PM	1	MAIL
0	GN	UGI UTL ARCHBALD	GN	1/12/2024 7:57:24 PM	56	MAIL
0	DSA	DALTON SEWER AUTHORITY	DSA	1/12/2024 7:57:26 PM	1	MAIL
0	AQ1	COMCAST	AQ1	1/12/2024 7:57:24 PM	34	MAIL
0	ET	FRONTIER COMMUNICATIONS OF PA INC	ET	1/12/2024 7:57:24 PM	105	MAIL

ATTACHMENT for S/N: 20240122488 (20240122488-0.gif):



I&E Exhibit 3

CDC 00000 POCS MM/DD/YY TT:TT:TT 20240150570-000 NEW XCAV RTN

=====PENNSYLVANIA UNDERGROUND UTILITY LINE PROTECTION REQUEST=====

Serial Number--[20240150570]-[000] Channel#--[0915A999][0072][2019-08]
Message Type--[NEW][EXCAVATION][ROUTINE]

County--[LACKAWANNA] Municipality--[LAPLUME TWP]

Work Site--[OLD LOGGERS RD]

Nearest Intersection--[APPLE TREE]

Second Intersection--[TIMBER TRL]

At Intersection--[N] Between Intersections--[N] Site Marked in White--[Y]

Subdivision--[]

Location Information--

[THEY WILL BE WORKING ON OLD LOGGERS ROAD, STARTING AT THE PHYSICAL ADDRESS
OF 51 OLD LOGGERS RD NEAR APPLE TREE AND CONTINUE TO ELECTRIC POLE NUMBER
51519 LOCATED ON THE CORNER OF TIMBER TRL AND OLD LOGGER RD. WORKING ON
BOTH SIDES OF THE ROAD.]

Caller Lat/Lon--[]

Mapped Type--[P] Mapped Lat/Lon--

[41.564571/-75.765875,41.563945/-75.765574,41.563776/-75.766604,
41.563752/-75.768793,41.564475/-75.768203]

Attachments--[http://www.pa811.org/attachments/20240150570]

Type of Work--[INSTL TELE COM LINE] Depth--[24IN]

Extent of Excavation--[5FT X 2FT] Method of Excavation--[BORING]

Equip Type--[MISSILE AND DITCH WITCH]

Street--[X] Sidewalk--[X] Pub Prop--[X] Pvt Prop--[X] Other--[]

Private Front--[X] Rear--[] Left--[X] Right--[X]

Lawful Start Dates--[19-Jan-24] thru [30-Jan-24] Response Due Date--[18-Jan-24]

Scheduled Excavation Date--[19-Jan-24] Dig Time--[0700] Duration--[2-3 WEEKS]

Caller--[VALERIE RIVERA]

Caller Phone--[443-630-1163]

Excavator--[FRIENDLY UNDERGROUND CONSTRUCTION LLC]

Address--[525 MAIN ST]

City--[DUNDALK]

State--[MD] Zip--[21222]

FAX--[]

Caller Type--[B]

Email--[friendlyunderground@gmail.com]

Work For--[FRONTIER]

Onsite Contact--[MERLIN SERRANO]

Onsite Contact Phone--[443-630-1163]

Best Time to Call--[ANYTIME]

Onsite Contact Email--[friendlyunderground@gmail.com]

Job Number--[2511294]

Prepared--[15-Jan-24] at [0917] by [PAIGE SHONKWILER]

Remarks--

[]

AQ10 AQ1=COMCAST DSA0 DSA=DALTON SWR AUTH ET 0 ET =FRONTIER COMM

GN 0 GN =UGI ARCHBALD LAP0 LAP=LA PLUME TWP PT 0 PT =PPL ELEC SRTN

Serial Number--[20240150570]-[000]

===== Copyright (c) 2024 by Pennsylvania One Call System, Inc. =====


RESPONSES for S/N: 20240150570:

Ver	CDC	Name	Response	Time	Respondent
0	PT	PPL ELECTRIC UTILITIES CORPORATION	PT-SCHEDULED MARK	1/18/2024 6:01:42 PM	CLS-WEBSVC
0	PT	PPL ELECTRIC UTILITIES CORPORATION	PT-FIELD MARKED	1/29/2024 2:27:07 PM	CLS-WEBSVC
0	LAP	LA PLUME TOWNSHIP	LAP-NO RESPONSE	1/19/2024 12:02:53 AM	Auto-KARL
0	GN	UGI UTL ARCHBALD	GN-CLEAR. NO FACILITIES OR FACIL NOT INVOLVED	1/15/2024 9:59:43 AM	AAA-WEBSVC
0	DSA	DALTON SEWER AUTHORITY	DSA-NO RESPONSE	1/19/2024 12:02:53 AM	Auto-KARL
0	AQ1	COMCAST	AQ1-SCHEDULED MARK	1/18/2024 6:01:40 PM	CLS-WEBSVC
0	AQ1	COMCAST	AQ1-FIELD MARKED	1/29/2024 2:27:11 PM	CLS-WEBSVC
0	ET	FRONTIER COMMUNICATIONS OF PA INC	ET-SCHEDULED MARK	1/18/2024 6:01:40 PM	CLS-WEBSVC
0	ET	FRONTIER COMMUNICATIONS OF PA INC	ET-FIELD MARKED	1/29/2024 2:27:11 PM	CLS-WEBSVC

DELIVERIES for S/N: 20240150570:

Ver	CDC	Name	To	Time	Seq	Type
0	PT	PPL ELECTRIC UTILITIES CORPORATION	PT	1/15/2024 9:17:16 AM	16	MAIL
0	LAP	LA PLUME TOWNSHIP	LAP	1/15/2024 9:17:16 AM	3	MAIL
0	GN	UGI UTL ARCHBALD	GN	1/15/2024 9:17:13 AM	9	MAIL
0	DSA	DALTON SEWER AUTHORITY	DSA	1/15/2024 9:17:14 AM	3	MAIL
0	AQ1	COMCAST	AQ1	1/15/2024 9:17:12 AM	7	MAIL
0	ET	FRONTIER COMMUNICATIONS OF PA INC	ET	1/15/2024 9:17:12 AM	21	MAIL

ATTACHMENT for S/N: 20240150570 (20240150570-0.gif):



**BEFORE THE
PENNSYLVANIA PUBLIC UTILITY COMMISSION**

Pennsylvania Public Utility Commission,	:	
Bureau of Investigation and Enforcement,	:	
Complainant	:	
	:	
v.	:	Docket No. C-2025-
	:	
Dalton Sewer Authority,	:	
Respondent	:	

CERTIFICATE OF SERVICE

I hereby certify that I have this day served a true copy of the foregoing document upon the parties, listed below, in accordance with the requirements of 52 Pa. Code § 1.54 (relating to service by a party).

Service by Certified Mail and Electronic Mail

Dalton Sewer Authority
Attn: Meg Venn
P.O. Box 538
Dalton, PA 18414
daltonsewerauthority@gmail.com



Grant Rosul
Prosecutor
PA Attorney ID No. 318204

Pennsylvania Public Utility Commission
Bureau of Investigation and Enforcement
Commonwealth Keystone Building
400 North Street
Harrisburg, PA 17120
(717) 783-5243
grosul@pa.gov

Dated: May 20, 2025