



COMMONWEALTH OF PENNSYLVANIA
PENNSYLVANIA PUBLIC UTILITY COMMISSION
COMMONWEALTH KEYSTONE BUILDING
400 NORTH STREET, HARRISBURG, PA 17120

BUREAU OF
INVESTIGATION
&
ENFORCEMENT

March 26, 2026

Via Electronic Filing

Matthew Homsher, Secretary
Pennsylvania Public Utility Commission
Commonwealth Keystone Building
400 North Street
Harrisburg, PA 17120

Re: Pennsylvania Public Utility Commission,
Bureau of Investigation and Enforcement v.
Connell Equipment Inc. t/d/b/a RLE Enterprises
Docket No. C-2026-
I&E Formal Complaint (Damage Prevention)

Dear Secretary Homsher:

Enclosed for electronic filing please find the Formal Complaint of the Bureau of Investigation and Enforcement of the Pennsylvania Public Utility Commission in the above-referenced matter.

Copies are being served on the parties of record in accordance with the attached Certificate of Service.

Should you have any questions, please do not hesitate to contact me.

Sincerely,

A handwritten signature in blue ink, appearing to read 'Colby B. Widdowson', is written over a light blue circular stamp.

Colby B. Widdowson
Prosecutor
Bureau of Investigation and Enforcement
PA Attorney ID No. 326185
(717) 787-2139
cwiddowson@pa.gov

CW/nb
Enclosures

cc: Stephanie M. Wimer, Deputy Chief Prosecutor, I&E-Enf (via email – stwimer@pa.gov)
As per Certificate of Service

NOTICE

A. You must file an Answer within twenty (20) days of the date of service of this Complaint. The date of service is the date as indicated at the top of the Secretarial Letter. *See* 52 Pa. Code § 1.56(a). The Answer must raise all factual and legal arguments that you wish to claim in your defense, include the docket number of this Complaint, and be verified.

In Addition to filing your Answer with the Commission’s Secretary, please electronically serve a copy on:

Colby B. Widdowson, Prosecutor
Pennsylvania Public Utility Commission
Bureau of Investigation and Enforcement
cwiddowson@pa.gov

B. If you fail to answer this Complaint within twenty (20) days, the Bureau of Investigation and Enforcement will request that the Commission issue an Order imposing the administrative penalty and other requested relief.

C. You may elect not to contest this Complaint by paying the administrative penalty within twenty (20) days and performing the corrective actions, if any, set forth in the requested relief. A certified check, cashier’s check or money order should be payable to the “Commonwealth of Pennsylvania” and mailed to:

Matthew L. Homsher, Secretary
Pennsylvania Public Utility Commission
Commonwealth Keystone Building
400 North Street
Harrisburg, PA 17120

Your payment is an admission that you committed the alleged violations and an agreement to cease and desist from committing further violations. Upon receipt of your payment, the Complaint proceeding shall be closed.

D. If you file an Answer, which either admits or fails to deny the allegations of the Complaint, the Bureau of Investigation and Enforcement will request the Commission to issue an Order imposing the administrative penalty and granting the requested relief as set forth in the Complaint.

E. If you file an Answer which contests the Complaint, the matter will proceed before the assigned presiding Administrative Law Judge for hearing and decision. The Judge is not bound by the penalty set forth in the Complaint and may impose additional and/or alternative penalties as appropriate.

F. If you are a corporation, you must be represented by legal counsel. 52 Pa. Code § 1.21.

G. Alternative formats of this material are available for persons with disabilities by contacting the Commission's ADA Coordinator at (717) 787-8714.

**BEFORE THE
PENNSYLVANIA PUBLIC UTILITY COMMISSION**

Pennsylvania Public Utility Commission,	:	
Bureau of Investigation and Enforcement,	:	
Complainant	:	
	:	
v.	:	Docket No. C-2026-
	:	
Connell Equipment Inc. t/d/b/a RLE	:	
Enterprises,	:	
Respondent	:	

FORMAL COMPLAINT

NOW COMES the Bureau of Investigation and Enforcement (“I&E”) of the Pennsylvania Public Utility Commission, by its prosecuting attorneys, pursuant to Section 182 of the Underground Utility Line Protection Law (“UULPL” or “PA One Call Law”), Act of October 29, 2024, P.L. 1106, No. 127, 73 P.S. § 182.8(c)(2), and files this Formal Complaint (“Complaint”) against Connell Equipment Inc. t/d/b/a RLE Enterprises (“RLE Enterprises” or “Respondent”) alleging violations of the PA One Call Law in connection with six strikes on sewer laterals on Oaklawn Avenue, Hanover Township, Luzerne County, Pennsylvania. In support of its Complaint, I&E respectfully avers as follows:

I. COMMISSION JURISDICTION AND AUTHORITY

1. The Pennsylvania Public Utility Commission (“Commission” or “PUC”), with a mailing address of the Commonwealth Keystone Building, 400 North Street, Harrisburg, PA 17120, is a duly constituted agency of the Commonwealth of Pennsylvania empowered to

regulate, *inter alia*, excavators, within the Commonwealth pursuant to the PA One Call Law, Act of October 29, 2024, P.L. 1106, No. 127, 73 P.S. §§ 176 *et seq.*

2. Complainant is the Commission’s Bureau of Investigation and Enforcement, which is the bureau established to take enforcement actions against public utilities and other entities subject to the Commission’s jurisdiction pursuant to 66 Pa.C.S. § 308.2(a)(11).

See also Implementation of Act 129 of 2008; Organization of Bureaus and Offices,

Docket No. M-2008-2071852 (August 11, 2011) (delegating authority to initiate proceedings that are prosecutory in nature to I&E).

3. Complainant’s prosecuting attorney is as follows:

Colby B. Widdowson

Prosecutor

cwiddowson@pa.gov

(717) 787-2139

Pennsylvania Public Utility Commission

Bureau of Investigation and Enforcement

Commonwealth Keystone Building

400 North Street

Harrisburg, PA 17120

4. Respondent is Connell Equipment Inc. t/d/b/a RLE Enterprises with a principal place of business and mailing address of 457 North Main Street, Rear, Moscow, PA, 18444.

5. Connell Equipment Inc. trades and does business as RLE Enterprises.

6. Respondent is an “excavator,” as that term is defined in Section 176 of the PA One Call Law, 73 P.S. § 176.¹

¹ “Excavator” is defined as any person who or which performs excavation or demolition work for himself or for another person.” 73 P.S. § 176. “Excavation work” is defined as “the use of powered equipment or explosives in the movement of earth, rock or other material, and includes, but is not limited to, anchoring, augering, backfilling, blasting, boring, digging, ditching, drilling, driving-in, grading, plowing-in, pulling-in, ripping, scraping, trenching and tunneling.” *Id.*

7. Section 180 of the PA One Call Law, 73 P.S. § 180, imposes duties and responsibilities upon excavators.

8. Respondent, as an excavator, is subject to the authority of this Commission pursuant to Section 182.10 of the PA One Call Law, 73 P.S. § 182.10, which requires excavators to comply with the PA One Call Law. 73 P.S. § 182.10.

9. Section 182.8(c)-(d) and Section 182.10 of the PA One Call Law, 73 P.S. §§ 182.8(c)-(d) and 182.10, authorize the Commission to, *inter alia*, hear and determine complaints against excavators for violations of the PA One Call Law and to enforce the provisions of the PA One Call Law. 73 P.S. §§ 182.8(c)-(d) and 182.10.

10. Section 182.8(c)(2) of the PA One Call Law, 73 P.S. § 182.8(c)(2), authorizes the Commission's prosecutor staff to bring a formal complaint against entities subject to the PA One Call Law. 73 P.S. § 182.8(c)(2).

11. Section 182.10 of the PA One Call Law, 73 P.S. § 182.10(b)(1)(i)-(ii), authorizes the Commission to impose administrative penalties on any person or corporation, subject to the PA One Call Law, who violates any provisions of the PA One Call Law or any regulation or order issued thereunder governing underground utility lines, of up to \$2,500 per violation or if the violation results in injury, death, or property damage of \$25,000 dollars or more an administrative penalty not to exceed \$50,000. 73 P.S. § 182.10(b)(1)(i)-(ii).

12. Pursuant to the provisions of the applicable Commonwealth statutes and regulations, the Commission has jurisdiction over the subject matter of this Complaint and the actions of Respondent related thereto.

II. RESPONDENT'S COMPLIANCE HISTORY WITH THE PA ONE CALL LAW

13. The PA One Call Law was amended on October 29, 2024. Act of October 29, 2024, P.L. 1106, No. 127, 73 P.S. §§ 176 *et seq.* The content and citation of violations occurring prior to October 29, 2024, may differ from the current version of the PA One Call Law.

14. On or about February 11, 2020, at Case No. 007113, the following violations against Respondent were accepted by the Damage Prevention Committee (“DPC”):

- a. 73 P.S. § 180(3.1) – Scope of project exceeds the maximum area of a routine ticket.

Respondent paid an administrative penalty of \$250.00 to resolve this case.

15. On or about February 11, 2020, at Case No. 012159, the following violations against Respondent were accepted by the DPC:

- a. 73 P.S. § 180(4) – Excavator failed to exercise due care and employ prudent techniques; and
- b. 73 P.S. § 180(6)(i) – Failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area;

Respondent paid an administrative penalty of \$750.00 to resolve this case.

16. On or about February 14, 2023, at Case No. 030947, the following violations against Respondent were accepted by the DPC:

- a. 73 P.S. § 180(16) – Excavator failed to submit an alleged violation report within 10 days of striking a line.²

Respondent was issued a warning letter to resolve this case.

² The October 29, 2024 amendment to the PA One Call Law changed the 10 day requirement, to submit an alleged violation report, to 30 days.

17. On or about April 11, 2023, at Case No. 030011, the following violations against Respondent were accepted by the DPC:

- a. 73 P.S. § 180(16) – Excavator failed to submit an alleged violation report within 10 days of striking a line.³

Respondent paid an administrative penalty of \$500.00 to resolve this case.

18. On or about May 9, 2023, at Case No. 030924, the following violations against Respondent were accepted by the DPC:

- a. 73 P.S. § 180(4) – Excavator failed to exercise due care and employ prudent techniques; and
- b. 73 P.S. § 180(16) – Excavator failed to submit an alleged violation report within 10 days of striking a line.⁴

Respondent paid an administrative penalty of \$1,000.00 to resolve this case.

19. On or about May 9, 2023, at Case No. 030925, the following violations against Respondent were accepted by the DPC:

- a. 73 P.S. § 180(4) – Excavator failed to exercise due care and employ prudent techniques;
- b. 73 P.S. § 180(16) – Excavator failed to submit an alleged violation report within 10 days of striking a line;⁵ and
- c. 73 P.S. § 180(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request.

Respondent paid an administrative penalty of \$1,250.00 to resolve this case.

³ The October 29, 2024 amendment to the PA One Call Law changed the 10 day requirement, to submit an alleged violation report, to 30 days.

⁴ The October 29, 2024 amendment to the PA One Call Law changed the 10 day requirement, to submit an alleged violation report, to 30 days.

⁵ The October 29, 2024 amendment to the PA One Call Law changed the 10 day requirement, to submit an alleged violation report, to 30 days.

20. On or about September 12, 2023, at Case No. 030312, the following violations against Respondent were accepted by the DPC:

- a. 73 P.S. § 180(16) – Excavator failed to submit an alleged violation report within 10 days of striking a line;⁶
- b. 73 P.S. § 180(3.1) – Scope of project exceeds the maximum area of a routine ticket;
- c. 73 P.S. § 180(2.1) – Excavator failed to submit a location request to One call within the correct timeframe; and
- d. 73 P.S. § 180(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request.

Respondent paid an administrative penalty of \$2,250.00 to resolve this case.

21. On or about October 11, 2023, at Case No. 032261, the following violations against Respondent were accepted by the DPC:

- a. 73 P.S. § 180(4) – Excavator failed to exercise due care and employ prudent techniques;
- b. 73 P.S. § 180(16) – Excavator failed to submit an alleged violation report within 10 days of striking a line;⁷
- c. 73 P.S. § 180(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request.

Respondent paid an administrative penalty of \$7,500.00 to resolve this case.

22. On or about October 8, 2024, at Case No. 044445, the following violations against Respondent were accepted by the DPC:

⁶ The October 29, 2024 amendment to the PA One Call Law changed the 10 day requirement, to submit an alleged violation report, to 30 days.

⁷ The October 29, 2024 amendment to the PA One Call Law changed the 10 day requirement, to submit an alleged violation report, to 30 days.

- a. 73 P.S. § 180(6)(ii) – Excavator failed to provide support and mechanical protection for known facility owner’s lines at the construction work site during excavation.

At the time of this filing, Respondent has not paid the \$500 administrative penalty assessed in this case.

23. On or about February 11, 2025, at Case No. 046541, the following violations against Respondent were accepted by the DPC:

- a. 73 P.S. § 180(4) – Excavator failed to exercise due care and employ prudent techniques; and
- b. 73 P.S. § 180(16) – Excavator failed to submit an alleged violation report within 10 days of striking a line.⁸

At the time of this filing, Respondent has not paid the \$5,000.00 administrative penalty assessed in this case.

24. On or about July 8, 2025, at Case No. 052469, the following violations against Respondent were accepted by the DPC:

- a. 73 P.S. § 180(20) – Excavator failed to renotify One Call of an unmarked or incorrectly marked facility upon arrival at a work site and wait at least 3 hours for the facility owner to provide additional information; and
- b. 73 P.S. § 184 – Failed to make best efforts to comply with the Common Ground Alliance Best Practices.

Respondent paid an administrative penalty of \$500.00 to resolve this case.

III. FACTUAL BACKGROUND

25. On March 12, 2025, Respondent submitted a One Call notification ticket (“One Call ticket”) number 20250713607 indicating that it would be conducting an

⁸ The October 29, 2024 amendment to the PA One Call Law changed the 10 day requirement, to submit an alleged violation report, to 30 days.

excavation to install a water main, beginning on March 17, 2025 on Oaklawn Avenue, Hanover Township, Luzerne County, PA. This One Call ticket indicated that the excavation would be conducted in the street, at a depth of four feet, and would be approximately 1300 feet long. See attached I&E Exhibit 1.

26. On March 13, 2025, Hanover Township Luzerne County (“Hanover Township”) responded to One Call ticket number 20250713607 indicating that the sewer facilities had been marked. See attached I&E Exhibit 1.

27. On March 20, 2025, Respondent submitted an updated One Call ticket at ticket number 20250792701 indicating that work was still in progress and facilities would need to be remarked. See attached I&E Exhibit 2.

28. On March 21, 2025, Hanover Township responded to One Call ticket number 20250792701 indicating that the sewer facilities had been marked. See attached I&E Exhibit 2.

29. Hanover Township is the facility owner for the sewer system on Oaklawn Avenue.

30. Hanover Township marked the location of the sewer main, but did not mark the location of the sewer laterals on Oaklawn Avenue.

31. Hanover Township did not have maps of the locations of the sewer laterals.

32. On April 3, 2025, Respondent’s excavation crew, using a mechanical excavator, struck and damaged three sewer laterals in front of 20, 21, and 23 Oaklawn Avenue.

33. On April 4, 2025, Respondent submitted Alleged Violation Report (“AVR”) number AVR2025APR040025, stating that “while digging for a new water main installation,

our crew struck an unmarked sewer lateral for house #23 Oaklawn Ave. RLE made repairs and restored service in a timely manner.” See attached I&E Exhibit 3.

34. On April 4, 2025, Respondent submitted AVR number AVR2025APR040026, stating that “while digging for a new water main installation, our crew struck an unmarked sewer lateral for house #21 Oaklawn Ave. RLE made repairs and restored service in a timely manner.” See attached I&E Exhibit 4.

35. On April 4, 2025, Respondent submitted AVR number AVR2025APR040027, stating that “while digging for a new water main installation, our crew struck an unmarked sewer lateral for house #20 Oaklawn Ave. RLE made repairs and restored service in a timely manner.” See attached I&E Exhibit 5.

36. On April 7, 2025, Respondent’s excavation crew, using a mechanical excavator, struck and damaged three sewer laterals in front of 13, 14, and 15 Oaklawn Avenue.

37. On April 7, 2025, Respondent submitted AVR number AVR2025APR070011, stating that “while digging for a new water main installation, our crew struck an unmarked sewer lateral for house #15 Oaklawn Ave. RLE made repairs and restored service in a timely manner.” See attached I&E Exhibit 6.

38. On April 7, 2025, Respondent submitted AVR number AVR2025APR070012, stating that “while digging for a new water main installation, our crew struck an unmarked sewer lateral for house #14 Oaklawn Ave. RLE made repairs and restored service in a timely manner.” See attached I&E Exhibit 7.

39. On April 7, 2025, Respondent submitted AVR number AVR2025APR070014, stating that “while digging for a new water main installation, our crew struck an unmarked

sewer lateral for house #13 Oaklawn Ave. RLE made repairs and restored service in a timely manner.” See attached I&E Exhibit 8.

40. While engaged in excavation activities on April 3, 2025 and April 7, 2025, Respondent, while using a mechanical excavator, struck and damaged a total of six sewer laterals on Oaklawn Avenue.

41. After having struck and damaged the first sewer lateral on April 3, 2025, Respondent was on notice of the existence of the sewer laterals and that the sewer laterals were not marked.

42. Respondent, using a mechanical excavator, subsequently struck five more sewer laterals after having knowledge of the existence of the sewer laterals and that the sewer laterals were not marked.

IV. VIOLATIONS

COUNTS ONE THROUGH FIVE

43. All allegations in paragraphs 1 through 42 are incorporated as if fully set forth herein. Respondent failed to exercise due care and employ prudent techniques in its excavation after it had knowledge of the existence of the sewer laterals and that the sewer laterals were not marked. Each strike on a sewer lateral, after the first strike, represents a separate violation. If proven, this is a violation of 73 P.S. § 180(4)&(5) (Excavators, Duties).

WHEREFORE, for all the foregoing reasons, the Pennsylvania Public Utility Commission’s Bureau of Investigation and Enforcement respectfully requests that the Commission:

- (1) Find Respondent to be in violation of the PA One Call Law as alleged;

- (2) Impose an administrative penalty upon Respondent in the amount of \$2,500 per violation or a total administrative penalty of \$12,500;
- (3) Order Respondent to attend Online Compliance Training through the Pennsylvania One Call System for excavators and provide proof of compliance to the Commission within 30 days of the entry of a Final Commission Order; and
- (4) Order such other remedies as the Commission may deem appropriate.
- (5) If payment of the administrative penalty is not made as directed, the Bureau of Investigation and Enforcement requests that this matter be referred to the Pennsylvania Office of the Attorney General for collection and any other appropriate action.

Respectfully submitted,



Colby B. Widdowson
Prosecutor
Bureau of Investigation and Enforcement
PA Attorney ID No. 326185
(717) 787-2139
cwiddowson@pa.gov

Date: March 26, 2026


**BEFORE THE
PENNSYLVANIA PUBLIC UTILITY COMMISSION**

Pennsylvania Public Utility Commission,	:	
Bureau of Investigation and Enforcement,	:	
Complainant	:	
	:	
v.	:	Docket No. C-2026-
	:	
Connell Equipment Inc. t/d/b/a RLE	:	
Enterprises,	:	
Respondent	:	

VERIFICATION

I, Sara Locke, Damage Prevention Supervisor, Damage Prevention Section, Bureau of Investigation and Enforcement, hereby state that the facts above set forth are true and correct to the best of my knowledge, information, and belief and that I expect that the Bureau of Investigation and Enforcement will be able to prove the same at any hearing held in this matter. I understand that the statements herein are made subject to the penalties of 18 Pa.C.S. § 4904 relating to unsworn falsification to authorities.

Date: March 26, 2026



Sara Locke
Damage Prevention Supervisor
Damage Prevention Section
Pennsylvania Public Utility Commission
Bureau of Investigation and Enforcement
Commonwealth Keystone Building
400 North Street
Harrisburg, PA 17120

I&E Exhibit 1

CDC 00000 POCS MM/DD/YY TT:TT:TT 20250713607-000 NEW XCAV RTN

=====PENNSYLVANIA UNDERGROUND UTILITY LINE PROTECTION REQUEST=====

Serial Number--[20250713607]-[000] Channel#--[1444AWEB][0311][2019-08]
Message Type--[NEW][EXCAVATION][ROUTINE]

County--[LUZERNE] Municipality--[HANOVER TWP]
Work Site--[OAKLAWN AVE.]
Nearest Intersection--[S MAIN ST.]
Second Intersection--[E. SAINT MARYS ST.]
At Intersection--[N] Between Intersections--[Y] Site Marked in White--[Y]
Subdivision--[]

Location Information--
[PLEASE MARK OUT 50 FEET IN ALL DIRECTIONS AT INTERSECTIONS.]
Caller Lat/Lon--[]

Mapped Type--[C] Mapped Lat/Lon--[]

Attachments--[http://www.pa811.org/attachments/20250713607]
Type of Work--[MAIN EXCAVATION] Depth--[4FT]
Extent of Excavation--[1300 FT X 3FT] Method of Excavation--[]
Equip Type--[EXCAVATOR]
Street--[X] Sidewalk--[] Pub Prop--[X] Pvt Prop--[] Other--[]
Private Front--[] Rear--[] Left--[] Right--[]

Lawful Start Dates--[17-Mar-25] thru [26-Mar-25] Response Due Date--[14-Mar-25]
Scheduled Excavation Date--[17-Mar-25] Dig Time--[0700] Duration--[4 MONTHS]

Caller--[AJ KOCHANSKI]
Caller Phone--[570-904-4398]
Excavator--[R L E ENTERPRISES]
Address--[457 N MAIN STREET]
City--[MOSCOW] State--[PA] Zip--[18444]
FAX--[] Caller Type--[B]
Email--[AJK@RLEENTERPRISES.NET]
Work For--[PENNSYLVANIA AMERICAN WATER]
Onsite Contact--[AJ KOCHANSKI]
Onsite Contact Phone--[570-904-4398]
Best Time to Call--[ANYTIME]
Onsite Contact Email--[AJK@RLEENTERPRISES.NET]
Complex Project Number--[20250491663]-[000]
CPA Project ID--[4071471]

Prepared--[12-Mar-25] at [1449] by [AJKOCH]
Remarks--

[PLEASE MARK OUT 50 FEET IN ALL DIRECTIONS AT INTERSECTIONS.]

GJ 0 GJ =UGI WILKES HNO0 HNO=HANOVER TWP PW 0 PW =PPL ELEC CNTRL
SER0 SER=SERVICE ELEC UE 0 UE =UGI ELECTRIC WW 0 WW =PAWC WILKES-BAR

Serial Number--[20250713607]-[000]

===== Copyright (c) 2025 by Pennsylvania One Call System, Inc. =====

RESPONSES for S/N: 20250713607:

Ver	CDC	Name	Response	Time	Respondent
0	WW	PENNSYLVANIA AMERICAN WATER WILKES BARRE	WW-FIELD MARKED	4/10/2025 7:00:42 AM	EMM-WEBSVC
0	WW	PENNSYLVANIA AMERICAN WATER WILKES BARRE	WW-SCHEDULED MARK	3/14/2025 2:47:00 PM	EMM-WEBSVC
0	UE	UGI UTL ELECTRIC	UE-CLEAR. NO FACILITIES OR FACIL NOT INVOLVED	3/14/2025 4:18:27 PM	CLS-WEBSVC
0	SER	SERVICE ELECTRIC CABLE TV & COMM	SER-CLEAR. NO FACILITIES OR FACIL NOT INVOLVED	3/12/2025 3:00:48 PM	MW-MOBILE
0	PW	PPL ELECTRIC UTILITIES CORPORATION	PW-CLEAR. NO FACILITIES OR FACIL NOT INVOLVED	3/14/2025 4:18:32 PM	CLS-WEBSVC
0	HNO	HANOVER TOWNSHIP LUZERNE COUNTY	HNO-FIELD MARKED	3/13/2025 9:34:51 AM	MM-OTM
0	GJ	UGI UTL WILKES BARRE	GJ-NO RESPONSE	3/15/2025 12:04:10 AM	Auto-KARL
0	GJ	UGI UTL WILKES BARRE	GJ-FIELD MARKED	3/17/2025 6:34:54 AM	AAA-WEBSVC

DELIVERIES for S/N: 20250713607:

Ver	CDC	Name	To	Time	Seq	Type
0	WW	PENNSYLVANIA AMERICAN WATER WILKES BARRE	WW	3/12/2025 2:49:50 PM	155	MAIL
0	WEBCFM	WEB CONFIRMATION QUEUE	WEBCFM	3/12/2025 2:49:59 PM	0	MAIL
0	UE	UGI UTL ELECTRIC	UE	3/12/2025 2:49:50 PM	17	MAIL
0	SER	SERVICE ELECTRIC CABLE TV & COMM	SER	3/12/2025 2:49:50 PM	46	MAIL
0	PW	PPL ELECTRIC UTILITIES CORPORATION	PW	3/12/2025 2:49:49 PM	84	MAIL
0	HNO	HANOVER TOWNSHIP LUZERNE COUNTY	HNO	3/12/2025 2:58:39 PM	7	FM1
0	GJ	UGI UTL WILKES BARRE	GJ	3/12/2025 2:49:49 PM	84	MAIL

I&E Exhibit 2

CDC 00000 POCS MM/DD/YY TT:TT:TT 20250792701-000 UPDT XCAV RTN

=====PENNSYLVANIA UNDERGROUND UTILITY LINE PROTECTION REQUEST=====

Serial Number--[20250792701]-[000] Channel#--[1407AWEB][0005][2019-08]
Message Type--[UPDATE][EXCAVATION][ROUTINE]

County--[LUZERNE] Municipality--[HANOVER TWP]

Work Site--[OAKLAWN AVE.]

Nearest Intersection--[S MAIN ST.]

Second Intersection--[E. SAINT MARYS ST.]

At Intersection--[N] Between Intersections--[Y] Site Marked in White--[Y]

Subdivision--[]

Location Information--

[PLEASE MARK OUT 50 FEET IN ALL DIRECTIONS AT INTERSECTIONS.]

Caller Lat/Lon--[]

Mapped Type--[C] Mapped Lat/Lon--

[]

Attachments--[http://www.pa811.org/attachments/20250792701]

Type of Work--[MAIN EXCAVATION]

Depth--[4FT]

Extent of Excavation--[1300 FT X 3FT] Method of Excavation--[]

Equip Type--[EXCAVATOR]

Street--[X] Sidewalk--[] Pub Prop--[X] Pvt Prop--[] Other--[]

Private Front--[] Rear--[] Left--[] Right--[]

Lawful Start Dates--[25-Mar-25] thru [03-Apr-25] Response Due Date--[24-Mar-25]

Scheduled Excavation Date--[25-Mar-25] Dig Time--[0700] Duration--[4 MONTHS]

Caller--[AJ KOCHANSKI]

Caller Phone--[570-904-4398]

Excavator--[R L E ENTERPRISES]

Address--[457 N MAIN STREET]

City--[MOSCOW]

State--[PA] Zip--[18444]

FAX--[]

Caller Type--[B]

Email--[AJK@RLEENTERPRISES.NET]

Work For--[PENNSYLVANIA AMERICAN WATER]

Onsite Contact--[AJ KOCHANSKI]

Onsite Contact Phone--[570-904-4398]

Best Time to Call--[ANYTIME]

Onsite Contact Email--[AJK@RLEENTERPRISES.NET]

Complex Project Number--[20250491663]-[000]

CPA Project ID--[4071471]

Prepared--[20-Mar-25] at [1407] by [AJKOCH]

Remarks--

[PLEASE MARK OUT 50 FEET IN ALL DIRECTIONS AT INTERSECTIONS.]

*****== UPDATE 20250713607-000 --3/20/2025 1408 AJK WEB==*****

UPDATE REQUESTED BY: AJ KOCHANSKI

REASON FOR UPDATE: WORK IN PROGRESS

REMARK LINES.]

GJ 0 GJ =UGI WILKES HNO0 HNO=HANOVER TWP PW 0 PW =PPL ELEC CNTRL
SER0 SER=SERVICE ELEC UE 0 UE =UGI ELECTRIC WW 0 WW =PAWC WILKES-BAR

Serial Number--[20250792701]-[000]

===== Copyright (c) 2025 by Pennsylvania One Call System, Inc. =====

RESPONSES for S/N: 20250792701:

Ver	CDC	Name	Response	Time	Respondent
0	WW	PENNSYLVANIA AMERICAN WATER WILKES BARRE	WW-SCHEDULED MARK	3/24/2025 3:12:11 PM	MST-WEBSVC
0	WW	PENNSYLVANIA AMERICAN WATER WILKES BARRE	WW-FIELD MARKED	4/10/2025 7:00:42 AM	EMM-WEBSVC
0	UE	UGI UTL ELECTRIC	UE-CLEAR. NO FACILITIES OR FACIL NOT INVOLVED	3/24/2025 4:10:05 PM	CLS-WEBSVC
0	SER	SERVICE ELECTRIC CABLE TV & COMM	SER-CLEAR. NO FACILITIES OR FACIL NOT INVOLVED	3/20/2025 2:11:42 PM	MW-MOBILE
0	PW	PPL ELECTRIC UTILITIES CORPORATION	PW-CLEAR. NO FACILITIES OR FACIL NOT INVOLVED	3/24/2025 4:10:16 PM	CLS-WEBSVC
0	HNO	HANOVER TOWNSHIP LUZERNE COUNTY	HNO-FIELD MARKED	3/21/2025 6:53:04 AM	MM-OTM
0	GJ	UGI UTL WILKES BARRE	GJ-FIELD MARKED	3/21/2025 3:56:13 PM	AAA-WEBSVC

DELIVERIES for S/N: 20250792701:

Ver	CDC	Name	To	Time	Seq	Type
0	WW	PENNSYLVANIA AMERICAN WATER WILKES BARRE	WW	3/20/2025 2:08:19 PM	146	MAIL
0	WEBCFM	WEB CONFIRMATION QUEUE	WEBCFM	3/20/2025 2:09:05 PM	0	MAIL
0	UE	UGI UTL ELECTRIC	UE	3/20/2025 2:08:33 PM	17	MAIL
0	SER	SERVICE ELECTRIC CABLE TV & COMM	SER	3/20/2025 2:08:34 PM	32	MAIL
0	PW	PPL ELECTRIC UTILITIES CORPORATION	PW	3/20/2025 2:08:33 PM	58	MAIL
0	HNO	HANOVER TOWNSHIP LUZERNE COUNTY	HNO	3/20/2025 2:17:07 PM	1	FM1
0	GJ	UGI UTL WILKES BARRE	GJ	3/20/2025 2:08:22 PM	66	MAIL

ATTACHMENT for S/N: 20250792701 (20250792701-0.gif):



I&E Exhibit 3



Alleged Violation Report

PA Act 287, as amended 73 P. S. § 176 et. seq.
Powered by Pennsylvania One Call System, Inc.

AVR Number AVR2025APR040025

AVR Version 1

First Name AJ **Last Name** KOCHANSKI

Company Name R L E ENTERPRISES

Address 457 N MAIN STREET

City MOSCOW

State PA

Zip Code 18444

Email AJK@RLEENTERPRISE S.NET **Phone** 5709044398

Ext

Role

Submitter Role(s) (?)

- | | |
|---|---|
| <input type="checkbox"/> Facility Owner | <input type="checkbox"/> Designer |
| <input checked="" type="checkbox"/> Excavator | <input type="checkbox"/> Project Owner |
| <input type="checkbox"/> Locator | <input type="checkbox"/> Enforcement Agency |
| <input type="checkbox"/> Other | |

Are you representing a company other than your own? Yes No

What company or individual are you representing?

Alleged Violation Information

PUC Case Number (if known)

Related AVR Number (?)

Type of Alleged Violation (?) Facility Owner Issue

Reason Marked incorrectly §2(5)

When did the alleged violation occur? (?) 04/03/2025
11:00:00 AM

Was the One Call System notified? Yes No

Original Serial Number

Please enter the 11 digit One Call Serial Number under which work was taking place, which will populate the work site information of this alleged violation.

Related Damage Serial Number, if applicable

Other Related Serial Numbers (?)

Was the excavation exempt from One Call notification? Yes No Unknown

Reason for Exemption

Event Information



County LUZERNE
Municipality HANOVER TWP
Ward
Work Site OAKLAWN AVE.
Nearest Intersection SAINT MARY'S RD.
Second Intersection S. MAIN ST.
Geolocation (?)

Affected Facility Information



Primary Right of Way Type Public
Public Right of Way Type City Street
Private Right of Way Type

Affected Operation Sewer
Facility Subtype Affected Service/Drop/Lateral
Facility Owner Company Name HANOVER TOWNSHIP
Contact First Name Last Name
Address 1267 SANS SOUCI PKWY
City WILKES BARRE
State PA
Zip 18706

Email

Phone

Joint Trench? Yes No Unknown

Involve Cross Bore? Yes No Unknown

Measured Depth from Grade >36" / 91 cm

Exact Measured Depth from Grade Enter the inches or centimeters with number and measurement used

Work Information



Start Date of Excavation (?) 04/03/2025
07:00:00 AM

Excavation Activity WATER

Excavator Company Name RLE ENTERPRISES

Contact First Name TODD Last Name CANTAFIO

Address 457 N. MAIN ST.

City MOSCOW

State PA

Zip 18444

Email TODDC@RLEENTERPRISES.NET Phone 570-906-0600

Marked in White Yes No Unknown

Method of Excavation DIGGING

Equipment Used What Equipment was used for excavation or demolition when the event occurred?
BACKHOE/TRACKHOE

Type of Excavator What is the type of excavator for whom the work was being done when the event occurred?
Utility

Did Excavator incur down time? Yes No Unknown

How much down time? Unknown

Estimated cost of down time Unknown

Was a response posted to the One Call System? Yes No Unknown

Was the design serial number on the plans/bid documents? Yes No Unknown

Were the lines shown on the plans/bid documents? Yes No Unknown

What level of subsurface utility engineering was utilized? A (Test Hole/Pot Holing)

Estimated cost of the entire project \$400,000 or more

What was the length of the entire project?

Project Owner Company Name PAWC

Contact First Name JESSICA Last Name MILLER

Address 2699 STAFFORD AVE.

City SCRANTON

State PA

Zip 18505

Email JESSICA.MILLER@AMW ATER.COM Phone 570-369-3374

Event Impact



Did Violation result in underground damage or near miss event? Damage

OSHA Report Filed? Yes No

OSHA Report Number

Was 911 called? Yes No

Name of 911 Caller

Fire Response Yes No

Police Response Yes No

Did the incident cause any injuries? Yes

Number of Injuries (?)

Did the incident cause any deaths? Yes

Number of Deaths

Was there an evacuation? Yes No

Number of people evacuated?

Traffic Stopped? Yes No

Service Interrupted? Yes No

Duration of Service Interruption? 1 - < 6 hrs

Exact Value of Service Interruption

Approximately how many customers were affected? 1

Exact Number of Customers Affected

Cost of Damaged Line Repair? Unknown

Exact Cost of Damaged Line Repair

Was other property damaged? Yes No

What other property was damaged?

Cost of Other Property Repair

Locator/Locate Information



Who was the facility line locator? Employee Locator

Locator Company

Contact First Name

Last Name

Address

City

State

Zip

Email

Phone

Was the line marked? Accurately Inaccurately/Incompletely Not Marked
 Unknown

Were facilities marked according to APWA/CGA temporary marking color code (ANSI standard Z535.1)? Yes No Unknown

What types of marks were present?
 Paint
 Flags
 Stakes
 Other

Were offset markings used? Yes No Unknown

Condition of Marks

Was the line marked by the response due date or within the agreed upon locate schedule? (?) Yes No Unknown

Reason for Late Locate

Was the excavation within the tolerance zone? (?) Yes No Unknown

Was there an indication of underground facilities (clear evidence) in the excavation area? Yes No Unknown

What was the evidence?
(meter/pedestal, pipeline marker, valve
box, hydrant, manhole, etc.)

What method(s) were used to locate
the facility? Electronic Records
 Visual Exposed

Did the excavator request payment
under PennDOT Form 408
specifications for extra work
performed on a force account basis? Yes No

Additional Locate Comments

If this incident involved any locating/marketing errors, please include all records related to the locator's training and qualification (including training to meet UULPL standards as well as Operator Qualification).

Summary and Attachments

Provide a summary of the event

WHILE DIGGING FOR A NEW WATER MAIN INSTALLATION, OUR CREW STRUCK AN UNMARKED SEWER LATERAL FOR HOUSE #23 OAKLAWN AVE. RLE MADE REPAIRS AND RESTORED SERVICE IN A TIMELY MANNER.

If more space is needed, attach additional pages or documents.

Attachments

76538941205__18B92D87-8280-496D-9F04-2D985A14D235.jpg 3.6MB
76538942043__78D24567-BCFF-4F5F-B086-A032AE41F9D2.jpg 5.73MB

Attach pictures and additional documents

Submit Date

04/04/2025

Compliance Update

Research Result

Listed tickets found
 Additional tickets found
 No tickets found

Additional Tickets Found

Additional Serial Numbers 20250792701

Additional Serial Numbers 20250491663

Additional Serial Numbers 20242781470

Additional Serial Numbers 20231871827

Ticket Attachment

8317071_report.pdf 780.37KB
4071471_report.pdf 777.71KB

Comments

I&E Exhibit 4



Alleged Violation Report

PA Act 287, as amended 73 P. S. § 176 et. seq.
Powered by Pennsylvania One Call System, Inc.

AVR Number AVR2025APR040026
AVR Version 1
First Name AJ **Last Name** KOCHANSKI
Company Name R L E ENTERPRISES
Address 457 N MAIN STREET
City MOSCOW
State PA
Zip Code 18444
Email AJK@RLEENTERPRISE S.NET **Phone** 5709044398
Ext

Role

Submitter Role(s) (?)

- | | |
|---|---|
| <input type="checkbox"/> Facility Owner | <input type="checkbox"/> Designer |
| <input checked="" type="checkbox"/> Excavator | <input type="checkbox"/> Project Owner |
| <input type="checkbox"/> Locator | <input type="checkbox"/> Enforcement Agency |
| <input type="checkbox"/> Other | |

Are you representing a company other than your own? Yes No

What company or individual are you representing?

Alleged Violation Information

PUC Case Number (if known)

Related AVR Number (?)

Type of Alleged Violation (?) Facility Owner Issue

Reason Marked incorrectly §2(5)

When did the alleged violation occur? (?) 04/03/2025

12:00:00 PM

Was the One Call System notified? Yes No

Original Serial Number

Please enter the 11 digit One Call Serial Number under which work was taking place, which will populate the work site information of this alleged violation.

Related Damage Serial Number, if applicable

Other Related Serial Numbers (?)

Was the excavation exempt from One Call notification? Yes No Unknown

Reason for Exemption

Event Information



County LUZERNE
Municipality HANOVER BORO
Ward
Work Site OAKLAWN AVE.
Nearest Intersection SAINT MARY'S RD.
Second Intersection S. MAIN ST.
Geolocation (?)

Affected Facility Information



Primary Right of Way Type Public
Public Right of Way Type City Street
Private Right of Way Type
Affected Operation Sewer
Facility Subtype Affected Service/Drop/Lateral
Facility Owner Company Name HANOVER TOWNSHIP
Contact First Name Last Name
Address 1267 SANS SOUCI PKWY
City WILKES BARRE
State PA
Zip 18706

Email	Phone
Joint Trench?	<input type="radio"/> Yes <input checked="" type="radio"/> No <input type="radio"/> Unknown
Involve Cross Bore?	<input type="radio"/> Yes <input checked="" type="radio"/> No <input type="radio"/> Unknown
Measured Depth from Grade	>36" / 91 cm
Exact Measured Depth from Grade	Enter the inches or centimeters with number and measurement used

Work Information



Start Date of Excavation (?)	04/03/2025		
	07:00:00 AM		
Excavation Activity	WATER		
Excavator Company Name	RLE ENTERPRISES		
Contact First Name	TODD	Last Name	CANTAFIO
Address	457 N. MAIN ST.		
City	MOSCOW		
State	PA		
Zip	18444		
Email	TODDC@RLEENTERPRISES.NET	Phone	570-906-0600
Marked in White	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> Unknown		
Method of Excavation	DIGGING		
Equipment Used	What Equipment was used for excavation or demolition when the event occurred? BACKHOE/TRACKHOE		
Type of Excavator	What is the type of excavator for whom the work was being done when the event occurred? Utility		
Did Excavator incur down time?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> Unknown		
How much down time?	Unknown		
Estimated cost of down time	Unknown		
Was a response posted to the One Call System?	<input type="radio"/> Yes <input type="radio"/> No <input checked="" type="radio"/> Unknown		
Was the design serial number on the plans/bid documents?	<input type="radio"/> Yes <input type="radio"/> No <input type="radio"/> Unknown		
Were the lines shown on the plans/bid documents?	<input type="radio"/> Yes <input type="radio"/> No <input type="radio"/> Unknown		
What level of subsurface utility engineering was utilized?	A (Test Hole/Pot Holing)		

Estimated cost of the entire project \$400,000 or more

What was the length of the entire project?

Project Owner Company Name PAWC

Contact First Name JESSICA Last Name MILLER

Address 2699 STAFFORD AVE.

City SCRANTON

State PA

Zip 18505

Email JESSICA.MILLER@AMW ATER.COM Phone 570-369-3374

Event Impact



Did Violation result in underground damage or near miss event? Damage

OSHA Report Filed? Yes No

OSHA Report Number

Was 911 called? Yes No

Name of 911 Caller

Fire Response Yes No

Police Response Yes No

Did the incident cause any injuries? Yes

Number of Injuries (?)

Did the incident cause any deaths? Yes

Number of Deaths

Was there an evacuation? Yes No

Number of people evacuated?

Traffic Stopped? Yes No

Service Interrupted? Yes No

Duration of Service Interruption? 1 - < 6 hrs

Exact Value of Service Interruption

Approximately how many customers were affected? 1

Exact Number of Customers Affected

Cost of Damaged Line Repair? Unknown

Exact Cost of Damaged Line Repair

Was other property damaged? Yes No

What other property was damaged?

Cost of Other Property Repair

Locator/Locate Information



Who was the facility line locator? Employee Locator

Locator Company

Contact First Name

Last Name

Address

City

State

Zip

Email

Phone

Was the line marked? Accurately Inaccurately/Incompletely Not Marked
 Unknown

Were facilities marked according to APWA/CGA temporary marking color code (ANSI standard Z535.1)? Yes No Unknown

What types of marks were present?
 Paint
 Flags
 Stakes
 Other

Were offset markings used? Yes No Unknown

Condition of Marks

Was the line marked by the response due date or within the agreed upon locate schedule? (?) Yes No Unknown

Reason for Late Locate

Was the excavation within the tolerance zone? (?) Yes No Unknown

Was there an indication of underground facilities (clear evidence) in the excavation area? Yes No Unknown

What was the evidence?
(meter/pedestal, pipeline marker, valve
box, hydrant, manhole, etc.)

What method(s) were used to locate
the facility? Electronic Records
 Visual Exposed

Did the excavator request payment
under PennDOT Form 408
specifications for extra work
performed on a force account basis? Yes No

Additional Locate Comments

If this incident involved any locating/marketing errors, please include all records related to the locator's training and qualification (including training to meet UULPL standards as well as Operator Qualification).

Summary and Attachments

Provide a summary of the event

WHILE DIGGING FOR A NEW WATER MAIN INSTALLATION,
OUR CREW STRUCK AN UNMARKED SEWER LATERAL FOR
HOUSE #21 OAKLAWN AVE. RLE MADE REPAIRS AND
RESTORED SERVICE IN A TIMELY MANNER.

If more space is needed, attach additional pages or documents.

Attachments

IMG_3484.jpg 3.98MB

IMG_3485.jpg 4.48MB

Attach pictures and additional documents

Submit Date

04/04/2025

Compliance Update

Research Result

- Listed tickets found
- Additional tickets found
- No tickets found

Additional Tickets Found

Additional Serial Numbers 20250792701

Additional Serial Numbers 20250792701

Additional Serial Numbers 20242781470

Additional Serial Numbers 20231871827

Ticket Attachment

8317071_report.pdf 780.37KB

4071471_report.pdf 777.71KB

Comments

I&E Exhibit 5



Alleged Violation Report

PA Act 287, as amended 73 P. S. § 176 et. seq.
Powered by Pennsylvania One Call System, Inc.

AVR Number AVR2025APR040027
AVR Version 1
First Name AJ **Last Name** KOCHANSKI
Company Name R L E ENTERPRISES
Address 457 N MAIN STREET
City MOSCOW
State PA
Zip Code 18444
Email AJK@RLEENTERPRISE S.NET **Phone** 5709044398
Ext

Role

Submitter Role(s) (?)

- | | |
|---|---|
| <input type="checkbox"/> Facility Owner | <input type="checkbox"/> Designer |
| <input checked="" type="checkbox"/> Excavator | <input type="checkbox"/> Project Owner |
| <input type="checkbox"/> Locator | <input type="checkbox"/> Enforcement Agency |
| <input type="checkbox"/> Other | |

Are you representing a company other than your own? Yes No

What company or individual are you representing?

Alleged Violation Information

PUC Case Number (if known)

Related AVR Number (?)

Type of Alleged Violation (?) Facility Owner Issue

Reason Marked incorrectly §2(5)

When did the alleged violation occur? (?) 04/03/2025
01:00:00 PM

Was the One Call System notified? Yes No

Original Serial Number

Please enter the 11 digit One Call Serial Number under which work was taking place, which will populate the work site information of this alleged violation.

Related Damage Serial Number, if applicable

Other Related Serial Numbers (?)

Was the excavation exempt from One Call notification? Yes No Unknown

Reason for Exemption

Event Information



County LUZERNE
Municipality HANOVER TWP
Ward
Work Site OAKLAWN AVE.
Nearest Intersection SAINT MARY'S RD.
Second Intersection S. MAIN ST.
Geolocation (?)

Affected Facility Information



Primary Right of Way Type Public
Public Right of Way Type City Street
Private Right of Way Type

Affected Operation Sewer
Facility Subtype Affected Service/Drop/Lateral
Facility Owner Company Name HANOVER TOWNSHIP
Contact First Name Last Name
Address 1267 SANS SOUCI PKWY
City WILKES BARRE
State PA
Zip 18706

Email	Phone
Joint Trench?	<input type="radio"/> Yes <input checked="" type="radio"/> No <input type="radio"/> Unknown
Involve Cross Bore?	<input type="radio"/> Yes <input checked="" type="radio"/> No <input type="radio"/> Unknown
Measured Depth from Grade	>36" / 91 cm
Exact Measured Depth from Grade	Enter the inches or centimeters with number and measurement used

Work Information



Start Date of Excavation (?)	04/03/2025		
	07:00:00 AM		
Excavation Activity	WATER		
Excavator Company Name	RLE ENTERPRISES		
Contact First Name	TODD	Last Name	CANTAFIO
Address	457 N. MAIN ST.		
City	MOSCOW		
State	PA		
Zip	18444		
Email	TODDC@RLEENTERPRISES.NET	Phone	570-906-0600
Marked in White	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> Unknown		
Method of Excavation	DIGGING		
Equipment Used	What Equipment was used for excavation or demolition when the event occurred? BACKHOE/TRACKHOE		
Type of Excavator	What is the type of excavator for whom the work was being done when the event occurred? Utility		
Did Excavator incur down time?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> Unknown		
How much down time?	Unknown		
Estimated cost of down time	Unknown		
Was a response posted to the One Call System?	<input type="radio"/> Yes <input type="radio"/> No <input checked="" type="radio"/> Unknown		
Was the design serial number on the plans/bid documents?	<input type="radio"/> Yes <input type="radio"/> No <input type="radio"/> Unknown		
Were the lines shown on the plans/bid documents?	<input type="radio"/> Yes <input type="radio"/> No <input type="radio"/> Unknown		
What level of subsurface utility engineering was utilized?	A (Test Hole/Pot Holing)		

Estimated cost of the entire project \$400,000 or more

What was the length of the entire project?

Project Owner Company Name PAWC

Contact First Name JESSICA Last Name MILLER

Address 2699 STAFFORD AVE.

City SCRANTON

State PA

Zip 18505

Email JESSICA.MILLER@AMW ATER.COM Phone 570-369-3374

Event Impact



Did Violation result in underground damage or near miss event? Damage

OSHA Report Filed? Yes No

OSHA Report Number

Was 911 called? Yes No

Name of 911 Caller

Fire Response Yes No

Police Response Yes No

Did the incident cause any injuries? Yes

Number of Injuries (?)

Did the incident cause any deaths? Yes

Number of Deaths

Was there an evacuation? Yes No

Number of people evacuated?

Traffic Stopped? Yes No

Service Interrupted? Yes No

Duration of Service Interruption? 1 - < 6 hrs

Exact Value of Service Interruption

Approximately how many customers were affected? 1

Exact Number of Customers Affected

Cost of Damaged Line Repair? Unknown

Exact Cost of Damaged Line Repair

Was other property damaged? Yes No

What other property was damaged?

Cost of Other Property Repair

Locator/Locate Information



Who was the facility line locator? Employee Locator

Locator Company

Contact First Name

Last Name

Address

City

State

Zip

Email

Phone

Was the line marked? Accurately Inaccurately/Incompletely Not Marked
 Unknown

Were facilities marked according to APWA/CGA temporary marking color code (ANSI standard Z535.1)? Yes No Unknown

What types of marks were present?
 Paint
 Flags
 Stakes
 Other

Were offset markings used? Yes No Unknown

Condition of Marks

Was the line marked by the response due date or within the agreed upon locate schedule? (?) Yes No Unknown

Reason for Late Locate

Was the excavation within the tolerance zone? (?) Yes No Unknown

Was there an indication of underground facilities (clear evidence) in the excavation area? Yes No Unknown

What was the evidence?
(meter/pedestal, pipeline marker, valve box, hydrant, manhole, etc.)

What method(s) were used to locate the facility? Electronic Records
 Visual Exposed

Did the excavator request payment under PennDOT Form 408 specifications for extra work performed on a force account basis? Yes No

Additional Locate Comments If this incident involved any locating/marketing errors, please include all records related to the locator's training and qualification (including training to meet UULPL standards as well as Operator Qualification).

Summary and Attachments

Provide a summary of the event WHILE DIGGING FOR A NEW WATER MAIN INSTALLATION, OUR CREW STRUCK AN UNMARKED SEWER LATERAL FOR HOUSE #20 OAKLAWN AVE. RLE MADE REPAIRS AND RESTORED SERVICE IN A TIMELY MANNER.
If more space is needed, attach additional pages or documents.

Attachments IMG_5349.jpg 7.15MB
Attach pictures and additional documents

Submit Date 04/04/2025

Compliance Update

Research Result Listed tickets found
 Additional tickets found
 No tickets found

Additional Tickets Found

Additional Serial Numbers 20250792701

Additional Serial Numbers 20250491663

Additional Serial Numbers 20242781470

Additional Serial Numbers 20231871827

Ticket Attachment 4071471_report.pdf 777.71KB
8317071_report.pdf 780.37KB

Comments

I&E Exhibit 6



Alleged Violation Report

PA Act 287, as amended 73 P. S. § 176 et. seq.
Powered by Pennsylvania One Call System, Inc.

AVR Number AVR2025APR070011

AVR Version 1

First Name AJ **Last Name** KOCHANSKI

Company Name R L E ENTERPRISES

Address 457 N MAIN STREET

City MOSCOW

State PA

Zip Code 18444

Email AJK@RLEENTERPRISE S.NET **Phone** 5709044398

Ext

Role

Submitter Role(s) (?)

- | | |
|---|---|
| <input type="checkbox"/> Facility Owner | <input type="checkbox"/> Designer |
| <input checked="" type="checkbox"/> Excavator | <input type="checkbox"/> Project Owner |
| <input type="checkbox"/> Locator | <input type="checkbox"/> Enforcement Agency |
| <input type="checkbox"/> Other | |

Are you representing a company other than your own? Yes No

What company or individual are you representing?

Alleged Violation Information

PUC Case Number (if known)

Related AVR Number (?)

Type of Alleged Violation (?) Facility Owner Issue

Reason Marked incorrectly §2(5)

When did the alleged violation occur? (?) 04/07/2025
08:00:00 AM

Was the One Call System notified? Yes No

Original Serial Number

Please enter the 11 digit One Call Serial Number under which work was taking place, which will populate the work site information of this alleged violation.

Related Damage Serial Number, if applicable

Other Related Serial Numbers (?)

Was the excavation exempt from One Call notification? Yes No Unknown

Reason for Exemption

Event Information



County LUZERNE
Municipality HANOVER TWP
Ward
Work Site OAKLAWN AVE.
Nearest Intersection E SAINT MARY'S RD.
Second Intersection S. MAIN ST.
Geolocation (?)

Affected Facility Information



Primary Right of Way Type Public
Public Right of Way Type City Street
Private Right of Way Type
Affected Operation Sewer
Facility Subtype Affected Service/Drop/Lateral
Facility Owner Company Name HANOVER TOWNSHIP
Contact First Name Last Name
Address 1267 SANS SOUCI PKWY
City WILKES BARRE
State PA
Zip 18706

Email	Phone
Joint Trench?	<input type="radio"/> Yes <input checked="" type="radio"/> No <input type="radio"/> Unknown
Involve Cross Bore?	<input type="radio"/> Yes <input checked="" type="radio"/> No <input type="radio"/> Unknown
Measured Depth from Grade	>36" / 91 cm
Exact Measured Depth from Grade	Enter the inches or centimeters with number and measurement used

Work Information



Start Date of Excavation (?)	04/07/2025		
	07:00:00 AM		
Excavation Activity	WATER		
Excavator Company Name	RLE ENTERPRISES		
Contact First Name	TODD	Last Name	CANTAFIO
Address	457 N. MAIN ST.		
City	MOSCOW		
State	PA		
Zip	18444		
Email	TODDC@RLEENTERPRISES.NET	Phone	570-906-0600
Marked in White	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> Unknown		
Method of Excavation	DIGGING		
Equipment Used	What Equipment was used for excavation or demolition when the event occurred? BACKHOE/TRACKHOE		
Type of Excavator	What is the type of excavator for whom the work was being done when the event occurred? Utility		
Did Excavator incur down time?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> Unknown		
How much down time?	Unknown		
Estimated cost of down time	Unknown		
Was a response posted to the One Call System?	<input type="radio"/> Yes <input type="radio"/> No <input checked="" type="radio"/> Unknown		
Was the design serial number on the plans/bid documents?	<input type="radio"/> Yes <input type="radio"/> No <input type="radio"/> Unknown		
Were the lines shown on the plans/bid documents?	<input type="radio"/> Yes <input type="radio"/> No <input type="radio"/> Unknown		
What level of subsurface utility engineering was utilized?	A (Test Hole/Pot Holing)		

Estimated cost of the entire project \$400,000 or more

What was the length of the entire project?

Project Owner Company Name PAWC

Contact First Name JESSICA Last Name MILLER

Address 2699 STAFFORD AVE.

City SCRANTON

State PA

Zip 18505

Email JESSICA.MILLER@AMW ATER.COM Phone 570-369-3374

Event Impact



Did Violation result in underground damage or near miss event? Damage

OSHA Report Filed? Yes No

OSHA Report Number

Was 911 called? Yes No

Name of 911 Caller

Fire Response Yes No

Police Response Yes No

Did the incident cause any injuries? Yes

Number of Injuries (?)

Did the incident cause any deaths? Yes

Number of Deaths

Was there an evacuation? Yes No

Number of people evacuated?

Traffic Stopped? Yes No

Service Interrupted? Yes No

Duration of Service Interruption? 1 - < 6 hrs

Exact Value of Service Interruption

Approximately how many customers were affected? 1

Exact Number of Customers Affected

Cost of Damaged Line Repair? Unknown

Exact Cost of Damaged Line Repair

Was other property damaged? Yes No

What other property was damaged?

Cost of Other Property Repair

Locator/Locate Information



Who was the facility line locator? Employee Locator

Locator Company

Contact First Name Last Name

Address

City

State

Zip

Email Phone

Was the line marked? Accurately Inaccurately/Incompletely Not Marked
 Unknown

Were facilities marked according to APWA/CGA temporary marking color code (ANSI standard Z535.1)? Yes No Unknown

What types of marks were present?
 Paint
 Flags
 Stakes
 Other

Were offset markings used? Yes No Unknown

Condition of Marks

Was the line marked by the response due date or within the agreed upon locate schedule? (?) Yes No Unknown

Reason for Late Locate

Was the excavation within the tolerance zone? (?) Yes No Unknown

Was there an indication of underground facilities (clear evidence) in the excavation area? Yes No Unknown

What was the evidence?
(meter/pedestal, pipeline marker, valve box, hydrant, manhole, etc.)

What method(s) were used to locate the facility? Electronic Records Visual Exposed

Did the excavator request payment under PennDOT Form 408 specifications for extra work performed on a force account basis? Yes No

Additional Locate Comments If this incident involved any locating/marketing errors, please include all records related to the locator's training and qualification (including training to meet UULPL standards as well as Operator Qualification).

Summary and Attachments

Provide a summary of the event WHILE DIGGING FOR A NEW WATER MAIN INSTALLATION, OUR CREW STRUCK AN UNMARKED SEWER LATERIAL FOR HOUSE # 15 OAKLAWN AVE. RLE MADE REPAIRS AND RESTORED SERVICE IN A TIMELY MANNER.

If more space is needed, attach additional pages or documents.

Attachments IMG_3497.jpg 3.84MB
IMG_3498.jpg 6.83MB

Attach pictures and additional documents

Submit Date 04/07/2025

Compliance Update

Research Result Listed tickets found Additional tickets found No tickets found

Additional Tickets Found

Additional Serial Numbers 20250792701

Additional Serial Numbers 20250491663

Additional Serial Numbers 20242781470

Additional Serial Numbers 20231871827

Ticket Attachment 4071471_report.pdf 777.71KB
8317071_report.pdf 780.37KB

Comments

I&E Exhibit 7



Alleged Violation Report

PA Act 287, as amended 73 P. S. § 176 et. seq.
Powered by Pennsylvania One Call System, Inc.

AVR Number AVR2025APR070012

AVR Version 1

First Name AJ **Last Name** KOCHANSKI

Company Name R L E ENTERPRISES

Address 457 N MAIN STREET

City MOSCOW

State PA

Zip Code 18444

Email AJK@RLEENTERPRISE S.NET **Phone** 5709044398

Ext

Role

Submitter Role(s) (?)

- | | |
|---|---|
| <input type="checkbox"/> Facility Owner | <input type="checkbox"/> Designer |
| <input checked="" type="checkbox"/> Excavator | <input type="checkbox"/> Project Owner |
| <input type="checkbox"/> Locator | <input type="checkbox"/> Enforcement Agency |
| <input type="checkbox"/> Other | |

Are you representing a company other than your own? Yes No

What company or individual are you representing?

Alleged Violation Information

PUC Case Number (if known)

Related AVR Number (?)

Type of Alleged Violation (?) Facility Owner Issue

Reason Marked incorrectly §2(5)

When did the alleged violation occur? (?) 04/07/2025
09:00:00 AM

Was the One Call System notified? Yes No

Original Serial Number

Please enter the 11 digit One Call Serial Number under which work was taking place, which will populate the work site information of this alleged violation.

Related Damage Serial Number, if applicable

Other Related Serial Numbers (?)

Was the excavation exempt from One Call notification? Yes No Unknown

Reason for Exemption

Event Information



County LUZERNE
Municipality HANOVER TWP
Ward
Work Site OAKLAWN AVE.
Nearest Intersection SAINT MARY'S RD.
Second Intersection S. MAIN ST.
Geolocation (?)

Affected Facility Information



Primary Right of Way Type Public
Public Right of Way Type City Street
Private Right of Way Type

Affected Operation Sewer
Facility Subtype Affected Service/Drop/Lateral
Facility Owner Company Name HANOVER TOWNSHIP
Contact First Name Last Name
Address 1267 SANS SOUCI PKWY
City WILKES BARRE
State PA
Zip 18706

Email	Phone
Joint Trench?	<input type="radio"/> Yes <input checked="" type="radio"/> No <input type="radio"/> Unknown
Involve Cross Bore?	<input type="radio"/> Yes <input checked="" type="radio"/> No <input type="radio"/> Unknown
Measured Depth from Grade	>36" / 91 cm
Exact Measured Depth from Grade	Enter the inches or centimeters with number and measurement used

Work Information



Start Date of Excavation (?)	04/07/2025		
	07:00:00 AM		
Excavation Activity	WATER		
Excavator Company Name	RLE ENTERPRISES		
Contact First Name	TODD	Last Name	CANTAFIO
Address	457 N. MAIN ST.		
City	MOSCOW		
State	PA		
Zip	18444		
Email	TODDC@RLEENTERPRISES.NET	Phone	570-906-0600
Marked in White	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> Unknown		
Method of Excavation	DIGGING		
Equipment Used	What Equipment was used for excavation or demolition when the event occurred? BACKHOE/TRACKHOE		
Type of Excavator	What is the type of excavator for whom the work was being done when the event occurred? Utility		
Did Excavator incur down time?	<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> Unknown		
How much down time?	Unknown		
Estimated cost of down time	Unknown		
Was a response posted to the One Call System?	<input type="radio"/> Yes <input type="radio"/> No <input checked="" type="radio"/> Unknown		
Was the design serial number on the plans/bid documents?	<input type="radio"/> Yes <input type="radio"/> No <input type="radio"/> Unknown		
Were the lines shown on the plans/bid documents?	<input type="radio"/> Yes <input type="radio"/> No <input type="radio"/> Unknown		
What level of subsurface utility engineering was utilized?	A (Test Hole/Pot Holing)		

Estimated cost of the entire project \$400,000 or more

What was the length of the entire project?

Project Owner Company Name PAWC

Contact First Name JESSICA Last Name MILLER

Address 2699 STAFFORD AVE.

City SCRANTON

State PA

Zip 18505

Email JESSICA.MILLER@AMW ATER.COM Phone 570-369-3374

Event Impact



Did Violation result in underground damage or near miss event? Damage

OSHA Report Filed? Yes No

OSHA Report Number

Was 911 called? Yes No

Name of 911 Caller

Fire Response Yes No

Police Response Yes No

Did the incident cause any injuries? Yes

Number of Injuries (?)

Did the incident cause any deaths? Yes

Number of Deaths

Was there an evacuation? Yes No

Number of people evacuated?

Traffic Stopped? Yes No

Service Interrupted? Yes No

Duration of Service Interruption? 1 - < 6 hrs

Exact Value of Service Interruption

Approximately how many customers were affected? 1

Exact Number of Customers Affected

Cost of Damaged Line Repair? Unknown

Exact Cost of Damaged Line Repair

Was other property damaged? Yes No

What other property was damaged?

Cost of Other Property Repair

Locator/Locate Information



Who was the facility line locator? Employee Locator

Locator Company

Contact First Name

Last Name

Address

City

State

Zip

Email

Phone

Was the line marked? Accurately Inaccurately/Incompletely Not Marked
 Unknown

Were facilities marked according to APWA/CGA temporary marking color code (ANSI standard Z535.1)? Yes No Unknown

What types of marks were present?
 Paint
 Flags
 Stakes
 Other

Were offset markings used? Yes No Unknown

Condition of Marks

Was the line marked by the response due date or within the agreed upon locate schedule? (?) Yes No Unknown

Reason for Late Locate

Was the excavation within the tolerance zone? (?) Yes No Unknown

Was there an indication of underground facilities (clear evidence) in the excavation area? Yes No Unknown

What was the evidence?
(meter/pedestal, pipeline marker, valve
box, hydrant, manhole, etc.)

What method(s) were used to locate
the facility? Electronic Records
 Visual Exposed

Did the excavator request payment
under PennDOT Form 408
specifications for extra work
performed on a force account basis? Yes No

Additional Locate Comments

If this incident involved any locating/markings errors, please include all records related to the locator's training and qualification (including training to meet UULPL standards as well as Operator Qualification).

Summary and Attachments

Provide a summary of the event

WHILE DIGGING FOR A NEW WATER MAIN INSTALLATION,
OUR CREW STRUCK AN UNMARKED SEWER LATERIAL FOR
HOUSE # 14 OAKLAWN AVE. RLE MADE REPAIRS AND
RESTORED SERVICE IN A TIMELY MANNER.

If more space is needed, attach additional pages or documents.

Attachments

IMG_3499.jpg 3.6MB
IMG_3500.jpg 3.78MB

Attach pictures and additional documents

Submit Date

04/07/2025

Compliance Update

Research Result

Listed tickets found
 Additional tickets found
 No tickets found

Additional Tickets Found

Additional Serial Numbers 20250792701

Additional Serial Numbers 20250491663

Additional Serial Numbers 20242781470

Additional Serial Numbers 20231871827

Ticket Attachment

4071471_report.pdf 777.71KB
8317071_report.pdf 780.37KB

Comments

I&E Exhibit 8



Alleged Violation Report

PA Act 287, as amended 73 P. S. § 176 et. seq.
Powered by Pennsylvania One Call System, Inc.

AVR Number AVR2025APR070014

AVR Version 1

First Name AJ **Last Name** KOCHANSKI

Company Name R L E ENTERPRISES

Address 457 N MAIN STREET

City MOSCOW

State PA

Zip Code 18444

Email AJK@RLEENTERPRISE S.NET **Phone** 5709044398

Ext

Role

Submitter Role(s) (?)

- | | |
|---|---|
| <input type="checkbox"/> Facility Owner | <input type="checkbox"/> Designer |
| <input checked="" type="checkbox"/> Excavator | <input type="checkbox"/> Project Owner |
| <input type="checkbox"/> Locator | <input type="checkbox"/> Enforcement Agency |
| <input type="checkbox"/> Other | |

Are you representing a company other than your own? Yes No

What company or individual are you representing?

Alleged Violation Information

PUC Case Number (if known)

Related AVR Number (?)

Type of Alleged Violation (?) Facility Owner Issue

Reason Marked incorrectly §2(5)

When did the alleged violation occur? (?) 04/07/2025
11:00:00 AM

Was the One Call System notified? Yes No

Original Serial Number

Please enter the 11 digit One Call Serial Number under which work was taking place, which will populate the work site information of this alleged violation.

Related Damage Serial Number, if applicable

Other Related Serial Numbers (?)

Was the excavation exempt from One Call notification? Yes No Unknown

Reason for Exemption

Event Information



County LUZERNE

Municipality HANOVER TWP

Ward

Work Site OAKLAWN AVE.

Nearest Intersection SAINT MARY'S RD.

Second Intersection S. MAIN ST.

Geolocation (?)

Affected Facility Information



Primary Right of Way Type Public

Public Right of Way Type City Street

Private Right of Way Type

Affected Operation Sewer

Facility Subtype Affected Service/Drop/Lateral

Facility Owner Company Name HANOVER TOWNSHIP

Contact First Name Last Name

Address 1267 SANS SOUCI PKWY

City WILKES BARRE

State PA

Zip 18706

Email

Phone

Joint Trench? Yes No Unknown

Involve Cross Bore? Yes No Unknown

Measured Depth from Grade >36" / 91 cm

Exact Measured Depth from Grade Enter the inches or centimeters with number and measurement used

Work Information



Start Date of Excavation (?) 04/07/2025
07:00:00 AM

Excavation Activity WATER

Excavator Company Name RLE ENTERPRISES

Contact First Name TODD Last Name CANTAFIO

Address 457 N. MAIN ST.

City MOSCOW

State PA

Zip 18444

Email TODDC@RLEENTERPRISES.NET Phone 570-906-0600

Marked in White Yes No Unknown

Method of Excavation DIGGING

Equipment Used What Equipment was used for excavation or demolition when the event occurred?
BACKHOE/TRACKHOE

Type of Excavator What is the type of excavator for whom the work was being done when the event occurred?
Utility

Did Excavator incur down time? Yes No Unknown

How much down time? Unknown

Estimated cost of down time Unknown

Was a response posted to the One Call System? Yes No Unknown

Was the design serial number on the plans/bid documents? Yes No Unknown

Were the lines shown on the plans/bid documents? Yes No Unknown

What level of subsurface utility engineering was utilized? A (Test Hole/Pot Holing)

Estimated cost of the entire project \$400,000 or more

What was the length of the entire project?

Project Owner Company Name PAWC

Contact First Name JESSICA Last Name MILLER

Address 2699 STAFFORD AVE.

City SCRANTON

State PA

Zip 18505

Email JESSICA.MILLER@AMW ATER.COM Phone 570-369-3374

Event Impact



Did Violation result in underground damage or near miss event? Damage

OSHA Report Filed? Yes No

OSHA Report Number

Was 911 called? Yes No

Name of 911 Caller

Fire Response Yes No

Police Response Yes No

Did the incident cause any injuries? Yes

Number of Injuries (?)

Did the incident cause any deaths? Yes

Number of Deaths

Was there an evacuation? Yes No

Number of people evacuated?

Traffic Stopped? Yes No

Service Interrupted? Yes No

Duration of Service Interruption? 1 - < 6 hrs

Exact Value of Service Interruption

Approximately how many customers were affected? 1

Exact Number of Customers Affected

Cost of Damaged Line Repair? Unknown

Exact Cost of Damaged Line Repair

Was other property damaged? Yes No

What other property was damaged?

Cost of Other Property Repair

Locator/Locate Information



Who was the facility line locator? Employee Locator

Locator Company

Contact First Name Last Name

Address

City

State

Zip

Email Phone

Was the line marked? Accurately Inaccurately/Incompletely Not Marked Unknown

Were facilities marked according to APWA/CGA temporary marking color code (ANSI standard Z535.1)? Yes No Unknown

What types of marks were present? Paint Flags Stakes Other

Were offset markings used? Yes No Unknown

Condition of Marks

Was the line marked by the response due date or within the agreed upon locate schedule? (?) Yes No Unknown

Reason for Late Locate

Was the excavation within the tolerance zone? (?) Yes No Unknown

Was there an indication of underground facilities (clear evidence) in the excavation area? Yes No Unknown

What was the evidence?
(meter/pedestal, pipeline marker, valve box, hydrant, manhole, etc.)

What method(s) were used to locate the facility? Electronic Records Visual Exposed

Did the excavator request payment under PennDOT Form 408 specifications for extra work performed on a force account basis? Yes No

Additional Locate Comments If this incident involved any locating/marketing errors, please include all records related to the locator's training and qualification (including training to meet UULPL standards as well as Operator Qualification).

Summary and Attachments

Provide a summary of the event WHILE DIGGING FOR A NEW WATER MAIN INSTALLATION, OUR CREW STRUCK AN UNMARKED SEWER LATERIAL FOR HOUSE # 13 OAKLAWN AVE. RLE MADE REPAIRS AND RESTORED SERVICE IN A TIMELY MANNER.

If more space is needed, attach additional pages or documents.

Attachments IMG_3502.jpg 4.63MB
IMG_3502.jpg 4.63MB

Attach pictures and additional documents

Submit Date 04/07/2025

Compliance Update

Research Result Listed tickets found Additional tickets found No tickets found

Additional Tickets Found

Additional Serial Numbers 20250792701

Additional Serial Numbers 20250491663

Additional Serial Numbers 20242781470

Additional Serial Numbers 20231871827

Ticket Attachment 4071471_report.pdf 777.71KB
8317071_report.pdf 780.37KB

Comments

**BEFORE THE
PENNSYLVANIA PUBLIC UTILITY COMMISSION**

Pennsylvania Public Utility Commission,	:	
Bureau of Investigation and Enforcement,	:	
Complainant	:	
	:	
v.	:	Docket No. C-2026-
	:	
Connell Equipment Inc. t/d/b/a RLE	:	
Enterprises,	:	
Respondent	:	

CERTIFICATE OF SERVICE

I hereby certify that I have this day served a true copy of the foregoing document upon the parties, listed below, in accordance with the requirements of 52 Pa. Code § 1.54 (relating to service by a party).

**Service by Certified Mail, Return Receipt Requested,
and First-Class Mail**

Connell Equipment Inc. t/d/b/a RLE Enterprises
Attn: John Gentile
457 North Main Street, Rear
Moscow, PA 18444



Colby B. Widdowson
Prosecutor
PA Attorney ID No. 326185

Pennsylvania Public Utility Commission
Bureau of Investigation and Enforcement
Commonwealth Keystone Building
400 North Street
Harrisburg, PA 17120
(717) 783-5243
cwiddowson@pa.gov

Dated: March 26, 2026